

## Fort Worth, TX, USA - Dec 10, 2024

Lot #	Details	Lot #	Details	
1	2017 Case 570 N EP 4x4 Landscape Loader S/N: JJGN570NEHC739167 C/W: Open Operator Station, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Weight Box Usage: 4,852 Hr Asset located in: Lake Worth, TX	7	S/N: CAT00420TH8T02368 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 94 in	
2	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380199 C/W: Open Operator Station, 2006 US EPA Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 7,966 Hr		Loader Bucket, Forks, Quick Coupler, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 66 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX	
СНОІС	Asset located in: Lake Worth, TX  E OF 2 - Lot #'s: 3, 4	9 CHOICE 10	2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420CH8T00232 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 12 in	
3	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380435 C/W: Open Operator Station, 2006 US EPA		Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,244 Hr <b>Asset located in</b> : Lake Worth, TX	
	Label, 84 in Bucket, 84 in Hydraulic Tilting Box Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 2,597 Hr <b>Asset located in</b> : Lake Worth, TX		2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420AH8T00225 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 96 in Loader Bucket, 24 in Backhoe	
4	2006 Case 570MXT 4x2 Landscape Loader S/N: JJG0380358 C/W: Open Operator Station, 2006 US EPA Label, 82 in Bucket, 84 in Hydraulic Tilting Box			Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 4,803 Hr Asset located in: Lake Worth, TX
	Blade w/ Hydraulic Scarifier, Rear Frame Weights Usage: 4,932 Hr  Asset located in: Lake Worth, TX		E OF 4 - Lot #'s: 10, 11, 8, 9	
5	2015 John Deere 210L EP Landscape Loader S/N: 1T8210ELEFJ892655 C/W: Open Operator Station, Multi-Purpose Bucket, Box Blade, with Rippers Usage: Not Available Asset located in: Lake Worth, TX		S/N: CAT00420AH8T00287 C/W: Open Operator Station, Air Ride Sea Backhoe Pilot Controls, Tier 4, 2020 US E Label, Requires Diesel Exhaust Fluid, 95 i Loader Bucket, 24 in Backhoe Digging Bu	
6	<b>2006 Case 570 MXT 4x4 Landscape Loader</b> S/N: JJG0380343	11	Usage: 5,611 Hr  Asset located in: Lake Worth, TX	
	C/W: Enclosed Cab, 83 in Bucket, 83 in Hydraulic Tilting Box Blade Usage: 2,554 Hr <b>Asset located in</b> : Lake Worth, TX		2020 Cat 420 4x4 Backhoe Loader S/N: CAT00420JH8T00303 C/W: Open Operator Station, Backhoe Pilot Controls, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket Usage: 5,904 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
12	2017 Cat 420F2 4x4 Backhoe Loader S/N: CAT0420FJHWC02726 C/W: Open Operator Station, Backhoe Pilot Controls, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 95 in Loader Bucket, 15 in Backhoe Cleanup Bucket, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,487 Hr Asset located in: Lake Worth, TX	18	2015 Cat 420F2 IT 4x4 Backhoe Loader S/N: CAT0420FAHWD00353 C/W: Open Operator Station, Backhoe Pilot Controls, Control Pattern Changer, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 94 in Loader Bucket, Forks, 23 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,443 Hr Asset located in: Humble, TX
CHOIC	E OF 2 - Lot #'s: 13, 14	19	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FVHWD00240
13	2017 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FAHWD01616 C/W: Open Operator Station, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92.5 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available		C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 5,953 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	СНОІС	E OF 2 - Lot #'s: 20, 21
14	Asset located in: Humble, TX  2017 Cat 420F2 IT 4x4 Backhoe Loader	20	2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FCHWD00205
	S/N: CAT0420FHHWD01618 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 92 in Loader Bucket, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: Not Available		C/W: Open Operator Station, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 22 in Backhoe Digging Bucket EQUIPMENT-FROM-A-PRIMORIS-SERVICES CORP-COMPANY Usage: 5,886 Hr Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	21	21 2014 Cat 420FIT 4x4 Backhoe Loader S/N: CAT0420FKJWJ02630
15	Asset located in: Humble, TX  2016 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FKHWD00461 C/W: Open Operator Station, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 96 in Loader Bucket, 25 in Backhoe Digging Bucket		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 94 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 5,652 Hr Asset located in: Lake Worth, TX
16	Usage: 5,256 Hr Asset located in: Lake Worth, TX  2016 Cat 420F2IT 4x4 Backhoe Loader	22	<b>2015 Cat 420F 4x4 Backhoe Loader</b> S/N: CAT0420FVSKR04978 Usage: Not Available
	S/N: CAT0420FCHWD01301 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket Usage: 4,376 Hr Asset located in: Lake Worth, TX	24	Asset located in: Lake Worth, TX  2012 Cat 420E 4x4 Backhoe Loader S/N: CAT0420EHDJL03428 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, 86 in Loader Bucket, 24 in Backhoe Digging Bucket, Manual Thumb Usage: 4,236 Hr Asset located in: Lake Worth, TX
17	2016 Cat 420 F2 4x4 Backhoe Loader S/N: CAT0420FEHWC01679 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, 86 in Multi-Purpose Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, (2) Rear Auxiliary Hydraulics Usage: 2,720 Hr Asset located in: Lake Worth, TX	25	2011 Cat 420E IT 4x4 Backhoe Loader S/N: CAT0420EPDAN01657 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Hydraulic Coupler, 90 in Multi-Purpose Loader Bucket, 30 in Backhoe Digging Bucket, Thumb Bracket Usage: 6,276 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
26	2020 Cat 416F2 4x4 Backhoe Loader S/N: CAT0416FTHWB02400 C/W: Open Operator Station, Air Ride Seat, Requires Diesel Exhaust Fluid, 89 in Loader Bucket, 20 in Backhoe Cleanup Bucket Usage: 2,510 Hr Asset located in: Lake Worth, TX	34	2018 John Deere 310L EP 4x2 Backhoe Loader S/N: 1T0310ELCJG334570 C/W: Open Operator Station, 2018 US EPA Label, 84 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 3,480 Hr Asset located in: Lake Worth, TX	
27	2017 Cat 416F2 4x4 Backhoe Loader S/N: CAT0416FTHWB01148 C/W: Open Operator Station, 2017 US EPA	сноіс	E OF 2 - Lot #'s: 35, 36	
	Label, Requires Diesel Exhaust Fluid, 88 in Loader Bucket, 10 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	35	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKKEE263557 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,207 Hr	
28	2022 Cat 415 4x4 Backhoe Loader		Asset located in: Lake Worth, TX	
	S/N: CAT00415HH8A00347 C/W: Open Operator Station, Air Ride Seat, 2022 US EPA Label, 89 in Loader Bucket, 24 in Backhoe Digging Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 41 Hr	36	2014 John Deere 310SK 4x4 Backhoe Loader S/N: 1T0310SKAEE263368 C/W: Open Operator Station, 90 in Loader Bucket, 16 in Backhoe Digging Bucket Usage: 2,948 Hr Asset located in: Lake Worth, TX	
	Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS	37	2012 John Deere 310SJ 4x4 Backhoe Loader	
29	Asset located in: Lake Worth, TX  2018 Cat 415F2 IL Backhoe Loader S/N: 0PF400836 Usage: 2,538 Hr Asset located in: Lake Worth, TX	37	S/N: 1T0310SJABD210971 C/W: Enclosed Cab, Air Conditioner, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 92 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,804 Hr	
30	2017 Cat 415F2 4x4 Backhoe Loader S/N: CAT0415FCHWA00473 C/W: Open Operator Station, 88 in Loader Bucket, Extendable Stick, 22 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 2,258 Hr		ITEM AT OFFSITE LOCATION MUS PICKED UP BY DECEMBER 31ST OF SUBJECT TO 3RD PARTY STORAGE	
	Asset located in: Lake Worth, TX	38	2016 Case 580N 4x4 Backhoe Loader	
31	2016 John Deere 410L 4x4 Backhoe Loader S/N: 1T0410LXPGF298786 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, 94 in Loader Bucket, 25 in Backhoe Digging Bucket		S/N: JJGN580NJFC717602 C/W: Open Operator Station, 83 in Load Bucket, 24 in Backhoe Digging Bucket Usage: 4,827 Hr Asset located in: Lake Worth, TX	C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,827 Hr
	Usage: 7,966 Hr  Asset located in: Lake Worth, TX	39	<b>2014 Case 580 Super N 4x4 Backhoe Loader</b> S/N: JJGN58SNAEC705935	
32	2012 John Deere 410K 4x4 Backhoe Loader S/N: 1T0410KXKCE223394 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Extendable Stick, Quick Coupler, 24 in Backhoe Digging Bucket, Rear			C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Backhoe Pilot Controls, Control Pattern Changer, 2014 US EPA Label, 82 in Loader Bucket, Extendable Stick, 23 in Backhoe Digging Bucket Usage: 3,941 Hr Asset located in: Lake Worth, TX
	Auxiliary Hydraulics Usage: Not Available	40	2013 Case 580N 4x4 Backhoe Loader S/N: JJGN580NLDC581006 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 82 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,697 Hr Asset located in: Lake Worth, TX	
33	Asset located in: Midland, TX  2018 John Deere 310L EP 4x2 Backhoe Loader S/N: 1T0310ELEJG337511 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 3,151 Hr Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
41	2018 JCB 3CX 4x4 Backhoe Loader S/N: JCB3CXTTCJ2667099 C/W: Open Operator Station, 2018 US EPA Label, 86 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 1,433 Hr	49	2003 Case 580M 4x4 Backhoe Loader S/N: JJG0312663 C/W: Open Operator Station, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,258 Hr Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	49A	2018 Case 580SN 4x2 Backhoe Loader
42	2012 New Holland B95C 4x4 Backhoe Loader S/N: FNH0B95CNCHH02653 C/W: Open Operator Station, 88 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 2,544 Hr		S/N: JJGN58SNPJC75003 C/W: Open Operator Station, 81 in, Quick Coupler Usage: 2,055 Hr <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	49B	2018 Case 580SN 4x2 Backhoe Loader
43	2005 Cat 430D 4x4 Backhoe Loader S/N: CAT0430DKBML05163 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Hydraulic Coupler, 92 in Loader Bucket, 24 in Backhoe Cleanup Bucket Usage: 7,018 Hr Asset located in: Lake Worth, TX	496	S/N: JGN58SNCJC753046 C/W: Open Operator Station, Backhoe Pilot Controls, 81 in Loader Bucket, Quick Coupler, 30 in Backhoe Digging Bucket Usage: 3,537 Hr <b>Asset located in</b> : Lake Worth, TX
44	2005 Cat 420D 4x4 Backhoe Loader S/N: CAT0420DJFDP23675 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, 89 in Loader Bucket, 26 in Backhoe Digging Bucket	50	2006 Cat 416E 4x2 Backhoe Loader S/N: CAT0416EVSHA00900 C/W: Open Operator Station, Air Ride Seat, 89 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 12,955 Hr Asset located in: Lake Worth, TX
	Usage: 5,495 Hr	51	2008 John Deere 310J Backhoe Loader
45	5 2008 John Deere 310SJ 4x4 Backhoe Loader S/N: T0310SJ156742 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Backhoe Pilot Controls, Control Pattern Changer, Powershift Transmission, Tier 2,		S/N: T0310JX159493 C/W: Open Operator Station, Manual Coupler, 84 in Loader Bucket Usage: 2,804 Hr Asset located in: Lake Worth, TX
		53	2005 Case 590 Super M 4x2 Backhoe Loader S/N: N5C394910 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 93 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 4,876 Hr Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	<del>                                     </del>	
46	2005 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX945350 C/W: Enclosed Cab, Air Conditioner, 86 in Loader Bucket, 18 in Backhoe Digging Bucket Usage: 7,887 Hr Asset located in: Lake Worth, TX	54	2004 Case 580M 4x2 Backhoe Loader S/N: N4C303573 C/W: Open Operator Station, 2004 US EPA Label, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,191 Hr
47	2001 John Deere 310G 4x4 Backhoe Loader		Asset located in: Lake Worth, TX
	S/N: T0310GX895009 C/W: Open Operator Station, 2000 US EPA Label, 84 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 7,556 Hr <b>Asset located in</b> : Lake Worth, TX	55	2016 Kubota L47TLB 4x4 Backhoe Loader S/N: 50136 C/W: Open Operator Station, Manual Coupler, 71 in Loader Bucket, 11 in Backhoe Digging Bucket Usage: 671 Hr
48	2008 Case 580 Super M Series 3 4x4 Backhoe Loader S/N: N8C504007 C/W: Enclosed Cab, 82 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 9,616 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
56	2019 John Deere 844K-III Wheel Loader S/N: 1DW844KACJF692631 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Loadrite On-Board Scale, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9.3 cyd 144 in Bucket, Auto Lube, 875/65R29 Tires Usage: 9,476 Hr Asset located in: Lake Worth, TX	64	2019 Cat 950 M Wheel Loader S/N: CAT0950MVJ1S02214 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 116 in Bucket, Auto Lube, 23.5R25 Tires Usage: 9,296 Hr Asset located in: Lake Worth, TX
57	2015 Cat 980M High Lift Wheel Loader		
	S/N: LKRS00731 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Joystick Steering, loadrite On-Board Scale, Manual Coupler, 7.5 cyd 135 in Bucket, 29.5R25 Tires Usage: 20,599 Hr Asset located in: Lake Worth, TX	65	E OF 2 - Lot #'s: 65, 66  2017 Cat 950MZ Wheel Loader S/N: CAT0950MCHE810302 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label,
58	2018 Case 1121G Wheel Loader S/N: JEEN1121KJF246039 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Joystick Steering, 6.1 cyd 126 in		Requires Diesel Exhaust Fluid, 3.40 m3 117 in Bucket, 23.5R25 Tires Usage: 6,932 Hr <b>Asset located in</b> : Lake Worth, TX
	Bucket, 26.5R25 Tires Usage: 6,569 Hr <b>Asset located in</b> : Lake Worth, TX	66	2016 Cat 950M Wheel Loader S/N: CAT0950MKEMB02486 C/W: Enclosed Cab, Air Conditioner, Rear View
59	2022 Komatsu WA475-10 Wheel Loader S/N: KMTWA142VNNA40104 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4.4 m3 124 in Bucket, Auto Lube, 26.5-25 Tires Usage: 7,012 Hr Asset located in: Lake Worth, TX		Camera, Air Ride Seat, Ride Control, Autoshift, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 114 in Bucket, 23.5 R25 Tires, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,168 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located III. Lake Worth, TX		Asset located in: Humble, TX
CHOIC 61	CHOICE OF 2 - Lot #'s: 61, 9606A  2017 Cat 966M Wheel Loader S/N: CAT0966MPKJP02589 C/W: Enclosed Cab, Air Conditioner, Ride		2014 Cat 950 K Wheel Loader S/N: CAT0950KTR4A02440 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Traction Control, 2017 US EPA Label, 118 in Bucket, 23.5-25 Tires Usage: 20,054 Hr Asset located in: Lake Worth, TX
	Control, Joystick Steering, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 26.5-25 Tires, Auxiliary Hydraulics, Pipe Grapple Usage: 4,818 Hr Asset located in: Bridgeport, NJ	68	2011 Cat 950 H High Lift Wheel Loader S/N: CAT0950HEJAD00705 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 114 in Bucket, 23.5
62	<b>2021 Cat 950GC Wheel Loader</b> S/N: CAT00950TM5T04416 C/W: Enclosed Cab, Air Conditioner, Rear View		R25 Tires Usage: 23,037 Hr <b>Asset located in</b> : Lake Worth, TX
<del></del>	Camera, 23.5-25 Tires, 4.5 cyd 114 in Bucket Usage: 1,455 Hr <b>Asset located in</b> : Baton Rouge, LA	69	2013 Komatsu WA380-7 Wheel Loader S/N: KMYWA118L36A64146 Usage: Not Available Asset located in: Lake Worth, TX
63	2020 Cat 950GC Wheel Loader S/N: CAT00950AM5T03307 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 3.30 m3 116 in Bucket, 23.5-25 Tires Usage: 4,902 Hr Asset located in: Lake Worth, TX	70	2018 Volvo L110H Wheel Loader S/N: VCEL110HT0S631498 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 118 in Bucket, Forks, 23.5R25 Tires Usage: 6,898 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
70A	2011 Volvo L110F Wheel Loader (Inoperable) S/N: VCEL110FP00005039 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	78	2016 Cat 938M Wheel Loader S/N: CAT0938MTJ3R02448 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 106 in Bucket, 20.5R25 Tires Usage: 19,902 Hr Asset located in: Lake Worth, TX
71	2023 John Deere 644P Wheel Loader S/N: 1DW644PAVPLZ17531 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 23.5R25 Tires, Hydraulic Coupler, 4 cyd 120 in Bucket	79 79A	2014 Cat 938K Wheel Loader S/N: CAT0938KPSWL02223 C/W: Enclosed Cab, Rear View Camera, 2013 US EPA Label, 20.5R25 Tires Usage: 21,033 Hr Asset located in: Lake Worth, TX 2018 Case 621G Wheel Loader
CHOIC	Usage: 3,296 Hr Asset located in: St. Rose, LA  E OF 2 - Lot #'s: 73, 74		S/N: JEEN0621HJF243666 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 102 in Bucket, 20.5x25 Tires Usage: 5,236 Hr Asset located in: Lake Worth, TX
73	2014 John Deere 644 K Wheel Loader S/N: 1DW644KZLED661608 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2014 US EPA Label, Forks, 23.5R25 Tires Usage: 15,623 Hr	CHOIC	E OF 1 - Lot #'s: 81  2020 Hyundai HL955 Wheel Loader
74	Asset located in: Lake Worth, TX  2013 John Deere 644 K Wheel Loader S/N: 1DW644KZKCE650141 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, 102 in Bucket, 23.5 R25 Tires Usage: 16,918 Hr Asset located in: Lake Worth, TX		S/N: HHKHW500AL0000844 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 4,328 Hr Notes:
75	2021 LiuGong CLG848H Wheel Loader S/N: CLG848HZJML691727 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 3 cyd 115 in Bucket, Forks, 20.5R25 Tires Usage: 2,486 Hr Asset located in: Lake Worth, TX	82	Asset located in: Lake Worth, TX  2023 John Deere 544P Wheel Loader  S/N: 1DW544PALPLX19742  C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 20.5R25  Tires, Auxiliary Hydraulics, Hydraulic Coupler, 3.5 cyd 106 in Bucket Usage: 1,546 Hr
76	2019 Volvo L90H Wheel Loader S/N: VCEOL90HL0S624993 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 6,927 Hr Asset located in: Lake Worth, TX	85	Asset located in: Greenville, TX  2007 John Deere 544J Wheel Loader S/N: DW544JZ610127 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, Traction Control, 2006 US EPA Label, CARB Compliant, 3.0 cyd 103 in Bucket, 20.5R25 Tires Usage: 7,496 Hr Asset located in: Midland, TX
77	2015 Volvo L90G Wheel Loader S/N: VCE0L90GT0S617667 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 12,859 Hr Asset located in: Lake Worth, TX	87	2020 Hitachi ZW180-6 Wheel Loader S/N: RYUPD860CH8405515 C/W: Enclosed Cab, Air Conditioner, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 104 in Bucket, 23.5R25 Tires Usage: 12,123 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 88, 89		СНОІСІ	E OF 2 - Lot #'s: 95, 96
88	2015 Cat 930M Wheel Loader S/N: CAT0930MKKTG00791 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 11,259 Hr	95	2014 Komatsu WA270-7 Wheel Loader S/N: KMTWA122C01080092 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Ride Control, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, 20.5R25 Tires Usage: 8,531 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	96	2013 Komatsu WA270-7 Wheel Loader
89	2014 Cat 930K Wheel Loader S/N: CAT0930KTRHN03712 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 101 in Bucket, Forks, 20.5 R25 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 10,745 Hr	Camera, 2013 US EPA Label, Hydraulic	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Hydraulic Coupler, 104 in Bucket, 60 in Forks, Auto Lube, 20.5R25 Tires Usage: 11,558 Hr
	Asset located in: Livingston, LA	Сноісі	E OF 2 - Lot #'s: 97, 98
90	2012 Cat 930K Wheel Loader S/N: CAT0930KHRHN00708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 110 in Bucket, Forks, 20.5R25 Tires	97	2014 Cat 924K Wheel Loader S/N: CAT0924KJPWR03464 Usage: Not Available
	Usage: 12,980 Hr <b>Asset located in</b> : Lake Worth, TX	00	Asset located in: Lake Worth, TX
91	2012 Cat 930H Wheel Loader S/N: CAT0930HEDHC03679 C/W: Enclosed Cab, Air Ride Seat, Auxiliary Hydraulics, Hydraulic Coupler, 101 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 12,460 Hr	98	2013 Cat 924K Wheel Loader S/N: CAT0924KLPWR01641 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Hydraulic Coupler, 108 in Bucket, Forks, 20.5R25 Tires Usage: 8,775 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	99	2012 Volvo L60G Wheel Loader
92	2012 Volvo L70G Wheel Loader S/N: VCE0L70GC00002431 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 33,042 Hr Asset located in: Lake Worth, TX		S/N: VCE0L60GH00001263 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Autoshift, 2012 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 104 in Bucket, 20.5R25 Tires Usage: 11,335 Hr Asset located in: Lake Worth, TX
03		100	2014 Cat IT14G2 Wheel Loader
93	2017 Komatsu WA320-8 Wheel Loader S/N: KMTWA135JHA085240 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 108 in Bucket, 20.5R25 Tires Usage: 15,207 Hr Asset located in: Lake Worth, TX		S/N: CATIT14GLERP00499 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.40 m3 94 in Bucket, Forks, 17.5-25 Tires Usage: 2,976 Hr Asset located in: Lake Worth, TX
		101	2022 Bobcat L85 Wheel Loader S/N: B53C11128 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 405/70R18 Tires Usage: 1,595 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
102	2023 Cat 910 Wheel Loader (Unused) S/N: CAT00910KJW201852 Usage: 5 Hr Asset located in: Lake Worth, TX	110	1990 Cat 980C Wheel Loader S/N: 63X09341 C/W: Enclosed Cab, Air Conditioner, 29.5R25 Tires Usage: Not Available
103	2018 Cat 908M Wheel Loader S/N: CAT0908MEH8803041 C/W: Enclosed Cab, Air Conditioner, 78 in Grapple Bucket, Solid Tires Usage: 10,102 Mi		Asset located in: Lake Worth, TX
		111	<b>2000 Cat 966G Wheel Loader</b> S/N: 3SW00657 Usage: 23,326 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
104	2022 Cat 907M Wheel Loader S/N: CAT0907MKK5700489 Usage: 600 Hr Asset located in: Lake Worth, TX	112	2000 Cat 938G Wheel Loader S/N: 4YS01303 C/W: Enclosed Cab, Air Conditioner, 2000 US EPA Label, 110 in Bucket, Forks, 20.5R25 Tires Usage: 12,027 Hr
			Asset located in: Lake Worth, TX
105	HOICE OF 2 - Lot #'s: 105, 106  2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906HHZ600672 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, 2023 US EPA Label,	113	1985 Cat 966D Wheel Loader S/N: 99Y04055 C/W: Enclosed Cab, Manual Coupler, Forks, 26.5-25 Tires Usage: 5,678 Hr Asset located in: Lake Worth, TX
	Hydraulic Coupler, 70 in Forks, 405/70R18 Tires, 25 MPH Machine Usage: 27 Hr <b>Asset located in</b> : Lake Worth, TX	114	1989 Cat 950 E Wheel Loader S/N: 22Z04456 C/W: Open Operator Station, Hydraulic Coupl
106	2023 Cat 906 Wheel Loader (Unused) S/N: CAT00906CHZ601041 C/W: Enclosed Cab, Air Conditioner, Air Ride		110 in Bucket, Forks, 23.5-25 Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,198 Hr  Asset located in: Lake Worth, TX
	Seat, Ride Control, 2023 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 74 in Bucket, Forks, 405/70R18 Tires, 25 MPH Machine Usage: 3 Hr <b>Asset located in</b> : Lake Worth, TX	114A	1998 Cat IT28G High Lift Wheel Loader S/N: 8CR01014 C/W: Enclosed Cab, Air Conditioner, Ride Control, Auxiliary Hydraulics, 100 in, 20.5-25 Tires Usage: 18,294 Hr
107	2017 Cat 906M Wheel Loader		Asset located in: Lake Worth, TX
	S/N: CAT0906MKH6602101 C/W: Open Operator Station, 2011 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 1.6 cyd 82 in Bucket, 340/80R18 Tires Usage: 3,249 Hr Asset located in: Midland, TX	115	1998 Case 621B Wheel Loader S/N: JEE0055157 C/W: Enclosed Cab, Air Conditioner, 1997 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: Not Available
108	2006 Volvo L110E Wheel Loader		Asset located in: Lake Worth, TX
	S/N: L110EV61151 C/W: Enclosed Cab, 2006 US EPA Label, Hydraulic Coupler, 112 in Bucket, 23.5R25 Tires Usage: 9,676 Hr <b>Asset located in</b> : Lake Worth, TX	117	2016 Cat 14M Motor Grader S/N: R9J01751 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available
109	2005 Cat 924G Wheel Loader		Asset located in: Humble, TX
	S/N: CAT0924GJDDA02066 C/W: Enclosed Cab, Air Conditioner, Autoshift, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, 20.5R25 Tires Usage: 14,142 Hr Asset located in: Lake Worth, TX	118	2015 Cat 14M Motor Grader S/N: R9J01362 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
119	2012 Cat 14M Motor Grader S/N: R9J00660 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	125	S/N: CAT0140MJN9D00717 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2016 US EPA Label, Requires
120	2011 Cat 14M Motor Grader S/N: R9J00286 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available		Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires Usage: 10,845 Hr  Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	126	<b>2016 Cat 140M3 Motor Grader</b> S/N: CAT0140MHN9M00322
121	2009 Cat 14M Motor Grader S/N: B9J00952 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Ripper, 17.5R25 Tires, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 9,287 Hr Asset located in: Lake Worth, TX
122	2008 Cat 14M Motor Grader S/N: B9J00654 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	127	2015 Cat 140M3 Motor Grader S/N: CAT0140MLN9D00447 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for
123	2011 John Deere 872GP AWD Motor Grader S/N: 1DW872GPCBE636116 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 2011 US EPA Label, 16	128	Grade Control, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper /Scarifier, 17.5R25 Tires Usage: 5,571 Hr <b>Asset located in</b> : Lake Worth, TX
	ft / 4.88 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 7,669 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL		2015 Cat 140M3 Motor Grader  S/N: CAT0140MQN9D00463  C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Pre- Wired for Grade Control, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper /Scarifier, Rear Auxiliary Hydraulics, 17.5R25 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 11,666 Hr Asset located in: Lake Worth, TX
	SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD	СНОІС	E OF 2 - Lot #'s: 129, 130
	Asset located in: Lake Worth, TX	129	2013 Cat 140M2 Motor Grader
124	2019 Cat 140M3 Motor Grader S/N: CAT0140MKN9D01607 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 6,884 Hr Asset located in: Lake Worth, TX		S/N: M9J00716 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
		130	2012 Cat 140M2 Motor Grader S/N: M9J00680 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
131	2012 Cat 140M2 VHP Plus Motor Grader S/N: CAT0140MAM9D01207 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, Pre-Wired for Grade Control, 2012 US EPA Label, 14 ft / 4.27 m Moldboard, Push Block, Accumulators,	138	2007 Cat 140H Motor Grader S/N: CCA03626 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
	Combination Ripper/Scarifier, 17.5R25 Tires Usage: 8,784 Hr  Asset located in: Lake Worth, TX	139	<b>2012 Case 865B Motor Grader</b> S/N: HBZN0865TCAF01360 C/W: Enclosed Cab, Air Conditioner, 14 ft /
132	2011 Cat 140M2 VHP Plus Motor Grader S/N: M9D00692 C/W: Enclosed Cab, Air Conditioner, Low		4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 2,653 Hr <b>Asset located in</b> : Lake Worth, TX
	Profile, Air Ride Seat, Joystick Steering, Rear View Camera, Differential Lock, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 14.00-24 Tires, Topcon GX-60 Display, Topcon 3D MC-R3 Radio Receiver, Topcon MC2 Sensors with Masts Usage: 9,083 Hr	140	2013 LeeBoy 785 Motor Grader S/N: 413760-141 C/W: Enclosed Cab, Front Scarifier, 15.5-25 Tires Usage: 3,051 Hr Asset located in: Lake Worth, TX
133	Asset located in: Lake Worth, TX  2015 John Deere 772GP AWD Motor Grader S/N: 1DW772GPLFF667809 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 14 ft / 4.27 m Moldboard, Push Block,	141	1993 Cat 12G Motor Grader S/N: 61M15367 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
	Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,172 Hr <b>Asset located in</b> : Lake Worth, TX		1991 Cat 120G Motor Grader S/N: 87V09411 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, 14.00-24 Tires Usage: Not Available
134	2019 John Deere 672G Motor Grader S/N: 1DW672GXCKF693988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Rear View Camera, Differential Lock, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 5,387 Hr Asset located in: Lake Worth, TX	142A	Asset located in: Lake Worth, TX  1991 Champion 740A Motor Grader S/N: 21849 C/W: Enclosed Cab, 1991 US EPA Label, 14 ft / 4.27 m Moldboard, Front Auxiliary Hydraulics, 14.00R24 Tires Usage: 4,668 Hr
135	2015 John Deere 672G AWD Motor Grader S/N: 1DW672GXHEF665845 C/W: Enclosed Cab, Air Conditioner, Low Profile, Air Ride Seat, Differential Lock, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 6,673 Hr Asset located in: Lake Worth, TX	143	Asset located in: Lake Worth, TX  2022 John Deere 460E-II Articulated Dump Truck S/N: 1DW460EBJNF713715 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Tailgate, 29.5R25 Tires Usage: 4,497 Hr Asset located in: Lake Worth, TX
136	2013 John Deere 672GP AWD Motor Grader S/N: 1DW672GPHDE651559 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Accumulators, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 7,517 Hr Asset located in: Lake Worth, TX	144	E OF 2 - Lot #'s: 144, 145  2020 Cat 745 Articulated Dump Truck S/N: CAT00745P3T602347 C/W: Air Conditioner, Rear View Camera, Air
137	2012 John Deere 672G AWD Motor Grader S/N: 1DW672GPKCE643998 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5R25 Tires Usage: 12,634 Hr Asset located in: Lake Worth, TX		Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 5,300 Hr <b>Asset located in</b> : Humble, TX

Lot #	Details	Lot #	Details
145	2018 Cat 745 Articulated Dump Truck S/N: CAT00745V3T600426 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2017 US EPA Label, Tailgate, Steel Body Liner, Auto Lube, 29.5R25 Tires Usage: 6,080 Hr Asset located in: Humble, TX	152	2021 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016LMD011997 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,708 Hr Asset located in: Lake Worth, TX
CHOIC	CHOICE OF 3 - Lot #'s: 146, 147, 148		2022 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016KMD012141
146	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CVTFK00176		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Retarder, Engine Brake, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, 29.5R25 Tires Usage: 14,026 Hr Asset located in: Lake Worth, TX	153	2017 Bell B40E Articulated Dump Truck S/N: B93A640EJ01105751 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29.5R25 Tires
147	2015 Cat 745C Articulated Dump Truck		Usage: 7,600 Hr  Asset located in: Humble, TX
	S/N: TFK00437 C/W: 29.5R25 Tires Usage: 13,799 Hr <b>Asset located in</b> : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 154, 155
148	2015 Cat 745C Articulated Dump Truck S/N: TFK00280 Usage: Not Available Asset located in: Lake Worth, TX	 154	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BHT4R01959 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2013 US EPA Label, 29.5R25 Tires
149	2017 Bell B50E Articulated Dump Truck S/N: B93A650EA01105727		Usage: 10,492 Hr <b>Asset located in</b> : Lake Worth, TX
	C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, Steel Body Liner, 875 /65R29 Tires Usage: 9,289 Hr Asset located in: Lake Worth, TX	155	2013 Cat 740B Articulated Dump Truck S/N: CAT0740BKT4R01967 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, 2017 US EPA Label, CARB Compliant, 29.5R25 Tires Usage: 10,336 Hr
CHOIC	E OF 3 - Lot #'s: 150, 151, 152		Asset located in: Lake Worth, TX
150	2022 Komatsu HM400-5 Articulated Dump Truck	СНОІС	E OF 4 - Lot #'s: 156, 157, 158, 159
	S/N: KMTHM016JMD012108 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 4,566 Hr Asset located in: Lake Worth, TX	156	2015 Terex TA300 Articulated Dump Truck S/N: A11861079 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner, 23.5R25 Tires Usage: 7,974 Hr
151	2021 Komatsu HM400-5 Articulated Dump		Asset located in: Lake Worth, TX
	Truck S/N: KMTHM016HMD011998 C/W: Air Conditioner, Engine Brake, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, 29.5R25 Tires Usage: 4,217 Hr Asset located in: Lake Worth, TX	157	2015 Terex TA300 Articulated Dump Truck S/N: A11861065 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Steel Body Liner, 23.5R25 Tires Usage: 8,896 Hr Asset located in: Lake Worth, TX
		158	2014 Terex TA300 Articulated Dump Truck S/N: A11001282 C/W: Air Conditioner, Retarder, Rear View Camera, Steel Body Liner, 23.5R25 Tires Usage: 8,693 Hr

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
159	2014 Terex TA300 Articulated Dump Truck S/N: A11001278 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 23.5R25 Tires Usage: 8,343 Hr Asset located in: Lake Worth, TX	CHOIC	E OF 2 - Lot #'s: 169, 170  2006 Cat 621G Elevating Motor Scraper S/N: CAT0621GPDBB00312
160	2007 Terex TA30 Articulated Dump Truck S/N: A8941541 C/W: Air Conditioner, 23.5R25 Tires Usage: 43,274 Mi		C/W: Enclosed Cab, Air Conditioner, 33.25R29 Tires Usage: 175,403 Hr <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	170	2006 Cat 621G Motor Scraper
161	2006 Terex TA27 Articulated Dump Truck S/N: A8681159 C/W: Air Conditioner, Steel Body Liner, 23.5R25 Tires	171	S/N: CAT0621GTDBB00311 Usage: 18,091 Hr Asset located in: Lake Worth, TX 2004 Cat 615C Series II Motor Scraper
	Usage: 5,855 Hr <b>Asset located in</b> : Lake Worth, TX		S/N: CAT0615CE9XG01708 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 29.5R29 Tires
162	<b>2019 John Deere 260E Articulated Dump Truck</b> S/N: 1DW260ETCKF697666 C/W: Air Conditioner, Retarder, Rear View		Usage: 7,020 Hr  Asset located in: Lake Worth, TX
	Camera, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Heated Body, Tailgate, 23.5R25 Tires Usage: 4,508 Hr  Asset located in: Lake Worth, TX	172	1998 Cat 615C Series II Motor Scraper S/N: 09XG01112 Usage: Not Available Asset located in: Lake Worth, TX
163	2007 John Deere 250D Articulated Dump Truck S/N: DW250DT611160 Usage: 60,390 Mi Asset located in: Lake Worth, TX	173	2016 John Deere 9620R Articulated Tractor S/N: 1RW9620RPGE052942 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse e18 PowerShift, Autosteer, 2016 US EPA Lab
164	2007 Cat 725 Articulated Dump Truck S/N: CAT00725HB1L01150 C/W: Air Conditioner, 2007 US EPA Label, Tailgate, 23.5R25 Tires Usage: 9,403 Hr		Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, 6 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Rear Wheel Weights Usage: 5,943 Hr  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	175	2016 John Deere 9570R Articulated Tractor
165	2007 Cat 735 Articulated Dump Truck S/N: CAT00735AB1N01005 C/W: Air Conditioner, Retarder, Steel Body Liner, 26.5R25 Tires Usage: 22,553 Hr Asset located in: Lake Worth, TX		S/N: 1RW9570RCGP052988 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, Autosteer, Requires Diesel Exhaust Fluid, Grouser 16 ft 2 in Silage Blade, LED Lights, 5 Rear Remotes, Auxiliary Hydraulics, ISOBUS, Dual IF800/70R38 Tires,
166	Cat D35C Articulated Dump Truck S/N: Not Available		Rear Wheel Weights, Front Wheel Weights Usage: 7,520 Hr <b>Asset located in</b> : Lake Worth, TX
	C/W: Air Conditioner, Air Ride Seat, 26.5R25 Tires Usage: 9,124 Hr <b>Asset located in</b> : Lake Worth, TX	176 2 S S S S S S S S S S S S S S S S S S S	2014 Case IH Steiger 580S Scraper Tractor S/N: ZEF300648 C/W: Enclosed Cab, Air Conditioner, Air Ride
167	Cat D250E Articulated Dump Truck S/N: 5TN01384 C/W: Air Conditioner, 23.5R25 Tires Usage: 13,304 Hr Asset located in: Lake Worth, TX		Seat, Differential Lock, 16 Forward 2 Reverse, Requires Diesel Exhaust Fluid, 6 Rear Remotes ISOBUS, Scraper Hitch, Dual 710/70R42 Front Tires, Front Wheel Weights, Dual 710/70R42 Rear Tires Usage: 3,479 Hr Notes: FEBRUARY 2023 - COMPLETE DEALER
168	2017 Cat 631K Motor Scraper S/N: CAT0631KVWTR00117 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 37.25R35 Tires Usage: 8,898 Hr Asset located in: Midland, TX		INSTALLED LONG BLOCK ENGINE; UNIT WARPULLING K-TEC 1233 SCRAPER - ALSO IN TAUCTION LOT 176; NEW PTO DRIVEN WAT PUMP; NEW BOOM HOSES AND CLAMPS  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
177	2017 MTS MT42LGP 4 Tire Hydraulic Pull Scraper S/N: MT42LGP00287 C/W: 29.5R29, Rear Hydraulic Outlets Usage: Not Available Asset located in: Lake Worth, TX 2015 K-TEC 1233 4 Tire Ejector Pull Scraper S/N: KS2538 C/W: 33 cyd Capacity, Lead Scraper, 26.5R25 Tires, Rear Hydraulic Outlets	186	2023 Cat D6 LGP Crawler Dozer  S/N: CAT000D6LRDC01363  C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 156 in Wide PAT Blade, 36 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 627 Hr  Notes: EMISSIONS SYSTEM WARRANTY
	Usage: Not Available Notes: UNIT WAS BEING PULLED BY CASE		THROUGH NOVEMBER 2028 OR 3000 HOURS  Asset located in: Lake Worth, TX
	STEIGER 580S - ALSO IN AUCTION LOT 178; NEW PTO DRIVEN WATER PUMP; NEW BOOM HOSES AND CLAMPS Asset located in: Lake Worth, TX	187	2022 Cat D6 XE Crawler Dozer S/N: CAT000D6KD5M01006 C/W: Enclosed Cab, Air Conditioner, Air Ride
179	1994 Cat 621F 4x4 Water Wagon S/N: 4SK00164 C/W: Enclosed Cab, Air Conditioner, In-Cab Remote Controlled Water Cannon, Rear Spray, Side Spray, 83.25-29 Tires Usage: 8,377 Hr		Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 144 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 811 Hr Asset located in: Lake Worth, TX
 181	Asset located in: Lake Worth, TX  2023 Cat D8 Crawler Dozer	188	E OF 2 - Lot #'s: 188, 189
	S/N: CAT000D8AAW800429 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 153 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper w/Hydraulic Pin Puller Usage: 1,311 Hr Asset located in: Lake Worth, TX		2022 Cat D6 XL Crawler Dozer  S/N: CAT000D6CRBP01052  C/W: Enclosed Cab, Air Conditioner, Pre-Wire for Grade Control, 144 in Wide PAT Blade, 24  Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION
182	2012 Cat D8T Crawler Dozer S/N: CAT00D8TKMLN01612 Usage: Not Available Asset located in: Lake Worth, TX		Usage: 1,172 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX
183	2010 Cat D8T Crawler Dozer  S/N: KPZ03583  C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE  Usage: Not Available  Asset located in: Humble, TX	189	2022 Cat D6 XL Crawler Dozer  S/N: CAT000D6TRBP01067  C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps 137 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper,
184	2008 Cat D8T Crawler Dozer S/N: KPZ03026 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,538 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JULY 2027 OR 3000 HOURS Asset located in: Lake Worth, TX
185	2006 Cat D7R LGP Series II Crawler Dozer S/N: CAT00D7RLABJ01502 C/W: 192 in Wide Angle Blade	сноіс	E OF 3 - Lot #'s: 190, 191, 192
	Usage: 7,903 Hr  Asset located in: Lake Worth, TX	190	2020 Cat D6 Crawler Dozer  S/N: CAT000D6ESA900371  C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide Semi-U Blade w/ Single Tilt, 23 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 2,769 Hr  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
191	2020 Cat D6 Crawler Dozer  S/N: CAT000D6CSA900372  C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 3,462 Hr Asset located in: Bridgeport, NJ	197	2018 Cat D6T XL Crawler Dozer  S/N: CAT00D6TCNDY00387  C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION
192	2019 Cat D6 Crawler Dozer S/N: CAT000D6KHNK00387 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, GRADE with 3D, 2019 US EPA Label,		Usage: 3,768 Hr Notes: NEW RAILS, TRACK PADS, SPROCKET SEGMENTS, AND TOP ROLLERS INTALLED DECEMBER 3RD 2024 Asset located in: Lake Worth, TX
193	Requires Diesel Exhaust Fluid, 130 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes Usage: 4,017 Hr  Asset located in: North East, MD  2019 Cat D6T XW Crawler Dozer	198	2018 Cat D6T XW Crawler Dozer S/N: CAT00D6TVJNM00416 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 163 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper
170	S/N: CAT00D6TEJNM00566		Usage: 8,360 Hr <b>Asset located in</b> : Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 160 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,211 Hr	200	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TCDTD01184 C/W: Enclosed Cab, Air Conditioner, Sweeps, 150 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 4,275 Hr
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
194	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6TCNDY00513 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, US EPA Label, Requires Diesel Exhaust Fluid, 125 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 4,082 Hr	201	2013 Cat D6T XL Crawler Dozer S/N: CAT00D6TAGMK01351 C/W: Enclosed Cab, Air Conditioner, Sweeps, 127 in Wide Semi-U Blade w/ Single Tilt, 22 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 8,504 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	202	2012 Cat D6T XL Crawler Dozer
195	2019 Cat D6T XL Crawler Dozer S/N: CAT00D6THHYT00409 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 152 in Wide PAT Blade, 22 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 4,693 Hr		S/N: CAT00D6TCDTD00253 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Sweeps, 152 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,059 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	203	2011 Cat D6T XL Crawler Dozer
196	2018 Cat D6T XL Crawler Dozer S/N: CAT00D6TJ2B300199 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,831 Hr Asset located in: Lake Worth, TX		S/N: CAT00D6TCGMK00352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2011 US EPA Label, Sweeps, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,782 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
204	2023 Cat D5 LGP Crawler Dozer  S/N: CAT000D5KZ6A01796  C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 160 in Wide PAT Blade, 33 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 878 Hr  Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH APRIL 2026 OR 5,000 HOURS	211212213	S/N: DJY01194 C/W: Open Operator Station, 2008 US EPA Label, 160 in Wide PAT Blade, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,289 Hr Asset located in: Lake Worth, TX	C/W: Open Operator Station, 2008 US EPA Label, 160 in Wide PAT Blade, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,289 Hr Asset located in: Lake Worth, TX 2007 Cat D6R XL Series III Crawler Dozer
205	Asset located in: Lake Worth, TX  2022 Cat D5 Crawler Dozer  S/N: CAT000D5AZ2K01218  C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 127 in Wide PAT Blade, 22.5 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper		S/N: CAT00D6RCGJB00986 C/W: Enclosed Cab, Air Conditioner, 126 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,162 Hr Asset located in: Lake Worth, TX	
	Usage: 1,409 Hr <b>Asset located in</b> : Lake Worth, TX		2014 Komatsu D155AX-7 Crawler Dozer S/N: KMT0D118L02090176 C/W: Enclosed Cab, Air Conditioner, Rear View	
206	2019 Cat D6N XL Crawler Dozer S/N: CAT00D6NENJN00388 C/W: Enclosed Cab, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 128 in Wide PAT Blade, 24 in Single Grouser Track 1204 Ltr		Camera, Pre-Wired for Grade Control, 2013 US EPA Label, 156 in Wide Sigmadozer w/ Dual Tilt, 2 Cylinder Single-Shank Ripper, Sweeps, 24 in Single Grouser Track Shoes Usage: 9,795 Hr Asset located in: Poteau, OK	
	Usage: 8,394 Hr  Asset located in: Lake Worth, TX		<b>2018 John Deere 950K LGP Crawler Dozer</b> S/N: 1T0950KPPJF332504	
207	2015 Cat D6N LGP Crawler Dozer  S/N: PBA02428  C/W: Enclosed Cab, Air Conditioner, 2014 US  EPA Label, Sweeps, 160 in Wide PAT Blade, 9 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 10,608 Hr		C/W: Enclosed Cab, Air Conditioner, Ai Seat, 2017 US EPA Label, Requires Die Exhaust Fluid, 185 in Wide PAT Blade,	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 185 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Carco Winch Usage: 5,936 Hr
	Asset located in: Livingston, LA	Сноіс	E OF 2 - Lot #'s: 214, 215	
208	2012 Cat D6N XL Crawler Dozer S/N: CAT00D6NALJR00640 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 132 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 10,669 Hr Asset located in: Lake Worth, TX  2011 Cat D6N XL Crawler Dozer	214	2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXJKF360852 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 194 in Wide Angle Blade w/ Dual Tilt, Carco Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 1,640 Hr Asset located in: Robstown, TX	
207	S/N: CAT00D6NELJR00562 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 126 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 18,107 Hr Asset located in: Lake Worth, TX	215	2019 John Deere 850L LGP Crawler Dozer S/N: 1T0850LXTKF359972 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 195 in Wide Straight Blade w/ Dual Tilt, Carco H85-178V Winch, Sweeps, 35.5 in Single Grouser Track Shoes Usage: 2,054 Hr Asset located in: Baytown, TX	

Lot #	Details	Lot #	Details
CHOIC 216	2019 Komatsu D65WX-18 Crawler Dozer S/N: KMT0D127PKA091866 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2019 US EPA Label,	221	2022 John Deere 750L Crawler Dozer S/N: 1T0750LXCNF415326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 155 in Wide PAT Blade, 28 in Single Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,349 Hr
	Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco Winch, 30 in Single Grouser Track		Asset located in: Lake Worth, TX
	Shoes, PLUS Undercarriage Usage: 1,389 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE	221A	2022 John Deere 750L Crawler Dozer S/N: 1T0750LXJNF417535 Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;  Asset located in: McAlester, OK	222	2019 John Deere 750K LGP Crawler Dozer S/N: 1T0750KXAKF365020 C/W: Enclosed Cab, Air Conditioner, 2010 US
217	2019 Komatsu D65WX-18 Crawler Dozer S/N: 91854 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Carco H85-178VKOMD65-17/18 Winch, 30 in Single Grouser Track Shoes Usage: 1,872 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK		EPA Label, Requires Diesel Exhaust Fluid, 154 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 5,330 Hr  Asset located in: Lake Worth, TX
		224	2017 John Deere 700K Crawler Dozer S/N: 1T0700KXCHF313276 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 2 Cylinder Multi-Shank Ripper, 560 mm Single Grouser Track Shoes Usage: 4,035 Hr
218	2018 Komatsu D65WX-18 Crawler Dozer S/N: 91248 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 153 in Wide PAT Blade, Allied H6H Winch, 30 in Single Grouser Track Shoes Usage: 2,060 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK
		225	2013 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KTRST00359 C/W: Enclosed Cab, Air Ride Seat, 2013 US EPA Label, 142 in Wide PAT Blade, 30 in Single Grouser Track Shoes Usage: 2,583 Hr Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES;  Asset located in: McAlester, OK	226	2012 Cat D6K XL Crawler Dozer
219	<b>2015 Komatsu D65WX-17 Crawler Dozer</b> S/N: KMT0D117E01002551		S/N: CAT00D6KHFBH02165 Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 159 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 13,875 Hr Asset located in: Lake Worth, TX	<b>227</b>	2022 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKCNF421869 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 27.5 in Single Grouser Track Shoes
220	2008 Komatsu D65EX-15E0 Crawler Dozer S/N: 70954 C/W: Enclosed Cab, Air Conditioner, 135 in Wide Semi-U Blade w/ Single Tilt, Winch, Sweeps, 24 in Single Grouser Track Shoes Usage: 6,584 Hr Asset located in: Poteau, OK		Usage: 1,047 Hr Asset located in: Beaumont, TX

	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 228, 229	234	2013 Komatsu D61PX-23 Crawler Dozer S/N: 30310 C/W: Enclosed Cab, Air Conditioner, Air Ride
228	2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKTMF401153 C/W: Open Operator Station, US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide 18 in Single Grouser Track Shoes Usage: 469 Hr		Seat, Pre-Wired for Grade Control, Tier 4, 2013 US EPA Label, 156 in Wide PAT Blade, Allied H6H Winch, 34 in Single Grouser Track Shoes Usage: 5,210 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE
	Asset located in: Lake Worth, TX		SUBJECT TO 3RD PARTY STORAGE FEES;
229	2021 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKPMF392830 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,549 Hr	235	Asset located in: McAlester, OK  2012 Cat D5K2 XL Crawler Dozer  S/N: CAT0D5K2VKWW00232  C/W: Open Operator Station, 2012 US EPA Label, 106 in Wide PAT Blade, 20 in Single Grouser Track Shoes Usage: 7,645 Hr  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	236	2016 Cat D5K2 LGP Crawler Dozer
230	2019 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKKKF349894 C/W: Enclosed Cab, Air Conditioner, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,283 Hr		S/N: CAT00D5KKKY202228 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 12,759 Hr
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
231	2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKAHF307207 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Rear Auxiliary Hydraulics Usage: 8,434 Hr	237	2012 Cat D5K2 LGP Crawler Dozer S/N: CAT0D5K2HKYY00309 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 125 in Wide PAT Blade, 26 in Single Grouser Track Shoes Usage: 9,847 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	238	2019 John Deere 450K LGP Crawler Dozer
CHOICE OF 2 - Lot #'s: 232, 233			S/N: 1T0450KXKKF347727 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 114 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 2,420 Hr
232	2017 John Deere 650KLGP Crawler Dozer		Asset located in: Humble, TX
	S/N: 1T0650KKTHF316190 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes,	239	2021 Cat D2 Crawler Dozer S/N: CAT000D2TXKM00230 Usage: Not Available Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-PULICE-CONSTRUCTION	240	2016 Cat D4K2 LGP Crawler Dozer
233	Usage: 7,369 Hr Asset located in: Humble, TX  2017 John Deere 650K LGP Crawler Dozer S/N: 1T0650KKHHF316153 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar, EQUIPMENT-FROM-PULICE-		S/N: CAT00D4KJKR202288 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 121 in Wide PAT Blade, 25 in Single Grouser Track Shoes, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 5,218 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT
	CONSTRUCTION Usage: 8,590 Hr Asset located in: Humble, TX		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
СНОІС	CHOICE OF 2 - Lot #'s: 241, 242		2004 Cat D5G LGP Crawler Dozer S/N: CAT00D5GARKG01013 C/W: Open Operator Station, Sweeps, 120 in Wide PAT Blade, 18 in Single Grouser Track
241	2012 Cat D4K2 XL Crawler Dozer S/N: CAT0D4K2CKMM00228 C/W: Open Operator Station, Air Ride Seat,		Shoes Usage: 5,087 Hr  Asset located in: Lake Worth, TX
	2012 US EPA Label, Sweeps, 114 in Wide PAT Blade, 18 in Single Grouser Track Shoes, SystemOne Undercarriage, 2 Cylinder Multi- Shank Ripper Usage: 3,515 Hr Asset located in: Lake Worth, TX	249	1996 Cat D6E Crawler Dozer S/N: 2MJ02195 C/W: Open Operator Station, 146 in Wide Straight Blade w/ Dual Tilt, Winch, 560 mm Single Grouser Track Shoes Usage: 10,574 Hr
242	2011 Cat D4K XL Crawler Dozer S/N: CAT00D4KHMMM00764 C/W: Open Operator Station, Air Ride Seat, 2015 US EPA Label, 109 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK
	Shank Ripper Usage: 2,915 Hr  Asset located in: Lake Worth, TX	250	1994 Cat D6E Tack Tractor S/N: 2MJ1574 C/W: Open Operator Station, 560 mm Single Grouser Track Shoes, (2) Lincoln Arc Welders,
243	2008 Cat D4K XL Crawler Dozer S/N: CAT00D4KLMMM00181 C/W: Open Operator Station, Air Ride Seat, Sweeps, 115 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 3,155 Hr		Front-Mounted Air Compressor Usage: 37,271 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
244	Asset located in: Lake Worth, TX  2021 Cat D1 Crawler Dozer  S/N: CAT000D1EXKF00156  C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Requires Diesel Exhaust Fluid, 115 in Wide PAT Blade, 16 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 1,144 Hr Asset located in: Lake Worth, TX	251	2008 John Deere 700J Combination Pipelayer w/ 2008 Midwestern M540 Conversion S/N: T0700JX156344 C/W: Canopy, 3 Lever Boom Control, 2007 US EPA Label, Hydraulic Hoists, 30 in Single Grouser Track Shoes Usage: 6,999 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
245	2005 John Deere 700J XLT Crawler Dozer		Asset located in: Lahoma, OK
	S/N: T0700JX110023 C/W: Enclosed Cab, Air Conditioner, 2005 US EPA Label, 120 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: Not Available Asset located in: Humble, TX	CHOIC	E OF 3 - Lot #'s: 252, 253, 254  1977 Cat 561C Pipelayer w/ 2007 Conversion S/N: 92J776 C/W: 3 Lever Boom Control, 20 in Single
CHOICE OF 2 - Lot #'s: 246, 247			Grouser Track Shoes, 20 ft 0 in Side Boom, Hydraulic Hoists Usage: 997 Hr <b>Notes</b> : ITEM AT OFFSITE LOCATION MUST BE
246	2005 Cat D5G LGP Crawler Dozer S/N: CAT00D5GVRKG01267 C/W: Open Operator Station, 127 in Wide PAT Blade, 24 in Single Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES .  Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
253	1975 Cat 561C Pipelayer S/N: 92J593 C/W: 3 Lever Boom Control, 18 in Single Grouser Track Shoes, 25 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 539 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	CHOICI 258	E OF 2 - Lot #'s: 258, 259  1971 Cat D4D Pipelayer w/ Midwestern D4D Conversion S/N: 60J2695 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft 0 in Side Boom, Hydraulic Hoists, Winch Usage: Not Available
254	1973 Cat 561C Pipelayer S/N: 92J413 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom,		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.  Asset located in: Lahoma, OK
	Hydraulic Hoists Usage: 903 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK	259	1966 Cat D4D Pipelayer w/ Midwestern 0D4D Conversion S/N: 86A1705 C/W: 3 Lever Boom Control, 16 in Single Grouser Track Shoes, 17 ft Side Boom, Hydraulic Hoists Usage: 6,536 Hr
	E OF 2 - Lot #'s: 255, 256		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.  Asset located in: Lahoma, OK
255	1969 Cat 561C Pipelayer w/ Midwestern M561C Conversion S/N: 92J233 C/W: 3 Lever Boom Control, 510 mm Single Grouser Track Shoes, 20 ft 0 in Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	260	1956 Cat D7C Pipelayer w/ Conversion S/N: 17A4488 C/W: 560 mm Single Grouser Track Shoes, 20 ft Side Boom, Mechanical Hoists Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK
256	1969 Cat 561C Pipelayer S/N: 92J238 C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 20 ft Side Boom, Hydraulic Hoists Usage: 1,795 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	CHOIC 261	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF402857 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 101 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper
257	<b>1982 Cat D5B Pipelayer</b> S/N: 44X01116		Usage: Not Available Asset located in: Lake Worth, TX
	C/W: 3 Lever Boom Control, 20 in Single Grouser Track Shoes, 17 ft Side Boom, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 52 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	262	2021 John Deere 755K Crawler Loader S/N: 1T0755KXPMF399113 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 5,525 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
263	2021 John Deere 755K Crawler Loader S/N: 1T0755KXKMF400262 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Manual Coupler, 94 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 6,008 Hr	271	2009 Cat 939C Crawler Loader S/N: CAT0939CC6DS02032 C/W: Open Operator Station, 84 in Multi- Purpose Bucket, 18 in Double Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 2,351 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	272	2007 Cat 815F Soil Compactor
264	2021 John Deere 755K Crawler Loader S/N: 1T0755KXVMF409838 C/W: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, 95 in Bucket, 22 in Double Grouser Track Shoes, Multi-Shank Ripper Usage: 5,530 Hr Asset located in: Lake Worth, TX	72/2	S/N: CAT0815FCBYN00307 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, 38 in Compaction Wheel Width, 146 in Straight Blade w/ Single Tilt, Fast Fuel Usage: 10,824 Hr Asset located in: Lake Worth, TX
265	2021 John Deere 755K Crawler Loader S/N: 1T0755KXAMF411719 C/W: Enclosed Cab, Requires Diesel Exhaust Fluid, 99 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,012 Hr Asset located in: Lake Worth, TX	273	2013 Hamm 3410P Padfoot Drum Compactor S/N: H1791920 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Deutz TCD2012L042V 134 hp 4.03 L Diesel Engine, 84 in Drum Usage: 6,559 Hr Asset located in: Lake Worth, TX
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	274	2016 Dynapac CA2500PD Padfoot Drum
CHOIC:	2017 John Deere 605K Crawler Loader S/N: 1T0605KXCHE310174 C/W: Open Operator Station, Air Ride Seat, 88 in Bucket, 18 in Double Grouser Track Shoes, 2	2/4	Compactor S/N: 10000167PHA020589 C/W: Open Operator Station, 2017 US EPA Label, Cummins QSF 4 Cylinder 89 kW 3.8 L Diesel Engine, 84 in Drum Usage: 2,102 Hr Asset located in: Lake Worth, TX
	Cylinder Multi-Shank Ripper Usage: 1,822 Hr	274A	Vibromax 1106 Padfoot Drum Compactor
	Asset located in: Lake Worth, TX		S/N: JKC8305502
267	2017 John Deere 605K Crawler Loader S/N: 1T0605KXPHE310856 C/W: Open Operator Station, Air Ride Seat, 88 in Bucket, 18 in Double Grouser Track Shoes, 2		C/W: Enclosed Cab, Air Conditioner, Diesel Engine, 82 in Drum Usage: 2,512 Hr <b>Asset located in</b> : Lake Worth, TX
	Cylinder Multi-Shank Ripper Usage: 1,632 Hr  Asset located in: Lake Worth, TX	275	2008 Dynapac CA250PD Padfoot Drum Compactor S/N: 6582US5658
268	2015 Cat 963D Crawler Loader S/N: CAT0963DTLCS02294 C/W: Enclosed Cab, Air Conditioner, 101 in Bucket, 22 in Double Grouser Track Shoes, 2		C/W: Open Operator Station, 4 Cylinder Diesel Engine, 84 in Drum Usage: 3,598 Hr <b>Asset located in</b> : Lake Worth, TX
	Cylinder Multi-Shank Ripper Usage: 4,156 Hr Asset located in: Lake Worth, TX	276	2007 Cat CP563E Padfoot Drum Compactor S/N: CATCP563ACNT01503 C/W: Open Operator Station, Cat 6 Cylinder
269	2005 Cat 963C Crawler Loader		Diesel Engine, 84 in Drum, Leveling Blade Usage: 755 Hr
	S/N: CAT0963CCBBD01372		Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, 102 in Bucket, 22 in Double Grouser Track Shoes, 2 Cylinder Multi- Shank Ripper Usage: 24,275 Hr <b>Asset located in</b> : Lake Worth, TX	277 2003 Cat CP-433E Padfoo S/N: CATCP433JCFK002: C/W: Open Operator Stati Label, Perkins 3PKXL03.9 kW 3.99 L Diesel Engine, 6 Blade Usage: 1,105 Hr	2003 Cat CP-433E Padfoot Drum Compactor S/N: CATCP433JCFK00238 C/W: Open Operator Station, 2003 US EPA Label, Perkins 3PKXL03.9AKI 4 Cylinder 74.5
269A	2004 Cat 963C Crawler Loader S/N: AT0963CPBBD00676 Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
278	2014 Bomag BW145PDH Padfoot Drum Compactor S/N: 101586021003 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2014 US EPA Label, Kubota v3307 4 Cylinder 37 kW 3.3 L Diesel Engine, 60 in Drum Usage: Not Available Asset located in: Lake Worth, TX  2007 Bomag BW145PDH-3 Padfoot Drum	284	2018 Volvo SD115B Smooth Drum Compactor S/N: VCES115BA0S236505 C/W: Open Operator Station, Air Ride Seat, 2018 US EPA Label, Volvo D4J 4 Cylinder 148 hp 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 85 in Drum, Padfoot Shell Kit Usage: 2,594 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
2/9	Compactor		Asset located in: Humble, TX
	S/N: 901581491236 C/W: Open Operator Station, Diesel Engine, 58 in Drum Usage: 616 Hr <b>Asset located in</b> : Lake Worth, TX	285	2015 Volvo SD115 Padfoot Drum Compactor S/N: VCES115BL0S236313 C/W: Open Operator Station, 2017 US EPA Label, Volvo D4J 4 Cylinder 4.0 L Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 1,488 Hr
280	Sakai SV201TB-1 Padfoot Drum Compactor		Asset located in: Lake Worth, TX
281	S/N: LSV2720110 C/W: Open Operator Station, Tier 4, 2008 US EPA Label, Kubota V3307-D1-T-ET04 4 Cylinder 55.4 kW 3.3 L Diesel Engine, 55 in Drum, Leveling Blade Usage: 1,882 Hr Asset located in: Lake Worth, TX  Volvo SD45 Padfoot Drum Compactor	286	2013 Bomag BW211D-50 Smooth Drum Compactor S/N: 901583531097 C/W: Open Operator Station, 2013 US EPA Label, Duetz 4 Cylinder 121 hp 3.6 L Diesel Engine, 84 in Drum Usage: 3,618 Hr Asset located in: Lake Worth, TX
	S/N: VCE00S45L0S229308 C/W: Open Operator Station, Kubota Diesel Engine, 54 in Drum Usage: 833 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	287	2013 Dynapac CA2500D Smooth Drum Compactor S/N: 10000138C0A012121 C/W: Open Operator Station, 2013 US EPA Label, Cummins 4 Cylinder 130 hp 4.5 L Diesel Engine, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX
		288	2006 Cat CS563E Smooth Drum Compactor
282	Asset located in: Fort Smith, AR  Bomag BW124PDH-40 Padfoot Drum Compactor (Inoperable) S/N: 901581401027		S/N: CATCS563PCNG01830 C/W: Open Operator Station, Cat 6 Cylinder Diesel Engine, 84 in Drum Usage: 4,090 Hr <b>Asset located in</b> : Lake Worth, TX
	C/W: Open Operator Station, 2011 US EPA Label, Deutz 3 Cylinder 45 hp 2.3 L Diesel Engine, 48 in Drum Usage: 1,423 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	289	2005 Ingersoll Rand SD122DX Smooth Drum Compactor S/N: 183705 C/W: Open Operator Station, 84 in Drum Usage: Not Available Asset located in: Lake Worth, TX
	REMOVAL;  Asset located in: Lake Worth, TX	290	2019 Volvo SD75B Padfoot Drum Compactor
283	2021 XCMG CV123PDU Smooth Drum Compactor S/N: XUG01231CMJE04323 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2021 US EPA Label, Cummins 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum, Padfoot Shell Kit Usage: 692 Hr Asset located in: Lake Worth, TX		S/N: VCE0S75BK0S241348 C/W: Open Operator Station, Tier 4, Volvo Diesel Engine, 66 in Drum Usage: 1,190 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Fort Smith, AR

Lot #	Details	Lot #	Details
291	2019 Dynapac CA1500D Smooth Drum Compactor S/N: 10000160AKA024661 C/W: Open Operator Station, Swivel Operator Controls, 2021 US EPA Label, Deutz TD3.6L4 4 Cylinder 3.6 L Diesel Engine, 66 in Drum Usage: 749 Hr	295	2015 Hamm H5i Smooth Drum Compactor S/N: H2220266 C/W: Open Operator Station, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 54 in Drum Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	296	2018 Bomag BW124DH-5 Smooth Drum
292	2015 Dynapac CA1500D Padfoot Drum Compactor S/N: 10000156CFA016214 C/W: Open Operator Station, 2014 US EPA Label, Cummins QSB3.3 100 hp 3.26 L Diesel Engine, 66 in Drum, Leveling Blade, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT	Compactor S/N: 861586571071 C/W: Open Operator Station, 2018 US EF Label, Kubota V2403-CR-EF04 4 Cylinde kW 2.4 L Diesel Engine, 47.5 in Drum Usage: Not Available	Compactor S/N: 861586571071 C/W: Open Operator Station, 2018 US EPA Label, Kubota V2403-CR-EF04 4 Cylinder 33.6 kW 2.4 L Diesel Engine, 47.5 in Drum
	Usage: 1,459 Hr <b>Notes</b> : SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON <b>Asset located in</b> : Oklahoma City, OK	297	2017 Bomag BW 124 Smooth Drum Compactor S/N: 861832122115 Usage: Not Available Asset located in: Humble, TX
293	2015 Bomag BW177DH-5 Smooth Drum Compactor S/N: 101586041089 C/W: Open Operator Station, Air Ride Seat, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 3.3 L Diesel Engine, 66 in Drum Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	298	2011 Cat CB54 Double Drum Roller S/N: CAT0CB54VJLM00434 C/W: Open Operator Station, Swivel Operator Controls, Cat C4.4 4 Cylinder Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	THE INSPECTION REPORT  Asset located in: Humble, TX		2006 Cat CB-534D XW Double Drum Roller S/N: CATCB534KEAA00412
294	2010 Volvo SD70D Smooth Drum Compactor S/N: VC500670A00225225 C/W: Open Operator Station, Tier 3, 2009 US EPA Label, Kubota V3800-DI-T-ET02 4 Cylinder 74 kW Diesel Engine, 66 in Drum Usage: 2,841 Hr		C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	300	2005 Cat CB-534D XW Double Drum Roller
294A	2007 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 196662 C/W: Open Operator Station, 2007 US EPA Label, Cummins b4.5 4 Cylinder 78 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM- WATKINS-CONSTRUCTION		S/N: CATCB534AEAA00397 C/W: Open Operator Station, Swivel Operator Controls, 2005 US EPA Label, Cat 4 Cylinder 97 kW 4.4 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 3,215 Hr Asset located in: Lake Worth, TX	301A	<b>2015 Case DV210C Double Drum Roller</b> S/N: DDDD210CNENTL2010
294B	2004 Ingersoll Rand SD70D-TF Smooth Drum Compactor S/N: 177760 C/W: Open Operator Station, 2004 US EPA Label, Cummins B4.5 4 Cylinder 79 hp 4.5 L Diesel Engine, 66 in Drum, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: THE AGE AND CONDITION OF THE MACHINE INDICATES MORE HOURS THAN SHOWN ON THE HOUR METER Asset located in: Lake Worth, TX		C/W: Open Operator Station, Swivel Operator Controls, 2014 US EPA Label, Deutz 100 hp 3.62 L Diesel Engine, 66 in Compaction Width, Water System Usage: 1,004 Hr Asset located in: Lake Worth, TX
		302	2016 Cat CB36B Double Drum Roller S/N: CATCB36BAM3600111 C/W: Open Operator Station, Cat 4 Cylinder Diesel Engine, 55 in Compaction Width, Water System, Edge Cutter Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
303	2013 Hamm HD13VV Double Drum Roller S/N: H2011675 C/W: Open Operator Station, Kubota V2203 4 Cylinder 2.2 L Diesel Engine, 51 in Compaction Width, Edge Cutter Usage: 1,104 Hr	311	2018 Bomag BW900-50 Double Drum Roller S/N: 861834072457 C/W: Open Operator Station, Honda GX 630 2 Cylinder Gasoline Engine, 36 in Compaction Width, Edge Cutter Usage: 685 Hr	
	Asset located in: Lake Worth, TX	312	Asset located in: Lake Worth, TX	
CHOIC			2018 Bomag BW900-50 Double Drum Roller S/N: 881834072563 C/W: Open Operator Station, Honda GX 630 2 Cylinder Gasoline Engine, 35 in Compaction Width Usage: Not Available	
	(Unused) S/N: WGH0H230CHAA06595		Asset located in: Lake Worth, TX	
	C/W: Open Operator Station, E-Stops, Tier 4, 2020 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 22 Hr Asset located in: Lake Worth, TX	CHOIC	E OF 3 - Lot #'s: 313, 314, 315  2016 Bomag BW900-50 Double Drum Roller	
305	2022 Hamm HD12VV Double Drum Roller S/N: WGH0H230KHAA05864		S/N: 861834072133 Usage: 239 Hr <b>Asset located in</b> : Lake Worth, TX	
	C/W: Open Operator Station, E-Stops, Tier 4, 2022 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, 47 in Compaction Width, Water System Usage: 63 Hr <b>Asset located in</b> : Lake Worth, TX	314	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072137 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 36 in Compaction Width Usage: Not Available Asset located in: Lake Worth, TX	
307	Volvo DD24 Double Drum Roller	-		
	S/N: 196371 C/W: Open Operator Station, 3 Cylinder Diesel Engine, 47.25 in Compaction Width, Water System Usage: 2,886 Hr <b>Asset located in</b> : Lake Worth, TX	315	2016 Bomag BW900-50 Double Drum Roller S/N: 861834072138 C/W: Open Operator Station, Honda 2 Cylinder Gasoline Engine, 35.5 in Compaction Width, Water System Usage: Not Available Asset located in: Lake Worth, TX	
CHOIC	E OF 2 - Lot #'s: 308, 309	316	Wacker Neuson RD11A Double Drum Roller S/N: 5613749	
308	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263LHHAA00855 C/W: Open Operator Station, Tier 4, 2021 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel		C/W: Open Operator Station, 2014 US EPA Label, Honda GX 630 2 Cylinder Gasoline Engine, 35 in Compaction Width Usage: 594 Hr <b>Asset located in</b> : Humble, TX	
	Engine, 39 in Compaction Width, Water System Usage: 148 Hr <b>Asset located in</b> : Lake Worth, TX	317	2006 Isuzu NQR Sweeper Truck S/N: JALE5B16267903657	
309	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263THAA00778 C/W: Open Operator Station, Kubota D1105 Diesel Engine, 39 in Compaction Width, Water System Usage: Not Available			C/W: Isuzu 4 Cylinder Diesel 190 hp Engine, 2005 US EPA Label, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 134 in Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, Under Body Broom, Gutter Brooms Usage: 93,999 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	318	2019 LeeBoy CB95 Self-Propelled Broom	
310	2017 Hamm HD10C VV Double Drum Roller S/N: H1994782 C/W: Open Operator Station, Tier 4, 2016 US EPA Label, Kubota D1005-EF05 3 Cylinder 14.8 kW 1.0 L Diesel Engine, 39 in Compaction Width, Water System Usage: 892 Hr Asset located in: Lake Worth, TX		S/N: 242550 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2019 US EPA Label, Hatz 4H50TIC 4 Cylinder 55 kW 1.9 L Diesel Engine Usage: 359 Hr Asset located in: Lake Worth, TX	

			1450 21 01 300	
Lot #	Details	Lot #	Details	
319	2019 Broce RJT-350 Self-Propelled Broom S/N: 411566 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2018 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	326	2014 Superior DT80J Self-Propelled Broom S/N: 814877 C/W: Enclosed Cab, Air Conditioner, 8 ft 7 in Broom, Water System, 2014 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 691 Hr Asset located in: Lake Worth, TX	
СНОІС	E OF 2 - Lot #'s: 320, 321	327	<b>2014 Superior DT80J Self-Propelled Broom</b> S/N: 814869	
320	2015 Broce KR350 Self-Propelled Broom S/N: 409370 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota V3600-T-ET03 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, John Deere 4045TF290 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,536 Hr Asset located in: Lake Worth, TX	
	Usage: 1,930 Hr <b>Asset located in</b> : Lake Worth, TX	сноіс	E OF 2 - Lot #'s: 329, 330	
321	2015 Broce KR350 Self-Propelled Broom S/N: 409369 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder 55.4 kW 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 698 Hr Asset located in: Lake Worth, TX	329	2001 Broce BB250B Self-Propelled Broom S/N: 304993 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2015 US EPA Label, Kubota 4 Cylinder 18.5 kW 1.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available	
322	2015 Broce KR-350 Self-Propelled Broom S/N: 409307 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, Kubota 4 Cylinder Diesel		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	
	Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,522 Hr Asset located in: Oklahoma City, OK	330	S/N: 304910 C/W: Open Operator Station, 8 ft Broom, System, Tier 4, 2015 US EPA Label, Kubo	C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2015 US EPA Label, Kubota
323	2015 Broce KR350 Self-Propelled Broom S/N: 409308 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2015 US EPA Label,		V1505-EF01 4 Cylinder 18.5 kW 1.5 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 100 Hr <b>Asset located in</b> : Lake Worth, TX	
	Kubota V3600-Ť-ET03 4 Cylinder 3.6 L Diesel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,137 Hr Asset located in: Lake Worth, TX	330A	2001 Broce BB250B Self-Propelled Broom S/N: 305062 C/W: Open Operator Station, 8 ft Broom, Water System, Tier 4, 2018 US EPA Label, Kubota V1505 18.2 kW 1.5 L Diesel Engine	
324	2015 Broce KR350 Self-Propelled Broom S/N: 409371		Usage: 663 Hr <b>Asset located in</b> : Lake Worth, TX	
	C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, Water System, 2014 US EPA Label, Kubota 4 Cylinder Diesel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 1,187 Hr	333	2000 Rosco RB48 Self-Propelled Broom S/N: 36730 Usage: Not Available Asset located in: Lake Worth, TX	
325A	Asset located in: Lake Worth, TX  2014 Broce CRT350 Self-Propelled Broom S/N: 408677 C/W: Enclosed Cab, Air Conditioner, 8 ft Broom, 2013 US EPA Label, Cat 4 Cylinder 60.5 kW 4.4 L Diesel Engine Usage: 5,095 Hr Asset located in: Lake Worth, TX	334	2021 John Deere 870G LC Tracked Excavator S/N: 1FF870GXJMF890112 C/W: Air Conditioner, Air Ride Seat, 2021 US EPA Label, 9 ft 8 in Stick, 36 in Double Grouser Track Shoes, 96 in Digging Bucket, Counterweight Removal System Usage: 5,764 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
334A	2015 Komatsu PC650LC-8E0 Tracked Excavator S/N: KMTPC233CFC065343 C/W: Air Conditioner, Air Ride Seat, 10 ft Stick, 36 in Triple Grouser Track Shoes, 80 in Digging Bucket Usage: 18,316 Hr Asset located in: Lake Worth, TX	341	2013 Hitachi ZX470LC-5B Tracked Excavator S/N: HCMJAA70A00030283 C/W: Air Ride Seat, Tier 4, US EPA Label, 9 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 68 in Digging Bucket, Catwalks Usage: 11,455 Hr Asset located in: Humble, TX
335 CHOIC	2015 Kobelco SK500LC-9 Tracked Excavator S/N: YS1203617 Usage: Not Available Asset located in: Lake Worth, TX	342	2016 John Deere 380G LC Tracked Excavator S/N: 1FF380GXTGF900147 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket
337	2017 Cat 349FL Tracked Excavator		Usage: 10,290 Hr <b>Asset located in</b> : Lake Worth, TX
	S/N: CAT0349FCHPD10110 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 30 in V-Bottom Bucket Usage: 13,440 Hr Asset located in: Lake Worth, TX	343	2019 Cat 336 Tracked Excavator S/N: CAT00336PDKS00399 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 12,251 Hr
338	2017 Cat 349F L Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0349FAHPD10053 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2016 US EPA Label, 12 ft 10 in Stick, 35 in Triple Grouser Track Shoes, Manual Quick Coupler, 30 in V- Bottom Bucket Usage: 13,635 Hr Asset located in: Lake Worth, TX	344	2019 Cat 336 Tracked Excavator S/N: CAT00336LDKS01786 C/W: Air Conditioner, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, 33.5 in Triple Grouser Track Shoes, 43 in Digging Bucket Usage: Not Available
339	2013 Cat 349E Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT0349EPMPZ00695 C/W: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2013 US EPA Label, 12 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 35.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket Usage: 10,831 Hr Asset located in: San Antonio, TX	S/N: CAT0336FARKB21335 C/W: Air Conditioner, Straight Tra Ride Seat, Control Pattern Change Camera, 2018 US EPA Label, Req Exhaust Fluid, 12 ft 6 in Stick, Aux Hydraulic Plumbing, 33 in Triple G Shoes, 44 in Digging Bucket, EQU FROM-WATKINS-CONSTRUCTION Usage: 4,625 Hr Asset located in: Lake Worth, TX  346 2018 Cat 336FL Tracked Excavat S/N: TZA20175 C/W: Air Conditioner, Straight Tra Ride Seat, Rear View Camera, 207 Label, Requires Diesel Exhaust Fle Stick, Auxiliary Hydraulic Plumbin Grouser Track Shoes, 43 in Diggir	<b>2018 Cat 336FL Tracked Excavator</b> S/N: CAT0336FARKB21335 C/W: Air Conditioner, Straight Travel Pedal, Ride Seat, Control Pattern Changer, Rear Vie
340	2021 Hyundai HX480L Tracked Excavator S/N: HHKHKB01JL0000163 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in		Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 44 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 4,625 Hr
	Triple Grouser Track Shoes, 72 in Digging Bucket, Auto Lube Usage: 6,810 Hr <b>Asset located in</b> : Humble, TX		2018 Cat 336FL Tracked Excavator S/N: TZA20175 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA
340A	2014 John Deere 470GLC Tracked Excavator S/N: 1FF470GXTCE470692 C/W: Requires Diesel Exhaust Fluid, 13 ft 5 in Stick, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket Usage: 12,526 Hr Asset located in: Lake Worth, TX		Label, Requires Diesel Exhaust Fluid, 12 ft 6 Stick, Auxiliary Hydraulic Plumbing, 33 in Trip Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTI Usage: 4,883 Hr

Lot #	Details	Lot #	Details
347	2018 Cat 336FL Tracked Excavator S/N: CAT0336FKTZA20109 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 46 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 5,561 Hr Asset located in: Lake Worth, TX	352	CHOICE OF 2 - Lot #'s: 352, 353  2015 Cat 336FL Tracked Excavator S/N: CAT0336FJRKB00903 C/W: Air Conditioner, Straight Travel Pedal, Ai Ride Seat, Rear View Camera, 2014 US EPA Label, 12 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic Thumb Usage: 7,433 Hr
348	2018 Cat 336FL Tracked Excavator S/N: CAT0336FKRKB21071 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,613 Hr Asset located in: Lake Worth, TX		Asset located in: Midland, TX  2015 Cat 336FL Roadbuilder Tracked Excavator S/N: RKB00900 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 33.5
349	2017 Cat 336F L Tracked Excavator S/N: CAT0336FLTZA10137 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 10 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 13,138 Hr		in Triple Grouser Track Shoes, Rock Guards, 39 in Digging Bucket Usage: 6,370 Hr  Asset located in: Midland, TX  E OF 2 - Lot #'s: 354, 355
	Asset located in: Lake Worth, TX	354	2013 Cat 336 EL Tracked Excavator
350	2016 Cat 336FL Tracked Excavator S/N: CAT0336FJSSN00477 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Cab Screens, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, EQUIPMENT-FROM-PULICE-		S/N: CAT0336EJRZA00234 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 12 ft 10 in Stick, 34 in Triple Grouser Track Shoes, 48 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,605 Hr Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: 10,564 Hr	355	2013 Cat 336 EL Tracked Excavator
351	Asset located in: Humble, TX  2016 Cat 336FL Tracked Excavator  S/N: CAT0336FCTZA00440  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 56 in		S/N: CAT0336EEFJH00483 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 45 in Cleanup Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,199 Hr Asset located in: Lake Worth, TX
		356	2013 Cat 336EL Tracked Excavator S/N: CAT0336ECFJH00355 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 9 in Stick, 33.5 in Triple Grouser Track Shoes, 50 in Digging Bucket Usage: 8,712 Hr Asset located in: Midland, TX

Lot #	Details	Lot #	Details
357	2012 Cat 336 EL Tracked Excavator S/N: CAT0336EKBZY01618 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in Triple Grouser Track Shoes, 42 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 9,409 Hr	362	2012 Komatsu PC360LC-10 Tracked Excavator S/N: KMTPC24202070045 C/W: Air Conditioner, 2011 US EPA Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, 56 in Digging Bucket, Hydraulic Thumb Usage: 12,043 Hr Asset located in: Lake Worth, TX
		363	2017 XCMG XE360U Tracked Excavator
	Asset located in: Lake Worth, TX	303	S/N: XUG03600KHKA00061
СНОІС	E OF 2 - Lot #'s: 358, 359		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, US EPA Label, 8 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 823 Hr
358	<b>2012 Cat 336E L Tracked Excavator</b> S/N: CAT0336EVBZY01509		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2012 US EPA		Asset located in: Humble, TX
	Label, 10 ft 6 in Stick, 34 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 58 in Digging Bucket Usage: 12,654 Hr  Asset located in: Lake Worth, TX	364	2018 Cat 335F LCR Tracked Excavator S/N: SGJ20006 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel
359	S/N: CAT0336EKBZY00808 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2011 US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 42		Exhaust Fluid, 12 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, 43 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 5,806 Hr Asset located in: Lake Worth, TX
		365 2010 Komatsu PC350LC-8 Tracked Excavator S/N: KMTPC19IJ54A10246 C/W: Air Conditioner, Rear View Camera, 2010	
360	2010 Cat 336D Tracked Excavator S/N: CAT0336DKW3K01214 C/W: Air Conditioner, 2010 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 34 in		US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket Usage: 11,202 Hr
			Asset located in: Lake Worth, TX
	Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: 89,205 Hr <b>Asset located in</b> : Lake Worth, TX	EPA Label, 10 ft 6 in Stick, Auxiliary Hydra	S/N: 1FF350GXCCE808325 C/W: Air Conditioner, Air Ride Seat, 2011 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic
361	<b>2017 Komatsu PC360LC 11 Tracked Excavator</b> S/N: KMTPC256HHWA35865		Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 44 in Digging Bucket Usage: Not Available
	C/W: Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid,		Asset located in: Lake Worth, TX
	10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 60 in Digging Bucket Usage: 15,343 Hr	СНОІС	E OF 2 - Lot #'s: 367, 368
	Asset located in: Lake Worth, TX	367	2022 Cat 330 Tracked Excavator
361A	2017 Komatsu PC360LC-11 Roadbuilder Tracked Excavator S/N: KMTPC256AHWA35992 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 13 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 63 in Digging Bucket, Manual Thumb, Nye 516541, PC 360 Grapple Usage: 5,789 Hr Asset located in: Midland, TX		S/N: CAT00330VWCH30051 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,104 Hr  Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
368	2021 Cat 330 Tracked Excavator S/N: CAT00330AWCH20489 C/W: Air Conditioner, Straight Travel Pedal, Air	CHOICE OF 3 - Lot #'s: 372, 373, 374	
	Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,395 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	372	2020 Cat 330GC Tracked Excavator S/N: CAT00330CGDW10069 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,885 Hr
369	2020 Cat 330 Tracked Excavator S/N: CAT00330JWCH10184		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Surround View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,590 Hr  Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS  Asset located in: Lake Worth, TX	373	2020 Cat 330GC Tracked Excavator S/N: CAT00330CSCZ10029 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,443 Hr Notes: EMISSIONS SYSTEM WARRANTY
CHOIC	CHOICE OF 2 - Lot #'s: 370, 371		THROUGH JANUARY 2026 OR 3000 HOURS  Asset located in: Lake Worth, TX
370	2020 Cat 330 Tracked Excavator  S/N: CAT00330TWCH10651  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,428 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB	374	2020 Cat 330GC Tracked Excavator  S/N: CAT00330VGDW10047  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,462 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
371	2020 Cat 330 TC Tracked Excavator S/N: CAT00330JWCH10654 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,072 Hr Asset located in: Lake Worth, TX	375	2020 Cat 330GC Tracked Excavator S/N: CAT00330KGDW10058 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 38 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,503 Hr

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
376	2020 Cat 330GC Tracked Excavator S/N: CAT00330ESCZ10028 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 35 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 2,558 Hr	381	2018 Cat 330F L Tracked Excavator S/N: CAT0330FEMBX20643 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 3,732 Hr Asset located in: Lake Worth, TX
	Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	382	2018 Cat 330F L Tracked Excavator S/N: CAT0330FCMBX20666 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View
377	2020 Cat 330GC Tracked Excavator S/N: CAT00330LGDW10049 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track		Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,894 Hr  Asset located in: Lake Worth, TX
	Shoes, 36 in Cleanup Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION		
	Usage: 2,882 Hr Notes: EMISSIONS SYSTEM WARRANTY	СНОІС	E OF 2 - Lot #'s: 383, 384
	THROUGH APRIL 2026 OR 3000 HOURS  Asset located in: Lake Worth, TX	383 20	2018 Cat 330F L Tracked Excavator
378	2019 Cat 330 Tracked Excavator S/N: CAT00330TLHW00257 C/W: Air Conditioner, Rear & Side View Cameras, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 5,554 Hr Asset located in: Lake Worth, TX		S/N: CAT0330FTHCK20095 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,836 Hr Notes: COMES WITH UNUSED HYDRAULIC
379	2019 Cat 330F L Tracked Excavator S/N: CAT0330FJHCK20408		THUMB  Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,557 Hr  Asset located in: Lake Worth, TX	384	2018 Cat 330F L Tracked Excavator S/N: CAT0330FPMBX20257 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,485 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 3 - Lot #'s: 380, 381, 382	385	2012 Volvo EC300DL Tracked Excavator
380	2018 Cat 330F L Tracked Excavator S/N: MBX20638 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel	303	S/N: VCEC300DC00210349 C/W: Straight Travel Pedal, 2012 US EPA Label, 10 ft Stick, 36 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 9,162 Hr  Asset located in: Lake Worth, TX
	Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,586 Hr Asset located in: Lake Worth, TX	386	2017 John Deere 300G LC Tracked Excavator S/N: 1FF300GXKHF730514 C/W: Air Conditioner, 2017 US EPA Label, CARB Compliant, 13 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 28 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 43 in Digging Bucket, Hydraulic Thumb Usage: 6,335 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
387	2017 Volvo ECR305CL Tracked Excavator S/N: VCECR305V00110701 C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, 2016 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 6,005 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: El Paso, TX	392	2019 Komatsu PC290LC-11 Tracked Excavator S/N: KMTPC255AJKK73097 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 0 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, Rock Guards, 48 in Digging Bucket Usage: 4,542 Hr  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE
388	Hyundai R300LC-9A Tracked Excavator S/N: HHKHZ803ED0000030 C/W: Air Conditioner, Rear View Camera, 2012		AVAILABLE  Asset located in: McAlester, OK
	US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 4,396 Hr Asset located in: Lake Worth, TX	393	2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27917 C/W: Air Conditioner, Control Pattern Changer, 2018 US EPA Label, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 43 in Cleanup Bucket
389	2018 Volvo EC250ELR Tracked Excavator S/N: VCEC250EK00310554 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 25 ft 6 in Boom, 26 ft Stick, 36 in Triple Grouser Track Shoes, 60 in Cleanup Bucket Usage: 4,986 Hr		Usage: 4,865 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK
	Asset located in: Lake Worth, TX	394	2018 Komatsu PC290LC-11 Tracked Excavator
CHOICE	E OF 6 - Lot #'s: 390, 391, 392, 393, 394, 395  2019 Komatsu PC290LC-11 Tracked Excavator S/N: JKK73093 C/W: Air Conditioner, Rear View Camera, 10 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in		S/N: A27916 C/W: Air Conditioner, Air Ride Seat, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 5,473 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
	Triple Grouser Track Shoes, 42 in Cleanup Bucket Usage: 3,632 Hr <b>Notes</b> : LOADOUT BY APPOINTMENT ONLY ; ITEM AT OFFSITE LOCATION MUST BE		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE  Asset located in: McAlester OK	395	2018 Komatsu PC290LC-11 Tracked Excavator S/N: KMTPC255CJWA27918 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label,
391	Asset located in: McAlester, OK  2018 Komatsu PC290LC-11 Tracked Excavator S/N: A27915 C/W: Air Conditioner, Control Pattern Changer,		Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 5,920 Hr
	Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 5 in Stick, 31.5 in Triple	200	Asset located in: Lake Worth, TX
	Grouser Track Shoes Usage: 4,248 Hr  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; Asset located in: McAlester, OK	396	2009 Cat 329DL Tracked Excavator S/N: CAT0329DLJHJ00330 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 10 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Manual Thumb, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 10,025 Hr Notes: COMES WITH UNUSED HYDRAULIC THUMB Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICI	E OF 2 - Lot #'s: 397, 398	403	2015 John Deere 245G LC Tracked Excavator S/N: 1FF245GXLFE600773 C/W: Air Conditioner, Air Ride Seat, 10 ft 7 in
397	2019 Cat 326F L Tracked Excavator S/N: CAT0326FPFBR20575 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2018 US EPA		Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler 46 in Digging Bucket Usage: Not Available Asset located in: Humble, TX
	Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 34 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,230 Hr  Notes: COMES WITH UNUSED HYDRAULIC THUMB  Asset located in: Lake Worth, TX	404 2012 Cat 324 EL Tracked Excavator S/N: CAT0324EPPNW00408 C/W: Air Conditioner, Straight Travel Pedal, Ride Seat, Control Pattern Changer, Rear Vic Camera, 2011 US EPA Label, 9 ft 6 in Stick, in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, EQUIPMENT-FROM-	2012 Cat 324 EL Tracked Excavator S/N: CAT0324EPPNW00408 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Catwalks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION
398	2019 Cat 326F L Tracked Excavator		Usage: 8,469 Hr <b>Asset located in</b> : Lake Worth, TX
	S/N: CAT0326FLFBR20679 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket,	405	2012 Cat 324 EL Tracked Excavator S/N: CAT0324EHPNW00497 Usage: Not Available Asset located in: Lake Worth, TX
	Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,973 Hr <b>Asset located in</b> : Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 406, 407
399	2019 Cat 326F L Tracked Excavator S/N: CAT0326FEFBR20653 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 9,619 Hr Asset located in: Lake Worth, TX	406	2023 Cat 323 Tracked Excavator S/N: CAT00323ENDL20616 C/W: Air Conditioner, Straight Travel Pedal, A Ride Seat, Control Pattern Changer, Rear & S View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaus Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-
400	2015 Cat 326FL Tracked Excavator S/N: CAT0326FVWGL00317 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel		CONSTRUCTION Usage: 240 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS Asset located in: Lake Worth, TX
	Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 54 in Digging Bucket Usage: 9,061 Hr <b>Asset located in</b> : Lake Worth, TX		2023 Cat 323 Tracked Excavator S/N: CAT00323LNDL20614 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side
401	2020 LiuGong 888925E Tracked Excavator S/N: 888925EZJLU004037 C/W: Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket		View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 490 Hr
	Usage: 2,191 Hr		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2028 OR 3000 HOURS
402	Asset located in: Humble, TX  2016 John Deere 245G LC Tracked Excavator	$\dashv$	Asset located in: Lake Worth, TX
702	S/N: 1FF245GXJGF800123 C/W: with JRB coupler and bucket Usage: Not Available		
	Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
408	2023 Cat 323 Tracked Excavator  S/N: CAT00323JNDL20736  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 866 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 412, 413, 414	
		412	2019 Cat 323 Tracked Excavator S/N: CAT00323ARAZ10687 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,393 Hr Asset located in: Lake Worth, TX	
СНОІС	E OF 2 - Lot #'s: 409, 410	413	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10552	
409	·		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,527 Hr  Asset located in: Lake Worth, TX	
		414	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ11197 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control,	
410	Asset located in: Lake Worth, TX  2022 Cat 323 Tracked Excavator  S/N: CAT00323CNDL20219  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Surround View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick,		2019 US EPA Label, Requires Diesel Ex Fluid, 9 ft 6 in Stick, 31 in Triple Grouse Shoes, 36 in Digging Bucket, Thumb Bi Tool Control; EQUIPMENT-FROM-WAT CONSTRUCTION Usage: 2,958 Hr	2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 34 in Digging Bucket, Thumb Bracket, Tool Control, EQUIPMENT- FROM-WATKINS-CONSTRUCTION	СНОІС	E OF 3 - Lot #'s: 415, 416, 417	
	Usage: 156 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS Asset located in: Lake Worth, TX	S/N: CAT00323CRAZ11 C/W: Air Conditioner, St Ride Seat, Control Patte View Cameras, Pre-Wire 2019 US EPA Label, Rec Fluid, 9 ft 6 in Stick, Aux Plumbing, 32 in Triple G in Digging Bucket, Thun Control; EQUIPMENT-FF CONSTRUCTION Usage: 3,062 Hr	2019 Cat 323 Tracked Excavator S/N: CAT00323CRAZ11070 C/W: Air Conditioner, Straight Travel Pedal, Air	
411	2022 Cat 323 Tracked Excavator  S/N: NDL20218  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 814 Hr  Notes: EMISSIONS SYSTEM WARRANTY THROUGH APRIL 2028 OR 3000 HOURS  Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
416	2019 Cat 323 Tracked Excavator S/N: CAT00323TRAZ10972 C/W: Air Conditioner, Straight Travel Pedal, Rear & Side View Cameras, Pre-Wired for Grade Control, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.25 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,205 Hr Asset located in: Lake Worth, TX	421	2018 Cat 323 Tracked Excavator S/N: CAT00323HRAZ00227 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,498 Hr Asset located in: Lake Worth, TX
417	2019 Cat 323 Tracked Excavator S/N: CAT00323KRAZ11087 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,253 Hr Asset located in: Lake Worth, TX	422	2018 Cat 323 Tracked Excavator S/N: CAT00323JRAZ00303 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,641 Hr Asset located in: Lake Worth, TX
418	2019 Cat 323 Tracked Excavator S/N: RAZ10628 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Thumb Bracket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 4,636 Hr Asset located in: Lake Worth, TX	423	2018 Cat 323 Tracked Excavator S/N: CAT00323PRAZ00282 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, Tier 4, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,757 Hr Asset located in: Lake Worth, TX
419	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00176 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb,; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,439 Hr Asset located in: Lake Worth, TX	424	2018 Cat 323 Tracked Excavator S/N: CAT00323ARAZ00290 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,808 Hr Asset located in: Lake Worth, TX
420	2018 Cat 323 Tracked Excavator S/N: CAT00323ERAZ00293 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,103 Hr Asset located in: Lake Worth, TX	425	2018 Cat 323 Tracked Excavator S/N: CAT00323KRAZ00266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,852 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
426	2018 Cat 323 Tracked Excavator S/N: CAT00323LRAZ00288 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for Grade Control, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,063 Hr Asset located in: Lake Worth, TX	432	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXPJF526258 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 700 mm Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 5,427 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
427	2018 Cat 323 Tracked Excavator S/N: CAT00323HRAZ01166 C/W: Air Conditioner, Straight Travel Pedal, Air	433	Asset located in: Lahoma, OK  2012 John Deere 210GLC Tracked Excavator
	Ride Seat, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 48 in Digging Bucket, Thumb Bracket Usage: 4,053 Hr		S/N: 1FF210GXACE520458 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lahoma, OK
428	2017 Cat 323F L Tracked Excavator S/N: CAT0323FTXCF10375 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View	434	2012 Hitachi ZX210LC-5N Tracked Excavator S/N: 1FFDCJ70TCE330100 Usage: 8,921 Hr Asset located in: Lake Worth, TX
	Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 3,557 Hr Asset located in: Lake Worth, TX	435	2017 Komatsu PC210LC-11 Tracked Excavate S/N: KMTPC257CGTC80149 C/W: Air Conditioner, Rear View Camera, 201 US EPA Label, Requires Diesel Exhaust Fluid, ft 8 in Stick, Auxiliary Hydraulic Plumbing, 32 Triple Grouser Track Shoes, Hydraulic Quick Coupler, 34 in Digging Bucket
429	2015 Cat 323FL Tracked Excavator S/N: CAT0323FCXCF00606		Usage: 15,090 Hr  Asset located in: Lake Worth, TX
	C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 2014 US EPA Label, 10 ft Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 10,595 Hr Asset located in: Lake Worth, TX	436	2020 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257KKWA12903 C/W: Air Conditioner, Rear View Camera, 2019 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, Hydraulic Breaker Usage: 5,171 Hr Asset located in: Lake Worth, TX
430	2022 John Deere 210GLC Tracked Excavator	427	2013 Komatsu PC210LC-10 Tracked Excavator
	S/N: 1FF210GXENF529761 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, 9 ft 7 in Stick, 27.5 in Triple Grouser Track Shoes, 24 in Digging Bucket Usage: 2,416 Hr Asset located in: Lake Worth, TX	<b>437</b>  -	S/N: KMTPC243C02450042 C/W: Air Conditioner, Cab Screens, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, Auto Lube Usage: 14,738 Hr
CHOIC	E OF 2 - Lot #'s: 431, 432		Asset located in: Lake Worth, TX
431	2018 John Deere 210G LC Tracked Excavator S/N: 1FF210GXLJF526477 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 48 in Digging Bucket Usage: 4,374 Hr Asset located in: Lake Worth, TX	438	2013 Komatsu PC210LC-10 Tracked Excavator S/N: KMTPC243H02450734 C/W: Air Conditioner, 2013 US EPA Label, 10 ft 2 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 8,296 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
439	2019 XCMG XE210U Tracked Excavator S/N: XUGA210BVKKA00083 C/W: Air Conditioner, Air Ride Seat, Cab Screens, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 1 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 23 in Digging Bucket Usage: 721 Hr Asset located in: Humble, TX	444	2020 Cat 320 Tracked Excavator S/N: CAT00320CHEX20219 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre- Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 32 in Triple Grouser Track Shoes, 42 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 1,582 Hr
440	2014 Cat 321D LCR Tracked Excavator S/N: CAT0321DLMPG01100 Usage: Not Available		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		Asset located III. Lake Worth, TA
440A	<b>2018 Hitachi ZX210LC-5N Tracked Excavator</b> S/N: 1FFDCJ70JEE330489 Usage: Not Available	сноіс	E OF 2 - Lot #'s: 445, 446
	Asset located in: Lake Worth, TX	445	2020 Cat 320 Tracked Excavator
441	2022 Cat 320GC Tracked Excavator S/N: CAT00320HLKS20318 Usage: 1,073 Hr Notes: CAT POWERTRAIN - HYDRAULIC - TECHNOLOGY WARRANTY THROUGH DECEMBER 2025 OR 5,000 HOURS Asset located in: Lake Worth, TX		S/N: CAT00320KHEX20265 C/W: Air Conditioner, Straight Travel Pedal, Ai Ride Seat, Control Pattern Changer, Rear & Sic View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 3 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 2,321 Hr
CHOIC	E OF 3 - Lot #'s: 442, 443, 444		Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS
442	2020 Cat 320 Tracked Excavator		Asset located in: Lake Worth, TX
	S/N: CAT00320JHEX20266 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 30 in Digging Bucket, Catwalks, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,298 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH DECEMBER 2025 OR 3000 HOURS	446	2020 Cat 320 Tracked Excavator  S/N: CAT00320AHEX20207  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 2,462 Hr  Notes: EMISSIONS SYSTEM WARRANTY
	Asset located in: Lake Worth, TX		THROUGH MARCH 2026 OR 3000 HOURS
443	2020 Cat 320 Tracked Excavator  S/N: CAT00320HHEX20212  C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-	CHOIC	Asset located in: Lake Worth, TX  E OF 4 - Lot #'s: 447, 448, 449, 450  2019 Cat 320 Tracked Excavator S/N: CAT00320CHEX12081 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-

S/N: CAT00320CHEX12081 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION

Usage: 1,445 Hr

**Notes**: EMISSIONS SYSTEM WARRANTY THROUGH FEBRUARY 2026 OR 3000 HOURS

Asset located in: Lake Worth, TX

**Notes**: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
448	2019 Cat 320 Tracked Excavator S/N: CAT00320VHEX11425 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Pre-Wired for	СНОІС	E OF 2 - Lot #'s: 454, 455
	Grade Control, 2018 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,539 Hr  Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS  Asset located in: Lake Worth, TX	454	2014 Cat 320EL Tracked Excavator S/N: CAT0320EEWBK01967 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear & Side View Cameras, 2012 US EPA Label, 9 ft 7 in Stick, 31 in Triple Grouser Track Shoes, 31 in Digging Bucket, Hydraulic Thumb, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 4,345 Hr
449	2019 Cat 320 Tracked Excavator	455	Asset located in: Lake Worth, TX  2014 Cat 320 EL Tracked Excavator
	S/N: HEX11857 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, Tool Control; EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 1,702 Hr	433	S/N: CAT0320EAWBK02595 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,912 Hr  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	456	2014 Cat 320 EL Tracked Excavator
450	2019 Cat 320 Tracked Excavator S/N: CAT00320KHEX12604 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Cleanup Bucket, Tool Control; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,129 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH MARCH 2026 OR 3000 HOURS		S/N: CAT0320ECWBK02652 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 8 in Stick, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb Usage: 10,473 Hr Asset located in: Lake Worth, TX
		457	2014 Cat 320 EL Tracked Excavator S/N: CAT0320EPWBK02668 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US
	Asset located in: Lake Worth, TX		EPA Label, 8 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Hydraulic Breaker
451	2019 Cat 320 Tracked Excavator S/N: CAT00320LHEX11329 C/W: Rear & Side View Cameras, 2018 US EPA		Usage: 18,583 Hr  Asset located in: Lake Worth, TX
	Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 3,617 Hr Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 458, 459, 460
452	2018 Cat 320 Tracked Excavator	458	2013 Cat 320 EL Tracked Excavator
	S/N: CAT00320THEX01650 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 2,890 Hr  Asset located in: Lake Worth, TX		S/N: CAT0320ELWBK01626 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 5,381 Hr
453	2017 Cat 320FL Tracked Excavator S/N: CAT0320FKYBM10403 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Rear View Camera, 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, 27 in Cleanup Bucket Usage: 6,755 Hr Asset located in: Midland, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
459	2013 Cat 320 EL Tracked Excavator S/N: CAT0320EKREE00514 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 5,468 Hr Asset located in: Lake Worth, TX	465	2006 John Deere 200C LC Tracked Excavator S/N: FF200CX507611 C/W: Air Conditioner, Control Pattern Changer, Tier 2, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 800 mm Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 8,607 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.
460	2013 Cat 320 EL Tracked Excavator S/N: CAT0320EHWBK02230 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2013 US EPA Label, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,019 Hr Asset located in: Lake Worth, TX	466	Asset located in: Lahoma, OK  2019 Cat 316FL Tracked Excavator S/N: CAT0316FKYDL21033 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 24 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 3,683 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 461, 462	467	2013 Cat 316E L Tracked Excavator S/N: CAT0316EJDZW00889 C/W: Air Conditioner, Straight Travel Pedal, Air
461	2012 Cat 320 EL Tracked Excavator S/N: CAT0320EKWBK00212 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 9 ft 6 in Stick, 32 in Triple Craver Track Shape, 26 in Digging		Ride Seat, 2012 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 40 in Digging Bucket, Manual Thumb Usage: 14,360 Hr <b>Asset located in</b> : Lake Worth, TX
	in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 6,775 Hr <b>Asset located in</b> : Lake Worth, TX	468	2020 Cat 315FLCR Tracked Excavator S/N: CAT0315FJTDY14173 C/W: Air Conditioner, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Boom Check Valves, 27.5 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 1,758 Hr Asset located in: St. Rose, LA
462	2012 Cat 320E L Tracked Excavator S/N: CAT0320EJWBK00387 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2011 US EPA Label, 9 ft 6 in Stick, 32 in Triple Craver Track Shape, 36 in Digging		
	in Triple Grouser Track Shoes, 36 in Digging Bucket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 7,386 Hr <b>Asset located in</b> : Lake Worth, TX		2019 Kobelco SK140SRLC-5 Tracked Excavator S/N: YH08015117 C/W: Air Conditioner, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust
CHOIC	E OF 2 - Lot #'s: 463, 464		Fluid, 9 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 36 in Digging Bucket Usage: 2,068 Hr <b>Asset located in</b> : Baton Rouge, LA
463	2006 Komatsu PC200-LC-7 Tracked Excavator S/N: C50926 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX	470	2012 Kobelco SK140SRLC Tracked Excavator S/N: YH0608690 C/W: 2011 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, 31 in Digging Bucket Usage: 6,456 Hr
464	2006 Komatsu PC200LC-8 Tracked Excavator S/N: KMTPC180J54A88082 C/W: 2006 US EPA Label, 9 ft 8 in Stick, 32 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 17,098 Hr Asset located in: Lake Worth, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
471	2019 Cat 313F L GC Tracked Excavator S/N: CAT0313FEHDK10481 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, CARB Compliant, 10 ft 5 in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Rock Guards, Hydraulic Quick Coupler, 19.5 in Digging Bucket Usage: 3,746 Hr Asset located in: Lake Worth, TX	478	2018 Sany SY135C Tracked Excavator S/N: SY013JBJL2718 C/W: Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 43 in Cleanup Bucket Usage: 5,357 Hr Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 473, 474	-478A	2017 Case CX130D Tracked Excavator S/N: DAC130K7NHS7D1310 C/W: Air Conditioner, Air Ride Seat, Rear View
473	2019 Cat 313F L GC Tracked Excavator S/N: ZGS00152 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras,		Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 24 in Triple Grouser Track Shoes, 34 in Digging Bucket, Manual Thumb Usage: 934 Hr Asset located in: Lake Worth, TX
474	10 ft Stick, 27.5 in Track Shoes, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 2,826 Hr Asset located in: Lake Worth, TX 2019 Cat 313F L GC Roadbuilder Tracked	479	2004 Kobelco SK480LC Tracked Excavator S/N: YS06U0308 C/W: US EPA Label, 11 ft 6 in Stick, 36 in Triple Grouser Track Shoes, Hydraulic Quick Coupler Usage: 15,245 Hr
4/4	Excavator  S/N: ZGS00141  C/W: Air Conditioner, Rear & Side View Cameras, 2018 US EPA Label, 10 ft Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,843 Hr  Asset located in: Lake Worth, TX	480	Asset located in: Lake Worth, TX  1996 Cat 350L Tracked Excavator S/N: 3ML00899 C/W: Air Conditioner, Cab Screens, 10 ft Stick, 29.5 in Double Grouser Track Shoes, 46 in Digging Bucket, Catwalks, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 17,997 Hr Asset located in: Humble, TX
CHOICE OF 4 - Lot #'s: 475, 476, 477, 478		480A	2004 Komatsu PC200 LC-7L Tracked Excavator S/N: A86747 C/W: Air Conditioner, Air Ride Seat, 9 ft 6 in Stick, 32 in Triple Grouser Track Shoes, 51 in
475	2019 Sany SY135C Tracked Excavator S/N: SY013JBJM3218 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 48 in Cleanup Bucket Usage: 6,558 Hr Asset located in: Lake Worth, TX	481	Digging Bucket Usage: 11,171 Hr Asset located in: Lake Worth, TX  2001 Komatsu PC200 Tracked Excavator S/N: Not Available C/W: 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 96 in Cleanup Bucket
476	2019 Sany SY135C Tracked Excavator S/N: SY013JBJL6958 C/W: Air Conditioner, 2018 US EPA Label, 8 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 6,291 Hr Asset located in: Lake Worth, TX	CHOIC 482	Usage: Not Available Asset located in: Lake Worth, TX  E OF 4 - Lot #'s: 482, 483, 484, 485  2019 Volvo ECR88D Tracked Excavator
477	2018 Sany SY135C Tracked Excavator S/N: SY013EBJL6208 C/W: Air Conditioner, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 24 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 4,154 Hr Asset located in: Lake Worth, TX		S/N: VCE00E88H00215346 C/W: Air Conditioner, Swing Boom, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,742 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
483	2019 Volvo ECR88D Tracked Excavator S/N: 215385 C/W: Air Conditioner, Tier 4, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, 22 in Digging Bucket, Hydraulic Thumb Usage: 2,972 Hr Asset located in: Lake Worth, TX	490 491	CE OF 2 - Lot #'s: 490, 491  2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETMC500734 C/W: Air Conditioner, 2018 US EPA Label, CARB Compliant, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber
484	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88J00215338 C/W: Air Conditioner, 2019 US EPA Label, Swing Boom, 7 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 901 Hr Asset located in: Lake Worth, TX		Inserts, 38 in Digging Bucket Usage: 1,492 Hr  Asset located in: Lake Worth, TX  2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EVPC800527 C/W: Air Conditioner, 2018 US EPA Label, 5 ft 5 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 28 in Digging
485	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88H00215332 C/W: Air Conditioner, 6 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Boom Check Valves, Backfill Blade, 17.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,792 Hr	CHOICI	Bucket Usage: 1,694 Hr Asset located in: Lake Worth, TX  E OF 4 - Lot #s: 492, 493, 494, 495  2018 Cat 308E2 CR Tracked Excavator
486	Asset located in: Lake Worth, TX  2021 Bobcat E85 Tracked Excavator  S/N: B48414957  C/W: 2020 US EPA Label, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Rubber Tracks, 24 in Digging Bucket, Thumb Bracket Usage: 1,865 Hr	-	S/N: CAT0308ELFJX10405 C/W: Air Ride Seat, Rear View Camera, Swing Boom, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.75 in Triple Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 3,681 Hr Asset located in: Lake Worth, TX
CHOIC 488	Asset located in: Lake Worth, TX  IOICE OF 2 - Lot #'s: 488, 489  8 2022 Cat 308 CR Tracked Excavator S/N: CAT00308HGG805305 C/W: Air Ride Seat, Rear View Camera, 2021 US EPA Label, Swing Boom, 7 ft 10 in Stick,		2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELFJX07584 C/W: Air Conditioner, Air Ride Seat, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, 35.5 in Digging Bucket, Hydraulic Thumb Usage: 3,891 Hr Asset located in: Lake Worth, TX
	Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w/Rubber Inserts, 22 in Digging Bucket, Manual Thumb, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,546 Hr  Notes: EMISSIONS SYSTEM WARRANTY THROUGH MAY 2027 OR 3000 HOURS  Asset located in: Lake Worth, TX	494	2017 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETFJX07574 C/W: Air Conditioner, 2016 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, 18 in Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb Usage: 4,033 Hr
489	2021 Cat 308 CR Tracked Excavator S/N: CAT00308VGG803324 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, Tier 4, 2020 US EPA Label, Swing Boom, 6 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Track Shoes w/Rubber Inserts, 21 in Digging Bucket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,093 Hr Notes: EMISSIONS SYSTEM WARRANTY THROUGH JANUARY 2026 OR 3000 HOURS Asset located in: Lake Worth, TX	495	Asset located in: Lake Worth, TX  2017 Cat 308E2 CR Roadbuilder Tracked Excavator  S/N: CAT0308EEFJX08253  C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, Tier 4, 2017 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Single Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb, Strickland ZX85 MK2 Hydraulic Thumb Usage: 4,117 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
СНОІС	E OF 2 - Lot #'s: 496, 497		E OF 15 - Lot #'s: 501, 502, 503, 504, 505, 506, 507 19, 510, 511, 512, 513, 514, 515	
496	2015 Cat 308E2 CR Tracked Excavator S/N: CAT0308EKFJX02698 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, Tier 4, 2014 US EPA Label, Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Triple Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,281 Hr Asset located in: Lake Worth, TX	501	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55HPAJAL584 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	
497	2014 Cat 308E2 CR Tracked Excavator S/N: CAT0308ETFJX00852 C/W: Air Conditioner, Control Pattern Changer, 2013 US EPA Label, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Double Grouser Track Shoes w /Rubber Inserts, 24 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,625 Hr Asset located in: Lake Worth, TX	502	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55PPAJAL520 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	
498	2014 Cat 308E2 CR Mini Excavator S/N: CAT0308ELFJX00151 C/W: Swing Boom, 7 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 36 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX	503	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55PPAJAL422 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr	
499	2020 John Deere 75G Tracked Excavator S/N: 1FF075GXTKJ017240 C/W: 2019 US EPA Label, 6 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Track Shoes w/Rubber Pads, 30 in Bucket Usage: 2,121 Hr		Notes: WARRANTY AVAILABLE - S DOCUMENTS Asset located in: Lake Worth, TX  504 2023 Yanmar ViO55-6A Mini Excar (Unused)	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX  2023 Yanmar ViO55-6A Mini Excavator (Unused)
500	Asset located in: Lake Worth, TX  2021 Bobcat E60R2 Mini Excavator  S/N: B4GR11148  C/W: Enclosed Cab, Air Conditioner, 2020 US  EPA Label, Swing Boom, 6 ft 4 in Stick, Backfill  Blade, 16 in Rubber Tracks, Manual Quick  Coupler, 24 in Digging Bucket, Hydraulic Thumb  Usage: 2,271 Hr		S/N: YMRVIO55EPAJAL456 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	505	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55JPAJAL786 C/W: Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
506	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55CPAJAL420 C/W: Straight Travel Pedal, Control Pattern Changer, 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb, Yanmar A-T30-V55BKP Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	511	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55LPAJAL848 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	512	2023 Yanmar ViO55-6A Mini Excavator	
507	2023 Yanmar ViO55-6A Mini Excavator (Unused) S/N: YMRVIO55KPAJAL429 C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 5 ft 5 in Stick, Backfill Blade, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr			S/N: YMRVIO55VPAJAL846 C/W: 2023 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thun Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	513	2023 Yanmar ViO55-6A Mini Excavator	
		514	S/N: YMRVIO55EPAJAL702	
508	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55APAJAL461 C/W: 2023 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr		Stick, Auxiliary Hydraulic Plum Rubber Tracks, Hydraulic Quic Digging Bucket, Hydraulic Thu Usage: 2 Hr <b>Notes</b> : WARRANTY AVAILABL DOCUMENTS	Notes: WARRANTY AVAILABLE - SEE
	Notes: WARRANTY AVAILABLE - SEE DOCUMENTS		2023 Yanmar ViO55-6A Mini Excavator	
	Asset located in: Lake Worth, TX		S/N: YMRVIO55LPAJAL454	
509	2023 Yanmar ViO55-6A Mini Excavator S/N: YMRVIO55KPAJAL415 C/W: US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS		Auxiliary Hydraulic Plumbing, Bacl 15.5 in Rubber Tracks, Hydraulic C Coupler, 15.5 in Digging Bucket, H Thumb Usage: 4 Hr	Usage: 4 Hr <b>Notes</b> : WARRANTY AVAILABLE - SEE DOCUMENTS
	Asset located in: Lake Worth, TX	515	2023 Yanmar VIO55-6A Mini Excavator	
510	2023 Yanmar VIO55 Yanmar ViO 55 Mini Excavator S/N: YMRVIO55KPAJAK958 C/W: 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Hydraulic Quick Coupler, 30 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO55HPAJAL553 C/W: 2016 US EPA Label, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 17 in Rubber Tracks, Hydraulic Quick Coupler, Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
CHOIC	E OF 3 - Lot #'s: 516, 517, 518	CHOICI 532, 53	E OF 10 - Lot #'s: 525, 526, 527, 528, 529, 530, 531 3, 534	
516	2019 Cat 305.5E2 Mini Excavator S/N: CAT3055EPWE209294 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 863 Hr Asset located in: Lake Worth, TX	525	2023 Yanmar VIO35-6A Mini Excavator S/N: YMRVIO35APAJAT785 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE	
517	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055EVWE205445 C/W: Enclosed Cab, Air Conditioner, Tier 2,		DOCUMENTS  Asset located in: Lake Worth, TX	
	2017 US EPA Label, 5 ft Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 28 in Digging Bucket Usage: 792 Hr Asset located in: Lake Worth, TX	526	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35APAJAT947 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket,	
518	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055ETWE204417 C/W: Enclosed Cab, Air Conditioner, Tier 2, 2017 US EPA Label, 4 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.75 in Triple Grouser Track Shoes, Manual Quick			Usage: 3 Hr <b>Notes</b> : WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading
	Coupler, 28 in Digging Bucket Usage: 910 Hr  Asset located in: Lake Worth, TX	527	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35JPAJAT581 C/W: Swing Boom, 4 ft 6 in Stick, Backfill	
518A	2018 Cat 305E2 CR Mini Excavator S/N: CAT0305EPH5M06269 C/W: Swing Boom, 5 ft 9 in Stick, Auxiliary Hydraulic Plumbing, 16 in Rubber Tracks, 18 in Digging Bucket		Blade, 12 in Rubber Tracks, Hydi Coupler, 24 in Digging Bucket, H Usage: 3 Hr <b>Notes</b> : WARRANTY AVAILABLE DOCUMENTS	Notes: WARRANTY AVAILABLE - SEE
	Usage: 3,912 Hr Asset located in: Lake Worth, TX	528	2023 Yanmar VIO35 Mini Excavator	
520	2019 Sany SY50U Mini Excavator S/N: SY005CBJZ2158 C/W: Enclosed Cab, Swing Boom, 4 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX	529	Hydraulic Plumbing, 12 in Rubber Hydraulic Quick Coupler, 24 in Dige Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SDOCUMENTS Asset located in: Lake Worth, TX  529 2023 Yanmar ViO35-6A Mini Excav (Unused) S/N: YMRVIO35LPAJAT772 C/W: Swing Boom, 4 ft 6 in Stick, EBlade, 12 in Rubber Tracks, Hydrau Coupler, 24 in Digging Bucket, Hyd Usage: 2 Hr	C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS
522	2017 John Deere 50G Mini Excavator S/N: 1FF050GXCGH285257 C/W: Control Pattern Changer, 2016 US EPA Label, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 4,712 Hr Asset located in: Lake Worth, TX			2023 Yanmar ViO35-6A Mini Excavator (Unused)  S/N: YMRVIO35LPAJAT772  C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE
523	2016 John Deere 50G Mini Excavator S/N: 1FF050GXPGH284631 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 19 in Digging Bucket, Thumb Bracket Usage: 6,107 Hr Asset located in: Lake Worth, TX		DOCUMENTS Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
530	2023 Yanmar VIO35-6A Mini Excavator S/N: YMRVIO35VPAJAT865 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	CHOICI 542, 54 535	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35LPAJAU087 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb	
531	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35VAPJAT722 C/W: 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging		Usage: Not Available  Notes: WARRANTY AVAILABLE - SEE DOCUMENTS  Asset located in: Lake Worth, TX	
	Bucket, Hydraulic Thumb Usage: Not Available Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	536  2023 Yanmar ViO35-6A Mini Excavator (Unused)  S/N: YMRVIO35EPAJAT671  C/W: 2023 US EPA Label, Swing Boom, 4 Stick, Backfill Blade, 12 in Rubber Tracks Hydraulic Quick Coupler, 24 in Digging B Hydraulic Thumb  Usage: 2 Hr  Notes: WARRANTY AVAILABLE - SEE DOCUMENTS  Asset located in: Lake Worth, TX  537  2023 Yanmar VIO35 Mini Excavator  S/N: YMRVIO35VPAJAT851  C/W: Control Pattern Changer, Swing Boft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in D Bucket, Hydraulic Thumb  Usage: 3 Hr  Notes: WARRANTY AVAILABLE - SEE DOCUMENTS  Asset located in: Lake Worth, TX  538  2023 Yanmar VIO35 Mini Excavator (Unit S/N: YMRVIO35CPAJAT808  C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Usage: 2 Hr  Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	(Unused) S/N: YMRVIO35EPAJAT671 C/W: 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks,	
532	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35KPAJAT868 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		Usage: 2 Hr <b>Notes</b> : WARRANTY AVAILABLE - SEE DOCUMENTS	
	Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO35VPAJAT851 C/W: Control Pattern Changer, Swing B ft 6 in Stick, Backfill Blade, 12 in Rubbe	S/N: YMRVIO35VPAJAT851 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber
533	·		Bucket, Hydraulic Thumb Usage: 3 Hr <b>Notes</b> : WARRANTY AVAILABLE - SEE DOCUMENTS	
	Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		S/N: YMRVIO35CPAJAT808 C/W: Swing Boom, 4 ft 6 in Stick, Backfil	C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick
534	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35HPAJAU091 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX		Notes: WARRANTY AVAILABLE - SEE	
		539	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35VPAJAU322 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
540	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35JPAJAT970 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS	546	2021 John Deere 35G Mini Excavator S/N: 1FF035GXLLK291536 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 10 in Digging Bucket Usage: 1,292 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	СНОІСІ	E OF 4 - Lot #'s: 547, 548, 549, 550
541	2023 Yanmar ViO35-6A Mini Excavator (Unused) S/N: YMRVIO35TPAJAT700 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 4 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS Asset located in: Lake Worth, TX	547	2021 John Deere 35G Mini Excavator S/N: 1FF035GXVMK293316 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Bucket Usage: 466 Hr Asset located in: Lake Worth, TX
542	2023 Yanmar ViO35-6A Mini Excavator (Unused)  S/N: YMRVIO35PPAJAT794  C/W: Control Pattern Changer, 2023 US EPA Label, Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb Usage: 3 Hr  Notes: WARRANTY AVAILABLE - SEE	548	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292861 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 729 Hr Asset located in: Lake Worth, TX
	DOCUMENTS  Asset located in: Lake Worth, TX	549	<b>2021 John Deere 35G Mini Excavator</b> S/N: 1FF035GXVMK292537
543	2023 Yanmar VIO35 Mini Excavator S/N: YMRVIO35LPAJAS623 C/W: Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 11.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 922 Hr  Asset located in: Lake Worth, TX
	Usage: 3 Hr Notes: WARRANTY AVAILABLE - SEE DOCUMENTS, X1 - Updated odometer reading Asset located in: Lake Worth, TX	550	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292536 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary
544	2023 Yanmar VIO35 Mini Excavator (Unused) S/N: YMRVIO35APAJAT625 C/W: Swing Boom, 4 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb		Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in Bucket Usage: 1,134 Hr <b>Asset located in</b> : Lake Worth, TX
	Usage: 3 Hr <b>Notes</b> : WARRANTY AVAILABLE - SEE DOCUMENTS	СНОІС	E OF 2 - Lot #'s: 551, 9623C
	Asset located in: Lake Worth, TX	551	2017 John Deere 35G Mini Excavator
545	Yanmar V1035-5B Mini Excavator S/N: YMRVI035J8YY53169 C/W: 2008 US EPA Label, Swing Boom, 4 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket, Thumb Bracket Usage: 7,897 Hr		S/N: 1FF035GXEHK279948 C/W: Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket, Thumb Bracket Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
553	2007 John Deere 35D Mini Excavator S/N: FF035DX237345 C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket Usage: 8,759 Hr Asset located in: Lake Worth, TX  2016 Bobcat E35I Mini Excavator	560	2015 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM01212 C/W: Control Pattern Changer, Tier 4, 2015 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	
	S/N: AUYM13355 C/W: Enclosed Cab, Control Pattern Changer,		Asset located in: Lake Worth, TX	
	Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket Usage: 2,462 Hr  Asset located in: Midland, TX	S/N: NSUC37CRNZLN55583 C/W: 2017 US EPA Label, Swing Boom, Stick, Auxiliary Hydraulic Plumbing, Bac Blade, 12 in Rubber Tracks, 18 in Diggir Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REFROM YARD BY JANUARY 10TH AND GERELISTED; BUYER'S RESPONSIBILIT REMOVAL	C/W: 2017 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket	
555	2012 Komatsu PC35MR Mini Excavator S/N: KMTPC201C04018745 C/W: 2012 US EPA Label, Swing Boom, 5 ft 6 in Stick, Backfill Blade, 12 in Track Shoes w /Rubber Pads, 24 in Cleanup Bucket, Hydraulic Thumb		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR	
	Usage: Not Available	562	2006 Komatsu PC27MR-2 Mini Excavator	
	Asset located in: Lake Worth, TX		S/N: 16215 Usage: Not Available	S/N: 16215 Usage: Not Available
556	Hitachi ZX35U-5N Mini Excavator S/N: HCMADG60E00273351		Asset located in: Lake Worth, TX	
	C/W: Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 6,514 Hr Asset located in: Humble, TX	563	2017 Bobcat E26 Mini Excavator S/N: B3JE13055 C/W: Swing Boom, 3 ft 6 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 2,327 Hr Asset located in: Lake Worth, TX	
558	2018 Cat 303E CR Mini Excavator S/N: CAT0303EAHHM02733 C/W: Tier 4, 2017 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 24 in Digging Bucket, Thumb Bracket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 590 Hr Asset located in: Lake Worth, TX	564	2017 Takeuchi TB260 Mini Excavator S/N: 126102065 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Thumb Bracket, EQUIPMENT FROM UNITED RENTALS Usage: 3,025 Hr Asset located in: Lake Worth, TX	
CHOICE OF 2 - Lot #'s: 559, 560		565	<b>2021 Bobcat E20 Mini Excavator</b> S/N: B3BL19286 C/W: Control Pattern Changer, 2021 US EPA	
559	2016 Cat 303E CR Mini Excavator S/N: CAT0303EVHHM01984 C/W: Tier 4, 2016 US EPA Label, Swing Boom, 4 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Cleanup Bucket, Thumb Bracket, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 2,021 Hr Asset located in: Lake Worth, TX		Label, Swing Boom, 4 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 12 in Digging Bucket Usage: 753 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
CHOICE OF 4 - Lot #'s: 566, 567, 568, 569		572	2004 Cat M318C Wheel Excavator S/N: CATM318CPBCZ00846 C/W: 2 Piece Hyd. Boom, 9 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Front and Rear	
566	56 2022 John Deere 17G Mini Excavator S/N: 1FF017GXJNK232661 C/W: Control Pattern Changer, 2022 US EPA Label, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 401 Hr Asset located in: Lake Worth, TX		Stabilizers, 10.00x20 Tires, 78 in Hydraulic Tilting Bucket Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
		573	Gradall XL3300 Wheel Excavator S/N: 0210017540 C/W: Backfill Blade, Stabilizers, 60 in Cleanup Bucket, Additional 30 in Digging Bucket Usage: 2,899 Hr	
567	2021 John Deere 17G Mini Excavator		Asset located in: Lake Worth, TX	
	S/N: 1FF017GXPMK231345 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary	574	2003 Mantis 3612 18 ton Telescopic Crawler Crane	
	Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Bucket Usage: 467 Hr		S/N: 36250 C/W: Anti Two-Block, PAT DS160 Load Moment Indicator, 2002 US EPA Label, 29 ft Minimum 71 ft Maximum Boom Length,	
568	Asset located in: Lake Worth, TX  2021 John Deere 17G Mini Excavator	1	Rooster Sheave, Overhaul Ball, Counterweight Removal System, 30 in Triple Grouser Track Shoes, Expandable Width Tracks	
000	S/N: 1FF017GXLMK231337 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary		Usage: 7,472 Hr  Asset located in: Humble, TX	
		575	2011 Link-Belt HTC8675 75 ton 8x4 Series II Hydraulic Truck Crane S/N: 1F9P9K221CL028751 C/W: Air Conditioner, 13310 hrs Carrier Engine,	
	Asset located in: Lake Worth, TX		Cat C13 8 Cylinder Diesel Carrier Engine, Air	
569	2021 John Deere 17G Mini Excavator S/N: 1FF017GXTMK231117 C/W: Control Pattern Changer, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Manual Quick Coupler, 12 in Digging Bucket Usage: 479 Hr		Conditioner, Anti Two-Block, Hirschmann Load Moment Indicator, 34 ft Minimum 113 ft Maximum Boom Length, Rooster Sheave, Bifold Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 356 lb Overhaul Ball, 18400 lb Counterweight, Counterweight Removal System Usage: 1,190 Mi	
	Asset located in: Lake Worth, TX	_	Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION	
569A	<b>2018 Yanmar SV08-1B Mini Excavator</b> S/N: YMRSV08YEJBJBF106		AVAILABLE IN OFFICE - MSO ;	
	C/W: 2017 US EPA Label, Swing Boom, 2 ft 3 in	F76	Asset located in: Lake Worth, TX	
	Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Expandable Width	576	2001 Link-Belt RTC-8075 70 ton 4x4x4 Rough Terrain Crane	
	Tracks, 14 in Digging Bucket Usage: 1,259 Hr		S/N: D7J1-5709LB C/W: Air Conditioner, Anti Two-Block,	
	Asset located in: Lake Worth, TX		Microguard 534 Load Moment Indicator, 4994	
571	JCB HD110W Wheel Excavator S/N: JCBW11CFEN3148944 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Swing Boom, 6 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9-20 Tires, Steelwrist X12 650-650 GR FPL Tiltrotator Attachment Usage: 202 Hr		hp 8.3 L Diesel Engine, 41 ft Minimum 1 Maximum Boom Length, Auxiliary Hois Rooster Sheave, 39.5 ft to 67 ft Bifold Swingaway Offset Jib, 1502 lb 65 ton C Johnson 5 Sheave Hook Block, Overha	Swingaway Offset Jib, 1502 lb 65 ton Capacity Johnson 5 Sheave Hook Block, Overhaul Ball, 15000 lb Counterweight, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 4,994 Hr
Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
577 577A	2008 Link-Belt RTC-8065 Rough Terrain Crane S/N: J8J815707 C/W: EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 11,117 Hr Asset located in: Humble, TX  2008 Link-Belt 8065 65 ton 4x4x4 Rough Terrain Crane S/N: J9J80231 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator,	581	2008 Link-Belt RTC 8050 II 50 ton 4x4x4 Rough Terrain Crane S/N: J6J8-9992 C/W: Microguard 534 Load Moment Indicator, 12354 hrs Crane Operation, Cummins B5.9C 6 Cylinder 173 hp 5.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 33 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Bifold Swingaway Offset Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, Overhaul Ball Usage: 12,353 Hr
	11140 hrs Crane Operation, Cat C6.6 Acert 6		Asset located in: Humble, TX
	Cylinder 6.6 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 35 ft to 58 ft Bifold Swingaway Offset Jib, 1154 lb 70 ton Capacity Johnson 5 Sheave Hook Block, 347 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 11,225 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Humble, TX	582	<b>2011 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane</b> S/N: 231622 C/W: Air Conditioner, Anti Two-Block, PAT iFlex5 Load Moment Indicator, 11660 hrs Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball Usage: 11,660 Hr
<del></del> 578	2001 Link-Belt RTC-8065 65 ton 4x4x4 Rough	<b>-</b>	Asset located in: Humble, TX
	Terrain Crane S/N: D7J1-5707 C/W: Air Conditioner, Anti Two-Block, Link Belt MicroGuard 534 Load Moment Indicator, 6824 hrs Crane Operation, Cummins C8.3C 6 Cylinder 215 hp 8.3 L Diesel Engine, 38 ft Minimum 115 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 36.5 ft to 61 ft Bifold Swingaway Offset Jib, 1103 lb 60 ton Capacity Johnson 4 Sheave Hook Block, 350 lb 8.5 ton Capacity Overhaul Ball, 12000 lb Counterweight, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 6,828 Hr	583	2009 Grove RT600E 50 ton 4x4x4 Rough Terrain Crane S/N: 229898 C/W: Air Conditioner, Anti Two-Block, PAT Load Moment Indicator, 10124 hrs Crane Operation, Cummins QSB 6 Cylinder 173 hp 6.7 L Diesel Engine, 33 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson 3 Sheave Hook Block, Overhaul Ball Usage: 10,124 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	584	1998 Grove RT880 Rough Terrain Crane
579	2012 Grove RT765E-2 65 ton 4x4x4 Rough Terrain Crane	Terrain Crane S/N: 83337 C/W: Anti Two-Block, PAT DS 350 GW L Moment Indicator, Cummins cbd126 6 128 hp Diesel Engine, 28 ft Minimum 70 Maximum Boom Length, 566 lb 30 ton	Usage: Not Available
	S/N: 232495 C/W: Air Conditioner, Anti Two-Block, Hirschmann iScout Load Moment Indicator, 7421 hrs Crane Operation, 2011 US EPA Label, Cummins QSB 6 Cylinder 240 hp 6.7 L Diesel Engine, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 56 ft Bifold Swingaway Offset Jib, 1252 lb 66 ton Capacity Johnson 5 Sheave Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball, Counterweight Removal System Usage: 7,421 Hr		S/N: 83337 C/W: Anti Two-Block, PAT DS 350 GW Load Moment Indicator, Cummins cbd126 6 Cylinder 128 hp Diesel Engine, 28 ft Minimum 70 ft Maximum Boom Length, 566 lb 30 ton Capacity McKissick 3 Sheave Hook Block Usage: 511 Hr
	Asset located in: Humble, TX	585A	P & H Century II 22 ton 4x4 Rough Terrain
580	2006 Grove RT760E Rough Terrain Crane S/N: 226196 Usage: Not Available Asset located in: Humble, TX		Crane S/N: 32R1032 C/W: Anti Two-Block, PAT Load Moment Indicator, 8653 hrs Crane Operation, Detroit 4087-7100 V8 Diesel Engine, 29 ft Minimum 72 ft Maximum Boom Length, Swingaway Jib, Overhaul Ball Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details	
586	Elliott 45142 Straight Boom on 2016 Peterbilt 367 12x6 Boom Truck  S/N: 1NPTX4TX4GD307479  C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4016 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 22000 lb Front Axle, 72600 lb Rears, 89000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Steerable Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Air Trac Air Ride Suspension, 278 in Wheelbase, PTO, 45 ton Capacity, Center Mounted, 34 ft - 142 ft 5 Section Boom, McKissick 592 lb 2 Sheave 25 ton Capacity Hook Block, 31 ft Min - 55 ft Max Jib, Rooster Sheve, Anti-Two Block, Greer Load	591	2018 Barreto E1324STK-4MS Walk Behind Trencher S/N: STK202 C/W: 2021 US EPA Label, Honda GX390 1 Cylinder Gasoline Engine, Hydrostatic Drive, 5 in Wide x 24 in Long Combination Trencher Chain, 7 in Rubber Tracks Usage: 303 Hr Asset located in: Lake Worth, TX	
		592	2007 Ditch Witch RT36 4x4 Trencher S/N: CMWRT36XJ70000141 C/W: Deutz Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Combination Trencher Chain, Angle Blade Usage: 1,182 Hr Asset located in: Lake Worth, TX	
	Moment Indicator, Enclosed Cab, w/ Air Conditioner, Out and Down Outriggers, Rear Outriggers, 21 ft 6 in x 96 in Bed Usage: 17,970 Mi <b>Asset located in</b> : Lake Worth, TX	593	2004 Charles Machine Works 3700DD 4x4 Trencher S/N: 3Y0864 C/W: Canopy, Diesel Engine, 5 in Wide x 87 in Long Dirt Trencher Chain, A322 Backhoe	
587	2007 International 4200 4x2 Boom Truck S/N: 1HTMPAFN37H426012 C/W: International A215 4 Cylinder 6.0 L Diesel 200 hp Engine, 2006 US EPA Label, 11193 Engine hrs, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring Suspension, 236 in Wheelbase, PTO, 34000 lb Capacity, Center Mounted, 27 ft - 70 ft 3 Section Boom, McKissick 170 lb 1 Sheave 7 ton Capacity Hook Block, Dual Controls, A-Outriggers, Rear Outriggers, 20 ft 0 in x 96 in Bed Usage: 103,701 Mi		Attachment, Straight Blade Usage: 1,924 Hr <b>Asset located in</b> : Lake Worth, TX	
		594	2007 Ditch Witch RT155H 4x4 Trencher S/N: CMWRT115E70000255 C/W: Canopy, US EPA Label, John Deere 4 Cylinder 82 kW 4.5 L Diesel Engine, Hydrostatic Drive, 10 in Wide x 80 in Long Dirt Trencher Chain, Crumbling Shoe Usage: 452 Hr	
		595	Asset located in: Lake Worth, TX	
588	Asset located in: Lake Worth, TX  Ditch Witch C99 Walk Behind Trencher  S/N: 116761  C/W: Gasoline Engine, 6 in Wide x 3 ft Long Dirt  Trencher Chain, Discharge Conveyor		S/N: 1VRT1124411000207 C/W: Canopy, Hydrostatic Drive, 6 ir	C/W: Canopy, Hydrostatic Drive, 6 in Wide x 9 ft 3 in Long Dirt Trencher Chain, Straight Blade Usage: 2,431 Hr
	Usage: Not Available  Asset located in: Lake Worth, TX	596	2015 Ditch Witch RT45 4x4 Trencher	
589	2000 Vermeer LM11 Walk Behind Cable Plow S/N: 1VRP04095Y1000294 C/W: Kawasaki FE350 Gasoline Engine, 6 in Rubber Tracks Usage: Not Available		C/W: Deutz I in Wide x 64 Straight Blad Usage: 996 F	S/N: CMWRT45XEF0002812 C/W: Deutz Diesel Engine, Hydrostatic Drive, 6 in Wide x 64 in Long Rock Trencher Chain, Straight Blade, Side Shift Usage: 996 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	597	2018 Vermeer RTX450 Trencher	
590	Barreto Trencher S/N: M2913 C/W: Honda gx270 Gasoline Engine, 3 ft 6 in Cable Plow, 4 in Wide x 39 in Long Dirt Trencher Chain Usage: 73 Hr Asset located in: Lake Worth, TX		S/N: 1VR4092U0J1003787 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	

Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 599, 600	605	1978 (unverified) Cleveland H320 Tracked Bucket Wheel Trencher S/N: 325300
599	2014 Vermeer T755III Tracked Trencher S/N: 1VR2160RXE1000550 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, Cat C9 6 Cylinder 746 hp 8.8 L Diesel Engine, 16 in Wide x 11 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 2,792 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Cat D330 4 Cylinder Diesel Engine, Manual Transmission, 27 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK
600	2012 Vermeer T755III Tracked Trencher	Сноіс	E OF 2 - Lot #'s: 606, 607
	S/N: 1VR2160R3C1000516 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C9 375 hp Diesel Engine, 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,066 Hr Asset located in: Lake Worth, TX	606	1974 Cleveland S320 Tracked Bucket Wheel Trencher S/N: K427 C/W: Canopy, Diesel Engine, Manual Transmission, 26 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available
601	<b>2007 Vermeer T755III Tracked Trencher</b> S/N: 1VR2190S371000123 C/W: Enclosed Cab, Air Conditioner, 2007 US EPA Label, Cat C9 6 Cylinder 480 hp 8.8 L	607	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.  Asset located in: Lahoma, OK
	Diesel Engine, 16 in Wide x 12 ft Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Double Grouser Track Shoes, Auto lube, Elevating Cab Usage: 5,025 Hr Asset located in: Lake Worth, TX		1969 Cleveland 320 Tracked Bucket Wheel Trencher S/N: K414 C/W: Enclosed Cab, Cat D333 6 Cylinder Diesel Engine, Manual Transmission, 25.5 in
602	2009 Tesmec TRS975 Tracked Trencher S/N: 975-111 C/W: Enclosed Cab, Air Conditioner, Cat C9DI 6 Cylinder 300 hp Diesel Engine, Hydrostatic Drive, 23 in Wide x 186 in Long Rock Trencher Chain, Crumbling Shoe, Discharge Conveyor, 24 in Single Grouser Track Shoes		Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK
	Usage: 4,256 Hr	608	1962 Cleveland 320 Trencher
603	Asset located in: Midland, TX  2000 Tesmec 1075 Tracked Trencher  S/N: 15211  C/W: Enclosed Cab, Air Conditioner, Cat 6  Cylinder Diesel Engine, Hydrostatic Drive, 24 in Trenching Width, 160 in Trenching Depth,	СНОІСЕ	S/N: K364 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES . Asset located in: Lahoma, OK
	Discharge Conveyor, Side Shift, Hydraulic Leveling, 22 in Single Grouser Track Shoes Usage: 185 Hr <b>Asset located in</b> : Midland, TX		E OF 2 - Lot #'s: 609, 610
604	1997 Trencor 960HD Tracked Trencher S/N: 136 C/W: Enclosed Cab, Air Conditioner, 6 Cylinder Engine, Trencor Cable Plow, 26 in Trenching Width, 84 in Trenching Depth, Discharge Conveyor, 24 in Triple Grouser Track Shoes Usage: 5,333 Hr Asset located in: Lake Worth, TX	609	1959 (unverified) Cleveland 320 Tracked Bucket Wheel Trencher  S/N: K328  C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, Manual Transmission, 21 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes  Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.

Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
610	Cleveland 350 Tracked Bucket Wheel Trencher S/N: 3514110 C/W: Canopy, Cat 3304 4 Cylinder 165 hp Diesel Engine, Manual Transmission, 42 in Trenching Width, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	614	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XLE0002319 C/W: 2004 US EPA Label, Deutz D2011 3 Cylinder 42 hp 2.33 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 3 in Long Dirt Trencher Chain Usage: 2,034 Hr Asset located in: Lake Worth, TX	
610A	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK Tracked Bucket Wheel Trencher	615	2014 Ditch Witch RT45 4x4 Trencher S/N: CMWRT45XHE0002029 C/W: US EPA Label, Deutz 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 in Wide x 5 ft 5 in Long Dirt Trencher Chain, Straight Blade Usage: 989 Hr	
	S/N: K280 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 42 in Trenching Width, 84 in Trenching Depth, 18 in Single Grouser Track Shoes Usage: Not Available Asset located in: Oklahoma City, OK	616	Asset located in: Lake Worth, TX  2011 Ditch Witch RT45 4x4 Trencher Cable Plow  S/N: CMWRT45XJC0001226  C/W: Canopy, 2011 US EPA Label, Deutz d2011  3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, Ditch Witch 5 ft 6 in Cable Plow, 6 in Wide x 5 ft 6 in Long Dirt Trencher	
610B	Tracked Bucket Wheel Trencher S/N: K364 C/W: Canopy, Cat D339 6 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching	447	Chain Usage: 2,614 Hr <b>Asset located in</b> : Lake Worth, TX	
	Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available <b>Asset located in</b> : Oklahoma City, OK	617	2014 Ditch Witch RT45 4x4 Trencher Cable Plow S/N: CMWRT45XLE0002028 C/W: Canopy, 2011 US EPA Label, CARB	
610C	Cleveland 350S Tracked Bucket Wheel Trencher S/N: 3512290 C/W: Canopy, Cat 3304PC 4 Cylinder Diesel Engine, Manual Transmission, 24 in Trenching Width, 72 in Trenching Depth, Discharge Conveyor, 24 in Single Grouser Track Shoes Usage: Not Available		Compliant, Deutz D2011L03 3 Cylinder 42 hp 2.3 L Diesel Engine, Hydrostatic Drive, 5 ft 4 in Cable Plow, 6 in Wide x 6 ft 4 in Long Combination Trencher Chain, Discharge Conveyor, H314 Traversing Trencher Attachment s/n: CMWH314XCD0002861 Usage: 2,993 Hr Asset located in: Lake Worth, TX	
611	Asset located in: Oklahoma City, OK  1957 Cleveland 320 Trencher S/N: K280	618	S/N: 1VRB360W5G1000135 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Drill Rod Loading	C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, Drill Rod Loading
	Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.		System 8 Drill Rods, 18 in Triple Grouser Track Shoes Usage: 4,790 Hr <b>Asset located in</b> : Lake Worth, TX	
612	Asset located in: Lahoma, OK  Cleveland 320 Trencher  S/N: K285  Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK	619	2019 Vermeer D23x30III Directional Drill S/N: 1VRN20074K1001288 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Drill Rod Loading System 22 Drill Rods, 12 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX	
613	1979 Cleveland 350S Trencher S/N: 3512290 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	620	2017 Vermeer 20X22III Directional Drill S/N: 1VRA170V3H1000764 C/W: 2016 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, Drill Rod Loading System 31 Drill Rods, 11 in Rubber Tracks Usage: 2,859 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
621	2019 Ditch Witch JT20 Directional Drill S/N: DWPJT20BAK0000234 C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, Drill Rod Loading System 39 Drill Rods, 11 in Rubber Tracks Usage: 3,005 Hr Asset located in: Lake Worth, TX	630	2022 Ditch Witch HX30G 500 gal T/A Vacuum Excavation Unit  S/N: 1DST522N2N1701879  C/W: Spring Suspension, Electric Brakes, Steel Debris Tank, 500 gal Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Blower, 235/80R16 Tires, 2022 US EPA Label, Vanguard NBSXS.9932VB 2 Cylinder 31
622	2017 Ditch Witch JT20 Directional Drill w/2016 Felling FT24 Trailer S/N: CMWJT20XKH0000950 C/W: Open Operator Station, Deutz 4 Cylinder Diesel Engine, 30 Drill Rods, 11 in Rubber Tracks, T/A Trailer w/ S/N- 5FTEE2923G1003458, Lunette Ring, Electric Brakes, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY		hp 896 cc Gasoline Engine Usage: 162 Hr  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	631	2011 Ditch Witch FX30 800 gal T/A Vacuum
CHOIC	CHOICE OF 2 - Lot #'s: 624, 625		Excavation Unit  S/N: 1DSB202S5B1702339  C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Rear Hose Reel, 800 gal Fresh Water Tank, Manual
624	2020 Vermeer LP573XDT T/A Vacuum Excavation Unit S/N: 5HZJ16231LK002166 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 2020 Vermeer LP573XDT Steel Debris Tank, Rear Hose Reel, Fresh Water Tank,		Tailgate Locks, 8 ft Telescopic Boom, 4 in Suction Hose, Engine Driven Pump, 215/75R17 5 Tires, 18000 lb GVWR, Kubota D1105-T 3 Cylinder 1.1 L Diesel Engine Usage: 2,095 Hr Asset located in: Lake Worth, TX
	Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Wash Down System, 3 in Suction Hose, Vac-Tron Engine Driven Pump, Vac-Tron 200257 Blower, Remote Control w/ Cord, 235 /80R16 Tires, 12000 lb GVWR, 2019 US EPA Label, CARB Compliant, Kohler KKHXL1.37SF1 3 Cylinder 23.4 hp 1.02 L Diesel Engine Usage: Not Available Asset located in: Midland, TX	632	2011 Vermeer VX50500 Vacuum Excavation Unit  S/N: 1M9FE122XBS284256 C/W: Ball Hitch, Spring Suspension, Electric Brakes, McLaughlin Mfg Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Engine Driven Pump, 235/80R16 Tires, 12000.0 lb
625	2020 Vermeer Lp573xdt T/A Vacuum		GVWR, 3 Cylinder Diesel Engine Usage: Not Available
	Excavation Unit		Asset located in: Lake Worth, TX
	S/N: 5HZJ16235LK002140 C/W: Aluminum Frame, Lunette Ring Hitch, 2019 VERMEER Debris Tank, Fresh Water Tank, 235/80R16 Tires, 1200 lb GVWR, 2019 US EPA Label, Kohler 8 kW Diesel Engine Usage: 475 Hr Asset located in: Lake Worth, TX	633	Vermeer Air 573 SDT Vacuum System S/N: 181403 C/W: Torsion Axle, Electric Brakes, Vermeer Air573SDT Steel Debris Tank, Fresh Water Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Wash Down System, 3.5 in Suction Hose, Aanovi reverberi Engine Driven Pump,
CHOICE OF 2 - Lot #'s: 628, 9628A			Vactron 59URAI Blower, Remote Control w/ Cord, 235/80R16 Tires, 20000 lb GVWR, 4 Cylinder Diesel Engine, Vermeer Vactron
628	2017 LOKT T/A Vacuum Excavation Unit S/N: 4M9E2TG23HE015031 C/W: Lunette Ring Hitch, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Drop Down Tailgate, Engine Driven Pump, 215/75R17.5 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available		System, 4 Cylinder Diesel, Control Panel w/ Display, Rear Lift Door, Rear Hydraulic Hose Reels, Poly Water Tanks; EQUIPMENT-FRON WATKINS-CONSTRUCTION Usage: 316 Hr Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
634	2000 Vermeer Vac-tron Vacuum Excavation Unit S/N: 1A9AF152XYF495615 C/W: Lunette Ring Hitch, Spring Suspension, Steel Debris Tank, Fresh Water Tank, Full Open Tailgate, Manual Tailgate Locks, 235/85R16 Tires, Kohler 2 Cylinder Gasoline Engine	640	2009 McCloskey 621RE Screen Plant S/N: 11915 Usage: Not Available Asset located in: Lake Worth, TX  E OF 4 - Lot #'s: 641, 642, 643, 644
	Usage: Not Available  Asset located in: Lake Worth, TX	СПОІС	E OF 4 - LOT # 5. 041, 042, 043, 044
635	64'	641	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused)  S/N: M202409548  C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	UNAVAILABLE ON THIS ITEM. BUYER WILL NEED TO SET UP OUTSIDE ASSISTANCE.  Asset located in: Lake Worth, TX	642	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409547
636	2012 Powerscreen XH250 Impact Crusher S/N: PIDXH250A0MC55102 C/W: Terex 7 ft Belt Feeder Terex CR004 Jaw Crusher, 2012 US EPA Label, Cat 6.6 L Diesel Engine, 16 in Triple Grouser Track Shoes Usage: Not Available Asset located in: Lake Worth, TX		C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
637	2023 Ark K-JC503 Jaw Crusher S/N: 323878 C/W: 1 ft 4 in x 6 ft 6 in Belt Feeder 12 in Rubber Tracks Usage: 186 Hr Asset located in: Lake Worth, TX	643	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused)  S/N: M202409550  C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available
638	· · · · · · · · · · · · · · · · · · ·		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	in Wide Under Screen Conveyor, 41 in Wide Left Discharge Conveyor, Cat 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 15.75 in Triple Grouser Track Shoes Usage: 307 Hr Asset located in: Lake Worth, TX	644	2024 Vickwest PRS36-60 Portable 36 in x 60 ft Conveyor (Unused) S/N: M202409549 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring
639	2020 Terex/Finlay 883 Tracked Screen Plant S/N: TRX883M4CDGLB3827 C/W: 8 ft 7 in x 16 ft Apron Feeder 16 ft x 5 ft Double Deck Screen, 35 in Wide Fines Discharge Conveyor, 47 in Wide Under Screen Conveyor, 31 in Wide Left Discharge Conveyor, 2020 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Hydraulic Leveling, 15.75 in Triple Grouser Track Shoes Usage: 1,040 Hr Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		645	JCT Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
646	2012 Klein KPT-120 12000 gal S/A Water Tower S/N: 40797 C/W: Hydraulic Raise, Gasoline Engine Driven Hydraulic Power Pack, 12 in Downspout, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	655 CHOIC —656	2005 Cat AP-655C Track Asphalt Paver S/N: CATAP655PAYP00240 C/W: Dual Controls, Carlson Electric Heated 8 ft - 13 ft 6 in Screed, 16 in Rubber Tracks Usage: Not Available Asset located in: Lake Worth, TX  E OF 2 - Lot #'s: 656, 657  2001 Cat AP-650B Track Asphalt Paver
648	2020 RoadHog RH60250 60" Wheel Loader Cold Planer Attachment S/N: 2009026 C/W: Cat C7.1, 250hp, Diesel, Diesel Exhaust Fluid, Q/C, Side Shift, 80 Gallon Water Tank Usage: 37 Hr Asset located in: Lake Worth, TX		S/N: 9DN00434 C/W: Fume Extractor, Cat 7MR02145, 8-16B Diesel Heated 8 ft 4 in - 15 ft 8 in Screed, 13.5 in Single Grouser Track Shoes w/Rubber Inserts Usage: Not Available Asset located in: Lake Worth, TX
649	2018 Bomag RS460 Wheel Soil Stabilizer Reclaimer S/N: 101590161008 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires AdBlue, 96 in Rotor, Water /Emulsion Application System, 19.7 in Cutting	657	2000 Cat AP-650B Track Asphalt Paver S/N: 9DN00414 C/W: 8 ft 4 in - Screed, 14 in Track Shoes w /Rubber Inserts Usage: 6,827 Hr Asset located in: Lake Worth, TX
650	Depth Usage: 1,584 Hr Asset located in: Baytown, TX  2016 Cat RM300 Wheel Soil Stabilizer	658	Roadtec RP195 Track Asphalt Paver S/N: 10950808 C/W: Dual Controls, Carlson Electric Heated 10 ft - 19 ft Screed, 18 in Rubber Tracks
030	Reclaimer  S/N: CATRM300HBWR00791  C/W: Canopy, 96 in Soil Rotor, EQUIPMENT-FROM-PULICE-CONSTRUCTION  Usage: 4,284 Hr  Asset located in: Humble, TX		Usage: Not Available  Asset located in: Lake Worth, TX
		659	2007 Mauldin 1750C Track Asphalt Paver S/N: 879G75TJS6Y201879 C/W: Dual Controls, Propane Heated 7 ft 6 in - 16 ft Screed, 12 in Track Shoes w/Rubber Pads
651	Bomag MPH364R-2 Wheel Soil Stabilizer Reclaimer S/N: Not Available C/W: Canopy, 2013 US EPA Label, 84 in		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Combination Rotor, 14 in Cutting Depth, Water /Emulsion Application System Usage: 3,562 Hr <b>Asset located in</b> : Poteau, OK	660	Mauldin 690G Track Asphalt Paver S/N: 459Q69TKS8Y203459 C/W: Dual Controls, Propane Heated 8 ft 1 in - 13 ft 3 in Screed, 12 in Rubber Tracks
652	<b>2021 Vogele S2100-31 Track Asphalt Paver</b> S/N: 08192375		Usage: 934 Hr Asset located in: Lake Worth, TX
	C/W: Canopy, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in - 9 ft 8 in Screed, 12 in Rubber Tracks Usage: 2,345 Hr <b>Asset located in</b> : Humble, TX	661	1982 Blaw-Knox RW100 Road Widener S/N: 956003 C/W: Open Operator Station, John Deere Engine, Automatic Transmission, 10 " Spreader
653	2011 Cat AP1055E Asphalt Paver S/N: TJF00111 Usage: 17,076 Hr Asset located in: Lake Worth, TX		Width, Truck Hitch, Open Operator Station, Dual Controls, John Deere 4 Cylinder Diesel Engine, Hydrostatic Drive, - 10 ft Spreading Width, Truck Hitch, 20 in Conveyor Usage: 430 Hr Asset located in: Poteau, OK
654	Cat BG-260C Wheel Asphalt Paver S/N: CATBG260C8GN00575 Usage: Not Available Asset located in: Lake Worth, TX	662	1995 Etnyre K Series Chip Spreader S/N: K5706 C/W: Open Operator Station, Diesel Engine, 11 ft - Spreader Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
663	2016 Crafco 125D Asphalt Kettle S/N: 1C9SV1221G1418015 C/W: 125 gal Capacity Tank, Diesel Fired Heater, Hydraulic Agitator, Hydraulic Driven Pump, Hose & Wand, Air Compressor, T/A Trailer Mounted Usage: 554 Hr Asset located in: Lake Worth, TX	671	Finn T-30 Hydroseeder S/N: RUA730 C/W: Ball Hitch, Spring Suspension, ST8-14.5 Tires, Aluminum Tank, Gasoline Powered Pump, T/A Utility Trailer Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY;
664	Etnyre 2000 gal on 2002 GMC C7500 4x2		Asset located in: Lake Worth, TX
	Asphalt Distributor Truck  S/N: 1GDM7H1C82J513848  C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 5-Speed Manual Transmission, 11000 lb Front Axle, 22000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 13 ft 2 in	672	2011 Barko 930B 4x4 Mulcher Tractor S/N: 11293023740 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Fecon Mulcher, Winch Usage: 5,000 Hr Asset located in: Lake Worth, TX
	Folding Spray Bar, Diesel Burners, In-Cab Controls Usage: 50,865 Mi <b>Asset located in</b> : Lake Worth, TX	674	Demco Model HP 60 ft T/A Pull-Type Sprayer S/N: Not Available C/W: 540 PTO, ISOBUS, PTO Driven Pump, 500
665	2016 Cimline 410 Magma Pothole Patcher S/N: 1G9441622GM119018 C/W: Isuzu 3cj1 4 Cylinder .99 L Diesel Engine, 225/75R15, Spring Suspension, Diesel Heating System Usage: 1,838 Hr Asset located in: Lake Worth, TX		gal Poly Tank, Chemical Mix Tank, Rinse Tank, Single Nozzle Bodies, Fence Row Nozzles, 11l- 15, Hydraulic Fold Booms, Guidance and Auto Steer Ready, Section Control, 29 In. Ground Clearance, Dual Agitators, Front Tank Walkway Usage: Not Available Notes: PERSONAL SPRAYER FOR LONGTIME CUSTOMER - FULLY OPERATIONAL
667	2008 (unverified) Valmet 430FXL Track Feller		Asset located in: Lake Worth, TX
668	S/N: AT4K-2992-052108 C/W: Air Conditioner, Hydraulic Tilting Cab, US EPA Label, Quadco OFH 22 in Feller Buncher, 27.5 in Single Grouser Track Shoes, Rock Guards Usage: 969 Hr Asset located in: St. Rose, LA  2014 John Deere 648H 4x4 Skidder	675 676	E OF 2 - Lot #'s: 675, 676  2023 Bell TC7A Crawler Carrier S/N: AEBK607AA01000128 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks,
	S/N: 1DW648HXKED658603 C/W: Air Conditioner, Air Ride Seat, Sweeps, Screens, Blade, John Deere Grapple, Single Arch, John Deere Single Drum Winch, 30.5L32 Tires, Floatation Tires Usage: 9,491 Hr		EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 30 Hr Asset located in: Lake Worth, TX  2022 Bell TC7A Crawler Carrier S/N: AEBK607AC01000118
669	Asset located in: Lake Worth, TX  2003 Cat 525B 4x4 Line Skidder S/N: CAT0525BK3KZ00929 C/W: Air Conditioner, Blade, Single Arch, cat Single Drum Winch, 30.5x32 Tires Usage: Not Available Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Long x 15 in High Flatbed Dump Body, 27 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 26 Hr  Asset located in: Lake Worth, TX
670	<b>2013 John Deere 2954D Log Loader</b> S/N: 1FF2954DED0290150 C/W: Air Conditioner, Air Ride Seat, Cab	сноіс	E OF 3 - Lot #'s: 677, 678, 679
	Screens, Hydraulic Tilting Cab, 31.5 in Triple Grouser Track Shoes, Rock Guards, ROTOBEC Log Grapple Usage: 9,719 Hr Asset located in: Lake Worth, TX	677	2018 Terramac RT-14 Crawler Carrier S/N: 14G0060 C/W: Enclosed Cab, Air Conditioner, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13 ft 6 in Long x 2 ft High Flatbed Dump Body, 31 in Rubber Tracks, Stake Sides; EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 1,183 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
678	2017 Terramac RT-14 Crawler Carrier S/N: 14C0040 C/W: 13 ft 6 in Long x 2 ft High Dump Body, 32 in Pubber Tracks, FOLIDMENT-EPOM-	СНОІС	E OF 3 - Lot #'s: 684, 685, 686
	in Rubber Tracks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 1,912 Hr	684	2014 Morooka MST-2200VD Crawler Carrier S/N: 223666
	Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, 2013 US
679	2017 Terramac RT-14 Crawler Carrier S/N: 14C0036 C/W: Enclosed Cab, Air Conditioner, 13 ft 6 in Long Flatbed Dump Body, 32 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,703 Hr Asset located in: Lake Worth, TX	EPA Label, Cat C7 6 Cylinder 7.2 L D Engine, 30 in Rubber Tracks, 9 ft 2 ir ft 4 in Long Flatbed Usage: 4,082 Hr Notes: ITEMS AT OFFSITE LOCATIO BE PICKED UP BY JANUARY 3RD OF	Engine, 30 in Rubber Tracks, 9 ft 2 in Wide x 13 ft 4 in Long Flatbed
	·	- 685	<u>`</u>
CHOIC	S/N: A2202131 C/W: Enclosed Cab, Air Conditioner,		2011 Morooka MST-2200VD Crawler Carrier S/N: 223442 C/W: Enclosed Cab, Air Conditioner, 2011 US EPA Label, Cat C7 6 Cylinder 7.2 L Diesel Engine, 30 in Rubber Tracks, 13 ft 4 in Long Flatbed Dump Body Usage: 6,040 Hr
	Hydrostatic Drive Usage: 2,294 Hr <b>Asset located in</b> : Baytown, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
681	2019 Morooka MST2200VD Crawler Carrier S/N: A2202124 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2018 US EPA Label, Cat 6 Cylinder Diesel Engine, 29.5 in Rubber Tracks, 9 ft Wide x 12 ft 9 in Long Flatbed Usage: 2,393 Hr		Asset located in: Louisville, MS
		686	2013 Morooka MST-2200VD Crawler Carrier S/N: 223553 Usage: 2,407 Hr Asset located in: Louisville, MS
	Asset located in: Baytown, TX	СНОІС	E OF 2 - Lot #'s: 687, 688
СНОІС	E OF 2 - Lot #'s: 682, 683	687	2019 Morooka MST1500VD Crawler Carrier S/N: A1505075
682	2015 Morooka MST-2200VD Crawler Carrier S/N: A220291 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 13 ft Long x 0 ft High Swivel Dump Body, 30 in Rubber Tracks, Bed Dump Cylinders; EQUIPMENT-FROM-WATKINS-		C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27 in Rubber Tracks, 10 ft 5 in Long Flatbed Dump Body Usage: 864 Hr Asset located in: Beaumont, TX
	CÓNSTRUCTION Usage: 679 Hr	688	2019 Morooka MST1500VD Crawler Carrier S/N: A1505077
683	2015 Morooka MST-2200VD Crawler Carrier S/N: A220247 C/W: Enclosed Cab, Air Conditioner, 13 ft Long Flatbed Dump Body, 30 in Rubber Tracks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 3,659 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Cat C 7.1 Diesel Engine, Requires Diesel Exhaust Fluid, 27.5 in Rubber Tracks, 10 ft 5 in Long Flatbed Dump Body Usage: 1,005 Hr  Asset located in: Beaumont, TX
		690	2019 Morooka MST1000VD Crawler Carrier S/N: A1001007 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Diesel Engine, Requires Diesel Exhaust Fluid, 23.5 in Rubber Tracks, 10 ft Long Flatbed Dump Body Usage: 1,115 Hr Asset located in: Beaumont, TX

Lot #	Details	Lot #	Details
691	Morooka MST1500 Crawler Carrier S/N: 151791 C/W: Canopy, 9 ft 10 in Long Flatbed Dump Body, 26 in Rubber Tracks, Lincoln 300D Welder w/ Leads; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 8,681 Hr Asset located in: Lake Worth, TX	695	IHI IC45-2 Crawler Carrier Aerial Lift w/2001 Terex HI-Ranger HR46M S/N: CE000831 C/W: Canopy, 2007 US EPA Label, Mitsubishi S6S-DTDP 6 Cylinder 99 hp 5.0 L Diesel Engine, 26250 lb Capacity, Rear Mounted, One-Person Articulated Boom, Flatbed, Turret Mounted Winch, X-Type Outriggers, Rear Outriggers, Bumper Mounted Winch, Hydraulic Hose Reel, 24 in Rubber Tracks Usage: 2,407 Hr
692	DICE OF 2 - Lot #'s: 692, 693  2018 Canycom S25A Crawler Carrier		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	S/N: 9161386		Asset located in: Louisville, MS
	C/W: Canopy, US EPA Label, Kubota V2203-M-ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 1 ft 2 in High Dump Body Usage: 194 Hr	696	2018 Cat 272D2 XHP Skid Steer Loader S/N: CAT0272DTMD200939 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS	697A	2016 Cat 272D2 Two-Speed High Flow XPS Skid Steer Loader S/N: CAT0272DABL200550 C/W: Open Operator Station, Joystick Steering,
693	S/N: 9161385 C/W: Canopy, US EPA Label, Kubota V2203-M-ET02 4 Cylinder 35.9 kW 2.2 L Diesel Engine, 12 in Rubber Tracks, 5 ft Long x 2 ft 2 in High Dump Body Usage: 1,799 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Louisville, MS		Rear View Camera, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,097 Hr Asset located in: Lake Worth, TX
		697B	2016 Cat 272D2 Two-Speed Skid Steer Loader S/N: CAT0272DLBL200551 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, Manual Coupler, 80 in Bucket Usage: 6,474 Hr Asset located in: Lake Worth, TX
694		698A	2014 Cat 272D Two-Speed Skid Steer Loader S/N: CAT0272DHB5W00695 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 9 Pin Electric Kit, Manual Coupler, 72 in Bucket Usage: 6,717 Hr Asset located in: Lake Worth, TX
		699	2021 Bobcat S66 Two-Speed Skid Steer Loader S/N: B4SA12489 C/W: Open Operator Station, Joystick Steering, Manual Coupler Usage: 985 Hr Asset located in: Lake Worth, TX
		700	2015 Bobcat S630 Skid Steer Loader S/N: AHGL11719 C/W: Open Operator Station, 2014 US EPA Label, Manual Coupler, 66 in Bucket Usage: 9,891 Hr Asset located in: Lake Worth, TX
		701	2019 Cat 262D Skid Steer Loader S/N: CAT0262DKDTB09532 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Tier 4, 2018 US EPA Label, Manual Coupler, 67 in Bucket Usage: 1,988 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOICI 702	OF 4 - Lot #'s: 702, 703, 704, 705  2020 Bobcat S570 Skid Steer Loader S/N: ALM429836 C/W: Open Operator Station, Creep Mode, Joystick Steering, Control Pattern Changer,	710	2021 John Deere 318G Skid Steer Loader S/N: 1T0318GKCMJ407875 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2021 US EPA Label, Aperture Tires, 9 Pin Electric Kit, Hydraulic Coupler, Counterweight Kit Usage: 1,521 Hr Asset located in: Lake Worth, TX
	Self Leveling, 2019 US EPA Label, Aperture Tires, Manual Coupler, 74 in Bucket Usage: 932 Hr <b>Asset located in</b> : Lake Worth, TX	711	2020 Cat 242D3 Two-Speed Skid Steer Loader S/N: CAT0242DAHSX00818 C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, Manual Coupler, 74
703	2020 Bobcat S570 Skid Steer Loader S/N: ALM429810 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 67 in Bucket		in Bucket Usage: 2,764 Hr  Asset located in: Lake Worth, TX
	Usage: 1,237 Hr  Asset located in: Lake Worth, TX	сноіс	E OF 3 - Lot #'s: 712, 713, 714
704	2020 Bobcat S570 Skid Steer Loader S/N: ALM429670 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 66 in Bucket Usage: 1,759 Hr Asset located in: Lake Worth, TX	712	2014 Cat 242D Two-Speed Skid Steer Loader S/N: CAT0242DTDZT00301 C/W: Tier 4, 2013 US EPA Label, CARB Compliant, Manual Coupler, 68 in Bucket Usage: Not Available
705	2017 Bobcat S570 Skid Steer Loader		Asset located in: Midland, TX
	S/N: ALM418117 C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 66 in Bucket Usage: 751 Hr <b>Asset located in</b> : Lake Worth, TX	713	2015 Cat 242D Skid Steer Loader S/N: CAT0242DEDZT01204 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Tier 4, 2014 US EPA Label, CARB Compliant, Hydraulic Coupler, 74 in Bucket Usage: Not Available
CHOIC	HOICE OF 2 - Lot #'s: 706, 707		Asset located in: Midland, TX
706	2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BCTNK01891 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 13,461 Hr Asset located in: Lake Worth, TX	714	2014 Cat 242D Skid Steer Loader S/N: CAT0242DJDZT00366 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Tier 4, 2013 US EPA Label, CARB Compliant, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: Not Available Asset located in: Midland, TX
707	2012 Cat 252B3 Skid Steer Loader S/N: CAT0252BHTNK01905 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 73 in Bucket Usage: 11,292 Hr	715	2016 Kubota SSV65 Skid Steer Loader S/N: JKUS0651L01S12051 Usage: Not Available Asset located in: Lake Worth, TX
708	Asset located in: Lake Worth, TX  Gehl R165 Skid Steer Loader  S/N: GHL0R165E00197514  C/W: Open Operator Station, 2015 US EPA Label, Manual Coupler	717	2021 Bobcat S510 Skid Steer Loader S/N: B4RE11047 C/W: EQUIPMENT FROM UNITED RENTALS Usage: 1,258 Hr Asset located in: Lake Worth, TX
	Usage: 2,245 Hr Asset located in: Lake Worth, TX	718	2012 Bobcat S150 Skid Steer Loader
709	2014 Cat 246D Skid Steer Loader S/N: CAT0246DHBYF01000		S/N: A3L485751 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2014 US EPA Label, 9 Pin Electric Kit, Electric Coupler, 68 in Bucket Usage: 6,328 Hr Asset located in: Lake Worth, TX	719	2015 Gehl V270 Two-Speed Skid Steer Loader S/N: GHL00270H00023697 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Manual Coupler, 79 in Bucket Usage: 1,653 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
720	2006 Bobcat S205 Skid Steer Loader S/N: 530512291 C/W: Open Operator Station, Tier 2, 2006 US EPA Label, Aperture Tires, Manual Coupler, 66 in Grapple Bucket, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,830 Hr Asset located in: Lake Worth, TX	727	2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DHFD205803 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 80 in Bucket Usage: 2,733 Hr
721	Case 1845C Skid Steer Loader S/N: 4810330 C/W: Enclosed Cab, Manual Coupler, 73 in Bucket Usage: 335 Hr Asset located in: Lake Worth, TX	727A	Asset located in: Lake Worth, TX  2020 Takeuchi TL12V2 Two-Speed High Flow Compact Track Loader S/N: 412002791 C/W: Enclosed Cab, Control Pattern Changer,
	E OF 2 - Lot #'s: 722, 723		Rear View Camera, 17.5 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 79 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,813 Hr  Asset located in: Lake Worth, TX
722	2020 Cat 299D3 Two-Speed Compact Track Loader S/N: CAT0299DADY902326 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 3,301 Hr Asset located in: Lake Worth, TX	728	2017 Takeuchi TL12R2-CR Compact Track Loader S/N: 412100427 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17 in Track Belts, Manual Coupler, 81 in Bucket Usage: 1,197 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
723	<b>2020 Cat 299D3 Compact Track Loader</b> S/N: 0DY901742 Usage: 3,515 Hr	728A	ASSET located in: Lake Worth, TX  2020 Cat 289D3 Compact Track Loader
724	Asset located in: Lake Worth, TX  2019 Cat 299D3XE Two-Speed Compact Track Loader  S/N: CAT0299DCBX901368  C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, 17 in Track Belts, Manual Coupler Usage: 2,412 Hr		S/N: CAT0289DCJX903131 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 18 in Track Belts, Hydraulic Coupler, 73 in Bucket Usage: 5,426 Hr Asset located in: Lake Worth, TX  E OF 2 - Lot #'s: 729, 9634A
725	Asset located in: Lake Worth, TX  2019 Cat 299D2XHP Two-Speed High Flow Compact Track Loader S/N: CAT0299DEDX204437 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Rear View Camera, 15 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 2,589 Hr Asset located in: Lake Worth, TX	729	2014 Cat 289D Compact Track Loader S/N: TAW01012 C/W: Enclosed Cab (Door missing), Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Self Leveling, Tier 4, 2014 US EPA Label, CARB Compliant, 18 in Track Belts, Hydraulic Coupler, 74 in Bucket, Counterweight Kit Usage: Not Available Asset located in: Midland, TX
сноіс	CHOICE OF 2 - Lot #'s: 726, 727		2020 Cat 279D3 Compact Track Loader S/N: CAT0279DTRB901084
726	2019 Cat 299D2 Two-Speed Compact Track Loader S/N: CAT0299DCFD205903 C/W: Enclosed Cab, Air Ride Seat, Joystick Steering, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 78 in Bucket Usage: 2,224 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler, 86 in Bucket, Counterweight Kit Usage: 2,944 Hr Asset located in: Beaumont, TX

Lot #	Details	Lot #	Details
731A	2019 Bobcat T770 Two-Speed Compact Track Loader S/N: AT6321914 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,269 Hr Asset located in: Lake Worth, TX	738	2012 Bobcat T750 Compact Track Loader S/N: ANKA12005 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Manual Coupler Usage: 4,888 Hr Asset located in: Lake Worth, TX
		738A	<b>2011 Bobcat T750 Compact Track Loader</b> S/N: ANKA11840 Usage: Not Available
CHOIC	E OF 2 - Lot #'s: 732, 733	739	Asset located in: Lake Worth, TX  2019 Bobcat T740 Two-Speed Compact Track
732 2017 Bobcat T770 Compact Track Loader S/N: AT6314655 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 66 in Bucket, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,422 Hr			Loader S/N: B3CA15269 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 18 in Track Belts, Hydraulic Coupler, 78 in Bucket Usage: 3,052 Hr Asset located in: Lake Worth, TX
733	Asset located in: Lake Worth, TX  2016 Bobcat T770 Compact Track Loader S/N: AT6312284 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17.5 in Track Belts, 7	740	2022 John Deere 333G Compact Track Loader S/N: 1T0333GMCNF420256 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Hydraulic Coupler, 83 in Bucket Usage: 726 Hr Asset located in: Lake Worth, TX
	Pin Electric Kit, Manual Coupler, 80 in Bucket Usage: 3,647 Hr <b>Asset located in</b> : Lake Worth, TX		E OF 3 - Lot #'s: 741, 742, 743
	,		
734	2022 Bobcat T76 Compact Track Loader S/N: B4CE19605 C/W: Open Operator Station, Joystick Steering, 2021 US EPA Label, Manual Coupler, 72 in Bucket	741	2016 John Deere 329E Compact Track Loader S/N: 1T0329EKHGE294140 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Control Pattern Changer, 17 in Track Belts, Manual Coupler, 83 in Bucket Usage: 2,760 Hr Asset located in: Lake Worth, TX
735	Usage: 1,897 Hr Asset located in: Lake Worth, TX  2022 Bobcat T76 Compact Track Loader S/N: B4CE17367 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, Manual Coupler, 79 in Bucket Usage: 2,765 Hr	742	2014 John Deere 329E Compact Track Loader S/N: 1T0329EMCEE255596 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Control Pattern Changer, 17.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 3,794 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		2021 John Deere 325G Two-Speed Compact
736	2020 Bobcat T76 R-Series Compact Track Loader S/N: B4CE11296 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2019 US EPA Label, 12.5 in Track Belts, Manual Coupler, 80 in Bucket Usage: 1,481 Hr Asset located in: Lake Worth, TX	743	Track Loader S/N: 1T0325GKEMJ407899 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, 15.5 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, Counterweight Kit Usage: 1,692 Hr Asset located in: Lake Worth, TX
737	2015 Bobcat T750 Compact Track Loader S/N: ATF614726 C/W: Open Operator Station, 18 in Track Belts, Manual Coupler, 76 in Bucket Usage: 4,848 Hr Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
743A	Case TV380 Two-Speed Compact Track Loader S/N: JAFTV380AJM452078 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available	751	2012 Kubota SVL90 Compact Track Loader S/N: 1003128 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2011 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler Usage: 1,052 Hr
	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX
744	2015 Case TV380 Compact Track Loader S/N: JAFTV380HEM482982 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, Manual Coupler, 86 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	<b>752</b> 	2023 Kubota SVL75-3 Compact Track Loader S/N: KBCZ053CTP1E12118 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual Coupler Usage: 388 Hr Asset located in: Humble, TX
CHOIC	E OF 2 - Lot #'s: 745, 746	753	<b>2022 Kubota SVL75-2 Two-Speed Compact Track Loader</b> S/N: 66119
745	2020 Kubota SVL95-2S Compact Track Loader S/N: KBCZ063CJL1F51637 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, US EPA Label, 17 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 1,986 Hr	754	C/W: Open Operator Station, Joystick Steering, 12.5 in Track Belts, Manual Coupler, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 677 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		<b>2020 Kubota SVL75 Compact Track Loader</b> S/N: KBCC0953PK1E47374
746	2019 Kubota SVL95-2HFC Compact Track Loader S/N: KBCC0953LK1E47027 C/W: Enclosed Cab, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler Usage: 1,501 Hr		C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Tier 4, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 74 in Bucket Usage: 318 Hr Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	⊣сноіс	E OF 3 - Lot #'s: 756, 757, 758
748	2017 Kubota SVL95-2S Two-Speed Compact Track Loader S/N: JKUC0953L01S34123 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Hydraulic Coupler Usage: 2,023 Hr	756	2019 Kubota SVL75-2 Compact Track Loader S/N: KBCC0752TK1J46403 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, Manual Coupler, 72 in Bucket Usage: 1,718 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	757	2019 Kubota SVL75-2 Compact Track Loader
749	2017 Kubota SVL95-2SHF Compact Track Loader S/N: JKU00953001S34806 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 17.5 in Track Belts, Hydraulic Coupler	758	S/N: KBCC0752VK1J46375 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,369 Hr Asset located in: Lake Worth, TX
	Usage: 4,389 Hr Asset located in: Lake Worth, TX		2018 Kubota SVL75-2 Compact Track Loader S/N: JKUC0752L01S38233 C/W: Open Operator Station, Joystick Steering,
750	Kubota SVL95-2S Compact Track Loader S/N: 1024968 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, Requires Diesel		15.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,370 Hr <b>Asset located in</b> : Lake Worth, TX
	Exhaust Fluid, 18 in Track Belts, Manual Coupler, 70 in Bucket Usage: 1,813 Hr <b>Asset located in</b> : Lake Worth, TX	759	2017 Kubota SVL75-2 Compact Track Loader S/N: 29876 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
760	2021 Wacker Neuson ST45 LF CTL Vert Compact Track Loader	CHOICE OF 2 - Lot #'s: 766, 767	
	S/N: WNCS0606TPUM00800 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Control Pattern Changer, 2023 US EPA Label, 16.5 in Track Belts, Hydraulic Coupler, 84 in Bucket, Counterweight Kit Usage: 1,666 Hr Asset located in: Lake Worth, TX	766	6 2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506CPUM01235 C/W: Open Operator Station, Joystick Steerin Control Pattern Changer, 12 in Track Belts, Hydraulic Coupler, 76 in Bucket
761	2018 Wacker Neuson ST45 Compact Track Loader		Usage: 513 Hr Asset located in: Humble, TX
	S/N: WNCS0404PPUM01126 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 2018 US EPA Label, 18 in Track Belts, Manual Coupler, 66 in Bucket Usage: 499 Hr Asset located in: Lake Worth, TX	767	2019 Wacker Neuson ST31 Compact Track Loader S/N: WNCS0506HPUM01189 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 12 in Track Belts, Manual Coupler
762	2019 LiuGong 388B Compact Track Loader S/N: LGZ388BZCKZ010679 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Requires Diesel Exhaust Fluid, 17 in		Usage: 491 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Track Belts, Manual Coupler, 82 in Bucket Usage: 4,737 Hr <b>Asset located in</b> : Lake Worth, TX	768	<b>2019 Case TR310 Compact Track Loader</b> S/N: JAFTR310JJM450180 Usage: Not Available
		7	Asset located in: Lake Worth, TX
CHOIC 763	2021 Bobcat T64 Compact Track Loader S/N: B4SD13020 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,018 Hr	769	2018 Case TR310 Compact Track Loader S/N: JAFTR310VJM449341 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 76 in Bucket Usage: 3,253 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
764	2021 Bobcat T64 Compact Track Loader S/N: B4SD12133 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 1,051 Hr Asset located in: Lake Worth, TX	771	2019 Bobcat T590 Compact Track Loader S/N: ALJU31295 C/W: Open Operator Station, 2019 US EPA Label, CARB Compliant, 13 in Track Belts, Manual Coupler, 68 in Bucket
765	2021 Bobcat T64 R-Series Compact Track Loader		Usage: 1,490 Hr  Asset located in: Lake Worth, TX
	S/N: B4SD12149 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in	СНОІС	E OF 2 - Lot #'s: 772, 773
	Bucket Usage: 1,494 Hr <b>Asset located in</b> : Lake Worth, TX	772	2017 Bobcat T590 Compact Track Loader S/N: ALJU23267 C/W: Open Operator Station, 2017 US EPA Label, 12.5 in Track Belts, Manual Coupler, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,715 Hr

Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
773	2017 Bobcat T590 Compact Track Loader S/N: ALJU23698 C/W: Open Operator Station, Joystick Steering, 2017 US EPA Label, 12 in Track Belts, Manual Coupler, 57 in Bucket, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,084 Hr Asset located in: Lake Worth, TX	781	E OF 3 - Lot #'s: 781, 782, 783  2021 Cat 259D3 Two-Speed Compact Track Loader  S/N: CAT0259DECW912426  C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 73 in Bucket
CHOIC	E OF 1 - Lot #'s: 775		Usage: 1,011 Hr  Asset located in: Lake Worth, TX
775	2015 Bobcat T590 Compact Track Loader S/N: ALJU14338 C/W: Open Operator Station, 2014 US EPA Label, 12.5 in Track Belts, Manual Coupler Usage: 3,479 Hr Asset located in: Lake Worth, TX	782	2021 Cat 259D3 Compact Track Loader S/N: CAT0259DJCW914734 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Tier 4, 2021 US EPA Label, 12 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,523 Hr
776	2019 Bobcat T550 Compact Track Loader		Asset located in: Lake Worth, TX
	S/N: AJZV23563 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, Forks Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	783	2021 Cat 259D3 Two-Speed Compact Track Loader S/N: CAT0259DCCW907770 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4,
777	2024 Takeuchi TL10V2 Compact Track Loader S/N: 410007722 Usage: Not Available		2020 US EPA Label, 16 in Track Belts, Manual Coupler, 74 in Bucket Usage: 1,817 Hr <b>Asset located in</b> : Lake Worth, TX
	Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	784	2018 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DLFTL16672 C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 13 in Track Belts, Manual Coupler
778	2019 Takeuchi TL10V2 Compact Track Loader		Usage: 3,619 Hr <b>Asset located in</b> : Lake Worth, TX
	S/N: 410002668 C/W: Open Operator Station, Joystick Steering, Tier 4, 2019 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,355 Hr		E OF 3 - Lot #'s: 785, 786, 787
	Asset located in: Lake Worth, TX	785	2017 Cat 259D Compact Track Loader
779	2017 Takeuchi TL10V2R Compact Track Loader S/N: 410000884 Usage: Not Available Asset located in: Lake Worth, TX	_	S/N: CAT0259DLFTL12430 C/W: Open Operator Station, Joystick Steering, Tier 4, 2021 US EPA Label, 12.5 in Track Belts, Manual Coupler, 74 in Bucket Usage: 7,140 Hr Asset located in: Lake Worth, TX
780	2022 ASV RT-135 Two-Speed Compact Track Loader S/N: ASVRT135ANDS00237 C/W: Enclosed Cab, Air Conditioner, 2021 US EPA Label, 17 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 460 Hr Asset located in: Lake Worth, TX	<b>⊣786</b>	2016 Cat 259D Compact Track Loader S/N: CAT0259DLFTL07339 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Self Leveling, Tier 4, 2022 US EPA Label, 12.5 in Track Belts, Manual Coupler, 75 in Bucket Usage: 6,778 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
787	2016 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DEFTL08493 C/W: Open Operator Station, Joystick Steering, Tier 4, 2016 US EPA Label, 16 in Track Belts, Manual Coupler, 79 in Bucket Usage: 4,493 Hr	795	2020 Bobcat T450 Compact Track Loader S/N: AUVP16939 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 910 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	796	2020 Bobcat T450 Compact Track Loader
788	2012 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BCYYZ02661 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 66 in Bucket Usage: 3,600 Hr		S/N: AUVP17085 C/W: Open Operator Station, Joystick Steering, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 1,387 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	797	2019 Bobcat T450 Compact Track Loader
789	2011 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BPYYZ00856 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 12.5 in Track Belts, Manual Coupler, 72 in Bucket	/9/	S/N: AUVP15801 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 571 Hr Asset located in: Lake Worth, TX
	Usage: 4,736 Hr	798	2019 Bobcat T450 Compact Track Loader
790	Asset located in: Lake Worth, TX  2018 Takeuchi TL8 Two-Speed Compact Track Loader  S/N: 200806258  C/W: Open Operator Station, Joystick Steering, Tier 4, 2017 US EPA Label, 12.5 in Track Belts,		S/N: AUVP16910 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 73 in Bucket Usage: 636 Hr <b>Asset located in</b> : Lake Worth, TX
	14 Pin Electric Kit, Manual Coupler Usage: 2,652 Hr <b>Asset located in</b> : Lake Worth, TX	799	S/N: AUVP15804 C/W: Open Operator Station, 2018 US EPA
791	<b>2012 Takeuchi TL230 Compact Track Loader</b> S/N: 223101077 Usage: Not Available	800	Label, Manual Coupler, 67 in Bucket Usage: 772 Hr <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX		2019 Bobcat T450 All-Wheel Steer Compact
792	2020 Gehl RT165 Compact Track Loader S/N: GHLRT165GOD302276 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, Manual Coupler Usage: 397 Hr Asset located in: Lake Worth, TX		Track Loader S/N: AUVP16039 C/W: Open Operator Station, 2018 US EPA Label, 12 in Track Belts, Manual Coupler, 67 in Bucket Usage: 954 Hr Asset located in: Lake Worth, TX
		801	2009 Bobcat T180 Compact Track Loader
800	E OF 8 - Lot #'s: 793, 794, 795, 796, 797, 798, 799,		S/N: A3LL30017 C/W: Open Operator Station, 2008 US EPA Label, 12.5 in Track Belts, Manual Coupler, 67 in Bucket
793	2020 Bobcat T450 Compact Track Loader S/N: AUVP16938 C/W: Open Operator Station, 2018 US EPA		Usage: 3,840 Hr <b>Asset located in</b> : Lake Worth, TX
70.4	Label, Manual Coupler, 67 in Bucket Usage: 675 Hr <b>Asset located in</b> : Lake Worth, TX	802	2003 Cat 277 Compact Track Loader S/N: CAT00277LCNC02031 C/W: Open Operator Station, Joystick Steering, 18 in Track Belts, Manual Coupler, 79 in Bucket
794	2020 Bobcat T450 Compact Track Loader S/N: AUVP16950 C/W: Open Operator Station, 2019 US EPA Label, 12 in Track Belts, Manual Coupler, 65 in Bucket Usage: 802 Hr Asset located in: Lake Worth, TX		Usage: 6,389 Hr  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
802A	John Deere 5203 2WD Utility Tractor S/N: PY5203U004017 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncReverser, 2005 US EPA Label, 540 PTO, 3-Point Hitch, Drawbar, 7.50-16 Front Tires, 14.9x28 Rear Tires	CHOIC 809	E OF 2 - Lot #'s: 809, 810  2017 Case IH Magnum 310 4WD Tractor S/N: JJAM0310THRF01144
	Usage: 119 Hr Asset located in: Lake Worth, TX		C/W: Enclosed Cab, Air Conditioner, Front Weights, Rear Remotes, 540 PTO, Drawbar, 380 /85R34 Front Tires, Dual 480/80r46 Rear Tires
803	2010 John Deere 5045E 4WD Utility Tractor S/N: PY5045E000742 C/W: Differential Lock, Forward/ Reverse		Usage: 2,635 Hr  Asset located in: Robstown, TX
	Shuttle, John Deere 553 Loader w/Joystick, Quick Coupler, John Deere 68 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Pickup Hitch, 9.5x24 Front Tires, 14.9x28 Rear Tires Usage: 3,181 Hr Asset located in: Humble, TX	810	2017 Case MAGNUM 310 4WD Tractor S/N: JJAM0310KHRF01180 C/W: Enclosed Cab, Air Conditioner, CVT, Forward/ Reverse Shuttle, Front Weights, 5 Rear Remotes, 1000 PTO, 3-Point Hitch, Dual 380/85R34 Front Tires, Dual 380/90r50 Rear
804	2003 Kubota MX5000E 2WD Utility Tractor S/N: 11584 C/W: 4 Forward 4 Reverse, Manual Transmission, 38.0 kW Engine, 2003 US EPA Label, TAS ML280 Loader, 61 in Bucket, 3-Point		Tires Usage: 2,810 Hr Notes: TODAY'S PRICE: 14% OFF \$123,419 (\$106,000) Asset located in: Baytown, TX
	Hitch, 29x12.50-15 Front Tires, 44x18.00-20 Rear Tires Usage: 481 Hr <b>Asset located in</b> : Lake Worth, TX	811	John Deere 8320R 4WD Tractor S/N: R0H8NBR611453 Usage: Not Available Asset located in: Lake Worth, TX
805	Massey Ferguson 2WD Tractor (Inoperable) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 812, 813
806	1988 John Deere 2955 2WD Tractor S/N: L02955T626188 C/W: Enclosed Cab, 16 Forward 8 Reverse, John Deere Loader, Quick Coupler, 72 in Bucket, 540 PTO, 3-Point Hitch, Drawbar, 10.00- 16 Front Tires, 18.4-38 Rear Tires Usage: 3,219 Hr Asset located in: Lake Worth, TX	812	2024 John Deere 6155M 4WD Tractor (Unuse S/N: 1L06155MTRG423600 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Fro 3-Point Quick Hitch, 3 Rear Remotes, Air Brak System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420 /70R28 Front Tires, 520/70R38 Rear Tires Usage: 4 Hr Asset located in: Lake Worth, TX
807	1979 John Deere 4440 2WD Tractor S/N: 025940R		
	C/W: Enclosed Cab, Air Ride Seat, Differential Lock, 16 Forward 6 Reverse, Quad Range, Front Weights, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, 38x11 Front Tires, 18.4x38 Rear Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 966 Hr  Notes: JERRY WATKINS PERSONAL RANCH TRACTOR  Asset located in: Lake Worth, TX	813 203 S/N C/N Sea Po' EP, 3-F Sys /10 /70 Us:	2024 John Deere 6155M 4WD Tractor (Unused) S/N: 1L06155MLRG423350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 20 Forward 20 Reverse, PowrQuad Plus, Left Hand Reverser, 2024 US EPA Label, Requires Diesel Exhaust Fluid, Front 3-Point Quick Hitch, 3 Rear Remotes, Air Brake System, Exterior 3-Point Hitch Controls, 540 /1000 PTO, 3-Point Hitch w/ Quick Hitch, 420
808	1983 John Deere 4450 2WD Tractor S/N: RW4450P005964 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 15 Forward 4 Reverse, Front Weights, 3 Rear Remotes, 540 PTO, Drawbar, 14L16.1-10 Front Tires, 20.8x38 Rear Tires Usage: 753 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK		/70R28 Front Tires, 520/70R38 Rear Tires Usage: 1 Hr <b>Asset located in</b> : Lake Worth, TX

Lot #	Details	Lot #	Details
814	2013 John Deere 6105D 4WD Tractor S/N: 1P06105DADM050351 C/W: Enclosed Cab, Air Conditioner, 3 Forward 3 Reverse, Hydrostatic Drive, Forward/ Reverse Shuttle, 130 kW Engine, 2013 US EPA Label, CARB Compliant, 4 Rear Remotes, 540 PTO, 3- Point Hitch, Hydraulic Top Link, 340/85R24 Front Tires, 18.4x34 Rear Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY	820	1998 Kubota L3600DT 4WD Tractor S/N: 56376 C/W: 4 Forward 4 Reverse, Manual Transmission, Forward/ Reverse Shuttle, Kubota LA680 Loader w/Joystick, 1 Mid-Mount Remotes, HID Lights, 540 PTO, 3-Point Hitch, 8- 16 Front Tires, 14.9x24 Rear Tires Usage: 790 Hr Asset located in: Lake Worth, TX
	Usage: 4,107 Hr <b>Asset located in</b> : Humble, TX	822	<b>Kioti LB1914 4WD Tractor</b> S/N: 04000837
815	2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MLNM104106 C/W: Canopy, Differential Lock, 16 Forward 16		C/W: 8 Forward 4 Reverse, Manual Transmission, 3-Point Hitch, 6-12 Front Tires, 12.4-16 Rear Tires Usage: 667 Hr
	Reverse, PowrReverser, Forward/ Reverse Shuttle, 2022 US EPA Label, Requires Diesel	2224	Asset located in: Lake Worth, TX
	Exhaust Fluid, John Deere 540M Loader w /Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, 320/85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,124 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	822A	2010 John Deere 9530 Articulated Tractor S/N: 1RW9530PCAP018006 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Grouser 16 ft Blade, 4 Rear Remotes, Auxiliary Hydraulics, Rear Weights, Dual 800/70R38 Tires Usage: 11,887 Hr Asset located in: Lake Worth, TX
816		822B	2019 Shelbourne CVS16 16 ft Stripper
	S/N: 87373 C/W: Enclosed Cab, Air Conditioner, 4 Forward,		Combine Header
	Loader, Quick Coupler, Pallet Forks, 4 Mid-		S/N: CVS16193113 Usage: Not Available
	Mount Remotes, 2 Rear Remotes Usage: 561 Hr		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	823	2016 Manitou MRT2550 High Reach Rotating
817	2013 Mahindra 6110ST 4WD Tractor S/N: 61GCF00632 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, Powershift, Forward/ Reverse Shuttle, 60 hp Engine, Mahindra ML161 Loader w/Joystick, Quick Coupler, 79 in Bucket, 2 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, Rhino Turbo 96 96 in Mower, 10.5/80-18 Front Tires, 18.4x24 Rear Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 738 Hr		4x4x4 Telehandler S/N: 769939 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Load Moment Indicator, 81 ft Max Lift Height, 11000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 71 in Forks, Outriggers, Auxiliary Hydraulic Plumbing, 445 /65R22.5 Tires Usage: 3,059 Hr Asset located in: Lake Worth, TX
	Notes: JERRY WATKINS PERSONAL RANCH TRACTOR	824	2019 JLG 1255 Telehandler
	Asset located in: Lake Worth, TX		S/N: 0160096252 C/W: Enclosed Cab, Air Conditioner, Rear View
818	2012 Kubota M7040 4WD Tractor S/N: 53487 C/W: Enclosed Cab, Air Conditioner, 4 Forward, Quick Coupler, 83 in Bucket, 4 Mid-Mount Remotes, 6 Rear Remotes Usage: 2,003 Hr Asset located in: Lake Worth, TX		Camera, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 3,852 Hr  Asset located in: Lake Worth, TX
819	Challenger MT665B 4WD Tractor S/N: S206014 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
CHOICE OF 2 - Lot #'s: 825, 826		831	2014 JLG G12-55A Telehandler S/N: 0160060643 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US
825	2018 JLG 1255 Telehandler S/N: 0160084208 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks,		EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 6,716 Hr
	Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires	222	Asset located in: Lake Worth, TX
	Usage: 12,673 Hr <b>Asset located in</b> : Humble, TX	832	2011 JLG G12-55A Telehandler S/N: 0160042364 C/W: Enclosed Cab, Air Conditioner, 55 ft Max
826	2019 JLG 1255 Telehandler S/N: 0160091605 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler,		Lift Height, 12000 lb Max Lift Capacity, 2011 US EPA Label, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: Not Available Asset located in: Humble, TX
	Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 360/85-28 Solid Tires Usage: 9,502 Hr <b>Asset located in</b> : Lake Worth, TX	833	2019 Skytrack 12054 Telehandler S/N: 0160092640 C/W: Enclosed Cab, Air Conditioner, Air Ride
СНОІС	E OF 4 - Lot #'s: 827, 828, 829, 830		Seat, 0 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 3,148 Hr Asset located in: Lake Worth, TX
827	2015 JLG 1255 Telehandler S/N: 0160070550 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,988 Hr	834	2006 Dieci Pegasus 40.25 Telehandler S/N: 1560587 C/W: Enclosed Cab, 69 ft Max Lift Height, 8800 lb Max Lift Capacity, 2006 US EPA Label, Crane Attachment, 18-22.5 Tires
			Usage: 5,470 Hr <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Oklahoma City, OK	4	
828	<b>2015 JLG 1255 Telehandler</b> S/N: 0160070536	CHOICE OF 3 - Lot #'s: 836, 837, 838	
	C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT	836	<b>2018 Skyjack SJ1056TH Telehandler</b> S/N: 87311173 Usage: 2,541 Hr
			Asset located in: Lake Worth, TX
	Usage: 5,626 Hr Asset located in: Lake Worth, TX	<b>837 2018 Skyjack SJ1056TH Telehandler</b> S/N: 87310698	
829	2015 JLG G12-55A Telehandler S/N: 0160065521 C/W: Open Operator Station, Air Ride Seat, 55		C/W: Open Operator Station, 56 ft 0 in Max Lift Height, 10000 lb Max Lift Capacity, Outriggers, 14.00-24 Tires Usage: 2,041 Hr
	ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Hydraulic		Asset located in: Midland, TX
	Coupler, Outriggers, Frame Leveling, 17.5-25 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,930 Hr  Asset located in: Lake Worth, TX	838	2017 Skyjack SJ1056TH Telehandler S/N: 8730578 C/W: Open Operator Station, 56 ft Max Lift Height, 2017 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires
830	2014 JLG G12-55A Telehandler S/N: 0160061321 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,775 Hr Asset located in: Lake Worth, TX		Usage: 4,532 Hr  Asset located in: Midland, TX

Lot #	Details	Lot #	Details
839	2018 Genie GTH-1056 Telehandler S/N: GTH10E12290 C/W: Open Operator Station, Air Ride Seat, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 2,530 Hr Asset located in: Humble, TX	845	2014 JLG G10-55A Telehandler S/N: 0160058853 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Foam Filled Tires Usage: Not Available Asset located in: Lake Worth, TX
840	2013 JCB 510-56 Telehandler S/N: JCB5CGXGK01403372 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 4,527 Hr Asset located in: Lake Worth, TX	846	2015 Gehl RS10-55 Telehandler S/N: RS1055CG90781 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,609 Hr
841	2007 Genie GTH-1056 Telehandler S/N: GTH1007A-11371 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Tilt Carriage, Outriggers, 14.00-24 Tires Usage: 8,632 Hr Asset located in: Lake Worth, TX	847	Asset located in: Lake Worth, TX  2018 JLG 10054 Telehandler  S/N: 0160086824  C/W: Open Operator Station, 53 ft Max Lift Height, 10000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling,
842	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90900 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperus 2 546 Lb	сноіс	Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 3,294 Hr Asset located in: Humble, TX  E OF 5 - Lot #s: 848, 849, 850, 851, 852
	Usage: 3,546 Hr Asset located in: Humble TX	848	2016 JLG 10054 Telehandler
CHOIC	Asset located in: Humble, TX  HOICE OF 2 - Lot #'s: 843, 844  3 2018 JLG 1055 Telehandler S/N: 0160083964 C/W: Open Operator Station, 55 ft Max Lift		S/N: 160076446 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 47 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 14.00-24 Solid Tires Usage: 4,051 Hr Asset located in: Lake Worth, TX
	Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,300 Hr Asset located in: Lake Worth, TX	849	2015 JLG 10054 Telehandler S/N: 0160065420 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Outriggers, Frame Leveling, 14.00-24 Aperture Tires Usage: 8,383 Hr Asset located in: Lake Worth, TX
844	2017 JLG 1055 Telehandler S/N: 160082583 C/W: Enclosed Cab, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 59 in Forks, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 7,542 Hr Asset located in: Lake Worth, TX	850	2015 JLG 1055 Telehandler S/N: 0160070447 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires, EQUIPMENT-FROM-SUNSTATE EQUIPMENT Usage: 5,727 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
851	2015 JLG 10054 Telehandler S/N: 0160064214 C/W: Open Operator Station, 42 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 96 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 5,103 Hr Asset located in: Lake Worth, TX	856	2017 JLG 943 Telehandler S/N: 160079732 C/W: Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires
852	2014 JLG 10054 Telehandler		Usage: 7,159 Hr <b>Asset located in</b> : Lake Worth, TX
	S/N: 0160062880 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, Manual Coupler, Outriggers, Frame Leveling, 17.5-25 Tires Usage: 5,424 Hr Asset located in: Lake Worth, TX	857	2016 JLG 943 Telehandler S/N: 160078141 C/W: Enclosed Cab, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary
852A	<b>2013 SkyTrak 10054 Telehandler</b> S/N: 0160052932 C/W: Open Operator Station, 42 ft Max Lift		Hydraulic Plumbing, 370/75-28 Foam Filled Tires Usage: 6,476 Hr <b>Asset located in</b> : Lake Worth, TX
	Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,413 Hr	СНОІС	E OF 1 - Lot #'s: 859
	Asset located in: Lake Worth, TX	859	2014 Genie GTH-844 Telehandler
853	2007 SkyTrak 10054 Telehandler S/N: 0160029235 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Tier 3, 2007 US EPA Label, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,666 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK		S/N: GTH081419083 C/W: Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: Not Available Asset located in: Midland, TX
		859A	JCB 509.42 Telehandler
			S/N: JCB5CF7GPJ2755050 C/W: Open Operator Station, 42 ft Max Lift Height, 9000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing,
854	<b>2018 Haulotte HTL9055 Telehandler</b> S/N: 2030718	860 20 S/I C/Y He For Plu SU Us	14.00-24 Tires Usage: 2,174 Hr <b>Asset located in</b> : Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, Load Moment Indicator, 55 ft Max Lift Height, 9000 lb Max Lift Capacity, Manual Coupler Usage: 635 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		2016 SkyTrak 8042 Telehandler S/N: 0160077066 C/W: Open Operator Station, 42 ft Max Lift Height, 4000 lb Max Lift Capacity, 47.5 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,626 Hr Asset located in: Lake Worth, TX
	Asset located in: Fort Smith, AR		5.05.0 Let #2.061.060.060
CHOIC	E OF 3 - Lot #'s: 855, 856, 857	861	E OF 3 - Lot #'s: 861, 862, 863  2015 JLG 8042 Telehandler
855	2017 JLG 943 Telehandler S/N: 160079731 C/W: Open Operator Station, 9000 lb Max Lift Capacity, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 59 in Forks, Frame Leveling, 370 /75-28 Tires Usage: 5,224 Hr	001	S/N: 0160069747 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
862	2015 JLG 8042 Telehandler S/N: 0160070986 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Solid Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,470 Hr	870	2006 Mustang 944L Telehandler S/N: 944LJX0635018 C/W: Open Operator Station, 44 ft Max Lift Height, 9000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 14.00-24 Tires Usage: 2,580 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	873	2006 SkyTrak 8042 Telehandler
863	2014 SkyTrak 8042L Telehandler S/N: 0160060584 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 5,289 Hr Asset located in: Lake Worth, TX		S/N: 0160024470 C/W: Enclosed Cab, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2006 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 2,478 Hr Asset located in: Lake Worth, TX
865	2013 JLG 8042 Telehandler	874	2012 Genie GTH-644 Telehandler
	S/N: 0160054404 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, Frame Leveling, 15.5-25 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,889 Hr Asset located in: Lake Worth, TX	074	S/N: GTH061215400 C/W: Open Operator Station, 44 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, 13.00-24 Tires Usage: 4,133 Hr Asset located in: Lake Worth, TX
066		─ <b>874A</b>	2017 JLG Skytrak 6042 Telehandler
866	Gehl RS8-42 Telehandler S/N: RS842JE0917426 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT		S/N: 0160079780 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing Usage: 1,949 Hr Asset located in: Lake Worth, TX
	Usage: 4,721 Hr <b>Asset located in</b> : Lake Worth, TX	CHOIC	E OF 4 - Lot #'s: 875, 876, 877, 878
867	2017 Gehl RS8-42 Telehandler		C OF 4 - LOT # 5. 6/3, 6/0, 6//, 6/6
	S/N: RS842CJ18031 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,714 Hr Asset located in: Lake Worth, TX	875	2014 JLG 6042 Telehandler S/N: 0160056200 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,631 Hr
CHOIC	E OF 2 - Lot #'s: 868, 869		Asset located in: Lake Worth, TX
868	2013 Gehl RS8-42 Telehandler S/N: RS842JE0617386 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,087 Hr Asset located in: Oklahoma City, OK	876	2014 JLG 6042 Telehandler S/N: 0160058949 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 47 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,476 Hr Asset located in: Lake Worth, TX
869	2013 Gehl RS8-42 Telehandler S/N: RS842JF0517510 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,342 Hr Asset located in: Oklahoma City, OK	877	2015 SkyTrak 6042 Telehandler S/N: 0160070308 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,236 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
878	2015 SkyTrak 6042 Telehandler S/N: 0160067892 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 kg Max Lift Capacity, 2014 US	СНОІСІ	E OF 2 - Lot #'s: 885, 886
CHOIC	EPA Label, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,160 Hr Asset located in: Lake Worth, TX  E OF 3 - Lot #'s: 881, 882, 883	885	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814891 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2014 US EPA Label, Forks, Frame Leveling, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,499 Hr
			Asset located in: Lake Worth, TX
881	2013 SkyTrak 6042 Telehandler S/N: 0160055011 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,040 Hr	886	2014 Gehl RS6-42 Telehandler S/N: RS642JF0814899 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 47 in Forks, 13.00-24 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,177 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	887	2018 JLG 6036 Telehandler
882	2013 SkyTrak 6042 Telehandler S/N: 0160054643 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires,		S/N: 0160083772 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 315/95-28 Solid Tires Usage: 1,190 Hr Asset located in: Humble, TX
	EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,159 Hr		
	Notes: . Asset located in: Oklahoma City, OK		E OF 12 - Lot #'s: 888, 889, 890, 891, 892, 893, 894 6, 897, 898, 899
883	2013 SkyTrak 6042 Telehandler S/N: 0160047623 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,052 Hr Notes: . Asset located in: Oklahoma City, OK	888	2014 Gehl RS6-34 Telehandler S/N: RS634JF0822387 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,160 Hr Asset located in: Lake Worth, TX
884	2013 JLG G6-42A Telehandler S/N: 0160051054 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2012 US EPA Label, 47 in Forks, Frame Leveling, 370/75- 28 Tires Usage: 4,609 Hr Asset located in: Lake Worth, TX	889	2014 Gehl RS6-34 Telehandler S/N: RS634JF0522222 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,001 Hr Asset located in: Lake Worth, TX
		890	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022527 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,227 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
891	2014 Gehl RS6-34 Telehandler S/N: RS634DF1022506 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, 15-9.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,025 Hr Asset located in: Lake Worth, TX	898	Gehl RS6-34 Telehandler S/N: RS634JE1122021 C/W: Open Operator Station, Air Ride Seat, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 60 in Forks, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,296 Hr Asset located in: Lake Worth, TX
892	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921970 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,144 Hr Asset located in: Oklahoma City, OK	899	Gehl RS6-34 Telehandler S/N: RS634DF1022514 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,338 Hr Asset located in: Lake Worth, TX
893	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921972 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,418 Hr Asset located in: Lake Worth, TX	900	Gehl RS6-34 Telehandler S/N: RS634JF0722333 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,642 Hr Asset located in: Lake Worth, TX
894	2013 Gehl RS6-34 Telehandler S/N: RS634JE0921979 C/W: Open Operator Station, 35 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,678 Hr	901	Gehl RS6-34 Telehandler S/N: RS634DF0922487 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 47.5 in Forks, Tilt Carriage, 15-19.5 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,389 Hr
	Asset located in: Oklahoma City, OK		Asset located in: Lake Worth, TX
895	2012 Gehl RS6-34 Telehandler S/N: RS634JD0121707 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2011 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 3,712 Hr Asset located in: Oklahoma City, OK	CHOICI 903	E OF 4 - Lot #'s: 903, 904, 905, 906  2013 Gehl RS5-19 Telehandler S/N: RS519YF0251046 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,565 Hr
896	2012 Gehl RS6-34 Telehandler S/N: RS634JD0321723 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 72 in Forks, Manual Coupler, Frame Leveling, 15-19.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,973 Hr Asset located in: Lake Worth, TX	904	Asset located in: Lake Worth, TX  2013 Gehl RS5-19 Telehandler  S/N: RS519YF0851124  C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,272 Hr
897	Gehl RS6-34 Telehandler S/N: RS634DG22553 C/W: Open Operator Station, 34 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Frame Leveling, Foam Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,136 Hr Asset located in: Lake Worth, TX	905	Asset located in: Lake Worth, TX  2013 Gehl RS5-19 Telehandler  S/N: RS519YF0251049  C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 48 in Forks, Manual Coupler, 12-16.5 Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 2,838 Hr  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
906	Gehl RS5-19 Telehandler S/N: RS519YE1050991 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, US EPA Label, 46 in Forks, Foam Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	911A	2000 Case 580G 8000 lb 4x2 Rough Terrain Forklift S/N: JJG0291451 C/W: 2 Stage Mast, 180 in Max Lift Height, 127 in Lowered Mast Height, 44 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 10,539 Hr Asset located in: Humble, TX
CHOIC	E OF 2 - Lot #'s: 907, 908	911B	2014 JCB 9504 4700 kg 4x4 Rough Terrain Forklift
907	2020 Manitou MT625 Telehandler S/N: MAN00000J01033352 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 5500 lb Max Lift Capacity, Hydraulic Coupler, Auxiliary Hydraulic Plumbing, 12x16.5		S/N: JCB95004H02364093 C/W: 3 Stage Mast, 127 in Lowered Mast Height, 47 in Forks, Side Shift, 2010 US EPA Label, JCB Power Sources 4 Cylinder 56 kW Diesel Engine Usage: 5,199 Hr Asset located in: Lake Worth, TX
	Tires Usage: 2,764 Hr  Asset located in: Lake Worth, TX	912	Sellick S80J4I-2 8000 lb 4x4 Rough Terrain Forklift
908	2019 Manitou MT625 Telehandler S/N: MAN00000J01021296 C/W: Enclosed Cab, 19 ft 1 in Max Lift Height, 5500 lb Max Lift Capacity, Tier 4, 2019 US EPA Label, Hydraulic Coupler, Auxiliary Hydraulic		S/N: 10015609S8J4I C/W: 3 Stage Mast, 264 in Max Lift Height, 126 in Lowered Mast Height, 69 in Forks, JCB Diesel Engine Usage: 3,868 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR
	Plumbing, 12-16.5 Tires Usage: 2,832 Hr <b>Asset located in</b> : Lake Worth, TX		
909	<b>2007 Genie GTH-5519 Telehandler</b> S/N: 17897 C/W: Open Operator Station, 19 ft Max Lift		
	Height, 5500 lb Max Lift Capacity, 2007 US EPA Label, 48 in Forks, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 1,676 Hr  Asset located in: Lake Worth, TX	913	913 2015 Ford F-750 Service Truck S/N: 3FRWF7FL6FV730422 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY
910	2015 Genie GTH-5519 Telehandler	1	INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX
	S/N: GTH5515B2885 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Frame Leveling, 12-16.5 Tires Usage: 1,522 Hr Asset located in: Lake Worth, TX	914	2024 Ford F-550 XL 4x4 Extended Cab Service Truck S/N: 1FD0X5HT8RED27006 C/W: Ford V8 6.7 L Diesel Engine, 2024 US El Label, Requires Diesel Exhaust Fluid, 11 Engi
910A	2020 JLG 3013 Telehandler S/N: H160000215 C/W: Open Operator Station, Air Ride Seat, 13 ft Max Lift Height, 2360 lb Max Lift Capacity, Tier 4, 2020 US EPA Label, 46 in Forks, Hydraulic Coupler, 11.0/65-12 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 667 Hr Asset located in: Lake Worth, TX		hrs, Engine Brake, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, PTO, Caseco MM238 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote Control, American Eagle SHD-60 Hydraulic Air Compressor, Air Hose Reel Usage: 241 Mi  Asset located in: Lake Worth, TX
911	Cat R80 8000 lb 4x2 Rough Terrain Forklift S/N: 49A01169 C/W: 3 Stage Mast, 192 in Max Lift Height, 117 in Lowered Mast Height, 48 in Forks, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX		

#### **Details** Lot # **Details** Lot # 915 2023 Ford F-550 4x4 Extended Cab Service 918 2019 Ford F-550 XL 4x4 Extended Cab Service Truck Truck S/N: 1FD0X5HTXPED24749 S/N: 1FD0X5HT0KEE24254 C/W: 6.7 L Diesel Engine, 2023 US EPA Label, C/W: Ford Power Stroke Turbo Diesel V8 6.7 L Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Diesel 330 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Suspension, 192 in Wheelbase, 2017 Altec 10 Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 193 in Wheelbase, PTO, 2019 Auto Crane 772101 13 ft 4 in Body, Hydraulic Stabilizers, 2019 Auto ft 3 in Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 2 Section Electric Crane, Wired Remote Control, Boss BA435 Hydraulic Air Compressor, Air Hose Reel, Miller Bluestar 185 Crane F79200160 7000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Miller Bobcat Welder Usage: 95 Mi 11000 W Gasoline Generator Set, Auto Crane 250 cfm PTO Air Compressor, Air Hose Reel, Asset located in: Lake Worth, TX Miller Bobcat 11000 W 250 A Gasoline Welder 916 2023 Ford F-550 XL 4x4 Extended Cab Service Usage: Not Available Truck Asset located in: Midland, TX S/N: 1FD0X5HT3PEC87656 919 2018 Ford F-550 XL 4x4 Service Truck C/W: V8 6.7 L Diesel Engine, 2023 US EPA S/N: 1FDUF5HY3JDA01060 Label, Requires Diesel Exhaust Fluid, Engine C/W: Ford V10 6.8 L Gasoline Engine, 2018 US Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 30 Engine hrs, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 11 ft Body, Hydraulic Stabilizers, Auto Crane HC-5 5000 lb 3 Section EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft Body, Vanair Air N Arc All-In-One Power System, Product Tanks, Hose Reels Hydraulic Crane, Tomahawk TWG120A Usage: 182,415 Mi Gasoline Generator Set, Boss BA435 Hydraulic Air Compressor, Air Hose Reel Notes: EQUIPMENT FROM UNITED RENTALS Usage: 308 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 920 2017 Ford F-550 XL 4x2 Service Truck S/N: 1FDUF5GT5HDA09578 CHOICE OF 2 - Lot #'s: 917, 918 C/W: Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 114706 lb Rears, 19500 lb GVWR, 917 2019 Ford F-550 4x4 Service Truck Steel, 225/70R19.5, Spring Suspension, 169 in S/N: 1FDUF5HT3KEC14526 C/W: Power Stroke V8 6.7 L 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Wheelbase, PTO, Auto Crane Titan 38K 11 ft Body, Hydraulic Stabilizers, Auto Crane HC6 6000 lb 3 Section Hydraulic Crane, Wired Fluid, Automatic Transmission, 7000 lb Front Remote Control, Gasoline Air Compressor, Axle, 14706 lb Rears, 19500 lb GVWR, 245 Lincoln Bobcat 225 Gasoline Welder /70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 2018 Stellar TMAX1-11AL 11 Usage: 69,562 Mi ft 1 in Body, Hydraulic Stabilizers, Stellar 7621 Asset located in: Lake Worth, TX 3 Section Hydraulic Crane, Wireless Remote 920A 2017 Ford F-550 XL 4x2 Service Truck Control, American Eagle 30P Piston Series Hydraulic Air Compressor, Miller Bobcat 250 S/N: 1FDUF5GT1HEB70066 C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel 250 A Gasoline Welder Usage: 190,847 Mi Exhaust Fluid, Automatic Transmission, 7000 Asset located in: Midland, TX lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, Knapheide 11 ft Body,

Hydraulic Stabilizers, Stellar 7621 7500 lb 2 Section Crane, Wireless Remote Control, Boss Hydraulic Air Compressor, Air Hose Reel

Asset located in: Lake Worth, TX

Usage: 228,233 Mi

Lot #	Details	Lot #	Details
920B	2016 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4GEA46341 C/W: Ford 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT 11 ft Body, 55 gal Oil Tanks, ( 5 ) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, Vanair Air N Arc 150 Gasoline Air Compressor, Air Hose Reel, Vanair Air N Arc 150 Welder, Rear View Camera; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 230,316 Mi Asset located in: Lake Worth, TX	924	2012 Dodge Ram 5500 4x2 Service Truck S/N: 3C7WDMBL1CG197440 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, 11 ft Body, Hydraulic Stabilizers, Stellar 7621 7500 lb 3 Section Hydraulic Crane, Wireless Remote Control Usage: 296,712 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 922, 923	СНОІС	E OF 1 - Lot #'s: 925
922	2014 Ford F-550 XL 4x4 Crew Cab Service Truck  S/N: 1FD0W5HT0EEB12698 C/W: V8 6.7 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, Knaphiede 11 ft 2 in Body, Manual Stabilizers, Auto Crane 6006EH 3 Section Electric Crane, Wired Remote Control, Compressor air systems c140gec34hc Gasoline Air Compressor, Air Hose Reel Usage: Not Available	925	2023 Chevrolet 4500 4x2 Service Truck S/N: 1HTKHPVH4PH293943 C/W: International 350 V8 6.6 L Diesel 350 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 10 Engine hrs, Allison Automatic Transmission, 7000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 141 in Wheelbase, PTO, Knapheide 9 ft Body, Manual Stabilizers, Liftmoore 4000X 4000 lb 3 Section Electric Crane, Wired Remote Control, Land Honor LHR- GAC40T Gasoline Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 54 Mi Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	927	2019 Chevrolet 4500 4x4 Crew Cab Service Truck
923	2012 Ford F-550 XL 4x4 Extended Cab Service Truck  S/N: 1FD0X5HY9CEB86563  C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 162 in Wheelbase, PTO, Knaphiede 9 ft 2 in Body, Hydraulic Stabilizers, Auto Crane 5005H 5000 lb 3 Section Hydraulic Crane, Wired Remote Control, Speedair 4LW38 Gasoline Air Compressor, Air Hose Reel Usage: 193,733 Mi		S/N: 1HTKJPVK0KH619357 C/W: NAVISTAR 350 6 Cylinder 6.6 L Diesel 350 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Allison P,R,N,D,L,1 Automatic Transmission, 7500 lb Front Axle, 13500 lb Rears, Factory-GM Drive Axles, 19500 lb GVWR, 245/70R19.5, Factory-GM Spring Suspension, 199 in Wheelbase, 2019 Auto Crane 13 ft 6 in Body, Manual Stabilizers, Auto Crane EHC 6 6000 lb 2 Section Hydraulic Crane Usage: 120,371 Mi Asset located in: Midland, TX
923A	2008 Ford F-550 4x2 Service Truck S/N: 1FDAF56R08EE06327 C/W: V8 Diesel Engine, 2008 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, United Truck Bodies 108UTB 12 ft 4 in Body, Northstar Gasoline Air Compressor Usage: 211,927 Mi Asset located in: Lake Worth, TX	928	2023 Ram 4500HD 4x2 Service Truck S/N: 3C7WRKBL5PG620080 C/W: Cummins B6.7 360 6 Cylinder 6.7 L Diesel 360 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 16 Engine hrs, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, PTO, Hydraulic Stabilizers, Palfinger PSC 6025 6000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel, Lincoln Eagle 10000 Plus Gasoline Welder Usage: 302 Mi Notes: 3 YEAR 36,000 MILE - FACTORY BUMPER TO BUMPER WARRANTY; 5 YEAR 60,000 MILE - FACTORY POWERTRAIN WARRANTY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
929	Truck S/N: 1FD0X4HT2KED48305 C/W: Ford V8 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 6500 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, Royal Truck Body 12 ft Body, Manual Stabilizers, Liftmoore 10000 lb 3 Section Electric Crane Usage: Not Available	934	2019 Ford F-350 XL 4x4 Crew Cab Utility Truck S/N: 1FD8W3HT2KEF96442 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 179 in Wheelbase, Knapheide 9 ft Body Usage: 121,763 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	-	S/N: 3C7WRSCL3HG632261
930	2013 Ford F-450 4x4 Crew Cab Service Truck S/N: 1FD0W4HY5DEB45653 C/W: Ford V8 6.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500.0 lb GVWR, 225/70R19.5, Spring Suspension, 202 in Wheelbase, PTO, 2007 11 ft Body, Manual Stabilizers, Stahl 3200 LRX 3200 lb 3 Section Electric Crane, Wired Remote Control Usage: 215,755 Mi		C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235/80R17, Spring Suspension, 170 in Wheelbase, Knapheide 9 ft Body, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	936	2017 Ram 3500 4x2 Crew Cab Utility Truck
931	2017 Ford F-250 Utility Truck S/N: 1FDBF2A62HED60788 C/W: 6.2 Gasoline Engine, Automatic Transmission, 3800 lb Front Axle, 6340 lb Rears, 9900 lb GVWR, Steel, 245/75R17, Spring Suspension, 142 in Wheelbase, Knapheide 8 ft Body Usage: 190,429 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 3C7WRSCL5HG632262 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 4102 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, Dual Rear Wheel, 235 /80R17, Spring Suspension, 172 in Wheelbase, Knapheide 6108D54J1 9 ft Body, Vanair Viper Gasoline Air Compressor, Air Hose Reel, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 104,083 Mi
932	2012 Ford F-550 XL 4x2 Crew Cab Utility Truck		Asset located in: Lake Worth, TX
	S/N: 1FD0W5GT8CEC42968 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 202 in Wheelbase, Knapheide 6132D54 11 ft Body Usage: 319,591 Mi	937	2015 Ford F-350 4x4 Crew Cab Utility Truck S/N: 1FD8W3HT5FEB51666 C/W: V8 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, Dual Rear Wheel, Spring Suspension, 7 ft Body Usage: 167,166 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	+	, , , , , , , , , , , , , , , , , , ,
933	2012 Ford F-550 4x2 Utility Truck S/N: 1FDUF5GT7CEB42748 C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 163 in Wheelbase, 10 ft 11 in Body, Manual Stabilizers, Liftmoore 3200 lb Hydraulic Crane, Wired Remote Control, Miller Wildcat 200 6500 W Gasoline Generator Set, Gasoline Air Compressor Usage: 296,236 Mi Asset located in: Lake Worth, TX	CHOIC 938	2021 Chevrolet Silverado 2500 HD 4x2 Crew Cab Utility Truck S/N: 1GB2WLE77MF235677 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2137 Engine hrs, Automatic Transmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 162 in Wheelbase, 2021 Harbor 8 ft 2 in Body Usage: 75,339 Mi Asset located in: Midland, TX

Lot #	Details	Lot #	Details
939	2021 Chevrolet Silverado 2500 HD 4x2 Utility Truck S/N: 1GB0WLE72MF189165 C/W: V8 6.6 L Gasoline Engine, 2021 US EPA Label, 2015 Engine hrs, Automatic Transmission, 4400 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 140 in Wheelbase, Scelzi 8 ft 2 in Body Usage: 109,730 Km Asset located in: Midland, TX	943	Truck S/N: 1GC1CVCG7EF160110 C/W: GM Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9500 lb GVWR, 265/70R17, Spring Suspension, 167 in Wheelbase, Omaha 8 ft Body, Air Hose Reel Usage: 161,768 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICITO SIGN REQUIRED DOCUMENTS TO
939A	<b>2016 GMC 2500HD 4x4 Crew Cab Utility Truck</b> S/N: 1GT12REG1GF303868		PROCESS TITLE  Asset located in: Lake Worth, TX
	C/W: GM V8 6.0 L Gasoline Engine, 2016 US EPA Label, 8880 Engine hrs, Automatic Transmission, 4800 lb Front Axle, 6200 lb Rears, 9900 lb GVWR, 265/70R17, Spring Suspension, Reading 9 ft Body Usage: 214,244 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	944	2012 Ford F-250 XL 4x2 Extended Cab Utility Truck S/N: 1FD7X2A6XCEC57999 C/W: Ford 6.2 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, 4250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 158 in Wheelbase, Knapheide 696J 8 ft Body Usage: 215,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
940	2015 Chevrolet 2500HD 4x4 Crew Cab Utility Truck		TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX
	S/N: 1GC1KUE87FF581426 C/W: Chevy duramax V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2003 Engine hrs, Exhaust Brake, Allison Automatic Transmission, 5600 lb Front Axle, 6200 lb Rears, 10000 lb GVWR, 285/70/R18, Spring Suspension, 2015 Coseco 8 ft Body Usage: 258,913 Mi	945	2003 Ford F-250 4x2 Extended Cab Utility Truck S/N: 1FDNX20L13EC09631 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
941	2015 Chevrolet Silverado 2500 HD 4x2 Utility Truck  S/N: 1GC0CUEG1FZ528560  C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9300 lb GVWR, 245/75R17, Spring Suspension, 130 in Wheelbase Usage: 230,081 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY-UNIT SHOWS 230,081, TITLE SHOWS 232,270  Asset located in: Humble, TX  2014 Ford F-250 XL 4x4 Extended Cab Utility	946	2009 Ford F-250 XL 4x2 Utility Truck  S/N: 1FDNF20569EA84459 C/W: Ford 5.4 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, 3950 lb Front Axle, 5892 lb Rears, 8800 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, 2009 Omaha 8 ft Body Usage: 152,394 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2008 Ford F-250 XL 4x4 Utility Truck S/N: 1FTNF21548EE41543 C/W: V8 5.4 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 6100 lb Rears, 9000 lb GVWR, 245/75R17, Spring Suspension, 137 in Wheelbase, Knapheide 8 ft Body
	Truck S/N: 1FT7X2B68EEB70690 C/W: Ford V8 6.2 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 225 /70R19.5, Spring Suspension, 142 in Wheelbase, 6 ft 10 in Body Usage: 421,371 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	948	Usage: 195,357 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2006 Chevrolet 2500 4x2 Utility Truck
		740	S/N: 1GBHC24U76E153672 C/W: V8 6.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, 245/75R16, Spring Suspension, 8 ft 2 in Body Usage: 33,621 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
949	2019 Nissan Frontier 4x2 Extended Cab Utility Truck  S/N: 1N6AD0CU5KN753789  C/W: Nissan V6 4.0 L Gasoline Engine, 2019  US EPA Label, Automatic Transmission, 3296  Ib Front Axle, 3331 lb Rears, 5588 lb GVWR, 265  /70R16, Spring Suspension, 126 in Wheelbase, 6 ft 8 in Body  Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX	953	2018 Kenworth T370 6x4 Water Truck S/N: 2NKHLJ9X7JM189233 C/W: Paccar 6 Cylinder Diesel Engine, US EPA Label, 4518.8 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 14600 lb Front Axle, 20000 lb Rears, 54600 lb GVWR, 12R22.5 Front Tires, 11R22.5 Rear Tires, 228 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 30,539 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 950, 951	954	2014 International 5900I 4000 gal 6x4 Water Truck S/N: 3HSXYSNR9EN795890
950	2020 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 1NP3LJ0X8LD732020 C/W: Paccar L9 6 Cylinder 8.9 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8871 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 18740 lb Front Axle, 40000 lb Rears, 58740 lb GVWR, Steel, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Suspension, 210 in Wheelbase, PTO, Niece WT-4K 4000 gal Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray	CHOIC	C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 476 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14777 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 285/75R24.5, Dual Steering Boxes, Air Ride Suspension, 214 in Wheelbase, Fiberglass Reinforced Plastic Tank Usage: 382,841 Mi  Asset located in: Lake Worth, TX
	Usage: 100,644 Mi Asset located in: Lake Worth, TX	CHOICE	E OF 2 - Lot #'s: 955, 956
951	2019 Peterbilt 348 4000 gal 6x4 Water Truck S/N: 2NP3LJ0XXKM624300 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 18180 lb Front Axle, 40000 lb Rears, 4.11:1 Axle Ratio, 58180 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 210 in Wheelbase, PTO, 2018 Niece Tank, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 92,315 Mi Asset located in: Lake Worth, TX	955	2014 Freightliner M2 106 4000 gal 6x4 Water Truck  S/N: 1FVHCYCYOEHFN9171  C/W: Cummins ISL 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-11210C 10-Speed Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.11:1 Axle Ratio, 58000 lb GVWR, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 196 in Wheelbase, PTO, Ledwell LW4000 WT 4000 gal Steel Tank, PTO Driven Pump, 0 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: Not Available  Asset located in: Lake Worth, TX
952	2015 Peterbilt 348 6x4 Water Truck S/N: 2NP3LJ0XXFM280411 C/W: Paccar PX-9 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9583 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 44000 lb Rears, Dana DSH44 Drive Axles, 4.88:1 Axle Ratio, 64000 lb GVWR, Aluminum Wheels, 315 /80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Air Trac 4-Bag Air Ride Suspension, 209 in Wheelbase, PTO, 2008 curry supply Steel Tank, PTO Driven Pump, 6 ft 5 in, Spray Bar, Hose Reel, In-Cab Remote Controlled Water Cannon, Front Spray, Rear Spray Usage: 118,261 Mi Asset located in: Lake Worth, TX	956	2012 Freightliner M2 106 Business Class M2 6x4 4000 Gallon 6x4 Water Truck S/N: 1FVHCYBS3CHBS9418 C/W: Cummins ISB 6 Cylinder 8.3 L Diesel 300 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4544.0 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Double Frame, Airliner 4-Bag Air Ride Suspension, 200 in Wheelbase, PTO, 2012 Ledwell LW4000WT 4000 gal Steel Tank, BERKELEY PTO Driven Pump, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
956A	C/W: Paccar PX-8 6 Cylinder Diesel Engine, 13743 Engine hrs, Exhaust Brake, Allison 3000	CHOIC	E OF 4 - Lot #'s: 961, 962, 963, 964
		961	2021 International MV607 Water Truck S/N: 3HAEUMMN0ML087250 C/W: Lands Unused Powder Coated 2000 gal Steel Tank Usage: Not Available Asset located in: Lake Worth, TX
	Hose Reel, Rear Spray, Side Spray Usage: 53,003 Mi <b>Asset located in</b> : Lake Worth, TX	962	2019 International 4300 2500 gal 4x2 Water Truck
957	2003 International 5600i 4500 gal 6x4 Water Truck  S/N: 1HTXHAHT13J068496  C/W: Cummins ISM 320V 6 Cylinder Diesel 305 hp Engine, 19509 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 212 in Wheelbase, 2013 United Truck & Equipment 4500 gal Steel Tank,		S/N: 1HTMMMML3KH515096 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4450 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 164 in Wheelbase, PTO, Lands 2500 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 191,161 Mi Asset located in: Lake Worth, TX
	Franklin Flactric Livelravilla Drivan Dvman 6 ft 0	963	2019 International MA025 2500 gal 4x2 Water Truck S/N: 1HTMMMML4KH515138 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label,
958	1999 International 8100 Vacuum Tanker Truck S/N: 1HSHCAHR2XH630060 Usage: Not Available Asset located in: Lake Worth, TX		Requires Diesel Exhaust Fluid, 4769 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 168 in Wheelbase, PTO, LANDS 2500 gal Steel Tank, PTO Driven Pump,
959	1998 Oshkosh FF-115 6x6 Water Truck S/N: 10TDCKY32WS064147 C/W: Cummins L10 6 Cylinder 10 L Diesel 260 hp Engine, 1997 US EPA Label, 4536 Engine hrs, Eaton Fuller 9-Speed Manual Transmission, Differential Lock, 23000 lb Front Axle, 45000 lb Rears, 69000 lb GVWR, Air Ride Cab, Steel, 445/65R22.5 Front Tires, 12R22.5 Rear Tires, Hendrickson Rubber over Walking Beam Suspension, 212 in Wheelbase, Housby Tank, Rear Spray, Side Spray		In-Cab Remote Controlled Water Cannon, Front Spray, Rear Spray, Side Spray, Lands Unused Powder Coated 2000 gal Steel Tank Usage: 197,374 Mi Asset located in: Lake Worth, TX
Tra Axle Cab Rea Bea		964	2018 International MA025 Water Truck S/N: 1HTMMMML0JH351983 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 105,114 Mi	CHOIC	E OF 2 - Lot #'s: 965, 966
960	Asset located in: Lake Worth, TX  1995 International 8200 6x4 Water Truck	-	2 3. 2 20. # 3. 300, 300
VOC	S/N: 1HSHGAER3SH682251 C/W: Cummins 6 Cylinder Diesel Engine, 31586 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Steel, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 164 in Wheelbase, 1 Compartments, PTO Driven Pump, Rear Spray Usage: 658,690 Mi Asset located in: Lake Worth, TX	965	2014 International 4300 4x2 Water Truck S/N: 1HTMMAAM8EH467675 C/W: International 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 177,213 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
966	2013 International 4300 2000 gal 4x2 Water Truck  S/N: 1HTMMAAL4DH202404  C/W: 6 Cylinder Diesel Engine, 7386 Engine hrs, Automatic Transmission, Steel, 11R22.5, Air Ride Suspension, 156 in Wheelbase, PTO, 2000 gal Tank, 1 Compartments, 7 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 238,027 Mi  Asset located in: Lake Worth, TX	971	2007 Ford F-750 XL 4x2 Water Truck S/N: 3FRWF75RX7V441258 C/W: Cat C7 6 Cylinder 7.2 L Diesel 230 hp Engine, 2006 US EPA Label, 5138.2 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, Aluminum Front Wheels, 11R22.5, Spring Suspension, 178 in Wheelbase, PTO, Tiger Steel Tank, Hydraulic Driven Pump, 7 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 176,955 Mi
967	<b>2011 International 4400SBA Water Truck</b> S/N: 1HSMKAAN8BH358390		Asset located in: Lake Worth, TX
	C/W: International 6 Cylinder Diesel Engine, 10838 Engine hrs, 10000 lb Front Axle, 20000 lb Rears, Air Ride Suspension, PTO, PTO Driven Pump, Rear Spray, Side Spray Usage: Not Available Asset located in: Humble, TX	972	2007 Ford F-750 4x2 Water Truck S/N: 3FRXF75N07V509486 C/W: Caterpillar 6 Cylinder Diesel Engine, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 162 in Wheelbase, PTO, Steel Tank, Berkeley PTO Drive Pump, 5 ft 5
968	2005 International 4200 2000 gal 4x2 Water Truck		in, Spray Bar, Rear Spray, Side Spray Usage: 19,377 Mi
	S/N: 1HTMPAFP95H166536	0==	Asset located in: Lake Worth, TX
	C/W: International VT365 6 Cylinder Diesel 215 hp Engine, 2004 US EPA Label, 5463 Engine hrs, 5-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5 Front Tires, 22.5 MIX Rear Tires, Spring Suspension, 152 in Wheelbase, PTO, Ledwell LW2000WT 2000 gal Steel Tank, Berkeley PTO Driven Pump, 6 ft 2 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 15,846 Mi  Asset located in: Humble, TX	973	2003 Ford F-650 XL 4x2 Water Truck S/N: 3FDNF65AX3MB00757 C/W: Cat 3126 6 Cylinder 7.2 L Diesel 330 hp Engine, 2002 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, Steel Tank, Berkeley PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 21,069 Mi
			Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 969, 970	974	2008 Ford F-650 2000 gal 4x2 Water Truck
969	2013 Ford F-750 4x2 Water Truck S/N: 3FRXF7FA1DV026323 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, 8 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 14,173 Mi		S/N: 3FRNF65A88V660849 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2007 US EPA Label, 6-Speed Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22. 5, Spring Suspension, 158 in Wheelbase, PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 17,325 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 17,325, TITLE SHOWS 40,000 Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	975	2005 Ford F-650 XL 2000 gal 4x2 Water Truck
970	2013 Ford F-750 4x2 Water Truck S/N: 3FRXF7FA8DV026450 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 3997 Engine hrs, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 12,250 Mi Asset located in: Lake Worth, TX		S/N: 3FRNF65905V181715 C/W: Cat C7 6 Cylinder 7.2 L Diesel 350 hp Engine, 2005 US EPA Label, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 10R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, PTO, Niece 2000 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Front Spray, Rear Spray Usage: 45,392 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
976	2001 International 4700 4x2 Water Truck S/N: 1HTSCAAM31H382229 C/W: International 6 Cylinder Diesel Engine, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, Steel, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 154 in Wheelbase, PTO, Steel Tank, Hose Reel, Rear Spray Usage: 138,204 Mi Asset located in: Lake Worth, TX	982	2019 Hino 338 2600 gal 4x2 Fuel Truck S/N: 5PVNV8JV1K4S58832 C/W: Hino J08E-VB 6 Cylinder 469 cid 260 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12537 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 197 in Wheelbase, PTO, 2600 gal Aluminum Tank, 3 Compartments, 2 Reels Usage: 274,979 Mi
977	2000 Sterling A9513 4x2 Water Truck S/N: 2FWWJWDBXYAB94058 C/W: Cat C12 6 Cylinder 12 L Diesel Engine, 5610 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 12000 lb Front Axle, 22000 lb Rears, 34000 lb GVWR, 11R22.5 Front Tires,		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	295/75R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 23,621 Mi Asset located in: Lake Worth, TX	983	2014 Ram 5500 4x2 Lube Truck S/N: 3C7WRMBL1EG241604 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission,
978	1998 International 4700 4x2 Water Truck S/N: 1HTSCABN9WH510827 C/W: International T444E V8 7.3 L Diesel Engine, US EPA Label, 1166 Engine hrs, Spicer 6-Speed Manual Transmission, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 151 in Wheelbase, PTO, PTO Driven Pump, 6 ft		7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 168 in Wheelbase, 11 ft Body, (3) Oil Tanks, (4) Hose Reels, Metered Nozzles, Air Hose Reel, Vanair Air N Arc 150 All-In-One Power System; EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 202,597 Mi  Asset located in: Lake Worth, TX
	8 in, Spray Bar, Front Spray, Rear Spray Usage: 15,286 Hr <b>Asset located in</b> : Lake Worth, TX	984	2016 Freightliner M2 106 1000 gal 4x2 Fuel and Lube Truck
979	1996 International 4700 4x2 Water Truck S/N: 1HTSCABN1TH276159 C/W: 6 Cylinder Diesel Engine, 9393 Engine hrs, Automatic Transmission, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 182 in Wheelbase, Steel Tank, Pump w/ Engine, 8 ft, Spray Bar, Dribble Bar Usage: 233,739 Mi Asset located in: Lake Worth, TX		S/N: 3ALACXDT1GDGY4896 C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 14852 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.00:1 Axle Ratio, 33000.0 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 2008 1000 gal Steel Tank, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 269,399 Mi
980	1990 Ford L8000F 2000 gal 4x2 Water Truck S/N: 1FTXR82A2LVA15969 C/W: Ford 6 Cylinder 7.8 L Diesel 210 hp Engine, Manual Transmission, 9000 lb Front		Notes: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
			Asset located in: Lake Worth, TX
	Axle, 21000 lb Rears, 30000 lb GVWR, Steel, 11R22.5, Spring Suspension, 150 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 6 ft 6 in, Spray Bar, Water Cannon, Front Spray, Rear Spray Usage: 457,293 Mi Asset located in: Lake Worth, TX	985	2011 Peterbilt 337 1000 gal 4x2 Fuel and Lube Truck  S/N: 2NP2HN7X5BM119419  C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 300 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 19886 Engine hrs, Eaton Fuller Automated Transmission, 12000 lb Front Axle,
981	2014 Freightliner M2 106 4x2 Propane Tanker Truck S/N: 3ALACXDT3EDFV6933 C/W: Cummins ISB 6.7 L Diesel 280 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison 3500 6-Speed Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 6.14:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 207 in Wheelbase, Westmor 3200 gal Steel Tank, 2 Reels Usage: 302,437 Mi Asset located in: Lake Worth, TX		21000 lb Rears, 4.33:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 16 ft 6 in Body, (2) 1000 gal Diesel Tank, (9) Oil Tanks, (10) Hose Reels, Metered Nozzles, Grease Barrel, Hydraulic Air Compressor, Air Hose Reel Usage: 203,370 Mi  Asset located in: Lake Worth, TX

			1 4 6 01 01 5 00	
Lot #	Details	Lot #	Details	
CHOICE OF 2 - Lot #'s: 986, 987		990	2024 Peterbilt 567 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1XPCP4EX2RD669008	
986	S/N: 1FDUF5HT8FEB16131 C/W: V8 6.7 L Diesel 309 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 162 in Wheelbase, 10 ft 10 in Body, (2) Oil Tanks, (5) Hose Reels, Metered Nozzles, Oil Recovery System, AirnArc 150 Gasoline Generator Set, Ingersoll-Rand Gasoline Air Compressor, Air Hose Reel,		C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 18-Speed Manual Transmission, 20000 lb Front Axle, 66280 lb Rears, 80000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 273 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 696 Mi  Asset located in: Lake Worth, TX	
	EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 172,086 Mi	991	2013 Peterbilt 389 8x4 Heavy Haul Tri/A Day Cab Truck Tractor	
СНОІС	Asset located in: Lake Worth, TX  E OF 1 - Lot #'s: 987		S/N: 1XPXP4EX8DD177786 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 600 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20678.2 Engine hrs,	
987	2015 Ford F-550 4x4 Fuel and Lube Truck S/N: 1FDUF5HT5FEA45745 C/W: V8 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, CTEC 12 ft Body, (2) Oil Tanks, (6) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, NAPA 82133GTH 20 cfm Gasoline Air		Engine Brake, Eaton Fuller 18-Speed Transmission, Double Differential Locks, 20000 Ib Front Axle, 60400 Ib Rears, 80000 Ib GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 265 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 461,474 Mi	
	Compressor, Air Hose Reel, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT	992	Asset located in: Lake Worth, TX  2013 Kenworth T800 8x4 Heavy Haul Tri/A Day	
	Usage: 129,968 Mi <b>Asset located in</b> : Lake Worth, TX		Cab Truck Tractor	
CHOICE OF 2 - Lot #'s: 988, 989			S/N: 1XKDP4EX0DJ358004 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 550 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18818 Engine hrs, Engine Brake, Eaton Fuller 8-Speed Manual	
988	2014 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT4EEB70543 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft Body, (4) Hose Reels, Metered Nozzles, Vanair Gasoline Air Compressor, Air Hose Reel, Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT		Transmission, Double Differential Lock Ib Front Axle, 66000 lb Rears, 4.10:1 A 80000 lb GVWR, Air Ride Cab, Aluminu Wheels, 425/65R22.5 Front Tires, 11R Rear Tires, Air Lift Pusher Axle, Air Lift Axle, Dual Steering Boxes, Double Frar Air Ride Suspension, 258 in Wheelbase	Transmission, Double Differential Locks, 20000 lb Front Axle, 66000 lb Rears, 4.10:1 Axle Ratio, 80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, 8-Bag Air Ride Suspension, 258 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,162 Mi
	Usage: 163,834 Mi <b>Asset located in</b> : Lake Worth, TX	993	2013 Peterbilt 579 8x4 Tri/A Day Cab Truck	
989	2013 Ford F-550 4x2 Fuel and Lube Truck S/N: 1FDUF5GT9DEA86667 C/W: 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 14 ft 4 in Body, (1) Diesel Tank, Metered Nozzles, Ingersoll-Rand Air Compressor, Air Hose Reel, Miller Welder, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 120,748 Mi Asset located in: Lake Worth, TX		Tractor  S/N: 1XPBD49X9DD193833  C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20865.5 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Lift Pusher Axle, Paccar Air Ride Suspension, 244 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 585,366 Mi  Asset located in: Lake Worth, TX	

This catalog was created at December 8, 2024 01:25:57 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

Details	Lot #	Details
2001 Peterbilt 379 8x4 Tri/A Day Cab Truck	997	2021 Peterbilt 389 8x4 Tri/A Sleeper Truck
Tractor S/N: 1XP5PBEXX1D567716 C/W: Cat C15 6 Cylinder 15.2 L 475 hp Engine, Engine Brake, Eaton Fuller RTLO-16918B 18- Speed Manual Transmission, Differential Lock, 14060 lb Front Axle, 63000 lb Rears, Spicer DS463P Drive Axles, 3.90:1 Axle Ratio, 77060 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 656,865 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XPXP4EX9MD740781 C/W: Cummins X15 6 Cylinder 15 L Diesel 605 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18- Speed Manual Transmission, 20000 lb Front Axle, 66000 lb Rears, 80000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Air Ride Suspension, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available
2009 Mack CHU613 8x4 Tri/A Day Cab Truck	0074	Asset located in: Lake Worth, TX
Tractor S/N: 1M2AN07Y39N003780 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 16784 Engine hrs, Mack MAXITORQUE 18-Speed Manual Transmission, 11R24.5, Air Lift Tag Axle, Camelback Spring Suspension, Air Sliding 5th Wheel, Rolling Tailboard, Dual Fuel Tanks Usage: 258,896 Mi Asset located in: Lake Worth, TX	997A	2021 Western Star 4900EX 8x4 Heavy Haul Tri /A Sleeper Truck Tractor  S/N: 5KJNABD18MPMG3713  C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 13055.3 Engine hrs, Eaton Fuller RTLO-20918B 18-Speed Manual Transmission, 18000 lb Front Axle, 66000 lb Rears, Meritor RT- 46-160P Drive Axles, 3.73:1 Axle Ratio, 83300 lb GVWR, 82 in Mid Roof Sleeper Cab, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires,
2008 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M1AN07Y98N002197 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, 6242 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 243 in Wheelbase,		Steerable Air Lift Pusher Axle, Airliner Air Ride Suspension, 291 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 295,587 Mi Notes: LOCATED-IN-FORT-WORTH-TX PER THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN
	200	Asset located in: Lake Worth, TX
PTO, Wet Kit, Air Śliding 5th Wheel, Headache Rack	998	2015 Kenworth T800 Wide Hood 8x4 Tri/A Sleeper Truck Tractor
-		S/N: 1XKDP4TX3FJ427032 C/W: Cummins ISX15 15.0 L Ultra Low Sulfur
2007 Mack CHN613 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1M1AJ07Y57N007228 C/W: Mack AC 6 Cylinder 11.9 L Diesel 460 hp Engine, 2005 US EPA Label, 13255 Engine hrs, Engine Brake, Mack Maxitorque 18-Speed Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Twin Y Air Ride Suspension, 254 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT- FROM-WATKINS-CONSTRUCTION		Diesel 550 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 9997 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, Dana D46-170H Drive Axles, 3.91:1 Axle Ratio, 86000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson Primaax EX Air Ride Suspension, 278 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY
	2001 Peterbilt 379 8x4 Tri/A Day Cab Truck Tractor S/N: 1XP5PBEXX1D567716 C/W: Cat C15 6 Cylinder 15.2 L 475 hp Engine, Engine Brake, Eaton Fuller RTLO-16918B 18- Speed Manual Transmission, Differential Lock, 14060 lb Front Axle, 63000 lb Rears, Spicer DS463P Drive Axles, 3.90:1 Axle Ratio, 77060 lb GWWR, Air Ride Cab, 385/65R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 656,865 Mi Asset located in: Lake Worth, TX  2009 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M2AN07Y39N003780 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 16784 Engine hrs, Mack MAXITORQUE 18-Speed Manual Transmission, 11R24.5, Air Lift Tag Axle, Camelback Spring Suspension, Air Sliding 5th Wheel, Rolling Tailboard, Dual Fuel Tanks Usage: 258,896 Mi Asset located in: Lake Worth, TX  2008 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M1AN07Y98N002197 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, 6242 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GWWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 243 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 591,040 Mi Asset located in: Lake Worth, TX  2007 Mack CHN613 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1M1AJ07Y57N007228 C/W: Mack AC 6 Cylinder 11.9 L Diesel 460 hp Engine, 2005 US EPA Label, 13255 Engine hrs, Engine Brake, Mack Maxitorque 18-Speed Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Twin Y Air Ride Suspension, 254 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-	2001 Peterbilt 379 8x4 Tri/A Day Cab Truck Tractor  S/N: 1XP5PBEXX1D567716 C/W: Cat C15 6 Cylinder 15.2 L 475 hp Engine, Engine Brake, Eaton Fuller RTLO-16918B 18- Speed Manual Transmission, Differential Lock, 14060 lb Front Axle, 63000 lb Rears, Spicer DS463P Drive Axles, 3.90:1 Axle Ratio, 77060 lb GVWR, Air Ride Cab, 385/65R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 656,865 Mi Asset located in: Lake Worth, TX  2009 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M2AN07Y39N003780 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 16784 Engine hrs, Mack MAXITORQUE 18-Speed Manual Transmission, 11R24.5, Air Lift Tag Axle, Camelback Spring Suspension, Air Sliding 5th Wheel, Rolling Tailboard, Dual Fuel Tanks Usage: 258,896 Mi Asset located in: Lake Worth, TX  2008 Mack CHU613 8x4 Tri/A Day Cab Truck Tractor S/N: 1M1AN07Y98N002197 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, 6242 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, 243 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 591,040 Mi Asset located in: Lake Worth, TX  2007 Mack CHN613 8x4 Heavy Haul Tri/A Day Cab Truck Tractor S/N: 1M1A,07Y57N007228 C/W: Mack AC 6 Cylinder 11.9 L Diesel 460 hp Engine, 2005 US EPA Label, 13255 Engine hrs, Engine Brake, Mack Maxitorque 18-Speed Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Twin Y Air Ride Suspension, 254 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-

This catalog was created at December 8, 2024 01:25:57 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
999	2008 Western Star 4900 8x4 Tri/A Sleeper Truck Tractor  S/N: 5KJNALAV48PZ19813  C/W: Cat C15 6 Cylinder 14.6 L Diesel 550 hp Engine, Engine Brake, Eaton Fuller RTLO-22918B 18-Speed Manual Transmission, 20000 lb Front Axle, 66000 lb Rears, 4.56:1  Axle Ratio, 78150 lb GVWR, Air Ride Cab, 40 in Mid Roof Sleeper Cab, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Airliner Air Ride Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: 777,671 Mi	1003	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X3JD468940 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12339 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 216 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 251,546 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1004	2018 Peterbilt 389 6x4 T/A Day Cab Truck
1000	2020 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X4LD636684 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13970 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 240 in Wheelbase, Headache Rack, Dual Fuel Tanks		Tractor S/N: 1XPXD49X1JD468922 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12890 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 254,950 Mi Asset located in: Lake Worth, TX
	Usage: 391,604 Mi <b>Asset located in</b> : Lake Worth, TX	1005	2018 Peterbilt 389 6x4 T/A Day Cab Truck
1001	2019 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X0KD266266 C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 17028 Engine hrs, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, 11R24.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel Usage: 470,871 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XPXD49X0JD468958 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11930 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 216 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Air Sliding 5th Wheel Usage: 261,844 Mi  Asset located in: Lake Worth, TX
011010	- OF C   Way 1000 1000 1001 1005 1005 1005	1006	2018 Peterbilt 389 6x4 T/A Day Cab Truck
1002	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X0JD468877 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11115 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, Paccar Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Wheel Usage: 239,179 Mi		Tractor S/N: 1XPXD49X0JD468930 C/W: Cummins X15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 12410.3 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel Usage: 282,762 Mi Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1007 2018 Peterbilt 389 6x4 T/A Day Cab Truck 1012 2016 Peterbilt 367 6x4 T/A Day Cab Truck **Tractor** Tractor S/N: 1XPXD49X4JD468879 S/N: 1XPTD40X5GD334936 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12212 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Transmission, 13200 lb Front Axle, 40000 lb Differential Locks, 14320 lb Front Axle, 46000 Rears, 53200 lb GVWR, Air Ride Cab, Aluminum lb Rears, 60320 lb GVWR, Air Ride Cab, Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 200 in Wheelbase, Air Sliding Usage: 292,060 Mi 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-Asset located in: Lake Worth, TX CORP-COMPANY 1009 2012 Peterbilt 389 6x4 T/A Day Cab Truck Usage: 99,798 Mi Tractor Notes: . S/N: 1XPXDP9X2CD158752 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 17118.9 Engine hrs, Asset located in: Humble, TX 1013 2016 Peterbilt 367 6x4 T/A Day Cab Truck Tractor Engine Brake, Eaton Fuller 13-Speed Manual S/N: 1XPTD40X7GD334940 Transmission, Differential Lock, 12000 lb Front C/W: Cummins ISX15 6 Cylinder 15 L Diesel Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Tires, 11R24.5 Rear Tires, Air Trac Air Ride 7220.5 Engine hrs, Engine Brake, 14320 lb Suspension, 235 in Wheelbase, Air Sliding 5th Front Axle, 46000 lb Rears, 60320 lb GVWR, 11R24.5, Air Trac Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Headache Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 350,526 Mi Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-Asset located in: Lake Worth, TX PRIMORIS-SERVICES-CORP-COMPANY Usage: 131,902 Mi 1010 2012 Peterbilt 388 6x4 T/A Day Cab Truck Asset located in: Humble, TX Tractor 1014 2016 Peterbilt 367 6x6 T/A Day Cab Truck S/N: 1XPWDP0X1CD140235 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2011 US EPA Label, Requires S/N: 1XPTD40X7GD334937 Diesel Exhaust Fluid, 18806.4 Engine hrs, Eaton C/W: Cummins ISX15 6 Cylinder 15 L Diesel Fuller 10-Speed Manual Transmission, 14320 485 hp Engine, 2015 US EPA Label, CARB Ib Front Axle, 46000 lb Rears, 60320 lb GVWR, Compliant, Requires Diesel Exhaust Fluid, Air Ride Cab, 11R24.5, Air Trac Air Ride 5526.6 Engine hrs, Engine Brake, Eaton Fuller Suspension, 214 in Wheelbase, Dual Fuel Tanks 18-Speed Manual Transmission, Double Usage: 306,786 Mi Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Asset located in: Lake Worth, TX Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, CHOICE OF 4 - Lot #'s: 1011, 1012, 1013, 1014 EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 208,518 Mi 1011 2016 Peterbilt 367 6x4 T/A Day Cab Truck Notes: . S/N: 1XPTD40X3GD334935 Asset located in: Humble, TX C/W: Cummins ISX15 6 Cylinder 15 L Diesel

C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5172.2 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY

Usage: 181,470 Mi

Notes: .

Asset located in: Humble, TX

# 1015 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor

S/N: 3WKDD40X1LF369046 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 268 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 297,971 Mi

1 -+ "	D.A. II.	1 - 4 #	D.A. H.
Lot #	Details	Lot #	Details
1021, 1	CHOICE OF 9 - Lot #'s: 1016, 1017, 1018, 1019, 1020, 1021, 1022, 1023, 1024		2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X2LF369055 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust
1016	16 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 1XKDD40X5LR369029 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 268 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	Au 23 Al 11 W Ta Us	Fluid, 18503.8 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 243 ir Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 262,049 Mi Asset located in: Lake Worth, TX  2020 Kenworth T800 6x4 T/A Day Cab Truck
	Usage: 282,374 Mi		<b>Tractor</b> S/N: 1XKDD40X1LR369030
1017	Asset located in: Lake Worth, TX  2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40X9LF369053  C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab Aluminum Whoele, 11824 5 Air Ride		C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 19464 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 60321 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 305,184 Mi
	Usage: 525,807 MI		Asset located in: Lake Worth, TX
		1023	23 2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor
1018	Asset located in: Lake Worth, TX  2020 Kenworth T800 T/A Day Cab Truck Tractor S/N: 1XKDD40X2LR369022 Usage: Not Available Asset located in: Lake Worth, TX	S/N: 1XKDD40X2LR369036 C/W: Cummins X15 6 Cylindo 450 hp Engine, 2019 US EPA Diesel Exhaust Fluid, 10215 B Brake, Eaton Fuller Automate Double Differential Locks, 14 46000 lb Rears, 3.73:1 Axle F GVWR, Air Ride Cab, Aluminu 5, 8-Bag Air Ride Suspension Wheelbase, Air Sliding 5th W Tanks Usage: 112,632 Mi	S/N: 1XKDD40X2LR369036 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10215 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60321 lb
1019	2020 Kenworth T800 T/A Day Cab Truck Tractor S/N: 3WKDD40X4LF369042 Usage: Not Available Asset located in: Lake Worth, TX		GVWR, Air Ride Cab, Aluminum Wheels, 11R 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1020	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40X8LF369044  C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 21597.7 Engine hrs, Eaton Fuller FAO-16810C 10-Speed Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 216 in Wheelbase, PTO, Blower, Dual Fuel Tanks Usage: 363,166 Mi Asset located in: Lake Worth, TX	1024	2020 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40XXLF369059  C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9057 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, 8-Bag Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 100,288 Mi  Asset located in: Lake Worth, TX

			č
Lot #	Details	Lot #	Details
CHOICI 1025	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40X7KF257267 C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23462.2 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 23000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5 Front Tires,	1029	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40X7KF369082  C/W: Cummins X15 V10 15 L 450 hp Engine, 2018 US EPA Label, CARB Compliant, 19985  Engine hrs, Eaton Fuller UltraShift Plus 18- Speed Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Aluminum Wheels, 11R24.5, AG400 8-Bag Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Blower Usage: 298,935 Mi  Asset located in: Lake Worth, TX
	11R24.5 Rear Tires, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 358,214 Mi <b>Asset located in</b> : Lake Worth, TX	1030	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 3WKDD40XXKF369089 C/W: Cummins X15 6 Cylinder 15 L Diesel 450
1026	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40X9KF257268  C/W: Cummins X15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 23630.9 Engine hrs, Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 279,656 Mi		hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19786 Engine hrs, Engine Brake, Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Dana D46-172 Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 325,018 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1030A	•
1027	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40X7KF369101  C/W: Cummins ISX15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19647 Engine hrs, Engine Brake, Automatic Transmission, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 338,611 Mi		Tractor S/N: 3WKDD40X5KF369100 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 6495 kg Front Axle, 20866 lb Rears, 27361 kg GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 336,440 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1031	2014 Kenworth T800 6x4 T/A Day Cab Truck
1028	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 3WKDD40X6KF257275  C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 16403.1 Engine hrs, Engine Brake, Eaton UltraShift Plus Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, AG400 8-Bag Air Ride Suspension, 243 in Wheelbase, Blower, Dual Fuel Tanks Usage: 237,353 Mi		Tractor S/N: 1XKDDP9X7EJ387103 C/W: Paccar MX 6 Cylinder 12.9 L Engine, 201 US EPA Label, Requires Diesel Exhaust Fluid, 15503 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 324,545 Mi  Asset located in: Lake Worth, TX

## This catalog was created at December 8, 2024 01:25:57 PM GMT. Please check our website for the most accurate and up-to-date information.

Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1032 2014 Kenworth T800 6x4 T/A Day Cab Truck 1036 2012 Kenworth T800 6x4 T/A Day Cab Truck **Tractor** Tractor S/N: 1XKDDP9X0CJ335275 S/N: 1XKDDP9X9EJ404502 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11282 Engine hrs, Engine 430 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 181 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, Manual Transmission, Differential Lock, 12350 Ib Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 3.70:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, 40000 lb Rears, Dana Drive Axles, 3.55:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Airglide Suspension, 185 in Wheelbase, PTO, Suspension, 187 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 297,724 Mi Wet Kit, Air Sliding 5th Wheel, Headache Rack, **Dual Fuel Tanks** Usage: 282,261 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1037 2012 Kenworth T800 6x4 T/A Day Cab Truck 1033 2014 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDD40X4CR298390 S/N: 1XKDDP9XXEJ367542 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel C/W: Paccar 6 Cylinder 12.9 L 455 hp Engine, 500 hp Engine, 2011 US EPA Label, Requires 2012 US EPA Label, 13028 Engine hrs, Eaton Diesel Exhaust Fluid, 17475 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Fuller FO-16E313A-MHP ULT Automatic Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 295/75R22. Axles, 4.89:1 Axle Ratio, 60321 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 5, 8-Bag Air Ride Suspension, 194 in Rear Tires, Double Frame, Neway Air Ride Suspension, 209 in Wheelbase, Air Sliding 5th Wheelbase, PTO, Air Sliding 5th Wheel, Dual **Fuel Tanks** Usage: 297,728 Mi Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Asset located in: Humble, TX Usage: 324,740 Mi 1034 2013 Kenworth T800 T/A Day Cab Truck Asset located in: Lake Worth, TX Tractor 1037A 2018 Kenworth T880 6x4 T/A Day Cab Truck S/N: 1XKDD40X9DJ345459 Tractor C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-**INFRASTRUCTURE** S/N: 1XKZDP9X1JJ215858 C/W: Paccar 6 Cylinder Diesel Engine, Requires Usage: Not Available Diesel Exhaust Fluid, 8375 Engine hrs, Engine Asset located in: Humble, TX Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350.0 lb GVWR, Air CHOICE OF 2 - Lot #'s: 1035, 1036 Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel 1035 2012 Kenworth T800 6x4 T/A Day Cab Truck Usage: 237,444 Mi Tractor Notes: DEFICIENCIES NOTED - PLEASE SEE S/N: 1XKDDP9X2CJ335276 THE INSPECTION REPORT C/W: Paccar MX 6 Cylinder 12.9 L Diesel Engine, 2011 US EPA Label, Requires Diesel Asset located in: Humble, TX Exhaust Fluid, 18030 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.55:1 CHOICE OF 6 - Lot #'s: 1038, 1039, 1040, 1041, 1042, 104

Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** 

Usage: 343,666 Mi

Asset located in: Lake Worth, TX

#### 1038 2016 Kenworth T880 T/A Day Cab Truck **Tractor**

S/N: 1XKZDP9XXGJ495370

C/W: EQUIPMENT-FROM-SUNSTATE-

**EQUIPMENT** Usage: 241,499 Mi

			1 age 88 01 300
Lot #	Details	Lot #	Details
1039	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor  S/N: 1XKZDP9X2GJ495377 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR015210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Detroit Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airglide Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 293,721 Mi Asset located in: Lake Worth, TX	1043	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor  S/N: 1XKZDP9X3GJ495372  C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 352,092 Mi  Asset located in: Lake Worth, TX
1040	2016 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1GJ495371 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 276,776 Mi Asset located in: Lake Worth, TX	CHOIC	E OF 2 - Lot #'s: 1044, 1045  2015 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXFJ445423
1041	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor  S/N: 1XKZDP9XXGJ486765  C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Headache Rack,		C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15520 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 376,184 Mi  Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 269,329 Mi <b>Asset located in</b> : Lake Worth, TX	1045	2015 Kenworth T880 6x4 T/A Day Cab Truck Tractor
1042	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X0GJ495376 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Double Frame, 8-Bag Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 280,242 Mi		S/N: 1XKZDP9X8FJ425865 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 430 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 316,151 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	2022 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1XPCD49X8ND788534 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 226 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 140,650 Mi	1050	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor  S/N: 1XPCD40X7KD611272  C/W: Cummins X15 6 Cylinder 15 L Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 239,603 Mi Asset located in: Lake Worth, TX  E OF 4 - Lot #'s: 1051, 1053, 1054, 1055
	Asset located in: Lake Worth, TX	CHOIC	E OF 4 - LOT # S: 1051, 1053, 1054, 1055
1047	2022 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1XPCD49X4ND788532 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 152,789 Mi Asset located in: Lake Worth, TX  2022 Peterbilt 567 6x4 T/A Day Cab Truck	1051	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X6GD332564 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27335.9 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 596,995 Mi Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - MAIN KEY Asset located in: Lake Worth, TX
	Tractor S/N: 1XPCD49X6ND788533 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4410 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5, Air Trac Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,800 Mi Asset located in: Lake Worth, TX	1053	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X4GD332529 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24210 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 206 in Wheelbase, PTO, Blower, Auto Lube Usage: 565,546 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 1049, 1050	1054	2015 Peterbilt 365 6x4 T/A Day Cab Truck
1049	2020 Peterbilt 567 6x4 T/A Day Cab Truck Tractor  S/N: 1NPCD40X8LD649153  C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Dual Steering Boxes, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 198,766 Mi Asset located in: Lake Worth, TX		Tractor S/N: 1XPSD79X9FD262699 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20820 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 206 in Wheelbase, PTO, Blower, Auto Lube Usage: 553,424 Mi Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1055 2015 Peterbilt 365 6x4 T/A Day Cab Truck 1060 2020 Freightliner SD122 6x4 T/A Day Cab **Tractor Truck Tractor** S/N: 3AKJGNDV6LDLZ5583 S/N: 1XPSD79X3FD262701 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 27922 Engine hrs, Engine Exhaust Fluid, 8086 Engine hrs, Engine Brake, Brake, Eaton Fuller 8LL Manual Transmission, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, Blower, Dual Fuel Tanks Usage: 719,738 Mi Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Asset located in: Lake Worth, TX Usage: 114,295 Mi 1056 2014 Peterbilt 365 6x4 T/A Day Cab Truck Asset located in: Lake Worth, TX Tractor 1061 2020 Freightliner SD122 6x4 T/A Day Cab S/N: 1XPSD79X7ED225682 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2013 US EPA Label, 35544 **Truck Tractor** S/N: 3AKJGNDV8LDMF6945 Engine hrs, Engine Brake, Eaton Fuller 8LL C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7577 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-Aluminum Wheels, 11R22.5, Air Ride Suspension, 203 in Wheelbase, Auto Lube Usage: 620,451 Mi 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5, Asset located in: Lake Worth, TX Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 125,283 Mi 1056A 2012 Peterbilt 367 T/A Day Cab Truck Tractor S/N: 2XPTD40X9CM137840 Usage: 344,254 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1062 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** S/N: 3AKJGNDV6LDMF6944 CHOICE OF 8 - Lot #'s: 1058, 1059, 1060, 1061, 1062, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 1063, 1064, 1065 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7652 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission 1058 2020 Freightliner SD122 6x4 T/A Day Cab Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 **Truck Tractor** S/N: 3AKJGNDV2LDLZ5581 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Hendrickson Air Ride Suspension, 196 in Exhaust Fluid, 6973 Engine hrs, Engine Brake, Wheelbase, Air Sliding 5th Wheel Allison 4700 RDS Automatic Transmission, Usage: 137,436 Mi 13300 lb Front Axle, 46000 lb Rears, Meritor RT-Asset located in: Lake Worth, TX 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, Steel, 11R24.5 1063 2020 Freightliner SD122 6x4 T/A Day Cab Hendrickson Air Ride Suspension, 196 in **Truck Tractor** Wheelbase, Air Sliding 5th Wheel Usage: 109,108 Mi S/N: 3AKJGNDV3LDMF6934 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Asset located in: Lake Worth, TX hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8183 1059 2020 Freightliner SD122 6x4 T/A Day Cab Engine hrs, Engine Brake, Allison 4700 RDS **Truck Tractor** Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-S/N: 3AKJGNDV4LDLZ5582 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7090.33 Engine hrs, Engine Brake, Allison 4700 RDS Automatic lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 139,306 Mi Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Asset located in: Lake Worth, TX

Axles, 4.30:1 Axle Ratio, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Air Ride Suspension, 196 in

Wheelbase, Air Sliding 5th Wheel Usage: 109,592 Mi Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1064 2020 Freightliner SD122 6x4 T/A Day Cab 1068 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor Truck Tractor** S/N: 3AKJGNDV5LDMF6935 S/N: 3AKJGNDV7LDMF6936 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8247 Engine hrs, Engine Brake, hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7764 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Hendrickson Air Ride Suspension, 196 in Usage: 144,087 Mi Wheelbase, Air Sliding 5th Wheel Usage: 159,984 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1065 2020 Freightliner SD122 6x4 T/A Day Cab 1069 2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor Truck Tractor S/N: 3AKJGNDV0LDMF6938 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel S/N: 3AKJGNDV0LDMF6941 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Exhaust Fluid, 8251.39 Engine hrs, Engine hp Engine, 2019 US EPA Label, Requires Diesel Brake, Allison 4700 RDS Automatic Exhaust Fluid, 7204 Engine hrs, Engine Brake, Allison 4700 RDS 6-Speed Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24.5 Rear Tires, Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 146,736 Mi 5th Wheel Usage: 163,146 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1070 2020 Freightliner SD122 6x4 T/A Day Cab CHOICE OF 8 - Lot #'s: 1066, 1067, 1068, 1069, 1070, **Truck Tractor** 1071, 1072, 1073 S/N: 3AKJGNDV9LDMF6940 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7512.45 Engine hrs, Engine Brake, Allison 4700 RDS Automatic 1066 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** S/N: 3AKJGNDV2LDMF6942 Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, 11R24.5, Hendrickson Air Ride C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6915 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Suspension, 196 in Wheelbase, Air Sliding 5th Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Wheel Usage: 166,473 Mi Axle Ratio, 59300 lb GVWR, Air Ride Cab, Asset located in: Lake Worth, TX 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel 1071 2020 Freightliner SD122 6x4 T/A Day Cab Usage: 149,353 Mi Truck Tractor Asset located in: Lake Worth, TX S/N: 3AKJGNDV2LDMF6939 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel 1067 2020 Freightliner SD122 6x4 T/A Day Cab **Truck Tractor** Exhaust Fluid, 8294 Engine hrs, Engine Brake, S/N: 3AKJGNDVXLDMF6946 Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 59300

S/N: 3AKJGNDVXLDMF6946 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7122.12 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24. 5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 158,266 Mi

Asset located in: Lake Worth, TX

Sliding 5th Wheel Usage: 182,995 Mi

lb GVWR, Air Ride Cab, 11R24.5, Hendrickson

Air Ride Suspension, 196 in Wheelbase, Air

Lot #	Details	Lot #	Details
1072	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV4LDMF6943 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8575.57 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, Air Ride Cab, 11R24.5, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 206,153 Mi Asset located in: Lake Worth, TX	1076	2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor  S/N: 3AKJGND64EDFT1921  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 18532 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner 4-Bag Air Ride Suspension, 224 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 394,360 Mi
1073	2020 Freightliner SD122 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGNDV9LDMF6937 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8897.09 Engine hrs, Engine Brake, Allison 4700 RDS Automatic Transmission, Differential Lock, 13300 lb Front Axle, 46000 lb Rears, Meritor RT-46-160P Drive Axles, 4.30:1 Axle Ratio, 59300 lb GVWR, Air Ride Cab, All Steel, 11R24.5 Front Tires, 11R24. 5 Rear Tires, Hendrickson Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel Usage: 212,117 Mi Asset located in: Lake Worth, TX  2019 Freightliner Coronado 122SD 6x4 T/A	1077	Asset located in: Lake Worth, TX  E OF 2 - Lot #'s: 1077, 1078  2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor  S/N: 1FVXFB00XBDBC0203  C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: 669,379 Mi  Asset located in: Lake Worth, TX
	Day Cab Truck Tractor  S/N: 3AKJGNDR5KDKK3918  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12990 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.58:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 497,607 Mi Asset located in: Lake Worth, TX	1078	2011 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor S/N: 1FVXFB008BDBC0202 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 709,338 Mi Asset located in: Lake Worth, TX
011010		сноіс	E OF 2 - Lot #'s: 1079, 1080

CHOICE OF 2 - Lot #'s: 1075, 1076

## 1075 2014 Freightliner Coronado 122 6x4 T/A Day Cab Truck Tractor

S/N: 3AKJGNDV4EDFU3235 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 9972 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.91:1 Axle Ratio, 52000 lb GVWR, 275 /80R22.5, Airliner Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 210,817 Mi

Asset located in: Lake Worth, TX

### 1079 2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor

S/N: 5KJJAVDV9FPGC9066 C/W: Detroit DD13 12.8 L Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 220 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 537,904 Mi

Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1080	2015 Western Star 4700 6x4 T/A Day Cab Truck Tractor S/N: 5KJJAVDV4FLGW9017 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, Requires Diesel Exhaust Fluid, 13494 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 3.91:1 Axle Ratio, 58000 lb GVWR, Air Ride Cab, 11R24.5, Airliner Air Ride Suspension, 210 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 325,533 Mi	1085	2013 International 7500 6x4 T/A Day Cab Truck Tractor S/N: 1HSWPAZR8DJ239297 C/W: International International 570 6 Cylinder 9.3 L Diesel Engine, 2012 US EPA Label, 5501 Engine hrs, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, PTO, Wet Kit Usage: 28,123 Mi Asset located in: Lake Worth, TX
4004	Asset located in: Lake Worth, TX	Сноісі	E OF 4 - Lot #'s: 1086, 1087, 1088, 1089
1081	2016 Cat CT680L 6x4 T/A Day Cab Truck Tractor S/N: 3HSKBTKTXGN379223 C/W: Cat CT13 6 Cylinder 12.4 L 475 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8172 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Hendrickson Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,040 Mi Asset located in: Lake Worth, TX	1086	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X2PD889441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2693 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 186 in Wheelbase, Wet Kit, Air Sliding 5th Wheel Usage: 54,153 Mi
1082	2012 Cat CT660S 6x4 T/A Day Cab Truck		Notes: . Asset located in: Humble, TX
	Tractor S/N: 1HTJGTKT7CJ635078 C/W: Cat CT13 6 Cylinder 13 L Diesel Engine, 2011 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 70000 lb GVWR, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, 241 in Wheelbase Usage: 123,545 Mi Asset located in: Humble, TX	1087	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X4PD889442 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3278 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride
CHOIC	CHOICE OF 2 - Lot #'s: 1083, 1084		Suspension, 192 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 62,819 Mi <b>Notes</b> : .
1083	2017 International TranStar 8600 T/A Day Cab		Asset located in: Humble, TX
	Truck Tractor S/N: 3HSHXSNRXHN412325 Usage: Not Available Asset located in: Lake Worth, TX	1088 20 Tra S// C/ 45 Die Bra Tra Re Air Kit Us No	2023 Peterbilt 579 6x4 T/A Day Cab Truck Tractor S/N: 1XPBDP9X6PD875834 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel
1084	2014 International 8600 6x4 T/A Day Cab Truck Tractor S/N: 1HSHXSJR4EH754607 C/W: Navistar N13 6 Cylinder 13 L Diesel Engine, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Asset located in: Humble, TX		456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 2323 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Air Leaf Air Ride Suspension, 190 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 72,678 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1089	7223 Peterbilt 579 6x4 T/A Day Cab Truck Tractor  S/N: 1XPBDP9X8PD875835 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3195 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Leaf Air Ride Suspension, 189 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 77,420 Mi	1093	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY6KM008144 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11664 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 174 in Wheelbase Usage: 517,765 Mi Asset located in: Lake Worth, TX
	Notes: .	1094	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor
1090	Asset located in: Humble, TX  2020 Peterbilt 579 6x2 T/A Day Cab Truck Tractor  S/N: 1XPBAK9X6LD656295  C/W: Paccar mx11 6 Cylinder 10.8 L Diesel Engine, 2019 US EPA Label, 9406 Engine hrs, Engine Brake, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 178 in Wheelbase, Air		S/N: 1M1AN4GY6KM003456 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15036 Engine hrs, Engine Brake, Mack mDrive Automatic Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 743,483 Mi Asset located in: Humble, TX
	Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,689 Mi	1095	2019 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor
1091	Asset located in: Lake Worth, TX  2019 Peterbilt 579 6x4 T/A Day Cab Truck Tractor  S/N: 1XPBD49X5KD619305  C/W: Cummins ISX15 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10474.6 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 19000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 220 in	1096	S/N: 1M1PN4GY4KM002736 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 429,136 Mi Asset located in: Lake Worth, TX
	Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 153,131 Mi <b>Asset located in</b> : Lake Worth, TX		96 2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 1FUJHLDR2KLKW2362
1092	2022 Mack Pl64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY9NM010092 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MDrive 12- Speed Automated Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Neway Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks		
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1097	2019 Freightliner Cascadia 126 T/A Day Cab Truck Tractor S/N: 3AKJHLDV5KSKE1227 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 460,195 Mi

#### **Details** Lot # **Details** Lot # 1098 1102 2021 Freightliner Cascadia 116 6x4 T/A Day 2017 Peterbilt 579 6x4 T/A Day Cab Truck **Cab Truck Tractor Tractor** S/N: 3AKJHTDV3MSMF5488 S/N: 1XPBDP9X1HD387523 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel hp Engine, 2020 US EPA Label, CARB 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19516 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Compliant, Requires Diesel Exhaust Fluid, 9731 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 184 in Wheelbase Rear Wheels, 11R24.5, Paccar Air Ride Suspension, 192 in Wheelbase, PTO, Blower Usage: 356,606 Mi Usage: 731,511 Mi Notes: THIS UNIT RUNS BUT MAY HAVE Asset located in: Lake Worth, TX DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE CHOICE OF 3 - Lot #'s: 1103, 1104, 1105 RESTORATION OF ALL POLLUTION CONTROL 1103 2013 Peterbilt 386 6x4 T/A Day Cab Truck SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE S/N: 1XPHDP9X5DD190441 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel PRIOR TO REMOVAL OF UNIT FROM YARD 405 hp Engine, 2012 US EPA Label, Requires Asset located in: Lake Worth, TX Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 1099 2019 Volvo VNL760 6x4 T/A Sleeper Truck 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Leaf Air Ride Suspension, 186 in Wheelbase, Air Sliding **Tractor** S/N: 4V4NC9EH7KN193984 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 5th Wheel 455 hp Engine, 2018 US EPA Label, Requires Usage: 783,395 Mi Diesel Exhaust Fluid, Engine Brake, Volvo Asset located in: Humble, TX ATO2612F 12-Speed Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb 1104 2013 Peterbilt 386 6x4 T/A Day Cab Truck Rears, 53200 lb GVWR, 70 in High Rise Sleeper Tractor Cab, Bunk Beds, Aluminum Wheels, 295/75R22. S/N: 1XPHDP9X7DD190442 5, Air Ride Suspension, 224 in Wheelbase, Air C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2012 US EPA Label, Requires Sliding 5th Wheel, Dual Fuel Tanks Usage: 480,468 Mi Diesel Exhaust Fluid, 20012 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front Asset located in: Lake Worth, TX 1100 2019 International LT625 6x4 T/A Day Cab **Truck Tractor** Tires, 445/50R22.5 Super Singles Rear Tires, S/N: 3HCDZAPR8KL194089 Air Leaf 4-Bag Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel C/W: Cummins X15 505 6 Cylinder 15.0 L Diesel 505 hp Engine, 2018 US EPA Label, Usage: 382,740 Mi Requires Diesel Exhaust Fluid, 10422 Engine Asset located in: Humble, TX hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb 1105 2013 Peterbilt 386 6x4 T/A Day Cab Truck GVWR, Air Ride Cab, Aluminum Wheels, 11R22. **Tractor** 5, Air Ride Suspension, 199 in Wheelbase, PTO, S/N: 1XPHDP9X9DD190443 Wet Kit, Air Sliding 5th Wheel, Headache Rack, C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel **Dual Fuel Tanks** 405 hp Engine, 2012 US EPA Label, Requires Usage: 171,523 Mi Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Asset located in: Lake Worth, TX 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air 1101 2018 Peterbilt 579 6x4 T/A Day Cab Truck Ride Cab, Aluminum Wheels, 11R22.5 Front **Tractor** Tires, 445/50R22.5 Super Singles Rear Tires, S/N: 1XPBDP9X1JD490933 Air Leaf Air Ride Suspension, 183 in C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Wheelbase, Air Sliding 5th Wheel Usage: 346,321 Mi Exhaust Fluid, Engine Brake, Paccar Automated Asset located in: Humble, TX Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 455/50R22.5 Rear Tires, Paccar Air Ride Suspension, 168 in Wheelbase Usage: Not Available

		I		
Lot #	Details	Lot #	Details	
1106	Tractor S/N: 1XPHD49X2CD135202 C/W: Cummins ISX15 15.0 L Diesel 500 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 20630 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb	1111	2015 Kenworth T370 T/A Day Cab Truck Tractor S/N: 2XKHAJ8XXFM458197 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 212,393 Hr Asset located in: Lake Worth, TX	
		1112	2017 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1HM081245 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 4592 Engine hrs, Engine Brake,	
1107	2018 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYD49X1JJ198747 C/W: Cummins X15 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19006 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission,	CHOICE	Mack mDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 204 in Wheelbase Usage: 569,651 Mi  Asset located in: Humble, TX	
	Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, 8- Bag Air Ride Suspension, 187 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower Usage: 633,908 Mi		E OF 3 - Lot #'s: 1113, 1114, 1115  2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor	
	Asset located in: Lake Worth, TX	_	S/N: 1M1AW09YXGM056302	
1108	2015 Kenworth T680 6x2 T/A Day Cab Truck Tractor S/N: 1XKYAP9X7FJ437901 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 34000 lb Rears, 3.42:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22. 5, Flex Air Air Ride Suspension, 225 in		C/W: Mack MP8 6 Cylinder hp Engine, 2015 US EPA La Exhaust Fluid, Engine Brak Transmission, 13220 lb Fro Rears, 53220 lb GVWR, Air Wheels, 11R22.5, Air Ride S Wheelbase, Air Sliding 5th Tanks Usage: 174,528 Mi	C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 186 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Wheelbase, Dual Fuel Tanks Usage: 575,781 Mi	1114	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor	
1109	Asset located in: Lake Worth, TX  2012 Kenworth T660 T/A Day Cab Truck Tractor S/N: 1XKAD49X8CJ297036 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1M1AW09Y6GM056281 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7091 Engine hrs, Engine Brake, Mack 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5 Front	
1110	2012 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X9CJ297000		Tires, 11R22.5 Rear Tires, 4-Bag Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 192,351 Mi	
	C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid,		Asset located in: Lake Worth, TX	
	22628 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,564 Mi	1115	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor  S/N: 1M1AW07Y7FM048675  C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26801 Engine hrs, Engine Brake, Mack MDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	

This catalog was created at December 8, 2024 01:25:57 PM GMT. Please check our website for the most accurate and up-to-date information.

Tanks

Usage: 271,385 Mi

Asset located in: Lake Worth, TX

			1 age 97 01 300
Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 1116, 1117	сноіс	E OF 5 - Lot #'s: 1121, 1122, 1123, 1125, 1126
1116	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y4EM043164 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 190 in Wheelbase Usage: 484,651 Mi Asset located in: Humble, TX  2014 Mack CXU613 6x4 T/A Day Cab Truck	1121	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor  S/N: 1M2AN07Y0EM015773  C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 32141 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Hendrickson Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks Usage: 731,351 Mi Asset located in: Lake Worth, TX
1118	Tractor  S/N: 1M1AW02Y3EM036867  C/W: Mack 6 Cylinder 10.8 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, Air Ride Suspension, 222 in Wheelbase Usage: 384,415 Mi Asset located in: Lake Worth, TX  2012 Mack CXU613 6x4 T/A Day Cab Truck	1122	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXEM016719 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 478,839 Mi
1110	Tractor		Asset located in: Lake Worth, TX
	S/N: 1M1AW02Y8CM017308 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 11235 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Twin Y Air Ride Suspension, 182 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 300,710 Mi  Asset located in: Lake Worth, TX	1123	2014 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y5EM015669 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Mack Automatic Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, 11R24.5, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 569,098 Mi Asset located in: Lake Worth, TX
1119	2018 Mack CHU613 6x4 T/A Day Cab Truck	1125	2013 Mack CHU613 6x4 T/A Day Cab Truck
	Tractor  S/N: 1M1AN07YXJM027640  C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 590,377 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE	1123	Tractor  S/N: 1M1AN07Y0DM013475  C/W: Mack MP8 6 Cylinder 12.7 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 22679 lb GVWR, 11R24.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 847,795 Mi  Asset located in: Lake Worth, TX

Notes: DEFICIENCIES NOTED - PLEASE SEE
THE INSPECTION REPORT

Asset located in: Lake Worth, TX

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1126	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor  S/N: 1M2AN07Y5DM014066  C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 31299 Engine hrs, Engine Brake, Mack 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Dual Fuel Tanks Usage: 767,495 Mi  Asset located in: Lake Worth, TX	1130	Tractor S/N: 1M2AN07Y1DM013920 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Mack MaxiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, 11R24.5, Spring over Walking Beam Suspension, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 211,417 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 1127, 1128	1132	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07YXCM010660
1127	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y8DM011473 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 536,413 Mi Asset located in: Lake Worth, TX	сноіс	C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MultiTorque 18-Speed Manual Transmission, 13220 lb Front Axle, 44000 lb Rears, 57220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 97,753 Mi  Asset located in: Lake Worth, TX  E OF 3 - Lot #'s: 1133, 1136, 1137
1128	2013 Mack CHU613 6x4 T/A Day Cab Truck	1133	2012 Mack CHU613 6x4 T/A Day Cab Truck
1120	Tractor  S/N: 1M1AN07Y5DM014492  C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack MAXITORQUE 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 215 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 488,617 Mi	1100	Tractor  S/N: 1M1AN07Y8CM008989  C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Mack maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 511,996 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	1136	2012 Mack CHU613 6x4 T/A Day Cab Truck
1129	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor  S/N: 1M2AN07Y1DM014095  C/W: Mack MP8 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 29537 Engine hrs, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 747,931 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT  Asset located in: Humble, TX		Tractor S/N: 1M1AN07Y3CM009662 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28676 Engine hrs, Mack 8-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Mack Drive Axles, 50000 lb GVWR, Air Ride Cab, 11R24.5, Twin Y Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 732,133 Mi Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1137 1141 2018 Freightliner Cascadia 125 6x4 T/A Day 2012 Mack CHU613 6x4 T/A Day Cab Truck Cab Truck Tractor **Tractor** S/N: 3AKJGEDV7JSJK4542 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10452 Engine hrs, Engine Brake, S/N: 1M1AN07Y7CM011172 C/W: Mack MP8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18044 Engine hrs, Engine Brake, Mack 8-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Detroit 12-Speed Automated Transmission, Rears, 50000 lb GVWR, Air Ride Cab, Aluminum 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-Front Wheels, 11R24.5, 4-Bag Air Ride Suspension, 219 in Wheelbase, Dual Fuel Tanks Usage: 710,969 Mi Asset located in: Lake Worth, TX MAINTAINED-FLEET-VEHICLE-PAG 1138 Usage: 393,960 Mi 2011 Mack CHU613 6x4 T/A Day Cab Truck Tractor Asset located in: Lake Worth, TX S/N: 1M1AN07Y6BM006995 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2010 US EPA Label, Requires Diesel CHOICE OF 3 - Lot #'s: 1142, 1143, 1144 Exhaust Fluid, 963 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 1142 2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Twin Y Air Ride Suspension, 222 in Wheelbase, S/N: 3AKJGEDV6JDJN8606 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 Air Sliding 5th Wheel, Headache Rack, Dual hp Engine, Requires Diesel Exhaust Fluid, Fuel Tanks, EQUIPMENT-FROM-WATKINS-Exhaust Brake, Detroit DT12-OB-1650 12-Speed Automated Transmission, 12350 lb CONSTRUCTION Usage: 333,241 Mi Front Axle, 40000 lb Rears, Meritor RT-40-145 Asset located in: Lake Worth, TX Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Air Assist Front Suspension, Airliner Air Ride Suspension, 183 in Wheelbase, PTO, CHOICE OF 2 - Lot #'s: 1139, 1140 Wet Kit, Air Sliding 5th Wheel Usage: 870,330 Mi 1139 2019 Freightliner Cascadia 125 6x4 T/A Day Asset located in: Lake Worth, TX **Cab Truck Tractor** 1143 2018 Freightliner Cascadia 125 6x4 T/A Day S/N: 3AKJGEDR8KSKM6301 **Cab Truck Tractor** C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 3AKJGEDV0JDJN8598 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Exhaust Fluid, 16826 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, Engine, 2017 US EPA Label, Requires Diesel 12000 lb Front Axle, 40000 lb Rears, Meritor Exhaust Fluid, Engine Brake, Detroit DT12-OB-MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 1650HD 12-Speed Automated Transmission, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Suspension, 178 Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52350 lb GVWR, Air in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Ride Cab, Aluminum Front Wheels, 295/75R22. Tanks 5, Air Assist Front Suspension, Air Ride Usage: 760,027 Mi Suspension, 183 in Wheelbase, PTO Usage: 852,283 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1140 2018 Freightliner Cascadia 125 T/A Day Cab 1144 2018 Freightliner Cascadia 125 6x4 T/A Day **Truck Tractor** Cab Truck Tractor S/N: 1FUGGEDV1JLJN6683 Usage: 583,000 Mi S/N: 3AKJGEDR1JDJW5319 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Asset located in: Lake Worth, TX hp Engine, Requires Diesel Exhaust Fluid, 9924 Engine hrs, Engine Brake, Detroit DT12-OA-1650 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 190 in

Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel,

Asset located in: Lake Worth, TX

Dual Fuel Tanks Usage: 667,742 Mi

Lot #	Details	Lot #	Details
1145	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor  S/N: 3AKJGEDV7JSJH2022  C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 520,949 Mi  Asset located in: Lake Worth, TX		2016 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 3AKGGEDV4GDHC4943 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR- 14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 175 in Wheelbase,
CHOIC	E OF 3 - Lot #'s: 1146, 1147, 1148		Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 850,687 Mi <b>Asset located in</b> : Lake Worth, TX
1146	2017 Freightliner Cascadia 125 T/A Day Cab Truck Tractor S/N: 3AKJGEDV9HSJB4181 Usage: Not Available Asset located in: Lake Worth, TX	1150	2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED63FLGD5692 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505
1147	2017 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 1FUGGEDV1HLJF1652 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear	Exhaust Flui Eaton Fuller Meritor MT-Ratio, 52000 Wheels, 11R Wheelbase, Tanks Usage: 570,	hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15861 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 570,528 Mi  Asset located in: Lake Worth, TX
	Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 485,070 Mi  Asset located in: Humble, TX	1152	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGEDV1DSBV1048
1148	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDVXGSGV9490 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, Requires Diesel Exhaust Fluid, 7413 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, Spicer DS404 Drive Axles, 3.70:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 675,354 Mi Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - CPC Asset located in: Lake Worth, TX
	Usage: 596,350 Mi Asset located in: Lake Worth, TX	1153	2012 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor
			S/N: 1FUJGEDR3CSBM7925 C/W: Detroit 6 Cylinder Diesel Engine, 1828.42 Engine hrs, Automated Transmission, 13300 lb Front Axle, 46000 lb Rears, 59300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Usage: 512,461 Mi Asset located in: Lake Worth, TX

			Page 101 01 300
Lot #	Details	Lot #	Details
СНОІС	E OF 2 - Lot #'s: 1154, 1155	1157	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDVXGLGS4295
1154	2019 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV3KLKT7979 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 13571 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 5.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 184 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 535,686 Mi	C/W hp E Exha Detro Tran Rear Axle Alum Susp Whe Usag	C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 11444 Engine hrs, Engine Brake, Detroit DT12-OB-1450 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 355,568 Mi  Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	СНОІС	E OF 3 - Lot #'s: 1158, 1159, 1160
1155	Asset located in: Humble, TX	1158	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor
1100	2019 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGBDV5KLKT7983 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 12590 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275 /80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 184 in		S/N: 1FUJGBDV5BSBB6309 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 2153 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Rear Wheels, 275/80R22.5 Front Tires, 445 /50R22.5 Super Singles Rear Tires, Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 861,133 Mi Asset located in: Lake Worth, TX
	Wheelbase, Air Sliding 5th Wheel Usage: 484,854 Mi	1159	2011 Freightliner Cascadia 113 6x4 S/A Day Cab Truck Tractor
CHOIC 1156	Asset located in: Humble, TX  E OF 2 - Lot #'s: 1156, 1157  2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGBDV7GDHA6151 C/W: Detroit DD13 6 Cylinder 12.8 L 380 hp Engine, Requires Diesel Exhaust Fluid, 17605		S/N: 1FUJGBDV9BSAX2724 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 1001 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 36576 lb Rears, 48546 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 884,817 Mi Asset located in: Lake Worth, TX
	Engine hrs, Retarder, Detroit DT12-DB-1450 HD 12-Speed Automated Transmission, 12000 lb	1160	2011 Freightliner Cascadia 113 6x4 T/A Day
Front Axle, 4 Drive Axles, Air Ride Cab /75R22.5, Ai Wheelbase, Usage: 520,4 <b>Notes</b> : DEFIG THE INSPEC	Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Dual Fuel Tanks Usage: 520,442 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Cab Truck Tractor S/N: 1FUJGBDV4BSBB6320 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 8206 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, Air Ride Cab, 275/80R22.5, Airliner Suspension, 162 in Wheelbase, Dual Fuel Tanks

Wheelbase, Dual Fuel Tanks Usage: 856,222 Mi

Asset located in: Lake Worth, TX

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1161	2011 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor  S/N: 1FUJGBDV6BSBB6321  C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, 29567 Engine hrs, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 162 in Wheelbase, Dual Fuel Tanks Usage: 869,100 Mi  Asset located in: Lake Worth, TX	1166	2016 Volvo VNL 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG4GN973794 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2358 Engine hrs, Engine Brake, Volvo Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 805,146 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
CHOIC	E OF 2 - Lot #'s: 1162, 1163	1167	2016 Volvo VNL300 6x2 T/A Day Cab Truck
1162	2015 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1911 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 15249 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 3.73:1 Axle Ratio, 12000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider		Tractor S/N: 4V4NC9EH7GN941916 C/W: Volvo D13J435 6 Cylinder 12.8 L Diesel 435 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D 12- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 503,664 Mi Asset located in: Lake Worth, TX
	Kit	СНОІСЕ	Addet located III. Luke Worth, TX
	Usage: 697,934 Mi <b>Asset located in</b> : Lake Worth, TX		E OF 9 - Lot #'s: 1168, 1169, 1170, 1171, 1172,
1163	2015 Freightliner Columbia 120 6x4 T/A Day	1173, 1	174, 1175, 1176
	Cab Truck Tractor (Glider Kit) S/N: 3ALXA7CG1FDGP1908 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 500 hp Engine, 17818 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.73:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks, Glider Kit Usage: 333,663 Mi Asset located in: Lake Worth, TX	1168	2018 International HX620 6x4 T/A Day Cab Truck Tractor  S/N: 3HSDTAPRXJN404541  C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11699 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Hydraulic Oil Cooler, Dual Fuel Tanks
CHOICI	E OF 2 - Lot #'s: 1164, 1165		Usage: 274,941 Mi  Asset located in: Lake Worth, TX
1164	2016 Volvo VNM T/A Day Cab Truck Tractor S/N: 4V4MC9EG8GN967797 Usage: Not Available Asset located in: Lake Worth, TX	1169	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR0JN406699 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires
1165	2016 Volvo VNM T/A Day Cab Truck Tractor S/N: 4V4MC9EGXGN972144 Usage: Not Available Asset located in: Lake Worth, TX		Diesel Exhaust Fluid, 14368 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 277,391 Mi  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1170	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR4JN405670 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12721 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 286,193 Mi Asset located in: Lake Worth, TX	1174	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR2JN405652 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14783 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 206 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 330,024 Mi Asset located in: Lake Worth, TX
1171	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR8JN406076 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12523 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 294,702 Mi Asset located in: Lake Worth, TX	1175	2018 International HX620 6x4 T/A Day Cab Truck Tractor  S/N: 3HSDTAPR5JN404544  C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15215 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Wet Kit, Hydraulic Oil Cooler, Dual Fuel Tanks Usage: 331,216 Mi Asset located in: Lake Worth, TX
1172	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR9JN404529 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13473 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 208 in Wheelbase, PTO, Dual Fuel Tanks Usage: 314,141 Mi Asset located in: Lake Worth, TX	1176	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR6JN405671 C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 40000 kg Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Hendrickson 4-Bag Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 375,019 Mi Asset located in: Lake Worth, TX
1173	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR3JN405675 C/W: Cummins X15 6 Cylinder 15 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15260 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24. 5 Front Tires, 11R24.5 Rear Tires, Hendrickson 4-Bag Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 329,456 Mi Asset located in: Lake Worth, TX	1177	2016 International Prostar+122 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJSNR4GN748793 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13825 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 183 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 390,546 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1178	2011 International Prostar 6x2 T/A Day Cab Truck Tractor	1182	2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor
	S/N: 3HSCUAPRXBN346408 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2009 US EPA Label, 15012 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 148 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		S/N: 1XP5DB9X56D648777 C/W: Cat C15 6 Cylinder 15 L Diesel Engine, Engine Brake, Eaton Fuller 15-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 652,502 Mi
	Usage: 28,954 Mi		Asset located in: Lake Worth, TX
	Notes: THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN SHOWN ON THE ODOMETER	СНОІС	E OF 2 - Lot #'s: 1183, 1184
	Asset located in: Lake Worth, TX	4	
1179	2011 International 7400 6x4 T/A Dump Truck S/N: 1HTWGAZR5BJ399579 C/W: International MaxxForce 9 9.3 L Diesel Engine, 4726 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, 11R24.5, Spring over Walking Beam Suspension, PTO, Godwin 14 ft 8 in Long x 3 ft 4 in High Steel Body, Electric Roll Tarp Usage: 95,655 Mi	1183	2009 Kenworth T800 T/A Day Cab Truck Tractor S/N: 1XKDD49X49J255212 Usage: Not Available Asset located in: Lake Worth, TX
		1184	2008 Kenworth T800 T/A Day Cab Truck Tractor S/N: 1XKDD49X38J237363 Usage: Not Available
	Asset located in: Lake Worth, TX	4	Asset located in: Lake Worth, TX
1180	Truck Tractor  S/N: 5KJJABAV07PV66073  C/W: Cat C15 6 Cylinder 15.2 L Diesel 475 hp Engine, 2006 US EPA Label, 25128 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 16000 lb Front Axle, 46000 lb Rears, 62000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 671,173 Mi Asset located in: Lake Worth, TX	СНОІС	E OF 3 - Lot #'s: 1185, 1186, 1187
		1185	2007 Kenworth T800 6x4 T/A Day Cab Truck Tractor  S/N: 1XKDDU9X37R154046  C/W: Cat C13 6 Cylinder 12.5 L Diesel 430 hp Engine, 2006 US EPA Label, 19630 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride
CHOIC	CHOICE OF 2 - Lot #'s: 1181, 1182		Suspension, 202 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 81,923 Mi
1181	2006 Peterbilt 379 6x4 T/A Day Cab Truck		Asset located in: Lake Worth, TX
	Tractor S/N: 1XP5DB9X16D644337 C/W: Cat C15 6 Cylinder 15.2 L Diesel 435 hp Engine, 2005 US EPA Label, CARB Compliant, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	1186	2006 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X46R114993 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.70:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 202 in Wheelbase, Dual Fuel Tanks Usage: 566,399 Mi

Usage: 1,086,784 Mi

Asset located in: Humble, TX

Notes: ENGINE REBUILD NOVEMBER 2024

Lot #	Details	Lot #	Details
1187	2005 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X45R086045	СНОІС	E OF 2 - Lot #'s: 1191, 1193
	C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 3.70: 1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 285/75R24.5, 8-Bag Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 675,236 Mi Asset located in: Lake Worth, TX	1191	191 2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y98N001127 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 485 hp Engine, 2006 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 218 in Wheelbase, PTO, Air Sliding 5th Wheel, Lowboy Ramps, Rolling Tailboard, Dual Fuel Tanks Usage: 299,016 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1188	2000 Western Star 4964EX 8x4 Tri/A Day Cab Truck Tractor S/N: 2WKEDDCJ2YK963807 C/W: Cat 3406 6 Cylinder 14.6 L Diesel 475 hp Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 58000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Air Lift Tag Axle, Air over Walking Beam Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 594,259 Mi		
			THE INSPECTION REPORT
		1102	Asset located in: Humble, TX
		1193	2008 Mack CHU613 6x4 T/A Day Cab Truck Tractor  S/N: 1M1AN09Y58N003666  C/W: Mack MP8 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,062 Mi
	Asset located in: Lake Worth, TX		
1189	1990 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5D29X1LN295315 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 9-Speed		
	Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 11R24.5,		Asset located in: Lake Worth, TX
	Air Trac Air Ride Suspension, 227 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks	сноіс	E OF 3 - Lot #'s: 1194, 1195, 1196
	Usage: 211,059 Mi  Asset located in: Humble, TX	1194	2008 Mack CHU613 6x4 T/A Day Cab Truck
1190	2009 Peterbilt 384 6x4 T/A Day Cab Truck Tractor S/N: 1XPVD09X29D784986 C/W: Cummins 6 Cylinder Diesel 425 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 191 in Wheelbase, Air		Tractor S/N: 1M1AN09Y68N001683 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, 11687 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 206 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 437,607 Mi

Air Ride Suspension, 191 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 310,703 Mi

Asset located in: Lake Worth, TX

### Asset located in: Lake Worth, TX 1195 2008 Mack CHU613 6x4 T/A Day Cab Truck

S/N: 1M1AN09Y48N001827 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2007 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Spring Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 37,316 Mi

**Tractor** 

Lot #	Details	Lot #	Details
1196	2007 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AJ06Y47N008341 C/W: Mack 6 Cylinder Diesel Engine, 14078 Engine hrs, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 14320 lb Front Axle, 44000 lb Rears, 58320 lb GVWR, 11R24.5, Camelback Suspension, 207 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 85,326 Mi Asset located in: Lake Worth, TX	1202	2006 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor  S/N: 1FUJA6CK36LX13895  C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 8563 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 174,408 Mi  Asset located in: Lake Worth, TX
1198	2006 Mack CV713 T/A Day Cab Truck Tractor S/N: 1M2AG11Y96M034378 Usage: Not Available Asset located in: Lake Worth, TX	1203	2007 Freightliner Columbia 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CVX7LU42622 C/W: Mercedes-Benzi MBE4000 6 Cylinder 12.8
1199	2003 Mack CX613 Vision 6x4 T/A Day Cab Truck Tractor S/N: 1M1AE07Y23W014985 C/W: Mack AC 6 Cylinder 12.0 L Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 285/75 /24.5, Air Lift Pusher Axle, Air Ride Suspension, 242 in Wheelbase, PTO, Wet Kit, Hydraulic System, Air Sliding 5th Wheel, Dual Fuel Tanks		L Diesel 370 hp Engine, 2006 US EPA Label, 16998 Engine hrs, Engine Brake, Meritor MO-15Z12A 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Steel, 295/75R22.5, Airliner Air Ride Suspension, 165 in Wheelbase Usage: 664,314 Mi Notes: .  Asset located in: Lake Worth, TX
	Usage: 576,917 Mi  Asset located in: Humble, TX	1204	2009 Volvo VNL300 6x4 T/A Day Cab Truck Tractor  S/N: 4V4NC9EG89N270007  C/W: Volvo D13F405 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, 1272  Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50000 lb GVWR, Steel, 295/75R22.5, Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 607,811 Mi  Asset located in: Lake Worth, TX
1200	2009 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK79LAH0941 C/W: Detroit Series 60 6 Cylinder 14 L Diesel Engine, 2008 US EPA Label, Requires Diesel Exhaust Fluid, 15762.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase,		
	Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi		
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	СНОІС	E OF 2 - Lot #'s: 1205, 1206
СНОІС	Asset located in: Humble, TX E OF 2 - Lot #'s: 1201, 1202	1205	2009 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG39N283601 C/W: Volvo D13 6 Cylinder 375 hp Engine,

## 1201 2007 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor

S/N: 1FUJA6CK97DZ42349 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th

Wheel, Dual Fuel Tanks Usage: 901,926 Mi

Asset located in: Lake Worth, TX

S/N: 4V4MC9EG39N283601 C/W: Volvo D13 6 Cylinder 375 hp Engine, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 18739 lb Rears, 49478 lb GVWR, 275/80R22.5, Air Ride Suspension, 168 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP

Usage: Not Available

Lot #	Details	Lot #	Details
1206	2008 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG98N498365 C/W: Volvo D13 6 Cylinder 12.8 L Diesel 375 hp Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, Aluminum Wheels, 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 167 in Wheelbase, Air Silding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,449,683 Mi Asset located in: Lake Worth, TX  2019 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X1KJ257014 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15624 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, 75 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275 /80R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 662,371 Mi Asset located in: Lake Worth, TX  2017 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDP9X6HR157986 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 500 hp Engine, 2016 US EPA Label, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.55: 1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 28 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 232 in Wheelbase, Dual Fuel Tanks Usage: 626,873 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY	CHOICE OF 6 - Lot #'s: 1212, 1213, 1214, 1215, 1216, 12	
		1212	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49XXLD648550 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 40155 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 306,491 Mi Asset located in: Lake Worth, TX
1209			
1210		1213	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3LD648549 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 39980 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 266,350 Mi Asset located in: Lake Worth, TX
		1215	2020 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X5LD648553 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, 266 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 276,137 Mi

			1 age 100 of 500
Lot #	Details	Lot #	Details
1216	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor	1220	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor
	S/N: 1XPXD49X6KD612210 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39162 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 259 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 330,281 Mi Asset located in: Lake Worth, TX		S/N: 1XPXD49X2FD291241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23876 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Wet Kit, Dual Fuel Tanks Usage: 402,552 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.
1217	2019 Peterbilt 389 6x4 T/A Sleeper Truck		Asset located in: Humble, TX
	Tractor S/N: 1XPXD49X9KD611195 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 39138 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Suspension, 259 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 313,841 Mi	1220A	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9FD268605 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26545 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 260 in Wheelbase, Dual Fuel Tanks
	Asset located in: Lake Worth, TX	_	Usage: 573,398 Mi <b>Asset located in</b> : Midland, TX
1218	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3KD273048 C/W: Cummins X15 6 Cylinder 14.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 24049 Engine hrs, Engine Brake, Eaton Fuller RTLO 189-18B 18-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 78 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Paccar Air Ride Suspension, 281 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 582,536 Mi Asset located in: Humble, TX	1221	2012 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X9CD164118 C/W: Cummins 6 Cylinder Diesel Engine, 15073.9 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, 44 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 273 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 326,225 Mi Asset located in: Lake Worth, TX
1219	2016 Peterbilt 389 6x4 T/A Sleeper Truck	1222	2015 Peterbilt 567 6x4 T/A Sleeper Truck Tractor
	Tractor S/N: 1XPXD49X3GD369706 C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 57373 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 5320 lb GVWR, 63 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,399 Mi Asset located in: Humble, TX		S/N: 1XPCDP9X2FD297265 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21748.4 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 39000 lb Rears, 52200 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 403,572 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT.

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1223	2013 Kenworth T800 6x4 T/A Sleeper Truck Tractor  S/N: 1XKDD49X1DJ346141  C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 62 in Mid Roof Sleeper Cab, 11R24.5, Air Ride Suspension, Air Sliding 5th Wheel, Headache Rack Usage: 637,776 Mi	CHOIC 1227	7 2023 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X0PJ248970 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12344 Engine hrs, Engin Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, A
1224	Asset located in: Lake Worth, TX  2018 Freightliner Coronado 122SD 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGNDR7JDJV8925 C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automated Transmission, 52350.0 lb GVWR, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 264 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 485,348 Mi Asset located in: Lake Worth, TX		Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 343,012 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT REPORT  Asset located in: Humble, TX
1225	2011 Freightliner Coronado 122 T/A Sleeper Truck Tractor S/N: 1FUJGNDR6BDBB8157 Usage: Not Available Asset located in: Lake Worth, TX	1230	E OF 4 - Lot #'s: 1230, 1231, 1232, 1233  2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X2LJ317474
1225A	2021 Western Star 4900EX 6x4 T/A Sleeper Truck Tractor S/N: 5KJJABD14MPMU5583 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Engine Brake, 18-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 60 in Flat	C/W: Pac hrs, Pacc Transmis Rears, Pa 52350 lb Bunk Bec Usage: 5	C/W: Paccar 6 Cylinder Engine, 12173 Engine hrs, Paccar PO16F112C Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Paccar Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, 75 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Sliding 5th Wheel Usage: 523,545 Mi  Asset located in: Lake Worth, TX
	Top Sleeper Cab, 285/75R24.5, Airliner Air Ride Suspension, 286 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 258,341 Mi  Asset located in: Lake Worth, TX	1231	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 3WKYD49X5LF407169 C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10333 Engine hrs, Engine Brake,
1226	2019 Western Star 4900FA 6x4 T/A Sleeper Truck Tractor S/N: 5KJJAEDRXKPKC9060 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Eaton Fuller RTLO 13-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,054 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		Eaton Fuller 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.79:1 Axle Ratio, 53200 lb GVWR, 76 High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 481,871 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DI PRIOR TO BIDDING Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1232 2020 Kenworth T680 6x4 T/A Sleeper Truck **Tractor** CHOICE OF 5 - Lot #'s: 1234, 1235, 1236, 1237, 1238 S/N: 1XKYDP9X4LJ348287 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15421 Engine hrs, Engine 1234 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor Brake, Automated Transmission, 12500 lb S/N: 1XKYD49X2KJ220594 Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel 52500.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Exhaust Fluid, 25999 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 Ib Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5, Paccar Air Ride Suspension, 229 in Wheelbase, Air Sliding Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 589,051 Mi 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX Usage: 608,021 Mi Notes: SELLING WITH A REPOSESSION 1233 2020 Kenworth T680 6x4 T/A Sleeper Truck AFFIDAVIT AND MAY NOT BE ACCEPTED IN Tractor YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING S/N: 1XKYD49X3LJ357819 C/W: Cummins X15 6 Cylinder 15.0 L Diesel Asset located in: Lake Worth, TX 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16890.8 Engine hrs, 1235 2019 Kenworth T680 6x4 T/A Sleeper Truck Engine Brake, Paccar Automated Tractor Transmission, 13200 lb Front Axle, 40000 lb S/N: 1XKYD49X6KJ236748 Rears, 2.64:1 Axle Ratio, 53200.0 lb GVWR, Air C/W: Cummins X15 6 Cylinder 15 L Diesel 450 Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar hp Engine, 2018 US EPÁ Label, Requires Diesel Exhaust Fluid, 23865 Engine hrs, Engine Brake, Air Ride Suspension, 242 in Wheelbase, Air Automated Transmission, 13200 lb Front Axle, Sliding 5th Wheel, Dual Fuel Tanks 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Usage: 660,370 Mi Asset located in: Humble, TX Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 224 in Wheelbase, Dual 1233A 2020 Kenworth T680 6x4 T/A Sleeper Truck **Fuel Tanks Tractor** Usage: 632,548 Mi S/N: 1XKYDP9X7LJ344640 Notes: SELLING WITH A REPOSESSION C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low AFFIDAVIT AND MAY NOT BE ACCEPTED IN Sulfur Diesel 340 hp Engine, 2019 US EPA YOUR STATE. VERIFY WITH YOUR LOCAL DMV Label, Requires Diesel Exhaust Fluid, 15907 PRIOR TO BIDDING Engine hrs, Engine Brake, Paccar 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT4014x3 Drive Axles, Asset located in: Lake Worth, TX 1236 2019 Kenworth T680 6x4 T/A Sleeper Truck 2.79:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel **Tractor** S/N: 1XKYDP9X3KJ239771 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 13393 Tanks Usage: 474,515 Mi Engine hrs, Engine Brake, Paccar PO-16F112 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 2.79:1 Axle Ratio, Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 48000 lb GVWR, Air Ride Cab, 75 in High Rise Asset located in: Lake Worth, TX Sleeper Cab. Bunk Beds. Comfort Pro Auxiliary

Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 581,308 Mi

			Page 111 of 566
Lot #	Details	Lot #	Details
1237	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X2KJ257324 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P0- 16F112 Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, TriPac evolution Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,832 Km Asset located in: Humble, TX	1240	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor  S/N: 1XPBDP9X5MD741828 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 8557.7 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 461,648 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1238	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3KJ247254 C/W: Cummins X15 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14976.3 Engine hrs, Engine Brake, Eaton Fuller EED-16F112C 12-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.79: 1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 692,453 Mi Asset located in: Lake Worth, TX	1241	2021 Peterbilt 579 6x4 T/A Sleeper Truck Tractor  S/N: 1XPBDP9X7MD755875  C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 19042 Engine hrs, Engine Brake, Paccar Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
CHOIC	E OF 3 - Lot #'s: 1239, 1240, 1241		Asset located in: Lake Worth, TX
1239	2022 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7ND782896 C/W: Cummins X15 6 Cylinder 15.0 L 500 hp Engine, 2021 US EPA Label, Requires Diesel	1242	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2KD263251 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23729 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual

Exhaust Fluid, 8204 Engine hrs, Engine Brake, Paccar Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 359,739 Mi

Asset located in: Lake Worth, TX

Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** Usage: 671,185 Mi

Asset located in: Midland, TX

#### <sup>1</sup>1243 2019 Peterbilt 579 6x4 T/A Sleeper Truck **Tractor**

S/N: 1XPBDP9X7KD601681 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15553 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Bunk Heater, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 245 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 756,792 Mi

#### **Details** Lot # **Details** Lot # 1244 2019 Peterbilt 579 6x4 T/A Sleeper Truck 1248 2022 Freightliner Cascadia 126 6x4 T/A Tractor Sleeper Truck Tractor S/N: 1XPBDP9X9KD607207 S/N: 3AKJHHDV6NSMY0047 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-HL 12-Speed Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, 12000 lb Front Axle, 40000 lb Automated Transmission, 12350 lb Front Axle, Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid 40000 lb Rears, Meritor RT-40-145 Drive Axles, Roof Sleeper Cab, Aluminum Front Wheels, 275 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding /80R22.5 Front Tires, 11R22.5 Rear Tires, AG210 Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual 5th Wheel, Dual Fuel Tanks **Fuel Tanks** Usage: 488,776 Mi Usage: 298,212 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Asset located in: Lake Worth, TX THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING CHOICE OF 4 - Lot #'s: 1249, 1250, 1251, 1252 Asset located in: Midland, TX 1249 2020 Freightliner Cascadia 126 6x4 T/A 1245 2019 Peterbilt 579 6x4 T/A Sleeper Truck Sleeper Truck Tractor Tractor S/N: 3AKJHHDR9LSLR4781 S/N: 1XPBDP9X6KD604443 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, 2019 US EPA Label, Requires Diesel 485 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Exhaust Fluid, 14419.45 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 80 in Condo Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Wheel, Dual Fuel Tanks Usage: 534,026 Mi Usage: 565,195 Mi Asset located in: Lake Worth, TX Notes: ODOMETER DISCREPENCY -1250 2020 Freightliner Cascadia 126 6x4 T/A **ODOMETER SHOWS 565195 TITLE SHOWS** Sleeper Truck Tractor 565852 Asset located in: Humble, TX S/N: 3AKJHHDR1LSMG6164 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel 1246 2022 Mack AN64T 6x4 T/A Sleeper Truck Tractor Exhaust Fluid, 16808 Engine hrs, Engine Brake, Detroit DT12-1650 12-Speed Automated S/N: 1M1AN4GYXNM023469 Transmission, 12350 lb Front Axle, 40000 lb C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in hp Engine, Requires Diesel Exhaust Fluid, 19021 Engine hrs, Engine Brake, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 449,805 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Usage: 409,839 Mi THE INSPECTION REPORT Notes: DEFICIENCIES NOTED - PLEASE SEE Asset located in: Humble, TX THE INSPECTION REPORT 1251 2020 Freightliner Cascadia 126 6x4 T/A Asset located in: Humble, TX Sleeper Truck Tractor 1247 2022 Mack Anthem T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSLY5486 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel S/N: 1M1AN4GY3NM023250 Usage: Not Available Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16924 Engine hrs, Engine Brake, Detroit Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Asset located in: Lake Worth, TX

Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,619 Mi

Lot #	Details	Lot #	Details
1252 CHOIC	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSLT5963 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13413 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 466,120 Mi Notes: COLL B37639 LOT 871 (P53-46) \$45K NON PYMT 2024221 PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Asset located in: Lake Worth, TX	1256	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8LSMC8947 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, 72 in Condo Sleeper Cab, Bunk Beds, ParkSmart Electric Sleeper Air Conditioner, Aluminum Wheels, 11R22.5, 228 in Wheelbase, Air Sliding 5th Wheel, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 552,948 Mi Asset located in: Lake Worth, TX  2020 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2LSLJ9064 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 661,770 Mi
1253	2020 Freightliner Cascadia 126 T/A Sleeper		Asset located in: Lake Worth, TX
	Truck Tractor S/N: 3AKJHHDRXLSME9797 C/W: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 399,946 Mi Asset located in: Lake Worth, TX	CHOIC 1259	E OF 5 - Lot #'s: 1259, 1260, 1263, 1264, 1265  2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor
1254	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR6LSME9795 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 423,637 Mi Asset located in: Lake Worth, TX		S/N: 3AKJHHDR9KSLG7882 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19617 Engine hrs, Engine Brake, Detroit DT12 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED- FLEET-VEHICLE-PAG Usage: 527,337 Mi Asset located in: Lake Worth, TX
1255	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR2LLLL3459 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2019 US EPA Label, Requires Diesel	1260	2019 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSLG7832 Usage: 534,097 Mi Asset located in: Lake Worth, TX
	Exhaust Fluid, 16366 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Steel, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 549,606 Mi  Asset located in: Lake Worth, TX	1263	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7KSLG7847 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 570,587 Mi Asset located in: Lake Worth, TX

#### **Details** Lot # **Details** Lot # 1264 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor CHOICE OF 3 - Lot #'s: 1268, 1269, 1270 S/N: 3AKJHHDRXKSKF0425 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 1268 2019 Freightliner Cascadia 126 6x4 T/A hp Engine, Requires Diesel Exhaust Fluid, 18430 Engine hrs, Automated Transmission, Sleeper Truck Tractor 13220 lb Front Axle, 40000 lb Rears, 3.08:1 S/N: 3AKJHHDR3KSKJ2880 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, Exhaust Fluid, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb PROFESSIONALLY-MAINTAINED-FLEET-Rears, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding VEHICLE-PAG Usage: 588,359 Mi Asset located in: Lake Worth, TX 5th Wheel, Dual Fuel Tanks 1265 2019 Freightliner Cascadia 126 6x4 T/A Usage: 684,650 Mi Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 3AKJHHDR7KSKE1407 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 1269 2019 Freightliner Cascadia 126 6x4 T/A hp Engine, 2018 US EPA Label, Requires Diesel Sleeper Truck Tractor Exhaust Fluid, Engine Brake, Detroit Automated S/N: 3AKJHHDR5KSKJ2878 Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Exhaust Fluid, Automated Transmission, 12350 Ride Cab, 72 in High Rise Sleeper Cab, Bunk lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Beds, 11R22.5, Airliner Air Ride Suspension, Air Ride Cab, High Rise Sleeper Cab, Bunk 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-Beds, 275/80R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th FLEET-VEHICLE-PAG Wheel Usage: 609,505 Mi Usage: Not Available Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1266 2019 Freightliner Cascadia 126 6x4 T/A 1270 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJHHDR2KSKE4277 S/N: 3AKJHHDR1KSKJ2876 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17458 Engine hrs, Engine Brake, Exhaust Fluid, 17776 Engine hrs, Engine Brake, Detroit DT12-V 12-Speed Automated Detroit 12-Speed Automated Transmission, Transmission, 12500 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.28:1 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.85:1 Axle Ratio, Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in 52350 lb GVWR, Air Ride Cab, 72 in High Rise High Rise Sleeper Cab, Bunk Beds, Bunk Sleeper Cab, Bunk Beds, Thermo King TriPac Heater, Sleeper Air Conditioner, Auxiliary Power Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Suspension, 231 in Wheelbase, Air Sliding 5th Sliding 5th Wheel, Dual Fuel Tanks Wheel, Dual Fuel Tanks Usage: 634,187 Mi Usage: 718,586 Mi Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1267 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3KSKH0824 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Requires Diesel Exhaust Fluid, 10620 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5

Rear Tires, Airliner Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 477,320 Mi

#### **Details** Lot # **Details** Lot # 1274 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor CHOICE OF 10 - Lot #'s: 1271, 1272, 1273, 1274, 1275, S/N: 3AKJHHDR5KSKA2508 1276, 1277, 1278, 1279, 1280 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed 1271 2019 Freightliner Cascadia 126 6x4 T/A Automated Transmission, 12000 lb Front Axle, **Sleeper Truck Tractor** 40000 lb Rears, Meritor MT-40-14X Drive Axles, S/N: 1FUJHHDR3KLKM1453 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8310 Engine hrs, Engine Brake, Unit, Aluminum Wheels, 295/75R22.5 Front Automated Transmission, 12350 lb Front Axle, Tires, 11R22.5 Rear Tires, Airliner Suspension, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 225 in Wheelbase, Air Sliding 5th Wheel, 72 in High Rise Sleeper Cab, Bunk Beds, Lowboy Ramps, Dual Fuel Tanks Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner 4-Bag Usage: 677,092 Mi **Notes**: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 579,939 Mi YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX Asset located in: Lake Worth, TX 1272 2019 Freightliner Cascadia 126 6x4 T/A 1275 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 3AKJHHDR7KSKB3770 S/N: 3AKJHHDR5KSKK8191 C/W: Detroit DD15 14.8 L Diesel Engine, 2018 C/W: Detroit DD15 6 Cylinder 14.8 L Engine, 2017 US EPA Label, Automated Transmission. US EPA Label, Requires Diesel Exhaust Fluid, 12500 lb Front Axle, 40000 lb Rears, 52000 lb 22547.51 Engine hrs, Engine Brake, Detroit GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, DT12-1650-OH 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel **Tanks** Usage: 701,338 Mi High Rise Sleeper Cab, Bunk Beds, Aluminum Asset located in: Lake Worth, TX Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 2019 Freightliner Cascadia 126 6x4 T/A 1273 Sleeper Truck Tractor Usage: 727,804 Mi S/N: 3AKJHHDR3KSJY3462 Asset located in: Lake Worth, TX C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel 1276 2019 Freightliner Cascadia 126 6x4 T/A Exhaust Fluid, Engine Brake, Detroit 12-Speed Sleeper Truck Tractor Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive S/N: 3AKJHHDV5KSKJ2974 Axles, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner 16810C 10-Speed Manual Transmission, Air Ride Suspension, 223 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 544,147 Mi

C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Eaton Fuller FAO-12500 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 445,195 Mi

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1277	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2KSKP1628 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15930 Engine hrs, Engine Brake, Detroit DT12-1650-OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,964 Mi	1281	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR0KLLJ6173 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23298 Engine hrs, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 685,332 Mi Asset located in: Lake Worth, TX
1278	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4KSKS9784 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 20138.21 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 256 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 593,973 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Asset located in: Lake Worth, TX	1282	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3JSJW9253 C/W: Detroit DD15 6 Cylinder 14.7 L 455 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-1650-OHI HD 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
1279	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2KSKW8471 Usage: 610,972 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Asset located in: Lake Worth, TX	1283	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXJSJW4146 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-
1280	O 2019 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXKSKL3824 C/W: Detroit DD15 Diesel 455 hp Engine, Engine Brake, Detroit DT-12 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 72 in High Rise Sleeper Cab, Aluminum Outer Wheels, 275		RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 550,012 Mi  Asset located in: Lake Worth, TX
		1285	2022 Volvo VNL860 6x4 T/A Sleeper Truck Tractor  S/N: 4V4NC9EH6NN603923  C/W: Volvo 6 Cylinder 12.8 L Diesel 425 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 283,601 Mi

			Page 117 of 566
Lot #	Details	Lot #	Details
1286	2022 Volvo VNL880 6x4 T/A Sleeper Truck Tractor  S/N: 4V4NC9EH6NN600794 C/W: Volvo D13H455 6 Cylinder 13.0 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 21619.0 Engine hrs, Engine Brake, Volvo AT02612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 789,122 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV	1289	2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6LN249446 C/W: Volvo 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 667,184 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
PRIOR TO BIDDING  Asset located in: Lake Worth, TX  CHOICE OF 4 - Lot #'s: 1287, 1288, 1289, 1290		1290	2020 Volvo VNL860 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TJ8LN253794 C/W: Cummins X15 6 Cylinder 15 L Ultra Low
1287	1287 2021 Volvo VNL860 6x4 T/A Sleeper Truck Tractor  S/N: 4V4NC9EH8MN600892 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, 8277 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th		Sulfur Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18160 Engine hrs, Engine Brake, Eaton Fuller FO-18E313A MHP Automatic Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/70R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 540,590 Mi  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	Wheel, Dual Fuel Tanks Usage: 374,829 Mi	1292	Asset located in: Lake Worth, TX
	Notes: PER THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN  Asset located in: Lake Worth, TX		2020 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH0LN249443 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp Engine, 2019 US EPA Label, Requires Diesel
1288	2020 Volvo VNL860 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EG7LN223199 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 19723 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride		Exhaust Fluid, 22710.9 Engine hrs, Engine Brake, Volvo ATO2612F Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 611,970 Mi  Notes: SELLING WITH A REPOSESSION

Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 511,249 Mi

**Notes**: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot #	Details	Lot #	Details
1293	S/N: 4V4NC9EH3LN245807 C/W: Volvo D13M 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 16978.1 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 50500 lb GVWR, Air Ride Cab, 70 in Flat Top Sleeper Cab, 11R22.5, Volvo Air Ride Suspension, 254 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 366,216 Mi  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV	1297	2020 Volvo VNL64T740 6x4 T/A Sleeper Truck Tractor  S/N: 4V4NC9EH8LN258469 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14884 Engine hrs, Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, 295 /75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,732 Hr Asset located in: Humble, TX
		сноіс	E OF 3 - Lot #'s: 1298, 1299, 1300
СНОІС	E OF 3 - Lot #'s: 1294, 1295, 1296	1298	2019 Volvo VNL64T760 6x4 T/A Sleeper Truck Tractor

#### 1294 2020 Volvo VNL760 6x4 T/A Sleeper Truck Tractor

S/N: 4V4NC9EH6LN221498 C/W: Volvo 6 Cylinder 12.8 L 425 hp Engine, Requires Diesel Exhaust Fluid, 19160 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 739,489 Mi

Asset located in: Lake Worth, TX

#### 1295 2020 Volvo VNL760 6x4 T/A Sleeper Truck **Tractor**

S/N: 4V4NC9EH6LN249009 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** Usage: 387,288 Mi

Asset located in: Lake Worth, TX

#### 1296 2019 Volvo VNL760 6x4 T/A Sleeper Truck Tractor

S/N: 4V4NC9EH6KN195791 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50350 lb GVWR, 61 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel Usage: 412,464 Mi

Asset located in: Lake Worth, TX

## ruck

S/N: 4V4NC9EH1KN206101 C/W: Volvo D13H455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US ÉPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Volvo Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX

1299 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor

> S/N: 4V4NC9TJ3KN204274 C/W: Cummins X15 500ST 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-20913A 13-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: Not Available

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

Lot #	Details	Lot #	Details
1300	2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1KN232987 C/W: Volvo D13M 6 Cylinder 12.8 L 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Volvo Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX	1304 CHOIC	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3LN800182 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16079 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 484,652 Mi Asset located in: Lake Worth, TX
1301	2020 Volvo VNR 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH1LN270436 C/W: Volvo 6 Cylinder Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 8942 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 196 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 251,927 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1305	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZTZR3LN684488 C/W: International A26 6 Cylinder 12.4 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16142 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
1302	2019 International LoneStar 6x4 T/A Sleeper Truck Tractor  S/N: 3HSLGAPR6KN527657  C/W: Cummins X15 500 6 Cylinder 15.0 L Diesel 500 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,536 Mi Asset located in: Lake Worth, TX	1306	2020 International LT625 6x4 T/A Sleeper Truck Tractor  S/N: 3HSDZAPR5LN854650  C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12492 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 351,096 Mi Asset located in: Lake Worth, TX
1303	2022 International LT625 6x4 T/A Sleeper Truck Tractor  S/N: 3HSDZAPR0NN285693  C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 12- Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 450,017 Mi Asset located in: Lake Worth, TX		Truck Tractor S/N: 3HSDZAPR7LN854651 C/W: Cummins X15 6 Cylinder Diesel 450 hp Engine, 2019 US EPA Label, Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, Air Ride Cab, 51 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Sliding 5th Wheel Usage: 471,259 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1308	2019 International LT625 6x4 T/A Sleeper Truck Tractor  S/N: 3HSDZAPR8KN122995  C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	1312	2019 International LT625 6x4 T/A Sleeper Truck Tractor  S/N: 3HSDZAPR3KN350628  C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 73 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY MAINTAINED-FLEET-VEHICLE-PAG Usage: 561,974 Mi  Asset located in: Lake Worth, TX
1309	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8KN566457 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	1313	2019 International LT 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3KN319055 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 459,002 Mi Asset located in: Humble, TX
	CHOICE OF 3 - Lot #'s: 1310, 1311, 1312		2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR5KN284342
1310	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR0KN070889 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15367 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22. 5, Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 467,363 Mi		C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19700 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 603,242 Mi  Notes: .  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	Сноіс	E OF 2 - Lot #'s: 1315, 1316
Truck Tra S/N: 3HS C/W: Cur 450 hp E Diesel Ex Brake, Au Front Axl Ride Cab Steel, 11 Wheelba Tanks Usage: 4	2019 International LT625 6x4 T/A Sleeper Truck Tractor  S/N: 3HSDZAPR9KN748748  C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19547 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 73 in Condo Sleeper Cab, Bunk Beds, Steel, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	1315	2019 International LT62F T/A Sleeper Truck Tractor S/N: 3HSDZAPR6KN290893 C/W: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 510,647 Mi Asset located in: Lake Worth, TX  2019 International RH613 T/A Sleeper Truck Tractor
	Usage: 467,585 Mi  Asset located in: Lake Worth, TX		S/N: 3HSDWTZR6KN106957 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 379,633 Mi

			Page 121 of 566	
Lot #	Details	Lot #	Details	
CHOICE OF 2 - Lot #'s: 1317, 1318		1320	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X0HD422634 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel	
1317	2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7JD457743 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15889 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 685,817 Mi	СНОІСЕ	455 hp Engine, 2016 US EPA Label, Requi Diesel Exhaust Fluid, 15184 Engine hrs, E Brake, Eaton Fuller Automatic Transmiss Differential Lock, 13200 lb Front Axle, 400 Rears, 53200 lb GVWR, 63 in Mid Roof Sle Cab, Aluminum Wheels, 11R22.5, Paccar Ride Suspension, 237 in Wheelbase, PTO	Usage: 373,658 Mi Asset located in: Midland, TX
1318	2018 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6JD488661 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 22731.5 Engine hrs, Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, 295 /75R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,951 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS; ADMINISTRATIVE CODE SECTIONS	1321	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor  S/N: 1XPBD49X0GD330582  C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 19825 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 908,570 Mi Asset located in: Lake Worth, TX	
СНОІСІ	114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX  E OF 2 - Lot #'s: 1319, 1320		2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9XXGD298189 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 20896 Engine hrs, Engine Brake, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 635,966 Mi Asset located in: Lake Worth, TX	

#### 1319 2017 Peterbilt 579 6x4 T/A Sleeper Truck **Tractor**

S/N: 1XPBD49X6HD423821 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 23493.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 78 in High Rise Sleeper Cab, 295/75R22.5, Paccar Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** 

Usage: 730,143 Mi

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 1323, 1324	сноіс	E OF 2 - Lot #'s: 1326, 1328
1323	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD262361 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 37998 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Flex Air Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 893,094 Mi Asset located in: Lake Worth, TX	1326	2013 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHD49XXDD206468 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Eaton Fuller Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Low Air Leaf Air Ride Suspension, 246 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes:
1324	2015 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X7FD285266 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Coolant Heater, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, 80 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel Usage: 862,250 Mi Asset located in: Lake Worth, TX	1328	Asset located in: Midland, TX  2012 Peterbilt 386 6x4 T/A Sleeper Truck Tractor  S/N: 1XPHD49X0CD142424  C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 28592 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Leaf Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 778,429 Mi
1325	2017 Peterbilt 367 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X0HD357509 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 402,192 Mi Asset located in: Lake Worth, TX	1329	Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX  2011 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7D49X7BD121337 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th

			_
Lot #	Details	Lot #	Details
CHOIC	CHOICE OF 2 - Lot #'s: 1330, 1331		2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor
1330			S/N: 1XKYDP9X2HJ146961 C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 25916 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT40- 14X3 Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 643,846 Mi Asset located in: Lake Worth, TX
	5, Paccar 4-Bag Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available <b>Asset located in</b> : Midland, TX	Tractor  S/N: 1XKYDP9X3HJ145768  C/W: Paccar MX-13 6 Cylinder 12  455 hp Engine, Requires Diesel E: 26851 Engine hrs, Engine Brake, Eaton Advantage 12-Speed Autor Transmission, 12350 lb Front Axl Rears, Meritor MT-40-14X Drive A Axle Ratio, 52350 lb GVWR, 76 in Sleeper Cab, Bunk Beds, Aluminu /75R22.5, Air Ride Suspension, 25	S/N: 1XKYDP9X3HJ145768 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel
1331	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3JJ185028 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 222 in		26851 Engine hrs, Engine Brake, Eaton Fuller Eaton Advantage 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,016 Mi
	Wheelbase, Dual Fuel Tanks Usage: 630,153 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	1336	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X0HJ153938 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19893 Engine hrs, Engine Brake, Eaton
СНОІС	Asset located in: Lake Worth, TX  CHOICE OF 4 - Lot #'s: 1333, 1334, 1335, 1336		Fuller 10-Speed Manual Transmission, Differential Lock, 12500 lb Front Axle, 40000 l Rears, 3.36:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 76 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride
1333	2017 Kenworth T680 6x4 T/A Sleeper Truck Tractor		Suspension, 238 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 631,336 Mi
	S/N: 1XKYDP9XXHJ144648 C/W: Paccar MX-13 6 Cylinder Diesel Engine,		Asset located in: Lake Worth, TX
	C/W: Paccar MX-13 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 24355 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 52 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 901,856 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1337	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor  S/N: 1XKYDP8X6GJ121464  C/W: Paccar 6 Cylinder 12.9 L Diesel 430 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 2310 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Assist Front Suspension, Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 60,967 Mi

	Details	1 0+ #	Detaile
Lot #	Details	Lot #	Details
1338	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X4GJ118091 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 2504 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 38 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 827,511 Mi Asset located in: Lake Worth, TX	1342	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD48X2FJ420768 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 30258 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, 46350 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,080,201 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
CHOIC	E OF 5 - Lot #'s: 1339, 1340, 1341, 1342, 1343		Asset located in: Humble, TX
1339	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor  S/N: 1XKYD49X7FJ430257  C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Dual Fuel Tanks Usage: 866,880 Mi	1343	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X1FJ450926 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks Usage: 809,582 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX		
1340	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X9FJ449653 C/W: Paccar 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 23432 Engine hrs, Engine Brake, Automatic Transmission, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro	CHOIC 1344	E OF 2 - Lot #'s: 1344, 1345  2013 Kenworth T700 T/A Sleeper Truck Tractor S/N: 1XKFDP9X7DJ348972 Usage: Not Available Asset located in: Lake Worth, TX
	Auxiliary Power Unit, 295/75R22.5, 8-Bag Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 810,190 Mi Asset located in: Humble, TX	1345	2012 Kenworth T700 6x4 T/A Sleeper Truck Tractor S/N: 1XKFDP9X9CJ325479
1341	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD48XXFJ420758 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810C 10-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 3.36:1 Axle Ratio, 46350 lb GVWR, Air Ride Cab, 75 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,063,376 Mi Asset located in: Humble, TX		C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR0-16210B 10-Speed Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, 11R22.5, Paccar Air Ride Suspension, 231 in Wheelbase, Dual Fuel Tanks Usage: Not Available  Asset located in: Midland, TX

			Page 125 of 566
Lot #	Details	Lot #	Details
CHOIC 1346	Tractor S/N: 1XKAD49X2GJ481393 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 31744 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, Spicer DSP40 Drive Axles, 3.55:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 52 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 244 in	Tractor  S/N: 1XKAD49XXEJ397691 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 35718 Engine hrs, Eaton Fuller Manual Transmission, Differential Lock, 12000 Ib Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Dual Fuel Tanks Usage: 970,194 Mi  Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS	
	Wheelbase, Dual Fuel Tanks Usage: 908,066 Mi  Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	E 114.20 OPERA RESTO SYSTEI EQUIPF ACKNO PRIOR Asset I  1349 2014 K Tractor S/N: 1X C/W: C 500 hp Diesel I Brake, I 12000   GVWR, Cab, Slo Assist   Suspen Wheel Usage:	114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX  2014 Kenworth T600 6x4 T/A Sleeper Truck Tractor  S/N: 1XKAD48X8EJ414196  C/W: Cummins ISX15 6 Cylinder 15 L Diesel
1347	7 2016 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X4GJ481394 C/W: Cummins ISX 6 Cylinder 14.9 L Diesel 500 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4526 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, Flat Top Sleeper Cab, Aluminum Wheels, 275/80R22 5 Front Tires, 295/75R22 5 Rear		500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17145 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Air Ride Cab, 50 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, 11R24.5, Air Assist Front Suspension, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th
		1350	2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKADP9X3DJ353712 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 340 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTOC16909A Manual Transmission,

RTOC16909A Manual Transmission,
Differential Lock, 12000 lb Front Axle, 40000 lb
Rears, Dana DSP41 Drive Axles, 3.36:1 Axle
Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Flat
Top Sleeper Cab, Aluminum Outer Wheels, 295
/75R22.5 Front Tires, 11R22.5 Rear Tires,
Paccar Air Ride Suspension, 128 in Wheelbase,
PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks

Usage: 554,558 Mi

Asset located in: Lake Worth, TX

TEXAS ADMINISTRATIVE CODE SECTIONS
114.20 AND 114.50. THIS MAY APPLY IF YOU
OPERATE THE UNIT PRIOR TO THE ADEQUATE
RESTORATION OF ALL POLLUTION CONTROL
SYSTEMS OR DEVICES AS ORIGINALLY
FOUNDED BY INCELOR EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Lot #	Details	Lot #	Details
1350A	2013 Kenworth T660 6x2 T/A Sleeper Truck Tractor S/N: 1XKAA48X9DJ365291	1354	2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM049326
	C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 20304 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 34000 lb Rears, 2.53:1 Axle Ratio, 46000 lb GVWR, Air Ride Cab, 52 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 914,459 Mi Asset located in: Lake Worth, TX		C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: Not Available  Asset located in: Lake Worth, TX
1351A	2012 Kenworth T660 6x4 T/A Sleeper Truck	-	
10017	Tractor S/N: 1XKAD49X6CJ297018	1360, 1	E OF 7 - Lot #'s: 1355, 1356, 1357, 1358, 1359, 361
	C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 24434 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 34000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 809,118 Mi  Asset located in: Lake Worth, TX	1355	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y2EM036889  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 897,867 Mi
1352	2016 Mack CXU613 6x4 T/A Sleeper Truck Tractor		Asset located in: Lake Worth, TX
	S/N: 1M1AW21Y4GM077413 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 15300 Engine hrs, Engine Brake, Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 450,360 Mi	1356	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM040890 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R22.5, Air Ride Suspension, 214 in Wheelbase Usage: 773,925 Mi
	Asset located in: Lake Worth, TX	1077	Asset located in: Lake Worth, TX
CHOICE	E OF 2 - Lot #'s: 1353, 1354	1357	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y1EM036897 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395
1353	2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3FM051337 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22586 Engine hrs, Engine Brake, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 607,391 Mi Asset located in: Lake Worth, TX		hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 25651 Engine hrs, Engine Brake, Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 836,651 Mi  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1358	Tractor  S/N: 1M1AW02Y8EM042227 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 22893 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285 /75R24.5 Front Tires, 275/80R22.5 Rear Tires, 4-Bag Air Ride Suspension, 219 in Wheelbase, PTO Usage: 822,170 Mi Asset located in: Lake Worth, TX	СНОІСІ	E OF 6 - Lot #'s: 1362, 1363, 1364, 1365, 1366, 136
		2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y9EM042236  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 675,329 Mi	
1359	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor		Asset located in: Lake Worth, TX
1360	S/N: 1M1AW02Y1EM042263 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase, Dual Fuel Tanks Usage: 778,799 Mi Asset located in: Lake Worth, TX  2014 Mack CXU613 6x4 T/A Sleeper Truck	1363	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y4EM042225  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, mRide Air Ride Suspension, 218 in Wheelbase
1300	Tractor		Usage: 730,061 Mi <b>Asset located in</b> : Lake Worth, TX
	S/N: 1M1AW02YXEM040902 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 222 in Wheelbase Usage: 805,702 Mi Asset located in: Lake Worth, TX	1364	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y7EM033793 C/W: Mack MP7 6 Cylinder 10.8 L Diesel Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 31248 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Air Ride Cab, 60 in Mid Roof Sleeper
1361	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM036877 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9682 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, 285/75R24.5, Air Ride Suspension, 217 in Wheelbase Usage: 794,371 Mi Asset located in: Lake Worth, TX		Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 218 in Wheelbase Usage: 755,801 Mi <b>Asset located in</b> : Lake Worth, TX
		1365	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y6EM042243 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 791,657 Mi

Lot #	Details	Lot #	Details
1366	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y7EM040887  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 690,857 Mi Asset located in: Lake Worth, TX	1370	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y7DM024736  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase Usage: 701,446 Mi  Asset located in: Lake Worth, TX
1367	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM042244 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 285 /75R24.5, Air Ride Suspension, 222 in Wheelbase Usage: 741,289 Mi Asset located in: Lake Worth, TX	1371	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y8DM029525  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension Usage: 643,699 Mi  Asset located in: Lake Worth, TX
1368	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW07Y6EM042008 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18- Speed Manual Transmission, 6600 kg Front Axle, 20800 kg Rears, 27400 kg GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 707,937 Mi	1372	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y6DM029524  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 13523 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase, PTO Usage: 756,971 Mi  Asset located in: Lake Worth, TX
Asset located in: Humble, TX  CHOICE OF 6 - Lot #'s: 1369, 1370, 1371, 1372, 1373, 1374		-1373	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y3DM029500 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel
1369	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, 26792 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5 Front		Exhaust Fluid, 3225 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R24.5 Rear Tires, Air Ride Suspension, 220 in Wheelbase Usage: 674,399 Mi  Asset located in: Lake Worth, TX
	Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase Usage: 871,001 Mi <b>Asset located in</b> : Humble, TX	1374	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW21Y6DM034381 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, 30700 Engine hrs, Mack Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase Usage: 813,858 Mi

Lot #	Details	Lot #	Details
1375 2013 Mack CXU61 Tractor S/N: 1M1AW02YX C/W: Mack MP7 6 hp Engine, 2012 US Exhaust Fluid, 242 Eaton Fuller 13-Sp	S/N: 1M1AW02YXDM029512 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 24261 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission,	1379	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AW02Y4DM033748  C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 216 in Wheelbase Usage: 624,802 Mi
	12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 215 in Wheelbase Usage: 648,076 Mi Asset located in: Lake Worth, TX	1380	Asset located in: Lake Worth, TX  2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM031484 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395
1376	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y2DM024739 C/W: Mack MP7 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 26124 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Mid Roof Sleeper Cab,		hp Engine, 2012 US ÉPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 216 in Wheelbase Usage: Not Available  Asset located in: Humble, TX
	Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 218 in Wheelbase Usage: 690,603 Mi <b>Asset located in</b> : Lake Worth, TX	1381	Tractor S/N: 1M1AW07Y3BM015005 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505
1377	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033782 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20338 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride		hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, Mack MDrive Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,133,741 Mi  Asset located in: Lake Worth, TX
	Suspension, 215 in Wheelbase Usage: 658,728 Mi  Asset located in: Lake Worth, TX	СНОІС	E OF 2 - Lot #'s: 1382, 1383
1378	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y4DM033751 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 220 in Wheelbase Usage: 783,814 Mi Asset located in: Lake Worth, TX	1382	2015 Mack CHU613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AN07Y2FM019667  C/W: Mack MP8 6 Cylinder Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 237 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 510,043 Mi Notes:

Lot #	Details	Lot #	Details
1383	2014 Mack CHU613 6x4 T/A Sleeper Truck Tractor	1386	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
	S/N: 1M1AN07Y1EM015852 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 2950 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 462,432 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX		S/N: 3AKJGLDV6KSKH9486 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23543 Engine hrs, Detroit DT12-1550- OH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 720,855 Mi
1384	2020 Freightliner Cascadia 125 6x4 T/A	1	THE INSPECTION REPORT  Asset located in: Humble, TX
	Sleeper Truck Tractor S/N: 3AKJGLDR6LDLX1078 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX	1387	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR3KDKM9521 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel Usage: 512,155 Mi Asset located in: Lake Worth, TX
СНОІС	E OF 2 - Lot #'s: 1385, 1386	1388	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
1385	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6KSKS1465 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19541.1 Engine hrs, Detroit DT12-1550 OH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 723,931 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Lake Worth, TX		S/N: 3AKJGLDR9KDKM9524 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Air Sliding 5th Wheel Usage: 525,435 Mi Asset located in: Humble, TX

			Page 131 of 566
Lot #	Details	Lot #	Details
СНОІС	CHOICE OF 3 - Lot #'s: 1390, 1391, 1392		2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV4JLJV0967
1390	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR7JSJU3695 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, 11R22.5, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8996 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C-EA Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 373,961 Mi  Asset located in: Lake Worth, TX
	Usage: 484,584 Mi Asset located in: Lake Worth, TX	СНОІС	E OF 4 - Lot #'s: 1394, 1395, 1396, 1397
1391	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR5JDHF7017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR- 15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel Usage: 495,548 Mi Asset located in: Lake Worth, TX	1394	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR8JSHF3927 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit 12- Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 604,042 Mi Asset located in: Lake Worth, TX
1392	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR0JSHF3632 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Exo Air Sleeper Air Conditioner, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 614,080 Mi Asset located in: Humble, TX	1395	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV2JLJP4880 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 21109 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 218 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 890,800 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

			Page 132 of 566
Lot #	Details	Lot #	Details
1396	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLFG9JLJN0560 C/W: Cummins X15 6 Cylinder 15 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 21765 Engine hrs, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 665,249 Mi Asset located in: Lake Worth, TX	1399	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR2JLJV0565 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier Comfort Pro Auxiliary Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 442,347 Mi Asset located in: Lake Worth, TX
1397	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV0JLJK2888 C/W: Detroit DD13 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive	1400	2018 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 1FUJGLDR0JLJV0564 C/W: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 479,762 Mi Asset located in: Lake Worth, TX
	Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 408,806 Mi Asset located in: Lake Worth, TX	1401	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR5JLJV0558 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12958 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA
CHOIC 1398	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR4JLJV0566 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12180 Engine hrs, Engine Brake, Detroit DT12-1650-OA 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Steel, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 420,575 Mi		RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 479,989 Mi  Asset located in: Lake Worth, TX
		1402	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR3JLJV0560 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OA-1750 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb GVMR, Air Ride Cab, 70 in Figh Rise Sleeper

GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 506,969 Mi

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1403	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR7JLJV0576 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 20205 Engine hrs, Engine Brake, Detroit DT12-OA-1750 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 528,613 Mi Asset located in: Lake Worth, TX	1406	2017 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLDR1HSHY7691 Usage: Not Available Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX
1404	2017 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLBG6HSJE6319 Usage: Not Available Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	1407	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR6HLHW3673 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1650 12-Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,350 Mi Asset located in: Lake Worth, TX
1405	2017 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLDR0HSHY7696 Usage: Not Available Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS	1408	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR5HLHF2174 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1750 HD 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22 5 Airliner Air

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 813,536 Mi

Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV

PRIOR TO BIDDING

#### **Details** Lot # **Details** Lot # 1409 2017 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** CHOICE OF 9 - Lot #'s: 1412, 1413, 1414, 1415, 1416, S/N: 3AKJGLDR6HSHF0874 1417, 1418, 1419, 1421 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1750 12-Speed 2016 Freightliner Cascadia 125 6x4 T/A 1412 Automated Transmission, 12500 lb Front Axle, Sleeper Truck Tractor 40000 lb Rears, Meritor MT-40-14X Drive Axles, S/N: 3AKJGLD57GSHV4416 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Engine, Requires Diesel Exhaust Fluid, 27284 Engine hrs, Engine Brake, Detroit DT12-DA-1550 HD 12-Speed Automated Transmission, Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 12000 lb Front Axle, 40000 lb Rears, Detroit DA-Usage: 720,617 Mi RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Asset located in: Lake Worth, TX Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 1410 2017 Freightliner Cascadia 125 6x4 T/A 5, Airliner Suspension, 224 in Wheelbase, Air Sleeper Truck Tractor Sliding 5th Wheel, Dual Fuel Tanks S/N: 3AKJGLBG4HSJE6318 Usage: 873,575 Mi C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, CARB Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV Compliant, Requires Diesel Exhaust Fluid, 2448 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid PRIOR TO BIDDING Asset located in: Lake Worth, TX Roof Sleeper Cab, Aluminum Wheels, 295 1413 2016 Freightliner Cascadia 125 6x4 T/A /75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 208 in Wheelbase, Air Sliding Sleeper Truck Tractor S/N: 3AKJGLBG0GSGY9123 5th Wheel, Dual Fuel Tanks C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 3793 Engine hrs, Engine Usage: 785,075 Mi Asset located in: Lake Worth, TX Brake, Eaton Fuller FRO-15210C 10-Speed 1411 2017 Freightliner Cascadia 125 6x4 T/A Manual Transmission, 12000 lb Front Axle, **Sleeper Truck Tractor** 40000 lb Rears, Meritor MT-40-14X Drive Axles, S/N: 1FUJGLDR0HLHX4331 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 72 in High Rise Sleeper Cab, Bunk Beds, 295 Engine, 2016 US EPA Label, Requires Diesel /75R22.5, Airliner Air Ride Suspension, 228 in Exhaust Fluid, Engine Brake, Eaton Fuller 10-Wheelbase, Air Sliding 5th Wheel, Dual Fuel Speed Manual Transmission, 12350 lb Front **Tanks** Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Usage: 666,327 Mi Cab, 60 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Notes: . Asset located in: Lake Worth, TX Wheel, Dual Fuel Tanks Usage: 610,011 Mi

Asset located in: Humble, TX

#### 1414 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGLBG2GSHB0517 C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 29538 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 772,091 Mi

Lot #	Details	Lot #	Details
1415	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	1421	2016 Freightliner Cascadia 125 T/A Sleeper Truck Tractor
	S/N: 3AKJGLD52GSGU0419 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, Engine Brake, Detroit DT12-DA 12- Speed Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle		S/N: 3AKGGLD55GSGC5502 C/W: Detroit DD15 Engine, Detroit DT12 Automatic Transmission, Air Ride Cab, Air Ride Suspension Usage: 618,196 Mi <b>Asset located in</b> : Lake Worth, TX
	Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner 4-Bag Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual	сноіс	E OF 5 - Lot #'s: 1422, 1423, 1424, 1425, 1426
	Fuel Tanks Usage: 1,114,394 Mi <b>Asset located in</b> : Lake Worth, TX	1422	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD59GLGU1997
1416	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG3GSGX0680 C/W: Cummins ISX 6 Cylinder Diesel 450 hp Engine, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 790,465 Mi	1423	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 880,832 Mi Asset located in: Humble, TX
	Asset located in: Lake Worth, TX		2016 Freightliner Cascadia 125 6x4 T/A
1417	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD50GSHA9524 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 778,378 Mi		Sleeper Truck Tractor S/N: 3AKJGLBGXGSHT7100 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24362 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 606,456 Mi Asset located in: Lake Worth, TX
	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	1424	2016 Freightliner Cascadia 125 6x4 T/A
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		Sleeper Truck Tractor
	Asset located in: Lake Worth, TX		S/N: 1FUJGLD56GLGU2007 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455
1418	2016 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 1FUJGLD53GLHH3522 Usage: Not Available Asset located in: Lake Worth, TX		hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27811 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner
1419	2016 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 1FUJGLD54GLHB1188		Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 812,953 Mi  Asset located in: Livingston LA

### 1419 2016 Freightliner Cascadia 125 T/A Sleeper **Truck Tractor**

S/N: 1FUJGLD54GLHB1188 Usage: Not Available

Asset located in: Lake Worth, TX

Asset located in: Livingston, LA

#### **Details** Lot # **Details** Lot # 1425 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor CHOICE OF 7 - Lot #'s: 1428, 1429, 1430, 1432, 1433, S/N: 3AKJGLDR6GSHD7573 1434, 1435 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA-1750 12-Speed 1428 2015 Freightliner Cascadia 125 6x4 T/A Automated Transmission, 12350 lb Front Axle, Sleeper Truck Tractor 40000 lb Rears, Detroit DA-RT-40.0-4 Drive S/N: 1FUJGLD57FLGE5847 Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air C/W: Detroit 6 Cylinder 14.8 L Diesel Engine, Ride Cab, 60 in Condo Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner 2014 US EPA Label, Engine Brake, Detroit DT12-DA 12-Speed Automated Transmission, 12000 Air Ride Suspension, 222 in Wheelbase, Air lb Front Axle, 40000 lb Rears, Meritor MT-40-Sliding 5th Wheel, Dual Fuel Tanks 14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb Usage: 669,139 Mi GVWR, Air Ride Cab, 72 in High Rise Sleeper Notes: THIS UNIT IS BEING SOLD WITH A Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, **BONDED TITLE** Airliner Air Ride Suspension, 228 in Wheelbase, Asset located in: Lake Worth, TX Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 834,687 Mi 1426 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX S/N: 1FUJGLD50GLHF0201 1429 2015 Freightliner Cascadia 125 6x4 T/A C/W: Detroit Remanufactured 1/19/23 6 Cylinder Ultra Low Sulfur Diesel Engine, 2023 Sleeper Truck Tractor US EPA Label, Requires Diesel Exhaust Fluid, S/N: 3AKJGLBG3FSGU4319 Engine Brake, Detroit DT12-OA-1750 12-Speed C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Automated Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 29056 RT-40.0-4HT Drive Axles, 3.23:1 Axle Ratio, Engine hrs, Engine Brake, Eaton Fuller FO-16E310C Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding Drive Axles, 3.36:1 Axle Ratio, Air Ride Cab, 70 5th Wheel, Dual Fuel Tanks in High Rise Sleeper Cab, Bunk Beds, 295 Usage: Not Available /75R22.5, Airliner Air Ride Suspension, 228 in Notes: . Wheelbase, Air Sliding 5th Wheel, Dual Fuel Asset located in: Lake Worth, TX Usage: 832,290 Mi 1427 2015 Freightliner Cascadia 125 6x4 T/A Asset located in: Lake Worth, TX Sleeper Truck Tractor 1430 2015 Freightliner Cascadia 125 6x4 T/A S/N: 1FUJGLDV4FLGM6667 Sleeper Truck Tractor C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, S/N: 3AKJGLBG5FSGC7243 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp Engine, 2014 US EPA Label, Requires Diesel 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18642 Engine hrs, Eaton Fuller 10-Speed Automated Transmission, 12000 lb Front Axle, Exhaust Fluid, 23900 Engine hrs, Engine Brake, 40000 lb Rears, 3.23:1 Axle Ratio, 52000 lb Eaton Fuller FRO-16210C 10-Speed Manual GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 212 in Wheelbase. Air Sliding 5th Wheel, Dual Fuel Tanks Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Usage: 632,880 Mi Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Asset located in: Humble, TX Airliner Air Ride Suspension, 216 in Wheelbase Usage: 742,719 Mi 1427A 2015 Freightliner Cascadia 125 6x4 T/A **Notes**: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN Sleeper Truck Tractor S/N: 3AKJGLD66FSGL9720 YOUR STATE. VERIFY WITH YOUR LOCAL DMV C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2014 US EPA Label, Requires Diesel PRIOR TO BIDDING Exhaust Fluid, Automated Transmission, 12000 Asset located in: Lake Worth, TX lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 843,243 Mi Asset located in: Humble, TX

#### **Details** Lot # **Details** Lot # 1432 1436 2015 Freightliner Cascadia 125 6x4 T/A 2015 Freightliner Cascadia 125 T/A Sleeper Sleeper Truck Tractor Truck Tractor S/N: 3AKJGLD55FSGB5654 S/N: 3AKJGLBG1FSGN2970 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Usage: Not Available hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 33891 Engine hrs, Engine Brake, Asset located in: Lake Worth, TX Detroit DT12-OA-1650 HD 12-Speed 1437 2015 Freightliner Cascadia 125 6x4 T/A Automated Transmission, 13220 lb Front Axle, Sleeper Truck Tractor 40000 lb Rears, Detroit DA-RT-40.0-4 Drive S/N: 3AKJGLD52FSGK9029 Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Beds, 11R22.5, Airliner Air Ride Suspension, Exhaust Fluid, 24896 Engine hrs, Engine Brake, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Detroit 12-Speed Automated Transmission, **Fuel Tanks** 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 52000 lb GVWR, Air Ride Usage: 986,645 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Cab, 72 in High Rise Sleeper Cab, Bunk Beds, THE INSPECTION REPORT Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Asset located in: Humble, TX Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 1433 2015 Freightliner Cascadia 125 6x4 T/A Usage: 697,727 Mi Sleeper Truck Tractor S/N: 1FUJGLD54FLGE3862 Asset located in: Lake Worth, TX C/W: Detroit 6 Cylinder 14.8 L Diesel 505 hp 1438 2015 Freightliner Cascadia 125 6x4 T/A Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Sleeper Truck Tractor Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, High Rise S/N: 3AKJGLD54FSFK4749 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 Engine, Requires Diesel Exhaust Fluid, 22930 /75R22.5, Airliner Air Ride Suspension, 234 in Engine hrs, Engine Brake, Detroit 12-Speed Wheelbase, Air Sliding 5th Wheel, Headache Automated Transmission, Detroit DA-RT-40.0-4 Rack, Dual Fuel Tanks Drive Axles, 2.53:1 Axle Ratio, Air Ride Cab, 72 Usage: 724,909 Mi in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Asset located in: Midland, TX Wheelbase, Air Sliding 5th Wheel, Headache 1434 2015 Freightliner Cascadia 125 6x4 T/A Rack, Dual Fuel Tanks Usage: 588,173 Mi Sleeper Truck Tractor S/N: 3AKJGLD53FSGH9952 Asset located in: Midland, TX C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 45413 Engine hrs, Engine Brake, CHOICE OF 3 - Lot #'s: 1439, 1440, 1442 Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in 1439 2015 Freightliner Cascadia 125 6x4 T/A High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Sleeper Truck Tractor S/N: 3AKJGLD53FSGM5613 C/W: Detroit 6 Cylinder Diesel Engine, Requires Ride Suspension, 224 in Wheelbase, Air Sliding Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 5th Wheel, Dual Fuel Tanks Usage: 882,767 Mi 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Asset located in: Humble, TX Aluminum Front Wheels, 11R22.5, Airliner Air 1435 2015 Freightliner Cascadia 125 6x4 T/A Ride Suspension, 252 in Wheelbase, Air Sliding Sleeper Truck Tractor 5th Wheel, Dual Fuel Tanks Usage: 724,691 Mi S/N: 3AKJGHDV8FSGL7536 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 Asset located in: Humble, TX hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17707 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 1440 2015 Freightliner Cascadia 125 T/A Sleeper **Truck Tractor** 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb S/N: 3AKJGLD54FSGG3288 GVWR, Air Ride Cab, 60 in High Rise Sleeper Usage: Not Available Cab, Bunk Beds, Aluminum Wheels, 275/80R22.

Asset located in: Lake Worth, TX

Tanks

Notes: DEFICIENCIES NOTED - PLEASE SEE

5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

THE INSPECTION REPORT Asset located in: Humble, TX

#### **Details** Lot# **Details** Lot # 1442 2014 Freightliner Cascadia 125 6x4 T/A 1445 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLD5XELFM3669 S/N: 3AKJGLD50ESFY3229 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLOhp Engine, Requires Diesel Exhaust Fluid, 24797 Engine hrs, Engine Brake, Detroit DT12-16913A 13-Speed Manual Transmission, OA-1550 12-Speed Automated Transmission, Differential Lock, 12500 lb Front Axle, 40000 lb 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Rears, Meritor MT-40-14X Drive Axles, 3.20:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Axle Ratio, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Heater, Aluminum Outer Wheels, 11R22.5 Front Suspension, 228 in Wheelbase, Air Sliding 5th Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Wheel, Dual Fuel Tanks Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 733,766 Mi Usage: 816,732 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Asset located in: Humble, TX 1446 2014 Freightliner Cascadia 125 6x4 T/A CHOICE OF 4 - Lot #'s: 1443, 1444, 1445, 1446 Sleeper Truck Tractor S/N: 3AKJGLD52ESFR3485 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 1443 2014 Freightliner Cascadia 125 6x4 T/A hp Engine, US EPA Label, Requires Diesel **Sleeper Truck Tractor** Exhaust Fluid, 22596 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, S/N: 1FUJGLDV0ELFK3902 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Automated Transmission, 13220 lb Front Axle, Ride Suspension, 238 in Wheelbase, Air Sliding 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 899,662 Mi GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Notes: DEFICIENCIES NOTED - PLEASE SEE Wheelbase, Air Sliding 5th Wheel, Dual Fuel THE INSPECTION REPORT Tanks Asset located in: Humble, TX Usage: 542,197 Mi Asset located in: Lake Worth, TX CHOICE OF 3 - Lot #'s: 1447, 1448, 1449 1444 2014 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** S/N: 3AKJGLD58ESFK2646 1447 2013 Freightliner Cascadia 125 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Sleeper Truck Tractor S/N: 1FUJGLDR8DLBV8807 Exhaust Fluid, 27101 Engine hrs, Engine Brake, Eaton Fuller RTOCM-16909A 13-Speed Manual C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Air Ride Cab, 70 in High Transmission, 12350 lb Front Axle, 34000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 46350 lb GVWR, 70 in High Rise Rise Sleeper Cab, Bunk Beds, Aluminum Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5 Front Tires, 11R22.5

Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel

Usage: 1.278.392 Mi

Asset located in: Lake Worth, TX

Rear Tires, Airliner Air Ride Suspension, 230 in

Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Tanks

Usage: 191,299 Mi

## **Details** Lot # 1448 2013 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** S/N: 1FUJGLBG4DSBZ8339 C/W: Cummins ISX15 400ST 6 Cylinder 15.0 L Diesel 400 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller FRM-15210B 10-Speed Manual Transmission, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A **BONDED TITLE** Asset located in: Lake Worth, TX 1449 2013 Freightliner Cascadia 6x4 T/A Sleeper **Truck Tractor** S/N: 3AKJGLDR7DSBB5155 C/W: 6 Cylinder Diesel 455 hp Engine, 27508.2 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Rear Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in

Tanks Usage: 128,090 Mi

**Notes:** ODOMETER DISCREPANCY-PLEASE SEE INSPECTION REPORT DEFICIENCIES

Wheelbase, Air Sliding 5th Wheel, Dual Fuel

NOTED

Asset located in: Humble, TX

CHOICE OF 3 - Lot #'s: 1450, 1451, 1452

## 1450 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR8CSBT4009 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Lake Worth, TX

## 1451 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

Lot #

**Details** 

S/N: 1FUJGLBG4CSBP1768
C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel
450 hp Engine, 2011 US EPA Label, Requires
Diesel Exhaust Fluid, Engine Brake, Eaton Fuller
FRO-15210C 10-Speed Manual Transmission,
12000 lb Front Axle, 40000 lb Rears, Meritor
MT-40-14X Drive Axles, 3.55:1 Axle Ratio,
52000 lb GVWR, Air Ride Cab, 72 in High Rise
Sleeper Cab, Bunk Beds, Auxiliary Power Unit,
Aluminum Front Wheels, 295/75R22.5, Airliner
Air Ride Suspension, 230 in Wheelbase, PTO,
Hydraulic Oil Cooler, Air Sliding 5th Wheel, Dual
Fuel Tanks
Usage: 592,035 Mi

Asset located in: Humble, TX

## 1452 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLBG1CSBM5211 C/W: Cummins ISX 15 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 3.42: 1 Axle Ratio, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 899,518 Mi

Asset located in: Lake Worth, TX

## 1453 2010 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGLDR0ASAS4603 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 35268 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 47268 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 836,813 Mi

Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1454, 1455

## 1454 2018 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGHDV8JSJX1807 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650-OH 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in Condo Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 815,447 Mi

Lot #	Details	Lot #	Details
1455	2018 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGHDV9JSJJ2300 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 209 in Wheelbase, Air Sliding 5th Wheel Usage: 649,665 Mi Asset located in: Midland, TX	1460	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD55ESFN2395 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 32691 Engine hrs, Engine Brake, Eaton Fuller FRO-16210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, Bunk Beds, RigMaster Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 717,423 Mi Asset located in: Lake Worth, TX

CHOICE OF 2 - Lot #'s: 1457, 1458

### 1457 2016 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGHDV9GLGS0046 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 762,092 Mi

Asset located in: Humble, TX

## 1458 2016 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor

S/N: 1FUJGHDV2GLGS0048 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.31:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Hydraulic Oil Cooler, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: 634,517 Mi

Asset located in: Humble, TX

## 1459 2014 Freightliner Cascadia 113 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGHDV1ESFN7414
C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500
hp Engine, 2013 US EPA Label, CARB
Compliant, Requires Diesel Exhaust Fluid,
Exhaust Brake, Eaton Fuller 10-Speed Manual
Transmission, Differential Lock, 12300 lb Front
Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride
Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds,
Aluminum Outer Wheels, 11R22.5, Air Assist
Front Suspension, Airliner 4-Bag Air Ride
Suspension, 232 in Wheelbase, PTO, Wet Kit,
Air Sliding 5th Wheel, Dual Fuel Tanks
Usage: Not Available

Asset located in: Midland, TX

CHOICE OF 2 - Lot #'s: 1461, 1462

## 1461 2018 Western Star 5700 6x4 T/A Sleeper Truck Tractor

S/N: 5KJJBHDR2JLJZ0716 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 27535 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40009 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 653,881 Mi

**Notes**: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

### 1462 2017 Western Star 5700 XE 6x4 T/A Sleeper Truck Tractor

S/N: 5KJJBHDRXHLJE5495 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 27690 Engine hrs, Retarder, Detroit DT12-OA-1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 54 in Mid Roof Sleeper Cab, 11R22.5, Airliner Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 718,491 Mi

#### **Details** Lot # **Details** Lot # 1463 2020 Volvo VNR400 6x4 T/A Sleeper Truck 1469 2016 Volvo VNL 64T 630 6x4 T/A Sleeper **Tractor Truck Tractor** S/N: 4V4WC9DH8LN270434 S/N: 4V4NC9EJ3GN946212 C/W: Volvo D11 6 Cylinder 10.8 L Diesel 425 hp C/W: Volvo D13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10991 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Engine, Requires Diésel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 13200 lb Front Axle, Transmission, 13200 lb Front Axle, 40000 lb 40000 lb Rears, Meritor MT-40-14X Drive Axles, Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 61 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Volvo Air Ride Top Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Volvo Air Ride Suspension, 197 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Suspension, 136 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Tanks Usage: 304,892 Mi Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV THE INSPECTION REPORT Asset located in: Humble, TX PRIOR TO BIDDING 1464 2018 Volvo VNL300 6x4 T/A Sleeper Truck Asset located in: Lake Worth, TX Tractor 1470 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH1JN899041 C/W: Volvo D13M425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2017 US EPA S/N: 4V4NC9TH2FN912681 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2011 US EPA Label, CARB Label, Requires Diesel Exhaust Fluid, 12-Speed Compliant, Requires Diesel Exhaust Fluid, Automated Transmission, 12500 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, 61 in High Engine Brake, Eaton Fuller 10-Speed Manual Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 208 in Wheelbase, Air Sliding Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 42 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air 5th Wheel, Dual Fuel Tanks Ride Suspension, 226 in Wheelbase, Air Sliding Usage: 568,767 Mi 5th Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 480,143 Mi 1466 2017 Volvo VNL 6x4 T/A Sleeper Truck Tractor Notes: ODOMETER DISCREPANCY-UNIT SHOWS 480,143, TITLE SHOWS 485,418; THIS S/N: 4V4NC9EH4HN971537 UNIT RUNS BUT MAY HAVE DEFICIENCIES IN C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel ITS POLLUTION CONTROL SYSTEMS WITH 455 hp Engine, 2016 US ÉPA Label, Requires LIABILITIES OUTLINED IN TEXAS Diesel Exhaust Fluid, Automatic Transmission, Differential Lock, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, High Rise ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 RESTORATION OF ALL POLLUTION CONTROL /75R22.5, Air Ride Suspension, 216 in SYSTEMS OR DEVICES AS ORIGINALLY Wheelbase, Air Sliding 5th Wheel, Headache EQUIPPED. BUYER OF THIS UNIT MUST SIGN Rack, Dual Fuel Tanks ACKNOWLEDGEMENT FORM OF THIS NOTICE Usage: 838,421 Mi PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE Asset located in: Lake Worth, TX INSPECTION REPORT 1468 2017 Volvo VNL630 6x4 T/A Sleeper Truck **Tractor** Asset located in: Humble, TX S/N: 4V4NC9EG2HN990322 1471 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor C/W: Volvo D13 6 Cylinder 12.8 L Diesel 405 hp S/N: 4V4NC9EH3FN916526 Engine, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612D 12-Speed Automated C/W: Volvo D13J425 6 Cylinder 12.8 L 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT02612D Transmission, 12500 lb Front Axle, 40000 lb Rears, 50350 lb GVWR, 61 in Mid Roof Sleeper 12-Speed Automated Transmission, 12350 lb Cab, 295/75R22.5 Front Tires, 275/80R22.5 Front Axle, 38000 lb Rears, Meritor MT-40-14X Rear Tires, Volvo Air Ride Suspension, 216 in Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Wheelbase, Air Sliding 5th Wheel Usage: 645,246 Mi Beds, Aluminum Wheels, 275/80R22.5 Front Asset located in: Lake Worth, TX Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 763,465 Mi

# Asset located in: Lake Worth, TX 1472 2013 Volvo VNL T/A Sleeper Truck Tractor

S/N: 4V4NC9TG2DN142504 Usage: Not Available

Lot #	Details	Lot #	Details
1473	2012 Volvo VNL T/A Sleeper Truck Tractor S/N: 4V4NC9EH0CN543487 Usage: Not Available	сноіс	E OF 4 - Lot #'s: 1477, 1478, 1479, 1480
Asset located in: Lake Worth, TX  CHOICE OF 3 - Lot #'s: 1474, 1475, 1476		1477	2017 International Prostar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR8HN284030 C/W: Cummins ISX15 6 Cylinder 15.0 L 450 hp
1474	2018 International LT625 6x4 T/A Sleeper Truck Tractor  S/N: 3HSDZAPR4JN524544  C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14712 Engine hrs, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mic Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22 Super Singles Rear Tires, Air Ride Suspensior 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 644,916 Mi Notes: .  Asset located in: Lake Worth, TX
	Usage: 433,846 Mi <b>Asset located in</b> : Lake Worth, TX	1478	2017 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor
1475	2018 International LT62F T/A Sleeper Truck Tractor S/N: 3HSDZAPR3JN532604 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3HSDJSNR2HN447862 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19396 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds,
1476	2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR2JN247098 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11639 Engine hrs, Engine Brake, Automated Transmission, 12350 lb		Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 542,861 Mi
		1479	Asset located in: Lake Worth, TX  2017 International ProStar T/A Sleeper Truck
	Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 429,685 Mi		Tractor S/N: 3HSDJAPR1HN693549 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	1480	2017 International ProStar 6x4 T/A Sleeper Truck Tractor
1476A	2018 International LT625 T/A Sleeper Truck Tractor S/N: 3HSDZAPR4JN233073 Usage: Not Available Asset located in: Humble, TX		S/N: 3HSDJAPR1HN204325 C/W: Cummins ISX 450ST 6 Cylinder 15 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission,
1476B	2018 International LT625 T/A Sleeper Truck Tractor S/N: 3HSDZAPR9JN326333 Usage: Not Available Asset located in: Humble, TX		13200 lb Front Axle, 40000 lb Rears, 53200 l GVWR, Air Ride Cab, 73 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, 267 Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 505,833 Mi <b>Asset located in</b> : Humble, TX

Lot #	Details	Lot #	Details
CHOIC 1481	E OF 5 - Lot #'s: 1481, 1482, 1483, 1484, 1485  2016 International Prostar 6x2 T/A Sleeper Truck Tractor S/N: 3HSDJSNR0GN058653 C/W: International N13 6 Cylinder 12.4 L Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 12350 Ib Front Axle, 40000 Ib Rears, Meritor MT-40- 14X Drive Axles, 52350 Ib GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front	1484	2015 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR9FN526675 C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 275 /80R22.5, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 676,438 Mi Asset located in: Humble, TX
	Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Dual Fuel Tanks Usage: 842,762 Mi <b>Asset located in</b> : Lake Worth, TX	1485	2015 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR3FN668830 C/W: Cummins ISX 400ST 6 Cylinder Diesel 218 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 19195 Engine hrs, Engine Brake, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, 252 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,953 Mi Asset located in: Humble, TX
1482	2016 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR2GN428556 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16496 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Usage: 614,573 Mi Asset located in: Lake Worth, TX		
1483	2015 International ProStar 6x4 T/A Sleeper	-	_ 0. 0 _ 0
	Truck Tractor  S/N: 3HSDJAPR3FN676250  C/W: Cummins ISX15 15 L Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19816 Engine hrs, Engine Brake, 9-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 73 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 654,586 Hr  Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX	1486	2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR7EN796955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17185 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1487	2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR7EN759578 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17281 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 549,311 Mi

Lot #	Details	Lot #	Details
1488	2014 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor	1493	2007 Peterbilt 379 6x4 T/A Sleeper Truck Tractor
	S/N: 3HSDJSJR8EN418495 C/W: International MaxxForce 13 6 Cylinder 13 L Diesel Engine, Automatic Transmission Usage: Not Available		S/N: 1XP5DB9X87N667738 C/W: Cat C15 6 Cylinder Diesel 550 hp Engine, 35138.1 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Mid Roof Sleeper Cab, COLEMAN
	Asset located in: Lake Worth, TX		
CHOICE OF 2 - Lot #'s: 1490, 1491			MACK Electric Sleeper Air Conditioner, 3cyl KUBOTA Auxiliary Power Unit, 315/80R22.5 Front Tires, 285/75R24.5 Rear Tires, Low Air Leaf Air Ride Suspension, 312 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, Custom
1490	2012 International Prostar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR7CN094078 C/W: 6 Cylinder Diesel Engine, 34209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 11R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 689,264 Mi		Condo Sleeper Equipped with Shower/Toilet Combo, Convection Oven and Refrigerator Usage: 1,479,428 Mi
			Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
			Asset located in: Humble, TX
		1494	2003 Peterbilt 379 6x4 T/A Sleeper Truck Tractor
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1XP5DB9X43D802164 C/W: Cat C15 6 Cylinder 14.6 L Diesel 475 hp Engine, 2001 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Wheels, 285/75R24.5, Low Air Leaf Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 93,811 Mi Asset located in: Lake Worth, TX
1491	Asset located in: Humble, TX  2012 International Prostar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR1CN094075 C/W: 6 Cylinder Diesel Engine, 27815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 798,884 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
		1495	2000 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DR9X3YD506553 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 450 hp Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Leaf 4-Bag Air Ride
1492	Asset located in: Humble, TX  2005 Kenworth W900L 6x4 T/A Sleeper Truck		
1492	Tractor S/N: 1XKWD49X55R076276 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, 13-Speed Manual Transmission, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,655 Mi Asset located in: Lake Worth, TX		Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,326 Mi
			Asset located in: Humble, TX
		1496	2007 Kenworth T800 6x4 T/A Sleeper Truck Tractor
			S/N: 1XKDD40X17R994789 C/W: Cummins ISX 6 Cylinder 15 L Diesel 475 hp Engine, 2005 US EPA Label, 10738 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 4.30:1 Axle Ratio, 59220 lb GVWR, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel Usage: 276,651 Mi

Asset located in: Midland, TX

Lot #	Details	Lot #	Details
1497	2005 Kenworth T800 6x4 T/A Sleeper Truck Tractor  S/N: 1XKDDB9X95J099229  C/W: Cat C15 6 Cylinder 15 L Diesel 475 hp Engine, 30565 Engine hrs, Engine Brake, Eaton Fuller 10-Speed hybrid, automatic with clutch Transmission, 40000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 62 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, 4- Bag Air Ride Suspension, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 161,706 Mi Asset located in: Lake Worth, TX	1502	2007 Kenworth T600 6x4 T/A Sleeper Truck Tractor  S/N: 1XKADB9X57J158461  C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller RTLOC16909AT2  Manual Transmission, Dana DSP40 Drive Axles, 3.55:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,098,883 Mi  Asset located in: Lake Worth, TX
1498	1996 Kenworth W900L 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDR9XXTR729761 C/W: Detroit/series60 6 Cylinder 12.7 L Diesel 470 hp Engine, 1996 US EPA Label, Engine Brake, Manual Transmission, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 258 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 310,988 Mi Asset located in: Lake Worth, TX	1503	2005 Kenworth T2000 6x4 T/A Sleeper Truck Tractor  S/N: 1XKTDB9X15J058198  C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Differential Lock, Spicer DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1499	2005 Freightliner Coronado 132 6x4 T/A Sleeper Truck Tractor		Usage: Not Available  Asset located in: Lake Worth, TX
515 hp Engine, 2004 US EPA Label Brake, Eaton Fuller RTLO-16913A 1 Manual Transmission, 12000 lb Fro 40000 lb Rears, Meritor RT-40-145 3.58:1 Axle Ratio, 52000 lb GVWR, 70 in High Rise Sleeper Cab, Bunk I Aluminum Front Wheels, 295/75R2 Assist Front Suspension, Airliner States in Wheelbase, Air Sliding 5th W Fuel Tanks Usage: 1,885,684 Mi	C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2004 US EPA Label, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 295/75R22.5, Air Assist Front Suspension, Airliner Suspension, 265 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	1504	2009 Mack CXU613 Pinnacle 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW09Y49N006962 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 338 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
1500	2006 International 9400L 6x4 T/A Sleeper Truck Tractor S/N: 2HSCNSCR46C195887 C/W: 6 Cylinder Diesel Engine, Engine Brake,		E OF 2 - Lot #'s: 1505, 1506
	Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 72 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual	1505	2006 Mack CXN613 T/A Sleeper Truck Tractor S/N: 1M1AK07YX6N011822 Usage: Not Available Asset located in: Lake Worth, TX
	Fuel Tanks Usage: 1,001,440 Mi <b>Asset located in</b> : Lake Worth, TX	1506	2006 Mack CXN613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AK06Y86N014932
1501	2006 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7DB9X16D896274 C/W: Cat C15 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, Low Air Leaf Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,814,828 Mi Asset located in: Lake Worth, TX		C/W: Mack AC 6 Cylinder Diesel 380 hp Engine 2005 US EPA Label, 23678 Engine hrs, Engine Brake, Mack T310 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Fla Top Sleeper Cab, Bunk Heater, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 214 in Wheelbase, PTO, Headache Rack Usage: 549,542 Mi  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1507	2005 Mack CX613 6x4 T/A Sleeper Truck Tractor  S/N: 1M1AE05Y75N021491  C/W: Mack 6 Cylinder Diesel Engine, 2004 US  EPA Label, 15393 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front  Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Sleeper Air Conditioner, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 211 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 517,922 Hr  Asset located in: Lake Worth, TX	1512	2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK86LV66960 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2005 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, 295/75R22.5, Airliner Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,027,381 Mi Asset located in: Lake Worth, TX
1500	·	1514	2001 Freightliner ST120 6x4 T/A Sleeper Truck
1508	2008 International ProStar Premium 6x4 T/A Sleeper Truck Tractor S/N: 2HSCUAPR48C686955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,049,713 Mi Asset located in: Lake Worth, TX		Tractor  S/N: 1FUJBBBD91LH91702  C/W: Cummins N14 6 Cylinder 14.0 L Diesel 435 hp Engine, 2000 US EPA Label, Meritor MO- 14G10A-M14 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT- 40-145 Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Suspension, 226 in Wheelbase, Dual Fuel Tanks Usage: 854,362 Mi Asset located in: Lake Worth, TX
1509	2006 International 9400i 6x4 T/A Sleeper	1515	·
	Truck Tractor S/N: 2HSCNAPR16C228106 C/W: Cummins ISX 14.9 L Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,412,255 Mi Asset located in: Lake Worth, TX	470 hp Engine, 1999 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 Rears, 52000 lb GVWR, Air Ride Cab, 58 in Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 262 in Wheelbase, Air Sliding Wheel, Dual Fuel Tanks Usage: 972,743 Mi  Asset located in: Midland, TX  1516 1995 Freightliner FLD 120 6x4 T/A Sleepe Truck Tractor  S/N: 1FUPDZYB7SH718722  C/W: Detroit 6 Cylinder Diesel Engine, Eng Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 Rears, 52000 lb GVWR, Air Ride Cab, 58 in Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Air Ride Suspension, 24 Wheelbase, Air Sliding 5th Wheel, Dual Fu Tanks Usage: 687,717 Mi	Truck Tractor  S/N: 1FUPCSEB4YDF85578  C/W: Detroit Series 60 6 Cylinder 12.7 L Dies 470 hp Engine, 1999 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in H Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 262 in Wheelbase, Air Sliding 5t
1510	2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor		Usage: 972,743 Mi
	S/N: 1FUJA6CK19LAD2685 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, Engine Brake, Eaton Fuller RTO- 16910B-DM 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Dana DS404 Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 587,873 Mi Asset located in: Humble, TX		S/N: 1FUPDZYB7SH718722 C/W: Detroit 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Air Ride Suspension, 246 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 687,717 Mi
1511	2007 Freightliner Century Class CST120 6x4 T		Asset located in: Humble, TX
	/A Sleeper Truck Tractor S/N: 1FUJBBAV37LX21774 C/W: Cat C15 6 Cylinder Diesel Engine, 18993 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: 955,175 Mi		

Lot #	Details	Lot #	Details
1517	1996 Freightliner USF-E1 6x4 T/A Sleeper Truck Tractor S/N: 1FUYDDYBXTP613588 C/W: 6 Cylinder Diesel Engine, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 285/75R24.5 Front Tires, 11R24. 5 Rear Tires, Airliner Air Ride Suspension, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available	1522	2019 Ottawa 4x2 Spotter Truck S/N: 4LMSB2114KL031788 C/W: Cummins QSB4.5 4 Cylinder 5.4 L Diesel 173 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 24000 lb Rears, Steel, 11R22.5, 115 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 10,626 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1523	2017 Ottawa T2 4x2 Spotter Truck
	E OF 2 - Lot #'s: 1518, 1519		S/N: 343984 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, 7207 Engine hrs, Allison Transmission, Steel, 11R22.5, Spring Suspension, 116 in Wheelbase, Hydraulic Lift 5th Wheel
1518	2023 Capacity TJ5000 Spotter Truck S/N: 4LMBF5111PL041353 C/W: Allison Automatic Transmission, 295 /75R22.5, 130 in Wheelbase, Hydraulic Lift 5th		Usage: 30,805 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY
	Wheel Usage: Not Available		Asset located in: Lake Worth, TX
1519	Asset located in: Lake Worth, TX  2023 Capacity 4x2 Spotter Truck	1524	2015 Ottawa Sabre 5 4x2 Spotter Truck S/N: 335984 C/W: Cummins QSB 6.7 L 165 hp Engine, 2014
	S/N: 4LMBF5119PL041360 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 11R22.5, 132 in		US EPA Label, Allison Transmission, 295 /75R22.5, 118 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available
	Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available		Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE
	Asset located in: Humble, TX		Asset located in: Lake Worth, TX
1520	2021 Capacity 4x2 Spotter Truck S/N: 4LMBF2115ML029314 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel	СНОІС	E OF 5 - Lot #'s: 1525, 1526, 1527, 1528, 1529
	200 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, 116 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 30,689 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	1525	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2110BL022565 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Allison Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
CHOICI	E OF 2 - Lot #'s: 1521, 1522	1526	2011 Capacity TJ5000 4x2 Spotter Truck
1521	2019 Ottawa 6x4 Spotter Truck S/N: 4LMDB7136KL027975 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 173 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5750 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Steel, 11R22.5 Front Tires, 255/70R22.5 Rear Tires, 154 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 8,516 Mi	1020	S/N: 4LMBR2112BL022566 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2014 US EPA Label, Automatic Transmission, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1527	2011 Capacity TJ5000 4x2 Spotter Truck	1532	CRC PB Pipe Bending Machine
102,	S/N: 4LMBR2113BL022611 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 160 hp Engine, 2021 US EPA Label, 2649 Engine hrs, Allison Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 110 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 87,798 Mi	1002	S/N: 20-267 C/W: Bends 6 in to 20 in Pipe, Tow Behind, Winch, Kubota Diesel Engine Usage: 1,103 Hr
			Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
	Notes: NO TITLE AVAILABLE, SOLD WITH BILL		Asset located in: Lahoma, OK
	OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;  Asset located in: Lake Worth, TX	1534	2012 Tensioner S/N: 1F9UZ1313CV048037 Usage: Not Available
1528	2011 Capacity TJ5000 4x2 Spotter Truck S/N: 4LMBR2118BL022569 C/W: Cummins 6 Cylinder Diesel Engine, 275		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	/80R22.5 Front Tires, 295/75R22.5 Rear Tires,		Asset located in: Lake Worth, TX
	112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available	1535	2008 TSE T/A Tensioner
	Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		S/N: 1T92C15238S268017 C/W: 2007 US EPA Label, John Deere 4024TF270C 4 Cylinder Diesel Engine Usage: Not Available
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
1529	S/N: 4LMBR211XBL022573 C/W: Cummins 6.7 L Diesel Engine, Allison Automatic Transmission, 275/80R22.5, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 25,696 Hr	1536	2003 Sherman Reily T/A Tensioner S/N: 123WM212831T16188 C/W: Honda 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		FŘOM-A-PRIMORIŠ-SERVÍCES-CORP- COMPANY Usage: Not Available	Cable Puller S/N: 1W9DP4321BA161085
1530	2008 Ottawa TY30 4x2 Spotter Truck S/N: 318992 C/W: Cummins QSB 6 Cylinder 6.7 L Diesel Engine, Allison Automatic Transmission, 275		Cylinder Diesel Engine, (5) Reels; FROM-A-PRIMORIS-SERVICES-CO COMPANY Usage: Not Available
	/80R22.5, 111 in Wheelbase, Hydraulic Lift 5th Wheel	1538	Altec AT235P 35 ft on 2015 Ford F-550 XL 4x2
	Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	1556	Bucket Truck S/N: 1FDUF5GT5FED59378 C/W: Ford 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid,
-	Asset located in: Lake Worth, TX		Automatic Transmission, 7000 lb Front Axle,
1531	2006 Ottawa TY30 4x2 Spotter Truck S/N: 314014 C/W: Cummins USB 6 Cylinder 5.9 L 155 hp Engine, Automatic Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX		13660 lb Rears, 18000 lb GVWR, Steel, 225 /70R19.5, Spring Suspension, 165 in Wheelbase, 300 lb Capacity, Front Mounted, One-Person Articulating-Telescopic Boom, Utility Body, 11 ft x 94 in Bed Usage: 75,582 Mi Asset located in: Lake Worth, TX

## **Details** Lot # **Details** Lot # 1539 1543 Vactor 2100 Series on 2002 Sterling L9500 6x4 Tornado F4SL on 2015 Western Star 4900 8x6 **Vacuum Excavator Truck** Vacuum Excavator Truck S/N: 5KKPALD10FPGA1440 S/N: 2FZHAZAS02AK42561 C/W: Cat C12 6 Cylinder Diesel 355 hp Engine, C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 35902 Engine hrs, Engine Brake, 8023 Engine hrs, Éngine Brake, Allison Automatic Transmission, 20000 lb Front Axle, Eaton Fuller 18-Speed Manual Transmission, 46000 lb Rears, 66000 lb GVWR, Steel, 425 Triple Differential Locks, 20000 lb Front Axle, /65R22.5, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Spring over 57000 lb Rears, 4.30:1 Axle Ratio, 77000 lb GVWR, Air Ride Cab, Aluminum Wheels, 445 /65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Walking Beam Suspension, 252 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Boom, 8 in Suction Hose, PTO Steering Boxes, Double Frame, Airliner Suspension, 303 in Wheelbase, Steel 2150 gal Debris Tank, Hydraulic Tailgate Locks, Telescopic Boom, 8 in Suction Hose, Cat Hydraulic Driven Pump, Robuschi Blower w/ 5642 hrs, Hotshot Boiler, Cordless Remote Driven Pump, Roots 824RSCV18 Blower, 66000 **Ib GVWR** Usage: 134,573 Mi Asset located in: Lake Worth, TX Control, 77000 lb GVWR 1544 2001 Ford F-550 XL 4x2 Vacuum Excavator Usage: 10,861 Km Truck Asset located in: Lake Worth, TX S/N: 1FDAF56F71EC85002 C/W: Ford 7.3 V8 7.3 L Diesel Engine, 978 1540 2013 Western Star 4900 Vacuum Excavator Engine hrs, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 201 in Wheelbase, 100 gal Debris Tank, Rear Hose Truck S/N: 5KKPALDR6DPBH7992 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 530 hp Engine, Requires Diesel Exhaust Fluid, 8104 Reel, 4 in Suction Hose, 17500 lb GVWR Engine hrs, Engine Brake, Eaton Fuller RTLO-Usage: 233,622 Mi 18918B Manual Transmission, Double Asset located in: Lake Worth, TX Differential Locks, 20000 lb Front Axle, 56700 lb Rears, Meritor RZ-166 Drive Axles, 4.56:1 Axle Ratio, 76700 lb GVWR, Air Ride Cab, CHOICE OF 2 - Lot #'s: 1545, 1546 Aluminum Front Wheels, 445/65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Airliner Air Ride Suspension, 1545 2013 Mack GU713 3800 gal 6x4 Vacuum 318 in Wheelbase, PTO, Hydraulic Oil Cooler, **Tanker Truck** Steel Debris Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Telescopic Boom, 8 in Suction Hose, Cat Hydraulic Driven Pump, S/N: 1M2AX07C0DM014703 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US ÉPA Label, Requires Diesel Robuschi Blower, Cordless Remote Control, Exhaust Fluid, 27175 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Differential Lock, 38000 lb GVWR, Air Ride Cab, 76700 lb GVWR Usage: 105,864 Mi Asset located in: Midland, TX Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual 1541 Hi-Vac X-10 on 2015 Peterbilt 367 Vacuum Steering Boxes, Double Frame, Air Ride **Excavator Truck** Suspension, 268 in Wheelbase, Aluminum S/N: 1NPTL40X1FD270583 3800 gal Debris Tank, Non Code Code, Manual C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-Tailgate Locks, PTO Driven Pump, 38000 lb **INFRASTRUCTURE GVWR** Usage: Not Available Usage: 402,799 Mi Asset located in: Humble, TX Asset located in: Lake Worth, TX 1542 Gap-Vac on 2002 Volvo VHD 6x4 Vacuum 1546 2012 Mack GU713 8x4 Vacuum Tanker Truck **Excavator Truck** S/N: 1M2AX07C8CM012213 S/N: 4V5KC9UF92N321981 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 C/W: Cummins ISM 10.8 L Diesel 325 hp hp Engine, 2011 US EPA Label, Requires Diesel Engine, Engine Brake, Eaton Fuller Manual Exhaust Fluid, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, 385/65R22.5 Front Rears, 64000 lb GVWR, Air Ride Cab, 425 Tires, 11R22.5 Rear Tires, Double Frame, Spring over Walking Beam Suspension, 254 in /65R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Wheelbase, PTO, Steel Debris Tank, Front Hose Suspension, 272 in Wheelbase, Aluminum Debris Tank, 64000 lb GVWR Usage: 469,818 Mi Reel, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, PTO Driven Pump, 64000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1547	2014 International 7600 6x4 Vacuum Tanker Truck  S/N: 1HTGSSNTXEH029640  C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 46000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Air Ride Suspension, 228 in Wheelbase, 2000 gal Debris Tank, 64000 lb GVWR Usage: 240,009 Mi  Asset located in: Lake Worth, TX  2013 International 7400 4x2 Pressure Truck	1552	Texoma 500-15 on 2004 International 7400 6x4 Pressure Digger  S/N: 1HTWGADT34J083149  C/W: Detroit 4 Cylinder Upper Engine, Winch, Straight Down Outriggers, Rear Outriggers, Bumper Mounted Winch, International 6  Cylinder Diesel Engine, 10013 Engine hrs, Allison Automatic Transmission, Differential Lock, 16000 lb Front Axle, 53120 lb Rears, 56000 lb GVWR, Air Ride Cab, 385/65R22.5  Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 205 in Wheelbase Usage: 91,448 Mi
	S/N: 1HTWCAZN2DJ200547 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 8LL		Asset located in: Lake Worth, TX
	Manual Transmission, 10000 lb Front Axle, 23000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Spring Suspension, 222 in Wheelbase, PTO, weatherford Triplex Pump, Fiberglass Reinforced Plastic Tank Usage: 221,859 Mi  Asset located in: Lake Worth, TX	1554	Texoma 3301500 on 1993 Mack RD690S 4x2 Drill Truck S/N: 1M2P264Y0PM013308 C/W: Cummins 4BTA3.9-C 3.9 L 4 Cylinder Upper Engine, Mack EM7 6 Cylinder Diesel 300 hp Engine, 1993 US EPA Label, 16469 Engine hrs, Eaton Fuller 9-Speed Manual Transmission, Steel, 11R24.5, Camelback
1549	Elgin Crosswind on 2013 Freightliner M2 106 Sweeper Truck S/N: 1FVACXDT5DHFB1562		Spring Suspension, 212 in Wheelbase Usage: 273,655 Mi <b>Asset located in</b> : Lake Worth, TX
	C/W: Cummins 6.7 L Diesel 200 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 11R22.5, Spring Suspension, Auxiliary Engine, Under Body Broom Usage: 44,365 Mi  Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	1555	Texoma 600 on 1985 International F-1954 6x4 Drill Truck S/N: 1HTLKTVR9FHA26144 C/W: Deutz TCD2012L042V 4.0 L 4 Cylinder Upper Engine, Winch, Out and Down Outriggers Rear Outriggers, 6 Cylinder Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, 11R22.5, Double Frame, Hendrickson RT/RTE Series Suspension, 206 in Wheelbase
1550	2000 International 9900 6x4 Winch Truck S/N: 2HSFTAER6YC050198 C/W: Cummins N14 6 Cylinder 14.0 L Diesel		Usage: 164,298 Mi Asset located in: Lake Worth, TX
	435 hp Engine, Eaton Fuller 8LL Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Steel, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, Tail Roll, Tulsa Winch Usage: 540,116 Mi Asset located in: Lake Worth, TX		Texoma 270 on 1984 International 1954 4x2 Drill Truck S/N: 1HTLDUXP6EHA31702 C/W: John Deere 4045DF 6.8 L 4 Cylinder Upper Engine, Straight Down Outriggers, Rear Outriggers, 6 Cylinder Diesel Engine, Manual Transmission, 11R22.5, Spring Suspension, 170 in Wheelbase Usage: 280,022 Mi
1551	1995 International 9200 6x4 Winch Truck		Notes: RITCHIE-BROS-ENERGY
	S/N: 2HSFMAHR6SC052503 C/W: Cummins 6 Cylinder 10.8 L Diesel 370 hp		Asset located in: Lake Worth, TX
	Engine, 1995 US EPA Label, Spicer 10-Speed Manual Transmission, 295/75R22.5, Air Ride Suspension, 190 in Wheelbase, Tulsa Winch, Air sliding fifth wheel Usage: 691,448 Mi Asset located in: Lake Worth, TX	1557	2019 Thunder Vermeer R250C Mud Mixing System S/N: 56ZL2UZ20KP000069 C/W: (4) Shale Shakers, John Deere 4045 4 Cylinder 4.5 L Diesel Engine Usage: 1,607 Hr Asset located in: Lake Worth, TX
		1558	Quantity of (4) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1559	Quantity of (2) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	1577	Star 150 on 2004 Gefco Star 150K 10x4 Twin- Steer Drill Truck  S/N: 907612  C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder Diesel Engine,
1560	2011 Vermeer D100X120II Directional Drill S/N: 1VRZ33046B1000486 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 42000 lb Front Axle, 74240 lb Rears, 116240 lb GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 294 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Asset located in: Cedar Bluff, VA
1561	2008 Vermeer D100X120II Directional Drill S/N: 1VRZ3304781000182 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX	1578	(Rig#24) Lee C Moore 133 ft Cantilever Mast S/N: T1728 C/W: 470,000 Lb Static Hook Load, Crown Block, w/ Sheave Cluster, Fastline Sheave, Racking Board, Tong Counter Weights, Ladder, Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, qty 4 (2) sets of 40"H x 30'L triangular pipe racks, block hook combo, drill line spool; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
1562	2007 Vermeer D100X120II Directional Drill S/N: 1VRZ3304471000168 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Asset located in: Humble, TX		
1575	Star 185K on 2008 Gefco Star 185K 10x4 Twin- Steer Drill Truck S/N: 907835 C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14 L Diesel 665 hp Engine, 2007 US EPA Label, Engine Brake,	1579	(Rig#24) 28 ft x 16 ft x 46 ft 9 in Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
	Eaton Fuller 18-Speed Manual Transmission, 44000 lb Front Axle, 74240 lb Rears, 118240 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 8,461 Hr Asset located in: Cedar Bluff, VA		(Rig#24) 10 ft x 32 ft Doghouse S/N: Not Available C/W: knowledge box, bench storage, lockers, parts bins, fluorescent lighting, skidded;; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Asset located in: Coleman, TX
1576	Star 150K on 2006 Gefco Star 150K 10x4 Twin- Steer Drill Truck  S/N: 907730  C/W: PTO Driven, Rotary Air Drill, Auto Rod Changer, Winch, Straight Down Outriggers, Detroit Series 60 6 Cylinder 14.0 L Diesel 665 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 44000 lb Front Axle, 54240 lb Rears, 98240 lb		(Rig#24) 8 ft x 31 ft Mud House S/N: Not Available C/W: shelving, misc rig parts, skidded, Parts /Change House, Bench Storage, Parts Room; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Asset located in: Coleman, TX
	GVWR, 425/65R22.5 Front Tires, 12R22.5 Rear Tires, Air Lift Pusher Axle, Walking Beam Suspension, 298 in Wheelbase, PTO, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 3,356 Hr Asset located in: Cedar Bluff, VA	1582	(Rig#24) Quantity of (2) 10 ft x 33 ft 500 bbl Water Tank S/N: Not Available C/W: cent pump, ladder, skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX

Lot #	Details	Lot #	Details	
1583	(Rig#24) 3-Pit Mud System Mud Tank S/N: Not Available C/W: shopbuilt 8'W x 6'h x 20'L 220-BBL premix tank mud agitator, shopbuilt 8'W x 6'H x 30'L 206-BBL suction tank mud agitators, Shopbuilt 8'W x 6'H x 30'L 206-BBL shaker tank, Vortex Orbital 3000M single screen linear motion shale shaker, all skidded; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC	1589	(Rig#24) 10 ft x 40 ft Toolpusher's House S/N: Not Available C/W: office area, bedroom, bathroom area, kitchen area (gutted) skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX (Rig#24) Quantity of Closing Unit, Choke	
	Usage: Not Available  Asset located in: Coleman, TX		Manifold, Lubester, Swivel, Catwalk, Basket S/N: Not Available	
1584	(Rig#24) Fuel Tank & Parts House S/N: Not Available C/W: 7'W x 12'L round top flat steel parts house w/ 4'L covered porch extension, shelving fluorescent lighting skidded, 8'W x 8'H x 21'L 10,000 gallon fuel tank, w/ 8'L porch extension,		C/W: 5,000# choke manifold, 8'x 10' x 5' junk basket skidded w/contents, 5-station closing unit, 4-compartment lubester; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
	(2) 110V pumps, skidded ; EQUIPMENT-FROM- TPI-COLEMAN-PROJECT-LLC Usage: Not Available <b>Asset located in</b> : Coleman, TX	1591	(Rig#24) 27-½ in Rotary Table S/N: Not Available C/W: w/ Kelly drive bushing housing, chain guard; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC	
1585	(Rig#24) Quantity of (2) Cat Containerized Generator Set S/N: Not Available		Usage: Not Available  Asset located in: Coleman, TX	
	C/W: Cat 3406 Diesel Engine, Electrical panels, Fluorescent lighting, Storage area, Sullivan Palatek compressor; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available	1592	(Rig#24) 6 ft x 3 ft - 6 ft x 28 ft Catwalk S/N: Not Available C/W: assorted gates Usage: Not Available Asset located in: Coleman, TX	
	Asset located in: Coleman, TX	1500		
1586	(Rig#24) National 55 S/D Drawworks Drawworks S/N: T1890 C/W: 1,000 Hp, Lebus Grooved for 1-1/8" line, FOSTER Makeup & Breakout Catheads,2- Engine in line compound, (2) National c300185 torque converters, 2-stage air compressor, radiators, air start, muffler, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-	1593	(Rig#24) Junk Basket S/N: Not Available C/W: air hoist, elevator links, tongs, closing unit remote panel, mud bucket, drill pipe slips, drill collar slips and misc drilling equipment; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
	LLC Usage: Not Available <b>Asset located in</b> : Coleman, TX	1594	(Rig#24) Quantity of Drill Collars S/N: Not Available C/W: 6" OD Drill Collars w/4-1/25" XH	
1587	(Rig#24) Triplex Mud Pump S/N: Not Available C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/ screw in caps, pulsation dampener, mud gauge, cent pump, Cat 12V Diesel engine,	1595	Connections (3) 8" OD Drill Collars w/ 6-34" REG Connections, (1) Hex Kelley; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	
	air start, radiator, muffler, air and fuel tanks, master skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX		S/N: T3067 C/W: 440,000 Lb Static Hook Load, Crow Block w/ (4) 36" Cluster, 54" Fastline She Racking Board, Tong Counter Weights, La	C/W: 440,000 Lb Static Hook Load, Crown, Block w/ (4) 36" Cluster, 54" Fastline Sheave, Racking Board, Tong Counter Weights, Ladder,
1588	2010 (Rig#24) RS-F1000 Triplex Mud Pump S/N: RS11012 C/W: Cat 12 Cylinder Diesel Engine, steel fluid ends w/screw in caps, pulsation dampener, mud gauge, cent pump, bull wheel, belt guard, Cat 12V Diesel engine, air start, radiator, muffler, air volume tank, fuel tank, master skidded; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available  Asset located in: Coleman, TX		Derrick Climber, Geronimo, 4" Standpipe and Manifold, mast stand, spool of 1-1/8" drill line racking board 'EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available  Asset located in: Coleman, TX	

Lot #	Details	Lot #	Details
1596	(Rig#25) 26 ft 1 in x 16 ft x 47 ft Substructure S/N: Not Available C/W: Box-On-Box Substructure w/Rotary Beams, V-Door Ramp, Stairs, Safety Rails, Emsco type 17-1/2" rotary table, Ingeraoll Rand Air hoist, weight indicator, wireline measuring device, National deadman anchor, air volume tank, fold doghouse supports, pony subs, skidded 'EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available	1603	Cat (Rig#25) Containerized Generator Set S/N: Not Available C/W: Cat SR4B generator p/b Cat 6-cylinder diesel engine, generator p/b 6-cylinder diesel engine, skidded, electrical control panel, Curtis 30HP air compressor, all mud in 10'W x 40'L generator house, skidded; ; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available  Asset located in: Coleman, TX  (Rig#25) National 50-CA S/D Drawworks
1597	(Rig#25) 8 ft x 32 ft Doghouse S/N: Not Available C/W: Doghouse, 8'L Covered Porch, Lockers, Knowledge Box, Bench Storage, Cabinets; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1604	S/N: Not Available C/W: w/ (2) Cat D353 Diesel Engines, (2) National C-245-80 Torque Converters, 2-Engine inline compound, Quincy type air compressor, Air start, radiators, Foster makeup and breakout catheads, Levi's grooved f/1-1/8" drill line; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX
1598	(Rig#25) 10 ft x 5 ft 10 in x 30 ft 300 bbl Mud Tank S/N: Not Available C/W: VORTEX Orbital 3000M Single, Single Screen, Linear Motion Shale Shaker, mud house, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX		(Rig#25) Quantity of (2) Bomco 3NB1300C Triplex Mud Pump S/N: Not Available C/W: each with forged fluid ends w/ screw in caps, cent pump, Hydril pulsation dampeners mud gauges, p/b (1) Cat D398, (1) Cat D399F 12-Cylinder & 16-Cylinder Diesel engines, radiators, master skidded; EQUIPMENT-FRO
1599	(Rig#25) Quantity of (2) 500 bbl Water Tank S/N: Not Available C/W: skidded, w/water pump, (4) cent pumps; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC	1606	TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX  (Rig#25) Toolpushers House S/N: Not Available
1600	Usage: Not Available Asset located in: Coleman, TX  (Rig#25) 8000 gal Fuel Tank S/N: Not Available C/W: (2) transfer pumps, ladder; EQUIPMENT-		C/W: (1) office, (1) bedroom, (1) bathroom, skidded (doors locked could not access); EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available  Asset located in: Coleman, TX
	FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1607	(Rig#25) Sowa Block Hook Combination S/N: Not Available
1601	(Rig#25) Skidded Parts house S/N: Not Available C/W: shelving, lockers, bench storage, fluorescent lighting, skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available		C/W: (2) WTM 4- ¼" - 6 ¾" Rotary Tongs, elevator links, elevator, drill pipe slips, drill collar slips, lift subs, and bit breaker; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT- LLC Usage: Not Available Asset located in: Coleman, TX
1602	Asset located in: Coleman, TX  Parts House S/N: Not Available C/W: flat steel, round top, shelving, bench storage, fluorescent lighting, misc rig parts, skidded; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX	1608	(Rig#25) 4-Station Accumulator Closing Unit S/N: Not Available C/W: Parkersburg brake, (3) suitcases, stairs, tong and misc drilling equipment; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX

Lot #	Details	Lot #	Details
1609	(Rig#25) 2-Section Catwalk  S/N: Not Available C/W: Steel Deck, Ideco swivel, hex Kelly, mouse hole, hex Kelly drive bushing, junk basket w/lift subs and misc, water pump, v- door ramp; EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available	1616	1998 Triplex Mud Pump S/N: 160 TP 6L C/W: 4 in Intake, 3 in Discharge, Mud Pump, Cat 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	Asset located in: Coleman, TX	1617	Wheatley HP-250H Skid Mounted Triplex Test
1610	(Rig#25) Junk Box S/N: Not Available C/W: EQUIPMENT-FROM-TPI-COLEMAN- PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX		Pump S/N: Not Available C/W: 1 in Intake, 1 in Discharge, Triplex Detroit 8W-71 8 Cylinder Diesel Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
CHOICE OF 2 - Lot #'s: 1611, 1612  1611 2006 Bomco 3NB1000C Triplex Mud Pump		1618	2012 Keystone Skid-Mounted Booster Air Compressor S/N: MCW02262 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 1,899 Hr
	S/N: 1060917 C/W: Cat 12 Cylinder Diesel Engine, pulsation		Asset located in: Cedar Bluff, VA
	dampener, bolt on caps, mud gauge, bull wheel, skidded, Parkersburg torque converter, radiator, skidded; EQUIPMENT-FROM-TPI- COLEMAN-PROJECT-LLC Usage: Not Available	СНОІС	E OF 4 - Lot #'s: 1619, 1620, 1621, 1622
	Asset located in: Coleman, TX	1619	2007 Ingersoll Rand XHP1170 1170 cfm Ski
1612	2006 Bomco 3NB1000C Triplex Mud Pump S/N: 1060919 C/W: Cat 12 Cylinder Diesel Engine, bolt on caps, pulsation dampener, mud gauge, cent pump, manifold, torque converter, radiator, air and fuel tanks, master skidded; EQUIPMENT- FROM-TPI-COLEMAN-PROJECT-LLC		S/N: 378088 C/W: 365 psi Working Pressul Cylinder 540 hp Diesel Engine FROM-GASCO-DRILLING-INC Usage: 8,391 Hr
	Usage: Not Available <b>Asset located in</b> : Coleman, TX	1620	2007 Ingersoll Rand XHP1170 1170 cfm Skid-
1613	2008 NLB Skid Mounted Triplex Test Pump S/N: P4012901 C/W: Triplex Cummins N14 6 Cylinder Diesel Engine, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Mounted Air Compressor S/N: 380841ULQB78 C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 8,256 Hr Asset located in: Cedar Bluff, VA
	Asset located in: Lake Worth, TX	1621	2007 Ingersoll Rand XHP1170 1170 cfm Skid-
1614	Pai PAI70HP3250 Mud Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine Usage: 168 Hr Asset located in: Humble, TX		Mounted Air Compressor S/N: 378089 C/W: 365 psi Working Pressure, Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 9,385 Hr
1615	Tulsa Rig Iron Mud Pump S/N: TT150-52 C/W: Triplex 2014 US EPA Label, Cummins 6 Cylinder Diesel Engine Usage: 642 Hr Asset located in: Humble, TX	1622	Asset located in: Cedar Bluff, VA  2007 Ingersoll Rand XHP1170 Skid-Mounted Air Compressor S/N: 380840ULQB78 C/W: Cat C15 6 Cylinder 540 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 11,640 Hr Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
CHOIC 1623	E OF 2 - Lot #'s: 1623, 1624  2004 Sullair 1170 Skid-Mounted Air Compressor S/N: 006-04011489 C/W: Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available	1629	Quantity of (144) 3-1/2 in Range 2 (4,464') Drill Pipe  S/N: Not Available C/W: (4,464 ft), w/3-1/2"IF conns, HB, w/(4) (2) sets of 40"H x 30'L trainagular pipe racks; EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC Usage: Not Available Asset located in: Coleman, TX  Quantity of Approximately 6353 ft 4 in Drill Pipe
1624	Asset located in: Cedar Bluff, VA  2004 Sullair 1170 1170 cfm Skid-Mounted Air Compressor S/N: 006-04011490 C/W: 365 psi Working Pressure, Detroit Series 60 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1631	S/N: Not Available C/W: Approximately 6353 ft, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA  Quantity of Approximately 12114 ft of 3.5 in Drill Pipe S/N: Not Available C/W: Approximately 12114 ft; EQUIPMENT-FROM-GASCO-DRILLING-INC
CHOIC	E OF 3 - Lot #'s: 1625, 1626, 1627		Usage: Not Available  Asset located in: Cedar Bluff, VA
1625	2008 Ariel JGQ/2 Skid-Mounted Booster Air Compressor S/N: KB102 C/W: Cat C7 6 Cylinder 250 hp Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: 4,357 Hr Asset located in: Cedar Bluff, VA	1632	Quantity of Approximately 5767 ft of 4 in Drill Pipe S/N: Not Available C/W: Approximately 5767 ft; EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1626	2003 Ariel Skid-Mounted Booster Air Compressor S/N: KB-10 C/W: Cat 3126 6 Cylinder 309 hp 7.2 L Diesel Engine, EQUIPMENT-FROM-GASCO-DRILLING- INC Usage: 3,541 Hr Asset located in: Cedar Bluff, VA	CHOICE OF 10 - Lot #'s: 1633, 1634, 1635, 1636, 1638, 1639, 1640, 1641, 1642  1633 Quantity of (7) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRIL	
1627	2003 Ariel Skid-Mounted Booster Air Compressor S/N: BEJ02783 C/W: Cat 6 Cylinder Diesel Engine, EQUIPMENT- FROM-GASCO-DRILLING-INC Usage: 906 Hr Asset located in: Cedar Bluff, VA	1634	Usage: Not Available Asset located in: Cedar Bluff, VA  Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1628	Quantity of (152 joints)(4,712') 4-1/2 in Range 2 Drill Pipe  S/N: Not Available  C/W: (4,712 ft), w/ 4-1/2" FH conns, w/(6) 3  sets of 40"H x 30'L triangular pipe racks;  EQUIPMENT-FROM-TPI-COLEMAN-PROJECT-LLC  Usage: Not Available  Asset located in: Coleman, TX	1635	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
		1636	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
		1637	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
1638	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA  Quantity of (5) 4.5 in Drill Collars S/N: Not Available	1646	Quantity of (5) 4.5 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA
	C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available <b>Asset located in</b> : Cedar Bluff, VA	1647	Quantity of (5) 4.5 in Drill Collars S/N: Not Available
1640	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA
1641	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Quantity of (5) 4.5 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
1642	Quantity of (5) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Cedar Bluff, VA
	Usage: Not Available  Asset located in: Cedar Bluff, VA  OF 10 - Lot #'s: 1643, 1644, 1645, 1646, 1647, 1649, 1650, 1651, 1652		Quantity of (5) 4.5 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
			SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Cedar Bluff, VA
1643	Quantity of (5) 4.5 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Cedar Bluff, VA	1650	Quantity of (4) 4.5 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
1644	Quantity of (5) 4.5 in Drill Collars	4.554	Asset located in: Cedar Bluff, VA
1645	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA Quantity of (5) 4.5 in Drill Collars	1651	Quantity of (4) 4.5 in Drill Collars  S/N: Not Available  C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Cedar Bluff, VA
	S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA	1652	Quantity of (4) 4.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details	
	CHOICE OF 10 - Lot #'s: 1653, 1654, 1655, 1656, 1657, 1658, 1659, 1660, 1661, 1662		CHOICE OF 10 - Lot #'s: 1663, 1664, 1665, 1666, 1667, 1668, 1669, 1670, 1671, 1672	
1653	Quantity of (4) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1663	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1654	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1664	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1655	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1665	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1656	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1666	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1657	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1667	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1658	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1668	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1659	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1669	Quantity of (3) 6 in Drill Collars  S/N: Not Available  C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Asset located in: Cedar Bluff, VA	
1660	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1670	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1661	Quantity of (3) 6 in Drill Collars  S/N: Not Available  C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Asset located in: Cedar Bluff, VA	1671	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	
1662	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1672	Quantity of (3) 6 in Drill Collars  S/N: Not Available  C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Asset located in: Cedar Bluff, VA	

Lot #	Details	Lot #	Details
	E OF 9 - Lot #'s: 1673, 1674, 1675, 1676, 1677, 679, 1680, 1681	CHOICE OF 8 - Lot #'s: 1682, 1683, 1684, 1685, 1686, 1687, 1688, 1689	
1673	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1682	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1674	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1683	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1675	Quantity of (3) 6 in Drill Collars  S/N: Not Available  C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Asset located in: Cedar Bluff, VA	1684	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1676	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1685	Quantity of (1) 7.5 in Drill Collars  S/N: Not Available  C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC  Usage: Not Available  Asset located in: Cedar Bluff, VA
1677	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1686	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1678	Quantity of (3) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1687	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1679	Quantity of (3) 6 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1688	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1680	Quantity of (2) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1689	Quantity of (1) 7.5 in Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
1681	Quantity of (2) 6 in Drill Collars  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA	1690	Drill Collars S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA

Lot #	Details	Lot #	Details
1691	S/N: 1NKDX4EXXEJ404952 C/W: Cummins ISX15 15.0 L 525 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20872.4 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 71340 lb GVWR, Air Ride Cab, 11R24. 5 Front Tires, 11R24.5 Rear Tires, Hendrickson Primaax EX Air Ride Suspension, 229 in Wheelbase, 103 in Cab to Axle, 286 in Cab to End of Frame, Pintle Hitch Usage: 514,573 Mi	1694	2020 Freightliner M2 106 4x2 Cab and Chassis S/N: 3ALACWFC1LDMA1987 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller EDCO-6F107A Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 204 in Wheelbase, 140 in Cab to Axle, 212 in Cab to End of Frame Usage: 221,672 Mi Asset located in: Humble, TX
	Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD ASSET IOCATED IN LAKE WORTH, TX	1695	2019 International 4300 4x2 Cab and Chassis S/N: 3HAMMMMN5KL559225 C/W: Cummins B6.7 260 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12755 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 254 in Wheelbase, 186 in Cab to Axle, 278 in Cab to End of Frame Usage: 193,556 Mi Asset located in: Lake Worth, TX
1692	2018 Mack GU713 6x4 Cab and Chassis S/N: 1M1AX07YXJM038681 C/W: Mack MP8 6 Cylinder 12.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 189 Engine hrs, Engine Brake, Mack Automated Transmission, 13220 lb Front Axle, 46000 lb Rears, 59220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Double Frame, Rubber Suspension, 206 in Wheelbase Usage: 463,795 Mi Asset located in: Lake Worth, TX	1696	
1692A	2011 International 4400 6x4 Cab and Chassis S/N: 1HTMSAZR3BH340351		Usage: 393,327 Mi Asset located in: Lake Worth, TX
	C/W: International MaxxForce 9 6 Cylinder 9.3 L Diesel Engine, Engine Brake, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 271 in Wheelbase, 208 in Cab to Axle, 315 in Cab to End of Frame Usage: 198,057 Mi Asset located in: Humble, TX		2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV9J4S57961 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10275 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Spring Suspension, 272 in Wheelbase, 206 in Cab to Axle, 283 in Cab to End of Frame
1693	<b>2011 Kenworth T370 4x2 Cab and Chassis</b> S/N: 2NKHHN7X2BM296249		Usage: 284,232 Mi <b>Asset located in</b> : Lake Worth, TX
	C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8574 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Spring Suspension, 229 in Wheelbase, 164 in Cab to Axle, 216 in Cab to End of Frame Usage: 163,110 Mi Asset located in: Lake Worth, TX	1698	2018 Hino 338D 4x2 Cab and Chassis S/N: 5PVNV8JV0J4S58139 C/W: Hino J08E-VB 6 Cylinder Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9483 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 204 in Cab to Axle, 284 in Cab to End of Frame Usage: 301,522 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1699	2018 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JV8J4S68672 C/W: J08E 6 Cylinder 7.6 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6352 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, 205 in Cab to Axle, 319 in Cab to End of Frame Usage: 234,436 Mi	1704 1704A	2011 Kenworth T370 Cab and Chassis S/N: 2NKHLN9X8BM285610 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 300 hp Engine, Engine Brake, Allison 3500 Automatic Transmission, 13200 lb Front Axle, 40000 lb Rears, 252 in Wheelbase, PTO Usage: Not Available Asset located in: Humble, TX
1700	Asset located in: Lake Worth, TX  2014 Freightliner M2 106 4x2 Cab and Chassis		S/N: JALC4W161J7K00299 Usage: Not Available
	S/N: 1FVACXDT6EHFY9046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 7129 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb	1705	Asset located in: Humble, TX  2007 Mack CXP613 Cab and Chassis S/N: 1M1AP02YX7N001530 Usage: Not Available Asset located in: Lake Worth, TX
	GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 270 in Wheelbase, 204 in Cab to Axle, 300 in Cab to End of Frame Usage: 200,956 Mi Asset located in: Lake Worth, TX	1706	2019 Ford F-550 XL 4x4 Extended Cab Cab and Chassis S/N: 1FD0X5HT1KEF25139 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid,
1701	2014 Hino 268 4x2 Cab and Chassis S/N: 5PVNJ8JL5E4S51770 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, 102 in Cab to Axle, 162 in Cab to End of Frame Usage: 263,506 Mi		Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: Not Available Asset located in: Midland, TX
		СНОІСІ	E OF 2 - Lot #'s: 1707, 1708
1700	Asset located in: Lake Worth, TX	1707	2017 Ford F-550 4x4 Extended Cab Cab and
1702	2013 Peterbilt 337 4x2 Cab and Chassis S/N: 2NP2HN7X2DM190208 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel Engine, Requires Diesel Exhaust Fluid, 10775 Engine hrs, Allison 3500 Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, Dana Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Double Frame, Reyco Spring Suspension, 238 in Wheelbase, 168 in Cab to	1767	Chassis  S/N: 1FD0X5HT8HEE59326  C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 86 in Cab to Axle, 128 in Cab to End of Frame Usage: 141,292 Mi
	Axle, 222 in Cab to End of Frame Usage: 204,502 Mi	1700	Asset located in: Lake Worth, TX
1703	Asset located in: Humble, TX  2012 International 7500 Work Star Cab and Chassis  S/N: 1HTWPAZRXCJ641719  C/W: Navistar 6 Cylinder 9.3 L 310 hp Engine, 2011 US EPA Label, Allison Automated Transmission, 14000 lb Front Axle, Air Ride Cab, Air Ride Suspension, 256 in Wheelbase, PTO  Usage: Not Available  Asset located in: Humble, TX		2017 Ford F-550 4x2 Extended Cab Cab and Chassis  S/N: 1FDOX5GT0HEE87879  C/W: Ford Power Stroke 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8271 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 134 in Cab to End of Frame Usage: 204,811 Mi  Asset located in: Lake Worth, TX
1703A	2012 International 4300 Cab and Chassis S/N: 3HAMMAAN5CL562842 Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details	
1709	2016 Ram 5500 4x2 Cab and Chassis S/N: 3C7WRMDL1GG283996 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission,	1714	2006 International 4300 Cab and Chassis S/N: 1HTMMAAM46H186863 Usage: Not Available Asset located in: Lake Worth, TX	
	7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 255/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 204 in Wheelbase, 120 in Cab to Axle, 173 in Cab to End of Frame Usage: 185,092 Mi  Asset located in: Lake Worth, TX	1715	2005 Peterbilt 335 4x2 Cab and Chassis S/N: 2NPLHD6X45M857023 C/W: Cat C7 6 Cylinder 7.2 L Diesel 250 hp Engine, 2006 US EPA Label, 15489 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75822.	
1709A	2012 Ford F-550 4x2 Extended Cab Cab and Chassis  S/N: 1FD0X5GT5CEC83751  C/W: V8 6.7 L Diesel 300 hp Engine, 2012 US		5, Low Air Leaf Suspension, 191 in Wheelbase, PTO, 120 in Cab to Axle, 195 in Cab to End of Frame Usage: 459,210 Mi <b>Asset located in</b> : Lake Worth, TX	
	EPA Label, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 183 in Wheelbase, 80 in Cab to Axle, 130 in Cab to End of Frame Usage: 204,360 Mi Asset located in: Lake Worth, TX	1715A	2007 GMC C7500 4x2 Cab and Chassis S/N: 1GDK7C1C67F900371 C/W: Cat C7 6 Cylinder 7.2 L Diesel 210 hp Engine, 2006 US EPA Label, Automatic Transmission, 8001 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5 Front Tires,	
1710	2012 Chevrolet 3500 4x2 Crew Cab Cab and Chassis S/N: 1GB4CZCL2CF161801 C/W: GM 6.6 L Engine, 2017 US EPA Label,		295/75R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, 192 in Cab to Axle, 228 in Cab to End of Frame Usage: 226,533 Mi <b>Asset located in</b> : Lake Worth, TX	
	Requires Diesel Exhaust Fluid, Automatic Transmission, 5200 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 265/70R17, Spring Suspension, 172 in Wheelbase, 60 in Cab to Axle, 112 in Cab to End of Frame Usage: Not Available  Asset located in: Lake Worth, TX  2009 Peterbilt 335 4x2 Cab and Chassis S/N: 2NPLHN7X19M788656 C/W: Paccar 6 Cylinder Diesel Engine, Engine Brake, Allison 3500 Automatic Transmission, 10000 lb Front Axle, 23000 lb Rears, Dana S23-	1716	1998 Peterbilt 330 4x2 Cab and Chassis S/N: 3BPNHD7X1WF459167 C/W: Cat 3126B 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 274 in	
1711			Wheelbase, PTO, 200 in Cab to Axle, 329 in Cab to End of Frame Usage: 912,630 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Lake Worth, TX	
	170 Drive Axles, 6.14:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, 134 in Cab to Axle, 171 in Cab to End of Frame Usage: 102,359 Mi Asset located in: Humble, TX		1717 1992 Ford LT8000F 6x4 T/A Dump Truck S/N: 1FDYU82A8NVA25956 C/W: Ford 6 Cylinder Diesel Engine, Eator Fuller Manual Transmission, 54600 lb GV 11R24.5 Front Tires, 11R22.5 Rear Tires, Steering Boxes, Hendrickson Spring over Walking Beam Suspension, 236 in Wheell PTO, 17 ft Long x 3 ft High Steel Body, Fla Manual Roll Tarp, Pintle Hitch Usage: 336,571 Mi	C/W: Ford 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 54600 lb GVWR, 11R24.5 Front Tires, 11R22.5 Rear Tires, Dual
1712	2007 Mack CTP713 Cab and Chassis S/N: 1M2AT04Y27M006909 Usage: Not Available Asset located in: Lake Worth, TX			Walking Beam Suspension, 236 in Wheelbase, PTO, 17 ft Long x 3 ft High Steel Body, Flat Bed, Manual Roll Tarp, Pintle Hitch
1713	2007 Hino 258 4x2 Cab and Chassis S/N: 5PVND8JT672S50164 C/W: Hino 6 Cylinder Diesel 220 hp Engine, 2006 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 255 /70R22.5, Spring Suspension, 219 in Wheelbase, 150 in Cab to Axle, 183 in Cab to End of Frame Usage: 329,692 Mi Asset located in: Lake Worth, TX	1718	1990 International 4600 4x2 Cab and Chassis S/N: 1HTSAZRN0MH332118 C/W: International 7.3 L Diesel 155 hp Engine, Steel, 255/70R22.5, Double Frame, Spring Suspension, 152 in Wheelbase, 84 in Cab to Axle, 147 in Cab to End of Frame Usage: 218,680 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
1719	2019 Freightliner M2 106 6x4 Flatbed Truck S/N: 3ALHCYFE7KDKU9146 C/W: Cummins L9 6 Cylinder 8.9 L Diesel 350 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6627 Engine hrs, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.33:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 28 ft x 102 in Bed, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG	1723	2014 Freightliner M2 106 6x4 Flatbed Truck S/N: 1FVHCYCY5EHFV7934 C/W: Cummins ISL9 6 Cylinder Diesel 350 hp Engine, Requires Diesel Exhaust Fluid, 9346 Engine hrs, Allison Automatic Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 274 in Wheelbase, 24 ft x 91 in Bed, Forklift Mount Kit Usage: 158,702 Mi Asset located in: Humble, TX	
	Usage: 288,102 Mi <b>Asset located in</b> : Lake Worth, TX	1724	2019 Isuzu NPR HD 4x2 COE Crew Cab Flatbed Truck	
1720	2014 International 7600 6x4 Flatbed Truck S/N: 1HTGSSJT6EH786752 C/W: International 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Ride Suspension, 261 in Wheelbase, 20 ft	1724B	S/N: 54DC4J1B6KS801218 C/W: 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225/70R19.5, Spring Suspension, 181 in Wheelbase, 19 ft x 93 in Bed, Dovetail, Manual Ramps Usage: 138,503 Mi Asset located in: Lake Worth, TX	
	10 in x 97 in Bed Usage: 323,203 Mi Asset located in: Lake Worth, TX		2007 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAM17H382700 C/W: International DT466 6 Cylinder 7.6 L Diesel 210 hp Engine, 2006 US EPA Label, 7485	
1721	2003 Mack RD688S 6x4 Flatbed Truck S/N: 1M2P267C93M065482 C/W: Mack E7 6 Cylinder Diesel 350 hp Engine, 2002 US EPA Label, 28682 Engine hrs, Eaton Fuller 8LL Manual Transmission, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Camelback Spring Suspension, 252 in		Front Axle, 17500 lb Re 11R22.5, Spring Suspe 18 ft x 92 in Bed, Poly 1 Concrete Mixer, Usage: 238,996 Mi	
	Wheelbase, PTO, 20 ft 6 in x 92 in Bed Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		1725	2006 Hino 268 4x2 Flatbed Truck S/N: 5PVNE8JT462S12363 C/W: Hino 6 Cylinder Diesel Engine, Automatic
1721A	2018 International 4300 4x2 Flatbed Truck S/N: 1HTMMMMMXJH632780 C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11497 Engine hrs, Allison Automatic Transmission, 10000 lb		Transmission, 11R22.5, Spring Suspension, 245 in Wheelbase, 23 ft 8 in x 94 in Bed Usage: 672,876 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT  Asset located in: Humble, TX	
	Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 10R22.5, Spring Suspension, 181 in Wheelbase, 14 ft 5 in x 96 in Bed Usage: 148,134 Mi  Asset located in: Lake Worth, TX	1725A	2004 International 4300 Flatbed Truck S/N: 1HTMMAAL54H662588 Usage: Not Available Asset located in: Humble, TX	
1722	2016 Freightliner M2 106 4x2 Flatbed Truck S/N: 1FVACXDT0GHHR9676 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel	1725B	2007 International 4400 Flatbed Truck S/N: 1HTMRAAL97H464165 Usage: Not Available Asset located in: Humble, TX	
Exhaust Fluid, 13474 Engine hrs, Allison 250 Automatic Transmission, 12000 lb Front Ax 21000 lb Rears, 5.56:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Rid	GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Aluminum Frame, Liftgate Usage: 206,090 Mi	1726	2019 Ford F-750 4x2 Flatbed Truck S/N: 1FDXF7DE5KDF11884 C/W: 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 260 in Wheelbase, 18 ft x 92 in Bed, Pintle Hitch Usage: 34,747 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
CHOIC	E OF 2 - Lot #'s: 1727, 1728	1732	1995 Stewart and Stevenson M1078 COE 4x4 Flatbed Truck S/N: AT0761BEC
1727	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65C79V065767 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2008 US EPA Label, 2379 Engine hrs, Eaton Fuller Automated Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, 13 ft x 94 in Bed, Winch Usage: 14,420 Mi	сноіс	C/W: Allison Automatic Transmission, 395 /85R20, 155 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch, Diesel, Allison Auto, Central Tire Inflation; EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 3,055 Mi Asset located in: Lake Worth, TX  E OF 3 - Lot #'s: 1734, 1735, 1736
	Asset located in: Lake Worth, TX	-	
1728	2009 Ford F-650 XL 4x2 Flatbed Truck S/N: 3FRNF65H89V109657 C/W: Cummins 6 Cylinder Diesel Engine, Automatic Transmission, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 195 in Wheelbase, 8 ft x 96 in Bed Usage: 74,757 Mi	1734	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C12X6F431782 C/W: V8 6.6 L Diesel 300 hp Engine, 2006 US EPA Label, Automatic Transmission, 225 /70R19.5, Spring Suspension, 179 in Wheelbase, 14 ft 4 in x 93 in Bed Usage: 214,436 Mi
	Asset located in: Lake Worth, TX	4707	Asset located in: Lake Worth, TX
СНОІС	E OF 2 - Lot #'s: 1729, 1730	1735	2006 GMC 4500 4x2 Flatbed Truck S/N: 1GDE4C1256F431754 C/W: Chevy V8 6.6 L Diesel Engine, US EPA Label, Allison 4 Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR,
1729	729 2001 Stewart and Stevenson M1078 4x4 Flatbed Truck S/N: 14619G C/W: cat 3126 6 Cylinder 7.2 L Diesel 246 hp Engine, 1999 US EPA Label, Automatic Transmission, 395/85R20, Spring Suspension, 154 in Wheelbase, 12 ft 6 in x 96 in Bed, Diesel, Allison Auto, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 196 Mi Asset located in: Lake Worth, TX		225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 177 in Wheelbase, 14 ft x 92 in Bed, Receiver Usage: 182,782 Mi Asset located in: Lake Worth, TX
		1736	2006 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBE4C1226F434247 C/W: V8 6.6 L Diesel Engine, Allison Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 225/70R19.5, Spring Suspension, 190 in Wheelbase, 13 ft x 96 in
1730	1998 Stewart and Stevenson M1079 4x4 COE Flatbed Truck S/N: V011285EDKG C/W: Cat 6 Cylinder Diesel Engine, Allison Automatic Transmission, 395/85R20, Spring		Bed, Hitch Receiver Usage: 179,635 Mi
		1737	Asset located in: Lake Worth, TX  2023 Ford F-550 4x4 Extended Cab Flatbed
	Suspension, 154 in Wheelbase, 12 ft 6 in x 94 in Bed, Pintle Hitch, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 4,949 Mi		Truck S/N: 1FD0X5HT7PED26877 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1738	2022 Ford F-550 XL 4x4 Flatbed Truck
CHOICE OF 2 - Lot #'s: 1731, 1732		-1/38	S/N: 1FDUF5HT4NEE52440 C/W: power stroke V8 6.7 L Diesel Engine, 2022 US EPA Label, 1589 Engine hrs, Automatic Transmission, 6500 lb Front Axle,
1731	1998 Stewart and Stevenson M1078 4x4 COE Flatbed Truck S/N: AT9310EDEG C/W: Diesel Engine, Automatic Transmission, 395/85R20, Spring Suspension, 152 in Wheelbase, 12 ft 7 in x 96 in Bed, Diesel, Allison Automatic, Central Tire Inflation; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 7,226 Mi Asset located in: Lake Worth, TX		14706 lb Rears, 19500.0 lb GVWR, 225/70R19. 5, Spring Suspension, 169 in Wheelbase, 12 ft x 96 in Bed, Aluminum Frame Usage: 46,064 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
CHOIC	E OF 3 - Lot #'s: 1739, 1740, 1741  2019 Ford F-550 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT9KED42817 Usage: Not Available	1744	2018 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL8JG207251 C/W: Cummins 6.7 L Diesel Engine, 6818 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 194 in Wheelbase
	Asset located in: Lake Worth, TX		Usage: 114,766 Mi  Asset located in: Lake Worth, TX
1740	Truck S/N: 1FD0W5HT5KEF71138 C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, 9 ft 6 in x 56 in Bed, Pintle Hitch Usage: 199,717 Mi Asset located in: Lake Worth, TX	1745	2011 Dodge Ram 5500 4x2 Crew Cab Flatbed Truck (Inoperable)  S/N: 3D6WA7CL0BG612391  C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 196 in Wheelbase, 12 ft x 102 in Bed Usage: Not Available
1741	2019 Ford F-550 XL 4x4 Crew Cab Flatbed	<b>-</b>	Asset located in: Lake Worth, TX
1741	Truck  S/N: 1FD0W5HT9KEF71160  C/W: V8 6.7 L Diesel 330 hp Engine, 2019 US  EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 204 in Wheelbase, 11 ft 4 in x 96 in Bed, Pintle Hitch, EQUIPMENT-FROM- A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available	1746	2017 Ford F-550 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT4HEC85077 C/W: V8 6.7 L 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 187 in Wheelbase, 12 ft x 96 in Bed, Pintle Hitch Usage: 147,936 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1747	2017 Ford F-450 XL 4x4 Crew Cab Flatbed
1742	2018 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT6JEC24738 C/W: 6 Cylinder 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 203 in Wheelbase, 10 ft 6 in x 89 in Bed, Fuel Tank Usage: 160,056 Mi		Truck S/N: 1FD0W4HY8HEC86836 C/W: 6 Cylinder 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 205 in Wheelbase, 11 ft 6 in x 60 in Bed, Fuel Tank, Pintle Hitch Usage: 45,366 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1748	2017 Ford F-550 XL 4x2 Extended Cab Cab and

CHOICE OF 2 - Lot #'s: 1743, 1744

#### 1743 2018 Ram 5500 4x4 Crew Cab Flatbed Truck

S/N: 3C7WRNFL1JG157387 C/W: Cummins ISB6.7 325 6.7 L 325 hp Engine, 2018 US EPA Label, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500.0 lb GVWR, 225/70R19. 5, Spring Suspension, 197 in Wheelbase, 12 ft x 96 in Bed, Fuel Tank /w Pump, Pintle Hitch Usage: 81,063 Mi

Asset located in: Lake Worth, TX

# Chassis

S/N: 1FD0X5GT9HEC48136 C/W: V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 65000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 192 in Wheelbase, 86 in Cab to Axle, 122 in Cab to End of Frame Usage: 131,502 Mi

Lot #	Details	Lot #	Details
1749	749 2016 Ford F-550 XL 4x4 Crew Cab Flatbed Truck  S/N: 1FD0W5HT2GEB95778  C/W: Power Stroke V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft 6 in x 96 in Bed, Liftgate, Rear View Camera; EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 120,695 Mi Asset located in: Lake Worth, TX	1756	2012 Ford F-550 4x2 Extended Cab Flatbed Truck S/N: 1FD0X5GT6CEC35272 Usage: Not Available Asset located in: Lake Worth, TX
		1757	2013 Ford F-450 4x2 Flatbed Truck S/N: 1FDUF4GY5DEA18226 C/W: Ford V10 6.8 L Gasoline Engine, 2012 US EPA Label, 5-Speed Automatic Transmission, 6000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 201 in
1750	2016 Ford F-550 XL 4x4 Extended Cab Flatbed Truck		Wheelbase, 17 ft 5 in x 96 in Bed, Liftgate Usage: 204,057 Mi <b>Asset located in</b> : Lake Worth, TX
	S/N: 1FD0X5HT8GEC75339 C/W: 6.7 L 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8438 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft x 91 in Bed, Fuel Tank Usage: 191,492 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1758	2013 Ford F-450 XL 4x2 Flatbed Truck S/N: 1FDUF4GT4DEB86573 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, Steel, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft x 94 in Bed Usage: 201,329 Mi Asset located in: Lake Worth, TX
	Asset located in: Midland, TX	1759	2011 Ford F-450 XL 4x4 Crew Cab Flatbed
1751	2016 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL3GG329797 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Bunk Beds, 225/70R19. 5, Spring Suspension, 198 in Wheelbase, 12 ft x 55 in Bed, Pintle Hitch Usage: 158,301 Mi Asset located in: Lake Worth, TX		Truck S/N: 1FD0W4HT0BEC98605 C/W: Ford Power Stroke V8 6.7 L Ultra Low Sulfur Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, 8 ft 9 in x 94 in Bed Usage: 290,111 Mi Asset located in: Lake Worth, TX
1753	2015 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT2FEC27629 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft 6 in x 96 in Bed, Receiver, Fifth Wheel ball, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY	1760	2003 Chevrolet C4500 4x2 Flatbed Truck S/N: 1GBC4E1E93F503492 C/W: V8 8.1 L Gasoline Engine, Automatic Transmission, 6000 lb Front Axle, 11000 lb Rears, 16000 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 13 ft 4 in x 97 in Bed Usage: 281,996 Mi Asset located in: Lake Worth, TX
	Usage: 150,132 Mi Notes: . Asset located in: Lake Worth, TX	1761	S/N: 3C7WRTCL3NG365057 C/W: 6.7 L Diesel Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic
1754	2013 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT9DEB58125 C/W: V8 6.7 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 2 in x 88 in Bed Usage: 301,436 Mi Asset located in: Midland, TX		Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; PLEASE SEE DEFICIENCIES, TRANSMISSION IS IN VERY BAD CONDITION Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1762	2021 GMC Sierra 3500HD 4x4 Crew Cab Flatbed Truck  S/N: 1GD49SE76MF148113  C/W: V8 6.6 L Gasoline Engine, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 182 in Wheelbase, 9 ft x 96 in Bed, Fuel Tank /w Pump, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 116,066 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	1767	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck  S/N: 1FD8W3HT3KEF22298  C/W: 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 181 in Wheelbase, 9 ft 6 in x 98 in Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1768	2019 Ford F-350 XL 4x2 Crew Cab Flatbed Truck
1763	2021 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT2MED56469 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1FD8W3G63KEC30873 C/W: V8 6.2 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase,
1764	2022 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3GN1NEC44542 C/W: Ford V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245 /75R17, 9 ft x 93 in Bed Usage: 111,959 Mi		9 ft 5 in x 90 in Bed Usage: 93,217 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		E OF 3 - Lot #'s: 1769, 1770, 1771
CHOICI 1765	Asset located in: Lake Worth, TX  E OF 3 - Lot #'s: 1765, 1766, 1767  2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3G6XLEE32269 C/W: V8 6.2 L Gasoline Engine, 2020 US EPA	2019 US EPA Label, CARB Com Diesel Exhaust Fluid, 5246 Engi Automatic Transmission, 5600 9900 lb Rears, Ford-Factory Dri lb GVWR, Aluminum Wheels, 24 Factory Spring Suspension, 178 9 ft x 98 in Bed, Receiver hitch, Usage: 194,430 Mi  Asset located in: Midland, TX  1770 2019 Ford F-350 4x4 Crew Cab S/N: 1FD8W3HT5KEE24230 C/W: Ford V8 6.7 L Diesel 330 h US EPA Label, Requires Diesel I Automatic Transmission, 5990 10040 lb Rears, 14000 lb GVWF	S/N: 1FT8W3DT6KEG85635 C/W: Ford Power Stroke 6.7 L Diesel Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 5246 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9900 lb Rears, Ford-Factory Drive Axles, 14000 lb GVWR, Aluminum Wheels, 245/75R17, Ford- Factory Spring Suspension, 178 in Wheelbase, 9 ft x 98 in Bed, Receiver hitch, Fifth wheel ball
	Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 265 /70R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 90 in Bed Usage: 121,378 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2019 Ford F-350 4x4 Crew Cab Flatbed Truck
1766	2020 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT5LED87360	-	in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 134,504 Mi <b>Asset located in</b> : Lake Worth, TX
	C/W: V8 6.7 L Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 10400 lb Rears, 14000 lb GVWR, 245:75R17, Spring Suspension, 181 in Wheelbase, 108 m x	1771	2019 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT6KEG06521 Usage: Not Available Asset located in: Midland, TX
	89 in Bed Usage: 115,425 Mi <b>Asset located in</b> : Lake Worth, TX	1772	2018 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT7JEC67900 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1773	2019 Ford F-550 XL 4x2 Flatbed Truck S/N: 1FDUF5GT6KDA03912 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid,	CHOICE	E OF 2 - Lot #'s: 1778, 1779
	5452 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13660 lb Rears, 18000 lb GVWR, 245/70R19.5, Spring Suspension, 169 in Wheelbase, 11 ft 6 in x 96 in Bed Usage: 176,902 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1778	2018 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL7JG325302 C/W: Cumins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 640 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80/17, Spring
1774	Asset located in: Humble, TX  2018 Ford F-350 XL 4x4 Crew Cab Flatbed		Suspension, 174 in Wheelbase, 9 ft 4 in x 96 in Bed Usage: 90,276 Mi
.,,,	Truck		Asset located in: Lake Worth, TX
	S/N: 1FD8W3HT5JEC95579 C/W: V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 8284 Engine hrs, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 3 in x 98 in Bed Usage: 221,150 Mi Asset located in: Humble, TX	1779	2017 Ram 3500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRTCL9HG759022 C/W: 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 173 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 382,795 Mi
1775	2017 Ford F-350 4x4 Crew Cab Flatbed Truck		Asset located in: Midland, TX
	S/N: 1FD8W3H6XHEE85592 Usage: Not Available	1780	2019 GMC Sierra 3500HD 4x4 Crew Cab
	Asset located in: Lake Worth, TX		Flatbed Truck S/N: 1GD42TCG9KF236339
1776	6 2017 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H62HEE73498 C/W: Ford V8 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 10040 lb Rears, 14000.0 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 92 in Bed, Pintle Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 119,438 Mi		C/W: V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9375 lb Rears, 13025 lb GVWR, 265 /70R17, Spring Suspension, 168 in Wheelbase, 8 ft x 92 in Bed, Fuel Tank Usage: 112,708 Mi  Notes: NOT ACTUAL MILEAGE  Asset located in: Lake Worth, TX
		1780A	2019 GMC 3500HD 4x4 Crew Cab Flatbed Truck
1777	Asset located in: Lake Worth, TX  2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT6GEA98185 C/W: Ford V8 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, 11342 Engine hrs, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 265/70R17, Spring Suspension, 176 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 279,994 Mi Asset located in: Lake Worth, TX		S/N: 1GB4KVCG5KF127400 C/W: V8 6.0 L Gasoline Engine, 11709 Engine hrs, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Spring Suspension, 171 in Wheelbase, 9 ft 4 in x 93 in Bed Usage: 178,678 Mi Asset located in: Lake Worth, TX
		1781	Truck S/N: 1GB3KYCY1HF207209 C/W: GM Duramax 6.6 L Diesel Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Exhaust Brake, Allison Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 163 in Wheelbase, 11 ft 4 in x 98 in Bed, Aluminum/Steel Combination Frame, Better Built 100 Gallons Fuel Tank /w Pump Usage: 100,497 Mi Asset located in: Midland, TX

Lot #	Details	Lot #	Details	
CHOICI	CHOICE OF 2 - Lot #'s: 1782, 1783		2011 Ford F-250 4x4 Crew Cab Flatbed Truck S/N: 1FT7W2B6XBED03559 C/W: Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 4800 lb Front Axle,	
1782	2017 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY3HF162424 C/W: Duramax 6.6 L Diesel Engine, Automatic Transmission, 9 ft 4 in Bed		6100 lb Rears, 10000 lb GVWR, 245/75R17, Spring Suspension, 154 in Wheelbase, 7 ft x 84 in Bed Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: 113,083 Mi Asset located in: Lake Worth, TX	1788A	2011 Ford F-250 4x2 Flatbed Truck S/N: 1FTBF2A67BEC16567	
1783	2017 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY0HF162509 C/W: Duramax 6.6 L Diesel Engine, Automatic Transmission, 9 ft 4 in Bed Usage: 113,384 Mi Asset located in: Lake Worth, TX		C/W: Ford V8 6.2 L Gasoline Engine, US EPA Label, Automatic Transmission, 3950 lb Front Axle, 9800 lb Rears, 9800 lb GVWR, LT245 /75R17, Spring Suspension, 136 in Wheelbase, 8 ft 3 in x 79 in Bed, Receiver, Fifth wheel ball Usage: 318,291 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	
1784	2012 Dodge Ram 3500 Flatbed Truck		PROCESS TITLE	
	S/N: 3C7WDSCLXCG193793 Usage: 329,146 Mi	1700	Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	1789	2015 Chevrolet Silverado 1500 4X4 Crew Cab Flatbed Truck	
1785	2011 Chevrolet 3500 HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4K1CL3BF151507 C/W: General Motors V8 6.6 L Diesel Engine, 2011 US EPA Label, Automatic Transmission, 245/70R17, Spring Suspension, 175 in Wheelbase, 8 ft 6 in x 84 in Bed, Better Built 50 gallons Fuel Tank Usage: Not Available		C/W: V8 6.6 L Diesel Engine, 2015 Label, Requires Diesel Exhaust Flu Automatic Transmission, 5600 lb 9750 lb Rears, 13200 lb GVWR, 23	Usage: 61,854 Mi
	Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; Asset located in: Lake Worth, TX	1790	2015 Chevrolet Silverado 1500 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYC84FF512267	
1786	2017 Ford F-250 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD7W2B67HED35955 C/W: Ford V8 6.2 L Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 6340 lb Rears, 10000.0 lb GVWR, 285/70R17, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in		C/W: V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 174 in Wheelbase, 9 ft 6 in x 87 in Bed Usage: 117,117 Mi  Asset located in: Lake Worth, TX	
	Bed, Fuel Tank /w Pump Usage: 105,808 Mi <b>Notes</b> : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS <b>Asset located in</b> : Lake Worth, TX	1791	1971 Ford F100 4x2 Flatbed Truck S/N: F10YRM02564 C/W: V8 Gasoline Engine, Automatic Transmission, 4500 lb GVWR, 7.00-15, Spring Suspension, 131 in Wheelbase, 8 ft x 78 in Bed,	
1787	2015 Ford F-250 XL 4x2 Crew Cab Flatbed Truck S/N: 1FT7W2AT3FEB68857 C/W: V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 6100 lb Rears, 10000 lb GVWR, 265/70R17, Spring Suspension, 171 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 288,298 Mi		Ingersoll-Rand T30 Air Co EQUIPMENT-FROM-YELL Usage: Not Available <b>Notes</b> : CANNOT VERIFY ( VEHICLE IS EXEMPT FRO DISCLOSURE;TEXAS BUY OFFICE TO SIGN REQUIRI PROCESS TITLE	Pintle Hitch, Goodall Start-All Jumpstart Pack, Ingersoll-Rand T30 Air Compressor; EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available  Notes: CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	1792	2019 Western Star Car Carrier Truck S/N: 2WKDD40X2KF369099 Usage: Not Available Asset located in: Lake Worth, TX	

			1 age 107 01 300
Lot #	Details	Lot #	Details
1793	2012 Peterbilt 388 T/A Sleeper Car Carrier Truck S/N: 1NPWD49X3CD134979 Usage: Not Available Asset located in: Lake Worth, TX	1798	2014 Kenworth T440 6x4 Dump Truck S/N: 1NKBLJ9X0EJ389440 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fulle 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Ai
1794	2012 Peterbilt 388 6x4 Sleeper Car Carrier Truck  S/N: 1NPWD49X2CD134987  C/W: Cummins ISX15 6 Cylinder 15.0 L 525 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 44842 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 58 in Flat Top Sleeper Cab, Aluminum Wheels, 295/60R22.5 Front Tires, 255/70R22.5 Rear Tires, Low Low Air Leaf Air Ride Suspension, 264 in Wheelbase, PTO, Hydraulic Lift, Soft Tie Downs, SOLD WITH - Cottrell CX-11HCSI T/A, Trailer S/N - 5E0AJ144XCG335301, Soft Ties, Aluminum Wheels, 225/70R22.5 Tires Usage: 1,087,566 Mi  Asset located in: Lake Worth, TX		Ride Cab, Aluminum Wheels, 11R22.5, 2 Steerable Air Lift Pusher Axle, Spring Suspension, 233 in Wheelbase, PTO, OX Bodies 17 ft 9 in Long x 4 ft 3 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 376,489 Mi  Asset located in: Humble, TX  2014 Freightliner 114SD 8x4 Tri/A Dump Truck S/N: 3AKJG3DV2EDGA1049 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller RTO-16908LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Steerable Air Lift Pusher Axle, Airliner Air Ride Suspension, 202 in Wheelbase, 16 ft 5 in Long x 2 ft 6 in High Steel Body, Electric Roll Tarp
1796	2012 Kenworth T800 14x4 Five Axle Dump Truck	1800	Usage: 525,886 Mi  Asset located in: Lake Worth, TX
	S/N: 1NKDL40X0CJ335866 C/W: Cummins 6 Cylinder 15 L Diesel 248 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 24448.6 Engine hrs, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.91:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, PTO, 14 ft 8 in Long x 5 ft 8 in High Steel Body, Electric Roll Tarp Usage: 259,946 Mi Asset located in: Lake Worth, TX		2015 Freightliner Cascadia 113 8x4 Tri/A  Dump Truck  S/N: 1FUJGHDVXFLGF1087  C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Airliner Air Ride Suspension, 207 in Wheelbase, PTO, 16 ft 8 in Long x 4 ft 3 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 816,761 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE
1797	2012 Freightliner Cascadia 125 10x4 Quad/A Dump Truck		THE INSPECTION REPORT  Asset located in: Humble, TX
	S/N: 1FUJGEDV2CSBM1515 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Dana DS404 Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5, Steerable Air Lift Tag Axle, Double Frame, Airliner Air Ride Suspension, 312 mm Wheelbase, PTO, 21 ft Long x 4 ft High Steel Body, Manual Roll Tarp Usage: 520,916 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1801	2007 Sterling LT9500 8x4 Tri/A Dump Truck S/N: 2FZMAZCV87AX38981 C/W: Mercedes-Benz MBE4000 6 Cylinder 12.8 L Diesel Engine, 2006 US EPA Label, Engine Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 20000 lb Front Axle, 66000 lb Rears, 86000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 202 in Wheelbase, PTO, OX Bodies 16 ft Long x 4 ft High Steel Body, Flat Bed, Electric Roll Tarp, Pintle Hitch Usage: 528,890 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1802	2003 Mack CHU613 8x4 Tri/A Dump Truck S/N: 1M1AA12Y23W149926 C/W: 6 Cylinder Diesel Engine, 22935 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Lift Pusher Axle, Air Ride Suspension, 196 in Wheelbase, PTO, 16 ft 5 in Long x 5 ft 6 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 706,035 Mi Asset located in: Humble, TX	1807	2013 Cat CT660S 6x4 T/A Dump Truck S/N: 1HSJGTKR3DJ301284 C/W: Cat CT13 13 L Diesel Engine, 23623 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Air Ride Suspension, 199 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Bed Vibrator, Electric Roll Tarp, High-Lift Tailgate Usage: 250,468 Mi Asset located in: Lake Worth, TX
1803	1999 Mack RD600 8x4 Tri/A Dump Truck S/N: 1M2P270C4XM046117 C/W: Mack E7 6 Cylinder 11.9 L Diesel 400 hp Engine, 1999 US EPA Label, 34470 Engine hrs, Manual Transmission, Aluminum Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Camelback Spring Suspension, 234 in Wheelbase, PTO, 16 ft Long x 3 ft 2 in High Steel Body, Flat Bed, Electric Roll Tarp, Split Swing Tailgate, Pintle Hitch Usage: 654,884 Mi Asset located in: Lake Worth, TX	1808	2012 International 7500 6x4 T/A Dump Truck S/N: 1HTWNAZR5CJ587087 C/W: International MaxxForce 10 6 Cylinder 9.3 L Diesel 310 hp Engine, 2011 US EPA Label, 7272 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Hendrickson Haulmaax Suspension, 171 in Wheelbase, PTO, Warren 13 ft Long x 4 ft High Steel Body, 14 cyd, Capacity Usage: 157,181 Mi Asset located in: Lake Worth, TX
1804	2015 Peterbilt 365 6x4 T/A Dump Truck S/N: 1XPSD79X9FD262718 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, 14 ft Long x 4 ft 3 in High Steel Body, Electric Roll Tarp Usage: 598,800 Mi Asset located in: Humble, TX  2018 Kenworth T370 T/A Dump Truck	1809	2006 International 7600 6x4 T/A Dump Truck S/N: 1HTWYAHT76J239980 C/W: 6 Cylinder Diesel Engine, Engine Brake, Automated Transmission, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, 18 ft Long x 6 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 1,054,079 Km Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1806	S/N: 2NKHHM7X3JM183693 Usage: Not Available Asset located in: Lake Worth, TX 2016 Volvo VHD 8x4 T/A Dump Truck	1811	Asset located in: Humble, TX  2005 Mack CH613 T/A Dump Truck  S/N: 1M2AA18Y65N157393  Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 4V5KC9EH4GN923100 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Volvo Automatic Transmission, Differential Lock, 20000 lb Front Axle, 40000 lb Rears, 53500 lb GVWR, Air Ride	1812	2002 Volvo VHD T/A Dump Truck S/N: 4V5K99GH02N332959 Usage: Not Available Asset located in: Lake Worth, TX
	Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, 286 in Wheelbase, PTO, Strong Inc. 16 ft 0 in Long x 4 ft 8 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 408,393 Mi  Asset located in: Lake Worth, TX	1813	2000 International 8100 6x4 T/A Dump Truck S/N: 1HTHCADR0YH332934 C/W: International Diesel Engine, Manual Transmission, 11R22.5, 179 in Wheelbase, 13 ft Long x 4 ft High Steel Body, Electric Roll Tarp Usage: 258,544 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1814 1814A	1998 Mack CH613 6x4 T/A Dump Truck S/N: 1M2AA18Y6WW094985 C/W: Mack E7 6 Cylinder Diesel 427 hp Engine, 1999 US EPA Label, 20507 Engine hrs, Mack 13-Speed Manual Transmission, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Double Frame, Camelback Suspension, 216 in Wheelbase, PTO, Warren 15 ft Long x 3 ft 6 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 37,076 Mi Asset located in: Lake Worth, TX  1998 Freightliner FLD 120 6x4 T/A Dump Truck	1818	2016 Freightliner M2 106 4x2 S/A Dump Truck S/N: 1FVACXDU3GHGZ0167 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 152 in Wheelbase, PTO, Ledwell 10 ft Long x 3 ft High Body, Manual Roll Tarp, Double Tailgate Chutes Usage: 33,240 Mi Asset located in: Lake Worth, TX
10144	S/N: 1FUYDCYB2WP980791 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 370 hp Engine, 1998 US EPA Label, Engine Brake, Eaton Fuller RTLO-14610B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 192 in Wheelbase, PTO, OX Bodies 14 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Manual Roll Tarp, Ball hitch Usage: 864,969 Mi Asset located in: Midland, TX	1819	2013 Kenworth T300 4x2 S/A Dump Truck S/N: 2NKHHM7XXDM348014 C/W: Paccar PX6 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 6897 Engine hrs, Engine Brake, Allison 6-Speed Automatic Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, Dana Drive Axles, 6.17:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 178 in Wheelbase, 12 ft Long x 0 ft 32 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 96,126 Mi Asset located in: Lake Worth, TX
1815	1996 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUYDDYB6TH854798 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Rockwell 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 210 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 8 in High Body, Electric Roll Tarp, Pintle Hitch Usage: 647,766 Mi Asset located in: Lake Worth, TX	1820	2008 International 4300 4x2 S/A Dump Truck S/N: 1HTMMAAN28J688226 C/W: International 6 Cylinder Diesel Engine, 2007 US EPA Label, 8057 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 19000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 153 in Wheelbase, PTO, 8 ft Long x 3 ft High Steel Body, Manual Roll Tarp, Pintle Hitch Usage: 188,392 Mi Asset located in: Lake Worth, TX
1816	1991 International 2574 6x4 T/A Dump Truck S/N: 1HSGGGRRXMH360976 C/W: Cummins NTC-350 6 Cylinder 14.0 L Diesel 350 hp Engine, Eaton Fuller 13-Speed Manual Transmission, Aluminum Front Wheels, 11R24.5, Double Frame, Hendrickson RT/RTE Series Suspension, 197 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Body, Manual Roll Tarp Usage: Not Available Asset located in: Lake Worth, TX	1821	2005 Ford F-750 XL 4x2 S/A Dump Truck S/N: 3FRNF75Y05V169058 C/W: International V8 6.0 L Diesel 200 hp Engine, 2004 US EPA Label, Allison Automatic Transmission, 9080 lb Front Axle, 17200 lb Rears, 25999 lb GVWR, 10R22.5, Spring Suspension, 158 in Wheelbase, PTO, Heil 10 ft Long x 3 ft 8 in High Body, Manual Roll Tarp, Pintle Hitch Usage: 52,237 Mi Asset located in: Lake Worth, TX
1817	1981 Kenworth W900 6x4 T/A Dump Truck S/N: 1XKWDB9X3BK188647 C/W: Cat 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller RTO12513 Manual Transmission, 10600 lb Front Axle, 38000 lb Rears, 4.11:1 Axle Ratio, 48600 lb GVWR, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Galion 14 ft Long x 4 ft High Steel Body, Manual Roll Tarp Usage: 316,268 Mi Asset located in: Lake Worth, TX	1821A	2012 Ford F-450 XL 4x4 Crew Cab Dump Truck S/N: 1FD0W4HTXCEB65433 C/W: Ford V8 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft Long x 1 ft 3 in High Body, Pintle Hitch Usage: 188,303 Mi Asset located in: Lake Worth, TX
		1821B	2017 International 4300 Flatbed Dump Truck S/N: 3HAMMMMN4HL489029 Usage: Not Available

## **Details** Lot # **Details** Lot # 1821C 2015 International 4300 4x2 Flatbed Dump Truck CHOICE OF 4 - Lot #'s: 1825, 1826, 1827, 1828 S/N: 3HAMMAAN7FL683988 C/W: 6 Cylinder 7.6 L Diesel 230 hp Engine, 2014 US EPA Label, 8701 Engine hrs, Manual 1825 Altec AA55 56 ft on 2017 International 4300 Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Steel, 11R22.5, Spring 4x2 Bucket Truck S/N: 1HTMMMMN2HH474504 Suspension, 238 in Wheelbase, PTO, OX Bodies C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low 20 ft Long Steel Body Sulfur Diesel 260 hp Engine, 2016 US EPA Usage: 269,403 Mi Label, Requires Diesel Exhaust Fluid, 9996 Asset located in: Lake Worth, TX Engine hrs. Allison Automatic Transmission. 13000 lb Front Axle, 20000 lb Rears, 33000 lb 1822 Altec on 2016 Freightliner M2 106 4x2 Digger GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, Derrick Truck 700 lb Capacity, Rear Mounted, Two-Person S/N: 1FVACXDT4GHHL5754 Articulated Boom, Utility Body, Material C/W: Cummins 6 Cylinder Ultra Low Sulfur Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Diesel 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5611 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Usage: 65,169 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 46 ft Sheave Height, Rear Mounted, 18 in THE INSPECTION REPORT Asset located in: Humble, TX Auger, Pole Guide, Auxiliary Hydraulics, One-Man Basket, 14 ft 6 in Body, Straight Down 1826 2017 Altec AA55 56 ft on 2017 International Outriggers, Rear Outriggers 4300 4x2 Bucket Truck Usage: 75,001 Mi S/N: 1HTMMMMNXHH161930 Asset located in: Lake Worth, TX C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA 1823 2017 Altec DB37 Tracked Digger Derrick Label, Requires Diesel Exhaust Fluid, 8422 S/N: 0817FT1063 Engine hrs, Allison Automatic Transmission, C/W: Kubota 3 Cylinder Diesel Engine, 3800 lb Capacity, 30 ft Reach, 18 in Auger, Pole Guide, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Auxiliary Hydraulics, Remote Control w/ Cord, Spring Suspension, 193 in Wheelbase, PTO, 12 in Rubber Tracks, T/A Trailer, Lunette Ring, 700 lb Capacity, Rear Mounted, Two-Person Electric Brakes Boom, Utility Body, Material Handling Jib, A-Usage: 368 Hr Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Asset located in: Lake Worth, TX Pintle Hitch Usage: 72,652 Mi 1824 2017 Altec L42M 42 ft on 2017 Freightliner M2 Notes: DEFICIENCIES NOTED - PLEASE SEE 106 4x2 Bucket Truck THE INSPECTION REPORT S/N: 3ALACXDT9HDJE9096 Asset located in: Humble, TX C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 hp Engine, 2017 US EPA Label, Requires Diesel 1827 2016 Altec AA55 56 ft on 2017 International Exhaust Fluid, 8165 Engine hrs, Allison 3500 4300 4x2 Bucket Truck Automatic Transmission, 13000 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb S/N: 1HTMMMMNXHH474542

GVWR, 11R22.5, 154 in Wheelbase, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Material Handling Jib, A-Outriggers, Rear Outriggers, 12 ft 6 in x 48 in Bed, Pintle Hitch Usage: 137,691 Mi

Asset located in: Lake Worth, TX

C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11175 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, 700 lb Capacity, Rear Mounted, Insulated One-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 16 ft 3 in x 94 in Bed, Pintle Hitch Usage: 76,773 Mi

Lot #	Details	Lot #	Details
1828	2016 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN3HH161820 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8357 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 196 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed Usage: 82,950 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1832 CHOIC	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck  S/N: 1HTMMMMN3HH474544  C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8552 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 16 ft x 94 in Bed, Pintle Hitch Usage: 80,587 Mi  Asset located in: Lake Worth, TX
СНОІС	E OF 4 - Lot #'s: 1829, 1830, 1831, 1832	1833	2016 Altec AA55 56 ft on 2017 International
1829	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN0HH474565 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 7992 Engine hrs, Allison Automatic Transmission, 11R22.5, 192 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 61,145 Mi		4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH452529 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 13023 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 96 in Bed, Pintle Hitch Usage: 133,654 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1834	2017 Altec AA55 56 ft on 2017 International
1830	2017 Altec AA55 55 ft on 2017 International 4300 4x2 Bucket Truck  S/N: 1HTMMMMN5HH161964  C/W: Cummins ISB 6 Cylinder 6.7 L 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8818 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 194 in Wheelbase, PTO, 700 lb Capacity, Center Mounted, Insulated Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 92 in Bed, Pintle Hitch Usage: 53,675 Mi Asset located in: Lake Worth, TX		4300 4x2 Bucket Truck  S/N: 1HTMMMMN0HH161936  C/W: Cummins 6 Cylinder 6.7 L Ultra Low  Sulfur Diesel 260 hp Engine, 2016 US EPA  Label, CARB Compliant, Requires Diesel  Exhaust Fluid, 8428 Engine hrs, Allison  Automatic Transmission, 13000 lb Front Axle, 66000 lb Rears, 11R22.5, 194 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulating-Telescopic Boom, Utility Body, A-Outriggers, Rear Outriggers, Remote Control w/Cord, 16 ft x 60 in Bed, Pintle Hitch Usage: 89,264 Mi  Asset located in: Lake Worth, TX
1831	2016 Altec AA55 56 ft on 2017 International	1835	2016 Altec AA55 55 ft on 2017 International
1001	4300 4x2 Bucket Truck S/N: 1HTMMMMNXHH474556 C/W: Cummins Engine, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 330000 lb GVWR, 11R22.5, PTO, 700 lb Capacity, Center Mounted, Insulated Two- Person Articulated Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Rear Outriggers, Pintle Hitch Usage: 76,812 Mi Asset located in: Lake Worth, TX		4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH474515 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 260 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8241 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, A-Outriggers, Rear Outriggers, 17 ft x 96 in Bed, Pintle Hitch Usage: 65,063 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1836	2012 Altec AA755 55 ft on 2013 Freightliner 4x4 Bucket Truck S/N: 1FVDCXDTXDHBY0785 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 10422 Engine hrs, Eaton Fuller 6- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MS-21-14X Drive Axles, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Spring Suspension, 190 in Wheelbase, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Winch, Pintle Hitch Usage: 66,347 Mi Asset located in: Lake Worth, TX	1840	2012 Altec LRV55 55 ft on 2011 Freightliner M2 106 4x2 Forestry Bucket Truck S/N: 1FVACXDU3BDAU8449 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2009 US EPA Label, Requires Diesel Exhaust Fluid, 15196 Engine hrs, Eaton Fuller FS-6406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 21-145 Drive Axles, 4.88:1 Axle Ratio, 33000 lb GVWR, Steel, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 187 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating- Telescopic Boom, Chip Body, A-Outriggers, 11 ft x 92 in Bed Usage: 84,033 Mi Notes: ODOMETER DISCREPANCY-UNIT
1837	Exhaust Fluid, 7733 Engine hrs, Eaton Fuller EH- 8EX06A Automated Transmission, Differential Lock, 13220 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 6.14:1 Axle		SHOWS 84,033, TITLE SHOWS 999,999 , TITLE BRANDED NOT ACTUAL MILEAGE <b>Asset located in</b> : Lake Worth, TX
		1841	2006 International 4300 Bucket Truck S/N: 1HTMMAAL16H341098 Usage: Not Available Asset located in: Humble, TX
		1842	2005 GMC C8500 Bucket Truck S/N: 1GDP8C1C75F512565 Usage: Not Available Asset located in: Humble, TX
	Outriggers, 9 ft x 94 in Bed, Pintle Hitch Usage: 95,253 Mi	1843	Versalift on 1999 Ford F-450 4x2 Crew Cab Bucket Truck
CHOICI	Asset located in: Lake Worth, TX  HOICE OF 2 - Lot #'s: 1838, 1839  2019 Altec AT41M 41 ft on 2019 Ford F-550 XL 4x2 Bucket Truck		S/N: 1FDXW46F9XEA93643 C/W: V8 Diesel Engine, Automatic Transmission, 5790 lb Front Axle, 10880 lb Rears, 15000 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Center Mounted, Insulated One-Person Articulating- Telescopic Boom, Utility Body, Out and Down Outriggers, 13 ft 9 in x 96 in Bed
	S/N: 1FDUF5GTXKED88465 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019		Usage: 143,468 Mi  Asset located in: Lake Worth, TX
	US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, 400 lb Capacity, Front Mounted, Insulated One-Person Articulating-Telescopic Boom, Utility Body, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 94 in Bed Usage: 190,407 Mi  Asset located in: Lake Worth, TX	1844	2011 Ford F-550 XL 4x2 Chipper Truck S/N: 1FDUF5GT2BEB53610 C/W: 6 Cylinder 6.7 L 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14704 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, 11 ft x x 78 in High Body, Pintle Hitch Usage: 101,174 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1839	2019 Altec AT41M 40 ft on 2019 Ford F-550 4x2 Bucket Truck		THE INSPECTION REPORT  Asset located in: Humble, TX
	S/N: 1FDUF5GT7KED57111 C/W: Ford V8 6.7 L 330 hp Engine, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 lb Front Axle, 19500 lb GVWR, 225/70R19.5, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulating-Telescopic Boom, Material Handling Jib, Straight Down Outriggers, Bumper Mounted Winch, 13 ft 6 in x 96 in Bed Usage: 149,980 Mi Asset located in: Lake Worth, TX	1845	2017 Putzmeister BSF42-5.16H on 2018 Mack MRU613 8x6 Concrete Pump Truck S/N: 1M2AV04C0JM018451 C/W: Mack 6 Cylinder Engine, Manual Transmission, 20000 lb Front Axle, 23000 lb Rears, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, Hydraulic System, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 72,820 Mi Asset located in: Humble, TX

			C
Lot #	Details	Lot #	Details
1846	2009 Peterbilt 340 6x4 Volumetric Mixer Truck S/N: 2NPRLN0X69M771130 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 315 hp Engine, 2008 US EPA Label, 15485 Engine hrs, Eaton Fuller RTO-11908LL 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, Dana D46-170HP Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring over Walking Beam Suspension, 240 in Wheelbase, PTO, 2008 Cemen Tech MCD8-130 8 cyd Mixer Unit Usage: 141,364 Mi	1850	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJM2090 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 12913 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 238 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 107,793 Mi Asset located in: Lake Worth, TX
1847	Asset located in: Lake Worth, TX  2005 Mack CV713 8x4 Volumetric Mixer Truck S/N: 1M2AG11C65M015628 C/W: Mack 6 Cylinder Diesel Engine, 12565 Engine hrs, Engine Brake, Manual Transmission, 16540 lb Front Axle, 44000 lb Rears, 60540 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24. 5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Camelback Spring Suspension, 252 in Wheelbase, PTO, 2005 Cemen Tech	CHOICE 1851	E OF 3 - Lot #'s: 1851, 1852, 1853  2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV0JDJM2089 C/W: DD13, Allison 4500 Automatic, 11 Yard Beck Mixer Usage: 175,338 Mi Asset located in: Lake Worth, TX
	MCD10-150 Mixer Unit Usage: 265,336 Mi <b>Asset located in</b> : Lake Worth, TX	1852	852 2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJM2087 C/W: Detroit 6 Cylinder Diesel Engine, Require
1848	2004 Kenworth T800 8x4 Volumetric Mixer Truck  S/N: 1NKDXUTX94J051508  C/W: Cat C12 6 Cylinder 11.9 L Diesel 380 hp Engine, 2003 US EPA Label, 13738 Engine hrs, Eaton Fuller 8LL Manual Transmission, 4.33:1 Axle Ratio, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson RT/RTE Series Suspension, 224 in Wheelbase, PTO Usage: 52,449 Mi		Diesel Exhaust Fluid, 13808 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 176,719 Mi  Asset located in: Lake Worth, TX
		1853	2018 Freightliner 114SD 10x4 Mixer Truck

CHOICE OF 2 - Lot #'s: 1849, 1850

## 1849 2018 Freightliner 114 SD 10x4 Mixer Truck

Asset located in: Lake Worth, TX

S/N: 3ALHG3DV5JDJL7485 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14464 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes

Usage: 51,410 Mi

Asset located in: Lake Worth, TX

## 853 2018 Freightliner 114SD 10x4 Mixer Truck

S/N: 3ALHG3DV9JDJM2088 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14895 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, 11 cyd Mixer Unit, 3 Removable Chutes

Usage: 198,768 Mi

			Page 176 of 566
Lot #	Details	Lot #	Details
CHOICE OF 3 - Lot #'s: 1854, 1855, 1856		сноіс	E OF 2 - Lot #'s: 1857, 1858
1854	2018 Freightliner 114SD 10x4 Mixer Truck S/N: 3ALHG3DV7JDJL7486 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17360 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 205,429 Mi	1857	2014 Kenworth W900 8x4 Mixer Truck S/N: 1NKWL70X3EJ387392 C/W: Cummins 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 3 Removable Chutes Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1858	2014 Kenworth W900 8x4 Mixer Truck
1855	2018 Freightliner 114 SD 10x4 Mixer Truck S/N: 3ALHG3DV3JDJL7484 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, Double Frame, TufTrac Suspension, 248 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes Usage: 208,663 Mi Asset located in: Lake Worth, TX		S/N: 1NKWL70X1EJ387391 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17553 Engine hrs, Allison 4500 Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 66000 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Trailing Tag Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 250 in Wheelbase, PTO, 2 Removable Chutes, Remote Control w/Cord Usage: 182,221 Mi Asset located in: Lake Worth, TX
1856	2018 Freightliner 114SD 10x4 Mixer Truck		
	S/N: 3ALHG3DV0JDJM2092 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15416 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Trailing Tag Axle, Dual Steering Boxes, TufTrac Suspension, 248 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 184,716 Mi  Asset located in: Lake Worth, TX	1859	2019 Freightliner 114 SD 6x4 T/A Mixer Truck S/N: 1FVHG3DV5KHJS0956 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automated Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 234 in Wheelbase, PTO, Hydraulic System, Beck Mixer Unit, 3 Removable Chutes, Remote Control w /Cord, DD13, Allison 4500 Automatic, Beck

Unit, 3 Removable Chutes, Remote Control w /Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote Usage: 133,211 Mi

## **Details** Lot# **Details** Lot # 1860 1863 2019 Freightliner 114SD 6x4 Mixer Truck 2018 Freightliner 114 SD 6x4 T/A Mixer Truck S/N: 1FVHG3DV7KHJS0957 S/N: 3ALHG3DVXJDJW4875 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15048 Engine hrs, Engine Brake, Exhaust Fluid, 14693 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Allison 4500 Automatic Transmission, Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 232 in Wheelbase, 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord PTO, Hydraulic System, Beck Mixer Unit, 3 Removable Chutes, Remote Control w/Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Usage: 147,480 Mi Asset located in: Lake Worth, TX Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, 1861 2019 Freightliner 114 SD 6x4 Mixer Truck Remote Usage: 159,856 Mi S/N: 1FVHG3DV9KHKF4834 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Asset located in: Lake Worth, TX hp Engine, 2018 US EPA Label, CARB 1864 2018 Freightliner 114 SD 6x4 T/A Mixer Truck Compliant, Requires Diesel Exhaust Fluid, 14290 Engine hrs, Allison Automatic S/N: 3ALHG3DV6JDJW4873 Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16397 Engine hrs, Engine Brake, Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, TufTrac Suspension, 232 in Wheelbase, PTO, Allison 4500 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb 10.5 cyd Mixer Unit, 3 Removable Chutes, Rears, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Remote Control w/Cord Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Hydraulic System, Usage: 167,132 Mi Asset located in: Lake Worth, TX Beck Mixer Unit, 3 Removable Chutes, Remote Control w/Cord, DD13, Allison 4500 Automatic, CHOICE OF 3 - Lot #'s: 1862, 1863, 1864 Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote Usage: 171,963 Mi 1862 2018 Freightliner 114 SD 6x4 T/A Mixer Truck Asset located in: Lake Worth, TX S/N: 3ALHG3DV4JDJW4872 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13917 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, CHOICE OF 3 - Lot #'s: 1865, 1866, 1867 Differential Lock, 22000 lb Front Axle, 46000 lb 1865 2018 Freightliner 114 SD T/A Mixer Truck Rears, 4.56:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering S/N: 3ALHG3DV8JDJW4874 C/W: DD13, Allison 4500 Automatic, Beck 10.5 Boxes, Rubber over Walking Beam Suspension, 234 in Wheelbase, PTO, Hydraulic System, Yard Mixer Unit, 20,000 Lb Front, 46,000 Lb Rears, Remote Beck Mixer Unit, 3 Removable Chutes, Remote Control w/Cord, DD13, Allison 4500 Automatic, Beck 10.5 Yard Mixer Unit, 20,000 Lb Front, Usage: 174,579 Mi Asset located in: Lake Worth, TX 46,000 Lb Rears, Remote 1866 2018 Freightliner 114 SD 6x4 Mixer Truck Usage: 143,981 Mi S/N: 3ALHG3DV1JDJW4876 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Asset located in: Lake Worth, TX Exhaust Fluid, 14061 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes,

TufTrac Suspension, 232 in Wheelbase, PTO,

Beck 10.5 cyd Mixer Unit Usage: 139,282 Mi

Lot #	Details	Lot #	Details
1867 CHOIC	2017 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV6HDJG5267 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, Requires Diesel Exhaust Fluid, 13679 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.56:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 36,162 Mi Asset located in: Lake Worth, TX	CHOIC	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 3ALHG3DV8FDGK8255 C/W: Detroit DD13 6 Cylinder Diesel Engine, 18450 Engine hrs, Engine Brake, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 234 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 204,227 Mi Asset located in: Lake Worth, TX
1868	2015 Freigthliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV9FHGD2918 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 20129 Engine hrs, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 242,364 Mi Asset located in: Lake Worth, TX	1872	2015 Freightliner 114SD 6x4 Mixer Truck S/N: 1FVHG3DV6FHGC6641 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19288.9 Engine hrs, Engine Brake, Allison 4000 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Usage: 225,694 Mi Asset located in: Lake Worth, TX
1869	2015 Freightliner 114SD 6x4 Mixer Truck S/N: 3ALHG3DV8FDGP8010 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15144 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 231 in Wheelbase, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 162,097 Mi Asset located in: Lake Worth, TX	1873	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV0FHGD3309 C/W: 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT- 46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 8.03 m3 Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 220,173 Mi Asset located in: Lake Worth, TX
1870	2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DVXFHGC6643 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 186,822 Mi Asset located in: Lake Worth, TX		

## **Details** Lot # **Details** Lot # 1877 2015 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV2FHGN1430 CHOICE OF 2 - Lot #'s: 1874, 1875 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 350 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 4500 Automatic 1874 2015 Freightliner 114 SD 6x4 Mixer Truck Transmission, 20000 lb Front Axle, 46000 lb S/N: 3ALHG3DVXFDGK8256 Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 Ride Cab, 425/65R22.5 Front Tires, 11R22.5 hp Engine, Requires Diesel Exhaust Fluid, 5810 Rear Tires, Dual Steering Boxes, Double Frame, Engine hrs. Engine Brake, Allison 6-Speed Hendrickson Haulmaax Suspension, 222 in Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Wheelbase, McNeilus Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Axles, 4.86:1 Axle Ratio, 68000 lb GVWR, Air Usage: 36,664 Mi Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE; Boxes, Double Frame, Rubber over Walking Beam Suspension, 232 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Asset located in: Lake Worth, TX Usage: 204,689 Mi 1878 2014 Freightliner 114 SD 6x4 Mixer Truck S/N: 1FVHG3DV7EHFW3536 Asset located in: Lake Worth, TX C/W: Detroit DD15 6 Cylinder Diesel Engine, 1875 2015 Freightliner 114SD 6x4 Mixer Truck Requires Diesel Exhaust Fluid, 18254 Engine hrs, Engine Brake, Allison 4500 Automatic S/N: 1FVHG3DV7FHGD2917 Transmission, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19761.8 Engine hrs, Allison 4500 Steering Boxes, Double Frame, TufTrac Suspension, 232 in Wheelbase, PTO, Beck 10.5 Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 4.89:1 cyd Mixer Unit, Composite Water Tank Usage: 185,216 Mi Axle Ratio, 68000 lb GVWR, Air Ride Cab Aluminum Wheels, 425/65R22.5 Front Tires, Asset located in: Lake Worth, TX 11R22.5 Rear Tires, Dual Steering Boxes, 1879 Double Frame, Rubber over Walking Beam 2015 Mack GU813 6x4 Mixer Truck Suspension, 230 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes Usage: 21,980 Mi S/N: 1M2AX13C9FM028775 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US ÉPA Label, Requires Diesel Exhaust Fluid, 14199 Engine hrs, Engine Brake, Asset located in: Lake Worth, TX Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. CHOICE OF 2 - Lot #'s: 1876, 1877 5, Dual Steering Boxes, Camelback Suspension, 234 in Wheelbase, PTO, Beck Mixer Unit, 3 Removable Chutes 1876 2015 Freightliner 114 SD 6x4 Mixer Truck Usage: 133,877 Mi S/N: 1FVHG3DVXFHGS0264 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV Exhaust Fluid, Allison 4500 Automatic PRIOR TO BIDDING Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.09:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Asset located in: Lake Worth, TX 1880 2008 Mack GU813 Mixer Truck Boxes, Double Frame, Hendrickson Haulmaax S/N: 1M2AX13C98M001689 Suspension, 222 in Wheelbase, McNeilus Mixer Usage: Not Available Unit, 3 Removable Chutes, Remote Control w Asset located in: Lake Worth, TX /Cord Usage: 34,426 Mi 1881 2007 Mack CV713 6x4 Mixer Truck **Notes: ADDITIONAL INFORMATION** S/N: 1M2AG11C07M061944 C/W: Mack AMI 6 Cylinder Diesel 325 hp Engine, 10175 Engine hrs, Mack Manual AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX Transmission, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame,

Camelback Spring Suspension, 227 in Wheelbase, PTO, CBMW 10.5 cyd Mixer Unit, 2

Removable Chutes Usage: 38,616 Mi

Lot #	Details	Lot #	Details
1882	2007 Mack CPT713 Mixer Truck S/N: 1M2AT04C27M006297 Usage: Not Available Asset located in: Lake Worth, TX	S/N: 1M2E178CXXM002704 C/W: Mack EM7 6 Cylinder 728 co Engine, 1998 US EPA Label, 4745 8LL Manual Transmission, Alumi Wheels, 445/65R22.5, Walking B. Suspension, 180 in Wheelbase, N. cyd Mixer Unit, 3 Removable Chu Usage: 89,880 Mi Asset located in: Lake Worth, TX  1890 2009 GMC T8500 4x2 COE Exten Loader Waste Collection Truck S/N: 1GDP8F1B29F405423 C/W: Isuzu 6HK1X 6 Cylinder 7.8 hp Engine, 2008 US EPA Label, A Automatic Transmission, 13220 23360 lb Rears, 36580 lb GVWR, Tires, 445/65R22.5 Rear Tires, Sy Suspension, 171 in Wheelbase, F 1710 17 cyd Capacity Collection Usage: 68,923 Mi Asset located in: Humble, TX  1891 1997 Freightliner FL70 4x2 Atten S/N: 1FV3HLAA4VH739867 C/W: Cummins C8.3 8.3 L Diesel US EPA Label, 6-Speed Manual T 12000 lb Front Axle, 21000 lb Rec GVWR, 295/75R22.5, Spring Susj in Wheelbase, Flatbed Usage: Not Available Asset located in: Humble, TX  1892 2017 Freightliner M2 106 4x2 Att S/N: 3ALACWDT6HDJE8126 C/W: Cummins ISB 6 Cylinder 6.7 hp Engine, 2016 US EPA Label, R Exhaust Fluid, 4774 Engine hrs, A Automatic Transmission, 10000 18000 lb Rears, 5.13:1 Axle Ratio GVWR, 10R22.5, Airliner Suspens Wheelbase, Flatbed, In-Cab Atter Controller, Arrow Board, In-Cab A Controller Usage: 84,841 Mi Asset located in: Lake Worth, TX  1894 2011 International 4300SBA Atter Controller, Arrow Board, In-Cab A Controller Usage: 84,841 Mi Asset located in: Lake Worth, TX  1894 2011 International GDT255 6 Cyli Diesel 255 hp Engine, 8911 Engir Automatic Transmission, Air Ride S/N: 1HTMMAAN2BH322958 C/W: International GDT255 6 Cyli Diesel 255 hp Engine, 8911 Engir Automatic Transmission, Air Ride	C/W: Mack EM7 6 Cylinder 728 cid Diesel Engine, 1998 US EPA Label, 47454 Engine hrs, 8LL Manual Transmission, Aluminum Front Wheels, 445/65R22.5, Walking Beam Suspension, 180 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 89,880 Mi
1883	2008 Mack CHU613 Mixer Truck S/N: 1M1AN09Y38N003147 Usage: Not Available Asset located in: Lake Worth, TX		
1884	2005 Mack CV713 6x4 Mixer Truck S/N: 1M2AG11C75M034222 C/W: Mack 6 Cylinder Diesel Engine, 28940 Engine hrs, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Suspension, 229 in Wheelbase, 3 Removable Chutes Usage: 337,303 Mi Asset located in: Lake Worth, TX		2009 GMC T8500 4x2 COE Extended Cab Rear Loader Waste Collection Truck  S/N: 1GDP8F1B29F405423  C/W: Isuzu 6HK1X 6 Cylinder 7.8 L Diesel 260 hp Engine, 2008 US EPA Label, Allison Automatic Transmission, 13220 lb Front Axle, 23360 lb Rears, 36580 lb GVWR, 11R22.5 Front Tires, 445/65R22.5 Rear Tires, Spring Suspension, 171 in Wheelbase, PTO, McNelius 1710 17 cyd Capacity Collection Body Usage: 68,923 Mi
1885	2006 Peterbilt 357 6x4 Mixer Truck S/N: 1NPALT0X46D890572 C/W: Cat 6 Cylinder Diesel Engine, 9701 Engine hrs, Allison Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Aluminum Wheels, 445/65R22.5 Front Tires, 12R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Suspension, 216 in Wheelbase, PTO, 3 Removable Chutes, Remote Control w/Cord Usage: 267,072 Mi		1997 Freightliner FL70 4x2 Attenuator Truck S/N: 1FV3HLAA4VH739867 C/W: Cummins C8.3 8.3 L Diesel Engine, 1996 US EPA Label, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 216 in Wheelbase, Flatbed Usage: Not Available
1886	Asset located in: Lake Worth, TX  2003 Peterbilt 357 6x4 Mixer Truck  S/N: 1NPALT0X53D802186  C/W: Cat C10 6 Cylinder Diesel 305 hp Engine, 7071 Engine hrs, Eaton Fuller 8LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 230 in Wheelbase, PTO, 3 Removable Chutes		C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2016 US EPA Label, Requires Diese Exhaust Fluid, 4774 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, 5.13:1 Axle Ratio, 26000 lb GVWR, 10R22.5, Airliner Suspension, 282 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 84,841 Mi
	Usage: 266,861 Mi Notes: LOCATED-IN-HOUSTON-TX Asset located in: Humble, TX		2011 International 4300SBA Attenuator Truck S/N: 1HTMMAAN2BH322958 C/W: International GDT255 6 Cylinder 7.6 L
1887	2007 Western Star 4900 SA T/A Sleeper Truck Tractor S/N: 5KJJALCK77PX38561 Usage: Not Available Asset located in: Lake Worth, TX		Diesel 255 hp Engine, 8911 Engine hrs, Automatic Transmission, Air Ride Suspensio Flatbed, Arrow Board, In-Cab Arrow Board Controller Usage: Not Available
1888	2002 Kenworth T800 6x4 Mixer Truck S/N: 1NKDLU0X12J703485 C/W: Cat C-12 6 Cylinder 11.9 L Diesel 505 hp Engine, 2002 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 425/65R22. 5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Suspension, 3 Removable Chutes Usage: 159,586 Mi Asset located in: Lake Worth, TX		

		T	
Lot #	Details	Lot #	Details
1896	2007 Hino 268 4x2 Attenuator Truck  S/N: 5PVNJ8JP872S50064  C/W: Hino Motors J08E-TA 6 Cylinder 7.7 L  Diesel Engine, 2008 US EPA Label, Automatic  Transmission, 10000 lb Front Axle, 19000 lb  Rears, 25950 lb GVWR, 11R22.5, Spring  Suspension, 218 in Wheelbase, Flatbed, In-Cab  Attenuator Controller  Usage: 343,850 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE  THE INSPECTION REPORT DEFICIENCIES  NOTED - PLEASE SEE THE INSPECTION  REPORT  Asset located in: Humble, TX  2007 International 8000 4x2 Toter Truck  S/N: 1HSHWAHN67J535045	1901	2022 Chevrolet Silverado 5500HD 4x2 Rollback Truck  S/N: 1HTKHPVM6NH675305  C/W: Navistar Duramax V8 6.6 L Diesel 350 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7940 lb Front Axle, 15000 lb Rears, 4.10:1 Axle Ratio, 22940 lb GVWR, 225/70R19.5, Spring Suspension, 232 in Wheelbase, PTO, Century Steel Wrecker Body, 5000 lb Winch Capacity, Tow Dollies  Usage: 60,704 Mi  Notes: X2-CNV Dash Vin from photo; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	C/W: 6 Cylinder Diesel Engine, 21882 Engine		Asset located in: Lake Worth, TX
	hrs, Eaton Fuller Manual Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 11R22. 5 Rear Tires, Air Ride Suspension, 156 in Wheelbase Usage: 239,028 Mi Asset located in: Midland, TX	1902	2020 Ram 5500 4x4 Rollback Truck S/N: 3C7WRNDL4LG136586 C/W: Cummins 6 Cylinder 6.7 L Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 205 in Wheelbase, PTO, Danco 12SR20 Rollback
1898	2020 Peterbilt 567 6x4 Roll-Off Truck	1	Body, 20 ft x 96 in Bed, Ramsey 8000 lb Winch, Hydraulic Wheel Lift, EQUIPMENT-FROM-US-
	S/N: 1NPCL40X3LD650696 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10547 Engine hrs, Engine		AUTO-RECYCLING Usage: 70,701 Mi  Asset located in: Lake Worth, TX
	Brake, 10-Speed Manual Transmission, Triple Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 276 in Wheelbase, PTO, 2019 Galbreath U5-OR-174 Roll-Off Body, 23 ft 4 in Hoist, Winch Usage: 285,990 Mi  Asset located in: Lake Worth, TX	S/N: JALE5W160K7304175 C/W: Isuzu 4HK1TC 4 Cylinder 3 Engine, 2018 US EPA Label, Req Exhaust Fluid, 5916 Engine hrs, a Transmission, 7275 lb Front Axla Rears, 19500.0 lb GVWR, 225/70 Suspension, 178 in Wheelbase, I 21 ft 6 in x 96 in Bed, Aluminum lb Winch	C/W: Isuzu 4HK1TC 4 Cylinder 317 cid 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5916 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500.0 lb GVWR, 225/70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6 in x 96 in Bed, Aluminum Frame, 18000 lb Winch
1899	2013 Freightliner 114 6x4 Roll-Off Truck		Usage: 196,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	S/N: 3ALHG3DV8DDFF1962	THE INSPECTION	THE INSPECTION REPORT
	C/W: Detroit 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission,		Asset located in: Humble, TX
	16000 lb Front Axle, 44000 lb Rears, 60000 lb GVWR, Air Ride Cab, 295/75R22.5, Double	1904	2005 Freightliner M2 106 4x2 Sleeper Tow Truck
	Frame, TufTrac Suspension, 23 ft 4 in Hoist Usage: 472,556 Mi		S/N: 1FVAC20C35HV14126
	Asset located in: Lake Worth, TX	12717 Engine Speed Transn 21000 lb Rear 3.90:1 Axle Ra Double Frame Wheelbase, P Usage: 262,31 Notes: DEFICI THE INSPECT Asset located	C/W: Cat C7 6 Cylinder Diesel 250 hp Engine, 12717 Engine hrs, Eaton Fuller RT8709B 9-
1900	2005 Peterbilt 357 6x4 Roll-Off Truck S/N: 1NPALT0XX5N857701 C/W: Cat C11 6 Cylinder Diesel Engine, 1888 Engine hrs, Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 266 in Wheelbase, PTO, GH 1560 Roll-Off Body, 23 ft Hoist Usage: Not Available		Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS21145 Drive Axles 3.90:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 178 in Wheelbase, PTO, Steel Wrecker Body Usage: 262,313 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1904A	2009 Forest River Georgetown Motor Home S/N: 1F6NF53Y590A00112 C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2009 US EPA Label, 3 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Onan RV QG 5500 LP 5.5 kW Generator, Rear View Camera Usage: 23,619 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1908	S/N: 5PVNJ8JV1H4S66305 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR,
1904B	2007 Gulf Stream Independence Motor Home S/N: 4UZACLBW57CZ34853 C/W: Air Conditioner, Automatic Transmission, 1899.5 hrs Carrier Engine, Cummins 6 Cylinder Diesel Engine, 2007 US EPA Label, 3 Slide Outs, Power Entrance Step, Power Leveling Jacks, Power Awning, Generator w/ 266 hrs		Steel, 11R22.5, Air Ride Suspension, Thermo King T-1080R Whisper Reefer Unit, 8637 Reefer Engine Hours:, 8637 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 293,547 Mi Asset located in: Lake Worth, TX
	Usage: 82,082 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1909	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT8H4S57955 C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid,
1905	2002 Prevost H3-45 Motor Home S/N: 2PCV33491X1013393 C/W: Air Conditioner, Allison Automatic Transmission, Detroit 6 Cylinder 12.7 L 500 hp Engine, Sleeps 2 People, Clothes Washer & Dryer, Power Awning, Power Tech 25 kW Generator Usage: 142,465 Mi Asset located in: Lake Worth, TX		Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Reefer Unit, 9481 Reefer Engine Hours:, 9481 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 297,803 Mi  Asset located in: Lake Worth, TX
1906	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JV5J4S67771 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9282 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Carrier Reefer Unit, 8457 Reefer Total Hours:, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 171,017 Mi Notes: SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	1910	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT2H4S57952 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 254 in Wheelbase, Thermo King T-1080R Whisper Reefer Unit, 5965 Reefer Engine Hours:, 5965 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 322,392 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
1907	2018 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JL0J4S52089 C/W: Hino 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 188 in Wheelbase, Carrier Reefer Unit, 9213 Reefer Total Hours:, Morgan 16 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 184,843 Mi Asset located in: Lake Worth, TX	1911	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JTXH4S57455 C/W: Hino 6 Cylinder Diesel Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, Carrier Transicold Reefer Unit, 12952 Reefer Engine Hours:, 16707 Reefer Total Hours:, Supreme 24 ft x 102 in Wide x 98 in High Body, Curbside Door Usage: 237,435 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1912	2017 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JT1H4S57439 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 252 in Wheelbase, Carrier Reefer Unit, Supreme 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Walk-Up Ramp, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 284,077 Mi Asset located in: Lake Worth, TX	1916	2015 Freightliner M2 106 4x2 Refrigerated Truck  S/N: 3ALACXDT1FDGF1570  C/W: Cummins ISB 6.7 L Diesel Engine, 2014  US EPA Label, Requires Diesel Exhaust Fluid, 10137 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 5.88:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, steel, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Carrier Transicold Reefer Unit, 11638 Reefer Total Hours:, Morgan 22 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 313,978 Mi
1913	2019 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFC0KDKL2452 C/W: Cummins B 6 Cylinder 6.7 L Diesel 250 hp Engine, 2018 US EPA Label, 9375 Engine hrs, Eaton Fuller 3 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Thermo King T- 680R Reefer Unit, Morgan 24 ft x 102 in Wide x 96 in High Body, Curbside Door, Liftgate Usage: 332,255 Mi		Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1917	<b>2012 Freightliner M2 106 Refrigerated Truck</b> S/N: 1FVACWDT0CHBS3944
1914	2016 Freightliner M2 106 Refrigerated Truck S/N: 3ALACWDT5GDGV8814 Usage: Not Available Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD		Usage: Not Available  Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1918	2018 International 4300 4x2 Refrigerated Truck
1915	2016 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWDT5GDHE5396 C/W: Cummins 6 Cylinder Diesel Engine, 11342 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Steel, 11R22.5, Air Ride Suspension, 256 in Wheelbase, Carrier Reefer Unit, 13046 Reefer Total Hours:, Kidron 24 ft x 102 in Wide x 97 in High Body Usage: 297,043 Mi		S/N: 3HAMMMML4JL736540 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5440 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 156,143 Mi Asset located in: Lake Worth, TX
	Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD ASSET located in: Lake Worth, TX	1920	2019 Isuzu NQR 4x2 COE Refrigerated Truck S/N: JALE5W167K7900576 C/W: Isuzu 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6830 lb Front Axle, 12980 lb Rears, 17950 lb GVWR, 225/70R19.5, Spring Suspension, 150 in Wheelbase, Thermo King T-680R Reefer Unit, supreme 18 ft x 102 in Wide x 92 in High Body, Curbside Door, Liftgate Usage: 179,717 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1921	2017 Chevrolet G3500 4x2 Refrigerated Truck S/N: 1GB0GRFF4H1344050 C/W: V8 Gasoline Engine, 8673 Engine hrs, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, Aluminum Wheels, 245/75R16, Spring Suspension, 139 in Wheelbase, Thermo King V-520 NM Max Reefer Unit, GCE 11 ft x 88 in Wide x 72 in High Body, Curbside Door	CHOIC	E OF 2 - Lot #'s: 1926, 1927  2020 Hino 268 Van Truck  S/N: 5PVNJ8JV3L4S75936  Usage: 223,964 Mi  Asset located in: Lake Worth, TX
	Usage: 328,694 Mi <b>Asset located in</b> : Lake Worth, TX	1927	2020 Hino 268 4x2 Van Truck
1922	2016 International 4300 4x2 Beverage Truck S/N: 1HTMMMML3GH225609 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison 6-Speed Automatic Transmission, 8618 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 235 in Wheelbase, Mickey 21 ft Body, 36 in Wide Bays, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG		S/N: 5PVNJ8JV4L4S75931 C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5949 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 237,576 Mi Asset located in: Lake Worth, TX
	Usage: 343,147 Mi <b>Asset located in</b> : Lake Worth, TX	сноіс	E OF 2 - Lot #'s: 1928, 1929
1923	2018 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM7X2JM491941 C/W: Paccar B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7218 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 6.17:1 Axle Ratio, 32000 lb GVWR, 275/80R22.5, Spring Suspension, 275 in Wheelbase, Wabash 24 ft x 102 in Wide x 88 in High Body, Liftgate, EQUIPMENT-FROM- YELLOW-CORP Usage: 110,293 Mi	1928	2020 Hino 268 4x2 Van Truck  S/N: 5PVNE8JVXL4S57650  C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 5054 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 243,455 Mi  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1929	2020 Hino 268 4x2 Van Truck
1924	2017 Peterbilt 337 4x2 Van Truck S/N: 2NP2HM6X2HM409086 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9288 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Dana S21170 Drive Axles, 4.56: 1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 101 in High Body, Curbside Door, Liftgate Usage: 312,144 Mi		S/N: 5PVNE8JV0L4S57611 C/W: Hino J08E-WU 6 Cylinder Diesel 230 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 274,702 Mi Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	Сноіс	E OF 2 - Lot #'s: 1930, 1931
1925	2015 Peterbilt 337 4x2 Van Truck S/N: 2NP2HJ7X9FM275736 C/W: Paccar ISL 6 Cylinder 8.9 L Diesel 260 hp Engine, Requires Diesel Exhaust Fluid, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 4.11:1 Axle Ratio, 33000.0 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 287,399 Mi Asset located in: Lake Worth, TX	1930	2019 Hino 268 Van Truck S/N: 5PVNJ8JV9K4S70786 Usage: 241,223 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1931	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9K4S72697 C/W: Hino 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11873 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, Supreme 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 311,559 Mi Asset located in: Lake Worth, TX	1936	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV1K4S70474 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8646 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 227,375 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 5 - Lot #'s: 1932, 1933, 1934, 1935, 1936	СНОІС	E OF 4 - Lot #'s: 1937, 1938, 1939, 1940
1932	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S74135 C/W: Hino 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, 7853 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 252,005 Mi Asset located in: Lake Worth, TX	1937	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV5K4S71661 C/W: Hino 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7844 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 264,419 Mi Asset located in: Lake Worth, TX
1933	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3K4S70413 C/W: Hino J08E-WU 6 Cylinder 7.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6861 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hino Air Ride Suspension, 272 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body Usage: 195,635 Mi Asset located in: Lake Worth, TX	1938	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV7K4S70785 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11645 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 271 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 394,055 Mi
1934	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXK4S70473 C/W: Hino Motors J08E-WU 6 Cylinder 7.7 L Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7082 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp Usage: 199,209 Mi Asset located in: Lake Worth, TX	1939	Asset located in: Lake Worth, TX  2018 Hino 268 4x2 Van Truck  S/N: 5PVNJ8JV9J4S67062  C/W: Hino 6 Cylinder Diesel Engine, 2017 US  EPA Label, Requires Diesel Exhaust Fluid,  Allison Automatic Transmission, 10000 lb  Front Axle, 19000 lb Rears, 25950.0 lb GVWR,  11R22.5, Spring Suspension, 274 in Wheelbase,  Mickey 26 ft x 102 in Wide x 103 in High Body,  Liftgate  Usage: 226,779 Mi  Asset located in: Lake Worth, TX
1935	2019 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3K4S70475 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 103 in High Body Usage: 220,034 Mi Asset located in: Lake Worth, TX	1940	2018 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV5J4S67334 C/W: 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
СНОІС	CHOICE OF 2 - Lot #'s: 1941, 1942		2015 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV7F4S58836 C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp
1941	2018 Hino 268 Van Truck S/N: 5PVNJ8JV7J4S70011 Usage: 239,327 Mi Asset located in: Lake Worth, TX		Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 999 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 762,239 Mi
1942	<b>2018 Hino 268 Van Truck</b> S/N: 5PVNJ8JV6J4S70016 Usage: 335,947 Mi		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1947	<b>2014 Hino 268 4x2 Van Truck</b> S/N: 5PVNE8JT3E4S55904
CHOIC 1943	10ICE OF 2 - Lot #'s: 1943, 1944 43 2017 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0H4S55963 C/W: Hino J08E-WU 6 Cylinder 469 cid Diesel 230 hp Engine, 2016 US EPA Label, Requires	C/W: Hino J08E-VC 6 Cylinder Diesel 220 Engine, 2013 US EPA Label, Requires Die Exhaust Fluid, Automatic Transmission, Ib Front Axle, 19000 Ib Rears, 25950 Ib G 11R22.5, Spring Suspension, 254 in Whe Supreme Corp 24 ft x 102 in Wide x 103 Body, Liftgate Usage: 665,898 Mi	C/W: Hino J08E-VC 6 Cylinder Diesel 220 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Supreme Corp 24 ft x 102 in Wide x 103 in High Body, Liftgate
	Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 302,562 Mi Asset located in: Lake Worth, TX	Diesel 220 hp Engine, 2012 US Él Requires Diesel Exhaust Fluid, 20	
1944	2016 Hino 268 4x2 Van Truck S/N: 5PVNJ8JVXG4S61134 C/W: Hino J08E-VC 6 Cylinder 469 cid Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic		19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 239 in Wheelbase, Morgan 20 ft x 102 in Wide x 93 in High Body Usage: 163,671 Mi <b>Asset located in</b> : Lake Worth, TX
	Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: Not Available  Asset located in: Lake Worth, TX	1948A	2013 Hino 268 4x2 Van Truck S/N: 5PVNE8JT8D4S54925 C/W: 6 Cylinder 7.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 251 in Wheelbase, Reading 24 ft x 102 in Wide x 102
CHOIC	E OF 3 - Lot #'s: 1945, 1946, 1947		in High Body, Liftgate Usage: 733,693 Mi  Asset located in: Lake Worth, TX
1945 2016 Hino 268 4x2 Van Truck S/N: 5PVNE8JV0G4S54665 C/W: J08E-VC 6 Cylinder Diesel 220 hp Ei		СНОІСІ	E OF 2 - Lot #'s: 1949, 1950
	2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 274 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 779,914 Mi  Asset located in: Lake Worth, TX	1949	2017 Hino 165 4x2 Van Truck S/N: 5PVNE8JV8H4S55600 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 1000 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 235 in Wheelbase, Supreme 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 691,347 Mi Asset located in: Lake Worth, TX
		1950	2016 Hino 165 Van Truck S/N: 5PVNE8JV7G4S54761 Usage: Not Available Asset located in: Lake Worth, TX

			1 age 107 of 500
Lot #	Details	Lot #	Details
1951	2013 Hino 165 4x2 Van Truck S/N: 5PVNE8JT2D4S55035 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, READING 24 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 791,274 Mi Asset located in: Lake Worth, TX	1956	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXFC5LDMA4042 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, MARION 26 ft x 102 in Wide x 109 in High Body, Liftgate Usage: 294,302 Mi Asset located in: Lake Worth, TX
3		1960	2020 Freightliner M2 106 4x2 Van Truck
1952	2010 Hino 165 4x2 Van Truck S/N: 5PVNJ8JV5A4S52235 C/W: Hino Motors J08E-TV 6 Cylinder 7.7 L Diesel 220 hp Engine, 2009 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, Steel, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 413,815 Mi		S/N: 3ALACWD29LDLW1690 C/W: Detroit DD8 6 Cylinder 7.7 L Diesel 260 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 10R22.5, Air Ride Suspension, 283 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 327,840 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	1961	2019 Freightliner M2 106 4x2 Van Truck
1953	2010 Hino 268 4x2 Van Truck  S/N: 5PVNE8JV3A4S51573  C/W: Hino J08E-TV 6 Cylinder Diesel 220 hp Engine, 2009 US EPA Label, 999 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 269 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 542,329 Mi  Asset located in: Lake Worth, TX	1961	S/N: 3ALACWFC8KDKK6432 C/W: Cummins 6 Cylinder 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5, Spring Suspension, Smyrna 26 ft x 96 in Wide x Body, Liftgate Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN
1954	2016 Hino 155 Van Truck	1	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	S/N: JHHXDM1H2GK003847		Asset located in: Lake Worth, TX
	Usage: 206,947 Mi <b>Asset located in</b> : Lake Worth, TX		
1955	2020 Freightliner M2 112 4x2 Moving Van Truck  S/N: 3ALAC4DV3LDME8608  C/W: Detroit DD13 6 Cylinder 12.8 L Diesel Engine, 2019 US EPA Label, 9094 Engine hrs, Engine Brake, Eaton Fuller FAO-14810C  Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-21-160 Drive Axles, 3.07:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 234 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: 533,064 Mi	-CHOIC	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB3KDKH7131 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2018 US EPA Label, 5566 Engine hrs, Allison 2200 4 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19- 14X Drive Axles, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 96 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 214,259 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1963	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB4KDKH7137 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,942 Mi Asset located in: Lake Worth, TX	1967	2018 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWFB4JHJH4986 C/W: Detroit DD5 4 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7569.8 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000.0 lb GVWR, Air Ride Cab, 11R22. 5, Airliner Air Ride Suspension, 270 in Wheelbase, PTO, AMH 26 ft x 102 in Wide x 97 in High Body, Liftgate, Asset includes a 2.5Ton pallet jack and straps Usage: 288,869 Mi Notes:
1964	2018 Freightliner M2 106 4x2 Van Truck		Asset located in: Livingston, LA
	S/N: 3ALACWFC5JDJH4350 C/W: Cummins 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 312,803 Mi Asset located in: Lake Worth, TX	1968	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC6JDJK7266 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7811 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Steel, 295 /75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, AMH 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 259,719 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 1965, 1966	1969	2018 Freightliner M2 106 4x2 Van Truck
1965	2018 Freightliner M2 106 4x2 Van Truck 3/N: 3ALACWFC1JDJZ7466 3/W: Cummins 6 Cylinder 6.7 L Engine, 2018 3/S EPA Label, Requires Diesel Exhaust Fluid, 3/Automatic Transmission, 10000 lb Front Axle, 3/7000 lb Rears, 26000 lb GVWR, Air Ride Cab, 3/95/75R22.5, Airliner Air Ride Suspension, 3/Aorgan 24 ft x x Body, Curbside Door, Liftgate		S/N: 3ALACWFC1JDJS4825 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17126 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 28 ft x 102 in Wide x Body, Liftgate Usage: 431,154 Mi Asset located in: Midland, TX
	Usage: 397,493 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1970 2017 Freightliner M2 106 4x2 Van S/N: 3ALACWCY4HDJF0552 C/W: Cummins ISL 6 Cylinder Dies Engine, Requires Diesel Exhaust F Engine hrs, Engine Brake, Allison A Transmission, 10000 lb Front Axle Rears, 5.22:1 Axle Ratio, 26000 lb Aluminum Wheels, 295/75R22.5 F 275/80R22.5 Rear Tires, Airliner A Suspension, 215 in Wheelbase, M	S/N: 3ALACWCY4HDJF0552 C/W: Cummins ISL 6 Cylinder Diesel 270 hp Engine, Requires Diesel Exhaust Fluid, 8157 Engine hrs, Engine Brake, Allison Automatic
1966	2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFCXJDJZ7465 C/W: Cummins B 6 Cylinder 6.7 L 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10762.9 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum		Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 215 in Wheelbase, MORGAN 18 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 305,761 Mi
	Wheels, 295/75R22.5, Airliner Air Ride Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 379,528 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	1971	2017 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8HDJA1678 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 316,107 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot #	Details	Lot #	Details
CHOICI 1972	E OF 2 - Lot #'s: 1972, 1973  2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT8GDHM0083 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 5608 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle,	1976	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT7GHHG9662 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 374,343 Mi
	19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5, Spring Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG		Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX
	Usage: 180,227 Mi <b>Asset located in</b> : Lake Worth, TX	1977	2016 Freightliner M2 106 4x2 Van Truck
1973	2016 Freightliner M2 4x2 Van Truck S/N: 3ALACWDT2GDHN0995 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2018 US EPA Label, 7610 Engine hrs, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG	19//	S/N: 1FVACWDT6GHHK2059 C/W: Cummins ISB6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8186 Engine h Allison 2100 Automatic Transmission, 1000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ra: 26000 lb GVWR, Air Ride Cab, 11R22.5, Sprin Suspension, 234 in Wheelbase, Morgan 22 ft 102 in Wide x 97 in High Body, Liftgate Usage: 170,085 Mi Asset located in: Lake Worth, TX
	Usage: 589,467 Mi <b>Asset located in</b> : Lake Worth, TX	1978	2016 Freightliner M2 106 4x2 Van Truck
CHOICI 1974	2016 Freightliner M2 106 4x2 Van Truck S/N: 3ALACXDT2GDHA4391 C/W: Cummins ISB 6 Cylinder 6.7 L 280 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 271 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3ALACWDT3GDHM9628 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 11463 Engine hrs, 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 334,137 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
1975	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDU2GHGW9627 C/W: Cummins ISB 6 Cylinder 6.7 L 200 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8376 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 6.14:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 294,823 Mi	<b>- 1979</b>	2015 Freightliner M2 106 4x2 Van Truck S/N: 1FVACXDT1FHGJ9796 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FO-6406B Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.22:1 Axle Ratio, 33000 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Spring Suspension, 270 in Wheelbase, wabash 22 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 191,299 Mi

Lot #	Details	Lot #	Details
1980	2020 International MV607 4x2 Van Truck S/N: 3HAEUMML2LL115482 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 552 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 54,274 Mi Notes: ODOMETER REPLACED AT 171,023 MILES -PLEASE SEE INSPECTION REPORT, ACTUAL MILEAGE IS 225,297 Asset located in: Lake Worth, TX	1984	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML5KH519554 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 4381 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.29:1 Axle Ratio, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 202,297 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW
1981	2019 International MV607 4x2 Van Truck		Asset located in: Lake Worth, TX
	S/N: 3HAEUMML6KL437363 C/W: Cummins B 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, 7555 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, AMH 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 250,820 Mi Asset located in: Lake Worth, TX	1985	2019 International 4300 4x2 Dry Van Van Truck S/N: 1HTMMMML6KH382477 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3654 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Ball Hitch Usage: 155,349 Mi Asset located in: Lake Worth, TX
1982	2020 International MV607LP 4x2 Moving Van	1006	
	Truck S/N: 1HTEWMML1LH870977 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6412 Engine hrs, Allison Automatic Transmission, 9000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 245 /70R19.5, Air Ride Suspension, 187 in Wheelbase, Morgan 16 ft x 102 in Wide x 97 in High Body Usage: 292,284 Mi Asset located in: Lake Worth, TX	1986	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML2KL519280 C/W: Cummins B6.7 220 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x Body, Walk-Up Ramp, Ball Usage: Not Available Asset located in: Lake Worth, TX
	Asset located III. Lake Worth, 17	┥	
CHOIC	E OF 4 - Lot #'s: 1983, 1984, 1985, 1986	CHOIC	E OF 4 - Lot #'s: 1987, 1988, 1989, 1990
1983	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML5KH382549 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3964 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.57:1 Axle Ratio, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp, Ball Hitch Usage: 165,232 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX	1987	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML1KH382497 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3778 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in High Body, Pintle Hitch Usage: 146,547 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
1988	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML8KL382233 C/W: Cummins ISB6.7 6.7 L Diesel Engine, 2019 US EPA Label, 3703 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 97 in High Body, Walk-Up Ramp, Ball Usage: 150,368 Mi Asset located in: Lake Worth, TX	1993	S/N: 1HTMMMML6KH514928 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Dies Exhaust Fluid, 4766 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle 17500 lb Rears, Meritor MS-17-14X-3DFL Driv Axles, 5.29:1 Axle Ratio, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Walk-U	
1989	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML2KH518412		Ramp, Ball Hitch Usage: 211,781 Mi <b>Asset located in</b> : Lake Worth, TX	
	C/W: Cummins B6.7 220 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Ball Usage: Not Available  Asset located in: Lake Worth, TX	1994	2019 International 4300 4x2 Van Truck S/N: 3HAMMMML3KL382012 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3995 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 96 in	
1990	<b>2019 International 4300 4x2 Moving Van Truck</b> S/N: 3HAMMMML7KL383325		High Body, Walk-Up Ramp Usage: 162,399 Mi	
	C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3819		Asset located in: Lake Worth, TX	
	Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X-3DFL Drive Axles, 5.57:1 Axle Ratio, 11783 lb GVWR, 11R22.5 Front Tires, 11R22.5	1997 2019 Inter S/N: 1HTM C/W: Cum hp Engine, Exhaust Fl Automatic 17500 lb F Tires, 11R: 272 in Who x 96 in Hig Usage: 17: Asset loca  1998 2019 Inter S/N: 3HAM C/W: Cum hp Engine, Exhaust Fl Automatic 17500 lb F Tires, 11R: 272 in Who 102 in Hig Usage: 18:	E OF 3 - Lot #'s: 1997, 1998, 1999	
	Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 156,125 Mi		2019 International 4300 4x2 Van Truck S/N: 1HTMMMMLXKH519808 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel	
CHOIC 1991	Asset located in: Lake Worth, TX  E OF 4 - Lot #'s: 1991, 1992, 1993, 1994  2019 International 4300 4x2 Van Truck S/N: 3HAMMMML4KL382553		Exhaust Fluid, 4042 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body, Walk-Up Ramp Usage: 175,179 Mi Asset located in: Lake Worth, TX	
	C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3570 Engine hrs, Allison 2200 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x Body, Ball Hitch Usage: 165,388 Mi Asset located in: Lake Worth, TX		S/N: 3HAMMMMLXKL383447 C/W: Cummins B6.7 220 6 Cylinder 6. hp Engine, 2018 US EPA Label, Requir Exhaust Fluid, 4243 Engine hrs, Allison Automatic Transmission, 10000 lb Fro 17500 lb Rears, 25999 lb GVWR, 11R2 Tires, 11R22.5 Rear Tires, Air Ride Sus 272 in Wheelbase, Morgan 26 ft x 96 i	2019 International 4300 4x2 Moving Van Truck S/N: 3HAMMMMLXKL383447 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4243 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x
1992	2019 International 4300 4x2 Van Truck S/N: 3HAMMML0KL382789 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4077 Engine hrs, Allison 6-Speed Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 11793 lb GVWR, 11R22.5, International Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body Usage: 180,545 Mi		102 in High Body Usage: 188,842 Mi <b>Asset located in</b> : Lake Worth, TX	

Lot #	Details	Lot #	Details
1999	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML8KH514655 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4722 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.29:1 Axle Ratio, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp, Ball Hitch Usage: 207,720 Mi Notes: PLEASED SEE SELLER SUPPLIED MAINTENANCE RECORD - ATTACHED IS THE DOCUMENTATION SECTION BELOW Asset located in: Lake Worth, TX	2003	2018 International 4300 4x2 Van Truck S/N: 3HAMMMML2JL544906 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, Morgan 28 ft x 102 in Wide x 109 in High Body, Liftgate, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 225,961 Mi Asset located in: Lake Worth, TX
2000	2019 International 4300 SBA 4x2 Van Truck S/N: 3HAMMMML3KL559187 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5636 Engine hrs, Allison 2500 5- Speed Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 4.63:1 Axle Ratio, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, SMYRNA TRUCK 26 ft x 102 in Wide x 102 in High Body, Liftgate Usage: 147,079 Mi Asset located in: Lake Worth, TX	2004	2018 International 4300 4x2 Van Truck S/N: 1HTMMMML6JH350045 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9004 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 275,971 Mi Asset located in: Lake Worth, TX
CHOIC	E OF 2 - Lot #'s: 2001, 2002	2005	2017 International 4300 4x2 Van Truck S/N: 1HTMMMML2HH654807 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 250 hp Engine, 2016 US EPA Label, Requires Diesel
2001	102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 233,934 Mi  Asset located in: Humble, TX  2018 International 4300 4x2 Van Truck S/N: 3HAMMMML9JL589552 C/W: Cummins B 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8327 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb		Exhaust Fluid, 6442 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 179,428 Mi <b>Asset located in</b> : Lake Worth, TX
		S/N: 3HAMMMML4GL740046 C/W: Cummins ISB 6 Cylinder 6.7 L D hp Engine, 2015 US EPA Label, Requi Exhaust Fluid, 17251 Engine hrs, Allis	2016 International 4300 4x2 Van Truck S/N: 3HAMMMML4GL740046 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17251 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle,
2002			19000 lb Rears, 26000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 260 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 222,929 Mi Asset located in: Lake Worth, TX
		2007	2016 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML9GH012776 C/W: Cummins ISB V6 6.7 L 240 hp Engine, 2015 US EPA Label, Automatic Transmission, 10000 lb Front Axle, 15999 lb Rears, 25999 lb GVWR, 295/75R22.5, Supreme 26 ft x 96 in Wide x 102 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 247,400 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2008	2015 International 4300 4x2 Van Truck S/N: 1HTMMMMLXFH710991 C/W: Cummins 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Supreme 28 ft x 96 in Wide x Body, Liftgate Usage: 491,297 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	2014 V 2015	2003 International 4300 SBA 4x2 Van Truck S/N: 1HTMMAAM63H583373 C/W: International DT466 6 Cylinder 7.6 L Diesel Engine, Automatic Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, 256 in Wheelbase, Morgan 24 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 503,203 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX  1998 International 4700 4x2 Moving Van Truck S/N: 1HTSCABM3WH533169 C/W: International V8 7.3 L Diesel Engine, US
2009	Asset located in: Lake Worth, TX  2015 International Durstar 4300 4x2 Van Truck S/N: 3HAMMMML2FL040069 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic		EPA Label, Spicer 5-Speed Manual Transmission, Spring Suspension, 188 in Wheelbase, Timpte 16 ft x 96 in Wide x 84 in High Body Usage: 41,973 Mi <b>Asset located in</b> : Lake Worth, TX
	Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		2007 GMC C5500 4x2 Van Truck S/N: 1GDE5C1207F411068 C/W: GM Duramax 6.6 L Diesel Engine, 2006 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 285/70R19.5, Spring Suspension, 208 in Wheelbase, 18 ft x 96 in Wide x 90 in High Body, Liftgate Usage: 292,010 Mi
	Asset located in: Lake Worth, TX	4	Notes: **Shelving built in box area**
2010	2008 Hino 268 4x2 Van Truck S/N: 5PVNE8JV582S50883 C/W: Hino J08E-TV 6 Cylinder 469 cid Diesel 220 hp Engine, 2007 US EPA Label, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 270 in Wheelbase, 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 112,668 Mi Asset located in: Lake Worth, TX	2016	Asset located in: Humble, TX  2006 Nissan 4x2 COE Van Truck S/N: JNAPA80H66AS55788 C/W: Hino J08E-UJ 6 Cylinder 469 cid Diesel 230 hp Engine, 2007 US EPA Label, Automatic Transmission, 9480 lb Front Axle, 18000 lb Rears, 25995 lb GVWR, 11R22.5, Spring Suspension, 254 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate
2011	2008 International 4300 4x2 Van Truck	1	Usage: 259,568 Mi <b>Asset located in</b> : Lake Worth, TX
	S/N: 1HTMMAAL38H572202 C/W: International MaxxForce DT 7.6 L Diesel 225 hp Engine, 2007 US EPA Label, CARB Compliant, 9586 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 226 in Wheelbase, Morgan 26 ft x 102 in Wide x 93 in High Body, Liftgate Usage: 245,473 Mi Asset located in: Lake Worth, TX	2017	2021 Chevrolet 4500 4x2 COE Van Truck S/N: 54DCDW1D5MS205390 C/W: Isuzu V8 Gasoline Engine, 2021 US EPA Label, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Morgan 20 ft x 96 in Wide x 91 in High Body, Liftgate Usage: Not Available Asset located in: Lake Worth, TX
2012	2005 International 4300 SBA 4x2 Van Truck S/N: 1HTMMAAN05H119538 C/W: International D226 6 Cylinder 7.6 L Diesel 225 hp Engine, 2004 US EPA Label, 10254 Engine hrs, Eaton Fuller Manual Transmission, Aluminum Wheels, 295/75R22.5, Spring Suspension, Morgan 26 ft x 102 in Wide x 104 in High Body, Curbside Door, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: 196,863 Mi Asset located in: Lake Worth, TX	2018	2018 Chevrolet 4500 COE Van Truck S/N: 54DCDW1B6JS807385 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
2019	2019 Hino 195 4x2 COE Van Truck S/N: JHHRDM2H6KK007187 C/W: Hino J05E-TP 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7270 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 152 in Wheelbase, Morgan 16 ft x 96 in Wide x 91 in High Body, Liftgate Usage: 203,811 Mi Asset located in: Lake Worth, TX	2024	2016 Isuzu NPR 4x2 COE Extended Cab Van Truck  S/N: 54DC4J1B8GS803916  C/W: Isuzu Gasoline Engine, Automatic Transmission, Steel, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Supreme 16 ft x 102 in Wide x 85 in High Body, Curbside Door, Liftgate Usage: 137,402 Mi Asset located in: Lake Worth, TX
	Asset located III. Lake Worth, 17	2025	2012 Mitsubishi Fuso 4x2 COE Van Truck
	E OF 3 - Lot #'s: 2020, 2021, 2022		S/N: JL6BNG1A5CK002630 C/W: Fuso F1C 3.0 L Engine, 2011 US EPA Label, Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 15995 lb GVWR, 215
2020	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B2KS806624 C/W: GM V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, 150 in Wheelbase, Morgan 16 ft x 96 in Wide x 85 in		/75R17.5, Spring Suspension, 153 in Wheelbase, 16 ft x 102 in Wide x 94 in High Body, Liftgate Usage: 169,507 Mi Notes: LOCATED-IN-LAKE WORTH-TX Asset located in: Lake Worth, TX
	High Body, Liftgate Usage: 187,646 Mi <b>Asset located in</b> : Lake Worth, TX	2027	2015 Ram 5500 4x2 Van Truck S/N: 3C7WRMDL6FG506015 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine,
2021	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W168K7008461 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6880 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, Steel, 215/85R16, Spring Suspension, 151 in Wheelbase, Morgan		Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, Morgan 16 ft x 96 in Wide x 80 in High Body, Curbside Door, Liftgate Usage: 169,865 Mi Asset located in: Lake Worth, TX
	16 ft x 96 in Wide x 85 in High Body, Liftgate Usage: 236,438 Mi  Asset located in: Lake Worth, TX	2028	<b>2022 GMC G3500 4x2 Van Truck</b> S/N: 7GZ37TC76NN001010 C/W: GM V8 6.6 L Gasoline Engine, 2022 US
2022	2019 Isuzu NPR HD 4x2 COE Van Truck S/N: JALC4W16XK7009739 C/W: Isuzu 4HK1TC 4 Cylinder Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 6856 Engine hrs, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, 215/85R16, Spring Suspension, 151 in Wheelbase, 16 ft x 96 in		EPA Label, Requires Diesel Exhaust Fluid, 3838 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225/75R16 Front Tires, 224/75R16 Rear Tires, Spring Suspension, 176 in Wheelbase, 16 ft x 96 in Wide x 80 in High Body, Curbside Door Usage: 109,545 Mi  Asset located in: Lake Worth, TX
	Wide x 94 in High Body, Liftgate Usage: 271,219 Mi  Asset located in: Lake Worth, TX		2020 GMC Savana 3500 4x2 Van Truck S/N: 7GZ37TCG8LN010465 C/W: GMC Vortec V8 6.0 L Gasoline Engine,
2023	2018 Isuzu NPR HD 4x2 COE Van Truck S/N: 54DC4W1B9JS802729 C/W: V8 6.0 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, 6630 lb Front Axle, 11020 lb Rears, 14500 lb GVWR, 225 /70R19.5, Spring Suspension, Supreme 16 ft x 96 in Wide x 94 in High Body, Liftgate Usage: 105,477 Mi Asset located in: Lake Worth, TX		7655 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16, Curbside Door Usage: 150,248 Mi Asset located in: Lake Worth, TX
		2029A	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP9L1182263 C/W: V6 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 74 in High Body Usage: 89,341 Mi

Notes: TITLE SHOWS NOT ACTUAL MILEAGE

Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
2030	2019 Ford E350 4x2 Van Truck S/N: 1FDWE3FS8KDC22914 C/W: Ford 6.8 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, Steel, 225 /75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 78,825 Mi Asset located in: Humble, TX	2043	2021 Nissan NV200 4x2 Cargo Van S/N: 1N6BF0KY5MN807503 C/W: V6 4.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 3825 lb Front Axle, 5875 lb Rears, 9100 lb GVWR, 245/70R17, Spring Suspension, 146 in Wheelbase, 9 ft x x 50 in High Body Usage: 80,655 Mi Asset located in: Midland, TX	
2031	<b>2019 Ford E350 4x2 Van Truck</b> S/N: 1FDWE3FS4KDC15555	2044	<b>2016 Ford Transit 350 Passenger Van</b> S/N: 1FBZX2ZM3GKA06205	
	C/W: Gasoline Engine, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225/75R16, Spring Suspension, 176 in Wheelbase, Morgan 16 ft x 96 in Wide x 78 in High Body Usage: 81,416 Mi		C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	
2038	Asset located in: Lake Worth, TX  2015 Ford E-350 4x2 14-Seat Transit Bus S/N: 1FDEE3FS2FDA21995		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Midland, TX	
	C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2014 US EPA Label,	2045	2014 Freightliner Sprinter 3500 4x2 Van Truck	
	225/75R16, Spring Suspension, 156 in Wheelbase Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		S/N: WDPPF4CC7E9564671 C/W: V6 3.0 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 4080 lb Front Axle, 7720 lb Rears, 11030 lb GVWR,	
2039	2013 International PC505 4x2 Bus S/N: 5WEASSKP5DH416814	1	215/85R16, Spring Suspension, 16 ft x 86 in Wide x 78 in High Body, Curbside Door, Walk- Up Ramp	
	C/W: Air Conditioner, Allison Automatic Transmission, 5483 hrs Carrier Engine, International MaxxForce 7 V8 6.4 L Diesel 260		Usage: 313,155 Mi <b>Asset located in</b> : Lake Worth, TX	
	hp Engine, 2012 US EPA Label, Aluminum Outer Wheels, 255/70R22.5, Air Ride Suspension, 305 in Wheelbase Usage: 173,055 Mi Asset located in: Lake Worth, TX	2046	S/N: 1GCWGAF70R1101434 C/W: V8 6.6 L Gasoline Engine, 2024 US E Label, Automatic Transmission, Air	S/N: 1GCWGAF70R1101434 C/W: V8 6.6 L Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera,
2040	2011 BlueBird 4x2 36-Seat School Bus S/N: 1BAKGC5A2CF286372		Towing Hitch Usage: 131 Mi <b>Asset located in</b> : Lake Worth, TX	
	C/W: Air Conditioner, Automatic Transmission, 11R22.5, Spring Suspension, 275 in Wheelbase Usage: 105,391 Mi <b>Asset located in</b> : Humble, TX	2047	2016 Ford Transit 250 4x2 Cargo Van S/N: 1FTYR2ZM4GKA77642 C/W: Ford V6 3.7 L Gasoline Engine, 2016 US	
2041	2012 BlueBird 4x2 47-Seat School Bus S/N: 1BAKGL5A8CF286375 C/W: Air Conditioner, Automatic Transmission, V8 8.1 L Liquefied Natural Gas (LNG) Engine,		EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9000 lb GVWR, 235 /65R16, Spring Suspension, 138 in Wheelbase, 9 ft x 78 in Wide x 56 in High Body Usage: 214,134 Mi	
	2010 US EPA Label, 11R22.5, Spring Suspension, 274 in Wheelbase Usage: 118,477 Mi <b>Asset located in</b> : Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED; DOCUMENTS TO PROCESS TITLE; SELLING	
2042	2007 Chevrolet C5500 4x2 26-Seat Transit Bus S/N: 1GBE5V1G67F425251 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, GM V8 8.1 L Gasoline Engine, 2007 US EPA Label, 225/70R19.5, Spring Suspension, 232 in Wheelbase, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 80,972 Mi Asset located in: Lake Worth, TX		WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	
		2048	2020 Ram Promaster Cargo Van S/N: ZFBHRFAB3L6R54595 Usage: Not Available	
			Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
СНОІС	E OF 2 - Lot #'s: 2049, 2050	2054	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E27M1496972 C/W: ford 4 Cylinder 2.0 L Gasoline Engine,	
2049	2019 Ram ProMaster 2500 4x2 Cargo Van S/N: 3C6TRVDG2KE531385 C/W: V6 3.6 L Gasoline 280 hp Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 3.86:1 Axle Ratio,		2021 US EPA Label, Automatic Transmissio 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 205/55R16, 121 in Wheelbase, 6 ft x in Wide x 44 in High Body Usage: 46,847 Mi Asset located in: Midland, TX	2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 205/55R16, 121 in Wheelbase, 6 ft x 72 in Wide x 44 in High Body Usage: 46,847 Mi
	8900 lb GVWR, 225/75R16, Spring Suspension, 159 in Wheelbase, 11 ft x 80 in Wide x 76 in High Body, Curbside Door Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	2055	2016 Ford Transit 150 4x2 Cargo Van S/N: 1FTYE1YM9GKB48843 C/W: V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5070 lb Rears, 8600 lb GVWR, 235/65R16 Spring Suspension, 132 in Wheelbase, 9 ft x 96 in Wide x 55 in High Body, Curbside Door Usage: 144,833 Mi	
2050	2019 Ram ProMaster 2500 4x2 Cargo Van		Asset located in: Lake Worth, TX	
	S/N: 3C6TRVDGXKE557829 C/W: V6 3.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 8900.0 lb GVWR, 225 /75R16, Spring Suspension, 159 in Wheelbase, 11 ft x x 76 in High Body, Curbside Door Usage: 44,182 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	2056	2020 Mercedes-Benz 135 WB 4x2 Cargo Van S/N: W1YV0CEY3L3688564 C/W: Mercedes-Benz 2.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 3307 lb Front Axle, 3307 lb Rears, 6614 lb GVWR, 225/55R17, Spring Suspension, 136 in Wheelbase Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
2051	2019 GMC Savana 1500 Cargo Van	5000	2024 Landhonor ABC-13-125A Articulating	
	S/N: 1GTW7BFP3K1277096 C/W: V6 4.3 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 91,916 Hr Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	5000	Skid Steer Brush Cutter (Unused) S/N: HL00249 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	
2052	2007 Chevrolet 2500 Express 4x2 Cargo Van S/N: 1GCGG25V471223513 C/W: Chevy V8 4.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 4100 lb		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	
	Front Axle, 5360 lb Rears, 8600 lb GVWR, 245 /75R16, Spring Suspension, 139 in Wheelbase, 9 ft x 72 in Wide x 54 in High Body, Curbside Door Usage: 135,450 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	5001	2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
CHOIC	E OF 2 - Lot #'s: 2053, 2054		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
2053	2021 Ford Transit Connect 4x2 Cargo Van S/N: NM0LS7E25M1496971 C/W: 4 Cylinder 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 2700 lb Front Axle, 2875 lb Rears, 5302 lb GVWR, 215 /55R16, 121 in Wheelbase, 6 ft x x 44 in High Body Usage: Not Available		Asset located in: Lake Worth, TX	

Asset located in: Midland, TX

Lot #	Details	Lot #	Details
5002	2024 Raytree RMC72 72 in Skid Steer Brush Cutter (Unused)  S/N: C20241007112  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	5013	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5003	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5014	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5004	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE
5005	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5006	All-Star 80 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5015	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5007	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5008	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5016	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Wolverine BC-13-72W 72 in Skid Steer
5009	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Brush Cutter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5010	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5011	2023 Mower King SSRC 72 in Skid Steer Brush Cutter S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5017	Asset located in: Lake Worth, TX  2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available
5012	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC20240919 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5018	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5027	2024 Suihe SSBC 66 in Skid Steer Brush Cutter (Unused)  S/N: 001602498  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5019	All-Star 72 in Skid Steer Brush Cutter (Unused)	5028	2024 Suihe SSBC 0 ft 66 in Skid Steer Brush
5020	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  All-Star 72 in Skid Steer Brush Cutter (Unused)	_	Cutter (Unused)  S/N: 001602505  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5021	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5029	Quantity of (2) 2024 Wolverine SBM-12-72W 72
5022	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available		in Sickle Bar Skid Steer Mower (Unused) S/N: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
5023	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
	Asset located in: Lake Worth, TX		<ul> <li>MAY NOT BE AN EXACT REPRESENT</li> </ul>
5024	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5030	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused)
5025	2021 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused)		S/N: SBM202409115 Usage: Not Available
	S/N: SSRC21092604 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5026	Wolverine 70 in Pallet Skid Steer Brush Cutter		THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX	5031	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202409114 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5032	2023 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW02312 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5033 5034	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Handy HAB72 72 in Skid Steer Broom (Unused)	5041	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: AB202409111 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5042	Asset located in: Lake Worth, TX  2024 Wolverine PBS-11-72W 72 in Skid Steer Sweeper (Unused)  S/N: ZW00289 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5035	2024 Handy HAB72 72 in Skid Steer Broom (Unused) S/N: AB202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5043	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 Wolverine MBS-11-48W 48 in Mini Skid Steer Sweeper (Unused) S/N: ZW00327 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCTHE PRODUCT IMAGES
5036	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		
5037	All-Star 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5038	JCT 72 in Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5044	2014 Bobcat 144 Skid Steer Sweeper S/N: 714428587 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
5039	Bobcat 84 in Skid Steer Angle Broom S/N: 231412786 Usage: Not Available Asset located in: Lake Worth, TX	5045	Asset located in: Lake Worth, TX  2024 TOFT TOFT750 Skid Steer Post Driver (Unused) S/N: JW43Z5685
5040	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5046	2024 TOFT TOFT680 Skid Steer Post Driver (Unused) S/N: JW40Z17058 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5047	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202406543 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5048	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202409560 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5054	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406092 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5049		5055	2024 Trojan TH35SSL Skid Steer Breaker
3049	2024 Raytree RMH680 Skid Steer Breaker (Unused) S/N: HH20241012180 Usage: Not Available Asset located in: Lake Worth, TX	3033	(Unused) S/N: SB30YOM20247065 Usage: Not Available Asset located in: Lake Worth, TX
5050	2024 Wolverine CB-11-750F Skid Steer Breaker (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	5056	Mini Skid Steer Breaker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5057	2024 TOFT TOFT750 Skid Steer Breaker (Unused) S/N: JW43Z5799 Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5058	2024 TOFT TOFT680 Skid Steer Breaker (Unused)
5051	2024 Jisan JSB400SL Skid Steer Breaker (Unused)		S/N: JW40Z17265 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: 2404298 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5059	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409143 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5052	2024 Jisan JSB400SL Skid Steer Breaker		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	<b>(Unused)</b> S/N: 2404295		Asset located in: Lake Worth, TX
5053	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Elephant EPB400SL Skid Steer Breaker (Unused)	5060	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409145 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: 2406091		Asset located in: Lake Worth, TX
	Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5061	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202409142 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5062	2024 Handy HPD680 Skid Steer Post Driver (Unused)  S/N: PD202409144 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5069	5068 2024 Raytree RMPP680 Skid Steer Post Drive (Unused)  S/N: PP20241012196  C/W: 7.9" Domed Cup Inside Diameter, (2)  Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF TH
5063	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00017 Usage: Not Available		ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX  2024 Raytree RMPP680 Skid Steer Post Driver
5064	Asset located in: Lake Worth, TX  2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: PP20241012195 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual, THE PRODUCT IMAGES SHOWN ARE FOR
5065	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 Jisan JSB400SLT Skid Steer Post Driver (Unused) S/N: CP2407183 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5066	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5071	Asset located in: Lake Worth, TX  2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused)  S/N: HL00381 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5072	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00384 Usage: Not Available Asset located in: Lake Worth, TX
5067	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20241009192 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/	5073	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00382 Usage: Not Available Asset located in: Lake Worth, TX
		5074	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00383 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5075	<b>2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused)</b> S/N: VR202409472 Usage: Not Available	5081	TMC 72 in Skid Steer Vibratory Roller S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5082	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20241008159 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5076	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409474 Usage: Not Available	5083	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 Handy HST48 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: 8 In Dirt & Rock Chain, Crumbling Shoe Usage: Not Available
5077	2024 Handy HVR76 72 in Skid Steer Vibratory Roller (Unused) S/N: VR202409473 Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 Handy HST48 48 in Skid Steer Trencher (Unused) S/N: TR202409613 C/W: 8 In Dirt & Rock Chain, Crumbling Shoe
5078	2024 Raytree RMVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR20241012184 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5085	<b>2024</b> Suihe SST-1000/200 Skid Steer Trencher (Unused) S/N: 001702343
5079	2024 Suihe SSVR-72 72 in Skid Steer Vibratory Roller (Unused) S/N: 001300876 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5086	Asset located in: Lake Worth, TX  2024 Suihe SST-1000/200 Skid Steer Trencher
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		(Unused)
5080	2024 Wolverine VR-11-66W 66 in Skid Steer Vibratory Roller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: 001702342 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5087	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	Steer Dozer (Unused) S/N: SD202409300 Usage: Not Available Notes: THE PRODUCT IMAGES SH FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  5093 2024 Handy HSD96 96 in 6 Way do Steer Dozer (Unused) S/N: SD202409301 Usage: Not Available Notes: THE PRODUCT IMAGES SH FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  5094 2024 Raytree RSWD96 94 in Six With Dozer (Unused) S/N: SW20241012042 C/W: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX  5095 2024 Suihe SSD-YS86 86 in 4-Way Dozer (Unused) S/N: 031789472 C/W: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  5096 2024 Suihe SSD-YS86 86 in 4-Way Dozer (Unused) S/N: 031789296 C/W: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE	S/N: SD202409300 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Handy HSD96 96 in 6 Way dozer Skid Steer Dozer (Unused)	
5088	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT		Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY A MAY NOT BE AN EXACT REPRESENTAT THE ACTUAL PRODUCT	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		S/N: SW20241012042 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5089	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused)  S/N: 031789472  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5090	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused)  S/N: 031789296  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5091	2024 Handy HSD96 96 in 6 Way Skid Steer Dozer (Unused) S/N: SD202409302 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5097	2024 Suihe SSD-YS86 86 in 4-Way Skid Steer Dozer (Unused) S/N: 031789880 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5104	2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202409216 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused)	
5098	2024 Wolverine DB-15-84W 84 in Angle Skid Steer Dozer (Unused)		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5106	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5099	Asset located in: Lake Worth, TX  All-Star 72 in Skid Steer Dozer (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5107	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5100	Mid-State 72 in Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5108	72 in Skid Steer Gravel Leveler Skid Steer Grader (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5101	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202409595 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	Tiller (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGE FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Asset located in: Lake Worth,  5110  2024 Wolverine TL-12-72W 7 Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES	5109	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5102	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202409594 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5103	2024 Handy HGB86 96 in Skid Steer Grader (Unused) S/N: GB86202409217 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5111	111 2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5117	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5118	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5119	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409392 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in,
5112	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: Not Available		(1) 18 in Bits, One Crate Usage: Not Available <b>Notes</b> : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	S/N: SSA2409390 C/W: Quick Coupler Bracket, (1) 10 (1) 18 in Bits, One Crate Usage: Not Available  Notes: THE PRODUCT IMAGES SHE FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  5121 2024 Handy SSA18 Skid Steer Aug S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHE FOR ILLUSTRATION PURPOSES OF STATE	C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available
5113	Asset located in: Lake Worth, TX  2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402687		
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409393 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5114	2024 Suihe SSTL 72 in Skid Steer Tiller (Unused) S/N: 002402685 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5122	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409394 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	S/N: SSA2409389 C/W: (1) 10 in bit, (1) 12 in bit, (1) 1 crate Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES ON	<b>2024 Handy SSA18 Skid Steer Auger (Unused)</b> S/N: SSA2409389
5115	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5116	All-Star 72 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT

Lot #	Details	Lot #	Details
5124	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2409391 C/W: Quick Coupler Bracket, (1) 10 in, (1) 12 in, (1) 18 in Bits, One Crate Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5128	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused)  S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5125	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5129	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20241012230 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5126	Asset located in: Lake Worth, TX 2024 Wolverine ADB-13-1218R Skid Steer	5130	2024 Raytree RMA42 Skid Steer Auger
5126	Auger (Unused)  S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: A20241012229 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
		5131	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503461 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR
5127	2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5132	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503471 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5133	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503502 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5142	2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409146 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Handy HBC72 Concrete Crusher (Unused) S/N: CC202409147 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5134	Belltec LC350 Skid Steer Auger (Unused) S/N: L09284 C/W: Quick Attach 2 in Hex Head Auger Usage: Not Available Asset located in: Lake Worth, TX	5144	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Handy HBC72 Concrete Crusher (Unused)
5135	2018 Bobcat 15C Skid Steer Auger S/N: 944261257 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		S/N: CC202409148 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5136	<b>16 in Mini Skid Steer Auger (Unused)</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5145	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20241010172 C/W: THE PRODUCT IMAGES SHOWN ARE
5137	Quantity of (3) Mini Skid Steer Augers (Unused) S/N: Not Available C/W: (1) 16 in, (1) 12 in, (1) 8 in Bits Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
5138	Pengo 10-2500 Auger Bit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	5146	2024 Landhonor CC-11-08V 24 in Skid Steer Concrete Crusher (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5139	Asset located in: Lake Worth, TX  2024 Raytree RMSC78 72 in Skid Steer Soil Conditioner  S/N: SC20241010053  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5147	2024 Handy HFB52 Skid Steer Feller Buncher (Unused) S/N: FB202409119 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5140	Level Best LBSS6 72 in Skid Steer Laser Grading Box Blade S/N: 1187 Usage: Not Available Asset located in: Lake Worth, TX		2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused) S/N: RC202409626 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5141	Raytree 28 in Skid Steer Hyd Pole Jack (Unused) S/N: 20231025031 Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5149	2024 Handy HSRC12 Rotating Skid Steer Pole Clamp (Unused) S/N: RC202409627 Usage: Not Available	5158	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5159	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5150	2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5160 5161 5162	5160 Kubota PS2086 84 in Skid Steer Grain S/N: 1064217K C/W: 3 Pt Hitch Usage: Not Available Asset located in: Lake Worth, TX 5161 2024 Handy HSNC78 72 in Skid Steer	Kubota PS2086 84 in Skid Steer Grain Planter S/N: 1064217K C/W: 3 Pt Hitch Usage: Not Available Asset located in: Lake Worth, TX 2024 Handy HSNC78 72 in Skid Steer Power Rake (Unused)
5151	Asset located in: Lake Worth, TX  2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused)  S/N: RP202409465 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		S/N: SC202409110 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Handy HSNC78 72 in Skid Steer Power	
5152	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Landhonor FW-13-15000G 15000 lb Skid Steer Winch (Unused) S/N: Not Available		Rake (Unused)  S/N: SC202409112  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
	Usage: Not Available  Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	
5153	2024 Industrias America Post/Tree Puller (Unused) S/N: HPOST202421670 Usage: Not Available Asset located in: Lake Worth, TX	5163 2024 Handy HSN Rake (Unused) S/N: SC2024091 Usage: Not Avail Notes: THE PROI FOR ILLUSTRATI MAY NOT BE AN THE ACTUAL PR	Rake (Unused) S/N: SC202409111 Usage: Not Available Notes: THE PRODUCT IMAGE	S/N: SC202409111
5154	2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421749		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	
	Usage: Not Available  Asset located in: Lake Worth, TX	5164	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused)	
5155	2024 Industrias America Post/Tree Puller (Unused) S/N: POST202421748 Usage: Not Available Asset located in: Lake Worth, TX	_		S/N: HL01191 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5156	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TY	
5157	All-Star Skid Steer Tree/Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5165	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: HL01192 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5171	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409925 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Asset located in: Lake Worth, TX Quantity of (2) 2024 Landhonor BH-11-06H Big	
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		Arm Skid Steer Backhoe (Unused) S/N: Not Available	
5166	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused)		C/W: 18 In Bucket, One Crate Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: HL01193 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5173	All-Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX	
5167	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Poutroe PTSC20 21 in Transverse Skid	5174	All Star Skid Steer Backhoe (Unused) S/N: Not Available C/W: 14 In Bucket Usage: Not Available Asset located in: Lake Worth, TX	
5107	2024 Raytree RTSG30 31 in Transverse Skid Steer Stump Grinder (Unused)  S/N: TS20241012241  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	5175	Bobcat 709FDS Skid Steer Backhoe S/N: 270020062 C/W: NO BUCKET Usage: Not Available Asset located in: Lake Worth, TX	
		5176	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused)	
5168	2024 Raytree RMSG29 29 in Skid Steer Stump Grinder (Unused) S/N: SG20241010315		S/N: HM20241012049 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	5178	Mulcher (Unused)  S/N: HM20241009048  C/W: THE PRODUCT IMAGES SHOWN A FOR ILLUSTRATION PURPOSES ONLY A MAY NOT BE AN EXACT REPRESENTAT	· · ·
5169	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409926		Usage: Not Available  Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012445 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5170	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202409924 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5179	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012450 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5186	2024 Raytree RMDM70 60 in Skid Steer Mulcher (Unused) S/N: DM20241012194 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5180	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20241012447 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5187	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241009067 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5181	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused)  S/N: DRM20241008440  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5188	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241010069 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5182	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409470 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5189	2024 Raytree RMBD50 Drum Skid Steer Mulcher (Unused) S/N: LM20241009068 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
5183	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202409469 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5190	All-Star 78 in E-Series Rock Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX All-Star 78 in Skeleton Skid Steer Grapple
5184	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Handy HSDM70 Skid Steer Mulcher	5191	Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: DM202409332 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5192	All-Star 72 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5185	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124060901E Usage: Not Available Asset located in: Oklahoma City, OK	5193	All-Star 72 In E-Series Rock Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5194	All-Star 72 In Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	5205	All Star 74 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5195	Asset located in: Lake Worth, TX  2024 Landhonor RG-11-5000G Rotating Skid Steer Grapple (Unused)  S/N: HL00372 Usage: Not Available Asset located in: Lake Worth, TX	5206 	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5196	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5207	All-Star 72 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5197	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5208	All Star 72 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5198	All-Star 48 in Rock W/Teeth Skid Steer Grapple Bucket (Unused) S/N: Not Available	5209	All Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
<u></u> 5199	Usage: Not Available Asset located in: Lake Worth, TX 72 in Skid Steer Grapple Bucket	5210	All-Star E-Series Root Skid Steer Grapple (Unused) S/N: Not Available
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Usage: Not Available  Asset located in: Lake Worth, TX
5200	Kit Containers 48 in Skeleton Mini Skid Steer Grapple (Unused) S/N: B14E1606 Usage: Not Available	5211	All Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5201	Asset located in: Lake Worth, TX  All-Star 80 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5212	All-Star 68 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5202	Asset located in: Lake Worth, TX  All-Star 78 In E-Series Root Skid Steer Grapple (Unused)  S/N: Not Available Usage: Not Available	5213	All-Star 68 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5203	Asset located in: Lake Worth, TX  All-Star 78 In E-Series Root Skid Steer Grapple (Unused)  S/N: Not Available Usage: Not Available	5214	Mid-State 60 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5204	Asset located in: Lake Worth, TX  All Star 78 in E-Series Root Skid Steer Grapple (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<del>5215</del>	All Star 48 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5216	36 in Q/C Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5223	All-Star 80 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available
5217	All-Star 40 in Stump Skid Steer Grapple		Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5224	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available
5218	All-Star 40 in Stump Skid Steer Grapple		Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5225	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset Inserted in: Lake Worth, TV
5219	All-Star 40 in Stump Skid Steer Grapple Bucket	5006	Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5226	All-Star 78 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5220	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused)	5227	All-Star 74 in Skid Steer Grapple Bucket
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	0227	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	5228	All Star 72 in E-Series Skid Steer Grapple
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Bucket (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5221	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5229	2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	<u>`</u>	5230	2024 Wolverine GB-11-72W 72 in Skid Steer
5222	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5231	Raptor 72 in Skid Steer Grapple Bucket (Unused) S/N: 23400249 Usage: Not Available Asset located in: Lake Worth, TX	5241	All Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5232	All-Star 68 in E-Series Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5242	All-Star 40 in Stump Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5233	Cat 66 in Skid Steer Grapple Bucket S/N: A4164CB50022 Usage: Not Available Asset located in: Lake Worth, TX	5243	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5234	<b>30 in Mini Skid Steer Grapple Bucket (Unused)</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5244	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5235	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5245	All-Star 84 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5236	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5246	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808766 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
5237	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5238	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5247	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808741 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5239	2024 Suihe SSRGB-72 72 in Skeleton Skid Steer Grapple Bucket (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5240	Asset located in: Lake Worth, TX  All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5248	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808738 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5257	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5258	Mid-State 68 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5259	Mid-State 68 In E-Series Skid Steer Root Rake (Unused)
5249	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: 001808746		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE	5260	All-Star 68 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5261	Mid-State 60 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available
5250	All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5262	Asset located in: Lake Worth, TX  Mid-State 60 In E-Series Skid Steer Root Rake (Unused)  S/N: Not Available Usage: Not Available
5251	All-Star 78 In E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5263	Asset located in: Lake Worth, TX  Mid-State 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5252	All-Star 78 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5264	All-Star 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5253	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5265	All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5254	All-Star 74 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5266	All-Star 72 in E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5255	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5267	All-Star 60 in E-Series Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5256	All-Star 72 In E-Series Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5268	Asset located in: Lake Worth, TX  All-Star 84 in Skid Steer Root Rake (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5269	84 in Skid Steer Ripper Scarifier (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5276	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241009347 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5270	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused) S/N: VSB202409688		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5277	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20241012354 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5271	2024 Handy HVSB72 72 in Screening Skid Steer Bucket (Unused)		Asset located in: Lake Worth, TX
	S/N: VSB202409689 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5278	Mid-State General Purpose 84 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5279	Mid-State General Purpose 80 in Skid Steer Bucket (Unused)
5272	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: ATT SPERMENT IMAGES CHOWN ARE		S/N: Not Available Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	5280	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5273	2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5281	Mid-State 84 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5282	All-Star 80 In Low Pro W/Teeth Skid Steer
5274	Asset located in: Lake Worth, TX  2024 Skyway WBCT-4IN1 Backhoe Loader Bucket (Unused)		Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5283	All-Star 80 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5275	Asset located in: Lake Worth, TX  2024 Raytree RMVB78F 70 in (Unused)  S/N: SB20241009346  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5284	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5285	Mid-State General Purpose 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5286	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Bucket (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN AR  FOR ILLUSTRATION PURPOSES ONLY AN  MAY NOT BE AN EXACT REPRESENTATION  THE ACTUAL PRODUCT  Usage: Not Available  Asset located in: Lake Worth, TX	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5287	All-Star 78 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Lake Worth, TX		Bucket (Unused)
5288	2024 Kit Containers QT-DB-S78 78 in Skid Steer Bucket (Unused) S/N: B28J1613 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5289	Teran BKT26278 78 in Skid Steer Bucket - Fits		Asset located in: Lake Worth, TX
	Cat 226 (Unused) S/N: 1220 C/W: 0.5m3 with 8HD Tips for CAT 226 - 299 Usage: Not Available Asset located in: Lake Worth, TX	5298	Mid-State 74 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5290	Mid-State 78 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5299	Mid-State 74 In Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5291	Kit Containers 78 in Skid Steer Bucket (Unused) S/N: B26J1610 Usage: Not Available Asset located in: Lake Worth, TX	5300	72 in Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5292	<b>78 in General Purpose Skid Steer Bucket</b> S/N: Not Available Usage: Not Available	5301	Asset located in: Lake Worth, TX  72 In Low Pro W/Teeth Skid Steer Bucket
	Asset located in: Lake Worth, TX	_	<b>(Unused)</b> S/N: Not Available
5293	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5302	72 In Low Pro W/Teeth Skid Steer Bucket (Unused) S/N: Not Available
5294	All-Star 74 In Low Pro W/Teeth Skid Steer Bucket (Unused)		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5303	Mid-State General Purpose 72 in Skid Steer Bucket (Unused) S/N: Not Available
5295	2024 Warrior WSSGB-1740 Backhoe Loader Bucket (Unused)		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5304	<b>72 in General Purpose Skid Steer Bucket</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	5305	2020 Bobcat 7326129/Teeth Skid Steer Bucket S/N: 004164 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5306	Teran BKT26272 72 in Skid Steer Bucket - Fits Cat 226 (Unused)  S/N: 3142  C/W: 0.45m3 with 8 HD Tips to fit Cat 226 - 299  Usage: Not Available	5317	Mid-State 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5307	Asset located in: Lake Worth, TX  Mid-State 72 In Low Profile Skid Steer Bucket (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	-5318 -5319	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5308	All Star 72 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	-5320	All-Star 60 in Low Profile Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Teran BKT26260 60 in C Skid Steer Bucket -
5309	All Star 68 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5520	Fits Cat 226 (Unused)  S/N: 3119  C/W: 0.35m3 with 7 HD Tips to fit Cat 226 - 299  Usage: Not Available  Asset located in: Lake Worth, TX
5310	All-Star 68 in General Purpose Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5321	Bobcat 80 in General Purpose Skid Steer Bucket S/N: 6726344 Usage: Not Available Asset located in: Lake Worth, TX
5311	Mid-State 68 In Low Pro w/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5322	Arrow 2307206BUN 74 in Skid Steer Bucket S/N: YB12397 Usage: Not Available Asset located in: Lake Worth, TX
5312	Asset located in: Lake Worth, TX  Mid-State 68 In Low Profile Skid Steer Bucket (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5323	2018 Bobcat 68 67 in General Purpose Skid Steer Bucket S/N: BS77771 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Oklahoma City, OK
5313	2018 Takeuchi 68" Smooth Skid Steer Bucket S/N: VG1708386 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5324	67 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5315	2024 Kit Containers QT-DB-T66 66 in Skid Steer Bucket (Unused) S/N: B23J1617	5325	61 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5316	Usage: Not Available  Asset located in: Lake Worth, TX  2024 Kit Containers QT-DB-S66 66 in Skid Steer Bucket (Unused)	5326	2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused) S/N: B30J1625 Usage: Not Available
	S/N: B23J1632 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5327	Asset located in: Lake Worth, TX  2024 Kit Containers QT-SNB-84 84 in Snow & Litter Skid Steer Bucket (Unused)  S/N: B29J1617 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5328	Mid-State 78 In Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5339	All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5329	All-Star 74 In Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5340	Kit Containers 72 in Rock Skid Steer Bucket (Unused) S/N: B21J1615 Usage: Not Available Asset located in: Lake Worth, TX
5330	Mid-State 80 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5341	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5331	Mid-State 68 in Snow & Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5342	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5332	All Star 68 in Snow & Litter Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5343	All-Star 68 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TV
5333	All-Star 80 In Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	Skid Steer Bucket (L S/N: Not Available C/W: THE PRODUCT FOR ILLUSTRATION MAY NOT BE AN EX THE ACTUAL PRODU Usage: Not Available Notes: THE PRODUC FOR ILLUSTRATION	2024 Landhonor RB-14-84W 84 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5334	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available C/W: With Teeth Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5335	All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5345	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Landhonor RB-14-78W 78 in Skeleton
5336	Asset located in: Lake Worth, TX  All-Star 84 in Rock W/Teeth Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5343	Skid Steer Bucket (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF  THE ACTUAL PRODUCT  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE
5337	Kit Containers 82 in Rock Skid Steer Bucket (Unused) S/N: B22J1604 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5338	Asset located in: Lake Worth, TX  All-Star 72 in Rock W/Teeth Skid Steer Bucket (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5346	Kit Containers 76 in Skeleton Skid Steer Bucker (Unused) S/N: B17J1620 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5347	Kit Containers 76 in Skeleton Skid Steer Bucket (Unused) S/N: B16J1620 Usage: Not Available Asset located in: Lake Worth, TX	5355	Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5348	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL' MAY NOT BE AN EXACT REPRESENT
5349	2024 Landhonor RB-14-72W 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5356 5357	Asset located in: Lake Worth, TX  All-Star 40 in Stump Skid Steer Bucket (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5350	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5358	All-Star 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5351	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5359	2024 Kit Containers QT-TS-40 40 in Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5352	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5360	2024 Kit Containers QT-RD 36 in Skeleton Stump Skid Steer Bucket (Unused) S/N: B28J1958 Usage: Not Available Asset located in: Lake Worth, TX
5353	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5361	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5354	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5362	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5368	2024 Suihe SSBG 75 in Skid Steer Landplane (Unused)  S/N: 005500748  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5363		5369	<b>72 in Skid Steer Landplane (Unused)</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5370	<b>42 in Mini Skid Steer Landplane (Unused)</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5371	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409282 Usage: Not Available
5364	2024 Kit Containers 2YFT-SST 5 ft 7 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 7 in Long x 4 ft 7 in Wide x 3 ft 10 in High		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5372	2024 Handy HLS35 Skid Steer Log Splitter
5365	2024 Kit Containers 2YFT-SST 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: LS202409283 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5366	2024 Kit Containers 1.5YFT-SST Skid Steer Dump Hopper (Unused) S/N: B29E1207 Usage: Not Available Asset located in: Lake Worth, TX	5373	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202409281 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5367	2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
		5374	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused) S/N: LS20241012044 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

1 64 #	Detaile	1 64 #	Detaile
Lot # 5375	Details  Mid-State 80 in Skid Steer Landplane (Unused)	Lot # 5382	Details 2024 Handy HSSB72 72 in Skid Steer
	S/N: Not Available Usage: Not Available		Snowblower (Unused) S/N: SBM202409137
	Asset located in: Lake Worth, TX	_	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5376	<b>Mid-State 80 in Skid Steer Landplane (Unused)</b> S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5377	(Unused) S/N: SP202409130 Usage: Not Available	5383	2024 Kit Containers QT-RR-70 70 in Skid Steer Ripper Scarifier (Unused) S/N: B24J1305 Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	F204	<u> </u>
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5384	<b>84 in Skid Steer Ripper Scarifier (Unused)</b> S/N: Not Available Usage: Not Available
5378	2024 Handy HSP24 Skid Steer Planer (Unused)		Asset located in: Lake Worth, TX
	S/N: SP202404110 Usage: Not Available Notes: .	5385	2024 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5379	Asset located in: Lake Worth, TX  2024 Landhonor VPC-11-72W 72 in Skid Steer Plate Compactor (Unused) S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
			Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5386	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available
	Asset located in: Lake Worth, TX		Usage: Not Available
5380	2024 Handy HSSB72 72 in Skid Steer		Asset located in: Lake Worth, TX
	Snowblower (Unused) S/N: SBM202409139	5387	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused)
	Usage: Not Available		S/N: Not Available
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Usage: Not Available  Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5388	2024 Landhonor HRB-11-127A Hydraulic
	Asset located in: Lake Worth, TX		Rotating Skid Steer Forks (Unused)
5381	2024 Handy HSSB72 72 in Skid Steer Snowblower (Unused)		S/N: HL00018 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available
	S/N: SBM202409138 Usage: Not Available		Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5389	2024 Landhonor HRB-11-127A Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00017 C/W: 42 in Forks, 127° Hydraulic Rotating Base Usage: Not Available
		I	Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5390	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409301 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5396	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused)  S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5391	2024 Handy HF2T 48 in Skid Steer Forks		THE ACTUAL PRODUCT
	<b>(Unused)</b> S/N: HF202409297		Asset located in: Lake Worth, TX
	C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5397	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused)  S/N: Not Available  C/W: Fork Positioner, THE PRODUCT IMAGES  SHOWN ARE FOR ILLUSTRATION PURPOSES  ONLY AND MAY NOT BE AN EXACT  REPRESENTATION OF THE ACTUAL PRODUCT  Usage: Not Available
5392	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409299 C/W: Fork Positioner Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5398	2024 Wolverine PFA-11-3300G 48 in Skid Ste Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES
5393	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409300 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5399	2024 Wolverine PFA-11-3300G 48 in Skid Steer
5394	Asset located in: Lake Worth, TX  2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202409298 C/W: Fork Positioner Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5399	Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5395	Quantity of (4) 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: (4) Universal Adapter Plates, One Crate Usage: Not Available	5400	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5401	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5402	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX	5413	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5403	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Lake Worth, TX	5414	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5404	Handy HSRF48 48 in Rotating Skid Steer Forks (Unused) S/N: RF202401136 Usage: Not Available Asset located in: Lake Worth, TX	5415	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5405	2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5416	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5406	Asset located in: Lake Worth, TX  2024 Kit Containers MSS-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available	5417	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5407	Usage: Not Available Asset located in: Lake Worth, TX  2024 Kit Containers QT-45-FF-42 42 in Skid	5418	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5419	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5408	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5420	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5409	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5421	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5410	Asset located in: Lake Worth, TX  2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available	5422	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5411	Usage: Not Available Asset located in: Lake Worth, TX  2024 Kit Containers QT-45-FF-42 42 in Skid	5423	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
	Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5424	Asset located in: Lake Worth, TX  All-Star 48 in Skid Steer Forks (Unused)  S/N: Not Available Usage: Not Available
5412	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5425	Asset located in: Lake Worth, TX  All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5426	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5439	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5427	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5440	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5428	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5441	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5429	Land Pride 48 in Skid Steer Forks S/N: 999569 Usage: Not Available Asset located in: Lake Worth, TX	5442	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5430	Trojan SPF15 48 in Skid Steer Forks (Unused) S/N: 124438 Usage: Not Available Asset located in: Lake Worth, TX	5443	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5431	<b>48 in Skid Steer Forks</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5444	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5432	<b>38 in Skid Steer Forks</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5445	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5433	All Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5446	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5434	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5447	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5435	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5448	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5436	Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5449	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5437	<b>48 in Skid Steer Fork Frame (Unused)</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5450	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5438	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5451	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5455	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5452	2024 Landhonor BS-12-2500G 45 in Skid Steer	5456	All-Star 44 in Skid Steer Bale Spear (Unused)
0102	Bale Spear Frame (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND	0.100	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available <b>Notes</b> : THE PRODUCT IMAGES SHOWN ARE	5457	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5458	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5453	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5459	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5460 5461	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5454	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Landhonor BS-12-2500G 45 in Skid Steer	- 3401	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Bale Spear (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5462	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5463	All-Star 44 in Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5464	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5465	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5473	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5466	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5474	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00018 Usage: Not Available Asset located in: Lake Worth, TX
5467	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5475	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00017 Usage: Not Available
5468	<b>32 in Skid Steer Tree Spade (Unused)</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5476	Asset located in: Lake Worth, TX  2024 Landhonor DPC-21-13W Skid Steer Pole Clamp (Unused)
5469	<b>32 in Skid Steer Tree Spade (Unused)</b> S/N: Not Available Usage: Not Available		S/N: HL00009 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
5470	Asset located in: Lake Worth, TX  32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		2024 Kit Containers QT-TM Receiver Hitch (Unused) S/N: B06J1903 Usage: Not Available Asset located in: Lake Worth, TX
5471	32 in Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5478	2024 Kit Containers QT-TM Skid Steer Receiver Hitch (Unused) S/N: B06J1913 Usage: Not Available Asset located in: Lake Worth, TX
5472	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5479	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5480	480 2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5488	Set of OTT Tracks for Skid Steer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		5489	2024 Handy HSTS12 Skid Steer Tree Shear (Unused) S/N: TS202409117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5481	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5490 5491	Asset located in: Lake Worth, TX  Quantity of (4) All-Star Quick Attach Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (10) 2024 Kit Containers QT-F-	
5482	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Landhonor UHA-16-3000G 2 in Skid Steer	5491	BLANK Skid Steer Attachment Mounting Plate (Unused)  S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	
	Hitch Receiver (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	5492	Quantity of (10) 2024 Kit Containers QT-F-BLANK Skid Steer Attachment Mounting Plate (Unused)  S/N: Not Available  C/W: One Pallet Usage: Not Available  Asset located in: Lake Worth, TX	
5483	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  All-Star Receiver Hitch (Unused)	5493	5493 Quantity of 2024 Kit Containers QT-F-BLA Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available	(Unused) S/N: Not Available
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5494	Asset located in: Lake Worth, TX  Quantity of (10) 2024 Kit Containers QT-F-	
5484	All-Star Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5495	BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available	
5485	Titan 47 in ADJUSTABLE INDUSTRIAL SKID STEER JIB BOOM CRANE - Fits Skid Steer/CTL S/N: Not Available Usage: Not Available Asset located in: Midland, TX		Asset located in: Lake Worth, TX  Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused)  S/N: Not Available Usage: Not Available	
5486	Set of Grouser Steel Skid Steer Tracks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5496	Asset located in: Lake Worth, TX  Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused)  S/N: Not Available	
5487	Set of McLaren Steel Skid Steer Tracks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5497 5498	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (3) All-Star Skid Steer Attachment	5507	Quantity of (2) Pallets of Okada Padding Bucket Screens S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	
	Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5508	Quantity of (9) 2024 AGT 12EX-ATA Mini Excavator Attachment (Unused) S/N: 12EX-ATA24042002A C/W: Quick Coupler, Rake, Ripper, Grapple,	
5499	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Auger, 12 in Auger Bit, 8 in Bucket, 20 in Bucket, 32 in Bucket Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
5500	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused)  S/N: Not Available Usage: Not Available	5509	Contech 2200 Excavator Plate Compactor S/N: 7800220A1191132 Usage: Not Available Asset located in: Lake Worth, TX	
5501	Asset located in: Lake Worth, TX  2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused)  S/N: DM20241009163  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5510	Volvo ARM-EC380E-9FT6IN BARE Excavator stick S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5511	KBKC 72 in Excavator Rake - Fits Cat 320 (Unused) S/N: RR240122 Usage: Not Available Asset located in: Lake Worth, TX	
5502	Quantity of (9) Agrotek Mini Excavator Attachments (Unused) S/N: 12EXATA24042002A C/W: (3) Buckets, Quick Coupler, Grapple, Auger, Two Bits, Rake, Ripper, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	5512	KBKC 48 in Excavator Rake - Fits Cat 305-306 (Unused) S/N: RR240103 Usage: Not Available Asset located in: Lake Worth, TX	
5503	All-Star E35 40 in Q/C Excavator Brush Cutter (Unused) S/N: Not Available Usage: Not Available	5513	Excavator Ripper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5504	Asset located in: Lake Worth, TX  All-Star 40 in Excavator Brush Cutter (Unused) S/N: Not Available C/W: No Coupler Usage: Not Available Asset located in: Lake Worth, TX	5514	Deere 310SJ S/N: Not Available C/W: 45 mm Diameter Pins, 340 Pin Boss to Center of Pin Boss, 2	S/N: Not Available C/W: 45 mm Diameter Pins, 340 mm Center of Pin Boss to Center of Pin Boss, 205 mm Inside to Inside Pin Boss Spacing, 10 in & 12 in Auger Bits
5505	Paladin Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	
5506	Cat Misc. attachment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX			

Lot #	Details	Lot #	Details
5515	John Deere 210 S/N: 1804110013 C/W: 75 mm Diameter Pins, 470 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside	5524	2024 Jisan JSB2200B 144 mm Hydraulic Breaker (Unused) S/N: 2404338 Usage: Not Available Asset located in: Lake Worth, TX
	to Inside Pin Boss Spacing, 16 in & 20 in Auger Bits Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	5525	2024 Jisan JSB2200B 140 mm Hydraulic Breaker (Unused) S/N: 2404339 Usage: Not Available Asset located in: Lake Worth, TX
5516	2019 Stanley MB/XP4035 Hydraulic Breaker S/N: XP40350054 C/W: 8000 lb class, 5.6 in Tool / Chisel, Fits Excavators Usage: Not Available Asset located in: Lake Worth, TX	5526 5527	2024 TOFT TOFT1550 Hydraulic Breaker (Unused) S/N: JW121Z0715 Usage: Not Available Asset located in: Lake Worth, TX 2024 TOFT TOFT1400 Hydraulic Breaker
5517	2024 JESON HM3300 Hydraulic Breaker (Unused) S/N: JQ HM 012 Usage: Not Available Asset located in: Lake Worth, TX	5528	(Unused) S/N: JW81Z3340 Usage: Not Available Asset located in: Lake Worth, TX 2024 Jisan JSB2200B Hydraulic Breaker
5518	2024 Jisan JSB3200B Hydraulic Breaker (Unused) S/N: CP2404445 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		(Unused) S/N: CP2404401 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5519	Asset located in: Lake Worth, TX  2024 JESON HM3200 Hydraulic Breaker (Unused) S/N: JQ HM 011 Usage: Not Available Asset located in: Lake Worth, TX	5529	2024 Jisan JSB2200T Hydraulic Breaker (Unused) S/N: CP2406139 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE ACTUAL PRODUCT
5520	2024 JESON HM3150 Hydraulic Breaker (Unused) S/N: JQ HM 015 Usage: Not Available Asset located in: Lake Worth, TX	5530	THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Elephant EPB2200B Hydraulic Breaker S/N: CP2407167 Usage: Not Available
5521	2024 JQ POWER JQB3000STB Hydraulic Breaker (Unused) S/N: 814075918 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5522	2024 JESON HM3070 Hydraulic Breaker (Unused) S/N: JQ HM 014 Usage: Not Available Asset located in: Lake Worth, TX	5531	2024 Elephant EPB2200T Hydraulic Breaker S/N: CP2406053 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5523	2024 JESON HM3070SL Skid Steer Breaker (Unused) S/N: JQHM010 Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5532	Teran THH2000B Hydraulic Breaker - Fits Cat 320 (Unused)  S/N: CEH715D14HZ C/W: B Linkage For all 18-25 Ton Excavators - With Auto - Lubrication Pre-Disposition. Box Type - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual. Usage: Not Available Asset located in: Lake Worth, TX	5538	2024 Elephant EPB430BL Hydraulic Breaker S/N: CP2406081 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5539	2016 C & P RX8-11 Hydraulic Breaker S/N: BES062122 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5533	2024 TOFT TOFT1000 Hydraulic Breaker (Unused) S/N: JW50Z2170	5540	Usage: Not Available Asset located in: Lake Worth, TX 2024 Elephant EPB400T Hydraulic Breaker
	Usage: Not Available  Asset located in: Lake Worth, TX	3540	(Unused) S/N: CP2406114
5534	2024 Jisan JSB800B Hydraulic Breaker (Unused) S/N: CP2406128 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5541	<b>2024 Elephant EPB400T Hydraulic Breaker</b> (Unused) S/N: CP2406112
5535	2024 Elephant EPB800T Hydraulic Breaker (Unused) S/N: CP2406101 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	Usage: Not Available  Notes: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSE MAY NOT BE AN EXACT REPR THE ACTUAL PRODUCT	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5542	<b>2024</b> Jisan JSB400B Hydraulic Breaker (Unused) S/N: CP2403154
5536	2024 Elephant EPB430BL Hydraulic Breaker (Unused) S/N: CP2406079 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5543	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		<b>2024</b> Jisan JSB400B Hydraulic Breaker (Unused) S/N: CP2403166
5537	2024 Jisan JSB430B Hydraulic Breaker (Unused) S/N: CP2408266 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
		5544	2024 Jisan JSB400BL Hydraulic Breaker (Unused) S/N: CP2404523 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5545	Teran THH400B-CAT308 Hydraulic Breaker - Fits Cat 307 (Unused)  S/N: Not Available C/W: For Mini Excavators CAT 307/308 - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen	5549	Trojan 50CL Hydraulic Breaker - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: SB40Y0M20246073 Usage: Not Available Asset located in: Lake Worth, TX
	Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX	5550	Trojan 35CL Hydraulic Breaker - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: SB30YOM20246119
5546	Teran THH400BH Hydraulic Breaker - Fits Cat		Usage: Not Available  Asset located in: Lake Worth, TX
	416 (Unused) S/N: CAB00398C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Tean Hydraulic	5551	Teledyne TB8309X Hydraulic Breaker S/N: 9991991983 Usage: Not Available Asset located in: Lake Worth, TX
	Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual	5553	2017 Okada 100A Hydraulic Breaker S/N: 3160R C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
		5554	Kelly Hydraulic Breaker - Fits Kelly CB7500 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	5555	Kent 5 in Hydraulic Breaker - Fits John Deere
5547	Teran THH400B-SSL Skid Steer Breaker - Fits Cat 226 (Unused) S/N: Not Available C/W: For Skid Steer Loader Cat 226-299 With Mounting Plate included -68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box		200C LC  S/N: F272749  C/W: 80 mm Diameter Pins, 440 mm Center of Pin Boss to Center of Pin Boss, 325 mm Inside to Inside Pin Boss Spacing Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES.  Asset located in: Lahoma, OK
	with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Lake Worth, TX  Teran THH400BT Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA3496B54HR C/W: For Backhoe Loaders CAT 416, 428, 444 -68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available	5556	Hydraulic Breaker S/N: Not Available Usage: Not Available
5548			Asset located in: Lake Worth, TX
3348		5557	Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5558	2024 TOFT TOFT280R Rotating Demolition Shear (Unused) S/N: TOFT280R24032 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5559	2019 Hammer GRP150 15 in Excavator Grapple S/N: H183515GRP Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5560	Viper Metal VPH 3-1700 68 in Padding Excavator Bucket (Unused) S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5565	2024 Jisan BKT32078DB 78 in Cleanup Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: 24072902553 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5561	Viper Metal VPH 4-1500 57 in Padding Excavator Bucket (Unused)		THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE	5566 5567	2024 JESON BKT 345-78 78 in Digging Excavator Bucket (Unused) S/N: JQ BKT 059 Usage: Not Available Asset located in: Lake Worth, TX 2024 JESON BKT 345-78 78 in Digging	
5562	Asset located in: McAlester, OK  2019 Remu EX140 48 in Screening Excavator Bucket S/N: 14000062		Excavator Bucket (Unused) S/N: JQ BKT 049 Usage: Not Available Asset located in: Lake Worth, TX	S/N: JQ BKT 049 Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX	5568	2024 Jisan BKT34572HD 72 in Excavator Bucket (Unused)	
5563	Remu CAT C/EX140 48 in Padding Excavator Bucket - Fits REMU EX140 S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE		S/N: 24072902536 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE  Asset located in: McAlester, OK	5569	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 058 Usage: Not Available Asset located in: Lake Worth, TX	
5564	B&D Fab CAT C/EX140 48 in Padding Excavator Bucket - Fits CAT EX140 S/N: B93283 Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE	5570	2024 JESON BKT 345-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 040 Usage: Not Available Asset located in: Lake Worth, TX	
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5571	2024 Jisan BKT336D72HD 72 in Excavator Bucket (Unused) S/N: 24062202043 Usage: Not Available	
5564A	Rockland 84 in Excavator Bucket S/N: 9757101 Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5572	Teran BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336D (Unused)  S/N: 0838  C/W: DB Linkage - 2.00m3 for Cat 336D, 336D2, 336E, 336F, 340D2, 340F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips - DB Linkage  Usage: Not Available  Asset located in: Lake Worth, TX	5580	2024 Jisan BKT36066HD 66 in 2.2 cyd Digging Excavator Bucket - Fits Komatsu PC360 (Unused)  S/N: 24072902567  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE
5573	2024 JESON BKT 336-72 72 in Digging Excavator Bucket (Unused) S/N: JQ BKT 053 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5574	Asset located in: Lake Worth, TX  2024 Warrior WBRC40-1700 72 in Digging 40- 45T 1700mm to fit CAT349 Rock Excavator Bucket (Unused)  S/N: 2024-09-20-JL01	5581	2022 Werk-Brau 480-66-VO-HC 66 in Digging Excavator Bucket S/N: 48834 Usage: Not Available Asset located in: Lake Worth, TX
5575	Usage: Not Available Asset located in: Lake Worth, TX  2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused)	5582	2024 BTTL CAT345 60 in Digging Excavator Bucket (Unused) S/N: TOFTEB24581 Usage: Not Available Asset located in: Lake Worth, TX
	S/N: JQ BKT 039 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2024 Elephant BKT336D60HD 60 in Excavator Bucket (Unused)
5576	2024 JESON BKT 345-66 66 in Excavator Bucket (Unused) S/N: JQBKT037 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 24062200411 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5577	2024 JESON BKT 345-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 057 Usage: Not Available Asset located in: Lake Worth, TX	5584	Asset located in: Lake Worth, TX  2024 Jisan BKT336D60HD 60 in Excavator Bucket (Unused)  S/N: 24062202027 Usage: Not Available
5578	2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 052 Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
5579	Asset located in: Lake Worth, TX  2024 JESON BKT 336-66 66 in Digging Excavator Bucket (Unused) S/N: JQ BKT 028 Usage: Not Available Asset located in: Lake Worth, TX	<b></b> 5585	2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 020 Usage: Not Available Asset located in: Lake Worth, TX
		5586	2024 JESON BKT 336-60 60 in Digging Excavator Bucket (Unused) S/N: JQ BKT 023 Usage: Not Available Asset located in: Lake Worth, TX
		5587	Esco 58 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: RH80487 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5588	Teran BKT325D54HD 54 in Digging Excavator Bucket - Fits Cat 329D (Unused)  S/N: 3655  C/W: CB Linkage - 1.22m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6RC Tips Usage: Not Available  Asset located in: Lake Worth, TX	5595	2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
5589	2024 Jisan BKT32054HD 54 in Excavator Bucket (Unused) S/N: 2406220204 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5596	2024 Warrior WBRC20-1200 53 in Digging Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5590	Teran BKT32054HD 54 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 1847 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 6HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5597	Asset located in: Lake Worth, TX  2024 Elephant BKT32048HD 48 in Excavator Bucket (Unused)  S/N: 24151503617 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5591	2024 Elephant BKT22054HD 54 in Excavator Bucket (Unused) S/N: 2407280051 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5598 5599	Asset located in: Lake Worth, TX  2024 JESON BKT 320-48 48 in Digging Excavator Bucket (Unused)  S/N: JQ BKT 054 Usage: Not Available Asset located in: Lake Worth, TX  2024 JESON BKT 320-48 48 in Digging
5592	Asset located in: Lake Worth, TX  2024 Jisan BKT22054HD 54 in Excavator Bucket (Unused)  S/N: 24062300918 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5600	Excavator Bucket (Unused)  S/N: JQ BKT 055 Usage: Not Available Asset located in: Lake Worth, TX  Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused)  S/N: Not Available
5593	C & P 60 in Digging Excavator Bucket S/N: NHK50615 Usage: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
5594	Asset located in: Lake Worth, TX  56 in Digging Excavator Bucket - Fits Komatsu PC300 S/N: 1844 Usage: Not Available Asset located in: Lake Worth, TX	5601	Trojan 200CL 48 in Digging Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
5602	Teran 48 in .88 cyd Digging Excavator Bucket - Fits Cat 312 S/N: BKT31248 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	5612	Teran BKT31236 36 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5583 C/W: 312 Linkage - 0.48m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 5HD Tips	
5603	Teran 48 in 1.16 cyd Digging Excavator Bucket		Usage: Not Available  Asset located in: Lake Worth, TX	
	- Fits Cat 320 S/N: BKT32048HD C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	5613	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available	
5604	<b>48 in Q/C Digging Excavator Bucket</b> S/N: 804560244191		Asset located in: Lake Worth, TX	
	Usage: Not Available  Asset located in: Lake Worth, TX	5614	Trojan 120CL 36 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140	
5605	Paladin 48 in Digging Excavator Bucket - Fits John Deere 350G S/N: J000094897-1 Usage: Not Available Asset located in: Lake Worth, TX		Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
5606	2024 BTTL CAT320 42 in Excavator Bucket (Unused) S/N: TOFTEB24553 Usage: Not Available Asset located in: Lake Worth, TX	5615	Trojan 120CL 36 cyd Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available	
5607	Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available	5616	Asset located in: Lake Worth, TX  36 in Digging Excavator Bucket  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	5617	Esco 36 in Excavator Bucket - Fits Komatsu PC220	
5608	Trojan 120CL 42 in Digging Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused)		S/N: 56553 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5618	32 in Digging Excavator Bucket S/N: Not Available Usage: Not Available	
5609	Teran BKT30742 42 in Digging Excavator Bucket - Fits Cat 307 (Unused)	5619	Asset located in: Lake Worth, TX  Trojan 80CL 30 in Digging Excavator Bucket -	
	S/N: 1208 C/W: 0.41m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 7HD Tips Usage: Not Available Asset located in: Lake Worth, TX	3019  -	Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available	
5610	2020 Cat A 42 BU 42 in Excavator Bucket S/N: 0XC702965 Usage: Not Available	5620	Asset located in: Lake Worth, TX  Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88	
5611	Asset located in: Lake Worth, TX  Komatsu 42 in Digging Excavator Bucket S/N: Not Available Usage: Not Available		Deere/Hitachi 75/85 Case, New H	Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available

Lot #	Details	Lot #	Details
5621	Trojan 80CL 30 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5630	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available
5622	Teran BKT30730 30 in Digging Excavator		Asset located in: Lake Worth, TX
	Bucket - Fits Cat 307 (Unused) S/N: 1205 C/W: 0.27m3 for Cat 307/308 with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5631	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available
5623	<b>2014 Tag 30 in Digging Excavator Bucket</b> S/N: 102177-41		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available <b>Asset located in</b> : Oklahoma City, OK	5632	Trojan 50CL 24 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case,
5624	30 in Q/C Digging Excavator Bucket S/N: 60941C Usage: Not Available Asset located in: Lake Worth, TX		New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5625 5626	Tooth Pro 26 in V-Ditching Excavator Bucket S/N: 2360 Usage: Not Available Asset located in: Lake Worth, TX  Teran BKT31224 24 in Digging Excavator	5633	Teran BKT305C24 24 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2941 C/W: 0.16m3 with Side Cutters Reinforcement Plates and 5HD Tips
0020	Bucket - Fits Cat 312 (Unused)		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: 0171 C/W: 312 Linkage - 0.32m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Lake Worth, TX	5634	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available
5627	Trojan 80CL 24 in Digging Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88		Asset located in: Lake Worth, TX
5628	Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Trojan 80CL 24 in Digging Excavator Bucket -	5635	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5636	Trojan 35CL 24 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available
5629	Trojan 80CL 24 in Digging Excavator Bucket -		Asset located in: Lake Worth, TX
	Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5637	24 in Digging Excavator Bucket S/N: 3181 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5638	2018 Cat B 24 BU 24 in Digging Excavator Bucket S/N: B-24-MHJ74545 Usage: Not Available Asset located in: Lake Worth, TX 24 in Digging Excavator Bucket S/N: Not Available	5646	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX	5647	Asset located in: Lake Worth, TX  Trojan 50CL 12 in Digging Excavator Bucket -
5640	24 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available
5641	Bobcat 24 in Q/C Digging Mini Excavator Bucket S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5648	Trojan 35CL 12 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused)
5642	2023 Kubota K7874A-18 18 in Excavator Bucket S/N: Not Available		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5649	Trojan 35CL 12 in Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused)
5643	Rockland 18 in V-Ditching Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	5650	Trojan 35CL 12 cyd Digging Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G
5643A	Adco 16 in V-Ditching Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5644	Tooth Pro 15 in Mini Excavator Bucket S/N: 5707 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5651	Teran BKT305C12 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2920 C/W: 0.08m3 With Side Cutters Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Lake Worth, TX
5645	Trojan 50CL 12 in Digging Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5652	Tooth Pro 12 in Mini Excavator Bucket S/N: 5480 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
		5653	12 in Q/C Digging Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5654	Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) Mini Excavator Bucket (Unused) S/N: Not Available C/W: (1) 7 in, (1) 23 in Usage: Not Available Asset located in: Lake Worth, TX	5662	2024 Warrior WBSC30-1600 62 in Skeleton Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused)  S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5656	2024 Jisan BKT34572SKEL 72 in Skeleton Excavator Bucket (Unused)		Asset located in: Lake Worth, TX
	S/N: 24072903037 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5663	Teran BKT325D60SKEL 60 in Skeleton Excavator Bucket - Fits Cat 329D (Unused) S/N: 2220 C/W: CB Linkage - 1.14m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips
5657	2024 Elephant BKT336D72SKEL 72 in Skeleton Excavator Bucket (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 2407290019 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5664	2024 Jisan BKT32060SKEL 60 in Skeleton Excavator Bucket (Unused) S/N: 24072903014 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
5658	2024 JESON BKT 336-72 SKEL 78 in Skeleton Excavator Bucket (Unused)	5665	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	S/N: JQBKT051 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Teran BKT32054SKEL 54 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 2159
5659	2024 Jisan BKT336D66SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: 2409040117 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6HD Tips 80mm Pins Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5666	2024 Jisan BKT32048SKEL 48 in Skeleton Excavator Bucket (Unused)
5660	2024 JESON BKT 336-66 SKEL 66 in Skeleton Excavator Bucket (Unused) S/N: JQ BKT 056 Usage: Not Available Asset located in: Lake Worth, TX 2024 JESON BKT 336-66 SKEL 66 in Skeleton		S/N: 2407290301 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
3301	Excavator Bucket (Unused) S/N: JQ BKT 050 Usage: Not Available Asset located in: Lake Worth, TX	5667	Teran BKT31248SKEL 48 in Skeleton Excavator Bucket - Fits Cat 312 (Unused) S/N: 3112 C/W: 312 Linkage - 0.77m3 for CAT 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters and 5HD Tips Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5668	2024 TOFT CAT336 48 in Skeleton Excavator Bucket (Unused) S/N: TOFTEB24674 Usage: Not Available Asset located in: Lake Worth, TX	5674	Teran BKT30736SKEL 36 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 1126 C/W: 0.34m3 for Cat 307/308 with 6HD Tips Usage: Not Available
5669	Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)  S/N: Not Available  C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL		Asset located in: Lake Worth, TX
		5675	Trojan 200CL 72 in Tilting Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5676	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135,
5670	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)  S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5677	Trojan 120CL 60 in Tilting Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		·
5671	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT	5678	Trojan 80CL 48 in Tilting Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	5679	Trojan 80CL 48 in Tilting Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available
5672	2024 Warrior WBSC20-1100 47 in Skeleton Excavator Bucket - Fits Cat 320 / 20 - 25 ton		Usage: Not Available  Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5673	Teran BKT30742SKEL 42 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 0.573 C/W: 0.39m3 for Cat 307, 308 with 5 HD Tips Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
5681	Trojan 50CL 42 in Tilting Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50 /55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341 /337 (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G	5688	2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused)  S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5689	2024 Warrior WBRC30-1500 59 in Cleanup Excavator Bucket - Fits Cat 320/ 20 - 25 ton (Unused)
5683	Trojan 35CL 42 in Tilting Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5690	S/N: Not Available C/W: 90 mm Stick Pin Diameter, 100 mm Link Pin Diameter, 500 mm Center of Pin Boss to Center of Pin Boss, 385 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5684	Trojan 200CL 72 in Ditch Cleaning Excavator Bucket - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200 /225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
5685	Teran BKT32072CLN 72 in Cleanup Excavator Bucket - Fits Cat 320 (Unused)		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 4843 C/W: B Linkage - 0.66m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2024 Warrior WBMCC20-1500 59 in Cleanup Excavator Bucket - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available
5686	<b>72 in Excavator Bucket - Fits Mobile Excavator</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
5687	Teran BKT32060CLN 60 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 1319		PRODUCT Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: B Linkage - 0.54m3 for CAT 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available Asset located in: Lake Worth, TX	5692	2024 Warrior WBMCC20-1500 60 in Digging Excavator Bucket - Fits Cat 336 / 30 - 35 ton (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5693	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5701	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D /G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5694	Trojan 120CL 60 in Ditch Cleaning Excavator Bucket - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere/Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Teran BKT31260CLN 60 in Cleanup Excavator	5702	Trojan 50CL 42 in Ditch Cleaning Excavator Bucket - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D /G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Bucket - Fits Cat 312 (Unused) S/N: 0183 C/W: 312 Linkage - 0.38m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Lake Worth, TX	5703	Teran BKT30742CLN 42 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3032 C/W: 0.20m3 for Cat 307/308 Usage: Not Available Asset located in: Lake Worth, TX
5696	Trojan 80CL 48 in Ditch Cleaning Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5704	Trojan 35CL 42 in Ditch Cleaning Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D /G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5697	Trojan 80CL 48 in Ditch Cleaning Excavator Bucket - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5705	Trojan 35CL 42 in Ditch Cleaning Excavator Bucket - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D /G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5698	Teran BKT30748CLN 48 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3045 C/W: 0.23m3 for Cat 307/308 Usage: Not Available Asset located in: Lake Worth, TX	5706	Teran BKT30342CLN 42 in Cleanup Excavator Bucket - Fits Cat 303 (Unused) S/N: 2836 C/W: 0.13m3 Usage: Not Available Asset located in: Lake Worth, TX
5699	Teran BKT305C48CLN 48 in Cleanup Excavator Bucket - Fits Cat 305 (Unused) S/N: 01071 C/W: 0.15m3 Usage: Not Available Asset located in: Lake Worth, TX	5707	Teran BKT30436CLN 36 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 01063 C/W: 0.12m3 Usage: Not Available Asset located in: Lake Worth, TX
5700	Teran BKT30448CLN 48 in Cleanup Excavator Bucket - Fits Cat 304 (Unused) S/N: 2301 C/W: 0.15m3 Usage: Not Available Asset located in: Lake Worth, TX	5708	Teran BKT30136CLN 36 in Cleanup Excavator Bucket - Fits Cat 301 (Unused) S/N: 2645 C/W: 0.07m3 30mm Pins Usage: Not Available Asset located in: Lake Worth, TX

		_			
Lot #	Details	Lot #	Details		
5709	Bobcat 36 in Q/C Mini Excavator Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5714	5714	5714	REMU EX140 49 in Padding Bucket  S/N: Not Available C/W: 80 mm Diameter Pins, 465 mm Center of Pin Boss to Center of Pin Boss, 340 mm Inside to Inside Pin Boss Spacing Usage: Not Available  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
5710	<b>84 in Bucket</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		
5711	2019 Viper 3-1700 67.5 in Padding Bucket - Fits Komatsu PC200 S/N: 3-17001714 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5715	REMU EX140 48 in Padding Bucket - Fits Cat S/N: 14270 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		
5712	2019 Viper 4-1100 48 in Padding Shaker Bucket S/N: 4-1100218 C/W: 80 mm Diameter Pins, 410 mm Center of Pin Boss to Center of Pin Boss, 330 mm Inside to Inside Pin Boss Spacing Usage: Not Available  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE  Asset located in: McAlester, OK	5716	REMU EX140 48 in Padding Bucket - Fits Cat S/N: 14268 C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 352 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		
5713	2018 Viper 4-1100 48 in Padding Shaker Bucket - Fits Komatsu PC-200 S/N: 4-1100214 C/W: 80 mm Diameter Pins, 415 mm Center of Pin Boss to Center of Pin Boss, 328 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	5717	19.5 in Digging Bucket - Fits Hitachi 160 S/N: 779435681 C/W: 80 mm Diameter Pins, 392 mm Center of Pin Boss to Center of Pin Boss, 307 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		

Lot #	Details	Lot #	Details
5718	Tooth Pro 25 in Digging Bucket S/N: 3333 C/W: 80 mm Diameter Pins, 390 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	5727	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 041212842 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX  Tooth Pro 24 in Excavator Compaction Wheel S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5719	<b>82 in Q/C Wheel Loader Bucket</b> S/N: CH031182522 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5729	Rockland 24 in Excavator Compaction Wheel S/N: 7102601 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5720	Bobcat Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5730	Asset located in: Lake Worth, TX  American Compaction DC24BLWP 24 in Excavator Compaction Wheel
5721	61 in Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: 031012020 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
5722	American Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 100711104 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5731	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 041212819 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5723	American Compaction DC24BLWP 24 in Excavator Compaction Wheel  S/N: 0801012007  C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available	5732 —5733	Entek 36 in Excavator Compaction Wheel S/N: 8420 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5724	Asset located in: Lake Worth, TX  American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 121817519 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		Rockland WE36-4 36 in Excavator Compaction Wheel S/N: 7921501 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5725	Asset located in: Lake Worth, TX  Rockland 24 in Excavator Compaction Wheel S/N: 9412601 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	<b></b> 5734	Entek 18 in Excavator Compaction Wheel S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5726	Asset located in: Lake Worth, TX  American Compaction DC18S 18 in Excavator Compaction Wheel S/N: 111012261 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5735	American Compaction DC24BLWP 24 in Excavator Compaction Wheel S/N: 080710899 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5736	2015 Vacuworx RC12 Vacuum Lifter S/N: RC1200144 Usage: 413 Hr Asset located in: Sulphur, LA	5744	Quantity of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5737	2007 Superior SVL90 Pipe Vacuum Lifter		Asset located in: Corsicana, TX
	S/N: VL153 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5745	Cat Excavator Coupler S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5738	<b>2024</b> Jisan QCCAT336D Excavator Coupler (Unused) S/N: 24042900759		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5746	Simex SM3-17 84 in Excavator Crusher Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5739	Asset located in: Lake Worth, TX  2024 Jisan QCCAT320 Excavator Coupler (Unused)  S/N: 24042900737  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5747	2024 Elephant JXJMQC345 51 in Excavator Grapple (Unused)  S/N: 24072900212 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
5740	Asset located in: Lake Worth, TX  2024 Elephant QCCAT320 Excavator Coupler	5748	2024 Elephant JXJMQC336 46 in Excavator Grapple (Unused)
	(Unused) S/N: 2407290022 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: 2406220032 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5749	
5741	Teran QCCAT305 Excavator Coupler - Fits Cat 305 (Unused) S/N: 2014 C/W: For Cat 305 - 45mm Pins Usage: Not Available Asset located in: Lake Worth, TX		Grapple (Unused) S/N: 2407290131 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5742	Quantity of (2) Pallets of Cat Excavator		Asset located in: Lake Worth, TX
	Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5750	2024 TOFT TOFT04G Excavator Grapple (Unused) S/N: TOFTHG24110 Usage: Not Available Asset located in: Lake Worth, TX
5743	Quantity of (3) Pallets of Cat Excavator Coupler - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5752	Tysea 60 in Q/C Clamshell Style Q/C Hydraulic Excavator Grapple S/N: TY14465 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX

		I		
Lot #	Details	Lot #	Details	
5753 5754	Tysea 60 in Hydraulic Excavator Grapple S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX  2024 Elephant RAKE32065 65 in Excavator	5759	2024 Warrior WRC20-025 Excavator Ripper - Fits Cat 320 / 20 - 25 ton (Unused) S/N: Not Available C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	<b>Rake (Unused)</b> S/N: 24072900230		Usage: Not Available  Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5760	Teran RIPPER307 Excavator Ripper - Fits Cat 307 (Unused) S/N: 1307 C/W: For Cat 307/308 50mm Pin Usage: Not Available Asset located in: Lake Worth, TX	
5755	2024 Jisan RIPPER336D Excavator Ripper (Unused) S/N: 24072903240 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5761 5762 5763	2024 TOFT TOFT08R Excavator Ripper (Unused) S/N: TOFTERP24117 Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 TOFT TOFT04R Excavator Ripper (Unused) S/N: TOFTERP24073147	
5756	2024 Elephant RIPPER320 Excavator Ripper (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX	
	S/N: 24072900226 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Bucket - Fits 80mm Cat 320/321/323, R210 Komatsu PC200/220, Deere 160, /225 Kobelco SK210, Case 210/225, D DX225 (Unused) S/N: Not Available	S/N: Not Available
5757	2024 Jisan RIPPER320 Excavator Ripper (Unused)		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: 24072903228 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5764	Screening Bucket - Fits CAT C/E) S/N: B99434 C/W: EQUIPMENT-FROM-WATKII CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHE	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
5758	2024 Warrior WRC20-025 Excavator Ripper -		Asset located in: Lake Worth, TX	
	Fits Cat 320 / 20 - 25 ton (Unused)  S/N: Not Available  C/W: 80 mm Diameter Pins, 445 mm Center of Pin Boss to Center of Pin Boss, 310 mm Inside to Inside Pin Boss Spacing, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	5765	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000061 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
5766	REMU EX140 48 in Q/C Screening Excavator Screening Bucket S/N: 14000058 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5773	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903057 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
5767	Okada TMB70 Excavator Screening Bucket S/N: 508 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE	5774	Quantity of (2) Cat Excavator Thumb - Fits Cat 320  S/N: Not Available C/W: (1) 28 In Hydraulic, (1) 24 In Manual Usage: Not Available Asset located in: Lake Worth, TX	
5768	Asset located in: Lake Worth, TX  Okada TMB70 Trommel Excavator Screening Bucket  S/N: 262  C/W: EQUIPMENT-FROM-WATKINS-	5775	Teran THUMB30-35 M 40 in Excavator Thumb - Fits Cat 336D (Unused) S/N: Not Available C/W: 4 Tines - For Cat 330,336D and 30-36 Ton Excavators Usage: Not Available	
	CONSTRUCTION Usage: Not Available		Asset located in: Lake Worth, TX	
5769	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX  Okada TMB70 Excavator Screening Bucket S/N: 7050 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	5776	Cat 320/321/323, Hyur PC200/220, Deere 160, SK210, Case 210/225, S/N: Not Available Usage: Not Available	
	Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX		5777 Trojan 200CL Excavator Thumb - F Cat 320/321/323, Hyundai R210 Ko PC200/220, Deere 160/200/225 Ko SK210, Case 210/225, Doosan DX2	Trojan 200CL Excavator Thumb - Fits 80mm Cat 320/321/323, Hyundai R210 Komatsu PC200/220, Deere 160/200/225 Kobelco SK210, Case 210/225, Doosan DX225 (Unused) S/N: Not Available
5770	Okada TMB70 Excavator Screening Bucket S/N: 569 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Usage: Not Available  Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5778	Teran THUMB20-25 M 30 in Excavator Thumb - Fits Cat 320 (Unused)  S/N: Not Available C/W: 4 Tines - For Cat 320,325 and 20 - 25 Ton Excavators	
5771	Okada TMB70 Excavator Screening Bucket S/N: 351		Usage: Not Available  Asset located in: Lake Worth, TX	
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	5779	Teran THUMB12 - 15 M 26 in Excavator Thumb - Fits Cat 312 (Unused) S/N: 3188 C/W: For Cat 312, 315 and all 12-15 Ton Excavators 4 Tines Usage: Not Available	
5772	2024 Jisan THUMB20-25H Hydraulic Excavator Thumb (Unused) S/N: 24072903054 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5780	Asset located in: Lake Worth, TX  Teran THUMB5M 11 in Excavator Thumb - Fits Cat 305 (Unused)  S/N: 3177  C/W: Manual Thumb for Cat 305 and 5 Ton Mini Excavators Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5781	Teran THUMB2-3.5M 8 in Excavator Thumb - Fits Cat 303 (Unused) S/N: Not Available C/W: Manual Thumb for all 2-3.5 Ton Mini Excavators Usage: Not Available Asset located in: Lake Worth, TX	5790	Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat E80 (Unused) S/N: XD202408201 Usage: Not Available
5782	Trojan 120CL Excavator Thumb - Fits 65mm		Asset located in: Lake Worth, TX
	Cat 311/312/313/314 Kobelco 140 Deere /Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5791	Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5783	Trojan 120CL Excavator Thumb - Fits 65mm Cat 311/312/313/314 Kobelco 140 Deere /Hitachi ZX120/135 Case 130/135, Doosan DX140 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5792	Trojan 50CL Excavator Thumb - Fits 45mm Cat 305, 305.5 Komatsu PC45/50/55 Hyundai R55, Hitachi/Deere 50D/G Case, New Holland, Kobelco SK50 Bobcat E50/341/337 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5784	Gentec HT1035 30 in Excavator Thumb S/N: Not Available C/W: Hydraulic - Fits loader-backhoes & excavators from 10000 to 20000 lbs Usage: Not Available Asset located in: Lake Worth, TX	5793	Diesel Equipment 50CL 15 in Excavator Thur - Fits 45mm Cat 305, 305.5 Komatsu PC45/5 /55 Hyundai R55, Hitachi/Deere 50D/G Case New Holland, Kobelco SK50 Bobcat E50/341 /337
5785	Trojan 80CL Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75 /85 Case, New Holland, Kobelco SK80 Bobcat		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	E80 (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Gentec HT830 25 in Excavator Thumb S/N: Not Available C/W: Fits loader-backhoes & excavators from 6000 - 10000 lbs Usage: Not Available
5786	Diesel Equipment 80CL 16 in Excavator Thumb - Fits 50mm Cat 307/308, Komatsu PC78/88 Deere/Hitachi 75/85 Case, New Holland, Kobelco SK80 Bobcat E80 S/N: Not Available Usage: Not Available	5795	Asset located in: Lake Worth, TX  Gentec MT830 Excavator Thumb (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5796	Gentec MT824 - Fits mini excavators from
5787	2022 Rockland BTH-CL Excavator Thumb - Fits Rockland BTHCL S/N: 238845 Usage: Not Available		4000 - 9000 lbs Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	5797	Trojan 35CL Excavator Thumb - Fits 40mm Cat
5788	Quantity of (4) Cat Excavator Thumb - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5789	Asset located in: Corsicana, TX  Quantity of (4) Cat Excavator Thumb  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION  Usage: Not Available  Asset located in: Corsicana, TX	5798	Trojan 35CL Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5799	Diesel Equipment 35CL 14 in Excavator Thumb - Fits 40mm Cat 303, 303.5, 304 Case, New Holland, Kobelco SK35 Deere/Hitachi 35D/G (Unused)	5808	Quantity of (4) Crawler Pipelayer Side Booms S/N: Not Available C/W: (2) 20 ft, (1) 18 ft, (1) 13 ft Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available	F000	
	Asset located in: Lake Worth, TX	5809	<b>Hill 144 in Dozer Rake</b> S/N: Not Available
5800	Gentec HT618 16 in Excavator Thumb - Fits Gentec	1	Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Fits mini excavators up to 4000 lbs Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5810	Cat Light brackets - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5801	Excavator Thumb S/N: Not Available		Asset located in: Corsicana, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5811	Cat Radiator - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
5802	2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused)		Usage: Not Available <b>Asset located in</b> : Corsicana, TX
	S/N: DM20241009164 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5812	Cat Scarifier S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	5813	Quantity of Cat Misc. Parts
5803	Edge TH4800 48 in Skid Steer Mulcher S/N: TH0226 Usage: Not Available Asset located in: Lake Worth, TX	5813	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5804	Fecon 90 in Mulcher Attachment		Asset located in: Corsicana, TX
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5814	Cat Pipelayer hook and block - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
5805	2024 Jisan JSV765S Demolition Pulverizer (Unused)		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	S/N: 24072903210 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5815	Quantity of (3) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5806	2024 TOFT TOFT08P Demolition Pulverizer	5816	Quantity of (3) Pallets of Trunnion ball - Fits
	(Unused) S/N: TOFTHP24107 Usage: Not Available Asset located in: Lake Worth, TX		Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5807	Bodine 200 Demolition Pulverizer		Asset located in: Corsicana, TX
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5817	Quantity of (4) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
5818	Quantity of (4) Hook & Block S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5827	Rear Screen Dozer Attachment - Fits John Deere 700K S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE	
5819	System One Undercarriage Chain / Rails - Fits Cat D6T S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEE BUYER RESPONSIBLE FOR LOADOUT. R NOT BE ABLE TO ASSIST WITH LOADIN THESE	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
	Usage: Not Available <b>Asset located in</b> : Corsicana, TX	5828	Allied W6G Crawler Tractor Winch	
5820	Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE	
	Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE		Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	5829	Paccar Crawler Tractor Winch S/N: Not Available	
5821	Cat Crawler Tractor Counterweight (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	5830	CONSTRUCTION	CONSTRUCTION Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX		Crawler Tractor Winch	
5822	Cat Crawler Tractor Drawbar - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
5823	Carco Crawler Tractor Winch - Fits Cat D8 S/N: 12608 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5831	Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED	
5824	Carco Crawler Tractor Winch - Fits Cat D8 S/N: Not Available		FROM MACHINE  Asset located in: Lake Worth, TX	
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5832	Paccar PA56 Crawler Tractor Winch S/N: 1300340 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	
5826	2012 Midwestern M 530C Winch Pipe Laying System: Fits Cat D5 Dozer Attachment S/N: 13A12187		Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	
	C/W: 15 Ft Folding Boom Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5833	Allied W6G Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM OPERATIONAL WHEN REMOVED FROM MACHINE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5834	Cat Crawler Tractor Winch - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5843	164 in Angle Dozer Blade - Fits Cat D6T XL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5835	198 in Angle Dozer Blade - Fits Cat D6 LGP S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5844	162 in U-Blade Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5836	194 in Angle Dozer Blade - Fits Cat D8 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5845	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5837	174 in Angle Dozer Blade - Fits Cat D6XW S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5846	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5838	174 in Angle Dozer Blade - Fits Cat D6TXW S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5847	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5839	174 in Angle Dozer Blade - Fits Cat D6XW S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5848	162 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5840	174 in Angle Dozer Blade - Fits Cat D6TXW S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5849	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5841	174 in Angle Dozer Blade - Fits CatXW D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5850	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
5842	164 in Angle Dozer Blade - Fits Cat D7 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5851	160 in Angle Dozer Blade - Fits Cat D6T XL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
5852	160 in Angle Dozer Blade - Fits Cat D6TXL S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5862	Mini Excavator 280x72x56 Rubber Tracks S/N: Not Available C/W: 12 in, one set Usage: Not Available Asset located in: Lake Worth, TX	
5853	152 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	<b></b> 5863	Bobcat Mini Excavator 12 In All Purpose Rubber Tracks S/N: Not Available C/W: (1) 300x 52.5x74, (1) 300x52.5x98 Usage: Not Available Asset located in: Lake Worth, TX	
5854	150 in Angle Dozer Blade - Fits Cat D6DT S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	5864	Cat scarifier, drawbars, trench box - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	
5855	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5867	90 in Multi-Shank Motor Grader Ripper - Fits Cat 140G S/N: RP125 Usage: Not Available Asset located in: Lake Worth, TX	
5856	Asset located in: Corsicana, TX  148 in Angle Dozer Blade - Fits Cat D6D  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS-	5867A 5868 5869	5867A	S/N: Not Available Usage: Not Available
	CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX		Loader Bucket - Fits Hyundai HL955 S/N: 21041840101	
5857	146 in Angle Dozer Blade - Fits Cat D6D S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available			C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5858	Asset located in: Corsicana, TX  128 in PAT Dozer Blade - Fits Cat D6M  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		102 in Q/C Wheel Loader Bucket S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	
 5859	Usage: Not Available  Asset located in: Corsicana, TX  Bobcat 96 in PAT Skid Steer Dozer	5870	2022 Cat IT 1.5YD BU 96 in Q/C Wheel Loader Bucket S/N: CY220505839	
3039	S/N: 224403408 Usage: Not Available Asset located in: Lake Worth, TX	5871	Usage: Not Available Asset located in: Lake Worth, TX  2022 Cat 908 1.4YD E ISO 82 in Q/C General	
5860	<b>24 in single grouser Tracks - Fits Cat D6</b> S/N: Not Available C/W: System 1 ; EQUIPMENT-FROM-WATKINS-CONSTRUCTION	5871	Purpose Wheel Loader Bucket S/N: CH031182822 Usage: Not Available Asset located in: Lake Worth, TX	
 5861	Usage: Not Available Asset located in: Corsicana, TX  Ditch Witch Drill Rubber Tracks		2022 Cat 908 1.4YD E ISO 82 in Q/C General Purpose Wheel Loader Bucket S/N: CH031183322	
3001	S/N: Not Available C/W: 300x52.5x98, 12 in Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
5873	2022 Cat 908 1.4YD E ISO 82 in Q/C Wheel Loader Bucket S/N: CH021139822 Usage: Not Available Asset located in: Lake Worth, TX	5884	60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5874	2022 Cat 908 1.4YD E ISO Wheel Loader Bucket S/N: K5803211BU Usage: Not Available Asset located in: Lake Worth, TX	5885	Asset located in: Corsicana, TX  60 in Q/C Wheel Loader Forks - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
5875	JRB 102 in Q/C Wheel Loader Bucket - Fits Case 621D/ New Holland LW130B S/N: 0106-172069-211 Usage: Not Available	5885A 5886	Usage: Not Available Asset located in: Corsicana, TX  56 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available
5876	Asset located in: Lake Worth, TX  2018 Volvo L150H4.7POSPN 35 m3 Digging Wheel Loader Bucket S/N: 18599 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX  53 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5877	KA Fabrication 164 in Q/C Wheel Loader Forks - Fits Hyundai HL955 S/N: KA3246 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5887	Balderson BF9360 59 in Q/C Wheel Loader Forks - Fits Cat 950 S/N: 3WL1826 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
5878	96 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5888	68 in Wheel Loader Quick Coupler S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5879	2021 BR Co 84 in Q/C Wheel Loader Forks - Fits Hyundai HL955 S/N: 63782 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5889	Teran THH400BH Backhoe Hydraulic Breaker - Fits Cat 416 (Unused)  S/N: CAB00407C52HRL  C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen
5881	Cat 72 in Q/C Wheel Loader Forks - Fits Cat 950 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with
5882	JRB 60 in Q/C Wheel Loader Forks S/N: J458821 Usage: Not Available Asset located in: Lake Worth, TX		N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available
5883	Pemberton 60 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  Teran THH400BT Backhoe Hydraulic Breaker - Fits Cat 416 (Unused)  S/N: CAA2730B54HR Usage: Not Available
5883A	60 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5890A	Usage: Not Available Asset located in: Lake Worth, TX  Stanley Q/C Backhoe Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5891	2018 Stanley MBX15E09 Q/C Backhoe Hydraulic Breaker S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5901 	Tooth Pro 18 in Backhoe Rear Bucket S/N: 5108 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX 18 in Backhoe Rear Bucket
5892	Construction Tools RX8-11 Backhoe Hydraulic Breaker S/N: BES062129 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5902	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX  17 in Backhoe Rear Bucket
5893	Asset located in: Lake Worth, TX  FRD F6 Q/C Backhoe Hydraulic Breaker S/N: 12453 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5894	Kent F6 Backhoe Hydraulic Breaker S/N: 6137 Usage: Not Available Asset located in: Lake Worth, TX	5904	Hensley 13 in Backhoe Rear Bucket S/N: 19943 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5895	Tooth Pro 46 in Cleanup Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5905	Asset located in: Lake Worth, TX  12 in Backhoe Rear Bucket  S/N: Not Available Usage: Not Available
5896	2013 Woods Wainroy 30 in Backhoe Rear Bucket S/N: 102344430 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	5906	Asset located in: Lake Worth, TX  Strickland 12 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5896A	Asset located in: Oklahoma City, OK  30 in Backhoe Rear Bucket  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5907 	12 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5897	28 in Digging Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5908	16 in Backhoe Rear Bucket  S/N: Not Available  C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5898	24 in Backhoe Rear Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5909	Asset located in: Lake Worth, TX  12 in Backhoe Rear Bucket S/N: Not Available
5899	Tooth Pro 18 in Backhoe Rear Bucket S/N: 2382 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY		C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
5900	Usage: Not Available  Asset located in: Lake Worth, TX  Geith 18 in Backhoe Rear Bucket  S/N: Not Available  C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY  Usage: Not Available  Asset located in: Lake Worth, TX	5910	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5911	Quantity of (2) 18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5920	Hensley 16 in V-Ditching Backhoe Rear Bucket S/N: 33666 C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes:
5912	Bobcat 18 in Q/C Digging Backhoe Rear Bucket S/N: 1720020 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5921	Asset located in: Lake Worth, TX  Hensley 12 in Digging Backhoe Rear Bucket S/N: 19884 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
5913	18 in Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	5922	Asset located in: Lake Worth, TX  Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 4933 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5914	<b>24 in Backhoe Rear Bucket</b> S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY		Usage: Not Available Notes: . Asset located in: Lake Worth, TX
5915	Usage: Not Available Asset located in: Lake Worth, TX  John Deere 18 in Backhoe Rear Bucket S/N: 1852831	5923	Tooth Pro 12 in Backhoe Rear Bucket S/N: 2916 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5924	Asset located in: Lake Worth, TX  24 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-
5916	18 in Backhoe Rear Bucket  S/N: Not Available  C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	5925	SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX  WB 12 in Backhoe Rear Bucket
 5917	Usage: Not Available Notes: . Asset located in: Lake Worth, TX Tag 12 in Digging Backhoe Rear Bucket		S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: . Asset located in: Lake Worth, TX	5926	Asset located in: Lake Worth, TX  Quantity of (2) 60 in Backhoe Forks  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
5918	Tooth Pro 18 in V-Ditching Backhoe Rear Bucket S/N: 2611 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	5927	Asset located in: Corsicana, TX  42 in Backhoe Forks - Fits Terex 760  S/N: Not Available  C/W: accessories  Usage: Not Available  Asset located in: Lake Worth, TX
5919	Notes: . Asset located in: Lake Worth, TX  24 in Digging Backhoe Rear Bucket S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	-	Quantity of (3) 48 in Backhoe Forks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
5929	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5942	Post Driver Guide S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5930	44 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5943	Quantity of Forks (Unused) S/N: Not Available C/W: (1) 48 in set, (1) 42 in set Usage: Not Available Asset located in: Lake Worth, TX
5931	Cat 96 in Backhoe Loader Bucket S/N: 190300052 Usage: Not Available Asset located in: Lake Worth, TX	5944	Post Driver Guide S/N: Not Available Usage: Not Available
5932	Cat 96 in Backhoe Loader Bucket S/N: 190300048 Usage: Not Available Asset located in: Lake Worth, TX	5945	Asset located in: Lake Worth, TX  38 In x 98 In Material Basket  S/N: Not Available  C/W: fork pockets
5933	Cat 96 in Backhoe Loader Bucket S/N: 190300051	5946	Usage: Not Available  Asset located in: Lake Worth, TX  Post Driver Guide
<u> </u>	Usage: Not Available  Asset located in: Lake Worth, TX  Oct 26 in Realthead and Realth and Asset located in the second se		S/N: Not Available Usage: Not Available
5934	Cat 96 in Backhoe Loader Bucket S/N: 190500058 Usage: Not Available Asset located in: Lake Worth, TX	5947	Asset located in: Lake Worth, TX  44 in Misc. attachment  S/N: Not Available
5935	96 in Forks S/N: Not Available Usage: Not Available		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX
5936	Asset located in: Lake Worth, TX  Quantity of (6) 72 in Fork tines  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available  Asset located in: Corsicana, TX	5948	American Compaction DC18S 18 in Q/C Excavator Compaction Wheel S/N: 04038094 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
5937	Quantity of (4) 72 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	5949	<b>30 in Auger Bit</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
5938	Asset located in: Corsicana, TX  Quantity of (4) 48 in Fork tines  S/N: Not Available	5949A	Quantity of (2) System One Idlers - Fits Cat D6T S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX	5950 202 (Un S/N C/W Usa Ass 5952 CXI S/N Usa	2024 Mower King SSECAGY Skid Steer Auger (Unused) S/N: SSECAG-Y24060902F
5939	Quantity of (8) 40 in Fork tines S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits Usage: Not Available  Asset located in: Oklahoma City, OK
	Usage: Not Available  Asset located in: Corsicana, TX		<b>CXI 44 in Excavator Grapple</b> S/N: ZZA1398 Usage: Not Available
5941	Quantity of (2) 48 In x 56 In Screens S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5953	Quantity of (2) 2024 Landhonor BA-22-09W 105 in Tractor Rear Blade Blade Attachment (Unused) S/N: HL00018/HL00017 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX	5967	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
5954	Frontier LL1410 119 in Land Leveler Box Blade S/N: XFLL14X000009 Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	 5968	
5955	Gannon HD244 Box Blade S/N: HD24484HXDFNG Usage: Not Available Asset located in: Lake Worth, TX	5968	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5956	2024 Industrias America F10T 10 ft Box Scraper (Unused) S/N: F10T202435760 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5957	2024 Industrias America F08T 96 in Box		Asset located in: Lake Worth, TX
	Scraper (Unused) S/N: F08T202537998 Usage: Not Available Asset located in: Lake Worth, TX	5969	2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5958	2005 ICON 18D 4 Tire Hydraulic Pull Scraper S/N: 5075A C/W: Lead Scraper, 20.5x25 Tires Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5959	Level Best PL 72D Box Scraper		THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	5970	2024 Suihe F-8 8 ft Fork Extensions (Unused) S/N: Not Available
5961	Volvo 72 in Wheel Loader Forks S/N: 15200002 Usage: Not Available Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5965	Volvo 48 in L50-L120 Fork Attachment S/N: Not Available Usage: Not Available		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
5966	42 in Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	5971	Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 78 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX
		5972	Quantity of (5) 2024 Wolverine EX-66-78L/84L Sets of 84 In Fork Extensions (Unused) S/N: Not Available C/W: Two Bundles Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5973	96 in Fork Extensions S/N: Not Available C/W: Vise Stand Usage: Not Available Asset located in: Lake Worth, TX	5983	Teran QCCAT336D Quick Coupler - Fits Cat 336D (Unused) S/N: 5704 C/W: DB Linkage for Cat 330D, 336D Usage: Not Available Asset located in: Lake Worth, TX
5974	Volvo Wheel Loader Material Handling Arm S/N: 252 Usage: Not Available Asset located in: Lake Worth, TX	5984	Teran QCCAT320 Quick Coupler - Fits Cat 320 (Unused) S/N: 5311
5976	Caldwell 8000 lb Material Handling Arm - Fits Forklift		C/W: B Linkage - 80mm Pins Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	5985	Teran QCCAT312 Quick Coupler - Fits Cat 312 (Unused) S/N: 6159 C/W: 312 Linkage for Cat 311, 312, 314 - 65mm Pins Usage: Not Available Asset located in: Lake Worth, TX
 5976A	Asset located in: Lahoma, OK 2013 Arrow 1000100-12-152 140 in Material	5986	Quantity of (4) 16 In Trench Compactor Drums S/N: Not Available
3970A	Handling Arm S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	5987	23 in Excavator Compaction Wheel S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5979	2024 Jisan JSC160 Excavator Plate Compactor (Unused) S/N: 24072903224 Usage: Not Available	5988	66 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5989	66 in Padfoot Shell Kit - Fits Padfoot Shell Kit (Unused) S/N: 32598 C/W: EQUIPMENT-FROM-WATKINS-
5980	2024 Jisan JSC50 Excavator Plate Compactor (Unused)		CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
	S/N: 2404290048 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5990	2018 Cat CS34 50 in Padfoot Shell Kit S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	5991	Quantity of (4) 48 In x 48 In Steel Crane Pads S/N: Not Available
5981	2024 Elephant EPC50 Excavator Plate Compactor (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 24072900219 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	5992	Quantity of (4) 48 In x 50 In Steel Crane Pads S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		5993	Quantity of (3) Crane Caps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
5994	Johnson 4 Sheave Hook Block S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6004	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5995	60 ton 5 Sheave Hook Block S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6005	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
5996	Crane Ball S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6006	2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX
5997	Quantity of (2) Material Handling Arm S/N: Not Available C/W: (1) Arrow CE60TH 6000 lb 80 in boom, (1) 116 in boom Usage: Not Available Asset located in: Lake Worth, TX	6007	2025 Double A 18 ft Bale Mover (Unused) S/N: 1UFBU182XST012578 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
5998	40 ft Crane Boom - Fits Grove S/N: Not Available C/W: 23 Ft Swimg Away Job Usage: Not Available Asset located in: Lake Worth, TX	6008	2024 Landhonor UC-22-60W Bale Unroller (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
5999	60 ton 5 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6009	2024 Landhonor UC-22-60W Bale Unroller (Unused) S/N: Not Available Usage: Not Available
6000	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available C/W: Assorted Size, One Pallet Usage: Not Available Asset located in: Lake Worth, TX	6010	Asset located in: Lake Worth, TX  1999 Rome TAW20S 10 ft Disc  S/N: 10TAW3237R  C/W: 25 in Notched Front Discs, 26 in Notched Rear Discs, 11 in Spacing, EQUIPMENT-FROM-
6001	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available		A-PRIMORIS-SERVICES-ČORP-COMPANY Usage: Not Available Asset located in: Livingston, LA
-225	C/W: Assorted Size, One Pallet Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	6011	International 5100 13 ft 16 ft Pull-Type Air Drill S/N: 0390213C003164 C/W: 7 in Spacing, 14 in Discs Usage: Not Available
6002	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6012	Asset located in: Lake Worth, TX  Case 12 ft Seed Drill  S/N: 0419636  C/W: 4 in Spacing, 13 in Discs Usage: Not Available
6003	Quantity of 2024 Landhonor LHR-G80 7 ft Double Leg Chain Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6012A	Asset located in: Lake Worth, TX  SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240617 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6012B	SKLP 60 in 3-Point 9 Row No Till Drill (Unused) S/N: BZJ9240616 C/W: 6 in Spacing, Double Shoot, Rubber Packer, 14 in Discs Usage: Not Available	6020	Quantity of Ratchet Binders S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6021	Land Pride PD15 10 in 3-Point 15 Series Utility
6013	Scherer 28 In Kernel Processor S/N: W0602106010 Usage: Not Available Asset located in: Lake Worth, TX		Post Hole Digger S/N: 1747822 C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX
6013A	Strauss Clipper 20 ft Offset Sickle Bar Mower S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6022	Land Pride RCR1260 60 in 3-Point Brush Cutter S/N: 1820706 C/W: 540 PTO, 3 hp Standard Duty w/Shear Bolt
6014	2012 Rhino SE8 15 ft 0 in Batwing Brush Cutter Attachment - Fits Tractor Drawbar		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: 11278 Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES. Asset located in: Lahoma, OK	6024	Cat Bale Spear S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
6015	60 in Rotary Brush Cutter S/N: Not Available Usage: Not Available Asset located in: Midland, TX	6025	Euro Double 42 in Bale Spear S/N: Not Available C/W: c/w: 2 prongs and stabilizer prong Usage: Not Available Asset located in: Lake Worth, TX
6016	Land Pride RCF2060 60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX	6025A	Quantity of (3) Auger Bit S/N: Not Available C/W: (1) 15 in, (1) 22 ln, (1) 30 ln Usage: Not Available Asset located in: Lake Worth, TX
6017	60 in 3-Point Brush Cutter S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Lake Worth, TX	6026	1959 Allis Chalmers D17 Antique Tractor (Inoperable) S/N: D1726103 C/W: 8 Forward 2 Reverse, Partial Powershift, Gasoline Engine, Electric Start, 1 Rear
6017A	6 ft 3-Point Hitch Rotary Mower S/N: Not Available C/W: 540 PTO Usage: Not Available		Remotes, 540 PTO, 3-Point Hitch, Drawbar, 6.00-16 Front Tires, 16.9-28 Rear Tires Usage: Not Available Asset located in: Lake Worth, TX
6017B	Asset located in: Lake Worth, TX  John Deere MX15 15 ft Batwing Brush Cutter S/N: W0MX15E001181 C/W: 540 PT0 Usage: Not Available Asset located in: Lake Worth, TX	6027	2024 Landhonor SMS-64-40G Skid-Mounted Screen (Unused) S/N: Not Available C/W: 4 ft 9 in x 4 ft 2 in Double Deck Screen Usage: Not Available Asset located in: Lake Worth, TX
6018	Steel Fluid Filter Tank S/N: Not Available C/W: 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX		
6019	Scherer 28 In Kernel Processor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
6028	2024 Suihe VG Skid-Mounted Vibratory Screen (Unused)  S/N: Not Available  C/W: 5 ft x 4 ft 6 in Double Deck Screen, THE  PRODUCT IMAGES SHOWN ARE FOR  ILLUSTRATION PURPOSES ONLY AND MAY  NOT BE AN EXACT REPRESENTATION OF THE  ACTUAL PRODUCT  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE	6035	Storage Container S/N: 2-682990-01 Usage: Not Available Asset located in: Midland, TX	
		6036	16 ft x 8 ft Trench Shield  S/N: Not Available  C/W: 4 in Thick Panels, (0) Spreader Bars  Usage: Not Available  Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	6037	8 ft x 20 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (4) 96 in Spreader Bars Usage: Not Available	
6029	Burcham Ultimate Bagger Electric Sandbag		Asset located in: Lake Worth, TX	
	Filling Machine S/N: Not Available C/W: 12 in Conveyor, DeWalt 4 Gal Air Compressor, 12 in Conveyor & Accessories Usage: Not Available Asset located in: Lake Worth, TX	6038	8 ft x 18 ft Trench Shield S/N: 982669 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	
6030	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6039	8 ft x 20 ft Trench Shield  S/N: Not Available  C/W: 4 in Thick Panels, (4) 96 in Spreader Bars  Usage: Not Available  Asset located in: Lake Worth, TX	
6031	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6040	8 ft x 16 ft Trench Shield S/N: 982678 C/W: 4 in Thick Panels, (4) 72 in Spreader Bars Usage: Not Available Asset located in: Lake Worth, TX	
6032	2024 Genius GSM-66IN Separator Magnet (Unused) S/N: GSM09112 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6041	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSI MAY NOT BE AN EXACT REPE THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGE	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6033	2024 Genius GSM-66IN Separator Magnet (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	S/N: GSM09111		Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6042	2024 Suihe BX-9 9 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
6034	2024 Paladin SM-66-3206E 32 in x 6 ft Separator Magnet (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6043	2024 Suihe BX-7 7 cyd Bedding Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6051	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX  2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused)
6044	2024 Suihe BX-5 5 cyd Bedding Box (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6045	Asset located in: Lake Worth, TX  Quantity of (2) 2024 Kit Containers Steel 5 ft 4 in x 8 ft 2 in (.75 in Thick) Steel Plates  S/N: Not Available  C/W: One Bundle  Usage: Not Available  Asset located in: Lake Worth, TX	6053	Compactor (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6046	Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) 2024 Kit Containers Steel 5 ft x 8 ft (.75 in Thick) Steel Plates	6054 2024 Landhonor LHR-PC90 Vibra Compactor (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOT FOR ILLUSTRATION PURPOSES OF MAY NOT BE AN EXACT REPRES THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX  6055 Quantity of (4) Vibratory Plate Compact Syn: Not Available C/W: 1 Cylinder Gasoline Engine, FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX  6056 Quantity of (4) Vibratory Plate Compact Syn: Not Available C/W: 1 Cylinder Gasoline Engine, FROM-WATKINS-CONSTRUCTION Usage: Not Available C/W: 1 Cylinder Gasoline Engine, FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX  6057 Quantity of (4) Vibratory Plate Compact Syn: Not Available	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	S/N: Not Available C/W: One Bundle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT-
6048	Quantity of (2) 2024 Kit Containers Steel 6 ft x 8 ft 3 in (.75 in Thick) Steel Plates S/N: Not Available C/W: One Bundle Usage: Not Available		Usage: Not Available Asset located in: Corsicana, TX  Quantity of (4) Vibratory Plate Compactor
6049	Asset located in: Lake Worth, TX  Quantity of (2) 2024 Kit Containers Steel 5 ft x 10 ft (.75 in Thick) Steel Plates  S/N: Not Available  C/W: One Bundle  Usage: Not Available  Asset located in: Lake Worth, TX		C/W: 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX  Quantity of (4) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT-
6050			FROM-WATKINS-CONSTRUČTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX
		6058	Quantity of (3) Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
6059	Quantity of Mustang & Wacker Vibratory Plate Compactor S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6067	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6060	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705481 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6068	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738243 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6061	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815555 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6069	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738734 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6062	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705482 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6070	Wacker Neuson Vibroplate BPS2050BW Vibratory Plate Compactor (Unused) S/N: 11666297 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6063	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743231 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6071	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11743232 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6064	Wacker Neuson Vibroplate BPS2050B Vibratory Plate Compactor (Unused) S/N: 11862553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6072	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11738234 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6065	Wacker Neuson BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728975 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6073	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738225 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6066	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11733549 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6074	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815554 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6075	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11662551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6083	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666300 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6076	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11737833 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6084	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666298 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6077	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728974 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6085	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815550 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6078	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11728979 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6086	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815551 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6079	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11705489 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6087	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815553 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6080	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738240 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6088	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11705485 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6081	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738224 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6089	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11815552 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6082	Wacker Neuson Vibroplate BPS1550Bw Vibratory Plate Compactor (Unused) S/N: 11738235 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6090	Wacker Neuson Vibroplate BPS1550B Vibratory Plate Compactor (Unused) S/N: 11728978 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6091	Wacker Neuson Vibroplate BPS2050Bw Vibratory Plate Compactor (Unused) S/N: 11666299 C/W: Briggs & Stratton 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	6098	2016 Bomag BMP8500 Trench Compactor S/N: 101720125102 C/W: Tier 4, 2015 US EPA Label, Kubota D1005 3 Cylinder 14.5 kW 1.0 L Diesel Engine, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
6092	2015 Wacker Neuson RT Trench Compactor S/N: 24250030 C/W: 2024 US EPA Label, Kohler 3 Cylinder Diesel Engine, / 32 in Drums, Remote Control w/ Cord Usage: 305 Hr Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  Bomag BMP8500 Trench Compactor  S/N: 101720134167  C/W: Open Operator Station, Tier 4, 2019 US  EPA Label, Kubota D1005-EF06 3 Cylinder 14.3  kW 1.0 L Diesel Engine, 25 in / 35 in Drums,  Remote Control w/ Cord, Articulated Steering  Usage: Not Available
6093	Wacker Neuson RT Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA Label, CARB Compliant, Lombardini 6LBDL1. 37SFO:IFI 3 Cylinder 15.5 kW 1028 cc Diesel Engine, 33 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2011 Wacker Neuson RTSC2 Trench Compactor S/N: Not Available C/W: Open Operator Station, 2011 US EPA Label, 3 Cylinder Diesel Engine, 32 in Drums, Articulated Steering Usage: Not Available
6094	Wacker Neuson Articulating Trench Compactor S/N: Not Available C/W: Open Operator Station, 2006 US EPA Label, CARB Compliant, Lombardini 6LBD1. 37SFO:IFI 3 Cylinder 15.5 kW 1023 cc Diesel Engine, 32 in Drums, Articulated Steering, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  Wacker Neuson Trench Compactor S/N: 24540169 C/W: Tier 4, 2020 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Cordless Remote Control, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 512 Hr Asset located in: Lake Worth, TX
6095	·	6102	Wacker Neuson Trench Compactor S/N: 24498021 C/W: 2019 US EPA Label, Kubota D902 3 Cylinder 15.3 kW .89 L Diesel Engine, 24 in Drums, Remote Control w/ Cord, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 520 Hr Asset located in: Lake Worth, TX
6096	Usage: Not Available Asset located in: Lake Worth, TX  2016 Bomag BMP 8500 Articulating Trench Compactor S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in /	6103	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
6097	33 in Drums, Cordless Remote Control, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX  Bomag BMP 8500 Articulating Trench Compactor	6104	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available
	S/N: Not Available C/W: Kubota 3 Cylinder Diesel Engine, 24 in / 33 in Drums, Remote Control w/ Cord, Articulated Steering, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	6105	Asset located in: Lake Worth, TX  Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused)  S/N: Not Available  C/W: 1 Cylinder Gasoline Engine Usage: Not Available  Asset located in: Lake Worth, TX

Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available	6119	2014 Toro MB-1600 Walk-Behind Concrete Buggy
Asset located in: Lake Worth, TX	6119	S/N: 314000161 C/W: Hydrostatic Drive, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available
2024 Landhonor LHR-RM90 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available	6120	Asset located in: Lake Worth, TX  Bad Boy Electric Utility Vehicle  S/N: BBE514B3785006557  C/W: Canopy, 2 Passenger, Winch, Brush Guard
Asset located in: Lake Worth, TX		Usage: Not Available  Asset located in: Lake Worth, TX
Bomag Jumping Jack Tamper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6121	Mortar and Grout Mixer S/N: Not Available C/W: 2013 US EPA Label, Honda GX240 Gasoline Engine, S/A Trailer, Ball Hitch,
Quantity of Concrete Hoppers & Stand S/N: Not Available Usage: Not Available		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
2007 Starind 1550 Concrete Chute S/N: Not Available C/W: Fork Pockets; EQUIPMENT-FROM- SUNSTATE-EQUIPMENT	6122	2024 Landhonor LHR-CM300 Portable Concrete Mixer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
Asset located in: Lake Worth, TX	6123	2024 Landhonor LHR-CM400 Portable Concrete Mixer (Unused)
S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
Quantity of (3) Pneumatic Chipping Hammers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>—</b>  6124	Quantity of (2) Walk-Behind Saws  S/N: 2800003 / 3A9S46M10G1168026  C/W: Water Hose Connection, Manual Blade Raise / Lower, Honda GX390 1 Cylinder Gasoline Engine, (1) Husqvarna FS513 Walk- Behind Saw s/n: 2800003 & (1)Tiger MSM
Quantity of (3) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Walk-Behind Saw s/n: 3A9S46M10G1168026 (Inoperable) Usage: Not Available Asset located in: Lake Worth, TX
Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6125	Husqvarna FS6600D Walk-Behind Saw (Inoperable) S/N: 001298383001 C/W: Water Hose Connection, Electric Blade Raise / Lower, US EPA Label, John Deere
Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		4024HF295 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
Toro 23135 Mini Skid Steer Breaker S/N: 313000111	6126	REMOVAL;  Asset located in: Lake Worth, TX
Usage: Not Available  Asset located in: Lake Worth, TX		2024 Landhonor LHR-Q300 Heavy Duty Concrete Floor Walk-Behind Saw (Unused)
2024 Gar-Bro Concrete Bucket S/N: 427-R DWG 14-11 Usage: Not Available		S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Bomag Jumping Jack Tamper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of Concrete Hoppers & Stand S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  2007 Starind 1550 Concrete Chute S/N: Not Available C/W: Fork Pockets; EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Toro 23135 Mini Skid Steer Breaker S/N: 313000111 Usage: Not Available Asset located in: Lake Worth, TX	Bomag Jumping Jack Tamper S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of Concrete Hoppers & Stand S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX  2007 Starind 1550 Concrete Chute S/N: Not Available C/W: Fork Pockets; EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) Pneumatic Breakers S/N: Not Available Usage: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (3) Pneumatic Chipping Hammers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Toro 23135 Mini Skid Steer Breaker S/N: 313000111 Usage: Not Available Asset located in: Lake Worth, TX  2024 Gar-Bro Concrete Bucket S/N: 427-R DWG 14-11 Usage: Not Available

Lot #	Details	Lot #	Details
6129	2019 Core Cut Walk-Behind Saw S/N: 162276 C/W: 30 in Max Blade Diameter, 15 in Max Cutting Depth, Hydraulic Blade Raise / Lower, 2019 US EPA Label, Kubota 4 Cylinder 2.6 L Diesel Engine Usage: 1,607 Hr Asset located in: Lake Worth, TX  2012 Hsqvarna 4000 Walk-Behind Saw S/N: 001309168002 C/W: 13 in Max Blade Diameter, 6.5 in Max Cutting Depth, Manual Blade Raise / Lower,	6138	Quantity of (3) 16 in Sono-Tube Concrete Forms  S/N: Not Available C/W: 16 in Wide, (1) 7 ft 6 in, (1) 8 ft, (1) 10 ft Usage: 5 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
	Kohler 20 hp 624 cc Gasoline Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	6139	<b>8 ft Man Guard</b> S/N: Not Available
6131	Merit 600.62DR4 Walk-Behind Saw S/N: 10002020		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: 4 Cylinder Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 780 Hr  Asset located in: Lake Worth, TX	6140	<b>8 ft Man Guard</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
6133	Quantity of (3) 2018 Multiquip B46H11H Power Trowel S/N: MG0112140/MF0111393/MG0112160 C/W: Honda Gas Engine, (2) 42 In, (1) 36 In	6141	NTS 52-88 in Trench Shield S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX		2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused)
6134	Wacker Electric Concrete Vibrator S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		S/N: Not Available C/W: Two Crates Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	6143	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused)
6135	2007 Wacker M3000 Concrete Vibrator S/N: 1782595 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available		S/N: Not Available C/W: Two Crates Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	6144	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused)
6136	2013 Edco 2EC-NG-1.5 Electric Concrete Grinder S/N: 130910129 C/W: 22 in Grinding Width, 2 Grinding Discs,	6145	S/N: Not Available C/W: Two Crates Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available  Asset located in: Lake Worth, TX		2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused)
6137	2010 Whiteman WRS-5200 Concrete Screed S/N: WG1800464 C/W: 7 ft Screed, 41 ft Boom Length, 2009 US EPA Label, Daihatsu 3 Cylinder Diesel Engine Usage: 24 Hr Asset located in: Lake Worth, TX		S/N: Not Available C/W: Two Crates Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
		6146	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX

1 ** "	Deteile	1 -+ "	Dataila
Lot #	Details	Lot #	Details
6147	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available Asset located in: Lake Worth, TX	6154	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6148	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Two Crates Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6149	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building Shed (Unused) S/N: Not Available C/W: Two Crates Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
6150	Asset located in: Lake Worth, TX  2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused)	6156	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Usage: Not Available		Asset located in: Lake Worth, TX
6151	Asset located in: Lake Worth, TX  2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6157	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6158	2024 Agriquip DG2322 Double Garage Metal
6152	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6159	2024 Agriquip DG2322 Double Garage Metal
6153	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6160	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6166	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6161	2024 Agriquip DG2322 Double Garage Metal	6167	2024 Agriquip CP2020 20 ft x 20 ft Steel
	Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6162	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6168	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6163	2024 Agriquip CP2020 20 ft x 20 ft Steel	6169	2024 Agriquip CP2020 20 ft x 20 ft Steel
	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
6164	2024 Agriquip CP2020 20 ft x 20 ft Steel	6170	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All-
	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6171	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport Shed (Unused) S/N: Not Available
6165	2024 Agriquip CP2020 20 ft x 20 ft Steel		Usage: Not Available  Asset located in: Lake Worth, TX
	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6172	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6173	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6179	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6174	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6180	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6175	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6181	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6176	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6182	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6177	2024 Agriquip SG1420 Single Garage Metal Shed (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6183	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6178	2024 SUNTOP S1220 Metal Shed (Unused) S/N: Not Available		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	6184	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6185	5 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6192	2024 Landhonor LHR-CP1119 11 ft x 19 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6193	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available
6186	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6194	2024 Landhonor LHR-MS1119 11 ft x 19 ft Metal Garage Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6195	2024 Landhonor PLD-MS0608 6 ft x 8 ft
6187	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Galvanized Metal Shed (Unused) S/N: Not Available C/W: Two Boxes Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	6196	2024 Landhonor PLD-MS0608 6 ft x 8 ft Galvanized Metal Shed (Unused) S/N: Not Available
6188	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)		C/W: Two Boxes Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6197	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF  THE ACTUAL PRODUCT
6189	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available	6198	2024 Landhonor PLD-MS0604P 6 ft x 4 ft
	Asset located in: Lake Worth, TX	4	Galvanized Metal Pent Shed (Unused) S/N: Not Available
6190	KJ K1220 12 Ft x 20 Ft Single Garage Metal Shed S/N: Not Available	6199	C/W: Two Boxes Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: one crate Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Quantity of (2) 4 Ft x 6 Ft Metal Shed S/N: Not Available C/W: two boxes
6191	2024 Landhonor LHR-CP1119 11 ft x 19 ft All- Steel Carport Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6200	Cummins CXL855GP200 270 kW Mobile Generator Set S/N: 1080210013 C/W: Cummins 6 Cylinder Diesel Engine, 337.5 kVA/270 kW Rated 3 Phase Output, / 347 V / 600 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, E-Stops, T/A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX	6208	2005 Katolight 50 kW Mobile Stand-By Generator Set S/N: 5FTGE102051024328 C/W: 2004 US EPA Label, John Deere 5030TF270C 5 Cylinder 60 kW 3.0 L Diesel Engine, 50 kVA,/50 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 20,410 Hr Asset located in: Lake Worth, TX
6201	Cummins 200DGFC-5199 200 kW Skid-Mounted Stand-By Generator Set S/N: D050767149 C/W: US EPA Label, Cummins 6CTAA8.3G3 6 Cylinder 8.3 L Diesel Engine, 250 kVA/200 kW Rated 3 Phase Output, 134 kVA,/134 kW, Rated Single Phase Output, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, E-Stops Usage: Not Available Asset located in: Lake Worth, TX	6209	Allmand MP45-8E1 45 kVA Mobile Generator Set  S/N: 1338E10445 C/W: 2018 US EPA Label, Isuzu BP-4LE2X 4 Cylinder 49 kW Diesel Engine, 45 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 120 V Rated Voltage, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: 2,301 Hr Asset located in: Lake Worth, TX
6202	Sdmo J230 240 kW Mobile Generator Set S/N: J23031607497801 C/W: John Deere 6 Cylinder Diesel Engine, 240 V / 480 V Rated Voltage, T/A Trailer, Lunette Ring Usage: 2,753 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX  2014 Magnum MMG100D Generator Set	-6210	2019 Magnum Pro MMG45IF4 38 kW Mobile Generator Set  S/N: 3004557276  C/W: 2019 US EPA Label, Isuzu BQ4IE2X 19 kW  2.2 L Diesel Engine, 33 kVA/ Rated 3 Phase  Output, 480 V / 208 V Rated Voltage, 240 V  Rated Voltage, Sound Attenuated, Bottom  Mounted Fuel Tank, T/A Trailer, Ball Hitch,  Surge Brakes, EQUIPMENT FROM UNITED  RENTALS  Usage: 13,399 Hr  Asset located in: Lake Worth, TX
	S/N: 1408172 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 14,441 Hr <b>Asset located in</b> : Lake Worth, TX	6213	2013 Wacker Neuson G50 38 kW Mobile Generator Set S/N: 4TCSU1851DH189075 C/W: 2013 US EPA Label, John Deere 4045Tf290B 4 Cylinder 4.5 L Diesel Engine, 48
6205A	S/N: C11-12-05372 C/W: 2011 US EPA Label, CARB Compliant, Perkins 3362 4 Cylinder 116.9 kW 4.4 L Diesel Engine, 100 kVA/80 kW Rated 3 Phase Output, 480 V / 208 V / 120 V Rated Voltage, 100 kVA,		kVA/38 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Lunette Ring Usage: Not Available  Asset located in: Lake Worth, TX
	/80 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: Not Available Asset located in: Midland, TX		2014 Multiquip DCA-45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1222EL014135 C/W: 2014 US EPA Label, Isuzu 4LE2X 4 Cylinder 56 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated
6206	2016 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set  S/N: 7353339  C/W: Isuzu BR-4JJ1X 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 12,507 Hr  Notes: .  Asset located in: Lake Worth, TX		Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,121 Hr  Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6214	2012 Multiquip DCA-45SSIU4 36 kW Mobile Generator Set S/N: 4GNBG1221CB030860 C/W: Isuzu 4JJ1T 4 Cylinder 2.99 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 24,512 Hr Asset located in: Lake Worth, TX	6220	Airman SDG25S 25 kVA Skid-Mounted Generator Set S/N: 1238E13551 C/W: 2022 US EPA Label, Isuzu 4 Cylinder 30 kW Diesel Engine, 25 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 13,453 Hr Asset located in: Lake Worth, TX  2017 Multiquip DCA-25SSIU4F 20 kW Mobile
6215	Cat Mobile Generator Set		Generator Set S/N: 4GNBG0918HB044057
	S/N: 1JG110206N1606402 C/W: Cat 4 Cylinder Diesel Engine, T/A Trailer, Ball Hitch, Electric Brakes Usage: 1,300 Hr <b>Asset located in</b> : Lake Worth, TX		C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer,
6216	2019 Wacker Neuson G25 20 kW Mobile Generator Set (Inoperable)		Lunette Ring Usage: 768 Hr
	S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: 4 Cylinder Diesel Engine, 24.4 kVA/19.5 kW Rated 3 Phase Output, 240 V / 480 V / 120 V Rated Voltage, 16 kVA,/16 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 661 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX	6222	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set  S/N: 4GNBG0910GB043032  C/W: 2016 US EPA Label, Isuzu 4LE2T 4  Cylinder 37 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT
6217	Allmand MP25 25 kVA Skid-Mounted Generator Set		Usage: 7,983 Hr Asset located in: Lake Worth, TX
	S/N: 1238E12204 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 9,942 Hr Asset located in: Lake Worth, TX	6224	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 7152111 C/W: 2015 US EPA Label, Isuzu 4LE2T 4 Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/2 kW Rated 3 Phase Output, 240 V / 480 V Rat
6218	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12050 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V /		Voltage, 14 kVA,/14 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 2,725 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 10,981 Hr <b>Asset located in</b> : Lake Worth, TX		Multiquip DCA25SSIU4F Generator Set S/N: 7154328 Usage: Not Available Asset located in: Lake Worth, TX
6219	Allmand MP25 25 kVA Skid-Mounted Generator Set S/N: 1238E12221 C/W: 2019 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder 30 kW Diesel Engine, 120 V / 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 11,249 Hr Asset located in: Lake Worth, TX	6225	Multiquip DCA45SSIU4F Generator Set S/N: 7252100 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6226	2016 Atlas Copco 20 kW Mobile Generator Set S/N: 4500G1111GR121222 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 1,895 Hr	6239	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07000969 C/W: 2015 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: 4,827 Hr Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	6240	2016 Allmand 8KWNLP 1250 W Light Tower
6228	2006 MMD SDG25S 20 kVA Mobile Generator Set S/N: 5UABU09196V000009 C/W: 2006 US EPA Label, Isuzu 4LE1 4 Cylinder 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3	02.10	S/N: 07-000162 C/W: Cat c1.1 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 2,815 Hr <b>Asset located in</b> : Lake Worth, TX
	Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 5,460 Hr Asset located in: Lake Worth, TX	6241	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA4LU497838 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 300 Hr
6233	Generac Guardian 24 kW Stand-By Generator		Asset located in: Lake Worth, TX
	Set S/N: Not Available C/W: Natural Gas Engine Usage: Not Available Asset located in: Lake Worth, TX	6242	2020 Doosan 6 kVA Light Tower S/N: 4FVLSBAA2LU497952 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch
6234	<b>1997 Kohler 40RZ Electric Transfer Switch</b> S/N: 384987 C/W: To Fit Kohler	6243	Usage: 294 Hr <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX		2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0410PM003593 C/W: 2023 US EPA Label, CARB Compliant,
6235	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC17JH000125 C/W: Tier 4, 2015 US EPA Label, Kubota d1105 3 Cylinder 12 kW 1.1 L Diesel Engine, 4 Lamps,		Kohler 19 kW 1.0 L Diesel Engine, 2 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1 Hr <b>Asset located in</b> : Humble, TX
	Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,070 Hr Asset located in: Lake Worth, TX	6244	S/N: 5XFLV0416PM003596
6236	2018 Allmand 7 kW Light Tower S/N: 5AEA1AC19JH000334 C/W: Tier 4, 2017 US EPA Label, Kubota d1005 3 Cylinder 10 kW 1 L Diesel Engine, 4 Lamps,		Usage: 1 Hr
	Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,493 Hr <b>Asset located in</b> : Lake Worth, TX	6245	2023 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV14PM003595
6237	<b>2018 Allmand NLV-P Light Tower</b> S/N: 39-003469 Usage: 3,471 Hr		C/W: 2023 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8 Hr
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
6238	Allmand Night-Lite Pro II 7.5 kW Light Tower S/N: 07-001037 C/W: Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Balloon Diffuser, S/A Trailer, Ball Hitch Usage: 4,887 Hr Asset located in: Midland, TX	6246	2023 Wacker Neuson 6 kW Light Tower S/N: 5XFLV0416PM000889 C/W: 2022 US EPA Label, CARB Compliant, Kohler 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 9 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6247	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0417JM03162 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,418 Hr	6254	2018 Magnum Pro MLT6SM 6 kW Light Tower S/N: 7FSBL1010JB586914 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8,910 Hr
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	6255	Asset located in: Lake Worth, TX  2017 Magnum Pro MLT6SM 6 kW Light Tower
	Asset located in: Lake Worth, TX	_	(Inoperable)
6248	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0415JM003256 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,574 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		S/N: 3001715479 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,347 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
6249	2018 Wacker Neuson LTV6 6 kW Light Tower		Asset located in: Lake Worth, TX
02-17	S/N: 5XFLV0416JM003847 C/W: Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,817 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	6256	2018 Magnum MLT6SK Light Tower S/N: 3003103485 C/W: Kubota 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6257	2018 Wacker Neuson LTV6K Light Tower
6250	2018 Wacker Neuson LTV6 6 kW Light Tower S/N: 5XFLV0413JM003840 C/W: 2018 US EPA Label, Kohler 3 Cylinder 19		S/N: WNCLTV02CPUM04886 Usage: 9,715 Hr <b>Asset located in</b> : Lake Worth, TX
	kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 5,346 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6258	2022 Generac MLT6S 2.5 kVA Light Tower S/N: 7FSBL1015NB259608 C/W: 2022 US EPA Label, Mitsubishi L2E 2 Cylinder 8 kW .6 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,788 Hr
6251	2019 Magnum Pro MLT6SM 6 kW Light Tower		Asset located in: Lake Worth, TX
	S/N: 7FSBL1012KB834551 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,483 Hr Asset located in: Lake Worth, TX	6259	2017 Generac MLT6SMD Light Tower S/N: 3001517568 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 803 Hr
6252	2019 Magnum MLT6SMD Light Tower S/N: 7FSBL1013JB992752		Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
	C/W: US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch	6061	
	Usage: 673 Hr  Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX	6261	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1016HB880618 C/W: US EPA Label, Mitsubishi 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch
6253	2018 Magnum MLT6SMD 6 kW Light Tower S/N: 7FSBL1010JB983099 C/W: 2018 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		Usage: 1,312 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6262	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1013HB568871 C/W: 2016 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 3,886 Hr	6269	2014 Allmand PAL1250W2 Light Tower S/N: 0203PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6270	2012 Allmand Light Tower S/N: 0229PAL12	
6263	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880896 C/W: 2017 US EPA Label, Mitsubishi L3E 3		C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,613 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6271	2012 Allmand Light Tower S/N: 0224PAL12 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
6264	2017 Generac MLT6SMD Light Tower S/N: 7FSBL1011HB880607 C/W: 2017 US EPA Label, Mitsubishi L3E- W464MLD 3 Cylinder 1.0 L Diesel Engine, 4	6272	<b>1997 Amida AL4075D-4MH Light Tower</b> S/N: 971044029 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch, Electric Brakes Usage: 6,831 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880607		2018 Doosan HP1600WCU-T4F 1600 cfm Mobile Air Compressor S/N: 4FVCCBPB8JU483256 C/W: 150 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel	
6265	Asset located in: Lake Worth, TX  2019 Terex RL4 6 kW Light Tower  S/N: 4ZJSA1015J1009757  C/W: 2018 US EPA Label, Deutz 3 Cylinder 1.0		Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes Usage: 1,806 Hr  Asset located in: Lake Worth, TX	
	L Diesel Engine, 4 Lamps, Power Receptacles, S /A Trailer, Ball Hitch Usage: Not Available Asset located in: Midland, TX	6275	6275 2011 Doosan HP1600 Mobile Air Co S/N: 419233UJUB83 C/W: 200 psi Working Pressure, 201	2011 Doosan HP1600 Mobile Air Compressor S/N: 419233UJUB83 C/W: 200 psi Working Pressure, 2019 US EPA
6266	2016 Terex RL4 6 kW Light Tower S/N: RL416J-1024 C/W: 2015 US EPA Label, Kohler FKHXL1.3 3		Label, Cummins QSX15 6 Cylinder 344 hp 15 L Diesel Engine, T/A Trailer, Lunette Ring Usage: 9,344 Hr <b>Asset located in</b> : Lake Worth, TX	
	Cylinder 8 kW 1.3 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 8,753 Mi Notes: LOCATED-IN-HOUSTON-TX; EQUIPMENT FROM SUNBELT RENTALS; Asset located in: Humble, TX	6276 2012 Sullair 900H Mobile Air C S/N: 201202150037 C/W: Air Dryer, 250 psi Working C9 6 Cylinder Diesel Engine, T/ Lunette Ring, Electric Brakes Usage: Not Available Notes: CERTIFICATE OF ORIGI OFFICE; Asset located in: Lake Worth, T 6277 2015 Doosan XP825WCU Mob Compressor S/N: 4FVCBBFB3FU46608 C/W: 250 psi Working Pressure Cylinder Diesel Engine, Require Exhaust Fluid, T/A Trailer, Lune Brakes Usage: 3,198 Hr	C/W: Air Dryer, 250 psi Working Pressure, Cat C9 6 Cylinder Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes	
6267	2011 Magnum MLT3060M Light Tower S/N: 5AJLS1614BB006243 C/W: 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch		Notes: CERTIFICATE OF ORIGIN AVAILABLE IN	
	Usage: 5,275 Hr  Asset located in: Lake Worth, TX		•	
6268	2014 Allmand PAL1250W2 Light Tower S/N: 0202PAL14 C/W: Single Lamp, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		C/W: 250 psi Working Pressure, Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, T/A Trailer, Lunette Ring, Electric Brakes	

Lot #	Details	Lot #	Details
6278	2012 Atlas Copco XAS750JD7T3 Mobile Air Compressor S/N: 4500B1611CR080883 C/W: 261 psi Working Pressure, John Deere 6 Cylinder 6.8 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 468 Hr Asset located in: Lake Worth, TX	6286	2013 Atlas Copco XATS400JD7 Mobile Air Compressor S/N: 4500B1310DR074160 C/W: 175 psi Working Pressure, John Deere 4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,323 Hr Asset located in: Lake Worth, TX
6280	Airman PDS400S Mobile Air Compressor	6287	2011 Atlas Copco XAVS375 Mobile Air
	S/N: C16B10076 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,172 Hr <b>Asset located in</b> : Lake Worth, TX	_	Compressor S/N: 4500B1312BR071984 C/W: 2011 US EPA Label, John Deere 4045HF285 4 Cylinder 4.5 L Diesel Engine Usage: 889 Hr
6281	Airman PDS400S Mobile Air Compressor S/N: C16B10484 C/W: Isuzu 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 3,252 Hr		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	6288	2018 Doosan P250 Air Compressor
6282	2018 Doosan HP375WCU-T4F Mobile Air Compressor S/N: Not Available C/W: 250 psi Working Pressure, 2018 US EPA Label, Cummins QSB4.5 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A		S/N: 4FVCABBA2JU483872 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available <b>Asset located in</b> : Humble, TX
	Trailer, Ball Hitch, Electric Brakes Usage: 4,337 Hr  Asset located in: Lake Worth, TX	6289	Sullair 250Q Air Compressor S/N: 004-100085 Usage: Not Available
6283	2017 Doosan P425/HP375 Mobile Air Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 6 Cylinder 130 hp 4.8 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Usage: 1,709 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6290	<b>2021 Atlas Copco XAS188 KD8 Air Compressor</b> S/N: UVC200482 Usage: 13 Hr <b>Asset located in</b> : Lake Worth, TX
6284	2017 Doosan P425/HP375WCU-T4F Mobile Air Compressor S/N: Not Available C/W: 2017 US EPA Label, Cummins 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring, Electric Brakes Usage: 3,099 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL	6291	2021 Atlas Copco XAS188 KD8 Mobile Air Compressor S/N: 4500A1017MR200473 C/W: 125 psi Working Pressure, Kubota D1803- T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
	OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO ; Asset located in: Lake Worth, TX		Compressor S/N: 4500A1012MR200476
6285	2016 Atlas Copco XATS400PEJD7 Mobile Air Compressor S/N: 4500B1315GR076376 C/W: 175 psi Working Pressure, John Deere		C/W: 125 psi Working Pressure, Kubota D1803- T 3 Cylinder 49 hp Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	4045HFC93 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,560 Hr <b>Asset located in</b> : Lake Worth, TX	6293	<b>2021 Kaeser M55 PE Air Compressor</b> S/N: WKA0N1000M8357329 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX

Lot #	Details	Lot #	Details
6294	Kaeser M55 PE Air Compressor S/N: 1383-8357356 Usage: Not Available Asset located in: Lake Worth, TX	6302	2019 Allmand MA185-5E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L
6295	Kaesar M58 Air Compressor S/N: 1062-7593833 Usage: Not Available Asset located in: Lake Worth, TX		Diesel Engine, S/A Trailer, Ball Hitch Usage: 6,855 Hr <b>Asset located in</b> : Lake Worth, TX
6296	Kaeser M58 Air Compressor S/N: 1060-7586681 Usage: Not Available Asset located in: Lake Worth, TX	6303 	2020 Allmand MA185-6E1 185 cfm Mobile Air Compressor S/N: 5AEA1KF16LH000831 C/W: 185 psi Working Pressure, 2018 US EPA Label, Yanmar 4NNDAC 4 Cylinder 2.19 L Diesel Engine, S/A Trailer, Ball Hitch
6297	2015 Atlas Copco XAS185KD7PE 185 cfm Mobile Air Compressor S/N: 4500A1013FR049103 C/W: 123 psi Working Pressure, 2014 US EPA Label, Kubota V2403-CR-EF02 3 Cylinder 36.8 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch		Usage: 8,456 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; CERTIFICATE OF ORIGIN AVAILABLE IN OFFICE; Asset located in: Lake Worth, TX
	Usage: 976 Hr Asset located in: Lake Worth, TX	6304	2018 Sullair 185DPQ-KU-T3 185 cfm Mobile Air Compressor
6298	2021 Chicago Pneumatic CPS 185 KD8 Air Compressor S/N: HOP030934 Usage: 7 Hr Asset located in: Lake Worth, TX		S/N: 201801250011 C/W: 200 psi Working Pressure, 2017 US EPA Label, Kubota D1803 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT FROM UNITED RENTALS Usage: 2,460 Hr Asset located in: Lake Worth, TX
6299	2021 Airman PDS185S Mobile Air Compressor S/N: 7H6BY11A6MA002935 C/W: 200 psi Working Pressure, 2021 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 185 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX	6305	2018 Doosan P185WDOU-T4F 185 cfm Skid- Mounted Air Compressor S/N: 486622UFAGF89 C/W: 185 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Doosan 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Midland, TX
6300	Airman PDS185S 185 cfm Skid-Mounted Air Compressor S/N: B4-6811098 C/W: 150 psi Working Pressure, 2003 US EPA Label, Isuzu NE2 4 Cylinder 2.17 L Diesel Engine Usage: 1,840 Hr Asset located in: Lake Worth, TX	6306	2017 Doosan C185WDZ Mobile Air Compressor S/N: 4FVCABAA8HU479739 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,131 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
6301	2019 Allmand Maxi-Air 185 Mobile Air	6007	Asset located in: Lake Worth, TX
	Compressor S/N: 5AEA1KF10KH000628 C/W: 200 psi Working Pressure, 2018 US EPA Label, Yanmar 4 Cylinder 37 kW 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 9,961 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	6307	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 479354UAABG07 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,381 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE -MSO Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6308	2017 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 4FVCABAA2HU479803 C/W: 185 psi Working Pressure, 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 3,825 Hr Notes: ADDITIONAL INFORMATION	6314	2018 Sullair 185DPQ Mobile Air Compressor S/N: 201802270074 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 4 Cylinder 36 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,685 Hr Asset located in: Lake Worth, TX
	AVAILABLE IN OFFICE - MSO;  Asset located in: Lake Worth, TX	6315	2011 Sullair 185DPQJD Skid-Mounted Air Compressor S/N: 201107210060
6309	·		C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4 L Diesel Engine Usage: 2,365 Hr Asset located in: Lake Worth, TX
		6316	2004 Sullair 250DPQ-JDD Mobile Air Compressor S/N: 2004100085 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine Usage: 3,195 Hr
6310	2010 Doosan C185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2010 US EPA Label, Kubota V2403 36.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,140 Hr		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TY	6317	2017 Atlas Copco XAS185KD Mobile Air
6311	S/N: 151780U85957 C/W: 120 psi Working Pressure, John Deere 4 Cylinder Diesel Engine Usage: 3,697 Hr Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		Compressor S/N: 4500A1014HR055415 C/W: 185 psi Working Pressure, 2017 US EPA Label, Kubota 3 Cylinder 1.8 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 1,075 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
		6318	Asset located in: Lake Worth, TX  2017 Atlas Copco XAS185KD7PET4F Mobile
			Air Compressor S/N: 4500A1012HR055090 C/W: Kubota 4 Cylinder Diesel Engine, S/A
6312			Trailer, Lunette Ring Usage: 947 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX
	Lunette Ring Usage: 1,438 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6319	2017 Atlas Copco XAS185KD7PET4F Mobile Air Compressor S/N: 4500A1012HR055414 C/W: 2017 US EPA Label, Kubota 3 Cylinder 1.6 L Diesel Engine, S/A Trailer, Lunette Ring
6313	2013 Sullivan Palatek 185 cfm Mobile Air Compressor S/N: 101343 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF231A 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,018 Hr Asset located in: Lake Worth, TX		Usage: Not Available  Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6320	2013 Ingersoll Rand 185 cfm Mobile Air Compressor S/N: 4FVCABAAXDU454478 C/W: 200 psi Working Pressure, 2012 US EPA Label, John Deere 4024TF281C 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available	6327	2014 Lincoln Vantage 500 Multi-Process Engine Driven Welder S/N: U1140846332 C/W: Kohler Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 213 Hr Asset located in: Lake Worth, TX  2013 Lincoln Vantage 300 400 A Skid-Mounted
	Asset located in: Lake Worth, TX	0328	Multi-Process Engine Driven Welder
6321	2011 Atlas Copco XAS185JDRSC Mobile Air Compressor S/N: 4500A1019BR038617 C/W: 2011 US EPA Label, John Deere 4024TF281A 4 Cylinder 2.4 L Diesel Engine Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE		S/N: U1130305650 C/W: Tier 4, 2012 US EPA Label, CARB Compliant, Kohler V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 4,763 Hr Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	6329	2013 Lincoln Vantage 300 400 A Skid-Mounted Multi-Process Engine Driven Welder
6322	2007 Airman PDS185S 185 cfm Mobile Air Compressor S/N: B46B44752 C/W: 150 psi Working Pressure, 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY	6330	S/N: U1130301883 C/W: 2012 US EPA Label, CARB Compliant, Kubota V1505-BG-ET02 4 Cylinder 16.4 kW 1.0 L Diesel Engine, Welding Leads Not Included, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 5,080 Hr Asset located in: Lake Worth, TX
	Usage: 1,309 Hr  Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY  Asset located in: Lake Worth, TX		2020 Miller Bobcat 260 Multi-Process Engine Driven Welder S/N: NA300101R
6324	2021 Rotair D400T4F 150 cfm Mobile Air Compressor S/N: 16MBB1319MD081696 C/W: 150 psi Working Pressure, 2021 US EPA Label, Cummins QSF3.8 4 Cylinder 3.8 L Diesel		C/W: Kohler Engine, Welding Leads, 120 V / 240 V Rated Voltage, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 496 Hr Notes: . Asset located in: Lake Worth, TX
	Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch Usage: 1,709 Hr <b>Asset located in</b> : Lake Worth, TX	6332	2015 Miller Trailblazer 251 Multi-Process Engine Driven Welder S/N: MF500520R
6325A	Sullair Skid-Mounted Air Compressor S/N: 5AEA1KF15KH000737 C/W: 185 psi Working Pressure, 2011 US EPA Label, John Deere 4024TF 4 Cylinder 37 kW 2.4	6333	C/W: 2015 US EPA Label, Kohler CH730 725 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage Usage: 2,736 Hr <b>Asset located in</b> : Lake Worth, TX
	L Diesel Engine Usage: 979 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX		2016 Miller Bobcat 250 Mobile Multi-Process Engine Driven Welder S/N: MG310150R C/W: 2016 US EPA Label, Kohler 3 Cylinder 725 cc Engine, 240 V / 208 V Rated Voltage, 120 V Rated Voltage
6325B	Genaer Skid-Mounted Air Compressor S/N: 1611	G334 Miller S/N: L C/W: Voltage Usage	Usage: 619 Hr  Asset located in: Lake Worth, TX
	C/W: 15 hp Motor, 2014 US EPA Label, Kubota V3800 4 Cylinder 3.8 L Diesel Engine Usage: Not Available <b>Asset located in</b> : Midland, TX		Miller Multi-Process Engine Driven Welder S/N: LG076841 C/W: Gasoline Engine, 240 V / 120 V Rated
6326	Smith Mobile Air Compressor S/N: 100510361 C/W: 125 psi Working Pressure, Ford 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX		Voltage, 120 V Rated Voltage Usage: 1,576 Hr <b>Asset located in</b> : Lake Worth, TX

Lot #	Details	Lot #	Details
6335	2005 Miller Bobcat 250 Engine Driven Welder S/N: LF041958 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	6342	Slanzi Skid-Mounted Water Pump S/N: 249606 C/W: 4 in Intake, 3 in Discharge, Centrifugal Water Pump, Slanzi 4 Cylinder Diesel Engine Usage: 183 Hr Notes: ITEMS AT OFFSITE LOCATION MUST
6336	2005 Miller Bobcat 250 Skid-Mounted Multi- Process Engine Driven Welder S/N: LF041958 C/W: 2005 US EPA Label, Kohler CH20S 624 cc Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY		SUBJECT TO 3RD PARTY STORAGE I BUYER RESPONSIBLE FOR LOADOUT
	Usage: 1,686 Hr  Asset located in: Lake Worth, TX	6343	<b>2022 Stealth Trailer-Mounted Water Pump</b> S/N: 1R9RBUAA7NS723142
6337	Lincoln Vantage 520SD 520 A Mobile Stick Engine Driven Welder S/N: Not Available C/W: 2015 US EPA Label, Deutz d2.9I 4 Cylinder 40 hp 2.9 L Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S/A	6344	C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, 2021 US EPA Label, CARB Compliant, Deutz TD2.9L4 4 Cylinder 55.4 kW 2.92 L Diesel Engine, S/A Trailer, Ball Hitch, 85 Gallon Skid Usage: Not Available Asset located in: Midland, TX
6338	Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) Miller Millermatic 255 Wire		6 In Water Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
0000	Electric Welder  S/N: NA168518N/NB358903N  C/W: Single Phase, 200 V/ 240 V Input,  Welding Leads, EQUIPMENT-FROM-US-AUTO- RECYCLING  Usage: Not Available  Notes:	6345	Quantity of (4) Water Pump  S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Water Pump, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
6339	Asset located in: Lake Worth, TX  Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder	6346	Quantity of (3) Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
	S/N: Not Available C/W: 2013 US EPA Label, Kubota v1505 4 Cylinder Diesel Engine, Welding Leads Not		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Included, 120 V / 240 V Rated Voltage Usage: 4,301 Hr <b>Asset located in</b> : Lake Worth, TX	6347	Quantity of (3) Water Pump S/N: Not Available C/W: 3 in Intake, 2 in Discharge
6340	2012 Gorman-Rupp PA6C60-4045T Trailer- Mounted Water Pump		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 1493129N C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 8,350 Hr	6348	Quantity of (3) Water Pump S/N: Not Available C/W: 2 in Intake, 3 in Discharge Usage: Not Available Asset located in: Lake Worth, TX
6341	Asset located in: Lake Worth, TX  Gorman-Rupp Mobile Centrifugal Pump S/N: Not Available C/W: US EPA Label, John Deere 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	6349	Quantity of (3) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: Trash Pump, 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		6350	Quantity of (2) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Trash Pump Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6352	Cornell 25WHRPPF86 Electric Skid-Mounted Water Pump S/N: 2530458 C/W: 3 in Intake, 2.5 in Discharge, Centrifugal, WEC 25 Hp Electric Motor; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	6360	1998 Mitsubishi FD35 8000 lb Pneumatic Tire Forklift S/N: AF19B00320 C/W: 2 Stage Mast, 148 in Max Lift Height, 97 in Lowered Mast Height, 48 in Forks, Side Shift, Mitsubishi 6 Cylinder Diesel Engine Usage: 9,917 Hr Asset located in: Lake Worth, TX
6353	Skid-Mounted Water Pump	6361	2001 Hyster H80XM 7700 lb Pneumatic Tire
	S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal Trash Pump, 2014 US EPA Label, Honda 270 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE		Forklift S/N: K005A04243Y C/W: 2 Stage Mast, 122 in Max Lift Height, 57 in Forks, Fork Positioner, Solid Pneumatic Tires, V6 LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	6361A	2015 Toyota 8FG35U 7300 lb Cushion Tire Forklift S/N: 10863 C/W: 3 Stage Mast, 159.5 in Max Lift Height, 106 in Lowered Mast Height, 48 in Forks, Side
6354	Quantity of Pump & PTO S/N: Not Available C/W: MC L0614SC Triplex pump, Muncie PTO, (2) Tanks, One Pallet		Shift, Fork Positioner, 2015 US EPA Label, Toyota 4 Cylinder 63 kW 3.6 L LPG Engine Usage: 1,917 Hr Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	6362	2007 TCM FD70-9 12980 lb Pneumatic Tire Forklift
6356	Taylor Y-23WOF 23000 lb Dual Front Tires Pneumatic Tire Forklift  S/N: S2113943  C/W: 2 Stage Mast, 24 in Lowered Mast Height, 93 in Forks, Solid Pneumatic Tires, Detroit 4  Cylinder Diesel Engine Usage: 6,519 Hr		S/N: A30K00809 C/W: 2 Stage Mast, 157 in Max Lift Height, 96 in Lowered Mast Height, 94 in Forks, Fork Positioner, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 5,357 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6363	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused)
6357	2005 Hyster H155XL2 Pneumatic Tire Forklift S/N: G006V03382C Usage: Not Available Asset located in: Lake Worth, TX  Doosan GC55C-9 11850 lb Pneumatic Tire	S/N: 23L3001161 C/W: 3 Stage Mast, 189 in Max Lift in Lowered Mast Height, 48 in Fork 4 Cylinder LPG Engine Usage: 22 Hr	S/N: 23L3001161 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine
	Forklift S/N: FGB1C256000013 C/W: 2 Stage Mast, 162 in Max Lift Height, 82 in Lowered Mast Height, 59 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 3 Cylinder LPG Engine Usage: 7,819 Hr Asset located in: Lake Worth, TX	6364	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001163 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
6359	2017 Toyota 8FG45U 9300 lb Pneumatic Tire Forklift  S/N: 11419  C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 92 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 1,152 Hr  Asset located in: Lake Worth, TX	6365	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001164 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6366	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001157 C/W: 3 Stage Mast, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX	6374	Cat 2PD6000 6000 lb Pneumatic Tire Forklift S/N: AT14E30364 C/W: 2 Stage Mast, 147 in Max Lift Height, 96 in Lowered Mast Height, 53 in Forks, Side Shift, Solid Pneumatic Tires, 2010 US EPA Label, 4 Cylinder 3.3 L Diesel Engine Usage: 18,085 Hr Asset located in: Lake Worth, TX
6267	·	6375	Mitsubishi FG30 Pneumatic Tire Forklift
6367	<b>2014 Toyota 8FD35U 6500 lb Pneumatic Tire Forklift</b> S/N: 8FD35U-10678 C/W: 3 Stage Mast, 187 in Max Lift Height, 72	0373	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	in Forks, Fork Positioner, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder Diesel Engine Usage: 5,597 Hr <b>Asset located in</b> : Lake Worth, TX	6376	2015 Toyota 8FGU30 5820 lb Pneumatic Tire Forklift S/N: 65650 C/W: 2 Stage Mast, 159 in Max Lift Height, 102 in Lowered Mast Height, 40 in Forks, Side Shift,
6368	2019 Toyota 8FD35U 7000 lb Pneumatic Tire Forklift S/N: 8FD35U13204 C/W: 3 Stage Mast, 187 in Max Lift Height, 78 in Lowered Mast Height, 48 in Forks, Fork		Solid Pneumatic Tires, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 3,750 Hr Asset located in: Lake Worth, TX
	Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4 Cylinder 2.9 L Diesel Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	6377	2006 Toyota 7FGU30 5750 lb Pneumatic Tire Forklift S/N: 69901 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 83 in Lowered Mast Height, 45 in
6369	2005 Toyota 7FGU32 6020 lb Pneumatic Tire Forklift S/N: 68341 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 48 in		Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2006 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: Not Available  Asset located in: Lake Worth, TX
	Forks, Side Shift, 2006 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 8,373 Hr <b>Asset located in</b> : Lake Worth, TX	6378	2015 Cat DP30N Pneumatic Tire Forklift S/N: AT14G00200 C/W: 3 Stage Mast, 84 in Lowered Mast Height,
6370	2004 Tailift FD30 Pneumatic Tire Forklift S/N: 318920B Usage: Not Available		59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,524 Hr <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	6379	2017 Cat 2C6000 5750 lb Cushion Tire Forklift
6371	Doosan G30P-5 5550 lb Pneumatic Tire Forklift S/N: FGA0C-1330-02057 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, GM Vortec 4 Cylinder Dual Fuel Engine Usage: 6,566 Hr Asset located in: Lake Worth, TX	S/N: AT83F42214 C/W: 3 Stage Mast, Full Free Lift, Lift Height, 24 in Lowered Mast F Forks, Side Shift, Solid Pneumati 2017 US EPA Label, GCT 4 Cylind Engine Usage: Not Available	S/N: AT83F42214 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 52 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine
6372	2017 Hyundai 30L-7A 5900 lb Pneumatic Tire Forklift  S/N: 3HHKHH09CH8001849  C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 86 in Lowered Mast Height, 45 in Forks, Side Shift, 2017 US EPA Label, Hyundai 4 Cylinder 2.4 L LPG Engine Usage: 4,100 Hr  Asset located in: Lake Worth, TX	6380	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift  S/N: 69980  C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 4,420 Hr  Asset located in: Lake Worth, TX
6373	2016 Hyundai 301-7A Pneumatic Tire Forklift S/N: HHKHHF009CH0001849K Usage: Not Available Asset located in: Lake Worth, TX		Acceliocated III. Lake Worth, TA

Lot #	Details	Lot #	Details
6381	2017 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift  S/N: 8FDU30-62078  C/W: 3 Stage Mast, 187 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 3 Cylinder 1.7 L Diesel Engine Usage: 8,465 Hr  Asset located in: Lake Worth, TX  2014 Toyota 8FDU30 5620 lb Pneumatic Tire	6387	2018 Toyota 8FDU25 4800 lb Pneumatic Tire Forklift  S/N: 8FDU25-62405  C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Toyota Diesel Engine  Usage: 2,362 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
	Forklift S/N: 60256 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 88 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Fort Smith, AR
	Engine Usage: 2,134 Hr <b>Asset located in</b> : Lake Worth, TX	6388	2007 Cat P6000LP 5050 lb Pneumatic Tire Forklift S/N: AT13F10861
6383	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift S/N: 69985 C/W: 2 Stage Mast, Full Free Lift, 187 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota		C/W: 3 Stage Mast, 186 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Block Forks, Solid Pneumatic Tires, Tier 2, 2007 US EPA Label, Nissan K25 L 4 Cylinder 2.5 L LPG Engine Usage: Not Available  Asset located in: Lake Worth, TX
	4Y ECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 3,920 Hr  Asset located in: Lake Worth, TX	6389	2019 Toyota 8FDU25 5000 lb Pneumatic Tire Forklift S/N: 62836 C/W: Enclosed Cab, 2 Stage Mast, Full Free Lift, 131.5 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2019 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 1,127 Hr Asset located in: Lake Worth, TX
6384			
		6390	2016 Cat GP25N2-LE 5000 lb Pneumatic Tire Forklift S/N: AT35A02417
6385	2000 Toyota 7FGU30 Pneumatic Tire Forklift S/N: 61163 C/W: 3 Stage Mast, 47 in Forks, Solid Pneumatic Tires, LPG Engine Usage: Not Available Asset located in: Lake Worth, TX		C/W: 3 Stage Mast, 83 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2016 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 4,117 Hr Asset located in: Midland, TX
6386	Cat 2PD6000 5500 lb Pneumatic Tire Forklift S/N: AT14E30407 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 58 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 11,707 Hr Asset located in: Lake Worth, TX	-6391 -	2004 Cat P5000 Pneumatic Tire Forklift S/N: AT3500741 C/W: 3 Stage Mast, Full Free Lift, 46 in Forks, Side Shift, Solid Pneumatic Tires, 2004 US EPA Label, Nissan 4NSXB02.5 4 Cylinder 61.5 hp 2.5 L LPG Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
6386A	Doosan D30G 5467 lb Pneumatic Tire Forklift S/N: K360403 C/W: 3 Stage Mast, Full Free Lift, 185.6 in Max Lift Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	6391A	Hyundai G25SP-3 5000 lb Pneumatic Tire Forklift  S/N: D201409  C/W: 3 Stage Mast, 186 in Max Lift Height, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, Daewoo G430-LP 4  Cylinder LPG Engine  Usage: 9,190 Hr  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6392	2020 Cat Gp25N 4500 lb Pneumatic Tire Forklift S/N: AT35A09092 C/W: 3 Stage Mast, 188 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 1,558 Hr Asset located in: Lake Worth, TX	6398	2024 Viper FY30T 4795 lb Pneumatic Tire Forklift (Unused) S/N: 23L3000549 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Hyundai 4 Cylinder LPG Engine Usage: 2 Hr Asset located in: Lake Worth, TX
6393	2018 Doosan G25N7 4600 lb Pneumatic Tire Forklift	6398A	Heli 4600 lb Pneumatic Tire Forklift
	S/N: FGA14-1290-00939 C/W: 2 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Tier 2, 2018 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 2,390 Hr	OJYKA	S/N: 25025117944 C/W: 3 Stage Mast, 75 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder 3.0 L Dual Fuel Engine Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6399	2014 Komatsu FG25HT-16 4650 lb Pneumatic
6393A	2011 Doosan G25P-5 Pneumatic Tire Forklift S/N: FGA0B133001275 C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, 2011 US EPA Label, GM 4 Cylinder 46 kW 2.4 L LPG Engine Usage: 3,885 Hr Asset located in: Lake Worth, TX		Tire Forklift S/N: A260155 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, Tier 2, 2014 US EPA Label, GCT 4 Cylinder 2.5 L Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
6395	2019 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift		Usage: 2,436 Hr  Asset located in: Humble, TX
	S/N: 94056 C/W: 3 Stage Mast, 131 in Max Lift Height, 24 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 11,841 Hr Asset located in: Lake Worth, TX	6399A	2016 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 78142 C/W: 3 Stage Mast, Full Free Lift, 198 in Max Lift Height, 87 in Lowered Mast Height, 48 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L Dual Fuel Engine Usage: 4,861 Hr
6396	2015 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift		Asset located in: Lake Worth, TX
	S/N: 8FGU25-67336 C/W: 2 Stage Mast, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 10,669 Hr Asset located in: Lake Worth, TX	6400	2015 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 67140 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4YECS 2.2 L Dual Fuel Engine, EQUIPMENT-FROM-US-AUTO- RECYCLING
6397	2016 Toyota 8FGU25 4900 lb Pneumatic Tire Forklift S/N: 72494		Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	C/W: 2 Stage Mast, Full Free Lift, 131.5 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, CARB Compliant, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6401	2019 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift  S/N: 94048  C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, 2019 US EPA Label, Toyota 4Y 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 28,396 Mi  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6401A	2015 Doosan D25S-7 4200 lb Pneumatic Tire Forklift  S/N: FDA00193000440  C/W: 2 Stage Mast, 163 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, 4  Cylinder Engine Usage: 3,385 Hr  Asset located in: Lake Worth, TX	6407A	1997 Mitsubishi FG30 5300 lb Pneumatic Tire Forklift  S/N: AF13D30869  C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 83 in Lowered Mast Height, 41 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: 2,369 Hr Asset located in: Lake Worth, TX	
6402	1994 Hyster H40XM 4000 lb Pneumatic Tire Forklift S/N: D177G9392R C/W: 3 Stage Mast, 153 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Isuzu 4 Cylinder Diesel Engine Usage: 2,238 Hr Asset located in: Lake Worth, TX	6408	1989 Clark GPS25MB 3800 lb Pneumatic Tire Forklift S/N: GP138MB03476968K0F C/W: 2 Stage Mast, 196 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 1,200 Hr Asset located in: Lake Worth, TX	
6403	Komatsu FG25 3990 lb Pneumatic Tire Forklift S/N: 144043A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 24 in Lowered Mast Height, 46 in Forks, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 4,607 Hr Asset located in: Lake Worth, TX	6409A	2015 Doosan D25S-7 3650 lb Pneumatic Tire Forklift  S/N: FDA0Q-1930-01126  C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 76 in Lowered Mast Height, 40 in Forks, Solid Pneumatic Tires, 4 Cylinder Diesel Engine  Usage: 2,689 Hr	
6404	Nissan PJ02A25PV 3975 lb Pneumatic Tire Forklift  S/N: PJ029H3529  C/W: 3 Stage Mast, 188 in Max Lift Height, 86 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 13,012 Hr  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6410	Asset located in: Lake Worth, TX  2002 Komatsu FG15HC-16 2500 lb Pneumatic Tire Forklift  S/N: 652910A  C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder Gasoline Engine Usage: 9,201 Hr  Asset located in: Lake Worth, TX	
6405	Asset located in: Humble, TX  2024 Viper FY25BCS 3900 lb Pneumatic Tire Forklift (Unused)  S/N: 222010033  C/W: 3 Stage Mast, 189 in Max Lift Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Mitsubishi 4 Cylinder LPG Engine Usage: 2 Hr	6410A 6412 6413	Crown Cushion Tire Forklift S/N: Not Available C/W: 3 Stage Mast, 74 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, John Deere 4 Cylinder LPG Engine Usage: 6,624 Hr Asset located in: Lake Worth, TX	
6406	Asset located in: Lake Worth, TX  2024 Viper FY25C 3900 lb Pneumatic Tire Forklift (Unused)  S/N: 222011086  C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2023 US EPA Label, CARB Compliant, Kubota		6412	2021 Yale GLC155VX 10000 lb Cushion Tire Forklift S/N: F879V02837V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
6407	WG2503 4 Cylinder 41 kW 2.5 L LPG Engine Usage: 3 Hr  Asset located in: Lake Worth, TX  Heli CPYD25 3900 lb Pneumatic Tire Forklift S/N: 2302574499 C/W: 3 Stage Mast, 185 in Max Lift Height, 24 in Lowered Mast Height, 59 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: Not Available  Asset located in: Lake Worth, TX		2021 Yale GLC155VX 10000 lb Cushion Tire Forklift S/N: F879V02836V C/W: 3 Stage Mast, 221 in Max Lift Height, 112 in Lowered Mast Height, Paper Roll Clamp, 6 Cylinder LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6414	2013 Toyota 7FGCU45 Cushion Tire Forklift S/N: 72832 C/W: 3 Stage Mast, Full Free Lift, 47 in Forks, Auxiliary Hydraulic Plumbing, LPG Engine Usage: 7,006 Hr Notes: . Asset located in: Lake Worth, TX	6423	2021 Mitsubishi FGC25N4 5000 lb Cushion Tire Forklift S/N: AF82F50026 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 56 in Forks, Load Weigh System, 2022 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,534 Hr
6415	2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42218 C/W: 3 Stage Mast, Full Free Lift, 185 in Max		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: Not Available  Asset located in: Lake Worth, TX	6424	2021 Mitsubishi FGC25N 5000 lb Cushion Tire Forklift S/N: AF82F49734 C/W: 2 Stage Mast, Full Free Lift, 80 in Max Lift
6416	2017 Cat 2C6000 5750 lb Cushion Tire Forklift S/N: AT83F42219 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 24 in Lowered Mast Height, 53 in Forks, Side Shift, 2017 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine		Height, 58 in Lowered Mast Height, 60 in Forks, Side Shift, Tier 2, 2021 US EPA Label, CARB Compliant, 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 3,757 Hr Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	6424A	<b>2013</b> Linde H25CT 5000 lb Cushion Tire Forklift S/N: A1131D00241
6419	2015 Toyota 8FGCU30 5820 lb Cushion Tire Forklift S/N: 62544 C/W: 2 Stage Mast, 147 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Side Shift,		C/W: 2 Stage Mast, Full Free Lift, 180 in Max Lift Height, 81 in Lowered Mast Height, 41 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 10,212 Hr Asset located in: Lake Worth, TX
		6424B	
6420	2011 Toyota 8FGCU25 7500 lb Cushion Tire Forklift S/N: 31741		in Lowered Mast Height, 40 in Forks, Nissan 4 Cylinder Gasoline Engine Usage: 5,084 Hr <b>Asset located in</b> : Lake Worth, TX
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 36 kW 2.23 L LPG Engine Usage: 2,786 Hr Asset located in: Lake Worth, TX	6425	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19416W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine
6421	Toyota 2600 lb Cushion Tire Forklift S/N: 74438 C/W: 3 Stage Mast, 258 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift,		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Toyota 4YECS LPG Engine Usage: 5,098 Hr <b>Asset located in</b> : Lake Worth, TX	6426	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19413W
6422	2021 Mitsubishi FGC25N 5000 lb Cushion Tire Forklift  S/N: AF82F50153  C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Load Weigh System, 2021 US EPA Label, GCT 4 Cylinder LPG Engine, EQUIPMENT-FROM-YELLOW-CORP Usage: 2,245 Hr  Asset located in: Humble, TX		C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6427	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19411W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: . Asset located in: Humble, TX	6433	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19412W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6428	2022 Hyster S50FT 4800 lb Cushion Tire		Asset located in: Humble, TX
	Forklift S/N: H187V19408W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6434	2020 Yale GLC050VX 4750 lb Cushion Tire Forklift  S/N: C910V14422U  C/W: 3 Stage Mast, 189 in Max Lift Height, 58 in Lowered Mast Height, 56 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder LPG Engine Usage: Not Available  Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	6435	2020 Yale GC050VX 4750 lb Cushion Tire
6429	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19417W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available		Forklift S/N: C910V14424U C/W: 3 Stage Mast, 189 in Max Lift Height, 83 in Lowered Mast Height, 58 in Forks, Side Shift, 2020 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6436	2006 Yale GLC050VXNVSE083 4700 lb Cushion Tire Forklift
6430	·	_	S/N: A910V06226D C/W: 3 Stage Mast, 189 in Max Lift Height, 80 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: Not Available
			Asset located in: Lake Worth, TX
		6437	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19418W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4
6431	2022 Hyster S50FT 4800 lb Cushion Tire Forklift		Cylinder 2.4 L LPG Engine Usage: Not Available
	S/N: H187V19409W C/W: 3 Stage Mast, 189 in Max Lift Height, 82		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine	6438	2022 Hyster S50FT 4650 lb Cushion Tire
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	0438	Forklift S/N: H187V19419W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in
6432	2022 Hyster S50FT 4800 lb Cushion Tire Forklift		Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available
	S/N: H187V19415W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: . Asset located in: Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6439	2022 Hyster S50FT 4650 lb Cushion Tire Forklift  S/N: H187V19401W  C/W: 3 Stage Mast, Full Free Lift, 189 in Max  Lift Height, 82 in Lowered Mast Height, 42 in  Forks, Side Shift, 2022 US EPA Label, PSI 4  Cylinder 2.4 L LPG Engine  Usage: Not Available  Notes: .  Asset located in: Humble, TX	6443A	2017 Toyota 8FGCU25 4600 lb Cushion Tire Forklift  S/N: 85179  C/W: 3 Stage Mast, Full Free Lift, 198 in Max  Lift Height, 87 in Lowered Mast Height, 42 in  Forks, Auxiliary Hydraulic Plumbing, Side Shift,  2017 US EPA Label, Toyota 4YECS 4 Cylinder  38 kW 2.23 L LPG Engine  Usage: 1,226 Hr  Asset located in: Lake Worth, TX
6440	2022 Hyster S50FT 4650 lb Cushion Tire	6443B	2017 Toyota 8FGCU25 4500 lb Cushion Tire Forklift
	Forklift S/N: H187V19414W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 84139 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 7,442 Hr Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	6444	2017 Toyota 8FGCU25 4500 lb Cushion Tire
6441	41 2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19400W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, PSI 4 Cylinder 2.4 L LPG Engine		Forklift S/N: 83017 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 5,739 Hr Asset located in: Lake Worth, TX
	Usage: Not Available	6444A	2016 Toyota 8FGCU25 4500 lb Cushion Tire
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Forklift
	Asset located in: Humble, TX		S/N: 80050 C/W: 3 Stage Mast, 189 in Max Lift Height, 76
6442	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19406W C/W: 3 Stage Mast, Full Free Lift, 189 in Max	Fork Positioner, 2016 US EPA L 4YECS 4 Cylinder 38 kW 2.2 L L Usage: 5,987 Hr	in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 5,987 Hr Asset located in: Lake Worth, TX
	Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4	6446B	2015 Toyota 8FGCU25 4500 lb Cushion Tire
	Cylinder 2.4 L LPG Engine Usage: Not Available		Forklift
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 72871 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder
6443	2022 Hyster S50FT 4650 lb Cushion Tire		38 kW 2.3 L LPG Engine Usage: 1,944 Hr
	Forklift S/N: H187V19407W		Asset located in: Lake Worth, TX
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: . Asset located in: Humble, TX	6446C	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 67976 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 6,206 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6446D	2015 Toyota 8FGCU25 4500 lb Cushion Tire Forklift  S/N: 72623  C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 3,747 Hr  Asset located in: Lake Worth, TX	6449	Heli CPYD25C-KU1H 4190 lb Cushion Tire Forklift S/N: 23025N7358 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
6447	2015 Toyota 8FGCU25 4500 lb Cushion Tire	6450	Heli CPYD25C-KU1H Cushion Tire Forklift
	Forklift S/N: 70241 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine	0430	S/N: 230252P8451 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 6,085 Hr <b>Asset located in</b> : Lake Worth, TX	6451	Heli CPYD25C-KU1H 4080 lb Cushion Tire Forklift
6447A	2014 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 62161 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine	6452	S/N: 230252P8453 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 5,663 Hr		Heli CPYD25C-KU1H 4080 lb Cushion Tire Forklift
6448	Asset located in: Lake Worth, TX  2007 Toyota 8FGCU25 4500 lb Cushion Tire Forklift  S/N: 12090  C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in		S/N: 230252P8452 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, 2021 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX
	Forks, Side Shift, Fork Positioner, 2007 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 4,459 Hr Asset located in: Lake Worth, TX	6453	2014 Toyota 8FGCU20 4000 lb Cushion Tire Forklift S/N: 8FGCU25-64619 C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in
6448A	2010 Doosan GC25P-5 4450 lb Cushion Tire Forklift S/N: MW00736		Lowered Mast Height, 36 in Forks, Side Shift, Toyota 4 Cylinder LPG Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift, 2010 US EPA Label, Woodward 4 Cylinder 2.4 L LPG Engine Usage: Not Available Asset located in: Lake Worth, TX	6454	2005 Komatsu FG20ST-14R 4000 lb Cushion Tire Forklift S/N: 587879A C/W: 2 Stage Mast, 72 in Max Lift Height, 55 in Lowered Mast Height, 48 in Forks, Load Weigh
6448B	2015 Doosan GC25E-5 4300 lb Cushion Tire Forklift  S/N: FGA0L179001251  C/W: 3 Stage Mast, Full Free Lift, 76 in Max Lift  Height 190 in Lowered Most Height 40 in		System, 2006 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine, EQUIPMENT-FROM-YELLOW- CORP Usage: 19,433 Hr <b>Asset located in</b> : El Paso, TX
Height, 189 in Lowered Mast Height, 40 in	6454A	2002 Daewoo GC15S-2 2550 lb Cushion Tire Forklift S/N: D100192 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 40 in Forks, Side Shift, 2002 US EPA Label, DAEWOO G420 4 Cylinder LPG Engine Usage: 9,145 Hr	

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6454B	2015 Toyota 8FGCU15 2500 lb Cushion Tire Forklift  S/N: 31743  C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, Toyota 4Y ECS 4 Cylinder 36 kW 2.23 L LPG Engine	6460	2013 Raymond 960-CSR30TT 3000 lb Electric Order Picker S/N: 9601302364 C/W: 2 Stage Mast, 250 in Max Lift Height, 130 in Lowered Mast Height, 24 V Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	6461	2017 Raymond 550-OPC30TT 3000 lb Order
6454C	2017 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 83746 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 94 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota		Picker S/N: 55017A36471 C/W: 2 Stage Mast, Full Free Lift, 240 in Max Lift Height, 106 in Lowered Mast Height, 42 in Forks, 24 V, Battery Watering System Usage: Not Available Asset located in: Lake Worth, TX
	4YECS 4 Cylinder 2.23 L LPG Engine Usage: 6,964 Hr Asset located in: Lake Worth, TX	6462	2024 STL Industrial STL3TN Electric Forklift (Unused)
6454D	Tusk 500CG-16 3975 lb Cushion Tire Forklift S/N: 590948A C/W: 3 Stage Mast, 188 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift,	6463	S/N: 01A06131 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 5 Hr <b>Asset located in</b> : Lake Worth, TX
	2005 US EPA Label, Nissan 4 Cylinder 55 hp 2.1 L LPG Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2017 Raymond 4750C50 4850 lb Electric Forklift S/N: 4751710850
6456	1989 Nissan CPF02A25V Cushion Tire Forklift S/N: CPH02026383 C/W: EQUIPMENT FROM CENTRAL FREIGHT LINES INC Usage: Not Available		C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V, Battery Watering Syste Usage: 5,947 Hr Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6464	2024 JQ POWER JQ2T-MAX 4400 lb Electric
6457	·		Forklift (Unused) S/N: 24482054 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX
	LPG Engine Usage: 9,584 Hr  Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	6465	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482026 C/W: 2 Stage Mast, 118 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: 3 Km
6458	2017 Raymond 550-OPC30TT 3000 lb Order		Asset located in: Lake Worth, TX
	Picker S/N: 55017A36479 C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6466	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482051 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX
6459	2017 Raymond 550-OPC30TT 3000 lb Order Picker S/N: 55017A36483 C/W: Single Stage Mast 240 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6467	2024 JQ POWER JQ2T-MAX 4409 lb Electric Forklift (Unused) S/N: 24482008 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 60 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6468	2024 JQ POWER JQ2T-MAX 2000 kg Electric Forklift (Unused) S/N: 24482052 C/W: 2 Stage Mast, 120 in Max Lift Height, 47 in Forks, Side Shift, 64 V, Battery Charger Usage: Not Available Asset located in: Lake Worth, TX	6479	2016 Jungheinrich ETR340 4000 lb Reach Truck S/N: 82820438 C/W: 2 Stage Mast, 302 in Max Lift Height, 42 in Forks, 36 V, Battery Charger, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 5,007 Hr
6469	2024 STL Industrial STL2TN Electric Forklift (Unused)		Notes: . Asset located in: Lake Worth, TX
	S/N: DM202401A06213 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 29 Hr Asset located in: Lake Worth, TX	6480	Crown RR5700 Order Picker S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6470	2024 STL Industrial STL1TN Electric Forklift (Unused) S/N: 24A0235 C/W: 2 Stage Mast, 84 in Lowered Mast Height, 42 in Forks, Side Shift Usage: Not Available Asset located in: Lake Worth, TX	6481	2012 Moffett P6000 6000 lb 3x3 Truck Mounted Forklift S/N: L270049 C/W: 3 Stage Mast, 124 in Max Lift Height, 78 in Lowered Mast Height, 74 in Forks, Fork Rotation, Tier 4, 2012 US EPA Label, Kubota V2203 4 Cylinder 2.2 L Diesel Engine Usage: 1,732 Hr Asset located in: Humble, TX
6471	2025 STL Industrial Electric Forklift S/N: DM202401A06206 C/W: 2 Stage Mast, 48 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 26 Hr Asset located in: Lake Worth, TX	6482	2013 Navigator RT5500 5500 lb 3x3 Truck Mounted Forklift S/N: 413847 C/W: 2 Stage Mast, 144 in Max Lift Height, 93 in Lowered Mast Height, 48 in Forks, Side Shif Kubota 4 Cylinder 2.0 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
6474	2011 Toyota 7FBCU18 2900 lb Electric Forklift S/N: Not Available Usage: Not Available		
6475	Asset located in: Humble, TX  Cat R80 2800 lb Electric Forklift  S/N: 4SM01049  C/W: 3 Stage Mast, Full Free Lift, 191 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: 69 Hr  Asset located in: Lake Worth, TX	6483	2013 Princeton PB50X 5000 lb 3x3 Truck Mounted Forklift S/N: M480268C C/W: Single Stage Mast 24 in Lowered Mast Height, 47 in Forks, Tier 4, 2012 US EPA Label, Kubota v2203 4 Cylinder 35 kW 2.2 L Diesel Engine Usage: 2,060 Hr Asset located in: Lake Worth, TX
6476	Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused) S/N: Not Available C/W: One crate Usage: Not Available Asset located in: Lake Worth, TX	6484	2013 Moffett M50 Lite 5000 lb 3x3 Truck Mounted Forklift S/N: M220415A C/W: Single Stage Mast 12 in Max Lift Height, 1 in Lowered Mast Height, 48 in Forks, Side Shift, Kubota 4 Cylinder 1.5 L Diesel Engine Usage: 3,850 Hr
6477	<b>Eingp PHT620 620 lb Walk Behind Electric Forklift (Unused)</b> S/N: PHT6206139	6485	Asset located in: Lake Worth, TX  2021 Combilift COMBI-RT 3000 lb 3x3 Rough
6478	C/W: 610 lb Capacity, 24 V, One Crate Usage: Not Available Asset located in: Lake Worth, TX  2012 Raymond 960-CSR30TT 3000 lb Electric Reach Truck S/N: 9601202198 C/W: 2 Stage Mast, 250 in Max Lift Height, 130		Terrain Forklift S/N: 55866 C/W: 2 Stage Mast, 124 in Max Lift Height, 24 in Lowered Mast Height, 72 in Forks, Side Shift, 2020 US EPA Label, Deutz TD2.9L4 4 Cylinder 55 kW 2.9 L Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX
	in Lowered Mast Height, 24 V Usage: Not Available  Asset located in: Lake Worth, TX		Asset located III. Lake Worth, 1X

Lot #	Details	Lot #	Details
6486	2013 Genie S125 4WD Diesel Telescopic Boom Lift  S/N: S12513D505  C/W: 125 ft Max Platform Height, 500 lb Max  Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz td2011 4 Cylinder 74 hp 3.6 L Diesel Engine, 445  /50D710 Tires  Usage: 3,738 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6491	2011 Genie S85 4WD Diesel Telescopic Boom Lift  S/N: S85118854  C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2011 US EPA Label, Deutz 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 2,485 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX
<u> </u>	Asset located in: Lake Worth, TX	6492	2010 Genie S85 4WD Diesel Telescopic Boom
6487	2012 Genie S-125 4WD Diesel Telescopic Boom Lift  S/N: S125123373  C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, Deutz TD2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 4,191 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Lift S/N: S85108432 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, 2010 US EPA Label, Deutz TD 2011L04I 4 Cylinder 3.61 L Diesel Engine, 18-625NHS Tires Usage: 5,544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6493	2018 Haulotte HT85RT 4WD Diesel Telescopic
6488	2002 Genie S-125 Telescopic Boom Lift S/N: S125525 C/W: 125 m Max Lift Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine, 445/65D22.5 Tires Usage: 5,200 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX		Boom Lift S/N: 2030133 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 4 Cylinder Diesel Engine Usage: 1,938 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6489	2018 Genie S-85 XC 4WD Diesel Telescopic	6494	2017 Haulotte HT85RTJ PRO 4WD Diesel
	Boom Lift S/N: S85XCH-262 C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Tires Usage: 3,157 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Telescopic Boom Lift S/N: 2021508 C/W: 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2016 US EPA Label, Kubota V2607 4 Cylinder 2.6 L Diesel Engine Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6495	2015 Snorkel TB85J 4WD Diesel Telescopic
6490	2018 Genie S85XC 4WD Diesel Telescopic Boom Lift  S/N: S85XCH260  C/W: 85 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2017 US EPA Label, Deutz TD 2.9 LP 4 Cylinder 2.95 L Diesel Engine, 18-625NHS Tires Usage: 4,567 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Boom Lift  S/N: TB85J-04-000049  C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Kubota V2403 4 Cylinder 44 kW 2.4 L Diesel Engine, 15-625 Tires Usage: 4,173 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6496	2014 Genie S-80X Telescopic Boom Lift S/N: S80X14-12022 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4,561 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6501	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift  S/N: 0300236292  C/W: 65 ft Max Platform Height, 750 lb Max  Weight Capacity, Jib, Power to Platform,  Onboard Generator, 2017 US EPA Label, Deutz  TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine,  355/55D625 Foam-Filled Tires, EQUIPMENT-  FROM-SUNSTATE-EQUIPMENT
6497	2014 Genie S-80X 4WD Diesel Telescopic Boom Lift S/N: S80X1412022 C/W: 80 ft Max Platform Height, 500 lb Max		Usage: 4,928 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,562 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6502	2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300233965 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-
6498	2012 JLG 800S 4WD Diesel Telescopic Boom Lift S/N: 0300158033 C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2011 US		EQUIPMENT Usage: 5,192 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD <b>Asset located in</b> : Lake Worth, TX
	EPA Label, Deutz D2011L04 4 Cylinder 3.6 L Diesel Engine Usage: 2,352 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	Boom Lift  S/N: S6016H-35454  C/W: 65 ft Max Platform Height, 500  Weight Capacity, Jib, Power to Platfo US EPA Label, CARB Compliant, 4 Cy kW 2.5 L Dual Fuel Engine, 355/55D6  Tires Usage: 3,590 Hr  Notes: AERIAL UNITS REQUIRE PRO	S/N: S6016H-35454 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, CARB Compliant, 4 Cylinder 64.3
6499	Haulotte HT67RTJ Telescopic Boom Lift S/N: TD500215 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Tires Usage: 3,590 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6500	Asset located in: Lake Worth, TX  2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift  S/N: 0300236291  C/W: 65 ft Max Platform Height, 750 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp	_6504	2012 Genie S-65 Telescopic Boom Lift S/N: S6012-23502 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 748 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6505	2017 Genie S60X 4WD Diesel Telescopic Boom Lift  S/N: S60XH-37752  C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, CARB Compliant, Deutz D2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355 /55D625 NHS Tires Usage: 2,105 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6506	2015 Genie S60X 4WD Diesel Telescopic Boom Lift	6510	2006 Genie S60 4WD Diesel Telescopic Boom Lift
	S/N: S60X15A-29654 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D 2.9 L4 49 hp 2.92 L Diesel Engine, 355/55D625 Tires, EQUIPMENT-FROM-		S/N: S600614228 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Diesel Engine, 355/55D625 Tires Usage: 973 Hr
	SUNSTATE-EQUIPMENT Usage: 4,781 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Humble, TX
	FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6510A	2017 JLG 460SJ 4WD Diesel Telescopic Boom
6507	2017 JLG 600S 4WD Diesel Telescopic Boom Lift  S/N: 300236812  C/W: 59 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 355/55D625 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 5,026 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Lift S/N: 0300236779 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, Deutz D 2.9 L4 36.4 kW 2.9 L Diesel Engine, 1417.5 NHS Tires Usage: 3,690 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6511	2019 Skyjack SJ45T 4WD Diesel Telescopic
6508	Lift  S/N: 300229396  C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 5,530 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		Boom Lift S/N: 98003735 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Deutz Diesel Engine Usage: 2,136 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Fort Smith, AR
6500	· · · · · · · · · · · · · · · · · · ·	6513	2007 Snorkel TB42DZ 4WD Diesel Telescopic
6509	2017 JLG 600S 4WD Diesel Telescopic Boom Lift  S/N: 0300233241  C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4  4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15-22.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 6,286 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		Boom Lift S/N: MR07088RBLT C/W: 42 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2008 US EPA Label, Deutz F3L2011 3 Cylinder 48 hp 2.33 L Diesel Engine, 12.16.5N Tires Usage: 3,176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

			C
Lot #	Details	Lot #	Details
6514	2015 Genie S40 4WD Diesel Telescopic Boom Lift	6518	2015 JLG 400S 4WD Diesel Telescopic Boom Lift
	S/N: S4015-20737 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12-16.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,771 Hr		S/N: 0300209072 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz d2.914 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,731 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
6515	2017 JLG 400S 4WD Diesel Telescopic Boom Lift  S/N: 0300236550 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6519	2015 JLG 400S 4WD Telescopic Boom Lift S/N: 0300204969 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Deutz 4 Cylinder Diesel Engine, 12- 16.5 Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,775 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6520	•
6516	2016 JLG 400S 4WD Diesel Telescopic Boom Lift  S/N: 0300211074  C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,626 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	-6520	2015 JLG 400S 2WD Diesel Telescopic Boom Lift  S/N: 0300210976  C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, 2015 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 14-17.5  NHS Foam-Filled Tires, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 4,245 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6521	2015 JLG 400S 4WD Diesel Telescopic Boom
6517	2016 JLG 400S 4WD Diesel Telescopic Boom Lift  S/N: 0300210880 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 4,719 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		Lift S/N: 0300208881 C/W: 40 ft Max Platform Height, 600 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 4,536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6522	2014 JLG 400S 4WD Diesel Telescopic Boom Lift  S/N: 0300191770  C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz d2.9l4 4  Cylinder 49 hp 2.9 L Diesel Engine, Foam-Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,228 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6526	2018 JLG 600AJ 4WD Diesel Articulating Boom Lift  S/N: 0300239502  C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017  US EPA Label, Deutz 2.9l4 4 Cylinder 67 hp 2.9  L Diesel Engine Usage: 1,081 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX  2011 JLG 600AJ 4WD Diesel Articulating
6523	Asset located in: Lake Worth, TX  2014 JLG 400S 4WD Diesel Telescopic Boom Lift  S/N: 0300192112  C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 14-17.5 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 3,661 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6527	Boom Lift S/N: 0300143499 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2010 US EPA Label, Deutz D2011L4 4 Cylinder 3.1 L Diesel Engine, 355/55D625 Tires Usage: 4,083 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6528	2015 Snorkel AB60J Articulating Boom Lift S/N: AB60J-04-000082
6524	2016 Haulotte HA130RTJPRO 4WD Diesel Articulating Boom Lift S/N: AD127595 C/W: 129 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform,		Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6525	Perkins Engine Usage: 3,370 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6529	2014 Genie Z-60/34 4WD Diesel Articulating Boom Lift S/N: Z601414246 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Deutz D2011L03I 4 Cylinder 49 hp Diesel Engine, 355/55D625 Foam-Filled Tires,
0525	2015 JLG 660SJ 4WD Diesel Telescopic Boom Lift S/N: 0300198551 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine,		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,716 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
	39x15-22.5 Tires Usage: 3,975 Hr  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Humble, TX	6530	2014 Genie Z60/34 Articulating Boom Lift S/N: Z6014-14246 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,714 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6531	2015 Snorkel A46JRT 4WD Diesel Articulating Boom Lift  S/N: A46JRT-04-000348  C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505 4 Cylinder 18.5 kW 1.5 L Diesel Engine, 355/55D62.5 Tires Usage: 1,226 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6537	2014 Genie Z45/25 2WD Electric Articulating Boom Lift  S/N: Z452514A52188  C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam- Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 1,167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6532	Skyjack SJ46AJ 4WD Diesel Articulating Boom	6538	2012 Genie Z40/23NRJ 2WD Electric
	Lift S/N: 95000588 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine Usage: 2,493 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Articulating Boom Lift S/N: Z40N12-1774 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 25.6 X7 Non-Marking Tires Usage: 1,120 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6534	2012 JLG 450AJ 4WD Articulating Boom Lift	6539	2012 Genie Z40/23NRJ 2WD Electric
	S/N: 0300161279 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011 3 Cylinder 49 hp 2.3 L Diesel Engine, 33X15.50 Tires Usage: 3,162 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Articulating Boom Lift S/N: Z40N12-1683 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22X7X17 Non-Marking Tires Usage: 1,393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6535	2015 Genie Z-45/25J 2WD Electric Articulating Boom Lift S/N: Z452515A54948 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Foam- Filled Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT	6540	2012 Genie Z40/23NRJ Articulating Boom Lift S/N: Z40N12-1786 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Usage: 1,406 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6541	2012 Genie Z40/23NRJ Articulating Boom Lift S/N: Z40N12-1775 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
6536	2015 Genie Z45/25J 4WD Diesel Articulating Boom Lift S/N: Z452515A-53530		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
	C/W: 24 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2017 US EPA Label, Deutz U2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 315/55D20 Tires, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,249 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6542	2012 Genie Z40/23NRJ Articulating Boom Lift S/N: Z40N12001797 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6543	2017 Genie Z-33/18 2WD Electric Articulating Boom Lift  S/N: Z3318M1589  C/W: 32 ft Max Platform Height, 440 lb Max Weight Capacity, Power to Platform, 22X9 Solid Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 619 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6550	Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift S/N: 40002479 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,620 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6544	2015 JLG E300 AJP 2WD Electric Articulating	6551	2017 Skyjack SJ8841 RT 4x4 Dual Fuel Scissor
	Boom Lift S/N: 0300203331 C/W: 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 823 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Lift S/N: 40002473 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Foam Filled Tires, Upper Control Box, 2017 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 3,292 Hr
6545	2018 JLG T500J Electric Towable Lift S/N: 0030009466		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform		Asset located in: Lake Worth, TX
	Usage: 37 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6552	Lift S/N: 40001765 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2015 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 2,788 Hr
6546	2018 JLG T500J Electric Towable Lift S/N: 5DYACJ1J3JF009464 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 50 Hr		
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6547	2018 JLG T500J Electric Towable Lift S/N: 5DYACJ1J5JF009465 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 55 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6553	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift  S/N: 40001309  C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, Kubota WG972 3 Cylinder Dual Fuel Engine Usage: 2,649 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6548	2014 JLG T500J Towable Lift S/N: 0030008920 C/W: 50 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform Usage: 182 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6553A 6554	2013 JLG M4069 4x4 Diesel Scissor Lift S/N: 0200217745 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2012 US EPA Label, Kubota 1 Cylinder 0.2 L Diesel Engine Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX 2007 JLG 3394RT Scissor Lift	6560	2015 Genie GS-2669RT 4x4 LPG Scissor Lift S/N: GS6915-7055 C/W: 26 m Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder LPG Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,044 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	S/N: 200164159 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6561	2017 Skyjack SJ6826 RT Scissor Lift S/N: 37010550 Usage: 1,397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6555	2017 Genie GS3390RT 4x4 Dual Fuel Scissor Lift	6562	Asset located in: Lake Worth, TX  2017 Skyjack SJ6826 RT Dual Fuel Scissor Lift
	S/N: GS90F-54078 C/W: 2500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, 2017 US EPA Label, 4 Cylinder 64.3 kW 2.5 L LPG Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 3,011 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Oklahoma City, OK		S/N: 37010717 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Foam Filled Tires, Upper Control Box, Kubota WG752-GL - ET 3 Cylinder 740.5 cc Dual Fuel Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,991 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX
6556	2015 Genie GS-3369RT Scissor Lift	6562A	2000 Skyjack SJ8841RT Scissor Lift
	S/N: GS6915-7051 Usage: 1,360 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; <b>Asset located in</b> : Lake Worth, TX		S/N: 42378 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6557	<b>2015 Genie GS-3369RT Scissor Lift</b> S/N: GS6915-7099	6563	2014 JLG M4069LE Scissor Lift
6558	Usage: 1,738 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX  2017 Skyjack SJ6832RT 4x4 Dual Fuel Scissor Lift	-	S/N: 0200238747 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 552 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	S/N: 37010203 C/W: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, 2016 US EPA Label, Kubota WG752-GL-ET 3 Cylinder 740 cc Dual Fuel Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 2,144 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6564	2013 JLG M4069LE 4x4 Diesel Scissor Lift S/N: 0200217747 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Power Inverter, Solid Non-Marking Tires, Upper Control Box, Tier 4, 2012 US EPA Label, Kubota 0C60-ET01 1 Cylinder 0.27 L Diesel Engine Usage: 276 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Midland, TX

oilo
ails
7 Genie GS-4047 Electric Scissor Lift I: GS47P-1802 V: 40 ft Max Platform Height, 550 lb Max ight Capacity, Platform Extension, Power to tform, Solid Non-Marking Tires, Upper ntrol Box, EQUIPMENT-FROM-SUNSTATE-JIPMENT ige: 504 Hr Les: AERIAL UNITS REQUIRE PROPER TETY HARNESS, LANYARD, AND PPE TO NCTION TEST AND LOAD;
set located in: Lake Worth, TX
7 Genie GS-4047 Electric Scissor Lift l: GS47P1430 V: 40 ft Max Platform Height, 550 lb Max ight Capacity, Platform Extension, Power to efform, Solid Non-Marking Tires, Upper introl Box, EQUIPMENT-FROM-SUNSTATE-JIPMENT ige: 509 Hr
es: AERIAL UNITS REQUIRE PROPER ETY HARNESS, LANYARD, AND PPE TO
NCTION TEST AND LOAD
set located in: Lake Worth, TX
7 Genie GS-4047 Electric Scissor Lift I: GS47P-1824 V: 550 lb Max Weight Capacity, Platform ension, Power to Platform, Solid Non-rking Tires, Upper Control Box, EQUIPMENT-
ge: 594 Hr  ges: AERIAL UNITS REQUIRE PROPER FETY HARNESS, LANYARD, AND PPE TO NCTION TEST AND LOAD  get located in: Lake Worth, TX
7 Genie GS-4047 Electric Scissor Lift I: GS47P1822 V: 40 ft Max Platform Height, 550 lb Max ight Capacity, Platform Extension, Power to the form, Solid Non-Marking Tires, Upper introl Box, EQUIPMENT-FROM-SUNSTATE-JIPMENT
res: AERIAL UNITS REQUIRE PROPER FETY HARNESS, LANYARD, AND PPE TO NCTION TEST AND LOAD; Set located in: Lake Worth, TX  7 Genie GS-4047 Scissor Lift I: GS47P-1822 V: EQUIPMENT-FROM-SUNSTATE- JIPMENT Inge: 628 Hr Ses: AERIAL UNITS REQUIRE PROPER FETY HARNESS, LANYARD, AND PPE TO
1 N L a

Lot #	Details	Lot #		
6575	2017 Genie GS-4047 Electric Scissor Lift	6580	2016 Genie GS-4047 Electric Scissor Lift	
03/3	S/N: GS47P-1678 C/W: 39 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 615 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	0380	S/N: GS4716D-3104 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 500 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
6576	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47D6070 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6581	2016 Genie GS-4047 Scissor Lift S/N: GS4716D-1513 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 589 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
	FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6582	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1580	
6577	2017 Genie GS-4047 Electric Scissor Lift S/N: GS47P2225 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;			C/W: 40 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 590 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX  2016 Genie GS-4047 Electric Scissor Lift
	Asset located in: Lake Worth, TX		S/N: GS4716D-2977	
6578	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D-1545 C/W: 20 ft Max Platform Height, 550 lb Max Weight Capacity, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 498 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Extension, Power to Platform, Sólid Marking Tires, Upper Control Box, EG FROM-SUNSTATE-EQUIPMENT Usage: 627 Hr Notes: AERIAL UNITS REQUIRE PRO	Usage: 627 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	6584	2016 Genie GS-4047 Electric Scissor Lift	
6579	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1620 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 499 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS4716D-1511 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 633 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6584A	2016 Genie GS-4047 Electric Scissor Lift S/N: GS4716D1543 C/W: 39 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6589	Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202542 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 515 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6585	2015 Genie GS-4047 Electric Scissor Lift	6590	·
0383	S/N: GS4715D-1286 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	0390	2017 Skyjack SJIII4740 Electric Scissor Lift S/N: 70201795 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Stabilizers, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	ļ	Asset located in: Lake Worth, TX
6586	2015 Genie GS-4047 Electric Scissor Lift S/N: GS4715D-1278 C/W: 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 534 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6591	Skyjack SJIII-4740 Electric Scissor Lift S/N: Not Available C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 349 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6587	2015 Genie GS-4047 Electric Scissor Lift	6592	2017 MEC 4046SE Electric Scissor Lift
6588	S/N: GS4715D-1054 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 788 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK Skyjack SJIII-4740 Electric Scissor Lift S/N: 70202991	6592	S/N: 16700245 C/W: 38 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	C/W: 40 ft Max Platform Height, 500 lb Max	6502	
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6593	2017 MEC 4046SE Electric Scissor Lift S/N: 16700250 C/W: 38 ft 7 in Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 536 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6594	2015 JLG 3248RS Electric Scissor Lift S/N: 0200237506 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 480 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6600	2017 Genie GS-3246 Electric Scissor Lift S/N: GS46P-143947 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 290 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6601	2017 Genie GS-3246 Electric Scissor Lift
6595	2015 JLG 3248RS Electric Scissor Lift S/N: 0200243786 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 538 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: GS46P143978 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 335 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6602	2017 Genie GS-3246 Scissor Lift
6597	2017 Snorkel S4732E Electric Scissor Lift S/N: S4732E-04-900112 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT FROM UNITED RENTALS Usage: 180 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: GS46P-143966 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 337 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6603	2017 Genie GS-3246 Electric Scissor Lift
6598	Asset located in: Lake Worth, TX  2017 Genie GS-3246 Electric Scissor Lift  S/N: GS46P-143973  C/W: 32 ft Max Platform Height, 700 lb Max  Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 4 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		C/W: 32 ft Max Platform Height, 70 Weight Capacity, Platform Extensic Platform, Solid Non-Marking Tires, Control Box, EQUIPMENT-FROM-SU EQUIPMENT Usage: 337 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PR
	Asset located in: Lake Worth, TX	6604	2017 Genie GS3246 Electric Scissor Lift
6599	2017 Genie GS-3246 Electric Scissor Lift S/N: 143969 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 114 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS46P143806 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 297 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
	S/N: GS46P143724 C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD AERIAL UNITS	6609	2017 JLG 3246ES Scissor Lift  S/N: 0200266190  C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT  Usage: 189 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	
	REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	TE-ROPER	<b>2017 JLG 3246ES Electric Scissor Lift</b> S/N: 0200263931	
6605	Asset located in: Lake Worth, TX  2015 Genie GS-3246 Scissor Lift  S/N: GS4615-137265  C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT  Usage: 362 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		C/W: 31 ft Max Platform Height, 750 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 206 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	
6606	Asset located in: Lake Worth, TX  2015 Genie GS-3246 Electric Scissor Lift S/N: GS4615A137584 C/W: 33 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 484 Hr	6612	2017 JLG 3246ES Scissor Lift  S/N: 0200266023  C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT  Usage: 328 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		2017 JLG 3246ES Electric Scissor Lift S/N: M200013247 C/W: 31.75 ft Max Platform Height, 700 lb Max	
6607	2017 JLG 3246ES Electric Scissor Lift S/N: 0200263928 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 59 Hr Notes: AERIAL UNITS REQUIRE PROPER		Platform, Solid Non-Marking Tires, Up Control Box, EQUIPMENT-FROM-SUNS EQUIPMENT Usage: 401 Hr Notes: AERIAL UNITS REQUIRE PROP	Usage: 401 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX		<b>2017 JLG 3246ES Electric Scissor Lift</b> S/N: 0200266207 C/W: 31.75 ft Max Platform Height, 700 lb Max	
6608	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266401 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 81 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 402 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6614	2017 JLG 3246ES Electric Scissor Lift S/N: M200013176 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6619	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266209 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6615	2017 JLG 3246ES Electric Scissor Lift	6620	2017 JLG 3246ES Electric Scissor Lift
	S/N: 0200266205 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 405 Hr		S/N: M200013245 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6616	2015 JLG 3246ES Electric Scissor Lift S/N: M200001109 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 413 Hr	6621	2016 JLG 3246ES Electric Scissor Lift S/N: M200000621 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 492 Hr
	<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	ļ	Asset located in: Lake Worth, TX
6617	2017 JLG 3246ES Electric Scissor Lift S/N: M200013175 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 425 Hr	6622	2017 Skyjack SJIII-4632 Electric Scissor Lift S/N: 80180032 C/W: 32 ft Max Platform Height, 750 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
	<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6618	2017 JLG 3246ES Electric Scissor Lift S/N: M200013211 C/W: 31 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6623	2019 Skyjack SJIII4632 Electric Scissor Lift S/N: 70041193 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 189 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6624	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70017904 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 289 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6630	2014 Skyjack SJIII4632 Electric Scissor Lift S/N: 70017856 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Upper Control Box Usage: 339 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6625	2015 Skyjack SJIII 4632 Electric Scissor Lift	6631	Skyjack SJIII 4632 Electric Scissor Lift
0023	S/N: 70022067 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 314 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		S/N: Not Available C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 325 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	-	Asset located in: Lake Worth, TX
6626	2015 Skyjack SJIII 4632 Scissor Lift S/N: 70022705 Usage: 419 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX  2014 Skyjack SJIII 4632 Electric Scissor Lift	6632	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018708 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension Usage: 358 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	S/N: 70019200 C/W: 32 ft Max Platform Height, 700 lb Max	6600	Asset located in: Lake Worth, TX
	Weight Capacity, Platform Extension Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6633	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70018805 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 358 Hr
6628	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70019482 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
	Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available <b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD <b>Asset located in</b> : Lake Worth, TX		2018 Genie GS3232 Electric Scissor Lift S/N: GS32P-157610 C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
6629	2014 Skyjack SJIII 4632 Electric Scissor Lift S/N: 70019116		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6635	Asset located in: Lake Worth, TX  2017 Genie GS3232 Electric Scissor Lift S/N: GS32P-154160 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
6636	2017 Genie GS-3232 Electric Scissor Lift	6642	2014 Genie GS-3232 Electric Scissor Lift
0030	S/N: GS32P-148830 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 509 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0042	S/N: 135791 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6637	2017 Genie GS-3232 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS32P148756 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6643	2018 Snorkel S4726E Electric Scissor Lift S/N: S4726E-04-180500837 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 109 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6644	2017 JLG 2646ES Electric Scissor Lift
6640	2017 Genie GS3232 Electric Scissor Lift S/N: GS32P-149344 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX  2015 Genie GS3232 Electric Scissor Lift		S/N: M200007467 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 291 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	S/N: GS3215A141191	6645	2015 JLG 2646ES Electric Scissor Lift
	C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 465 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6645	S/N: M200001100 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 477 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6641	2015 Genie GS-3232 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 141232 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 398 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6646	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70026601 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6647	2015 Skyjack SJIII-4626 Electric Scissor Lift S/N: 70022572 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 200 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6652	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263898 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 328 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6648	2015 Skyjack SJIII4626 Electric Scissor Lift S/N: 70022293 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 240 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6653	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263463 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 375 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6649	2015 Skyjack SJIII4626 Electric Scissor Lift		Asset located in: Lake Worth, TX
6650	S/N: 70022355 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 260 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX  2015 Skyjack SJIII4626 Electric Scissor Lift	6654	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263458 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
0000	S/N: 70021519		Asset located in: Lake Worth, TX
	C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 282 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6655	2016 JLG 2646ES Electric Scissor Lift S/N: M200001128 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 227 Hr
6651	2014 Skyjack SJIII4626 Electric Scissor Lift S/N: 70021343		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Upper		Asset located in: Lake Worth, TX
	Control Box Usage: 410 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6656	2015 JLG 2646ES Electric Scissor Lift S/N: M200001101 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6657	2015 JLG 2646ES Electric Scissor Lift S/N: M200000271 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6662	2016 Genie GS-2632 Electric Scissor Lift S/N: GS3216P-145511 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 489 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6658	2015 Genie GS2646 Electric Scissor Lift	6663	2016 Genie GS-2632 Electric Scissor Lift
	S/N: 137357 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 246 Hr		S/N: GS3216P145971 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 540 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
6659	2015 Genie GS2646 Electric Scissor Lift S/N: GS4615A136705 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6664	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140574 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 28 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
	Asset located in: Lake Worth, TX	6665	2015 Genie GS-2632 Electric Scissor Lift
6660	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137346 C/W: 25 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3215A-140508 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 245 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
		6666	2015 Genie GS-2632 Scissor Lift
6661	2015 Genie GS-2646 Electric Scissor Lift S/N: GS4615A137130 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3215A-139249 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 312 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6667	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A140092 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 333 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6672	2015 Genie GS-2632 Scissor Lift S/N: GS3215A-139149 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 497 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX  2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A138162	
6668	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-138165 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 343 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		C/W: 26 ft Max Platform Height, 700 l Weight Capacity, Platform Extension, Platform, Solid Non-Marking Tires, Up Control Box, EQUIPMENT-FROM-SUN EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROP	Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6674	<b>2015 Genie GS-2632 Electric Scissor Lift</b> S/N: GS3215A137939	
6669	2015 Genie GS-2632 Electric Scissor Lift S/N: GS3215A-140139 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 404 Hr Notes: AERIAL UNITS REQUIRE PROPER		C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	
SAFETY HARNESS, LANYARD, AND PPE FUNCTION TEST AND LOAD		6675	2015 Genie GS-2632 Electric Scissor Lift	
6670	Asset located in: Lake Worth, TX  2015 Genie GS-2632 Electric Scissor Lift  S/N: GS3215A138159  C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 424 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		S/N: GS3215A140581 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 380 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	6676	2015 Genie GS2632 Electric Scissor Lift	
6671	2015 Genie GS-2632 Scissor Lift S/N: GS3215A-139266 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 435 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: GS3215A-139158 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Genie GS-2632 Electric Scissor Lift GS3215A-140565 26 ft Max Platform Height, 500 lb Max	6681	0040 0
ort Capacity, Platform Extension, Power to born, Solid Non-Marking Tires, Upper ol Box, EQUIPMENT-FROM-SUNSTATE-PMENT E: Not Available E: AERIAL UNITS REQUIRE PROPER TY HARNESS, LANYARD, AND PPE TO TION TEST AND LOAD;  located in: Lake Worth, TX		2013 Genie GS-2632 Electric Scissor Lift S/N: GS3213A116224 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
Genie GS-2632 Electric Scissor Lift	6682	2016 JLG 2632ES Electric Scissor Lift
GS3215A139156 26 ft Max Platform Height, 500 lb Max nt Capacity, Platform Extension, Power to orm, Solid Non-Marking Tires, Upper ol Box e: 525 Hr s: AERIAL UNITS REQUIRE PROPER	6683	S/N: 200252535 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 339 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PROPER
TY HARNESS, LANYARD, AND PPE TO TION TEST AND LOAD <b>located in</b> : Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
Genie GS-2632 Scissor Lift		Asset located in: Lake Worth, TX
GS3214A-136132 EQUIPMENT-FROM-SUNSTATE- PMENT e: 383 Hr s: AERIAL UNITS REQUIRE PROPER TY HARNESS, LANYARD, AND PPE TO TION TEST AND LOAD; located in: Lake Worth, TX		2016 JLG 2632ES Electric Scissor Lift S/N: 0200252837 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER
Genie GS-2632 Electric Scissor Lift GS3214A136069		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
26 ft Max Platform Height, 500 lb Max nt Capacity, Platform Extension, Power to		Asset located in: Lake Worth, TX
orm, Solid Non-Marking Tires, Upper ol Box, EQUIPMENT-FROM-SUNSTATE-PMENT :: 396 Hr :: AERIAL UNITS REQUIRE PROPER TY HARNESS, LANYARD, AND PPE TO TION TEST AND LOAD   located in: Lake Worth, TX	6684	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252763 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr
Genie GS-2632 Electric Scissor Lift		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
GS3214A-118609 26 ft Max Platform Height, 26 lb Max		FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
nt Capacity, Platform Extension, Power to orm, Solid Non-Marking Tires, Upper	6685	2016 JLG 2632ES Electric Scissor Lift
Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		S/N: 0200252494 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
ol I PM e: N e: A TY TIO	Box, EQUIPMENT-FŘOM-SUNSTATE- ENT Not Available JERIAL UNITS REQUIRE PROPER HARNESS, LANYARD, AND PPE TO ON TEST AND LOAD;	Box, EQUIPMENT-FŘOM-SUNSTATE- ENT Not Available JERIAL UNITS REQUIRE PROPER HARNESS, LANYARD, AND PPE TO DN TEST AND LOAD ;

Lot #	Details	Lot #	Details
6686	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252789 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6690	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244222 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6687	2016 JLG 2632ES Electric Scissor Lift S/N: M200002023 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 435 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6691	2015 JLG 2632ES Electric Scissor Lift S/N: 0200246996 C/W: 25 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 444 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6688	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252492 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 482 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6692	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244228 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 470 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6688A	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252564 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6693	2015 JLG 2632ES Electric Scissor Lift S/N: 0200243900 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6689	2015 JLG 2632ES Electric Scissor Lift S/N: M200000541 C/W: 25.5 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6694	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244546 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 471 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

1 64 "	Detaile	1.4."	Details
Lot #	Details	Lot #	Details
6695	2015 JLG 2632ES Electric Scissor Lift S/N: 0200244248 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 421 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6700	2014 Skyjack SJIII-3226 Electric Scissor Lift S/N: 27017585 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 251 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
6696	2015 JLG 2632ES Electric Scissor Lift	6701	2016 JLG 2630ES Electric Scissor Lift
	S/N: 0200247096 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: 0200252795 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 388 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
6697	2015 JLG 2632ES Electric Scissor Lift  S/N: 0200251446  C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 370 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6702	2011 JLG 2630ES Electric Scissor Lift S/N: 0200200580 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 369 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	4=00	Asset located in: Lake Worth, TX
6698	2015 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27023528 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6703	2017 Snorkel S3220E Electric Scissor Lift S/N: S3220E-04-900021 C/W: 20 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6699	2014 Skyjack SJIII 3226 Electric Scissor Lift	6704	<b>2013 Genie GS2032 Electric Scissor Lift</b> S/N: GS3213A113424
	S/N: 27020188 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 299 Hr		C/W: 20 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: 144 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TY		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TY
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

		I	
Lot #	Details	Lot #	Details
6705	Hangcha 81XE-II Electric Scissor Lift S/N: Not Available C/W: 400 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6713	2019 JLG 1932R Electric Scissor Lift  S/N: M200029543  C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 83 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX
6709	2018 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22135992 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 284 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6714	2015 JLG 1932RS Scissor Lift S/N: 0200243362 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 332 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6710	Skyjack SJIII-3219 Electric Scissor Lift S/N: 1000025 C/W: 19 m Max Platform Height, 600 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 161 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6715	2015 JLG 1932RS Electric Scissor Lift S/N: 0200244480 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 383 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6711	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22063947 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 218 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	<b>-6716</b>	2015 JLG 1932RS Electric Scissor Lift S/N: 0200243353 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK
6712	Asset located in: Lake Worth, TX  2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22060591 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 258 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6717	2015 JLG 1932RS Electric Scissor Lift S/N: 0200251219 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6718	2015 JLG 1932RS Electric Scissor Lift	6723	2014 JLG 1932RS Electric Scissor Lift
0/16	S/N: 0200247820 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 409 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	0/23	S/N: 200235081 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 158 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6719	2015 JLG 1932RS Electric Scissor Lift S/N: 0200244479 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6724	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236585 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 373 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6720		6725	2014 JLG 1932RS Electric Scissor Lift
		-	S/N: 0200234422 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PROPER
6721	<b>2015 JLG 1932RS Scissor Lift</b> S/N: 0200244472		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 505 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6725A 2014 JLG 1932RS Electric S/N: 0200236594 C/W: 19 ft Max Platform H Weight Capacity, Platform Platform, Solid Non-Markir Control Box, EQUIPMENT-I EQUIPMENT Usage: 623 Hr	C/W: 19 ft Max Platform Height, 500 lb Max
	FUNCTION TEST AND LOAD;		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper
6722	Asset located in: Lake Worth, TX  2015 JLG 1932RS Electric Scissor Lift S/N: 0200243354 C/W: 19 ft Max Platform Height, 500 lb Max		Control Box, EQUIPMENT-FŘOM-SUNSTATE- EQUIPMENT
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6726	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234817 C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 423 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6727	2014 JLG 1932RS Scissor Lift S/N: 0200236066 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 460 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6733	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235121 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6728	2014 JLG 1932RS Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 0200236060 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 488 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6734	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234070 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr
6729	2014 JLG 1932RS Scissor Lift S/N: 0200236064 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Usage: 490 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		2014 JLG 1932RS Electric Scissor Lift S/N: 200234879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper
6730	2014 JLG 1932RS Scissor Lift S/N: 0200235088 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 510 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 594 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX  2014 JLG 1932RS Electric Scissor Lift
6731	Asset located in: Lake Worth, TX  JLG 1932RS Electric Scissor Lift  S/N: 0200234825  C/W: 19 ft Max Platform Height, 500 lb Max  Weight Capacity, Platform Extension, Power to  Platform, Solid Non-Marking Tires, Upper  Control Box, EQUIPMENT-FROM-SUNSTATE-  EQUIPMENT  Usage: 520 Hr  Notes: AERIAL UNITS REQUIRE PROPER  SAFETY HARNESS, LANYARD, AND PPE TO  FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		S/N: 0200236058 C/W: 19 m Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX  2016 Snorkel S3219E Electric Scissor Lift
6732	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235386 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: S3219E-04-001508 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 1,362 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	
6738	2018 Snorkel S3129E Electric Scissor Lift S/N: S3219E-04-181006644 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6743	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6739	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168879 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	6744	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P-167041 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 438 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6740	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166134 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 65 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6745	Asset located in: Lake Worth, TX  2016 Genie GS-1930 Electric Scissor Lift  S/N: GS3016A-150796  C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 64 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
6741	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P166091 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6746	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156688 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 312 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6742	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P168863 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 338 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6747	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-151099 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 381 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

	B	1, . "	B : 1		
Lot #	Details	Lot #	Details		
6748	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-159299 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 396 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6753	S C W P C E U <b>N</b>	0733	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156662 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
6749	<b>2016 Genie GS-1930 Electric Scissor Lift</b> S/N: GS3016P159321		FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX		
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 399 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6754	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-156662 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 440 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		
6750	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P153060 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 411 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6755	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P156684 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		
6751	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-151109 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6756	2016 Genie GS-1930 Scissor Lift S/N: GS3016P-156684 C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		
	FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6757	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A-150674 C/W: 19 ft Max Platform Height, 500 lb Max		
6752	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A150812 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 433 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 471 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details	
6757A	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159322 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 544 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6762	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P159764 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	
6758	2016 Genie GS-1930 Scissor Lift	6763	2016 Genie GS-1930 Electric Scissor Lift	
	S/N: GS3016P-159736 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 550 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	0/03	S/N: GS3016P159709 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available <b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	
6759	2016 Genie GS-1930 Electric Scissor Lift		FUNCTION TEST AND LOAD	
	S/N: GS3016P159736		Asset located in: Lake Worth, TX	
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 550 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6764	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016P-159326 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 622 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	
6760	2016 Genie GS-1930 Electric Scissor Lift		FUNCTION TEST AND LOAD	
	S/N: GS3016P-159631		Asset located in: Lake Worth, TX	
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 552 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6765	S/N: GS3016A150748 C/W: 19 ft Max Platform Height Weight Capacity, Platform Exte Platform, Solid Non-Marking Til Control Box, EQUIPMENT-FRON EQUIPMENT Usage: 450 Hr Notes: AERIAL UNITS REQUIRE	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
6761	2016 Genie GS-1930 Electric Scissor Lift		FUNCTION TEST AND LOAD	
	S/N: GS3016P156681 C/W: 19 ft Max Platform Height, 500 lb Max		Asset located in: Lake Worth, TX	
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 603 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6766	2016 Genie GS-1930 Scissor Lift S/N: GS3016P- 154550 Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6767	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149270 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6772	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146154 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 386 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6768	2015 Genie GS-1930 Electric Scissor Lift	6773	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A-146342 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 329 Hr Notes: AERIAL UNITS REQUIRE PROPER		S/N: GS3015A149284 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6770	2015 Genie GS-1930 Scissor Lift  S/N: GS3015A-145107  C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT  Usage: 332 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX  2015 Genie GS-1930 Scissor Lift	6774	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3016159299 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 397 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	S/N: GS3015A-146337	6775	2015 Genie GS-1930 Electric Scissor Lift
	C/W: EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 353 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6775	S/N: GS3015A-149399 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 400 Hr
6771	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148159 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box,		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-SUNSTÄTE-EQUIPMENT Usage: 360 Hr	6776	2015 Genie GS-1930 Electric Scissor Lift
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK		S/N: GS3015A146310 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 403 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6777	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146331 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 407 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6782	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145084 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6778	2015 Genie GS-1930 Electric Scissor Lift	6783	2015 Genie GS-1930 Electric Scissor Lift
0770	S/N: GS3015A-142980 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 410 Hr	0700	S/N: GS3015A146435 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 430 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6779	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145103 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 415 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO	6784	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149417 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO
	FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX		FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
6780	2015 Genie GS-1930 Electric Scissor Lift	6785	2015 Genie GS-1930 Electric Scissor Lift
0760	S/N: GS3015A148246 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 422 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	0763	S/N: GS3015A-149321 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 432 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6781	2015 Genie GS-1930 Electric Scissor Lift	6786	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A146258 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 424 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: GS3015A145121 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 439 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	ASSEL IUGALEU III. LAKE WUILII, IA	I	ASSEL IUGALEU III. LAKE WUITI, TA

Lot #	Details	Lot #	Details
6787	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A145117 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 442 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6792	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146194 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6788	2015 Genie GS-1930 Electric Scissor Lift	6793	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A146104 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 443 Hr		S/N: GS3015A-145141 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available <b>Notes</b> : AERIAL UNITS REQUIRE PROPER
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6789	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-148249 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;	6794	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015149276 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 445 Hr Notes: AERIAL UNITS REQUIRE PROPER
	Asset located in: Oklahoma City, OK	_	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6790	2015 Genie GS-1930 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS3015A146319 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 449 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6795	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149414 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6791	2015 Genie GS-1930 Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: GS3015A149351 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 458 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6795A	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148197 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 461 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6796	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149305 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 466 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6801	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146325 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6797	2015 Genie GS-1930 Electric Scissor Lift	6802	2015 Genie GS-1930 Electric Scissor Lift
	S/N: GS3015A149397 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 468 Hr		S/N: GS3015A149391 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 504 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6798	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149413 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 491 Hr	6803	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-146335 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 408 Hr
	<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		<b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	ļ	Asset located in: Lake Worth, TX
6799	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A-149349 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 493 Hr	6804	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A149262 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 543 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6800	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A148168 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 503 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6805	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146282 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6806	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A142971 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6811	2014 Genie GS-1930 Electric Scissor Lift  S/N: GS3014A-136463  C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 429 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6807	2015 Genie GS-1930 Electric Scissor Lift S/N: GS3015A146318 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6812	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A138505 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 453 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6808	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138135 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 393 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6813	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138417 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 459 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6809	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A138418 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 412 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-6814	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138080 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6810	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138412 C/W: 19 ft Max Platform Height, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	-6815	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A-138082 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 464 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6816	2014 Genie GS-1930 Electric Scissor Lift S/N: GS3014A136467 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 561 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6821	2017 JLG 1930ES Electric Scissor Lift S/N: M200012778 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 426 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6817	2013 Genie GS-1930 Electric Scissor Lift	6822	2017 JLG 1930ES Electric Scissor Lift
	S/N: GS3013A124360 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 367 Hr <b>Notes</b> : AERIAL UNITS REQUIRE PROPER		S/N: M200006460 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 488 Hr Notes: AERIAL UNITS REQUIRE PROPER
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
6818	2013 Genie GS-1930 Scissor Lift S/N: GS3013A124169 C/W: 19 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX  2017 JLG 1930ES Electric Scissor Lift	6823	2017 JLG 1930ES Electric Scissor Lift S/N: 0200264246 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 525 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
0819	S/N: M200012853	6824	2017 JLG 1930ES Electric Scissor Lift
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 324 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX		S/N: M200006500 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 387 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
6820	2017 JLG 1930ES Electric Scissor Lift		Asset located in: Lake Worth, TX
0020	S/N: 0200264250 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 392 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6825	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006381 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 521 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6826	2017 JLG 1930 ES Electric Scissor Lift S/N: 0200264702 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 379 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6830	2016 JLG 1930 ES Electric Scissor Lift  S/N: M200003881  C/W: 19 ft Max Platform Height, 509 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 390 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
6827	2017 JLG 1930 ES Electric Scissor Lift S/N: M200005469 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 436 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6832	2016 JLG 1930ES Electric Scissor Lift S/N: M200003701 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 446 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6827A	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006504 C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 447 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6834	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200248756 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 236 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
6828	2016 JLG 1930 ES Electric Scissor Lift S/N: 0200256735 C/W: 18 ft 8 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 176 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6835	2015 JLG 1930 ES Electric Scissor Lift S/N: 0200246003 C/W: 18 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 402 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6829	2017 JLG 1930 ES Electric Scissor Lift S/N: M200006299 C/W: 18 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 382 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Oklahoma City, OK	6836	2015 JLG 1930ES Electric Scissor Lift  S/N: 0200246832  C/W: 18.8 ft Max Platform Height, 500 lb Max  Weight Capacity, Platform Extension, Power to  Platform, Solid Non-Marking Tires, Upper  Control Box, EQUIPMENT-FROM-SUNSTATE-  EQUIPMENT  Usage: 425 Hr  Notes: AERIAL UNITS REQUIRE PROPER  SAFETY HARNESS, LANYARD, AND PPE TO  FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX

1 at "	Dataila	1 "	Dataila
Lot #	Details	Lot #	Details
6837	2012 JLG 1930ES Scissor Lift  S/N: B200004837 Usage: 496 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	6842	2018 MEC 1330SE Electric Scissor Lift S/N: 16301451 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 256 Hr
6838	8 2020 MEC MICRO 19 Electric Scissor Lift S/N: 16907444 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
	Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6843	2018 MEC 1330SE Electric Scissor Lift S/N: 16301467 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
6839	2018 MEC 1330SE Electric Scissor Lift S/N: 16301468 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-		Usage: Not Available  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX
	EQUIPMENT Usage: 24 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		2018 MEC 1330SE Electric Scissor Lift S/N: 16301460 C/W: 13 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
6840	2018 MEC 1330SE Electric Scissor Lift S/N: 16301584 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	6845	Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX
	Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available <b>Notes</b> : AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD <b>Asset located in</b> : Lake Worth, TX		2018 MEC 1330SE Electric Scissor Lift S/N: 16301603 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT
6841	2018 MEC 1330SE Electric Scissor Lift S/N: 16301583 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT	6846	Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX  2017 MEC 1330SE Scissor Lift
	Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX		S/N: 16301230 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 19 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6847	2017 MEC 1330SE Scissor Lift S/N: 16301591 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 88 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6853	2018 Genie IWP-25S Vertical Mast Lift S/N: IWPG-12193 C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK
6848	2017 MEC 1330SE Electric Scissor Lift	6054	
	S/N: 16301447 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 105 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6854	2017 Genie AWP-25S Vertical Mast Lift S/N: AWPG-90308 C/W: 24 ft 11 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
6849	MEC 1330SE Electric Scissor Lift	ļ	Asset located in: Lake Worth, TX
	S/N: 16301456 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6855	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-49588 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 167 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6850	2017 MEC 1330SE Electric Scissor Lift S/N: 16301120 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	6856	2017 Genie GR20 Vertical Mast Lift S/N: GRP-50131 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 342 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6851	2017 Genie AWP30SDC Vertical Mast Lift S/N: AWPG-89720 C/W: 29 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6857	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-50133 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 419 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6852	2017 Snorkel MB26J Vertical Mast Lift	6858	
	S/N: MB26J-01-170700055 C/W: 26 ft Max Platform Height, 475 lb Max Weight Capacity, Power to Platform, Upper Control Box Usage: 258 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	0638	2017 Genie GR20 Vertical Mast Lift S/N: GRP-48660 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 448 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6859	2017 Genie GR-20 Vertical Mast Lift S/N: GRP-49586 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 482 Hr Notes: AERIAL UNITS REQUIRE PROPER	6865	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539233 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6865A	<b>2015 Genie GR-20 Vertical Mast Lift</b> S/N: GR1539281 Usage: Not Available
6860	S/N: GR16P-40894 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT	6865B	Asset located in: Lake Worth, TX  2015 Genie GR-20 Vertical Mast Lift S/N: GR1538466 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 6 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	6865C	<b>2014 Genie GR-20 Vertical Mast Lift</b> S/N: GR14-30574 Usage: 362 Hr <b>Asset located in</b> : Lake Worth, TX
6861	2016 Genie GR-20 Vertical Mast Lift S/N: GR16P-43838 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 640 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6866	2013 Genie GR-20 Vertical Mast Lift S/N: GR13-27800 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 495 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
6862	2015 Genie GR-20 Vertical Mast Lift S/N: GR15-39295 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires,	6867	2013 Genie GR20 Vertical Mast Lift S/N: GR13-28800 Usage: Not Available Asset located in: Lake Worth, TX
6863	Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 487 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Oklahoma City, OK  2015 Genie GR-20 Vertical Mast Lift S/N: GR1538516	6868	2013 JLG 20MVL Vertical Mast Lift S/N: 0130019279 C/W: 19 ft 6 in Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	6869	2019 Haulotte STAR 20 Vertical Mast Lift S/N: 2062580 Usage: Not Available
6864	2015 Genie GR-20 Vertical Mast Lift S/N: GR1539023 C/W: 20 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box, EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: 435 Hr Asset located in: Lake Worth, TX		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6870	2023 Ballymore DVML-18 Vertical Mast Lift (Unused)  S/N: DBA2302163  C/W: 19 ft 7 in Max Platform Height, 350 lb Max Weight Capacity, Solid Non-Marking Tires, Upper Control Box Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX	6875	2015 Genie GR-12 Vertical Mast Lift S/N: GR1539738 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 367 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
6871	2017 Genie GR-12 Vertical Mast Lift	6876	2015 Genie GR-12 Vertical Mast Lift
0071	S/N: GRP-49699 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 214 Hr		S/N: GR1538757 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 433 Hr
	Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD		Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
	Asset located in: Lake Worth, TX	_	Asset located in: Lake Worth, TX
6872	2017 Genie GR-12 Vertical Mast Lift S/N: GRP-49754 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 301 Hr Notes: AERIAL UNITS REQUIRE PROPER	6877	2014 Genie GR-12 Vertical Mast Lift S/N: GR14-36227 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 495 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX
	SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD	6878	2014 Genie GR-12 Vertical Mast Lift S/N: GR1436093
	Asset located in: Lake Worth, TX		
6873	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41021 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 319 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO		C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 544 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX
	FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX	6879	2014 Genie GR-12 Vertical Mast Lift S/N: GR14-35973
6874	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41028 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 476 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX		C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Solid Non-Marking Tire Upper Control Box, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 552 Hr  Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6880	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P21140 C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 208 Hr	6888	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178459 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6000	·
6881	2022 Bobcat MT100 Mini Compact Track Loader S/N: B52P20643 C/W: Open Operator Station, Tier 4, 2022 US EPA Label, 7 in Track Belts, Manual Coupler, 36 in Bucket Usage: 455 Hr	6889	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused)  S/N: 2404163371  C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available  Asset located in: Lake Worth, TX  2024 JQ POWER JQ400 Mini Compact Track
	Asset located in: Lake Worth, TX	-	Loader
6882	2019 Vermeer S925TX Mini Compact Track Loader S/N: 1VRL07056J1000534 C/W: Open Operator Station, Tier 4, 2018 US EPA Label, 7 in Track Belts, Manual Coupler, 42 in Bucket		S/N: 2404178462 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: 2,318 Hr	6891	2024 JQ POWER JQ400 Mini Compact Track
6883	Asset located in: Lake Worth, TX  2014 Ditch Witch SK755 Mini Ride-On Compact Track Loader S/N: CMWZ57NLCE0000057 Usage: Not Available		Loader (Unused) S/N: 2404163356 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	6892	2024 Machpro MP-S300 Mini Compact Track
6884	2024 Eingp SCL850 Mini Compact Track Loader (Unused) S/N: SCL8500125 C/W: Open Operator Station, 9 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6000	Loader (Unused)  S/N: MP2409073147  C/W: Open Operator Station, Manual Coupler, 44 in Bucket  Usage: Not Available  Asset located in: Lake Worth, TX
6885	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: 2 Hr Asset located in: Lake Worth, TX	-6893	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT232024060000006 C/W: Open Operator Station, 2024 US EPA Label, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6886	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6894	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178498 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX
6887	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: 1 Hr Asset located in: Lake Worth, TX	6895	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409073142 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6896	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043138 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available	6904	2007 Ditch Witch R300 Wheel Loader S/N: CMW1D4XK70000069 C/W: Open Operator Station, Auxiliary Hydraulics, Manual Coupler, 36 in Bucket, 20x100-8 Tires Usage: Not Available
	Asset located in: Lake Worth, TX	<del>                                     </del>	Asset located in: Lake Worth, TX
6897	2024 Machpro MP-S300 Mini Compact Track Loader S/N: SLP2403080620 C/W: Open Operator Station, 2023 US EPA Label, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: 37 Hr Asset located in: Lake Worth, TX	6905	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080305 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX
6898	2024 Machpro MP-S300 Mini Compact Track Loader (Unused) S/N: MP2409043137 C/W: Open Operator Station, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6906	2024 Digmaster DM200 Mini Excavator (Unused) S/N: DM24080303 C/W: 3 ft Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX
6899	2024 BTTL ST25M-6 Mini Compact Track Loader (Unused) S/N: A2407158825 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6907	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408069118 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6900	2024 BTTL ST25M-6 Mini Compact Track Loader (Unused) S/N: A2407158835 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6908	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408043843 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6901	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT232024052200230 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Lake Worth, TX	6909	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044079 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX
6902	2024 AGT LRT23 Mini Compact Track Loader (Unused)  S/N: LRT23202408010005  C/W: Open Operator Station, Joystick Steering, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	6910	2024 FF Industrial FF18R Mini Excavator (Unused) S/N: 2408044073 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
6903	2024 AGT CH904 Wheel Loader S/N: CH9042024L0618005 C/W: Open Operator Station, 38 in Bucket, 23X8.5-12 Tires Usage: Not Available Asset located in: Lake Worth, TX	6911	2024 FF Industrial FF18R Mini Excavator S/N: 2408069186 C/W: 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6912	2024 Landhero LDH-KV16 Mini Excavator (Unused) S/N: Not Available C/W: 2 ft 8 in Stick, Backfill Blade, 7 in Rubber Tracks, 15 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6920	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515626 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX
		6021	2024 VICSEC VC15P Mini Excavator (Unused)
6913	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515624 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6921	S/N: VA15P240703 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, Manual Quick Coupler, 17 in Digging Bucket, Manual Thumb Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
6914	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515549 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks,		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	12 in Digging Bucket, Manual Thumb Usage: Not Available	6922	2024 FF Industrial FF-15 Mini Excavator
6915	Asset located in: Lake Worth, TX  2024 Machpro MP15 Mini Excavator (Unused)  S/N: SLP241515621  C/W: 2 ft 7 in Stick, Auxiliary Hydraulic  Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb		(Unused) S/N: 423032738 C/W: Straight Travel Pedal, Tier 2, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX		Asset located in: Humble, TX
6916	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515538 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	<b>—</b> 6923	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423032626 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: 66 Hr Asset located in: Lake Worth, TX
6917	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515589 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6924	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423050691 C/W: Enclosed Cab, 2 ft 6 in Stick, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket Usage: Not Available Asset located in: Lake Worth, TX
6918	2024 Machpro MP15 Mini Excavator (Unused) S/N: SLP241515609 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6925	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423105139 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available
6919	2024 Machpro MP15 Mini Excavator (Unused)		Asset located in: Lake Worth, TX
	S/N: SLP241515546 C/W: 2 ft 7 in Stick, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6926	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423123854 C/W: Enclosed Cab, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
6927	2024 VICSEC VC13 Mini Excavator (Unused) S/N: VC13240617 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Thumb Bracket Usage: Not Available	6934	Quantity of (5) 2024 Landhonor LHR-SG64 6 ft x 4 ft Livestock Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6928	Asset located in: Humble, TX  2024 FF Industrial FF-12 Mini Excavator (Unused)  S/N: 423136819  C/W: 2024 US EPA Label, 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb  Usage: Not Available  Asset located in: Lake Worth, TX	6935	Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6929	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136832 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6936	Asset located in: Lake Worth, TX  Quantity of (20) 2024 Suihe SP10-20G 10 ft Livestock Gate (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6930	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423136824 C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6931	Asset located in: Lake Worth, TX  2024 FF Industrial FF-12 Mini Excavator (Unused)  S/N: 423136840  C/W: 2 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX	6937	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6932	2024 BTTL ET12M-6 700718 Mini Excavator (Unused)  S/N: ET12M-6 700718  C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX  Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused)  S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6933	2024 BTTL ET12M-6 Mini Excavator (Unused) S/N: ET12M-6700717 C/W: 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION ( THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6939	Quantity of (56) 2024 Suihe SP10-S-56 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	6945	Quantity of (4) Bundles of 10 Ft Livestock Panel S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	6946	2024 Industrias America R820 20 Ft Loading Ramp (Unused) S/N: R82020242517 Usage: Not Available Asset located in: Lake Worth, TX	
		6947	<b>20 ft Loading Ramp (Unused)</b> S/N: Not Available	
6940	Quantity of (56) 2024 Suihe SP10-G-56 10 ft Livestock Panel (Unused)		C/W: 30,000 lb. Capacity Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6948	2024 Landhonor LHR-CSC10 Cattle Squeeze Chute (Unused) S/N: HL00009 Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	6949	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6941	·		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
			Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		<b>Shelter (Unused)</b> S/N: Not Available	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused) S/N: Not Available
6942	Asset located in: Lake Worth, TX  Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available			FOR ILLUSTRATION PURPOSES O MAY NOT BE AN EXACT REPRESE THE ACTUAL PRODUCT.
	Notes: THE PRODUCT IMAGES SHOWN ARE	6051	Asset located in: Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6951	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available	
6040	Asset located in: Lake Worth, TX	_	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
6943	Quantity of (12) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
_	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		<b>Notes</b> : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
6944	Quantity of (24) 2024 Landhonor LHR-SP07 7 ft Sheep Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6952	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6959	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: M12S225549 Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	6960	Quantity of (50) 12 ft Corral Livestock Panel S/N: Not Available C/W: Two Bundles Usage: Not Available Asset located in: Lake Worth, TX
6953	Asset located in: Lake Worth, TX  2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6961	2024 SUNTOP S0720 Qty of (6) 20FT Bi- Parting Wrought Iron Driveway Gate (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	6962	Quantity of (6) 2024 SUNTOP S0720 20 ft
6954	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	0902	Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
6955	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused)		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	6963	Asset located in: Lake Worth, TX  Quantity of (6) 2024 SUNTOP S207 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6956	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX
6957	Asset located in: Lake Worth, TX  Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused)  S/N: M12S224202 Usage: Not Available Asset located in: Lake Worth, TX	6964	Quantity of (3) 2024 Suihe NFG-20FB-3 Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
6958	Eingp MSC1220F 20 ft x 12 ft Livestock Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6965	Quantity of (3) 2024 Suihe NFG-20FC-3 20 ft Bi- Parting Farm Driveway Gate (Unused)  S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6970	2024 Suihe SG 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	
6966	Asset located in: Lake Worth, TX  2024 Suihe NFG-20FGP-D 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	-6971	Quantity of (2) 2024 Suihe NG-14D -2 14 ft Bi- Parting Driveway Gate (Unused)  S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	6972	Quantity of (2) 2024 Suihe NG-14Eu-2 14 ft Bi- Parting Driveway Gate (Unused) S/N: Not Available	
6967	7 2024 Suihe NFG-20FGP-E 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
		6973	Quantity of (6) 2024 SUNTOP SO7020 20 ft x 7 ft Driveway Gate  S/N: Not Available  C/W: 20 ft x 7 ft Wrought Iron Bi Parting  Driveway Gate  Usage: Not Available  Asset located in: Lake Worth, TX	
6968	Quantity of (8) 2024 Suihe NG-20D-8 20 ft Bi- Parting Driveway Gate (Unused)  S/N: Not Available C/W: Oval Deer Motif Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	6974	6974 Quantity of (20) 2024 SUNT ft Chain Link Temporary Sit S/N: Not Available C/W: THE PRODUCT IMAGE FOR ILLUSTRATION PURPO MAY NOT BE AN EXACT RE THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGE	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6969	Quantity of (8) 2024 Suihe SG-20D-8 20 ft Bi- Parting Driveway Gate (Unused)  S/N: Not Available C/W: Rectangle Deer Motif Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
6975	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	6980	Quantity of (26) 2024 Suihe SF-D-26 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
6976	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available Usage: Not Available	6981	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	6982	Quantity of (20) 8 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6977	2024 SUNTOP S0610 Qty of (20) 10FT Portable Construction Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	6983	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE	6984	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6978	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX  Quantity of (20) 2024 SUNTOP S0610 10 ft x 6	6985	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available
0370	ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6986	Asset located in: Lake Worth, TX  Quantity of (20) 10 ft x 7 ft Site Fence (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6987	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
6979	THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX  Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6988	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
		6989	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	6990	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
6991	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	6997	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 f Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6992	Quantity of (30) 6 ft x 8 ft Site Fence (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX			
6993	Quantity of (20) 10 ft x 7 ft Site Fence (Unused) S/N: Not Available Usage: Not Available	6998	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  Overtice of (24) 10 ft x 7 ft Columnized Engine	
6994	94 Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	0996	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	
		6999	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	7000	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	
6995	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND			
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7002	Quantity of (24) 10 ft x 7 ft Galvanized Fencing (Unused)	
6996	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available C/W: One Rack Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7003	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
		7004	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7005	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	7010	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7011	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused)
7006	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	7012	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused)
	Asset located in: Lake Worth, TX	4	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7007	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused)  S/N: Not Available  C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN  ARE FOR ILLUSTRATION PURPOSES ONLY  AND MAY NOT BE AN EXACT		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
		7013	Quantity of (20) 2024 Agriquip GLWF1007 10 ft
	REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	7010	x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7008	Quantity of (30) 2024 SUNTOP S0710-30 10 ft	<del> </del>	Asset located in: Lake Worth, TX
7000	x 7 ft Powder Coated Fencing (Unused)  S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7014	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7009	Quantity of (20) 2024 FENS FEN20 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: B44823 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7016	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7017	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available	7026	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7018	Asset located in: Lake Worth, TX  18 Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing	7027	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available	
	(Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX	7028	Asset located in: Lake Worth, TX  Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused)  S/N: Not Available Usage: Not Available	
7019	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing		Asset located in: Lake Worth, TX	
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7029	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7020	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7030	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7021	Quantity of (20) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: One Rack Usage: Not Available	7031	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Chain Link Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7022	Asset located in: Lake Worth, TX  Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7032	40 in Galvanized Farm Fencing ( S/N: Not Available C/W: THE PRODUCT IMAGES SIFOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRE THE ACTUAL PRODUCT Usage: Not Available	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7023	Quantity of (24) 2024 HUNTER PRO WLFT10- 24P 10 ft x 7 ft Powder Coated Fencing (Unused)		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7033	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused)	
7024	Quantity of (44) 7 ft 10 in x 7 ft Powder Coated Fencing S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
7025	Quantity of (2) Pallets of 78 In x 10 Ft Site Fence S/N: Not Available C/W: Accessories Usage: Not Available Asset located in: Lake Worth, TX		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7034	2024 SUNTOP S4200 Qty of (21) 200ft x 40in Galvanized Farm Fencing (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7038	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)  S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX
7035	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)  S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7039	Quantity of (36) Rolls of Field Fence 47 In x 330 Ft Fencing (Unused)  S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX  Quantity of Fencing S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
7036	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
7037	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX  2024 SUNTOP G500 500 ft x 7 ft Chain Link		S/N: Not Available C/W: Braces. Rack Usage: Not Available Notes: ITEMS AT OFFS BE PICKED UP WITHIN AUCTION (JANUARY 3I SUBJECT TO 3RD PAR BUYER RESPONSIBLE F
	Galvanized Fencing (Unused) S/N: Not Available		THESE  Asset located in: Lahoma, OK
	C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7042	Quantity of (8) Fencing S/N: Not Available C/W: Braces Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
7043	43 Quantity of (4) Fencing  S/N: Not Available C/W: Braces Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	7050	Quantity of (2) Dewalt DXGNR6500 Portable Generator Set S/N: Not Available C/W: 2021 US EPA Label, Generac 389 cc Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	
		7051	Quantity of (2) Generac GP8000E 8 kW Portable Generator Set S/N: Not Available C/W: 2023 US EPA Label, Generac 420 cc	
7044	Quantity of Fencing S/N: Not Available C/W: 36 in. Silt Fence With Additional Wooden		Gasoline Engine, 240 V & 120 V Receptacles Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	Stakes Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	7052	Quantity of (3) Generac GP3600 3.6 kW Quantity of (1) Generac GP3500i Portable Generator Set S/N: Not Available C/W: Generac 212 cc Gasoline Engine, 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX	
7045	Asset located in: Lahoma, OK  2024 Agriquip GLHP100 100 ton Air/Hydraulic Shop Press (Unused)  S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7053	Quantity of Ryobi 3400 Watt & Champion 3500 Watt Portable Generator Set S/N: Not Available C/W: Dual Fuel Engine, 120 V Receptacles, Gasoline Usage: Not Available Asset located in: Lake Worth, TX	
		7056	Quantity of (3) Pallets of Portable Generator Set S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7046	Quantity of (4) Portable Generator Set S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7057	Portable Generator Set S/N: 5682943 C/W: Gasoline Engine, 240 V / 120 V Voltage, 120 V Rated Voltage, EQUI FROM-SUNSTATE-EQUIPMENT	S/N: 5682943 C/W: Gasoline Engine, 240 V / 120 V Rated Voltage, 120 V Rated Voltage, EQUIPMENT-
7047	Quantity of (2) Portable Generator Set S/N: Not Available Usage: Not Available	7058	Asset located in: Lake Worth, TX  2020 Ingersoll Rand RS22N 115 cfm Skid-	
7048	Asset located in: Lake Worth, TX  Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	FROM-US-AUTO-RECYCLING Usage: 5 Hr Notes: . Asset located in: Lake Worth, TX  7059 2020 Ingersoll Rand RS22N 114.6 Mounted Electric Air Compressor S/N: CBV703202		S/N: CBV699949 C/W: 3 Phase, 30 hp Motor, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 5 Hr Notes: . Asset located in: Lake Worth, TX
7049	Quantity of (2) Wacker Neuson GP6600 6600 Watts Portable Generator Set S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		S/N: CBV703202 C/W: 3 Phase, 30 hp Motor, EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: 7,397 Hr <b>Notes</b> :	

Lot #	Details	Lot #	Details
7060	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor S/N: CBV713664 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 7,936 Hr	7068	Skid-Mounted 30 gal Air Compressor S/N: Not Available C/W: Predator 1 Cylinder 420 cc Gasoline Engine Usage: 88 Hr Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	7069	<b>Eagle 30 Gal Truck Mount Air Compressor</b> S/N: Not Available
7061	2020 Ingersoll Rand R11i 50.4 cfm Skid- Mounted Electric Air Compressor		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: CBV710808 C/W: 15 hp Motor, EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: 2,281 Hr Notes: . Asset located in: Lake Worth, TX	7070	PowerTrain 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available C/W: 175 psi Working Pressure, Gasoline Engine Usage: Not Available
7062	2024 Landhonor LHR-GAC60Y 60 Gallon 2-		Asset located in: Lake Worth, TX
	Stage Truck Mounted Air Compressor (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7071	PowerTrain 11.2 cfm 10 gal Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7063	Iron Horse Electric 60 gal Shop Air Compressor S/N: Not Available C/W: 150 psi Working Pressure, 6 hp Motor Usage: Not Available Asset located in: Lake Worth, TX	7072	Quantity of (5) Electric Air Compressor S/N: Not Available C/W: 120V, (2) Goodyear 20 gal, (1) Goodyear 10 gal, (1) Campbell Hausfeld 6 gal, (1) Hyper Tough 6 gal
7064	2024 Landhonor LHR-GAC60 Skid-Mounted 60 gal Air Compressor (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7073	Mi-T-M 13.1 cfm Skid-Mounted Air Compressor S/N: 20175543 C/W: 100 psi Working Pressure, 2013 US EPA Label, Honda GX200 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
7065	2024 Landhonor LHR-GAC40 Skid-Mounted 40 gal Air Compressor (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7074	Jenny Skid-Mounted Air Compressor S/N: Not Available C/W: 2008 US EPA Label, Honda 1 Cylinder 270 cc Gasoline Engine, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7075	2024 Suihe PW Skid-Mounted Pressure
7066	Coltec Industries OSI370WNW41A Skid- Mounted Electric Air Compressor S/N: 94897 C/W: 175 psi Working Pressure, 230/460 volts Usage: 2,363 Hr Asset located in: Lake Worth, TX		Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE
7067	Skid-Mounted Air Compressor S/N: 380091 C/W: 2013 US EPA Label, Kohler Command Pro 1 Cylinder 429 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7075A	Northstar Pressure Washer S/N: 4K1BP1625FF001307 C/W: Water Heater, 500 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7083	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244542 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available
7076	Easy-Kleen Magnum 3600 Pressure Washer		Asset located in: Lake Worth, TX
	(Unused) S/N: 2440130 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in: Lake Worth, TX	7084	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243899 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available
7077	Easy-Kleen Magnum 3600 Pressure Washer (Unused)		Asset located in: Lake Worth, TX
	S/N: 243819 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available Asset located in: Lake Worth, TX	7085	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244616 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc
7078	Easy-Kleen Magnum 3600 Pressure Washer (Unused)		Gasoline Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: 2440131 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Electric Operated Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244541 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
7079	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 243888		
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: 243887 C/W: 4000 psi Rating, Water Heater, Hose,
7080	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244614		Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7088	2023 Power Wash Store Pressure Washer S/N: 5RHCT101XPH003995 C/W: 225 gal Water Supply, Hose, Trailer Mounted, Honda GX390 1 Cylinder 389 cc
7081	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244615		Gasoline Engine, Spring Suspension, Ball Hitch Wood Flooring Usage: Not Available <b>Asset located in</b> : Midland, TX
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Aladin 8430-C Pressure Washer S/N: Not Available C/W: Water Heater, Electric Operated Usage: 1,411 Hr
7082	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244617 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Lifan 1 Cylinder 15 hp 420 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Midland, TX

Lot #	Details	Lot #	Details	
7090	All American 8357L Skid Mounted Pressure Washer (Inoperable) S/N: 105855 C/W: Water Heater, Kubota D1105 3 Cylinder Diesel Engine Usage: 1,058 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Landa PGDC5-3500 Pressure Washer	7100	Simpson MS61219 Pressure Washer S/N: 05235011741 C/W: 3400 psi Rating, Hose, Spray Wand, Simpson CRX225 1 Cylinder 224 cc Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	
	S/N: 11100510101372 C/W: 3500 psi Rating, Water Heater, Honda GX630 Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lahoma, OK  Simpson Pressure Washer S/N: Not Available C/W: 4000 psi Rating, Honda 1 Cylinder Gasoline Engine	
7092	<b>2020 Hotsy 1075SSE Pressure Washer</b> S/N: 11100120168267 C/W: 3500 psi Rating, Water Heater, Hose,	7101	Usage: Not Āvailable  Asset located in: Lake Worth, TX	
	Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 67 Hr Notes: . Asset located in: Lake Worth, TX	7101	Quantity of (4) Boxes of Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available	
7094	2018 Mi-T-M HS-3505-0MDK Pressure Washer	1	Asset located in: Lake Worth, TX	
7095	S/N: 15119001 Usage: 404 Hr Asset located in: Lake Worth, TX 2016 Mi-T-M CW-3504-5MGH Pressure Washer S/N: Not Available	7102	Quantity of (4) Simpson Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Honda GCV160 Gasoline Engine Usage: Not Available	
	C/W: 3500 psi Rating, Honda GX390 1 Cylinder Gasoline Engine Usage: Not Available	7103 Quantity of (5) Murray Pressure Was S/N: Not Available C/W: 3200 psi Rating, Hose, Spray W	Quantity of (5) Murray Pressure Washer	
7096	Asset located in: Lake Worth, TX  2018 Mi-T-M CW25054MGH Pressure Washer S/N: 11041408 C/W: 2500 psi Rating, Honda GX390 Gasoline Engine		Usage: Not Available	
	Usage: Not Available  Asset located in: Lake Worth, TX	7104	<b>Quantity of (5) Murray Pressure Washer</b> S/N: Not Available	
7097	2017 Mi-T-M HSP-2503-0MMH Pressure Washer S/N: 15111154 C/W: 2500 psi Rating, Water Heater, Honda GX200 196 cc Gasoline Engine			C/W: 3200 psi Rating, Hose, Spray Wand, Briggs & Stratton CR950 208 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	7105	2019 Mi-T-M HSP-3504-3MGH Pressure Washer	
7098	Quantity of (2) Pressure Washer S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		S/N: 15132271 C/W: 3500 psi Rating, Water Heater, Hose, Spray Wand, Honda GX390 Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Corsicana, TX	7106	Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, Briggs & Stratton 208 cc Gasoline Engine Usage: Not Available	

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7107	Landa PGDC5-3500 Pressure Washer S/N: 11100500101087 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton Vanguard 18 hp 570 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX  2002 Pressure Washer S/N: 1P9HT1S2321293177 C/W: 3000 psi Rating, Water Heater, 500 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler Command Pro 2 Cylinder	7113	2024 Suihe 2040P 40 ft x 20 ft Commercial Party Tent (Unused)  S/N: Not Available C/W: (18) Removable Side Walls w/PVC Clear Windows, (2) Zipper Doors, 500 gsm PVC Coated Fabrics, Waterproof, Fire & UV Resistant, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
	Gasoline Engine, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 1,068 Hr <b>Asset located in</b> : Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
7109	40 ft High Cube Office Storage Container (Unused) S/N: KDCU5211968 C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED Ceiling Lights, Interior Outlets, forklift pockets Usage: Not Available Asset located in: Lake Worth, TX	7114	2024 SUNTOP S2119 19 ft x 21 ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7110	20 ft Office Storage Container (Unused) S/N: SKYU2652356	7115	THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX
	C/W: Seller Comments: Single Walk Steel Door, Dual Pane Windows w/ sun screens, R30 Insulation in roof, R19 Insulation in walls, A/C w/ heat, vinyl flooring, Electric Panel, LED Ceiling Lights, Interior Outlets, forklift pockets Usage: Not Available		2024 Suihe GS2119 21ft x 19ft Portable Metal Shed (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7116	2024 Suihe GS2322 Metal Shed (Unused)
7111	2024 LEVE LE20 19 ft 5 in x 20 ft Expandable House (Unused)  S/N: A0282  C/W: ( 2 ) Bedrooms w/, ( 1 ) Bathrooms, (1)  Living Room  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	<u>`</u>	7117	2024 Suihe M202010P Light Steel Carport
7112	2024 Suihe GS2533 Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		(Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7118	2024 Suihe M122009P Light Steel Carport (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7125	2024 Suihe S5010023DP-750gPVC 100 ft x 50 ft x 23 ft Storage Building (Unused)  S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
7119	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Asset located in: Lake Worth, TX	
		7126	2024 HIlls Industrial 805026 80 Ft x 50 Ft x 26 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	7127	2024 HIlls Industrial 504026 50 Ft x 40 Ft x 26 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
7120	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7128	2024 HIlls Industrial 804024 80 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	7129	2024 Suihe S408023DP-610gPVC 80 ft x 40 ft x 23 ft Storage Building (Unused)  S/N: Not Available  C/W: Quantity of (3) Boxes - Builds (1) Storage  Building, THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF	
7121	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Notes: THE PRODUCT IMAG FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REF THE ACTUAL PRODUCT	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7122	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2024 Suihe S408020R-300gPE 80 ft x 40 ft x 20 ft Storage Building (Unused)  S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE	
7123	Quantity of (200) 2024 Machpro S3048C 10 ft Corrugated PPGI Steel Panels (Unused) S/N: 2408070018 C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX		FOR ILLUSTRATION PURPOSE MAY NOT BE AN EXACT REPF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSE	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7124	Quantity of (200) 2024 Machpro S3048C 10 ft Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7131	2024 Landhonor LHR-ST3085 85 ft x 30 ft Storage Building (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7137	2024 Suihe S306020DP-610gPVC 60 ft x 30 ft x 20 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7138	2024 Landhonor LHR-ST3040 40 ft x 30 ft Storage Building (Unused) S/N: Not Available
7132	2024 Suihe S406423DP-610gPVC 64 ft x 40 ft x 23 ft Storage Building (Unused)  S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7139	2024 Hills Industrial 604024 60 Ft x 40 Ft x 24
7133	2024 Hills Industrial 604024 60 Ft x 40 Ft x 24 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available		Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7140	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x
7134	2024 Suihe S308515R-300gPE 85 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7141	2024 Hills Industrial 603022 60 Ft x 30 Ft x 22 Ft Storage Building (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7135		7142	2024 Hills Industrial 403022 40 Ft x 30 Ft x 22 Ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	15 ft Storage Building (United Structure of Storage Building (United Storage Building (United Storage Building (United Storage Building (United Storage Building Buil	2024 Suihe S304015R-300gPE 40 ft x 30 ft x 15 ft Storage Building (Unused)
7136	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF

Lot #	Details	Lot #	Details
7144	2024 Suihe S2040DP-500gPVC 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7149	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused)  S/N: Not Available C/W: C/W: 2x6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX
7145	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused)  S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7150	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused)  S/N: Not Available C/W: C/W: 2 x 6 Wood Trusses, 6 in x 6 in x16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX
7146	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12	7151	Pole Barn Package 16 ft x 32 ft x 40 ft Storage Building (Unused)  S/N: Not Available  C/W: C/W: 2 x 6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly
	ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		Usage: Not Available  Asset located in: Lake Worth, TX
		7152	16 ft x 24 ft x 40 ft Pole Barn Package Storage Building (Unused)  S/N: Not Available C/W: Includes: 2x6 Wood Trusses, 16 ft Treated Timbers, Lumber, Roof Metal ONLY, Ridge Cap & Trim, & Hardware Needed For Assembly Usage: Not Available Asset located in: Lake Worth, TX
		7153	2024 Suihe C404015S-610gPVC x 15 ft
7147	t Storage Building (Unused)  S/N: Not Available  C/W: Dome Frame, PE Fabric, 2-Year PE  Estimated Service Life, THE PRODUCT IMAGES  SHOWN ARE FOR ILLUSTRATION PURPOSES  ONLY AND MAY NOT BE AN EXACT  REPRESENTATION OF THE ACTUAL PRODUCT  Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF		Container Storage Canopy (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT	7154	2024 Suihe C404013-300gPE x 13 ft Container
7148	Asset located in: Lake Worth, TX  2023 HOS HF2N1 19 ft x 21 ft Folding Storage Building S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7155	2024 Suihe C404013-300gPE x 13 ft Container Storage Canopy (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7160	Quantity of (2) Conveyor Belts - Fits Tractor S/N: Not Available C/W: (1) 55 ln, (1) 42 ln; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7161	Quantity of (3) Uline Tool Cabinet  S/N: Not Available  C/W: (1) 42 In 11 Drawer, (1) 29 In 5 Drawer,  (1) 29 In 7 Drawer; EQUIPMENT-FROM-US-AUTO-RECYCLING	
7156	2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused)		Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7162	Cabinet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTATION OF T Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7157	2024 Suihe C2040-300gPE 20 ft x 40 ft Container Shelter Storage Canopy (Unused)		MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7163	18 In x 24 In Tool Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
		7164	7164 Quantity of Tool Box S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST	
7158	Asset located in: Lake Worth, TX  2024 Suihe C2020-300gPE 20 ft x 20 ft Container Shelter Storage Canopy (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF	7165	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		UWS TBC60N Tool Box S/N: Not Available C/W: 60 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	
7159	2024 Suihe C504017DR-610gPVC 50 ft x 40 ft x 17 ft Container Shelter Storage Canopy (Unused) S/N: Not Available		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7166	Quantity of (3) Tool Box  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION  Usage: Not Available  Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
7167	Quantity of (3) Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7173	2024 Suihe NWB-H40DB-10 10 ft 40-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
7168	Quantity of (3) Truck Toolboxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7169	2024 Suihe NWB-30DS-10 10 ft 30-Drawer Workbench (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7175 7176	Can Industrial 10 ft 40 Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available
7170	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused)		Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7171	Asset located in: Lake Worth, TX  2024 Suihe NWB-15DR-2-10 10 ft 15-Drawer		Asset located in: Lake Worth, TX
	Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7178	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
7172	2024 Suihe NWB-25DB-10 10 ft 25-Drawer Workbench (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7179	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7180	2024 Suihe NWB-H30DS-9.5 9 ft 6 in 30-Drawer Workbench (Unused)  S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused)  S/N: Not Available Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7185	2024 Suihe NWB-10DS-2-7 7 ft 10-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  6 ft 7 in Workbench
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		S/N: Not Available C/W: 4 doors, 16 drawers Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7182	<u> </u>	7188	U. S. General 72 In 18 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7189	Yukon 46 In 9 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7183	3 2024 Suihe NWB-20DS-7 7 ft 20-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7190	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
		7191	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7184	Asset located in: Lake Worth, TX  2024 Suihe NWB-H18DR-7 7 ft 18-Drawer Workbench (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7192	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7193	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	<sup> </sup> 7194	Quantity of (2) Milwaukee 40 in 6-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7195	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7205	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 34 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7196	Milwaukee 40 In 6 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7206	Quantity of (4) U. S. General Service Carts S/N: Not Available C/W: (3) 4 Drawer, (1) 5 Drawer; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7197	Milwaukee 40 In 5 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7207	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7198	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7208	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7199	Asset located in: Lake Worth, TX  Quantity of (3) U. S. General 30 In Tech Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7209	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7200	Asset located in: Lake Worth, TX  U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7210 	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7201	Asset located in: Lake Worth, TX  U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING	7211	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7202	Usage: Not Available Asset located in: Lake Worth, TX  U. S. General 44 In 13 Drawer Workbench S/N: Not Available	7212	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7213	2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available
7203	U. S. General 44 In 13 Drawer Workbench S/N: Not Available C/W: U.S.General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7214	Usage: Not Available Asset located in: Lake Worth, TX  2024 Kit Containers WB-90-243 7 ft 6 in Workbench S/N: Not Available
7204	U. S. General 44 in 13-Drawer Workbench S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7215	Usage: Not Available Asset located in: Lake Worth, TX  2024 Kit Containers WB-60-190 5 ft Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7216	2024 Kit Containers WB-60-190 26 In x 60 In Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7226	2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available
7217	2024 Kit Containers ST-57 29 In x 57.5 In Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7227	Asset located in: Lake Worth, TX  2024 Kit Containers 2YFT-SDH Skid Steer Dump Hopper (Unused)  S/N: B21J1204 Usage: Not Available
7218	2024 Kit Containers ST-57 4 ft 10 in Workbench S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7228	Asset located in: Lake Worth, TX  2024 Kit Containers 2YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused)
7220	Quantity of (4) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX		S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 10 in High Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7221	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: B12I407 Usage: Not Available Asset located in: Lake Worth, TX	7229	2024 Kit Containers 1.5YFT-SDH Skid Steer Dump Hopper (Unused) S/N: B21J1206 Usage: Not Available Asset located in: Lake Worth, TX
7222	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: B191402 Usage: Not Available Asset located in: Lake Worth, TX	7230	2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available
7223	Quantity of (5) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7231	Asset located in: Lake Worth, TX  2024 Kit Containers 1.5YFT-SDH 5 ft 6 in Self- Dumping Hopper (Unused)  S/N: Not Available C/W: 5 ft 6 in Long x 4 ft 2 in Wide x 3 ft 3 in
7224	Quantity of (4) 6 ft Self-Dumping Hopper S/N: Not Available C/W: 6 ft Long x 4 ft 9 in Wide x 4 ft 6 in High,		High Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7232	Quantity of (5) 4 ft 6 in Self-Dumping Hopper S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING
7225	Quantity of (2) 2024 Suihe N-1CY -2 1 cyd Self- Dumping Hopper (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	7233	Quantity of (4) 4 ft 6 in Self-Dumping Hopper S/N: Not Available C/W: 4 ft 6 in Long x 3 ft 3 in Wide x 2 ft 10 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7234	Quantity of (2) 2024 Suihe N-1.5CY-2 1.5 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7243	Quantity of (3) Bundles of Standard Beam 4" 7.7 A36/572-50 44' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7244	Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7235	Asset located in: Lake Worth, TX 25 ft Loading Ramp (Unused)	7245	Quantity of (3) Square Bar 5/8 A-36 20' S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available	7246	Asset located in: Lake Worth, TX
7236	Asset located in: Humble, TX  Quantity of (5) Abell-Howe 1 Ton Electric Shop Pedestal Crane  S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases;		Quantity of (1) Bundle of 4 In x 36 Ft Wide Flange Beam S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7247	Quantity of (1) Bundle of Wide Flange Beam 10 in 15.0 A992/A572-50 40 ft S/N: Not Available
7237	Quantity of (5) Abell-Howe 1Ton Electric Shop Pedestal Crane S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Asset located in: Lake Worth, TX
		7248	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available
7238	Quantity of (5) 2020 Abell-Howe 1 Ton Electric	7040	Asset located in: Lake Worth, TX
	Shop Pedestal Cranes S/N: Not Available C/W: JLC 1 Ton Electric Chain Hoist, Bases; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7249	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	7250	Quantity of (3) Bundles of Hex Netting Mazel Co 22
7240	Quantity of (2) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44' S/N: Not Available	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX	7251	Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black C40 12.0-12.5
7241	Quantity of (3) Bundles Of Standard Beam 4" 7.7 A36/572-50 44' S/N: Not Available		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7252	Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft
7242	Quantity of (3) Bundles Of Standard Beam 4 in 7.7 A36/572-50 44"  S/N: Not Available Usage: Not Available		S/N: Not Available C/W: One Stack Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	7253	Quantity of (5) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7254	Quantity of (6) Bundles of Panels 8 in x 34 in x 12 ft S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX	7266	Quantity of (2) Bundles of Chainlink Xtreme 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7255	Quantity of (2) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	-7267 -7268	Quantity of (2) Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7256	Quantity of (3) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7269	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) Bundles of Stay Tuff Fixed Knot
7257	Quantity of (3) Bundles of Horse Fence Xtreme Black 12.5-12.5 2 in x 48 in x 200 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7258	Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7270	Quantity of Bundles of Chainlink Xtreme NC 2 In x 72 In x 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7259	Quantity of (3) Bunldes Of Horse Fence Xtreme Black 12.5-12.5 2" 48" 200'  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>-</b> 7271	Quantity of (4) Bundles of Stay Tuff Fixed Knot Fence 6 In x 96 In x 330 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7260	Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7272	Quantity of (4) Bundles of Horse Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7261	Quantity of (2) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 72" 50 Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>-</b> 7273	Quantity of (2) Bundles of 9 Gauge 20 in 48 in, 50 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7262	Quantity of (2) Bundles of Stay Tuff Fixed Know C3 12.0-12.5 6 in x 96 in x 330 ft S/N: Not Available Usage: Not Available	<b>-7274</b>	Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7263	Asset located in: Lake Worth, TX  Quantity of (1) Bundle of EZ-Roll Chainlink C1 12.5-2-3/8" 96" 50 Ft  S/N: Not Available Usage: Not Available	_7275	Quantity of Horse Fence Xtreme Black S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7265	Asset located in: Lake Worth, TX  Quantity of (1) Bundle Of Sheep/Goat Fence 10- 12.5 4 ln x 48 ln x 330 Ft  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7276	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7277	Quantity of (2) Bundles of Chainlink Xtreme Fence S/N: Not Available Usage: Not Available	7288	Quantity of (4) Bundles of Horse Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7278	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black C40 S/N: Not Available Usage: Not Available	7289 	Quantity of (4) Bundles of Galvanized Welded Fence 1 in x2 in 48 in 100 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7279	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>7290</b>	Bundle of Galvanized Welded Fence 2 in x4 in 60 in 100 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7280	Asset located in: Lake Worth, TX  Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available	7291 	Quantity of (3) Bundles of Galvanized Welded Fence 1"x2" 48" 100' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7281	Asset located in: Lake Worth, TX  Quantity of (4) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available	7292 	Quantity of (2) Bundles of Mazel Hex Netting 2" x 60" x 150' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7282	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7293 	Quantity of (2) Bundles of EZ Rol Chainlink PVC 1 1/2" 60" 50' S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7283	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Mazel 2 in x 36 in x 150 ft Hex Netting  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	729 <b>4</b>	Quantity of (1) Bundle Of Game Fence Stay Lock 12.5-12.5 6 In x 96 In x 330 Ft Fencing S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7284	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>7295</b>	Quantity of (1) Bundle of Fixed Knot Fence Xtreme Black 12.0-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7285	Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7296	Quantity of (2) Bundles of Chainlink Fence (1) C3 11.5 2-3/8" 72" 50ft KT (1) C3 11.5 2-3/8" 48" 50ft KK S/N: Not Available Usage: Not Available
7286	Quantity of (3) Bundles of Fixed Knot Fence Xtreme Black S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7297	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Game Fence Stay Lock C3 12.5-12.5 6  S/N: Not Available Usage: Not Available
7287	Quantity of (2) Bundles of Welded Utility Fence S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7298	Asset located in: Lake Worth, TX  Quantity of (2) Bundles of Fixed Knot Fence Xtreme Black 12.0-12.5  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details		
7299	Quantity of (3) Bundles of Fencing S/N: Not Available C/W: (2) Fixed Knot Xtreme Black 96 In x 330 Ft, (1) Game Fixed Knot Stay Lock 96 In x 330 Ft Usage: Not Available Asset located in: Lake Worth, TX	7309	Quantity of (4) Pallets of Eye Wash Stations & Spill Kits  S/N: Not Available  C/W: (1) Pallet of Absorbent Socks, (1) Pallet of Spill Kits, (2) Pallets of Eye Wash Stations; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		
7300	Quantity of (3) Bundles of Game Fence Stay Lock C3 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7310	Asset located in: Lake Worth, TX  Electric Pump S/N: Not Available C/W: MT 1/3 Hp Electric Motor, Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		
7301	Quantity of (1) Bundle of Game Fence Stay Lock 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  Sipco Hydraulic Drive Notor  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING		
7302	Quantity of High-Tensile Galvanized 15.5 Gauge Barbed Wire S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7312 Enerpac MSFP10 Hydraulic Pum S/N: P392 C/W: Sheet Metal Pieces, (2) 10 Stands; EQUIPMENT-FROM-US-A RECYCLING Usage: Not Available Asset located in: Lake Worth, TX  7314 Quantity of (2) Pallets of Assorte hoses S/N: Not Available Usage: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTM ITEM AT OFFSITE LOCATION MU PICKED UP BY DECEMBER 31ST SUBJECT TO 3RD PARTY STORA FORKLIFT ASSISTANCE WILL NO AVAILABLE Asset located in: McAlester, OK  7315 Quantity of (5) Spy Pipeline Deter Recorder S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTM ITEM AT OFFSITE LOCATION MU PICKED UP BY DECEMBER 31ST SUBJECT TO 3RD PARTY STORA FORKLIFT ASSISTANCE WILL NO AVAILABLE Asset located in: McAlester, OK	Asset located in: Lake Worth, TX  Enerpac MSFP10 Hydraulic Pump S/N: P392 C/W: Sheet Metal Pieces, (2) 10 Ton Jack Stands; EQUIPMENT-FROM-US-AUTO-		
7303	Quantity of Magnum 3 in 16d Nails S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) Pallets of Assorted fittings and hoses		
7304	Quantity of (2) Pallets of Magnum 3" 16d Nails S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX			Us <b>No</b> ITI Plu SU	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
7305	Quantity of (2) Pallets of 3 1/2" 16d Bright Common Nails S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		AVAILABLE Asset located in: McAlester, OK  Quantity of (5) Spy Pipeline Detectors & (1)		
7306	Quantity of (2) Bundles of Barbed Wire High Tensile C3 15.5 8 Rod S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX Quantity of Conveyor Belt		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ITEM AT OFFSITE LOCATION MUST I PICKED UP BY DECEMBER 31ST OR V SUBJECT TO 3RD PARTY STORAGE I	S/N: Not Available Usage: Not Available <b>Notes</b> : LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE	
, , ,	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available				
7308	Asset located in: Lake Worth, TX  Quantity of (4) Tool Carts S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7316  - 	S/N: Not Available C/W: Hydraulic Hoses, Tool Box, Caution Tape, Heavy Duty Rack, Sand Bags, and Misc Parts Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		

Lot #	Details	Lot #	Details
7317 7317A	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7323	Quantity of Hose S/N: Not Available C/W: 2 in. Discharge Hose Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
7317B	Asset located in: Lake Worth, TX  2023 Zetech Hydraulic drive motor		THESE  Asset located in: Lahoma, OK
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7324	Quantity of Water Hose S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7318	General EP8 Manhole Blower S/N: 33313 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7319	Quantity of (2) Discharge/Suction Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>-7326</b>	2015 Wanco WTMMB Solar Message Board S/N: 5F12S1611F1000499 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX
7320	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7327	2015 Wanco WTMMB Solar Message Board S/N: 5F12S161XF10005003 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch
7321	Quantity of Hose S/N: Not Available C/W: 3 in. Discharge Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL		Usage: Not Available  Asset located in: Lake Worth, TX
		7328	2012 Solar Signal Message Board S/N: 1B9ST1012CL657441 C/W: 6 Lamps, Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	7329	2012 HORIZON SIGNAL TECH SQ3TS Traffic Signal
7322	Quantity of Suction Hose S/N: Not Available		S/N: 1B9ST1010CL657471 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: 2 in., 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7330	2021 Wanco WTMMB Solar Arrow Board S/N: 5F12S1614M005001 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Lake Worth, TX
		7331	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006322 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7332	2016 Wanco WTSP Solar Arrow Board S/N: 5F11S1016G1006319 C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available	7342	Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7333	Asset located in: Humble, TX  2015 Wanco WTMMB Solar Arrow Board S/N: 5F12S161XF1000503 C/W: LED Lighting, Electric Winch Raise and Lower, S/A Trailer, Lunette Ring Usage: Not Available Asset located in: Lake Worth, TX	7343	Quantity of (250) 2024 HUNTER PRO C-75 Traffic Cones Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7334	Truck Mount Arrow Board S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7344	Quantity of (250) 2024 Agriquip GL28TC Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7335	Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Rack		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7336	Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (74) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused)	7345	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Lake Worth, TX		Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available
7337	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	7347	Asset located in: Lake Worth, TX  Quantity of (250) Traffic Cones (Unused)  S/N: Not Available  C/W: One Pallet  Usage: Not Available  Asset located in: Lake Worth, TX
7338	Quantity of (40) 4 Ft x 7 Ft 6 In Crowd Panels Barrier (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	7348	Quantity of (250) Traffic Cones (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7339	Quantity of (50) Traffic Barrier S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7349	Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7340	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7341	2024 HUNTER PRO C-75 29 in Traffic Cones (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7350	7359  Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7359	2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82442 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
		7360	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005579 C/W: 120V Pump, 13 ft Hose, Fuel Meter, Auto Nozzle, Spill Containment
7351	2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7361	2024 4-Fuel.com 4F2330 Gal Skid Mounted Diesel Fuel Tank (Unused)
7352	2024 HUNTER PRO RB-100 Traffic Control Device (Unused) S/N: Not Available Usage: Not Available		S/N: 000005580 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	7362	2024 4-Fuel.com 4F1100 Gal Skid Mounted
7353	Quantity of (100) 2024 HUNTER PRO RB-100 Traffic Delineators & Bases (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX		Diesel Fuel Tank (Unused) S/N: 000005581 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX
7354	Quantity of (100) 2024 HUNTER PRO RB-100 Traffic Delineators & Bases (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available	7363	2000 gal Steel Gasoline Fuel Tank S/N: ST5376 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7355	Asset located in: Lake Worth, TX  Quantity of (130) Traffic Barrels	7364	2000 gal Steel Diesel Fuel Tank S/N: ST5384
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7356	Quantity of (13) 7 Ft x 4 Ft Crowd Control Barriers S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7365	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000364 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
7357	2008 Milstead 4000 gal Skid Mounted Steel Fuel Tank S/N: 1818-C881958 Usage: Not Available Asset located in: Lake Worth, TX	7366	1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000427 C/W: Spill Containment Usage: Not Available
7358	2024 AM Tank 2300N 2376 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82443 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7367	Asset located in: Lake Worth, TX  2000 gal Skid Mounted Steel Single Wall Fuel Tank  S/N: ORP2000468  C/W: Spill Containment Usage: Not Available  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7368	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000343 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7377	750 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Asset located in: Lake Worth, TX
7369	1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000313 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7378	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82446 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
7370	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000310 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7379	2024 AM Tank 600 655 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82447 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment
7371	2000 gal Skid Mounted Steel Single Wall Fuel Tank		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: ORT2000127 C/W: Spill Containment Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7380	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005289 Usage: Not Available Asset located in: Lake Worth, TX
7372	1000 gal Skid Mounted Steel Single Wall Fuel Tank S/N: ORT1000350 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7381	1000 gal Skid Mounted Steel Fuel Tank S/N: ORT1000332 C/W: Spill Containment Usage: Not Available Asset located in: Lake Worth, TX
7373	2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82445 C/W: 120 V Transfer Pump, Fuel Meter,	7382	<b>500 gal Skid Mounted Steel Fuel Tank</b> S/N: ORT5005280 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7974	Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7383	500 gal Skid Mounted Steel Fuel Tank S/N: ORT5005362 Usage: Not Available
7374	2024 AM Tank 800 838 gal Skid Mounted Steel Fuel Tank (Unused) S/N: 82444 C/W: 120 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Lake Worth, TX	7384	Asset located in: Lake Worth, TX  Morrison Bros Co. FTBDS-0500 Skid Mounted Steel Unknown Contents Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX
7375	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005582 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment	7385	300 gal Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	7386	Wen Industries Diesel Buggy Portable Steel
7376	2024 4-Fuel.com 4F838 Gal Skid Mounted Diesel Fuel Tank (Unused) S/N: 000005583 C/W: 120V pump, 13 ft hose, fuel meter, auto nozzle, spill containment Usage: Not Available Asset located in: Lake Worth, TX		Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7387	2024 AM Tank 116 gal Portable Poly Tank (Unused) S/N: 57066L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7394	Fuel Tank (Unused)  S/N: Not Available  C/W: 12 V Transfer Pump, THE PRODUCT  IMAGES SHOWN ARE FOR ILLUSTRATION  PURPOSES ONLY AND MAY NOT BE AN  EXACT REPRESENTATION OF THE ACTUAL
7388	2024 AM Tank 116 gal Portable Poly Tank (Unused)		PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 57067L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7395	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION
7389	2024 AM Tank 116 116 gal Portable Poly Fuel Tank (Unused) S/N: 57068L C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle		PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	7396	2022 Teran TDT116GL 116 gal Fuel Tank
7390	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005586 C/W: 12 v transfer pump, 13 ft hose, auto- nozzle, for PICK-UP trucks Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: 46570L C/W: Polyethylene tank for diesel fuel transport equipped with a fuel transfer unit, 116 gal with 12V Pump (12GPM), 13ft Hose, Auto-Nozzle, Top Covering Lid. Usage: Not Available Asset located in: Lake Worth, TX
7391	2024 4-Fuel.com 4F116 Gal Portable Poly	7397	Quantity of (2) 100 gal Steel Diesel Fuel Tank
7331	Diesel Fuel Tank (Unused)  S/N: 000005584  C/W: 12 v transfer pump, 13 ft hose, autonozzle, for PICK-UP trucks Usage: Not Available	CONSTRUCTION Usage: Not Available	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	Asset located in: Lake Worth, TX	7398	DeeZee 92 gal Steel Diesel Fuel Tank
7392	2024 4-Fuel.com 4F116 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005585 C/W: 12 v transfer pump, 13 ft hose, auto-		S/N: Not Available C/W: DEEZEE tool box; EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX
	nozzle, for PICK-UP trucks Usage: Not Available	7399	DeeZee 92 gal Portable Steel Diesel Fuel Tank
	Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available
7393	2024 Agriquip GLDP480 116 gal Portable Poly Fuel Tank (Unused)  S/N: Not Available  C/W: 12 V Transfer Pump, THE PRODUCT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7400	DeeZee 92 gal Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Midland, TX
		7401	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX

Lot #	Details	Lot #	Details
7402	Weather Guard 92 gal Steel Diesel Fuel Tank S/N: 1915613344 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7410	Quantity of Steel Truck Bed Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE
7403	DeeZee 92 gal Steel Diesel Fuel Tank S/N: Not Available		PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX
	C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7411	Steel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7404	<b>DeeZee 92 gal Portable Steel Diesel Fuel Tank</b> S/N: Not Available C/W: 12 V Transfer Pump, 11 ft Hose Usage: Not Available		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7412	<b>2024 AM Tank 58 gal Portable Poly Tank</b> (Unused) S/N: 57172A
7405	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available	7413	C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		2024 AM Tank 58 58 gal Portable Poly Fuel Tank (Unused) S/N: 57170A
7406	DeeZee 92 gallon Portable Steel Diesel Fuel Tank S/N: Not Available Usage: Not Available		C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	7414	<b>2024 AM Tank 58 gal Portable Poly Tank (Unused)</b> S/N: 57171A C/W: 12 V Transfer Pump, 13 ft Hose,
7407	Quantity of (7) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Automatic Shut-Off Nozzle Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Corsicana, TX	7415	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused)
7408	Quantity of (3) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		S/N: 000005593 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Corsicana, TX	7416	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel
7409	Quantity of (2) Steel Diesel Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Fuel Tank (Unused) S/N: 000005591 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX	7417	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel
		/41/	Fuel Tank (Unused) S/N: 000005592

S/N: 000005592 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7418	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005590 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7426 7427	Quantity of (3) 100 Gal Transfer Fuel Tanks S/N: Not Available C/W: (2) L-Shaped, (1) Rectangle Usage: Not Available Asset located in: Lake Worth, TX Skid Mounted Steel Fuel Tank
7419	· · · · · · · · · · · · · · · · · · ·		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Humble, TX
	S/N: 000005589 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7428	2000 gal Steel Gasoline Tank S/N: ST5369 C/W: 12 V Transfer Pump, Fuel Meter, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7420	2024 4-Fuel.com 4F58 Gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005588		Notes: . Asset located in: Lake Worth, TX
	C/W: 12 v transfer pump, 13 ft hose, auto- nozzle Usage: Not Available Asset located in: Lake Worth, TX	7429	2000 gal Steel Oil Tank S/N: ST5383 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7421	2013 Transcube 30TCG 792 gal Skid Mounted Steel Fuel Tank S/N: D871188 C/W: 12 V Transfer Pump Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7430	2000 gal Steel Coolant Tank S/N: ST5374 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM US-AUTO-RECYCLING Usage: Not Available
7422	2024 AM Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 15160E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7431	Asset located in: Lake Worth, TX  300 gal Steel Windshield Wash Tank S/N: ST5329 C/W: 12 V Transfer Pump, Fuel Meter, Automatic Shut-Off Nozzle, EQUIPMENT-FROM US-AUTO-RECYCLING Usage: Not Available Notes: .
7423	2024 AM Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 15158E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX	7432	Asset located in: Lake Worth, TX  2024 AM Tank 29 gal Portable Poly NH3 Tank (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7424	2016 Transcube 20TCG 528 gal Skid Mounted Steel Fuel Tank S/N: A61281755 C/W: 12 V Transfer Pump Usage: Not Available	7433	2024 AM Tank AM-SPRAYER 14 14 gal Portable Poly NH3 Tank (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7425	Notes: . Asset located in: Lake Worth, TX  Fuel Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	7434	2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15159E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7435	2024 AM Tank 29 gal Portable Poly Tank (Unused) S/N: 15157E C/W: 12 V Transfer Pump, 10 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	7444	2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused) S/N: Not Available C/W: 49 ft Hose Reel, 12v DC, 10 gpm Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7445	Quantity of (2) Fuel Boss 12 V DC Fuel Pump
7436	Ace Roto-Mold 300 gal Poly Holding Tank S/N: LP00300BHSS Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7437	Steel Hydraulic Tank S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Quantity of (2) Fuel Boss 12 v Fuel Pump S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Corsicana, TX	7447	Fuel Boss 1 in Hose Reel W/ 110 V Pump, 50 ft. Deliver Hose Fuel Pump
7439	2024 Agriquip GLDP20 Fuel Pump (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7448	S/N: Not Available C/W: Fuel Pump Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX		2012 IMT 30/217 Truck Mounted Boom S/N: 771397 C/W: 54 ft reach, 5 section knuckle boom, 3 pallets of hydraulic fluid tank, stabilizers, re
7440	2024 GLDP20 12V Diesel Transfer Fuel Pump (Unused) S/N: Not Available	7449	bumper Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX		<b>Knapheide 8 Ft Flatbed</b> S/N: Not Available Usage: Not Available
7441	2024 Agriquip GLDP20 Fuel Pump (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7450	Caseco MM225 11 Ft Service Body S/N: 70628170 C/W: Auto Crane 6406H 6000 LB Crane Usage: Not Available Asset located in: Lake Worth, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7451	2024 F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-COMPANY
7442	Quantity of (2) 2024 Agriquip GLGP20 Fuel Pump (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Hose, Nozzle THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7452	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
7443	Asset located in: Lake Worth, TX  2024 Landhonor LHR-DFP10 Transfer Diesel Fuel Pump (Unused)  S/N: Not Available C/W: 49 ft Hose Reel, 12v DC, 10 gpm	7453	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7454	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	7464	Quantity of (4) Freightliner Fuel Tanks S/N: Not Available C/W: 100 gal Aluminum Usage: Not Available Asset located in: Lake Worth, TX
7455	Asset located in: Lake Worth, TX  F250 & F350 Truck Box  S/N: Not Available  C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY  Usage: Not Available  Asset located in: Lake Worth, TX	<b>7465</b>	Quantity of (4) Freightliner Fuel Tanks; (2) Tanks-100gal, (1)-120gal, (1) Unknown - Fits Truck S/N: Not Available C/W: Aluminum Usage: Not Available Asset located in: Lake Worth, TX
7456	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	7466	Quantity of Truck Parts S/N: Not Available C/W: Mud Flaps, Belts, Filter, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7457	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available	7467	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7458	Asset located in: Lake Worth, TX  F250 & F350 Truck Box  S/N: Not Available  C/W: EQUIPMENT-FROM-A-PRIMORIS-	7468	HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		HTM Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available
7459	F250 & F350 Truck Box S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	7470	Asset located in: Lake Worth, TX  Liftmore 3200REE Service Crane S/N: 10-1123W106 Usage: Not Available Asset located in: Lake Worth, TX
7460	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available Asset located in: Lake Worth, TX	7471 	Aerzen GMB 16.F13-12 Blower S/N: 830564 Usage: Not Available Asset located in: Lake Worth, TX Palfinger PK15500 Knuckleboom Crane
7461	L-Shaped Transfer Tank S/N: Not Available C/W: Fill Rite 12 v pump Usage: Not Available		S/N: 100052586 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7462	Asset located in: Lake Worth, TX  Quantity of (25) Hendrickson S-34446-L Brake Chambers	7473	HMT Model 5 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7474	Quantity of (4) Seats & (2) Consoles S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7463	Quantity of (2) Pallets of Trailer sub frame complete assembly S/N: 2017045964 C/W: Steel Usage: Not Available Asset located in: Lake Worth, TX	7475	Asset located in: Lake Worth, TX  Quantity of Truck Toolbox & Ladder Rack S/N: Not Available C/W: Rawson Koenig tool box Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7476	Quantity of (2) Pallets of Dock Bumper (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7488	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7477	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 256 Usage: Not Available Asset located in: Lake Worth, TX	7489	Asset located in: Corsicana, TX  Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T
7478	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 260 Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX
7479	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 255 Usage: Not Available Asset located in: Lake Worth, TX	7490	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7480	<b>2024 Neks Fifth Wheel Wrecker (Unused)</b> S/N: 259 Usage: Not Available		Usage: Not Available Asset located in: Corsicana, TX
<b>7481</b>	Asset located in: Lake Worth, TX  ProTech Aluminum Headache Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING	7491	Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX		Cat Truck Dump Body S/N: Not Available C/W: Steel, To Fit Cat 745C, 19 ft Body Length
7482	Truck Hood S/N: Not Available C/W: Fiberglass, To Fit Peterbilt		Usage: Not Available Asset located in: Lake Worth, TX Cot To Fit CAT 745 Truck Dump Body
	Usage: Not Available  Asset located in: Lake Worth, TX	7493	Cat To Fit CAT 745 Truck Dump Body S/N: Not Available Usage: Not Available
7484	Peterbilt Truck Cab S/N: 67741 Usage: Not Available Asset located in: Lake Worth, TX	7494	Asset located in: Lake Worth, TX  John Deere To Fit Deere 410E Truck Dump Body S/N: Not Available
7485	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX	7495	Cat To Fit CAT 740B Truck Dump Body S/N: Not Available C/W: Lift Cylinders, Tailgate Usage: Not Available Asset located in: Lake Worth, TX
7486	Cat Cab - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7497	Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7487	Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7498	Quantity of (2) Transmission S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7509	Quantity of (2) Aluminum Fuel Tanks - Fits Freightliner Cascadia S/N: Not Available C/W: (1) 150 Gallon & (1) 125 Gallon Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7510	Detroit DD15AT Engine
7499	Asset located in: Corsicana, TX  2012 Hanco 20 ft Flatbed  S/N: 107585	1	S/N: Not Available C/W: 6 Cylinder 505 hp 14.8 L Diesel Engine Usage: Not Available
	C/W: 2 storage boxes Usage: Not Available Asset located in: Lake Worth, TX	7511	Asset located in: Lake Worth, TX  Quantity of (12) 22.5 Rims  S/N: Not Available
7500	Cat Radiator - Fits Truck S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		C/W: (9) Aluminum, (3) Steel, One Pallet Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7512	Quantity of (12) 24.5 In Steel Rims S/N: Not Available C/W: One Pallet Usage: Not Available
7501	<b>Quantity of Quarter Fenders</b> S/N: 50567		Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Humble, TX	7513	Quantity of (16) 22.5 In Aluminum Rims S/N: Not Available C/W: One Pallet
7502	Hood S/N: Not Available C/W: To Fit Hood	7515	Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX		International DT466 Engine with Spicer Transmission S/N: Not Available
7503	Thermaflow Wet Kit S/N: Not Available C/W: Hoses, PTO, One Pallet		Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	7516	hood to fit - Peterbilt 387 S/N: Not Available C/W: To Fit Peterbilt 387 Hood
7504	Quantity of (16) 22.5 Aluminum Rims S/N: Not Available C/W: One Pallet		Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Lake Worth, TX	7517	7517 Quantity of (2) Air ride seats S/N: Not Available Usage: Not Available
7505	<b>Quantity of (27) Brake chambers</b> S/N: Not Available		Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	<b>7526</b>	Quantity of (6) Truck Toolboxes  S/N: Not Available
7506	Quantity of (2) Paccar 75 &100 gal 24.5 in dia Fuel Tanks (Unused) S/N: K424-0457N0102K075 Usage: Not Available Asset located in: Lake Worth, TX		C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7507	Volvo D13H Engine S/N: Not Available C/W: 6 Cylinder 425 hp Diesel Engine Usage: Not Available	7527	Asset located in: Corsicana, TX  Truck Toolbox  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS-
7508	Asset located in: Lake Worth, TX  Quantity of (6) 19.5 steel rims (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7528	Quantity of (3) Truck Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7534	Quantity of (2) ProTech Truck Tractor Tool Box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7529	Truck Toolbox	7557	Truck Flatbed Body
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7530	Quantity of (3) Truck Tool Boxes	7573	Synder Tank Corp Truck Fuel Tank
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
 7531	Truck Tractor Tool Box	7574	Quantity of (2) CNG Fuel Tanks
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7374	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7532	Merritt Saddle Box Truck Tractor Tool Box	7575	Quantity of Truck Fuel Tanks
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7533	Quantity of (2) Merritt Saddle Box Truck	7576	Wet Kit Pump and Hydraulic Tank
	Tractor Tool Boxes S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
7577	Water Pump Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7596	Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX	7597	Quantity of (6) PowerTrain PTG2500XCS Engine (Unused) S/N: Not Available	
7578	Truck Blower Parts S/N: Not Available		C/W: Gasoline Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	C/W: EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7598	Quantity of (6) PTTP300 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
7579	Asset located in: Corsicana, TX  Drive Axle S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	<b>—</b> 7599	Quantity of (6) PTWP400 Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
7580	4.10 Axle S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7600	Detroit 50435001 DD 453 Engine S/N: 4D0131900 C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX	7601	Isuzu Engine S/N: Not Available C/W: 4 Cylinder Diesel Engine Usage: Not Available	
7591A	Etnyre Lowboy Stinger S/N: 30149-2 Usage: Not Available	7602	Asset located in: Lake Worth, TX  7602 1996 Cat 3406E Engine S/N: 5EK38572	1996 Cat 3406E Engine
7592	Asset located in: Lake Worth, TX  Tag Axle S/N: Not Available		C/W: 6 Cylinder Diesel Engine Usage: Not Available  Asset located in: Lake Worth, TX	
	C/W: Air Ride Suspension, 11R22.5, Aluminum Rims Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7603	Cummins N14 Engine S/N: 11849308 C/W: 6 Cylinder Diesel Engine Usage: Not Available	
7593	Cat 3306 Engine		Asset located in: Lake Worth, TX	
	S/N: 08Z32520 C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX	7604	BMW Engine S/N: Not Available C/W: 6 Cylinder Gasoline Engine, EQUIPMENT- FROM-NATAINS-CONSTRUCTION	
7594	Quantity of (6) PowerTrain PT240 Engine S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available		Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	
	Notes: .		Asset located in: Corsicana, TX	
7595	Asset located in: Lake Worth, TX  Quantity of (6) 2.4 HP General Purpose Engine S/N: Not Available C/W: Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7605	19 In x 71 In Loading Ramps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7606	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX	7615	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7607	Quantity of (4) Salvation Trailers Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX	7616	Asset located in: Corsicana, TX  Quantity of hydraulic hoses Hydraulic Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7608	Quantity of (4) Salvation Trailers (4)Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX	7617	Quantity of (9) 11R24.5 Tires  S/N: Not Available  C/W: All Tires with Wheels  Usage: Not Available  Asset located in: Lake Worth, TX
7609	Quantity of (4) Salvation Trailers (4) Heavy Duty Metal Trailer Ramps (Unused) S/N: Not Available C/W: Steel, 6 ft 6 in Body Length Usage: Not Available	7618 7619	Alliance 700/40-22.5 Flotation Tire S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (2) 480/80R42 Tires
7610	Asset located in: Lake Worth, TX  Quantity of (4) Salvation Trailers (4) Heavy  Duty Metal Trailer Ramps (Unused)  S/N: Not Available		S/N: Not Available C/W: All Tires with Wheels Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7611	C/W: Steel, 6 ft 6 in Body Length Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (3) Mercury Boat Engine	7620	Quantity of (2) 1300x530x508 Tires S/N: Not Available C/W: Some Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX
7612	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T	7621	Quantity of (2) Hubs & Tires S/N: Not Available C/W: 18x8.50x10 Usage: Not Available Asset located in: Lake Worth, TX
7610	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7622	Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7613	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7623	Quantity of John Bean Tire Balancer & Tire Changer S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7614	Quantity of Cat Hydraulic Blade Lift Cylinders - Fits Cat D6R/D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7624	Quantity of (32) 235x80x16 10 Ply Radial Trailer Tires on Dial Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7625	Quantity of (48) 205x75x15 Radial Tires & 5 Lug Wheels (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX	7636	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042601H C/W: 110V, 2 HP Electric Motor, Bead Blaster System Usage: Not Available Asset located in: Humble, TX	
7626 7627	Quantity of (4) 6-PLY RADIAL TIRE 5 ON 5 SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX Quantity of (4) 235/80R16 10-PLY RADIAL	7637	2024 Agriquip GLWB8100 Wheel Balancer (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	TRAILQUEST 16" 8-HOLE SILVER MODULAR WHEEL Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX	7638	Asset located in: Lake Worth, TX  2024 Agriquip GLWB8100 Wheel Balancer (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
7628	Quantity of (2) Armour 11.00-16 Tires S/N: Not Available C/W: All Tires with Wheels, EQUIPMENT-FROM- WATKINS-CONSTRUCTION		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		<ul> <li>2024 Agriquip GLWB8100 Wheel Balancer (Unused)</li> <li>S/N: Not Available</li> <li>C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND</li> </ul>	
7629	<b>2024 Agriquip GLTC24 Tire Changer (Unused)</b> S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7640	MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	Usage: Not Available
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
7630	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONL	Usage: Not Available
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX		Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100210	
7631	Quantity of (2) 2020 Weaver W-898XS Semi- Automatic Tire Changer		Usage: Not Available  Asset located in: Midland, TX	
	S/N: 820052876/820052872 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7642	Cuda H20-4860 Parts Washer - Fits CUDA H20- 4860 S/N: 10434450-100209 Usage: Not Available Asset located in: Midland, TX	
7635	Quantity of (2) Weaver W-898XS Semi Automatic Tire Changer S/N: 820052875/820052871 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7643	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050641 Usage: Not Available Asset located in: Lake Worth, TX	

	Details	Lot #	Details
7644	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050639 Usage: Not Available Asset located in: Lake Worth, TX	7652 7653	Quantity of (2) 2020 Weaver F12N300BBL 12000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
7645	ARI Hetra HDML8 Electric 15000 Lbs Vehicle Lift S/N: 01050640 Usage: Not Available		Notes: . Asset located in: Lake Worth, TX  Transmission Stand
7646	Asset located in: Lake Worth, TX  ARI Hetra HDML8 Electric 150000 Lbs Vehicle		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
	Lift S/N: 01050638 Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7647	2024 Agriquip GLTP4500 10000 lb Two-Post	Ī	Asset located in: Corsicana, TX
	Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	7654	Graco Grease Injection Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7648	2024 Agriquip GLTP4500 10000 lb Two-Post		Asset located in: Corsicana, TX
	Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7655	Quantity of (3) Bolt Bin S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7656	
7649	Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts		S/N: Not Available Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7657	Greenlee 24 In x 48 In Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7650	Quantity of (5) Weaver 10N000DWRD 10000 Lb 2 Post Auto Lifts	7659	2024 Landhero UBP-25-60 Universal Bucket
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7658	Pin (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7651	Quantity of (5) 2020 Weaver 10N000DWRD 10000 Lb 2 Post Vehicle Lift S/N: Not Available C/W: 2 Hp; EQUIPMENT-FROM-US-AUTO- RECYCLING		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PROPUGT
	Usage: Not Available		THE ACTUAL PRODUCT

Lot #	Details	Lot #	Details
7659	Quantity of 2024 Landhero UBP-65-80 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 65 mm x 475 mm & (4) 70 mm x 475 mm & (4) 80 mm x 550 mm, ; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE	7666	Master MH190T-KFA 190000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
		7667	Quantity of (4) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7660	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7668	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7660	2024 Landhero UBP-90-100 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 90 mm x 650 mm, (2)100 mm x 750 mm, ;THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7669	Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	7670	Quantity of Parts & Tools S/N: Not Available C/W: Bosch Drill, Wrenches, Wheels, One Palle Usage: Not Available Asset located in: Lake Worth, TX
		7671	NVE 607 Challenger Vacuum Pump S/N: 36777 Usage: Not Available Asset located in: Lake Worth, TX
7661	Quantity of Engines and Generators S/N: Not Available		
7662	Usage: Not Available Asset located in: Lake Worth, TX  Excavator Parts	7672	Quantity of Hydraulic Pump & Crusher Blades S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX		Asset located in: Lake Worth, TX  Quantity of Contractor Supplies  S/N: Not Available  C/W: Hose, Poulan Pro Chain Saw, One Pallet Usage: Not Available  Asset located in: Lake Worth, TX
7663	Quantity of Parts & Tools S/N: Not Available C/W: (2) Seats, Mud Flap, Sockets, Barbed Wire, (2) Pallets Usage: Not Available	7674	Quantity of Truck Parts S/N: Not Available C/W: Exhausts/Pipes, Headlights Usage: Not Available Asset located in: Lake Worth, TX
7664	Asset located in: Lake Worth, TX  Pro Tech Aluminum Headache Rack S/N: Not Available	7675	Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7665	Usage: Not Available Asset located in: Lake Worth, TX  Quantity of PVC Fittings  S/N: Not Available	7676	S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7677	Asset located in: Lake Worth, TX  Quantity of (2) Pallets of 5 In Water Hose S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7678	Quantity of Sheet Metal Parts S/N: Not Available C/W: assorted size & type Usage: Not Available Asset located in: Lake Worth, TX	7687	Quantity of Parts - Fits Chevrolet 3500 HD 6.0L S/N: Not Available C/W: Intake, Transfer Case, Wiring Harness Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST
7679	Quantity of (2) Hydraulic Pumps S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7680	25' Steel Floor Ramp (Unused)		Asset located in: Lahoma, OK
	S/N: Not Available C/W: 25'x101" Loading ramp, 12"x14Lbs I- beam frame, 6" channel in the middle, 3" Channel crossmembers, Smooth plate floor with expanded metal welded on, 18' long angled ramp with 7' flat surface, 3-10K adjustable jacks. Usage: Not Available	7688	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Asset located in: Lake Worth, TX	7689	Quantity of Parts
7681	Quantity of Parts S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX
7682	Quantity of (2) Zato Hydraulic Pumps S/N: Not Available C/W: Linde HPV280; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7690	Crawler tractor drive motor teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7683	Quantity of (2) Schaeffler Roller Bearings S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7691	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7684	Star Industries 1210 4 ft x 8 ft Work Platform S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7692	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7685	JLG 3248RS Parts S/N: Not Available		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	C/W: Deck, Boom Arms, Cylinders Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7693	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-
7686	Skyjack SJ8841 RT Parts S/N: Not Available C/W: Deck, Tires, Outriggers, Hyd Cylinders,		CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	Transfer Case, Drive Shaft, Engine, Fuel & Hydraulic Tank Box	7694	Quantity of (2) Pallets of Bucket teeth
	Usage: Not Available  Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		7695	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7696	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7705	705 Quantity of (4) Teran 1066878 Bucket Pins (Unused) - Fits Cat 315 S/N: Not Available C/W: 70mm X 508mm for Komatsu PC160 Front & Rear - 315 Linkage Usage: Not Available
7697	Quantity of Parts		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX	7706	Quantity of (2) Teran 2357636 Bucket Pins (Unused) - Fits Cat 349  S/N: Not Available C/W: 110mm X 705mm (Long total W/Flange) TB Linkage Front for Cat 345,345C,336DL,
7698	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE, 340FL, 340FLLRE, 336FLNXE, 336FL, 336DLN, 336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH,
7699	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	330DMH, 324DL, 336FLXE, 3 336FXE, 336F, 349F, 352FXE Usage: Not Available Asset located in: Lake Worth  7707 Quantity of (2) Teran 235764 (Unused) - Fits Cat 349 S/N: Not Available C/W: 100mm X 695mm (Lon TB Linkage Rear for Cat 345, 352FVG, 349DL, 330D, 349EL 345DLVG, 349DL, 330D, 349EL 349EL, 330DL, 345DL, 349FL 340FL, 340FLLRE, 336FLNXE 336ELN, 336D2LXE, 336FLNXE 336ELN, 349FL, 345BIIL, 329DL 336D2GC, 345BL, 352F2VG, 3 330DMH, 324DL, 336FLXE, 3 336FXE, 336F, 349F, 352FXE Usage: Not Available Asset located in: Lake Worth  7708 Quantity of (2) Teran 251255 (Unused) - Fits Cat 336D S/N: Not Available C/W: 100mm X 640mm (Lon	330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available
	Usage: Not Available  Asset located in: Corsicana, TX		Quantity of (2) Teran 2357642 Bucket Pins
7700	Quantity of (2) Pallets of Bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		(Unused) - Fits Cat 349 S/N: Not Available C/W: 100mm X 695mm (Long total W/Flange) TB Linkage Rear for Cat 345,345C,336DL, 352FVG, 349DL, 330D, 349ELVG, 330DLN, 345DLVG, 349D2, 324D, 349DLVG, 336D2L, 349EL, 330DL, 345DL, 349FLXE, 336D2XE,
7701	Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Lake Worth, TX		336ELN, 336D2LXE, 336FLN, 336D2, 349D2L, 336EL, 349D, 336E, 345D, 330CL, 336D, 345BII, 349E, 349FL, 345BIIL, 329DLN, 340D2L, 340DL, 336D2GC, 345BL, 352F2VG, 329DL, 336FLH, 330DMH, 324DL, 336FLXE, 352FXEVG, 336FXE, 336F, 349F, 352FXE, 340F Usage: Not Available
7702	Quantity of (4) Teran 0860523 Bucket Pins		Asset located in: Lake Worth, TX
	(Unused) - Fits Cat 311/314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Lake Worth, TX		
7703	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available Asset located in: Lake Worth, TX		385CL, 336FLN, 340FL, 329DL, 324D, 325DL, 329EL, 336FLNXE, 324DL, 330FLN, 336EL, 330FL, 324ELN, 385COEM, 329D2L, 326D2, 326FL, 349ELVG, 336FLXE, 340D2L, 324DLN, 326D2L, 329DLN, 349EL, 325DLOEM, 336E, 385C, 336FL, 340DL, 325DLN, 329FL, 324EL, 329D2, 336ELH, 324E, 329E, 325D, 336EHVGOEM, 336EH, 336ELN, 329D, 326DL,
7704	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available Asset located in: Lake Worth, TX		345CLVG, 336ELNH, 336EOEM, 329ELN, 345CLVG, 336ELNH, 336EOEM, 329ELN, 326FLN, 336FLH, 340FLLRE, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7709	Quantity of (2) Teran 2512558 Bucket Pins (Unused) - Fits Cat 336D  S/N: Not Available C/W: 90mm X 635mm (Long total W/Flange) DB Linkage Rear for Cat 336D,330D,324E, 336ELH, 325D, 329E, 336FL, 325DLOEM, 330FL, 329DLN, 336EL, 336EH, 336ELN, 336EHVGOEM, 330CL, 324DL, 340FLLRE, 325DL, 324EL, 336FLXE, 329ELN, 385COEM, 329EL, 324ELN, 329D2L, 326D2, 329DL, 326FL, 340D2L, 326D2L, 324DLN, 324D, 336FLN, 336E, 385C, 340DL, 385CL, 325DLN, 329FL, 340FL, 329D2, 336FLNXE, 330FLN, 329D,	7716	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
		7717	Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
	326DL, 345CLVG, 336ELNH, 336EOEM, 326FLN, 336FLH, 340FUHD, 336FXE, 340F, 336F, 328DLCR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7718	Quantity of (2) Pallets of Bucket pins S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Library Not Available
7710	Quantity of (2) Teran 4I5015 Bucket Pins (Unused) - Fits Cat 330		Usage: Not Available <b>Asset located in</b> : Corsicana, TX
	S/N: Not Available C/W: 80mm X 735mm F Linkage for CAT 330,330B, 345B, 345C, 350, Usage: Not Available Asset located in: Lake Worth, TX	7719	Quantity of (2) Pallets of Misc. parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7711	Quantity of (4) Teran 7Y3549 Bucket Pins	7700	Asset located in: Corsicana, TX  Overtity of (2) Pollete of Exterior Sefety Poils
7712	(Unused) - Fits Cat 330 S/N: Not Available C/W: 80mm X 630mm D Linkage - Rear Usage: Not Available Asset located in: Lake Worth, TX	7720	Quantity of (2) Pallets of Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
//12	Quantity of (4) Teran 7Y3550 Bucket Pins (Unused) - Fits Cat 330		Asset located in: Corsicana, TX
	S/N: Not Available C/W: 90mm X 650mm D Linkage - Front Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7721	Quantity Of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7713	2003 American Compaction DC-18S 18 in		Asset located in: Corsicana, TX
	Backhoe Trench Wheel S/N: 4036094 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	7722	Quantity of Track Idlers - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7714	Excavator compartment doors - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7723	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7715	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7724	Quantity of (2) Excavator components box S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7725	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7734	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7726	Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7735	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7727	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7736	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7728	Hood - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7737	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7729	Shovel holders S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7738	Exterior Safety Rails - Fits Cat Dozer & Excavator S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7730	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7739	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7731	Quantity of (2) Pallets of Hand rails - Fits Cat S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7740	Quantity of (2) Pallets of Parts  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION  Usage: Not Available  Asset located in: Corsicana, TX
7732	Quantity of (2) Pallets of Trencher chain teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7741	Quantity of (3) Track idlers  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7733	Quantity Of Hydraulic Parts S/N: Not Available C/W: Hydraulic Hoses, Hydraulic Tank, Hydraulic Pump EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7742	Quantity of Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7743	Quantity of (2) Pallets of Crawler tractor parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7750	Quantity of Shredder Teeth (Unused) S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7744	Bucket Cutting Edges S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7751	Quantity of (2) Pallets of Shredder Teeth S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (6) Wheels - Fits Cat 740B
7745	Asset located in: Corsicana, TX  Track Idlers  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS-	7758	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7746	Dozer Sweeps - Fits Cat D6  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION  Usage: Not Available  Asset located in: Corsicana, TX	7760	Quantity of (2) Axles - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7747	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7761	Quantity of Exhaust Stacks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE
7748	Dozer Sweeps - Fits Cat D6 S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	7762	SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX  Quantity of Assorted Truck & Trailer Parts S/N: Not Available
7749	Usage: Not Available Asset located in: Corsicana, TX  Enclosed Cab & ROPS Structure - Fits Cat D6R / D6T  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		C/W: used tires, (3) Wheel barrows, air, fuel and hyd filters, banding machine, folding chairs, trash can, truck tractor seat, hyd hoses, mud flaps, brake pads, mirrors, a/c compressors, cat injectors, Denso Protal 7200 2 part resin, Black Beauty Abrasive, and misc parts Usage: Not Available  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE
7749A	Walking Beam - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
7749B	Middle & Front Frame - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7763	Quantity of (3) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION
7749C	Quantity of (2) Stair/Fender Assemblies - Fits Cat 740B S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7764	Quantity of Equipment and Vehicle Lights S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7770	Quantity of (4) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7765	Quantity of (3) Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7771	Quantity of Truck Side Panels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7766	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7772	Quantity of Truck Metal Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7767	Quantity of (2) 22.5 x 8.25 Rims S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7773	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7768	Quantity of 2 5/16 in Ball Hitches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7774	Quantity of Radiators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX
7769	Quantity of Mack Front Grills  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX	7775	Quantity of (2) 16 x 24 Rims  S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details
7776	Quantity of Truck Parts S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	7784	101 in x 25 Ft Loading Ramp S/N: Not Available C/W: 45,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX	7784A	X-STAR 40 ft x 100 in Bridge (Unused) S/N: Not Available C/W: 14,000 lb.
7777	Quantity of (2) Pallets of Hose Reels S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7785	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
7778	Quantity of Truck Tactor Cat Walks S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE	7786	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX	7787	101 in x 25 ft Bridge Platform Bridge S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber
7779	Quantity of Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-		Floor Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX	7788	101 in x 25 ft Bridge Platform Bridge - Fits xstal S/N: Not Available C/W: 14,000 lb Rated with 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
7780	Quantity of (5) Portable Electrical Distribution Boxes S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7789	101"x40' 14k Rated Bridge (Unused) S/N: Not Available C/W: 2x8 Treated Lumber Floor Usage: Not Available Asset located in: Lake Worth, TX
7781	Power Distribution Unit S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	7790	Quantity of (2) Stainless Steel Brewing Vats S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	7791	Quantity of (2) Workshop Work Table S/N: Not Available
7782	<b>Quantity of (8) Intertek Lighting Fixtures</b> S/N: Not Available Usage: Not Available		Usage: Not Available  Asset located in: Midland, TX
7783	Asset located in: Lake Worth, TX  Quantity of (2) Stantion 3 Ft x 12 Ft Truck Undercarriage Wash System  S/N: Not Available	7792	Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7793	Quantity of (3) Workshop Work Table S/N: Not Available Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
7794	Quantity of (3) 30 In x 42 In Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7802	Quantity of (4) 2024 4-Fuel.com PFFF-ARLHALTO Safety Cabinets (Unused) S/N: Not Available C/W: DIMENSIONS 78" H x 39" W x 17" D Usage: Not Available
7795	Quantity of (3) 30 In x 42 In Metal Tables		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7803	Quantity of Contractor Supplies S/N: Not Available C/W: Floor Jacks, Sockets, Bit Sets, Bottle Jack, Trolley Jack, Control Block, Trolley Jack, Trolley Jack, Control Block, Control Block, Trolley Jack, Control Block, Cont
7796	Quantity of (3) 31 In x 72 In Metal Shop Tables S/N: Not Available C/W: Wilton Vise ; EQUIPMENT-FROM-US- AUTO-RECYCLING		FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	7804	Quantity of (3) Pallets of Rolling Service Carts S/N: Not Available
7797	Quantity of (2) Metal Tables  S/N: Not Available  C/W: (1) 20.5 in x 60 in, (1) 30 in x 72 in;  EQUIPMENT-FROM-US-AUTO-RECYCLING		C/W: Uline, U.S. General, (11) Carts; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
	Usage: Not Available		Asset located in: Lake Worth, TX
7798	Asset located in: Lake Worth, TX  Quantity of (5) Shop Supplies  S/N: Not Available  C/W: Engine Hoist, Shop Fan, (2) Dollies,  EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available	7805	Quantity of (7) Pallets of Tools & Parts S/N: Not Available C/W: Hose, Assorted Parts, Electrical Supplies; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
7799	Quantity of (2) Hydraulic Hose Rack S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7807	Royal Gourmet 8 Burner Propane Grill S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7800	Quantity of (200) 2024 Suihe LCSS-200	7808	31.5 In Rubber Belt
	Corrugated Structural Steel (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7600	S/N: Not Available C/W: Blue Rack; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7809 2020 Weg W21 Electric Motor S/N: 1053815288 C/W: 315 KW, 3 Phase, 467 Amp FROM-US-AUTO-RECYCLING	S/N: 1053815288 C/W: 315 KW, 3 Phase, 467 Amp ; EQUIPMENT-
	Asset located in: Lake Worth, TX		FROM-US-AUTO-RECYCLING Usage: Not Available
7801	Quantity of (200) 2024 Suihe LCSS-200 Corrugated Structural Steel (Unused) S/N: Not Available		Notes: . Asset located in: Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7810	Blue Diamond 1 1/4 In Sch 40 HDPE Conduit S/N: Not Available C/W: One Spool Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		ASSEL IOCALEU III. LANE WOLLI, TA

Lot #	Details	Lot #	Details
7811	Quantity of (3) Pallets of Shop Fans S/N: Not Available C/W: (4) 42 in, (11) 24 in, (1) Air Mover; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7824	Quantity of (16) 48 In x 48 In Wheeled Drain Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7813	Quantity of (3) Pallets of Shop Supplies S/N: Not Available C/W: (1) Pallet of Banders & Strapping, (1) Pallet of Shop Vacs & Mop Kits, (1) Table W /Roadmags; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes:	7825	Quantity of (4) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7815	Asset located in: Lake Worth, TX  Quantity of (3) Pallets of  S/N: Not Available Usage: Not Available Notes: .  Asset located in: Lake Worth, TX	7826	GenMega G6000 Series ATM S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7817	Quantity of (5) Pallets of Parts & Tools S/N: Not Available C/W: Hose, Wire, Pumps, Bolt Bins/Racks; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7827	300 Gallon Air Tank S/N: Not Available C/W: Ingersoll Rand PSG30 Separator System; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7818	Quantity of (5) Hand Trucks S/N: Not Available C/W: (4) Martins 1000 lb capacity, one pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .	7828	20 ton Air Press S/N: 193562011 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7820	Asset located in: Lake Worth, TX  Quantity of (2) 30 In x 96 In Metal Tables  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes:	7830	Quantity of (4) 30 in x 96 in Metal Tables S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7822	Asset located in: Lake Worth, TX  Quantity of (3) Pallets of Belt Material  S/N: Not Available  C/W: Assorted Size/Type; EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes:	7831	Modular Cage System  S/N: Not Available C/W: Two Pallets; EQUIPMENT-FROM-US- AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7823	Asset located in: Lake Worth, TX  Quantity of (2) Pallets of Tools  S/N: Not Available  C/W: Wrenches, Sockets, Drills, Impacts;  EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes: .  Asset located in: Lake Worth, TX	7832	Quantity of Bolt Bins S/N: Not Available C/W: Contents, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7833	Quantity of (7) Pallets of Misc S/N: Not Available C/W: Air Tanks, Tables, Power Strips, Cables, Misc EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7844	Quantity of (3) Pallets of Misc Supplies S/N: Not Available C/W: (1) Pallet of Assorted Wire, (1) Pallet of Assorted Office Supplies, (1) Pallet of Chairs; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7835	47.25 In Rubber Belt S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7845	Quantity of (4) 30 In x 96 In Metal Tables  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes: .  Asset located in: Lake Worth, TX
7836 	47 In x 47 In Platform Scale S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX  Quantity of (3) Bundles of Cardboard Boxes	7846	Quantity of (3) Hopper Extensions  S/N: Not Available  C/W: (2) 69 In, (1) 74 In; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available  Notes: .  Asset located in: Lake Worth, TX
7839	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX		Quantity of (3) 4 Ft x 4 Ft Storage Boxes S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
	Quantity of (4) Misc Supplies  S/N: Not Available  C/W: (1) Pallet of Assorted Tools/Jacks, (1)  Pallet of Assorted Filters, (1) Pallet of Misc, (1)  Pallet of Assorted Parts/Fittings; EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes: .  Asset located in: Lake Worth, TX	7848	Asset located in: Lake Worth, TX  Quantity of (4) Metal Shop Tables S/N: Not Available C/W: (2) 30 In x 72 In, (1) 36 In x 72 In, vise, saw; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX
7841	Quantity of (2) Pallets of Misc Supplies S/N: Not Available C/W: Rakes/Shovels, Chains; EQUIPMENT- FROM-US-AUTO-RECYCLING Usage: Not Available Notes:	7849	Quantity of (5) Pallets of Assorted Filters S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7842	Asset located in: Lake Worth, TX  Quantity of (8) Trash Cans  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes: .  Asset located in: Lake Worth, TX	7850	36 In x 44 In Steel Storage Cabinet S/N: Not Available C/W: Contents ; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
7843	U. S. General 72 in 18-Drawer Workbench S/N: Not Available C/W: U.S. General 30 In Tech Cart; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7853	Quantity of (13) Pallets of Fluid Recovery Bay Protective Screens S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7855	Quantity of (3) Pallets of Parts, Mats & Trays S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	7865	Binks Pneumatic Paint Pot  S/N: 316637  C/W: Hose, Hood  Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE  Asset located in: Lahoma, OK  Carport Kit - 18 ft w x 21 ft L x 10 ft H (Unused)
7856	Quantity of Tool Bins & Cabinet S/N: Not Available C/W: (1) 36 In x 24 In x 78 In Cabinet W /Contents, Rolling Pegboard, Bolt Bins; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7866	
 7857	Notes: . Asset located in: Lake Worth, TX  Quantity of (10) Wen Industries 6 x 3 Ft Fluid		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7007	Drain Tables  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available  Notes: .	7867	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7858	Asset located in: Lake Worth, TX  Quantity of (2) Pallets of Warehouse Supplies S/N: Not Available C/W: Assorted Hose, Safety Supplies;	7868	Carport Kit - 24 ft W x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7869	Carport Kit - 18 ft w x 25 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7860	Modular Cage System S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	7870	Carport Kit - 12 ft w x 21 ft L x 10 ft H (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Notes: . Asset located in: Lake Worth, TX	7871	Quantity of Oils, Service Fluids S/N: Not Available
7862	Gates GC32TSI Crimper Machine S/N: TSI0980E21 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX		Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7863	JET JDP-15F 15" Drill Press S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING		Asset located in: Lahoma, OK
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX	7872	Quantity of (22) Wagner HPLV Paint Sprayer S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST
7864	Superwrap Taping Machine S/N: Not Available C/W: To Fit Superwrap Taping machine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WINOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
7873	Quantity of Air Hose & Accessories  S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7878	Napa, Carlyle 7916021A Engine Hoist S/N: Not Available C/W: To Fit Carlyle 7916021A Engine Hoist, With Spreader Bar Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
7874	Entry Steps		Asset located in: Lahoma, OK
	S/N: Not Available C/W: 36 in W, 18 in H Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7879	Napa, Carlyle 7917170A Transmission Jack S/N: Not Available C/W: To Fit Carlyle 7917170A Transmission Jack, 1 Ton Capacity Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
7875	Quantity of (3) Piusi 017945010 DEF Pump		NOT BE ABLE TO ASSIST WITH LOADING THESE
	S/N: Not Available C/W: Fits 55 Gal Drum		Asset located in: Lahoma, OK
	Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  Wheeler 4160 Pipe Threading Tripod S/N: Not Available C/W: Tools. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	7880	Graco Line Lazer IV Walk Behind Paint Striper S/N: Not Available C/W: 2008 US EPA Label, Honda 163 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX
		7881	Centech Battery Charger
7876			S/N: Not Available C/W: Shop-Vac, Oil Pump, Oil, Fencing Supplie Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WIL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	NOT BE ABLE TO ASSIST WITH LOADING THESE	7882	Quantity of Contractor Supplies
7877	sset located in: Lahoma, OK  apa, Carlyle 7915070B Engine Stand  (N: Not Available  (W: To Fit Carlyle 7915070B, Geared Rotation sage: Not Available  otes: ITEMS AT OFFSITE LOCATION MUST  E PICKED UP WITHIN 14 DAYS OF THE  UCTION (JANUARY 3RD) OR WILL BE  JBJECT TO 3RD PARTY STORAGE FEES;  JYER RESPONSIBLE FOR LOADOUT. RB WILL  OT BE ABLE TO ASSIST WITH LOADING  HESE		S/N: Not Available C/W: Vice, Extension Cords, Bolts, Pillow Block Bearings, Track Link for JOHN Deere 2106, Trailer Parts Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lahoma, OK	7883	Quantity of (3) Crates of PVC Fittings 4"-12" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7884	Quantity of Power Washers and Generators S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7894	Quantity of (8) Torque Wrenches S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7885	Quantity of Construction Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7895	shop tools S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX
7886	Quantity of Pressure Washer and Concrete Saw S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7896	Quantity of Vibratory Plate Compactor, Generator, Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7887	Quantity of Weed Eater, Tools, Sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7897	Asset located in: Corsicana, TX  Quantity of Parts  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7888	Misc. shop supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7898	Asset located in: Corsicana, TX  Quantity of Shop Tools  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7889	Quantity of Generators and Water Pumps S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7899	Asset located in: Corsicana, TX  Construction supplies  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7890	Quantity of (4) Airless paint sprayers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7900	Asset located in: Corsicana, TX  Quantity of Shop Supplies  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION  Usage: Not Available
7891	Construction supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7901	Asset located in: Corsicana, TX  Misc Supplies  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION  Usage: Not Available
7892	Generator, plate compactor, water pump S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	7902	Asset located in: Corsicana, TX  Misc. shop supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available
7893	mail box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Corsicana, TX

	Details	Lot #	Details
7903	construction supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7913	Quantity of (7) Pneumatic Concrete Breakers S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX
7904	Asset located in: Corsicana, TX  Quantity of Power Washers, Battery Charger, Air Compressor  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	<b></b> 7914	Quantity of Napa Oil Filters (Unused) S/N: Not Available C/W: Assorted Size/Type Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Corsicana, TX	7916	<b>100 Ft Galvanized Chain</b> S/N: Not Available Usage: Not Available
7905	Quantity of Shop Supplies S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS-	7917	Asset located in: Lake Worth, TX Scotsman C05305A-1E Ice Machine
	CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		S/N: 19051320014944 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
7906	Pipe sizers S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available	7918	Ice-O-Matic CIM0430FA Commercial Ice maker w/ collection bin S/N: 23011280011235 Usage: Not Available Asset located in: Lake Worth, TX
7907	Asset located in: Corsicana, TX  Quantity of chlorine recovery boxes  S/N: Not Available Usage: Not Available	7919	Comfortmaker NXA660GKA100 Air Conditioner S/N: E160802838 Usage: Not Available Asset located in: Lake Worth, TX
7908	Asset located in: Lake Worth, TX  SCBA packs S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7920	2020 H&S 410 S/A Running Gear S/N: 021SG10014 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
7909	FS400ASK oil skimmer S/N: A2968 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	7921	Asset located in: Humble, TX  Reelcraft Compressor Cart  S/N: Not Available  C/W: Hose Reel; EQUIPMENT-FROM-WATKINS-CONSTRUCTION
7910	misc firefighting accessories S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
7911	Miller Bobcat 225NT Stick Engine Driven Welder (Inoperable) S/N: KJ029548 C/W: Onan 2 Cylinder Gasoline Engine Usage: 763 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	7922	Asset located in: Corsicana, TX  Quantity of Assorted Shop Tools and Supplies (Inoperable)  S/N: Not Available  C/W: (1) Craftsman Weed Eater, (2)  Generators, (1) Pressure Washer, (5) Trash  Pumps, Ladders, Bolt Bin with Contents,  Pressure Washer and Air Hoses, Spill Kits,  Electrical Wire, Misc Shop Tools, Electrical  Supplies and Misc Shop/Warehouse Equipment  Usage: Not Available
7912	Quantity of Misc. wiring  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS-		Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;

Lot #	Details	Lot #	Details
7923	Haul Master 5-Ton Crane Hoist S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	7930 7931	Quantity of (4) Pallets of Chains and Clevises (Unused) S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (9) Thermal Arc Suitcase Welders S/N: Not Available C/W: One Pallet
7924	Quantity of Assorted Shop Tools and Parts		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Hammer Wrenches, 1 in Torque Wrenches, Micro Tester, Valves, Filing Cabinet, Shop Fan, Heavy Duty Rack, Brake Bands, Pipe Benders, Caulking Guns, Misc Shop Tools Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	7932 7933	Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: Bigfoot W/Fish Motif Usage: Not Available Asset located in: Lake Worth, TX  Big Daddy Targets Large AR500 Shooting Target (Unused) S/N: Not Available C/W: T-Rex Motif
7925	Quantity of Bolts	_	Usage: Not Available  Asset located in: Lake Worth, TX
,,,,	S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES	7934 7935	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Raccoons Motif Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Corsicana, TX		Big Daddy Targets Small AR500 Shooting
7926	Quantity of Metal Grating S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available		Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Corsicana, TX	7936	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Raccoons Motif
7927	Quantity of Safety Air Masks S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Tank Holders, Regulators Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7937	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available
7928	Suihe Mens/Womens Portable Restroom (Unused)		Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7938	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available
7929	Greatbear 2 Ton Magnetic Lifter & 5 Ton Scale (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: Birds & Turkey Motif Usage: Not Available  Asset located in: Lake Worth, TX
		7939	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7940	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX	7951	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		7952	Big Daddy Feeders 700 LB Solar Deer Feeder
7941	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif	7953	w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	/953	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused)
7942	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: Birds & Rabbits Motif Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7954	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available
7943	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: Coyote & Deer Motif Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7955	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available
7944	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Hogs & Sheep Motif Usage: Not Available Asset located in: Lake Worth, TX	7956	Big Daddy Feeders 700 LB Solar Deer Feede w/ Timer (Unused) S/N: Not Available
7945	Steel Shooting Target (Unused) S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Bigfoot Motif Usage: Not Available Asset located in: Lake Worth, TX	7957	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available
7946	Steel Shooting Target (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Gunfighter Motif Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7958	Big Daddy Feeders Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7947	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7959	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available
7948	Target (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	7960	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused)
7949	Target (Unused) S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Asset located in: Lake Worth, TX	7961	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused)
7950	Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7962 7963	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7971	Quantity of (5) Bundles of Panels 8 in x 34 in x 12 ft  S/N: Not Available C/W: One Stack Usage: Not Available Asset located in: Lake Worth, TX
	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7972	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7964	Big Daddy Targets Small AR500 Shooting Target (Unused) S/N: Not Available C/W: Birds & Rabbits Motif Usage: Not Available Asset located in: Lake Worth, TX	7973	Quantity of (2) Bundles of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7965	Big Daddy Fire Pits 30 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7974	Quantity of (1) Bundle of Cattle Fence Stay Lock 12.5-12.5 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7966	Big Daddy Fire Pits 30 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7975	Quantity of (2) Bundles Of Channels 4 in x 5.4 A36/529-50 20 ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
7967	Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7976	Manitowoc SY0324A Ice Machine S/N: 110558398 Usage: Not Available Asset located in: Lake Worth, TX
7968	Big Daddy Fire Pits 24 Inch. Decorative Metal Fire Pit (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	7977 	Manitowoc QY0454A Ice Machine S/N: 040262489 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
7969	Quantity of Sand Bags S/N: Not Available		Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE	7978	Dust Collector S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	7979	Park Indistries Fastback Electric Stone Polisher S/N: Not Available C/W: extensions Usage: Not Available Asset located in: Lake Worth, TX
7970	Quantity of (2) Bundles of 40 Ft Angle Iron S/N: Not Available C/W: (1) 1 1/2 In, (1) 2 In Usage: Not Available Asset located in: Lake Worth, TX	7980	Supershear Hydraulic Catalytic Converter Cutter S/N: 1411 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7981	Supershear Hydraulic Catalytic Converter Cutter S/N: 1409 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7990	Quantity of (3) Fuel Cans & (1) Lifting Strap S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
7982	Quantity of Conveyer Belts & Rollers S/N: Not Available C/W: (1) 10 In Belt, (1) 24 In Belt, (1) 47 In Vinyl, (3) 84 In Rollers; EQUIPMENT-FROM-US- AUTO-RECYCLING	7991	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
7983	Usage: Not Available Asset located in: Lake Worth, TX  Quantity of HWI MC25 Plus Fireclay Based Cement S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available		Quantity of (4) Gas Monitors  S/N: Not Available Usage: 5 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lake Worth, TX	_	Asset located in: Lahoma, OK
7984	Quantity of (8) Reelcraft HD76100 Hose Reels S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7992	Quantity of (10) Pallets of Shelving Guardrails & Accessories S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7985	Quantity of (3) Donaldson Torit MM1200		Asset located in: Lake Worth, TX
	Electric Mist Collectors  S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	7993	Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available
7987	Hillman 15 Ton Rollers S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	7994	Asset located in: Lake Worth, TX  Quantity of (2) Pallets of Reelcraft HD76100 Hose Reels S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
7988 	Quantity of (6) Pipe Racks S/N: Not Available C/W: Assorted Sizes Usage: Not Available Asset located in: Lake Worth, TX  Quantity of Contractor Supplies	7995	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Lockout Tags, Marking Paint, Measuring Wheel, Hitch Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	7996	Quantity of (2) Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase, (1) Koehring B150D, (1) Porta Heat 97 Usage: Not Available Asset located in: Lake Worth, TX
		7997	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7998 7999	Quantity of (2) Dayton 170000 BTU Space Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available Asset located in: Lake Worth, TX Quantity of (2) Dayton 170000 BTU Space	8007	10 ft x 10 ft Canopy S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
	Heater S/N: Not Available C/W: Kerosene Fueled, Single Phase Usage: Not Available		NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK  2017 Tennant T20 Ride-On Floor Sweeper
8000	Asset located in: Lake Worth, TX  Quantity of (10) Storage Crates  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	8010	S/N: T20-9225 C/W: 56 in Working Width, Water System, Rear Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 2,922 Hr Asset located in: Lake Worth, TX
8001	Asset located in: Lake Worth, TX  Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8011	2016 Tennant T20 Ride-On Floor Sweeper S/N: T20-6540 C/W: 48 in Working Width, Water System, Rear Squeegee, PSI 4 Cylinder 2.0 L Dual Fuel Engine Usage: 1,348 Hr Asset located in: Lake Worth, TX
8002	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8012	2015 Tennant T20 Ride-On Floor Sweeper S/N: T20-6442 C/W: 56 in Working Width, Water System, Rear Squeegee, Mitsubishi 4 Cylinder LPG Engine Usage: 566 Hr Asset located in: Lake Worth, TX
8003	Quantity of (10) Storage Crates S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX Quantity of (6) Storage Crates	8013	2019 Tennant M17 Ride-On Electric Floor Sweeper S/N: M17-11001 C/W: 52 in Working Width, Water System, Rear Squeegee, 36 Volt Operating System Usage: 4,574 Hr
8005	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX  Quantity (3) Commercial (Car Wash) Vacuum System	8014	Asset located in: Lake Worth, TX  2019 Tennant T17 Ride-On Floor Sweeper S/N: T17-13185 C/W: 44 in Working Width, 36 Volt Operating System Usage: 2,013 Hr
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Asset located in: Lake Worth, TX  2016 Tennant T17 Ride-On Electric Floor Sweeper
8006	Quantity of (5) Pallets of Generators & Pressure Washers S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac, Titan, North Star, Simpson, Ex-Cell, Mi-T-M, Power Ease Usage: Not Available Asset located in: Humble, TX		S/N: T17-11025 C/W: 44 in Working Width, Water System, 36 Volt Operating System Usage: 2,098 Hr <b>Asset located in</b> : Lake Worth, TX
		8016	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8017	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8026	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8018	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8027	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8019	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8028	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8020	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8029	Quantity of (25) 19 ft 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX
8021	Quantity of (16) 3-5/8 in Square Gauge 12 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8030	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8022	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8031	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8023	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8032	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8024	Quantity of (19) 2-7/8 in OD Schedule 10 Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8033	Quantity of (25) 2-3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8025	Quantity of (19) 2 7/8 In OD Pipe S/N: Not Available C/W: 21 ft, one bundle Usage: Not Available Asset located in: Lake Worth, TX	8034	Quantity of (25) 19 ft x 2 in x 2 3/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8035	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8044	Quantity of Safety Supplies S/N: Not Available C/W: (4) Fall Protection Harnesses Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
8036	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	8045	Quantity of Safety Supplies
8037	Quantity of (25) 20 ft x 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: Vests, Hard Hats, Safety Glasses, Latch Kits Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE
8038	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lake Worth, TX	8046	Quantity of Safety Supplies
8039	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused) S/N: Not Available C/W: (1) Bundle Usage: Not Available Asset located in: Lake Worth, TX	8047	S/N: Not Available C/W: Assorted Truck and Safety supplies Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WII NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
8040			
0041	Usage: Not Available  Asset located in: Lake Worth, TX		Quantity of Chain Construction Hoist S/N: Not Available Usage: Not Available
8041	Quantity of (25) 20 ft 2 in x 2 1/4 in Square 12 Gauge Steel Pipe (Unused)		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: (1) Bundle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8048	60 in x 565 ft Rubber Conveyor Belt S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8042		8049	<b>42 in x 570 ft Rubber Conveyor Belt</b> S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	8050	Bridgestone 60 in x 525 ft Conveyor Belt
8043	<b>Quantity of (2) Water Pumps</b> S/N: Not Available		S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
V	C/W: Diaphragm, (1) Wilden 2 In, (1) 2.5 In Water Pumps Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8051	32 in Discharge Conveyor Belt - Fits Vermeer Trencher S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX

Lot #	Details	Lot #	Details	
8052	Donzi 32 ft Wood Cabin Cruiser (Inoperable) w/ Trailer S/N: Not Available C/W: T/A Trailer, Ball Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	8061	2024 Paladin PLD-PSM31H 31 in Portable Sawmill (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
8054	Quantity of (2) 2020 Ludlum Radiation Detectors		THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	S/N: 348035 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - GEIGER COUNTER Asset located in: Lake Worth, TX	8062	2020 Mcintyre 600 HD Metal Shear S/N: 765 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth TY	
8055	Vortex Hydraulic Catalytic Converter Decanner S/N: Not Available C/W: 10 hp hydraulic power unit, 2014 P & J Dust Extraction LTD PJB175-4.8-8-1E2-1-JMC- 60 dust collector s/n 98468, work platform; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8063	Asset located in: Lake Worth, TX  2020 JET Electric Band Saw  S/N: 081337  C/W: 1 Hp Electric, .75 blade, Milwaukee 40 in work station; EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes:	
8056	Quantity of (3) 2021 Vortex PFS Gas De-	<u> </u>	Asset located in: Lake Worth, TX	
8057	Pollution Systems  S/N: 139/041  C/W: (2) Gas Tank Tower System Punch; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8064	2023 MMLJ DB500 Mobile System Sand Blaster S/N: 1M9BU1828PH774174 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9890 lb GVWR Usage: Not Available Notes: .	
803/	Quantity of (4) 2020 Vortex UHPC Fluid De- Pollution System Pump S/N: Not Available	8065	Asset located in: Midland, TX  2019 Allegro Ambient Air Pump Sand Blaster	
	C/W: 3 Fluid Distraction, oil, coolant, washer fluid; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available  Asset located in: Lake Worth, TX		S/N: 336581 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
8058	2008 Bosch 11304KD Demolition Breaker S/N: 889-000307 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8066	8066 Quantity of Assorted Steel Cable Cab S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION BE PICKED UP WITHIN 14 DAYS OF	Quantity of Assorted Steel Cable Cable S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE
8060	2024 Landhonor LHR-PSM26A 26 in Portable Sawmill (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	
THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN AR FOR ILLUSTRATION PURPOSES ONLY AND	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8067	Quantity of (6) Ladder S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	

Lot #	Details	Lot #	Details
8068	2014 Jungheinrich ECR327 6000 lb Electric Pallet Jack S/N: 82800864 C/W: 6000 lb Capacity, 24 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX Jungheinrich EJE120 Electric Pallet Jack	8077	S/N: Not Available C/W: (10) Pallets of 42 In x 25 Ft Uprights, (7 Pallets of 96 In Crossarms, (2) Pallets of 144 In Crossarms, (54) Pallets of 43 In x 46 In Wil Racks; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available <b>Notes</b> : .
	S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8078	Asset located in: Lake Worth, TX  Quantity of Uline 36 In x 72 In Shelving S/N: Not Available C/W: One Pallet; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available
8070	Toyota 8HBW23 4500 lb Electric Pallet Jack S/N: 8HBW2322023 C/W: 4500 lb Capacity, 24 V Usage: Not Available Asset located in: Lake Worth, TX	8079	Asset located in: Lake Worth, TX  Quantity of 2 3/8 In Pipe  S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8071	2012 Rico PWH-DD-300 Electric Pallet Jack S/N: R-14544 C/W: 30000 lb Capacity, 24 V, Battery Charger Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	8080	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8072	2008 Tempest PAL30 Electric Fan S/N: 6050820402234 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	8081	Quantity of 2 3/8 In Pipe S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8073	Asset located in: Lake Worth, TX  2008 Tempest PAL30 Electric Fan  S/N: 6030820400225  C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available	8082	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8074	Asset located in: Lake Worth, TX  Quantity of (3) 24 In Shop Fan  S/N: Not Available  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available	8083 8084	Quantity of 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (6) 5X4X11 GA Rectangle Tube
8075	Asset located in: Lake Worth, TX  Quantity of (2) J & D Mfg VPRF36 36 in Fan S/N: 0621 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available		17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8076	Asset located in: Lake Worth, TX  Quantity of (4) Pallets of 24 In x 72 In Pallet Racking  S/N: Not Available C/W: 24 In x 48 In Wire Racks, 96 In Crossarms; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: Asset located in: Lake Worth, TX	_ 8085	Quantity of (6) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8086	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8096	Quantity of (4) Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8087	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8097	Quantity of (8) Diamond Plate Steel S/N: Not Available C/W: Assorted Size Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (6) Diamond Plate Steel S/N: Not Available
8088	Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available	8099	C/W: Assorted Size Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (3) Diamond Plate S/N: Not Available
8089	Asset located in: Lake Worth, TX  Quantity of (9) 5 X 4 X 11 GA Rectangle Tube 17 ft		C/W: Assorted Size, One Bundle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: Not Available C/W: One Bundle Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8100	Quantity of (2) 8GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available
8090	Quantity of (6) 5 X 4 X 11 GA Rectangle Tube 17 ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8101	Asset located in: Lake Worth, TX  Quantity of (8) 10 GA Steel Plate  S/N: Not Available  C/W: One Bundle  Usage: Not Available  Asset located in: Lake Worth, TX
8091	Quantity of (9) 5X4X11 GA Rectangle Tube 17Ft S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8102	Quantity of (7) 10GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8092	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available Asset located in: Lake Worth, TX	<b>8103</b>	Quantity of (7) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8093	Quantity of 4X3X1/4 Angle Iron S/N: Not Available C/W: 130 Ft, One Bundle Usage: Not Available	8104	Quantity of (6) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8094	Asset located in: Lake Worth, TX  Quantity of (3) 1/4 in Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8105	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX
8095	Quantity of (5) 3/16 Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX	8106	Quantity of (4) 10 GA Steel Plate S/N: Not Available C/W: One Bundle Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8106A	Quantity of Corrugated Sheet Metal S/N: Not Available C/W: Assorted Length Usage: Not Available Asset located in: Lake Worth, TX	8114	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
8107	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
8108	<b>4 Ft x 6 Ft Tornado Shelter (Unused)</b> S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. <b>Asset located in</b> : Lake Worth, TX	
	Asset located in: Lake Worth, TX	8115	Quantity of (100) 2024 SUNTOP S3048	
8109	4 Ft x 6 Ft Tornado Shelter (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	_	Corrugated Galvalume Steel Panels  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND  MAY NOT BE AN EXACT REPRESENTATION OF  THE ACTUAL PRODUCT	
8110	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Shipping Container Roof Cover		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Asset located in: Lake Worth, TX	
8111	38 ft x 40 ft Shipping Container Roof Cover Kit (Unused) S/N: Not Available C/W: Quantity of (2) Crates - Builds (1) Container Roof Cover Kit. Usage: Not Available Asset located in: Lake Worth, TX	8116 8117	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
8112	Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		FOR ILLUS MAY NOT E THE ACTUA  8117 Quantity of Corrugated S/N: Not AV C/W: THE F FOR ILLUS MAY NOT E THE ACTUA Usage: Not Notes: THE	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX
8113	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX  Quantity of (100) 2024 SUNTOP S2134C 7 ft x			Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
30	35 in Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8118	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8124	2015 Grainger 29AK54 Dolly Johnson Bars S/N: N/A C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. Asset located in: Lake Worth, TX	8125	2014 Grainger 4W944 72 in Dolly Johnson Bars S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
8119	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT.	8128	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8129	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8120	Asset located in: Lake Worth, TX  Quantity of Assorted Brackets  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8130	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8121	Quantity of Filters S/N: Not Available C/W: Assorted Size/Type, One Crate Usage: Not Available Asset located in: Lake Worth, TX	8131	Quantity of 2 in x 8 in x 20 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8122	Quantity of Concrete Mix S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8132	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8133	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8123	Quantity of Mohawk -20 Sand S/N: Not Available C/W: (7) 80 lbs bags Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8134	Quantity of 2 in x 8 in x 16 ft Oak Decking Lumber Lumber S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8135	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8140	Quantity of (26) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8136	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8141	Quantity of (23) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8137	Quantity of (32) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8142	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8138	Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8143	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
8139	Quantity of (27) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber  S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	8144	Quantity of (18) Pallets of 4 ft x 6 in x 4 in Dunnage Lumber S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
		8145	2019 KwiKool KP05-21H Air Conditioner S/N: 1014321 Usage: Not Available Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8146	2019 KwiKool KPO5-21H Air Conditioner S/N: 1014318 Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8159	AXH 42VVF Air Cooler S/N: 149606 E Usage: Not Available Asset located in: Midland, TX
8147	Quantity of (3) Air Conditioner  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8160 8161	AXH 42VVF Air Cooler S/N: 149491E Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler
8148	Quantity of (2) GE Window Air Conditioner S/N: Not Available C/W: 99 sqft, 230v, 17,600 BTU Usage: Not Available	8162	S/N: 149491 P Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler
8149	Asset located in: Lake Worth, TX  AXH 42VVF Air Cooler  S/N: 149606G Usage: Not Available	8163	S/N: 149606J Usage: Not Available <b>Asset located in</b> : Midland, TX
8150	Asset located in: Midland, TX  AXH 42VVF Air Cooler  S/N: 149491K Usage: Not Available	8103	<b>AXH 42VVF Air Cooler</b> S/N: 149491 J Usage: Not Available <b>Asset located in</b> : Midland, TX
8151	Asset located in: Midland, TX  AXH 42VVF Air Cooler  S/N: 149491 D	8164	AXH 42VVF Air Cooler S/N: 149606 H Usage: Not Available Asset located in: Midland, TX
8152	Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler S/N: 149606 F	8165	AXH 42VVF Air Cooler S/N: 149491 I Usage: Not Available Asset located in: Midland, TX
8153	Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler	8166	AXH 42VVF Air Cooler S/N: 149491 G Usage: Not Available
	S/N: 149491 L Usage: Not Available <b>Asset located in</b> : Midland, TX	8167	Asset located in: Midland, TX  AXH 42VVF Air Cooler  S/N: 149491 N
8154	<b>AXH 42VVF Air Cooler</b> S/N: 149491 Q Usage: Not Available	8168	Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler
8155	Asset located in: Midland, TX  AXH 42VVF Air Cooler  S/N: 119084 C		S/N: 119084 A Usage: Not Available Asset located in: Midland, TX
8156	Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler S/N: 119084B	8169	AXH 42VVF Air Cooler S/N: 149491 F Usage: Not Available Asset located in: Midland, TX
	Usage: Not Available <b>Asset located in</b> : Midland, TX	8170	Asset located in: Midland, TX  AXH 42VVF Air Cooler  S/N: 149491 M
8157	<b>AXH 42VVF Air Cooler</b> S/N: 1494910 Usage: Not Available	Q171	Usage: Not Available Asset located in: Midland, TX  AXH 42VVF Air Cooler
8158	Asset located in: Midland, TX  AXH 42VVF Air Cooler  S/N: 149606l Usage: Not Available Asset located in: Midland, TX	8171	S/N: 149491 H Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8172	AXH 36VVF Air Cooler S/N: 89463E Usage: Not Available Asset located in: Midland, TX	8185	<b>2018 Dri-Eaz DRITEC 4000I Dehumidifier</b> S/N: 1794 Usage: Not Available <b>Notes</b> : .
8173	AXH 36VVF Air Cooler S/N: 89463 C Usage: Not Available	8186	Asset located in: Lake Worth, TX  2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1797
8174	Asset located in: Midland, TX  AXH 36VVF Air Cooler  S/N: 89463 D  Usage: Not Available		Usage: Not Available Notes: . Asset located in: Lake Worth, TX Quantity of (4) Heaters
8175	Asset located in: Midland, TX  AXH 36VVF Air Cooler  S/N: 89509A  Usage: Not Available  Asset located in: Midland, TX		S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available <b>Asset located in</b> : Corsicana, TX
8176	AXH 36VVF Air Cooler S/N: 89509B Usage: Not Available Asset located in: Midland, TX	8188	2018 Campo EB400D 400000 BTU Space Heater S/N: B400-17-9254 C/W: Diesel Fueled Usage: Not Available
8177	<b>AXH 36VVF Air Cooler</b> S/N: 89416E Usage: Not Available		Notes: . Asset located in: Lake Worth, TX 2018 Campo EB400D 400000 BTU Space
8178	Asset located in: Midland, TX  AXH 36VVF Air Cooler  S/N: 89463 F Usage: Not Available  Asset located in: Midland, TX		Heater S/N: B400-18-8975 C/W: Diesel Fueled, 120 V Input Usage: Not Available Notes: .
8179	AXH 36VVF Air Cooler S/N: 89416 C Usage: Not Available Asset located in: Midland, TX	8190	Asset located in: Lake Worth, TX  Heat star HS3500DF 361439 BTU Space Heater S/N: 27901109 C/W: Kerosene Fueled, 120 V Input
8180	AXH 36VVF Air Cooler S/N: 89509 C Usage: Not Available Asset located in: Midland, TX	8191	Usage: Not Available Asset located in: Lake Worth, TX  91 Mi-T-M 375000 BTU Space Heater S/N: Not Available
8181	AXH 36VVF Air Cooler S/N: 89463 B Usage: Not Available		C/W: Propane Fueled, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
8182	Asset located in: Midland, TX  AXH 36VVF Air Cooler  S/N: 89463 A  Usage: Not Available  Asset located in: Midland, TX	8192	Quantity of (4) Mr. Heater 60,000 BTU Forced Air Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8183	2015 Air Comman AC1600 Hydraulic Oil Cooler S/N: AC29 Usage: 124 Hr Notes: . Asset located in: Lake Worth, TX	8193	Quantity of (4) Mr. Heater 60000 BTU Space Heater S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8184	2018 Dri-Eaz DRITEC 4000I Dehumidifier S/N: 1798 Usage: Not Available Notes: . Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8194	Mr. Heater 30000 BTU Space Heater S/N: Not Available C/W: Propane Fueled, (3) Space Heaters, (9) Tanks, (1) Burner Wand. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	8205	2024 Landhonor LHR-MC766 Massage Chair Sofa (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8206	BarcaLounger (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	THESE  Asset located in: Lahoma, OK	8207	Osaki 3D Prestige Massage Chair S/N: Not Available
8196	Innovatech Terminator 2000El Electric Ride-On Floor Scraper		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: T200E302IB Usage: 1,733 Hr <b>Asset located in</b> : Lake Worth, TX	8208	Osaki 3D Prestige Massage Chair S/N: Not Available Usage: Not Available
8197	Karcher Chariot 2 iVac 24 ATV Electric Ride-On Vacuum Cleaner (Unused) S/N: 10090690000894 Usage: Not Available Asset located in: Lake Worth, TX	8209	Asset located in: Lake Worth, TX  Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available
8198	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240913 Usage: Not Available Asset located in: Lake Worth, TX	8210	Asset located in: Lake Worth, TX  Quantity of (2) 55 in Adjustable Height Propane Fire Pit W/ Table Top Lid S/N: Not Available Usage: Not Available
8199	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240915 Usage: Not Available Asset located in: Lake Worth, TX	8211	Asset located in: Lake Worth, TX  GE Front Load Washer & Dryer Set  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8200	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240914 Usage: Not Available Asset located in: Lake Worth, TX	8212	Frigidaire Freezer  S/N: AA15240684  C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available  Asset located in: Lake Worth, TX
8201	2024 HUNTER PRO CS3 Massage Chair Sofa (Unused) S/N: 240916 Usage: Not Available	8214	True 3-Door Commercial Refrigerator S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8202	Asset located in: Lake Worth, TX  2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available	8215	Quantity of (3) Meat Slicers S/N: Not Available C/W: (2) Bizerba, (1) Hobart Usage: Not Available Asset located in: Lake Worth, TX
8203	Asset located in: Lake Worth, TX  2024 HUNTER PRO CS3 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8216	Quantity of (7) Pallets of Landscape Sandstone Boulders S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX
8204	Quantity of Human Touch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8217	Quantity of (7) Pallets of Landscape Sandstone S/N: Not Available C/W: assorted size, shape Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8218	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8226	Predator Power Auger S/N: 44FAPL24013877 C/W: 2024 US EPA Label, Predator 1 Cylinder 52 cc Gasoline Engine, (1) 8 in Auger, (1) 6 in Auger Usage: Not Available
8219	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING
8220	Legend Walk Behind 20 in Garden Tiller S/N: Not Available C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available	8227	THESE Asset located in: Lahoma, OK Quantity of (4) Kubota Mower Decks
8221	Asset located in: Lake Worth, TX  Legend Walk Behind 20 in Garden Tiller		S/N: Not Available C/W: (3) 60 in & (1) 72 in Mower Decks Usage: Not Available
	S/N: Not Available C/W: Legend Force 212 cc Gasoline Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8228	Asset located in: Lake Worth, TX  Crary 75060 Lawn Vacuum  S/N: 103825  C/W: Briggs & Stratton 1 Cylinder Gasoline
8222	Quantity of (18) Rhino Rugged Landscaping Tools W/ Fiberglass Handles S/N: Not Available		Engine Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10 in Hoe, (3) Square Pt Shovel Usage: Not Available		Craftsman Walk-Behind Leaf Vacuum S/N: 1H01NK10291 C/W: 1 Cylinder Gasoline Engine Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8223	Tools W/ Fiberglass Handles  S/N: Not Available  C/W: (3) # 12 Aluminum Scoop, (3) 16 in Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10	8230	Quantity of Rhino Rugged Landscaping Hand Tools S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	in Hoe, (3) Square Pt Shovel Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8231	Cat Engine (Inoperable) S/N: Not Available
8224	Quantity of (3) Hand Held Pump Sprayers S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	8232	C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Quantity of Truck Parts S/N: Not Available C/W: Hubs, Fenders, One Pallet Usage: Not Available
8225	S/N: Not Available C/W: String Trimmer, Accessories Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	8233	Asset located in: Lake Worth, TX  72 in Forks S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		8234	Cat 48 in Q/C Wheel Loader Forks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8235	Quantity of (2) Dolly Bars S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8244	Quantity of (2) Pallets of engine bay doors S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	
8236	Pearl Abrasive 15 In Floor Preparation Disc S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8245	bucket teeth S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	
8237	Quantity of Cat Final Drive Sprocket Segments - Fits Cat D6 S/N: Not Available C/W: To Fit Cat D6M, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	8246	JLG Man Basket S/N: 2017920 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	
8238	Pipe handler S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	8246A 8247	Hydraulic Scrap Metal Bailer S/N: 1676784 C/W: 3 ph Usage: Not Available Asset located in: Oklahoma City, OK 2024 Machpro MP-MS100 Sofa (Unused)	
8239	Quantity of (3) Cat Weights  S/N: Not Available  C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION	8248	S/N: SLP2707080862 Usage: Not Available Asset located in: Lake Worth, TX 2024 Machpro MP-MS100 Sofa (Unused)	
	Usage: Not Available  Asset located in: Corsicana, TX	_	S/N: SLP2707080861 Usage: Not Available Asset located in: Lake Worth, TX	
8240	Grieve 333 Electric Airless oven - Fits S/N: 104626A1111 C/W: To Fit Grieve 333 Electric Industrial Oven, Grieve .33 hp 3 Phase Motor Usage: Not Available Asset located in: Midland, TX	8251	8251 Quantity of Fire Extinguisher S/N: Not Available Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCAT	S/N: Not Available
8241	Grieve 3330 Electric Airless oven S/N: 114490A0315 C/W: To Fit Grieve 333 Electric Industrial Oven, Grieve .33 hp 3 Phase Motor Usage: Not Available		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
8242	Asset located in: Midland, TX  2018 Bomag BMP8500 Trench Compactor S/N: 101720129533 C/W: 2018 US EPA Label, Kubota D1005 3 Cylinder 14.3 kW 1.0 L Diesel Engine, 32 in drums w/extensions, remote; EQUIPMENT- FROM-SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX  Mobydick Kitflex 400C Wheel Washing System S/N: Not Available		Quantity of (15) Assorted Sized Fire Extinguisher S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8253	2024 Topcon RL-H5B Rotary Laser Level (Unused) S/N: 1B019363 C/W: Receiver Usage: Not Available	

Usage: Not Available

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8254 8255 8256	2014 Sokkia 7383-40 w/ Grade Rod Laser Level S/N: 270612 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX  Trimble EM410 Antenna Mount S/N: 2599J501CN Usage: Not Available Asset located in: Lake Worth, TX  Topcon GP-3	8263	2024 Suihe A200 200 lb Cast Iron Anvil (Unused)  S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	S/N: Not Available C/W: Topcon GR-3 RTK GPS GNSS, SN#442- 0693, Topcon GR-3 RTK GPS GNSS, SN#442- 0485, Topcon FC-2600 Data Collector, SN#55802743 Usage: Not Available Asset located in: Lake Worth, TX	8264	2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8257	Topcon Hiper Lite RTK S/N: Not Available C/W: Topcon Hiper Lite RTK GPS, SN#263- 1167, Topcon Hiper Lite RTK GPS, SN#296- 0181, Topcon FC-120 Data Collector, SN#A30665	8265	2024 Landhonor LHR-CIA200 200 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX		Quantity of Floor Jacks & Parts S/N: Not Available C/W: (4) Floor Jacks, Receiver Hitch, Scissor
8258	Topcon GR-5 RTK  S/N: Not Available C/W: Topcon GR-5 RTK GPS GNSS Rover, SN#800-10190 Topcon FC-2600 Data Collector, Magnet Field, SN#556-06832 Usage: Not Available		Jack, Lights, One Pallet; EQUIPMENT-FROM- US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8268	Quantity of (4) Jack Stands
8259	Quantity of Laser Equipment S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8269	S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
8260	2024 Suihe A400 400 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		Quantity of (4) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT, RB WILL
8261	2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
8262	2024 Landhonor LHR-CIA400 400 lb Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8270	Quantity of (3) Jack Stands S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8276	Quantity of (16) 2024 Agriquip GLWH16 Auto Darkening Welding Helmets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8278	48" Frontier Job Box W/ 25 PC Makita Power Tool Set
8271	28 In x 50 In Metal Table S/N: Not Available C/W: Vise Usage: Not Available	9270	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
8272	Asset located in: Lake Worth, TX  Lifting Strap, Sockets  S/N: Not Available Usage: 5 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST	8279 8280	Wokin 158 PC Standard & Metric Tool Set W/ 42" Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Wokin/Valley 8 PC Hydraulic Jack & Jack Stand Kit W/ 42" Job Site Box S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8281	2008 Sokkia C22 Builders Level W/Tripod
8273	Quantity of Electric Grease Guns S/N: Not Available C/W: Tools Usage: 5 Hr Notes: ITEMS AT OFFSITE LOCATION MUST		S/N: 004062 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	8282	Wood Tuff Tow 48" Job Site Box W/ 7 PC Cub Cadet Tool Kit S/N: Not Available C/W: HT24E- Hedge Trimmer - CS160E- Cordless Chainsaw - LB600E- Leaf Blower - ST15E- String Trimmer - Battery - Charger Usage: Not Available
8274	<b>Quantity of Tools</b> S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: 1 in Socket Set & Misc. Tools Usage: 5 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL	8283 8284	2013 APT M133 Rivet Buster S/N: 1210195 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK		2011 APT M133 Rivet Buster S/N: 1010004M133 C/W: EQUIPMENT-FROM-SUNSTATE-
8275	Quantity of Shovels, Post Hole Diggers. S/N: Not Available		EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 5 Hr  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	8285	2012 APT M190 1-1/8"X6" 90 lb Air Hammer S/N: 312531M190BV C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8286	2008 APT M160 60 lb Air Hammer S/N: 303907 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8298	2024 Suihe WW 20000 lb Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
8287	2007 APT 30 lb Air Hammer S/N: 502390 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8288	2008 APT M654 Chipping Hammer S/N: 52139 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX	8299	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
8289	Quantity of (5) 2024 Landhonor LDH-FPR36 36 in Fire Pit Ring S/N: Not Available Usage: Not Available	8300	Asset located in: Lake Worth, TX  2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused)
8290	Asset located in: Lake Worth, TX  2024 Landhonor LHR-AIW1 Pneumatic 1 in Impact Wrench (Unused)  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX
8294	Quantity of (3) Battery Charger S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	8301	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
8295	GNB GTC12-600T1 Battery Charger S/N: Not Available C/W: Skid Mounted Basket Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
8296	Asset located in: Lake Worth, TX  Quantity of (2) Battery Charger  S/N: Not Available  C/W: Die Hard DH0168, DSR Pro Series  DSR121; EQUIPMENT-FROM-US-AUTO- RECYCLING	8302	2024 Landhonor LHR-EW20000 20000 lb Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8297	Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (4) Midtronics GR8 Commercial	8303	Wood WW15000V12 15000 lb Winch S/N: Not Available C/W: 4.5hp, Remote Control Usage: Not Available
	Battery Charger S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  Quantity of (8) 3 in OD Fire Water Hose S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK

Lot #	Details	Lot #	Details	
8306	Quantity of Bottle Cart & Torches  S/N: Not Available C/W: Gauges; EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8312	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8307	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available		Usage: Not Available  Asset located in: Lake Worth, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX	8313	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8308	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		FOR ILLUSTRATION PURPOSES ON	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8314	Quantity of 2024 Landhonor LHR-RC5400 5400 lb Ratchet Binders w/20 ft Chains (Unused)	
8309	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available	8315	C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available	S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX		Quantity of 2024 Landhonor LHR-RC5400 5400 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: (16) Chains, (8) Ratchet Binders Usage: Not Available	
8310	Quantity of (5) 2024 Suihe BC-9200 9200 lb		Asset located in: Lake Worth, TX	
8311	Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX  Quantity of (5) 2024 Suihe BC-9200 9200 lb	8316	Quantity of (48) 2024 SKLP SK003 Ratchet Straps (Unused) S/N: B31577 C/W: (32) 2 in x 27 ft, (16) 1.5 in x 27 ft Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
	Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX		S/N: Not Available Usage: Not Available	

Lot #	Details	Lot #	Details
8318	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT	8329	Quantity of (3) Boxes of Wokin 3 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
	IMAGÈS SHOWN ARÈ FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8330	Quantity of (3) Boxes of 10 Ton Jack S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
8319	Asset located in: Lake Worth, TX  9 Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused)  S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT	8331	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in: Lake Worth, TX
	IMAGÉS SHOWN ARÉ FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8332	Semi-Trailer Landing Gear S/N: Not Available C/W: 62000 lbs Rating, 2 Speed Gear Box Usage: Not Available Asset located in: Lake Worth, TX
8320	Ratchet Straps (Unused)  S/N: Not Available  C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT  IMAGES SHOWN ARE FOR ILLUSTRATION  PURPOSES ONLY AND MAY NOT BE AN	8333	Electric Submersible Water Pump S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Lake Worth, TX	8334	Armor Titanium Series 64 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital
8321	2024 Landhonor LHR-LB8850 Leaf Blower (Unused) S/N: Not Available C/W: 1 Cylinder 3.1 kW 75.6 cc Gasoline Engine Usage: Not Available		Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX
8322	Asset located in: Lake Worth, TX  Little Wonder Optimax Walk-Behind Leaf Blower  S/N: Not Available  C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available  Asset located in: Lake Worth, TX	8335	Armor Titanium Series 40 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available
8324	Quantity of (3) Arcan Farm Jack S/N: Not Available Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8336	Asset located in: Lake Worth, TX  2024 Agriquip GLGS40 40 Gun Safe (Unused)  S/N: Not Available  C/W: THE PRODUCT IMAGES SHOWN ARE  FOR ILLUSTRATION PURPOSES ONLY AND
8325	Quantity of (5) 2024 Powertek 20 Ton Pneumatic Bottle Jack (Unused) S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX
8328	Asset located in: Lake Worth, TX  Sunex Transmission Jack S/N: Not Available C/W: Under Hoist Stands, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX	8337	Armor Titanium Series 24 Gun Safe S/N: Not Available C/W: 24 in Wide x 56 in High x 24 in Deep, 1400 Degree Fire Rating, Digital Combination key pad, 5 live action locking bolts Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8338	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts	8346	2024 Landhonor LHR-PWC6 Wood Chipper (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	
	Usage: Not Available  Asset located in: Lake Worth, TX	8347	2024 LANM LAM750 Electric Remote Control Crawler Lawn Mower (Unused)	
8339	Armor Titanium Series 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof, 1400 Degree Fire Rating, Digital Combination Key Pad w/Backup Key, Additional Door Pouch Storage Feature For Pistols & Other Valuables, 5 Live Action Locking Bolts Usage: Not Available Asset located in: Lake Worth, TX		S/N: LAM750240707 C/W: 22 in Mower Usage: Not Available <b>Notes</b> : THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES ON	C/W: 22 in Mower Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
8340	2024 Agriquip GLGS14 14 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	8348	2024 Landhero LHR-HT550 Remote Control Lawn Mower (Unused) S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available  Asset located in: Lake Worth, TX		2024 Landhero LHR-HT550 REMOTE CONTROL Lawn Mower (Unused) S/N: Not Available	
8341	2024 Raccoon RC-G1.5 Electric Bicycle (Unused)		Usage: Not Available  Asset located in: Lake Worth, TX	
8342	S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  2024 Raccoon RC-G1.5 Electric Bicycle (Unused)	8350	2024 Machpro MP-M500 Tracked Lawn Mowe (Unused) S/N: MP20240711180 C/W: Remote Control Usage: Not Available	
	S/N: RC2405310 Usage: Not Available Asset located in: Lake Worth, TX	8351 2024 Machpro MP-M50 (Unused) S/N: MP20240711182 C/W: Remote Control Usage: Not Available	Asset located in: Lake Worth, TX  2024 Machpro MP-M500 Tracked Lawn Mowe (Unused)	
8343	2024 Landhonor LHR-GLS34 Gasoline Tow Behind Log Splitter (Unused) S/N: Not Available		C/W: Remote Control	C/W: Remote Control Usage: Not Available
	C/W: Ball Hitch, Kohler 7 hp Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8353	Hustler Dash XD 34 Zero-Turn Lawn Mower S/N: 23100864	
8344	2024 Landhonor LS-13-36D Skid Steer Log Splitter (Unused) S/N: Not Available C/W: Skid Steer Carpet Pole, One Crate		C/W: Hydrostatic Drive, 2023 US EPA Label, 11x4.00-5 Front Tires, 18x6.5/8 Rear Tires, Hustler 34 in Mower Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	Usage: Not Available  Asset located in: Lake Worth, TX	8354	<b>2014 Kubota GR2100 Lawn Mower</b> S/N: 12438	
8345	2019 Morbark Boxer X7 Tow-Behind Wood Chipper		Usage: Not Available  Asset located in: Lake Worth, TX	
	S/N: 4S8SZ1010KW006193 C/W: 2018 US EPA Label, CARB Compliant, Kohler ech740 2 Cylinder 747 cc Gasoline Engine, 36 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch Usage: 110 Hr Asset located in: Lake Worth, TX	8355	2018 Kubota Z725KH Zero-Turn Lawn Mower S/N: 23133 C/W: Hydrostatic Drive, 2017 US EPA Label, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 180 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8356	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX	8381A	Utility Vehicle S/N: 1B9AC2110PA284014 C/W: Canopy, 4 Passenger, Windshield, 4 Cylinder Gasoline Engine Usage: 2,637 Mi Asset located in: Lake Worth, TX
8357	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower, Briggs & Stratton, Gasoline Usage: Not Available Asset located in: Lake Worth, TX	8382	2012 Polaris Ranger XP Utility Vehicle S/N: 4XATH7EA1CE289808 C/W: Canopy, 2 Passenger, Windshield, Hitch Receiver, Manual Dump Bed Usage: 1,799 Hr Asset located in: Lake Worth, TX
8358	White Outdoor 17BK2ACK090 Zero-Turn Lawn Mower S/N: 1B208G90011 C/W: Hydrostatic Drive, 13x5.00x6 Front Tires, 20x10.00x8 Rear Tires, 54 in Mower Usage: 631 Hr	8383	Bobcat UV34XL Utility Vehicle S/N: B53721117 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, Polaris Gasoline Engine Usage: 1,521 Hr Asset located in: Lake Worth, TX
8359	Asset located in: Lake Worth, TX  2016 Kubota Z725KH Zero-Turn Lawn Mower S/N: 21339 C/W: Hydrostatic Drive, 13x6.5-6 Front Tires, 24x12.00-12 Rear Tires, KUBOTA 60 in Mower Usage: 2,329 Hr Asset located in: Lake Worth, TX	8384 	2021 John Deere Gator XUV 855M Utility Vehicle S/N: 1M0855MBPMM040235 C/W: Canopy, 4 Passenger, Windshield, Manual Dump Bed, 2021 US EPA Label, John Deere 3tnv70 Gasoline Engine Usage: 3,905 Hr Asset located in: Lake Worth, TX
8360	Quantity of (3) Yard Force 22 in Walk Behind String Trimmer S/N: Not Available C/W: Briggs & Stratton Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8396	2017 Club Car Carryall 1700 Utility Vehicle S/N: A5CUAA4FTHA840664 C/W: Canopy, 4 Passenger, Hitch Receiver, Manual Dump Bed, 2 Cylinder Gasoline Engine, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,294 Hr
8362	Quantity of (3) Yard Force 9 in Edger S/N: Not Available C/W: 79 cc Gasoline Engine Usage: Not Available Asset located in: Lake Worth, TX	8397	Asset located in: Lake Worth, TX  2017 Club Car Carryall 1700 Utility Vehicle S/N: A5CUAA4FTHA841104 C/W: Canopy, 4 Passenger, Brush Guard, Hite Receiver, Manual Dump Bed, Gasoline Engine
8367	<b>2021 Polaris 500 Utility Vehicle</b> S/N: 3NSRM2504ME534422 C/W: Canopy, 2 Passenger, Brush Guard, Hitch		EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: 1,674 Hr  Asset located in: Lake Worth, TX
	Receiver, Manual Dump Bed, 500 cc Gasoline Engine Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8403	2007 John Deere TX Turf Gator Utility Vehicle S/N: Not Available C/W: Open Operator Station, 2 Passenger, Hitch Receiver, Manual Dump Bed Usage: Not Available
8371	2018 Kubota RTVX1140WH Utility Vehicle S/N: A5KD2GDBTJG027894 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 2,192 Hr Asset located in: Lake Worth, TX	8404	Asset located in: Lake Worth, TX  1998 E-Z-Go 898445 Club Car Utility Vehicle S/N: C98004700 C/W: Canopy, 2 Passenger, Windshield, Rear Screen, 3 Cylinder Diesel Engine, Diesel Engine
8381	2012 Polaris 800 EFI Crew Cab 6 Passenger Utility Vehicle S/N: 4XAWH76AXDE646836 C/W: Canopy, 6 Passenger, Manual Dump Bed, Diesel Engine, Gas Engine Usage: Not Available Asset located in: Lake Worth, TX	8405	Usage: 2,184 Hr  Asset located in: Lake Worth, TX  2017 Taylor Dunn Bigfoot 48V N/M Utility Cart S/N: 205477 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 560 Hr  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8406	2017 Taylor Dunn SS5-36 Utility Cart S/N: 205453 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: 177 Hr Asset located in: Lake Worth, TX	8415	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409071 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8407	Tao Motor Boulder 4x2 ATV (Unused) S/N: L9NACFB30N1604821 C/W: 2022 US EPA Label, Tao 107 cc Gasoline Engine Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY	8416	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409096 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
8408	Asset located in: Lake Worth, TX  Tao Motor Boulder 4x2 ATV (Unused)  S/N: L9NACFB34N1402404  C/W: Electric Start, 2022 US EPA Label, Tao 107 cc Gasoline Engine	8417	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409061 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO & KEY Asset located in: Lake Worth, TX	8418	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409062
8409	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0112975 C/W: Battery Charger, 4 Passenger, Canopy,		C/W: 4 Passenger, Canopy, Windshield Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Windshield, Lift Kit Usage: 9 Hr <b>Asset located in</b> : Lake Worth, TX	8419	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409098
8410	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140193 C/W: Battery Charger, 4 Passenger, Canopy,		C/W: 4 Passenger, Canopy, Windshield Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Windshield, Lift Kit Usage: 12 Hr <b>Asset located in</b> : Lake Worth, TX	8420	8420 2024 HUNTER PRO GFE-4.0 Electric Golf Ca (Unused) S/N: 202409100
8411	Icon LTA617 Electric Golf Cart (Unused) S/N: LTA0140519 C/W: Battery Charger, 4 Passenger, Canopy,		C/W: 4 Passenger, Canopy, Windshield Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Windshield, Lift Kit Usage: 7 Hr <b>Asset located in</b> : Lake Worth, TX	8421	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused)
8412	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409051		S/N: 202409099 C/W: 4 Passenger, Windshield Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: 4 Passenger, Canopy, Windshield Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8422	2024 HUNTER PRO GFX-4.0 Electric Golf Cart (Unused) S/N: 202409069
8413	<b>2024 HUNTER PRO GFE-4.0 Electric Golf Cart</b> S/N: 202409097 C/W: 4 Passenger, Canopy, Windshield		C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	8423	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart
8414	2024 HUNTER PRO GFE-4.0 Electric Golf Cart (Unused) S/N: 202409072 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		(Unused) S/N: 37020241084 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8424	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409115 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX 2024 HUNTER PRO GFZ-4.0 Electric Golf Cart	8433	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused)  S/N: A07DE5W8CPC001632  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE
	(Unused) S/N: 202409114 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL
8426	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused)		INFORMATION AVAILABLE IN OFFICE - MSO ;  Asset located in: Lake Worth, TX
	S/N: 3702020241243 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8434	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001670 C/W: 48 Volt Battery Charger, 4 Passenger,
8427	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 3702020241242 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY
8428	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 37020241100 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available		SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONA INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8435	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)
8429	2024 HUNTER PRO GFZ-4.0 Electric Golf Cart (Unused) S/N: 202409116 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		S/N: A07DE5W8HPC001636 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN
8430	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused) S/N: 37020241241 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX		WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
8431	2024 HUNTER PRO GFZ-4.0PRO Electric Golf Cart (Unused) S/N: 37020241240 C/W: 4 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Lake Worth, TX	8436	Asset located in: Lake Worth, TX  2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)  S/N: A07DE5W8KPC001613  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8437	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8EPC001671 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8441	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001605 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX	1	Asset located in: Lake Worth, TX
8438	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)  S/N: A07DE5W8TPC001673  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	8442	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)  S/N: A07DE5W8LPC001604  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8439	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)	8443	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused)
	S/N: A07DE5W8EPC001606 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8TPC001656 C/W: 48 Volt Battery Charger, 4 Passenger, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
0440	Asset located in: Lake Worth, TX	0444	Asset located in: Lake Worth, TX
8440	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused)  S/N: A07DE5W8VPC001633  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8444	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused)  S/N: A07DE5W8HPC001653  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8445	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused) S/N: A07DE5W8PPC001593 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8449	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8JPC001600 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8446	2023 Kandi KS4PSLR-R Electric Golf Cart (Unused)  S/N: A07DE5W8JPC001662  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;	8450	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8JPC001676  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8447	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)	8451	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)
	S/N: A07DE5W8TPC001687 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available		S/N: A07DE5W8KPC001689 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;		Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO;
0440	Asset located in: Lake Worth, TX	0.450	Asset located in: Lake Worth, TX
8448	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8CPC001646  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8452	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8CPC001677  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8453	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8VPC001602  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL	8457	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8TPC001690  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL
	INFORMATION AVAILABLE IN OFFICE - MSO ; <b>Asset located in</b> : Lake Worth, TX		INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
8454	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8APC001679  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8458	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)  S/N: A07DE5W8VPC001678  C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX
8455	2023 Kandi KS4PSLR-W Electric Golf Cart (Unused) S/N: A07DE5W8PPC001688 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available	8459	Electric Golf Cart S/N: JW9-200800 C/W: Battery Charger, 2 Passenger, Canopy, Windshield, Utility Body Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY	8460	2024 RCcar Electric 3 Person Scooter S/N: SLP2413080202 Usage: Not Available Asset located in: Lake Worth, TX
8456	SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX  2023 Kandi KS4PSLR-W Electric Golf Cart (Unused)		Quantity of (4) Synergy DP209 285/75R24.5 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Lake Worth, TX
	S/N: A07DE5W8PPC001691 C/W: 48 Volt Battery Charger, 4 Passenger, Canopy, Windshield, 5 kW Engine Usage: Not Available  Notes: THE GOLF CARTS ARE IN CREATE CONSITION. EXCESS INVENTORY STORED IN WAREHOUSE FOR EXTENDED TIME, SOME BATTERIES MAY BE DEAD. ITEM SOLD AS-IS AND BATTERIES WILL NOT BE REPLACED BY SELLER. PLEASE SEE SELLER SUPPLIED SPECIFICATIONS IN THE SUPPORTING DOCUMENTS SECTION BELOW; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	8462	53 ft High Cube Storage Container S/N: GTJU968067 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8463	45 ft High Cube Storage Container S/N: HDHM94691473 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	8469	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101003 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	Asset located in: Lahoma, OK	8470	2024 40 ft Multi-Door Storage Container
8464	2024 40 ft High Cube Multi-Door Storage Container S/N: CICU6930839 C/W: One-Way		S/N: XHCU5647588 C/W: One-Way Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	8471	2024 40 ft High Cube Multi-Door Storage Container
8465	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0174629 C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	8472	S/N: JPCU0101024 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX		<b>2024 40 ft High Cube Multi-Door Storage Container</b> S/N: RYDU0026300
8466	2024 40 ft High Cube Multi-Door Storage Container		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: LYPU0174613 C/W: One-Way Usage: Not Available <b>Notes</b> : THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8473	2024 40 ft High Cube Multi-Door Storage Container S/N: RYDU0026260 Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	8474	2024 40 ft High Cube Multi-Door Storage Container
8467	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0173793		S/N: RYDU0025562 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8475	2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212025 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8468	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU0101019 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8476	2024 40 ft High Cube Multi-Door Storage Container S/N: PPLU1212046 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX  40 ft High Cube Multi-Door Storage Container S/N: HHXU3309737 Usage: Not Available

Lot #	Details	Lot #	Details
8478	2024 40 ft Multi-Door Storage Container S/N: LYPU0173772 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8486	2024 40 ft High Cube Multi-Door Storage Container S/N: LYGU4159586 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	8487	2024 40 ft High Cube Multi-Door Storage
8479	2024 40 ft Multi-Door Storage Container S/N: LYPU0173807 C/W: One-Way Usage: Not Available	(	Container S/N: LYGU4159436 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
	Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	8488	2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0152117 C/W: One-Way
8480	2024 40 ft Multi-Door Storage Container	1	Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: XHCU5647593 C/W: One-Way Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8489	2024 40 ft High Cube Multi-Door Storage Container S/N: ZXJU0151928
8481	2024 40 ft High Cube Multi-Door Storage Container S/N: LYPU0173788		C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
	C/W: One-Way Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8490	2024 40 ft High Cube Storage Container S/N: DFCU1640679 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8491	2024 40 ft High Cube Storage Container S/N: SPRU9037160 C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX
8482	<b>2024 40 ft High Cube Multi-Door Storage Container</b> S/N: MMPU1045114		
	C/W: One-Way Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8492	<b>20 ft Standard Open-Sided Storage Container</b> S/N: SPRU2813703 Usage: Not Available
8483	<b>2024 40 ft Multi-Door Storage Container</b> S/N: LYGU0185801		Asset located in: Lake Worth, TX
	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	8493	20 ft Standard Open-Sided Storage Container S/N: SPRU2813880 Usage: Not Available Asset located in: Lake Worth, TX
	THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	8494	2024 20 ft Multi-Door Storage Container
8484	2024 40 ft High Cube Storage Container S/N: DFCU1640658 C/W: One-Way	8495	S/N: XHCU2623751 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX		<b>2024 20 ft Multi-Door Storage Container</b> S/N: XHCU2626766 Usage: Not Available
8485	<b>2024 40 ft High Cube Storage Container</b> S/N: DFCU1640663		Asset located in: Lake Worth, TX
	C/W: One-Way Usage: Not Available Asset located in: Lake Worth, TX	8496	20 ft Standard Multi-Door Storage Container S/N: SPRU2807634 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8497	20 ft Standard Multi-Door Storage Container S/N: SPRU2808250 Usage: Not Available Asset located in: Humble, TX	8510	20 ft Standard Multi-Door Storage Container S/N: SPRU2812287 Usage: Not Available Asset located in: Humble, TX
8498	20 ft Standard Multi-Door Storage Container S/N: SPRU2807871 Usage: Not Available Asset located in: Humble, TX	8511	2024 20 ft Standard Double-Ended Storage Container S/N: SPRU2611575 Usage: Not Available
8499	<b>20 ft Standard Multi-Door Storage Container</b> S/N: SPRU2808266 Usage: Not Available <b>Asset located in</b> : Humble, TX	8512	Asset located in: Lake Worth, TX  20 ft Standard Multi-Door Storage Container S/N: SPRU2810812 Usage: Not Available
8500	2024 SHANG 20 ft One-Way Storage Container S/N: MCCU1088835 Usage: Not Available Asset located in: Lake Worth, TX	8513	Asset located in: Humble, TX  20 ft Standard Multi-Door Storage Container S/N: SPRU2810833 Usage: Not Available
8501	2024 20 ft Storage Container S/N: HYJU1077876 Usage: Not Available Asset located in: Lake Worth, TX	8514	Asset located in: Humble, TX  20 ft Standard Storage Container S/N: SPRU3063223 Usage: Not Available Asset located in: Lake Worth, TX
8502	2024 20 ft Storage Container S/N: VSLU3245246 Usage: Not Available Asset located in: Lake Worth, TX	8515	20 ft Standard Storage Container S/N: SPRU3064493 Usage: Not Available Asset located in: Lake Worth, TX
8503	2024 20 ft Standard Storage Container S/N: MCCU1088917 Usage: Not Available Asset located in: Lake Worth, TX	8516	20 ft Standard Storage Container S/N: APZU3578440 Usage: Not Available Asset located in: Lake Worth, TX
8504	2024 20 ft Standard Double-Ended Storage Container S/N: SPRU2611786 Usage: Not Available Asset located in: Lake Worth, TX	8517	20 ft Standard Storage Container S/N: ECMU1513031 Usage: Not Available Asset located in: Lake Worth, TX
8505	<b>20 ft Standard Storage Container</b> S/N: SPRU3086580 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8518	2006 20 ft Storage Container S/N: HDMU2493989 C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: .
8506	20 ft Standard Storage Container S/N: SPRU3086189 Usage: Not Available Asset located in: Lake Worth, TX	8519	Asset located in: Lake Worth, TX  20 ft Standard Storage Container S/N: AXIU2245734
8507	2024 20 ft Standard Storage Container S/N: SPRI3098791 Usage: Not Available		C/W: Man Door, AC Unit Usage: Not Available Asset located in: Lake Worth, TX
8508	Asset located in: Lake Worth, TX  20 ft Standard Multi-Door Storage Container S/N: SPRU280883	8520	20 ft Storage Container S/N: TCKU2807327 Usage: Not Available Asset located in: Humble, TX
8509	Usage: Not Available Asset located in: Humble, TX  2024 20 ft Standard Storage Container S/N: SPRU3078970 Usage: Not Available Asset located in: Lake Worth, TX	8521	20 ft Standard Storage Container S/N: CBHU3069110 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8522	2024 12 ft Storage Container S/N: GMPU9027419 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8528	2024 8 ft Storage Container S/N: GMPU9026520 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	
8523	2024 12 ft Storage Container S/N: GMPU9027430 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	8529	2022 Suihe Storage Container S/N: LYPU00109 Usage: Not Available Notes: . Asset located in: Lake Worth, TX	
8524	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX  2024 9 ft Storage Container	8530	7 ft Storage Container S/N: LYP710660 C/W: Window Usage: Not Available Asset located in: Lake Worth, TX	
	S/N: GMPU9002935 C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8531	2024 7 ft Storage Container  S/N: GMPU9027851  C/W: Man Door, Window Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8525	<b>2024 9 ft Storage Container</b> S/N: GMPU9026027		Asset located in: Lake Worth, TX	
	C/W: Man Door, Window Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Lake Worth, TX	8532	2004 40 ft Storage Container S/N: 749036 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
8526	2024 9 ft Storage Container  S/N: GMPU9026285  C/W: Man Door, Window Usage: Not Available  Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT  Asset located in: Lake Worth, TX	8533	S/N: KKFU72268889 Usage: Not Available Notes: THE PRODUCT IMAGES SHO FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN THE ACTUAL PRODUCTHE PRODUC	2002 40 ft Storage Container S/N: KKFU72268889 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES
8527	2024 8 ft Storage Container S/N: GMPU9027893 C/W: Man Door, Window		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Asset located in: Huntsville, TX	
Usage: Not Available <b>Notes</b> : THE PRODUCT IMAGES SHOWN A FOR ILLUSTRATION PURPOSES ONLY AN	Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8534	2002 Storage Container S/N: XAH318284 Usage: Not Available Notes: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCTHE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	

Asset located in: Huntsville, TX

Lot #	Details	Lot #	Details
8535	40 ft High Cube Storage Container S/N: NYKU7937152 C/W: 2007 Carrier Transicold Reefer Unit Usage: Not Available Asset located in: Lake Worth, TX	8544	18 ft Roll-Off Container (Unused) S/N: C202462 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in: Lake Worth, TX
8536	Quantity of (6) 2022 Box Gang 22 ft 30 YD Roll-Off Container  S/N: Not Available  C/W: 22 ft Long x 8 ft Wide x 5 ft High,  EQUIPMENT-FROM-US-AUTO-RECYCLING  Usage: Not Available  Notes: .	8545 8546	17 ft Roll-Off Container (Unused) S/N: Not Available C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available Asset located in: Lake Worth, TX 17 ft Roll-Off Container (Unused) S/N: C202462
8537	Asset located in: Lake Worth, TX  Quantity of (4) 22 ft 30 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 5 ft High,	8547	C/W: 17 ft Long x 6 ft 8 in Wide x 3 ft 6 in High Usage: Not Available  Asset located in: Lake Worth, TX  Quantity of (2) Waste Container
	EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX		S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
8538	Quantity of (2) 2022 Box Gang 22 ft 40 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 6 ft 9 in High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8548	1956 Chevrolet Bel Air Classic Car S/N: VC56S103217 C/W: V8 4.3 L Gasoline Engine, Automatic Transmission, Air Conditioner Usage: 9,673 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - KEY;
8539	Quantity of (2) 22 ft 20 YD Roll-Off Container S/N: Not Available C/W: 22 ft Long x 8 ft Wide x 4 ft High, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: . Asset located in: Lake Worth, TX	8549	Asset located in: Lake Worth, TX  1976 Chevrolet Corvette Stingray Classic Car S/N: 1Z37L6S414551 C/W: V8 Gasoline Engine, Automatic Transmission, Power Windows Usage: 45,448 Mi Notes: ADDITIONAL INFORMATION
8540	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 5 in Wide x 4 ft 11 in High Usage: Not Available		AVAILABLE IN OFFICE - KEY; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
8541	Asset located in: Lake Worth, TX  16 ft Roll-Off Container (Unused)  S/N: Not Available  C/W: 16 ft Long x 7 ft 4 in Wide x 5 ft 8 in High  Usage: Not Available  Asset located in: Lake Worth, TX	8550	1976 Ford 4x2 Pickup S/N: F10GLB78702 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 20,841 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8542	16 ft Roll-Off Container (Unused) S/N: Not Available		TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX
	C/W: 16 ft Long x 7 ft 6 in Wide x 5 ft 8 in High Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8551	2015 Ford E350 4x2 14-Seat Passenger Van S/N: 1FDEE3FL1FDA16098 C/W: Air Conditioner, Automatic Transmission,
8543	18 ft Roll-Off Container (Unused) S/N: C202461 C/W: 18 ft Long x 7 ft 4 in Wide x 4 ft High Usage: Not Available Asset located in: Lake Worth, TX		Wheelchair Ramp, Wheelchair Lift, V8 5.4 L Gasoline Engine, 2014 US EPA Label, 225 /75R16, Spring Suspension, 158 in Wheelbase Usage: 103,717 Mi Notes: . Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8552	2019 Mercedes-Benz Sprinter Van Passenger Van S/N: WD3PF0CD3KT003689 C/W: 3.0 L Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, EQUIPMENT-FROM-A-PRIMORIS-	8558A	2018 Ford Fusion Automobile S/N: 3FA6P0HD1JR180576 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 83,930 Mi Asset located in: Lake Worth, TX
	SERVICES-CORP-COMPANY Usage: 167,464 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8559	2017 Nissan Altima Automobile S/N: 1N4AL3AP5HN317978 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 67,245 Mi
8553	2022 Chrysler Voyager Minivan S/N: 2C4RC1CG3NR103312 Usage: Not Available Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
8554	2011 Dodge Caravan SE Minivan S/N: 2D4RN5DG0BR682712 C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 169,386 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	8560	2016 Dodge Challenger Automobile S/N: 2C3CDZAG7GH256566 C/W: V6 3.6 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows Usage: 55,445 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A FLOODED BRAND ON THE TITLE Asset located in: Humble, TX
8555	2021 Nissan Sentra Automobile S/N: 3N1AB8BV5MY267560 C/W: 4 cyl 2.0 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 54,098 Mi Asset located in: Midland, TX	8561	2016 Kia Optima Automobile S/N: 5XXGT4L38GG043240 C/W: 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 176,089 Mi Asset located in: Lake Worth, TX
8556 8557	2019 Ford Fusion Automobile S/N: 3FA6P0HD8KR223201 C/W: 4 cyl 1.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 41,980 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2019 Kia Optima Automobile	8562	2015 Nissan Juke Automobile  S/N: JN8AF5MR0FT505833  C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 147,550 Mi  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT;TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Humble, TX
	S/N: 5XXGT4L3XKG357335 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	8563	2015 Chevrolet Impala Automobile S/N: 2G11Y5SN8F9263766 C/W: 6 cyl 3.6 L Gasoline Engine, 2015 US EPA
8558	2018 Chevrolet Malibu Automobile S/N: 1G1ZF5SU0JF291884 C/W: 4 cyl 1.8 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 50,772 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 92,389 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

	Details	Lot #	Details
Lot #		_	
8564	2014 Toyota Camry Automobile S/N: 4T4BF1FK5ER408856 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 138,538 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8570	2007 BMW 328I Automobile  S/N: WBAVC535X7FZ77345  C/W: 6 cyl Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 138,111 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
8565	2013 Nissan Sentra RS Automobile S/N: 3N1AB7AP4DL790448 C/W: 4 cyl 1.8 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, sunroof Usage: 127,946 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8571	2013 Jeep Wrangler 4WD 6-Door SUV S/N: 1C4HJWEG2DL570305 C/W: V6 3.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 57,484 Mi Notes: COMPLETE CUSTOM BUILD IN UTAH -
8566	TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX  2013 Mini Cooper Automobile		COMES WITH BLUE OX AVENTA LX MOTORHOME/COACH CUSHION TOW BAR; ALL DOORS AND TOPS ARE REMOVEABLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ADDITIONAL
0000	S/N: WMWSS5C53DWN49392 C/W: 4 cyl 1.6 L Gasoline Engine, 2013 US EPA		INFORMATION AVAILABLE IN OFFICE - KEY  Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 137,997 Mi <b>Asset located in</b> : Lake Worth, TX	8572	2018 Ford Expedition 4x4 SUV S/N: 1FMJU2ATXJEA25730 C/W: V6 3.5 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 130,626 Mi
8566A	2012 Subaru Outback AWD Automobile S/N: 4S4BRBLC3C3303630 C/W: 2.5 L Gasoline Engine, Automatic		
	Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 209,226 Mi		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	0572	2018 Nissan Pathfinder SV 2WD SUV
8567	2011 Mercedes-Benz E350 Automobile S/N: WDDGF5GB0BR142256 Usage: Not Available Asset located in: Lake Worth, TX	<b>8573</b>	S/N: 5N1DR2MN0JC605382 C/W: V6 3.5 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera Usage: 134,053 Mi
8568	<b>2011 Toyota Camry Automobile</b> S/N: 4T4BF3EK3BR115028		Asset located in: Lake Worth, TX
	C/W: 4 cyl 2.4 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX	8574	2017 Ford Escape S 2WD SUV S/N: 1FMCU0F70HUB26560 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 134,079 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8569	2008 Saab 9-3 Aero Automobile S/N: YS3FH41U081156520 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8575	2017 Ford Escape 2WD SUV S/N: 1FMCU0GD9HUE71445 C/W: 3 cyl 1.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 175,892 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8581	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC6GR252511 C/W: V8 5.3 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 202,310 Mi Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Humble, TX	8582	<b>2016 Nissan Rogue 2WD SUV</b> S/N: JN8AT2MT0GW019414
8576	2017 Chevrolet Traverse SUV S/N: 1GNKRFKDXHJ203590 Usage: 187,606 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		C/W: 4 cyl 2.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 143,099 Mi Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	8583	2016 Nissan Rogue SV SUV S/N: KNMAT2MT6GP624673 C/W: 4 cyl 2.5 L Gasoline Engine, 2015 US EPA
8577	2017 Chevrolet Trax 2WD SUV S/N: 3GNCJKSB6HL220642 C/W: 1.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 131,519 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 159,117 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX
	Asset located in: Humble, TX	8584	2016 Dodge Journey SUV
8578	2017 Chevrolet Tahoe 4WD SUV S/N: 1GNSKFEC1HR217144 C/W: V8 5.3 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks, Rear View Camera Usage: 152,407 Mi Asset located in: Lake Worth, TX		S/N: 3C4PDCAB6GT219191 C/W: 4 cyl 2.4 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 3rd Row Usage: 88,015 Mi Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Lake Worth, TX
8579	2016 Chevrolet Tahoe 4WD SUV		
	S/N: 1GNSKFEC8GR440859 C/W: V8 5.3 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 145,373 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8585	2016 Kia Soul Automobile  S/N: KNDJP3A52G7276905  C/W: 4 cyl 2.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 134,403 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE
8580	2016 Chevrolet Tahoe 2WD SUV S/N: 1GNLCDEC5GR437584 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 155,738 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE  Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8586	2015 Infiniti QX60 2WD SUV  S/N: 5N1AL0MN6FC525522  C/W: V6 3.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 132,145 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	8592 8593	2012 Ford Expedition 2WD SUV  S/N: 1FMJK1K58CEF12802  C/W: V8 5.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row, Towing Hitch Usage: 131,092 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; NTHIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE  Asset located in: Lake Worth, TX  2011 Jeep Grand Cherokee 2WD SUV  S/N: 1J4RS4GGXBC513599
8587	2015 Land Rover Range Rover 4WD SUV S/N: SALVP2BG7FH957087 C/W: 4 cyl Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 144,024 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	C/W: V6 3.6 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 168,573 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8588	Asset located in: Humble, TX  2015 Dodge Durango SUV  S/N: 1C4RDHDG1FC702143  Usage: Not Available  Asset located in: Lake Worth, TX	8594	2009 Chevrolet Suburban LT SUV S/N: 1GNFC26J89R299573 C/W: 6 cyl 5.3 L Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Towing Hitch Usage: 301,880 Mi
8589	39 2015 Chevrolet Tahoe LS 2WD SUV S/N: 1GNSCAKC2FR521634 C/W: V8 5.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: 144,233 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8595	Asset located in: Lake Worth, TX  2008 Land Rover LR2 2WD SUV  S/N: SALFP24N68H043304  C/W: 6 cyl 3.2 L Gasoline Engine, 2008 US EPA  Label, Automatic Transmission, Air  Conditioner, Power Windows  Usage: Not Available  Asset located in: Lake Worth, TX
8590 8591	TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2014 Chevrolet Tahoe 2WD SUV S/N: 1GNLC2E03ER162966 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 197,207 Mi Asset located in: Lake Worth, TX  2014 Audi Q7 2WD SUV (Inoperable)	8596	2007 Cadillac Escalade SUV  S/N: 1GYEC63867R384531  C/W: 6.2 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 137,706 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
	S/N: WA1LGAFE6ED011693 C/W: V6 3.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation, 3rd Row Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8597	2007 Jeep Grand Cherokee 4WD SUV S/N: 1J8HR78327C629860 Usage: Not Available Asset located in: Lake Worth, TX
		8598	2006 BMW X5 4WD SUV S/N: 5UXFA13596LY40272 C/W: V6 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 189,977 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX

	Detaile	1 -4 4	Detaile
Lot #	Details	Lot #	Details
8599	2006 Chevrolet Suburban LT 4WD SUV S/N: 1GNFK16Z86J170794 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row, Brush Guard and Rear Bumper., Towing Hitch Usage: 193,404 Mi	8605	2018 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BT1JEC94927 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11500 lb GVWR, 275/65R18 Tires, 8 ft Bed Usage: 44,439 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
0600	Asset located in: Midland, TX	4	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8600	<b>2006 Chevrolet Tahoe Z71 4WD SUV</b> S/N: 1GNEK13Z26R125089		Asset located in: Lake Worth, TX
	C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 229,606 Mi	8606	2018 Ford F-350 4x4 Crew Cab Pickup S/N: 1FD8W3H62JEB96227 C/W: EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING		Asset located in: Humble, TX
	WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	8607	2018 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT2JEC44330 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air
8601	2003 Lincoln Aviator 2WD SUV S/N: 5LMEU68H33ZJ43427 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 218,683 Mi		Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 11500 lb GVWR, 275/70R16 Tires, 8 ft Bed Usage: 186,195 Mi Asset located in: Humble, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX		2016 Ford F-350 4x4 Crew Cab Pickup S/N: 1FD8W3HT1GED26318 Usage: Not Available Asset located in: Lake Worth, TX
8602	2019 Chevrolet Silverado 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG9KF138086 C/W: V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 11000 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 79,152 Mi Asset located in: Lake Worth, TX	8609	2011 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT0BEC51343 C/W: 6.7 L V8 Diesel Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 11200 lb GVWR, 35x12.50R22 Tires, 8 ft Bed Usage: 106,357 Mi
8603	2019 Chevrolet 3500HD 4x4 Crew Cab Pickup S/N: 1GC4KVCG2KF227899		Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX
	W: 6.0 L V8 Gasoline Engine, Automatic ansmission, Air Conditioner, Power indows, Headache Rack, Tool Box, 11000 lb /WR, 275/70R18 Tires, 8 ft Bed sage: Not Available	8610	2003 GMC Sierra 3500HD 4x4 Crew Cab Pickup S/N: 1GTJK33183F161783 Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8611	1999 Ford F-350 4x4 Crew Cab Pickup
8604	2014 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KZCGXEF154345 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 245/75R17 Front Tires, 235/80R17 Rear Tires, Spring Suspension, 171 in Wheelbase, 9 ft 4 in x 92 in Bed Usage: 244,091 Mi Asset located in: Lake Worth, TX		S/N: 1FTSW31F2XEA09050 C/W: Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, 9900 lb GVWR, 295/60R20 Tires, 8 ft Bed Usage: 263,566 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8612	2013 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3CT8DEB22137 C/W: 6.7 L Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Spray-On Bed Liner, 14000.0 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 386,746 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8618	2023 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5DL0PG517224 C/W: 6.7 L V8 Diesel Engine, 2023 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 10000.0 lb GVWR, 37X12.50R20 Tires, 6 ft 4 in Bed Usage: 12,741 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
8613	2009 Ford F-350 XL 4x2 Crew Cab Pickup	8619	2021 Ram 2500 4x4 Crew Cab Pickup
	S/N: 1FTWW32Y29EA83928 C/W: 6.8 L V10 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 12600.0 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 57,245 Mi Asset located in: Lake Worth, TX	8619	S/N: 3C6UR5HJ7MG630043 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 65,623 Mi
8614	2009 Chevrolet Silverado 3500HD 4x2 Crew Cab Pickup		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;
	S/N: 1GCJC83619F178424 C/W: 6.6 L V8 Diesel Engine, Automatic		Asset located in: Lake Worth, TX
	Transmission, Air Conditioner, Power Windows, Dual Rear Wheel, Spray-On Bed Liner, 11400 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 368,242 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	8620	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ8MG631265 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY
8615	2024 GMC Sierra 3500HD 4x4 Pickup	-	Usage: 122,390 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
0010	S/N: 1GT39SE7XRF130995 C/W: 6.6 L V8 Gasoline Engine, 2024 US EPA Label, Automatic Transmission, Air		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
	Conditioner, Power Driver's Seat, Power Windows, 14000 lb GVWR, 235/80R17 Tires, 8 ft Bed Usage: 43,278 Mi <b>Asset located in</b> : Lake Worth, TX	8621	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ2MG631262 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air
8616	2015 GMC Sierra 3500HD 4x2 Utility Truck S/N: 1GD311CG4FZ538631 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235		Conditioner, Power Windows, Headache Rack, 275/70R18 Tires, 8 ft 1 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 176,662 Mi <b>Asset located in</b> : Lake Worth, TX
	/80R17, Spring Suspension, 10 ft Body Usage: 97,811 Mi	8622	2021 Ram 2500 4x4 Crew Cab Pickup
8617	2011 Ford F-350 XL 4x2 Pickup S/N: 1FTBF3A63BEC53993 C/W: 6.2 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 127,569 Mi Asset located in: Lake Worth, TX		S/N: 3C6UR5HJ5MG631241 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8623	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CJ3JG404410 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 96,524 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8627	2017 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL0HG589107 C/W: 6.7 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 6 ft 4 in Bed Usage: 196,427 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
8623A	2018 Ram 2500 4x4 Crew Cab Pickup	8628	2017 Ram 2500 4x4 Crew Cab Pickup
8623A	S/N: 3C6UR5HJOJG327360 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed		S/N: 3C6UR5CL9HG570121 C/W: 6.7 L 6 Cylinder Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 35X12.50R20 Tires, 6 ft 2 in Bed Usage: 133,929 Mi Asset located in: Lake Worth, TX
	Usage: 122,776 Mi	8629	2021 Ford F-250 King Ranch 4x4 Crew Cab
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX		Pickup S/N: 1FT7W2BT9MEC11318 C/W: 6.7 L V8 Diesel Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power
8624	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ6JG354370 C/W: 6.4 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 8 ft Bed		Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 10000 lb GVWR, 275 /65R20 Tires, 7 ft Bed Usage: 16,533 Mi Asset located in: Lake Worth, TX
	Usage: 167,897 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	S/N: 1FT7W2B63LEE12818 C/W: 6.2 L V8 Gasoline Engine, 202 Label, Automatic Transmission, Air	C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack,
8625	<b>2018 Ram 2500 4x4 Crew Cab Pickup</b> S/N: 3C6UR5CL8JG274920	1	PROTECH Tool Box, Spray-On Bed Liner, 100 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed Usage: 140,719 Mi
	C/W: 6.7 L Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 275/65R18 Tires, 6		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
	ft 4 in Bed Usage: 197,428 Mi	8631	2020 Ford F-250 4x4 Crew Cab Pickup
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: 1FT7W2B66LEE12831 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack,
0606	Asset located in: Lake Worth, TX	-	Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed
8626	2018 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CL3JG148321 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 2 in Bed Usage: 159,765 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		Usage: 153,207 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8632	632 2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B68KED41291 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 139,607 Mi	8637	2013 Ford F-250 Lariat 4x4 Crew Cab Pickup S/N: 1FT7W2BT3DEA48102 C/W: 6.7 L V8 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 10000 lb GVWR, 35x12.5R20 Tires, 6 ft 10 in Bed Usage: 226,784 Mi Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	8638	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19ME73MF197398 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows,
8633	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B63KEF04896 C/W: 6.2 L V8 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 6 ft 6 in Bed		Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 104,683 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Usage: 142,484 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8639	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE75MF221517 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows,
8634	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B6XKEF04796 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 176,645 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 119,305 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	8640	2021 GMC Sierra 2500HD 4x4 Crew Cab Picku S/N: 1GT19ME74MF197121
8635	2019 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2BT1KEE55378 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Sunroof, Better Built 100 gal Fuel Tank /w Pump, Drop-In Bed Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 8 in Bed Usage: 145,565 Mi		C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 106,361 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Midland, TX	8641	<b>2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup</b> S/N: 1GT19LE72MF223676
8636	2016 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2BT2GEA52971 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 7 ft Bed Usage: 121,086 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 109,870 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8642	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE73MF131055 C/W: 6.6 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 112,785 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8647	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF135301 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 105,910 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
06.40	Asset located in: Lake Worth, TX	8648	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup
8643	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223689 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 115,084 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: 1GT12NEG8KF128147 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 103,405 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8649	2019 GMC Sierra 2500 4x4 Crew Cab Pickup
8644	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF222266 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,468 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: 1GT12NEG5KF172137 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 117,114 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Asset located in: Lake Worth, TX	0650	Asset located in: Lake Worth, TX
8645	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT19LE70MF223837 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Rawson Koenig Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 118,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	-8650 -8651	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG9KF243775 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 9900 lb GVWR, 265 /70R17 Tires, 8 ft Bed, EQUIPMENT-FROMWATKINS-CONSTRUCTION Usage: 121,440 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX 2019 GMC Sierra 2500 4x4 Crew Cab Pickup
8646	2021 GMC Sierra 2500HD 4x4 Crew Cab Pickup	0001	S/N: 1GT12NEG7KF143089
	S/N: 1GT19LE79MF223755 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: 131,224 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, Tool Box, 265 /70R17 Tires, 8 ft 2 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 130,846 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8652	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEGXKF172537 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 265/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 121,433 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8657	2016 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12RE87GF259741 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 169,025 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
8653	2019 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12NEG5KF273565 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank, RKI Tool Box, 9900 lb GVWR, 245 /75R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION	8658	2014 GMC Sierra 2500HD 4x4 Crew Cab Picks S/N: 1GT12ZCG9EF123876 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 9900 lb GVWR, 269 /70R17 Tires, 8 ft Bed Usage: 162,483 Mi Asset located in: Lake Worth, TX
	Usage: 121,235 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		2019 Chevrolet Silverado 2500HD LT 4x4 Crew Cab Pickup S/N: 1GC1KSEY0KF118493 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's
8654	2018 GMC Sierra 2500 4x4 Crew Cab Pickup S/N: 1GT12REG3JF174233 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-		Seat, Power Windows, Fuel Tank, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	WATKINS-CONSTRUCTION Usage: 128,754 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		2019 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KSEG2KF213547 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 245
8655	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG6JF173030 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power		/75R17 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: 138,145 Mi <b>Asset located in</b> : Lake Worth, TX
	Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 156,754 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX	8661	2019 Chevrolet 2500HD Z71 4x4 Crew Cab Pickup S/N: 1GC1KTEG8KF220198 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 9500 lb
8656	2018 GMC Sierra 2500HD 4x4 Crew Cab Pickup S/N: 1GT12REG5JF173486 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Tool Box, 265 /70R17 Tires, 8 ft Bed Usage: 158,292 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX		GVWR, 275/65R18 Tires, 6 ft Bed, EQUIPMENT FROM-SUNSTATE-EQUIPMENT Usage: 144,285 Mi <b>Asset located in</b> : Lake Worth, TX

	B : 1	T	B
Lot #	Details	Lot #	Details
8662	2017 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KUEG5HF192312 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 128,022 Mi	8668	2018 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A69JEC58484 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weatherguard Tool Box, 10000 lb GVWR, 265/70R15 Tires, 8 ft Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 157,129 Mi Asset located in: Humble, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	8670	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A61HEE08405 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air
8663	2017 Chevrolet Silverado 2500 HD LT Z71 4x4 Crew Cab Pickup S/N: 1GC1KVEG8HF198725 C/W: 6.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 6 ft Bed, Wireless Charging		Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 176,168 Mi  Asset located in: Humble, TX  2015 Ford F-250 4x2 Crew Cab Pickup
	Usage: 149,617 Mi  Asset located in: Lake Worth, TX		S/N: 1FT7W2A64FEC22645 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather
8664	2012 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC1KVCG5CF145928 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 9900 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 322,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 268,869 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX		S/N: 1FT7W2A69EEB42367
8665	2012 Dodge Ram 2500 4x4 Crew Cab Pickup S/N: 3C6TD5JT7CG347856 C/W: 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, 8000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 218,934 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear Power Lift Gate, Aluminum Truck Cap, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 173,752 Hr  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Midland, TX
8667	2019 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A66KED56261 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 122,599 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	8672	2021 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ6MG648396 C/W: 6.4 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 166,144 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8673	2019 Ram 2500 4x2 Crew Cab Flatbed Truck S/N: 3C6UR4HJ5KG590150 C/W: V8 6.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 5500 lb Front Axle, 6390 lb Rears, 10000 lb GVWR, 275 /70R18, Spring Suspension, 170 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: 158,739 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8679	2015 Chevrolet 2500HD 4x4 Crew Cab Pickup S/N: 1GC1KWE89FF640746 C/W: 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 7 in Bed Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A BONDED TITLE;
80/4	<b>2019 Ram 2500 4x2 Crew Cab Pickup</b> S/N: 3C6UR4HJ6KG603858		Asset located in: Lake Worth, TX
	C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6800.0 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: 170,384 Mi <b>Notes</b> : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8680	2020 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B68LEC63951 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 166,422 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
0675	Asset located in: Lake Worth, TX	$\dashv$	TO SIGN REQUIRED DOCUMENTS TO
8675	<b>2019 Ram 2500 4x2 Crew Cab Pickup</b> S/N: 3C6UR4HJXKG643411	8680A	PROCESS TITLE  Asset located in: Lake Worth, TX
	Usage: 224,960 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2016 Ford F-250 4x4 Extended Cab Pickup S/N: 1FT7X2BT8GEC22330 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power
8676	2019 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ7KG631829 C/W: 6.4 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed		Windows, Spray-On Bed Liner, 10000 lb GVWR, 8 ft Bed Usage: 154,291 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Usage: 180,148 Mi <b>Asset located in</b> : Lake Worth, TX	8681	2015 Ford F-250 XL 4x4 Extended Cab Pickup
8677	2018 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ1JG188981 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 275/70R18 Tires Usage: 204,579 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE		S/N: 1FT7X2B61FEB25480 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rac Weather Guard Fuel Tank /w Pump, Tractor Supply Co Tool Box, Spray-On Bed Liner, 100 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: 111,775 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Asset located in: Lake Worth, TX	<u> </u>	Asset located in: Lake Worth, TX
8678	2018 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ8JG287331 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Fuel Tank, Weather Guard Tool Box, 10000 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 175,042 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8682	2015 Ford F-250 XL 4x4 Extended Cab Pickup S/N: 1FT7X2B61FEC04213 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 320,450 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8683	2018 Chevrolet Silverado 2500 HD 4x4 Dual Cab Pickup S/N: 1GC2KWEG9JZ193614 C/W: 6.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 9500 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 162,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8688	2016 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FT7X2A69GEC19075 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 10000.0 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 199,413 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8689	2016 Ford F-250 XL 4x2 Extended Cab Pickup
8684	2016 Chevrolet 2500HD 4x4 Extended Cab Pickup S/N: 1GC2KUEG4GZ109955 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 9500.0 lb GVWR, 8 ft Bed Usage: 355,555 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		S/N: 1FT7X2A69GEB70864 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 10 in Bed Usage: 201,688 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	PROCESS TITLE  Asset located in: Lake Worth, TX	8690	2014 Ford F-250 4x2 Extended Cab Pickup
8685	2015 GMC 2500 4x4 Extended Cab Pickup S/N: 1GT22XEG0FZ106115 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, RKI Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		S/N: 1FT7X2A66EEB24227 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, GPI Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 195,848 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8686	2017 Ford F-250 XL 4x2 Extended Cab Pickup	8691	2014 Ford F-250 XL 4x2 Extended Cab Pickup
	S/N: 1FT7X2A64HEF24694 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8691	S/N: 1FT7X2A6XEEA58748 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, WeatherGuard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 312,914 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE
	PROCESS TITLE  Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
8687	2017 Ford F-250 XL 4x2 Extended Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1FT7X2A65HEB28242 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 238,717 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8692	2014 Ford F-250 4x2 Extended Cab Pickup S/N: 1FT7X2A67EEB17769 C/W: 6.2 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 191,870 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8693	2012 Chevrolet Silverado 2500HD 4x2 Extended Cab Pickup S/N: 1GC2VC83CZ320119 C/W: 6.6 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 6 ft 7 in Bed Usage: 279,928 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	8698	2013 Ford F-250 4x2 Pickup S/N: 1FTBF2A60DEB82104 C/W: 6.2 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Truck Cap, 10000 lb GVWR, 245/70R17 Tires Usage: 81,563 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2012 Chevrolet Silverado 2500 HD LS 4x2
24224	Asset located in: Lake Worth, TX	-	Pickup S/N: 1GC0CVCG6CF138379
8693A	2008 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FTSX20578EE54529 C/W: 5.4 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, 9200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 331,802 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		C/W: 6.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 8 ft 3 in Bed Usage: 223,391 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8700	2022 GMC Sierra 1500 4x4 Crew Cab Pickup
8694	<b>2020 Ram 2500 4x4 Pickup</b> S/N: 3C6MR5AJ9LG164012 C/W: V8 Engine, Automatic Transmission	1	S/N: 1GTU9DED3NZ162699 Usage: Not Available
			Asset located in: Lake Worth, TX
	Usage: 102,553 Mi  Asset located in: Lake Worth, TX	8701	<b>2021 GMC Sierra 1500 4x4 Crew Cab Pickup</b> S/N: 3GTU9DED4MG242107
8695 8696	2020 Ram 2500 4x4 Pickup S/N: 3C6MR5AJ5LG164010 C/W: V8 Engine, Automatic Transmission Usage: 107,621 Mi Asset located in: Lake Worth, TX 2017 Chevrolet Silverado 2500 HD 4x4 Pickup		C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FRO WATKINS-CONSTRUCTION Usage: 97,407 Mi Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS
	S/N: 1GC0KUEG2HZ225955 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 99,657 Mi	8702	Asset located in: Lake Worth, TX  2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DEDXMG239485
	Asset located in: Lake Worth, TX		C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's
8697	2015 Ram 2500 4x2 Pickup S/N: 3C6LR4AT0FG649313 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9000 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 106,565 Mi	8703	Seat, Power Windows, 7100 lb GVWR, 275 /60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 107,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX		2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED3MG200127 C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's
8697A	2015 Ford F-250 4x2 Pickup S/N: 1FTBF2ATXFEA40769 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 255/70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 117,144 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX

		Details
2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED6MG240892 Usage: Not Available Asset located in: Lake Worth, TX	8707	2014 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU2TECXEG385182 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air
2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED2MG205545 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION		Conditioner, Power Windows, 265/70R17 Tires, 5 ft 9 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 127,548 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
Usage: 109,324 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8708	2016 Chevrolet Silverado 1500 LT 4x4 Crew Cab Pickup S/N: 1GCUKREC4GF141714 C/W: 5.3 L V8 Gasoline Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's
2021 GMC Sierra 1500 Crew Cab 4x4 Pickup S/N: 3GTU9BED7MG203323 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO		Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Decked Tool Box, Drop-In Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 263,036 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
PROCESS TITLE		Asset located in: Midland, TX
2020 GMC Sierra 1500 4x4 Crew Cab Denali Pickup S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7100 lb GVWR, 5 ft 7 in Bed	<b>–</b> 8709	2020 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFLT1LN227445 Usage: Not Available Asset located in: Lake Worth, TX
	8709A	2020 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFLT1LN333989 Usage: Not Available Asset located in: Lake Worth, TX
Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8710	2019 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFFT7KN714613 C/W: 5.7 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air
2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Drop-In Bed Liner, 7000 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 113,313 Mi		Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 7100.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 129,734 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX		2019 Ram 1500 Big Horn 4x4 Crew Cab Picku S/N: 1C6SRFFT3KN739606 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100.0 lb GVWR, 285/65R18 Tires, 5 ft 3 in Bed Usage: 196,574 Mi Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED0LG267777 Usage: Not Available Asset located in: Lake Worth, TX		
	S/N: 3GTU9DED6MG240892 Usage: Not Available Asset located in: Lake Worth, TX  2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED2MG205545 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 109,324 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2021 GMC Sierra 1500 Crew Cab 4x4 Pickup S/N: 3GTU9BED7MG203323 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2020 GMC Sierra 1500 4x4 Crew Cab Denali Pickup S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7100 lb GVWR, 5 ft 7 in Bed Usage: 98,858 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Sliding Rear Window, Drop-In Bed Liner, 7000 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 113,313 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED0LG267777 Usage: Not Available	S/N: 3GTU9DED6MG240892 Usage: Not Available Asset located in: Lake Worth, TX  2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9BED2MG205545 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Drive's Seat, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 109,324 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2021 GMC Sierra 1500 Crew Cab 4x4 Pickup S/N: 3GTU9BED7MG203323 C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2020 GMC Sierra 1500 4x4 Crew Cab Denali Pickup S/N: 1GTU9FEL4LZ152697 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Spray-On Bed Liner, 7100 lb GVWR, 5 ft 7 in Bed Usage: 98,858 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTP9EEL1LZ336096 C/W: 6.2 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Power Bliding Rear Window, Drop-In Bed Liner, 7000 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- WATKINS-CONSTRUCTION Usage: 113,313 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2020 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 3GTU9DED0LG267777 Usage: Not Available

1 04 #	Dataila	1 #	Detaile
Lot #	Details	Lot #	Details
8712	2019 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6SRFJT8KN822441 Usage: Not Available Asset located in: Lake Worth, TX	8718	2016 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFDW5F17GX526706 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air
8713	2017 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7LT4HS620059 Usage: Not Available Asset located in: Lake Worth, TX		Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray- On Bed Liner, 7200.0 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 323,409 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8714	2016 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7MT0GS416856 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tonneau Cover, Spray-On Bed Liner, 6900 lb GVWR, 6 ft 5 in Bed, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 88,711 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		2018 Nissan Titan Platinum Reserve 4x4 Crew Cab Pickup S/N: 1N6AA1E55JN509451 C/W: 5.6 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Tool Box, Spray-On Bed Liner, 7300 lb GVWR, 275 /60R20 Tires, 5 ft 7 in Bed Usage: 2,600 Mi
8715	5 2018 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F19JX740667 C/W: 5.7 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR,		Notes: TEXAS BUYERS MUST STOP IN OFF TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; ODOMET DISCREPENCY - ODOMETER SHOWS 2600 TITLE SHOWS 105570 Asset located in: Lake Worth, TX
	275/70R18 Tires, 5 ft 7 in Bed Usage: 260,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8720	2021 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E55MKD34831 C/W: 5.0 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed
8716	2017 Toyota Tundra SR5 4x4 Crew Cab Pickup S/N: 5TFUW5F16HX610386 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Spray-On Bed Liner, 7100 lb GVWR, 275 /55R20 Tires, 6 ft Bed Usage: 262,750 Mi		Liner, 7050.0 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 96,289 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8721	2020 Ford F-150 XL 4x4 Crew Cab Pickup
8717	2016 Toyota Tundra 4x4 Crew Cab Pickup S/N: 5TFDW5F12GX506041 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 285/65R18 Tires, 5 ft 6 in Bed Usage: 276,601 Mi Asset located in: Lake Worth, TX		S/N: 1FTEW1E58LKD34168 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 245/70R17 Tires, 5 ft 7 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 96,164 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8722	2020 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1E53LKD47734 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Protech Tool Box, Spray-On Bed Liner, 7000 lb GVWR, 265 /70R17 Tires, 5 ft 6 in Bed Usage: 121,047 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8728	2016 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTEW1EF5GFA47779 C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 155,109 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8723	2020 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTEW1E52LKE45508 Usage: Not Available Asset located in: Lake Worth, TX	8729	2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF4EKF62314 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power
8724	2019 Ford F-150 STX 4x4 Crew Cab Pickup S/N: 1FTEW1E56KKC96325 C/W: 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7000.0 lb GVWR, 275/55R20 Tires, 5 ft 6 in Bed Usage: 90,968 Mi		Windows, 7350 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 99,175 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2014 Ford F-150 XLT 4x4 Crew Cab Pickup
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	8730	S/N: 1FTFW1EF3EFA28438 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power
8725	2019 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1E49KKC43100 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 140,907 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		Windows, Spray-On Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 6 in Bed Usage: 167,074 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
<b>Notes</b> : T TO SIGN PROCES		8731	2013 Ford F-150 Raptor 4x4 Crew Cab Pickup S/N: 1FTFW1R66DFA62527 Usage: Not Available Asset located in: Lake Worth, TX
8726	2018 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1EG1JKD95560 C/W: 3.5 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 245/75R17 Tires, 7 ft Bed Usage: 124,873 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8732	2013 Ford F-150 XL 4x4 Crew Cab Pickup S/N: 1FTFW1ET9DKF21987 C/W: 3.5 L V6 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Better Built Tool Box, 7200 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 100,112 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
S/N: 1FTEW1EP9HFE Usage: Not Available	2017 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTEW1EP9HFB20551 Usage: Not Available Asset located in: Lake Worth, TX	8733	Asset located in: Lake Worth, TX  2013 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1EF8DKF76148 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Drop-In Bed Liner, 7350 lb GVWR, 275/65R18 Tires, 5 ft 5 in Bed Usage: 289,799 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8735	735 2011 Dodge Ram 1500 4x4 Crew Cab Pickup S/N: 1D7RV1GT9BS552169 C/W: V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6700 lb GVWR, 275/65R20 Tires, 6 ft 8 in Bed Usage: 154,689 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8740	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1E52JKE26129 Usage: Not Available Asset located in: Lake Worth, TX
		8741	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1E58JFD71503 Usage: Not Available Asset located in: Lake Worth, TX
	PROCESS TITLE; ODOMETER DISCREPENCY - ODOMETER SHOWS 154689 TITLE SHOWS 155742 Asset located in: Lake Worth, TX	8742	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKE23730 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA
8736	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CP5JKD52645 C/W: 2.7 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, 6360 lb GVWR, 265 /60R18 Tires, 5 ft 8 in Bed		Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 8 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 86,433 Mi Asset located in: Humble, TX
	Usage: 121,549 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; ODOMETER DISCREPANCY- UNIT SHOWS 121,549, TITLE SHOWS 139,907 Asset located in: Humble, TX	8743 2017 Ford F-150 XL 4x2 Crew Cab P S/N: 1FTEW1CF5HKC49971 C/W: 5.0 L Gasoline Engine, 2017 US Label, Automatic Transmission, Air Conditioner, Power Windows, Tonne Spray-On Bed Liner, 6800 lb GVWR, 2 Tires, 5 ft 6 in Bed Usage: 119,231 Mi Notes: TEXAS BUYERS MUST STOP TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  8744 2017 Ford F-150 XLT 4x2 Crew Cab S/N: 1FTEW1CF0HKE23722 C/W: 5.0 L V8 Gasoline Engine, 2017 Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Box, Spray-On Bed Liner, 6800 lb GV /70R17 Tires, 4 ft 6 in Bed, EQUIPME PULICE-CONSTRUCTION Usage: 119,473 Mi Asset located in: Humble, TX  8745 2017 Ford F-150 XLT 4x2 Crew Cab S/N: 1FTEW1CF2HKE53076 C/W: 5.0 L V8 Gasoline Engine, 2017 Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power	C/W: 5.0 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17
8737	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C56JKC10769 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power		Usage: 119,231 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Windows, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 145,418 Hr Asset located in: Humble, TX		C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool
8738	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C52JKC10770 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power		/70R17 Tires, 4 ft 6 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 119,473 Mi
	Adjustable Pedals, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 146,917 Mi  Asset located in: Humble, TX		C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265
8739	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1C54JKC10768 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Weatherguard Tool Box, Drop-In Bed Liner, 6950 Ib GVWR, 265/70R18 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 120,300 Mi Asset located in: Humble, TX		Usage: 140,099 Mi

Lot #	Details	Lot #	Details	
8746	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF6HKE23725 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 5 in Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 142,764 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8751	2014 Ford F-150 XL 4x2 Crew Cab Pickup S/N: 1FTFW1CFXEKG11583 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, Tool Box, Spray- On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 322,798 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
8747	2017 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1CP8HKD86640 C/W: 2.7 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6260 lb GVWR, 275/55R20 Tires, 5 ft 5 in Bed Usage: 199,080 Mi Asset located in: Lake Worth, TX	<b>–</b> 8752	2019 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFRM5F17KX141585 C/W: 4.6 L V8 Gasoline Engine, 2019 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Craftsman Tool Box, Spray-On Bed Liner, 6700 lb GVWR, 275/70R18 Tires, 6 ft Bed Usage: 195,476 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	
8748	<b>2016 Ford F-150 XL 4x2 Crew Cab Pickup</b> S/N: 1FTEW1CF9GKF65372		PROCESS TITLE  Asset located in: Lake Worth, TX	
C/W: 5.0 L Label, Aut Condition Fuel Tank 6950 lb G' Usage: 19 <b>Notes</b> : TE	C/W: 5.0 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, 6950 lb GVWR, 255/70R17 Tires, 6 ft 5 in Bed Usage: 196,241 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8753	2019 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFRM5F18KX141630 Usage: 291,345 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
	PROCESS TITLE  Asset located in: Lake Worth, TX	8754	<b>2016 Ram 1500 SLT 4x2 Crew Cab Pickup</b> S/N: 1C6RR6GG7GS403918	
8749	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF4EKG33790 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 129,930 Mi Asset located in: Humble, TX		C/W: 3.6 L V Label, Auton Conditioner, Windows, 68 3 in Bed Usage: 67,06 <b>Notes</b> : TEXA	C/W: 3.6 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, 6800 lb GVWR, 275/55R20 Tires, 6 ft 3 in Bed Usage: 67,066 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8750	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF3EKG33800 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed, EQUIPMENT-FROM-PULICE-CONSTRUCTION Usage: 133,616 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8755	2014 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6KM8ES408801 C/W: 3.0 L V6 Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 5 ft 10 in Bed Usage: 266,474 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
	Asset located in: Humble, TX	8756	2014 GMC Sierra 1500 4x2 Crew Cab Pickup S/N: 3GTP1UEC6EG110768 C/W: 5.3 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7000 lb GVWR, 275/55R20 Tires, 6 ft 7 in Bed Usage: 216,631 Hr Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
8757	2010 Toyota Tundra 4x2 Crew Cab Pickup S/N: 5TFTM5F17AX001055 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 255/70R18 Tires, 8 ft Bed Usage: 244,207 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8762	2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC6HZ350529 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 189,063 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8758	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEHXMZ203075 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 107,212 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8763	2015 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKPEH5FZ173329 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, Drop-In Bed Liner, 7100.0 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 91,050 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; NOT ACTUAL MILEAGE Asset located in: Lake Worth, TX
8759	2021 GMC Sierra 1500 4x4 Crew Cab Pickup S/N: 1GTR9AEH4MZ201452 C/W: 4.3 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKI Tool Box, 7000 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 113,431 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8764	2015 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKREC2FZ382091 C/W: 5.3 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 231,215 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8760	2019 Chevrolet Silverado 1500 LT 4x4 Dual Cab Pickup S/N: 1GCRYDED9KZ191418 C/W: 5.3 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 7000 lb GVWR, 265/65R18 Tires, 6 ft 8 in Bed Usage: 148,223 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8765	2018 GMC Sierra 1500 4x4 Extended Cab Pickup S/N: 1GTV2LEC5JZ370765 C/W: 5.3 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, 7200 lb GVWR, 265/70R17 Tires, 6 ft 9 in Bed, EQUIPMENT-FROM-5J-GROUP Usage: 227,149 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
8761	2017 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEC3HZ107938 C/W: 5.3 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 7200 lb GVWR, 295/55R20 Tires, 6 ft 6 in Bed, EQUIPMENT-FROM-HERC-RENTALS Usage: 63,030 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT EQUIPMENT FROM HERC RENTALS; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	8766	2016 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7FT9GS207693 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 285/70R17 Tires, 6 ft Bed Usage: 177,486 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX

Details 2015 Ram 1500 4x4 Dual Cab Pickup	Lot #	Details
2015 Pam 1500 AvA Dual Cab Dickup		
S/N: 1C6RR7GMXFS671274 C/W: 3.0 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6950 lb GVWR, 35x12.5R20 Tires, 6 ft 3 in Bed Usage: 137,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8773	2004 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V84Z272706 C/W: 4.8 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 245/75R16 Tires, 6 ft 10 in Bed Usage: 172,966 Mi Asset located in: Lake Worth, TX
Asset located in: Lake Worth, TX	8774	2021 Chevrolet Silverado 4x2 Extended Cab
2015 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7GT4FS643767 Usage: Not Available Asset located in: Lake Worth, TX		Pickup S/N: 1GCRWAEH8MZ261016 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
2018 Ford F-150 XL 4x4 Extended Cab Pickup		Asset located in: Lake Worth, TX
C/W: 5.0 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 7 in	8775	2014 Chevrolet Silverado 1500 4x2 Extended Cab Pickup S/N: 1GCRCPEC8EZ211055 Usage: Not Available Asset located in: Lake Worth, TX
Usage: 149,967 Mi	8776	2019 Ford F-150 XL 4x2 Extended Cab Pickup
Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		S/N: 1FTEX1C43KKE83254 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 255/70R18 Tires, 6 ft 6 in Bed Usage: 139,472 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
Asset located in: Lake Worth, TX		
70 2016 Ford F-150 XLT 4x4 Extended Cab Pickup S/N: 1FTFX1EF6GFB81556 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7050 lb GVWR, 265/70R17 Tires, 7 ft Bed		
Notes: TEXAS BUYERS MUST STOP IN OFFICE	8777	2018 Ford F-150 XL 4x2 Extended Cab Pickup
PROCESS TITLE  Asset located in: Lake Worth, TX		S/N: 1FTEX1C56JKF84490 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air
2012 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EM1CFC36807 C/W: 3.7 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner		Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 4 in Bed Usage: 135,767 Mi
Spray-On Bed Liner, 6900 lb GVWR, 275/65R18 Tires, 6 ft 10 in Bed		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
2006 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V36Z259882 C/W: 4.8 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed	8778	2018 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C55JKF84478 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 172,916 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
_	C/W: 3.0 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6950 lb GVWR, 35x12.5R20 Tires, 6 ft 3 in Bed Usage: 137,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2015 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7GT4FS643767 Usage: Not Available Asset located in: Lake Worth, TX  2018 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E53JKE13763 C/W: 5.0 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 149,967 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2016 Ford F-150 XLT 4x4 Extended Cab Pickup S/N: 1FTFX1EF6GFB81556 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7050 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 127,639 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2012 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EM1CFC36807 C/W: 3.7 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 275/65R18 Tires, 6 ft 10 in Bed Usage: 84,649 Mi Asset located in: Lake Worth, TX  2006 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V36Z259882 C/W: 4.8 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 6 ft 6 in	C/W: 3.0 L V6 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6950 lb GVWR, 35x12.5R20 Tires, 6 ft 3 in Bed Usage: 137,629 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2015 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7GT4FS643767 Usage: Not Available Asset located in: Lake Worth, TX  2018 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1E53JKE13763 C/W: 5.0 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 7 in Bed Usage: 149,967 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2016 Ford F-150 XLT 4x4 Extended Cab Pickup S/N: 1FTFX1EF6GFB81556 C/W: 5.0 L 6 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7050 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 127,639 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2012 Ford F-150 4x4 Extended Cab Pickup S/N: 1FTEX1EM1CFC36807 C/W: 3.7 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6900 lb GVWR, 275/65R18 Tires, 6 ft 10 in Bed Usage: 84,649 Mi Asset located in: Lake Worth, TX  2006 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCEK19V36Z259882 C/W: 4.8 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 6 ft 6 in

Details	Lot #	Details
2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C89HKC50152 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 5 in Bed Usage: 169,011 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE	8785	2005 Chevrolet Silverado 1500 4x4 Pickup S/N: 1GCEK14V55Z288807 C/W: 4.8 L V8 Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft 5 in Bed Usage: 99,043 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
PROCESS TITLE		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
		Asset located in: Lake Worth, TX
S/N: 1FTEX1CFXFKE52008 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 199,497 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO	8786	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH3FZ285656 C/W: 4.3 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 125,012 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
		Asset located in: Lake Worth, TX
2015 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CF9FKE51996 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 219,104 Mi	8787	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH5FZ270933 C/W: 4.3 L V6 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed, Pump, Tank, Reel Usage: 194,254 Mi Asset located in: Humble, TX
TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX	8788	<b>2014 Chevrolet Silverado 1500 4x2 Pickup</b> S/N: 1GCNCPEH7EZ346442 C/W: 4.3 L V6 Gasoline Engine, 2014 US EPA
2014 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTFX1CF8EKF95610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi		Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6700 lb GVWR, 265/70R17 Tires, 8 ft 6 in Bed Usage: 114,136 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX
Notes: TEXAS BUYERS MUST STOP IN OFFICE	8789	2013 Chevrolet 1500 4x2 Pickup
PROCESS TITLE	0,05	S/N: 1GCNCPEA5DZ356873
Asset located in: Lake Worth, TX	_	C/W: 4.8 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air
2010 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CWXAFB90668 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray- On Bed Liner, 6700 lb GVWR, 235/75R17 Tires, 6 ft 5 in Bed Usage: 215,747 Mi		Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 6400 lb GVWR, 265/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: 74,650 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE; TEXAS BUYERS MUST STOP IN
		OFFICE TO SIGN REQUIRED DOCUMENTS; ODOMETER DISCREPANCY-UNIT SHOWS
Usage: 215,747 Mi		OFFICE TO SIGN REQUIRED DOCUMENTS;
	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C89HKC50152 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 5 in Bed Usage: 169,011 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2015 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CFXFKE52008 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 199,497 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2015 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CF9FKE51996 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 219,104 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2014 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CFSPKE59610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2010 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CFSPKEPS610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C89HKC50152 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 5 in Bed Usage: 169,011 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2015 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CFXFKE52008 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 199,497 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2015 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTEX1CF9FKE51996 C/W: 5.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 219,104 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2014 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTFX1CF8EKF95610 C/W: 5.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, weather guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft 7 in Bed Usage: 209,297 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  2010 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEXICWXAFB90668 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air

Lot #	Details	Lot #	Details
8790	2020 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1C50LKD46068 C/W: 5.0 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6750 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 124,533 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8796	2022 Ford Ranger 4x2 Crew Cab Pickup S/N: 1FTER4EH5NLD35536 C/W: 2.3 L 4 Cylinder Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 3500 lb GVWR, 265/70R16 Tires, 5 ft Bed Usage: 20,876 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8791	2018 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1E55JKF44493 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray- On Bed Liner, 6950 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 140,414 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8797	2021 Chevrolet Colorado 4x2 Crew Cab Pickup S/N: 1GCGSCEN1M1296032 C/W: 2.5 L V6 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 5800 lb GVWR, 255/65R17 Tires, 5 ft Bed Usage: 47,944 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;  Asset located in: Lake Worth, TX
8792	2017 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1CF4HKD34876 C/W: 5.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, protech Tool Box, Spray-On Bed Liner, 6750 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 117,485 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	8798	2022 Chevrolet Colorado 4x2 Extended Cab Pickup S/N: 1GCHSBEA4N1311703 C/W: Automatic Transmission, Air Conditioner, Power Windows, 255/65R17 Tires, 6 ft 2 in Bed Usage: 34,661 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8793	2010 Ford F-150 4x2 Pickup S/N: 1FTMF1CW8AKE17930 C/W: 4.7 L V6 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6750 lb GVWR, 235/75R17 Tires, 8 ft 5 in Bed Usage: 126,592 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8799	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN724934 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Stainless Steel Truck Cap, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 84,482 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
8794	2003 Ford F-150 4x2 Pickup S/N: 2FTRF17L83CB00193 C/W: 5.4 L V8 Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6050 lb GVWR, 235/75R16 Tires, 8 ft 4 in Bed Usage: 94,369 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8800	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE5LN721727 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 103,120 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8795	1989 GMC Sierra 2500 4x2 Pickup S/N: 1GTFC24C1KE543722 C/W: V8 Diesel Engine, 4 Speed Manual Transmission, Drop-In Bed Liner, 72000 lb GVWR, 225/75R16 Tires, 8 ft Bed, EQUIPMENT- FROM-YELLOW-CORP Usage: 113,113 Mi Asset located in: Midland, TX		

Lot #	Details	Lot #	Details
8801	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE3LN719166 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 100,824 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8807	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CTXHN757261 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 118,621 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
8802	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE1LN721059 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 101,844 Mi Asset located in: Lake Worth, TX	8808	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT3HN721511 C/W: 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 4700.0 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 127,844 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE
8803	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE1LN721210		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;  Asset located in: Lake Worth, TX
	C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 109,927 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8809	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19CNC000009 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 2 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE
8804	2020 Nissan Frontier 4x2 Extended Cab Pickup		DOCUMENT SECTION.
	S/N: 1N6ED0CE3LN721807 C/W: V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/70R16 Tires, 6 ft 2 in Bed Usage: 111,655 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8810	Asset located in: Lake Worth, TX  2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000010 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 4 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.
8805	2020 Nissan Frontier 4x2 Extended Cab Pickup		Asset located in: Lake Worth, TX
	S/N: 1N6ED0CE9LN721892 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6012 lb GVWR, 265/75R16 Tires, 6 ft Bed Usage: 116,183 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	8811	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19KNC000024 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8806	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT1HN724360 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft 6 in Bed Usage: 103,998 Mi  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;  Asset located in: Lake Worth, TX	8812	2022 Kandi K32S-B Utility Vehicle (Unused) S/N: A074EA19PNC000006 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 12 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8813	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19JNC000011 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 13 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8819	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19TNC000005 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX
8814	2022 Kandi K32S-GY Utility Vehicle (Unused)	8820	2022 Kandi K32S-W Utility Vehicle (Unused)
	S/N: A074EA19PNC000023 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.		S/N: A074EA19TNC000022 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch, Charger Usage: 16 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION.
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8815	2022 Kandi K32S-GY Utility Vehicle (Unused) S/N: A074EA19ANC000014 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 14 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8821	Subaru Sambar 4x4 COE Flatbed Truck S/N: TT2096235 C/W: Subaru Clover4 4 Cylinder Gasoline Engine, 5-Speed Manual Transmission, 145R12, Spring Suspension, 74 in Wheelbase, 77 ft x 55 in Bed Usage: 98,817 Mi Notes: **This item is right hand drive** Asset located in: Humble, TX
8816		8822	2022 Peterbilt 579 6x2 S/A Day Cab Truck
	2022 Kandi K32S-R Utility Vehicle (Unused)  S/N: A074EA19KNC000007  C/W: Enclosed Cab, Air Conditioner, 4  Passenger, Windshield, Winch  Usage: 9 Mi  Notes: ***FOR OFF ROAD USE ONLY***  PLEASE SEE SELLER SUPPLIED  SPECIFICATIONS ATTACHED IN THE  DOCUMENT SECTION.  Asset located in: Lake Worth, TX		Tractor S/N: 1XPBAK9X2ND758793 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 5233.9 Engine hrs, Engine Brake, Paccar Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 150 in Wheelbase, Air Sliding 5th Wheel Usage: 231,143 Mi
8817	<b>2022 Kandi K32S-R Utility Vehicle (Unused)</b> S/N: A074EA19LNC000015		Asset located in: Lake Worth, TX
	C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 15 Mi Notes: ***FOR OFF ROAD USE ONLY*** PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX	8823	2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X1ND759335 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4478 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires,
8818	2022 Kandi K32S-W Utility Vehicle (Unused) S/N: A074EA19CNC000021 C/W: Enclosed Cab, Air Conditioner, 4 Passenger, Windshield, Winch Usage: 11 Mi		Air Trac Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 200,027 Mi  Asset located in: Lake Worth, TX
	Notes: ***FOR OFF ROAD USE ONLY***; PLEASE SEE SELLER SUPPLIED SPECIFICATIONS ATTACHED IN THE DOCUMENT SECTION. Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8824	2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBAP8X0ND759228 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Trac Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 213,663 Mi Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 213663 TITLE SHOWS	8830	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X6GD339491 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX
	213700	8831	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor
8825	Asset located in: Lake Worth, TX  2021 Peterbilt 579 4x2 S/A Day Cab Truck Tractor  S/N: 1XPBAP8X9MD759078  C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 5299 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Air Trac Suspension, 154 in Wheelbase, Dual Fuel Tanks		S/N: 1XPBA48X8GD339671 C/W: Cummins ISX15 6 Cylinder 15.0 L 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17898.4 Engine hrs, Engine Brake, Eaton Fuller UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 275/80R22.5, Air Trac Air Ride Suspension, 159 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 888,673 Mi Asset located in: Lake Worth, TX
	Usage: 238,812 Mi <b>883</b> 2	8832	<b>2016 Peterbilt 579 S/A Day Cab Truck Tractor</b> S/N: 1XPBA48X6GD339488
	Notes: ODOMETER DISCREPENCY - ODOMETER SHOWS 238812 TITLE SHOWS 239000		Usage: Not Available  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8833	2016 Peterbilt 579 S/A Day Cab Truck Tractor
8826	2017 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X2HD428752		S/N: 1XPBA48X6GD339555 Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase. Air Sliding 5th Wheel	8834	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X6FD286306 Usage: Not Available Asset located in: Lake Worth, TX
	Usage: 933,275 Mi  Asset located in: Lake Worth, TX	8835	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X5FD286278 Usage: Not Available
8827	2017 Peterbilt 348 S/A Day Cab Truck Tractor S/N: 1NP3A28X9HD409487		Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	8836	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X5FD286314 Usage: Not Available
8828	<b>2017 Peterbilt 579 S/A Day Cab Truck Tractor</b> S/N: 1XPBA48X0HD428751		Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	8837	2015 Peterbilt 579 S/A Day Cab Truck Tractor S/N: 1XPBA48X7FD286248
8829	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8GD339556 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 896,378 Mi Asset located in: Lake Worth, TX		Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8838	2015 Peterbilt 579 4x2 S/A Day Cab Truck Tractor S/N: 1XPBA48X8FD286307 C/W: Cummins ISX15 6 Cylinder 15 L Petrol 400 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 22701 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in: Lake Worth, TX		Tractor S/N: 1XKYA48X0FJ443782 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fulle FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 990,189 Mi
8839	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor		Notes: X2-No frame stamp vin pic Asset located in: Lake Worth, TX
	S/N: 1XKYA48XXGJ119241 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 828,937 Mi Asset located in: Lake Worth, TX	8843	2015 Kenworth T-680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48X6FJ443771 C/W: Cummins ISX 6 Cylinder 15 L Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 17203 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Airglide 4-Bag Air Ride Suspension, 160 in Wheelbase, Air Sliding 5th Wheel Usage: 732,450 Mi
8840	2016 Kenworth T-680 4x2 S/A Day Cab Truck Tractor		Asset located in: Lake Worth, TX
	S/N: 1XKYA48X9GJ496496 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17916 Engine hrs, Engine Brake, Eaton Fuller ADV Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 2.67:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, 4-Bag Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 912,222 Mi	8844	2015 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYD49X7FJ466031 Usage: Not Available Asset located in: Lake Worth, TX
		8845	2015 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48XXFJ403435 Usage: Not Available Asset located in: Lake Worth, TX
8841	2015 Kenworth T680 4x2 S/A Day Cab Truck Tractor S/N: 1XKYA48XXFJ403449 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22634 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear	8846	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X9EJ402288 Usage: Not Available Asset located in: Lake Worth, TX
		8847	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X7EJ402287 Usage: Not Available Asset located in: Lake Worth, TX
	Tires, 4-Bag Air Ride Suspension, 168 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,009,300 Mi <b>Asset located in</b> : Lake Worth, TX	8848	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X3EJ402450 Usage: Not Available Asset located in: Lake Worth, TX
		8849	2014 Kenworth T680 S/A Day Cab Truck Tractor S/N: 1XKYA48X0EJ403264 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8850	2014 Kenworth T-680 4x2 S/A Day Cab Truck Tractor  S/N: 1XKYA48XXEJ402851  C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Eaton Fuller FM-15E310B-LAS Automatic Transmission, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700.0 lb GVWR, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,154,795 Mi  Asset located in: Lake Worth, TX	8855	2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor  S/N: 1XKAA48X8DJ354945  C/W: Cummins ISX15 6 Cylinder 15 L 400 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 4-Bag Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available  Asset located in: Lake Worth, TX
8851	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor	8857	2019 Mack AN42T 4x2 S/A Day Cab Truck
	S/N: 1XKYA48X4EJ403168 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-15E310B-LAS 10-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53:1 Axle Ratio, 34700 lb GVWR, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 767,305 Mi		Tractor S/N: 1M1AN2AY6KM001154 C/W: Mack MP7 6 Cylinder Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 154 in Wheelbase, Auto Lube Usage: 537,481 Mi Asset located in: Lake Worth, TX
0050	Asset located in: Lake Worth, TX	8858	2019 Mack Anthem 4x2 S/A Day Cab Truck
Low Sulfur Diesel 400 hp Engine, Label, Requires Diesel Exhaust Fl Engine hrs, Engine Brake, Eaton F 15E310B 10-Speed Automated T 12000 lb Front Axle, 22700 lb Rea 190 Drive Axles, 2.53:1 Axle Ratio GVWR, Air Ride Cab, 295/75R22. Bag Air Ride Suspension, 159 in N	Tractor		Tractor S/N: 1M1AN2AY2KM001152 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 4523 Engine hrs, Engine Brake, Mack 12-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 158 in Wheelbase Usage: 476,581 Mi Asset located in: Lake Worth, TX
	Usage: 937,106 Mi	8859	2017 Mack CXU612 6x2 S/A Day Cab Truck
8853	Asset located in: Lake Worth, TX  2013 Kenworth T660 4x2 S/A Day Cab Truck Tractor  S/N: 1XKAA48X1DJ354916  C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Air Sliding 5th		Tractor S/N: 1M1AW01Y9HM010179 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Air Ride Suspension, 159 in Wheelbase Usage: 477,424 Mi Asset located in: Lake Worth, TX
	Wheel, Dual Fuel Tanks	8860	2017 Mack CXU612 4x2 S/A Day Cab Truck
	Usage: 769,223 Mi <b>Asset located in</b> : Humble, TX		<b>Tractor</b> S/N: 1M1AW01Y7HM010164
8854	2013 Kenworth T660 S/A Day Cab Truck Tractor S/N: 1XKAD48X1DJ367527 Usage: Not Available Asset located in: Lake Worth, TX		C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14979 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 548,175 Mi  Asset located in: Lake Worth, TX

		1	
Lot #	Details	Lot #	Details
8861	Cab Truck Tractor  S/N: 3AKBGEDV5JSJH1844 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10441 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, 3.08:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 244,661 Mi Asset located in: Lake Worth, TX	8865	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV5HDHY5843 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 588,024 Mi Asset located in: Lake Worth, TX
8862	2017 Freightliner Cascadia 125 4x2 S/A Day	8866	2015 Freightliner Cascadia 125 4x2 S/A Day
	Cab Truck Tractor S/N: 3AKBGDDV1HDHY5841 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12543 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-161 Drive Axles, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 553,773 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDD54FLGB0385 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17775 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 920,721 Mi Asset located in: Lake Worth, TX
8863	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8867	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 3AKBGDDV4HDHY5848 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG Usage: 569,326 Mi		S/N: 1FUBGDD59FLGB0401 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18682 Engine hrs, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,203 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8868	2015 Freightliner Cascadia 125 4x2 S/A Day
8864	2017 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDV6HDHY5849 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 15402 Engine hrs, Engine Brake, Detroit DT12-DA-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-161 Drive Axles, 2.50:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, PROFESSIONALLY- MAINTAINED-FLEET-VEHICLE-PAG Usage: 620,515 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDD5XFLGB0164 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18936 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor MFS-12-143A Drive Axles, 3.42:1 Axle Ratio, 33000 kg GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 871,985 Mi Asset located in: Lake Worth, TX

		1	
Lot #	Details	Lot #	Details
8869	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8873	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD50FLGB0206 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19010 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 865,103 Mi		S/N: 1FUBGDD57FLGB0459 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17399 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 802,794 Mi
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
8870	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 20941 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 984,115 Mi	8874	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0324 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 818,368 Mi Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8875	2015 Freightliner Cascadia 125 4x2 S/A Day
8871	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGJ1241 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 2052 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks	88/5	Cab Truck Tractor S/N: 1FUBGDD55FLGJ1193 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19725 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, Dual Fuel Tanks Usage: 871,783 Mi Asset located in: Lake Worth, TX
	Usage: 703,022 Mi	8876	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
8872	Asset located in: Lake Worth, TX  2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0245 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19950 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,022 Mi Asset located in: Lake Worth, TX		S/N: 1FUBGDD51FLGJ1322 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 16251 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,874 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8877	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8882	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD56FLGJ1204 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20437 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 882,971 Mi Asset located in: Lake Worth, TX		S/N: 1FUBGDD50FLGB0254 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,066,619 Mi
8878	2015 Freightliner Cascadia 125 4x2 S/A Day		Asset located in: Lake Worth, TX
	Cab Truck Tractor S/N: 1FUBGDD55FLGB0301 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18129 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 10R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 771,423 Mi	8883	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1297 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 847,972 Mi
	Asset located in: Lake Worth, TX	ļ	Asset located in: Lake Worth, TX
8880	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGJ1327 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20282 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 896,379 Mi Asset located in: Lake Worth, TX	8884	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGJ1248 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 853,850 Mi
8881	2015 Freightliner Cascadia 125 4x2 S/A Day		Asset located in: Lake Worth, TX
0001	Cab Truck Tractor  S/N: 1FUBGDD52FLGJ1233  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, CARB  Compliant, Requires Diesel Exhaust Fluid, 21113 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks  Usage: 927,772 Mi  Asset located in: Lake Worth, TX	8885	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0455 C/W: 21346 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23- 186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner II Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 978,516 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8886	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0423 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 870,847 Mi Asset located in: Lake Worth, TX	8890	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGJ1150 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor Drive Axles, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 844,869 Mi Asset located in: Lake Worth, TX
8887	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0200 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 840,242 Mi Asset located in: Lake Worth, TX	8891	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor  S/N: 1FUBGDD54FLGJ1217  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18209 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 823,386 Mi  Asset located in: Lake Worth, TX
8888	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGB0420 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21049 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 971,468 Mi	-8892	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0278 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20497 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 954,240 Mi Asset located in: Lake Worth, TX
8889	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0084 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21221 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,002,152 Mi Asset located in: Lake Worth, TX	8893	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGJ1249 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 995,766 Mi Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8894	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGB0247 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19933 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 926,620 Mi Asset located in: Lake Worth, TX	8898	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0351 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19389 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275 /80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 867,504 Mi Asset located in: Lake Worth, TX
8895	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0266 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 910,815 Mi Asset located in: Lake Worth, TX		Cab Truck Tractor  S/N: 1FUBGDD57FLGB0283  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18643 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1  Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 985,816 Mi  Asset located in: Lake Worth, TX
8896	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22008 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,012,404 Mi Asset located in: Lake Worth, TX	8900	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0208 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 19799 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks Usage: 922,423 Mi Asset located in: Lake Worth, TX
8897	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0161 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19325 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 889,925 Mi	- 8901	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGJ1223 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19901 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 851,964 Mi Asset located in: Lake Worth, TX

	Datails	I ot #	Datails
Lot #	Details 2015 Freightliner Concodin 125 4x2 C/A Day	Lot #	Details 2015 Freightliner Concedin 125 4v2 S/A Day
8902	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8906	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD50FLGB0173		S/N: 1FUBGDD55FLGB0153
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel
	Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front		Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42:
	Axle, 21000 lb Rears, Meritor RS-23-186 Drive		1 Axle Ratio, 33000 lb GVWR, Air Ride Cab,
	Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5		11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase,
	Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks		Dual Fuel Tanks Usage: 1,039,845 Mi
	Usage: 842,483 Mi		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	8907	2015 Freightliner Cascadia 125 4x2 S/A Day
8903	2015 Freightliner Cascadia 125 4x2 S/A Day		Cab Truck Tractor
	Cab Truck Tractor S/N: 1FUBGDD52FLGJ1328		S/N: 1FUBGDD51FLGB0120 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505		hp Engine, 2014 US EPA Label, Requires Diesel
	hp Engine, 2014 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 4695		Exhaust Fluid, 19024 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual
	Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission,		Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1
	12000 lb Front Axle, 21000 lb Rears, 33000 lb		Axle Ratio, 33000 lb GVWR, Air Ride Cab,
	GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks		11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase,
	Usage: 862,038 Mi  Asset located in: Lake Worth, TX		Dual Fuel Tanks Usage: 874,425 Mi
0004			Asset located in: Lake Worth, TX
8904	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	8908	2015 Freightliner Cascadia 125 4x2 S/A Day
	S/N: 1FUBGDD56FLGB0145		Cab Truck Tractor
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel		S/N: 1FUBGDD58FLGB0339 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505
	Exhaust Fluid, 19762 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission,		hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19629 Engine hrs, Engine Brake,
	12000 lb Front Axle, 23000 lb Rears, Meritor RS-		Eaton Fuller FRO-15210C 10-Speed Manual
	23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride		Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air
	Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 857,268 Mi		Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks
	Asset located in: Lake Worth, TX		Usage: 766,317 Mi
8905	2015 Freightliner Cascadia 125 4x2 S/A Day		Asset located in: Lake Worth, TX
	Cab Truck Tractor	8909	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
	S/N: 1FUBGDD57FLGJ1227 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505		S/N: 1FUBGDD53FLGB0314
	hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17987 Engine hrs, Engine Brake,		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel
	Eaton Fuller FRO-15210C 10-Speed Manual		Exhaust Fluid, 19888 Engine hrs, Engine Brake,
	Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1		Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb
	Axle Ratio, 33000 lb GVWR, Air Ride Cab,		Rears, Meritor RS-23-186 Drive Axles, 3.42:1
	11R22.5, Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks		Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires,
	Usage: 859,845 Mi		Airliner Air Ride Suspension, 159 in Wheelbase, Dual Fuel Tanks
	Asset located in: Lake Worth, TX	I	Usage: 854,701 Mi

10+#	Detaile	o+ #	 Details
Lot # 8910	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0176 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 792,126 Mi Asset located in: Lake Worth, TX	8914	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50ELFL7275 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19027 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 783,595 Mi Asset located in: Lake Worth, TX
8911	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor  S/N: 1FUBGDD57FLGB0347  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1735 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 940,040 Mi Asset located in: Lake Worth, TX	8915	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58ELFL7265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 730,348 Mi Asset located in: Lake Worth, TX
8912	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor  S/N: 1FUBGDD55ELFL7286  C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 777,001 Mi	-8916	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGEBG0ELFT4306 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM-14E310B Automated Transmission, Meritor RS-23-160 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 552,293 Mi Asset located in: Humble, TX
8913	Asset located in: Lake Worth, TX  2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XELFL7283 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20475 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 868,356 Mi Asset located in: Lake Worth, TX	-8918	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBX1004 C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 748,352 Mi Asset located in: Lake Worth, TX

			1 age 401 01 300
Lot #	Details	Lot #	Details
8919	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR6DLBX1162 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 16476 Engine hrs, Engine Brake, Eaton Fuller FR0-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 647,254 Mi	8924 8925	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX1080 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 45 hp Engine, 2012 US EPA Label, Requires Diese Exhaust Fluid, Engine Brake, Eaton Fuller FRO 15210C 10-Speed Manual Transmission, 3.42 1 Axle Ratio, Air Ride Cab, 11R22.5 Front Tires 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tan Usage: 515,155 Mi Asset located in: Lake Worth, TX  2013 Freightliner Cascadia 125 4x2 S/A Day
8920	Asset located in: Lake Worth, TX  2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBX1102 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19727 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 662,005 Mi		Cab Truck Tractor S/N: 1FUBGDDR1DLBX0906 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19497 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 724,603 Mi Asset located in: Lake Worth, TX  2013 Freightliner Cascadia 125 4x2 S/A Day
	Asset located in: Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDDR7DLBX1185
8921	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR0DLBX1156 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18326 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in		
	Wheelbase, Dual Fuel Tanks	8926	2013 Freightliner Cascadia 125 4x2 S/A Day
	Usage: 422,808 Mi <b>Asset located in</b> : Lake Worth, TX		Cab Truck Tractor S/N: 1FUBGDDR1DLBX0985
8922	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX0897 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20167 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 812,847 Mi		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 566 hp Engine, 2012 US EPA Label, Requires Diese Exhaust Fluid, 21973 Engine hrs, Engine Brake Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 802,200 Mi  Asset located in: Lake Worth, TX

This catalog was created at December 8, 2024 01:25:57 PM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details	
8927	3927 2012 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR9CLBF2891 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 19508 Engine hrs, Engine Brake,	8932	2014 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY3EDFY1228 Usage: Not Available Asset located in: Lake Worth, TX	
	Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 712,633 Mi	8933	2014 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY3EDFY1164 Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	8934	2014 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor	
8928	2018 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGBDV9JSJR3316 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, 13472 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 22700 lb Rears, 3.08:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 165 in Wheelbase,		S/N: 3AKBCYCY4EDFX5745 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 9009 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Meritor RS-23-160 Drive Axles, 5.38:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, steel, 295/75R22.5, Spring Suspension, 155 in Wheelbase, Dual Fuel Tanks Usage: 120,247 Mi Asset located in: Lake Worth, TX	
	Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 623,326 Mi	Tractor  S/N: 4V4W19EG7NN285618 C/W: Volvo D13N405 6 Cylinder 1 405 hp Engine, 2021 US EPA Labe Diesel Exhaust Fluid, 7146 Engine Brake, Volvo AT2612F 12-Speed A Transmission, 12000 lb Front Axle Rears, Meritor RS-23-160 Drive Ax GVWR, 275/80R22.5, Volvo Air Ric Suspension, 152 in Wheelbase, Di Usage: 295,698 Mi	2022 Volvo VNR300 4x2 S/A Day Cab Truck	
	Asset located in: Lake Worth, TX			
8929	2014 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor S/N: 1FUJC5DV2EHFX4554 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.62:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels,		C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 7146 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, 275/80R22.5, Volvo Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks	
	295/75R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel	8936		
	Tanks Usage: 698,878 Mi <b>Asset located in</b> : Lake Worth, TX	8930	2022 Volvo VNR 4x2 S/A Day Cab Truck Tract S/N: 4V4W19EG7NN285540 C/W: Volvo D13N405 6 Cylinder 12.8 L 405 hp Engine, 2021 US EPA Label, Requires Diesel	
8930	2015 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor S/N: 3AKBCYCY6FDGJ1937 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8522 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Detroit DA-RS-23.0-4 Drive Axles, 5.22:1 Axle Ratio, 34700 lb GVWR, Air		Exhaust Fluid, 8483 Engii Volvo AT2612F 12-Speed Transmission, 12000 lb F Rears, 32000 lb GVWR, R /75R22.5 Rear Tires, Air I in Wheelbase, Dual Fuel FROM-YELLOW-CORP Usage: 347,925 Mi	Exhaust Fluid, 8483 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, R22.5 Front Tires, 295 /75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP
	Ride Cab, 295/75R22.5, Spring Suspension,	8937	2021 Volvo VNR300 4x2 S/A Day Cab Truck	
	155 in Wheelbase, Dual Fuel Tanks Usage: 147,777 Mi		<b>Tractor</b> S/N: 4V4W19EG7MN285326	
	Asset located in: Lake Worth, TX	4	C/W: Volvo D13N405 6 Cylinder 12.8 L Diesel	
8931	2015 Freightliner M2 106 S/A Day Cab Truck Tractor S/N: 3AKBCYCY2FDGJ1949 Usage: Not Available Asset located in: Lake Worth, TX	405 hp Engine, 2020 US ÉPA Label, Diesel Exhaust Fluid, 7976 Engine h Brake, Volvo AT2612F 12-Speed Au Transmission, 12000 lb Front Axle, Rears, Meritor RS-23-160 Drive Axle GVWR, 295/75R22.5, Volvo Air Ride	405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 7976 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, 295/75R22.5, Volvo Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks Usage: 322,314 Mi	

Lot #	Details	Lot #	Details
8938	2021 Volvo VNR300 6x4 S/A Day Cab Truck Tractor S/N: 4V4WC9EG1MN286031 C/W: 7784 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, 275/80R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 286,472 Mi Asset located in: Lake Worth, TX  2019 Volvo VNR300 4x2 S/A Day Cab Truck	8943	2019 Volvo VNR 4x2 S/A Day Cab Truck Tract S/N: 4V4W19EG3KN901925 C/W: Volvo D13M405 6 Cylinder 12.8 L 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17551 Engine hrs, Engine Brake Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 754,359 Mi
0.00	Tractor		Asset located in: Midland, TX
	S/N: 4V4W39EG8KN226146 C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, 35350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 664,493 Mi Asset located in: Lake Worth, TX	8944	2018 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG1JN901758 C/W: Volvo D13M405 6 Cylinder 12.8 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 154 in Wheelbase,
8940	2019 Volvo VNR300 4x2 S/A Day Cab Truck		Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW- CORP
	Tractor S/N: 4V4W39EGXKN226147 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel		Usage: Not Available  Asset located in: Lake Worth, TX
	405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15950 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, Meritor RS23-160 Drive Axles, 35350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 156 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 730,594 Mi  Asset located in: Lake Worth, TX	8945	2017 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EG1HN985095 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 22474 Engine hrs, Volvo AT2612D 12-Speed Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295
8941	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EGXKN907544		/75R22.5 Rear Tires, VOLVO Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tar Usage: 876,316 Mi
	C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel		Asset located in: Lake Worth, TX
	405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000.0 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 680,054 Mi Asset located in: Lake Worth, TX	8946	2015 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH4FN184666 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15123 Engine hrs, Engine Brake, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32350 lb GVWR, Air Ride Cab, 295/75R22.5,
8942	2019 Volvo VNR 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG1KN907528 C/W: Volvo D13M-405 6 Cylinder 12.8 L 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 706,546 Mi		Volvo Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 579,823 Mi <b>Notes</b> : TITLE COMES WITH A CORRECTION OF AFFIDAVIT <b>Asset located in</b> : Humble, TX

Lot #	Details	Lot #	Details
8947	2013 Volvo VNL200 4x2 S/A Day Cab Truck Tractor S/N: 4V4N39EG8DN142388 C/W: Volvo D13H405 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 23000 lb Rears, 35350 lb GVWR, 11R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel Usage: 535,477 Mi Asset located in: Lake Worth, TX	8952	2009 International ProStar Premium 4x2 S/A Day Cab Truck Tractor S/N: 2HSCSAPN49C045678 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 400 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Ride Suspension, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 610,101 Mi Asset located in: Lake Worth, TX
8948	2012 Volvo VNL300 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG6CN560842 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 32350.0 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 311,531 Mi Asset located in: Humble, TX	8953	2008 International TranStar 8600 4x2 S/A Day Cab Truck Tractor S/N: 1HSHWAHN68J673895 C/W: Cummins 6 Cylinder Engine, 22559 Engine hrs, Eaton Fuller 10-Speed Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 582,442 Mi Asset located in: Midland, TX
8949	2014 International ProStar 4x2 S/A Day Cab Truck Tractor S/N: 1HSDGAPN6EH036926 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Aluminum Outer Rear Wheels, 11R22.5, Air Ride Suspension, 173 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 360,386 Mi Asset located in: Lake Worth, TX	8954	2005 International 9400i 4x2 S/A Day Cab Truck Tractor S/N: 3HSCPAPN05N049267 C/W: Cummins ISX 6 Cylinder 400 hp Engine, 2004 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 835,214 Mi Notes: CANNOT VERIFY ODOMETER READING - VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE
8950	2015 International 4400 4x2 S/A Day Cab Truck Tractor S/N: 1HSMTSTN8FH726444 C/W: Navistar N9 6 Cylinder 9.3 L Diesel Engine, Requires Diesel Exhaust Fluid, 3580 Engine hrs, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 152 in Wheelbase, PTO Usage: 85,797 Mi Asset located in: Lake Worth, TX	8955	Asset located in: Lake Worth, TX  2003 Freightliner FLD 112 4x2 S/A Day Cab Truck Tractor S/N: 1FUBACA873DK79061 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel 370 hp Engine, 2002 US EPA Label, Meritor 10- Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 2.93:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 919,458 Mi Asset located in: Lake Worth, TX
8951	2012 International 4400 4x2 S/A Day Cab Truck Tractor S/N: 1HSMTAAN4CH561985 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel 300 hp Engine, 2011 US EPA Label, 4407 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 148 in Wheelbase, Dual Fuel Tanks Usage: 136,823 Mi Asset located in: Lake Worth, TX	8956	2008 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH28N498237 C/W: Volvo 6 Cylinder 12.8 L Diesel Engine, 2007 US EPA Label, Engine Coolant Heater, 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295 /75R22.5, Paccar Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,428,300 Mi Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8956A	2007 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GFX7N451743 C/W: Volvo 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Engine Brake, Eaton Fuller FR13210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-186 Drive Axles, 2.93:1 Axle Ratio, 32000 lb GVWR, Aluminum Front Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 144 in Wheelbase, Dual Fuel Tanks Usage: 1,551,805 Mi Asset located in: Lake Worth, TX	8961	2017 Peterbilt 579 4x2 (CNG) S/A Day Cab Truck Tractor S/N: 1NPBAH8X7HD421460 C/W: Cummins ISX12 6 Cylinder 11.9 L Compressed Natural Gas (CNG) 400 hp Engine, 2016 US EPA Label, Engine Brake, Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, 35050 lb GVWR, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel Usage: 549,140 Mi Asset located in: Lake Worth, TX
8957	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19GF32N335289 C/W: Volvo DT12C345 6 Cylinder 12.1 L Diesel 345 hp Engine, 2001 US EPA Label, Engine Brake, Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.93:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 344,373 Mi Asset located in: Lake Worth, TX	-8962	2017 Freightliner Cascadia 113 CNG 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGBD98HLGV4596 C/W: Cummins ISX12G 11.9 L Compressed Natural Gas (CNG) 400 hp Engine, 2015 US EPA Label, Allison 4000 HS Automatic Transmission, 12500 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 3.91:1 Axle Ratio, 35050 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 182 in Wheelbase Usage: 23,705 Mi Asset located in: Lake Worth, TX
8958	2002 Volvo VNM 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19RF72N324549 C/W: Detroit 6 Cylinder 12.7 L Diesel 470 hp Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 32000 lb GVWR, 295/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 154 mm Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 1,393,840 Mi Asset located in: Midland, TX 2014 Kenworth T370 S/A Sleeper Truck Tractor	-8963	2008 Trail King TK140MDG-693 70 ton Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ069368B045330 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, Tri/A Jeep, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 30 ft Main Deck, 108 in Usable Deck Width, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 175300 lb GVWR Usage: Not Available Notes: UNIT IS BEING SOLD WITH A TITLE IN TRANSIT FOR 14 DAYS AND UNIT CANNOT LEAVE YARD UNTIL TITLE IS RECEIVED
8939	S/N: 2NKHHJ7X8EM417041 C/W: EQUIPMENT FROM A PRIMORIS SERVICES CORP COMPANY Usage: Not Available Notes: . Asset located in: Midland, TX	8964	Asset located in: Lake Worth, TX  2008 Etnyre RTN65TD3-RA 3+1+1 Lowboy Trailer  S/N: 1E92980888E111025  C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed
8960	1999 Volvo VN 4x2 Flatbed Truck S/N: 4VG7DBUF5XN768395 C/W: Cummins ISM 6 Cylinder 10.8 L Ultra Low Sulfur Diesel 330 hp Engine, 1998 US EPA Label, Eaton Fuller Automatic Transmission, Aluminum Wheels, 295/75R22.5 Front Tires,		for Booster Axle, 25 ft 7 in Main Deck, 98 in Usable Deck Width, 108 in Overall Deck Width, 275/70R22.5 Tires Usage: Not Available  Asset located in: Lake Worth, TX
	275/80R22.5 Rear Tires, Volvo Spring Suspension, 237 in Wheelbase, 10 ft 4 in x 96 in Bed Usage: 834,602 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	8965	2006 Trail King TK130HDG-573 Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ057386M014661 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, Plumbed for Booster Axle, 28 ft Main Deck, 120 in Overall Deck Width, Honda Gas Powered Self Contained Hydraulic System, 235/75R17.5 Tires, 161280 lb GVWR, Spreader Bar Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8966	2016 Etnyre RTN60TD4-PS Quad/A Removable Gooseneck Lowboy Trailer S/N: 1E9320301GE111172 C/W: Air Ride Suspension, Lift 4th- Axles, Hydraulic Removable Gooseneck, 26 ft Main Deck, 16 ft Rear Deck, 102 in Usable Deck Width, Folding Side Extensions, Deck Over Tires, Manual Ramps, 275/70R22.5 Tires, 66842 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: Asset located in: Humble, TX	8971	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E36RS000474 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9067		8072	
8967	2015 XL Specialized 120SDE Tri/A 53 ft Extendable Lowboy Trailer S/N: 4U3B05337FL014387 C/W: Air Ride Suspension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 42 ft Main Deck, 97 in Overall Deck Width, 102 in Widening Width, 235/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	8972	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E34RS000473 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR
8968	2007 Trail King TK110HDG 55 t Tri/A Double		
	Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533X7M051363 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, S/A Pin-On Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, 12 in Widening Width, Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 132800 lb GVWR, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED Asset located in: Lake Worth, TX		Usage: Not Available
			Asset located in: Lake Worth, TX
		8973	2015 XL Specialized 120SDE Lowboy Trailer S/N: 4U3B05330FL014621
			Usage: Not Available
			Asset located in: Lake Worth, TX
		8974	2013 Trail King TK110HDG533 55 t Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ05333DM041625 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 26 ft Main Deck, 102 in Usable Deck Width, Folding Side Extensions, Deck Over Tires, Honda Gas Powered Self
8969	2007 Trail King TK55T 55 ton Quad/A Removable Gooseneck Lowboy Trailer		Contained Hydraulic System, 275/70R22.5 Tires, EQUIPMENT-FROM-A-PRIMORIS-
			SERVICES-CORP-COMPANY Usage: Not Available
	S/N: 1TKJ053347B051452 C/W: Air Ride Suspension, Hydraulic		Asset located in: Humble, TX
	Removable Gooseneck, S/A Flip Booster Axle, Plumbed for Booster Axle, 26 ft Main Deck, 102 in Usable Deck Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275/70R22.5 Tires, 110000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX	8975	2013 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ05334DM109110 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Widening Width, Folding Side Extensions, Boom Recess, Deck
8970	2024 Witzco RG-52 Challenger 52 ton Tri/A Removable Gooseneck Lowboy Trailer (Unused) S/N: 1W8A11E32RS000472 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Honda Gas Powered Self Contained Hydraulic System, 255/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134820 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available  Notes: BRAND NEW FLOOR INSTALLED  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8976	2013 Trail King TK110HDG 55 t Tri/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 1TKJ0533XDM109113 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft Rear Deck, 102 in Usable Deck Width, 126 in Wedening Width,	8982	2019 Fontaine T/A Removable Gooseneck Lowboy Trailer S/N: 57J348208K3575771 C/W: Air Ride Suspension, Air Brakes, 255 /70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
8977	Folding Side Extensions, Boom Recess, Deck Over Tires, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 275 /70R22.5 Tires, 134660 lb GVWR, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED Asset located in: Lake Worth, TX  2010 Trail King TK110HDG533 55 ton Tri/A Single Drop Removable Gooseneck Lowboy Trailer	8983	2004 Fontaine 552-2MWNGB 55 ton 2+2 Removable Gooseneck Lowboy Trailer S/N: 4LFE7640943523624 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, 29 ft Main Deck, 96 in Usable Deck Width, 120 in Widening Width, Folding Side Extensions, Gas Powered Self Contained Hydraulic System, 275 /70R22.5 Tires, 147500 lb GVWR Usage: Not Available
	S/N: 1TKJ05330AM109858 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 26 ft Main Deck, 13 ft 7 in Rear Deck, 102 in Usable Deck Width, 24 in Widening Width, Folding Side Extensions, Boom Recess, Honda Gas Powered Self Contained Hydraulic System, Aluminum Wheels, 255/70R22.5 Tires, 133820 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: BRAND NEW FLOOR INSTALLED	8984	Asset located in: Lake Worth, TX  2000 Fontaine T/A Double Drop Removable Gooseneck Lowboy Trailer S/N: 13ND48291Y1590100 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, 9 ft 7 in Upper Deck, 29 ft 2 in Main Deck, 7 ft 8 in Rear Deck, 102 in Usable Deck Width, Deck Over Tires, 255 /70R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
8978	Asset located in: Lake Worth, TX  2022 Pitts LB51-22 51 ton Tri/A Single Drop Lowboy Trailer  S/N: 5JYLB5137NPP24054  C/W: Air Ride Suspension, Air Brakes, Lift 3rd-Axles, Hydraulic Removable Gooseneck, 26 ft Main Deck, 16 ft Rear Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Folding Side Extensions, Deck Over Tires, Aluminum Outer Wheels, 255  /70R22.5 Tires, 121500 lb GVWR  Usage: Not Available  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8985	1984 Cozad 2+2+2 Removable Gooseneck Lowboy Trailer S/N: 1C9B48207E1167105 C/W: Walking Beam Suspension, Mechanical Removable Gooseneck, Plumbed for Booster Axle, 30 ft Main Deck, 102 in Usable Deck Width, Dropside Deck, 11R24.5 Tires, 1984 Cozad 16 Wheel Expando Jeep w/Hyd Tower, s /n 1C9H24204E11677104. 1984 - Cozad Booster s/n: 1C9B48207E1167106 c/w: T/A Pin-On Booster, 70R22.5 Tires; Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX
8980	Asset located in: Humble, TX  2010 Witzco Challenger RG50 Tri/A Lowboy Trailer S/N: 1W8A11F37AS000227 Usage: Not Available Asset located in: Lake Worth, TX	8986	2008 Viking VFDD46R18F35T T/A Double Drop Lowboy Trailer S/N: 1V9CR46288N062389 C/W: Spring Suspension, 9 ft Upper Deck, 21 ft 5 in Main Deck, 9 ft 2 in Rear Deck, 4 ft Fixed Dovetail, 102 in Usable Deck Width, Upper Deck
8981	2009 Etnyre RTN60TD3-PS Tri/A Removable Gooseneck Lowboy Trailer S/N: 1E93014909E111031 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, S/A Flip Booster Axle, 24 ft 4 in Main Deck, 17 ft 2 in Rear Deck, 102 in Usable Deck Width, 275/70R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Ramps, Deck Over Tires, Spring Assisted Ramps, 255/70R22.5 Tires, 87000 lb GVWR Usage: Not Available  Asset located in: Midland, TX  2002 Kalyn Siebert LB0353T Quad/A Lowboy Trailer  S/N: 5DDKE404221000577  C/W: Walking Beam Suspension, 39 ft Main Deck, 98 in Usable Deck Width, 102 in Overall Deck Width, Tail Roller, 11R22.5 Tires Usage: Not Available  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
8988	1981 Nuttall 225-E T/A Lowboy Trailer S/N: NMC50296 C/W: Spring Suspension, 9 ft 4 in Upper Deck, 23 ft 5 in Main Deck, 5 ft 4 in Fixed Dovetail, 90 in Usable Deck Width, 96 in Overall Deck Width, Deck Over Tires, Manual Ramps, 10.00R15 Tires Usage: Not Available	8996A	1987 Fruehauf ELF-1 S/A Dolly S/N: 1H2E00617HH031475 C/W: 295/75R22.5 Tires, 20000 lb GVWR Usage: Not Available Notes: LOCATED-IN-MONTICELLO-MD- YELLOW; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	
8989	Asset located in: Lake Worth, TX  1990 Talbert TJ-11R22.5 35 ton T/A Heavy-Haul Jeep  S/N: 40FJK2725L1008821  C/W: Air Ride Suspension, 275/70R22.5 Tires, 67079 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX	8997	2016 Trail-Eze TE70XT T/A Hydraulic Tail Trailer S/N: 1DAHFC725GP022068 C/W: Air Ride Suspension, Sliding Suspension, 7 ft 9 in Upper Deck, 38 ft Main Deck, 5 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R17.	
8990	T/A Heavy-Haul Jeep S/N: Not Available C/W: Sliding 5th Wheel, Pickup Throat, Tail Roller, Rubber Block Suspension, 11R24.5 Tires, Low-Boy Ramps, Neck Roller Usage: Not Available		5 Tires, 86720 lb GVWR, EQUIPMENT-FROM- SUNSTATE-EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX 2019 Trail King TK70HT T/A Hydraulic Tail Trailer	
	Notes: . Asset located in: Lake Worth, TX		S/N: 1TKA04828KM102376 C/W: 84800 lb GVWR, Spring Suspension, 9 ft	
8992	2018 Liddell C55 S/A Booster Axle S/N: 1L93J0517JB564012 C/W: Flip-Up, Air Ride Suspension, 255/70R22. 5 Tires Usage: Not Available		Upper Deck, 38 ft 8 in Main Deck, 9 ft 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	<b>8999</b>	9 2018 Fontaine Traverse HT T/A Hydraulic Tai	
8993	2015 XL Specialized XL24FA S/A Booster Axle S/N: 4U3S00514FL014398 C/W: Pin-On, Air Ride Suspension, 235/75R17. 5 Tires, 26300 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Trailer  S/N: 57JV482DXJ3574695  C/W: Air Ride Suspension, 6 ft 10 in Upper Deck, 38 ft 5 in Main Deck, 4 ft 3 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch 10217 5 Tiron 23200 lb CVMP	
8994	1989 Fontaine S/A Booster Axle S/N: 13NM04107K1547671 C/W: Pin-On, Air Ride Suspension, 255/70R22.		Winch, 10R17.5 Tires, 83200 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPM Usage: Not Available  Asset located in: Lake Worth, TX	EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
	5 Tires, 18160 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9000	2016 Trail King TK80HT T/A Hydraulic Tail Trailer	
8995	2020 Wabash TCD/CDC-CDH S/A Dolly S/N: 1JJD061X6LL222455 C/W: Spring Suspension, 275/80R22.5 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX			S/N: 1TKA04823GM031272 C/W: Air Ride Suspension, 7 ft 8 in Upper Deck, 38 ft 10 in Main Deck, 7 ft 8 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R-17.5 Tires, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available
8996	1994 Pines S/A Dolly S/N: 1PNA09101RK056464 C/W: Spring Suspension, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9001	Asset located in: Lake Worth, TX  2016 Trail-Eze TE70XT T/A Hydraulic Tail Trailer  S/N: 1DAHFC727GP022069  C/W: Air Ride Suspension, Sliding Suspension, 7 ft Upper Deck, 38 ft 1 in Main Deck, 4 ft 10 in 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, 10R17.5  Tires, 86720 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9002	2016 Trail-Eze TE70XT 28983 lb T/A Hydraulic Tail Trailer  S/N: 1DAHFC725GC021848  C/W: Aluminum Frame, Spring Suspension, Air Brakes, 6 ft 6 in Upper Deck, 25 ft Main Deck, 2-Position Dovetail, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Hydraulic Ramps, 10r17.5 Tires, 40000 lb GVWR, EQUIPMENT-	9008A	2011 Landoll 48 ft T/A Sliding Axle Trailer S/N: 1LH317UHXB1D18600 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck, 37 ft Main Deck, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 87000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	FROM-SUNSTATE-EQUIPMENT Usage: Not Available  Asset located in: Lake Worth, TX	9009	2012 Lucon 44 ft T/A Sliding Axle Trailer S/N: 1L9SC5322CG423002 C/W: Lunette Ring Hitch, Spring Suspension,
9004	2007 Ledwell LW48 T/A Hydraulic Tail Trailer S/N: 1L9GA72A37L033118 C/W: Spring Suspension, 7 ft Upper Deck, 28 ft Main Deck, 8 ft 2-Position Dovetail, 102 in		Air Brakes, 44 ft Main Deck, 97 in Usable Deck Width, 99 in Overall Deck Width, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Overall Deck Width, Winch, Deck Over Tires, Hydraulic Ramps, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9010	2025 Maxey 40 ft T/A Sliding Axle Trailer (Unused) S/N: 5R8GF4025SM118166 C/W: Spring Suspension, Electric Brakes, Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall
9005	2006 Ledwell T/A Hydraulic Tail Trailer S/N: 1L9GA72A96L033669 C/W: Air Ride Suspension, 8 ft Upper Deck, 29	9011	Deck Width, 235/80R16 Tires, 25990 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX
	ft 2 in Main Deck, 8 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Winch, 255/70R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2023 Great Dane 53 ft T/A Single Drop Step Deck Trailer S/N: 1GR4M0629PH443585 C/W: Air Ride Suspension, 9 ft 6 in Upper Deck,
9006	2023 Maxey YHX T/A Gooseneck Hydraulic Tail Trailer S/N: 5R8GF4023PM106833 C/W: Spring Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in	9012	43 ft Main Deck, 96 in Usable Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires Usage: Not Available <b>Asset located in</b> : Humble, TX
	Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, 40000 lb GVWR, Hydraulic Landing Gear Usage: Not Available Asset located in: Lake Worth, TX		2022 Brazo 80000 lb 53 ft T/A Single Drop Step Deck Trailer S/N: 4B9BKFS23NH054914 C/W: 80000 lb GVWR, Air Ride Suspension, Aluminum w/Wood Strips Flooring, 255/70R22. 5 Tires
9007	1996 Trail-Eze DHT7048 T/A Hydraulic Tail Trailer		Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 1DA72C7D9TM012261 C/W: Air Ride Suspension, 9 ft 9 in Upper Deck, 30 ft 2 in Main Deck, 8 ft 2-Position Dovetail, 102 in Usable Deck Width, Winch, Deck Over Tires, 10R17.5 Tires, 83520 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9013	2017 Trail King TK80ACS-40 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB05326HY082695 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 10 ft 4 in Upper Deck, 42 ft 2 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires, 90930 lb GVWR Usage: Not Available
9008	<b>2014 Landoll 930C T/A Sliding Axle Trailer</b> S/N: 1LH930UHXE1C20991	9014	Asset located in: Lake Worth, TX  2013 Utility FS2CDHA 53 ft T/A Spread Axle
	C/W: Spring Suspension, Air Brakes, Sliding Suspension, 4 ft Upper Deck, 23 ft Main Deck, 13 ft Rear Deck, 91 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10r17.5 Tires, 86300 lb GVWR, EQUIPMENT-FROM-SUNSTATE-EQUIPMENT Usage: Not Available  Asset located in: Lake Worth, TX	9014	Single Drop Step Deck Trailer  S/N: 1UYFS2534DA605126  C/W: Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available  Notes: .  Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
9015	2012 Manac 14353A000 Tri/A 53 ft - 73 ft Extendable Single Drop Step Deck Trailer S/N: 2M5131611C1130362 C/W: Air Ride Suspension, 10 ft 6 in Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Extendable Deck, Tail Roller, Wood Flooring, Aluminum Outer Wheels, 255/70R22. 5 Tires, 45360 lb GVWR Usage: Not Available	9021	2006 Transcraft 48 ft T/A Single Drop Step Deck Trailer S/N: 1TTE4820861081701 C/W: Air Ride Suspension, Lift 1st- Axles, 10 ft 3 in Upper Deck, 36 ft Main Deck, 92 in Usable Deck Width, 102 in Overall Deck Width, 255 /70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9016	Asset located in: Humble, TX	9022	2005 Fontaine DFT-5-8048WSAWK 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N24830851529149 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 8 in Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, 255/70R22.5 Tires, 69556 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	9023	2000 Pro-Trak 53 ft T/A Step Deck Trailer S/N: 5BNDG5322YC001797 C/W: Spring Suspension, Electric Brakes, 9 ft
9017	2018 Trail King 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TKB04825JY067453 C/W: Air Ride Suspension, 9 ft 10 in Upper Deck, 37 ft Main Deck, 94 in Usable Deck Width, 97 in Overall Deck Width, Aluminum		Upper Deck, 39 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 225/75R16 Tires Usage: Not Available Asset located in: Humble, TX
	Flooring, 255/70R22.5 Tires, 90420 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9027	2016 Fontaine 53 ft T/A Step Deck Curtain Side Trailer
9018	2014 Direct Trailers 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 5UJDS4829EE002311 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 255/70R22.	Sliding Suspension, Ramp, Roll-Up	C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, Ramp, Roll-Up Door, Aluminum Outer Wheels, 225/70R22.5 Tires, 66667 lb GVWR Usage: Not Available
	5 Tires, 70852 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9028	2013 Utility FS2CHS 53 ft T/A Flatbed Trailer S/N: 1UYFS253XDA605017
9019	2013 Fontaine 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N248206D1557385 C/W: Air Ride Suspension, 10 ft Upper Deck, 38	9029	C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
,	ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Center Roller, Tail Roller, Wood Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX		2012 Great Dane 53 ft T/A Spread Axle Flatbed Trailer  S/N: 1GRDM0625CH715673  C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 70000
9020	2013 Transcraft 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE482S6D3756769		lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	C/W: Air Ride Suspension, 11 ft Upper Deck, 37 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available  Asset located in: Humble, TX	9030	2005 Benson 53 ft Tri/A Flatbed Trailer S/N: 5DMFABTC85M000235 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 255/70R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9031	2007 Chaparral 50 ft T/A Spread Axle Flatbed Trailer  S/N: 1C92F50257M949174  C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX	9036	2015 Benson 524 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A1F3882259 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9032	2023 Transcraft 40000 lb 48 ft T/A Spread Axle Flatbed Trailer (Unused) S/N: 1TTF482C2P3354782 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9037	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer  S/N: 1RNF48A29FR032427  C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX
9032A 9033	2020 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GR4M9624LH151129 C/W: Air Ride Suspension, Air Brakes, 97 in Deck Width, 102 in Overall Width, Aluminum w /Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX  2019 Manac 10248K001L 48 ft T/A Flatbed		2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer  S/N: 1RNF48A26FR032336  C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX
	Trailer S/N: 5MC124811K3181128 C/W: Air Ride Suspension, 92 in Deck Width, 102 in Overall Width, Wood Flooring, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A26FR032319 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 295/75R22.5 Tires, 90000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9034	Asset located in: Lake Worth, TX  2016 Great Dane FLP-0024-00048 48 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM9622GH729220 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Bulkhead, Aluminum Flooring, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9040	2015 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482A8F3882257 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX  2015 Fontaine 48 ft T/A Spread Axle Flatbed
9035	2015 Reitnouer 48 ft T/A Spread Axle Flatbed Trailer S/N: 1RNF48A22FR032303 C/W: Aluminum Frame, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum Flooring, 275/80R22.5 Tires, 90000 lb GVWR		Trailer S/N: 13N148202F1571993 C/W: Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 11R22.5 Tires, 70543 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	9042	2013 Transcraft 48 ft T/A Spread Axle Flatbed Trailer S/N: 1TTF482S7D3749530 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Wood Flooring, Aluminum Wheels, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9043	2012 Manac 48 ft T/A 48 ft - 80 ft Extendable Flatbed Trailer S/N: 2M5121463C1128632 C/W: Spring Suspension, Air Brakes, Sliding Suspension, 91 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 73855 lb GVWR	9050	2006 Transcraft 48 ft T/A Flatbed Trailer S/N: 1TTF4820961078665 C/W: Spring Suspension, Sliding Suspension, 95 in Deck Width, 102 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	9051	2008 Transcraft TL-2000N 45 ft T/A Flatbed Trailer
9044	2012 Utility 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2481CA431530 C/W: Air Ride Suspension, 79.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb GVWR	S C 9 F U	S/N: 1TTF4520082021315 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Humble, TX	9052	2005 Fontaine T/A 35 ft Extendable Flatbed Trailer
9045	2012 Utility FS2CHA 48 ft T/A Flatbed Trailer S/N: 1UYFS2483CA431528 C/W: Air Ride Suspension, 97.5 in Deck Width, 100.5 in Overall Width, Aluminum w/Wood Strips Flooring, 285/75R24.5 Tires, 73000 lb		S/N: 13N43620651527739 C/W: Spring Suspension, 87 in Deck Width, 91 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
9046	GVWR Usage: Not Available Asset located in: Humble, TX  2009 Wade WH1-48FT T/A Extendable Flatbed	9053	1999 Fontaine T/A Extendable Flatbed Trailer S/N: 13N548209X1586994 C/W: Air Ride Suspension, 98 in Deck Width, 98 in Overall Width, 11R22.5 Tires, 75074 lb GVWR
9040	Trailer		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
9047	S/N: 1W9FH48289E285033 C/W: Spring Suspension, Sliding Suspension, 11R22.5 Tires, 80000 lb GVWR, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: BENT FRAME PER SELLER Asset located in: Lake Worth, TX  2008 Fontaine 48 ft T/A Spread Axle Flatbed	9054	1999 Fontaine 48 ft T/A Spread Axle Flatbed Trailer  S/N: 1R1F94820XK990187  C/W: Aluminum Frame, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 11R24.5 Tires, 79600 lb GVWR Usage: Not Available
<del></del>	Trailer  S/N: 5TR34830081001876  C/W: Aluminum Frame, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum Flooring, 11R24.5 Tires, 71473 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  1988 Fontaine FTW-3-8045SL 45 ft T/A Flatbed Trailer  S/N: 13N1452CXJ1544459  C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 285/75R24.5 Tires Usage: Not Available
9048	2007 Lufkin 45 ft T/A Flatbed Trailer S/N: 1L01B452471164518 C/W: Spring Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		9056 2025 Atro 34 ft T/A Framel Trailer S/N: 3ELA6EH27SG000351 C/W: Spring Suspension, 34 Walls, Steel Body, Air Lift Tires, 74957 lb GVWR
9049	<b>2006 Lufkin 48 ft T/A Flatbed Trailer</b> S/N: 1L01B482761159825		Asset located in: Lake Worth, TX
	S/N: 1L01B482761159825 C/W: Spring Suspension, Sliding Suspension, 96 in Deck Width, 102 in Overall Width, Wood Flooring, 11R24.5 Tires, 80000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9057	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000348 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9058	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000349 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9065	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH20SG000384 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 Ib GVWR Usage: Not Available Asset located in: Lake Worth, TX	
9059	2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000347 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R24.5 Tires, 74957 lb GVWR, Aluminum Lead Body, 4 ft Lead Side Walls, Electric Lead Tarp Usage: Not Available Asset located in: Lake Worth, TX	9066	2015 MAC 40 ft T/A Aluminum Frameless End Dump Trailer  S/N: 5MADN4020FC033902  C/W: Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires, 80000 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX	
9060	2025 Atro T/A End Dump Trailer S/N: 3ELA6EH25SG000350 C/W: Spring Suspension, Air Brakes, 30 ft Body, 48 in Side Walls Usage: Not Available Asset located in: Lake Worth, TX	9067	2015 MAC 40 ft T/A Frameless End Dump Trailer S/N: 5MADN4029FC033901 C/W: Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Box Liner, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available	
9061	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH27SG000382 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2022 Discount Dumps 36 ft T/A End Dump Trailer  S/N: 1D91A3925N1865007  C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, 36 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum	
9062	2025 Atro 34 ft T/A Frameless End Dump Trailer	9069	Wheels, 11R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: 3ELA6EH24SG000386 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2016 Dragon 34 ft Tri/A Quarter Frame End Dump Trailer S/N: 1UNSD3431GS128862 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 34 ft Body, 50 in Side Walls,	
9063	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH22SG000385 C/W: Spring Suspension, 34 ft Body, 40 in Side Walls, Air Lift Tailgate, 11R24.5 Tires, 74957 lb		Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available Notes: . Asset located in: Humble, TX	
	GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		Dump Trailer	2016 Ranco ED 26-34 34 ft T/A Frameless End Dump Trailer S/N: 591SD3429GR136697
9064	2025 Atro 34 ft T/A Frameless End Dump Trailer S/N: 3ELA6EH29SG000383 C/W: Spring Suspension, 34 ft Body, 49 in Side Walls, High Lift Tailgate, 11R24.5 Tires, 74957		C/W: Spring Suspension, 34 ft Body, 44 in Side Walls, Steel Body, Electric Roll Tarp, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX	
	lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9071	2004 Midland MG34ST2400 34 ft T/A Quarter Frame End Dump Trailer  S/N: 2MFB2R5CX4R002967  C/W: Spring Suspension, 34 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Outer Wheels, 11R24.5  Tires, 80000 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9072	2017 Manac 32 ft T/A Frameless End Dump Trailer S/N: 5MC423214H3163988 C/W: Spring Suspension, 32 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 82000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9080	2021 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A3033XMH036270 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes:
9074	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer	0001	Asset located in: Humble, TX
	S/N: 5MC515423AP011370 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9081	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer S/N: 1M9A30339JH036173 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum
9075	2010 Manac HRS32 32 ft T/A Frameless End		Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available
	<b>Dump Trailer</b> S/N: 5MC515427AP011372		Notes: . Asset located in: Humble, TX
	C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift	9082	2001 Travis 39 ft T/A Frameless End Dump
	Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9082	Trailer S/N: 48X1F392911001782 C/W: Air Ride Suspension, 39 ft Body, 54 in
9076	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer S/N: 5MC515420AP011374 C/W: Spring Suspension, 32 ft Body, 41 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available		Side Walls, Aluminum Body, Manual Roll Tarp, 275/80R24.5 Tires Usage: Not Available
			Asset located in: Lake Worth, TX
		9083	2003 Ranco 36 ft T/A Frameless End Dump Trailer
	Asset located in: Lake Worth, TX		S/N: 1R9ESD5073L008627 C/W: Spring Suspension, 36 ft Body, 46 in Side
9077	2010 Manac HRS32 32 ft T/A Frameless End Dump Trailer		Walls, Šteel Bodý, Electric Roll Tarp, High Lift Tailgate, 11R22.5 Tires, 70000 lb GVWR Usage: Not Available
	S/N: 5MC515429AP011373 C/W: Spring Suspension, 32 ft Body, 41 in Side		Asset located in: Lake Worth, TX
	Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available	9084	2002 Vantage 37 ft T/A Aluminum Frameless End Dump Trailer S/N: 4EPAA37292ATA4342
9078	Asset located in: Lake Worth, TX  2021 Mate 30 ft Tri/A Aluminum Quarter Frame End Dump Trailer	C/W: Air Ride Suspension, 37 ft Body, 50 Side Walls, Aluminum Body, Manual Roll 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX  9085 1999 Smithco T/A Side Dump Trailer S/N: 1S9SS4022XL476665 C/W: Spring Suspension, Dumps to Both 36 in Side Walls, Steel Body, 425/66R22.	
	S/N: 1M9A30333MH036271		<u> </u>
	C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Notes: .		•
	Asset located in: Humble, TX		Asset located in: Lake Worth, TX
9079	2018 Mate 30 ft Tri/A Quarter Frame End Dump Trailer  S/N: 1M9A30332JH036175  C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 30 ft Body, 50 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires, 43500 lb GVWR Usage: Not Available  Notes: .  Asset located in: Humble, TX	9086	1983 Fontaine 12 ft T/A Pup Dump Trailer S/N: 1A1V2920XD16PT113 C/W: Spring Suspension, 12 ft Body, 46 in Side Walls, Steel Body, Manual Roll Tarp, 10.00-22 Tires, 47500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9087	2017 CTS BDT 40 T/A Belly Dump Trailer S/N: 5TU114021HS000432 C/W: Air Ride Suspension, Clam Gate Electric Roll Tarp Push Block, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9096	1997 Schaller Manufacturing Roadmaster G420 40 ft T/A Belly Dump Trailer S/N: 4SBGS4220VS100145 C/W: Spring Suspension, Clam Gate Manual Roll Tarp, 11R22.5 Tires, 60000 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available
9088	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114021GS000512 C/W: Air Ride Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9097	Asset located in: Lake Worth, TX  2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer  S/N: 1TDH42229HB156037  C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps, 42 ft Aluminum Box, 72 in, Side Walls, Electric
9089	2016 CTS BDT-40 T/A Belly Dump Trailer S/N: 5TU114028GS000197 C/W: Spring Suspension, Clam Gate Manual Roll Tarp Push Block, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9098	Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Asset located in: Midland, TX 1999 Timpte 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42224XB096554 C/W: Air Ride Suspension, Manual Traps, 42 ft Aluminum Box, 84 in, Side Walls, Manual Roll
9091	2016 Construction Trailer Specialist BDT-40 T /A Belly Dump Trailer S/N: 5TU114024GS000021		Tarp, Air Scales, 285/75R24.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9099	2023 East 53 ft T/A Curtain Side Trailer S/N: 1E1H5Z284PR080410 C/W: Aluminum Frame, Air Ride Suspension, Sliding Suspension, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available
9092	2014 Armor Lite SBD-40 40 ft T/A Belly Dump Trailer		Asset located in: Lake Worth, TX
	S/N: 56EA53K23EA000188 C/W: Spring Suspension, Cross Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9100	2012 Western 53 ft T/A Spread Axle Curtain Side Trailer S/N: 5DN115323CB000814 C/W: Air Ride Suspension, Aluminum Wheels, 295/75R22.5 Tires, 69000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9093	2013 Manac 40 ft T/A Belly Dump Trailer S/N: 5MC424017D3133810 C/W: Air Ride Suspension, Clam Gate Electric Roll Tarp Push Block, 11R24.5 Tires, 75000 lb GVWR, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9101	1999 Nu Van NVSS 53 ft 53 ft x 102 in T/A Curtain Side Trailer S/N: 1N9F532P7X1045092 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9094	2003 Trail King BD237 T/A Belly Dump Trailer S/N: 1TKSC40213W101924 C/W: Walking Beam Suspension, Cross Gate Electric Roll Tarp, 11R24.5 Tires, 74000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9102	1998 Raven 48 ft T/A Spread Axle Curtain Side Trailer S/N: 1R1F04823WK980200 C/W: Aluminum Frame, Air Ride Suspension, 285/75R24.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9095	1999 Midland MG36CLAM T/A Belly Dump Trailer S/N: 2MFB2S5C9XR000607 C/W: Spring Suspension, Clam Gate Electric Roll Tarp Push Block, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9103	2024 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX22RG000079 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9104	023 Atro 53 ft x 102 in Van Trailer /N: 3ELA6RX28PG000052 :/W: Air Ride Suspension, Sliding Suspension, Iluminum Roof, Hardwood Floor, Side Skirts, wing Door, 295/75R22.5 Tires, 68000 lb :/WR sage: Not Available lotes: SELLING WITH A REPOSESSION	9110	2022 Inland IN53-DPA-HK40 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N5NM180012 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
0105	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX	9111	2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N9MM180044 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof,
9105	2023 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX24PG003157 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Outer Wheels, 295		Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		2021 Inland 53 ft x 102 in T/A Van Trailer S/N: 3T9S372N0MM180045 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available
0106	Asset located in: Lake Worth, TX	0112	Asset located in: Lake Worth, TX  2021 Inland IN53-DPA-HK40 53 ft x 102 in T/A
9106	2023 Vanguard REM VXP 53 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5324PT305207 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN		Van Trailer S/N: 3T9S372N7MM180124 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Humble, TX	Trailer  S/N: 1UYVS2533L3961520 C/W: Air Ride Suspension, S Aluminum Roof, Hardwood Roll-Up Door, 295/75R22.5 Usage: Not Available Asset located in: Humble, T  9116  2020 Utility VS2DX 53 ft x 1 Trailer S/N: 1UYVS2532L7961064 C/W: 65000 lb GVWR, Air R Sliding Suspension, Alumin Floor, Side Skirts, Swing Do Tires Usage: Not Available Asset located in: Humble, T  9117  2020 Utility VS2DX 53 ft T/ S/N: 1UYVS2531L3961595 C/W: Air Ride Suspension, S Aluminum Roof, Hardwood Roll-Up Door, 295/75R22.5 Usage: Not Available Asset located in: Humble, T	2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer
9107	2022 Vanguard MaxCube 53 ft x 102 in T/A Van Trailer S/N: 5V8VA5321NM211220 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door,		S/N: 1UYVS2533L3961520 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		S/N: 1UYVS2532L7961064
9108	2022 Atro 53 ft x 102 in T/A Van Trailer S/N: 3ELA6RX21NG001704 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires		Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires
9109	Usage: Not Available Asset located in: Lake Worth, TX  2022 Hyundai VC2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532K6NS852024 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: FRAME IS DAMAGED; Asset located in: Lake Worth, TX		2020 Utility VS2DX 53 ft T/A Van Trailer S/N: 1UYVS2531L3961595 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9118	2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2534L3961509 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9125	2016 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2535GG724302 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9119	·	9126	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer  S/N: 1JJV532D5FL877087  C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX
9120	PRIOR TO BIDDING  Asset located in: Lake Worth, TX  2019 Great Dane CCC-3314-21053 53 ft x 102	9127	2015 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2531FG241727 C/W: 65000 lb GVWR, Aluminum/Steel
9120	in T/A Van Trailer  S/N: 1GRAP0621KJ137637  C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX	C B H T U <b>N</b> A	Combination Frame, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DIPRIOR TO BIDDING
9121	2019 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2539K3560164 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9128	Asset located in: Lake Worth, TX  2015 Wabash DVHDHPC 53 ft x 102 in T/A Van Trailer  S/N: 1JJV532D9FL880526  C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Notes: Asset located in: Lake Worth, TX
9122	2018 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9JR390021 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door Usage: Not Available	9129	2015 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D1FL799987 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9123	Asset located in: Lake Worth, TX  2018 Stoughton ZGPVW-535T-S-C 53 ft x 102 in T/A Van Trailer  S/N: 1DW1A5320JSA09456  C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9130	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D3FL845934 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

	D	T	
Lot #	Details	Lot #	Details
9131	2015 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532DXFL833585 C/W: Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9142	2008 Hyundai 53 ft x 102 in T/A Van Trailer S/N: 3H3V532C18T249117 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, Mixed Tires Usage: Not Available Notes: THE CLOSING TIME OF LOTS 8674 TO 8675 ARE TIED TOGETHER. IF A BID IS
9132	2015 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer  S/N: 1JJV532DXFL842528  C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX		RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER OF LOTS 8674 TO 8675 IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER  Asset located in: Lake Worth, TX
9136	2012 Hyundai VI2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C9CT100009 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	9143	2008 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E95388E520408 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9137	Asset located in: Lake Worth, TX  2012 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0628CT566670 C/W: Air Ride Suspension, Sliding Suspension,	9144	2008 Utility 53 ft Van Trailer S/N: 1UYVS25338U340103 Usage: Not Available Asset located in: Lake Worth, TX
	Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9145	2008 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS253X8P320087 C/W: Aluminum/Steel Combination Frame, Air
9139	2009 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VA53269M903270 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR		Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Humble, TX	9146	<b>2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer</b> S/N: 1GRAA06287T539717
9140	2009 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VA532X9M903272 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available		C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9147	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A
9141	2008 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A53208B027611 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Van Trailer S/N: 1GRAA06247G341628 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9148	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277J622907 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9154	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer  S/N: 1GRAA06257J618967  C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR  Usage: Not Available  Asset located in: Humble, TX
9149	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217J618769 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9155	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06217D423608 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Asset located in: Humble, TX
9150	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06277D423628 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 30845 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9158 9159 9160	2007 Great Dane 7411TP-SA 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06207J623042 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX  2007 Lufkin TFV-CL-SP 53 ft x 102 in T/A Van
9151	Asset located in: Humble, TX  2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06227D423651 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Trailer S/N: 1L01A532071163667 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9152	Asset located in: Humble, TX  2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06287D426747 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 445/50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX		2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W07L048317 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door Usage: Not Available Asset located in: Lake Worth, TX  2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W37L094904
9153	2007 Great Dane 7411TP 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06237D423576 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 445 /50R22.5 Super Single Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9161	C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX  2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W07L051279 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
9162	2007 Wabash DVLHHSA 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W37L064138 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9168	2006 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS25386G753257 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE
9163	<b>2007 Wabash 53 ft x 102 in T/A Van Trailer</b> S/N: 1JJV532W97L079985		Asset located in: Lake Worth, TX
	C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9170	2006 Lufkin TFC-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532361161071 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door,
9164	2007 Wabash DVLSHPC 53 ft x 102 in T/A Van Trailer		295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available <b>Asset located in</b> : Humble, TX
	S/N: 1JJV532W27L080010 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9171	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261160929 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts,
9165	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W97L080022 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor,	9172	Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available <b>Asset located in</b> : Humble, TX
	Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX		2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Var Trailer S/N: 1L01A532661160948 C/W: Air Ride Suspension, Sliding Suspension,
9166	2006 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W16L944656		Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available <b>Asset located in</b> : Humble, TX
	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9173	2006 Lufkin TFV-CL-110 53 ft T/A Van Traile S/N: 1L01A532461161032 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floo Side Skirts, Swing Door, 295/75R22.5 Tires,
9167	<b>2006 Wabash 53 ft x 102 in Van Trailer</b> S/N: 1JJV532W76L978391		65000 lb GVWR Usage: Not Available <b>Asset located in</b> : Humble, TX
	C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9174 2006 Lufkin TFV-CL-110 53 ft x 10 Trailer S/N: 1L01A532X61161066 C/W: Air Ride Suspension, Air Bra Suspension, Aluminum Roof, Har	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532X61161066 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb
9167A	2006 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W36L985340 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available

Lot #	Details	Lot #	Details
9175	2006 Lufkin TFV-CL-110 53 ft x 102 in T/A Van Trailer S/N: 1L01A532261161062 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	9183	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06274G332238 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX  2004 Great Dane 7311TP-S 53 ft x 102 in T/A
	THE INSPECTION REPORT  Asset located in: Humble, TX	9184	Van Trailer
9177	2006 Great Dane 7411T-SSL 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06206J610192 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP		S/N: 1GRAA06244G332231 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	9185	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer
9178	2006 Stoughton 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532468871342 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires		S/N: 1GRAA06274G332286 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available <b>Asset located in</b> : Humble, TX	9186	2004 Wabash DVLHHSA 53 ft x 102 in T/A Var
9179	2006 Stoughton AVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer  S/N: 1DW1A53266E813926  C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR		Trailer S/N: 1JJV532W74L875727 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	9187	2004 Wabash JWHDHPC 53 ft x 102 in T/A Van Trailer
9180	2005 Hyundai 53 ft Van Trailer S/N: 3H3V532C05T169027 Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1JJV532W44L873952 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available
9181	2005 Trailmobile 53 ft x 102 in T/A Van Trailer S/N: 2MN01JAH751003219 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9188	Asset located in: Lake Worth, TX  2004 Wabash 53 ft x 102 in T/A Van Trailer  S/N: 1JJV532W74L873251  C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available  Asset located in: Lake Worth, TX
9182	2004 Great Dane 7311TP-S 53 ft x 102 in T/A Van Trailer	9189	2003 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer
	S/N: 1GRAA06224G332275 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1JJV532W23L815529 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9190	2003 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W43L835135 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	9197	1998 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532Y4WL427465 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
9191	2003 Great Dane 7411TP-SA 53 ft x 102 in T/A	Ī	Asset located in: Lake Worth, TX
	Van Trailer S/N: 1GRAA06203G327168 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9198Z	1998 Dorsey AIDT-LS 53 ft x 102 in T/A Van Trailer S/N: 1DTV11520WA267474 C/W: Spring Suspension, Sliding Suspension, Lift Gate, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
9192	2001 Wabash Unknown 53 ft x 102 in T/A Van Trailer  S/N: 1JJV532W41L763639  C/W: Air Ride Suspension, Sliding Suspension, Hardwood Floor, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9199	1997 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532YX4VL387234 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9193	Asset located in: Midland, TX  2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W9YL723387 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door Usage: Not Available Asset located in: Lake Worth, TX	<b>-9200</b>	1997 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E953XVD412521 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX
9194	2000 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0626YB016106 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX 2000 Strick 53 ft x 102 in T/A Van Trailer	9201	1996 Lufkin TFV-IPST 53 ft x 102 in T/A Van Trailer  S/N: 1L01A5322T1120913  C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Asset located in: Lake Worth, TX
	S/N: 1S12E953XYD455230 C/W: 65000.0 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX		2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D9GL957237 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR, EQUIPMENT-FROM-YELLOW-CORP
9196	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W6YL657722 C/W: Spring Suspension, Air Brakes, Sliding		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: .  Asset located in: Humble, TX	9213	2016 Wabash DVCVHPC 40 ft x 102 in S/A Van Trailer  S/N: 1JJV401D1GL957202  C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5  Tires, 40000 lb GVWR, EQUIPMENT-FROM-YELLOW-CORP  Usage: Not Available  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9219	2004 Great Dane 48 ft x 102 in T/A Van Trailer S/N: 1GRAA962X4K262283 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9227Z	2004 Great Dane 7311TP-S 40 ft x 102 in T/A Van Trailer  S/N: 1GRAA80274K262745  C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 22.5 mix Tires, EQUIPMENT-FROM-YELLOW-CORP	
9220	<b>2004</b> Great Dane <b>7311TPS 40</b> ft x <b>102</b> in T/A <b>Van Trailer</b> S/N: 1GRAA80234K262726		Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP Asset located in: Greenwood, LA	
	C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9229	1999 Fruehauf 45 ft x 102 in T/A Van Trailer S/N: 1JJV452FXXF543251 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP	
9220A	2001 Great Dane 48 ft x 102 in T/A Van Trailer		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	S/N: 1GRAA962X1K237671 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Notes: LOCATED-IN-JUSTIN-TX-YELLOW; EQUIPMENT-FROM-YELLOW-CORP	9231	1995 Strick 48 ft x 102 in T/A Van Trailer S/N: 1S12E9489SD398829 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, hardwood floors with steel plate on top, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available	
0001	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX	
9221	2001 Great Dane 7311 T S 48 ft x 102 in T/A Van Trailer S/N: 1GRAA96281G318316 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available		1995 Pines 48 ft x 102 in T/A Van Trailer S/N: 1PNV482N3SKB67178 C/W: Aluminum Frame, Spring Suspension, Air Brakes, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX		1993 Wabash 48 ft x 102 in T/A Van Trailer	
9222	2000 Trailmobile 48 ft x 102 in T/A Van Trailer S/N: 1PT01JPH0Y8002343 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available		S/N: 1JJV482Y1PL197966 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: . Asset located in: Humble, TX	
	Asset located in: Lake Worth, TX	9234Z	1988 Fruehauf 48 ft x 102 in T/A Van Trailer	
9223	2001 Fruehauf 40 ft T/A Van Trailer S/N: 1JJV402F81F732037 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP		C/W: Spring Suspension, Hardwood	Usage: Not Available
	Usage: Not Available  Asset located in: Lake Worth, TX	9235	1988 Lufkin 48 ft T/A Van Trailer S/N: 1L01A4828J1078828 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, 295/75R22.5 Tires, 65000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
9224	2001 Fruehauf Unknown 40 ft x 102 in T/A Van Trailer S/N: 1JJV402F31F732060 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Lift Gate, Roll-Up Door, R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX			

Lot #	Details	Lot #	Details	
9236	1985 Budd 45 ft x 102 in T/A Van Trailer S/N: 1BK10W925FE217508 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9243	2014 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2819EB457745 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	
9237	1999 Fruehauf 40 ft x 102 in T/A Van Trailer		Asset located in: Lake Worth, TX	
	S/N: 1JJV402FXXF543849 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9244	2009 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W29L286194 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	
9238	1963 Fruehauf VG-X-F2-40 40 ft x 96 in T/A		Asset located in: Lake Worth, TX	
	Van Trailer S/N: MED289407 C/W: Spring Suspension, Sliding Suspension, Hardwood Floor, Roll-Up Door, 10.00-20 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX	9245	2008 Great Dane Unknown 28 ft x 102 in S/A Van Trailer  S/N: 1GRAA56178K295814  C/W: Spring Suspension, Pintle Hitch, Translucent Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP	
9239	2020 Wabash DVDBHPC 28 ft x 102 in S/A Van		Usage: Not Available <b>Asset located in</b> : Midland, TX	
	Trailer S/N: 1JJV281DXLL216433 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Aluminum Roof, Wood and Aluminum Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9250	2003 Great Dane 28 ft x 102 in S/A Van Trailer S/N: 1GRAA56103K246687 C/W: 34000 lb GVWR, Spring Suspension, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available  Asset located in: Lake Worth, TX	
0240	<u> </u>	0251		
9240	2020 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer  S/N: 1JJV281D5LL216422  C/W: 40000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295  /75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9251	2002 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F32F778964 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Lake Worth, TX	9252	1990 Stoughton FRPD-323S 32 ft S/A	
9241	2017 Stoughton 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2812HB720243 C/W: Spring Suspension, Pintle Hitch, Hardwood Floor, Side Skirts, Roll-Up Door, R22. 5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available		S/N: 1DW1A3217LS669202	C/W: Spring Suspension, Pintle Hitch, 295 /75R22.5 Tires, 68080 lb GVWR Usage: Not Available
	Asset located in: Rosharon, TX	9253	1999 Fruehauf 28 ft x 102 in S/A Van Trailer	
9242	2017 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D9HL987165 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	Hitch, Translucent Roof, Hardwo Up Door, 295/75R22.5 Tires, EQI FROM-YELLOW-CORP Usage: Not Available	C/W: Spring Suspension, Air Brakes, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP	

	D	I	
Lot #	Details	Lot #	Details
9254	1998 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F4WF456405 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Ramp, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Asset located in: Lake Worth, TX	9261Z	1978 Fruehauf FBB X F1 27 27 ft x 96 in S/A Van Trailer S/N: MEY545851 C/W: Spring Suspension, Pintle Hitch, Roll-Up Door, 11R24.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
9255	1992 Fruehauf FPP9-NF1-28 28 ft x 102 in S/A Van Trailer S/N: IH2V02815NE029459 C/W: 50000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Aluminum w/Wood Strips Flooring, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available	9262Z 9263	1977 Trailmobile 27 ft x 96 in S/A Van Trailer S/N: P95650 C/W: Spring Suspension, Pintle Hitch, Hardwood Floor, Roll-Up Door, 11R24.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX		Trailer
9256	1990 Trailmobile 28 ft x 96 in S/A Van Trailer S/N: 1PT071NE8L9001242 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 3UTVS2536N8451727 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2020 Thermo King Precedent S-600 Refrigeration Unit, Serial Number 6001327716,, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: 8,204 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES
9257	1988 TRMO 28 ft x 96 in S/A Van Trailer		NOTED - PLEASE SEE THE INSPECTION
7207	S/N: 1PT071NE8J9009726		REPORT  Asset located in: Humble, TX
	C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9264	2020 Wabash 53 ft x 102 in T/A Spread Axle Refrigerated Trailer S/N: 1JJV532B4LL218265 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Air
9258	1988 Trim 28 ft x 102 in S/A Van Trailer S/N: 1PT071NE1J9006327 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Aluminum Roof, Aluminum Floor, Ducted Floor, Roll-Up Door, 295/75R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX  1988 Trailmobile 28 ft x 102 in S/A Van Trailer		Brakes, Sliding Suspension, Front/Re Swing Door, 2008 Thermo King TK4: Refrigeration Unit, Aluminum Wheels /75R22.5 Tires Usage: Not Available <b>Notes</b> : SELLING WITH A REPOSESS AFFIDAVIT AND MAY NOT BE ACCE YOUR STATE. VERIFY WITH YOUR L
9239	S/N: 1PT071NE4J9002630	0065	<u> </u>
	C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Aluminum Floor, Ducted Floor, Roll-Up Door, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9265	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2539L2821820 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Precedent Refrigeration Unit, Serial Number 6001278644,
9260Z	1978 Pines 31 ft x 96 in S/A Van Trailer S/N: 323CDV7748 C/W: Spring Suspension, Hardwood Floor, Roll- Up Door, 10.00-20 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Midland, TX		295/75R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9265A	2019 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B6KL090898 C/W: Spring Suspension, Air Brakes, Side Skirts, Ducted Floor, Swing Door, Carrier X4 7500 Refrigeration Unit, Serial Number SAW91536396,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9271	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538HU767213 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2016 Carrier 7300 X4 Refrigeration Unit, Serial Number RAV91457566,, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9267	2018 Utility 53 ft x 102 in T/A Spread Axle Refrigerated Trailer S/N: 1UYVS2536J2076912 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION	9272	2017 Great Dane FTL-1114-31053 Refrigerated Trailer S/N: 1GRAA0627HB700016 Usage: 14,488 Hr Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE; Asset located in: Humble, TX
0060	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX	9272A	2017 CIMC 53 ft x 102 in T/A Refrigerated Trailer  S/N: 527SR5326HM009310  C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier
9268	2018 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XJ6106924 C/W: Air Ride Suspension, Sliding Suspension, Swing Door, Carrier 7300 Refrigeration Unit,	9273	Refrigeration Unit, Aluminum Wheels, 295 /75R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Serial Number SAL91508417,, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		Trailer S/N: 1UYVS2538GU615320 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor Swing Door, Carrier 7500X4 Refrigeration Ur Serial Number N/A, Aluminum Wheels, 295
9269	Asset located in: Lake Worth, TX  2018 Utility 53 ft x 102 in T/A Spread Axle Multi-Temp Refrigerated Trailer S/N: 1UYVS2536J2130709	_	/75R22.5 Tires Usage: 14,454 Hr Notes: . Asset located in: Lake Worth, TX
0070	C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX	9274	2016 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2532GU723903 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2016 Thermo King S600 Refrigeration Unit, Serial Number 6001214678, Aluminum Outer Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: 14,614 Hr
9270	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer		Asset located in: Lake Worth, TX
	S/N: 1UYVS2530HU891122 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Thermo King S-600 Refrigeration Unit, Serial Number 6001220977, Aluminum Wheels, 295/75R22.5 Tires Usage: 19,620 Hr Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9275	2016 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538GU451907 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, 2015 Thermo King 3000R Refrigeration Unit, Serial Number 6001196770,, 295/75R22.5 Tires Usage: 15,487 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9276	2015 Utility Multi Temp 53 ft T/A Refrigerated Trailer  S/N: 1UYVS2488FU171108  C/W: 65000 lb GVWR, Aluminum Frame, Spring Suspension Usage: Not Available  Asset located in: Lake Worth, TX  2015 Utility 53 ft x 102 in T/A Refrigerated	9282	
	<b>Trailer</b> S/N: 1UYVS253XFM838425		Usage: 29,942 Hr  Asset located in: Lake Worth, TX
	C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Swing Door, Carrier Refrigeration Unit, 295/75R22.5 Tires Usage: 5,800 Hr  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Humble, TX	9283	2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2532EU019102 C/W: 65000 lb GVWR, Air Ride Suspension, Air Brakes, Swing Door, 2013 Carrier X4 7500 Refrigeration Unit, Serial Number PAP91356207,, 295/75R22.5 Tires Usage: 17,869 Hr Asset located in: Lake Worth, TX
9278	<b>2015 Great Dane 53 ft Refrigerated Trailer</b> S/N: 1GRAA0625FE701757	9284	2014 Utility 53 ft Refrigerated Trailer
	Usage: Not Available  Asset located in: Lake Worth, TX		S/N: 1UYVS2533EM974720 C/W: Thermo King Refrigeration Unit Usage: Not Available
9279	2015 Great Dane ETL-1114-11053 53 ft x 102		Asset located in: Lake Worth, TX
	in T/A Refrigerated Trailer S/N: 1GRAA0624FB702447 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier Vector 6500 Refrigeration	9285	2013 Utility 48 ft Refrigerated Trailer S/N: 1UYVS2481DM771708 Usage: Not Available Asset located in: Lake Worth, TX
	Unit, Serial Number NAN9127382,, 295/75R22. 5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	9286	2013 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B1DL763731 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Swing Door, Thermo King SB-230 Refrigeration Unit,
	THE INSPECTION REPORT  Asset located in: Humble, TX		
9280	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B0EL788928		295/75R22.5 Tires Usage: 15,345 Hr Asset located in: Lake Worth, TX
	C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2013 Carrier X2 2500APX Refrigeration Unit, Serial Number PAM91348526,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available  Asset located in: Humble, TX		2013 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B2DL763740 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Thermo King SB-230 Refrigeration Unit, 295/75R22.5 Tires
9281	2014 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer		Usage: 12,753 Hr <b>Asset located in</b> : Lake Worth, TX
	S/N: 1JJV532BXEL817674 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 6001144127,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 9,279 Hr Asset located in: Lake Worth, TX	9288	2013 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C3DT256001 Usage: 17,316 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9289	Trailer  S/N: 3H3V532C8DT512004  C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001128459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 20,603 Hr	9295	2012 Wabash 53 ft x 102 in T/A Refrigerated Trailer
			S/N: 1JJV532BXCL686629 C/W: Spring Suspension, Air Brakes, Ducted Floor, Swing Door, Carrier 2100A Refrigeration Unit, 295/75R22.5 Tires, 68000 lb GVWR Usage: 16,897 Hr
			Asset located in: Lake Worth, TX
		9296	2012 Wabash RFALHSA 53 ft T/A Refrigerated
9290			Trailer S/N: 1JJV532B3CL703187 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Swing Door, Carrier X2500 Refrigeration Unit, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
	6001128461,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	9297	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer
	Asset located in: Lake Worth, TX		S/N: 1JJV532B7CL686636 C/W: Spring Suspension, Sliding Suspension,
9291	2012 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537CM264524		Side Skirts, Ducted Floor, Front/Rear Vents, Swing Door, Carrier 2100A Refrigeration Unit, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
	C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, 2013 Carrier 2500R		Asset located in: Lake Worth, TX
	Refrigeration Unit, Serial Number NAB91209850,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 13,798 Hr <b>Asset located in</b> : Humble, TX	9298	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B1CL686633 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Roll-Up Door, Carrier X2500R Refrigeration Unit, 295/75R22. 5 Tires Usage: 16,418 Mi Asset located in: Lake Worth, TX
9292	2012 Hyundai 53 Ft x 102 In T/A Refrigerated Trailer S/N: 3H3V532C4CT436005		
	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Roll-Up Door, Thermo King SB230 Refrigeration Unit, Serial Number 6001103448,, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9299	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV53CB1CL718268 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAN91272008,, 295/75R22.5
9293	2012 Hyundai 53 ft x 102 in T/A Refrigerated Trailer		Tires, 68000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: 3H3V532C7CT436001 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103459,, 295/75R22.5 Tires, 68000 lb GVWR Usage: 23,320 Hr Asset located in: Lake Worth, TX	9300	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B8CL686824 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Sliding Suspension, Swing Door, Carrier X2100A Refrigeration Unit, 295/75R22.5 Tires Usage: 16,925 Hr
9294	2012 Wabash 53 ft x 102 in T/A Refrigerated		Asset located in: Lake Worth, TX
	Trailer S/N: 1JJV532B7CL718324 C/W: Spring Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAM91270893,, 295/75R22.5 Tires Usage: 16,367 Hr Asset located in: Lake Worth, TX	9301	2012 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B4CL718345 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2011 Carrier X2 2100A Refrigeration Unit, Serial Number NAN91274448,, 295/75R22.5 Tires Usage: 17,075 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9302	2012 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0622CW703603 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Side Skirts, Swing Door, Carrier 2100A Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9308	2014 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480EU771507 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Thermo King Refrigeration Unit, Serial Number 600133514,, 11R22.5 Tires, 65000 lb GVWR Usage: 27,250 Hr Asset located in: Lake Worth, TX
9303	2011 Wabash RFALHSA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1JJV532B7BL330878 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, 2010 Carrier X2 2500A Refrigeration Unit, Serial Number NAA91203262, Usage: 32,464 Hr Notes: .	9309	2013 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2480DM567319 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 60011112528,, 11R22.5 Tires, 65000 lb GVWR Usage: 48,998 Hr Asset located in: Lake Worth, TX
9304	Asset located in: Lake Worth, TX  2011 Great Dane SUP-1114-01053 53 ft x 102 in T/A Refrigerated Trailer  S/N: 1GRAA0627BW702896  C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier 2500R Refrigeration Unit, 295  /75R22.5 Tires, 68000 lb GVWR  Usage: 20,695 Hr  Asset located in: Lake Worth, TX	9310	2013 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS248XDM771710 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2012 Thermo King Refrigeration Unit, Serial Number 6001128316,, 11R22.5 Tires, 65000 lb GVWR Usage: 42,743 Hr Asset located in: Lake Worth, TX
9305	2010 Graet Dane SUP-1114-11053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625AQ702846 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Swing Door, Carrier X2 2100 Advance Refrigeration Unit, 295/75R22.5 Tires Usage: 27,108 Hr Asset located in: Lake Worth, TX	9311	2014 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2483EU771503 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001133500,, 11R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX
9306	2006 Wabash 53 ft x 102 in T/A Refrigerated Trailer  S/N: 1JJV532W86L980540  C/W: Spring Suspension, Sliding Suspension, Swing Door, Carrier Refrigeration Unit, 295  /75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX  2015 Great Dane ECM-113 48 ft x 102 in T/A	9312	2012 Utility VS2RA 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2483CU463504 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Swing Door, 2011 Thermo King Smart Reefer 2 Refrigeration Unit, 11R22.5 Tires, 65000 lb GVWR Usage: 48,492 Hr Asset located in: Lake Worth, TX
	Refrigerated Trailer S/N: 1GRAA9622FE702031 C/W: Spring Suspension, Sliding Suspension, Curbside Door, Roll-Up Door, Thermo King Whisper Refrigeration Unit, Serial Number 6001178338,, 295/75R22.5 Tires Usage: 27,626 Hr Asset located in: Lake Worth, TX	9313	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2489CU248709 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2013 Thermo King Refrigeration Unit, Serial Number 6001133500,, 295/75R22.5 Tires, 65000 lb GVWR Usage: 31,576 Hr Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9314	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer  S/N: 1UYVS2488CU463501  C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Ducted Floor, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 6001103810,, 11R22.5 Tires, 65000 lb GVWR Usage: 49,586 Hr	9321	1992 TRMB 28 ft x 96 in S/A Refrigerated Trailer S/N: 1PT071NE4N9012595 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Pintle Hitch, Thermo King SII-50 MAX Refrigeration Unit, Serial Number 0322628122, Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9322	2019 Holcombe HM12H 12 cft Portable
9315	2012 Utility 48 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS248XCU463502 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, 2011 Thermo King Refrigeration Unit, Serial Number	9323	Concrete Mixer S/N: 16MBB3132KF078754 C/W: Deutz Diesel Engine Usage: Not Available Asset located in: Lake Worth, TX 2024 44 ft x 12 ft 1 in Portable Tri/A Mobile
	6001103816,, 65000 lb GVWR Usage: 50,063 Hr  Asset located in: Lake Worth, TX		Office S/N: 102410 C/W: ( 2 ) Offices, ( 1 ) Bathrooms, Air
9316	2001 Great Dane Refrigerated Trailer S/N: 1GRAA06221W001925 Usage: Not Available Asset located in: Lake Worth, TX	9324	Conditioner, Ball Hitch, Spring Suspension, 8- 14.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
9317	1996 Trailmobile 28 ft x 96 in S/A Refrigerated Trailer S/N: 1PT071NE2T9002371 C/W: Spring Suspension, Air Brakes, Ducted Floor, Roll-Up Door, Thermo King Sentry II Max Refrigeration Unit, Serial Number 1145AL6026,, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2022 20 ft x 8 ft Mobile Office  S/N: TJCC22122989  C/W: 12000 BTU Heat and AC Split System, Indoor Breaker Box, R-13 Insulation, 2 windows, Metal Front Door, Security Bars, Security Locks on all Doors, LED Lighting, Wood Trim, Laminated Flooring Storage Roo for High Value Tools and Equipment, Chargin Dock for Power Tools, Wire Shelving in Store Room Usage: Not Available
9318	1995 Trailmobile 28 ft S/A Refrigerated Trailer		Asset located in: Lake Worth, TX
	S/N: 1PT071NE6S9012996 C/W: Spring Suspension, Roll-Up Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9325	28 ft x 8 ft Portable S/A Mobile Office S/N: Not Available C/W: (2) Offices, Spring Suspension, Sliding Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
9319	1993 Great Dane 7011Z-1 28 ft x 102 in S/A		Asset located in: Lake Worth, TX
	Refrigerated Trailer S/N: 1GRAA5614PB081703 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Roll-Up Door, Thermo King Refrigeration Unit, Serial Number 0132822805,, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9326	28 ft x 8 ft Portable S/A Mobile Office S/N: Not Available C/W: (2) Offices, Air Conditioner, Spring Suspension, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
9320	1993 Great Dane 7011Z-1 28 ft x 102 in S/A Refrigerated Trailer S/N: 1GRAA5615PB081709 C/W: Spring Suspension, Air Brakes, Roll-Up	9327	2024 Garper GP8-24 Mobile Office S/N: 3ECG24C1XRGEP0174 Usage: Not Available Asset located in: Lake Worth, TX
	Door, Thermo King Refrigeration Unit, 11R22.5 Tires, 39000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9328Z	2024 Garper GP8-24 Mobile Office S/N: 3ECG24C1XRGEP0175 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9329	36 ft x 12 ft 1 in Portable T/A Mobile Office S/N: 135369 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, 8-14.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9350	2023 GRUPO 15 ft 8 in T/A Container Trailer S/N: 3BZPN402XPC008328 C/W: 65000 lb GVWR, Air Ride Suspension, 295 /75R22.5 Tires Usage: Not Available Asset located in: Midland, TX
9330	2025 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR29SG000287 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9351	2023 Kerr-Bilt 40 ft Container Trailer S/N: 1J9GC402XPB253228 C/W: Aluminum Frame, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9330A	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR21SG000302 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available	9351A	2018 Benlee TASMRS26S T/A Roll-Off Trailer S/N: 1B9A12625JB180059 C/W: Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX
9334	Asset located in: Lake Worth, TX  2025 Atro 40 ft T/A Quantity of (4) Container Trailer  S/N: 3ELA6CR21SG000297  C/W: Spring Suspension, 40 ft - Container Pins,	9352	2011 Dragon T/A Roll-Off Trailer S/N: 1D9SH4824BC661799 C/W: 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9353	2008 Dragon TCT440 T/A Roll-Off Trailer S/N: 1UNSH48288C066531 C/W: Air Ride Suspension, Aluminum Wheels 285/75R24.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9335	2025 Atro 40 ft T/A Quantity of (5) Container Trailer S/N: 3ELA6CR22SG000292		
	C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		S/N: 1E9RS4823Y1229101 C/W: Air Ride Suspension, Aluminum Whee
9346	2024 Atro 53 ft T/A Container Trailer (Unused) S/N: 3ELA6CX24RG000212		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Spring Suspension, Sliding Suspension, 53 ft - Container Pins, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9355	2024 PJ Trailers D7142 T/A Roll-Off Trailer S/N: 4P53D2328R1401125 C/W: 15680 lb GVWR, Spring Suspension, Electric Brakes, Manual Roll Tarp, Aluminum Wheels, 235/80R16 Tires
9347	2023 Horizon 40 ft T/A Container Trailer (Unused)		Usage: Not Available  Asset located in: Humble, TX
	S/N: 3H7KC402XPR000334 C/W: Spring Suspension, 40 ft - Container Pins, 11R22.5 Tires, 50000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9356	2023 MaxxD RPX8316G T/A Roll-Off Trailer (Unused) S/N: 5R8GR1625PM105017 C/W: Spring Suspension, Electric Brakes, 215 /75R17.5 Tires, 19200 lb GVWR
9348	2023 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR2XPG001679	9357	Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: 65000.0 lb GVWR, Air Ride Suspension, 11R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2023 Texas Pride RO71618KGN T/A Roll-Off Trailer S/N: 7HCGD1626PB039384 C/W: 18000 lb GVWR, Spring Suspension,
9349	2016 Hyundai DDT 40 ft T/A Container Trailer S/N: 145C412S3GL006968 C/W: Spring Suspension, 40 ft - Container Pins, 10.00-20 Tires Usage: Not Available Asset located in: Lake Worth, TX		Electric Brakes, Electric Roll Tarp, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9358	2016 Texas Pride Tri/A Gooseneck Roll-Off Trailer S/N: 1B973HGD9GB624110 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 7.50R16 Tires, 24000 lb GVWR Usage: Not Available	9366	2020 TFT T/A Concessions Trailer S/N: 3A9M1FD28LM050504 C/W: 2260 lb GVWR, Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 195R15C Tires Usage: Not Available
	Asset located in: Lake Worth, TX		Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT  Asset located in: Humble, TX
9359	2016 Texas Pride T/A Roll-Off Trailer S/N: 1B9G2DGD1GB624162 C/W: Spring Suspension, Electric Brakes, Electric Roll Tarp, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9367	2023 Freedom 8.5x28TA4G T/A Graco Spray Foam Trailer S/N: 5WKGE2829P1078616 C/W: 14000 lb GVWR, Torsion Axle, Electric Brakes, 235/80R16 Tires Usage: Not Available
9360	1996 T/A Roll-Off Trailer		Asset located in: Lake Worth, TX
	S/N: 1B9B14526TB183122 C/W: Air Ride Suspension, 295/75R22.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9368	2015 ACSI Tri/A Emergency Shower Recovery Station Trailer S/N: 1A9V6G631F1247629 C/W: Spring Suspension, Electric Brakes, 235
9361	S/N: 87080757		/80R16 Tires Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Spring Suspension, 11R24.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9369	2018 ED Trailers T/A Cooling Trailer S/N: 3A9BD1829J7266191
9362	2023 Diamond Cargo T/A 20' Concession Trailer S/N: 53NBE2020P1101295 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 9990 lb GVWR, Side Entry Door Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		C/W: Ball Hitch, Walking Beam Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9370	T/A Cooling Trailer  S/N: Not Available  C/W: Ball Hitch, Walking Beam Suspension, Electric Brakes, 205/75R15 Tires  Usage: Not Available  Asset located in: Lake Worth, TX
9364	2021 Margo Concessions Trailer S/N: 3A9M1C329MM050514 C/W: 2260 lb GVWR, Ball Hitch, Spring Suspension, 195R15C Tires, LPG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9371	2019 Cargo Craft T/A Splicing Trailer S/N: 4D6EB1225KC054750 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9365	<b>2022 FUD Concessions Trailer</b> S/N: 3F9F1A329NM066595		PROCESS TITLE  Asset located in: Lake Worth, TX
	C/W: Ball Hitch, Spring Suspension, 195R15C Tires	9372	S/A BBQ trailer
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: Not Available C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, Two benches with storage Usage: Not Available
	Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9373	2018 Wylie EXP500S Water Tank Trailer
		90/0	S/N: 63510 Usage: Not Available  Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9375	2016 CZ Engineering Pole Trailer S/N: 4CZPR2717G113G030 C/W: Lunette Ring Hitch, Air Ride Suspension, Electric Brakes, 2 Stanchions, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	9386	2017 Demco AT7000P T/A Open Car Carrier Trailer S/N: 15DPC1926HA989031 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: .
9376	2014 Bat 35TA Pole Trailer		Asset located in: Lake Worth, TX
	S/N: 1B9FB35264A439L69 C/W: 22400 lb GVWR Lunette Ring Hitch, Spring Suspension, Electric Brakes, 4 Stanchions, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9386A	2019 PJ DD202 19 ft T/A Dump Utility Trailer S/N: 4P5DD2029K1311819 C/W: Spring Suspension, Hydraulic Brakes, 97 in Deck Width, 97 in Overall Width, Steel Decking, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Asset located in: Midland, TX
	Asset located in: Lake Worth, TX	9387	2016 Texas Made 22 ft T/A Dump Utility Trailer
9379	2024 Silverback 45CHGN3 Tri/A 3 Car Open Car Carrier Trailer S/N: 4S9GC4535RH623425 C/W: Spring Suspension, 235/85R16 Tires Usage: Not Available Asset located in: Humble, TX		S/N: 59JT1DG22GD595842 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 85 in Overall Width, Steel Decking, 215/75R17.5 Tires, 12000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available
9380	2025 Double A 21 ft T/A Tilt Deck Trailer		Asset located in: Lake Worth, TX
	(Unused) S/N: 1UFBU2121ST012579 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9388	2024 East Texas 16 ft T/A Dump Utility Trailer S/N: 58SBD1625RE038870 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX
9383	2017 Demco AT7000P T/A 1 Car Open Car	0380	2024 MaxxD DTX8316 16 ft T/A Dump Utility
	Carrier Trailer S/N: 15DPC1920HA988585 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX	9389	Trailer (Unused)  S/N: 5R8BD1620RM116972  C/W: Ball Hitch, Spring Suspension, Electric  Brakes, 83 in Deck Width, 88 in Overall Width,  Steel Decking, 215/75R17.5 Tires, 16000 lb  GVWR
9384	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	S/N: 15DPC1927HA989006 C/W: Spring Suspension, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9390	2024 STL Industrial 16 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1629RM336009 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 12800 lb GVWR Usage: Not Available
9385	2017 Demco AT7000P T/A 1 Car Open Car		Asset located in: Lake Worth, TX
	Carrier Trailer S/N: 15DPC1927HA988910 C/W: Aluminum Frame, Ball Hitch, Surge Brakes, Soft Ties, 225/75R15 Tires, 5000 lb GVWR, PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9391	2024 MaxxD D9X9616 16 ft Tri/A Dump Utility Trailer (Unused) S/N: 5R8BD1637RM116735 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 21000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9392	2022 Big Tex 16 ft T/A Dump Utility Trailer S/N: 16V1D2122N5116206 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 98 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9398	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116824 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX		2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3363S1120884 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX  2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3360S1116825
9393	2016 Texas Made DT71616KBP 16 ft T/A  Dump Utility Trailer  S/N: 59JT1DG22GD595839  C/W: Ball Hitch, Spring Suspension, Electric  Brakes, 81 in Deck Width, 86 in Overall Width, Steel Decking, 235/85R16 Tires, 12000 lb  GVWR, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY  Usage: Not Available  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
	Asset located in: Humble, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width,
9394	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1120875 C/W: Ball Hitch, Spring Suspension, Electric		Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9401	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3366S1120877 C/W: Ball Hitch, Spring Suspension, Electric
9395	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1120873 C/W: Ball Hitch, Spring Suspension, Electric		Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9402	2025 Southland SL714-14K 14 ft S/A Dump Utility Trailer (Unused) S/N: 2SFJL3361S1120883 C/W: Ball Hitch, Spring Suspension, Electric
9396	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1116826 C/W: Ball Hitch, Spring Suspension, Electric	9403	Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3364S1120876 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9397	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL336XS1120655 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
9404	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116823 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9411	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3368S1118925 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX
9405	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1118976 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9412	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused)  S/N: 2SFKL4364S1113436  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX
9406	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3363S1120405 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9414	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused)  S/N: 2SFKL4362S1113435  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX
9407	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118932 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3367S1118981 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9408	2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3360S1115257 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		2025 Southland SL714-16K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3365S1118980 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 87 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17421 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9409	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3366S1118924 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available Asset located in: Lake Worth, TX		2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer S/N: 2SFKL4368S1113438 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available
9410	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused)  S/N: 2SFKL3364S1118923  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, hydraulic trailer jack Usage: Not Available  Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9417	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4366S1113437 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 88 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9423	2025 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused)  S/N: 5R8BD1421SM118478  C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 17500 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX  2025 Maxey MaxxD 14 ft T/A Dump Utility
9418	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1116854 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Trailer (Unused) S/N: 5R8BD1420SM117659 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9419	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1116855 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available	9425	2024 MaxxD DTX8314 14 ft T/A Dump Utility Trailer (Unused)  S/N: 5R8BD142XRM116741  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 215/75R17.5 Tires, 17500 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX
9420	Utility Trailer (Unused) S/N: 2SFJL3360S1116856 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR	9426	2024 ED Trailers 14 ft T/A Dump Utility Trailer S/N: 3LHBS1423R7000182 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 84 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9421	Usage: Not Available Asset located in: Lake Worth, TX  2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3365S1116853 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR	9427	2024 Maxey Maxx-D DKX8314 14 ft T/A Dump Utility Trailer (Unused)  S/N: 5R8BD1420RM116473  C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, 89 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX
9422	Usage: Not Available Asset located in: Lake Worth, TX  2025 Industrias America 7014R 14 ft T/A Dump Utility Trailer S/N: 3EZBTC14XSA003766 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9428	2024 MaxxD D9X9614 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1428RM116057 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
U <b>N</b> T P		9429	2024 MaxxD DKX8314 14 ft T/A Dump Utility Trailer (Unused) S/N: 5R8BD1424RM116489 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 88 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9430	2023 Park Performance HD142 14 ft T/A  Dump Utility Trailer  S/N: 13ZHD1426P1000074  C/W: Ball Hitch, Spring Suspension, Electric  Brakes, 83 in Deck Width, 87 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb  GVWR  Usage: Not Available  Asset located in: Lake Worth, TX	9437A	9437A Maxey T/A Gooseneck 40 Ft Hydraulic Tail Trailer S/N: Not Available C/W: Spring Suspension, Electric Brakes, 28 f Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width Storage Compartments, Electric Powered Sel Contained Hydraulic System, 215/75R17.5 Tires Usage: Not Available
9432	2025 MaxxD DTX8312 T/A Utility Trailer (Unused)		Asset located in: Lake Worth, TX
	S/N: 5R8BD1221SM118015 C/W: Aluminum Frame, Spring Suspension, 83 in Deck Width, 96 in Overall Width, Aluminum Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9438	2023 HD 30 ft T/A Tilt Deck Trailer  S/N: 7LKH3AL2XPP001032  C/W: 16500 lb GVWR, Spring Suspension, Electric Brakes, Storage Compartments, Deck Over Tires, 97 in Deck Width, 235/80R16 Tires Usage: Not Available  Asset located in: Lake Worth, TX
9433	2025 Industrias America FT510 10 ft T/A	9439	2021 Delco 24 ft T/A Tilt Deck Trailer
	Dump Utility Trailer  S/N: 3EZBTC10XSA004056  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 59 in Deck Width, 78 in Overall Width, Steel Decking, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	9439	S/N: 5WWGC2422M6016631 C/W: Torsion Axle, Electric Brakes, 24 ft Deck Tilting Length, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
9434	2025 Industrias America FT510 10 ft T/A	<del>-</del>	Asset located in: Lake Worth, TX
7101	2025 Industrias America FT510 10 ft T/A  Dump Utility Trailer  S/N: 3EZBTC105SA004059  C/W: Ball Hitch, Spring Suspension, Electric  Brakes, 59 in Deck Width, 77 in Overall Width, Steel Decking, 235/75R16 Tires, 7000 lb GVWR Usage: Not Available	9440	2019 Big Tex 22 ft T/A Tilt Deck Trailer S/N: 16VEX222XK2093519 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft 9 in Deck Tilting Length, 75 in Deck Width, 215/75R17.5 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	9441 2017 Felling 22 ft T/A Tilt Deck Trailer S/N: 5FTCE2923H1002738 C/W: Ball Hitch, Spring Suspension, Elect Brakes, 18 ft Deck Tilting Length, 82 in D	S/N: 5FTCE2923H1002738
9435	2023 Lamar 10 ft T/A Dump Utility Trailer S/N: 5RVDS1027PP119903 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, 65 in Overall Width,		Brakes, 18 ft Deck Tilting Length, 82 in Deck Width, 215/75R17.5 Tires, 19120 lb GVWR Usage: Not Available
	Steel Decking, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX	9442	2025 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2125ST012570
9436	2015 Texas Bragg 5X10 Dump Utility Trailer S/N: 17XFP1010F1051441 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	9443	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 17 ft Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX		2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004019
9437	2014 Interstate 40 ft T/A Tilt Deck Trailer S/N: 1JKGTL605EM012923 C/W: Spring Suspension, Deck Over Tires, 24 ft 5 in Deck Tilting Length, 102 in Deck Width, 245 /70R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9444	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP223SA004021 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX  2025 Industrias America 167T 20 ft T/A Tilt	9450 9450A	2025 Double A 12 ft S/A Tilt Deck Trailer (Unused)  S/N: 1UFBU1219ST012572  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 12 ft Deck Tilting Length, 79 in Deck Width, 225/75R15 Tires, 5200 lb GVWR, 2" Adjustable Bulldog Style Coupler, 2000# Set Back Jack, 7 Way Plug And Wiring, Sealed LEI Lights, Diamond Plate Fenders, 6 Stake pockets, 2" Treated Lumber Floor, Safety	
9443	Deck Trailer  S/N: 3EZBTP221SA004020  C/W: Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX		Chains, Spare Rack Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX  1974 Miller 18 ft T/A Tilt Deck Trailer S/N: 16982	
9446	2025 Industrias America 167T 20 ft T/A Tilt Deck Trailer S/N: 3EZBTP225SA004022 C/W: Ball Hitch, Spring Suspension, Electric	9451	C/W: Lunette Ring Hitch, Walking Beam Suspension, Deck Over Tires, 18 ft Deck Tilting Length, 96 in Deck Width, 8.25R15 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	
	Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 77 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2018 PJ Trailers 20 ft T/A Equipment Trailer S/N: 4P5L52025J1284500 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 101.5 in Usable Deck Width, Deck Over Tires, Manual Ramps, Wood	
9447	2023 Big Tex 20 ft T/A Tilt Deck Trailer S/N: 16V1C252XP2271331 C/W: Ball Hitch, Spring Suspension, 16 ft Deck Tilting Length, 72 in Deck Width, 235/80R16 Tires Usage: Not Available	9452	Flooring, 205/75R Usage: Not Availa <b>Notes</b> : TEXAS BU' TO SIGN REQUIRE PROCESS TITLE	Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		2007 B.A.T. Custom Trailers 35 ft T/A Gooseneck Equipment Trailer S/N: 1B9E???267A439M49 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 96 in Usable Deck Width, 102 in	
9448	2015 Butler 20 ft T/A Tilt Deck Trailer S/N: 1BUD18202F1007915 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 78 in Deck Width, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available		Overall Deck Width, Deck Over T Flooring, 215/75R17.5 Tires, EQ FROM-A-PRIMORIS-SERVICES-C COMPANY Usage: Not Available	Overall Deck Width, Deck Over Tires, Wood Flooring, 215/75R17.5 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY
9449	Asset located in: Lake Worth, TX  2015 Towmaster 16 ft T/A Tilt Deck Trailer  S/N: 4KNTT162XFL160923  C/W: Ball Hitch, Torsion Axle, Surge Brakes, Winch, 16 ft Deck Tilting Length, 82 in Deck Width, 235/85R16 Tires, 9990 lb GVWR Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX		1995 Norris 40 ft T/A Gooseneck Flatbed Trailer S/N: 1N9FS4023SC007555 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9454	2019 Interstate 50DLA 30 ft Tri/A Equipment Trailer  S/N: 1JKDLA500KM016883  C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 24 ft Main Deck, 6 ft 2 in Fixed Dovetail, 96 in Usable Deck Width, 101 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 60100 lb GVWR  Usage: Not Available  Asset located in: Lake Worth, TX	9460	2024 RAWMAXX FDX-40-27K 40 ft T/A Gooseneck Equipment Trailer S/N: 3EVGF4027R1109090 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 6 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Midland, TX	
9455	2001 Phelan 25TA-D 25 ton 29 ft Tri/A Equipment Trailer S/N: 40FR0303113020550 C/W: Lunette Ring Hitch, Spring Suspension, 24 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 60540 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9461	2024 Horizon 40 ft T/A Gooseneck Equipment Trailer  S/N: 3H7GF4022RR001350  C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /85R16 Tires  Usage: Not Available  Asset located in: Midland, TX	
9456	2008 Towmaster 25 ft T/A Equipment Trailer S/N: 4NKTF20298L163620 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /85R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9462	2024 Big Tex 40 ft T/A Gooseneck Equipment Trailer  S/N: 16V3F4821R6323173  C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 93 in Usable Deck Width, 98 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 23900 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX	
9457	2016 Load Trail 40 ft Tri/A Gooseneck Equipment Trailer S/N: 4ZEGC4031G1100325 C/W: Spring Suspension, Electric Brakes, 40 ft 4 in Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, 101.5 in Overall Deck Width, 0 in Widening Width, Storage Compartments, Manual Ramps, Wood Flooring, 235/80R16 Tires, 24990 lb GVWR Usage: Not Available Asset located in: Midland, TX	9463	2024 East Texas 40 ft T/A Gooseneck Equipment Trailer S/N: 58SGF4027RE040193 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 5 ft 6 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
9458	2025 X-STAR 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1X9T3GS28SH039957 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		7 S C 1 U S F	Trailer S/N: 5R8GF4025PM101424 C/W: Spring Suspension, Electric Bra 11 in Main Deck, 5 ft 9 in Fixed Dove Usable Deck Width, 97 in Overall Dec Storage Compartments, Spring Assi Ramps, Wood Flooring, 235/85R16
9459	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer		Usage: Not Available  Asset located in: Lake Worth, TX	
	S/N: 5R8GF4025SM119348 C/W: Air Ride Suspension, Electric Brakes, 34 ft 11 in Main Deck, 5 ft 9 in Fixed Dovetail, 93 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires, 25990 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9465	2023 Delco 40 ft T/A Gooseneck Equipment Trailer S/N: 5WWGF4023P6029756 C/W: Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX	

Lot #	Details	Lot #	Details
9466	2023 HD Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 7LKH3AP29PP000996 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 6 in Fixed Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9472	2017 Texline 35' GNI/D 35 ft T/A Gooseneck Equipment Trailer S/N: 5HNGN352XH1000107 C/W: Spring Suspension, Electric Brakes, 30 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22000 lb GVWR Usage: Not Available
9467 9467A	2023 Trailmaxx 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H4027TM000406 C/W: 12000 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX  2022 PJ Trailers 3F492 40 ft T/A Equipment		Asset located in: Lake Worth, TX  2012 Texas Bragg 35 ft T/A Gooseneck Equipment Trailer  S/N: 17XFG3528C1024464  C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
7.077	Trailer	0474	·
9469	S/N: 4P53F4924N1364159 C/W: 25900 lb GVWR, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Midland, TX  2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4023J1155164 C/W: Spring Suspension, Electric Brakes, 35 ft	9474	Equipment Trailer S/N: 17XFG352791093459 C/W: Spring Suspension, Electric Brakes, 20 f Main Deck, 5 ft Fixed Dovetail, 92 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 101 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX		
9470	2018 Load Trail 40 ft T/A Gooseneck Equipment Trailer S/N: 4ZEGH4021J1162680 C/W: Spring Suspension, Electric Brakes, 35 ft		Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 22500 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX
	Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX		2023 Big Tex 16GN-25BK+5MR 30 ft T/A Gooseneck Equipment Trailer S/N: 16V3F3828P6255347 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable
9471	2009 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GN40229M011427 C/W: Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/90D16 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX

Lot #	Details	Lot #	Details	
9477	2020 Sure-Pull 30 ft T/A Gooseneck Equipment Trailer  S/N: 1J9DG3024LJ143049  C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 101 in Usable Deck Width, 101 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR TO REPORT	9482	2024 Golden Arm 25 ft T/A Gooseneck Equipment Trailer S/N: 7S8GF2526RM000313 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft 6 in Fixed Dovetail, 94 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX  2012 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer	
	PRIOR TO BIDDING  Asset located in: Lake Worth, TX		S/N: 16VGX2521C2632812	
9478	2013 Big Tex 22GN-25BK+5 30 ft T/A Gooseneck Equipment Trailer S/N: 16VGX2527D2674032 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22400 lb GVWR, EQUIPMENT-FROM-WATKINS-		C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 102 in Usable Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available  Asset located in: Lake Worth, TX	
	CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9484	2009 Starlite 25TAGN 25 ft T/A Gooseneck Equipment Trailer S/N: 13YFS25269C113505	
9479	2001 HaWN 30 ft T/A Gooseneck Equipment Trailer S/N: 1H9GN302911176001 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires		C/W: Spring Suspension, 20 ft Main Deck, 5 ft 2 Position Dovetail, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: SELLING WITH AN SPI (FORM VTR-270) AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9485	2023 East Texas 24 ft T/A Gooseneck Equipment Trailer S/N: 58SGM2424PE036183 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 102 in Usable Deck Width, Wood Flooring, 235/80R16 Tires	
9480	2015 Kearney 28 ft Tri/A Gooseneck Equipment Trailer		Usage: Not Available  Asset located in: Lake Worth, TX	
	S/N: 5LCFT2830F1037125 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 4 ft Fixed Dovetail, 82 in Usable Deck Width, Hydraulic Ramps, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9486	(Unused) S/N: 7GG1U2022SW023510 C/W: Ball Hitch, Spring Suspension Brakes, 17 ft Main Deck, 3 ft Fixed in Usable Deck Width, 102 in Overa Width, Manual Ramps, Wood Floor	•
9481	2025 Double A 26 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1UFGN2624ST012569 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	
		9487	2023 Maxey XX-D 26 ft T/A Equipment Trailer S/N: 5R8BC2627PM106865 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 24 ft Main Deck, 2 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9488	2002 Parker 24 ft T/A Equipment Trailer S/N: 13ZPF242121003713 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft 10 in Main Deck, 5 ft 2 in Fixed Dovetail, 85 in Usable Deck Width, 91 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/85R16 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9494	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4464S1120265 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
(Inoperable) S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Susperate Ring Ring Ring Ring Ring Ring Ring Ring	S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 7 ft 6 in Upper Deck, 12 ft 4 in Main Deck, 3 ft 6 in Fixed Dovetail, 79 in Usable Deck Width, 79 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring,	9495	2025 Southland LBATR7-20 20 ft Tri/A Equipment Trailer S/N: 2SFHL4462S1120264 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9496	2025 Salvation Trailers 20 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 7GG3U2022SW023483 C/W: Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 82 in Usable Deck Width, 102 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR	
9490	2014 Kaufman 23 ft T/A Equipment Trailer S/N: 5SHFP2329EB001257		Usage: Not Available  Asset located in: Lake Worth, TX	
	C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	(Unused) S/N: 1X9T7GF21SH039958 C/W: Ball Hitch, Spring Suspensi Brakes, 20 ft Main Deck, 97 in Us Width, 101 in Overall Deck Width Flooring, 235/80R16 Tires, 1400 in x 8 in Treated Lumber Floor, 7 Usage: Not Available Asset located in: Lake Worth, TX  9498 2025 Double A 20 ft T/A Equipm (Unused) S/N: 1UFBU2029ST012573 C/W: Ball Hitch, Spring Suspensi Brakes, 20 ft Main Deck, 0 ft Dov Usable Deck Width, 102 in Overa Manual Ramps, Wood Flooring, 2 Tires, 14000 lb GVWR, 6" Channe Wrap Tng, 3" Channel Cross Mer 7000# Axles, 1 Brake 2-5/16 Cor Ramps, 2' Dovetail, All LED Light Hole Silver Mod, 12k Drop Leg J Plate Fenders Usage: Not Available	S/N: 1X9T7GF21SH039958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 97 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR, 2	
9491	2025 Southland LBATR7-22 22 ft Tri/A Equipment Trailer (Unused)		in x 8 in Treated Lumber Floor, 7k Axles	in x 8 in Treated Lumber Floor, 7k Axles Usage: Not Available
	S/N: 2SFHL4463S1120662 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 2 ft Fixed Dovetail, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 21043 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1UFBU2029ST012573 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 0 ft Dovetail, 83 in Usable Deck Width, 102 in Overall Deck Width,	
9492	2023 Maxey T/A 40 Ft Tilt Deck Trailer S/N: 5R8BC2226PM099011 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Electric Powered Self Contained Hydraulic System, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX			
9493	2022 Norstar 22 ft T/A Equipment Trailer S/N: 3EUGB2221N1011572 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Fixed Dovetail, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9499	2025 Double A 20 ft T/A Equipment Trailer (Unused)  S/N: 1UFBU2026ST012580  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9500	2022 East Texas 20 ft T/A Equipment Trailer S/N: 58SBM202XNE030305 C/W: Spring Suspension, 20 ft Main Deck, 96 in Usable Deck Width, 101 in Overall Deck Width, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	9506	2025 Double A 18 ft T/A Equipment Trailer (Unused)  S/N: 1UFBU1822ST012574  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires,
9501	2018 Big Tex 14ET-20BK-MR 20 ft T/A Equipment Trailer S/N: 16VEX2024J2005825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 20 ft 6 in Main Deck, 3 ft 6 in Fixed Dovetail, 84 in Usable Deck Width, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available		14000 lb GVWR, HDCH, 6" Channel Frame, 6" Wrap Tng, 3" Channel Cross Members, 2-7000# Axles, 1 Brake 2-5/16 Coupler, 5' Slide in Ramps, 2' Dovetail, All LED Lighting, 10-Ply on 8 Hole Silver Mod, 12k Drop Leg Jack, Diamond Plate Fenders Usage: Not Available  Asset located in: Lake Worth, TX  2005 Ditch Witch T18B 17 ft T/A Equipment
9502	Asset located in: Midland, TX  2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused)  S/N: 2SFJC331XS1121177  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR		Trailer S/N: 1DSB232N0517Z2161 C/W: 18000 lb GVWR, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 17 ft Main Deck, Manual Ramps, 215/75R17.5 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9508	2025 Southland LBAT7-16 16 ft T/A Equipment Trailer
9503	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3318S1121176 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires,		S/N: 2SFJL336XS1116038 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	15432 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9509	2024 MaxxD H5X10216 16 ft T/A Equipment Trailer (Unused)
9504	2025 Southland LBAT7-18 18 ft T/A Equipment Trailer (Unused) S/N: 2SFJC3313S1121179 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 5R8BC1625RM116789 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Main Deck, 2 ft 2 in Fixed Dovetail, 82 in Usable Deck Width, 97 in Overall Deck Width, Manual Ramps, Wood Flooring, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9505	2025 Double A 18 ft T/A Equipment Trailer		Asset located in: Lake Worth, TX
	S/N: 1UFBU1827ST012571 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 77 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR, 2" Bulldog Style Coupler, Brake and EBA, 5' Slide In Ramps Out Back, 2' Diamond	9510	2021 Buck Dandy 16 ft T/A Equipment Trailer S/N: 4DHCS2028MS047369 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 225/75R15 Tires, 10400 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
		9511	2013 Felling FT-10 P Equipment Trailer S/N: 5FTPH1626D1042166 Usage: Not Available Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
9512	2018 MMDI 614SLTD 14 ft T/A Equipment Trailer S/N: 5631F2024JM001703 C/W: Torsion Axle, 14 ft Main Deck, 5 ft 2 in Dovetail, 70 in Usable Deck Width, 97 in Overall Deck Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9519	2021 Big Tex 10Pl-20BK 24 ft T/A Utility Trailer S/N: 16V1W242XM2070825 C/W: Spring Suspension, Electric Brakes, 83 in Deck Width, Wood Flooring Usage: Not Available Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	9520	2022 Salvation Trailers 20 ft T/A Utility Trailer S/N: 7GG1U2021NW019503
9513	2017 MMDI 7 ft S/A Equipment Trailer S/N: 5631F1419HM017255 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 48 in Usable Deck Width, Manual Ramps, Steel Decking, 225 /75R15 Tires		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 88 in Deck Width, Wood Flooring, 235 /80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	9521	2018 Texline 20 ft T/A Utility Trailer S/N: 7HACU2025J1000949
9514	2016 Pratt CP0510 10 ft T/A Equipment Trailer S/N: 1P9UT1722GN343532 C/W: Torsion Axle, Surge Brakes, 60 in Usable Deck Width, Deck Over Tires, Manual Ramps, Steel Decking, 205/75R15 Tires Usage: Not Available		C/W: Spring Suspension, Electric Brakes, 79 in Deck Width, 102 in Overall Width, Wood Flooring, 215/75R17.5 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9522	2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2021JB069894
9515	Asset located in: Lake Worth, TX  1998 Interstate 18 ft T/A Equipment Trailer S/N: 1JK0DT202WA001000 C/W: Spring Suspension, Air Brakes, 18 ft 9 in Main Deck, 5 ft Fixed Dovetail, 91 in Usable Deck Width, 96 in Overall Deck Width, Deck		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
	Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9523	2018 Kearney 20 ft T/A Utility Trailer S/N: 5LCLB2023J1047150 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 101 in Overall Width,
9516	1995 Norris 25 ft T/A Gooseneck Equipment Trailer S/N: 1N9FS252XSC007758		Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available
	C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft Fixed Dovetail, 91 in Usable		Asset located in: Lake Worth, TX
	Deck Width, 96 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: . Asset located in: Lake Worth, TX	9524	2018 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029JB069898 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
9517	1998 SHIRLEY FB 12 ft T/A Utility Trailer S/N: 4XMFS1220WL000008 C/W: Ball Hitch, Spring Suspension, 77 in Deck Width, Ramp, Steel Decking, 235/80R16 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9525	2013 Ameritrail 20 ft T/A Utility Trailer S/N: 17YBP2029DB053351 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9526	2011 Texas Bragg 20 ft T/A Utility Trailer S/N: 17XFP2026B1014824 C/W: Ball Hitch, Spring Suspension, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 225 /90R16 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9533	2004 Cortex 18 ft T/A Utility Trailer S/N: WCC108200 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX
9527	2025 Double A 18 ft T/A Utility Trailer (Unused)	9534	2002 Diamond Pacesetter 18 ft T/A Utility
3027	S/N: 1UFBU1828ST012577 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Wood Flooring, 225 /75R15 Tires, 9995 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	3004	Trailer  S/N: 46UFU182721078242  C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/85R16 Tires Usage: Not Available  Notes: Asset located in: Lake Worth, TX
		9535	2017 Top Hat 16 ft T/A Utility Trailer
9528	2014 Lamar 18 ft T/A Utility Trailer S/N: 5RVUT1823EM017580 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT- FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9333	S/N: 4R7BU1625HT167477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 205 /75R15 Tires, 6000 lb GVWR, EQUIPMENT- FROM-PULICE-CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
			TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
9529	<b>2014 CM 18 ft T/A Tilt Deck Trailer</b> S/N: 5VNBU1821ET121130		Asset located in: Humble, TX
9530	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Deck Tilting Length, 77 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX 2008 Big Tex 18 ft T/A Utility Trailer S/N: 16VPX182381320591 C/W: Spring Suspension, Electric Brakes, 83 in	9536 202 Util S/N C/V Bra Wo G/V Usa	2025 East Texas 14 ft T/A Trash/Restroom Utility Trailer S/N: 58SBU1821SE042305 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 102 in Overall Width, Wood Flooring, 225/75R15 Tires, 7000 lb GVWR, w/(2) restrooms Usage: Not Available Asset located in: Midland, TX
	Deck Width, 90 in Overall Width, Wood Flooring, 235/85R16 Tires, EQUIPMENT-FROM-A-	0507	·
	PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	Width, 102 in Overall Width, Ramp, Woo Flooring, 205/75R15 Tires, 2995 lb GVV Top, 2" BD Coupler, All LED Lighting, 2k Back Jack, Diamond Plate Fenders, Tre	S/N: 1UFBU1418ST012575 C/W: Ball Hitch, Spring Suspension, 83 in Deck
9531	2008 Pero 18 ft T/A Utility Trailer S/N: 4PTU718248M014902 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 100 in Overall Width, Wood Flooring, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY		Flooring, 205/75R15 Tires, 2995 lb GVWR, Pipe Top, 2" BD Coupler, All LED Lighting, 2k Set Back Jack, Diamond Plate Fenders, Treated Lumber Floor, Stake Pockets, Spare Rack, 2' Exp Dovetail, 2' Gate Usage: Not Available
	Usage: Not Available	9538	2015 Big Tex 12 ft T/A Utility Trailer
	Notes: The chassis was manufactured in 2008, but was assigned as a 2009 when VIN was issued  Asset located in: Lake Worth, TX	_	S/N: 16VNX1224F2021991 C/W: Ball Hitch, Spring Suspension, 76 in Deck Width, 81 in Overall Width, Steel Decking, 205 /75R15 Tires, 5000 lb GVWR
9532			Usage: Not Available
7002	2005 Cortex 18 ft T/A Utility Trailer S/N: WCC108217 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Wood Flooring, 235 /85R16 Tires, EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	9539	Asset located in: Lake Worth, TX  11 ft S/A Utility Trailer S/N: Not Available C/W: Ball Hitch, Wood Flooring, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9540	2019 Pratt EZ-1980 19 ft T/A Tilt Deck Trailer S/N: 1P9UT1929KN343758 C/W: Ball Hitch, Electric Brakes, Electric Powered Self Contained Hydraulic System, 19 ft Deck Tilting Length, 69 in Deck Width, 225 /90R16 Tires, 14000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9547	2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA21FA018786 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Midland, TX	
	Asset located in: Humble, TX	9548	2025 Southland LARCT52-826V-86 26 ft T/A	
9541	2020 Pratt EZ-1480S 14 ft T/A Tilt Deck Trailer S/N: 1P9UT1425LN343409 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Electric Powered Self Contained Hydraulic System, 14 ft 10 in Deck Tilting Length, 79 in Deck Width, 235/85R16 Tires, 14000 lb GVWR Usage: Not Available		Enclosed Trailer (Unused) S/N: 2SFPL636XS1120196 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
0540	Asset located in: Humble, TX	9549	2025 Southland LARCT52-826V-86 25 ft T/A	
9542	2024 STL Industrial 12 ft Hydraulic Drop Deck Ground Load Trailer (Unused) S/N: 4B9BZ1220SM336008 C/W: Ball Hitch, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		Enclosed Trailer S/N: 2SFPK5313S1118257 C/W: Aluminum/Steel Combination Frame, Bal Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	Asset located in: Lake Worth, TX	9550	2017 Forest River 24 ft T/A Enclosed Trailer	
9543	2018 Barreto 6 ft S/A Trencher Trailer S/N: 1B9UC0616DL280544 C/W: Torsion Axle, 5.30-12 Tires Usage: Not Available Asset located in: Lake Worth, TX  2018 Barreto 6 ft S/A Tilt Deck Trailer S/N: 1B9UC0612JL280312 C/W: Aluminum Frame, Ball Hitch, 6 ft 3 in Deck Tilting Length, 45 in Deck Width, 5.30-12 Tires, 2200 lb GVWR	9551	Brakes, 98 in Deck Width, 101 in 0 Side Door 225/75R16 Tires, 9800 EQUIPMENT-FROM-A-PRIMORIS-S CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STO	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 98 in Deck Width, 101 in Overall Width, Side Door 225/75R16 Tires, 9800 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;
	Usage: Not Available  Asset located in: Lake Worth, TX		2025 Southland LARCT52-822V-86 22 ft T/A	
9545	2019 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA29KU036221 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, Side Door 225 /75R15 Tires, 7000 lb GVWR, Interior Racking Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE		Enclosed Trailer S/N: 2SFPK4318S1120466 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX	9552	2025 Southland LARCT52-822V-86 21 ft T/A	
9546	2015 LGS 16 ft T/A Enclosed Trailer S/N: 53BLTEA23FA018790 C/W: Aluminum/Steel Combination Frame, Spring Suspension, Electric Brakes, 82 in Deck Width, 96 in Overall Width, Ramp, Side Door 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Midland, TX		Enclosed Trailer S/N: 2SFPK4310S1118274 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 100 in Overall Width, Ramp, Side Door Aluminum Wheels, 225 /75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details	
9553	Enclosed Trailer S/N: 2SFPK5365S1118272 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available	9559	2014 Haulmark 18 ft T/A Cooling/Heating station Enclosed Trailer S/N: 575GB1826ET265922 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: 8,663 Hr Asset located in: Lake Worth, TX	
		9560	2014 Haulmark 18 ft T/A Cooling/Heating	
9554	2025 Southland LARCT52-820F-86 20 ft T/A Enclosed Trailer S/N: 2SFFK4310S1118271 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb		station Enclosed Trailer S/N: 575GB1828ET265923 C/W: Ball Hitch, Torsion Axle, Electric Brakes, Side Door 235/85R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	
	GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9561	2018 Lark 17 ft T/A Enclosed Trailer S/N: 571BE1626JM030477 C/W: Ball Hitch, Spring Suspension, 80 in Deck	
9555	2017 Cargo Craft Expedition 20 ft T/A Enclosed Trailer S/N: 4D6EB2021HC046825 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 102 in Overall Width, 235/80R16 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY	9562	205/75R15 Tires Usage: Not Available <b>Notes</b> : TEXAS BUYERS MUST STO	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE
	Usage: Not Available Notes: . Asset located in: Lake Worth, TX		2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH331XS1120960	
9556	2025 Southland LCHT35-718V-86 18 ft T/A Enclosed Trailer S/N: 2SFFL4367S1120950 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7716 lb GVWR		Brakes, 79 in Deck Width, 84 Side Door 205/75R15 Tires, Usage: Not Available <b>Notes</b> : TEXAS BUYERS MUS TO SIGN REQUIRED DOCUM PROCESS TITLE	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9563	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3363S1118428 C/W: Ball Hitch, Spring Suspension, Electric	
9557	2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1821ET265892 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		Brakes, 81 in Deck Width, 96 in Ramp, Side Door 205/75R15 Til GVWR Usage: Not Available <b>Notes</b> : TEXAS BUYERS MUST S TO SIGN REQUIRED DOCUMEN' PROCESS TITLE	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9558	2014 Haulmark 18 ft T/A Enclosed Trailer S/N: 575GB1823ET265909 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 96 in Deck Width, 105 in Overall Width, Ramp, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9564	2025 Southland LCHT35-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL3365S1118429 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9565	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFL336XS1120371 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11709 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9570	2020 Carry-On 7X16 16 ft T/A Enclosed Trailer S/N: 4YMBC1621LT010101 C/W: Walking Beam Suspension, Electric Brakes, 74 in Deck Width, 83 in Overall Width, 225/75R15 Tires, 9990 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
9566	2025 Southland LCHT52-816F-86 16 ft T/A Enclosed Trailer (Unused)		Asset located in: Humble, TX
	S/N: 2SFFL3365S1112775 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9571	2020 Carry-On 16 ft T/A Enclosed Trailer S/N: 4YMBC1627LT038050 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 78 in Deck Width, 86 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, Interior Racking; EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available
9567	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer		Notes: .
	S/N: 2SFFH3313S1118418 C/W: Ball Hitch, Spring Suspension, Electric	9572	Asset located in: Humble, TX  2013 CM Trailers 16 ft T/A Enclosed Trailer
	Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE		S/N: 49TCB1621D1009364 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 79 in Deck Width, 80 in Overall Width, Side Door 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE;
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9568	2025 Southland LCHT35-716V-86 16 ft T/A Enclosed Trailer S/N: 2SFFL4368S1120956 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE	9573	2013 Lark United 7X16 16 ft T/A Enclosed Trailer  S/N: 5RTBE1628DD034600  C/W: Walking Beam Suspension, 78 in Deck Width, 80 in Overall Width, Side Door 205  /75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Asset located in: Lake Worth, TX	<b>-</b>	Asset located in: Humble, TX
9569	2022 Rock Solid Cargo 16 ft T/A Enclosed Trailer S/N: 7H2BE1626ND044095 C/W: 7000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, 84 in Overall Width, Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9574	2013 Contract 16 ft T/A Enclosed Trailer S/N: 49TCB1624D1009164 C/W: Ball Hitch, Torsion Axle, 78 in Deck Width, 98 in Overall Width, 235/80R16 Tires, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Midland, TX
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	9575	2017 Doolittle 16 ft T/A Enclosed Trailer S/N: 1DGCS1422HM022245 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 84 in Overall Width, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9576	2025 Southland LCHT35-716V-86 15 ft T/A Enclosed Trailer S/N: 2SFFH3311S1120958 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 100 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7815 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	9581	2016 Lark United MFG VT6X14SA 14 ft S/A Enclosed Trailer S/N: 571BE1417GM017644 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, Ramp, 225/75R15 Tires, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	
9577	2025 Southland LCHT35-614V-78 14 ft T/A Enclosed Trailer S/N: 2SFFL2369S1120937 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 69 in Deck Width, 92 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7716 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9582	2009 Mongoose 15 ft T/A Enclosed Trailer S/N: 5SMFL142091005960 C/W: Spring Suspension, Electric Brakes, 80 in Deck Width, 225/75R15 Tires, 10000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	
	TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	9583	2015 Wells Cargo TW101 10 ft S/A Enclosed Trailer S/N: 575200D14FT278094	
9578	2018 Interstate 14.5 ft T/A Enclosed Trailer S/N: 1UK500F28J1095011 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A- PRINORIS-SERVICES-CORP-COMPANY		C/W: Ball Hitch, Spring Suspension, 72 in Deck Width, 205/75R15 Tires, Honda EM6000SX Generator; EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9585	2017 Lark 12 ft T/A Enclosed Trailer S/N: 571BE1226HM022380 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 92 in Deck Width, 101 in Overall Width,	
9579	2017 Doolittle 15 ft T/A Enclosed Trailer S/N: 1DGCS1428HM021181 C/W: Lunette Ring Hitch, Spring Suspension, 80 in Deck Width, 84 in Overall Width, 205 /75R15 Tires, 7000 lb GVWR Usage: Not Available		Side Door 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX	9586	2017 Lark VT712TA 13 ft T/A Enclosed Trailer S/N: 5RTBE122XHD058103 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 80 in	
9580	2018 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHULE420JY077081 C/W: Spring Suspension, Electric Brakes, 78 in Deck Width, 78 in Overall Width, 205/75R15 Tires, Bumper Pull with Plywood Decking and Walls. Wooden Shelving.; EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: Not Available			Deck Width, 80 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Humble, TX	9587	2015 Arising 7X12VTDW 12 ft T/A Enclosed Trailer  S/N: 5YCBE1228FH021263  C/W: Walking Beam Suspension, Electric Brakes, 76 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
9588 9589	2006 Forest River 12 ft T/A Enclosed Trailer S/N: 5NHUTB2236W053121 C/W: Spring Suspension, Electric Brakes, Side Door 205/75R14 Tires, 7000 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX  12 ft T/A Enclosed Trailer	9595	2016 Heartland Cyclone 44 ft Tri/A Toy Hauler Travel Trailer S/N: 5SFCG4436GE301886 C/W: Sleeps 2 People, 2 Slide Outs, Power Leveling Jacks, Cummins 5.5 kW Generator, 5th Wheel, Spring Suspension, Electric Brakes, 235/85R16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN	
	S/N: Not Available C/W: Ball Hitch, Spring Suspension, Electric Brakes, 69 in Deck Width, 71 in Overall Width, Side Door 205/75R15 Tires, 11000 lb GVWR Usage: Not Available	9595A	YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX  2015 Gateway 3900SE 42 ft T/A Travel Trailer	
9590	Asset located in: Lake Worth, TX  2019 Lark VT612TA 12 ft T/A Enclosed Trailer S/N: 571BE1228KM031668 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 205/75R15 Tires, 7000 lb GVWR, 425 gal Poly Tank Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX	_	S/N: 5SFSG4129FE293059 C/W: Sleeps 8 People, 3 Slide Outs, Exterior Entertainment, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 7.5/16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	
9591	2012 Atlas AU712SA 12 ft S/A Enclosed Trailer S/N: 5HCKU1219CE025510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 102 in Overall Width, Ramp, Side Door 205/75R15 Tires, 3500 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9596	2015 Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3933F1236485 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9592	2012 Arising 8 ft S/A Enclosed Trailer S/N: 5YCBE0817CH005074 C/W: Spring Suspension, 205/75R15 Tires, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX	9597 9597A	2014 Rich Kuntry Kustom 34 ft Tri/A Travel Trailer S/N: 1K9BU3934E1236252 C/W: Sleeps 2 People, 15740 lb GVWR, Bumper Pull, Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Lake Worth, TX	
9593	1995 Wells Cargo CVC4025 40 ft T/A Gooseneck Enclosed Trailer S/N: 1WC200R24S2028367 C/W: Spring Suspension, Electric Brakes, 95 in Deck Width, 97 in Overall Width, Side Door 225 /90/16 Tires, 12000 lb GVWR, Interior Racking, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Asset located in: Lake Worth, TX		Trailer S/N: 4YDF35326FA740535 C/W: Sleeps 8 People, Pow Power Awning, Roof Moun Receiver, 5th Wheel, Spring Electric Brakes, 235/80R16 Usage: Not Available Notes: TEXAS BUYERS MU	S/N: 4YDF35326FA740535 C/W: Sleeps 8 People, Power Leveling Jacks, Power Awning, Roof Mounted Satellite Receiver, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9594	2000 Wells Cargo T/A 12 ft Fiber Optic Trailer S/N: 1WC200E27Y1093265 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 225/75R15 Tires, Predator 9000 Watt Generator, Roof Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9598	2012 Keystone Fuzion 37 ft Tri/A Toy Hauler Travel Trailer S/N: 4YDF37527CF811331 C/W: 7000 lb GVWR, 2 Slide Outs, 5th Wheel, Spring Suspension, Electric Brakes, 235/80/16 Tires Usage: Not Available Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9600	2021 Forest River Alpha Wolf 29 ft T/A Travel Trailer  S/N: 5ZT2CKUB5M2001919  C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9598A	2012 Keystone Alpine 34 ft T/A Travel Trailer S/N: 4YDF34927CE780709 C/W: Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires, 5 Slide Outs Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9600A	2015 Keystone 30 ft T/A Travel Trailer S/N: 4YDT30R26F7207465 C/W: 2 Slide Outs, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE
9598B	<b>2011 Forest River Wildcat 34 ft T/A Travel Trailer</b> S/N: 4X4FWCK28BV024670		ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX
	C/W: 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9600B	2014 Forest River 31 ft T/A Travel Trailer S/N: 4X4TRLG28E1853494 C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Leveling Jacks, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE
9599	2008 McKenzie Starwood LX 33 ft T/A Travel Trailer		ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX
	S/N: 4K03B1M278E176497 C/W: Sleeps 4 People, Dish Washer, 2 Slide Outs, Power Awning, 5th Wheel, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Asset located in: Lake Worth, TX		2014 Forest River Lacrosse 33 ft T/A Travel Trailer S/N: 5ZT2LCYB9EB004792 C/W: Air Conditioner, 3 Slide Outs, Power Leveling Jacks, Power Awning, Bumper Pull,
9599A 	2016 Keystone Montana Travel Trailer S/N: 4YDF3102XGA740309 Usage: Not Available Asset located in: Lake Worth, TX		Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9599B	2011 Heartland Sundance 26 ft T/A Travel Trailer  S/N: 5SFSG3427BE213855  C/W: 3 Slide Outs, Power Leveling Jacks, 5th Wheel, Spring Suspension, Electric Brakes, 235 /80 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	PROCESS TITLE. SELLING WIT REPOSESSION AFFIDAVIT ANI ACCEPTED IN YOUR STATE. V YOUR LOCAL DMV PRIOR TO E	PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9601	2015 Gulf Stream Trailmaster 27 ft T/A Travel Trailer  S/N: 1NL1GTM21F1117001  C/W: 7860 lb GVWR, Single Slide Out, Bumper Pull, Spring Suspension, Electric Brakes, 205 /75R15 Tires  Usage: Not Available  Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX	9603	1993 Case 580SK 4x2 Backhoe Loader (Inoperable) S/N: JJG0172373 C/W: Enclosed Cab, Air Conditioner, 82 in Loader Bucket Usage: 6,290 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
9601A	2012 Forest River 3006W 30 ft T/A Travel Trailer  S/N: 4X4TRLF22C1843526  C/W: Sleeps 10 People, Single Slide Out, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available  Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	Seat, Differential Lock, 16 Forv PowerShift, Forward/ Reverse 2016 US EPA Label, Requires I Fluid, Front Weights, HID Light Remotes, Exterior 3-Point Hitc PTO, 3-Point Hitch W/ Quick H 420/85R34 Front Tires, 480/80 Usage: Not Available  Notes: ENGINE RUNS BUT SM HYDRAULICS AND DRIVETRAI OPERATIONAL; INOPERABLE REMOVED FROM YARD BY JA AND CANNOT BE RELISTED; BRESPONSIBILITY FOR REMOV Asset located in: Lake Worth,  9604A LS XU6168 4WD Utility Tractor S/N: 2273000807 C/W: Enclosed Cab, Air Condit Forward 16 Reverse, Power Shreverse Shuttle, Tier 4, 68 hp EQuick Coupler, Auxiliary Hydra Scraper Blade, 9.5x24 Front Titres Usage: Not Available Notes: INOPERABLE ITEM MUFROM YARD BY JANUARY 107 BE RELISTED; BUYER'S RESPOREMOVAL Asset located in: Lake Worth,  9605 Ford 2WD Tractor (Inoperable) S/N: Not Available C/W: 4 Forward 1 Reverse, Matransmission, 540 PTO, 4.00-11.2x28 Rear Tires Usage: 126 Hr Notes: INOPERABLE ITEM MUFROM YARD BY JANUARY 107 BE RELISTED; BUYER'S RESPOREMOVAL	(Inoperable)
9601B	2016 Keystone Outback 32 ft T/A Travel Trailer S/N: 4YDT32429GB451256 C/W: Air Conditioner, 2 Slide Outs, Outdoor Kitchen, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: THIS UNIT IT BEING SOLD WITH A BONDED TITLE; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX		Usage: Not Available  Notes: ENGINE RUNS BUT SMOKES, HYDRAULICS AND DRIVETRAIN ARE OPERATIONAL; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  LS XU6168 4WD Utility Tractor (Inoperable) S/N: 2273000807 C/W: Enclosed Cab, Air Conditioner, 16 Forward 16 Reverse, Power Shuttle, Forward/ Reverse Shuttle, Tier 4, 68 hp Engine, Loader,
9601C	2016 Shadow Cruiser 28 ft T/A Travel Trailer S/N: 5RXTD2821G1033089 C/W: Sleeps 2 People, Single Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE. SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH		Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Ford 2WD Tractor (Inoperable) S/N: Not Available
	YOUR LOCAL DMV PRIOR TO BIDDING  Asset located in: Lake Worth, TX		Transmission, 540 PTO, 4.00-19 Front Tires, 11.2x28 Rear Tires
9602	2009 Case 590 Super M 4x2 Backhoe Loader (Inoperable) S/N: N9C529033 C/W: Enclosed Cab, Air Conditioner, 94 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR

Lot #	Details	Lot #	Details	
9606	(Inoperable) S/N: 40219921 C/W: Enclosed Cab, Air Conditioner, Hydrostatic Drive, Requires Diesel Exhaust Fluid, 580/70R26 Front Tires, 16.5-16.1 Rear Tires, Header S/N - 43062222, 2022 MacDon R216 16 ft Rotary Header Usage: Not Available	9610	2000 Terex S17E Motor Scraper (Inoperable) S/N: S8031011 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Notes: UNIT HAS A BAD ENGINE, DRIVETRAIN, HYDRAULIC SYSTEM AND HEADER ARE COMPLETE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9611	2017 John Deere 9570R Scraper Special Articulated Tractor (Inoperable) S/N: 1RW9570RLGE054151 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 18 Forward 6 Reverse, e18 PowerShift, 2016 US EPA Label, Requires	
9606A	2017 Cat 966M Wheel Loader (Inoperable) S/N: CAT0966MJKJP02417 C/W: Enclosed Cab, Air Ride Seat, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, Log Grapple, 26.5-25 Tires Usage: 6,530 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL		Diesel Exhaust Fluid, Front Weights, 4 Rear Remotes, ISOBUS, Dual 710/70R42 Tires, Front Wheel Weights Usage: Not Available Notes: ENGINE RUNS, DRIVETRAIN IS COMPLETE BUT HAS A BAD REAR END, HYDRAULICS ARE COMPLETE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
9607	2013 Volvo L70G Wheel Loader (Inoperable) S/N: VCE0L70GK00002765 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 20.5R25 Tires Usage: 24,316 Hr Notes: LOADING ASSISTANCE UNAVAILABLE ON THIS ITEM. BUYER WILL NEED TO SET UP OUTSIDE ASSISTANCE. INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	-9612	2016 Cat D6K2 LGP Crawler Dozer (Inoperable) S/N: CAT00D6KVJTR00286 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 144 in Wide PAT Blade, 36 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics, EQUIPMENT-FROM- PULICE-CONSTRUCTION Usage: 10,000 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9608	1999 Volvo L90C Wheel Loader (Inoperable) S/N: L90CV63189 C/W: Enclosed Cab, Hydraulic Coupler, 20.5 R25 Tires, EQUIPMENT-FROM-US-AUTO- RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9612A	(Inoperable) S/N: 1T0750JXKBD203024 C/W: Enclosed Cab, Air Conditioner, S 152 in Wide PAT Blade, 33.5 in Single Track Shoes Usage: 8,566 Hr Notes: INOPERABLE ITEM MUST BE F	2011 John Deere 750J LGP Crawler Dozer (Inoperable) S/N: 1T0750JXKBD203024 C/W: Enclosed Cab, Air Conditioner, Sweeps, 152 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 8,566 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9609	2001 Terex S17E Motor Scraper (Inoperable) S/N: S8311020 C/W: Enclosed Cab, 29.5R25 Tires Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lake Worth, TX		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; UNIT RUNS, DRIVES HYDRAULICS ARE OPERATIONAL - WILL NOT THROTTLE UP Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details		
9613	2016 Cat D5K2 LGP Crawler Dozer (Inoperable) S/N: CAT00D5KCKY202614 C/W: Enclosed Cab, Air Conditioner, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 124 in Wide PAT Blade, 26 in Single Grouser Track Shoes, SystemOne Undercarriage, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 6,365 Hr	9616A	2011 Cat CD54 Double Drum Roller (Inoperable) S/N: CAT0CD54HJ5R00162 C/W: 67 in Compaction Width Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9617	2006 Ingersoll Rand DD-34HF Double Drum Roller (Inoperable) S/N: 188489 C/W: Open Operator Station, 2005 US EPA Label, Kubota V2203-M-ES 4 Cylinder 36.4 kW		
9613A	2001 Cat 963C LGP Crawler Loader (Inoperable) S/N: 2DS01267 C/W: Open Operator Station, 86 in Bucket, 21 in Double Grouser Track Shoes, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY	9620		2.2 L Diesel Engine, 54 in Compaction Width, Water System Usage: 5,526 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		2011 Lay-Mor 8HC Self-Propelled Broom (Inoperable) S/N: 33225 C/W: Open Operator Station, 7 ft 9 in Broom, Water System, 2019 US EPA Label, Kubota 3 Cylinder 26 kW 1.5 L Diesel Engine		
9614	Dynapac CA2500 Padfoot Drum Compactor (Inoperable) S/N: 10000138K0A011328 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED			Usage: 854 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED  Asset located in: Lake Worth, TX	
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX		1999 Broce BB250 Self-Propelled Broom (Inoperable) S/N: 981111 C/W: Open Operator Station, 6 ft 3 in Broom,		
9615	1998 Cat CP433C Padfoot Drum Compactor (Inoperable) S/N: 2JM00524 C/W: Enclosed Cab, Cat 4 Cylinder Diesel Engine, 66 in Drum, Leveling Blade Usage: 5,226 Hr Notes: INOPERABLE ITEM MUST BE REMOVED			Water Usage <b>Notes</b> FROM BE RE REMO	Water System, 4 Cylinder Diesel Engine Usage: 542 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED  Asset located in: Lake Worth, TX		2013 Komatsu PC360LC-10 Tracked Excavator (Inoperable) S/N: KMTPC242A54A32676		
9616	2017 Bomag BW 124 Smooth Drum Compactor (Inoperable) S/N: 861832121160 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX		C/W: Air Conditioner, Rear View Camera, US EPA Label, 10 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 56 in Digging Bucket, Thumb Bracket Usage: 13,098 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9622	2016 Cat 330F L Tracked Excavator (Inoperable)  S/N: CAT0330FCMBX00322 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Triple Grouser Track Shoes, Hydraulic Quick Coupler, 52 in Digging Bucket, EQUIPMENT-FROM-PULICE- CONSTRUCTION Usage: 10,017 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY	9623C	2016 John Deere 35G Mini Excavator (Inoperable) S/N: 1FF035GXTGK276310 C/W: Swing Boom, 4 ft 4 in Stick, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9624	2006 Komatsu PC27MR-2 Mini Excavator (Inoperable)
9623	Asset located in: Humble, TX  2020 Cat 320 Tracked Excavator (Inoperable)	-	S/N: KMTPC120A05016215 C/W: Control Pattern Changer, Swing Boom, 3
7020	S/N: CAT00320KHEX20346 C/W: Air Conditioner, Straight Travel Pedal, Cab Screens, Rear & Side View Cameras, 2019 US EPA Label, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, Manual Quick Coupler, Thumb Bracket		ft 8 in Stick, Backfill Blade, 12 in Rubber Tracks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
	Usage: 4,956 Hr <b>Notes</b> : INOPERABLE ITEM MUST BE REMOVED		Asset located in: Lake Worth, TX
9623A	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX  2014 John Deere 135G Tracked Excavator (Inoperable)  S/N: 1FF135GXJEE400550  C/W: Air Conditioner, Air Ride Seat, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 24 in	9624A _	2018 Wacker Neuson EZ53 Mini Excavator (Inoperable) S/N: WNCE0510TPAL00649 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: 1,989 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	Double Grouser Track Shoes w/Rubber Inserts, Hydraulic Quick Coupler, 24 in Digging Bucket,		Asset located in: Lake Worth, TX
9623B	EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  2018 Bobcat E50 Mini Excavator (Inoperable) S/N: AJ1814335	9625	2014 Terex TC16 Mini Excavator (Inoperable) S/N: TC00163259 C/W: Swing Boom, 3 ft 8 in Stick, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, 8 in Digging Bucket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
	C/W: Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in	9627	1998 Vermeer 8550A 4x4 Trencher (Inoperable)
	Rubber Tracks, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 4,351 Hr  Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNOBE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX	702/	S/N: 1VRT112P2W1000109 C/W: Canopy, Diesel Engine, Hydrostatic Drive, 6 in Wide x 5 ft 6 in Long Rock Trencher Chain, Straight Blade Usage: 1,406 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9628	628 1998 Vermeer V4150A 4x4 Trencher (Inoperable) S/N: 1VRP082R0W1000592 C/W: Deutz 4 Cylinder Diesel Engine, 8.5 in Wide x 7 ft Long Rock Trencher Chain, Crumbling Shoe, 8600 Backhoe Attachment, Angle Blade, Side Shift Usage: 349 Hr	9631	2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DLDTB05827 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9632	2016 Cat 262D Skid Steer Loader (Inoperable) S/N: CAT0262DPDTB05818 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED	
9628A	2016 LOKT T/A Vacuum Excavation Unit (Inoperable) S/N: 4M9F2TG22GE015001		FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
	S/N: 4M9E2TG22GE015001 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Front Hose Reel, 320 L Fresh Water Tank, Drop Down Tailgate, Manual Tailgate Locks, 3.5 in Suction Hose, Engine Driven Pump, 235/80R16 Tires, Honda 1 Cylinder Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	9632A	Asset located in: Lake Worth, TX  2018 Cat 226D Skid Steer Loader (Inoperable) S/N: CAT0226DJHRD03498 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 74 in Bucket Usage: 1,238 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9634 9634A	2017 Cat 299D2 Compact Track Loader	
9629	Asset located in: Lake Worth, TX  2011 Vermeer LP555DT T/A Vacuum Excavation Unit (Inoperable)  S/N: 5HZBF1624BLHB1501  C/W: 5440 lb GVWR, Lunette Ring Hitch, Torsion Axle, Electric Brakes, Vermeer Steel Debris Tank, Rear Hose Reel, Fresh Water Tank, Full Open Tailgate, Manual Tailgate		(Inoperable) S/N: CAT0299DHFD202254 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	Locks, Annovi Reverberi Engine Driven Pump, Blower, Remote Control w/ Cord, ST235/85R16 Tires, Yanmar 3TNV88-BDSA 3 Cylinder Engine Usage: 2,108 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Lo S, C, Ro 18	2018 Cat 289D Two-Speed Compact Track Loader (Inoperable) S/N: CAT0289DJTAW08857 C/W: Open Operator Station, Joystick Steering, Rear View Camera, Tier 4, 2017 US EPA Label, 18 in Track Belts, 9 Pin Electric Kit, Manual Coupler, 78 in Bucket Usage: 4,582 Hr
9629A	<b>4x4 Articulated Water Truck (Inoperable)</b> S/N: Not Available C/W: Open Operator Station, 23.1-26 Tires		Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED  Asset located in: Lake Worth, TX	
	Usage: 2,976 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX		2014 Cat 289D Compact Track Loader (Inoperable) S/N: CAT0289DVTAW00650 C/W: Enclosed Cab, Joystick Steering, 18 in Track Belts, Manual Coupler, 74 in Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-	
9630	Weiler P355 Track Asphalt Paver (Inoperable) S/N: P355-1010 C/W: Dual Controls, 8 ft - Screed, 12 in Rubber Tracks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9635 9635A	2019 Kubota SVL95-2S Compact Track Loader S/N: KBCC0953CK1D46350 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Asset located in: Midland, TX  2020 Bobcat T590 Compact Track Loader (Inoperable)	9638	2008 John Deere CT332 Compact Track Loader (Inoperable) S/N: T0332TA168479 C/W: Enclosed Cab (Door missing), 18 in Track Belts, Manual Coupler Usage: 6,793 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX
	S/N: ALJU32175 C/W: Open Operator Station, Air Ride Seat,	9639	2010 Bobcat T190 Compact Track Loader
	Joystick Steering, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,749 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		(Inoperable) S/N: A3LN36903 C/W: Open Operator Station, 12.5 in Track Belts, Manual Coupler Usage: 5,228 Hr
	REMOVAL		Notes: UNIT STARTS AND RUNS, PARKING BRAKE INOPERABLE ; INOPERABLE ITEM
9636	Asset located in: Humble, TX  2018 Case TR310 Compact Track Loader (Inoperable)	9640	MUST BE REMOVED FROM YARD BY JANUAF 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
	S/N: JAFTR310AJM449342		Asset located in: Lake Worth, TX
	C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2018 US EPA Label, 15.5 in Track Belts, Manual Coupler, 77 in Bucket Usage: 3,405 Hr		2019 Toro 22322 Compact Track Loader (Inoperable) S/N: 405588028 Usage: Not Available
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED  Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9636A	2018 Case TR270 Compact Track Loader	0641	Asset located in: Lake Worth, TX
	(Inoperable) S/N: NJM448663 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 13 in Track Belts, Manual Coupler, 68 in Bucket Usage: 2,404 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9641	2015 JLG 10054 Telehandler (Inoperable) S/N: 0160070159 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
9637	2017 John Deere 317G Compact Track Loader (Inoperable)		Asset located in: Humble, TX
	S/N: 1T0317GJPHJ308175 C/W: Open Operator Station, Joystick Steering, 13 in Track Belts, Hydraulic Coupler, 72 in Bucket, EQUIPMENT FROM UNITED RENTALS Usage: 2,121 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9642	2013 JCB 9404 8000 lb Rough Terrain Forklift (Inoperable)  S/N: JCB94004A02228045  C/W: 3 Stage Mast, 72 in Forks, 2012 US EPA Label, JCB tc-55 4 Cylinder 4.4 L Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX

		_	
Lot #	Details	Lot #	Details
9642A	1999 Mack RB688S 6x4 85 in Tree Spade Truck (Inoperable) S/N: 1M2AM08C9XM004800 C/W: Mack 6 Cylinder Diesel Engine, 1998 US EPA Label, Aluminum Front Wheels, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 258 in Wheelbase Usage: 216,359 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9645	2009 Toyota 7FGAU50 7550 lb Pneumatic Tire Forklift (Inoperable) S/N: 70256 C/W: 3 Stage Mast, 219 in Max Lift Height, 84 in Lowered Mast Height, 84 in Forks, Side Shift, 2009 US EPA Label, IMPCO 6 Cylinder 4.3 L LPG Engine Usage: 6,371 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Bryan, TX
9643	2007 Ford F-550 XL 4x2 Extended Cab Utility Truck (Inoperable) S/N: 1FDAX56P57EA34588 C/W: Ford V8 Diesel Engine, Automatic Transmission, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Knapheide 9 ft Body Usage: 296,251 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	<b>-9646</b>	2010 Toyota 7FGAU50 5950 lb Pneumatic Tire Forklift (Inoperable)  S/N: 70533  C/W: 3 Stage Mast, 219 in Max Lift Height, 109 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, Vortec LPG Engine Usage: 8,220 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Elmendorf, TX
	Asset located in: Lake Worth, TX	9646A	2012 Toyota 8FGCU30 5120 lb Cushion Tire
9644 9644A	Mitsubishi FG50K 11000 lb Pneumatic Tire Forklift (Inoperable)  S/N: AF33B50068  C/W: 2 Stage Mast, 148 in Max Lift Height, Solid Pneumatic Tires, 5 Cylinder LPG Engine Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX  2021 Yale GLC155VX 10000 lb Cushion Tire	- 9040A	Forklift (Inoperable) S/N: 17847 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, Toyota 4Y ECS 4 Cylinder 2.23 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Forklift (Inoperable) S/N: F879V02835V C/W: 3 Stage Mast, 221 in Max Lift Height, 111 in Lowered Mast Height, Paper Roll Clamp, 2021 US EPA Label, PSI 6 Cylinder 4.3 L Dual Fuel Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9647	1990 Cat T50D 5000 lb Cushion Tire Forklift (Inoperable) S/N: 8EB09438 C/W: 3 Stage Mast, 173 in Max Lift Height, 83 in Lowered Mast Height, 36 in Forks, Side Shift, Cat 4 Cylinder LPG Engine Usage: 20,099 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9648	2004 Hyundai HLF25-5 5000 lb Pneumatic Tire Forklift (Inoperable)  S/N: FU0211429  C/W: Single Stage Mast 130 in Max Lift Height, 86 in Lowered Mast Height, 47 in Forks, 2004  US EPA Label, CARB Compliant, IMPCO 6Z9XB02.4MPN 4 Cylinder 2.4 L LPG Engine Usage: 1,363 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX	9652	2013 Nissan CF40LP 4000 lb Pneumatic Tire Forklift (Inoperable)  S/N: CP1F2-9W1966  C/W: 2 Stage Mast, 80 in Max Lift Height, 56 in Lowered Mast Height, 40 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2013 US EPA Label, 4 Cylinder 2.1 L LPG Engine Usage: 10,133 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX
9649	2012 Cat 2EPC5000 4870 lb Electric Forklift (Inoperable)  S/N: FN459381  C/W: 3 Stage Mast, 86 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, 80 V, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED  Asset located in: Lake Worth, TX	9653	2000 Toyota 52-6FGCU45 8600 lb Cushion Tire Forklift (Inoperable)  S/N: 62206  C/W: 3 Stage Mast, Full Free Lift, 218.5 in Max Lift Height, 106 in Lowered Mast Height, 72 in Forks, Side Shift, V6 LPG Engine Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9650	2012 Doosan G25P-5 4600 lb Pneumatic Tire		Asset located in: Lake Worth, TX
-300	Forklift (Inoperable) S/N: FGA0B133002925 C/W: 3 Stage Mast, 186 in Max Lift Height, 84 in Lowered Mast Height, 60 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, 4 Cylinder 46.8 kW 2.4 L LPG Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9654	2011 Yale GLP040SVXNURV084 4000 lb Pneumatic Tire Forklift (Inoperable) S/N: C810V04664J C/W: 2 Stage Mast, 127.2 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2011 US EPA Label, 4 Cylinder 2.0 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9655	2014 Toyota 8FGCU20 4000 lb Cushion Tire
9651	2016 Cat GP25N 4500 lb Pneumatic Tire Forklift (Inoperable)  S/N: AT35A02995  C/W: 3 Stage Mast, 188 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.5 L LPG Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: 3,439 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED  Asset located in: Lake Worth, TX		Forklift (Inoperable) S/N: 62727 C/W: 2 Stage Mast, 80 in Max Lift Height, 57 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, Load Weigh System, 2014 US EPA Label, CARB Compliant, Toyota 4YECS 4 Cylinder 38 kW 2.2 L LPG Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9655A	2012 TCM FG25T3 3700 lb Pneumatic Tire Forklift (Inoperable) S/N: 2H507316 C/W: 3 Stage Mast, 189 in Max Lift Height, 41 in Forks, Side Shift, Tier 2, 2012 US EPA Label, Nissan 4 Cylinder 2.1 L Dual Fuel Engine Usage: 3,696 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9657C	2017 Toyota 8FGCU25 1700 lb Cushion Tire Forklift (Inoperable) S/N: 88346 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 95 in Lowered Mast Height, 42 in Forks, Side Shift, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 7,554 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9655B	2012 Toyota 7FBEU20 3050 lb Electric Forklift (Inoperable)  S/N: 7FBEU20-20440  C/W: 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, 36 V Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX	9658	Toyota Cushion Tire Forklift (Inoperable) S/N: Not Available C/W: 2 Stage Mast, 77 in Lowered Mast Height, 42 in Forks, 4 Cylinder Gasoline Engine, EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
9656	2003 Linde E30C 3060 lb Electric Forklift (Inoperable) S/N: A1X347P00155 C/W: 3 Stage Mast, 24 in Lowered Mast Height, 36 in Forks, 48 V, Battery Charger Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  1998 Toyota 5FBE18 2800 lb Electric Forklift	-9659 - 9659A	2014 Skyjack SJ8841RT 4x4 Dual Fuel Scissor Lift (Inoperable) S/N: 40001322 C/W: 41 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2014 US EPA Label, Kubota WG972-GL-ET 3 Cylinder 962 cc Dual Fuel Engine, LP Tank is not included Usage: 1,512 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY
	(Inoperable) S/N: 24164 C/W: 3 Stage Mast, Full Free Lift, 218 in Max Lift Height, 93 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX  2000 UpRight RT27 4x4 Gasoline Scissor Lift (Inoperable) S/N: 2922 C/W: 27 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Upper Control Box, 2000 US EPA Label, Kubota 3 Cylinder 740 cc Gasoline Engine Usage: 4,028 Hr
9657A	1995 Toyota 5FBE18 Electric Forklift (Inoperable) S/N: 15611 C/W: 3 Stage Mast, Full Free Lift, 82 in Lowered Mast Height, 47 in Forks, Side Shift, 48 V Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD  Asset located in: Lake Worth, TX

	D. C. II	l	D . 11
Lot #	Details	Lot #	Details
9659B	2016 Genie GS-3232 Electric Scissor Lift (Inoperable)  S/N: GS3216P-144587  C/W: 32 ft Max Platform Height, 500 lb Max  Weight Capacity, Platform Extension, Power to  Platform, Stabilizers, Solid Non-Marking Tires  Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED  FROM YARD BY JANUARY 10TH AND CANNOT  BE RELISTED; BUYER'S RESPONSIBILITY FOR  REMOVAL; AERIAL UNITS REQUIRE PROPER  SAFETY HARNESS, LANYARD, AND PPE TO  FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX	9662	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2013 US EPA Label, Kubota V1505 16 kW 1.5 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,620 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9660	2016 Skyjack SJ3226 Electric Scissor Lift (Inoperable) S/N: 27028952 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Onboard Generator, Solid Non-Marking Tires Usage: 285 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Lake Worth, TX	9663	Lincoln Electric Vantage 300 Skid-Mounted Multi-Process Engine Driven Welder (Inoperable)  S/N: Not Available  C/W: Tier 4, 2013 US EPA Label, Kubota v1505  4 Cylinder 16 kW 1.5 L Diesel Engine, 240 V  Rated Voltage, 120 V / 240 V Rated Voltage  Usage: 4,216 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED  FROM YARD BY JANUARY 10TH AND CANNOT  BE RELISTED; BUYER'S RESPONSIBILITY FOR  REMOVAL  Asset located in: Lake Worth, TX  Lincoln RA-250-V1903 300 A Skid-Mounted
9661	2016 Snorkel S3219E Electric Scissor Lift (Inoperable) S/N: S3219E04001808 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box Usage: 47 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9664	Engine Driven Welder (Inoperable)  S/N: C1080500072  C/W: Tier 4, 2008 US EPA Label, CARB  Compliant, Kubota V2003-M-BG-ET02e 4  Cylinder 24.3 kW 2.0 L Diesel Engine, Welding  Leads Not Included, 40 V Rated Voltage  Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED  FROM YARD BY JANUARY 10TH AND CANNOT  BE RELISTED; BUYER'S RESPONSIBILITY FOR  REMOVAL  Asset located in: Humble, TX
	Asset located in: Lake Worth, TX		1992 Onan 37DGBA 37 kW Skid-Mounted
9661A	2017 Generac MLT6SMD Light Tower (Inoperable) S/N: 7FSBL1018HB880619 C/W: 2017 US EPA Label, 3 Cylinder Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: 1,155 Hr Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; 3001880619; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Generator Set (Inoperable) S/N: 1910419145 C/W: Cummins 4B3.9G 4 Cylinder 66 hp 3.9 L Diesel Engine, /37 kW Rated 3 Phase Output Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9665A	2009 Drash 23 kW Mobile Generator Set (Inoperable) S/N: 610 C/W: 2009 US EPA Label, Perkins 4 Cylinder 19 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Lunette Ring Usage: 4,337 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9666B 9666C	2006 Ingersoll Rand G25 Mobile Generator Set (Inoperable) S/N: 4FVGCBAA06U374217 C/W: Ingersoll-Rand 3 Cylinder Diesel Engine, 480 V Rated Voltage, S/A Trailer, Lunette Ring Usage: 34,921 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  2016 Multiquip DCA220SSJU4F Generator Set (Inoperable)
9665B	Drash 20 kW Mobile Generator Set (Inoperable) S/N: 359 C/W: 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, 240 V Receptacles, S/A Trailer, Lunette Ring Usage: 737 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: 5SLBG1825GL018612 C/W: 2016 US EPA Label, John Deere 6 Cylinder 6.8 L Diesel Engine, 220 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 10,985 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9665C	2008 Drash 20 kW Mobile Generator Set (Inoperable) S/N: 346 C/W: Perkins 4 Cylinder 33 kW 2.2 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, Sound Attenuated, S/A Trailer, Lunette Ring Usage: 265 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9667	Gardner-Denver EAUSPG Skid-Mounted Electric Air Compressor (Inoperable) S/N: FACP8X0 C/W: 3 Phase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  2018 Tsurumi TPG4-4500HDX 4.5 kW Portable
9666	Asset located in: Lake Worth, TX  Cummins 682F9R7032 640 kW Skid-Mounted Generator Set (Inoperable)  S/N: C9M0682005  C/W: 2008 US EPA Label, Volvo TWD1643GE 6  Cylinder 1800 kW 16.2 L Diesel Engine, 800 kVA /640 kW Rated 3 Phase Output, 440 V Rated	9668	Generator Set (Inoperable) S/N: 051272 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Lake Worth, TX
	Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Humble, TX		2019 Tsurumi TPG4-4500HDX 4.5 kW Portable Generator Set (Inoperable) S/N: 051460 C/W: Honda GX240 Gasoline Engine, 3.6 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available
9666A	Redco Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Cummins 6 Cylinder Diesel Engine Usage: 269 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX		Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9670	Sullivan Palatek Skid-Mounted Electric Air Compressor (Inoperable) S/N: 11F046 C/W: 200 psi Working Pressure, 230, 75 hp Motor Usage: 18,303 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9673B	9673B 2001 Sullivan 185DPQ Mobile Air Compresso (Inoperable)  S/N: 4135193  C/W: 200 psi Working Pressure, 2001 US EPA Label, John Deere 4045DP150B 4 Cylinder 4. L Diesel Engine, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: 1,078 Hr  Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO BE RELISTED; BUYER'S RESPONSIBILITY FOR	
9671	2010 MGS Trailer-Mounted Water Pump (Inoperable) S/N: 16MPF0922AD056753 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, 2010 US EPA Label, John Deere 4 Cylinder 60 kW 4.5 L Diesel Engine, T/A Trailer, Lunette Ring, Surge Brakes Usage: 4,558 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		REMOVAL Asset located in: Lake Worth, TX  2017 Atlas Copco XAS110KD 110 cfm Mobile Air Compressor (Inoperable) S/N: YA3064283H0480254 C/W: 2017 US EPA Label, Kubota D902-EF01 3 Cylinder 0.89 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S	
9672	MMDI Trailer-Mounted Water Pump (Inoperable) S/N: Not Available C/W: 5 in Intake, 6 in Discharge, Centrifugal Water Pump, Kohler KD11903TCR 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9674	RESPONSIBILITY FOR REMOVAL;  Asset located in: Humble, TX  Ingersoll Rand Electric Air Compressor (Inoperable)  S/N: Not Available C/W: 3 Phase, 20 hp Motor Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	
9673	2011 Magnum MAG MTP 4000D Trailer- Mounted Water Pump (Inoperable)  S/N: 1105549  C/W: 4 in Intake, 4 in Discharge, Centrifugal 2013 US EPA Label, CARB Compliant, John Deere 4024TF281A 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,333 Hr  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9675	9675 Gardner-Denver WCC-1001 Vertical Compressor (Inoperable) S/N: 414039 Usage: Not Available Notes: INOPERABLE ITEM MUST B FROM YARD BY JANUARY 10TH AN BE RELISTED; BUYER'S RESPONSING REMOVAL Asset located in: Lake Worth, TX  9676 Gardner-Denver Air Compressor (In	S/N: 414039 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  Gardner-Denver Air Compressor (Inoperable) S/N: Not Available
9673A			Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9677	Ingersoll Rand 20VX15 Air Compressor (Inoperable) S/N: Not Available Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9682	Landa PGDC5-3500 Pressure Washer (Inoperable) S/N: 11100500101088 C/W: 3500 psi Rating, Water Heater, Briggs & Stratton 570 cc Gasoline Engine Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9678	Pneumatic Skid Mounted Lube Pan - Fits Truck (Inoperable)  S/N: Not Available  C/W: Kohler Command Pro 14 429 cc Gasoline Engine, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY  Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX	9682A	Asset located in: Lake Worth, TX  2022 Kubota RTV-X1140 Utility Vehicle (Inoperable)  S/N: A5KD2GDBVNG053697  C/W: Open Operator Station, 4 Passenger, Windshield, Electric Dump Bed, Tier 4, 2022 US  EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L  Diesel Engine Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT
9679	Gardner-Denver Air Compressor (Inoperable) S/N: Not Available		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9682B	2021 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBCMG044293 C/W: Canopy, 4 Passenger, Electric Dump Bed, Tier 4, 2021 US EPA Label, Kubota d1105 3 Cylinder 8 kW 1.1 L Diesel Engine Usage: 1,144 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX  2017 Kubota RTV-X1140 Utility Vehicle (Inoperable) S/N: A5KD2GDBLHG019685
9680	Quantity of (2) Water Pump (Inoperable) S/N: Not Available C/W: Trash Pump, 1 Cylinder Gasoline Engine, (1) Tsurumi 4 In, (1) 3 In, One Pallet Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED		
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9684	
9680A	2019 Cub Cadet Pro Z 500 Zero-Turn Lawn Mower (Inoperable) S/N: 1C089H70016 C/W: 2019 US EPA Label, 24x12.00-14 Rear Tires, 54 in Mower Usage: 105 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Humble, TX
	REMOVAL  Asset located in: Lake Worth, TX	9684A	2020 Club Car Carryall 1700D Utility Vehicle
9681	2016 Airrex Air Conditioner (Inoperable) S/N: 161010989L Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: SD2013059325 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota D722 3 Cylinder Diesel Engine Usage: 758 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9685A	Club Car Carryall 1500 Utility Vehicle (Inoperable) S/N: 104027428 C/W: Canopy, 2 Passenger, Brush Guard, Manual Dump Bed, 2 Cylinder 1500 cc Gasoline Engine Usage: 610 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9688	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X2FD262706 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21970 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 206 in Wheelbase, PTO, Auto Lube Usage: 745,623 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	
9686	John Deere Gator XUV Utility Vehicle (Inoperable) S/N: Not Available		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX	
	C/W: Canopy, 2 Passenger, Manual Dump Bed, John Deere 3 Cylinder Engine Usage: 1,574 Hr <b>Notes</b> : INOPERABLE ITEM MUST BE REMOVED	9689	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X0FD263191	
	FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 7302 Engine hrs, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air	
9687	7 2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X2GD332545 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 22171.7 Engine hrs, Eaton Fuller Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab,		Ride Cab, 11R22.5, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Auto Lube Usage: 539,809 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	
	11R22.5, Air Trac Air Ride Suspension, PTO, Auto Lube Usage: 693,335 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9689A	Tractor (Inoperable) S/N: 1XPSD79X8CD166896 C/W: Cummins ISX11.9 385V 6 Cylind Diesel 385 hp Engine, 2011 US EPA L Requires Diesel Exhaust Fluid, 26030 hrs, Eaton Fuller 8LL Manual Transmi	Tractor (Inoperable) S/N: 1XPSD79X8CD166896 C/W: Cummins ISX11.9 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 26030 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb
9687A	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPSD79X0GD263208 C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 8LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab,		GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Trac Suspension, 202 in Wheelbase, PTO Usage: 656,774 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX	
	Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase, PTO Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9690	2013 Kenworth T800 6x4 T/A Day Cab Truck Tractor (Inoperable)  S/N: 1XKDDP9X9DJ369135  C/W: Paccar MX-13 6 Cylinder 12.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.70:1 Axle Ratio, 53200 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 199 in Wheelbase, Air Sliding 5th Wheel, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED	

Lot #	Details	Lot #	Details
9691	2019 Peterbilt 567 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPCD79X0KD612896 C/W: Cummins ISX12 385V 6 Cylinder 11.9 L Diesel 385 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 202 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9694	2014 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor (Inoperable)  S/N: 3AKJGBDV6ESFU4154  C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 42 hp Engine, 2013 US EPA Label, Requires Dies Exhaust Fluid, Engine Brake, Eaton Fuller FRC 14210c 10-Speed Manual Transmission, 120 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 46000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 200 in Wheelbase, PTO, Blower Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVE FROM YARD BY JANUARY 10TH AND CANNO
9692	2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable)		BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX
	S/N: 3AKJGEBG6FDGN5797 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18055.3 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 52000 lb GVWR, 295 /75R22.5, Airliner Air Ride Suspension, 190 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 621,649 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9695	2007 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9GF47N449500 C/W: Volvo D12D365 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Manual Transmission, 275/80R22.5, 160 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,615,127 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9693	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEDV1DLBV2601 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 195 in Wheelbase, Dual Fuel Tanks Usage: 588,339 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9696	2003 Volvo VNL 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4NC9GH93N350140 C/W: Volvo 6 Cylinder Diesel Engine, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor RT-40-145 Drive Axles, 3.58:1 Axle Ratio, 50000 lb GVWR, 11R22.5, Air Ride Suspension, 169 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX

# Lot # Details 9697 2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XPBD49X1LD655901 C/W: Cummins X15 6 Cylinder 15.0 L Dies 450 hp Engine 2019 US EPA Label Requir

C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23259 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 5200 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel

Usage: 752,578 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Humble, TX

## 9698 2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X6LD655909 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Asset located in: Humble, TX

## 9700 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XPBD49X1GD326444 C/W: Cummins ISX15 6 Cylinder 14.9 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200.0 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 245 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL:

Asset located in: Lake Worth, TX

### 9701 2016 Peterbilt 579 6x4 T/A Sleeper Truck

Tractor (Inoperable)

Lot #

**Details** 

S/N: 1XPBD49X2GD346556 C/W: Cummins ISX15 6 Cylinder 15.0 L 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 24608.8 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 249 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel

Tanks Usage: 707.094 Mi

Asset located in: Lake Worth, TX

## 9701A 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor

S/N: 1XKYD49X5KJ310239 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 233 in Wheelbase, PTO, Dual Fuel Tanks

Usage: Not Available

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Midland, TX

## 9702 2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable)

S/N: 1XKYD49X6GJ463607 C/W: Cummins ISX15 450ST2 6 Cylinder 15.0 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 23925 Engine hrs, Engine Brake, Eaton Fuller 12-Speed Automated Transmission, 12350 lb Front Axle, 36000 lb Rears, 2.64:1 Axle Ratio, 48000 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Flex Air Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 793,933 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9703	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable)  S/N: 1XKYDP9X0FJ437603  C/W: Paccar MX-13 6 Cylinder 12.9 L 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 12000 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks Usage: Not Available  Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Humble, TX	9706	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR2MSMU7290 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9704	2015 Kenworth T680 6x4 T/A Sleeper Truck	9707	2020 Freightliner Cascadia 126 6x4 T/A
<i>5</i> , 6, 1	Tractor (Inoperable) S/N: 1XKYDP9X0FJ464641 C/W: Paccar 6 Cylinder Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 19664 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C- LAS Automated Transmission, 12000 lb Front Axle, 38000 lb Rears, Dana DSP40 Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, 36 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 204 in Wheelbase, Dual Fuel Tanks Usage: 683,198 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	3707	Sleeper Truck Tractor (Inoperable)  S/N: 3AKJHHDR5LSKS3557  C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 608,756 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX
9705	2011 Mack CHU613 6x2 T/A Sleeper Truck	9708	2020 Freightliner Cascadia 126 6x4 T/A
	Tractor (Inoperable) S/N: 1M1AN07Y2BM006847 C/W: Mack MP8 6 Cylinder Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Mack Drive Axles, 52000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 248 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX		Sleeper Truck Tractor (Inoperable)  S/N: 3AKJHHDR7LSLJ3051  C/W: Detroit DD15 6 Cylinder 14.5 L 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor DA-RT-40.0-4S Drive Axles, 3.23:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 594,374 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

#### **Details** Lot # **Details** Lot # 9709 2019 Freightliner Cascadia 126 6x4 T/A 9712 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR0KSKC2651 S/N: 3AKJGLDR5JSJK6667 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12-Speed hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 27034 Engine hrs, Engine Brake, Detroit DT12-1750-HD1 12-Speed Automated Automated Transmission, 13300 lb Front Axle, Transmission, 12000 lb Front Axle, 40000 lb 40000 lb Rears, 3.08:1 Axle Ratio, 53300 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.16:1 GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Sliding 5th Wheel, Headache Rack, Dual Fuel Rear Tires, Airliner Air Ride Suspension, 223 in Tanks Wheelbase, Air Sliding 5th Wheel, Headache Usage: Not Available Rack, Dual Fuel Tanks Notes: INOPERABLE ITEM MUST BE REMOVED Usage: 623,235 Mi FROM THE YARD BY JANUARY 10TH AND Notes: INOPERABLE ITEM MUST BE REMOVED CANNOT BE RELISTED FROM YARD BY JANUARY 10TH AND CANNOT Asset located in: Lake Worth, TX BE RELISTED; BUYER'S RESPONSIBILITY FOR 9713 2017 Freightliner Cascadia 125 6x4 T/A REMOVAL; Sleeper Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 3AKJGLDR9HSJC5723 9710 2018 Freightliner Cascadia 126 6x4 T/A C/W: Detroit DD15 14.8 L Engine, Requires Sleeper Truck Tractor (Inoperable) Diesel Exhaust Fluid, Engine Brake, Eaton Fuller S/N: 3AKJHHDR3JSJW8538 10-Speed Manual Transmission, Differential C/W: 6 Cylinder Diesel Engine, Detroit 12-Speed Lock, 13300 lb Front Axle, 40000 lb Rears, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5 Front Tires, 425/65R22.5 Super 3.08:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 295/75R22.5, Singles Rear Tires, Airliner Air Ride Suspension, Airliner Air Ride Suspension, Air Sliding 5th 234 in Wheelbase, Air Sliding 5th Wheel, Dual Wheel **Fuel Tanks** Usage: Not Available Usage: Not Available Notes: SELLING WITH A REPOSESSION Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY PRIOR TO BIDDING; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH 10TH AND CANNOT BE RELISTED AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX Asset located in: Midland, TX 9711 2018 Freightliner Cascadia 125 6x4 T/A 9714 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR0JSJR7937 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel S/N: 1FUJGLD5XGLGU2219 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-OA-1650 Exhaust Fluid, 24994 Engine hrs, Engine Brake, 12-Speed Automated Transmission, 12350 lb Eaton Fuller FRW-15210B 10-Speed Manual Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th 60 in High Rise Sleeper Cab, Bunk Beds, Wheel, Dual Fuel Tanks Aluminum Wheels, MIXED, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: Not Available

Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab,

Usage: 730,665 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

Asset located in: Humble, TX

#### **Details** Lot # **Details** Lot # 9715 2016 Freightliner Cascadia 125 6x4 T/A 9719 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDV4GSHD4846 S/N: 3AKJGLDR4ESFD3920 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel hp Engine, Requires Diesel Exhaust Fluid, Engine, 2012 US EPA Label, Requires Diesel Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Exhaust Fluid, 10571 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, Rears, Meritor RT-40-145 Drive Axles, 2.64:1 12000 lb Front Axle, 40000 lb Rears, Detroit DA-Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Sliding 5th Wheel, Dual Fuel Tanks Tanks Usage: 1,029,912 Mi Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE Notes: INOPERABLE ITEM MUST BE REMOVED REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR PLEASE SEE THE INSPECTION REPORT REMOVAL: INOPERABLE ITEM MUST BE REMOVED FROM Asset located in: Lake Worth, TX YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR 9720 2014 Freightliner Cascadia 125 6x4 T/A REMOVAL: Sleeper Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 1FUJGLD61ELFM1902 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel 9716 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Exhaust Fluid, Engine Brake, Eaton Fuller FRO-S/N: 3AKJGLD5XGSHJ8963 16210C 10-Speed Manual Transmission, C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 52000 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 244 in Axle Ratio, 53220 lb GVWR, Air Ride Cab, High Wheelbase, Headache Rack, Dual Fuel Tanks Rise Sleeper Cab, Bunk Beds, Aluminum Front Usage: Not Available Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY OCTOBER 18TH AND CANNOT **Fuel Tanks** BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: 696,122 Mi REMOVAL Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Midland, TX FROM THE YARD BY JANUARY 10TH AND 9721 CANNOT BE RELISTED 2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Asset located in: Humble, TX S/N: 1FUJGLBG8CSBM1768 9716A 2016 Freightliner Cascadia 125 6x4 T/A C/W: Cummins ISX 6 Cylinder 450 hp Engine, Sleeper Truck Tractor (Inoperable) Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DS404 Drive Axles, 3.55:1 Axle S/N: 3AKJGLDR8GSGV0892 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Ratio, 53200 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride hp Engine, Requires Diesel Exhaust Fluid, 21275 Engine hrs, Engine Brake, Detroit DT12-OH-1650 12-Speed Automated Transmission, Suspension, 228 in Wheelbase, Air Sliding 5th 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Whėel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 FROM YARD BY JANUARY 10TH AND CANNOT /75R22.5 Front Tires, 445/50R22.5 Super BE RELISTED; BUYER'S RESPONSIBILITY FOR Singles Rear Tires, Airliner Suspension, 236 in REMOVAL; Wheelbase, Air Sliding 5th Wheel, Headache Asset located in: Lake Worth, TX Rack, Dual Fuel Tanks Usage: 873,267 Mi

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR

#### **Details** Lot # **Details** Lot # 9722 2018 Volvo VNL 6x4 T/A Sleeper Truck Tractor 9725 2019 International LT625 6x4 T/A Sleeper (Inoperable) Truck Tractor (Inoperable) S/N: 4V4NC9EH1JN961795 S/N: 3HSDZAPR7KN110756 C/W: Cummins X15 6 Cylinder 15 L 450 hp C/W: Volvo D13M455 6 Cylinder 12.8 L 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, Differential Lock, 12350 lb Front Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Drive Axles, 2.47:1 Axle Ratio, 50350.0 lb Cab, 72 in High Rise Sleeper Cab, Bunk Beds, GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275 275/80R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 228 in Wheelbase, /80R22.5, Air Ride Suspension, 224 in Air Sliding 5th Wheel, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Usage: 1,015,854 Mi FROM THE YARD BY JANUARY 10TH AND Notes: INOPERABLE ITEM MUST BE REMOVED CANNOT BE RELISTED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Asset located in: Lake Worth, TX RFMOVAL 9726 2019 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) Asset located in: Lake Worth, TX S/N: 3HSDZAPR0KN110761 9723 2017 Volvo VNL670 6x4 T/A Sleeper Truck C/W: Cummins X15 6 Cylinder 15 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Tractor (Inoperable) S/N: 4V4NC9THXHN983209 Exhaust Fluid, Engine Brake, Automatic C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 10-Speed Manual Transmission, 12350 lb Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Usage: Not Available Beds, 11R22.5, Air Ride Suspension, 217 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND **CANNOT BE RELISTED** Usage: Not Available Asset located in: Lake Worth, TX Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT 9727 2019 International LT625 6x4 T/A Sleeper BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; DEFICIENCIES NOTED - PLEASE Truck Tractor (Inoperable) S/N: 3HSDZAPR5KN098185 SEE THE INSPECTION REPORT C/W: Cummins X15 6 Cylinder 15 L 450 hp Asset located in: Humble, TX Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic 2016 Volvo VNL 780 6x2 T/A Sleeper Truck 9724 Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Tractor (Inoperable) S/N: 4V4N99EH7GN950842 Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks C/W: Volvo D13 6 Cylinder 12.8 L Diesel 425 hp Engine, Requires Diésel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, Usage: Not Available 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, **Notes**: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Volvo CANNOT BE RELISTED Corporate Air Air Ride Suspension, 228 in Asset located in: Lake Worth, TX Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 9728 2019 International LT625 6x4 T/A Sleeper Usage: 826,608 Mi Truck Tractor (Inoperable) Notes: INOPERABLE ITEM MUST BE REMOVED S/N: 3HSDZAPRXKN109682 FROM YARD BY JANUARY 10TH AND CANNOT C/W: Cummins X15 6 Cylinder 15 L 450 hp BE RELISTED; BUYER'S RESPONSIBILITY FOR Engine, 2018 US EPA Label, Requires Diesel REMOVAL Exhaust Fluid, Engine Brake, Automatic Asset located in: Lake Worth, TX Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available

**Notes**: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED

#### **Details** Lot# **Details** Lot # 9729 2018 International LT625 6x4 T/A Sleeper 9732 2000 Freightliner Columbia 120 6x4 T/A **Truck Tractor (Inoperable)** Sleeper Truck Tractor (Inoperable) S/N: 1FUYSSZB1YLF32067 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel S/N: 3HSDZAPR2JN438729 C/W: Cummins X15 6 Cylinder 15.0 L 450 hp Engine, Engine Brake, Eaton Fuller 10-Speed Engine, 2017 US EPA Label, Requires Diesel Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-18913A 13-Speed Manual Transmission, 70 in High Rise Sleeper Cab, Bunk Beds, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 73 in Aluminum Outer Wheels, 295/75R22.5, Airliner High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Air Ride Suspension, 244 in Wheelbase, Air Usage: Not Available Sliding 5th Wheel, Dual Fuel Tanks Notes: INOPERABLE ITEM MUST BE REMOVED Usage: Not Available FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT REMOVAL; BE RELISTED; BUYER'S RESPONSIBILITY FOR Asset located in: Lake Worth, TX 9733 1999 Volvo VNL 6x4 T/A Sleeper Truck Tractor Asset located in: Lake Worth, TX (Inoperable) 9730 2018 International LT625 6x4 T/A Sleeper S/N: 4VG7DAJJ8XN788188 **Truck Tractor (Inoperable)** C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller FRO-16210C Manual S/N: 3HSDZTZR4JN416241 C/W: Navistar A26 6 Cylinder 13 L Diesel Transmission, 12350 lb Front Axle, 38000 lb Rears, Eaton Drive Axles, 3.7:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Engine, Requires Diesel Exhaust Fluid, 6691 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 73 in Suspension, 212 in Wheelbase, Lowboy Ramps, Dual Fuel Tanks Mid Roof Sleeper Cab, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED Super Singles Rear Tires, Hendrickson Air Ride FROM THE YARD BY JANUARY 10TH AND Suspension, 228 in Wheelbase, Air Sliding 5th **CANNOT BE RELISTED** Wheel, Dual Fuel Tanks Asset located in: Lake Worth, TX Usage: 671,789 Mi Notes: UNIT STARTS AND RUNS, ENGINE 9734 1998 Freightliner FLD 120 6x4 T/A Sleeper SEVERELY DERATED; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY Truck Tractor (Inoperable) S/N: 1FUYDDYB5WPA02987 10TH AND CANNOT BE RELISTED; BUYER'S C/W: 12000 lb Front Axle, 38000 lb Rears, RESPONSIBILITY FOR REMOVAL: 48000 lb GVWR, Air Ride Cab, 48 in Flat Top Asset located in: Lake Worth, TX Sleeper Cab, 285/75R24.5, Air Ride Suspension, 211 in Wheelbase, Dual Fuel Tanks Usage: 535,289 Mi 9731 2006 Volvo VT 880 6x4 T/A Sleeper Truck Tractor (Inoperable) **Notes**: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR S/N: 4V4LC9KL86N419522 C/W: Volvo D16D600 6 Cylinder 16.1 L Diesel 600 hp Engine, 2006 US EPA Label, Eaton REMOVAL Fuller 18-Speed Manual Transmission, 12500 Asset located in: Lake Worth, TX lb Front Axle, 38000 lb Rears, 50500 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk 9735 2011 Capacity TJ5000 4x2 Spotter Truck Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride (Inoperable) S/N: 4LMBR2118BL022572 Suspension, 256 in Wheelbase, Air Sliding 5th C/W: Cummins 6 Cylinder 6.7 L Diesel 173 hp Engine, Allison Automatic Transmission, 275 Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Notes: INOPERABLE ITEM MUST BE REMOVED 112 in Wheelbase, Hydraulic Lift 5th Wheel FROM YARD BY JANUARY 10TH AND CANNOT Usage: Not Available BE RELISTED; BUYER'S RESPONSIBILITY FOR Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY-MSO; ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO Asset located in: Lake Worth, TX INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9736	2012 Peterbilt 367 6x4 Winch Truck (Inoperable)  S/N: 1XPTD40X4CD146614  C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 15245 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 225 in Wheelbase, PTO, Tail Roll, Ramsey Winch, Lowboy Ramps Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;	9740	2010 Mack 6x4 Cab and Chassis (Inoperable) S/N: 1M2AN09C3AN006300 C/W: Mack MP8 6 Cylinder 12.8 L 425 hp Engine, 2008 US EPA Label, Engine Brake, Allison Automatic Transmission, Mack Drive Axles, Air Ride Cab, 11R24.5, Camelback Spring Suspension, 220 in Wheelbase, 130 in Cab to Axle, 180 in Cab to End of Frame Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A SALVAGE TITLE. MUST BE HAULED OFF YARD, CANNOT BE DRIVEN. TEMP TAGS WILL NOT BE ISSUED; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
-	Asset located in: Lake Worth, TX	9741	2012 Freightliner M2 106 4x2 Cab and Chassis
9737	2013 International 7600 6x4 Vacuum Excavator Truck (Inoperable) S/N: 1HTGSSJT1DJ167340 C/W: International 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, 58000 lb GVWR, 385 /65R22.5 Front Tires, 11R24.5 Rear Tires, Air Ride Suspension, 263 in Wheelbase, 58000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		(Inoperable) S/N: 1FVACWDT5CDBD9009 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 5.29:1 Axle Ratio, 10R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 90 in Cab to Axle, 139 in Cab to End of Frame Usage: 151,346 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
9738	1988 International 1954 4x2 Vacuum	9742	1999 Volvo VN 4x2 Cab and Chassis
7/30	Excavator (Inoperable)  S/N: 1HTLDTVN5JH610926  C/W: 6 Cylinder Diesel Engine, 5809 Engine hrs, Manual Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 188 in Wheelbase, PTO, Dual Fuel Tanks Usage: 326,151 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX	9/42	(Inoperable) S/N: 4VA7BBRF8XN784017 C/W: Detroit Series 60 6 Cylinder 11.1 L Diesel 365 hp Engine, 1998 US EPA Label, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Corporate Air Air Ride Suspension, 152 in Wheelbase, 89 in Cab to Axle, 121 in Cab to End of Frame, Pintle Hitch Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9739	2008 International 4400 4x2 Pressure Truck (Inoperable) S/N: 1HTMKAAN08H535972 C/W: 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 208 in Wheelbase, Dual PTO, Triplex Pump, Steel Tank Usage: Not Available Asset located in: Lake Worth, TX		REMOVAL; CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; LOCATED-IN-JUSTIN- TX; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9743	2016 Chevrolet Express G3500 4x2 Cab and	9746	2018 Ram 4500 4x2 Crew Cab Flatbed Truck
	Chassis (Inoperable) S/N: 1GB3GRCG1G1277688 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225 /75R16, Spring Suspension, 142 in Wheelbase, 81 in Cab to Axle, 139 in Cab to End of Frame Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX		(Inoperable) S/N: 3C7WRKEL5JG259100 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 9 ft 5 in x 93 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9744	2010 Mitsubishi Fuso 4x2 COE Extended Cab	07.47	Asset located in: Lake Worth, TX
	Flatbed Truck (Inoperable)  S/N: JL6CCG1S4AK009133  C/W: Mitsubishi 4 Cylinder Diesel Engine, Automatic Transmission, 6390 lb Front Axle, 12700 lb Rears, 17995 lb GVWR, 215/75R17.5, Spring Suspension, 153 in Wheelbase, 14 ft 3 in x 91 in Bed Usage: 162,766 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Humble, TX	9747	2006 Ford F-450 XL 4x2 Crew Cab Flatbed Truck (Inoperable)  S/N: 1FDXW46P46EB71060  C/W: V8 6.0 L Diesel Engine, 2008 US EPA Label, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 245 /70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft x 93 in Bed Usage: 170,254 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
9745	2020 International CV515 4x2 Crew Cab		Asset located in: Humble, TX
	Flatbed Truck (Inoperable) S/N: 1HTKSSWKXLH228328 C/W: International 6.6 L 350 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 1750 RDS 6-Speed Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 4.30:1 Axle Ratio, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 175 in Wheelbase, 9 ft 6 in x 96 in Bed Usage: 49,405 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX  1998 International 4900 6x4 Flatbed Truck	9748	2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3HT7KEC83810 C/W: Ford Power Stroke V8 6.7 L Diesel 330 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 2 in x 92 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9745A	(Inoperable)	9749	2018 Ford F-250 XL 4x4 Crew Cab Flatbed
	S/N: 1HTSHAAR5WH533334 C/W: 6 Cylinder Diesel Engine, International 6- Speed Manual Transmission, 11R22.5, Hendrickson RT/RTE Series Spring over Walking Beam Suspension, 226 in Wheelbase, 23 ft x 94 in Bed, Dovetail, Hydraulic Ramps Usage: 58,070 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		Truck (Inoperable) S/N: 1FT7W2BT4JEB73055 C/W: V8 6.7 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 6340 lb Rears, 10000 lb GVWR, 33X12. 50R18, Spring Suspension, 176 in Wheelbase, 8 ft 6 in x 80 in Bed, Fuel Tank /w Pump Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9750	2007 Ford F-550 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FDAW56PX7EA92103 C/W: Automatic Transmission, 6500 lb Front Axle, 13660 lb Rears, 17950 lb GVWR, 225- 70R19.5, Spring Suspension, 12 ft Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9753	2015 Freightliner 114SD 6x4 Mixer Truck (Inoperable)  S/N: 1FVHG3DV3FHGC6645  C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17826 Engine hrs, Engine Brake, Allison 4000 Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Suspension, 230 in Wheelbase, Beck 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: 208,567 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM  Asset located in: Lake Worth, TX
9751	2017 GMC 3500 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1GT42VCY6HF232993 C/W: V8 Diesel Engine, Automatic Transmission, 5600 lb Front Axle, 7050 lb Rears, 11600 lb GVWR, 275/65R18, Spring Suspension, 166 in Wheelbase, 8 ft 6 in x 80 in Bed Usage: Not Available		
	Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		2015 Freightliner 114 SD 6x4 Mixer Truck (Inoperable) S/N: 1FVHG3DV7FHGD3310 C/W: Detroit 6 Cylinder 12.8 L Ultra Low Sulfu Diesel Engine, Requires Diesel Exhaust Fluid,
9751A	2001 Peterbilt 379 Car Carrier Truck (Inoperable) S/N: 1NP5DB9X81N539761 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, 425/65R22.5, Double Frame, Rubber over Walking Beam Suspension, 229 in Wheelbase, PTO, Beck 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM
9752	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck (Inoperable) S/N: 1HTMMMMN6HH474540 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8160 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 198 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 55,091 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9755	Asset located in: Lake Worth, TX  1999 Peterbilt 357 8x4 Mixer Truck (Inoperable) S/N: 1NPALTOX7XD494329 C/W: Cat C10 6 Cylinder Ultra Low Sulfur Diesel Engine, 21033 Engine hrs, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 53200 lb Rears, 60000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Trailing Tag Axle, Hendrickson Walking Beam Suspension, 250 in Wheelbase, PTO, McNeilus 10.5 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 212,655 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX

#### **Details** Lot# **Details** Lot # 9756 2019 International 4300 4x2 Rollback Truck 9760 2021 Ford 4x2 Step Van (Inoperable) (Inoperable) S/N: 1F66F5KN2M0A15011 C/W: V8 7.3 L Gasoline Engine, 2021 US EPA S/N: 3HAEUMML5KL556456 Label, Automatic Transmission, 8000 lb Front C/W: Cummins B 6 Cylinder 6.7 L 300 hp Axle, 15000 lb Rears, 22000 lb GVWR, 225 Engine, 2018 US EPA Label, Requires Diesel /70R19.5 Front Tires, 225/70R19.5 Rear Tires. Exhaust Fluid, 7063 Engine hrs, Allison Spring Suspension, 210 in Wheelbase, 22 ft x Automatic Transmission, 8000 lb Front Axle, 102 in Wide x 87 in High Body 19000 lb Rears, 26000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 255/70R22.5, Air Ride Usage: Not Available Suspension, 210 in Wheelbase, PTO, Miller **Notes**: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT Rollback Body, 19 ft 4 in x 102 in Bed, Ramsey HD234 8000 lb Winch BE RELISTED; BUYER'S RESPONSIBILITY FOR Usage: 142,777 Mi REMOVAL Notes: INOPERABLE ITEM MUST BE REMOVED Asset located in: Lake Worth, TX FROM YARD BY JANUARY 10TH AND CANNOT 9761 2021 Ford F59 4x2 Step Van (Inoperable) BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL: S/N: 1F66F5KN4M0A15012 C/W: 7.3 L Gasoline Engine, 2021 US EPA Asset located in: Lake Worth, TX Label, Automatic Transmission, 8000 lb Front 9757 2016 International 4300 4x2 Van Truck Axle, 15000 lb Rears, 22000 lb GVWR, 225 /70R19.5 Front Tires, 245/70R19.5 Rear Tires, (Inoperable) Spring Suspension, 210 in Wheelbase, 22 ft x 102 in Wide x 87 in High Body S/N: 1HTMNAAL1GH031595 C/W: Navistar 6 Cylinder Engine, 2016 US EPA Usage: Not Available Label, Automatic Transmission, 9000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 8002 Engine hrs, 11R22.5, Spring Suspension, 254 in Wheelbase, 24 ft x 96 in Wide x 97 in High Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR Body, Curbside Door, Liftgate REMOVAL Usage: 149,593 Mi Asset located in: Lake Worth, TX Notes: INOPERABLE ITEM MUST BE REMOVED 9761A 2006 MCI J4500 6x2 56-Seat Coach FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED. BUYER'S RESPONSIBILITY FOR (Inoperable) REMOVAL OF THIS ITEM S/N: 2M93JMPA76W063464 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit 6 Cylinder Diesel Engine, Asset located in: Lake Worth, TX 9758 2012 Isuzu NPR 4x2 COE Van Truck Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 362 in Wheelbase (Inoperable) Usage: Not Available S/N: JALE5W163C7301062 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT 210 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, BE RELISTED; BUYER'S RESPONSIBILITY FOR 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 177 REMOVAL Asset located in: Humble, TX in Wheelbase, Morgan 18 ft x 96 in Wide x 85 in High Body, Curbside Door, Liftgate 9761B 2006 MCI J4500 6x2 56-Seat Coach Usage: Not Available (Inoperable) S/N: 2M93JMPA46W063454 Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT C/W: Air Conditioner, Automatic Transmission, BE RELISTED; BUYER'S RESPONSIBILITY FOR Lavatory, Detroit 6 Cylinder Diesel Engine, 315 /80R22.5, Air Ride Suspension, 363 in Wheelbase Asset located in: Lake Worth, TX Usage: Not Available 9759 2020 GMC G3500 4x2 Van Truck (Inoperable) Notes: INOPERABLE ITEM MUST BE REMOVED S/N: 7GZ37TCG1LN010503 FROM YARD BY JANUARY 10TH AND CANNOT C/W: GM V8 6.0 L Gasoline Engine, 2020 US BE RELISTED; BUYER'S RESPONSIBILITY FOR EPA Label, Automatic Transmission, 4300 lb REMOVAL Front Axle, 8600 lb Rears, 12300 lb GVWR, 225 Asset located in: Humble, TX /75R16, Spring Suspension, 178 in Wheelbase, 17 ft x 96 in Wide x 76 in High Body, Curbside Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9761C	2006 MCI J4500 6x2 56-Seat Coach (Inoperable)  S/N: 2M93JMPA26W063548  C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Humble, TX	9762B	2005 MCI J4500 6x2 56-Seat Coach (Inoperable)  S/N: 2M93JMDA65W063118  C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Humble, TX
9761D	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPA06W063547 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Detroit 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9763	2018 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYAP8X5JJ207624 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11R22.5, Air Ride Suspension, EQUIPMENT-FROM-YELLOW-CORP Usage: 490,446 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX
9762	2016 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XPBA48X4GD339490 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21678.6 Engine hrs, Engine Brake, Eaton Cummins UltraShift Plus Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 862,236 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX	9764	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYA48X2EJ355427 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 400 hp Engine, 2019 US EPA Label, 16235 Engine hrs, Eaton Fuller FM-15E310B-LAS Automated Transmission, 12700 lb Front Axle, 22700 lb Rears, Dana S23-190 Drive Axles, 2.53: 1 Axle Ratio, 34700 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 4-Bag Air Ride Suspension, 155 in Wheelbase, Air Sliding 5th Wheel Usage: 723,788 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
9762A	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA45W062954 C/W: Air Conditioner, Automatic Transmission, Wheelchair Lift, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5, Air Ride Suspension, 363 in Wheelbase Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX	9764A	Asset located in: Lake Worth, TX  2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGDD55FLGB0203 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT

Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL

Lot #	Details	Lot #	Details
9764B	Cab Truck Tractor (Inoperable) S/N: 3AKBGDDV3ESFV6407 C/W: Detroit DD13 6 Cylinder 12.8 L Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 15959 Engine hrs, Engine Brake, Eaton Fuller FRO-14210C 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 542,172 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL	9767	2009 International TranStar 8600 4x2 S/A Day Cab Truck Tractor (Inoperable)  S/N: 1HSHWAHN59J674277  C/W: Cummins ISM 6 Cylinder 10.8 L Diesel Engine, 24234 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 151 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 615,671 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9768	2005 International 9400i 4x2 S/A Day Cab
9765			Truck Tractor (Inoperable)  S/N: 3HSCPSBN35N049230  C/W: Cat 6 Cylinder Engine, Eaton Fuller Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL
			Asset located in: Lake Worth, TX
		9769	·
9766	2015 Freightliner M2 112 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBC5CY4FHGK0774 C/W: Cummins ISL9 Diesel 330 hp Engine, Eaton Fuller FO-10E310C-VAS Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-160 Drive Axles, 4.56:1 Axle Ratio, 34700 lb GVWR, 295/75R22.5, 158 in Wheelbase, Air Sliding 5th Wheel		
	Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM THE YARD BY JANUARY 10TH AND CANNOT BE RELISTED Asset located in: Lake Worth, TX	9770	2019 Chevrolet 2500 LT 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KSEY4KF120067 C/W: 6.6 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, 275/70R18 Tires, 7 ft 11 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9771	2019 Chevrolet 2500 4x4 Crew Cab Pickup (Inoperable)  S/N: 1GC1KSEY4KF119050  C/W: 6.6 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Fuel Tank, 10000 lb GVWR, 265/70R17 Tires, 4 ft 11 in Bed Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX	9776  9777A	2014 Ford F-250 XL 4x2 Crew Cab Pickup (Inoperable)  S/N: 1FT7W2A63EEB14161  C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 265 /70R17 Tires, 6 ft 8 in Bed Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH
9772	2019 Ford F-250 XL 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2BT9KEE68282		AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX
	C/W: Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, RKI Tool Box, Drop-In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS  Asset located in: Lake Worth, TX		2013 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GC1KVCG2DF243378 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 9500 lb GVWR, 285/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9773	2017 Ford F-250 4x4 Crew Cab Pickup (Inoperable)  S/N: 1FT7W2B65HEF24902  C/W: 6.7 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Power Windows, Weather Guard Fuel Tank /w Pump, Tool Box, 10000 lb GVWR, 285/70R17 Tires, 6 ft 10 in Bed Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX  2015 GMC 2500 4x4 Crew Cab Pickup (Inoperable)  S/N: 1GT12XE87FF109762  C/W: 6.6 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: Not Available  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX		PROCESS TITLE; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;
			Asset located in: Lake Worth, TX  2011 GMC Sierra 2500HD 4x4 Extended Cab Pickup (Inoperable)  S/N: 1GT22ZCG7BZ412902  C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Tool Box, Spray-On Bed Liner, 9500 lb GVWR, 245/75R17 Tires, 6 ft 6 in Bed Usage: 154,930 Hr Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9774			REMOVAL;  Asset located in: Lake Worth, TX
		9777B	(Inoperable) S/N: 1FTFW1EF8BKD94995 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7200 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 221,657 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;

Lot #	Details	Lot #	Details
9778 9778A	2014 Ford F-150 XLT 4x2 Extended Cab Pickup (Inoperable)  S/N: 1FTEX1CM5EKG46930  C/W: 3.7 L V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, UWS Tool Box, 6700 lb GVWR, 265/70R17 Tires, 6 ft 5 in Bed Usage: 177,206 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL;  Asset located in: Lake Worth, TX  2012 Chevrolet 1500 4x2 Extended Cab Pickup (Inoperable)	9781	2021 Ford Ranger XL 4x2 Extended Cab Pickup (Inoperable)  S/N: 1FTER1EH0MLD55223  C/W: 2.3 L 4 Cylinder Gasoline Engine, 2021 US  EPA Label, Automatic Transmission, Air  Conditioner, Power Windows, Headache Rack, Northern Tool Equipment Tool Box, 255/70R16  Tires, 6 ft Bed  Usage: 32,412 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED  FROM YARD BY JANUARY 10TH AND CANNOT  BE RELISTED; BUYER'S RESPONSIBILITY FOR  REMOVAL; TEXAS BUYERS MUST STOP IN  OFFICE TO SIGN REQUIRED DOCUMENTS TO  PROCESS TITLE
	S/N: 1GCRCPE00CZ144809 Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX  2015 Chevrolet Spark Automobile (Inoperable) S/N: KL8CD6S93FC709764 C/W: 4 cyl 1.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 94,644 Mi
9779	1994 Dodge Ram 2500 4x2 Pickup (Inoperable) S/N: 1B7KC26C5RS655611 C/W: 5.9 L 6 Cylinder Diesel Engine, 5 Speed Manual Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 245/75R16 Tires, 8 ft Bed, EQUIPMENT-FROM-YELLOW-CORP Usage: 184,458 Mi Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX		Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL  Asset located in: Humble, TX  2017 Jaguar F-Pace AWD SUV (Inoperable) S/N: SADCJ2BN8HA089275 C/W: 4 cyl 2.0 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 77,696 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX  1995 Fontaine 352J 70000 lb T/A Heavy-Haul Jeep (Inoperable) S/N: 4LF3N2625S3503582 C/W: Sliding 5th Wheel, Air Ride Suspension, 275/70R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Lake Worth, TX
9779A	2011 Chevrolet Silverado 1500 4x2 Extended Cab Pickup (Inoperable) S/N: 1GCRCPE04BZ255670 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Headache Rack, RKI Tool Box, 6800 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR		
9780	REMOVAL  Asset located in: Lake Worth, TX  1997 Ford F-150 XL 4x4 Pickup (Inoperable)  S/N: 1FTDF1823VNC21842  C/W: 4.2 L V6 Gasoline Engine, Automatic  Transmission, Air Conditioner, 6000 lb GVWR, 255/70R16 Tires, 8 ft Bed, EQUIPMENT-FROM-YELLOW-CORP  Usage: 191,594 Mi  Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE;		

Lot #	Details	Lot #	Details
9786	2005 Wilson 42 ft T/A Belly Dump Grain Trailer (Inoperable) S/N: 1W1MCF1A35B240910 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 2 Hoppers, Manual Traps, 9 ft Aluminum Box, 72 in, Side Walls, Manual Roll Tarp, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9790	Cat Engine S/N: Not Available C/W: Cat 3116 6 Cylinder 6.6 L Diesel Engine, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX  Quantity of (2) Electric Motor S/N: Not Available C/W: EQUIPMENT-FROM-US-AUTO-RECYCLING
9787	2015 Wabash RFALHSA 53 ft T/A Refrigerated		Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	Trailer (Inoperable) S/N: 1JJV532B4FL840000 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 10TH AND CANNOT	9792	Quantity of (2) Electric Motor S/N: Not Available C/W: Electrico, Sew-Eurodrive; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9793	Quantity of Electric Motor  S/N: Not Available C/W: Assorted Size, One Pallet; EQUIPMENT-FROM-US-AUTO-RECYCLING Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9794	2005 McElroy Roller Fusion Machine
9788	2013 Great Dane 48 ft x 96 in T/A Refrigerated Trailer (Inoperable)  S/N: 1GRAA9625DB711787  C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Swing Door, Carrier Transcd Refrigeration Unit, Serial Number JAV90746822,, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available  Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE  Asset located in: Lake Worth, TX	9/94	(Inoperable) S/N: C11420 C/W: 8 in Clamp SIze, Pipe Cutter Usage: 606 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 3RD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lahoma, OK
9788A	2016 Lucon T-125 S/A (1) Reel Trailer	9795	McElroy Roller Fusion Machine
	(Inoperable) S/N: 1L9PU1012GG423949 C/W: 225/75R15 Tires, 4260 lb GVWR, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY; INOPERABLE ITEM MUST BE	3,30	S/N: C14830 C/W: 8 in Clamp Slze, Pipe Cutter Usage: 352 Hr Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK
	REMOVED FROM YARD BY JANUARY 10TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX	9796	McElroy PitBull 412 Tracked Fusion Machine S/N: C15330 C/W: 13 in Clamp SIze, On-Board Generator, Pice Standa Kuhata P.723.3 Cylinder 14.0 kW
9789	2014 Sauber 1570-B Hydraulic Cable Puller and Tensioner  S/N: 1F9UZ1310EV048032  C/W: 2013 US EPA Label, Honda 1 Cylinder .68  L Gasoline Engine  Usage: Not Available  Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO  PROCESS TITLE  Asset located in: Lake Worth, TX		Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 2,119 Hr  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9797	McElroy PitBull 618 Tracked Fusion Machine S/N: C29981 C/W: 18 in Clamp SIze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 397 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Lahoma, OK	9806	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
		9807	Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
9798	McElroy PitBull 412 Tracked Fusion Machine S/N: C22603 C/W: 13 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW Diesel Engine, 7 in Rubber Tracks Usage: Not Available	9808	Blowout Preventer  S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
9799	Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK  McElroy PitBull 618 Tracked Fusion Machine	9809	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	S/N: C32754 C/W: 18 in Clamp Slze, On-Board Generator, Pipe Stands, Kubota D722 3 Cylinder 14.9 kW 719 cc Diesel Engine, 7 in Rubber Tracks Usage: 444 Hr Notes: ITEM AT OFFSITE LOCATION MUST BE	9810	Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
9800	PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK  Quantity of Tongs  S/N: Not Available		Regan Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA
	C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available  Asset located in: Cedar Bluff, VA	9812	Torus Blowout Preventer S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-IN Usage: Not Available Asset located in: Cedar Bluff, VA
9801	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC		
	Usage: Not Available  Asset located in: Cedar Bluff, VA	9813	
9802	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC	0014	Usage: Not Available  Asset located in: Cedar Bluff, VA
	Usage: Not Available Asset located in: Cedar Bluff, VA	9814	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks
9803	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
9804	Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9805	Asset located in: Cedar Bluff, VA  Quantity of Tongs S/N: Not Available C/W: EQUIPMENT-FROM-GASCO-DRILLING-INC Usage: Not Available Asset located in: Cedar Bluff, VA		

Lot #	Details	Lot #	Details
9815	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9820	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9816	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9821	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9817	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9822	Quantity of Sioux S195667 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9818	Quantity of Sioux S195667 Pipe Stands	9823	Quantity of Sioux S195667 Pipe Stands
	S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK		S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
9819	Quantity of Sioux S195667 Pipe Stands	9824	Quantity of Sioux S15813 Pipe Stands
	S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK		S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9825	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9830	Quantity of Sioux \$180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9826	Quantity of Sioux S15813 Pipe Stands S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9831	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	9832	Asset located in: Lahoma, OK
9827	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	3002	Quantity of Sioux \$180201 Pipe Stands  S/N: Not Available  C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE  Asset located in: Lahoma, OK
9828	Quantity of Sioux S180201 Pipe Stands	9833	Quantity of Sioux S180201 Pipe Stands
	S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK		S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
9829	Quantity of Sioux S180201 Pipe Stands	9834	Quantity of Sioux S180201 Pipe Stands
	S/N: Not Available C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK		S/N: Not Available C/W: 3 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9835	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;	9840	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	20.44	Asset located in: Lahoma, OK
9836	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available	9841	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available
	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	Asset located in: Lahoma, OK	1	Asset located in: Lahoma, OK
9837	Quantity of Sioux \$180201 Pipe Stands  S/N: Not Available  C/W: 4 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE	9842	Quantity of Pipe Stands  S/N: Not Available  C/W: 6 Stacks Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE
	Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
9838	Quantity of Sioux S180201 Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9843	Quantity of Pipe Stands S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9839	Quantity of Sioux S15813 Pipe Stands	9844	Quantity of Pipe Stands
	S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		S/N: Not Available C/W: 6 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9846 Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: TEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available C/W: 48 in: x 6 in: x 4 in. Usage: Not Availa	Lot #	Details	Lot #	Details
AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9846 Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available C/W: 6 Stacks Usage: Not Available C/W: 8 In x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48	9845	S/N: Not Available C/W: 2 Stacks Usage: Not Available <b>Notes</b> : ITEMS AT OFFSITE LOCATION MUST	9850	S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available <b>Notes</b> : ITEMS AT OFFSITE LOCATION MUST
9846 Quantity of Pipe Stands S/N: Not Available C/W: 4 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE ASSET LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE ASSET LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE A		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 48 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  8847  Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9852  Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848  Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849  Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849  Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Available C/W: 48 in x 6 in x 4 in. Usage: Not Avai		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE ASSET located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE ASSET located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Avail	9846	S/N: Not Available C/W: 4 Stacks	9851	S/N: Not Available C/W: 48 in x 6 in x 4 in
9847 Quantity of Pipe Stands S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS BE PICKED UP W		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 5 Stacks Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  NOTE BE ABLE TO ASSIST WITH LOADING THESE  NOTE BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9848 Quantity of (700) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE ASSET located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. Usage: Not Available C/W: 48 in. x 6 in. Usage:	9847	S/N: Not Available C/W: 5 Stacks	9852	S/N: Not Available C/W: 48 in. x 6 in. x 4 in.
9848 Quantity of (700) Pipeline Skids  S/N: Not Available  C/W: 48 in. x 6 in. x 4 in. Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  NOT BE ABLE TO ASSIST WITH LOADING THESE  REPORT O 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  ROUTH OF (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available ROUTHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR WILL BE PICKED UP WITHIN 14 DAYS AUCTION (JANU		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in.		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. Usage: Not Available C/W: 48 in x 6 in. x 4 in. U	9848	Quantity of (700) Pipeline Skids	9853	Quantity of (616) Pipeline Skids
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  9849 Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  BE PICKED UP WITHIN 14 DAYS SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		S/N: Not Available C/W: 48 in. x 6 in. x 4 in.		S/N: Not Available C/W: 48 in. x 6 in. x 4 in.
9849 Quantity of (616) Pipeline Skids  S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  9854 Quantity of (610) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCA BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCA BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOAD NOT BE ABLE TO ASSIST WITH LOADING THESE		Asset located in: Lahoma, OK		Asset located in: Lahoma, OK
BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  BE PICKED UP WITHIN 14 DAYS AUCTION (JANUARY 3RD) OR W SUBJECT TO 3RD PARTY STORA BUYER RESPONSIBLE FOR LOAD NOT BE ABLE TO ASSIST WITH L	9849	S/N: Not Available C/W: 48 in. x 6 in. x 4 in. Usage: Not Available	9854	S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available
Asset located in: Lahoma, OK Asset located in: Lahoma, OK		BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
· ·				Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9855	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in, There are some 4x4 in mixed in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9860	Pipeline Cradle S/N: Not Available C/W: Double Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9856	Quantity of (600) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	-9861	Pipeline Cradle S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lahoma, OK	9862	Pipeline Cradle
9857	Quantity of (580) Pipeline Skids  S/N: Not Available  C/W: 48 in x 6 in x 4 in  Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE  Asset located in: Lahoma, OK		S/N: Not Available C/W: Single Head, Single Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9858	Quantity of (616) Pipeline Skids S/N: Not Available C/W: 48 in x 6 in x 4 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9863	Pipeline Cradle  S/N: Not Available  C/W: Single Head, Double Roller  Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE  Asset located in: Lahoma, OK
9859	Quantity of (10) Approximately 16 ft x 4 ft Skids (10) Stacks & Misc Pieces Pipeline Skids S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	-9864	Darby Pipeline Cradle  S/N: Not Available C/W: Single Head, Double Rollers Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9865	DMH RO Pipeline Cradle S/N: 485 C/W: Single Head, Double Rollers Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9870	Mathey Dearman 12 in Beveling Machine S/N: CE106814 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9866	2013 Mcclain 28 Ft T/A Mobile Flare S/N: 4LYUS2223DH000570 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, (2) Tool Boxes, EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: Not Available Asset located in: Lake Worth, TX	-9871	Coating & Brushes S/N: Not Available C/W: Part A & B Coating Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WIL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9866A	Quantity of Assorted Drill Bit S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		
9867	Asset located in: Lake Worth, TX  2009 MacElroy LT0048 T/A Hydraulic Line Tamer  S/N: C30327  C/W: To Fit McElroy Manufacturing, Inc LineTamer poly pipe straightener, 2002 US EPA Label, Honda GXV160 1 Cylinder 163 cc Gasoline Engine Usage: Not Available  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE	9872	Quantity of (102) Rolls of PipelineRock Guard Mesh S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
9868	SUBJECT TO 3RD PARTY STORAGE FEES  Asset located in: Lahoma, OK  Quantity of (3) Vaculifter  S/N: LT30-000101  C/W: To Fit lift technology LT36 pipe vac lift, Tier 1, 2012 US EPA Label, Hatz CHZXL	9873	Sand Silo S/N: Not Available C/W: Seller Supplied Info: Approximate dimensions 8ft x 20ft. Buyer responsible for load-out and transport. Usage: Not Available Asset located in: Midland, TX
	445V42 1 Cylinder 6.4 kW .44 L Diesel Engine Usage: 1,278 Hr  Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES .  Asset located in: Lahoma, OK	9874	Quantity of (4) 15 Ft Pipe Cartridges S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
9869	Mathey Dearman 20 in Pipe Beveling Machine S/N: M68048 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9875	Quantity of (3) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 All Terrain S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX
		9876	Quantity of (2) 10 ft Pipe Cartridges - Fits Ditch Wtich JT30 & JT3020 S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9877	Quantity of (2) 10 Ft Pipe Cartridges - Fits Ditch Witch JT3020 Mach I S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (3) Pipe Elevators S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Lake Worth, TX	9884	Quantity of (8) Foam Pigs  S/N: Not Available  C/W: (7) 16 in, (1) 18 in  Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING
9879	Pipe Elevator		THESE  Asset located in: Lahoma, OK
	S/N: Not Available Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	9885	Quantity of (2) Pipeline Cleaners Plate Sizing Pigs
9880	Quantity of (15) 10 in Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		S/N: H582, P615 C/W: (1) 16 in, (1) 10 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	Asset located in: Lahoma, OK	9886	Quantity of (7) Stringing Cables
9881	Quantity of (20) Crates of 8 in Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE		S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9882	Asset located in: Lahoma, OK  Quantity of (13) Assorted Pigs S/N: Not Available C/W: (8) 8 in Bull nose, (1) 8 in Brush, (1) 8 in Bidirectional, (1) 10 in Bidirectional Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	9887	Quantity of (12) Boxes of Tape & Primer S/N: Not Available C/W: 3M Tape, RD-6 Tape & Primer Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	THESE	9888	Quantity of Wax Tape, Primer
9883	Asset located in: Lahoma, OK  Quantity of 8 In Foam Pigs S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9889	Quantity of Assorted Night Caps S/N: Not Available C/W: 4 in - 16 in gg Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9894	Quantity of Dies - Fits Poly Pipe Welding Machine  S/N: Not Available C/W: 4 in, 6 in, 8 in Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
9890	Quantity of (2) Rock Shield  S/N: Not Available C/W: (1) 36 in, (1-60) in Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	9895	Quantity of Dies - Fits McElroy 618 Poly Pipe Welding Machine S/N: Not Available C/W: 16 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
9891	Quantity of (6) Felt Lined Rock Shield  S/N: Not Available C/W: (5) 60 in, (1) 36 in Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK  Quantity of Dies	9896	Asset located in: Lahoma, OK  Quantity of Dies - Fits Poly Pipe Welding Machine  S/N: Not Available C/W: To Fit McElroy 412 Dies, (4) 6 in, (4) 8 in Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (9) 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9897	Asset located in: Lahoma, OK  Quantity of Dies - Fits Poly Pipe Welding Machine  S/N: Not Available C/W: To Fit McElroy 412 Dies, 10 in, 12 in Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL
9893	Quantity of Balon Valves S/N: Not Available C/W: One Pallet Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9898	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Dies, Poly PipeWelding Machine 6 in, 8 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9902	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 28 Poly Pipe Welding Machine, 6 in., 8 in. dies Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9899	Quantity of Dies	9903	Quantity of McElroy Poly Pipe Welding
	S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, 7-8 in, 4-6 in. Incomplete Sets. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Machine Parts S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9900	Quantity of Dies	9904	Quantity of Extension Hydraulic Hoses
	S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in, (8)12 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machines Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9901	Quantity of Dies	9905	Quantity of Flange Gaskets
9901	S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Mchine, (12)10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	THESE <b>Asset located in</b> : Lahoma, OK	9906	Quantity of Dies
	Asset Iocateu III. Lalloilla, OK	I	S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Mchine, (8) 16 in., (8) 12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9907	Heater - Fits S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9912	Bending Shoe S/N: Not Available C/W: 10 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9908	Quantity of Dies S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, (4) 2 in., (4) 3 in., (7) 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9913	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9909	McElroy 848701 Electric Heater S/N: Not Available Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	-9914	Quantity of (2) Roller Stands  S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK
9910	Quantity of Dies  S/N: Not Available C/W: To Fit McElroy 618 Poly Pipe Welding Machine, 12 in., 16 in. Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9915	Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9911	Asset located in: Lahoma, OK  Quantity of Dies  S/N: Not Available C/W: To Fit McElroy Pitbull 14 Poly Pipe Welding Machine, 2 in., 3 in., 4 in. Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	9916	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9917	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9922	Bending Shoe Bucket S/N: Not Available C/W: 4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
9918	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	<b>-</b> 9923	Bending Shoe Bucket S/N: 015M C/W: 6 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
	Asset located in: Lahoma, OK	9924	Bending Shoe Bucket	
9919	Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8) 6 in, (8) 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATIO BE PICKED UP WITHIN 14 DAYS OF AUCTION (JANUARY 3RD) OR WILL SUBJECT TO 3RD PARTY STORAGE BUYER RESPONSIBLE FOR LOADOU	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
	THESE	9925	Remco Bending Shoe	
9920	Asset located in: Lahoma, OK  Quantity of Dies S/N: Not Available C/W: To Fit McElroy 412 Poly Pipe Welding Machine, (8)10 in., (8)12 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		C/W: 8 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOG BE PICKED UP WITHIN 14 DAY AUCTION (JANUARY 3RD) OR SUBJECT TO 3RD PARTY STO BUYER RESPONSIBLE FOR LO NOT BE ABLE TO ASSIST WIT THESE Asset located in: Lahoma, OK  9926 Quantity of (2) Roller Stands S/N: Not Available	Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK  Quantity of (2) Roller Stands S/N: Not Available C/W: To Fit Poly Pipe
9921	Quantity of (2) Bending Shoe	1	Usage: Not Available	
	S/N: 3040918 C/W: (1) 8 in., (1) 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9927	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9931	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9928	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9932	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9929	McElroy Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 6-18 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9933	McElroy 1242112 Heater S/N: Not Available C/W: To Fit McElroy Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
9930	MMI Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9934	McElroy 1242112 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 4-12 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details	
9935	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9940	Quantity of McElroy Pitt Bull 14 Hot Plate, Facer S/N: C147848 C/W: 1-4 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	
9936	McElroy 848709 Electric Heater S/N: Not Available C/W: To Fit Poly Pipe Welding Machine, 2-8 Heater Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	-9941	Quantity of (5) Calipers  S/N: 29897, 52770  C/W: 6 in.  Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST  BE PICKED UP WITHIN 14 DAYS OF THE  AUCTION (JANUARY 3RD) OR WILL BE  SUBJECT TO 3RD PARTY STORAGE FEES;  BUYER RESPONSIBLE FOR LOADOUT. RB WILL  NOT BE ABLE TO ASSIST WITH LOADING  THESE  Asset located in: Lahoma, OK	
	Asset located in: Lahoma, OK	9942	Quantity of (5) Calipers	
9937	Rigid BF86C Electric Tie In Machine S/N: 086C03820A46 C/W: To Fit Poly Pipe Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE	9943	S/N: 55693, 1708, 51799, 56642. 77426 C/W: 12 in. Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK  Quantity of (4) Calipers	
	Asset located in: Lahoma, OK	-	S/N: 43635	
9938	Mustang DBG60 Polyethylene Pipe Squeeze Tool  S/N: Not Available C/W: To Fit Poly Pipe, 4 in & 6 in Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING		Usage: Not Available  Notes: ITEMS AT OFFSITE LO BE PICKED UP WITHIN 14 DA AUCTION (JANUARY 3RD) O SUBJECT TO 3RD PARTY ST BUYER RESPONSIBLE FOR L NOT BE ABLE TO ASSIST WI THESE Asset located in: Lahoma, OR	Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	THESE  Asset located in: Lahoma, OK	9944	<b>Quantity of (3) Calipers</b> S/N: 84426, 82563, 84437	
9939	Quantity of McElroy Pitt Bull 14 Electric Facer S/N: C20800 C/W: Hester not included Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		C/W: 16 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	

Lot #	Details	Lot #	Details
9945	Quantity of (3) Calipers S/N: 53951, 32791 C/W: 3 in. Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9953	Quantity of (4) Drill Racks S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY, (1) 16 ft, (3) 20 ft Usage: Not Available Asset located in: Lake Worth, TX  Quantity of (4) Spy Model 780 Pipeline Detectors S/N: Not Available C/W: (2) Spy Model 670 wet sponge detectors, Fisher TW-6 Pipe and cable locator
9946	Quantity of (4) Calipers  S/N: Not Available C/W: 8 in. Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK	9955	Quantity of (6) Assorted Pipeline Detectors S/N: Not Available C/W: (4) Spy Detectors, (2) Vivax Metrotech Detectors, misc parts and batteries
9947	Quantity of (2) Calipers  S/N: 57397  C/W: 4 in. Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	9956	Quantity of (4) Pipeline Recorders w/plastic tubs S/N: Not Available C/W: 150 degrees x 3000 PSI
9948	Pipe Fittings S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX		Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE
9949	Quantity of Pipelayer Equipment S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Asset located in: Corsicana, TX	9957	Asset located in: McAlester, OK  32 ft x 8 ft Mobile Test Unit  S/N: DCS489-196 Usage: Not Available Asset located in: Midland, TX
9950	Drilling Air Compressor  S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	9958	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-07 C/W: To Fit FMC Technologies FM100300 Usage: Not Available
9951	Drilling Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	9959	Asset located in: Midland, TX  2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-09
9952	Drilling Air Compressor S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX		C/W: To Fit FMC Technologies FM100300 Usage: Not Available Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9960	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-10 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Asset located in: Midland, TX	9967	Quantity of (3) Metrotech 810DX Line Locator S/N: 004314 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;
9961	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-03 C/W: To Fit FMC Technologies FM100300 Usage: Not Available	0060	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE <b>Asset located in</b> : Lahoma, OK
	Asset located in: Midland, TX	9968	Radiodetection Cat4+ Locator S/N: 10C4EN144291
9962	2015 Kaymore FM100300 Pneumatic Grease Hose Reel Skid S/N: 58240-05 C/W: To Fit FMC Technologies FM100300 Usage: Not Available Asset located in: Midland, TX		Usage: Not Available  Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE
9963	Quantity of (8) Reelcraft CA3319L Grease Hose Reel Skid		Asset located in: Lahoma, OK
	S/N: 230508-004 Usage: Not Available <b>Asset located in</b> : Midland, TX	9969	Quantity of (41) Mats S/N: Not Available Usage: Not Available
9964	Quantity of (14) Spy 780 Jeep Detector S/N: 7804998 C/W: To Fit Spy 780 Jeep Detector, 4", 6", 8", 10", 12", 16" springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
SUBJECT TO 3F BUYER RESPON NOT BE ABLE T THESE	SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING	9970	Evans HBM Horizontal Boring Machine S/N: 016 C/W: 2002 US EPA Label, Deutz BF4L913 4 Cylinder 99 hp Diesel Engine Usage: 5 Hr
9965	Quantity of (7) Spy 780 Jeep Detector S/N: 7805001 C/W: 4 in, 6 in, 8 in, 10 in, 12 in, 16 in Springs Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES;		Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK
	BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE  Asset located in: Lahoma, OK	9971	International Boring 224 Horizontal Boring Machine S/N: 1504
9966	Quantity of (4) Fisher Research Labs Gemini 3 Metal & Mineral Detector S/N: 102201652 Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK		C/W: 16 in Boring Auger, Wisconsin VH4D1A 4 Cylinder Gasoline Engine Usage: Not Available Notes: ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (JANUARY 3RD) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; BUYER RESPONSIBLE FOR LOADOUT. RB WILL NOT BE ABLE TO ASSIST WITH LOADING THESE Asset located in: Lahoma, OK

Lot #	Details	Lot #	Details
9971A	2008 Lufkin Tri/A Lowboy Trailer S/N: 1L01D513181166341 C/W: Air Ride Suspension, 28 ft Main Deck, 102 in Usable Deck Width, Pickup Throat, Tail Roller, 255/70R22.5 Tires, 90000 lb GVWR Usage: Not Available	9979	2016 John Evans 3TSLR S/A (1) Reel Trailer S/N: 1J9T112A4G0003908 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 6000 lb GVWR Usage: Not Available
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9972	2014 Dynacorp TL1280 Tri Axle HS Separator Trailer S/N: 2C9T3DFA1E3161480 C/W: 9.9 Mpa/1440psi Usage: Not Available Asset located in: Midland, TX	9980	2014 Brindle T/A (4) Reel Trailer S/N: 1L90R2626EG085221 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 21000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
9973	2013 Wyatt's Trailer Sales 24 ft T/A Spooling Trailer  S/N: 1W9GU24253L364589  C/W: 24000 lb GVWR, Spring Suspension, Electric Brakes, Deck Over Tires, Kubota Diesel Powered Self Contained Hydraulic System, 235 /80R16 Tires Usage: Not Available  Notes: RITCHIE-BROS-ENERGY Asset located in: El Reno, OK	9981	2012 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK18N3C1000066 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/75R17.5 Tires, 10000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
9974	1988 Big Tex 18 Ft T/A Gooseneck Chemical Trailer  S/N: 16VGB1622J1416669  C/W: Spring Suspension, Electric Brakes, Deck Over Tires, 235/85R16 Tires, 19400 lb GVWR, 4 Cylinder Diesel, Triplex Pump, (2) - 500 gallon tanks; EQUIPMENT-FROM-WATKINS-CONSTRUCTION Usage: 1,660 Hr	9982	2011 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK16N6B1000015 C/W: Lunette Ring Hitch, 12-16.5 Tires, 7500 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	9982A	1999 Butler S/A (1) Reel Trailer
9975	2005 C & S Trailer World Tri/A (3) Reel Trailer S/N: 44Z255LKX5T014462 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires Usage: Not Available Asset located in: Lake Worth, TX	_998ZA	S/N: 1BUC10105X1001719 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Hydraulic Reel Hoist, 245 /75R16 Tires, 8000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO
9976	<b>2012 Drake T/A (3) Reel Trailer</b> S/N: 1D9BU1410CP472777		PROCESS TITLE  Asset located in: Lake Worth, TX
	C/W: Spring Suspension, 225/75R15 Tires,	9984	1995 Redi-Haul S/A Reel Trailer
	9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE; Asset located in: Lake Worth, TX	9984	S/N: 47SZ041T5S1010806 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, Hydraulic Reel Hoist, 235/75R17.5 Tires Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
9977	2020 Pro Fabrication S/A Reel Trailer S/N: 1P9BR101XLC495135 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE Asset located in: Lake Worth, TX		TO SIGN REQUIRED DOCUMENTS TO PROCESS TITLE  Asset located in: Lake Worth, TX
		9985	1989 Sauber 1531 T/A (3) Reel Trailer S/N: 1F9RE1822KV048271 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9986	2011 Dragon 8400 gal T/A Tanker Trailer S/N: 1UNST4422BS082564 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 70000 lb GVWR Usage: Not Available Notes: .	9992	2025 X-STAR 990 gal T/A Tanker Trailer S/N: 1X9T7BA20SH039931 C/W: Ball Hitch, Spring Suspension, 235/80R16 Tires, 14000 lb GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	9993	2025 Industrias America 750 gal Trailer
9987	2011 Heil 9500 gal T/A Tanker Trailer S/N: 5HTDL4529B5H23926 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 73000 lb GVWR, Roper Hydraulic Powered Pump, 73000 lb GVWR		Mounted Fuel Tank S/N: 3EZBTT088SA003625 C/W: 12 V Transfer Pump, DEF Tank Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available	9994	2025 X-STAR 750 gal T/A Tanker Trailer
	Notes: . Asset located in: Humble, TX		S/N: 1X9T7B829SH039934 C/W: Ball Hitch, Spring Suspension, 225/75R15
9988A	2011 Stephens T/A Tanker Trailer S/N: 1S9AB15B9BH474104 C/W: 68000 lb GVWR, Air Ride Suspension,	9995	Tires, 10400 lb GVWR, Steel Tank, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available <b>Asset located in</b> : Lake Worth, TX
	11R22.5 Tires, Steel Tank Usage: Not Available		2025 X-STAR 750 gal T/A Tanker Trailer
	Asset located in: Lake Worth, TX		S/N: 1X9T7B827SH039933 C/W: Ball Hitch, 225/75R15 Tires, 10400 lb
9989	2010 Galyean 130 BBL T/A Tanker Trailer S/N: 1G9VT4020AH017248 C/W: Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, Steel Tank, 3		GVWR, Steel Tank, 1 Compartments, (1) Reels Electric Powered Pump, 10400 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Compartments, CHALLENGER Hydraulic Powered Pump Usage: Not Available Notes: . Asset located in: Humble, TX		2024 DNJ 750 T/A Tanker Trailer S/N: 1D9D7B927RH870580 C/W: Spring Suspension, Electric Brakes, 225 /75R15 Tires, 12000 lb GVWR, Steel Tank, FILL- RITE Electric Powered Pump, 12000 lb GVWR
9990	<b>2005 Polar SRJH 3800 gal T/A Tanker Trailer</b> S/N: 1PMS1452X51028313		Usage: Not Available  Asset located in: Lake Worth, TX
	C/W: Air Ride Suspension, Air Brakes, Aluminum Wheels, 445/50R22.5 Super Single Tires, 68000 lb GVWR, Insulated Stainless Steel Tank Usage: Not Available Asset located in: Livingston, LA		1998 Comptank 6250 gal Tri/A FRP Tanker Trailer S/N: 2C9LTA3C3WB075132 C/W: Spring Suspension, Lift 1st- Axles, 11R24. 5 Tires, FRP Tank, Catwalk w/Guardrails Usage: Not Available
9990A	2003 Heil 8400 gal T/A Tanker Trailer		Asset located in: Lake Worth, TX
	S/N: 5HTDL452X35G14702 C/W: Spring Suspension, 11R24.5 Tires, Stainless Steel Tank Usage: Not Available Asset located in: Lake Worth, TX	9998	1997 Trailmaster 8400 gal T/A Tanker Trailer S/N: 190DL4428V3G13006 C/W: Aluminum Frame, Spring Suspension, 11R24.5 Tires, Aluminum Tank Usage: Not Available
9991	2025 X-STAR 990 gal T/A Tanker Trailer		Asset located in: Lake Worth, TX
	S/N: 1X9T7BA22SH039932 C/W: Aluminum Frame, Ball Hitch, 235/80R16 Tires, 14000 lb GVWR, 1 Compartments, (1) Reels Electric Powered Pump, 14000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	9999	1995 Polar 4400 gal 4/Axle Tanker Trailer S/N: 1R9212339SL040301 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
10000	1973 Trim T/A Tanker Trailer S/N: K40092 C/W: Spring Suspension, Aluminum Wheels, 11R22.5 Tires, Stainless Steel Tank, Catwalk, Gasoline Powered Pump Usage: Not Available Asset located in: Lake Worth, TX	10008	3 2015 Keith Huber 5500 gal T/A Vacuum Tanker Trailer S/N: 1K9TS5522F1077001 C/W: Spring Suspension, 11R24.5 Tires, 4500 lb GVWR, Steel Tank, Catwalk w/Guardrails, Fruitland Diesel Powered Pump, 45000 lb GVWR
10001	2020 Troxell 5460 gal T/A Vacuum Tanker Trailer S/N: 1T9TA4320L1867597 C/W: Spring Suspension, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Challenger 607 Hydraulic	10000	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT. Asset located in: Humble, TX  2014 Dragon 150 BBL 6300 gal T/A Vacuum
	Blower, 50000 lb GVWR Usage: Not Available Asset located in: Humble, TX	10009	Tanker Trailer S/N: 1UNST4224ES128600 C/W: Aluminum Frame, Air Ride Suspension,
10002	2019 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4T9V6TA27KJ329225 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 63700 lb GVWR, 63700 lb GVWR Usage: Not Available		Aluminum Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Challenger 607SV Blower Usage: Not Available Notes: . Asset located in: Humble, TX
10003	Asset located in: Lake Worth, TX  2018 Southern Welding 150 bbl T/A Vacuum Tanker Trailer  S/N: 4S9V6TA25JG347005  C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available	Trail S/N: C/W Tanl Usa	2013 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST4223DL130024 C/W: Spring Suspension, 11R24.5 Tires, Steel Tank Usage: Not Available Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	10011	2012 Troxell 140 BBL 5880 gal T/A Vacuum
10004	2017 Southern 150 gal T/A Vacuum Tanker Trailer S/N: 4S9V6TA26HG347007 C/W: Air Ride Suspension, 11R24.5 Tires, 10000 lb GVWR, Aluminum Tank, 10000 lb GVWR		Tanker Trailer  S/N: 1T9TA4320C1867101  C/W: Spring Suspension, 11R24.5 Tires, 50000  Ib GVWR, Steel Tank, Catwalk w/Guardrails, 50000 Ib GVWR, 45 ft Pup  Usage: Not Available  Asset located in: Lake Worth, TX
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	10012	2011 Troxell 140 BBL 5880 gal T/A Vacuum
10005	2016 Southern 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA24GG347036 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX	Tanker Trailer  S/N: 1T9TA432XB1867783  C/W: Spring Suspension, Aluminur Wheels, 11R24.5 Tires, 50000 lb G Tank, Catwalk w/Guardrails, 50000 45 ft Pup Usage: Not Available  Asset located in: Lake Worth, TX  10013 2011 Dragon 150 bbl T/A Vacuum Trailer  S/N: 1UNST4225BL068770  C/W: Aluminum Frame, Air Ride Standinum Outer Wheels, 11R24.5 lb GVWR, Aluminum Tank, Catwalk /Guardrails	Tanker Trailer S/N: 1T9TA432XB1867783 C/W: Spring Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 50000 lb GVWR, Steel Tank, Catwalk w/Guardrails, 50000 lb GVWR, 45 ft Pup Usage: Not Available
10006	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA29GG347047 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1UNST4225BL068770 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, Catwalk w /Guardrails
10007	2016 Southern Welding 150 bbl T/A Vacuum Tanker Trailer S/N: 4S9V6TA27GG347032 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX		Usage: Not Available Notes: . Asset located in: Humble, TX

Lot #	Details	Lot #	Details
10014	2007 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST42277L063710 C/W: Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Steel Tank, Catwalk w/Guardrails Usage: Not Available Asset located in: Lake Worth, TX	10022	2001 Heil 1000 cft T/A Pneumatic Bulk Trailer S/N: 5JLSN422415T05772 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Outer Wheels, 295/75R22.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX
10015	·	10023	1998 LBT 1000 cft T/A Pneumatic Bulk Trailer S/N: 4J8B04229WT00303 C/W: Spring Suspension, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX
10016	Usage: Not Available Asset located in: Lake Worth, TX  2008 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGFT473888506205 C/W: 2 Hatches, Access Stairs, Spring Suspension, Air Brakes	10024	1996 Heil 1040 cft T/A Pneumatic Bulk Trailer S/N: 5HTSN4223T9T07318 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available  Asset located in: Lake Worth, TX	10025	1994 Heil 1600 cft T/A Pneumatic Bulk Trailer
10017	1999 VE Enterprises Flat Top S/A Frac Tank S/N: 5AGSB471XXS249824 C/W: Manifold, 1 Hatches, Access Stairs, Spring Suspension, Air Brakes Usage: Not Available		S/N: 1HLS5N8B8R9W07014 C/W: Aluminum Frame, Spring Suspension, 11R22.5 Tires, 70000 lb GVWR, Aluminum Tank, 4 Compartments, 70000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	10026	1994 Polar 1000 cft T/A Pneumatic Bulk Trailer S/N: 1PMB14225R2013531 C/W: Aluminum Frame, Air Ride Suspension,
10018	·		Air Brakes, 11R24.5 Tires, Aluminum Tank, 3 Compartments Usage: Not Available Notes: RITCHIE-BROS-ENERGY Asset located in: Lake Worth, TX
	Notes: ADDITIONAL INFORMATION AVAILABLE IN OFFICE - MSO; Asset located in: Lake Worth, TX	10027	1984 Fruehauf 1000 cft T/A Pneumatic Bulk Trailer
10019	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR27KP104096 C/W: Air Ride Suspension, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank		S/N: 1H4B04121EK004312 C/W: Aluminum Frame, Spring Suspension, Aluminum Wheels, 285/75R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Lake Worth, TX
	Usage: Not Available <b>Asset located in</b> : Lake Worth, TX	10028	2015 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer
10020	2019 Aldura 1040 cft T/A Pneumatic Bulk Trailer S/N: 3S9A6AR29KP104097 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Lake Worth, TX		S/N: 1Z9GG3228FN374020 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
10021	2012 Delu T/A Pneumatic Bulk Trailer S/N: 3BYD6TE29CH005151 C/W: Air Ride Suspension, 11R24.5 Tires, Steel Tank, 3 Compartments Usage: Not Available Asset located in: Lake Worth, TX	10029	2015 Intech 32 ft x 102 ft Portable T/A Lab Trailer S/N: 1Z9GG3228FN374017 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available Asset located in: Oklahoma City, OK

Lot #	Details	Lot #	Details
10030	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG322XFN374018 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX	10036	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer  S/N: 1Z9GG2820EN374917  C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
10031	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab	10037	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab
	Trailer S/N: 1Z9GG3226FN374016 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX		Trailer S/N: 1Z9GG2827EN374915 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: Asset located in: Midland, TX
10032	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab	10038	2014 Intech 28 ft x 102 ft Portable T/A Lab
.000_	Trailer S/N: 1Z9GG3221FN374019 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR		Trailer S/N: 1Z9GG2822EN374918 C/W: (1) Offices, Air Conditioner, Aluminum Frame, Torsion Axle, Electric Brakes, 235 /80R16 Tires, 14400 lb GVWR Usage: Not Available
	Usage: Not Available Notes: .		Asset located in: Oklahoma City, OK
	Asset located in: Midland, TX	10039	2014 Intech 28 ft x 8 ft 6 in Portable T/A Lab Trailer
10033	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer S/N: 1Z9GG3222FN374014 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available		S/N: 1Z9GG2829EN374916 C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX
	Notes: . Asset located in: Midland, TX	10040	2007 William Scotsman 52 ft x 11 ft 11 in
10034	·		Portable Tri/A Crew House S/N: 24348 C/W: To Fit SPACE MASTERS 40440 Usage: Not Available Asset located in: Lake Worth, TX
	/Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: .	95000	Kubota SUL-75 Skid Steer Loader S/N: 1034889 Usage: Not Available Asset located in: Midland, TX
	Asset located in: Midland, TX	95024	2014 Toyota 8FGCU30 5020 lb Cushion Tire
10035	2015 Intech 32 ft x 8 ft 6 in Portable T/A Lab Trailer  S/N: 1Z9GG3224FN374015  C/W: (1) Offices, Air Conditioner, Aluminum /Steel Combination Frame, Torsion Axle, Electric Brakes, 235/80R16 Tires, 14400 lb GVWR Usage: Not Available Notes: . Asset located in: Midland, TX		Forklift S/N: 60401 Usage: Not Available Asset located in: Lake Worth, TX
		95051	Moffett M5000 Placeholder Cushion Tire Forklift S/N: A05171R Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
95053	2014 Ford F-450 Pickup S/N: 1FD0W4GT0EEB80852 Usage: Not Available Asset located in: Lake Worth, TX 2015 Cat 16T 36 BU Excavator Bucket	95080	Scissor Lift S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER
	S/N: 316-36-MHJ06857 Usage: Not Available Asset located in: Lake Worth, TX		SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;  Asset located in: Lake Worth, TX
95073	smooth Bucket S/N: Not Available Usage: Not Available Asset located in: Lake Worth, TX	95081	2018 Arrow 4' Block Forks Telehandler S/N: L19846 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available
95075	Scissor Lift S/N: Not Available		Asset located in: Lake Worth, TX
	C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	95083	2016 Genie 1255567 Telescopic Boom Lift S/N: ORD FOR 135270 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD
95076	Scissor Lift		Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	95084	Scissor Lift S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
95077	Scissor Lift	95085	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX		Scissor Lift S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD;
95078	Scissor Lift		Asset located in: Lake Worth, TX
95079	S/N: Not Available C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD; Asset located in: Lake Worth, TX	95090	Pallet S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES
930/9	<b>2015 Sullair Air Compressor</b> S/N: 2015071-30056		Asset located in: Corsicana, TX
	Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95091	Pallet S/N: Not Available C/W: EQUIPMENT-FROM-WATKINS- CONSTRUCTION Usage: Not Available Notes: ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY JANUARY 3RD OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES Asset located in: Corsicana, TX

1 - 1 "	Datatle	1	Davile
Lot #	Details	Lot #	Details
95092	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95098	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95093	Asset located III. Michiester, OK	95099	Asset located III. MICAIESTEI, OK
93093	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	93099	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95094		95100	
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95095		95101	
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95096		95102	
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95097	O/NI: NI=+ A; II-lala	95103	O (NI) NI - A A II - II -
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK

Lot #	Details	Lot #	Details
95106	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95112	. S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95107	S/N: Not Available	95113	S/N: Not Available
	Usage: Not Available  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE  Asset located in: McAlester, OK		Usage: Not Available  Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95108		95116	
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95109		95117	
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK		S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK
95110	. S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE	95133	2015 JLG Telehandler S/N: 0160071104 C/W: EQUIPMENT-FROM-SUNSTATE- EQUIPMENT Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95145	1977 Pines Van Trailer S/N: 320CDV6061 C/W: EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available
95111			Asset located in: Lake Worth, TX
	S/N: Not Available Usage: Not Available Notes: LOADOUT BY APPOINTMENT ONLY; ITEM AT OFFSITE LOCATION MUST BE PICKED UP BY DECEMBER 31ST OR WILL BE	95146	2025 MaxxD D7X7212 End Dump Trailer S/N: 117643 Usage: Not Available Asset located in: Lake Worth, TX
	SUBJECT TO 3RD PARTY STORAGE FEES; FORKLIFT ASSISTANCE WILL NOT BE AVAILABLE Asset located in: McAlester, OK	95147	2025 MaxxD DTX8314 End Dump Trailer S/N: 118238 Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details
95152	1991 Belshe 20 ft T/A Utility Trailer S/N: 16JF01827M1021861 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 102 in Deck Width, 102 in Overall Width, Ramp, Steel Decking, 225/90R16 Tires Usage: Not Available Asset located in: Midland, TX
95160	1995 Talbert T/A Test Package S/N: 40FWK5239S1012196 C/W: To Fit Shop Built Pressure Test Trailer Usage: Not Available Asset located in: Midland, TX
95267	2009 Dodge Ram 1500 4x4 Pickup S/N: 1D3HV16P59J518182 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
95270	2006 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06256J612598 C/W: Spring Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Roll-Up Door, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Asset located in: Humble, TX