

Houston, TX, USA - Nov 5, 2024

Lot #	Details	Lot #	Details
1	1998 Case 570L-XT 4x4 Landscape Loader S/N: JJG0225687 C/W: Open Operator Station, 80 in Bucket, 85 in Box Blade Usage: 7,219 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	10	2016 Case 580N 4x4 Backhoe Loader S/N: JJGN580NCGC730093 C/W: Open Operator Station, Backhoe Pilot Controls, Control Pattern Changer, Requires Diesel Exhaust Fluid, Manual Coupler, 81 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 1,127 Hr
2	2015 Cat 420F2IT 4x4 Backhoe Loader		Asset located in: Humble, TX
	S/N: CAT0420FVHWD00240 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 5,953 Hr Asset located in: Humble, TX	11	2014 Case 580N 4x4 Backhoe Loader S/N: JJGN580NLEC700996 C/W: Open Operator Station, Backhoe Pilot Controls, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 3,549 Hr Notes: LOCATED-IN-FORT-WORTH-TX
3	2011 Cat 420E 4x4 Backhoe Loader	-	Asset located in: Lake Worth, TX
5	S/N: CAT0420ETDJL01215 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, 94 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,834 Hr Asset located in: Humble, TX	12	2014 Case 580SN 4x4 Backhoe Loader S/N: JJGN58SNEFC720697 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 82 in Multi-Purpose Loader Bucket, Quick Coupler, 12 in Backhoe Digging Bucket, 24 in Bucket, Rear Auxiliary Hydraulics
4	2010 Cat 420E IT 4x4 Backhoe Loader	1	Usage: 2,509 Hr
	S/N: CAT0420EVDAN00286 C/W: Open Operator Station, Control Pattern Changer, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Extendable Stick,		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
	24 in Backhoe Digging Bucket Usage: 3,006 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	14	2011 John Deere 310J 4x4 Backhoe Loader S/N: 1T0310JKBD203454 C/W: Enclosed Cab, Air Conditioner, 86 in Loader Bucket, 36 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 3,855 Hr
6	2010 Case 590SM 4x4 Backhoe Loader		Asset located in: Humble, TX
	S/N: JJGN590PHAC532537 C/W: Open Operator Station, Ride Control, Backhoe Pilot Controls, 92 in Multi-Purpose Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	16	2012 Volvo BL60B 4x4 Backhoe Loader S/N: VCE0B60BP02121355 C/W: Open Operator Station, Manual Coupler, 87 in Loader Bucket, 22 in Backhoe Cleanup Bucket, Hydraulic Hammer Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7	2019 JCB 3CX 4x4 Backhoe Loader	19	2007 Cat 416E 4x4 Backhoe Loader
-	S/N: 2823018 C/W: Open Operator Station, Auxiliary Hydraulics, 87 in Loader Bucket, 12 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 2,228 Hr Notes : LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Lake Worth, TX		S/N: CAT0416ELSHA03427 C/W: Open Operator Station, 88 in Loader Bucket, Quick Coupler, 22 in Backhoe Digging Bucket Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details	
21	2008 John Deere 310J 4x4 Backhoe Loader S/N: T0310JX163704 C/W: Open Operator Station, 86 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Asset located in: Humble, TX	31A	Case 580 Super E 4x2 Backhoe Loader S/N: 9076692 C/W: Open Operator Station, Backhoe Pilot Controls, Manual Coupler, 81 in Loader Bucket, 23 in Backhoe, Manual Thumb Usage: 3,493 Hr Asset located in: Humble, TX	
22	2007 John Deere 310G 4x4 Backhoe Loader S/N: T0310GX962137 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	31	2006 Case 580M Series 2 4x2 Backhoe Loader S/N: N6C400616 C/W: Open Operator Station, 81 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 3,423 Hr Asset located in: Humble, TX	
	THE INSPECTION REPORT Asset located in: Humble, TX	33	2021 Komatsu WA600-8 Wheel Loader	
25A	1992 Cat 416 4x2 Backhoe Loader S/N: 5PC15031 C/W: Open Operator Station, 89 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,526 Hr Asset located in : Humble, TX		Camera, Air Ride Seat, Ride Control, A Joystick Steering, Traction Control, Re Diesel Exhaust Fluid, Manual Coupler, 148 in Bucket, Auto Lube, 35/65R33 T Usage: 17,868 Hr	C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Traction Control, Requires Diesel Exhaust Fluid, Manual Coupler, 11.0 cyd 148 in Bucket, Auto Lube, 35/65R33 Tires
27	2015 John Deere 310KE 4x2 Backhoe Loader S/N: 1T0310EKKFG276262		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	C/W: Open Operator Station, Air Ride Seat,		Asset located in: Midland, TX	
	Powershift Transmission, Manual Coupler, 85 in Loader Bucket, Quick Coupler, 15 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 2,569 Hr Asset located in: Humble, TX	35	2020 Doosan DL550-5 Wheel Loader S/N: DWGCWLBLJL1010264 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust	
28	28 2014 Case 580 Super N 4x2 Backhoe Loader S/N: JJGN580NLEC701386 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Powershift Transmission, 81 in Loader Bucket, 24 in		Fluid, Manual Coupler, 136 in Bucket, Auto Lube, 29.5-25 Tires Usage: 3,302 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Backhoe Digging Bucket, Rear Auxiliary Hydraulics	36	2015 Cat 980M Wheel Loader	
	Usage: 3,201 Hr Asset located in: Humble, TX		S/N: CAT09080MEKRS0327 C/W: Enclosed Cab, Air Conditioner, Rear View	
29	2008 John Deere 310J 4x2 Backhoe Loader S/N: T0310JX154217 C/W: Open Operator Station, Powershift		Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, 144 in Spade Nose Bucket, 29.5R25 Tires Usage: 11,389 Hr	
	Transmission, 2007 US EPA Label, 84 in Loader Bucket, 17 in Backhoe Digging Bucket Usage: 2,022 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX	
		38	2017 Case 1121G Wheel Loader S/N: NHF240450 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust	
30	Asset located in: Humble, TX 2007 John Deere 310J 4x2 Backhoe Loader	1	Fluid, 144 in Bucket, Auto Lube, 26.5-25 Tires	
50	S/N: T0310JX143255		Usage: 6,394 Hr Asset located in: Humble, TX	
Controls, 2007 US EPA Label, Manual Co 84 in Loader Bucket, Quick Coupler, 24 ir Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available	Hydraulics Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	42	2015 Cat 972M Wheel Loader S/N: CAT0972MCA8P00498 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Requires Diesel Exhaust Fluid, 126 in Bucket, Auto Lube, 26.5-25 Tires Usage: 16,534 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
46	2015 Cat 966M Wheel Loader S/N: CAT0966MJKJP01123 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Requires Diesel Exhaust Fluid, 26.5- 25 Tires Usage: 7,584 Hr Asset located in: Humble, TX	56	2014 Volvo L90G Wheel Loader S/N: VCE0L90GA0S617371 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, 20.5R25 Tires, 104 in Bucket Usage: 8,802 Hr Notes: LOCATED-IN-EL PASO-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO	
48	2020 Volvo L110H Wheel Loader	-	TEXAS SALES TAX.	
	S/N: VCEL110HL0S631821 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, 23.5-25 Tires, Hydraulic Coupler, 118 in Bucket, Forks Usage: 5,534 Hr Notes : LOCATED-IN-EL PASO-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.	57	Asset located in: El Paso, TX 2013 Volvo L90G Wheel Loader S/N: VCE0L90GC00004006 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Positive Air Shutoff, Manual Coupler, Pipe Forks, 20.5R25 Tires Usage: Not Available Asset located in: Humble, TX	
49	Asset located in: El Paso, TX 2012 Komatsu WA380-7 Wheel Loader S/N: KMTWA118J36A64030 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 23.5R25 Tires Usage: 26,767 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	- 58	2006 Volvo L90E Wheel Loader S/N: L90EV67684 C/W: Enclosed Cab, Air Conditioner, 102 in Bucket, 20.5R25 Tires Usage: 2,124 Hr Asset located in: Humble, TX	
50	Notes: DEFICIENCIES NOTED - PLEASE SEE 59 THE INSPECTION REPORT 59 Asset located in: Humble, TX 2021 LiuGong CLG856H Wheel Loader S/N: CLG856HZJML691261 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2020 US EPA Label,	59	2016 Case 721F High Lift Wheel Loader S/N: NGF235686 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Autoshift, Requires Diesel Exhaust Fluid Hydraulic Coupler, 20.5R25 Tires Usage: 4,087 Hr Asset located in: Humble, TX	
	Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 115 in Bucket, 23.5R25 Tires Usage: 2,551 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	60	2017 Komatsu WA270-8 Wheel Loader S/N: KMTWA136CGA083044 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2016 US EPA Label, Hydraulic Coupler, 186 in Bucket, 20.5R25 Tires Usage: 22,331 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	
52	2022 Komatsu WA320-8 Wheel Loader S/N: KMTWA135JNA086688 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2022 US EPA Label, Hydraulic Coupler, 108 in Bucket, Forks, 20.5 R25 Tires Usage: 4,504 Hr Asset located in: Humble, TX	61 64	THE INSPECTION REPORT Asset located in: Humble, TX 2014 Cat 930K Wheel Loader S/N: CAT0930KLRHN02781 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT-	
54	2010 John Deere 624 K Wheel Loader S/N: 1DW624KZEA0631664 C/W: Enclosed Cab, Air Conditioner, 2010 US EPA Label, Manual Coupler, Forks, 20.5R25		FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 9,005 Hr Asset located in: Humble, TX	FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 9,005 Hr
55	Tires Usage: 24,584 Hr Asset located in: Humble, TX 2016 Volvo L90H Wheel Loader S/N: L90HV623361 C/W: Enclosed Cab, Air Conditioner, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 8,006 Hr Notes: LOCATED-IN-EL PASO-TX; COMES		2018 Case 621G Wheel Loader S/N: NJF243988 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 102 in Bucket, 20.5R25 Tires Usage: 9,999 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$9,800.00 Asset located in: Humble, TX	
	WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: El Paso, TX			

Lot #	Details	Lot #	Details
65	2010 John Deere 544 K Wheel Loader S/N: 1DW544KZKA0631756 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 3 cyd 104 in Bucket, 20.5R25 Tires Usage: 13,725 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	73	2002 Cat 972G Wheel Loader S/N: CAT0972GJ7LS00461 C/W: Enclosed Cab, Air Conditioner, Command Control Steering, 128 in Bucket, 26.5-25 Tires Usage: 14,089 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT	74	1993 Cat 936F Wheel Loader
67	Asset located in: Humble, TX 2010 Komatsu WA250-6 Wheel Loader S/N: KMTWA103V01075463 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 100 in Bucket, Forks, 20.5R25 Tires Usage: 17,972 Hr	-	S/N: 8AJ01225 C/W: Enclosed Cab, 103 in Bucket, 20.5-25 Tires Usage: 13,401 Hr Notes : LOT CAN BE BLAST & PAINTED FOR \$5,700.00 Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	75	2003 John Deere 444H Wheel Loader
	Asset located in: Humble, TX		S/N: DW444HX585856
68	2007 Komatsu WA250-5 Wheel Loader S/N: KMTWA055E57A74458 C/W: Open Operator Station, Hydraulic Coupler, 102 in Bucket, 20.5-25 Tires Usage: 13,486 Hr Asset located in: Humble, TX	-	C/W: Enclosed Cab, Air Conditioner, 2002 US EPA Label, 1.9 m3 94 in Bucket, 17.5-25 Tires Usage: 7,076 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
<u> </u>		- 76	2017 CMI C550 Tracked Mulcher Tractor
69	69 2014 Case 521F Wheel Loader S/N: NEF224229 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 20.5R25 Tires Usage: 525 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM		S/N: C550/GBJ01604 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, 30 in Track Belts, 2017, FAE 500/U-250/C GB C450 10 ft 3 in, Mulcher Usage: 434 Hr Notes : HOURS NOT REFLECTING ACTUAL HOURS
	Asset located in: Humble, TX		Asset located in: Humble, TX
70	2020 Hitachi ZW50 Wheel Loader S/N: RYUNBD60A00005040 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 66 in Bucket, 15.5/60-18 Tires Usage: 1,439 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	77	Blount 721E 4x4 Mulcher Tractor S/N: HA18652 C/W: Enclosed Cab, Air Ride Seat, FECON 8 ft 4 in, Mulcher Usage: 12,001 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT	78	2016 Cat 14M Motor Grader
71	Asset located in: Humble, TX 2024 TRANER TR45 Wheel Loader (Unused) S/N: TR45240871 C/W: Open Operator Station, Manual Coupler, 39 in Bucket, 23x8.50-12 Tires Usage: Not Available Asset located in: Humble, TX		S/N: CAT0014MAR9J01752 C/W: Enclosed Cab, Air Conditioner, 16 ft / 4.88 m Moldboard, Combination Ripper /Scarifier, 20.5R25 Tires, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 1,195 Hr Asset located in: Humble, TX
72	2024 TRANER TR45 Wheel Loader (Unused)	90	2016 Case 865B Motor Grader
	S/N: TR45240805 C/W: Open Operator Station, Manual Coupler, 39 in Bucket, 23x8.50-12 Tires Usage: Not Available Asset located in : Humble, TX		S/N: HBZN0865HGAF05510 C/W: Enclosed Cab, Air Conditioner, 12 ft / 3.66 m Moldboard w/ 14 ft Extension, Front Auxiliary Hydraulics, Accumulators, Rear Auxiliary Hydraulics, 17.5-25 Tires Usage: 3,579 Hr
73A	2002 Cat 972G Wheel Loader S/N: CAT0972GE7LS00453 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 118 in Bucket, 26.5-25 Tires Usage: 22,738 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
92 94	2000 Cat 160H Motor Grader S/N: 9EJ00851 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5-25 Tires, EQUIPMENT- FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 20,645 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ; LOT CAN BE BLAST & PAINTED FOR \$6,200.00 Asset located in: Humble, TX 2004 Cat 140H VHP Plus Motor Grader S/N: Not Available	108	2016 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016PFD010195 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 29.5 R25 Tires Usage: 10,883 Hr Asset located in: Humble, TX 2016 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016LFD010237 C/W: Air Conditioner, Retarder, Rear View
	C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Ripper, 14.00 R24 Tires Usage: Not Available Asset located in: Lake Worth, TX		Camera, Air Ride Seat, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner, 29.5R25 Tires Usage: 10,133 Hr Asset located in: Humble, TX
95	1999 Cat 12H Motor Grader S/N: 4XM02120 C/W: Enclosed Cab, 14 ft / 4.27 m Moldboard, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 8,958 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	-111	2021 Bell B30E Articulated Dump Truck S/N: B93A631EL0310030 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auto Lube, 23.5 R25 Tires Usage: 3,532 Hr Asset located in: Humble, TX
97	1992 Cat 120G Motor Grader S/N: 4HD01643 C/W: Enclosed Cab, 12 ft / 3.66 m Moldboard, Mid Mount Scarifier, 13.00-24 Tires Usage: Not Available Notes : LOT CAN BE BLAST & PAINTED FOR \$5,100.00	_112	2021 Bell B30E Articulated Dump Truck S/N: B93A631EE03010029 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Auto Lube, 23.5 R25 Tires Usage: 3,429 Hr Asset located in: Humble, TX
98	Asset located in: Humble, TX 2018 Cat 621K Motor Scraper S/N: CAT0621KPWTA00132 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 33.25R25 Tires Usage: 7,629 Hr	_113	2021 Bell B30E Articulated Dump Truck S/N: B93A631EJ03010023 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 23.5R25 Tires Usage: 4,530 Hr Asset located in: Humble, TX
103	Asset located in: Humble, TX 2015 Cat 745C Articulated Dump Truck S/N: CAT0745CETFK00507 C/W: Air Conditioner, Retarder, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, 29.5R25 Tires Usage: 11,591 Hr Asset located in: Humble, TX	114	2021 Bell B30E Articulated Dump Truck S/N: B93A631EH03010031 C/W: Air Conditioner, Engine Brake, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Auto Lube, 23.5R25 Tires Usage: 4,255 Hr Asset located in: Humble, TX 2016 Cat 730C Articulated Dump Truck
106	2016 John Deere 410E Articulated Dump Truck S/N: 1DW410ET0GF674161 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Tailgate, 29.5 R25 Tires Usage: 9,996 Hr Asset located in: Humble, TX		S/N: CAT0730CCTFF01310 C/W: Air Conditioner, Retarder, Rear View Camera, 2015 US EPA Label, Tailgate, Steel Body Liner, 23.5R25 Tires Usage: Not Available Asset located in : Humble, TX

Series II Articulated	124		
7782 tarder, 2011 US EPA Tires	124	IHI IC45-2 Crawler Carrier Flatbed Dump S/N: CE000796 C/W: Canopy, 10 ft Long Flatbed Dump Body, 23 in Rubber Tracks Usage: 1,510 Hr Asset located in: Humble, TX	
RT	128	2018 Komatsu D155AX-8 Crawler Dozer S/N: KMT0D126LHC100160	
		C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel	
tarder, Tier 3, Tailgate,		Exhaust Fluid, 208 in Wide Semi-Ù Blade 28 in Single Grouser Track Shoes, Counterweight Usage: 18,809 Hr Asset located in : Humble, TX	
	129	2012 Komatsu D155AX-6 Crawler Dozer S/N: KMTDD074PC2081273	
		C/W: Enclosed Cab, 162 in Wide Straight Blade w/ Dual Tilt, 22 in Single Grouser Track Shoes,	
-		2 Cylinder Single-Shank Ripper Usage: Not Available	
		Asset located in: Lake Worth, TX	
	130A	2012 Cat D8T Crawler Dozer S/N: CAT00D8TAMLN00675 C/W: Enclosed Cab, Air Conditioner, 156 in	
e, TX		Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank	
2010 Terex TA30 Articulated Dump Truck S/N: A8971247 C/W: Air Conditioner, Air Ride Seat, 2010 US EPA Label		Ripper w/Hydraulic Pin Puller Usage: 15,228 Hr	
		Asset located in: Humble, TX	
	130	2019 Cat D8T Crawler Dozer	
		S/N: CAT00D8TLAW400863 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 154 in Wide Semi-U Blade	
		w/ Single Tilt, 26 in Single Grouser Track Shoes Usage: 5,261 Hr	
C/W: Air Ride Seat, Steel Body Liner, 23.5R25 Tires Usage: 40,191 Hr		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ; LOT CAN BE BLAST & PAINTED FOR \$10,346.00	
DT		Asset located in: Humble, TX	
	133	2021 Cat D7 LGP Crawler Dozer S/N: CAT00D7AHPM00155	
uires Diesel Exhaust t High Flatbed Dump <s< td=""><td></td><td>C/W: I for Gr Single Count Hydra Usage</td><td>C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 166 in Wide U-Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 1,853 Hr Notes: LOT CAN BE BLAST & PAINTED FOR</td></s<>		C/W: I for Gr Single Count Hydra Usage	C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 166 in Wide U-Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 1,853 Hr Notes : LOT CAN BE BLAST & PAINTED FOR
		\$9,200.00 Asset located in : Humble, TX	
	13/	2021 Cat D6 LGP Crawler Dozer	
t in Rubber Tracks	134	S/N: CAT000D6EKEW01021 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 158 in Wide Semi-U Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 4,828 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$8,700.00 Asset located in: Humble, TX	
	r Ride Seat, 2010 US AST & PAINTED FOR e, TX lated Dump Truck	Articulated Dump Truck e, TX Articulated Dump Truck etarder, Tier 3, Tailgate, Articulated Dump Truck etarder, Tier 3, Tailgate, AST & PAINTED FOR e, TX Articulated Dump Truck r Ride Seat, Tailgate, AST & PAINTED FOR e, TX Iated Dump Truck r Ride Seat, 2010 US AST & PAINTED FOR e, TX Iated Dump Truck r Ride Seat, 2010 US AST & PAINTED FOR e, TX Iated Dump Truck I Body Liner, 23.5R25 OTED - PLEASE SEE RT e, TX IOVD Crawler Carrier utres Diesel Exhaust t High Flatbed Dump ks e, TX IOVD Crawler Carrier conditioner, 7 ft Wide x 4 in Rubber Tracks OTED - PLEASE SEE RT	

Lot #	Details	Lot #	Details
135	2021 Cat D6 Crawler Dozer S/N: CAT000D6JSA901012 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 127 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 5,040 Hr	144	2011 Cat D7E Crawler Dozer S/N: CAT00D7EATAN00415 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Sweeps, 168 in Wide Angle Blade w/ Dual Tilt, 24 in Single Grouser Track Shoes, Winch, Rear Auxiliary Hydraulics Usage: 827 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	145	2020 Komatsu D65WX-18 Crawler Dozer
136	2021 Cat D6 LGP Crawler Dozer S/N: CAT000D6JKEW00488 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 152 in Wide Semi-U Blade Single Grouser Track Shoes, Winch Usage: 5,416 Hr	-	S/N: KMT0D127LKA091990 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Auto Lube, 154 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 6,375 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	146	2018 Komatsu D65EX-18 Crawler Dozer
138	 2020 Cat D6 LGP Crawler Dozer S/N: CAT000D6VKEW00462 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 151 in Wide Straight Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Drawbar 		S/N: KMT0D127PGA090580 C/W: Enclosed Cab, Air Conditioner, US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 151 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Drawbar, Rear Auxiliary Hydraulics Usage: 2,794 Hr
	Usage: 4,257 Hr Notes : LOT CAN BE BLAST & PAINTED FOR		Asset located in: Humble, TX
	\$8,700.00	147	2013 Komatsu D65PX-17 Crawler Dozer S/N: KMT0D117E01001609
140	Asset located in: Humble, TX 140 2016 Cat D6N LGP Crawler Dozer S/N: CAT00D6NVMG500574 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Sweeps, 154 in Wide PAT Blade, 34 in Single Grouser Track	148	C/W: Enclosed Cab, Air Conditioner, 2012 US EPA Label, Sweeps, 156 in Wide Straight Blade w/ Single Tilt, 36 in Single Grouser Track Shoes Usage: 3,553 Hr Asset located in : Humble, TX
	Shoes, Drawbar Usage: 10,344 Hr Asset located in : Humble, TX	140	2022 Komatsu D61PX-24 Crawler Dozer S/N: KMT0D129HMBB65251 C/W: Enclosed Cab, Air Conditioner, Rear View
142	2 2015 Cat D6N XL Crawler Dozer S/N: CAT0066NCPER01072 C/W: Enclosed Cab, Air Conditioner, Pre-Wired	-	Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 150 in Wide PAT Blade, 34 in Single Grouser Track Shoes, Drawbar Usage: 4,016 Hr Asset located in : Humble, TX
	for Grade Control, 122 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar	149	2019 Komatsu D61PX-24 Crawler Dozer
	Usage: 10,608 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	149	S/N: KMT0D129VJB60770 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 151 in Wide PAT Blade, 34 in
143	2019 Cat D7E LGP Crawler Dozer S/N: CAT00D7EESSH00503 C/W: Enclosed Cab, Air Conditioner, Rear View		Single Grouser Track Shoes, Drawbar Usage: 7,013 Hr Asset located in: Humble, TX
	Camera, Pre-Wired for Grade Control, 178 in Wide Semi-U Blade w/ Single Tilt, 36 in Single Grouser Track Shoes Usage: 3,396 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$9,200.00	150	2018 Komatsu D61EXI-24 Crawler Dozer S/N: KMT0D129HJBB60661 C/W: Enclosed Cab, Air Conditioner, 126 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,951 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
151	2018 Komatsu D61EXI-24 Crawler Dozer S/N: KMT0D129HJBB60580 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 128 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 8,606 Hr Asset located in: Humble, TX	162	2013 Komatsu D39PX-23 Crawler Dozer S/N: KMT0D122E01090309 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 118 in Wide PAT Blade, 26 in Single Grouser Track Shoes, Drawbar Usage: 6,522 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
153	2018 John Deere 750K LGP Crawler Dozer		Asset located in: Humble, TX
	S/N: 1T0750KXTJF327146 C/W: Enclosed Cab, Air Conditioner, 149 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 11,284 Hr Asset located in : Humble, TX	163	2023 John Deere 450P XLT Crawler Dozer S/N: 1T0450PAPPMX02255 C/W: Open Operator Station, 2023 US EPA Label, 97 in Wide PAT Blade, 16 in Single Grouser Track Shoes Usage: 167 Hr
155	2019 Cat D6K2 LGP Crawler Dozer		Asset located in: Humble, TX
	S/N: CAT00D6KVEL703205 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 135 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 4,691 Hr	164	2022 John Deere 450k Crawler Dozer (Unused) S/N: 1T0450KXCPF434649 C/W: Open Operator Station, 97 in Wide PAT Blade, 16 in Single Grouser Track Shoes Usage: 37 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	165	2022 John Deere 450K Crawler Dozer
156	2019 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KAEL703206 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 144 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 4,697 Hr		S/N: 1T0450KXANF422050 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 97 in Wide PAT Blade, 16 in Single Grouser Track Shoes Usage: 222 Hr
	Asset located in: Humble, TX	1.00	Asset located in: Humble, TX
158	2022 John Deere 650KXLT Crawler Dozer S/N: 1T0650KKJNF419254 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 154 Hr	166	2019 Cat D3K2 XL Crawler Dozer S/N: CAT00D3KCKF207150 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 102 in Wide PAT Blade, 16 in Single Grouser Track Shoes, Drawbar Usage: 3,502 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	167	2002 Cat D6R XL Crawler Dozer
159	2022 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKANF421252 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 543 Hr Asset located in: Humble, TX		S/N: CAT00D6RP5LN03349 C/W: Enclosed Cab, 124 in Wide Semi-U Blade w/ Single Tilt, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: Not Available Notes : LOT CAN BE BLAST & PAINTED FOR \$6,500.00
160	2021 John Deere 650KXLT Crawler Dozer		Asset located in: Humble, TX
	S/N: 1T0650KKLMF401146 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 1,081 Hr Asset located in : Humble, TX	168	1998 Cat D6R XL Crawler Dozer S/N: 4MN00473 C/W: Open Operator Station, 160 in Wide Angle Blade 24 in Single Grouser Track Shoes, Drawbar Usage: Not Available
161	2016 Cat D5K2 LGP Crawler Dozer		Notes: DEFICIENCIES NOTED - PLEASE SEE
for Grade Control, Trimble Grade Contro	C/W: Enclosed Cab, Air Conditioner, Pre-Wired		THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 2,541 Hr	169	2005 Cat D6N XL Crawler Dozer S/N: AKM01683 C/W: Enclosed Cab, Air Conditioner, 129 in Wide Straight Blade 23.5 in Single Grouser Track Shoes, Drawbar Usage: 5,733 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
170	2004 Cat D5N LGP Crawler Dozer S/N: CAT00D5NVAKD00887 C/W: Open Operator Station, 128 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 7,156 Hr Asset located in: Humble, TX	179	1998 Case 850G Crawler Dozer S/N: JJG0254307 C/W: Open Operator Station, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 5,864 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
171	2003 John Deere 700H LGP Crawler Dozer S/N: T0700HX913761		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Enclosed Cab, Air Conditioner, 132 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 8,417 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	180	1976 Cat 955L Crawler Loader S/N: 85J10684 C/W: Open Operator Station, 89 in Bucket, 17 in Double Grouser Track Shoes Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE
173	2006 Case 850K Crawler Dozer		INSPECTION REPORT Asset located in: Lake Worth, TX
174	S/N: CAL005375 C/W: Open Operator Station, 103 in Wide PAT Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,005 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	184	Asset located III: Lake Worth, TX 2015 Bomag BW177PDH-5 Padfoot Drum Compactor S/N: 101586051008 C/W: Open Operator Station, Tier 4, 2014 US EPA Label, Kubota V3307 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 6,406 Hr Asset located in: Humble, TX
174	1996 Cat D5C LGP Crawler Dozer	185	2020 Cat CS-66B Smooth Drum Compactor
	S/N: 6ZL00517 C/W: Open Operator Station, 117.5 in Wide PAT Blade, 26 in Single Grouser Track Shoes Usage: 12,584 Hr Asset located in : Humble, TX	185	S/N: CATCS66BL48700649 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, 84 in Drum Usage: 2,639 Hr
175	2008 Cat D3K LGP Crawler Dozer		Asset located in: Humble, TX
	S/N: CAT00D3KHLLL00332 C/W: Open Operator Station, Sweeps, 122 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 3,534 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	186	2022 Ammann ARS110 Smooth Drum Compactor S/N: ACZ16382CN3037480 C/W: Open Operator Station, Tier 4, 2019 US EPA Label, Deutz TCD3.6L4 4 Cylinder 134 hp 3.6 L Diesel Engine, 84 in Drum Usage: 281 Hr Asset located in: Humble, TX
176	2008 Komatsu D-39PX-21 Crawler Dozer	187	2020 Wacker Neuson RC-110 Smooth Drum
	S/N: KMT0D014E01002355 C/W: Open Operator Station, 115 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		Compactor S/N: WNCR1101EHAA00345 C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 1,238 Hr Asset located in: Humble, TX
177	2007 Komatsu D-39PX-21 Crawler Dozer	192	2003 Dynapac CA262D Smooth Drum
.,,	S/N: KMT0D014V01002317 C/W: Open Operator Station, 118 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 6,637 Hr Asset located in: Humble, TX	192	Compactor S/N: 67220548 C/W: Open Operator Station, 2016 US EPA Label, Cummins 6 Cylinder 148 hp 5.9 L Diesel Engine, 84 in Drum
178	2006 Komatsu D39PX-21 Crawler Dozer	1	Usage: Not Available
	S/N: KMT0D014A01002030 C/W: Open Operator Station, 118 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 6,933 Hr Asset located in: Humble, TX		Notes: 2016 ENGINE Asset located in: Humble, TX

Lot #	Details	Lot #	Details
193	1987 Ingersoll Rand SP-48 Smooth Drum Compactor S/N: 6086S C/W: Open Operator Station, Swivel Operator Controls, Cummins 4B 4 Cylinder 100 hp 3.0 L Diesel Engine, 66 in Drum Usage: 6,103 Hr Asset located in : Humble, TX	202	2011 Bomag BW190AD-4 Double Drum Roller S/N: 101920291023 C/W: Open Operator Station, 2010 US EPA Label, Deutz 4 Cylinder 134 hp 4.03 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: 2,894 Hr Asset located in: Humble, TX
195	2020 Wacker Neuson RC-70 Smooth Drum	203	2014 Volvo DD110B Double Drum Roller
	Compactor S/N: WNCR1201PHAA00212 C/W: Open Operator Station, 2019 US EPA Label, Kubota 3307-cr-t-ew04 4 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 891 Hr Asset located in: Humble, TX		S/N: VCED110BE0S285062 C/W: Open Operator Station, 2013 US EPA Label, Volvo 6 Cylinder 131 hp 4.0 L Diesel Engine, 67 in Compaction Width, Water System Usage: 4,326 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
196	2020 Wacker Neuson RC-70 Smooth Drum		Asset located in: Humble, TX
	Compactor S/N: WNCR1201AHAA00217 C/W: Open Operator Station, 2019 US EPA Label, Kubota v3307-cr-t-ew04 4 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 1,757 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	204	2007 Cat CB-534D Double Drum Roller S/N: CATCB534JFGH00656 C/W: Open Operator Station, Swivel Operator Controls, 2006 US EPA Label, Cat 3054C 4.4 L Diesel Engine, 67 in Compaction Width, Water System Usage: 2,142 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
197	2020 Wacker Neuson RC-70 Smooth Drum	-	Asset located in: Humble, TX
	Compactor S/N: WNCR1201PHAA00209 C/W: Open Operator Station, 2019 US EPA Label, Kubota V3307 3 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 1,155 Hr Asset located in: Humble, TX	206	2013 Hamm HD12VV Double Drum Roller S/N: H2002240 C/W: Open Operator Station, Kubota 3 Cylinder 1.5 L Diesel Engine, 48 in Compaction Width Usage: 582 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
198	2020 Wacker Neuson RC-70 Smooth Drum	007	Asset located in: Humble, TX
	Compactor S/N: WNCR1201AHAA00203 C/W: Open Operator Station, 2019 US EPA Label, Kubota V3307 3 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 686 Hr Asset located in: Humble, TX	207	1998 Ingersoll Rand DD-24 Double Drum Roller S/N: 153638 C/W: Open Operator Station, Deutz F3L 1011 F Diesel Engine, 43 in Compaction Width Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
200	Dynapac CA1500D Smooth Drum Compactor		Asset located in: Lake Worth, TX
	S/N: 10000156L0A014071 C/W: Open Operator Station, 2014 US EPA Label, Cummins QSB3.3 100 hp 3.26 L Diesel Engine, 66 in Drum Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	208	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263JHAA00666 C/W: Open Operator Station, Tier 4, 2020 US EPA Label, Kubota D1105-EF05 3 Cylinder 1.1 L Diesel Engine, 39.5 in Compaction Width, Water System Usage: 436 Hr Asset located in: Humble, TX
201	Galion Smooth Drum Compactor	209	2021 Hamm HD10CVV Double Drum Roller
	S/N: 490054 C/W: Open Operator Station, Detroit Diesel Engine, 66 in Drum Usage: 2,253 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	209	S/N: WGH0H263KHAA00668 C/W: Open Operator Station, 2020 US EPA Label, Kubota D1105 3 Cylinder 16.1 kW 1.5 L Diesel Engine, 39.5 in Compaction Width Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
210	Hamm HD10CVV Double Drum Roller S/N: WGH0H263CHAA00679 C/W: Open Operator Station, Tier 4, 2020 US EPA Label, Kubota 3 Cylinder 16.1 kW 1.1 L Diesel Engine, Requires Diesel Exhaust Fluid, 39 in Compaction Width, Water System Usage: 233 Hr Asset located in: Humble, TX	224	2012 Cat 336E L Tracked Excavator S/N: CAT0336EABZY01673 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 12 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 65 in Digging Bucket Usage: 13,275 Hr Asset located in: Humble, TX
212	2018 Fuchs MHL340 T4F Wheel Material Handler S/N: 3404105374 C/W: Air Conditioner, Hydraulic Cab Riser, Rear & Side View Cameras, Auxiliary Hydraulic Plumbing, 10.00x20 Tires, Rotating Grapple Usage: 5,079 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2007 Gradall XL4100 Wheel Excavator	225	2023 LiuGong 936F Tracked Excavator S/N: CLG936FZEPE905812 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Surround View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 58 in Digging Bucket, Thumb Bracket Usage: 958 Hr Asset located in: Humble, TX
217	S/N: 4100000165 C/W: Air Conditioner, 13 ft Stick, 385/65R22.5 Tires, 60 in Cleanup Bucket Usage: 8,853 Hr Asset located in: Humble, TX 2017 Cat 349FL Tracked Excavator S/N: CAT0349FHHPD10055 C/W: Air Conditioner, Straight Travel Pedal, Air	226	2022 LiuGong 936F Tracked Excavator S/N: CLG936FZJNE903739 C/W: Air Conditioner, Surround View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 60 in Digging Bucket Usage: 1,151 Hr
218	Ride Seat, Control Pattern Changer, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, 66 in Digging Bucket Usage: 13,438 Hr Asset located in: Humble, TX 2021 Hyundai HX480A L Tracked Excavator	227	Asset located in: Humble, TX 2020 LiuGong 936E Tracked Excavator S/N: 888936EZKLU004041 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 58 in
	S/N: HHKHKB04VE0000003 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 38 in Digging Bucket Usage: 4,419 Hr Asset located in: Humble, TX 21 2021 Cat 336 Tracked Excavator S/N: CAT00336HYBN20483 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side	229	Digging Bucket Usage: 2,213 Hr Asset located in: Humble, TX 2016 Komatsu PC360LC-11 Tracked Excavator S/N: A35327 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2015 US EPA Label, Requires Diesel
221			Exhaust Fluid, 12 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 40 in Digging Bucket Usage: 10,167 Hr Asset located in: Humble, TX
	View Cameras, Pre-Wired for Grade Control, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 64 in Digging Bucket Usage: 4,794 Hr Asset located in : Humble, TX		S/N: YC14605003 C/W: Air Conditioner, Air Ride Seat, Co Pattern Changer, Rear View Camera, 2 EPA Label, Requires Diesel Exhaust F 6 in Stick, Auxiliary Hydraulic Plumbir Triple Grouser Track Shoes, 74 in Dig
222	2021 Cat 336 Tracked Excavator S/N: CAT00336KYBN20619 C/W: Air Conditioner, Straight Travel Pedal, Air		Bucket Usage: 4,748 Hr Asset located in: Humble, TX
Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 62 in Digging Bucket Usage: 6,944 Hr Asset located in : Humble, TX	232	2011 John Deere 350GLC Tracked Excavator S/N: 1FF350GXCBE808042 C/W: Air Conditioner, Air Ride Seat, 13 ft Stick, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 272 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
234	2019 Cat 330FL Tracked Excavator S/N: HCK20238 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 3,527 Hr Asset located in: Humble, TX Kobelco SK260LC-10 Tracked Excavator	242	2018 Hyundai 220L Tracked Excavator S/N: HHKLKG01PJ0000763 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 5,883 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: LL1610670		Asset located in: Humble, TX
	C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 56 in Digging Bucket, Thumb Bracket Usage: 5,590 Hr Asset located in: Humble, TX	243	2020 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257JKTC81129 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick
237	2022 John Deere 250G Tracked Excavator	1	Coupler, 24 in Digging Bucket Usage: 7,642 Hr
	S/N: 1FF250GXCNF611835		Asset located in: Humble, TX
	C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 1,246 Hr Asset located in: Humble, TX	246	2019 Cat 320 Tracked Excavator S/N: CAT00320LHEX11718 C/W: Air Conditioner, Control Pattern Changer, Rear & Side View Cameras, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 23.5 in Triple Grouser Track Shoes, 38 in
238	2020 John Deere 245G LC Tracked Excavator]	Digging Bucket Usage: 3,091 Hr
	S/N: 1FF245GXJLF801542		Asset located in: Humble, TX
	C/W: Air Conditioner, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 40 in Digging Bucket, Hydraulic Thumb Usage: 2,822 Hr Asset located in: Humble, TX	247	2019 Cat 320 Tracked Excavator S/N: CAT00320THEX12020 C/W: Air Conditioner, Air Ride Seat, Auxiliary Hydraulic Plumbing Usage: 4,036 Hr Asset located in: Lake Worth, TX
239	2017 Volvo ECR235EL Tracked Excavator	249	2022 Cat 320GC Tracked Excavator
	S/N: VCECR235P00310736 C/W: Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 24 in Rubber Tracks, 2021 SAS Extreme 35V3 235 Car Processor Usage: 4,865 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		S/N: CAT00320CLKS20323 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 37 in Digging Bucket Usage: 1,182 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
240	2020 LiuGong 925E Tracked Excavator	250	2019 Cat 320GC Tracked Excavator
240	S/N: 888925EZCLU004016 C/W: Air Conditioner, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 2,046 Hr Asset located in: Humble, TX		S/N: Not Available C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 6,583 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
251	2015 Cat 320E LRR Tracked Excavator S/N: CAT0320EHTFX01291 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 5,535 Hr	263	2007 Komatsu PC200LC8 Tracked Excavator S/N: KMTPC180C87C60745 C/W: Air Conditioner, 2006 US EPA Label, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 8,839 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	264	2006 Kobelco SK135SRLC-1E Tracked
252	2011 Komatsu PC200LC8 Tracked Excavator S/N: KMTPC180H54A89854 C/W: Air Conditioner, 2011 US EPA Label, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 29 in Digging Bucket, Thumb Bracket Usage: 13,292 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Excavator S/N: YH0403598 C/W: Air Conditioner, 2005 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, 24 in Digging Bucket Usage: 9,469 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
257	2010 Kobelco SK140SR-LC Tracked Excavator		Asset located in: Humble, TX
	S/N: YH0507944 C/W: 9 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 9,542 Hr Asset located in: Humble, TX	265	1997 John Deere 690E LC Tracked Excavator S/N: DW690EL564389 C/W: 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 42 in Digging Bucket Usage: 6,981 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE
S/N: CAT0336DLW3 C/W: Air Conditioner Ride Seat, 20 ft Stick Plumbing, 31.5 in Tr Usage: 88,514 Hr Notes : LOT CAN BE \$9,600.00	2009 Cat 336DL Tracked Excavator S/N: CAT0336DLW3K00443 C/W: Air Conditioner, Straight Travel Pedal, Air		THE INSPECTION REPORT
			Asset located in: Humble, TX
	Notes: LOT CAN BE BLAST & PAINTED FOR	266	2020 Volvo ECR88D Tracked Excavator S/N: 216242 C/W: Air Conditioner, 6 ft 11 in Stick, Backfill Blade, 18 in Rubber Tracks, 22 in Digging Bucket Usage: 2,400 Hr
259	2006 Cat 330CL Tracked Excavator		Notes: LOCATED-IN-FORT-WORTH-TX ;
239	S/N: CAT0330CL Tracked Excavator S/N: CAT0330CTCYA01139 C/W: Air Conditioner, Straight Travel Pedal,		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Cab Screens, 31.5 in Triple Grouser Track		Asset located in: Lake Worth, TX
	Shoes, Shear, LaBounty MSD3000 Hydraulic Shear - SN 700305 Usage: 5,833 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$10,600.00 Asset located in: Humble, TX		S/N: VCE00E88E00215347 C/W: Air Conditioner, Tier 4, 2019 US EPA Label, Swing Boom, 6 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17 in
260	2008 Komatsu PC 300 LC-8 Tracked Excavator	-	Digging Bucket, Hydraulic Thumb
260	S/N: A90468 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 10 ft 7 in Stick, 33.5 in Triple Grouser Track Shoes, 54 in Digging Bucket		Usage: 2,724 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 1,591 Hr		Asset located in: Lake Worth, TX
060	Asset located in: Humble, TX	268	2021 Bobcat E85 Mini Excavator S/N: B48414950
262	2008 Komatsu PC200LC8 Tracked Excavator S/N: KMTPC180J54A88678 C/W: Air Conditioner, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 50 in Cleanup Bucket Usage: 15,110 Hr		C/W: Enclosed Cab, Air Conditioner, 2020 US EPA Label, Swing Boom, 7 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 24 in Digging Bucket Usage: 968 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	1	

Lot #	Details	Lot #	Details
269	2021 Bobcat E85 Mini Excavator S/N: B48414940 C/W: Enclosed Cab, Air Conditioner, 2020 US EPA Label, 7 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 18 in Digging Bucket Usage: 989 Hr Asset located in: Humble, TX	278	2015 Takeuchi TB260 Mini Excavator S/N: 126100966 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 5 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, 18 in Digging Bucket Usage: 5,328 Hr Asset located in: Humble, TX
		070	
270	2017 Bobcat E85 Mini Excavator S/N: B34T13537 C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, 2016 US EPA Label, 7 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 18 in Rubber Tracks, Manual Quick Coupler, 23 in Digging Bucket Usage: 1,011 Hr	279	2016 Takeuchi TB260 Mini Excavator S/N: 126101490 C/W: 2015 US EPA Label, Swing Boom, 5 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, 24 in Digging Bucket Usage: 2,729 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	280	2018 Cat 305.5E2 Mini Excavator
271	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EEMC500732 C/W: Air Conditioner, Rear View Camera, Tier 4, 2018 US EPA Label, 5 ft 6 in Stick, Backfill Blade, 17.5 in Triple Grouser Track Shoes w /Rubber Inserts, 28 in Digging Bucket Usage: 2,209 Hr		S/N: CAT3055ETWE205440 C/W: Enclosed Cab, 2023 US EPA Label, 5 ft 9 in Stick, Backfill Blade, 15.5 in Triple Grouser Track Shoes, 26 in Digging Bucket Usage: 833 Hr Asset located in : Humble, TX
	Asset located in: Humble, TX	281	2017 Cat 305.5E2 Mini Excavator
272	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELMC500727 C/W: Air Conditioner, Rear View Camera, Tier 4, 2018 US EPA Label, 5 ft 6 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w /Rubber Inserts, 27 in Digging Bucket	282	S/N: CAT3055EEWE203491 C/W: Enclosed Cab, Air Conditioner, 5 ft 9 in Stick, Backfill Blade, 15.5 in Triple Grouser Track Shoes, 26 in Digging Bucket Usage: 884 Hr Asset located in: Humble, TX 2017 Cat 305.5E2 Mini Excavator
	Usage: 3,371 Hr Asset located in: Humble, TX	202	S/N: CAT3055EHWE202355 C/W: Enclosed Cab, Air Conditioner, 5 ft 9 in Stick, Backfill Blade, 15.5 in Triple Grouser Track Shoes, 26 in Digging Bucket Usage: 927 Hr Asset located in : Humble, TX
273 20 S/ C/ Hy	2019 Volvo ECR58D Mini Excavator S/N: 210698 C/W: Tier 4, Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 12 in Digging Bucket Usage: 1,576 Hr		
		283	2016 Cat 305E2 CR Mini Excavator
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: CAT0305ELH5M02800 C/W: Enclosed Cab, Air Conditioner, Swing
275	2003 Cat 308C Tracked Excavator S/N: CAT308CACPE01252 C/W: Air Conditioner, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in		Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 2,135 Hr Asset located in: Humble, TX
	Triple Grouser Track Shoes, 28 in Digging Bucket, Hydraulic Thumb	284	2017 Bobcat E50 Mini Excavator
	Usage: 2,545 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: AJ1813546 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 5 ft Stick, Backfill Blade, 15.5 in Rubber Tracks, 24 in Digging Bucket,
	Asset located in: Humble, TX	_	Hydraulic Thumb
277	2017 Takeuchi TB260 Mini Excavator S/N: 126102558		Usage: 2,705 Hr Asset located in: Humble, TX
	C/W: 2017 US EPA Label, Swing Boom, 5 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Cleanup Bucket Usage: 2,802 Hr Asset located in : Humble, TX	285	2018 Cat 303.5E2CR Mini Excavator S/N: JWY03540 C/W: Swing Boom, 5 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Tilt Blade, 12 in Rubber Tracks, 24 in Digging Bucket Usage: 3,154 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
286	2012 Kubota KX121-3ST Mini Excavator S/N: JKUK1213H01H73481 C/W: Swing Boom, 5 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Tilt Blade, 12 in Double Grouser Track Shoes, 24 in Digging Bucket Usage: 4,566 Hr Asset located in: Humble, TX	293	2021 John Deere 35G Mini Excavator S/N: 1FF035GXLMK292833 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 24 in Bucket Usage: 711 Hr
287	S/N: CAT0304ELME407006 C/W: Swing Boom, 5 ft 4 in Stick, Auxiliary		Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
	Hydraulic Plumbing, Backfill Blade, 14 in Rubber Tracks, 10 in Digging Bucket Usage: 2,477 Hr	294	2021 John Deere 35G Mini Excavator S/N: 1FF035GXAMK292863
288	Asset located in: Humble, TX 2018 Sany SY35U Mini Excavator S/N: SY0033BJ19538 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 4 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 12 in Digging Bucket Usage: 2,418 Hr	-	C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 11.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 625 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
	Notes: DEFICIENCIES NOTED - PLEASE SEE	005	Asset located in: Lake Worth, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	295	2021 John Deere 35G Mini Excavator S/N: 1FF035GXJMK293071
289	2018 Bobcat E35i Mini Excavator S/N: B3Y212264 C/W: Control Pattern Changer, Tier 4, 2017 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket Usage: 1,915 Hr Asset located in: Humble, TX		C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 543 Hr Notes : LOCATED-IN-FORT-WORTH-TX ; COME WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
290	2018 Bobcat E35i Mini Excavator		Asset located in: Lake Worth, TX
	S/N: B3Y212281 C/W: Control Pattern Changer, 2017 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 16 in Cleanup Bucket Usage: 2,058 Hr Asset located in : Humble, TX	296	2021 John Deere 35G Mini Excavator S/N: 1FF035GXKMK293067 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket
291	2020 Yanmar ViO35-6A Mini Excavator S/N: AL139 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic		Usage: 723 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
	Quick Coupler, 24 in Digging Bucket Usage: 2,191 Hr	297	2017 John Deere 35G Mini Excavator
292	Asset located in: Humble, TX		S/N: 1FF035GXPHK279839 C/W: Control Pattern Changer, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: 774 Hr Asset located in: Humble, TX
		298	2017 John Deere 35G Mini Excavator S/N: 1FF035GXCGK278385 C/W: Control Pattern Changer, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 11.5 in Rubber Tracks, 24 in Digging Bucket Usage: 4,241 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
299	2017 John Deere 35G Mini Excavator S/N: 1FF035GXKGK278058 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket, Additional 29 in Cleanup Bucket Usage: 4,524 Hr	306	2007 John Deere 50D Mini Excavator S/N: FF050DX245720 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	307	2005 John Deere 50D Mini Excavator
300	2013 John Deere 35D Mini Excavator S/N: 1FF035DXHCG270973 C/W: Control Pattern Changer, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: 5,672 Hr Asset located in: Humble, TX		S/N: FF050DX244276 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket Usage: 10,447 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
301	2016 Bobcat E32 Mini Excavator		Asset located in: Humble, TX
	S/N: B2VV12022 C/W: Control Pattern Changer, Tier 4, 2015 US EPA Label, Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 3,704 Hr Asset located in: Humble, TX	308	2021 Cat 301.8 Mini Excavator S/N: CAT03018CH8X06213 C/W: Enclosed Cab, Air Conditioner, 2014 US EPA Label, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 11.5 in Digging Bucket Usage: 31 Hr
302A	2021 John Deere 30G Mini Excavator S/N: 1FF030GXPMK268252 C/W: 2021 US EPA Label, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick		Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Midland, TX
302	Coupler, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket, Thumb Bracket Usage: 147 Hr Asset located in: Humble, TX 2016 Bobcat E32 Mini Excavator S/N: B2VV12015 C/W: Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 3,337 Hr Asset located in: Humble, TX	309	2019 Cat 301.7CR Mini Excavator S/N: CAT03017HJH701720 C/W: Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 11 in Digging Bucket, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 1,611 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Takeuchi TB216 Mini Excavator
303	2015 John Deere 27D Mini Excavator		S/N: 216101280
000	S/N: 1FF027DXHEG259747 C/W: Control Pattern Changer, 2014 US EPA Label, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in		C/W: Swing Boom, 3 ft 6 in Stick, Backfill Blade, 9 in Rubber Tracks, 12 in Digging Bucket Usage: 1,305 Hr Asset located in: Humble, TX
	Rubber Tracks, 33 in Cleanup Bucket, Additional 12 in Digging Bucket	311	2021 John Deere 17G Mini Excavator
304	Usage: 6,082 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Kubota U27-4R1 Mini Excavator		S/N: 1FF017GXPMK231121 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Digging Bucket
007	S/N: WKFRGH1200Z041167 C/W: Tier 4, 2018 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 600 Hr Asset located in: Humble, TX		Usage: 341 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
312	2021 John Deere 17G Mini Excavator S/N: 1FF017GXCMK231343 C/W: Control Pattern Changer, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Manual Quick Coupler, 12 in Digging Bucket Usage: 358 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX	318	 2006 Manitowoc 10000 100 ton Lattice-Boor Crawler Crane S/N: 10001060 C/W: 90 ft Boom, Self Erecting, Auxiliary Hois Rooster Sheave, Johnson 3856 lb 4 Sheave 7 ton Hook Block, 698 lb 12 ton Overhaul Ball, 79600 lb Counterweight, Counterweight Removal System, Anti Two-Block, Load Moment Indicator, 2006 US EPA Label, 36 in Track Shoes Usage: 10,664 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
313	 313 2021 John Deere 17G Mini Excavator S/N: 1FF017GXKMK231508 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Bucket Usage: 172 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX 		THE INSPECTION REPORT Asset located in: Humble, TX
		319	2005 Kobelco CK1000-II 100 ton Lattice-Boom Crawler Crane S/N: GH0201067 C/W: 160 ft Boom, 60 ft Luffing Jib, Self Erecting, Auxiliary Hoist, Rooster Sheave, Johnson 3 Sheave Hook Block, Overhaul Ball, Counterweight Removal System, Air Conditioner, Anti Two-Block, . Load Moment Indicator, 2005 US EPA Label, 36 in Track
314	2021 Kubota K008-3 Mini Excavator		Shoes, Expandable Width Tracks Usage: 17,816 Hr
	S/N: KBCAZ030TM3F44754 C/W: Swing Boom, 2 ft 11 in Stick, Backfill Blade 7 in Dubbar Tracks 12 in Director Bucket	320	Asset located in: Humble, TX Link-Belt LS-138H II 80 ton Lattice-Boom
Blade, 7 in Rubber Tracks, 12 in Digging Bucket Usage: 810 Hr		Crawler Crane	
315	Asset located in: Humble, TX 2020 Rapidmix 600CV Concrete Plant S/N: RMXV601121143 C/W: Portable Aggregate Bins Usage: Not Available Asset located in: Humble, TX 2008 Terex Pegson Metro HA Tracked Jaw	321	S/N: CDB960V911 C/W: 90 ft Boom, Self Erecting, Auxiliary Hoist, Rooster Sheave, Johnson 4 Sheave Hook Block, Overhaul Ball, 50706 lb Counterweight, Counterweight Removal System, Greer GS820 Load Moment Indicator, 1999 US EPA Label, 36 in Track Shoes, Expandable Width Tracks Usage: 5,899 Hr Asset located in: Humble, TX
317	Crushing Plant S/N: 960520FGHA C/W: 6 ft x 12 ft Vibratory Grizzly Feeder 600 mm x 900 mm Jaw Crusher, 32 in Wide End Discharge Conveyor, Terex 30 in x 6 ft Cross Belt Magnet, Cable Remote Control, Cat 6 Cylinder Diesel Engine, 16 in Triple Grouser Track Shoes Usage: 13,068 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2000 Terex HC125 125 ton Lattice-Boom		2000 Link-Belt HC-248 200 ton 10x4x2 Lattice- Boom Truck Crane S/N: C5NJ04608 C/W: 180 ft Boom, 50 ft Luffing Jib, Auxiliary Hoist, Johnson 5 Sheave 100 ton Hook Block, Overhaul Ball, 88440 lb Counterweight, Counterweight Removal System, Eaton Fuller 8LL Manual Transmission, Detroit 6 Cylinder Diesel Carrier Engine, LSI GS820 Load Moment Indicator, 2000 US EPA Label, Isuzu Diesel Upper Engine, Spicer 4 Speed Auxiliary Transmission Usage: Not Available
31/	Crawler Crane S/N: AC3753 C/W: 170 ft Boom, 60 ft Jib, Self Erecting, Auxiliary Hoist, Rooster Sheave, 3900 lb 3 Sheave 100 ton Hook Block, 850 lb 15 ton Overhaul Ball, Counterweight Removal System, Air Conditioner, Anti Two-Block, Wylie WW 250 Load Moment Indicator, 2012 US EPA Label, 44 in Track Shoes, Expandable Width Tracks Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
322	2011 Terex AC100/4L 120 ton 8x6 All Terrain Crane S/N: WMG4215H0BZ030168 C/W: Air Conditioner, Automatic Transmission, Mercedes-Benz OM460LA 6 Cylinder Diesel Carrier Engine, Air Conditioner, Tilt Cab, Anti Two-Block, Terex Load Moment Indicator, Mercedes-Benz Diesel Upper Engine, 39.4 ft Minimum 194.9 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 52 ft Bifold Swingaway Hydraulic Offset Jib, 550 kg 50 ton Capacity Terex 3 Sheave Hook Block, 170 kg 8 ton Capacity Overhaul Ball, 28.82 lb Counterweight, Counterweight Removal System, 1 sheave block Usage: 43,700 Km Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY	325	2003 Grove TMS700E 60 ton 8x4 Hydraulic Truck Crane S/N: 223634 C/W: Eaton Fuller 9LL Manual Transmission, 8544 hrs Carrier Engine, Cummins ISM 6 Cylinder 10.8 L Diesel Carrier Engine, Anti Two- Block, PAT Load Moment Indicator, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 56 ft Bifold Swingaway Offset Jib, 800 lb 40 ton Capacity McKissick 3 Sheave Hook Block, 8.3 ton Capacity Overhaul Ball, 16500 lb Counterweight, Counterweight Removal System Usage: 209,207 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	326	2003 Grove TMS700E 60 ton 8x4 Hydraulic Truck Crane
323	 323 2001 Grove GMK5120B 120 ton 10x8x8 All Terrain Crane S/N: 1005901WG12190 C/W: Daimler - Chrysler G 240-16 16 Speed Automatic Transmission, 2025 hrs Carrier Engine, 2001 US EPA Label, Mercedes-Benz OM502LA V8 15.9 L Diesel Carrier Engine, Air Conditioner, Tilt Cab, Anti Two-Block, Load Moment Indicator, Merceds-Benz OM904LA Diesel Upper Engine, 42 ft Minimum 167 ft Maximum Boom Length, Auxiliary Hoist, 36 ft to 112 ft Bifold Swingaway Hydraulic Offset Jib, 1816 lb 80 ton Capacity Johnson 5 Sheave Hook Block, 12 ton Capacity Overhaul Ball, 68300 lb Counterweight, Counterweight Removal System Usage: 153,731 Km 		S/N: 223635 C/W: Eaton Fuller 9LL Manual Transmission, 21276 hrs Carrier Engine, Cummins ISM 450 6 Cylinder 10.8 L Diesel Carrier Engine, Anti Two- Block, PAT Load Moment Indicator, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 796 lb 40 ton Capacity Johnson 3 Sheave Hook Block, 16500 lb Counterweight, Counterweight Removal System Usage: 226,835 Mi Asset located in : Humble, TX
 Hook Block, 12 ton Capacity Overhaul 68300 lb Counterweight, Counterweig Removal System Usage: 153,731 Km Asset located in: Humble, TX 324 2015 Link-Belt HTC8675 75 ton 8x4 H Truck Crane S/N: P9K5-4779 C/W: Air Conditioner, Automatic Trans Cummins ISX12 6 Cylinder Diesel Car Engine, Requires Diesel Exhaust Fluid Block, Link Belt Load Moment Indicat Minimum 127 ft Maximum Boom Len Auxiliary Hoist, Rooster Sheave, 38 ft Bifold Swingaway Offset Jib, 1082 lb Capacity Johnson 4 Sheave Hook Blo 		327	2003 Grove TMS500E 40 ton 6x4 Hydraulic Truck Crane S/N: 223654 C/W: Allison Automatic Transmission, Cat
	2015 Link-Belt HTC8675 75 ton 8x4 Hydraulic Truck Crane S/N: P9K5-4779 C/W: Air Conditioner, Automatic Transmission, Cummins ISX12 6 Cylinder Diesel Carrier Engine, Requires Diesel Exhaust Fluid, Anti Two- Block, Link Belt Load Moment Indicator, 41 ft	-	3126 6 Cylinder Diesel Carrier Engine, PAT iFlex5 Load Moment Indicator, 29 ft Minimum 95 ft Maximum Boom Length, Rooster Sheave, 26 ft to 45 ft Extendable Swingaway Offset Jib, 25 ton Capacity Johnson 3 Sheave Hook Block, 365 lb 7.7 ton Capacity Overhaul Ball, 8460 lb Counterweight Usage: 133,436 Mi Asset located in : Humble, TX
	Auxiliary Hoist, Rooster Sheave, 38 ft to 64 ft Bifold Swingaway Offset Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, Overhaul Ball, 18400 lb Counterweight, Counterweight Removal System Usage: 67,856 Mi	328	2003 Grove TMS500E 40 ton 6x4 Hydraulic Truck Crane S/N: 223655 C/W: Allison Automatic Transmission, Cat 3126 6 Cylinder Diesel Carrier Engine, Anti Two- Block, PAT Load Moment Indicator, 29 ft Minimum 95 ft Maximum Boom Length, 26 ft to 45 ft Extendable Swingaway Offset Jib, 550 Ib 25 ton Capacity 3 Sheave Hook Block, 365 lb 7.5 ton Capacity Overhaul Ball Usage: 13,850 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
329	2003 Grove TMS500E 40 ton 6x4 Hydraulic Truck Crane S/N: 223629 C/W: Allison Automatic Transmission, Cat 3126 6 Cylinder Diesel Carrier Engine, Anti Two- Block, PAT iFlex5 Load Moment Indicator, 29 ft Minimum 95 ft Maximum Boom Length, 26 ft to 45 ft Extendable Swingaway Offset Jib, 521 lb 25 ton Capacity Johnson 3 Sheave Hook Block, 7.5 ton Capacity Overhaul Ball, 8460 lb Counterweight Usage: 114,610 Mi	339	2007 Grove RT535E 4x4x4 Rough Terrain Crane S/N: 226028 C/W: Anti Two-Block, Hirschmann Load Moment Indicator, 5635 hrs Crane Operation, 6 Cylinder Diesel Engine, 32 ft Minimum 102 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 102 ft to 128 ft Swingaway Jib, 588 lb 35 ton Capacity Johnson 3 Sheave Hook Block, Overhaul Ball Usage: 5,635 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	340	2006 Grove RT535E 35 ton 4x4 Rough Terrain Crane
330			S/N: 226218 C/W: Air Conditioner, Hirschmann Load Moment Indicator, 8287 hrs Crane Operation, 2006 US EPA Label, Cummins 6 Cylinder Engine, 32 ft Minimum 102 ft Maximum Boom Length, 26 ft to 45 ft Extendable Swingaway Offset Jib, 588 lb 35 ton Capacity Johnson 3 Sheave Hook Block Usage: 8,287 Hr Asset located in: Humble, TX
	Usage: 4,590 Hr	341	2001 Terex RT335 35 ton 4x4x4 Rough Terrain
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Crane S/N: 12915 C/W: Anti Two-Block, Greer RCI 510 Load
332	 2011 Grove RT765E-2 65 ton 4x4 Rough Terrain Crane S/N: 232205 C/W: Air Conditioner, Anti Two-Block, Hirschmann iScout Load Moment Indicator, 3708 hrs Crane Operation, Cummins QSB 6 Cylinder 240 hp 6.7 L Diesel Engine, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 1252 lb 66 ton Capacity Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball Usage: 3,708 Hr Asset located in: Humble, TX 		Moment Indicator, 6 Cylinder Diesel Engine, 30 ft Minimum 94 ft Maximum Boom Length, 685 Ib 40 ton Capacity Johnson 4 Sheave Hook Block Usage: Not Available Asset located in : Humble, TX
		342A	Grove RT58D 20 ton 4x4 Rough Terrain Crane S/N: 75982 C/W: Air Conditioner, Anti Two-Block, 878 hrs Crane Operation, Cummins 6 Cylinder 5.9 L Diesel Engine, 28 ft Minimum 70 ft Maximum Boom Length, 23 ft to 23 ft Jib, 22 ton Capacity 3 Sheave Hook Block, 150 lb Overhaul Ball,
333	Terex RT665 65 ton 4x4x4 Rough Terrain Crane S/N: 16427		Rear Steer Usage: 878 Hr
	C/W: Air Conditioner, Anti Two-Block, Greer RCI		Asset located in: Humble, TX
- 227	510 Load Moment Indicator, 1354 hrs Crane Operation, Cummins QSB6.7 6 Cylinder 215 hp 6.7 L Diesel Engine, 36 ft Minimum 111 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 1204 lb 60 ton Capacity Terex 5 Sheave Hook Block, 400 lb 12 ton Capacity Overhaul Ball, 14200 lb Counterweight Usage: 1,354 Hr Asset located in: Humble, TX	342	Terex CD225 25 ton 4x4x4 Rough Terrain Crane S/N: 12287 C/W: Air Conditioner, Anti Two-Block, Greer RCI510 Load Moment Indicator, 4972 hrs Crane Operation, Cummins 4 Cylinder Diesel Engine, 30 ft Minimum 72 ft Maximum Boom Length, 26 ft to 43 ft Extendable Offset Jib, 636 Ib 25 ton Capacity Koehring 2 Sheave Hook Block, 250 lb 7 ton Capacity Overhaul Ball Usage: 4,972 Hr
337	Grove RT600E 4x4 Rough Terrain Crane S/N: 233495		Asset located in: Humble, TX
	C/W: Air Conditioner, Anti Two-Block, PAT iFlex5 Load Moment Indicator, 2013 US EPA Label, Cummins QSB6.7 6 Cylinder 173 hp 6.7 L Diesel Engine, 34 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball, Rear Steer Usage: Not Available Asset located in : Humble, TX	343	1995 Galion 15 ton 4x4x4 Rough Terrain Crane S/N: C200008U010610 C/W: Air Conditioner, Komatsu Dresser KDC 6 Cylinder Diesel Engine, 16 ft Minimum 60 ft Maximum Boom Length, 375 lb 15 ton Capacity Komatsu 2 Sheave Hook Block Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
344	2013 Broderson IC2003H 30000 lb 4x4x4 Carry Deck Crane S/N: 251913200 C/W: Anti Two-Block, Greer MG586 Load Moment Indicator, 3299 hrs Crane Operation, Diesel Engine, 12 ft Minimum 50 ft Maximum Boom Length, 16 ft Swingaway Jib, 204 lb 15 ton Capacity Johnson 2 Sheave Hook Block Usage: 3,299 Hr Asset located in: Humble, TX	349	2013 Broderson IC-80-3J 18000 lb Carry Deck Crane S/N: 65999380 C/W: Anti Two-Block, 4 Cylinder Diesel Engine, 12 ft Minimum 36 ft Maximum Boom Length, 10 ft to 10 ft Swingaway Jib, Overhaul Ball Usage: 1,471 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
345	2000 Grove YB4415XT 15 ton 4x4x4 Carry Deck Crane S/N: 221062 C/W: Anti Two-Block, Cummins 4 Cylinder 3.9 L Diesel Engine, 17 ft Minimum 40 ft Maximum Boom Length, 11 ton Capacity Crosby 1 Sheave Hook Block, 3 spd Electric Shift on Fly Transmission Usage: 5,005 Hr Asset located in: Humble, TX	350	2008 Broderson IC-80-3H 18000 lb 4x4 Carry Deck Crane S/N: 611040 C/W: Anti Two-Block, Greer MG586 Load Moment Indicator, 563 hrs Crane Operation, 4 Cylinder Diesel Engine, 12 ft Minimum 30 ft Maximum Boom Length, 10 ft Swingaway Jib, Crosby Hook Block Usage: 7,755 Hr Asset located in: Humble, TX
346	2019 Broderson IC-100-3A 10 ton 4x4x4 Carry Deck Crane S/N: 12057100 C/W: B3.3 4 Cylinder 74 hp 3.3 L Diesel Engine, 13 ft Minimum 33 ft Maximum Boom Length, 10 ft to 10 ft Swingaway Offset Jib, 122 lb 10 ton Capacity McKissick 1 Sheave Hook Block, 90 lb Overhaul Ball Usage: 1,448 Hr Asset located in: Humble, TX	351	2009 Grove YB4409-2 18000 lb Carry Deck Crane S/N: 321208 C/W: Air Conditioner, Anti Two-Block, LSI GS550 Load Moment Indicator, 1841 hrs Crane Operation, 4 Cylinder Diesel Engine, 12 ft Minimum 30 ft Maximum Boom Length, 30 ft to 48 ft Swingaway Jib, 100 lb 7 ton Capacity Johnson Hook Block Usage: 1,841 Hr Asset located in: Humble, TX
347	2014 Broderson IC-80-3J 18000 lb 4x4x4 Carry Deck Crane S/N: 68283380 C/W: Anti Two-Block, Greer MG580 Load Moment Indicator, 4206 hrs Crane Operation, 4 Cylinder 74 hp 3.3 L Diesel Engine, 11 ft Minimum 30 ft Maximum Boom Length, 10 ft to 10 ft Swingaway Jib, 122 lb 10 ton Capacity McKissick 2 Sheave Hook Block, 80 lb Overhaul Ball Usage: 4,206 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	352	2019 Broderson IC-80-3K 8.5 ton 4x4x4 Carry Deck Crane S/N: 73715080 C/W: B3.3 4 Cylinder 3.3 L Diesel Engine, 12 ft Minimum 30 ft Maximum Boom Length, 10 ft to 10 ft Offset Jib, 122 lb 10 ton Capacity McKissick 1 Sheave Hook Block, 90 lb Overhaul Ball Usage: 1,288 Hr Asset located in: Humble, TX
348	2013 Broderson IC-80-3J 18000 lb 4x4x4 Carry Deck Crane S/N: 67101580 C/W: Anti Two-Block, Greer MG586 Load Moment Indicator, 789 hrs Crane Operation, 2012 US EPA Label, Kem Power 4 Cylinder 86 hp Gasoline Engine, 12 ft Minimum 30 ft Maximum Boom Length, 10 ft Swingaway Jib, 122 lb 10 ton Capacity McKissick 1 Sheave Hook Block Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
353 Elliott 32117R 64000 lb Straight Boom on 2014 Freightliner 108SD 6x4 Boom Truck S/N: 3ALHG5CY2EDFU9850 C/W: Cummins ISL9 6 Cylinder Ultra Low Sulfur Diesel 330 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 12855 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Spring Suspension, 272 in Wheelbase, PTO, 64000 lb Capacity, Rear Mounted, 28 ft -	359	2009 Cat 325D L Foundation Drill S/N: C3N00476 C/W: Rear View Camera, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Lodrill 4 In Kelly, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 3,497 Hr Notes: LOCATED-IN-LIVINGSTON_LA SUBJECT TO LA TAX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA 2014 Ditch Witch JT30 Directional Drill	
	117 ft 5 Section Boom, McKissick 251 lb 1 Sheave 15 ton Capacity Hook Block, 170 lb Overhaul Ball 7 ton Capacity, 24 ft Swingaway Offset Jib, Greer Insight Load Moment Indicator, Out and Down Outriggers, Rear Outriggers, 5th Outrigger, 21 ft 6 in x 93 in Bed Usage: 241,402 Mi Notes : THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU	303	S/N: CMWAT30XVE0000226 C/W: Open Operator Station, 4 Cylinder Diesel Engine, Mud Mixing System, Drill Rod Loading System 13 Drill Rods, 13 in Rubber Tracks, Comes With: Ditch Witch FM13v Mud Mixing System Usage: 639 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	364	2012 Ditch Witch JT2020 Mack 1 Directional Drill S/N: CMWJ2020TC0001612 C/W: Open Operator Station, 4 Cylinder Diesel Engine, Drill Rod Loading System 38 Drill Rods, 11 in Rubber Tracks Usage: 3,977 Hr Notes: LOCATED-IN-FORT-WORTH-TX RITCHIE-
Asset located in: Humble, TX 356 2010 Hiab 144 B -3 HIDUO 9040 lb Kno		-	BROS-ENERGY Asset located in: Lake Worth, TX
	 6 2010 Hiab 144 B -3 HIDUO 9040 lb Knuckle Boom on 2011 Ford F-750 XL 4x2 Boom Truck S/N: 3FRXF7FG5BV545635 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 243 in Wheelbase, PTO, 9040 lb Capacity, Center Mounted, 5 ft - 35 ft 4 Section Boom, Out and Down Outriggers, 15 ft 10 in x 96 in Bed Usage: 45,502 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 	365	2015 Ditch Witch JT9 Directional Drill S/N: CMWJT9XXEF0000100 C/W: Open Operator Station, 2014 US EPA Label, Deutz td2.914 4 Cylinder 66 hp 2.9 L Diesel Engine, 9 in Rubber Tracks Usage: 2,248 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
		366	2021 Vermeer PD10R Crawler Mounted Post Driver S/N: 1VRR1008CM1001076 C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 26 4 kW 2 02 L Diagol Engine Remote
358 IMT 4825 6400 lb Knuckle Boo F800 4x2 Boom Truck S/N: 3FEXF8014XMA17998 C/W: Cummins ISB 6 Cylinder	S/N: 3FEXF8014XMA17998 C/W: Cummins ISB 6 Cylinder 5.9 L Diesel 215		Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks Usage: 2,152 Hr Notes : LOCATED-IN-MIDLAND-TX Asset located in : Midland, TX
	hp Engine, 1998 US EPÅ Label, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 6400 lb Capacity, Front Mounted, 7 ft 6 in - 30 ft 5 in 3 Section Boom, Dual Controls, Straight Down Outriggers, 8 ft x 96 in Bed, Winch, Pintle Hitch Usage: 107,048 Mi Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX	367	2021 Vermeer PD10R Crawler Mounted Post Driver S/N: 1VRR1008TM1001055 C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks Usage: 3,329 Hr Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX

Lot #	Details	Lot #	Details
368	2021 Vermeer PD10R Crawler Mounted Post	385	2014 Bobcat S650 Skid Steer Loader
S/N: 1VRR1008CM100105 C/W: 2020 US EPA Label, D Cylinder 36.4 kW 2.92 L Die	Driver S/N: 1VRR1008CM1001054 C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks		S/N: ALJ811941 C/W: Open Operator Station, 2014 US EPA Label, Manual Coupler, 73 in Bucket Usage: 6,028 Hr Asset located in : Humble, TX
	Usage: 2,869 Hr	387	2021 Bobcat S66 Two-Speed Skid Steer Loader
	Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	_	S/N: B4SA11821 C/W: Open Operator Station, 2020 US EPA
369	2021 Vermeer PD10R Crawler Mounted Post Driver		Label, Manual Coupler Usage: 2,088 Hr
	S/N: 1VRR1008LM1001051		Asset located in: Humble, TX
	C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks Usage: 4,084 Hr Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	388	2020 Bobcat S570 Skid Steer Loader S/N: ALM429801 C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 61 in Bucket Usage: 1,484 Hr Asset located in: Humble, TX
370	2012 Vermeer RT450 4x4 Trencher	389	2013 Bobcat S570 Skid Steer Loader
S/N: 1VRX C/W: Canc 5.5 in Wide Trencher C Straight Bl	S/N: 1VRX07217C1000145 C/W: Canopy, Diesel Engine, Hydrostatic Drive, 5.5 in Wide x 6 ft 5 in Long Combination Trencher Chain, Vermeer Backhoe Attachment, Straight Blade, Side Shift Usage: 2,286 Hr		S/N: A7U711635 C/W: Open Operator Station, Aperture Tires, Manual Coupler, Forks Usage: 880 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE	391	2022 Cat 226D3 Skid Steer Loader
THE INSPECTION REPORT		S/N: CAT0226DVEK501311 C/W: Enclosed Cab, Air Conditioner, Air Ride	
071	Asset located in: Humble, TX	-	Seat, Joystick Steering, 14 Pin Electric Kit,
	2007 Ditch Witch RT-40 4x4 Trencher S/N: CMWRT40XK70002016		Manual Coupler, 67 in Bucket Usage: 1,662 Hr
	C/W: 2007 US EPA Label, Deutz D2011L03 3		Asset located in: Humble, TX
Cylinder 31.5 kW 2.33 L Diesel Engine, Hydrostatic Drive, 5.5 in Wide x 5 ft Long A322 Backhoe Attachment, Angle Blade, Discharge Conveyor, Side Shift Usage: 330 Hr	392	2022 Cat 226D3 Skid Steer Loader S/N: CAT0226DEEK501234 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Manual Coupler, 68 in Bucket, Water	
	Asset located in: Humble, TX		System Usage: 1,628 Hr
381	2007 Mauldin 1750C Track Asphalt Paver		Asset located in: Humble, TX
	S/N: 879G75TJS6Y201879 C/W: Dual Controls, Propane Heated 7 ft 6 in - 16 ft Screed, 12 in Track Shoes w/Rubber Pads	393	2022 Cat 226D3 Skid Steer Loader S/N: CAT0226DTEK501124
	Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Manual Coupler, 73 in Bucket Usage: 1,950 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
382	2017 Case SV340 Skid Steer Loader	395	2010 Bobcat S130 Skid Steer Loader
	S/N: JAFSV340KHM440423 C/W: Enclosed Cab (Door missing), Joystick Steering, Hydraulic Coupler, Forks Usage: 5,253 Hr		S/N: A3KY37368 C/W: Enclosed Cab, Aperture Tires, Manual Coupler, 72 in Grapple Bucket, Grapple, Extra Bucket 67" Usage: 5,901 Hr
	Asset located in: Humble, TX	-	Notes: DEFICIENCIES NOTED - PLEASE SEE
384	2017 Case SV340 Skid Steer Loader		
	S/N: JAFSV340CHM437811 C/W: Enclosed Cab (Door missing), Joystick		Asset located in: Humble, TX
Steering, Hydraulic Coupler Usage: 1,733 Hr Asset located in : Humble, TX	396	2007 John Deere 325 Skid Steer Loader S/N: T00325A144100 C/W: Open Operator Station, 77 in Bucket, Counterweight Kit Usage: 566 Hr	
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
397	2007 John Deere 325 Skid Steer Loader S/N: T00325A143484 C/W: Open Operator Station, Manual Coupler, 74 in Bucket, Counterweight Kit Usage: 10,117 Hr Asset located in: Humble, TX	406	2024 Cat 299D3XE Two-Speed Compact Track Loader S/N: CAT299D3HB6203289 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, 18 in Track
398	2006 John Deere 325 Skid Steer Loader S/N: T00325A130381 C/W: Open Operator Station, Manual Coupler, 73 in Bucket, Counterweight Kit Usage: 9,932 Hr Asset located in: Humble, TX		Belts, 9 Pin Electric Kit, Manual Coupler, Counterweight Kit Usage: 20 Hr Notes : NO WARRANTY AVAILABLE; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
399	2000 John Deere 260 Two-Speed Skid Steer	407	2024 Cat 299D3 XE Two-Speed Compact Track
	Loader S/N: KV0260B261674 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 72 in Bucket Usage: 519 Hr Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA		Loader S/N: CAT299D3HB6203292 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Manual Coupler, Counterweight Kit Usage: 4 Hr Notes: NO WARRANTY AVAILABLE Asset located in: Humble, TX
400	2005 Cat 252B Skid Steer Loader	408	2019 Cat 299D2 Two-Speed High Flow XPS
	S/N: CAT0252BASCP01005 C/W: Enclosed Cab, Joystick Steering, Aperture Tires, 8 Pin Electric Kit, Manual Coupler, 79 in Bucket Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Compact Track Loader S/N: CAT0299DEFD204748 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Self Leveling, Rear View Camera, Requires Diesel Exhaust Fluid, 18 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 80 in Bucket Usage: 3,332 Hr Asset located in: Humble, TX
401	2006 Volvo MC80B Skid Steer Loader	400	
401	S/N: VCEMC80B06112300 C/W: Open Operator Station, 2005 US EPA Label, Aperture Tires, Manual Coupler Usage: 1,271 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	409	2022 Takeuchi TL12R2 Two-Speed High Flow Compact Track Loader S/N: 412105204 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Self Leveling, Rear View Camera, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Hydraulic Coupler, 84 in Bucket
402	2005 Cat 246B Skid Steer Loader	1	Usage: Not Available
102	S/N: CAT0246BTPAT01833 C/W: Enclosed Cab, Joystick Steering, 2004 US EPA Label, Aperture Tires, Manual Coupler, 73	411	Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2022 Takeuchi TL12R2 Compact Track Loader
	in Bucket, Forks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 412103401 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, 14 Pin Electric Kit, Hydraulic
404	2001 Bobcat 773 Skid Steer Loader		Coupler, 72 in Bucket Usage: 3,366 Hr
	S/N: 519020214 C/W: Open Operator Station, 2001 US EPA Label, Aperture Tires, Manual Coupler, 16 in Digging, Backhoe Usage: 1,853 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	412	Asset located in: Humble, TX 2021 Bobcat T76 Compact Track Loader S/N: B4CE14357 C/W: Open Operator Station, Joystick Steering, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 996 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
413	2021 Bobcat T76 Compact Track Loader S/N: B4CE14353	421	2019 Cat 289D3 Two-Speed Compact Track Loader
	C/W: Open Operator Station, Joystick Steering, US EPA Label, 12 in Track Belts, Manual Coupler, 79 in Usage: 1,105 Hr		S/N: CAT0289DKJX902266 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 17 in Track Belts, Manual
	Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.		Coupler, 79 in Bucket Usage: 4,129 Hr Notes : LOCATED-IN-FORT-WORTH-TX
	Asset located in: Lake Worth, TX	_	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
414	2021 Bobcat T76 Compact Track Loader S/N: B4CE15366		Asset located in: Lake Worth, TX
	C/W: Open Operator Station, Joystick Steering, US EPA Label, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 1,133 Hr Notes : LOCATED-IN-FORT-WORTH-TX; COMES	422	2014 Cat 289D Two-Speed High Flow XPS Compact Track Loader S/N: CAT0289DLTAW01963 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2014 US EPA Label, 18 in
	WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.		Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, Forks, EQUIPMENT-FROM-A-
	Asset located in: Lake Worth, TX	_	PRIMORIS-SERVICES-CORP-COMPANY Usage: 5,742 Hr
415	2016 John Deere 333G Two-Speed Compact Track Loader		Asset located in: Humble, TX
S/N: 1T0333GKVGF303710 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Pattern Changer, Requires Diesel Exhaust Fluid, 18 in Track Belts, 7 Pin Electric Kit, Hydraulic Coupler, 83 in Bucket, Counterweight Kit Usage: 3,995 Hr	424	2019 Case TV450 Compact Track Loader S/N: NKM470236 C/W: Open Operator Station, 17.5 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 77 in Bucket Usage: 1,622 Hr Asset located in: Humble, TX	
	Asset located in: Humble, TX	425	2019 Bobcat T770 Compact Track Loader
416 2012 John Deere 333D Two-Speed Con Track Loader S/N: 1T0333DMPCD232059 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control	S/N: 1T0333DMPCD232059 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Pattern Changer, 18 in Track Belts, 7 Pin Electric Kit,		S/N: AT6321907 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Manual Coupler, 67 in Bucket Usage: 2,566 Hr Asset located in: Humble, TX
	Hydraulic Coupler, 67 in Bucket, Counterweight Kit	426	2014 Bobcat T770 Two-Speed Compact Track
	Usage: 4,322 Hr Asset located in : Humble, TX		Loader S/N: AN8T13652
417	2017 John Deere 331G Two-Speed Compact Track Loader		C/W: Open Operator Station, 17 in Track Be Manual Coupler, 78 in Bucket Usage: 4,311 Hr
	S/N: 1T0331GMCHF311899 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Requires		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 83 in Bucket	428A	2022 Takeuchi TL10V2 Compact Track Loader
	Usage: 3,339 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 410005232 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Tier 4, 2021 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 76 in Bucket
	Asset located in: Humble, TX		
418	2020 Cat 289D3 Two-Speed Compact Track		Usage: Not Available
	Loader S/N: CAT0289DCJX901413		Notes: LOCATED-IN-MIDLAND-TX
C/W: Open C Tier 4, 2020 Manual Cou Usage: 3,285	C/W: Open Operator Station, Joystick Steering, Tier 4, 2020 US EPA Label, 17.5 in Track Belts, Manual Coupler, 78 in Bucket, Forks Usage: 3,285 Hr Asset located in: Humble, TX	428	Asset located in: Midland, TX 2011 Takeuchi TL240 Series 2 Compact Track Loader S/N: 224001342 C/W: Open Operator Station, Joystick Steering, 2011 US EPA Label, 17 in Track Belts, 14 Pin Electric Kit, 75 in Bucket Usage: 2,601 Hr
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
429	2017 Takeuchi TL10V2-CR Compact Track Loader S/N: 410000418 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Tier 4, 2016 US EPA Label, 14 in Track Belts, Manual Coupler, 66 in Bucket Usage: 63 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	439	2019 Cat 259 D3 Two-Speed Compact Track Loader S/N: CAT0259DPCW901608 C/W: Open Operator Station, Joystick Steering, Tier 4, 2023 US EPA Label, 15.5 in Track Belts, Manual Coupler, 80 in Bucket, Forks Usage: 2,314 Hr Asset located in: Humble, TX
		440	2018 Cat 259D Two-Speed Compact Track Loader
431	Asset located in: Humble, TX 2021 Cat 279D3 Two-Speed Compact Track Loader S/N: CAT0279DHRB903137 C/W: Open Operator Station, Joystick Steering, 2021 US EPA Label, 17.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 79 in Bucket Usage: 1,117 Hr	442	S/N: CAT0259DVFTL18483 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2018 US EPA Label, 16 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler Usage: 1,993 Hr Asset located in: Humble, TX 2021 Bobcat T64 R-Series Compact Track Loader
	Asset located in: Humble, TX		
432	2013 Cat 279C2 Two-Speed Compact Track Loader S/N: CAT0279CJKWB0075 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, 8 Pin Electric Kit, Manual Coupler, 80 in Bucket Usage: 4,273 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: B4SD12335 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,234 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
	Asset located in: Humble, TX		
433	2018 Case TV370 Compact Track Loader S/N: JAFTV370PJM448767 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 3,055 Hr Asset located in: Humble, TX 2017 Kubota SVL75-2 Compact Track Loader	_443	2021 Bobcat T64 R-Series Compact Track Loader S/N: B4SD13060 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,300 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO
	S/N: JKUCC752A01S30020 C/W: Open Operator Station, Joystick Steering, 15.5 in Track Belts, Manual Coupler		TEXAS SALES TAX. Asset located in: Lake Worth, TX
	Usage: 2,315 Hr	444	2021 Bobcat T64 Compact Track Loader
437	Asset located in: Humble, TX 2020 Bobcat T66 Compact Track Loader S/N: B4SB11862 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, 12 in Track Belts, 7 Pin Electric Kit, Manual Coupler, 75 in Bucket, Counterweight Kit Usage: 1,400 Hr Notes: LOCATED-IN-FORT-WORTH-TX	_	S/N: B4SD12333 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,248 Hr Notes : LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in : Lake Worth, TX
	Asset located in: Lake Worth, TX	445	2021 Bobcat T64 Compact Track Loader
438	2022 Cat 259 D3 Two-Speed High Flow Compact Track Loader S/N: CW916472 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Self Leveling, Rear View Camera, 2021 US EPA Label, 15.5 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 79 in Bucket Usage: 1,362 Hr Asset located in: Humble, TX		S/N: B4SD12390 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 73 in Bucket Usage: 1,341 Hr Notes : LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
446	2019 Bobcat T630 High Flow Compact Track Loader S/N: AJDT16716 C/W: Enclosed Cab (Door missing), Joystick Steering, 2019 US EPA Label, 15.5 in Track Belts, Manual Coupler, 77 in Bucket Usage: 1,455 Hr	461	2008 Bobcat T190 Compact Track Loader S/N: A3LN12027 C/W: Open Operator Station, 13 in Track Belts, Manual Coupler Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	462	2008 Bobcat T140 Compact Track Loader
447	2014 Bobcat T630 Compact Track Loader S/N: AJDT11279 C/W: Open Operator Station, 2014 US EPA Label, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 3,812 Hr		S/N: 529312573 C/W: Enclosed Cab (Door missing), Tier 2, 2015 US EPA Label, 12 in Track Belts, Manual Coupler, 66 in Usage: 6,414 Mi Asset located in : Humble, TX
440	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	463	2006 ASV RC30 Compact Track Loader S/N: RSA02549 C/W: Open Operator Station, Joystick Steering, 9 in Track Belts, Manual Coupler, 48 in Bucket Usage: 1,586 Hr
449	2016 Takeuchi TL8 Compact Track Loader S/N: 200803826		Asset located in: Humble, TX
	C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 15 in Track Belts, 14 Pin Electric Kit, Manual Coupler Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	464	2004 ASV RC30 Compact Track Loader S/N: RSA02171 C/W: Open Operator Station, Joystick Steering, 9 in Track Belts, Manual Coupler, 48 in Bucket Usage: 1,873 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	465	Mahindra 2555ST 4WD Utility Tractor
451	2011 Takeuchi TL230 Series 2 Compact Track Loader S/N: 223100502 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2011 US EPA Label, 12.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 72 in Bucket Usage: Not Available Asset located in: Humble, TX	400	S/N: 55GCJ00311 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, Forward/ Reverse Shuttle, Mahindra 2555CL Loader w /Joystick, Quick Coupler, 1 Rear Remotes, 540 PTO, 3-Point Hitch, 12x16.5 Front Tires, 16.9 x24 Rear Tires Usage: 415 Hr Asset located in: Humble, TX
458	2011 Cat 259B3 Two-Speed Compact Track	467	2019 John Deere 5045E 2WD Utility Tractor
	Loader S/N: CAT0259BCYYZ01297 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, 67 in Bucket Usage: 6,817 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	407	S/N: 1PY5045ELKK108917 C/W: Differential Lock, 2019 US EPA Label, John Deere 512 Loader, Quick Coupler, 74 in Bucket, 2 Mid-Mount Remotes, 1 Rear Remotes, 540 PTO, 3-Point Hitch w/ Quick Hitch, Frontier RC2072 72 in Mower, 7.50-16 Front Tires, 14.9-28 Rear Tires Usage: 1,136 Hr
459	2008 Takeuchi TL140 Compact Track Loader	-	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
105	S/N: 21406595		Asset located in: Humble, TX
	C/W: Open Operator Station, Joystick Steering, 17 in Track Belts, Manual Coupler, 73 in Bucket Usage: 794 Hr Asset located in : Humble, TX	468	2020 LS XR3135 4WD Utility Tractor S/N: 2259001198 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 12 Forward 12 Reverse,
460	2005 ASV RC100 R-Series Compact Track Loader S/N: RSD01507 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, 18 in Track Belts, 8 Pin Electric Kit, Hydraulic Coupler, 72 in Bucket Usage: 1,748 Hr Asset located in: Humble, TX		Manual Transmission, 35 hp Engine, LS Loader w/Joystick, Quick Coupler, 66 in Bucket, 2 Rear Remotes, Exterior 3-Point Hitch Controls, 540 PTO, 3-Point Hitch, 7-14 Front Tires, 11.2x24 Rear Tires Usage: 40 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
469 470	1991 John Deere 1070 2WD Utility Tractor S/N: M01070A105151 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, 540 PTO, 3-Point Hitch, 62 in Mower, 6.50-16 Front Tires, 13.6-28 Rear Tires Usage: 568 Hr Asset located in: Humble, TX 2016 John Deere 3032E 4WD Utility Tractor	476A	2006 John Deere 5525 2WD Tractor (Inoperable) S/N: LV5525T252147 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncShuttle, 2006 US EPA Label, 2 Rear Remotes, 540 PTO, Drawbar, 11L-15 Front Tires, 480/80R30 Rear Tires, Rear Wheel Weights
470	S/N: 1LV3032EJGG106774 C/W: Canopy, Hydrostatic Drive, John Deere D160 Loader w/Joystick, Quick Coupler, John Deere 63 in Bucket, 540 PTO, 3-Point Hitch, Frontier BB5072 72 in Box Blade, 25x8.50-14 Front Tires, 15x19.5 Rear Tires Usage: 1,032 Hr Asset located in: Humble, TX		Usage: 6,688 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
471	Kubota L2900GST 4WD Utility Tractor S/N: 64654 C/W: Canopy, 8 Forward 8 Reverse, Glide Shift, 32 hp Engine, Kubota LA482 Loader w /Joystick, 60 in Bucket, 540 PTO, 3-Point Hitch, drawbar, 7-16 Front Tires, 12.4x24 Rear Tires Usage: 1,016 Hr Asset located in: Humble, TX	⁻ 478	2006 John Deere 5303 2WD Tractor S/N: PYS5303U005344 C/W: Canopy, 9 Forward 3 Reverse, SyncReverser, 1 Rear Remotes, 540 PTO, Drawbar, 7.50-16 Front Tires, 16.9-28 Rear Tires Usage: 2,289 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
472	2016 Kubota BX2670 4WD Utility Tractor	1	Asset located in: Humble, TX
473	S/N: 25840 C/W: Differential Lock, Hydrostatic Drive, 2015 US EPA Label, Kubota LA243 Loader w /Joystick, 48 in Bucket, 60 in Mower Deck, 540 PTO, 3-Point Hitch, 18x8.50-10 Front Tires, 26x12.00-12 Rear Tires Usage: 140 Hr Asset located in: Humble, TX 2020 Kubota L2501D 4WD Utility Tractor	479	Mahindra 4540 2WD Tractor S/N: MBCNY2140 C/W: Differential Lock, 8 Forward 2 Reverse, Manual Transmission, Mahindra 4550-2L Loader w/Joystick, 59 in Bucket, 540 PTO, 3- Point Hitch, 225/90/16 Front Tires, 12.4x28 Rear Tires Usage: 417 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
470	S/N: KBUL6DDRHL8GA5665		Asset located in: Humble, TX
	C/W: Differential Lock, 8 Forward 4 Reverse, Manual Transmission, 2020 US EPA Label, Kubota LA526 Loader w/Joystick, Quick Coupler, Kubota L2248 66 in Bucket, HID Lights, 540 PTO, 3-Point Hitch, Drawbar, 7.2-16 Front Tires, 11.2x24 Rear Tires Usage: 392 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	481B	2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MANM104105 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, PowrReverser, Forward/ Reverse Shuttle, 2022 US EPA Label, Requires Diesel Exhaust Fluid, John Deere 540M Loader w /Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, 320/85R24 Front Tires, 460/85R30 Rear Tires
474	S/N: 18326 C/W: Manual Transmission, 540 PTO, 18x8.50- 8 Front Tires, 29x12.50-15 Rear Tires		Usage: 2,153 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	481A	2022 John Deere 5100M 4WD Tractor
		1	S/N: 1LV5100MHNM104107 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, Forward/ Reverse Shuttle, 2023 US EPA Label, Requires Diesel Exhaust Fluid, John Deere 540M Loader w/Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, Drawbar, 320 /85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,182 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
481	2022 Case IH Farmall 120C 4WD Tractor S/N: ELRFC120ENLF50113 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, Forward/ Reverse Shuttle, Case IH L630 Loader w /Joystick, Skid Steer Coupler, 84 in Bucket, 1 Front Remotes, 3 Rear Remotes, 540 PTO, 3- Point Hitch, Drawbar, 380/85R24 Front Tires, 460/85R34 Rear Tires	486	Hyster H190HD 17500 lb Pneumatic Tire Forklift S/N: H007E02563H C/W: 2 Stage Mast, 212 in Max Lift Height, 156 in Lowered Mast Height, 92 in Forks, Side Shift, Cummins 6 Cylinder Diesel Engine Usage: 10,098 Hr Asset located in: Humble, TX	
	Usage: 222 Hr Asset located in: Humble, TX	487	2014 Sellick S80J4I-2 8000 lb 4x4 Rough Terrain Forklift	
482	2018 John Deere 5065E 4WD Tractor S/N: 1PY5065EKJJ402021 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, PowrReverser, Forward/ Reverse Shuttle, John Deere 520M Loader w/Joystick, Quick Coupler, John Deere 70 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, Frontier LP1207 88 in Scraper Blade, 9.5x24 Front Tires, 16.9-28 Rear Tires,		S/N: 9135402S8J4T C/W: Enclosed Cab, Single Stage Mast Max Lift Height, 24 in Lowered Mast He in Forks, Auxiliary Hydraulic Plumbing, 2 EPA Label, Diesel Engine Usage: 11,227 Hr Notes: LOCATED-IN-FORT-WORTH-TX	S/N: 9135402S8J4T C/W: Enclosed Cab, Single Stage Mast 144 in Max Lift Height, 24 in Lowered Mast Height, 60 in Forks, Auxiliary Hydraulic Plumbing, 2014 US EPA Label, Diesel Engine Usage: 11,227 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	48 in Forks, Hay Baler, Post Hole Auger Usage: 2,713 Hr	400.4	Asset located in: Lake Worth, TX	
483	Asset located in: Humble, TX 1999 Hyster H1050E 88000 lb Container	488A	2008 Maximal 35M 7715 lb 4x4 Rough Terrain Forklift S/N: 1503501315	
	Handler S/N: D117E01627W C/W: Enclosed Cab, Air Conditioner, 498 in Max Lift Height, 1998 US EPA Label, Cummins M11- C 6 Cylinder 290 hp 11.0 L Diesel Engine Usage: 3,587 Hr		C/W: 3 Stage Mast, Full Free Lift, 119 in Lowered Mast Height, 72 in Forks, Side Shift, 4 Cylinder Diesel Engine Usage: 3,551 Hr Asset located in: Humble, TX	
		180	Cat RC60 6000 lb 4x2 Rough Terrain Forklift	
484	Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Kalmar DCG100-6T 22000 lb Pneumatic	489	S/N: 31A00998 C/W: 2 Stage Mast, 168 in Max Lift Height, 117 in Lowered Mast Height, 45 in Forks, Cat 4 Cylinder Diesel Engine Usage: 23,716 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	
	Tire Forklift S/N: B40500208		THE INSPECTION REPORT Asset located in: Humble, TX	
	C/W: Enclosed Cab, Air Conditioner, Single Stage Mast 4750 mm Max Lift Height, 154 in	490	2018 JCB 51256S Telehandler	
Lowered N Fork Posit US EPA La 105 kW Dio Fluid Usage: 12,	Lowered Mast Height, 91 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, CARB Compliant, Volvo penta 105 kW Diesel Engine, Requires Diesel Exhaust Fluid Usage: 12,598 Hr Asset located in : Humble, TX	490	S/N: JCB5CH2GTJ2754241 C/W: Enclosed Cab, Air Conditioner, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 3,507 Hr	
485	Taylor Y-18-WOM 18000 lb Pneumatic Tire		Asset located in: Humble, TX	
	Forklift S/N: S2611690 C/W: 2 Stage Mast, 117 in Lowered Mast Height, 72 in Forks, Side Shift, Ford 6 Cylinder Gasoline Engine Usage: 5,539 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	491	2012 Genie 1256T Telehandler S/N: CPTJTCN0493 C/W: Open Operator Station, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 4,149 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
492	2018 Cat TL1255D Telehandler S/N: ML701156 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 56 in Forks, Tilt Carriage, Hydraulic Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 6,926 Hr	500	2017 Skyjack SJ1056 Telehandler S/N: 87310357 C/W: Open Operator Station, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 2016 US EPA Label, 72 in Forks, Outriggers, Frame Leveling, 13.00-24 Aperture Tires Usage: 3,348 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	501	2015 Genie GTH-1056 Telehandler
493	2018 JLG 1255 Telehandler S/N: 0160086565 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 71 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75- 28 Tires Usage: 4,911 Hr Asset located in: Humble, TX		S/N: GTH1015E-11010 C/W: Open Operator Station, Air Ride Seat, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 96 in Forks, Outriggers, Frame Leveling, 14.00- 24 Aperture Tires Usage: 3,645 Hr Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Lake Worth, TX
495	2017 JLG 1255 Telehandler S/N: 160082036 C/W: Open Operator Station, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 1,486 Hr Asset located in: Humble, TX	-502	2019 Xtreme XR1055 Telehandler S/N: XR105511190594419 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 9,654 Hr Asset located in: Humble, TX
496	2017 JLG 1255 Telehandler S/N: 0160082037 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2017 US EPA Label, 60 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 4.00/75-28 Tires Usage: 1,721 Hr Asset located in: Humble, TX	504	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90868 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 59 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 2,416 Hr Asset located in: Humble, TX
497	2017 JLG 1255 Telehandler S/N: 0160082038 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 70 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 2,088 Hr Asset located in: Humble, TX	506	2014 Gehl RS10-55 Telehandler S/N: RS1055JF0990472 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, 14.00-24 Foam Filled Tires Usage: 3,949 Hr Asset located in: Humble, TX 2017 JLG 10054 Telehandler
498	2012 Cat TL1255 Telehandler S/N: TBN01043 C/W: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 58 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 6,744 Hr Notes: LOCATED-IN-FORT-WORTH-TX	507	S/N: 0160083016 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 2,379 Hr Asset located in: Humble, TX
499	Asset located in: Lake Worth, TX 2005 JLG 1255 Telehandler S/N: 0160016005 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, 17.5-25 Tires Usage: 1,493 Hr Asset located in: Humble, TX	508	2016 JLG 10054 Telehandler S/N: 0160077170 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 71 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 5,630 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
509	2015 JLG 10054 Telehandler S/N: 0160070116 C/W: Open Operator Station, Air Ride Seat, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 47.5 in Forks, Manual Coupler, 17.5-25 Tires Usage: 6,092 Hr	520	Ingersol Rand VR843 Telehandler S/N: 158070 C/W: Open Operator Station, 43 ft 1 in Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 6,462 Hr Asset located in: Humble, TX	
	Asset located in: Humble, TX	521	2017 Gehl RS8-42 Telehandler	
510	2017 SkyTrak 10054 Telehandler S/N: 0160083012 C/W: Open Operator Station, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 2,996 Hr Asset located in: Humble, TX		S/N: RS842CJ18035 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 60 in Forks Usage: 3,189 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
511	2016 SkyTrak 10054 Telehandler S/N: 0160073991 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 3,995 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	- 522 523	2017 JLG 8042 Telehandler S/N: 0160082629 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 3,835 Hr Asset located in: Humble, TX 2014 JLG 8042 Telehandler	
	Asset located in: Humble, TX		S/N: 0160063819	
512	2016 SkyTrak 10054 Telehandler S/N: 0160074014 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 4,382 Hr		C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2014 US EPA Label, 46 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Foam Filled Tires Usage: 4,224 Hr Asset located in : Humble, TX	
	Asset located in: Humble, TX	524	2015 SkyTrak 8042 Telehandler	
515	2003 SkyTrak 10054 Telehandler S/N: 19899 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2003 US EPA Label, 50 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic	S/N: 0160065776 C/W: Open Operat Height, 8000 lb Ma Frame Leveling, 3 Usage: 10,625 Hr	C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, 370/75-28 Tires	
	Plumbing, 17.5-25 Foam Filled Tires Usage: 2,844 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE	525	2015 SkyTrak 8042 Telehandler S/N: 0160070992 C/W: Open Operator Station, 42 ft Max Lift	
	THE INSPECTION REPORT	- C F U 528 2 S C F	Height, 8000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Manual	
517	Asset located in: Humble, TX 2015 Terex GTH844 Telehandler S/N: GTH0815-20941 C/W: Open Operator Station, 44 ft Max Lift		– Coupler, Frame Leveling, Auxiliary Hydra Plumbing, 15.5-25 Foam Filled Tires Usage: 282 Hr	Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Foam Filled Tires
	Height, 8000 lb Max Lift Capacity, 2014 US EPA Label, 60 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 2,767 Hr Asset located in : Humble, TX		2014 SkyTrak 8042 Telehandler S/N: 0160056453 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Frame Leveling,	
519	2018 Skyjack SJ843TH Telehandler S/N: 87111644 C/W: Enclosed Cab, 43 ft Max Lift Height, 8000 Ib Max Lift Capacity, 2018 US EPA Label, 48 in Forks, Frame Leveling, 13.00-24 Aperture Tires Usage: 1,521 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
531	2016 JLG 6042 Telehandler S/N: 0160077805 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 2,618 Hr Asset located in: Humble, TX	538	2013 JLG 6042 Telehandler S/N: 160056111 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 96 in Forks, Frame Leveling, 13.00- 24 Tires Usage: 4,196 Hr Asset located in: Humble, TX
532	2016 JLG 6042 Telehandler S/N: 0160076414 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires Usage: 3,312 Hr Asset located in: Humble, TX	540	2013 SkyTrak 6042L Telehandler S/N: 160056198 C/W: Open Operator Station, 71.5 in Forks, Manual Coupler, Frame Leveling Usage: 4,295 Hr Asset located in: Humble, TX 2012 SkyTrak 6042L Telehandler
533	2016 JLG 6042 Telehandler S/N: 0160073484 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: Not Available	-	S/N: 0160045502 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: 3,945 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
534	Asset located in: Humble, TX 2014 JLG 6042 Telehandler S/N: 0160056113 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 3,680 Hr Asset located in: Humble, TX	542	2012 SkyTrak 6042L Telehandler S/N: 0160045729 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 44 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
535	2013 JLG 6042 Telehandler S/N: 0160050487 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 48 in Forks, Frame Leveling, 13.00- 24 Tires Usage: Not Available Asset located in: Humble, TX	543	Asset located in: Humble, TX 2014 Gehl RS6-42 Telehandler S/N: RS642JF0714865 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Frame Leveling, 13.00- 24 Tires Usage: 2,501 Hr
536	2013 JLG 6042 Telehandler S/N: 0160054638 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, Tier 4, 2014 US EPA Label, 72 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 3,291 Hr Asset located in: Humble, TX	544	Asset located in: Humble, TX 2008 SkyTrak 6042 Telehandler S/N: 0160033198 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2007 US EPA Label, 47 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 4,109 Hr
537	2013 JLG 6042 Telehandler S/N: 0160054824 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, 13.00-24 Tires Usage: 4,812 Hr Asset located in: Humble, TX	545	Asset located in: Humble, TX 2019 Genie GTH-636 Telehandler S/N: GTH06E-12719 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 2019 US EPA Label, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 330/85. 28 Tires Usage: 1,504 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
546	2015 Genie GTH-636 Telehandler S/N: GTH0615H10192 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 2015 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00- 28 Tires Usage: 2,964 Hr	557	2014 Gehl RS5-19 Telehandler S/N: RS519YF0751114 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, 12- 16.5 Foam Filled Tires Usage: 4,484 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	558	2014 Gehl RS5-19 Telehandler
551	2006 Genie GTH-6622 Telehandler S/N: 15022 C/W: Open Operator Station, 6600 lb Max Lift Capacity, 2006 US EPA Label, 47 in Forks, Hydraulic Coupler, 405/70R20 Tires Usage: 3,789 Hr		S/N: RS519YF0751120 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, 12-16.5 Tires Usage: 4,109 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	559A	Blaw-Knox CB-90 Self-Propelled Broom
552	Asset located in: Humble, TX 1998 JCB 506C Telehandler S/N: SLP506COWE0585392 C/W: Open Operator Station, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame	-	S/N: 86295 C/W: Enclosed Cab, Air Conditioner, 7 ft 9 in Broom, Water System, Tier 3, Kubota 4 Cylinder 3.6 L Diesel Engine Usage: 2,153 Hr Asset located in : Humble, TX
	Leveling, 13.00-24 Tires Usage: 6,893 Hr	560	Broce BW260 Self-Propelled Broom
	Asset located in: Humble, TX		S/N: 202477
553	2021 Skyjack SJ519TH Telehandler S/N: 87500476 C/W: Open Operator Station, 19 ft 1 in Max Lift	-	C/W: Open Operator Station, 8 ft 4 in Broom, Water System, Kubota 4 Cylinder Diesel Engine Usage: 23 Hr Asset located in : Humble, TX
	Height, 5500 lb Max Lift Capacity, 2019 US EPA Label, 47 in Forks, Manual Coupler, Aperture Tires Usage: 700 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	561	561 Broce BW-260 Self-Propelled Broom S/N: 202473 C/W: Open Operator Station, 8 ft Broom, Wat System, 2020 US EPA Label, Kubota V1505 4 Cylinder 18.2 kW 1.5 L Diesel Engine Usage: Not Available
554	2021 Genie GTH-5519 Telehandler	1	Asset located in: Humble, TX
	S/N: GTH55M12836 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2021 US EPA Label, 47 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: Not Available Asset located in : Humble, TX	567	2013 Lay-Mor SM300 Self-Propelled Broom S/N: 34422 C/W: Open Operator Station, 7 ft 9 in Broom, Water System, 2012 US EPA Label, Kubota 4 Cylinder 1.5 L Diesel Engine Usage: 1,034 Hr Asset located in: Humble, TX
555	2017 Genie GTH-5519 Telehandler S/N: GTH55M7090 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2017 US EPA Label, 48 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 531 Hr Asset located in: Humble, TX	568	Elgin Broom Badger on 2020 Isuzu NRR Sweeper Truck S/N: JALE5W169L7306072 C/W: Isuzu 4HK1TC 5.2 L Diesel 210 hp Engine 2019 US EPA Label, 4817 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Air Ride Suspension, 110 in Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, 60 in Rear Broom, Gutter Brooms, Water System, Hydraulic Dump, Rear-View Camera Usage: 65,975 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
556	2014 Gehl RS5-19 Telehandler S/N: RS519YF0351063 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 46 in Forks, 12-16.5 Tires Usage: 3,964 Hr Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
569	Tymco 600 on 2004 Freightliner FC80 Sweeper Truck S/N: 1FVAB6BV34DN04457 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel Engine, Automatic Transmission, 12000 Ib Front Axle, 21000 Ib Rears, 33000 Ib GVWR, 11R22.5, Spring Suspension, 144 in Wheelbase, PTO, John Deere Auxiliary Engine, Regenerative Air, Dual Controls, Front Spray Bar, 96 in Under Body Broom, Gutter Brooms, Water System, Hydraulic Dump Usage: 41,127 Mi	574A	2010 Ford F-350 XL 4x2 Extended Cab Utility Truck S/N: 1FTWX3AR0AEA55282 C/W: Ford V8 6.4 L Diesel Engine, Automatic Transmission, 5000 lb Front Axle, 6693 lb Rears, 11000 lb GVWR, 275/65R18, Spring Suspension, 158 in Wheelbase, Stahl 8 ft 2 in Body Usage: 140,913 Mi Notes: TITLE BRAND "NOT ACTUAL MILEAGE" Asset located in: Humble, TX
	Notes: ODOMETER DISCREPANCY UNIT SHOWS 41,127, TITLE SHOWS 42,909	574	2013 Chevrolet Silverado 3500HD 4x2 Utility Truck
571A	Asset located in: Humble, TX 2012 Ford F-550 XL 4x2 Utility Truck S/N: 1FDUF5GT9CEB18399 C/W: Ford 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Knapheide 11 ft Body Usage: 215,721 Mi		S/N: 1GB3CZCGXDF128268 C/W: GM L96 6.0 L Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 138 in Wheelbase, 9 ft Body Usage: 234,877 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	575	2009 Chevrolet Silverado 3500HD 4x2 Extended Cab Utility Truck S/N: 1GBJC79K39E126737
571	2012 Ford F-550 Lariat 4x4 Crew Cab Utility Truck S/N: 1FD0W5HT9CED07485 C/W: 6 Cylinder 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Aluminum Outer Wheels, 225/70R19.5, Spring		C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 8600 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 162 in Wheelbase, Omaha 9 ft Body Usage: 260,590 Mi Asset located in : Humble, TX
	Suspension, 176 in Wheelbase, 2012 ROYAL TRUCK BODY 9 ft 11 in Body Usage: 166,544 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		2006 Ford F-350 4x2 Utility Truck S/N: 1FDWF36P56EB81571 C/W: V8 6.0 L Diesel Engine, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 245/75R17, Spring Suspension, 141 in Wheelbase, 9 ft Body Usage: 186,727 Mi
572	2017 Chevrolet Silverado 3500 4x2 Utility Truck S/N: 1GB3CYCY4HF146791 C/W: GM Duramax V8 6.6 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200.0 lb		Notes: LOCATED-IN-FORT-WORTH-TX , TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX
	4800 lb Front Axle, 9750 lb Rears, 13200.0 lb GVWR, Steel, 265/70R17, Spring Suspension, 138 in Wheelbase, Knapheide 9 ft Body Usage: 195,867 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		1999 Ford F-250 XL 4x2 Utility Truck S/N: 1FDNF20F3XED98673 C/W: V8 7.3 L Diesel Engine, Automatic Transmission, 265/75R16, Spring Suspension, 140 in Wheelbase, Koening 8 ft Body Usage: 170,782 Mi
573	2015 Ford F-350 XL 4x2 Utility Truck S/N: 1FDRF3GT4FEC32664 C/W: Ford 6 Cylinder 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4850 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 141 in Wheelbase, Knapheide 9 ft Body Usage: 184,838 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Humble, TX

Lot #	Details	Lot #	Details
580	2017 Kenworth T300 4x2 Service Truck S/N: 2NKHHM6X9HM153755 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8294 Engine hrs, Engine Brake, Allison 3500 Automated Transmission, Differential Lock, 10000 lb Front Axle, 16000 lb Rears, Dana P22060S Drive Axles, 5.29:1 Axle Ratio, 26000 lb GVWR, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 157 in Wheelbase, PTO, 11 ft Body, Hydraulic Stabilizers, Auto Crane HC-10 10000 lb 2 Section Hydraulic Crane, Wired Remote Control, Auto Crane Hydraulic Air Compressor, Air Hose Reel Usage: 234,394 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	585 586	2022 Ram 5500 4x4 Service Truck S/N: 3C7WRNBL3NG352063 C/W: Cummins V8 6.7 L Ultra Low Sulfur Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 239 Engine hrs, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Outer Wheels, 225/70R19.5, Spring Suspension, 88 in Wheelbase, PTO, Palfinger Pal Pro 43 11 ft Body, Hydraulic Stabilizers, Palfinger PSC8029 8000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor Usage: 5,218 Mi Asset located in: Humble, TX 2022 Ram 5500 4x4 Service Truck S/N: 3C7WRNBL8NG352060
581A	THE INSPECTION REPORT Asset located in: Humble, TX 2006 International 4200 4x2 Service Truck S/N: 1HTMPAFMX6H162955 C/W: International 6 Cylinder Diesel Engine, 2005 US EPA Label, 10069 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 15500 lb Rears, 23500 lb GVWR, 10R22.5, Spring Suspension, 187 in Wheelbase, 16 ft 5 in Body, Manual Stabilizers, IMT 3820-2H 7500	_	C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 360 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 599 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Front Wheels, 225/70R19.5 Front Tires, 225/70R19 Rear Tires, Spring Suspension, 169 in Wheelbase, PTO, Palfinger 13 ft 6 in Body, Hydraulic Stabilizers, Palfinger PSC8029 800
583	Ib Crane Usage: 195,086 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2004 Ford F-750 XL 4x2 Service Truck S/N: 3FRXF75334V618003		Ib 3 Section Electric Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel Usage: 15,279 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
- 50.4	C/W: Cat 6 Cylinder Diesel Engine, 7-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, 13 ft 10 in Body, Hydraulic Stabilizers, Auto Crane 2 Section Electric Crane, Wired Remote Control, Hydraulic Air Compressor Usage: 246,367 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	587	2017 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HYXHEE50935 C/W: Ford V8 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245 /70R19.5, Spring Suspension, 169 in Wheelbase, Knapheide 13 ft 7 in Body, Manual Stabilizers, Stellar EC3200 3200 lb 2 Section Electric Crane, Wired Remote Control, Van Air Generator Set, Van Air Air Compressor, Van Arc Welder Usage: 211,059 Mi
584	1998 Ford F800 4x2 Service Truck S/N: 1FDXF80E2WVA30115		Asset located in: Humble, TX
	C/W: Cummins ISC 6 Cylinder 8.3 L Diesel Engine, 8234 Engine hrs, 9-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 14 ft 8 in Body, 5000 lb Hydraulic Crane, Gasoline Air Compressor, Air Hose Reel Usage: 289,213 Mi Notes: LOCATED-IN-LAKE-WORTH-TX-HOU ; DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	589	2015 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HY0FEB96388 C/W: Ford V8 6.2 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 167 in Wheelbase, 13 ft 6 in Body, Manual Stabilizers, IMT 3203i 4000 lb 3 Section Electric Crane, Wireless Remote Control, VANAIR Hydraulic Air Compressor Usage: 201,881 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
590	2014 Ram 5500 4x4 Crew Cab Service Truck S/N: 3C7WRNFL9EG269005 C/W: Cummins V8 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 6451 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 197 in Wheelbase, PTO, 13 ft Body, Manual Stabilizers, Auto Crane 5005H 5000 lb 3 Section Electric Crane Usage: 295,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	594	2007 Ford F-550 XL 4x2 Service Truck S/N: 1FDAF56P97EA85725 C/W: Ford Power Stroke V8 Diesel Engine, 2006 US EPA Label, 9849 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 19000 lb GVWR, 225/70R19.5, Spring Suspension, 167 in Wheelbase, 13 ft 4 in Body, Manual Stabilizers, 2006 Iowa Mold Tooling Co 2020 J505094 5000 lb 3 Section Electric Crane, Wired Remote Control Usage: 296,730 Mi Asset located in: Humble, TX
		595A	2015 Ram 5500 4x2 Service Truck
591A	Asset located in: Humble, TX 2017 Ford F-450 XL 4x4 Extended Cab Service Truck S/N: 1FD0X4HY1HEE48450 C/W: Ford Triton V10 6.8 L Gasoline Engine, 2017 US EPA Label, CARB Compliant, Ford- Factory Automatic Transmission, 6000 lb Front Axle, 12880 lb Rears, Ford-Factory Drive Axles, 16500 lb GVWR, 225/70R19.5 Front Tires, 225 /70R19.5 Rear Tires, Ford-Factory Spring Suspension, 192 in Wheelbase, Auto Crane 38K 13 ft 4 in Body, Manual Stabilizers, 2015 Auto		S/N: 3C7WRMBL4FG594937 C/W: Cummins V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, IMT Dominator 11 ft Body, (5) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, Vanair Arc N Air Generator Set, Vanair 150 Hydraulic Air Compressor, Vanair Air N Arc Hydraulic Driven Welder Usage: Not Available Asset located in: Humble, TX
591	Crane 4004EH 4000 lb 3 Section Hydraulic Crane, Wired Remote Control, Champion HGR7- 3K Gasoline Air Compressor, Air Hose Reel Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2012 Ford F-550 4x4 Service Truck S/N: 1FDUF5HT8CEB44863 C/W: Ford 6 Cylinder 6.7 L Diesel 300 hp	595	2016 Dodge Ram 3500 4x2 Service Truck S/N: 3C7WRSAL3GG140251 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 235/80R17, Spring Suspension, 148 in Wheelbase, 9 ft Body, Champion Pneumatic HGR7-3K Gasoline Air Compressor, Air Hose Reel
	Engine, 2012 ÚS EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 245 /70R19.5, 168 in Wheelbase, 2012 Maintainer		Usage: 290,275 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Maintainer 13 ft Body, Hydraulic Stabilizers, 2012 H650TT 6500 lb Hydraulic Crane, Wireless Remote Control, Vanair RC 40 Diesel Air Compressor, Miller Bobcat 250 1100 W 250 A Diesel Welder Usage: 245,356 Mi Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Lake Worth, TX		2014 Peterbilt 365 3600 gal 6x6 Fuel Truck S/N: 1NPSM70X0ED235400 C/W: Cummins ISX12 6 Cylinder 12.0 L Ultra Low Sulfur Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11564 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 22000 Ib Front Axle, 44000 Ib Rears, 66000 Ib GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5, Dual Steering Boxes, Double Frame, Air Trac
592	2016 Ford F-450 XL 4x4 Extended Cab Service Truck S/N: 1FD0X4HY2GEA92282 C/W: Ford Triton V10 6.8 L Gasoline Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Factory Ford P,R,N,D,3,2,1 Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, Ford-Factory Drive Axles, 16500 lb GVWR, 225/70R19.5, Ford-Factory Spring Suspension, 186 in Wheelbase, 13 ft 4 in Body, Manual Stabilizers, Auto Crane 6006EH 6000 lb 3 Section Hydraulic Crane, Wired Remote Control Usage: 156,934 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		Air Ride Suspension, 214 in Wheelbase, 2013 Hanco 3600 gal Steel Tank, Fill-Rite PTO Driver Pump, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 157,247 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
Lot # 598A 598	2018 Kenworth T880 6600 gal 6x4 Tanker Truck S/N: 1NKZX4EX2JJ214143 C/W: Cummins X15 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15448 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, Double Differential Locks, 20000 Ib Front Axle, 46000 Ib Rears, 80000 Ib GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 288 in Wheelbase, PTO, 2017 MAC LTT ARX-6600-1-407TM 6600 gal Aluminum Tank, Hydraulic Driven Pump Usage: 339,587 Mi Asset located in: Humble, TX 2014 Ford F-450 4x4 Lube Truck S/N: 1FDUF4HY8EEB81615 C/W: V8 6.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4800 Ib Front	Lot # 603 604	2014 Cat CT660S SBA 6x4 Water Truck S/N: 3HTJGTKT1EN016671 C/W: Cat CT13 6 Cylinder Diesel Engine, 9421 Engine hrs, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 193 in Wheelbase, Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, EQUIPMENT- FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 75,964 Mi Asset located in: Humble, TX 2007 Kenworth T800 4000 gal 6x4 Water Truck S/N: 1XKDD09X67J168840 C/W: Cummins ISM 6 Cylinder Diesel 385 hp Engine, 2006 US EPA Label, 3463 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSH40P Drive Axles, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels,
	Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 133 in Wheelbase, 9 ft Body, 100 gal Oil Tanks, (3) Hose Reels, Metered Nozzles, Oil Recovery System, Vanair 20 cfm Gasoline Air Compressor, Air Hose Reel Usage: 181,705 Mi	605	11R24.5, Air Ride Suspension, 180 in Wheelbase, Smith 4000 gal Steel Tank, ATP PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 424,378 Mi Asset located in: Humble, TX 1990 Kenworth W900 4000 gal 6x4 Water Truck
599	Asset located in: Humble, TX 2015 Freightliner 114SD 4100 gal 6x4 Tanker Truck S/N: 3ALHG3DV2FDFZ7097 C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22117.9 Engine hrs, Engine Brake, Eaton Fuller FO-16E308LL VCS Ultrashift Automated Transmission, Differential Lock, 16000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.90:1 Axle Ratio, 56000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Airliner Air Ride Suspension, 256 in Wheelbase, PTO, 2014 Tremcar Industries 4100 gal Steel Tank, 3 Compartments, TC406 Code, Catwalk w/Guardrails, Hydraulic Driven Pump, 2 Reels Usage: 303,096 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	606	S/N: 1NKWL50X0LS545697 C/W: Cummins LTA10 6 Cylinder Diesel 285 hp Engine, 1989 US EPA Label, 33385 Engine hrs, 18-Speed Manual Transmission, 20000 lb Front Axle, 42400 lb Rears, 11R22.5, Hendrickson Suspension, 262 in Wheelbase, PTO, Hydraulic Driven Pump, 7 ft, Spray Bar, Rear Spray, Side Spray Usage: 260,233 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2018 Kenworth T370 6x4 Water Truck S/N: 2NKHLJ9X7JM189233 Usage: Not Available Asset located in : Humble, TX 2017 Freightliner M2 106 4x2 Water Truck S/N: 1FVACXDT3HHJC7914 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Eluid 3713 Engine hrs Allison
600	2015 Freightliner 114SD 4100 gal 6x4 Fuel Truck S/N: 3ALHG3DV3FDFZ7089 C/W: Detroit DD13 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 13637 Engine hrs, Engine Brake, Eaton Fuller FO-16E208LL 8LL Automated Transmission, Differential Lock, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5, Dual Steering Boxes, Double Frame, Air Ride Suspension, 265 in Wheelbase, PTO, Tremcar Industries 4100 gal Steel Tank, Catwalk w /Guardrails, PTO Driven Pump Usage: 269,344 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Diesel Exhaust Fluid, 3713 Engine hrs, Allison 2500 Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 5.88:1 Axle Ratio, 20000 lb GVWR, 11R22.5, Spring Suspension, 162 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray Usage: 15,586 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
609	2021 International MV607 2000 gal 4x2 Water Truck S/N: 3HAEUMMN2ML088996 C/W: Cummins B6.7 220 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12350 Ib Front Axle, 21000 Ib Rears, 33000 Ib GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 7 ft 6 in, Spray Bar, Rear Spray, Side Spray	614	2011 International 4400 SBA 2000 gal 4x2 Water Truck S/N: 3HCMKAAN1BL423772 C/W: 6 Cylinder Diesel Engine, 7912 Engine hrs, Allison Automatic Transmission, 295/75R22.5, Air Ride Suspension, 151 in Wheelbase, PTO, Lands 2000 gal Steel Tank, PTO Driven Pump, 7 ft 8 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 127,025 Mi Asset located in: Humble, TX
	Usage: 316,647 Mi Asset located in : Humble, TX	615	2018 International 4300 SBA 2000 gal 4x2
610	2021 International MV607 4x2 Water Truck S/N: 3HAEUMMN8ML088114 C/W: Unused Lands Powder Coated 2000 gal Steel Tank Usage: 256,692 Mi Asset located in: Humble, TX		Water Truck S/N: 1HTMMMMN0JH331136 C/W: Cummins B6.7 250 6 Cylinder 6.7 L 250 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5962 Engine hrs, Eaton Fuller Automatic Transmission, 12000 lb Front Axle, 23000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suppression, 140 in Wheelbase, Unused
611	· · · · · · · · · · · · · · · · · · ·		Spring Suspension, 149 in Wheelbase, Unused Lands Powder Coated 2000 gal Steel Tank, PTO Driven Pump, 6 ft 8 in, Spray Bar, Rear Spray, Side Spray Usage: 230,881 Mi Asset located in: Humble, TX
		616	2018 International 4300 2000 gal 4x2 Water Truck S/N: 1HTMMMML4JH350089 C/W: Cummins B6.7 220 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 158 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 7 ft 6 in, Spray Bar, Rear Spray, Side Spray
612	 2020 International MV607 2500 gal 4x2 Water Truck S/N: 1HTEUMMN8LH822903 C/W: Cummins B6.7 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 2393 Engine hrs, Exhaust Brake, Allison Automatic Transmission, 12350 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 158 in Wheelbase, PTO, Lands 2500 gal Steel Tank, PTO Driven Pump, 6 ft 8 in, Spray Bar, Rear Spray, Side Spray Usage: 178,228 Mi Asset located in: Humble, TX 		Usage: 262,740 Mi
		617	Asset located in: Humble, TX 2017 International 4300 SBA 4x2 Water Truck S/N: 1HTMMMMNXHH477909 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, 4516 Engine hrs, Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Spring Suspension, 163 in Wheelbase, Steel Tank, Berkeley PTO Driven Pump, 5 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: Not Available
613	2020 International MV607 2000 gal 4x2 Water		Asset located in: Humble, TX
	Truck S/N: 1HTEUMMN7LH822908 C/W: Unused Lands Powder Coated 2000 gal Steel Tank Usage: 100,317 Mi Asset located in : Humble, TX	619	2014 International 4300 DuraStar 2000 gal 4x2 Water Truck S/N: 1HTMNAALXEH762149 C/W: International MaxxForce DT 7.6 L Diesel 230 hp Engine, 2013 US EPA Label, 5136 Engine hrs, Automated Transmission, 9000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295 /75R22.5, Spring Suspension, 151 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 204,599 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
620	2012 International 4300 SBA 2000 gal 4x2 Water Truck S/N: 1HTMMAAN1CH587596 C/W: 6 Cylinder Ultra Low Sulfur Diesel Engine, 9244 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 22000 lb Rears, 32000 lb GVWR, 295/75R22.5, Spring Suspension, 167 in Wheelbase, PTO, Ledwell LW2000 Steel Tank, PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 210,165 Mi Asset located in: Humble, TX 2005 Freightliner M2106 4x2 Water Truck	628	2018 Kenworth T370 4x2 Cab and Chassis S/N: 2NKHHM7X3JM183693 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5351.4 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana P22060S Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Front Wheels, 11R22.5, Reyco Spring Suspension, 210 in Wheelbase, 140 in Cab to Axle, 174 in Cab to End of Frame Usage: 80,694 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1FVACXDC25HN87551		Asset located in: Humble, TX
	C/W: Cat C7 6 Cylinder Diesel Engine, 2 Engine hrs, 6-Speed Manual Transmission, 10000 lb Front Axle, 19000 lb Rears, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 150 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 7 ft 8 in, Spray Bar, Hose Reel, Front Spray, Rear Spray Usage: 26,735 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	629	2017 Freightliner M2 106 4x2 Cab and Chassis S/N: 3ALACWDT6HDJG0552 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8987 Engine hrs, Allison 2000 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DARS19 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 204 in Cab
600	Asset located in: Humble, TX	_	to Axle, 283 in Cab to End of Frame
623	 2013 Ford F-750 XL 4x2 Water Truck S/N: 3FRNF7FAXDV784393 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 160 in Wheelbase, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 21,736 Mi Asset located in: Humble, TX 		Usage: 299,804 Mi Notes : . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in : Humble, TX
		S/N: 3HAEUMML4LL626918 C/W: Cummins B6.7 250 6 Cylinde Diesel 250 hp Engine, 2019 US EP, Requires Diesel Exhaust Fluid, 985 Allison Automatic Transmission, 1 Front Axle, 19000 lb Rears, 25999 Aluminum Wheels, 11R22.5, 258 ir 185 in Cab to Axle, 288 in Cab to E Usage: 352,584 Mi Asset located in : Humble, TX 2019 International CV515 SFA 4x4	2020 International MV607 4x2 Cab and Chassis S/N: 3HAEUMML4LL626918 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label,
624	2012 Ford F-750 XL 2000 gal 4x2 Water Truck S/N: 3FRNF7FA6CV151775 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 159 in Wheelbase, 2012 Niece T 2000 2000 gal Steel Tank, PTO Driven Pump,		Requires Diesel Exhaust Fluid, 9856 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Wheels, 11R22.5, 258 in Wheelbase, 185 in Cab to Axle, 288 in Cab to End of Frame Usage: 352,584 Mi
	Front Spray, Rear Spray, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 72,752 Mi		S/N: 1HTKTSWK1KH067198 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, 6238.8 Engine hrs, Allison
	Asset located in: Humble, TX	-	Automatic Transmission, 7500 lb Front Axle,
625	2007 Ford F-750 2000 gal 4x2 Water Truck S/N: 3FRXF75E07V510024 C/W: Dodge Cummins 6 Cylinder Diesel Engine, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 160 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 7 ft 7 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 23,676 Mi Asset located in: Humble, TX		15000 lb Rears, 19500 lb GVWR, Aluminum Outer Wheels, 225/70R19.5 Front Tires, 225 /70R19.5 Rear Tires, Spring Suspension, 199 Wheelbase, 86 in Cab to Axle, 137 in Cab to End of Frame Usage: 228,163 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
632	2008 Kenworth T300 4x2 Cab and Chassis S/N: 2NKMHN7X38M223334 C/W: Paccar PX-8 6 Cylinder Diesel 260 hp Engine, 12718 Engine hrs, Engine Brake, Eaton Fuller FS08406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana 21060S Drive Axles, 4.88:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Reyco Spring Suspension, 234 in Wheelbase, PTO, Hydraulic System, 165 in Cab to Axle, 261 in Cab to End of Frame Usage: 439,073 Mi Asset located in: Humble, TX	638	2017 Ford F-450 4x2 Cab and Chassis S/N: 1FDUF4GT8HEB92950 C/W: Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6580 Ib Front Axle, 12880 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 193 in Wheelbase, 106 in Cab to Axle, 155 in Cab to End of Frame Usage: 133,662 Mi Asset located in: Humble, TX 2014 Ford F-450 4x2 Extended Cab Cab and
633	2013 International 4300 SBA 4x2 Cab and Chassis S/N: 1HTMMAAN0DH156264 C/W: 6 Cylinder Diesel Engine, 2012 US EPA Label, 12618 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 22000 lb Rears, 32000 lb GVWR, 295/75R22.5, Spring Suspension, 208 in Wheelbase Usage: 241,012 Mi Asset located in: Humble, TX		Chassis S/N: 1FD0X4GTXEEB27489 C/W: Ford Powerstroke V8 6.7 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 Ib Front Axle, 12000 Ib Rears, 16500 Ib GVWR, Aluminum Outer Wheels, 225/70R19.5, Air Ride Suspension, 187 in Wheelbase, 84 in Cab to Axle, 132 in Cab to End of Frame Usage: 114,199 Mi Asset located in: Humble, TX
634	2016 Ram 5500 4x2 Cab and Chassis S/N: 3C7WRMBL3GG182557 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 7414 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, 88 in Cab to Axle, 134 in Cab to End of Frame Usage: 203,715 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	640	2018 Chevrolet Silverado 3500HD 4x4 Cab and Chassis S/N: 1GB3KYCYXJF117904 C/W: Chevrolet duramax V8 6.6 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 Ib Front Axle, 9750 Ib Rears, 13200 Ib GVWR, 235/80R17, Spring Suspension, 163 in Wheelbase, 84 in Cab to Axle, 135 in Cab to End of Frame Usage: 186,105 Mi Asset located in: Humble, TX 2014 Chevrolet Silverado 3500HD 4x4 Cab and
636	2011 Ford F-550 4x4 Cab and Chassis S/N: 1FDUF5HT3BEA38027 C/W: V8 6.7 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 166 in Wheelbase, 84 in Cab to Axle, 166 in Cab to End of Frame Usage: 347,560 Mi Asset located in: Humble, TX		Chassis S/N: 1GB3K0C80EF144665 C/W: V8 6.6 L Ultra Low Sulfur Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Air Ride Suspension, 164 in Wheelbase, 84 in Cab to Axle, 137 in Cab to End of Frame Usage: 244,106 Mi Asset located in: Humble, TX
637	2006 Chevrolet C5500 4x2 Cab and Chassis S/N: 1GBE5C32X6F424382 C/W: V8 Diesel Engine, Automatic Transmission, 8000 lb Front Axle, 13500 lb Rears, 19500.0 lb GVWR, 245/70R19.5, Spring Suspension, 156 in Wheelbase, 84 in Cab to Axle, 161 in Cab to End of Frame, Pintle Hitch Usage: 279,560 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	642	2017 Ford F-350 XLT 4x2 Cab and Chassis S/N: 1FDRF3GT2HEF26664 C/W: Powerstroke V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75/17, Spring Suspension, 168 in Wheelbase, 85 in Cab to Axle, 130 in Cab to End of Frame Usage: 204,342 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
643	2017 Ford F-350 XLT 4x2 Cab and Chassis S/N: 1FDRF3GT6HEC46763 C/W: 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 170 in Wheelbase, 86 in Cab to Axle, 132 in Cab to End of Frame Usage: 128,655 Mi Asset located in: Humble, TX 2016 Ram 3500 4x2 Cab and Chassis S/N: 3C7WRSBL0GG221142 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235	4X2 4 S/N: C/W: US EI Diess Fulle Front Axles 11R2 Susp 100 i Winc Usag Note Asse 649 649 1997 6-Spe Auxil S800 425/ Dual Rubb Whee Tulsa Usag Asse 650 2004 S/N: C/W: hp Er Spice 650 2004 Susp 108 i Winc Usag Asse 650 2004 Susp 108 i Winc Usag Asse 651 2006	2012 International 4300 DuraStar 4300 SBA 4X2 4x2 Gin Pole Truck S/N: 3HAMMAAL7CL634526 C/W: Navistar 6 Cylinder Diesel Engine, 2010 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 9742 Engine hrs, Eaton Fuller 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, NAVISTAR Drive Axles, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Navistar Spring Suspension, 188 in Wheelbase, PTO, 15 ft x 100 in Bed, Tail Roll, 17 ft Gin Poles, RUFNEK Winch, Receiver Hitch Usage: 9,742 Hr Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
645	/80R17, Air Ride Suspension, 171 in Wheelbase, 87 in Cab to Axle, 135 in Cab to End of Frame Usage: 258,936 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2006 Isuzu NPR 4x2 COE Cab and Chassis		1998 Western Star 6900 8x4 Twin-Steer Bed Truck S/N: 2WLTMCCF0WK949894 C/W: Cat 3406 6 Cylinder 14.6 L Diesel Engine, 1997 US EPA Label, 215521 Engine hrs, Spicer 6-Speed Manual Transmission, 2-Speed Auxiliary Transmission, 36000 lb Front Axle, 58000 lb Rears, 94000 lb GVWR, Air Ride Cab,
043	S/N: 4KLB4B1U46J802998 C/W: V8 6.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 7950 lb Rears, 12000 lb GVWR, Steel, 215 /85R16, Spring Suspension, 178 in Wheelbase, 160 in Cab to Axle, 203 in Cab to End of Frame Usage: 262,622 Mi		425/65R22.5 Front Tires, 12.00R24 Rear Tires Dual Steering Boxes, Double Frame, Chalmers Rubber over Walking Beam Suspension, 387 ir Wheelbase, PTO, 28 ft x 108 in Bed, Tail Roll, Tulsa Winch, Rufnek Winch Usage: 215,521 Hr Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		2004 International 5600i 6x4 Bed Truck S/N: 1HTXHAPTX4J092735 C/W: Cummins ISX 6 Cylinder 15 L Diesel 40 hp Engine, 2003 US EPA Label, Engine Brake
646	2006 Isuzu NPR 4x2 COE Cab and Chassis S/N: 4KLB4B1U56J800807 C/W: V8 6.0 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 7950 lb Rears, 12000 lb GVWR, Steel, 215 /85R16, Spring Suspension, 176 in Wheelbase, 160 in Cab to Axle, 203 in Cab to End of Frame Usage: 252,928 Mi		Spicer 6-Speed Manual Transmission, 4-Speed Auxiliary Transmission, 445/65R22.5 Front Tires, 12R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Walking Beam Suspension, 360 in Wheelbase, PTO, 24 ft x 108 in Bed, Tail Roll, Braden Winch, Tulsa Winch Usage: 140,183 Mi Asset located in : Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2006 Chevrolet C4500 4x4 Rig-Up Truck S/N: 1GBE4C32X6F408847
647	2013 Freightliner M2 106 Base 4x2 Gin Pole Truck S/N: 1FVACWDU5DHBZ0520 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2012 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7558.9 Engine hrs, L,2,3,D,N,R Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 193 in Wheelbase, PTO, Wet Kit, 15 ft 9 in x 96 in Bed, Tail Roll, 18 ft Gin Poles, Tulsa Winch, Receiver Hitch Usage: 7,558 Hr Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		C/W: GM V8 Gasoline Engine, Automatic Transmission, 8000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 245/70R19.5, Spring Suspension, 151 in Wheelbase, PTO, 11 ft x 8 in Bed, Tail Roll, 9 ft 4 in Gin Poles, . Winch Usage: 115,048 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
652	2013 Kenworth T800 8x4 Winch Truck S/N: 1XKDP4TX0DJ350357 C/W: Cummins ISX 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 11770 Engine hrs, Engine Brake, 18-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 88500 lb GVWR, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 243 in Wheelbase, 10 ft x 96 in Bed, Tail Roll, Rufnek 44066 Winch, Lowboy Ramps, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 530,832 Mi	656	2002 Peterbilt 379 8x4 Tri/A Day Cab Truck Tractor S/N: 1XP5DB0X72D586127 C/W: Cat 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 14060 lb Front Axle, 46000 lb Rears, 60060 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Lift Tag Axle, Air Trac Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel Usage: 586,182 Mi Asset located in: Humble, TX 2021 Western Star 4900EX 8x4 Heavy Haul Tri	
	Asset located in: Humble, TX		/A Sleeper Truck Tractor	
653	2006 International TranStar 8600 6x4 Winch Truck S/N: 1HSHXSBR96J266827 C/W: Cat C13 6 Cylinder 12.5 L Diesel 445 hp Engine, 2005 US EPA Label, 14224 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer RS404 Drive Axles, 4.33:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Steel, 11R22.5, International IROS Air Ride Suspension, 170 in Wheelbase, PTO, Rufnek Winch Usage: 344,385 Mi	-	S/N: 5KJNABD18MPMG3713 C/W: Detroit DD16 6 Cylinder 15.6 L D hp Engine, 2020 US EPA Label, Requir Exhaust Fluid, 13055.3 Engine hrs, Ea RTLO-20918B 18-Speed Manual Trans 18000 lb Front Axle, 66000 lb Rears, N 46-160P Drive Axles, 3.73:1 Axle Ratic lb GVWR, 82 in Mid Roof Sleeper Cab, /65R22.5 Front Tires, 11R24.5 Rear Ti Steerable Air Lift Pusher Axle, Airliner Suspension, 291 in Wheelbase, Air Sliv Wheel, Dual Fuel Tanks Usage: 295,587 Mi	S/N: 5KJNABD18MPMG3713 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 13055.3 Engine hrs, Eaton Fuller RTLO-20918B 18-Speed Manual Transmission, 18000 lb Front Axle, 66000 lb Rears, Meritor RT- 46-160P Drive Axles, 3.73:1 Axle Ratio, 83300 lb GVWR, 82 in Mid Roof Sleeper Cab, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Airliner Air Ride Suspension, 291 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 295,587 Mi Notes: LOCATED-IN-FORT-WORTH-TX PER
	Asset located in: Humble, TX		THE DEALER ACTUAL MILEAGE IS HIGHER	
654	 1995 Kenworth T800 6x4 Winch Truck S/N: 1XKDAR8X0SS680417 C/W: Detroit Series 60 6 Cylinder Diesel Engine, Engine Brake, Meritor RMX10-145A Manual Transmission, Differential Lock, Meritor RS23- 180 Drive Axles, 3.91:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring Suspension, 192 in Wheelbase, PTO, Wet Kit, Rufnek Winch Usage: 91,324 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 		THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN Asset located in: Lake Worth, TX	
		658	2013 Kenworth T660 8x4 Tri/A Sleeper Truck Tractor S/N: 1XKAP40X7DJ368040 C/W: Cummins ISX15 15.0 L Diesel 550 hp Engine, Requires Diesel Exhaust Fluid, 14004.6 Engine hrs, Eaton Fuller RTLO-16918B 18- Speed Manual Transmission, 13200 lb Front Axle, 47200 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 60400 lb GVWR, Air Ride Cab, 52 in Flat Top Sleeper Cab, 295 /75R22.5 Front Tires, 455/55R22.5 Super	
655	2012 Kenworth T800 6x4 Tri/A Day Cab Truck Tractor S/N: 1XKDD40X2CJ332521 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 27222 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 8LL Manual		Singles Rear Tires, Steerable Air Lift Air Assist Front Suspension, 8-Bag Ai Suspension, PTO, Air Sliding 5th Whe Fuel Tanks Usage: 487,312 Mi Notes : LOCATED-IN-FORT-WORTH-TX	
	Transmission, Double Differential Locks, 14320	659	2020 Kenworth W900 6x4 T/A Day Cab Truck	
60320 lb 5 Front Ti Pusher A Ride Susp 5th Whee Usage: 81	Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 0320 lb GVWR, Aluminum Wheels, 425/65R22. Front Tires, 11R24.5 Rear Tires, Air Lift usher Axle, Air Lift Tag Axle, Hendrickson Air de Suspension, 229 in Wheelbase, Air Sliding th Wheel, Headache Rack, Dual Fuel Tanks sage: 819,498 Mi sset located in: Humble, TX		Tractor S/N: 1XKWD40XXLR364224 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13850 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 242 in Wheelbase, Dual Fuel Tanks Usage: 442,671 Mi Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
660	2015 Kenworth W900 6x4 T/A Day Cab Truck Tractor	665	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor
	S/N: 1XKWD49X7FJ447146 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18919 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 477,649 Mi Asset located in : Humble, TX		S/N: 1XPXD49X1JD468919 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 14989 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R22.5 Front Tires, 11R24. 5 Rear Tires, Paccar Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 436,910 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
661	2020 Peterbilt 389 6x4 T/A Day Cab Truck		Asset located in: Humble, TX
	Tractor S/N: 1XPXD49X5LD711523 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 16359 Engine hrs, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer Drive Axles, 53200 lb GVWR, Air Ride Cab, 11R24.5, Air Trac Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 322,424 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	666	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X2JD468914 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19070 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 217 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 530,638 Mi Asset located in: Humble, TX
663	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X4JD468901 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 13539 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 416,809 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	667	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X0JD468913 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17059.2 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 217 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 539,017 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	668	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor
664	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X6JD468916 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 355,698 Mi Asset located in: Humble, TX		S/N: 1M1PN4GYXNM010084 C/W: Mack 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 15,901 Mi Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
669	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY4NM010078 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 30,765 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	673	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY2NM010080 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 58,052 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX	674	2019 Mack P164T 6x4 T/A Day Cab Truck
670	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY4NM010081 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks		Tractor S/N: 1M1PN3GY0KM001707 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 217 in Wheelbase, Dual Fuel Tanks Usage: 188,265 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 33,279 Mi		Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX	675	2015 Western Star 4900 6x4 T/A Day Cab
671	Asset located in: Lake Worth, TX 2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY6NM010079 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual		Truck Tractor S/N: 5KJJAED61FLGK0866 C/W: Detroit DD15 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13300 lb Front Axle, 44000 lb Rears, 57300 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 613,663 Mi Asset located in: Humble, TX
	Fuel Tanks	676	2015 Western Star 4900 6x4 T/A Day Cab
	Usage: 36,266 Mi Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX		Truck Tractor S/N: 5KJJAED6XFLGK0865 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Engine Brake,
672	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY3NM009634 C/W: Mack MP8 6 Cylinder 12.8 L 505 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 36,603 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Eaton Fuller 10-Speed Manual Transmission, 13300 lb Front Axle, 44000 lb Rears, 3.90:1 Axle Ratio, 57300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 527,030 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
677	2018 Peterbilt 367 6x4 T/A Day Cab Truck Tractor S/N: 1XPTD40XXJD458823	681	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X4FD263176
	C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 485 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7245 Engine hrs, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 46000 lb Rears, 58000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 210 in Wheelbase, PTO,		C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22218 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, Auto
	Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 124,113 Mi Asset located in : Humble, TX		Lube Usage: 675,848 Mi Asset located in : Humble, TX
678	2012 Peterbilt 388 6x4 T/A Day Cab Truck	682	2021 Kenworth T880 6x4 T/A Day Cab Truck
070	Tractor	002	Tractor
	S/N: 1XPWD49X1CD158459 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Leaf Air Ride Suspension, 208 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,329 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION		S/N: 1XKZDP9X4MJ466121 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P016F112C Automated Transmission, 13200 Ib Front Axle, 40000 Ib Rears, 3.36:1 Axle Ratio, 53200 Ib GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 425/65R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 201 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 344,741 Mi Asset located in : Humble, TX
	REPORT	683	2020 Kenworth T880 6x4 T/A Day Cab Truck
	Asset located in: Humble, TX		Tractor
679	2012 Peterbilt 388 6x4 T/A Day Cab Truck Tractor S/N: 1XPWDP9X9CD136792 C/W: Paccar MX 6 Cylinder Diesel 485 hp Engine, 33060 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 230 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 930,756 Mi		S/N: 1XKZDP0X2LJ398820 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 510 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 13200 lb Front Axle, 46000 lb Rears, 3.91:1 Axle Ratio, 59200 lb GVWR, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 383,381 Mi Asset located in : Humble, TX
	Asset located in: Humble, TX	684	· ·
680	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor S/N: 1XPSD79X1GD332553 C/W: Cummins ISX12 11.9 L Diesel 385 hp Engine, 21599 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension Usage: 434,349 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2020 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP0X4LJ398821 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 510 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9622.8 Engine hrs, Engine Brake, Eaton Fuller RTLO-1891 18-Speed Manual Transmission, Double Differential Locks, Dana D40-170HP Drive Axles, 3.91:1 Axle Ratio, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 399,094 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		685	2020 Kenworth T880 T/A Day Cab Truck
			Tractor S/N: 1XKZDP9X4LJ426961 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
686	2018 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1JJ215858 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8375 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel Usage: 237,444 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	694	2016 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y9GM024279 C/W: Mack MP8 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 415 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 214 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 486,827 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	696	2013 Mack CHU613 6x4 T/A Day Cab Truck
687	2018 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXJJ215860 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11097.5 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Paccar Air Ride Suspension, 200 in Wheelbase,		Tractor S/N: 1M1AN07Y1DM014683 C/W: Mack MP8 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 445 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320.0 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 419,295 Mi Notes: LOCATED-IN-FORT-WORTH-TX
	Air Sliding 5th Wheel, Dual Fuel Tanks		Asset located in: Lake Worth, TX
	Usage: 238,110 Mi Asset located in : Humble, TX	697	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor
688	2018 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1NKZXPTX1JJ196609 Usage: Not Available Asset located in: Humble, TX		S/N: 1M1AN09YXDM013576 C/W: Mack MP8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels,
689	2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZD49X5GJ482170 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16827 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 176 in Wheelbase Usage: 380,794 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		11R24.5, Air Ride Suspension, 214 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 500,177 Mi Notes : LOCATED-IN-FORT-WORTH-TX, THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE
690	2016 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X3GJ495372 Usage: Not Available Asset located in: Humble, TX		INSPECTION REPORT Asset located in: Lake Worth, TX
691	2015 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X8FJ425865 Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
698A	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M2AN07Y1DM014095 C/W: Mack MP8 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 29537 Engine hrs, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 747,931 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	701	2010 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y1AN006069 C/W: Mack MP8-485E 6 Cylinder 12.8 L Engine, 2009 US EPA Label, 23998 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Wet Kit, Headache Rack, Dual Fuel Tanks Usage: 631,038 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
698	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y1DM015073 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18887 Engine hrs, Engine Brake, Mack MAXITORQUE 10-Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 598,672 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	703	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPRXJN406712 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7334 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Dual Fuel Tanks Usage: 217,611 Mi Asset located in: Humble, TX 2018 International HX620 6x4 T/A Day Cab
699	Asset located in: Humble, TX 2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y7CM009924 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26293 Engine hrs, Engine Brake, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Dual Fuel Tanks Usage: 675,788 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	705	Truck Tractor S/N: 3HSDTAPR5JN405659 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8240 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 52300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Dual Fuel Tanks Usage: 252,460 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 International HX620 6x4 T/A Day Cab
700	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y9CM010296 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 34419 Engine hrs, Engine Brake, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 219 in Wheelbase, PTO, Dual Fuel Tanks Usage: 723,169 Mi Asset located in: Humble, TX		Truck Tractor S/N: 3HSDTAPR3JN405658 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12785 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, PTO, Dual Fuel Tanks Usage: 303,075 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
706	2018 International HX620 6x4 T/A Day Cab Truck Tractor	711	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor
	S/N: 3HSDTAPR5JN405662 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 11700 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Dual Fuel Tanks		S/N: 1M1AN4GY6KM003456 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15036 Engine hrs, Engine Brake, Mack mDrive Automatic Transmission, 12500 Ib Front Axle, 40000 Ib Rears, 52500 Ib GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 743,483 Mi
	Usage: 361,409 Mi		Asset located in: Humble, TX
	Asset located in: Humble, TX	712	2020 Freightliner Cascadia 126 6x4 T/A Day
708	2020 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1XPCDP9X8LD713489 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 385 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16.8 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks		Cab Truck Tractor S/N: 1FUJHLDR5LLLD8475 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15492 Engine hrs, Retarder, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 176 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 655,434 Mi Asset located in: Humble, TX
	Usage: 271,600 Mi Notes : SELLING WITH A REPOSESSION	714	2019 Freightliner Cascadia 126 6x4 T/A Day
	AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING		Cab Truck Tractor S/N: 3AKJHLDVXKSKA4609 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450
	Asset located in: Humble, TX	_	hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid,
709	2019 Kenworth T-680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYDP9X0KJ251666 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P016F112 Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Paccar MT40-14x3 Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR,	Engine Brake, Detroit DT12 Speed Automated Transmi Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Ca Wheels, 295/75R22.5, Airlir Suspension, 174 in Wheelb Wheel Usage: 617,540 Mi	Engine Brake, Detroit DT12-1550-DH1 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel Usage: 617,540 Mi Asset located in : Humble, TX
	Air Ride Cab, Aluminum Outer Wheels, 275 /70R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 180 in Wheelbase, Air	715	2019 Freightliner Cascadia 125 T/A Day Cab Truck Tractor
	Sliding 5th Wheel Usage: 597,206 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 3AKJGEDR9KSKJ9009 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 22104 Engine hrs, Engine Brake Automated Transmission, 12000 lb Front Axle
76.0	Asset located in: Humble, TX	40000 lb Rears, 2.41:1 Axia GVWR, Air Ride Cab, Alumi 5, Airliner Air Ride Suspens Wheelbase, Air Sliding 5th Tanks Usage: 1,012,611 Mi Notes : PROFESSIONALLY- VEHICLE-PAG ; SELLER SU MAINTENANCE RECORD A DOCUMENT SECTION BEL	40000 lb Rears, 2.41:1 Axle Ratio, 52000 lb
710	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN2GY4KM003413 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16106 Engine hrs, Engine Brake, Mack Mdrive Automated Transmission, 13200 Ib Front Axle, 40000 Ib Rears, 53200 Ib GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase Usage: 594,033 Mi Asset located in: Humble, TX		5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Lot #	Details	Lot #	Details
716	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH9LN225162 C/W: Volvo D13 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, 14177 Engine hrs, Volvo ATO2612F Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 421,049 Mi Asset located in: Humble, TX 2020 Volvo VNP200 6x4 T/A Dov Cab Truck	720	2020 Volvo VNR64T300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH3LN225156 C/W: Volvo 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9320.7 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12500 lb Front Axle, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 308,397 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH0LN225146 C/W: Volvo D13M-425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11867 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 443,912 Mi Asset located in: Humble, TX	721	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH9LN225159 C/W: Volvo D13M-425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11022 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 171 in Wheelbase, Dual Fuel Tanks Usage: 370,396 Mi
718	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH6LN225166 C/W: Volvo D13M-425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13019 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 474,668 Mi Asset located in: Humble, TX 2020 Volvo VNR300 6x4 T/A Day Cab Truck	722	Asset located in: Humble, TX 2020 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR5LN089778 C/W: Navistar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10571 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 431,510 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Tractor S/N: 4V4WC9EH7LN225175 C/W: Volvo D13M-425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12215.8 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 485,817 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	723	Asset located in: Humble, TX 2020 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR8LN089788 C/W: International 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 7089 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 440,341 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
724	2020 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR7LN845451 C/W: International 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10487 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 421,090 Mi Asset located in: Humble, TX	728	2020 International LT 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZAPR8LN401039 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15239 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22. 5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 679,223 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
725	2020 International RH613 6x4 T/A Day Cab	1	THE INSPECTION REPORT Asset located in: Humble, TX
	Truck Tractor S/N: 3HSDWTZR2LN845471 C/W: International 6 Cylinder Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 6583 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 639,408 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset Least of the Use black of the sector	729	2019 International LT 6x4 T/A Day Cab Truck Tractor S/N: 3HCDZAPR3KL130218 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11880 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 498,574 Mi
706	Asset located in: Humble, TX	700	Asset located in: Humble, TX
726	2020 International LT 6x4 T/A Day Cab Truck Tractor S/N: 3HCDZAPR3LL322076 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9264 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	732	2017 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYD40X1HJ175122 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2016 US EPA Label, 8867.7 Engine hrs, Engine Brake, Eaton Fuller FO- 18E313A MHP Manual Transmission, 3.58:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 12R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 188 in Wheelbase, PTO Usage: 293,816 Mi Asset located in: Humble, TX
	Usage: 337,640 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	733	2017 Kenworth T680 6x4 T/A Day Cab Truck
	THE INSPECTION REPORT Asset located in: Humble, TX		Tractor S/N: 1XKYDP9X4HJ145701
727	2020 International LT 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZAPR4LN113566 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 673,372 Mi Asset located in: Humble, TX		C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 430 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Ultra Shift Plus Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Paccar DSP40 Drive Axles, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Paccar 4-Bag Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT THE TITLE COMES WITH AN AFFIDAVIT TITLE CORRECTION NOT ALL STATES ACCEPT THEM Asset located in : Humble, TX

Lot #	Details	Lot #	Details
734	2016 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYD40X8GJ115353 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, 16245.2 Engine hrs, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, 12000 Ib Front Axle, 45400 Ib Rears, Meritor RT-40- 160 Drive Axles, 3.42:1 Axle Ratio, 57400 Ib GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 773,399 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	737	2018 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y6JM089069 C/W: Mack MP7 6 Cylinder 10.8 L 395 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9700 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 202 in Wheelbase, Auto Lube Usage: 569,066 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
735	2013 Kenworth T660 6x4 T/A Day Cab Truck Tractor S/N: 1XKAD49X3DJ354695 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 12214 Engine hrs, Engine Brake, Eaton Fuller FM-15E310B-LAS Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Steel, 275 /80R22.5 Front Tires, MIXED Rear Tires, 8-Bag Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 327,222 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	738	2017 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y0HM081110 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 2592 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 204 in Wheelbase Usage: 568,398 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
736	2018 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1JM088010 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15926 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 206 in Wheelbase Usage: 414,968 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.	739	Asset located in: Livingston, LA 2017 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y7HM084229 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10607 Engine hrs, Engine Brake, Mack mDRIVE Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 187 in Wheelbase, Dual Fuel Tanks Usage: 412,790 Mi Asset located in: Humble, TX
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA	740	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1GM076383 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 18095 Engine hrs, Engine Brake, Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 193 in Wheelbase Usage: 495,686 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA

Lot #	Details	Lot #	Details	
741	 2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02YXGM058481 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11518 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 180 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 213,409 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 	746	Tractor S/N: 1M1AW02Y8EM042275 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19251 Engine hrs, Engine Brake, Mack Automated Transmission, 12000 lb Fron Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 198 in Wheelbase Usage: 579,235 Mi Asset located in: Humble, TX	
_	Asset located in: Humble, TX			
742	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1GM053119 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11146 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab Automated Transmission, 205/75022 5 Air Ride Cab		hp Engine, 2012 US ÉPA Label, F Exhaust Fluid, Engine Brake, Eat Speed Manual Transmission, Aiu Aluminum Wheels, 295/75R22.5 Suspension, 193 in Wheelbase, V Sliding 5th Wheel Usage: 756,552 Mi	C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 193 in Wheelbase, Wet Kit, Air Sliding 5th Wheel
	Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks	751	2018 Freightliner Cascadia 125 6x4 T/A Day	
	Usage: 238,391 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	751	Cab Truck Tractor S/N: 1FUJGEDR8JLJW4983 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel	
743	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y1FM043942 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14527 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspansion, 180 in Wheelbase, PTO, Air Sliding		Exhaust Fluid, 6751 Engine hrs, En Detroit DT12-DA-1650 HD 12-Spe Automated Transmission, 13300 40000 lb Rears, Meritor MT-40-14 2.47:1 Axle Ratio, 53300 lb GVWR Aluminum Wheels, 295/75R22.5, Ride Suspension, 178 in Wheelbar 5th Wheel, Dual Fuel Tanks Usage: 713,379 Mi	Exhaust Fluid, 6751 Engine hrs, Engine Brake, Detroit DT12-DA-1650 HD 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Suspension, 189 in Wheelbase, PTO, Air Sliding 5th Wheel		THE INSPECTION REPORT	
	Usage: 293,769 Mi Asset located in : Humble, TX	750-	Asset located in: Humble, TX	
745	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y8EM043166 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 4220 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 285 /75R24.5, Air Ride Suspension, 192 in Wheelbase Usage: 525,664 Mi Asset located in: Humble, TX	_752B	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV3JSJH1983 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8275 Engine hrs, Detroit DT12- OB-1550 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 283,337 Mi Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
752A	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV9JDJH2317 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OB-1550 HD 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 327,535 Mi Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	755	2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV5HDHT8698 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11453 Engine hrs, Engine Brake, Eaton Fuller FO- 18E313A MHP Automatic Transmission, 12000 Ib Front Axle, 40000 Ib Rears, Meritor MT-40- 14X Drive Axles, 3.55:1 Axle Ratio, 52000.0 Ib GVWR, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 465,451 Mi Asset located in: Humble, TX 2017 Freightliner Cascadia 125 6x4 T/A Day
	Asset located in: Humble, TX		Cab Truck Tractor S/N: 3AKJGEDV7HDHS9159
752	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGEDR2JLJW4980 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA- 1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,652 Mi	757	C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 346,393 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
	Asset located in: Humble, TX		Asset located in: Humble, TX
753	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV2JSJH2266 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 435 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 404,639 Mi Notes: . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	- 757	2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV6HSHZ3222 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM- 15E310B Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 488,101 Mi Notes: LOCATED-IN-HOUSTON-TX , . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX

Details	Lot #	Details
2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED50GLHL6329 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 15219 Engine hrs, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, 12000 Ib Front Axle, 40000 Ib Rears, Meritor MT-40- 14X Drive Axles, 3.55:1 Axle Ratio, 52000 Ib GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,104 Mi Notes : ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in : Humble, TX	763	2015 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 3AKGGEDV8FSGK3628 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8724 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 Ib Front Axle, 40000 Ib Rears, 52000 Ib GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 176 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM- YELLOW-CORP Usage: 912,917 Mi Notes: CANNOT VERIFY ODOMETER READING- VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV8GSGV9634 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16464 Engine hrs, Engine Brake, Detroit DT12OB1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 3.25:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 5,254 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	764	2015 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 3AKGGEDV8FSGK3449 C/W: Detroit 6 Cylinder Ultra Low Sulfur Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21446 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 151 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA SUBJECT TO LA TAX; SELLING WITH A BANKRUPTCY DOCUMENTS AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; ALL INOPERABLE ITEMS NEED TO BE REMOVED FROM THE YARD BY
2016 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 3AKGGEDVXGDHC4994 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DB-1450 HD 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 20K R-SRS Drive Axles, 2.50:1 Axle Ratio, 52000 lb GVWR, 275/80R22.5, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 738,601 Mi Asset located in: Humble, TX	765	SEPTEMBER 20th CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA 2015 Freightliner Cascadia 125 T/A Day Cab Truck Tractor S/N: 3AKGGLD54FSGP8291 Usage: Not Available Asset located in: Humble, TX 2014 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEBG8ESFY2250 C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2013 US EPA Label, 721.3 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 185 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 49,154 Mi Asset located in: Humble, TX
	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED50GLHL6329 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 15219 Engine hrs, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, 12000 Ib Front Axle, 40000 Ib Rears, Meritor MT-40- 14X Drive Axles, 3.55:1 Axle Ratio, 52000 Ib GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,104 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX 2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV8GSGV9634 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16464 Engine hrs, Engine Brake, Detroit DT120B1550 12-Speed Automated Transmission, 12000 Ib Front Axle, 40000 Ib Rears, Meritor MT-40-14X4 Drive Axles, 3.25:1 Axle Ratio, 52000.0 Ib GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 5,254 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 3AKGGEDVXGDHC4994 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DB-1450 HD 12- Speed Automated Transmission, 12000 Ib Front Axle, 40000 Ib Rears, Meritor MR-20-005 20K R-SRS Drive Axles, 2.50:1 Axle Ratio, 52000 Ib GVWR, 275/80R22.5, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 738,601 Mi	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor763S/N: 1FUJGED50GLHL6329 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 15219 Engine hrs, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, 12000 Ib Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,104 Mi764Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX7642016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV8GSGV9634 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16464 Engine hrs, Engine Brake, Detroit DT120B1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 3.25:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 5,254 Mi764Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX7652016 Freightliner Cascadia 125 6x2 T/A Day Cab Truck Tractor S/N: 3AKGGEDVXGDHC4994 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DB-1450 HD 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 20K R-SRS Drive Axles, 2.50: 1 Axle Ratio, 52000 lb GVWR, 275/80R22.5, Airliner Air

Lot #	Details	Lot #	Details
768	2016 Freightliner Cascadia 113 6x2 T/A Day Cab Truck Tractor S/N: 1FUGGBDV5GLGY6228 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 Drive Axles, 3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 196 in Wheelbase, Wet Kit, Hydraulic System, Air Sliding 5th Wheel, Blower Usage: 421,943 Mi Asset located in: Humble, TX	772	2016 Volvo VNL300 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EH2GN967808 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 161024 Engine hrs, Eaton Fuller FRO-17210C 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 180 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 596,344 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
769	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGBDV7GDHA6151 C/W: Detroit DD13 6 Cylinder 12.8 L 380 hp Engine, Requires Diesel Exhaust Fluid, 17605 Engine hrs, Retarder, Detroit DT12-DB-1450 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Dual Fuel Tanks Usage: 520,442 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	773	Asset located in: Humble, TX 2015 Volvo VNL 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG4FN167226 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612D Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 841,931 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
770	2014 Freightliner COLUMBIA 120 6x2 T/A Day Cab Truck Tractor S/N: 3ALXA7A85EDFP8335 C/W: Cummins 6 Cylinder Diesel Engine, 25369 Engine hrs, Eaton Fuller 7-Speed Manual Transmission, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM- YELLOW-CORP Usage: 882,021 Mi Notes: EQUIPMENT-FROM-YELLOW-CORP ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	778	2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG3JN888318 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9874 Engine hrs, Automated Transmission, 12000 lb Front Axle, 18739 lb Rears, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Volvo Air Ride Suspension, 204 in Wheelbase, PTO Usage: 335,652 Mi Asset located in: Humble, TX 2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG7JN888306
771	2014 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor S/N: 3AKJC5DV8EDFZ3289 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11397 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 202 in Wheelbase, PTO, Blower Usage: 337,809 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
780	2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG6JN888314 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 68 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478 lb GVWR, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: 363,236 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TITLE IS BEING SOLD WITH A REPO AFFIDAVIT Asset located in: Humble, TX	785	2017 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJSNR2HN461910 C/W: International 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 259,215 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX
781	2018 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG9JN888307 C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12000 lb Front Axle, 37478 lb Rears, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 199 in Wheelbase Usage: 381,761 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	786	2017 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR9HN710341 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12492 Engine hrs, Engine Brake, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 474,300 Mi Asset located in: Humble, TX
782	2018 Volvo VNM T/A Day Cab Truck Tractor S/N: 4V4MC9EG8JN888315 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: 391,770 Mi Asset located in: Humble, TX 2018 Volvo VNM200 6x4 T/A Day Cab Truck	787	2017 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HCDJAPR4HL722064 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12386 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 405,908 Mi
,	Tractor S/N: 4V4MC9EG0JN888311 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: 401,947 Mi Asset located in: Humble, TX	788	Asset located in: Humble, TX 2016 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR5GN135170 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 179 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 287,866 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
789	2016 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR5GN135167 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 179 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 335,198 Mi Asset located in: Humble, TX	792	2013 International ProStar Premium 6x4 T/A Day Cab Truck Tractor S/N: 1HSDJSJR7DJ307244 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 430 hp Engine, 2012 US EPA Label, 16142 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 295 /75R22.5, Air Ride Suspension, 168 in Wheelbase Usage: 311,781 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
790A	2015 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR6FN745786 C/W: Cummins ISX15 15.0 L Ultra Low Sulfur Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10566 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 267,490 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	795A	2008 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X58J236098 C/W: Cat 6 Cylinder Diesel Engine, 21271 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP4140 Drive Axles, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 174 in Wheelbase Usage: 894,694 Mi Asset located in: Humble, TX
	THE INSPECTION REPORT	795	2006 Peterbilt 379 6x4 T/A Day Cab Truck
790	Asset located in: Lake Worth, TX 2016 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 1HSDJAPR1GH733654 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 25894 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 229,878 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	796	Tractor S/N: 1XP5DU9X96N636797 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 8LL Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 240 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 1,259,542 Mi Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX 2005 Kenworth T800 6x4 T/A Day Cab Truck Tractor
	THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1XKDDU9X25R094788 C/W: 6 Cylinder Diesel Engine, 4747 Engine hrs
791	2015 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 1HSDJAPR5FH704110 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 269,135 Mi Asset located in: Humble, TX		Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 203 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 445,137 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
798	2009 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y19N005092 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2008 US EPA Label, 22028 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 220 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 829,975 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	807	2009 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK79LAH0941 C/W: Detroit Series 60 6 Cylinder 14 L Diesel Engine, 2008 US EPA Label, Requires Diesel Exhaust Fluid, 15762.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
799	2007 Freightliner FLD 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJALCK37DX39861 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 2006 US EPA Label, 9401 Engine hrs, Engine Brake, Eaton Fuller FRO-	808	2008 Freightliner Century Class CST120 T/A Day Cab Truck Tractor S/N: 1FUJBBCK68LZ69179 Usage: Not Available Asset located in: Midland, TX 2008 Freightliner Century Class CST120 T/A
	15210C 10-Speed Manual Transmission, Meritor RT-44-145 Drive Axles, 3.90:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 210 in Wheelbase, Dual Fuel Tanks Usage: 621,288 Mi Asset located in : Humble, TX	810	Day Cab Truck Tractor S/N: 1FUJBBCK78LAA3566 Usage: Not Available Asset located in: Midland, TX 2005 Freightliner ST120 6x4 T/A Day Cab
800A	1994 Western Star 4900 6x4 T/A Day Cab Truck Tractor S/N: 2WKPDCJH0RK934343 C/W: Cummins N14 6 Cylinder Diesel 430 hp Engine, Engine Brake, Eaton Fuller RTL014613B 13-Speed Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, Spicer DS402 Drive Axles, 46000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Reyco Spring Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 871,471 Mi	811	Truck Tractor S/N: 1FUJBBCG55LU03957 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 19647 Engine hrs, Engine Brake, Meritor 10- Speed Manual Transmission, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 173 in Wheelbase, Dual Fuel Tanks Usage: 640,000 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2001 Freightliner Century Class CST120 6x4 T
802	Asset located in: Humble, TX 1993 Ford LT900 6x4 T/A Day Cab Truck Tractor S/N: 1FDYU90R4PVA38897 C/W: 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 50000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 170 in Wheelbase, PTO, Wet Kit, Headache Rack, Dual Fuel Tanks Usage: 10,823 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2004 Mack CV713 T/A Day Cab Truck Tractor	_	/A Day Cab Truck Tractor S/N: 1FUJA9A821LG82188 C/W: 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1M2AG12C54M009994 Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
813	2008 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG68N262773 C/W: Volvo D13 6 Cylinder Engine, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, 295/75R22. 5 Front Tires, 295/75R22.5 Rear Tires, Volvo 4- Bag Air Ride Suspension, 166 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,246,354 Mi Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Internetionel 0200 6x4 T (A Day Cab	816	2019 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X2KJ257006 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15779 Engine hrs, Engine Brake, 18-Speed Manual Transmission, 13200 Ib Front Axle, 38000 Ib Rears, 51200 Ib GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 492,355 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
814 815A	2007 International 9200 6x4 T/A Day Cab Truck Tractor S/N: 2HSCEAHRX7C421158 C/W: Cummins ISM 6 Cylinder Diesel Engine, 27232 Engine hrs, Manual Transmission, Spicer RS404 Drive Axles, 2.85:1 Axle Ratio, Aluminum Wheels, 11R22.5, Air Ride Suspension, 192 in Wheelbase, Dual Fuel Tanks Usage: 837,012 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2009 International TranStar 8600 6x4 T/A Day Cab Truck Tractor	817	2019 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X4KJ257007 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17943 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X4 Drive Axles, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 76 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 508,076 Mi
	S/N: 1HSHXAHR09J115073 C/W: Cummins 6 Cylinder Diesel Engine, 2008 US EPA Label, 24262 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295 /75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 361,724 Mi Asset located in : Humble, TX	818	Asset located in: Humble, TX 2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X7KD611194 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 41823.6 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb
815	2007 International 9200 6x4 T/A Day Cab Truck Tractor S/N: 2HSCEAPR47C427393 C/W: Cummins 6 Cylinder Diesel Engine, 2006 US EPA Label, 21080 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 545,745 Mi Asset located in: Humble, TX		Rears, 53200 lb GVWR, Air Ride Cab, 63 in Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 309,780 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
819A	2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3GD361783 C/W: Cummins ISX15 6 Cylinder 15 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 30543.6 Engine hrs, Engine Brake, 13-Speed Manual Transmission, 12000 Ib Front Axle, 38000 Ib Rears, 50000 Ib GVWR, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Leaf Air Ride Suspension, 281 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 685,630 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Humble, TX	822	2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3GD369706 C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 57373 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 5320 lb GVWR, 63 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 261 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 423,399 Mi Asset located in: Humble, TX 2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49XXGD369704 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 49169 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 255 in Wheelbase, Air Olding, 5th Wheel, Parker Suspension, 255 in Wheelbase,
819	2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9KD611200 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 43831 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 63 in High Rise Sleeper Cab, 11R24.5, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 337,659 Mi Asset located in: Humble, TX	824	Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 347,806 Mi Asset located in: Humble, TX 2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X1FD261079 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 34303.2 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspensior
820	2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X3GD317203 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 36297 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 13200 Ib Front Axle, 40000 Ib Rears, 53200 Ib GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 352,560 Mi Asset located in: Humble, TX		282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 293,171 Mi Asset located in : Humble, TX
821	2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X5GD369710 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 396,833 Mi Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
Tractor S/N: 1XPXD C/W: Cumm 500 hp Engin Diesel Exhau Brake, Eator Transmissio Rears, 52000 Roof Sleepe Suspension, Wheel, Dual Usage: 713, Notes: THIS DEFICIENCIE SYSTEMS W TEXAS ADM 114.20 AND OPERATE TH RESTORATION SYSTEMS O EQUIPPED. I ACKNOWLE PRIOR TO RI DEFICIENCIE INSPECTION Asset locate	2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9FD260780 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15440 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb	828	2016 International LoneStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSCXAPR6GN111535 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 20473 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb
	Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, 11R24.5, Paccar Air Ride Suspension, 282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,133 Mi Notes : THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN		Rears, 52350 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 698,966 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
	TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Peterbilt 367 6x4 T/A Sleeper Truck	829	2013 International Paystar 5900i 6x4 T/A Sleeper Truck Tractor S/N: 1HSXYSJRXDJ078910 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, 48205 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Tractor S/N: 1XPTP4EX3DD197071 C/W: Cummins ISX15 15.0 L Diesel 525 hp Engine, 2015 US EPA Label, 28626 Engine hrs, Engine Brake, Manual Transmission, Differential Lock, 16000 lb Front Axle, 40666 lb Rears, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 385/65R22. 5 Front Tires, 11R24.5 Rear Tires, Air Trac Air Ride Suspension, 240 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,438,266 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		Usage: 78,430 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Humble, TX
	THE INSPECTION REPORT	830	2013 International Paystar 5900i 6x4 T/A
827	Asset located in: Humble, TX 2019 Freightliner Coronado 122SD 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGNFG3KDKV9053 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17821 Engine hrs, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53220 lb GVWR, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 502,082 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX		Sleeper Truck Tractor S/N: 1HSXYSJR3DJ078909 C/W: Cat 6 Cylinder Diesel Engine, 2012 US EPA Label, 30336 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 51 in Flat Top Sleeper Cab, 11R24.5, Hendrickson Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 431,459 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Humble, TX

Lot #	Details	Lot #	Details
831A 831	2010 Kenworth 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDU9X5AJ262884 C/W: Cat C13 6 Cylinder Diesel 445 hp Engine, 2009 US EPA Label, 31639 Engine hrs, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 3.55:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, 52 in Flat Top Sleeper Cab, 11R22.5, Air Ride Suspension, 226 in Wheelbase, Dual Fuel Tanks Usage: 1,131,845 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Western Star 4900 6x4 T/A Sleeper Truck Tractor	834	2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X0LD657204 C/W: Cummins ISX15 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 13148 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 80 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 546,016 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 5KJJALDR2BPAX2524 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Engine Brake, Automated Transmission, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 195,951 Mi Asset located in : Humble, TX	835	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X9KD607207 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 275/80R22.5 Front Tires, 11R22.5
832	2020 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR6LLLU6811 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1750- OH1 12-Speed Automated Transmission, 13000 lb Front Axle, 40000 lb Rears, 2.85:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 431,325 Mi Asset located in: Humble, TX		Rear Tires, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 488,776 Mi Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
		837 2023 Kenworth T680 6x4 T/A Slee Tractor S/N: 1XKYD49X9PJ239781 C/W: Cummins X15 6 Cylinder 15 I hp Engine, 2022 US EPA Label, Rec Exhaust Fluid, 3500 Engine hrs, En Automated Transmission, Differen 13200 lb Front Axle, 40000 lb Rear Drive Axles, 2.79:1 Axle Ratio, 5320 Air Ride Cab, 62 in High Rise Sleep Beds, Bunk Heater, Aluminum Whe /80R22.5 Front Tires, 295/75R22.5 Air Ride Suspension, 241 in Wheell Sliding 5th Wheel, Dual Fuel Tanks Usage: 166,668 Mi	2023 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X9PJ239781 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3500 Engine hrs, Engine Brake,
833	2019 Western Star 5700XE 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR2KLKE6957 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1750-OH1 Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 68 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Comfort pro Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 605,703 Mi Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
839	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X9LJ388380 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,254 Mi Asset located in: Humble, TX	842	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X0KJ999415 C/W: Paccar MX-13 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar PO-16F112 Automated Transmission, Differential Lock, 5988 kg Front Axle, 18144 kg Rears, Paccar Drive Axles, 2.93:1 Axle Ratio, 24132 kg GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, AG210 Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 525,423 Mi
840	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X4LJ348287 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15421 Engine hrs, Engine Brake, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 589,051 Mi Asset located in: Humble, TX	843	Notes: LOCATED-IN-MIDLAND-TX . Asset located in: Midland, TX 2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X5KJ310239 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 233 in Wheelbase, PTO, Dual Fuel Tanks Usage: Not Available
841	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X1KJ242070 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10275 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.08:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 407,257 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	844	Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX 2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5NSNC7969 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 14698 Engine hrs, Engine Brake, Detroit DT12-1750- OHE 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 278,457 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
845	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7NSNM0632 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1750-OH 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 322,891 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX	849	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7LSLV7454 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 523,264 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
846	2021 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDV8MSMK2617 Usage: 825,003 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	850	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4LSMJ0210 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14504 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 11R22. 5, Airliner Air Ride Suspension, 228 in
847	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR1LSMG6164 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16808 Engine hrs, Engine Brake, Detroit DT12-1650 12- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 449,805 Mi Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 534,243 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX 2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDRXLSLT5934 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18742 Engine hrs, Engine Brake, Eaton Fuller DT12-1750-DH1 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
848	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR1LSMJ0214 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1650-OH1 12- Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 505,902 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX		Usage: 663,899 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLE SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX

Lot #	Details	Lot #	Details
853	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHFG2KSLM8011 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 605 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 395 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, Dual Fuel Tanks Usage: 415,568 Mi Notes: LOCATED-IN-FORT-WORTH-TX PER THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN Asset located in: Humble, TX	856	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSKF5676 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 22183 Engine hrs, Engine Brake, Detroit DT12 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 610,297 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
854	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSLG2419 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1750 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 500,910 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ;	857	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2KSHU6374 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 13677 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 631,008 Mi Asset located in: Humble, TX
855	Asset located in: Humble, TX 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3KSKF3926 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Thermo King Tripac Auxiliary Power Unit, Aluminum Front Wheels, 275/80R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 551,919 Mi Asset located in: Humble, TX	858	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3KSHU6450 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15649 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 692,413 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
859	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4KSKH3019 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23189 Engine hrs, Engine Brake, Detroit DT12-1650-DH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 700,170 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX	862	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSKB5467 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17897 Engine hrs, Engine Brake, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 744,509 Hr Asset located in: Humble, TX 2019 Freightliner Cascadia 126 6x4 T/A
860	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR3KLKJ3572 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14880 Engine hrs, Engine Brake, Detroit DT12-1750-OH1 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Electric Sleeper Air Conditioner, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	864	Sleeper Truck Tractor S/N: 3AKJHHDR4KSHU6635 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Engine Brake, Automated Transmission, 12350 Ib Front Axle, 40000 Ib Rears, 52350 Ib GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 828,837 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 126 6x4 T/A
861	Usage: 704,993 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR0KSKH3017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 26157 Engine hrs, Engine Brake, Detroit DT12- 1650 DH1 12 Speed Automated Transmission	-	Sleeper Truck Tractor S/N: 3AKJHHDROKSKY4314 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 227 in Wheelbase,
	1650-DH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,578 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in : Humble, TX	865	Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 579,455 Mi Asset located in: Humble, TX 2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR0KSKY3762 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FAO-16810C 10- Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Thermo King Tri- Pac Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,917 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
866	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLFG8KSLE1713 C/W: Cummins ISX15 450 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12324 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 382,610 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG	869	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV6KLKD4477 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12351 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Thermo King Auxiliary Power Unit, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,467 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	871	2019 Freightliner Cascadia 125 6x4 T/A
867	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV1KLKD4452 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1550- OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel		Sleeper Truck Tractor S/N: 3AKJGLDR1KDKM9520 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR- 15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel Usage: 473,185 Mi Asset located in: Humble, TX 2019 Ereightliner Cascadia 125 6x4 T/A
	Tanks	874	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
868	Usage: 438,561 Mi Asset located in: Humble, TX 68 2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR5KDKM9522 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19103 Engine hrs, Engine Brake, Eaton Fuller FRM- 15210B 10-Speed Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air	_	S/N: 3AKJGLDVXKSKH9488 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23103 Engine hrs, Retarder, 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 680,003 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	875	2019 Freightliner Cascadia 125 6x4 T/A
	Usage: 524,983 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Sleeper Truck Tractor S/N: 3AKJGLDR3KDKG6301 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15355 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Bergstrom Electric Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 719,256 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
876	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV6KSKH9486 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23543 Engine hrs, Detroit DT12-1550- OH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 720,855 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	879	2019 Volvo VNL780 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2KN211694 C/W: Volvo D13M455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 695,175 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
877	2020 Freightliner Cascadia 116 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHPDV8LSLF0404 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 22242 Engine hrs, Engine Brake, Detroit DT12-1550-DH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4S HH NFD Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 252,232 Mi Notes: LOCATED-IN-FORT-WORTH-TX-HOU	880	2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH5KN211687 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, 25856.7 Engine hrs, Engine Brake, Volvo ATO2612F 12- Speed Automated Transmission, Meritor MT- 40-14X Drive Axles, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,056 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
878	Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 116 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHPDV2KSKF9689 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1550-DH1 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 469,839 Mi Asset located in: Humble, TX	882	2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6KN214100 C/W: Volvo D13H455 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16462 Engine hrs, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel Usage: 581,651 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2020 Volvo VNL64T740 6x4 T/A Sleeper Truck
			Tractor S/N: 4V4NC9EH8LN258469 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14884 Engine hrs, Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, 295/75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,732 Hr Notes: LOCATED-IN-HUMBLE-TX Asset located in: Humble, TX

Lot #	Details	Lot #	Details
885	2020 Volvo VNR400 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DHXLN270435 C/W: Volvo 6 Cylinder 10.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10632 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5, Volvo Corporate Air Air Ride Suspension, 203 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 317,822 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	889 890A	2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR8KN707107 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 13200 Ib Front Axle, 40000 Ib Rears, 53200 Ib GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 507,769 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2019 International 6x4 T/A Day Cab Truck
886	2019 Volvo VNR400 6x4 T/A Sleeper Truck Tractor S/N: 4V4WC9DH5KN217446 C/W: Volvo D11M 6 Cylinder 10.8 L 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5, Volvo Air Ride Suspension, 198 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 451,707 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Tractor S/N: 3HSDZAPR8KN256213 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8388 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 408,807 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
887	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR4LN800109 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, 15026 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Tripac Auxiliary Power Unit, 11R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 571,619 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER MAINTENANCE	890	Usage: 408,807 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7KN112927 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18532 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 530,126 Mi Asset located in: Humble, TX
	RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	891	2018 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR2JLJZ0716 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 27535 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40009 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 653,881 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details	Lot #	Details
2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6HD417518 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 14401.9 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MR2014X Drive Axles, 3.08:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, HP2000 Extreme Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Blower, Dual Fuel Tanks Usage: 645,132 Mi Asset located in: Humble, TX	897	2014 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHDP9X9ED208358 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 23336 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Spicer DSP40 Drive Axles, 50000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 245 in Wheelbase, Dual Fuel Tanks Usage: 883,374 Mi Notes: LOCATED-IN-FORT-WORTH-TX , THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN
2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X1GD298100 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 595,513 Mi	899	ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor
2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2GD281174 C/W: Cummins 6 Cylinder Diesel Engine, 29303 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 883,597 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	901	S/N: 1XKYDP9X6JJ210795 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 16372 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 297/75R22.5, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 592,164 Mi Notes: LOCATED-IN-HUMBLE-TX Asset located in: Humble, TX 2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X5JJ135569 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX
_	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X6HD417518 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 14401.9 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MR2014X Drive Axles, 3.08:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, HP2000 Extreme Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Blower, Dual Fuel Tanks Usage: 645,132 Mi Asset located in: Humble, TX 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X1GD298100 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 595,513 Mi Asset located in: Humble, TX 2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2GD281174 C/W: Cummins 6 Cylinder Diesel Engine, 29303 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 883,597 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor897S/N: 1XPBDP9X6HD417518 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 14401.9 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MR2014X Drive Axles, 3.08:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, HP2000 Extreme Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Blower, Dual Fuel Tanks Usage: 645,132 Mi8000 lb Rears, Meritor MR2014X Drive Axles, 3.08:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, HP2000 Extreme Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Blower, Dual Fuel Tanks Usage: 645,132 Mi8000 lb Rears, 52350 lb CVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 595,513 Mi899Asset located in: Humble, TX2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X2GD281174 C/W: Cummins 6 Cylinder Diesel Engine, 29303 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 83,597 Mi8901Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT901

Lot #	Details	Lot #	Details
903	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3GJ473723 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18566 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 42 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 563,861 Mi Asset located in: Humble, TX	907	2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKADP9X4DJ356635 C/W: Paccar MX 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20923 Engine hrs, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 62 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Assist Front Suspension, Paccar Air Ride Suspension, 240 in Wheelbase, Air
904	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49XXGJ101330 C/W: Cummins ISX15 450ST 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 30265 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50350 lb GVWR, 72 in Ulich Diese Schenzer Ceb Ruck Rade, Alumeirum		Sliding 5th Wheel, Dual Fuel Tanks Usage: 831,886 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2013 Kenworth T700 6x4 T/A Sleeper Truck Tractor S/N: 1XKFDP9X0DJ331902 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel
	High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Usage: 726,673 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		Exhaust Fluid, 3267 Engine hrs, Eaton Fuller FOM-16E310C-LAS 13-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.25:1 Axle Ratio, 53200 lb GVWR, 50 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 615,605 Mi Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Lake Worth, TX 2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM051321 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, 20180 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13250 lb Front Axle,
905	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X9FJ449653 C/W: Paccar 6 Cylinder Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 23432		
	Engine hrs, Engine Brake, Automatic Transmission, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, 295/75R22.5, 8-Bag Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 810,190 Mi Asset located in: Humble, TX 906 2014 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X5EJ385237 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2005 US EPA Label, Requires Diesel Exhaust Fluid, 13956.5 Engine hrs.	909	
906			40000 lb Rears, 53250 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 224 in Wheelbase Usage: 515,958 Mi Asset located in : Humble, TX
		910	2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8FM051320 C/W: Mack MP7 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 8246 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 215 in Wheelbase Usage: 655,608 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
911	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, 26792 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 285 /75R24.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase Usage: 871,001 Mi Asset located in: Humble, TX	916 917	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8JSJR1197 C/W: Detroit DD15 6 Cylinder Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 13751 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 690,279 Mi
912	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor		Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX
	S/N: 1M1AW02Y8DM031484 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 216 in Wheelbase Usage: Not Available Asset located in: Humble, TX		2018 Freightliner 126 6X4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR3JSJW4070 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diese Exhaust Fluid, 20312 Engine hrs, Detroit DT12 1650-OH1-HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Meritor RT-40.0-4 HT Drive Axles, 3.08:
913		-	Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 626,634 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Cab, 295/75R22.5, Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 700,969 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	,	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDV3JSJR8314 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor
914	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHFG6JSJJ1536 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19668 Engine hrs, Engine Brake, Eaton Fuller FAOM-15810S 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 531,460 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Dual Fuel Tanks Usage: 788,655 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
920	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHFGXJSJW1596 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 25160 Engine hrs, Engine Brake, Eaton Fuller FAOM-15810S-EC Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 830,526 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	924 925	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV0JLJK2907 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14135 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 Ib Front Axle, 40000 Ib Rears, 52000 Ib GVWR, Air Ride Cab, 60 in Flat Top Sleeper Cab, Thermo King Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 540,841 Mi Asset located in: Humble, TX 2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
	THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1FUJGLDR1JLJK3289
921	2018 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6JDJS5628 Usage: 317,722 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 621,799 Mi
922	2018 Freightliner Cascadia 125 6x4 T/A		Notes: CPC HAS BEEN REMOVED FROM THIS TRUCK AND STORED IN THE OFFICE
	Sleeper Truck Tractor S/N: 3AKJGLDR0JSJH2516		Asset located in: Humble, TX
	C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15289 Engine hrs, Detroit DT12- OA-1650 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,071 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in : Humble, TX	926	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR1HLJG3300 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 45 hp Engine, 2017 US EPA Label, Requires Diese Exhaust Fluid, Engine Brake, Eaton Fuller FRO 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 34 ir Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
923	2018 Freightliner Cascadia 125 6x4 T/A	-	Usage: 458,699 Mi Notes :
920	Solution Streightiner Cascadia 125 6x4 1/A Sleeper Truck Tractor S/N: 3AKJGLDR2JDJT9266 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17275 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 540,539 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX		RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX

Lot #	Details	Lot #	Details
927	Sleeper Truck Tractor S/N: 1FUJGLDR7HLJG3298 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 15724.4 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-4 HT Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, airliner Air Ride Suspension, 236 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 582,475 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	932	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDRXHSJC8811 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OA- 1650 HD 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 824,733 Mi Asset located in: Humble, TX
		933	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDRXHSGW4469
929	Asset located in: Humble, TX 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR0HLHX4331 C/W: Detroit 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 17755 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Comfort Pro Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 610,010 Mi		C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 826,868 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	937A	2017 Freightliner Cascadia 125 6x4 T/A
931			Sleeper Truck Tractor S/N: 3AKJGLDR1HSHR5628 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 628,464 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		937	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG2HSJA3080 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810S-EC Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.62:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 781,986 Mi

Lot #	Details	Lot #	Details
938	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR3GLHA5529 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,432 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	942	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLBG4GLHJ1460 C/W: Cummins ISX15 6 Cylinder 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810C Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.62:1 Axle Ratio, 52350.0 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 688,311 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
939	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR3GLGT8855 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 20296 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 641,028 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	943	Asset located in: Lake Worth, TX 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD66GSHC4487 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18886 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 755,342 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION DEPORT
941	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV3GSHC6947 C/W: Detroit DD13 6 Cylinder 12.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 26117 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5, Air Assist Front Suspension, Airliner Air Ride Suspension, 235 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 668,171 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	945	THE INSPECTION REPORT Asset located in: Humble, TX 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV3GSHM3347 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21834 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 693,914 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
947	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	951	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
	S/N: 3AKJGLBG6GSHT7580 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 3AKJGLBG2GSGZ5263 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 13961 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C-LAS Ultrashift Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 53300 lb GVWR, 70 in High Rise Sleeper Cab, Thermo King Electric Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 557,375 Mi Asset located in : Humble, TX
	Asset located in: Humble, TX	952	2015 Freightliner Cascadia 125 6x4 T/A
948	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD56GSGN1939 C/W: Detroit DD15 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 16757 Engine hrs, Engine Brake, Eaton Fuller FR-15210B 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks		Sleeper Truck Tractor S/N: 3AKJGLDV9FSGK2899 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22574 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 Ib Front Axle, 40000 Ib Rears, 3.42:1 Axle Ratio, 52350 Ib GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 471,635 Mi Asset located in: Humble, TX
	Usage: 701,624 Mi	953	2015 Freightliner Cascadia 125 6x4 T/A
949	Asset located in: Humble, TX 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD56GSHP2843 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 712,997 Mi		Sleeper Truck Tractor S/N: 3AKJGLD54FSFK4749 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 22930 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 588,173 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	954	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGHDV8FSGL7536 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17707 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 664,589 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
955	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD51FLGD0566 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OA-1750 HD 12- Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 2.85:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,042,345 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	958 959 960	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD54FLGE3862 C/W: Detroit 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 299 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 724,909 Mi Notes: LOCATED-IN-MIDLAND-TX . Asset located in: Midland, TX 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD6XFSAG2746 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, Requires Diesel Exhaust Fluid, 24048 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 781,669 Mi Asset located in: Humble, TX 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
956	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD52FSGK9029 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 24886 Engine hrs, Engine Brake, 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 697,726 Mi Notes: LOCATED-IN-FORT-WORTH-TX ,		
957	BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ; ITEM ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - CPC ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV1FSGC4111 C/W: Detroit DD13 6 Cylinder 12.8 L 500 hp Engine, 2014 US EPA Label, 15774 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52500 lb GVWR, Air		S/N: 3AKJGLD53FSGH9952 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 45413 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 882,767 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Ride Cab, 70 in Mid Roof Sleeper Cab, Electric Sleeper Air Conditioner, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 709,282 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	961	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD66FSGL9720 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 843,243 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
962	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD69FLGN1999 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-16913A 13- Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 52300 lb GVWR, 58 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, 232 in Wheelbase, Air Sliding 5th Wheel Usage: 112,065 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	966	2014 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLD58ESFK2646 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 27101 Engine hrs, Engine Brake, Eaton Fuller RTOCM- 16909A 13-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 46350.0 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 191,299 Mi Asset located in: Humble, TX
963	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV4FLGM6667 C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18642 Engine hrs, Eaton Fuller 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 632,880 Mi Asset located in: Humble, TX	967 968	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD50ESFY3229 C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 24797 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 816,732 Mi
964	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD55FSGB5654 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 33891 Engine hrs, Engine Brake, Detroit DT12-OA-1650 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 986,645 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD52ESFR3485 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22596 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 899,662 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION PEROPT
965	2015 Freightliner Cascadia 125 6x2 T/A Sleeper Truck Tractor S/N: 1FUGGLDV6FLGC1453 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17671 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 20K R-SRS Drive Axles, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 471,980 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
969	2013 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR0DSBR0012 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 25813 Engine hrs, Engine Brake, Eaton Fuller RTOCM- 16909A 9-Speed Manual Transmission, 13300 Ib Front Axle, 40000 Ib Rears, Detroit DA-RT- 40.0-4 Drive Axles, 3.42:1 Axle Ratio, 53300.0 Ib GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 967,604 Mi Asset located in: Humble, TX	972	2012 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR9CSBU1938 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 27153 Engine hrs, Eaton Fuller FRW- 15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 856,871 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor
970	2013 Freightliner Cascadia 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR7DSBB5155 C/W: 6 Cylinder Diesel 455 hp Engine, 27508.2 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Rear Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 128,090 Mi Notes: ODOMETER DISCREPANCY-PLEASE SEE INSPECTION REPORT DEFICIENCIES NOTED Asset located in: Humble, TX	973 974A	S/N: 4V4NC9TH2FN912681 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2011 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200.0 lb GVWR, Air Ride Cab, 42 in High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 480,143 Mi Notes : THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY
971	2013 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLBG2DLBZ8110 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires		EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Diesel Exhaust Fluid, 23467 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 kg GVWR, 58 in High Rise Sleeper Cab, 275/80R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 566,759 Mi Asset located in : Humble, TX		2013 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EJ0DN144762 C/W: Volvo D13H455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 35268 Engine hrs, Volvo ATO2612D Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 53200 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride
972A	2015 Volvo VNL670 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EG2FN183196 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612D Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 42 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Volvo Corporate Air Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,019,031 Mi		Auffinitian Outer Wheels, TTR22.3, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,131,390 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
974	2013 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TG1DN135981 C/W: Cummins ISX15 400ST 6 Cylinder 15 L Diesel 400 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 77 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 877,295 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN	979 980 980 981	2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3JN532408 C/W: Cummins X15 6 Cylinder 15.0 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 633,963 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Humble, TX		2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR2JN530990 C/W: Cummins X15 450SA 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 22612 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles,
976	976 2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3JN424032 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission,		3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, International IROS Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 644,374 Mi Asset located in: Humble, TX
	13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 415,632 Mi Notes : ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in : Humble, TX		2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPRXJN248578 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19058 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk
977			Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 595,641 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		982	2018 International LT625 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7JN205056 C/W: Cummins Engine Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
983 984	2017 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSNR4HN447796 C/W: Navistar A450MT 6 Cylinder 12.4 L Ultra Low Sulfur Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16541 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 428,511 Mi Asset located in: Humble, TX 2017 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor	987	
	•		INSPECTION REPORT
	Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, International IROS Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 478,931 Mi Asset located in: Humble, TX 35 2017 International ProStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR9HN652182 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19739 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, 73 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, International IROS Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 766,372 Mi Asset located in: Humble, TX	989 989 990B	Asset located in: Lake Worth, TX 2014 International ProStar+122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR7EN796955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17185 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
985			
			2012 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJSJR7CN094078 C/W: 6 Cylinder Diesel Engine, 34209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 11R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th
986			Wheel, Dual Fuel Tanks Usage: 689,264 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		990A	2012 International Prostar 6x4 T/A Sleeper
			Truck Tractor S/N: 3HSDJSJR1CN094075 C/W: 6 Cylinder Diesel Engine, 27815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 798,884 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
990	2013 International ProStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR0DN273354 C/W: 12832 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 Ib Front Axle, 40000 Ib Rears, 52350 Ib GVWR, 56 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 408,972 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	994	2008 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDU9X38J217145 C/W: Cat 6 Cylinder Diesel Engine, 22732.0 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Air Ride Cab, 28 in Flat Top Sleeper Cab, 275/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 204 in Wheelbase, PTO, Wet Kit, Headache Rack Usage: 298,453 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
991	2008 Peterbilt 388 6x4 T/A Sleeper Truck	005	Asset located in: Humble, TX
	Tractor S/N: 1XPWD40X88D750381 C/W: Cummins ISX 6 Cylinder 15 L Diesel 400 hp Engine, 2005 US EPA Label, 33217 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 224,527 Mi	995	1999 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWDR9XXXR815058 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 260 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 945,634 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	996	2000 Freightliner FLD 120 6x4 T/A Sleeper
992	2008 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X88D750378 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2007 US EPA Label, CARB Compliant, 3762 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, 44 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 251 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 320,021 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	998	Truck Tractor S/N: 1FUPC7WB1YLA88571 C/W: Cummins Signature Series 600 6 Cylinder 15.0 L Diesel 600 hp Engine, 1999 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 267 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 807,468 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2005 International 9400i T/A Sleeper Truck
003		-	Tractor
993	2009 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDU9X49J256621 C/W: Cat C13 6 Cylinder Diesel Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller FR014210C Manual Transmission, Differential Lock, 12000 lb Front Axle, 44000 lb Rears, Meritor RT-40-145 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 38 in Flat Top Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 198 in Wheelbase, PTO, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	999	S/N: 3HSCNAPR95N002019 Usage: Not Available Asset located in: Humble, TX 2005 International 9400i 6x4 T/A Sleeper Truck Tractor S/N: 2HSCNSBR55C033430 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 248 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 680,708 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1000	2001 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DR9X61D538905 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 8017 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Low Air Leaf Air Ride Suspension, 246 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 142,551 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1997 Peterbilt 378 6x4 T/A Sleeper Truck	1007	2009 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR39LAK1703 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2008 US EPA Label, 25234 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 45400 lb Rears, 3.58:1 Axle Ratio, 57400 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 11R24.5 Front Tires, 285 /75R24.5 Rear Tires, Airliner Air Ride Suspension, 240 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 193,151 Mi Notes: WAS PREVIOUSLY SALVAGED BEFORE
	Tractor S/N: 1XPFDR8X6VN422657 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,396,556 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1008	Asset located in: Humble, TX 2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CV89DAG6935 C/W: Mercedes-Benz 6 Cylinder Engine, 3767 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 468,087 Mi
1004	2006 Peterbilt 387 6x4 T/A Sleeper Truck Tractor S/N: 1XP7DB9X16D888837 C/W: Cat C15 6 Cylinder Diesel Engine, Engine Brake, 13-Speed Manual Transmission, 12000 Ib Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Air Ride Suspension, 243 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,896,411 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1009	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CV29DAG6929 C/W: Mercedes Benz 6 Cylinder 12.8 L Diesel 450 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 295
1005	THE INSPECTION REPORT Asset located in: Humble, TX 2005 Kenworth T600 T/A Sleeper Truck Tractor S/N: 1XKADB9XX5J085441 Usage: Not Available	-	75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 538,849 Mi Asset located in: Humble, TX
1006	Asset located in: Humble, TX 2000 Kenworth T2000 6x4 T/A Sleeper Truck Tractor S/N: 1XKTD69X2YJ839226 C/W: 6 Cylinder Diesel Engine, 4778 Engine hrs, 10-Speed Manual Transmission, 62 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, 8-Bag Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 407,466 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE AND SOLD WITH A BONDED TITLE. Asset located in: Humble, TX	_1010	2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CV49DAG6933 C/W: Mercedes Benz 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, 2008 US EPA Label, 28415 Engine hrs, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 34 in Flat Top Sleeper Cab, 295/75R22.5, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 688,850 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1011	2007 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK37LY88939 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 33617.5 Engine hrs, Engine Brake, Eaton Fuller FM—15D_10B-LST Automated Transmission, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 12R22.5 Rear Tires, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 845,685 Mi Asset located in: Humble, TX	1015	2007 Freightliner CST120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJBBCK57PU33895 C/W: Detroit Series 60 14.0 L Diesel Engine, 2006 US EPA Label, 39949 Engine hrs, Engine Brake, Eaton Fuller 9-Speed Manual Transmission, 60 in High Rise Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,430,680 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1012	2007 Freightliner Columbia 120 T/A Sleeper Truck Tractor S/N: 1FUJA6CK17LX78021 Usage: Not Available Asset located in: Humble, TX	- 1016 - 1017 - 1017	2009 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EJX9N269596 C/W: Volvo D13F485 6 Cylinder 12.8 L Diesel 485 hp Engine, 2008 US EPA Label, Engine Brake, Volvo ATO2512C 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor RT-40-145 Drive Axles, 3.21:1
1013	 2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK46LV45166 C/W: Detroit Series 60 6 Cylinder Ultra Low Sulfur Diesel Engine, 1166 Engine hrs, Meritor 10-Speed Manual Transmission, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 287 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,525,547 Mi Asset located in: Humble, TX 		Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 818,186 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
			2007 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9GH07N452013 C/W: Volvo 6 Cylinder 12.1 L Ultra Low Sulfur
1014	2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CVX6DW53148 C/W: Mercedes Benz 6 Cylinder Diesel 450 hp Engine, 2005 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 958,555 Mi		Exhaust Brake, Automatic Tran 12350 lb Front Axle, 38000 lb R GVWR, Air Ride Cab, 70 in High Cab, Bunk Beds, Aluminum Who 5, Air Ride Suspension, 243 in V Sliding 5th Wheel, Dual Fuel Tar Usage: 1,310,650 Mi Notes : LOCATED-IN-FORT-WOF DEFICIENCIES NOTED - PLEASI INSPECTION REPORT
	Asset located in: Humble, TX	1018	2007 Volvo VNL670 6x4 T/A Sleeper Truck
1015A	2007 Freightliner Century Class CST120 6x4 T /A Sleeper Truck Tractor S/N: 1FUJBBAV37LX21774 C/W: Cat C15 6 Cylinder Diesel Engine, 18993 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: 955,175 Mi Asset located in: Humble, TX		Tractor S/N: 4V4NC9TGX7N429657 C/W: Cummins 6 Cylinder 15 L 400 hp Engine, Engine Brake, Eaton Fuller RTO-16210B 10- Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Volvo Corporate Air Air Ride Suspension, 212 in Wheelbase, Dual Fuel Tanks Usage: 762,801 Mi Notes: LOCATED-IN-MIDLAND-TX . Asset located in: Midland, TX

Lot #	Details	Lot #	Details
1020	2019 Freightliner Cascadia 126 4x2 S/A Day Cab Truck Tractor S/N: 3AKBHKDV1KSKE0316 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15921 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.08:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 636,988 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1026	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG9KN901847 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 784,694 Mi Notes: LOCATED-IN-LIVINGSTON_LA_TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
1021	2019 Freightliner Cascadia 126 4x2 S/A Day Cab Truck Tractor S/N: 3AKBHKDVXKSKE0279 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15388 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Detroit DA-RS-23.0-6 Drive Axles, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 733,234 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1027	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG7KN901975 C/W: Volvo D13M 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19516 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5, Volvo Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 809,812 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Volvo VNR300 4x2 S/A Day Cab Truck
1022	2019 Freightliner Cascadia 116 4x2 S/A Day Cab Truck Tractor S/N: 3AKBHSDV8KSKT8745 C/W: 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 15801 Engine hrs, Retarder, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel Usage: 725,415 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1029	Tractor S/N: 4V4W19EG8KN901998 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F Automated Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 152 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 801,565 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Volvo VNR300 4x2 S/A Day Cab Truck
1023	2023 Volvo VNR300 S/A Day Cab Truck Tractor S/N: 4V4W19EG7PN616829 Usage: 68,000 Mi Asset located in: Humble, TX	- Tractor S/N: 4V4W19EG2KN901933 C/W: Volvo D13M 6 Cylinder 12.8 L hp Engine, 2018 US EPA Label, Rec Exhaust Fluid, 16928 Engine hrs, V	S/N: 4V4W19EG2KN901933 C/W: Volvo D13M 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16928 Engine hrs, Volvo
1024	2022 Volvo VNR300 S/A Day Cab Truck Tractor S/N: 4VAW19EGXNN285791 Usage: 150,000 Mi Asset located in: Humble, TX		AT2612F 12-Speed Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 153 in Wheelbase, Dual Fuel Tanks Usage: 718,615 Mi
1025	2022 Volvo VNR300 S/A Day Cab Truck Tractor S/N: 4V4W19EHXNN286271 Usage: 200,000 Mi Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1031	2013 Peterbilt 337 4x2 S/A Day Cab Truck Tractor S/N: 2XP2AN8X3DM195099 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 12944.8 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-170 Drive Axles, 5.25: 1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Trac Air Ride Suspension, 155 in Wheelbase Usage: 387,456 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1037	1037 2018 Freightliner Cascadia 126 4x2 S/A Day Cab Truck Tractor S/N: 3AKBHLDV4JSJZ6353 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diese Exhaust Fluid, Detroit DT12-1450-DH1-8 HD 12 Speed Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-161 Drive Axles, 2.50:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 518,001 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET
1032	2015 Kenworth T880 4x2 S/A Day Cab Truck Tractor		VEHICLE-PAG ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1XKZAP8X9FJ457590 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller F016E310C LAS 10-Speed Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Paccar S23-170 Drive Axles, 3.21:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 154 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 611,352 Mi Asset located in : Humble, TX	1039	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDVXFSGB5613 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15260.2 Engine hrs, Engine Brake, Eaton Fuller FO-14E313A-MHP 13- Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
1034	2013 Kenworth T660 S/A Day Cab Truck Tractor S/N: 1XKAA48X1DJ354916		Usage: 323,473 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX
1035	2015 Kenworth T370 S/A Day Cab Truck Tractor S/N: 2NKHHJ7XXFM440189 Usage: Not Available Asset located in: Humble, TX 2011 Kenworth T370 4x2 S/A Day Cab Truck Tractor S/N: 2XKHAM8A4BM286773 C/W: Paccar PX-6 280 6 Cylinder 6.7 L Diesel 280 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, 6967 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 153 in Wheelbase Usage: 173,734 Mi Asset located in: Humble, TX	1040	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0116 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21899 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 103,560 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGB0168 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21997 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 Ib Front Axle, 21000 Ib Rears, 33000 Ib GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 110,105 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1042	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0107 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21506 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 kg Rears, Meritor RS23 Drive Axles, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 187,415 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1046	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGB0220 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15922 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 3.42:1 Axle Ratio, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 777,139 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
1043	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0312 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18454.5 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RA-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 250,355 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1049	Cab Truck Tractor S/N: 1FUBGDD5XFLGB0097 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 2007 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 781,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
1044	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGJ1292 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 604,997 Mi Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day	-	Cab Truck Tractor S/N: 1FUBGDD53FLGB0152 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19047.5 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 837,506 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Cab Truck Tractor S/N: 1FUBGDD59FLGB0317 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14310 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 669,581 Mi Asset located in: Humble, TX	1049	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGB0122 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1348 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 842,477 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1050	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0001 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17962.1 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 851,140 Mi Asset located in: Humble, TX	1054	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0050 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18243 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 859,499 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1051	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor		Asset located in: Humble, TX
1050	S/N: 1FUBGDD55FLGB0413 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17637 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 853,270 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1055	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0201 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19095 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,507 Mi Asset located in: Humble, TX
1052	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	1056	2015 Freightliner Cascadia 125 4x2 S/A Day
	S/N: 1FUBGDD59FLGB0172 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18572 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 853,329 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		Cab Truck Tractor S/N: 1FUBGDD54FLGJ1265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,990 Mi Asset located in: Humble, TX
1053	2015 Freightliner Cascadia 125 4x2 S/A Day	1057	2015 Freightliner Cascadia 125 4x2 S/A Day
	Cab Truck Tractor S/N: 1FUBGDD55FLGJ1307 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19322 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 858,405 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Cab Truck Tractor S/N: 1FUBGDD52FLGB0191 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 873,692 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1058	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGJ1288 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18389 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 879,780 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1062	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0096 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19168.6 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 893,840 Mi Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
	THE INSPECTION REPORT Asset located in: Humble, TX		Cab Truck Tractor
1059	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0178 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18685 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Transmission, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 881,722 Mi	-	S/N: 1FUBGDD54FLGJ1184 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20771 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 898,557 Mi
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
1060	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0066 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18727 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 882,386 Mi Asset located in: Humble, TX	-	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGJ1230 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19151.7 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 905,857 Mi Notes: ODOMETER DISCREPANCY UNIT SHOWS 905,857, TITLE SHOWS 923,782
	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0189 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20032 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 885,785 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1065	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGJ1187 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17946 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 908,401 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1066	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0402 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21951 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.47:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 911,547 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1070	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0190 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20077 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 948,390 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	THE INSPECTION REPORT	1071	2015 Freightliner Cascadia 125 4x2 S/A Day
1067	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0162 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19314 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks		Cab Truck Tractor S/N: 1FUBGDD54FLGB0340 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 949,669 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 921,973 Mi	1072	2015 Freightliner Cascadia 125 4x2 S/A Day
1068	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0169 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18791 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks	1072	Cab Truck Tractor S/N: 1FUBGDD58FLGB0163 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22040 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 956,335 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Usage: 923,856 Mi	1073	2015 Freightliner Cascadia 125 4x2 S/A Day
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Cab Truck Tractor S/N: 1FUBGDD59FLGJ1178 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1557 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 956,831 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1069	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGB0434 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18038 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 935,396 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
1074	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0064 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20210 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 959,332 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1078A	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDV6FLGP7106 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO- 14E310C-LAS Automated Transmission, 12000 Ib Front Axle, 23000 Ib Rears, Meritor RS-23- 161 Drive Axles, 3.58:1 Axle Ratio, 33000 Ib GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 190 in Wheelbase, Dual Fuel Tanks Usage: 131,229 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT
1075	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor		SECTION BELOW
	S/N: 1FUBGDD53FLGJ1242		Asset located in: Humble, TX
	C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19775 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 986,983 Mi Asset located in : Humble, TX	1078	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD54FLGB0273 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 22700 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel
1076	2015 Freightliner Cascadia 125 4x2 S/A Day	1	Tanks Usage: 1,061,567 Mi
1070	Cab Truck Tractor S/N: 1FUBGDD56FLGB0260 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
Engine hrs, Engine Brake, Eaton Full 15210C 10-Speed Manual Transmis 12000 lb Front Axle, Meritor RS23 D 3.42:1 Axle Ratio, 33000 lb GVWR, A	Label, Requires Diesel Exhaust Fluid, 18869 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in	1079	2014 Freightliner Cascadia 125 S/A Day Cab Truck Tractor S/N: 1FUBGEBG0ELFT4306 Usage: Not Available Asset located in: Humble, TX
	Wheelbase, Dual Fuel Tanks Usage: 991,149 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1080	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57ELFL7290 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 682,222 Mi Asset located in: Humble, TX
1077	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGJ1192 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20429.8 Engine hrs, Engine Drake Factor FD0 150100 100 model		
Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axl 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride (Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,007,261 Mi	21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,007,261 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1081	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR8DLBX1020 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 3.42:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 642,780 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1082	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR0DLBX1187 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19292 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 713,691 Mi Asset located in: Humble, TX	1086	
1083	 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR2DLBX0932 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18045 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 721,588 Mi Asset located in: Humble, TX 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX0995 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel 		Fuel Tanks Usage: 745,581 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		1087	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR6DLBX0996 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18679 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 746,424 Mi Asset located in: Humble, TX 2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR8DLBX0952 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18814 Engine hrs, Engine Brake, Eaton Fuller FRO-
1084			
		1088	
1085 2013 Freightliner Cascadia Cab Truck Tractor S/N: 1FUBGDDR1DLBX099 C/W: Detroit DD15 6 Cylind hp Engine, 2012 US EPA La Exhaust Fluid, 19346 Engin	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR1DLBX0999 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19346 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission,		15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 759,762 Mi Asset located in : Humble, TX
	12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 739,978 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1089	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR5DLBU9573 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18024.3 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 762,470 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1090	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR6DLBX1131 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 17213.1 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 785,839 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1094	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBU6992 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20205 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 947,488 Mi Asset located in: Humble, TX
1091	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX0947 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18831 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 795,751 Mi Asset located in: Humble, TX	_1095	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7DLBU9574 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 17420.3 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,015,310 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1092	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FLUBGDDR9DLBX1074 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22139 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 818,005 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1096	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR3DLBX1068 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19122 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 925,930 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1093	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX1001 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21299 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 864,678 Mi Asset located in: Humble, TX	1097	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBU7060 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20334 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 907,140 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1098	2012 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7CLBF2999 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18070.1 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 570,711 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1102D	2015 Volvo VNM 4x2 S/A Sleeper Truck Tractor S/N: 4V4M19EH2FN184651 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21415 Engine hrs, Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 718,832 Mi Notes: TITLE COMES WITH STATEMENT OF FACTS CORRECTING THE TITLE Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	1102C	2014 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH1EN177088
1099	2017 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGADV1HSHX5191 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 12599.8 Engine hrs, Engine Brake, Detroit Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks, Gooseneck Ball Hitch Usage: 161,096 Mi Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1102B	C/W: Volvo D13H425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 854,779 Mi Notes : TITLE COMES WITH AFFIDAVIT CORRECTION Asset located in : Humble, TX 2014 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH9EN154061 C/W: Volvo D13H425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 25603.7 Engine hrs, Engine Brake, ZF 12-Speed Automated
	Asset located in: Midland, TX		Transmission, 12350 lb Front Axle, 20000 lb Rears, Meritor RS23-160 Drive Axles, 32350 lb
1100	· · ·	1102A	GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 900,627 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TITLE COMES WITH STATEMENT OF AFFIDAVIT Asset located in: Humble, TX 2015 Volvo VNL 4x2 S/A Day Cab Truck Tractor
			S/N: 4V4M19EH4FN184666 C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15123 Engine hrs, Engine Brake, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles,
1101	2014 Freightliner M2 112 4x2 S/A Day Cab Truck Tractor S/N: 1FUBC4DV1EHFX8691 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 20329 Engine hrs, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.67:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 161 in Wheelbase, Dual Fuel Tanks Usage: 333,910 Mi Asset located in: Humble, TX		32350 lb GVWR, Air Ride Cab, 295/75R22.5, Volvo Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 579,823 Mi Notes : TITLE COMES WITH A CORRECTION OF AFFIDAVIT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1102	2011 Freightliner M2106 4x2 S/A Day Cab Truck Tractor S/N: 1FUBCYDT0BDAW9880 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 hp Engine, Requires Diesel Exhaust Fluid, 10583 Engine hrs, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 5.63:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22. 5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase Usage: 146,582 Mi Asset located in: Humble, TX	1108	2005 International 9400i 4x2 S/A Day Cab Truck Tractor S/N: 3HSCPSBN85N051359 C/W: Caterpillar C13 6 Cylinder 12.5 L Diesel 525 hp Engine, 2004 US EPA Label, 28255 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Air Ride Cab, 275/80R22. 5, Air Ride Suspension, 163 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 952,792 Mi Asset located in: Humble, TX 2009 Sterling A9500 4x2 S/A Day Cab Truck
1100		-	Tractor
1103	2012 Volvo VNL300 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG6CN560842 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 32350 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks		S/N: 2FWBA2CK69AAJ3273 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 19717 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 160 in Wheelbase Usage: 428,446 Mi Asset located in : Humble, TX
	Usage: 311,531 Mi	1110	2019 Freightliner Cascadia 125 4x2 S/A
1104	Asset located in: Humble, TX 2012 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG8CN560938 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18486 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12350 Ib Front Axle, 20000 Ib Rears, 32350 Ib GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 491,264 Mi	-	Sleeper Truck Tractor S/N: 3AKBGLFG8KSKU3824 C/W: Cummins X15 6 Cylinder 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Freightliner SmartShift Automated Transmission, 13300 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 34300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, 295 /75R22.5, Airliner Air Ride Suspension, 222 in Wheelbase, Dual Fuel Tanks Usage: 851,098 Mi Notes: LOCATED-IN-LAKE WORTH-TX
4405	Asset located in: Humble, TX		Asset located in: Lake Worth, TX
1105	2010 International Durastar 4400 4x2 S/A Day Cab Truck Tractor S/N: 1HSMKAAN4AH236673 C/W: International Maxxforce 6 Cylinder 7.6 L Diesel 285 hp Engine, 2009 US EPA Label, 8236 Engine hrs, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 151 in Wheelbase Usage: 167,445 Hr Asset located in: Humble, TX	1111	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5110PL041358 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 2401.1 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 130 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 5,068 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1107	2009 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor		THE INSPECTION REPORT
	S/N: 1FUBCYBS39DAK0631		Asset located in: Humble, TX
	C/W: Cummins ISC 6 Cylinder Diesel 285 hp Engine, 1250 Engine hrs, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 22700 lb Rears, Alliance ARS-23.0-4 Drive Axles, 3.58:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22. 5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 150 in Wheelbase Usage: 77,729 Mi Asset located in : Humble, TX	1112	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5114PL041363 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 2483.2 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 130 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 10,506 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1113	2021 Capacity 4x2 Spotter Truck S/N: 4LMBF5112ML029336 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 5069.7 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 130 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 11,355 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	1120	2016 Kalmar 4x2 Spotter Truck S/N: 343965 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 173 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9167 Engine hrs, Allison Automatic Transmission, 11R22.5, 116 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 15,929 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX
1115	2018 Ottawa 4x2 Spotter Truck S/N: 4LMSB2119JL031476 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 130 kW Engine, 5891 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 121 in Wheelbase	-1121	2006 Ottawa Commando 30 4x2 Spotter Truck S/N: 313811 C/W: Cummins 6 Cylinder Diesel Engine, 2005 US EPA Label, 12577 Engine hrs, Allison Automatic Transmission, 295/75R22.5, 110 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 12,577 Hr Asset located in: Humble, TX
	Usage: 5,891 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1122	2004 Kalmar Industries Spotter Truck S/N: 308637 C/W: Cat 6 Cylinder Diesel Engine, 22269 Engine hrs, Allison Automatic Transmission,
1118	2017 Capacity 4x2 Spotter Truck S/N: 4LMSB2116HL031400 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 23834 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 295/75R22.5, 116 in Wheelbase, Hydraulic Lift 5th Wheel, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET		12000 lb Front Axle, 24000 lb Rears, 36000 lb GVWR, 295/75R22.5, 116 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 89,797 Mi Notes : LOCATED-IN-FORT-WORTH-TX ; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in : Lake Worth, TX
	MAINTAINED-WALMART-FLEET Usage: 120,139 Mi Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET ; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX		2019 Peterbilt 567 12x4 Five Axle Dump Truc S/N: 1NPCLPEX9KD608543 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 684 Engine hrs, Engine Brake, Eaton Fuller 8LL
1119	2017 Kalmar 4x2 Spotter Truck S/N: 11VJ813A7HA000175 C/W: Cummins ISB6.7 200 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 18306 Engine hrs, Allison Automatic Transmission, Differential Lock, 12000 lb Front Axle, 24000 lb Rears, 36000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 118 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 35,573 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Manual Transmission, 20000 lb Front Axle, 69996 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 315/80R22.5 Front Tires, 295/80R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 282 in Wheelbase, PTO, 17 ft Long x 5 ft 5 in High Steel Body, Electric Roll Tarp, High-Lift Tailgate, Rear Hydraulics Usage: 152,092 Mi Notes : . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1124	2019 Freightliner Cascadia 126 12x4 Super 16 Five Axle Dump Truck S/N: 3AKBHKDV1KSKD5150 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8871 Engine hrs, Engine Brake, Detroit DT12-0A Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 295/75R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Double Frame, Airliner Air Ride Suspension, 288 in Wheelbase, 22 ft Long x 4 ft 4 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 413,686 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1128	1128 2017 Kenworth T880 10x4 Quad/A Dump Tru S/N: 1NKZXPTX9HJ158944 C/W: Paccar MX-13 Diesel Engine, Allison Automatic Transmission, Aluminum Wheels, Steerable Air Lift Pusher Axle, Double Frame, Chalmers Rubber over Walking Beam Suspension, Electric Roll Tarp Usage: 503,515 Mi Asset located in: Humble, TX
1125	2007 Peterbilt 567 14x4 Super 18 Five Axle Dump Truck S/N: 1XPFDT9X27D666651	-	Lift Pusher Axle, Double Frame, Paccar Air Ride Suspension, 246 in Wheelbase, PTO, 18 ft Long x 5 ft High Steel Body, Electric Roll Tarp Usage: 460,469 Mi Asset located in : Humble, TX
1126	C/W: Cat 6 Cylinder 11.1 L Diesel 385 hp Engine, 2006 US EPA Label, 18114 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 Ib Front Axle, 40000 Ib Rears, 52000 Ib GVWR, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Air Trac Air Ride Suspension, 260 in Wheelbase, 18 ft 6 in Long x 5 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 283,202 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2006 Peterbilt 567 14x4 Super 18 Five Axle	1130	2016 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 1FVSG5CY2GHGY9545 C/W: Cummins 6 Cylinder Diesel 370 hp Engine, Requires Diesel Exhaust Fluid, 19622 Engine hrs, Allison Automatic Transmission, Double Differential Locks, 18000 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 73000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Air Lift Pusher Axles, TufTrac Spring Suspension, 224 in Wheelbase, OX Bodies 18 ft 5 in Long x 4 ft 8 in High Steel Body, Round Bottom Usage: 469,348 Mi Asset located in: Humble, TX
	Dump Truck S/N: 1XPFDT9X86D644734 C/W: Diesel Engine, Engine Brake, 8LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Air Trac Air Ride Suspension, 260 in Wheelbase, PTO, Strong 18 ft 6 in Long x 5 ft High Steel Body, Electric Roll Tarp Usage: 187,657 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2016 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 1FVSG5CY4GHGY9546 C/W: Cummins ISL9 8.9 L Diesel 310 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 23070.9 Engine hrs, Allison Automatic Transmission, 18000 lb Front Axle, 55000 lb Rears, 73000 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Rubber over Walking Beam Suspension, 228 in Wheelbase, OX Bodies 18 ft Long x 4 ft 4 in High Steel Body, Round Bottom Usage: 646,213 Mi
1127	2017 Kenworth T880 10x4 Quad/A Dump Truck S/N: 1NKZXPTX6HJ158948 C/W: Paccar MX-13 Diesel Engine, Allison Automatic Transmission, Aluminum Wheels, 2 Steerable Air Lift Pusher Axle, Double Frame, Chalmers Rubber over Walking Beam Suspension, Electric Roll Tarp Usage: 503,176 Mi Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1132	2015 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 3ALSG5CYXFDGK4978 C/W: Cummins ISL 6 Cylinder 8.9 L Diesel 380 hp Engine, 2014 US EPA Label, 209172 Engine hrs, Eaton Fuller RTO-14908LL 8LL Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.63:1 Axle Ratio, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Air Lift Pusher Axles, Air Lift Tag Axle, Spring Suspension, 224 in Wheelbase, PTO, OX Bodies 18 ft Long x 4 ft 5 in High Steel Body, Round Bottom, Electric Roll Tarp, Swing Tailgate Usage: 596,159 Mi	1135	2022 Peterbilt 579 8x4 Tri/A Dump Truck S/N: 1XPBAP8X1ND759271 C/W: Paccar 6 Cylinder Diesel Engine, 2021 US EPA Label, 5122.4 Engine hrs, Paccar 12-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Air Trac Air Ride Suspension, 258 in Wheelbase, 16 ft Long x 3 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 225,681 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX
	Asset located in: Humble, TX	1136B	2018 Kenworth T680 8x4 Tri/A Dump Truck
1133	2015 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 3ALSG5CY8FDGK4977 C/W: Cummins ISL9 8.9 L Diesel 380 hp Engine, 10752 Engine hrs, Eaton Fuller 8LL Manual Transmission, Double Differential Locks, 18000 lb Front Axle, 56000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Air Ride		S/N: 1XKYAP8X4JJ209865 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 1 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 45400 lb Rears, 35050 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Paccar Air Ride Suspension, 213 in Wheelbase, PTO, 16 ft 5 in Long x 4 ft 8 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 495,045 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Suspension, 228 in Wheelbase, PTO, OX Bodies 18 ft Long x 4 ft 4 in High Steel Body, Round		Asset located in: Humble, TX
1134B	Bottom Usage: 621,809 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2000 Peterbilt 379 T/A Day Cab Truck Tractor S/N: 1XP5DR9X3YN499744 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 8899.2 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 2 Steerable Air Lift Pusher Axle, Air Leaf Air Ride Suspension, 260 in Wheelbase, PTO, 18 ft 7 in Long x 4 ft 11 in High Body, Flat Bed, Electric Roll Tarp Usage: 244,675 Mi Asset located in: Humble, TX	1136A	2017 Peterbilt 567 8x4 Tri/A Dump Truck S/N: 1NPCXKEX7HD411323 C/W: Paccar MX11 6 Cylinder 10.8 L Diesel 430 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 59500 lb Rears, 79500 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 445/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber Suspension, 212 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp, Pintle Hitch Usage: 242,185 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1134	2016 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 1FVSG5CYOGHGY9544 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18200 Engine hrs, Allison Automatic Transmission, 18000 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 73000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Air Lift Pusher Axles, TufTrac Suspension, 224 in Wheelbase, OX Bodies 18 ft 5 in Long x 4 ft 8 in High Steel Body, Round Bottom Usage: 514,329 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1136	2017 Peterbilt 567 Tri/A Dump Truck S/N: 1XPCDP9X3HD363017 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, 16 ft 5 in Long x 4 ft 7 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 532,469 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1137	2014 Mack CHU613 8x4 Tri/A Dump Truck S/N: 1M1AN07Y2EM016671 C/W: Mack MP8 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 3346 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, PTO, 16 ft 9 in Long x 4 ft 5 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 315,697 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1141A	2013 Kenworth T680 8x4 Tri/A Dump Truck S/N: 1XKYA58X1DJ355384 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20533.3 Engine hrs, Engine Brake, Eaton Fuller FM15E310B LAS 10-Speed Automatic Transmission, 12000 lb Front Axle, Dana S23-190 Drive Axles, 3.53:1 Axle Ratio, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Tag Axle, Double Frame, 8-Bag Air Ride Suspension, 228 in Wheelbase, PTO, 16 ft Long x 4 ft High Steel Body, Electric Roll Tarp Usage: 331,042 Mi Asset located in: Humble, TX
1138	2023 Volvo VNR300 8x4 Tri/A Dump Truck	1142	2017 Freightliner Cascadia 125 8x4 Tri/A
	S/N: 4V4W19EG7PN616815 C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Volvo 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Volvo Corporate Air Air Ride Suspension, 16 ft 2 in Long x 3 ft 8 in High Body, Round Bottom, Electric Roll Tarp, Tailgate Chute Usage: 120,390 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX		Dump Truck S/N: 3AKJGLBG2HSJA3077 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 31957 Engine hrs, Engine Brake, Eaton Fuller FOAM-15810S-EC Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.62:1 Axle Ratio, 52350 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Airliner Air Ride Suspension, 233 in Wheelbase, PTO, 16 ft Long x 4 ft 8 in High Steel Body, Electric Roll Tarp Usage: 912,479 Mi
1139	2022 Volvo VNR 8x4 Tri/A Dump Truck		Asset located in: Humble, TX
1140	S/N: 4V4W19EG0NN285766 C/W: Volvo D13N-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Volvo AT2612F 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 32000 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 224 in Wheelbase, PTO, 18 ft Long x 3 ft High Body, Round Bottom, Electric Roll Tarp, Tailgate Chute Usage: 264,306 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1143	2014 Freightliner Cascadia 125 8x4 Tri/A Dump Truck S/N: 3AKBGEBG7ESFY3961 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM- 15E310B Automated Transmission, Meritor RS- 23-161 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Air Ride Suspension, 243 in Wheelbase, PTO, 18 ft Long x 4 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 351,876 Mi
 1140 2022 Volvo VNR 8x4 Tri/A Dump Truck S/N: 4V4W19EG5NN285634 C/W: Volvo 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Brake, Volvo 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 32000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22 5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 224 in Wheelbase, PTO, 18 ft Long x 3 ft High Body, Round Bottom, Electric Roll Tarp, High-Lift Tailgate, Tailgate Chute Usage: 262,785 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 	S/N: 4V4W19EG5NN285634 C/W: Volvo 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, Requires Diesel Exhaust		Notes: TITLE BRAND REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	1144	2007 Mack CL733 8x4 Tri/A Dump Truck S/N: 1M2AD64CX7M002918 C/W: Cummins ISX 565 6 Cylinder 15 L Diesel 565 hp Engine, 2006 US EPA Label, 29452 Engine hrs, Engine Brake, Mack Maxitorque ES 18-Speed Manual Transmission, 18740 lb Front Axle, 46000 lb Rears, 84740 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Rubber over Walking Beam Suspension, 238 in Wheelbase, Trail King 19 ft 5 in Long x 6 ft 9 in High Aluminium Body, Electric Roll Tarp Usage: 635,736 Mi Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1145	2007 Mack CHN613 8x4 Tri/A Dump Truck S/N: 1M2AJ07Y17N009117 C/W: Mack 6 Cylinder Diesel Engine, 28705 Engine hrs, Mack 18-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 385/65R22.5 Front Tires, 11R24. 5 Rear Tires, Steerable Air Lift Pusher Axle, Camelback Suspension, 224 in Wheelbase, PTO, 16 ft Long x 5 ft High Body, Electric Roll Tarp Usage: 485,725 Mi Notes: LOCATED-IN-FORT-WORTH-TX THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20	11482007 Sterling L9500 8x4 Tri/A Dum S/N: 2FZHAZCV17AY14462 C/W: Mercedes-Benz 6 Cylinder Die Engine, 2006 US EPA Label, Engine Eaton Fuller Manual Transmission, Front Axle, 60000 lb Rears, 72000 lb Ride Cab, Aluminum Front Wheels, 3 5 Front Tires, 11R22.5 Rear Tires, Si Lift Pusher Axle, Spring Suspension Wheelbase, 16 ft 11 in Long x 5 ft 3 Steel Body, Electric Roll Tarp Usage: 449,746 Mi Notes: LOCATED-IN-LIVINGSTON_L SUBJECT TO LOUISIANA SALES TA DEFICIENCIES NOTED - PLEASE SEI INSPECTION REPORT Asset located in: Livingston, LA11502014 Peterbilt 365 6x4 T/A Dump T S/N: 1XPSD79X2ED232393 C/W: Cummins ISX12 6 Cylinder 11 385 hp Engine, 2013 US EPA Label, Diesel Exhaust Fluid, Eaton Fuller 91 Transmission, 13200 lb Front Axle, Rears, 53200 lb GVWR, Air Ride Cab Outer Wheels, 11R22.5, Air Trac Air Suspension, 204 in Wheelbase, PTC x 4 ft 4 in High Steel Body, Electric F Usage: 622,990 Mi Notes: DEFICIENCIES NOTED - PLE/ THE INSPECTION REPORT	C/W: Mercedes-Benz 6 Cylinder Diesel 450 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 60000 lb Rears, 72000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 385/65R22. 5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Spring Suspension, 240 in Wheelbase, 16 ft 11 in Long x 5 ft 3 in High Steel Body, Electric Roll Tarp Usage: 449,746 Mi Notes : LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1146	AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD Asset located in: Lake Worth, TX 2006 Mack CV713 8x4 Tri/A Dump Truck		2014 Peterbilt 365 6x4 T/A Dump Truck S/N: 1XPSD79X2ED232393 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, 14 ft Long
	S/N: 1M2AG11C56M044796 C/W: 6 Cylinder Engine, 11087 Engine hrs, Mack Manual Transmission, 18000 lb Front Axle, 44000 lb Rears, Air Ride Cab, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22. 5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Camelback Spring Suspension, 234 in Wheelbase, PTO, 17 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 237,085 Mi Asset located in: Humble, TX		x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 622,990 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		1151A	2013 Mack CHU613 6x4 T/A Dump Truck S/N: 1M1AN07Y9DM011918 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 5 Engine hrs, Mack Maxitorque
1147	2009 International Prostar 8x4 Tri/A Dump Truck S/N: 2HSCUAPR89C142346 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Outer Wheels, 11R22.5 Front Tires,		13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 248 in Wheelbase, PTO, 15 ft 9 in Long x 4 ft 4 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 134,646 Mi Asset located in : Humble, TX
	Aluminum Outer Wheels, TTR22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 232 in Wheelbase, PTO, 16 ft 5 in Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 836,555 Mi Asset located in : Humble, TX	1151	2018 Mack CXU613 6x4 T/A Dump Truck S/N: 1M1AW02Y7JM089842 C/W: Mack MP7 10.8 L Diesel 425 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16315 Engine hrs, Engine Brake, Mack MDrive Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 186 in Wheelbase, PTO, 15 ft 8 in Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 612,316 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1152	Truck S/N: 3AKJGND66FDGH1837 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 25061 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 44000 lb Rears, Meritor MT-44-14XP Drive Axles, 3.70:1 Axle Ratio, 58320 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 208 in Wheelbase, PTO, 14 ft 8 in Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1156	2016 Freightliner M2 106 4x2 T/A Dump Truck S/N: 3AKBCXCY9GDHS6544 C/W: Cummins 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 8371 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 5.38:1 Axle Ratio, 30000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, PTO, 12 ft Long x 2 ft High Body, Round Bottom, Electric Roll Tarp Usage: 162,263 Mi Asset located in: Humble, TX
		1157	2016 Freightliner M2 106 4x2 T/A Dump Truck S/N: 3AKBCXCY1GDHS6540 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 6410 Engine hrs, Allison 3000 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 5.38:1 Axle Ratio, 30000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, PTO, 12 ft Long x 2 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 132,652 Mi Asset located in: Humble, TX
1153			
Rears, Meritor MT-40-14X Drive Axles, 3.90:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, PTO, 14 ft Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: 286,110 Mi Notes : TITLE BRANDED REBUILT SALVAGE Asset located in : Humble, TX	1159A	2002 Mack 6x2 T/A Dump Truck S/N: 1M2P264Y82M033850 C/W: Mack 6 Cylinder Diesel 300 hp Engine, 2002 US EPA Label, 40164.1 Engine hrs, Mack Maxitorque 7-Speed Manual Transmission, 11R24.5, Spring Suspension, 204 in Wheelbase, PTO, 15 ft Long x 4 ft 3 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 107 777 Mi	
1154	2015 Freightliner M2112 6x4 T/A Dump Truck S/N: 1FUJC5DV1FHGS1137		Usage: 107,777 Mi Asset located in: Humble, TX
	C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM15E310B 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, PTO, 14 ft Long x 4 ft High Steel Body, Electric Roll Tarp Usage: 389,510 Mi	1159	2009 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUJALCK09DAH4306 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel Engine, 2008 US EPA Label, 1316 Engine hrs, Eaton Fuller 9LL Manual Transmission, Air Ride Cab, 11R24.5, Hendrickson Haulmaax Suspension, 190 in Wheelbase, PTO, Crown Beds 14 ft 10 in Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: 363,611 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1160	2000 Mack CX613 6x4 T/A Dump Truck
1155	2012 Freightliner M2112 6x4 T/A Dump Truck S/N: 1FUJC5DV4CHBR7500 C/W: Detroit 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 14414 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, PTO, 14 ft 8 in Long x 4 ft 4 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 427,811 Mi Asset located in: Humble, TX		S/N: 1M1AE05Y5YW003263 C/W: Mack 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 184 in Wheelbase, PTO, Custom Fab Truck Rigging Inc 13 ft 6 in Long x 4 ft 4 in High Steel Body, Manual Roll Tarp Usage: Not Available Notes : THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN SHOWN ON THE ODOMETER Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1161		1166	1997 Mack RD690S 6x4 T/A Dump Truck S/N: 1M2P264Y3VM023442 C/W: Mack EM7 6 Cylinder Diesel 300 hp Engine, 1996 US EPA Label, 24550 Engine hrs, Manual Transmission, 11R24.5, Camelback Spring Suspension, 206 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Pintle Hitch Usage: 616,974 Mi Asset located in : Humble, TX
		1167	2021 Volvo VNR 4x2 S/A Dump Truck S/N: 4V4W19EG2MN285377 C/W: Volvo D13 12.8 L 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid,
1162	2006 International 7600 6x4 T/A Dump Truck S/N: 1HTWYAHT76J239980 C/W: 6 Cylinder Diesel Engine, Engine Brake, Automated Transmission, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, 18 ft Long x 6 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 1,054,079 Km		Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 151 in Wheelbase, PTO, 9 ft 11 in Long x 3 ft 10 in High Steel Body, Manual Roll Tarp Usage: 393,501 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1168	2013 International 4300 4x2 S/A Dump Truck
1164	Asset located in: Humble, TX 2005 International 7400 6x4 T/A Dump Truck S/N: 1HTWHAZT35J045640 C/W: 6 Cylinder Diesel Engine, 14363 Engine hrs, Automated Transmission, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 219 in Wheelbase, PTO, Wet Kit, 14 ft 8 in Long x 4 ft 3 in High Steel Body, Flat Bed, Manual Roll Tarp, Swing Tailgate Usage: 349,518 Mi Asset located in: Humble, TX	-	S/N: 3HAJTSKM1DL196932 C/W: International MaxxForce 7 6.4 L Diesel Engine, 2012 US EPA Label, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 157 in Wheelbase, PTO, America 10 ft Long x 2 ft High Steel Body, Electric Rol Tarp, Pintle Hitch Usage: 121,559 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
1165	1992 Kenworth T800 6x4 T/A Dump Truck S/N: 1XKDDR9X1NS581437 C/W: Detroit Series 60 12.7 L Diesel 400 hp Engine, 1993 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 11R24.5, Spring Suspension, 192 in Wheelbase, PTO, 16 ft Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 59,003 Mi Asset located in : Humble, TX	1169A	2006 Volvo VNM 4x2 S/A Dump Truck S/N: 4V4M19GF86N424815 C/W: Volvo D12D365 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Engine Brake, Meritor M-13G10A-M13 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 2.80:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 156 in Wheelbase, PTO, 10 ft 9 in Long x 4 ft 4 in High Steel Body, Manual
1166A	1990 Mack RD688S 6x4 T/A Dump Truck S/N: 1M2P142Y9LW008357 C/W: Mack E6 11.0 L Diesel 300 hp Engine, 5x2 Manual Transmission, 11R22.5 Front Tires, 11R24.5 Rear Tires, Camelback Spring Suspension, 189 in Wheelbase, PTO, Davis 13 ft Long x 4 ft High Body Usage: 230,841 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Humble, TX		Roll Tarp Usage: 937,295 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1169	2011 International 4300 4x2 S/A Dump Truck S/N: 1HTMMAAMXBH283799 C/W: International 6 Cylinder 7.6 L Diesel 210 hp Engine, 2009 US EPA Label, 7644 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 157 in Wheelbase, PTO, 10 ft 6 in Long x 3 ft 4 in High Steel Body, Round Bottom Usage: 242,999 Mi Asset located in: Humble, TX	1175A	2014 Freightliner M2 112 6x4 Flatbed Truck S/N: 1FVHC5DV0EHFK2124 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 54600 lb GVWR, 11R22.5, Double Frame, Airliner Air Ride Suspension, 274 in Wheelbase, 24 ft x 97 in Bed, Forklift Mount Kit Usage: 169,043 Mi
1170	2001 International 4900 4x2 S/A Dump Truck		Asset located in: Humble, TX
1171	S/N: 1HTSDADN11H397720 C/W: International 6 Cylinder Diesel Engine, Engine Brake, Spicer 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 178 in Wheelbase, Henderson 11 ft Long x 2 ft 3 in High Steel Body, Manual Roll Tarp Usage: 185,418 Mi Asset located in : Humble, TX 1997 Chevrolet C7500 4x2 S/A Dump Truck	1175	2016 Freightliner 114SD 6x4 Flatbed Truck S/N: 1FVHG3DV9GHHA2564 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 12241 Engine hrs, Engine Brake, Eaton Fuller FO-16E308LL Automatic Transmission, 18000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.73:1 Axle Ratio, 58000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 274 in Wheelbase, 25 ft x 102 in Bed, Forklift Kit
	S/N: 1GBL7H1J2VJ100072		Usage: 331,513 Mi
	C/W: Cat 6 Cylinder Diesel Engine, 6-Speed Manual Transmission, 3674 lb Front Axle, 19000 lb Rears, 12292 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Warren 10 ft Long x 3 ft High Steel Body, Pintle Hitch Usage: 18,274 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1176 1177B	Asset located in: Humble, TX 2017 Freightliner M2106 6x4 Flatbed Truck S/N: 3ALHCYCY2HDHZ2124 C/W: Cummins ISL 6 Cylinder Diesel 260 hp Engine, Requires Diesel Exhaust Fluid, 5566 Engine hrs, Allison Automatic Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 lb GVWR, 12R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 274 in Wheelbase, 24 ft x 96 in Bed
1172	014 Peterbilt 337 4x2 Flatbed Dump Truck		Usage: 173,661 Mi
	S/N: 2NP2HJ7X7EM246508 C/W: Paccar PX-9 6 Cylinder Diesel Engine,		Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ;
	2014 US EPA Label, Requires Diesel Exhaust		Asset located in: Humble, TX
1173	Fluid, 14169 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana S21-170 Drive Axles, 4.56: 1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Rayco Spring Suspension, 221 in Wheelbase, 20 ft Long x 8 ft 6 in High Steel Body Usage: 376,035 Mi Asset located in: Humble, TX 2003 International 4300 4x2 Flatbed Dump		S/N: 1FUJBBCG31LH39264 C/W: Detroit Series 60 12.7 L Diesel Eng Meritor M-14610A-M14 Manual Transm 12000 lb Front Axle, 40000 lb Rears, Me 40-145 Drive Axles, 2.79:1 Axle Ratio, 52 GVWR, Air Ride Cab, Aluminum Outer W 11R22.5 Front Tires, 295/75R22.5 Rear Air Ride Suspension, 196 in Wheelbase,
	Truck		Usage: 571,329 Mi
	S/N: 3HTMMAANX3N572469		Asset located in: Humble, TX
C/W: 6 Cylinder Diesel Engine, 13871 Engine hrs, Automatic Transmission, 295/75R22.5, Spring Suspension, 208 in Wheelbase, PTO, 18 ft Long Steel Body, Pintle Hitch Usage: 366,590 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1177A	2012 International 7400 6x4 Flatbed Truck S/N: 1HTWGAZR8CJ625504 C/W: 6 Cylinder Diesel Engine, 7279 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 11R22.5, International IROS Air Ride Suspension, 255 in Wheelbase, 24 ft x 95 in Bed Usage: 85,585 Mi Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1177	2015 Freightliner Cascadia 125 6x4 Flatbed Truck S/N: 3AKJGEBG1FDGP9053 C/W: Cummins ISX 6 Cylinder Ultra Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15644 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, 24 ft x 93 in Bed Usage: 307,264 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1181	2018 Freightliner M2106 4x2 Flatbed Truck S/N: 3ALACXFC2JDJK4404 C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8207 Engine hrs, Eaton Fuller Automated Transmission, 12000 Ib Front Axle, 21000 Ib Rears, 5.56:1 Axle Ratio, 33000 Ib GVWR, 11R22.5, Airliner Air Ride Suspension, 280 in Wheelbase, 25 ft x 100 in Bed Usage: 177,098 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX
1178	2017 Peterbilt 337 4x2 Flatbed Truck S/N: 2NP2HJ7X2HM388074 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 345 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11816.5 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana S21- 170 Drive Axles, 4.78:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Paccar Air Ride Suspension, 196 in Wheelbase, 13 ft 6 in x 100 in Bed, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 471,723 Mi	1182	2017 Freightliner M2 106 4x2 Flatbed Truck S/N: 3ALACWDT0HDHY0501 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 2891.5 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 25 ft x 96 in Bed, Liftgate Usage: 442,418 Mi Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1183	2017 Freightliner M2 106 4x2 Flatbed Truck S/N: 3ALACWDT2HDHY0502 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220
1179	2019 Freightliner M2 106 4x2 Flatbed Truck S/N: 1FVACWFC8KHKS6229 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3188 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 252 in Wheelbase, 24 ft x 98 in Bed Usage: 113,340 Mi	hp Engine, Requires Diesel Exha 13141 Engine hrs, Allison 2200 Transmission, 10000 lb Front A Rears, Detroit DARS19 Drive Ax Ratio, 26000 lb GVWR, Air Ride /75R22.5, Airliner Air Ride Susp Wheelbase, 24 ft x 96 in Bed, Li Usage: 368,761 Mi Asset located in: Humble, TX 1184 2015 Freightliner M2 106 4x2 C Flatbed Truck S/N: 3ALACWDT2FDGR9125 C/W: Cummins 6 Cylinder Diese Requires Diesel Exhaust Fluid, C Automated Transmission, 5.56 33000 lb GVWR, Air Ride Cab, 1 Suspension, 278 in Wheelbase, in Bed Usage: 176,352 Mi Notes: ; SELLER SUPPLIED MA	hp Engine, Requires Diesel Exhaust Fluid, 13141 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DARS19 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Liftgate Usage: 368,761 Mi
	Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX		
1180	2018 Freightliner M2 6x4 Flatbed Truck S/N: 3ALHCYFE5JDJJ9963 C/W: Cummins L9 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 8582 Engine hrs, Allison 3000 Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 5.86:1 Axle Ratio, 54000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 265 in Wheelbase, 28 ft x 102 in Bed Usage: 285,022 Mi Asset located in: Humble, TX		Usage: 176,352 Mi Notes : ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW

Lot #	Details	Lot #	Details
1185	2015 Freightliner M2106 4x2 Crew Cab Flatbed Truck S/N: 3ALACWDT0FDGR9124 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 Ib Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 278 in Wheelbase, 24 ft 5 in x 96 in Bed Usage: 198,899 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION	S/N: 3ALACWDT8FDGM1973 C/W: Cummins ISB 6 Cylinder 6.7 L Die hp Engine, Requires Diesel Exhaust Flu 15220 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 180 Rears, Detroit DA-RS-19.0-2 Drive Axle Axle Ratio, 26000 lb GVWR, 295/75R22	C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 15220 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 101 in Bed Usage: 387,269 Mi
	BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1190	2016 International 4300 4x2 Flatbed Truck S/N: 3HAMMML2GL738568
1186	2015 Freightliner M2106 4x2 Flatbed Truck S/N: 3ALACWDT9FDGR3385 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 240 hp Engine, 6460 Engine hrs, Allison 2500 Automatic Transmission, 10000 Ib Front Axle, 19000 Ib Rears, Detroit DARS19 Drive Axles, 5.56:1 Axle Ratio, 26000 Ib GVWR, 11R22.5, Spring Suspension, 252 in Wheelbase,	 C/W: Cummins B6.7 220 6 Cylinder Diesel 220 hp Engine, 2015 US EPA Requires Diesel Exhaust Fluid, Autor Transmission, 10000 lb Front Axle, 1 Rears, 25999 lb GVWR, 295/75R22.5 Tires, 11R22.5 Rear Tires, Air Ride S 271 in Wheelbase, 26 ft x 102 in Bec Usage: 116,035 Mi Asset located in: Humble, TX 1191 2013 International Terrastar 4x2 Fla S/N: 1HTJSSKK2DH413833 C/W: Navistar V8 Diesel Engine, 419 hrs, Allison Automatic Transmission Aluminum Wheels, 35X12.50R24, Sp 	5
	24 ft x 98 in Bed Usage: 272,705 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW		C/W: Navistar V8 Diesel Engine, 4199 Engine hrs, Allison Automatic Transmission, Aluminum Wheels, 35X12.50R24, Spring
1187	Asset located in: Humble, TX 2015 Freightliner M2 106 4x2 Flatbed Truck	-	Suspension, 159 in Wheelbase, 11 ft 4 in x 99 in Bed
1107	S/N: 3ALACWDT1FDGS2620 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel		Usage: 116,316 Mi Asset located in: Humble, TX
	220 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 12669 Engine hrs, Allison 2100 Automatic Transmission, 8000 lb Front Axle, 18000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft 6 in x 96 in Bed Usage: 349,897 Mi Asset located in : Humble, TX	S/N: 1HTMMAAL57H52846 C/W: International 6 Cylinde hp Engine, 2006 US EPA Lal hrs, Eaton Fuller Manual Tra Ib Front Axle, 17500 Ib Rear 11R22.5, Spring Suspensior	
1188	2015 Freightliner M2 106 4x2 Flatbed Truck	1104	Asset located in: Humble, TX
	S/N: 3ALACWDT8FDGB2159 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 12402 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 24 ft x 96 in Bed Usage: 383,049 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE	1194	2006 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAN06H196721 C/W: International DT466 6 Cylinder 7.6 L Ultra Low Sulfur Diesel 245 hp Engine, 2005 US EPA Label, Eaton Fuller 6-Speed Manual Transmission, 295/75R22.5, Spring Suspension, 189 in Wheelbase, 14 ft 3 in x 96 in Bed Usage: 28,351 Mi Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	1195	2002 International 4700 4x2 Flatbed Truck S/N: 1HTSCABM12H547193 C/W: International C195CF 6 Cylinder 7.3 L Diesel 195 hp Engine, 2002 US EPA Label, Automatic Transmission, 11R22.5, Spring Suspension, 152 in Wheelbase, 12 ft x 96 in Bed Usage: 92,682 Mi

Lot #	Details	Lot #	Details
Lot # 1196	Details2001 International 4700 Flatbed TruckS/N: 1HTSCAAN01H330095C/W: International DT466 6 Cylinder 7.6 LDiesel 215 hp Engine, 2000 US EPA Label, 7-Speed Manual Transmission, 12000 lb FrontAxle, 21000 lb Rears, 33000 lb GVWR, 11R22.5,Spring Suspension, 206 in Wheelbase, PTO,Flatbed, 16 ft 3 in x 96 in BedUsage: 93,792 MiNotes: DEFICIENCIES NOTED - PLEASE SEETHE INSPECTION REPORT; DEFICIENCIESNOTED - PLEASE SEETHE INSPECTION REPORT; DEFICIENCIESNOTED - PLEASE SEE THE INSPECTIONREPORTAsset located in: Humble, TX	Lot # 1202 1203	2019 Ram 5500 4x4 Flatbed Truck S/N: 3C7WRNBL4KG583128 C/W: immune B6.7 6 Cylinder 6.7 L Diesel 360 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6020 Engine hrs, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 170 in Wheelbase, 11 ft 9 in x 96 in Bed Usage: 189,019 Mi Asset located in: Humble, TX 2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck
1197	2006 Hino 268 4x2 Flatbed Truck S/N: 5PVNE8JT462S12363 C/W: Hino 6 Cylinder Diesel Engine, Automatic Transmission, 11R22.5, Spring Suspension, 245 in Wheelbase, 23 ft 8 in x 94 in Bed Usage: 672,876 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1FD0W5HTXKEG80257 C/W: Ford 6.7 L Ultra Low Sulfur Diesel 330 h Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12805 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 204 in Wheelbase, 11 ft x 94 in Bed, Better built 100 gal Fuel Tank /w Pump Usage: 106,726 Mi Notes : LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE
1198	2010 Ford F-750 XLT 4x2 Crew Cab Flatbed Truck		INSPECTION REPORT Asset located in: Midland, TX
1199	S/N: 3FRNW7FC7AV266349 C/W: CUMMINS 6 Cylinder Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 266 in Wheelbase, 20 ft x 97 in Bed Usage: 269,595 Mi Asset located in : Humble, TX 2019 Ford F-650 4x2 Crew Cab Flatbed Truck S/N: 1FDPW6DX1KDF02529 C/W: 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 29000 lb GVWR, 11R22.5, Spring Suspension, 231 in Wheelbase, 13 ft 9 in x 99 in Bed Usage: 24,998 Mi	1204	2018 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HTXJEC67057 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12420 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, steel, 255/70R19.5, Spring Suspension, 203 in Wheelbase, 11 ft 0 in x 96 in Bed, Fuel Tank Usage: 109,018 Mi Notes: LOCATED-IN-MIDLAND-TX,. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX 2016 Ford F-550 XL 4x4 Extended Cab Flatbed
1200	Asset located in: Humble, TX 2008 Ford F-650 XL 4x2 Crew Cab Flatbed Truck S/N: 3FRNW65M68V640657 Usage: 52,000 Mi Asset located in: Humble, TX		Truck S/N: 1FD0X5HT8GEC75339 C/W: 6.7 L Ultra Low Sulfur Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8438 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft x 91 in
1201	2019 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL8KG700283 C/W: CUMMINS 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 196 in Wheelbase, 11 ft 4 in x 97 in Bed, 100 gallons Fuel Tank Usage: 69,808 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Bed, Fuel Tank Usage: 191,492 Mi Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX

Lot #	Details	Lot #	Details
1206	2016 Ford F-550 4x4 Flatbed Truck S/N: 1FDUF5HY7GEB63180 C/W: Ford V10 6.8 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 170 in Wheelbase, 12 ft x 96 in Bed, Receiver Usage: 140,727 Mi Notes: LOCATED-IN-FORT-WORTH-TX EQUIPMENT FROM UNITED RENTALS Asset located in: Lake Worth, TX	1210	 2012 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT7CEC76740 C/W: V8 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 7040 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 178 in Wheelbase Usage: 135,734 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1207	2014 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL7EG274574		THE INSPECTION REPORT Asset located in: Humble, TX
1208	C/W: Cummins 6 Cylinder 6.7 L Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft x 96 in Bed Usage: 87,012 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Ram 5500 4x4 Crew Cab Flatbed Truck	1212	2015 Ford F-450 XLT 4x4 Crew Cab Flatbed Truck S/N: 1FD0W4HT5FEC81191 C/W: Ford V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6600 lb Front Axle, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 6 in x 86 in Bed Usage: 176,595 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 3C7WRNFL7EG202855		Asset located in: Humble, TX
	C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 196 in Wheelbase, 11 ft 10 in x 94 in Bed, Fuel Tank /w Pump Usage: 122,787 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1213	2015 Ram 4500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRLEL4FG559370 C/W: Cummins V8 6.7 L Ultra Low Sulfur Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 Ib Front Axle, 12000 Ib Rears, 16500 Ib GVWR, 245/70R19.5, Spring Suspension, 176 in Wheelbase, 9 ft 4 in x 90 in Bed Usage: 290,721 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1214	2011 Ford F-450 XL 4x4 Extended Cab Flatbed
1209	2012 Dodge Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WDMEL2CG266695 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 20500 lb GVWR, 225 /70R19.5, Spring Suspension, 173 in Wheelbase, 9 ft 5 in x 96 in Bed Usage: 302,353 Mi Asset located in: Humble, TX		Truck S/N: 1FD0X4HTXBEC16943 C/W: V8 6.7 L Ultra Low Sulfur Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 Ib Front Axle, 12000 Ib Rears, 16500 Ib GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 12 ft x 92 in Bed Usage: 262,361 Mi Asset located in: Humble, TX 2019 Ford F-350 4x4 Crew Cab Flatbed Truck
1210A	2011 IMT 5-33 Knuckle Boom on 2011 Ford F-	1215	S/N: 1FD8W3HT5KEE24230
	550 4x4 Flatbed Truck with Crane S/N: 1FDUF5HT6BEC54454 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 Ib Front Axle, 14706 Ib Rears, 19500 Ib GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, Front Mounted, 45 ft 2 Section Boom, Out and Down Outriggers, Liftgate, Receiver Usage: 206,876 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75/17, Spring Suspension, 180 in Wheelbase, 9 ft x 89 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 134,504 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1216D	2015 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HTXFED08897 C/W: V8 Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 12983 Engine hrs, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 179 in Wheelbase, 10 ft x 96 in Bed Usage: 380,270 Mi	1217A	2007 Ford F-350 XL Flatbed Truck S/N: 1FDWF37P37EB40226 C/W: V8 6.0 L Diesel Engine, 2008 US EPA Label, 7893 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 245/75R17, Spring Suspension, 165 in Wheelbase, 12 ft x 96 in Bed Usage: 221,797 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1217	2011 Ford F-350 XL 4x4 Crew Cab Flatbed
1216C	2018 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY0JF281165 C/W: GM Duramax V8 6.6 L Diesel Engine, 2018 US EPA Label, Exhaust Brake, Allison Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, Steel, 245 /75R17, Spring Suspension, 172 in Wheelbase, 9 ft x 93 in Bed, Fuel Tank /w Pump Usage: 162,533 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		Truck S/N: 1FD8W3H66BED06441 C/W: Ford V8 6.2 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 9750 lb Rears, 13300 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase Usage: 178,631 Mi Notes: TITLE BRAND NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	THE INSPECTION REPORT	1218	2017 Ram 5500 4x2 Crew Cab Flatbed Truck
1216B	Asset located in: Humble, TX 2017 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT9HEE36079 C/W: Ford 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 5600 Ib Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft x 94 in Bed, Fuel Tank /w Pump Usage: 181,755 Mi	1219	S/N: 3C7WRMELXHG520579 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5715 Engine hrs, Automatic Transmission, 7250 lb Front Axle, 13509 lb Rears, 19000 lb GVWR, 225/70R19.5, Spring Suspension, 174 in Wheelbase, 9 ft x 98 in Bed, Fuel Tank /w Pump Usage: 82,336 Mi Asset located in: Humble, TX 2004 GMC C5500 4x2 Flatbed Truck
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	_	S/N: 1GDE5C1234F514996 C/W: V8 Gasoline Engine, Automatic
1216A	2018 Ford F-350 XLT 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3HT2JEC43102 C/W: V8 6.7 L Diesel Engine, Requires Diesel		Rears, 19500 lb GVWR, 225/70R19 Suspension, 148 in Wheelbase, 11 in Bed, 100 Gal Fuel Tank /w Pump Usage: 225,977 Mi
1216	Exhaust Fluid, 8314 Engine hrs, Exhaust Brake, Automatic Transmission, 5600 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 171 in Wheelbase, 9 ft 6 in x 86 in Bed Usage: 268,666 Mi Asset located in: Humble, TX 2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H62KEF60857 C/W: V8 Gasoline Engine, Automatic	1220	2007 Ford F-450 XLT 4x2 Flatbed Truck S/N: 1FDXF46P47EA38543 C/W: V8 Diesel Engine, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Air Ride Suspension, 188 in Wheelbase, 13 ft x 89 in Bed Usage: 134,587 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Transmission, 14000 lb GVWR, 245/75R17, Spring Suspension, 180 in Wheelbase, 9 ft 5 in x 102 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: 154,310 Mi Asset located in : Humble, TX	1221A	2014 Ram 3500 4x2 Crew Cab Flatbed Truck S/N: 3C63RPGL5EG165578 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Exhaust Brake, Automatic Transmission, 5500 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, Steel, 235/80R17, Spring Suspension, 169 in Wheelbase, 9 ft x 94 in Bed Usage: 312,654 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1221	2017 Ram 3500 4x2 Crew Cab Flatbed Truck S/N: 3C7WRSCL9HG677981 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 3491 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 170 in Wheelbase, 10 ft 2 in x 96 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 136,451 Mi Asset located in: Humble, TX	1227	2012 Chevrolet Silverado 2500 HD 4x2 Crew Cab Flatbed Truck S/N: 1GC1CVCG5CF238915 C/W: V8 Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9500 lb GVWR, 245/75R17, Spring Suspension, 168 in Wheelbase, 8 ft 6 in x 94 in Bed Usage: 215,973 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1223	2013 Chevrolet Silverado 3500HD 4x2 Crew Cab Flatbed Truck S/N: 1GB4CZCGXDF102113 C/W: GM 6.0 L Gasoline Engine, Automatic Transmission, 235/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 4 in x 90 in Bed, Receiver Usage: 335,684 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1228	2008 Isuzu NPR 4x2 COE Flatbed Truck S/N: 4KLB4B1U68J800737 C/W: Chevrolet Vortec V8 6.0 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 12000 lb Rears, 18000 lb GVWR, 235/85/16, Spring Suspension, 134 in Wheelbase, 15 ft x 91 in Bed, Liftgate Usage: 238,983 Mi Asset located in: Humble, TX
1224	2012 Chevrolet Silverado 3500HD 4x2 Flatbed Truck S/N: 1GB3CZCL4CF165649 C/W: Chevy Duramax V8 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automated Transmission, 5600 lb Front Axle, 7050 lb Rears, 10800.0 lb GVWR, 235/80R17, Spring Suspension, 163 in Wheelbase, 11 ft 6 in x 93 in Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1231	2012 on 2013 Peterbilt 348 6x4 Vacuum Excavator Truck S/N: 2NP3LN9XXDM182583 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 19462 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Transmission, 14600 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 54600 lb GVWR, 11R22.5, Air Trac Air Ride Suspension, 222 in Wheelbase, PTO, Steel 24900 gal Debris Tank, Manual Tailgate Locks, Hydraulic Driven Pump Usage: 38,879 Mi Asset located in: Humble, TX
1225	2011 Ram 3500 4x2 Crew Cab Flatbed Truck S/N: 3D73M4CL2BG624594 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2011 US EPA Label, Automatic Transmission, 235/80R17, Spring Suspension, 170 in Wheelbase, 8 ft 10 in x 97 in Bed, Pintle Hitch Usage: 89,494 Mi Asset located in: Humble, TX 2008 Ford F-350 XL 4x2 Crew Cab Flatbed Truck	1233	2006 Guzzler on 2007 Sterling L9500 6x4 Vacuum Excavator Truck S/N: 2FZHAZDE47AY05611 C/W: Cat 6 Cylinder Diesel Engine, 15642 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 242 in Wheelbase, PTO, Steel Debris Tank, Fresh Water Tank, Hydraulic Lift Tailgate, PTO Driven Pump, Boiler
	S/N: 1FDWW36Y88EA76552 C/W: V10 6.8 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 245 /75R17, Spring Suspension, 178 in Wheelbase, 9 ft x 91 in Bed Usage: 174,830 Mi Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1235	Usage: 31,774 Mi Asset located in: Humble, TX Gap-Vac on 2002 Volvo VHD 6x4 Vacuum Excavator Truck S/N: 4V5KC9UF92N321981 C/W: Cummins ISM 10.8 L Diesel 325 hp Engine, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring over Walking Beam Suspension, 254 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, PTO Driven Pump, 64000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1237	Vac-Con on 1999 International 2554 4x2 Vacuum Excavator Truck S/N: 1HTGBADR7XH604442 C/W: 6 Cylinder 8.7 L Diesel 250 hp Engine, US EPA Label, 12756 Engine hrs, Allison Automated Transmission, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 235 in Wheelbase, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Manual Tailgate Locks, 11 ft Boom, 8 in Suction Hose, Bean Pump w/ Engine, Blower Usage: 101,605 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ; RITCHIE-BROS-	1242	2007 Prevac on 2007 Sterling Acterra 6x4 Vacuum Tanker Truck S/N: 2FZHCHDC97AX34568 C/W: Cat C7 7.2 L 210 hp Engine, 3517 Engine hrs, Eaton Fuller 18-Speed Manual Transmission, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Rubber over Walking Beam Suspension, 219 in Wheelbase, PTO, Steel 3000 gal Debris Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, PTO Driven Pump Usage: 29,156 Mi Asset located in: Humble, TX 2017 Ram 5500 4x4 Vacuum Tanker Truck	
	ENERGY DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3C7WRNCL3HG776832 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, 6385 Engine hrs, Engine Broke Automatic Transmission 7250 lb Front	
1239	Super Products on 2015 Freightliner 114SD 6x4 Vacuum Tanker Truck S/N: 1FVHG3CY1FHGK3761 C/W: Cummins 8.9 L Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 4031 Engine hrs, Allison Automatic Transmission,	1244	Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 245 /70R19.5, Spring Suspension, 194 in Wheelbase, PTO, Steel Debris Tank, Rear Hose Reel, Hydraulic Driven Pump, 19500 lb GVWR Usage: 139,118 Mi Asset located in : Humble, TX	
	20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, PTO, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Telescopic Boom, 6 in Suction Hose, PTO Driven Pump Usage: 19,316 Mi		2008 Junjin JXZ33416HP 33 m on 2007 Mack MR688S 6x4 Concrete Pump Truck S/N: 1M2K197C17M039785 C/W: Mack 6 Cylinder Diesel Engine, 14858 Engine hrs, Engine Brake, Mack T309 9LL Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 66000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Camelback	
1240	Asset located in: Humble, TX 2007 Mack CHN613 6x4 Vacuum Tanker Truck S/N: 1M1AJ06Y97N008500 C/W: Mack 6 Cylinder Diesel 427 hp Engine, 10492 Engine hrs, Mack 10-Speed Manual		Suspension, Pump Hours Controls, Bo Usage: 426,6	Suspension, 212 in Wheelbase, PTO, 8436 Pump Hours, Radio and Cable Remote Controls, Boom Light, Hopper Vibrator Usage: 426,636 Mi Asset located in: Humble, TX
	Transmission, Air Ride Cab, Aluminum Front Wheels, 11R24.5 Front Tires, 11R24.5 Rear Tires, Camelback Spring over Walking Beam Suspension, 260 in Wheelbase, Steel Debris Tank, Gardner Denver PTO Driven Pump Usage: 120,284 Mi Notes: TITLE BRAND REBUILT SALVAGE Asset located in: Humble, TX		Alliance on 2006 Mack 600 6x4 Concrete Pump Truck S/N: 1M2K197C36M029807 C/W: Mack E7 11.9 L Diesel Engine, 2006 US EPA Label, 18624.1 Engine hrs, Eaton Fuller 8- Speed Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires,	
1241	2007 Freightliner M2 106 6x4 Vacuum Tanker Truck S/N: 1FVHCYDC67DX53455 C/W: Cat C7 6 Cylinder 7.2 L 350 hp Engine, 2006 US EPA Label, Eaton Fuller RT-8908LL 8LL Manual Transmission, 16540 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 4.11:1 Axle Ratio, 56540 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 204 in Wheelbase, Steel 3000 gal Debris Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Summit Hydraulic Driven Pump Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		11R22.5 Rear Tires, Camelback Spring Suspension, 225 in Wheelbase, 268 Pump Hours, Radio Remote Controls, Hopper Vibrator Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1246	2022 Peterbilt 348 10x4 Volumetric Mixer Truck S/N: 2NP3LJ0X4NM792888 C/W: Paccar PX-9 6 Cylinder Ultra Low Sulfur Diesel 370 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 2456 Engine hrs, Allison Automatic Transmission, 20000 lb	1250	2014 Peterbilt 365 6x4 Mixer Truck S/N: 1NPSL70X4ED222376 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8224.6 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb
	Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Steerable Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 278 in Wheelbase, Strong Mixer		Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24. 5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 225 in Wheelbase, PTO, Con-Tech 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 177,773 Mi
	Unit Usage: 39,742 Mi Asset located in : Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1247	2022 Peterbilt 348 10x4 Volumetric Mixer Truck	1051	
,	S/N: 2NP3LJ0X2NM792887 C/W: Paccar PX-9 8.9 L Engine, Requires Diesel Exhaust Fluid, 2456 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /45R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 276 in Wheelbase, PTO Usage: 42,707 Mi Asset located in : Humble, TX	1251	2015 Western Star 4700 6x4 Mixer Truck S/N: 5KKHAXDV8FLGR9577 C/W: Detroit DD13 6 Cylinder Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18740 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Walking Beam Suspension, 225 in Wheelbase, PTO, Con-Tech 8.4 m3 Mixer Unit, 3 Removable Chutes Usage: 195,716 Mi
1248	2022 Peterbilt 348 10x4 Volumetric Mixer Truck	1	Asset located in: Humble, TX
	S/N: 2NP3LJ0X6NM792889 C/W: Paccar PX-9 6 Cylinder Ultra Low Sulfur Diesel 370 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 2460 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 278 in Wheelbase, Strong Mixer Unit Usage: 43,038 Mi Asset located in: Humble, TX	1252A	2012 Kenworth W900 6x4 Mixer Truck S/N: 1NKWX7EX8CJ326100 C/W: Cat ISX11.9 350V 6 Cylinder 11.9 L Diesel 350 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.78:1 Axle Ratio, 92000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Tag Axle, Trailing Tag Axle, Rubber over Walking Beam Suspension, 247 in Wheelbase, PTO, Con-Tech Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: Not Available
1249	2021 Kenworth T880 6x4 Mixer Truck S/N: 1NKZLK0X8MJ455930 C/W: Paccar 6 Cylinder Diesel Engine, Requires		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
	Diesel Exhaust Fluid, 4713 Engine hrs, Engine Brake, Eaton Fuller TO14909ALL 8LL Manual Transmission, 22000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 68000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 231 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 66,897 Mi Asset located in : Humble, TX	1252	2015 Western Star 4700 6x4 Mixer Truck S/N: 5KKHAXDV6FLGR9576 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14870 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 22000 Ib Front Axle, 46000 Ib Rears, Meritor RT-46- 160P Drive Axles, 4.89:1 Axle Ratio, 68000 Ib GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 222 in Wheelbase, PTO, Con- Tech 11 cyd Mixer Unit Usage: 158,980 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1253	2008 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C28M002196 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 335 hp Engine, 2007 US EPA Label, 6362 Engine hrs, Mack Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Camelback Suspension, 218 in Wheelbase, PTO, CBMW 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 442,601 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2006 Mack CV500 6x4 Mixer Truck	1257	2001 Freightliner FLD 120SD 6x4 Mixer Truck S/N: 1FVHALA8X1PJ93521 C/W: Cummins ISM 6 Cylinder Diesel 330 hp Engine, 2001 US EPA Label, Engine Brake, Eaton Fuller 9LL Manual Transmission, 20000 Ib Front Axle, 46000 Ib Rears, Meritor RT-46- 160 Drive Axles, 5.33:1 Axle Ratio, 66000 Ib GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 252 in Wheelbase, PTO, McNeilus 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 216,783 Mi Asset located in: Humble, TX
	S/N: 1M2AG11C06M046875 C/W: Mack 6 Cylinder Diesel Engine, 2005 US EPA Label, Mack Maxitorque T310 10-Speed Manual Transmission, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Camelback Spring Suspension, 228 in Wheelbase, Continental Mfg Co 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1258	2002 International 5600i 6x4 Mixer Truck S/N: 1HTXHAHT42J045938 C/W: Cummins ISM 6 Cylinder Diesel Engine, Automatic Transmission, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Chalmers Suspension, 212 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 2 Removable Chutes, Remote Control w/Cord Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1255	2000 Kenworth T800 6x4 Mixer Truck S/N: 1NKDL00X0YS852269 C/W: Cummins ISM 6 Cylinder 10.8 L Diesel 335 hp Engine, 1999 US EPA Label, 5136 Engine hrs, Eaton Fuller RTIO-14909MLL 9- Speed Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 5.43:1 Axle Ratio, 66000 lb GVWR, Aluminum Front Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber Suspension, 222	1259	2010 Mack Granite 6x2 Roll-Off Truck S/N: 1M2AX04CXAM007631 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 370 hp Engine, 13709 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 315/80R22.5, Spring Suspension, 269 in Wheelbase, PTO, 23 ft Hoist, Winch Usage: 277,880 Mi Asset located in: Humble, TX
1256	in Wheelbase, PTO, 10.5 cyd Mixer Unit, 2 Removable Chutes, Remote Control w/Cord Usage: 86,978 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2000 Kenworth T800 6x4 Mixer Truck	1260	2008 Kenworth T800 6x4 Roll-Off Truck S/N: 1NKDLU0X78J214825 C/W: Cat C13 6 Cylinder 12.5 L Diesel 470 hp Engine, 2007 US EPA Label, 20830 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 18000 lb Front Axle, 46000 lb Rears, Spicer D46-170H Drive Axles, 4.30:1
1230	S/N: 1NKDL00X3YJ857987 C/W: Cummins 6 Cylinder Diesel Engine, Eaton Fuller 8LL Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Rubber over Walking Beam Suspension, 224 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 75,071 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		Axle Ratio, 64000 lb GVWR, Air Ride Cab, Steel, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring over Walking Beam Suspension, 261 in Wheelbase, PTO, Galbreath U5-0R-174 Roll-Off Body, 23 ft Hoist Usage: Not Available Notes : THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN SHOWN ON THE ODOMETER DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1261	1995 Mack RD690S 6x4 Roll-Off Truck	1265	2021 Peterbilt 337 4x2 Rollback Truck
	S/N: 1M2P264C7SM017840 C/W: Mack EM7 6 Cylinder Diesel 300 hp Engine, 1995 US EPA Label, Manual Transmission, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 270 in Wheelbase, PTO, 1993 Galbreath U5-0R-174 Roll-Off Body, 23 ft Hoist Usage: 323,331 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 2NP2HM6X1MM743944 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000.0 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 97,157 Mi Notes : LOCATED-IN-FORT-WORTH-TX
1262	2022 Peterbilt 337 4x2 Rollback Truck		Asset located in: Lake Worth, TX
1262	S/N: 2NP2HM6X6NM762006 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 3608 Engine hrs, Engine Brake, Allison 2200 Automatic Transmission, 10000 Ib Front Axle, 20000 Ib Rears, 26000 Ib GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SR6T-W-LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 Ib Winch, Hydraulic Wheel Lift Usage: 85,024 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2022 Peterbilt 337 4x2 Rollback Truck	1266A	2017 Peterbilt 348 6x4 Flatbed Truck S/N: 2NP3LJ0X1HM416167 C/W: Paccar ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14157 Engine hrs, Allison 3000 Automatic Transmission, 20000 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 60000 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 256 in Wheelbase, PTO, 26 ft 10 in x 102 in Bed, Dovetail, Hydraulic Ramps Usage: 187,181 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 2NP2HM6X0NM762003 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000.0 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 58,166 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1266	2021 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X1MM762705 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 107,303 Mi Notes: LOCATED-IN-FORT-WORTH-TX
1264	2021 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X1MM721863 C/W: Paccar PX-7 6 Cylinder 6.7 L 260 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRRD6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 96,938 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	1267	Asset located in: Lake Worth, TX 2017 International 7400 6x4 Rollback Truck S/N: 3HAWGSTR7HL577727 C/W: Navistar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 254 in Wheelbase, Winch Usage: 202,328 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

 2620 Parm 5500 SLT 444 Rollback Truck SN: 3CVWRD13, 3163564 2747 2017 Aftec L42A 42 ft on 2018 Freightliner M2 106 4/2 Bucket Truck SN: 3LLCWFC11D):08098 2748 Dollbacket Truck SN: 3LLCWFC11D):08098 2749 Dollbacket Truck SN: 3LLCWFC11D):08098 2740 Dollb Front Akle, 1260 Dis Gears, 1960 Dis GWR, Aluminum Wheels, 225/7019.5, Spring Suspension, 205 2750 Store Statistics, 12000 Dis GWR, Aluminum Wheels, 225/7019.5, Spring Suspension, 205 270 2019 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: JLESWT60K7304175 270 19 Juzu NRR 4/2 COE Rollback Truck SN: HTMMMW14474566 270 19 Juzu NRR 4/2 COE Rollback Truck SN: HTMMMW14474566 270 19 Juzu NRR 4/2 COE Rollback Truck SN: HTMMMW14474566 270 19 Juzu NRR 4/2 COE Rollback Truck SN: HTMMMW14474566 270 10 JL Gazagut SR: Alumatic Transmission, 1300 Ib Front Akle, 2000 Ib Rese, 3300 Ib GWR, 11822, SA if Asset Front Suspension, 73 Ib Front Akle, 2000 Ib Rese, 537.3 Avie Ratio, SN: HTMMMW174H161 528 270 Altee DC47 TR on 2018 Freightliner M2 400 4/2 Bucket Truck SN: HTMMMW174H161 528 2716 Altee CA7 TR on 2018 Freightliner M2 400 4/2 Bucket Truck SN: HTMMMW174H14116 JLB Automatic Transmission, 1300 Ib Front Akle, 2000 Ib Rese, 3300 Ib GWR, 11822, SA if Asset Front Suspension, 130 Ib Front Akle, 2000 Ib Rese, 3300 Ib GWR, 11822, SA if Asset Front Suspension, 130 Ib Front Akle, 2000 Ib Rese, 3300 Ib GWR, 11822, SA if Asset Front Suspension, 130 Ib Front Akle, 2000 Ib Rese, 3300 Ib GWR, 11822, SA if Asset Front Suspension, 130 Ib Front Akle, 2000 Ib Rese, 3300 Ib GWR,	Lot #	Details	Lot #	Details
 1270 2019 Isuzu NRK 4X2 CDE Kolibačk Truck S/N: JALESW 160K 3064175 Sylte Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9916 Engine hrs, Automatic Transmission, 727 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225 (70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6i n x 96 in Bed, Aluminum Frame, 18000 lb Winch Usage: 196,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 2018 Altec DC47 TR on 2018 Freightliner M2 106 4x2 Digger Derrick Truck S/N: 11FVACKFG.JH.UI6406 C/W: Cummins G Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9415 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, 557: 1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 35 Ti Axle Ratio, Auxiliary Hydraulics, Turret Mounted, 35 ft Reach, Insulated Upper Born, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Torret Mounted, 710 Chease Rear Outriggers, Hydraulic More Reel Usage: 58,799 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Attec DC47TR on 2018 Freightliner M2 105 age: 58,799 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Atte DC47TR on 2018 Freightliner M2 106 4x2 Digger Derick Truck S/N: 1FVACKFCO.HJU4676 C/W: Cummins 67.6 Cylinder 6.7 L 250 hp Engine, Requires Diesel Exhaust Fluid, Positive Air Shutoff, 6714 Engine hrs, Allison 3500 Automatic Transmission, 17220 lb Front Akle, 2000 lb GWR, 11R22, 5, 57: 1 Akle Ratio, 3000 lb GWWR, 11R22, 5, 57: 1 Akle Ratio, 3000 lb GWR, 11R22, 5, 57: 1 A		S/N: 3C7WRNDL3LG136546 C/W: Cummins 6.7 L Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 205 in Wheelbase, Danco 12SR20 Rollback Body, 20 ft x 95 in Bed, Ramsey 8000 lb Winch, Hydraulic Wheel Lift Usage: 56,163 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1274	106 4x2 Bucket Truck S/N: 3ALACWFC1JDJG8898 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13258 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 5.57:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 160 in Wheelbase, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulated Boom, Utility Body, 14 ft x 96 in Bed, Pintle Hitch Usage: 342,197 Mi
 106 4x2 Digger Derrick Truck S/N: 1FVACXFC3JHJU6406 C/W: Curmins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9415 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, 5.57: 1 Axle Ratio, 33000 lb GWR, 11R22.5, Spring Suspension, 1900 in Wheelbase, PTO, 351 fShaeve Height, 23790 lb Capacity, Rear Mounted, 35 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Turret Mounted Winch, ALTEC 15 ft 4 in Body, A-Outriggers, Rear Outriggers, Rey Mounted, Too Born, Aske, 2000 lb Rears, 33000 lb GWR, 11R22.5, Air Assist Front Suspension, 13000 lb Front Axle, 2000 lb Rears, 33000 lb GWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 1993 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Material Handling, Jib, A- Outriggers, Rear Outriggers, Rear, 21000 lb Rears, 33000 lb GWR, 11R22.5, Spring Suspension, PTO, 47 ft Sheave Height, 23790 lb Capacity, Rear Mounted, 47 ft Reach, Auxiliary Hydraulics, Boom Tip Mounted Winch, Altec 15 ft Body, A-Outriggers, Rear Outriggers, Rear Outrigger		S/N: JALE5W160K7304175 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Ultra Low Sulfur Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5916 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6 in x 96 in Bed, Aluminum Frame, 18000 lb Winch Usage: 196,476 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1275	Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN2HH474566 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10448 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Material Handling Jib, A- Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch
 Digger Derrick Truck S/N: 1FVACXFC0JHJU4676 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, Requires Diesel Exhaust Fluid, Positive Air Shutoff, 6714 Engine hrs, Allison 3500 Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, Meritor MS21 Drive Axles, 5.57: 1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, PTO, 47 ft Sheave Height, 23790 lb Capacity, Rear Mounted, 47 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Boom Tip Mounted Winch, Altec 15 ft Body, A-Outriggers, Rear Outriggers, Hydraulic Hose Reel Usage: 95,262 Mi Asset located in: Humble, TX 		106 4x2 Digger Derrick Truck S/N: 1FVACXFC3JHJU6406 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9415 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 35 ft Sheave Height, 23790 lb Capacity, Rear Mounted, 35 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Turret Mounted Winch, ALTEC 15 ft 4 in Body, A-Outriggers, Rear Outriggers, Hydraulic Hose Reel Usage: 58,799 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1276	Asset located in: Humble, TX 2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH161528 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11915 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Material Handling Jib, A- Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 126,409 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	1273	Digger Derrick Truck S/N: 1FVACXFC0JHJU4676 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, Requires Diesel Exhaust Fluid, Positive Air Shutoff, 6714 Engine hrs, Allison 3500 Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, Meritor MS21 Drive Axles, 5.57: 1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, PTO, 47 ft Sheave Height, 23790 lb Capacity, Rear Mounted, 47 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Boom Tip Mounted Winch, Altec 15 ft Body, A-Outriggers, Rear Outriggers, Hydraulic Hose Reel Usage: 95,262 Mi	1277	Asset located in: Humble, TX Altec on 2017 International 4300 SBA 4x2 Bucket Truck S/N: 1HTMMMMN8HH452524 C/W: Cummins 6 Cylinder 6.7 L Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 9695 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, Rear Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 92 in Bed Usage: 83,494 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
				Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1278	Altec on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN5HH161530 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8064 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, Rear Mounted, Insulated	1282	2013 Terex Hi-Ranger 5TC-55 55 ft on 2014 International 4300 4x2 Bucket Truck S/N: 1HTMMAAN4EH490900 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel 260 hp Engine, 2012 US EPA Label, 7225 Engine hrs, Manual Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 169 in Wheelbase, PTO, 500 lb
	One-Person Articulated Boom, Utility Body, A- Outriggers, Rear Outriggers, 16 ft 2 in x 94 in Bed, Pintle Hitch Usage: 68,230 Mi Asset located in : Humble, TX		Capacity, Center Mounted, Articulating- Telescopic Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, 15 ft x 92 in Bed Usage: 49,143 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE
1279	2016 Altec AA55 56 ft on 2017 International	-	THE INSPECTION REPORT Asset located in: Humble, TX
	4300 4x2 Bucket Truck S/N: 1HTMMMN7HH474563 C/W: Cummins ISB 6 Cylinder 6.7 cid Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9219 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 196 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 97,165 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	12832013 Altec L37M 37 ft2044x2 Bucket Truck2055/N: 3FRWF6FCXDV76219C/W: Cummins 6 Cylind300 lbRequires Diesel Exhaus200 lbTransmission, 10000 lb200 nsion,Rears, 25999 lb GVWR,200 scienceSuspension, 156 in Who201 constructCapacity, Center Mount201 constructArticulated Boom, Utilit201 constructHandling Jib, A-Outrigg201 constructBed, Pintle Hitch201 constructUsage: 333,245 Mi	2013 Altec L37M 37 ft on 2013 Ford F-650 XL 4x2 Bucket Truck S/N: 3FRWF6FCXDV763172 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 156 in Wheelbase, PTO, 350 lb Capacity, Center Mounted, One-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, 13 ft 8 in x 96 in Bed, Pintle Hitch
	Asset located in: Humble, TX	1284	Altec AT37G 37 ft on 2020 Ford F-550 XL 4x2
1280	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMN5HH452528 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10216 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated One-Person		Bucket Truck S/N: 1FDUF5GT8LEC32538 C/W: V8 6.7 L Ultra Low Sulfur Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 145 in Wheelbase, PTO, 350 lb Capacity, Center Mounted, One-Person Articulated Boom, Utility Body, Bumper Mounted Winch, 9 ft x 65 in Bed Usage: 129,564 Mi
	Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers,	1007	Asset located in: Humble, TX
	16 ft 2 in x 94 in Bed, Pintle Hitch Usage: 80,523 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1285	Altec AT248F 43 ft on 2016 Ram 5500 4x2 Bucket Truck S/N: 3C7WRMDL7GG282240 C/W: Dodge Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic
1281	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH161903 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9071 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 61,809 Mi Asset located in: Humble, TX		Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, PTO, 360 lb Capacity, Center Mounted, One-Person Articulated Boom, Utility Body, Remote Contro w/Cord, 17 ft 4 in x 94 in Bed Usage: 200,250 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details	
1286	Altec AFU32 32 ft on 2015 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GT8FED70374 C/W: V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 Ib Front Axle, 14706 Ib Rears, 19500 Ib GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, PTO, 300 Ib Capacity, Rear Mounted, One-Person Telescopic Boom, Utility Body, 11 ft x 96 in Bed Usage: 116,212 Mi Asset located in: Humble, TX	1291	2011 Ford E-450 Econoline 4x2 25-Seat Transit Bus S/N: 1FDFE4FS2BDA49235 C/W: Air Conditioner, Automatic Transmission, V10 6.8 L Gasoline Engine, 2011 US EPA Label, 225/75R16, Air Ride Suspension, 202 in Wheelbase Usage: 311,992 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
1287	2006 Versalift Tel29N-02 29 ft on 2006 Ford F- 350 4x2 Bucket Truck S/N: 1FDWF36516EC11373 C/W: V8 5.4 L Gasoline Engine, 2006 US EPA Label, 9088 Engine hrs, Automatic Transmission, 4700 lb Front Axle, 9750 lb Rears, 14450 lb GVWR, 245/75R17, Spring Suspension, 165 in Wheelbase, 300 lb Capacity, Center Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Onan CMM/5F00EEL 5500 kW Capaciling	-1292	1999 Chevrolet Bus 4x4 8-Seat Crew Carrier Bus S/N: 1GBHG31R0X1081913 C/W: Air Conditioner, Automatic Transmission, V8 Gasoline Engine, 1999 US EPA Label, 40X15. 50R24, Spring Suspension, 144 in Wheelbase Usage: 180,934 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Onan CMM5500EFI 5500 kW Gasoline Generator Set, 11 ft x 96 in Bed, Pintle Hitch Usage: 118,572 Hr Notes: . Asset located in: Humble, TX	1293	2018 Ford Transit 350 XLT 15 Passenger Van S/N: 1FBVU4XG8JKB25388 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera	
1288	2005 Winnebago Journey Motor Home S/N: 4UZAAHDC95CU91450 C/W: Air Conditioner, Allison Automatic Transmission, Cat C7 6 Cylinder Diesel 350 hp Engine, Sleeps 4 People, Clothes Washer & Dryer, 27910 lb GVWR, 2 Slide Outs, Power		Usage: 66,098 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	Leveling Jacks, Air Ride Suspension Onan 7500 7.5 kW Generator Usage: 881 Mi Asset located in : Humble, TX	1294	S/N: 1FBNE31L61HA49437 C/W: V8 5.4 L Gasoline Engine, 2001 U	2001 Ford E-350 XL 10 Passenger Van S/N: 1FBNE31L61HA49437 C/W: V8 5.4 L Gasoline Engine, 2001 US EPA Label, Automatic Transmission, Air
1289	2006 Orion 4x2 44-Seat Transit Bus S/N: 1VHAH3H2166502546 C/W: Air Conditioner, Automatic Transmission, Cummins 6 Cylinder Diesel Engine, B305 /85R22.5, Air Assist Front Suspension, Air Ride Suspension, 284 in Wheelbase Usage: 379,161 Mi Asset located in: Humble, TX	1295	Conditioner, Towing Hitch Usage: 123,239 Mi Asset located in: Humble, TX 2020 GMC Savana 2500 9 Passenger Van S/N: 1GTW7BFG1L1273016 C/W: V8 6.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,	
1290	2013 Ford E-450 Econoline 4x2 Mini Bus S/N: 1FDFE4FS8DDA93047 C/W: Air Conditioner, Automatic Transmission, Ford 6.8 L Gasoline Engine, 2013 US EPA Label, 225/75R16, Spring Suspension, 188 in Wheelbase		Rear View Camera, Navigation, Towing Hitch Usage: 47,055 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	Wheelbase Usage: 178,763 Mi Notes : **Seats have been removed** DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1296	2019 Chevrolet Express 4x2 12-Seat Passenger Van S/N: 1GAWGFFP5K1260235 C/W: Automatic Transmission, V6 4.3 L Gasoline Engine, 2019 US EPA Label, 245 /75R16, Spring Suspension, 136 in Wheelbase Usage: 106,560 Mi Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1297	2019 Chevrolet Express 4x2 12-Seat Passenger Van S/N: 1GAWGEFP9K1286394 C/W: Air Conditioner, Allison Automatic Transmission, 3756.3 hrs Carrier Engine, GM 4.3 L Gasoline Engine, 2019 US EPA Label, 245 /75R16, Spring Suspension, 136 in Wheelbase Usage: 121,212 Mi Asset located in: Humble, TX 2014 Ford E-150 4x2 8-Seat Passenger Van S/N: 1FMNE1BL3EDA18489 C/W: Automatic Transmission, V8 5.4 L Gasoline Engine, 2014 US EPA Label, 225 /75R16, Spring Suspension, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP-	-	2019 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC2KDKB9102 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 6153 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 238,924 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	COMPANY Usage: 43,192 Mi		Asset located in: Humble, TX
	Asset located in: Humble, TX	1303	2019 Freightliner M2106 4x2 Van Truck
1299	2016 Peterbilt 330 4x2 Van Truck S/N: 2NPNHM6X2GM349371 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8796 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17000 lb Rears, 4.88:1 Axle Ratio, 26000 lb GVWR, 295 /75R22.5, Paccar Air Ride Suspension, 275 in Wheelbase, Morgan 26 ft x 102 in Wide x 106 in High Body, Liftgate Usage: 198,811 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3ALACWFC0KDKV8114 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 6965 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.88:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Supreme 20 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 252,494 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
1300	2020 Freightliner M2 106 4x2 Van Truck	1004	Asset located in: Humble, TX
	S/N: 3ALACWD27LDLW1705 C/W: Detroit DD8 6 Cylinder 7.7 L 260 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 7909 Engine hrs, Engine Brake, Allison 2500 Automatic Transmission, 10000 Ib Front Axle, 19000 Ib Rears, 5.56:1 Axle Ratio, 26000 Ib GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 281 in Wheelbase, Morgan 28 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 335,294 Mi Notes: LOCATED-IN-FORT-WORTH-TX , . Asset located in : Lake Worth, TX	1304	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC0KDKD5251 C/W: Cummins B6.7 240 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9045.7 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 22 ft x 102 in Wide x 86 in High Body, Liftgate Usage: 357,096 Mi Notes: ; SELLER SUPPLIED MAINTENANCE
1301	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWD23LDLW1703		RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
	C/W: Detroit DD8 7.7 L 260 hp Engine, 2019 US		Asset located in: Humble, TX
	EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 10000 Ib Front Axle, 19000 Ib Rears, 5.56:1 Axle Ratio, 26000 Ib GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 281 in Wheelbase, Morgan 28 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 376,513 Mi Notes: LOCATED-IN-FORT-WORTH-TX , . Asset located in: Lake Worth, TX	1305	2019 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFCXKDKL6105 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10198 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 537,307 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1306	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB3KDKH7212 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 272.9 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 189,467 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	1312	2018 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC0JDJR3604 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7489 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Supreme 24 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 348,022 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1307	Asset located in: Humble, TX 2019 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC2KDKD5249 C/W: Cummins B6.7 6 Cylinder 6.7 L 240 hp Engine, Requires Diesel Exhaust Fluid, 11201 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 283,890 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	-1314	2017 Freightliner M2106 4x2 Van Truck S/N: 3ALACWDTXHDJB3542 C/W: Cummins 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 96 in Wide x 106 in High Body Usage: 318,332 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1308	Asset located in: Humble, TX 2018 Freightliner M2106 4x2 Moving Van Truck S/N: 3ALACWFC6JDKA3452 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 6255 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Airliner Air Ride Suspension, 280 in Wheelbase, Kentucky 26 ft x 96 in Wide x 110 in High Body, Curbside Door Usage: 204,245 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	1316	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT2GHHN3194 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, 6945 Engine hrs, Allison 2200 Automatic Transmission, 8000 lb Front Axle, 18000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, Summit 26 ft x 102 in Wide x 104 in High Body, Liftgate Usage: 132,863 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1309	Asset located in: Humble, TX 2018 Freightliner M2106 4x2 Extended Cab Moving Van Truck S/N: 3ALACWFC4JDKA3465 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 7150 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 267 in Wheelbase, Kentucky Trailer 26 ft x 102 in Wide x 100 in High Body, Curbside Door Usage: 229,933 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	-1317	2016 Freightliner M2106 4x2 Van Truck S/N: 3ALACWDT1GDHR8066 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4948.3 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000.0 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 143,232 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1318	2016 Freightliner M2106 4x2 Van Truck S/N: 1FVACWDT5GHHN3187 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 9663 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 18000 lb Rears, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 263 in Wheelbase, Summit 26 ft x 102 in Wide x 94 in High Body, Liftgate Usage: 115,626 Mi Asset located in: Humble, TX	1322	2012 Freightliner M2 4x2 Van Truck S/N: 1FVACWBT9CDBK8764 C/W: Cummins ISC 6 Cylinder 8.3 L Diesel 260 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 7927 Engine hrs, Eaton Fuller FSO-6406A 6-Speed Manual Transmission, 8000 lb Front Axle, 17500 lb Rears, ARS-17.5-2 Drive Axles, 3.91:1 Axle Ratio, 25500 lb GVWR, Air Ride Cab, Steel, 11R22.5, Spring Suspension, 210 in Wheelbase, Morgan 18 ft x 102 in Wide x 91 in High Body Usage: 226,195 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1319	2015 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT7FDGM6131		THE INSPECTION REPORT
	C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220		Asset located in: Humble, TX
	hp Engine, 2014 US EPÁ Label, Requires Diesel Exhaust Fluid, 8450 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 278 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 242,912 Mi Asset located in : Humble, TX	1323	2018 Hino 338 4x2 Van Truck S/N: 5PVNV8JV3J4S58071 C/W: 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9665 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 290 in Wheelbase, Morgan 28 ft x 102 in Wide x 103 in High Body, Liftgate
1320	2013 Freightliner M2106 6x4 Van Truck	1	Usage: 333,734 Mi
	S/N: 1FVHCYBS0DHFF4334 C/W: Cummins ISC 6 Cylinder Diesel 270 hp		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Engine, Requires Diesel Exhaust Fluid, 11413.8		Asset located in: Humble, TX
	Engine hrs, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 264 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body, Curbside Door, Liftgate Usage: 339,084 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1324	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV1L4S75725 C/W: Hino 6 Cylinder Diesel Engine, 7266 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 99 in High Body, Liftgate Usage: 213,561 Mi
1321	2012 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT4CDBD8207	-	Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2011 US EPA Label, Requires Diesel		Asset located in: Humble, TX
	Exhaust Fluid, 9682.3 Engine hrs, Eaton Fuller Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor Drive Axles, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 234,171 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1325	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9L5S78351 C/W: Hino J08EBV 6 Cylinder 7.7 L 260 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 Ib Front Axle, 19000 Ib Rears, 25950 Ib GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 97 in High Body, Liftgate Usage: 282,311 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW

Asset located in: Humble, TX

Details	Lot #	Details
2018 Hino 268 4x2 Van Truck	1334	2019 International 4300 4x2 Van Truck
S/N: 5PVNJ8JV2J4S69767 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 4785 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 106 in High Body Usage: 125,655 Mi		S/N: 1HTMMMML2KH514831 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 2934 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, supreme 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 125,178 Mi
Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ;		Notes : ***Please See Seller Supplied Maintenance Record Attached in the Documentation Section Below***
	-	Asset located in: Humble, TX
	1335	2019 International 4300 4x2 Cargo Van Truck
C/W: 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX		S/N: 1HTMMMML0KH515489 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3441 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MT-40-14X Drive Axles, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 97 in High Body, Walk-Up Ramp, Liftgate, Ball Hitch
2014 Hino 268A Van Truck		Usage: 152,143 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
S/N: 5PVNJ8JT7E4S55125		THE INSPECTION REPORT
		Asset located in: Humble, TX
	1336	2019 International 4300 4x2 Van Truck
S/N: 3HAEUMMN4LL179234 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 3081 Engine hrs, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, 11R22.5, Air Ride Suspension, 285 in Wheelbase, 28 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 135,826 Mi		S/N: 1HTMMMML0KH515492 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3560 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body Usage: 159,115 Mi
Notes: PROFESSIONALLY-MAINTAINED-FLEET-		Notes: ***Please See Seller Supplied
		Maintenance Record Attached in the Documentation Section Below***
	1	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
S/N: 3HTHWSNN3JN626221		Asset located in: Humble, TX
	1337	2019 International 4300 SBA 4x2 Van Truck
Exhaust Fluid, 9141 Engine hrs, Engine Brake, Automated Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 314,311 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		S/N: 1HTMMMML6KH515089 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3786 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp Usage: 170,705 Mi Asset located in: Humble, TX
	2018 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV2J4S69767 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 4785 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 106 in High Body Usage: 125,655 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX 2017 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3H4S64734 C/W: 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX 2014 Hino 268A Van Truck S/N: 5PVNJ8JT7E4S55125 Usage: Not Available Asset located in: Humble, TX 2020 International MV607 4x2 Van Truck S/N: 3HAEUMMN4LL179234 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 3081 Engine hrs, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, 11R22.5, Air Ride Suspension, 285 in Wheelbase, 28 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 135,826 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; Asset located in: Humble, TX 2018 International 8600 SBA 4x2 Van Truck S/N: 3HTHWSNN3JN626221 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 370 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9141 Engine hrs, Engine Brake, Automated Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GWWR, Air Ride Suspension, 265 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 314,311 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	2018 Hino 268 4x2 Van Truck1334S/N: 5PVNJ8JV2J4S69767[]]C/W: Hino 6 Cylinder Diesel Engine, RequiresDiesel Exhaust Fluid, 4785 Engine hrs,Automatic Transmission, 10000 lb Front Axle,19000 lb Rears, 25950.0 lb GVWR, 11R22.5, AirRide Suspension, 272 in Wheelbase, Supreme26 ft x 102 in Wide x 106 in High BodyUsage: 125,655 MiNotes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG ;Asset located in: Humble, TX2017 Hino 268 4x2 Van TruckS/N: 5PVNJ8JV3H4S64734C/W: 6 Cylinder Diesel Engine, 2016 US EPALabel, Requires Diesel Exhaust Fluid, AllisonAutomatic Transmission, 10000 lb Front Axle,19000 lb Rears, 25950 lb GVWR, 11R22.5,Hendrickson Air Ride Suspension, 272 inWheelbase, Supreme 26 ft x 102 in Wide x 103in High Body, Liftgate, EQUIPMENT-FROM-YELLOW-CORPUsage: Not AvailableAsset located in: Humble, TX2020 International MV607 4x2 Van TruckS/N: 3PVNJ8JT7E4S55125Usage: Not AvailableAsset located in: Humble, TX2020 International MV607 4x2 Van TruckS/N: 3HAEUMMN4L179234C/W: Cummins 6 Cylinder Diesel Engine,Requires Diesel Exhaust Fluid, 3081 Engine hrs,Automated Transmission, 12000 lb Front Axle,21000 lb Rears, 33000.0 lb GVWR, 11R22.5, AirRide Suspension, 285 in Wheelbase, 28 ft x 102in Wide x 103 in High Body, LiftgateUsage: 135,826 MiNotes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG ;Asset located

Lot #	Details	Lot #	Details
1338	2019 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML6KH515125 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, 4093 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 282 in Wheelbase, Morgan 24 ft x 102 in Wide x 91 in High Body, Walk-Up Ramp Usage: 170,361 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1343	2018 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML2JH463295 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9475 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Mickey 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Ball Hitch Usage: 328,837 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1339	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML1KH581520 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 7716 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 269 in Wheelbase, Supreme 26 ft x 102 in Wide x 100 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 204,957 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	1344	2018 International 4300 4x2 Van Truck S/N: 1HTMMMMN1JH212849 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7529 Engine hrs, Eaton Fuller 6-Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 90 in High Body, Liftgate Usage: 288,944 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1346	2016 International 4300 4x2 Van Truck
1340	2018 International Durastar 4300 4x2 Cargo Van Truck S/N: 3HAMMML8JL111283 C/W: Cummins B6.7 6 Cylinder 6.7 L 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 4731 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body Usage: 123,901 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1HTMMMML8GH106888 C/W: Cummins ISB6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7190 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 226,452 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
1342	Asset located in: Humble, TX 2018 International 4300 4x2 Van Truck S/N: 3HAMMML9JL003769 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8873 Engine hrs, Eaton Fuller Automatic Transmission, 7937 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 317,510 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1347	2016 International 4300 4x2 Van Truck S/N: 1HTMMMML4GH081276 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 7781 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 230,393 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 International 4300 4x2 Van Truck S/N: 1HTMMMML0GH012990 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10795 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295 /75R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 101 in High Body, Curbside Door, Liftgate Usage: 426,973 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1351	2016 International 4300 SBA 4x2 Van Truck S/N: 3HAMMML0GL262692 C/W: Cummins 6 Cylinder 6.7 L Diesel 250 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11102 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 105 in High Body, Liftgate Usage: 260,824 Mi Asset located in: Humble, TX	1355	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP9L1182263 C/W: V6 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 74 in High Body Usage: 89,341 Mi Notes: TITLE SHOWS NOT ACTUAL MILEAGE Asset located in: Humble, TX 2020 GMC Savana G3500 4x2 Van Truck
1352	2006 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWCS36DW26014 C/W: Mercedes Benz MBE900-210 6 Cylinder 6.4 L Diesel 210 hp Engine, 2005 US EPA Label, 18792 Engine hrs, Allison 2100 Automatic Transmission, 5.13:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Liftgate Usage: 572,052 Mi Notes: LOCATED-IN-FORT-WORTH-TX BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM ; LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1357	S/N: 1GD07RFP4L1158517 C/W: Vortec 6 Cylinder 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6081 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 71 in High Body Usage: 93,097 Mi Notes : TITLE SHOW NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2019 GMC Savana G3500 4x2 Van Truck
1353	2005 Freightliner M2106 4x2 Van Truck S/N: 1FVACWDC65HV11888 C/W: Cat C7 6 Cylinder Diesel 210 hp Engine, 12350 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 5.57:1 Axle Ratio, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 270 in Wheelbase, supreme 26 ft x 96 in Wide x 97 in High Body, Liftgate Usage: 349,547 Mi Asset located in: Humble, TX		S/N: 7GZ37TCG1KN006093 C/W: V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 14300 lb GVWR, 225 /75R16, Spring Suspension, 178 in Wheelbase, Morgan 16 ft x 96 in Wide x 76 in High Body, ball Usage: 104,391 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in : Humble, TX
1354B 1354A	2022 Ford E-350 Van Truck S/N: 1FDWE3FK1NDC05666 C/W: Ford V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 8500 lb Rears, 12500 lb GVWR, 225 /75R16, Spring Suspension, 159 in Wheelbase, 14 ft x 96 in Wide x 81 in High Body Usage: 99,523 Mi Asset located in: Humble, TX 2005 Hino 268 4x2 Van Truck S/N: 5PVNJ8JT352S10274	1358	2022 Chevrolet Express 4x2 Van Truck S/N: 1HA3GTC70NN008060 C/W: V8 6.6 L Gasoline Engine, 2022 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225/75 /16, Spring Suspension, 178 in Wheelbase, 16 ft x 96 in Wide x 81 in High Body, Curbside Door Usage: 32,657 Mi Notes: TITLE SHOWS ODOMETER READING NOT ACTUAL Asset located in: Humble, TX
1354	C/W: Hino Motors J08E-TA 6 Cylinder 7.7 L Diesel 220 hp Engine, 2004 US EPA Label, Automatic Transmission, 8000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 253 in Wheelbase, MARATHON INDUSTRIES 24 ft x 101 in Wide x 109 in High Body, Liftgate Usage: 418,349 Mi Notes : TITLE BRAND WITH BONDED TITLE Asset located in : Humble, TX 2009 Hino Van Truck S/N: 5PVNJ8JV592S51738 Usage: Not Available Asset located in : Humble, TX	1359	2014 Chevrolet Express 3500 4x2 Van Truck S/N: 1GB3G3BG0E1186536 C/W: V8 6.0 L Gasoline Engine, 2014 US EPA Label, 4488 Engine hrs, Automatic Transmission, 8600 lb Rears, 225/75R18, Spring Suspension, 156 in Wheelbase, Supreme 15 ft x 96 in Wide x 88 in High Body Usage: 180,176 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1360	2014 Chevrolet Express 3500 4x2 Van Truck S/N: 1GB3G3CG8E1101781 C/W: Chevrolet V8 6.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4300 Ib Front Axle, 8600 Ib Rears, 12300 Ib GVWR, 225/75/16, Spring Suspension, 161 in Wheelbase, 15 ft x 94 in Wide x 86 in High Body Usage: 203,953 Mi Notes: ODOMETER DISCREPANCY UNIT SHOWS 203,953, TITLE SHOWS 208,908 DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1364	2019 Isuzu NRR 4x2 COE Van Truck S/N: JALE5W166K7303290 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7042 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 152 in Wheelbase, Supreme 18 ft x 96 in Wide x 91 in High Body, Curbside Door, Liftgate Usage: 211,629 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1365	2019 Isuzu NPR NPR HD 4x2 COE Van Truck
1361	 61 2014 Ford E350 4x2 Van Truck S/N: 1FDWE3FL7EDA06369 C/W: V8 5.4 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 6084 lb Rears, 10050 lb GVWR, 245 /75R16, Spring Suspension, 138 in Wheelbase, Supreme 12 ft x 79 in Wide x Body Usage: 246,541 Mi Notes: LOCATED-IN-LIVINGSTON_LA_TX , ; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 		S/N: JALC4W167K7007981 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7175.5 Engine hrs, Exhaust Brake, Automatic Transmission, 5360 Ib Front Axle, 9880 Ib Rears, 14500 Ib GVWR, 215/85R16, Spring Suspension, 152 in Wheelbase, Morgan 18 ft x 96 in Wide x 92 in High Body, Liftgate Usage: 161,545 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
1362	Asset located in: Livingston, LA 2019 Isuzu NRR 4x2 COE Van Truck		Asset located in: Humble, TX
1302	S/N: JALE5W161K7301687 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Ultra Low Sulfur Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7965 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 149 in Wheelbase, Supreme 17 ft x 92 in Wide x 74 in High Body, Curbside Door Usage: 111,909 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1368	2016 Isuzu NRR 4x2 COE Van Truck S/N: JALE5W164G7300668 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 6766 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Morgan 20 ft x 96 in Wide x 85 in High Body Usage: 204,049 Mi Asset located in: Humble, TX
		1369	·
1363			2016 Isuzu NPR 4x2 COE Van Truck S/N: JALB4W17XG7F00259 C/W: 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 5360 Ib Front Axle, 9880 Ib Rears, 13000 Ib GVWR, 215/85R16, Spring Suspension, 148 in Wheelbase, Marathon 16 ft x 96 in Wide x 82 in High Body Usage: 86,168 Mi Asset located in: Humble, TX
	13660 lb Rears, 19500 lb GVWR, 225/70R19.5,	1370	2014 Isuzu NPR Van Truck
	Spring Suspension, 147 in Wheelbase, Supreme 17 ft x 96 in Wide x 90 in High Body, Curbside Door Usage: 151,590 Mi		S/N: JALC4W169E7004598 Usage: Not Available Asset located in : Humble, TX
	Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1371	2022 Freightliner MT55G 4x2 Step Van S/N: 4UZAC3GA1NCNE9666 C/W: V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 8000 lb Front Axle, 15000 lb Rears, 23000 lb GVWR, 245/70R19.5, Spring Suspension, 208 in Wheelbase, Morgan Olson P1200 22 ft x 96 in Wide x 81 in High Body Usage: 71,991 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1372	2021 Ford 4x2 Step Van S/N: 1F65F5KN7M0A13007 C/W: V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 179 in Wheelbase, 18 ft x 96 in Wide x 87 in High Body Usage: 39,196 Mi Asset located in: Humble, TX	1380	2017 Ram Promaster 4x2 Cargo Van S/N: ZFBERFAB3H6G90159 C/W: Dodge 4 Cylinder 2.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 215/55R16, Spring Suspension, 121 in Wheelbase, 7 ft x x 53 in High Body Usage: 207,325 Mi Notes: ODOMETER DISCREPANCY-UNIT SHOWS 207,224 TITLE SHOWS 207,225
1374A	2009 Ford E-350 Cargo Van S/N: 1FTSE34P29DA34949 C/W: V8 6.0 L Diesel Engine, 2009 US EPA	-	SHOWS 207,324, TITLE SHOWS 207,325 DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner Usage: 152,095 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	1381	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF6H1142494 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x x
1374	2012 Ford E-350 Cargo Van S/N: 1FTNE1EW4CDB36459 C/W: V8 Gasoline Engine, Automatic		52 in High Body Usage: 179,205 Mi Asset located in: Humble, TX
	Transmission, Air Conditioner, Power Windows, Power Locks Usage: 181,379 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1383	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF1H1142659 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 136 in Wheelbase, 6 ft x 72
1376	2021 Ford Transit 250 4x2 Cargo Van S/N: 1FTBR1X86MKA08520 C/W: 4 Cylinder 3.5 L Gasoline Engine, 2021 US		in Wide x 52 in High Body Usage: 185,264 Mi Asset located in: Humble, TX
	EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9070 lb GVWR, 235 /65R16, Spring Suspension, 145 in Wheelbase, 10 ft x x 80 in High Body Usage: 75,756 Mi Notes : . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	1384	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF3H1142081 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x x 52 in High Body Usage: 190,385 Mi
1377	Asset located in: Humble, TX 2020 Ford Transit 4x2 Cargo Van	-	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1FTYE1Y86LKA02784 C/W: V6 3.5 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5070 lb Rears, 8670 lb GVWR, 235/65R16, Spring Suspension, 129 in Wheelbase, 9 ft x 70 in Wide x 46 in High Body, Curbside Door Usage: 85,329 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in : Humble, TX	1385	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF4H1140999 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, 6834 Engine hrs, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 135 in Wheelbase, 5 ft x 55 in Wide x 48 in High Body Usage: 226,555 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1378	2017 BlueBird Transit Cargo Van S/N: 1FTYE1ZM2HKA58028		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 6 cyl 3.7 L Gasoline Engine, 2017 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 252,865 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1386	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF3H1140783 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 136 in Wheelbase, 6 ft x 74 in Wide x 53 in High Body Usage: 189,868 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1388	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF1H1141690 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x x 52 in High Body Usage: 190,260 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1396 	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFB9G1128185 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, 11 ft x x 54 in High Body Usage: 166,437 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Chevrolet Express 2500 4x2 Cargo Van
1389	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF1H1143049 C/W: 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 72 in Wide x 51 in High Body Usage: 161,564 Mi Asset located in: Humble, TX		S/N: 1GCWGGCB6F1103552 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 11 ft x x 53 in High Body Usage: 162,246 Mi Asset located in : Humble, TX
1390	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF8H1140231 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 138 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 182,180 Mi Asset located in: Humble, TX	_1399	2016 Ford Transit 250 4x2 Cargo Van S/N: 1FTYR2ZM4GKA77642 C/W: Ford V6 3.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9000 lb GVWR, 235 /65R16, Spring Suspension, 138 in Wheelbase, 9 ft x 78 in Wide x 56 in High Body Usage: 214,134 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1393	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFB3G1151011 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 7 ft x 73 in Wide x 52 in High Body Usage: 159,993 Mi Asset located in: Humble, TX	1400	Asset located in: Humble, TX 2010 Ford E-250 Cargo Van S/N: 1FTNE2EL9ADA90300 C/W: V8 5.4 L Natural Gas Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner Usage: 98,382 Mi Asset located in: Humble, TX
1394	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFB2G1127282 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 200,214 Mi Asset located in: Humble, TX 2016 Chevrolet Express 2500 4x2 Cargo Van	- 1401	2007 Chevrolet 2500 Express 4x2 Cargo Van S/N: 1GCGG25V271224188 C/W: V6 4.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 5360 lb GVWR, 245/75R16, Spring Suspension, 123 in Wheelbase, 9 ft x x 54 in High Body Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX , TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	S/N: 1GCWGBFB6G1128242 C/W: V8 6.0 L Compressed Natural Gas (CNG) Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 155 in Wheelbase, 11 ft x x 54 in High Body Usage: 150,088 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1403	2019 International 4x2 Refrigerated Truck S/N: 3HAEUMML6KL031017 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10761 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 242 in Wheelbase, Thermo King T-880R Reefer Unit, MORGAN 22 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 376,042 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1404	2019 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXFC1KDKT1218 C/W: Cummins 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, 9463 Engine hrs, Eaton Fuller 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Carrier Supra 860 Reefer Unit, 764 Reefer Engine Hours:, Morgan 26 ft x 96 in Wide x 102 in High Body, Liftgate Usage: 280,649 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	1407	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFC5JDJL6587 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13930 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5, Spring Suspension, 270 in Wheelbase, Thermo King T-680R Reefer Unit, Supreme 26 ft x 102 in Wide x 103 in High Body Usage: 163,535 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
1405	2018 Freightliner M2 4x2 Refrigerated Truck S/N: 3ALACWFC2JDJH3995 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller EDCO- 6F107A Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Thermo King Reefer Unit, Supreme 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 184,074 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1408	Asset located in: Humble, TX 2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFC0JDJH4501 C/W: Cummins 6 Cylinder Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 6405 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 268 in Wheelbase, Carrier Reefer Unit, Standby Power, Supreme 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 205,482 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
1406	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXDT4JDJJ6808 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11330.6 Engine hrs, Eaton Fuller FS-6406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Detroit DA- RS-21.0-4 Drive Axles, 4.10:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Carrier Supra 860 Reefer Unit, 10044 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 91 in High Body, Liftgate Usage: 425,322 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1409	Asset located in: Humble, TX 2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFCXJDJH4019 C/W: 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 7591 Engine hrs, Eaton Fuller Automated Transmission, 10000 Ib Front Axle, 19000 Ib Rears, 5.56:1 Axle Ratio, 26000 Ib GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Thermo King Reefer Unit, 10449 Reefer Total Hours:, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 206,210 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1410	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXFC3JDJH5759 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, 4654 Engine hrs, Eaton Fuller EDCO-6F107A Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000.0 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Carrier Supra 860 Reefer Unit, 12823 Reefer Engine Hours:, 19826 Reefer Total Hours:, Standby Power, Hackney 26 ft x 102 in Wide x 96 in High Body, Curbside Door, Liftgate Usage: 237,396 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ;	1416	2013 Chevrolet Express G3500 4x2 Ambulance S/N: 1GB3G2CLXD1181820 C/W: 11429.2 Engine hrs, Automatic Transmission, 4600 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, GM Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 225/75R16, Spring Suspension, 138 in Wheelbase, Custom Works Inc 11 ft 9 in Body, First Aid Supplies Usage: 284,908 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Dodge Ram 3500 4x2 Ambulance S/N: 3D6WF4ET4BG628154 C/W: Automatic Transmission, 5200 lb Front
1411	Asset located in: Humble, TX 2018 Freightliner M2106 4x2 Refrigerated Truck S/N: 3ALACWFC1JDJU2984 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel	-	Axle, 9350 lb Rears, 12500 lb GVWR, Chrysler Group V8 5.7 L Gasoline Engine, 2011 US EPA Label, 235/80R17, Spring Suspension, 168 in Wheelbase, 12 ft Body Usage: 191,018 Mi Asset located in : Humble, TX
	240 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Carrier SUPRA 760 Reefer Unit, Morgan 26 ft x 102 in Wide x 103 in High Body Usage: 480,883 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION	1418	2005 Ford E-350 4x2 Ambulance S/N: 1FDWE35P15HA25769 C/W: Automatic Transmission, 4600 lb Front Axle, 7800 lb Rears, 11500 lb GVWR, V8 6.0 L Diesel Engine, 2005 US EPA Label, 225/75/16, Spring Suspension, 139 in Wheelbase, 12 ft Body Usage: 89,747 Mi Asset located in: Humble, TX
	BELOW SUPPLIED Asset located in: Humble, TX	1419	2009 Chevrolet Express G3500 4x2 Ambulance S/N: 1GBHG396891181433
1413			C/W: Automatic Transmission, 4600 lb Front Axle, 6084 lb Rears, 9600 lb GVWR, V8 6.6 L Diesel 250 hp Engine, 2009 US EPA Label, 245 /75/16, Spring Suspension, 155 in Wheelbase, 12 ft Body Usage: 227,847 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	102 in Wide x 103 in High Body, Curbside Door, Liftgate	1420	2007 Chevrolet Express G3500 4x2 Ambulance
	Usage: 166,547 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1GBHG396271250999 C/W: Automatic Transmission, 4600 lb Front Axle, 6084 lb Rears, 9600 lb GVWR, V8 6.6 L Diesel 250 hp Engine, 2007 US EPA Label, 245 /75/16, Spring Suspension, 155 in Wheelbase, 12 ft Body Usage: 163,544 Mi Asset located in : Humble, TX
1 41 5	Asset located in: Humble, TX	1421	2018 Chevrolet Tahoe 4WD SUV
1415	2014 Chevrolet G4500 4x2 Ambulance S/N: 1GB6G5CL3E1189337 C/W: 11553 Engine hrs, Automatic Transmission, 4600 lb Front Axle, 9700 lb Rears, 14200 lb GVWR, V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 225/75R16, Spring Suspension, 160 in Wheelbase, NORTHWESTERN EMERGENCY VEHICLES 14 ft 9 in Body Usage: 189,677 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1GNSKDEC4JR257440 C/W: 5.3 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch Usage: 112,866 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1422	2016 Chevrolet Tahoe 4x4 First Responders Vehicle S/N: 1GNSKDECXGR316130 C/W: Automatic Transmission, 3500 lb Front Axle, 3800 lb Rears, 7100 lb GVWR, V8 5.3 L Gasoline Engine, 2016 US EPA Label, 265 /65R17, Spring Suspension, 116 in Wheelbase	1427	2009 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM29H693135 C/W: International MaxxForce DT 7.6 L Diesel 210 hp Engine, 2008 US EPA Label, 14460 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires,
	Usage: 101,707 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Spring Suspension, 254 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In- Cab Arrow Board Controller Usage: 311,582 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE
1423	2016 Chevrolet Tahoe Automobile S/N: 1GNSKDEC7GR320359		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: V8 5.3 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 121,744 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	1428	2004 International 4300SBA 4x2 Attenuator Truck S/N: 1HTMMAAM44H596852 C/W: International 6 Cylinder Diesel Engine, 19009 Engine hrs, Automatic Transmission, 11R22.5, Spring Suspension, Stake Side Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller
1424	2008 Freightliner M2 106 4x2 Attenuator Truck S/N: 1FVACWDT58HZ60743		Usage: 311,464 Mi Asset located in: Humble, TX
	C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 1734 Engine hrs, Allison 2100 Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, Alliance ARS-17.5-2 Drive Axles, 4.56:1 Axle Ratio, 25500 lb GVWR, 245 /70R19.5, Spring Suspension, Cone Body, In- Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 297,982 Mi	1430	1968 Kaiser M35 4x4 2 1/2 Ton, Military Flatbed Truck S/N: 000000M35882 C/W: 6 Cylinder Diesel Engine, 1166 Engine hrs, 5-Speed Manual Transmission, 395/85R20, Spring Suspension, 147 in Wheelbase, 10 ft 2 in x 96 in Bed, Winch Usage: 30,999 Mi
	Asset located in: Humble, TX	<u> </u>	Asset located in: Humble, TX
1425	2007 Freightliner M2 106 4x2 Attenuator Truck S/N: 1FVACWDC17DZ43962 C/W: Cat C7 6 Cylinder Diesel 210 hp Engine, 4965.8 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, Meritor RS-17-144 Drive Axles, 5.57:1 Axle Ratio, 25500 lb GVWR, Aluminum Wheels, 295/75R22.5, Spring Suspension, 230 in Wheelbase, Cone Body, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 229,512 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1431	2007 Kenworth T300 6x4 Wireline Truck S/N: 2NKMLD9X87M183479 C/W: Cat C7 6 Cylinder Diesel 300 hp Engine, 2006 US EPA Label, 9992 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, Meritor Drive Axles, 5.29:1 Axle Ratio, 11R22.5, Hendrickson HAS Air Ride Suspension, 246 in Wheelbase Usage: 134,569 Mi Notes: LOCATED-IN-LIVINGSTON_LA SUBJECT TO LA TAX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
	THE INSPECTION REPORT Asset located in: Humble, TX	1432	2014 Freightliner 114SD 6x2 Car Carrier Truck
1426	2009 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM59H693856 C/W: Navistar 6 Cylinder Diesel Engine, 2007 US EPA Label, 14624 Engine hrs, Automatic Transmission, 11R22.5, Spring Suspension, 255 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board Usage: 231,262 Mi Asset located in: Humble, TX		S/N: 1FUFG3DV8EHFN6831 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11188 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C-VAS Automatic Transmission, 14600 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 Drive Axles, 3.21:1 Axle Ratio, 54600 lb GVWR, Aluminum Wheels, 295/60R22.5, Airliner Air Ride Suspension, 253 in Wheelbase, Soft Tie Downs, 54600 lb GVWR Usage: 894,653 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details
1433	2014 International 7400 SBA 4x2 Pressure Truck S/N: 1HTWCAZN0EH771964 C/W: 6 Cylinder Diesel Engine, 2013 US EPA Label, 10478 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 220 in Wheelbase, Weatherford W80 Triplex Pump, Fiberglass Reinforced Plastic Tank Usage: 105,762 Mi Asset located in: Humble, TX Knuckle Boom on 2013 Mack GU713 6x4	1437	2022 Ford F-650 4x2 Air Compressor Truck S/N: 1FDNF6DC5NDF06236 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 260 in Wheelbase, 150 psi Working Pressure, Cummins 6 Cylinder Engine, 186 in Cab to Axle, 279 in Cab to End of Frame, Doosan 935CFM Diesel Air Compressor S/N: 440490UEWE78 Usage: 32,298 Mi Asset located in: Humble, TX
110-07	Grapple Truck S/N: 1M1AX09Y7DM017188 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 21603 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 224 in Wheelbase, PTO, Center Mounted, 3 Section Boom, Straight Down Outriggers, Air Slide Fifth Wheel Usage: 397,134 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1438	Asset located III : Humble, TX 2013 Isuzu NPR 1000 gal 4x2 COE Hydroseeder Truck S/N: 54DB4W1B4DS802458 C/W: Chevrolet V8 6.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 4860 Ib Front Axle, 8840 Ib Rears, 12000 Ib GVWR, 215/85R16, Spring Suspension, 154 in Wheelbase, 1000 gal Tank, Pump w/ Honda Engine, Hose Reel Usage: 213,336 Mi Asset located in : Humble, TX
1435	THE INSPECTION REPORT Asset located in: Humble, TX 5 2018 International 4300 4x2 Flatbed Truck with Conveyor S/N: 1HTMNMML7JH753531 C/W: Cummins B6.7 250 6 Cylinder 6.7 L	1439	2004 International 4300 4x2 Armored Truck S/N: 1HTMMAAM04H667724 C/W: 6 Cylinder Ultra Low Sulfur Diesel Engine, 37303 Engine hrs, Automatic Transmission, 11R22.5 Usage: 622,060 Mi Asset located in: Humble, TX
	Diesel 250 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10098 Engine hrs, Automatic Transmission, 9000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5, Spring Suspension, 219 in Wheelbase, PTO, 22 ft x 9 in Bed Usage: 182,303 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1440	2016 Ram 5500 4x2 Armored Truck S/N: 3C7WRMAJ7GG325476 C/W: V8 5.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 18000 lb GVWR, 225 /70R19.5, Spring Suspension, 143 in Wheelbase Usage: 140,572 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1436	2018 Ford F-750 4x2 Hydraulic Ladder Utility Truck S/N: 1FDNF7DC5JDF06155 C/W: Ford Power Stroke 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 179 in Wheelbase, PTO, Hydraulic Stabilizers Usage: 145,640 Mi Asset located in: Humble, TX	5000	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20240825346 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20240825345 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5002	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20240825349 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5010	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused) S/N: HM20240825026 Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	5011	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124080601A C/W: THE PRODUCT IMAGES SHOWN ARE	
5003	Mulcher (Unused) S/N: DRM20240825348 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5012	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124080602A	
5004	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20240825347 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5014	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Top Cat SSDFM60 60 in Disc Skid Steer Mulcher (Unused) S/N: SSDFM6024080501B	
5005	5005 2024 Raytree RMBD50 50 in Drum Skid Steer Mulcher (Unused) S/N: LM20240825034 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5015	2024 Raytree RMDM70 60 in Disc Skid Steer Mulcher (Unused)	
5006	Asset located in: Humble, TX 2024 Raytree RMBD50 50 in Drum Skid Steer Mulcher (Unused) S/N: LM20240825035 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		S/N: DM20240825166 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5016	2024 Raytree RMDM70 60 in Disc Skid Steer Mulcher (Unused) S/N: DM20240825167	
5007	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused) S/N: BDM202408466 Usage: Not Available Asset located in: Humble, TX	1	C/W: THE PRODUCT IMAGES S FOR ILLUSTRATION PURPOSES MAY NOT BE AN EXACT REPRE THE ACTUAL PRODUCT Usage: Not Available	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5008	2024 Handy HBDM72-B 72 in Skid Steer	5017	2023 Top Cat HDRC 72 in Skid Steer Brush	
	Mulcher (Unused) S/N: BDM202408465 Usage: Not Available Asset located in: Humble, TX		Cutter (Unused) S/N: HDRC23092401D Usage: Not Available Asset located in: Humble, TX	
5009	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused) S/N: HM20240825025 Usage: Not Available Asset located in: Humble, TX	5018	2024 Handy HSBC72 72 in Skid Steer Brush Cutter (Unused) S/N: BC202408139 Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
5019	2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC202408140 Usage: Not Available Asset located in: Humble, TX	5026	2024 Wolverine BC-13-72W 72 in Skid Steer Brush Cutter (Unused) S/N: ZW07099 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5020	2024 Top Cat HFRC 72 in Skid Steer Brush Cutter (Unused) S/N: HFRC24080501B		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5027	2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5021	2024 Raytree RMC72 72 in Skid Steer Brush Cutter (Unused)		THE ACTUAL PRODUCT Usage: Not Available	
	S/N: C20240825085 C/W: THE PRODUCT IMAGES SHOWN ARE	L	Asset located in: Humble, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5028 5029 5030 5031	2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5022	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07085		MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080603A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5023	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07087		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	THE ACTUAL PRODUCT Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080604A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5024	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07086		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080605A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5025	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Upused)		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Brush Cutter (Unused) S/N: ZW07102 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX	
		5032	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080503B Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5033	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080504B Usage: Not Available Asset located in: Humble, TX	5044	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5034	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080505B Usage: Not Available	_5045	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5035	Asset located in: Humble, TX 2024 Mower King SSRC 72 in Skid Steer Brush	5046	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available
	Cutter (Unused) S/N: SSRC24080501B Usage: Not Available	5047	Asset located in: Humble, TX All-Star 66 in Skid Steer Brush Cutter (Unused)
5036	Asset located in: Humble, TX 2024 Mower King SSRC 72 in Skid Steer Brush	-	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Cutter (Unused) S/N: SSRC24080502B Usage: Not Available Asset located in: Humble, TX	5048	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5037	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5049	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5038	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5050	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5039	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5051	Mid-State 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available
5040	2024 Industrias America SK72 72 in Skid Steer Brush Cutter (Unused) S/N: SK72202522508 Usage: Not Available Asset located in: Humble, TX	5052	Asset located in: Humble, TX All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5041	2024 Suihe SSBC 66 in Skid Steer Brush Cutter (Unused) S/N: 001602290 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5053	2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: HL00139 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5042	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5054	2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: HL00138 C/W: THE PRODUCT IMAGES SHOWN ARE
5043	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5055	2024 Wolverine PBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW00302 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5063	2024 Handy HAB72 72 in Angle Skid Steer Broom (Unused) S/N: AB202408104 Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5064	2024 Handy HAB72 72 in Angle Skid Steer Broom (Unused) S/N: AB202408106
5056	2024 Wolverine PBS-11-72W 72 in Skid Steer	-	Usage: Not Available Asset located in: Humble, TX
	Sweeper (Unused) S/N: ZW00291 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5065	2024 Handy HAB72 72 in Angle Skid Steer Broom (Unused) S/N: AB202408105 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5066	2024 Mower King SSAB72 72 in Skid Steer
5057	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW02486 C/W: Quick Coupler Bracket Usage: Not Available Asset located in: Humble, TX	_	Broom (Unused) S/N: SSAB7224080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5058	2024 Wolverine BBS-11-72W 72 in Skid Steer		Asset located in: Humble, TX
	Sweeper (Unused) S/N: ZW02669 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5067	2024 Wolverine PAB-11-72W 72 in Angle Skid Steer Broom (Unused) S/N: ZW02647 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5059	2024 Mower King SSBM72 72 in Skid Steer		Asset located in: Humble, TX
Swa S/N C/V FOF MA	Sweeper (Unused) S/N: SSCM61S24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5068	2022 Paladin 21572P/M 72 in Skid Steer Sweeper S/N: 202213153 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5069	2024 Wolverine MBS-11-48W 48 in Mini Skid Steer Sweeper (Unused)
5060	2024 Mower King SSBM72 72 in Skid Steer Sweeper (Unused) S/N: SSCM61S24080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: ZW00341 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5070	2024 Handy HSD96 96 in PAT Skid Steer Dozer
5061	All-Star 72 in Angle Skid Steer Broom (Unused) S/N: Not Available	-	(Unused) S/N: SD202408290 Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX	5071	Asset located in: Humble, TX
5062	All-Star 72 in Angle Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5071	2024 Handy HSD96 96 in PAT Skid Steer Dozer (Unused) S/N: SD202408288 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5072 5073	2024 Handy HSD96 96 in PAT Skid Steer Dozer (Unused) S/N: SD202408289 Usage: Not Available Asset located in: Humble, TX 2024 Raytree RSWD96 94 in PAT Skid Steer Dozer (Unused) S/N: SW20240825023	5079	2024 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: ZW01001 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5080	All-Star 72 in Tilting Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
Asset located in: Humble, TX 5074 2024 Suihe SSD-YS86 86 in Angle Skid Steer Dozer (Unused) S/N: 031789653 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 5075 2024 Suihe SSD-YS86 86 in Angle Skid Steer	2024 Suihe SSD-YS86 86 in Angle Skid Steer Dozer (Unused)	5081	All-Star 72 in Tilting Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	5082	2024 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: AS00394 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	Dozer (Unused) S/N: 031789657 C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available
		5083	Asset located in: Humble, TX 2024 Wolverine TCR-12-48H 48 in Skid Steer
FOR ILLUS MAY NOT THE ACTU Usage: No Asset loca 5076 2024 Wolv Steer Doze	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	-	Trencher (Unused) S/N: ZW05775 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT
	2024 Wolverine DB-15-84W 84 in Angle Skid Steer Dozer (Unused) S/N: ZW00548		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	5084	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: ZW05807 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5077	Asset located in: Humble, TX 77 2024 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: ZW00978 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		
	Usage: Not Available Asset located in: Humble, TX	5085	2024 Wolverine TCR-12-48H 48 in Skid Steer
5078	2024 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: ZW01022 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Trencher (Unused) S/N: ZW05807 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5086	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5087	87 2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20240825124 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5095	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408101 Usage: Not Available Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5096	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408104	
5088	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused)		Usage: Not Available Asset located in: Humble, TX	
	S/N: T20240825126 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5097	2024 Wolverine SBM-12-72W 72 in Sickle Bar Skid Steer Mower (Unused) S/N: ZW02123 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5089	2024 Raytree RMT48 48 in Skid Steer Trencher	-	Usage: Not Available Asset located in: Humble, TX	
5090	(Unused) S/N: T20240825125 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Handy HST48 48 in Skid Steer Trencher	5098	2024 Wolverine SBM-12-72W 72 in Sickle Bar Skid Steer Mower (Unused) S/N: ZW02122 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	(Unused) S/N: TR202408610	5099	Asset located in: Humble, TX 2024 Mower King SSEFGC175 70 in Flail Skid	
5091	C/W: 4 ft bar, 8 in. rock & dirt chain, crumbing shoe Usage: Not Available Asset located in: Humble, TX 2024 Suihe SST-1000/200 36 in Skid Steer		Steer Mower (Unused) S/N: SSEFGC17524080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AN	Steer Mower (Unused) S/N: SSEFGC17524080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
3091	Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	
	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	Mower (Unused) S/N: SSEFGC17524080502B C/W: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY	S/N: SSEFGC17524080502B C/W: THE PRODUCT IMAGES SHOWN ARE	
5092	Asset located in: Humble, TX 2017 Bobcat LT313 40 in Skid Steer Trencher S/N: 045414038 C/W: 6 in. combination chain, crumbing shoe Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
_	Asset located in: Humble, TX	5101	2024 Mower King SSEFGC175 70 in Skid Steer	
5093	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408102 Usage: Not Available Asset located in: Humble, TX		Mower (Unused) S/N: SSEFGC17524080503B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
5094	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408103 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
5102	Mower (Unused) S/N: ZW00962 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5109	2024 Handy HVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR202408458 Usage: Not Available Asset located in: Humble, TX
5103	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine TBM-12-78W 78 in Skid Steer Mower (Unused)	5110	2024 Handy HVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR202408459 Usage: Not Available Asset located in: Humble, TX
	S/N: ZW00961 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5111	2024 Suihe SSVR-72 72 in Skid Steer Vibratory Roller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5104	AGT 48 in Mini Skid Steer Mower (Unused) S/N: Not Available Usage: Not Available	5112	Asset located in: Humble, TX 2024 Handy HGB86 96 in Heavy Duty Skid
5105	Asset located in: Humble, TX 105 2024 Landhonor VPC-11-72W 72 in Skid Steer Plate Compactor (Unused) S/N: HL00971	-	Steer Grader (Unused) S/N: GB86202408202 Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5113	2024 Wolverine VR-11-66W 66 in Skid Steer Vibratory Roller (Unused) S/N: ZW01475 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5106	2024 AGT SSPC72 72 in Skid Steer Plate Compactor (Unused) S/N: SSPC7224080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		5114	2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202408203 Usage: Not Available Asset located in: Humble, TX
5107	-	5115	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202408588 Usage: Not Available Asset located in: Humble, TX
		5116	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202408589 Usage: Not Available
5108	2024 Raytree RMVR76 76 in Skid Steer	1	Asset located in: Humble, TX
	Vibratory Roller (Unused) S/N: VR20240825150 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5117	2024 Raytree RMGB96 96 in Skid Steer Grader S/N: GB20240825104 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5118	2024 Raytree RMGB96 96 in Skid Steer Grader (Unused) S/N: GB20240825103 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5126	2024 Top Cat SSSCR72 72 in Skid Steer Power Rake (Unused) S/N: SSSCR7224080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5119	2024 Raytree RMGB96 96 in Skid Steer Grader (Unused) S/N: GB20240825105 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5127	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: HL01001 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5120	2024 Top Cat SSSG72 72 in Skid Steer Grader (Unused) S/N: SSSG7224080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5128	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5121	2024 Handy HSC78 78 in Skid Steer Power Rake (Unused) S/N: SC202408713 Usage: Not Available Asset located in: Humble, TX 2024 Handy HSNC78 78 in Skid Steer Power	5129	2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
0122	Rake (Unused) S/N: SC202408101 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX 2024 Top Cat ECSSLR72 72 in Skid Steer
5123	2024 Handy HSNC78 78 in Skid Steer Power Rake (Unused) S/N: SC202408102 Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT
5124	2024 Handy HSNC78 78 in Skid Steer Power		Asset located in: Humble, TX
	Rake (Unused) S/N: SC202408103 Usage: Not Available Asset located in: Humble, TX	5131	2024 Wolverine CB-11-750F Skid Steer Breaker (Unused) S/N: ZW01434 C/W: THE PRODUCT IMAGES SHOWN ARE
5125	2024 Top Cat SSSCR72 72 in Skid Steer Power Rake (Unused) S/N: SSSCR7224080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		5132	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406083 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5133	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406084 Usage: Not Available Asset located in: Humble, TX 2024 Jisan JSB400SL Skid Steer Breaker	5141	2024 Raytree RMH680 Skid Steer Breaker (Unused) S/N: HH20240825144 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5134	(Unused) S/N: CP2404286 Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	5142	2024 Raytree RMH680 Skid Steer Breaker (Unused)
5135	2024 Jisan JSB400SL Skid Steer Breaker (Unused) S/N: 2404284 Usage: Not Available Asset located in: Humble, TX		S/N: HH20240825145 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5136	Teran THH400B-SSL Skid Steer Breaker - Fits		Asset located in: Humble, TX
	Cat 226 (Unused) S/N: CAA00167C52HRL C/W: For Skid Steer Loader Cat 226-299 With Mounting Plate included -68mm Tool With Auto - Lubrication Pre-Disposition - All New	5143	Mini Skid Steer Breaker (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
Teran Hydraulic H Chisels Moil Point N2 Nitrogen Charg Pressure Gauge, 1 with Maintenance Manual	Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations	5144	Connect Work Tools CH70 Skid Steer Breaker (Unused) S/N: CH7022F1180 C/W: backhoe hydraulic breaker Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5145	Mini Skid Steer Breaker (Unused)
5137	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202408553		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	5146	Miva Mini Skid Steer Breaker (Unused)
5138	Asset located in: Humble, TX	_	S/N: 03287 Usage: Not Available Asset located in: Humble, TX
S/N: SB30YOM2 C/W: 2 moil poin Usage: Not Avail	S/N: SB30YOM20247061 C/W: 2 moil point, tool box Usage: Not Available Asset located in : Humble, TX	5147	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00006 Usage: Not Available
5139	2024 AGT SSHH680 Skid Steer Breaker		Asset located in: Humble, TX
	(Unused) S/N: SSHH68024080501B C/W: 2 moil point, tool box Usage: Not Available Asset located in : Humble, TX	5148	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00005 Usage: Not Available Asset located in: Humble, TX
5140	2024 AGT SSHH680 Skid Steer Breaker (Unused) S/N: SSHH68024080502B C/W: 2 moil point, tool box Usage: Not Available Asset located in: Humble, TX	5149	2024 Jisan JSB400SLT Skid Steer Post Driver (Unused) S/N: 2406151 Usage: Not Available Asset located in: Humble, TX
		5150	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408120 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5151	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408119 Usage: Not Available Asset located in: Humble, TX	5158	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20240825137 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/
5152	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408121 Usage: Not Available Asset located in: Humble, TX		N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5153	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408122 Usage: Not Available Asset located in: Humble, TX	5159	Asset located in: Humble, TX 2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20240825138 2004 7.0" Demond Our Inside Discustor (0)
5154	2024 AGT PD680-PZ Skid Steer Post Driver (Unused) S/N: PD680-PZ24080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	-	C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5155	Asset located in: Humble, TX 2024 AGT PD680-PZ Skid Steer Post Driver (Unused) S/N: PD680-PZ24080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine PD-12-08D Skid Steer Post	5160	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20240825139 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5161	Asset located in: Humble, TX 2024 Handy HST72 72 in Skid Steer Tiller (Unused) S/N: ST202408102 Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX 5157 2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	5162	2024 Handy HST72 72 in Skid Steer Tiller (Unused) S/N: ST202408103 Usage: Not Available Asset located in: Humble, TX
	5163	2024 Handy HST72 72 in Skid Steer Tiller (Unused) S/N: ST202408101 Usage: Not Available Asset located in: Humble, TX	
		5164	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04413 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5165	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04405	5174	2024 Wolverine SG-13-08D 25 in Skid Steer Stump Grinder (Unused) S/N: ZW00737
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5166	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04404 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5175	2024 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5167	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04406 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5176	2024 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5168	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5177	2024 Raytree RMSG29 29 in Skid Steer Stump Grinder (Unused) S/N: SG20240825266 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5169	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5170	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5178	Grinder (Unused) S/N: SG20240825267 C/W: THE PRODUCT IMAGES SHOWN ARE
5171	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
5172		5179	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408899 Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	5180	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408900
5173	2024 Raytree RTSG30 30 in Transverse Skid Steer Stump Grinder (Unused)		Usage: Not Available Asset located in: Humble, TX
	Siteer Stump Grinder (Unused) S/N: TS20240825206 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5181	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408901 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5182	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408902 Usage: Not Available Asset located in: Humble, TX 2024 Handy HSSG27 27 in Skid Steer Stump	5190	Quantity of (2) 2024 Landhonor DGB-14-84D Skid Steer Backhoe (Unused) S/N: HL00467/HL00468 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
0100	Grinder (Unused) S/N: SG202408897 Usage: Not Available	5101	Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5191	2024 Suihe SSBH Skid Steer Backhoe (Unused) S/N: 202201879
5184	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408898 Usage: Not Available Asset located in: Humble, TX		C/W: 14 in Bucket THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5185	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408903 Usage: Not Available Asset located in: Humble, TX	5192	2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5186	186 2024 Top Cat ECSSSTG200 Skid Steer Stump Grinder (Unused) S/N: ECSSSTG20024080501B C/W: 3/4 in x 24 in Cutting Wheel		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5193	2024 Suihe SSBG 72 in Skid Steer Landplane (Unused)
5187	2023 Top Cat ECSSSTG200 26 in Skid Steer Stump Grinder (Unused) S/N: ECSSSTG20023121801C Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5188	2024 AGT SSBKH Skid Steer Backhoe (Unused)	- 	Asset located in: Humble, TX
	S/N: SSBKH24080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5194	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5189	Usage: Not Available Asset located in: Humble, TX 2024 AGT SSBKH Skid Steer Backhoe (Unused)	5195	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available
5105	S/N: SSBKH24080602A		Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5196	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	5197	72 in Skid Steer Landplane (Unused) S/N: Not Available
5190A	Bobcat 709 Skid Steer Backhoe S/N: 270008310 C/W: 16 in. bucket		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5198	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		5199	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5200 5201	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 42 in Mini Skid Steer Landplane (Unused)	5209	2024 Landhonor CC-11-08V Skid Steer Concrete Crusher (Unused) S/N: HL00003 Usage: Not Available Asset located in: Humble, TX
5201	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5210	2024 Mower King SSCM53 53 in Skid Steer Concrete Mixer (Unused) S/N: SSCM5324080601A
5202	2024 Handy HBC72 Skid Steer Concrete Crusher (Unused) S/N: CC202408138 Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5203 5204	2024 Handy HBC72 Skid Steer Concrete Crusher (Unused) S/N: CC202408137 Usage: Not Available Asset located in: Humble, TX 2024 Handy HBC72 Skid Steer Concrete	5211	2024 Mower King SSCM53 53 in Skid Steer Concrete Mixer (Unused) S/N: SSCM5324080501A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Crusher (Unused) S/N: CC202408136		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5212	2024 AGT SSCM61S 48 in Skid Steer Concrete
5205	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20240825143 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Mixer (Unused) S/N: SSCM61S24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5213	2024 AGT SSCM61S 48 in Skid Steer Concrete Mixer (Unused)
5206	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20240825141 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: SSCM61S24080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5214	2024 Suihe SSM 50 in Skid Steer Concrete
5207	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20240825142 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5215	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused)
5208	2024 Landhonor CC-11-08V Skid Steer Concrete Crusher (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5216	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5227	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5217	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5228	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5218	2024 AGT SSCM61S 48 in Skid Steer Concrete Mixer (Unused) S/N: SSCM61S24042001C Usage: Not Available Asset located in: Humble, TX	5229	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5219	Wolverine 48 in Skid Steer Concrete Mixer S/N: Not Available Usage: Not Available Asset located in: Humble, TX	_5230	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSR-78 78 in Skid Steer Root Rake
5222	2024 Wolverine CCT-11-148V Concrete Placement Skid Steer Bucket (Unused) S/N: ZW00323 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5223	All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	_5231 5232	All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 78 in Skid Steer Root Rake (Unused)
5224	Asset located in: Humble, TX All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5233	S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available
5225	All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5234	Asset located in: Humble, TX All-Star 74 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available
5226	All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5235	Asset located in: Humble, TX All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5236	All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5249	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5237	All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5250	All-Star 72 In Skeleton Skid Steer Grapple (Unused) S/N: Not Available
5238	All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5251	All-Star 72 in Skeleton Skid Steer Grapple (Unused)
5239	All-Star 68 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5252	2024 Suihe SSRGB-72 72 in Skeleton Skid Steer Grapple (Unused)
5240	All-Star 68 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: 001402236 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5241	All-Star 68 in Skid Steer Root Rake (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5253	All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available
5242	All-Star 68 in Heavy Duty Skid Steer Root Rake (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5254	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5243	Mid-State 60 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	5255	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX		All-Star 68 in Skeleton Skid Steer Bucket
5244	Mid-State 48 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		(Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5245	Mid-State 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5256	All-Star 68 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5246	84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5257	All-Star 68 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available
5247	84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	5258	Usage: Not Available Asset located in: Humble, TX All-Star 72 in Heavy Duty Rock Skid Steer Grapple (Unused)
5248	Asset located in: Humble, TX 2024 Kit Containers QT-RR-70 70 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5259 5260	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 68 in Rock Skid Steer Grapple (Unused)	5272	All-Star 68 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5200	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5273	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5261	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5274	Asset located in: Humble, TX All-Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5262	All-Star 68 in Heavy Duty Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5275	Asset located in: Humble, TX All-Star 68 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5263	All-Star 68 in Heavy Duty Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5276	Asset located in: Humble, TX All-Star 60 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5264	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5277	2024 Kit Containers MSS-SG-S48 48 in Skeleton Mini Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5265	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5278	Kit Containers 48 in Skeleton Mini Skid Steer Grapple Bucket (Unused) S/N: Not Available
5266	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5279	Usage: Not Available Asset located in: Humble, TX All-Star 48 in Root Skid Steer Grapple (Unused)
5267	Asset located in: Humble, TX All-Star 74 in Heavy Duty Root Skid Steer Grapple (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5280	All-Star 48 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5268	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5281	Asset located in: Humble, TX All-Star 48 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5269	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5282	Asset located in: Humble, TX All-Star 48 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5270	All-Star 72 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5283	Asset located in: Humble, TX 42 in Skeleton Mini Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5271	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5284	36 in Skeleton Mini Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5293	All-Star 68 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
5286	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: 006600596 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5294 5295	All-Star 68 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Wolverine MSG-11-44W 44 in Mini Skid	
	Usage: Not Available Asset located in: Humble, TX		Steer Grapple Bucket (Unused) S/N: ZW00904	
5287	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5296	2024 Wolverine MSG-11-44W 44 in Mini Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00901	
5288	Raptor 76 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
5289	All-Star 72 in Heavy Duty Skid Steer Grapple	5297	2024 Wolverine MSG-11-44W 44 in Mini Skid	
5290	Bucket (Unused)S/N: Not AvailableUsage: Not AvailableAsset located in: Humble, TX2024 Wolverine GB-11-72W 72 in Skid Steer	-	Steer Grapple Bucket (Unused) S/N: ZW00907 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	Grapple Bucket (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5298	5298 2024 Wolverine MSG-11-44W 44 in Mini Ski Steer Grapple Bucket (Unused) S/N: ZW00902 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	2024 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00902
5291	2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: ZW04239		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5299	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	5300	2024 Wolverine FGP-11-3500G 48 in Grapple	
5292	All-Star 68 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Skid Steer Forks (Unused) S/N: ZW00350 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5301	74 in Skid Steer Grapple Bucket S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5310	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408355 C/W: 10 in., 12 in. & 18 in. bits Usage: Not Available
5302	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5311	Asset located in: Humble, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408353 C/W: 10 in, 12 in & 18 in Bits
5303	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5313	Usage: Not Available Asset located in: Humble, TX 2024 Handy SSA18 Skid Steer Auger (Unused)
	Asset located in: Humble, TX		S/N: SSA2408356 C/W: 10 in, 12 in & 18 in Bits
5304	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5014	Usage: Not Available Asset located in: Humble, TX
5305	Asset located in: Humble, TX 2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20240825173	5314	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408354 C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in: Humble, TX
C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF 1 ACTUAL PRODUCT	C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE	5315	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408357 C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5316	
5306	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20240825174 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	_5310	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408358 C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in: Humble, TX
		 5317 2024 Mower King SSECAG-Y S (Unused) S/N: SSECAG-Y24080501B C/W: (1) 6 in, (1)12 in, (1)14 in PRODUCT IMAGES SHOWN AF ILLUSTRATION PURPOSES ON NOT BE AN EXACT REPRESEN ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 5318 2024 Mower King SSECAG-Y S (Unused) S/N: SSECAG-Y24080502B C/W: (1) 6 in, (1)12 in, (1)14 in PRODUCT IMAGES SHOWN AF ILLUSTRATION PURPOSES ON NOT BE AN EXACT REPRESEN ACTUAL PRODUCT USAGE: NOT AVAILABLE 	2024 Mower King SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080501B C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5307	2024 Raytree RMA42 Skid Steer Auger (Unused)S/N: A20240825175 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX53		
			S/N: SSECAG-Y24080502B C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR
5308	Mini Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 8 in., (1) 12 in. & (1) 16 in. bits Usage: Not Available		NOT BE AN EXACT REPRESENTATION ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX	5010	Asset located in: Humble, TX
5309	Mini Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 8 in., (1) 12 in, & (1)16 in. bits Usage: Not Available Asset located in: Humble, TX	_5319	2024 AGT SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080503B C/W: (1) 6 in, (1) 12 in, (1) 14 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5320	2024 AGT SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080504B C/W: (1) 6 in, (1) 12 in, (1) 14 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5326	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5321	2024 Suihe SSA Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5327	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: ZW08554/ZW08566 C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5322 5323	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503372 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSA Skid Steer Auger (Unused)	5328	Asset located in: Humble, TX 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5324	S/N: 002503382 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX 2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503384	5329	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5325	C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: ZW08552/ZW08564 C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5330	Asset located in: Humble, TX 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE EOD II LUSTRATION PURPOSES ONLY AND
	Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5332	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine MAD-12-12D Mini Skid Steer	5339	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20240825306 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine SB-12-72W 72 in Screening Skid Steer Bucket (Unused)
	Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: ZW00665 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
5334	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: ZW01305 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	5341	2024 Wolverine SB-12-72W 72 in Screening Skid Steer Bucket (Unused) S/N: ZW00673 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMVB78 70 in Skid Steer Bucket
5335	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		(Unused) S/N: SB20240825303 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5336	Asset located in: Humble, TX 2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: ZW01303 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5343	2024 Raytree RMVB78 70 in Skid Steer Bucket (Unused) S/N: SB20240825304 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5337	Skid Steer Auger S/N: Not Available Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	5344	2024 Raytree RMVB78 70 in (Unused) S/N: SB20240825305 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5338	2024 Landhonor RB-14-78W 78 in Rock Skid Steer Bucket (Unused) S/N: HL00223 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Ulsage: Not Available	5345	Asset located in: Humble, TX 2024 Handy HVSB72 64 in Screening Skid Steer Bucket (Unused) S/N: VSB202408671 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5346	2024 Handy HVSB72 64 in Screening Skid Steer Bucket (Unused) S/N: VSB202408672 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5347	5347 2024 Landhonor RB-14-84W 84 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5357	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		5358	All-Star 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5348	Mid-State 84 in Rock Skid Steer Bucket	1	Asset located in: Humble, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5359	2024 Kit Containers QT-SB-L72 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5349	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5360	Asset located in: Humble, TX 2024 Kit Containers QT-SB-H72-F 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available
5350	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5361	All-Star 72 in Skeleton Skid Steer Bucket (Unused)
5351	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5362	All-Star 72 in Skeleton Skid Steer Bucket (Unused)
5352	2024 Kit Containers QT-SB-H76-V3 76 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5353	Asset located in: Humble, TX	5363	All-Star 68 in Rock Skid Steer Bucket (Unused) S/N: Not Available
5555	2024 Kit Containers QT-SB-L76-V3 76 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5364	All-Star 68 in Skeleton Skid Steer Bucket (Unused)
5354	2024 Landhonor RB-14-72W 72 in Rock Skid Steer Bucket (Unused)		S/N: Not Available Usage: Not Available
	S/N: HL00223 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5365	Asset located in: Humble, TX All-Star 68 in Rock Skid Steer Bucket (Unused) S/N: Not Available
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5366	All-Star 68 in Skeleton Skid Steer Bucket
5355	All-Star 72 In Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	1	(Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	5367	2024 Top Cat 4IN1BCT 72 in Multi-Purpose
5356	All-Star 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	S/N: 4IN1BCT24080601A C/W: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOS MAY NOT BE AN EXACT REP THE ACTUAL PRODUCT Usage: Not Available	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT

Lot #	Details	Lot #	Details
5368	Skid Steer Bucket (Unused) S/N: 4IN1BCT24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5375	2024 Kit Containers QT-SNB-84 84 in Snow /Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5376	2024 Kit Containers QT-SNB-84 84 in Snow /Litter Skid Steer Bucket (Unused) S/N: Not Available
5369	2024 Suihe SSB-4 72 in Multi-Purpose Skid		Usage: Not Available
	Steer Bucket (Unused)	5077	Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5377	Mid-State 84 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5378	Mid-State 78 in Snow/Litter Skid Steer Bucket
5370	2024 Suihe SSB-4 72 in Multi-Purpose Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		(Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
THE ACTUAL PRODUCT Usage: Not Available	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5379	Mid-State 84 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5371	2024 Wolverine MCB-11-48W 48 in Multi-		Asset located in: Humble, TX
	Purpose Mini Skid Steer Bucket (Unused) S/N: ZW01067 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5380 5381	Mid-State 78 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 74 in Snow/Litter Skid Steer Bucket (Unused)
	Asset located in: Humble, TX	_	S/N: Not Available
5372	2024 Wolverine MCB-11-48W 48 in Multi- Purpose Mini Skid Steer Bucket (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: ZW01017 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5382	All-Star 74 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5383	Mid-State 72 in Snow/Litter Skid Steer Bucket
5373	5373 2024 Wolverine MCB-11-48W 48 in Multi- Purpose Skid Steer Bucket (Unused) S/N: ZW01073 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		5384	Mid-State 72 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5374	2024 Wolverine MCB-11-48W 48 in Multi-		Asset located in: Humble, TX
	Purpose Skid Steer Bucket (Unused) S/N: ZW01061 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5385	All-Star 68 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5386	Mid-State 84 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX	5397	Mid-State 68 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
5387	All-Star 80 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX	5398	All-Star 68 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
5388	All-Star 80 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX Teran BKT26278 78 in Skid Steer Bucket - Fits	5399	2024 Landhonor RB-14-66W 66 in Rock Skid Steer Bucket (Unused) S/N: HL00220 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5389	Cat 226 (Unused) S/N: 4160 C/W: 0.5m3 with 8HD Tips for CAT 226 - 299		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers QT-DB-S66 66 in Skid
	Usage: Not Available Asset located in: Humble, TX	5400	S/N: Not Available
5390	2024 Kit Containers QT-DB-T78 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth		C/W: teeth Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5401	Mid-State 60 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
5391	All-Star 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth		
	Usage: Not Available Asset located in: Humble, TX	5402	Teran BKT26260 60 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: Not Available
5392	All-Star 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth		C/W: 0.35m3 with 7 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5403	2024 Wolverine TDB-11-84W 84 in Skid Steer
5393	Mid-State 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX		Bucket (Unused) S/N: ZW00607 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION (THE ACTUAL PRODUCT
5394	All-Star 74 in Skid Steer Bucket (Unused) S/N: Not Available		Usage: Not Available Asset located in : Humble, TX
	C/W: teeth Usage: Not Available Asset located in: Humble, TX	5404	2024 Wolverine TDB-11-84W 84 in Skid Steer Bucket (Unused) S/N: ZW00610
5395	All-Star 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5396	Teran BKT26272 72 in Skid Steer Bucket - Fits	5405	Asset located in: Humble, TX
	Cat 226 (Unused) S/N: 0374 C/W: 0.45m3 with 8 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Humble, TX	5405	Cat 74 in Skid Steer Bucket (Unused) S/N: A4229BK20432 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5406	Mid-State 80 in Skid Steer Bucket (Unused)	5417	All-Star 72 in Skid Steer Bucket (Unused)
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5407	2024 Kit Containers QT-DB-S78 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5418	2024 Wolverine TDB-11-72W 72 in Skid Steer Bucket (Unused) S/N: ZW00628 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5408	Mid-State 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5419	2024 Wolverine TDB-11-72W 72 in Skid Steer
5409	2024 Wolverine TDB-11-78W 78 in Skid Steer Bucket (Unused) S/N: ZW00624 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Bucket (Unused) S/N: ZW00623 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5410	Asset located in: Humble, TX 2024 Wolverine TDB-11-78W 78 in Skid Steer	5420	Mid-State 68 in Skid Steer Bucket (Unused)
5410	Bucket (Unused)		S/N: Not Available Usage: Not Available
	S/N: ZW00628		Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5421	Mid-State 68 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5422	2024 Kit Containers QT-DB-T66 66 in Skid
5411	All-Star 78 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5412	All-Star 74 in Skid Steer Bucket (Unused)	5423	2024 Wolverine TDB-11-66W 66 in Skid Steer
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Bucket (Unused) S/N: ZW00611 C/W: THE PRODUCT IMAGES SHOWN ARE
5413	74 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5414	All-Star 72 in Skid Steer Bucket (Unused)	5424	2024 Wolverine TDB-11-66W 66 in Skid Steer
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Bucket (Unused) S/N: ZW00607 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5415	Mid-State 72 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5416	Mid-State 72 in Skid Steer Bucket (Unused)	5425	
5410	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	0420	All-Star 60 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5426	Mid-State 60 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5441	68 in Skid Steer Bucket S/N: Not Available Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE
5430	80 in Snow/Litter Skid Steer Bucket S/N: Not Available		THE INSPECTION REPORT Asset located in: Humble, TX
<u> </u>	Usage: Not Available Asset located in: Humble, TX	5442	66 in Skid Steer Bucket S/N: Not Available Usage: Not Available
5431	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available	5443	Asset located in: Humble, TX 67 in Skid Steer Bucket
	Asset located in: Humble, TX		S/N: Not Available C/W: teeth
5432	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
E 400	Asset located in: Humble, TX	5444	Quantity of (3) Skid Steer Bucket S/N: Not Available
5433	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available		C/W: (1) 67 in., (1) 74 in. & (1) 80 in. Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
5434	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available	- 5445	Quantity of (3) Skid Steer Bucket S/N: Not Available C/W: (2) 67 in. & (1) 80 in. Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5435	74 in Skid Steer Bucket S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	5448	2024 Kit Containers QT-TS-40 Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5436	Bobcat 72 in Skid Steer Bucket S/N: 6732305 C/W: teeth Usage: Not Available	- 5449	Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Skid Steer Tree Spade (Unused)
5437	Asset located in: Humble, TX Cat 74 in Skid Steer Bucket S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5451	All-Star Stump Skid Steer Bucket (Unused)
5438	68 in Skid Steer Bucket S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	5452	All-Star Stump Skid Steer Bucket (Unused)
5439	68 in Skid Steer Bucket S/N: Not Available	-	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	5453	All-Star Stump Skid Steer Bucket (Unused)
5440	Asset located in: Humble, TX 68 in Skid Steer Bucket		S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5454	Asset located in: Humble, TX All-Star Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5455	2024 Kit Containers QT-RD Skid Steer Root Digger (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5464	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused) S/N: LS20240825010 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5456	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408255		
	Usage: Not Available	5465	2024 Landhonor HAG-12-24Q 88 in Skid Steer
	Asset located in: Humble, TX		Bale Accumulator Grapple (Unused)
5457	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408256 Usage: Not Available Asset located in: Humble, TX		S/N: HL00674 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5458	2024 Handy HLS35 Skid Steer Log Splitter		Asset located in: Humble, TX
	(Unused) S/N: LS202408258 Usage: Not Available Asset located in : Humble, TX	5466	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused) S/N: HL00675 C/W: THE PRODUCT IMAGES SHOWN ARE
5459	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408257 Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5460		5467	2024 Landhonor RG-11-5000G Skid Steer
5461	2024 Handy HFB52 52 in Skid Steer Feller Buncher (Unused) S/N: FB202408112 Usage: Not Available Asset located in: Humble, TX 2024 Handy HSRP72 72 in Skid Steer Rock		Rotating Tree Clamp (Unused) S/N: HL00308 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Picker (Unused)		Asset located in: Humble, TX
	S/N: RP202408461 Usage: Not Available Asset located in : Humble, TX	5468 2024 Raytree RMLS18T 18 ton Skid Splitter (Unused) S/N: LS20240825009 C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ON MAY NOT BE AN EXACT REPRESENTHE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused)
5462	2024 AGT STSD10 Skid Steer Seeder (Unused) S/N: STSD1024080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Usage: Not Available		2024 Raytree RMLS18T 18 ton Skid Steer Log
5463	Asset located in: Humble, TX 2024 AGT STSD10 Skid Steer Seeder (Unused) S/N: STSD1024080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Splitter (Unused) S/N: LS20240825011 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		5470	2024 Wolverine BSH-12-75D Skid Steer Bale
			Squeeze (Unused) S/N: ZW00365 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5471	Erskine CM18 18 in Skid Steer Planer S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5482	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00121 Usage: Not Available Asset located in: Humble, TX
5472	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00005 Usage: Not Available Asset located in: Humble, TX	5483	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5473	2024 Landhonor DPC-21-13W Skid Steer Pole Clamp (Unused) S/N: HL00003 Usage: Not Available Asset located in: Humble, TX	5484	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5474	2024 Top Cat ECSSRB Skid Steer Tree Shear (Unused) S/N: ECSSRB24080501B	_5485	All-Star Skid Steer Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5486	All-Star Skid Steer Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5475	2024 Handy HSRC12 12 in Rotating Skid Steer Pole Clamp (Unused) S/N: RC202408621 Usage: Not Available	_5487	2024 Industrias America Skid Steer Post Puller (Unused) S/N: HPOST202421214 Usage: Not Available Asset located in: Humble, TX
5476	Asset located in: Humble, TX 2024 Handy HRTH43 43 in Skid Steer Rock Handler (Unused) S/N: RTH202408489 Usage: Not Available	_5488	2024 Industrias America Skid Steer Post Puller (Unused) S/N: POST202421192 Usage: Not Available Asset located in: Humble, TX
5477	Asset located in: Humble, TX 2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00006 Usage: Not Available Asset located in: Humble, TX	5489	2024 Industrias America Skid Steer Post Puller (Unused) S/N: HPOST202421209 Usage: Not Available Asset located in: Humble, TX
5478	2024 Landhonor FW-13-15000G 15000 Lb Skid Steer Winch (Unused) S/N: Not Available Usage: Not Available	_5490	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5479	Asset located in: Humble, TX 2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00124 Usage: Not Available	_5491	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5480	Asset located in: Humble, TX 2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL0122 Usage: Not Available	5492	All-Star Tree Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star Tree Skid Steer Boom (Unused)
5481	Asset located in: Humble, TX 2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00123 Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5494 5495	2024 Landhonor HRB-11-127A 42 in Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00005 Usage: Not Available Asset located in: Humble, TX 2024 Landhonor HRB-11-127A 42 in Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00006	5503	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04749 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5504	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused)
5496	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408272 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX		S/N: ZW04809 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
5497	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408276 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	5505	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04816 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT
5498	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408273		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5499	C/W: Fork Positioner Usage: Not Available Asset located in : Humble, TX	5506	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04813 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	C/W: Fork Positioner Usage: Not Available Asset located in : Humble, TX	5507	Usage: Not Available Asset located in: Humble, TX
5500	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408275 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	-5507	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04821 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5501	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408277	5508	Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused)
	C/W: Fork Positioner Usage: Not Available Asset located in : Humble, TX	-	S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX
Forks (Unused) S/N: Not Available C/W: Fork Positioner, [¬] SHOWN ARE FOR ILLU ONLY AND MAY NOT I		5509	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5510	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5511	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	5520	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5512	Quantity of (10) 2024 Mower King SA 48 in Skid Steer Forks (Unused) S/N: SA24080601A-04A/SA24080401B-06B Usage: Not Available	5521	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused)
5513	Asset located in: Humble, TX 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused)	5522	S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: HL00930 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5523	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5514	Asset located in: Humble, TX 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused)	5524	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: HL00931 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5525	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5526	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available
5515	2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: HL00932 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5527	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5516	Usage: Not Available Asset located in: Humble, TX 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused)	5528	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
S/N: HL00929 C/W: THE PRO FOR ILLUSTRA MAY NOT BE A THE ACTUAL P	S/N: HL00929 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5529	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5517	Asset located in: Humble, TX JBX 4000 48 in Skid Steer Forks (Unused)	5530	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	•	Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available
5518	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5532	2024 Kit Containers MSS-45-FF-42 42 in Mini Skid Steer Forks (Unused)
5519	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5533	2024 Kit Containers MSS-45-FF-42 42 in Mini Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	5545	All-Star 60 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	5546	2024 Wolverine MPF-11-2500G 30 in Mini Skid
5534 5535	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused)	-	Steer Forks (Unused) S/N: ZW01074 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	5547	2024 Wolverine MPF-11-2500G 30 in Mini Skid Steer Forks (Unused)
	Asset located in: Humble, TX	4	S/N: ZW01078
5536	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5537	2024 Kit Containers QT-45-FF-42 42 in Skid	5548	2024 Wolverine MPF-11-2500G 30 in Mini Skid
	Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Steer Forks (Unused) S/N: ZW01075 C/W: THE PRODUCT IMAGES SHOWN ARE
5538	2024 Kit Containers QT-45-FF-42 42 in Skid	-	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5556	Steer Forks (Unused)		THE ACTUAL PRODUCT Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5549	2024 Wolverine MPF-11-2500G 30 in Mini Skid
5539	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers QT-45-FF-42 42 in Skid	-	Steer Forks (Unused) S/N: ZW01076 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5540	Steer Forks (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5550	2024 Wolverine MPF-11-2500G 30 in Mini Skid Steer Forks (Unused) S/N: ZW01077 C/W: THE PRODUCT IMAGES SHOWN ARE
5541	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5542	2024 Kit Containers QT-45-FF-42 42 in Skid	5551	Bradco 60 in Skid Steer Forks
	Steer Forks (Unused)		S/N: 458961 Usage: Not Available
	S/N: Not Available Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5552	All-Star 48 in Skid Steer Forks (Unused)
5544	2024 Trojan SPF15 48 in Skid Steer Forks (Unused) S/N: 124435		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5553	36 in Mini Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5554	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5567	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01291 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5555	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		
5556	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star Skid Steer Fork Frame (Unused)	5568	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01284 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5558	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5569	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01285 C/W: THE PRODUCT IMAGES SHOWN ARE
5559	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5560	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5570	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01292 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5561	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		
5562	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5571	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5563	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5572	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5564	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5573	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5565	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5574	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5566		5575	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5576	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5577	Armstrong 42 in Skid Steer Bale Spear	5586	All-Star 2 in Skid Steer Receiver Hitch (Unused)
	S/N: Not Available		S/N: Not Available
	Usage: Not Available Asset located in : Humble, TX		Usage: Not Available
		6507	Asset located in: Humble, TX
5578	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: HL01146	5587	All-Star 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available
			Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE		Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5588	2024 Landhonor PHA-16-2C Skid Steer 3-Point
	THE ACTUAL PRODUCT		Adapter (Unused)
	Usage: Not Available		S/N: HL00673
	Asset located in: Humble, TX	_	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5579	2024 Landhonor UHA-16-3000G 2 in Skid Steer		MAY NOT BE AN EXACT REPRESENTATION OF
	Hitch Receiver (Unused)		THE ACTUAL PRODUCT Usage: Not Available
	S/N: HL01145 C/W: THE PRODUCT IMAGES SHOWN ARE		Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND	5589	2024 Landhonor PHA-16-2C Skid Steer 3-Point
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Adapter (Unused)
	Usage: Not Available		S/N: HL00674
	Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5580	2024 Landhonor UHA-16-3000G 2 in Skid Steer		MAY NOT BE AN EXACT REPRESENTATION OF
	Hitch Receiver (Unused)		
	S/N: HL01148 C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND	5590	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5590	2024 Kit Containers 2YFT-SST 2 cu yd Skid Steer Dump Hopper (Unused)
			S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
5581	2024 Landhonor UHA-16-3000G 2 in Skid Steer		Asset located in: Humble, TX
	Hitch Receiver (Unused)	5591	2024 Kit Containers 2YFT-SST 2 cu yd Skid
	S/N: HL01147 C/W: THE PRODUCT IMAGES SHOWN ARE		Steer Dump Hopper (Unused) S/N: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND		Usage: Not Available
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Asset located in: Humble, TX
	Usage: Not Available	5592	Quantity of (10) Kit Containers QT-F-BLANK
	Asset located in: Humble, TX		Skid Steer Attachment Mounting Plate
5582	2024 Kit Containers QT-TM 2 in Skid Steer		(Unused)
	Receiver Hitch (Unused)		S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5593	Quantity of (4) 2024 Landhonor UAP-16-45W
5583	2024 Kit Containers QT-TM 2 in Skid Steer		Skid Steer Attachment Mounting Plate
0000	Receiver Hitch (Unused)		(Unused)
	S/N: Not Available		S/N: Not Available
	Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5504	
5584	All-Star 2 in Skid Steer Receiver Hitch (Unused)	5594	Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate
	S/N: Not Available Usage: Not Available		(Unused)
	Asset located in: Humble, TX		S/N: Not Available
5585	All-Star 2 in Skid Steer Receiver Hitch (Unused)	-	Usage: Not Available
0000	S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available		

Lot #	Details	Lot #	Details
5595	Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available	5606	2024 Jisan JXJMQC320 41 in Excavator Grapple - Fits Cat 320 (Unused) S/N: 2406220167 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5607	2024 KJ AMSR60 Excavator Grapple - Fits Cat
5596	Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		307 / 5 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5597	Quantity of (5) All-Star Skid Steer Attachment		Asset located in: Humble, TX
	Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5608	2024 KJ AMSR60 Excavator Grapple - Fits Cat 307 / 5 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5598	Quantity of (4) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5609	Teran THH3500 Hydraulic Breaker - Fits Cat
5599	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		345 (Unused) S/N: Not Available C/W: For CAT 345/349EL/352FL "TB" Linka All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2
5600	Quantity of (4) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available		Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual. Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5601	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5610	2024 JESON HM3300 Hydraulic Breaker (Unused) S/N: JQHM010 Usage: Not Available Asset located in: Humble, TX
5602	Quantity of (5) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5611	2024 Jisan JSB3200B Hydraulic Breaker - Fits Cat 330/336 (Unused) S/N: 2407191 Usage: Not Available Asset located in: Humble, TX
5603	2024 Jisan JSV765S Rotating Demolition Pulverizer - Fits Cat 320/325 (Unused) S/N: 24042901023 Usage: Not Available Asset located in: Humble, TX	5612	2024 JESON HM3200 Hydraulic Breaker (Unused) S/N: JQHM011 Usage: Not Available Asset located in: Humble, TX
5604	2024 Elephant JXJMQC345 51 in Excavator Grapple - Fits Cat 345 (Unused) S/N: 24062200311 Usage: Not Available	5613	2024 JESON HM3150 Hydraulic Breaker (Unused) S/N: JQHM006 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	E614	
5605	2024 Elephant JXJMQC336 46 in Excavator Grapple - Fits Cat 336 (Unused) S/N: 2406220038 Usage: Not Available Asset located in: Humble, TX	5614	2024 JQ POWER JQB3000STB Hydraulic Breaker - Fits Cat 320/325 (Unused) S/N: 814055724 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5615	Cat 320 (Unused) S/N: CEH637D14HZ C/W: For all 18-25 Ton 332mm FS - With Auto- Lubrication Pre-Disposition Box Type Cat 320 B Linkage, Komatsu PC200/220 (80mm 12.90 in (330 mm) Face Spread 18.00 in (450 mm) Front pin to back)- All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil	5623	2024 KJ AMB100 Hydraulic Breaker - Fits Cat 312 / 11 - 16 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5616	Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual. Usage: Not Available Asset located in: Humble, TX 2024 Jisan JSB2200B Hydraulic Breaker - Fits Cat 320/325 (Unused)	5624	2024 KJ AMB68 Hydraulic Breaker - Fits Cat 304 / 4 - 7 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	S/N: CP2404394 Usage: Not Available Asset located in : Humble, TX	5625	Asset located in: Humble, TX 2024 KJ AMB68 Hydraulic Breaker - Fits Cat
5617	2024 Jisan JSB2200T Hydraulic Breaker - Fits Cat 320/325 (Unused) S/N: 2406134 Usage: Not Available Asset located in: Humble, TX		304 / 4 - 7 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available
5618	2024 Elephant EPB2200B Hydraulic Breaker - Fits Cat 320/325 (Unused)		Asset located in: Humble, TX
5619	S/N: CP2407162 Usage: Not Available Asset located in: Humble, TX 2024 Elephant EPB2200T Hydraulic Breaker - Fits Cat 320/325 (Unused)	5626	2024 KJ AMB68 Hydraulic Breaker - Fits Cat 304 / 4 - 7 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	S/N: CP2406052 Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
5620	315 (Unused) S/N: CAM205D14HZ C/W: For Cat 315 - 125mm Tool - and all 15	5627	2024 Elephant EPB800T Hydraulic Breaker - Fits Cat 311/312/314 (Unused) S/N: CP2406100 Usage: Not Available Asset located in: Humble, TX
Ton Excavators - Box Type - With Auto - Lubrication Pre-Disposition. Box Type - All New Teran Hydraulic Hammers are supplied with: 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual	Lubrication Pre-Disposition. Box Type - All New Teran Hydraulic Hammers are supplied with: 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With	5628	2024 JESON HM3070 Hydraulic Breaker (Unused) S/N: JQHM012 Usage: Not Available Asset located in: Humble, TX
5621	Asset located in: Humble, TX 2024 Jisan JSB800B Hydraulic Breaker - Fits Cat 311/312/314 (Unused) S/N: 2407217	5629	2024 Jisan JSB430B Hydraulic Breaker - Fits Cat 307/307B/308/308B (Unused) S/N: 2404466 Usage: Not Available Asset located in: Humble, TX
5622	Usage: Not Available Asset located in: Humble, TX 2024 KJ AMB100 Hydraulic Breaker - Fits Cat 312 / 11 - 16 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5630	2024 Jisan JSB400B Hydraulic Breaker - Fits Cat 304/305 (Unused) S/N: CP2404209 Usage: Not Available Asset located in: Humble, TX

	Details	Lot #	Details
5631	2024 Jisan JSB400B Hydraulic Breaker - Fits Cat 304/305 (Unused)	5641	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused)
	S/N: 2404208 Usage: Not Available		S/N: CH7022G1219/CH7022G1220 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5632	Teran THH400B-CAT308 Hydraulic Breaker - Fits Cat 307 (Unused) S/N: CAA0137B54HR C/W: For Mini Excavators CAT 307/308 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic	5642	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: 22G1227/22G1216 Usage: Not Available Asset located in: Humble, TX
	Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available	5643	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1226/CH7022G1225 Usage: Not Available Asset located in: Humble, TX
5633	Asset located in: Humble, TX 2024 Elephant EPB400T Hydraulic Breaker -	5644	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused)
0000	Fits Cat 304/305 (Unused) S/N: CP2406111 Usage: Not Available		S/N: 22G1217/22G1218 Usage: Not Available Asset located in : Humble, TX
5634	Asset located in: Humble, TX 2024 Elephant EPB400T Hydraulic Breaker -	5645	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused)
	Fits Cat 304/305 (Unused) S/N: CP2406110		S/N: CH7022G1229/CH7022G1230 Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX	5646	Asset located in: Humble, TX Quantity of (2) Connect Work Tools CH70-22G
5635	2024 Trojan TH50 Hydraulic Breaker (Unused) S/N: SB40Y0M20246078 C/W: 2 moil point, tool box Usage: Not Available		Hydraulic Breaker (Unused) S/N: 22G1228/22G1213 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5647	Quantity of (2) Connect Work Tools CH70-22G
5636	2024 Trojan Th35 Hydraulic Breaker (Unused) S/N: SB30YOM20246070 C/W: 2 moil point, tool box Usage: Not Available Asset located in: Humble, TX	5648	Hydraulic Breaker (Unused) S/N: CH7022G1224/CH7022G1211 Usage: Not Available Asset located in: Humble, TX Quantity of (2) Connect Work Tools CH70-22G
5637	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1222/CH7022G1209 Usage: Not Available		Hydraulic Breaker (Unused) S/N: CH7022G1214/CH7022G1215 Usage: Not Available Asset located in: Humble, TX
5638	Asset located in: Humble, TX Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1212/CH7022G1223 Usage: Not Available	_ 5649	Quantity of (2) Connect Work Tools CH70 Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5650	Quantity of (2) Connect Work Tools CH70
5639	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1207/CH7022G1210 Usage: Not Available		Hydraulic Breaker S/N: CH7021J1139/CH7021H1093 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5651	2023 FRD FX475QTV Hydraulic Breaker
5640	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1208/CH7022G1221 Usage: Not Available Asset located in: Humble, TX		S/N: FX4752383 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5652	2020 TOKU TNB-151 Hydraulic Breaker S/N: 151LU215383 Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	5663	2024 JESON BKT 345-66 66 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: JQ BKT 036 Usage: Not Available Asset located in: Humble, TX
5653	Cat H95 Backhoe Hydraulic Breaker S/N: D9H00414 Usage: Not Available Asset located in: Humble, TX	5664	2024 JESON BKT 345-66 66 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: JQ BKT 035 Usage: Not Available Asset located in: Humble, TX
5654	Kent KHB8G Hydraulic Breaker S/N: HB8G1864 Usage: Not Available Asset located in: Humble, TX	5665	2024 JESON BKT 336-66 66 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 026 Usage: Not Available
5655	Quantity of (2) Kota 350 Mini Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5666	Asset located in: Humble, TX 2024 Jisan BKT36066HD 66 in Digging Excavator Bucket - Fits Komatsu PC360
5656	Cat H120ES Hydraulic Breaker S/N: HHE01524 Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: 240622020118 Usage: Not Available Asset located in: Humble, TX
5657	Teran BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336D (Unused) S/N: 4279 C/W: DB Linkage - 2.00m3 for Cat 336D, 336D2, 336E, 336F, 340D2, 340F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips - DB Linkage Usage: Not Available	5668	Teran BKT34560HD 60 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: 1351 C/W: TB Linkage - 2.17m3 for CAT 345, 345D /349D, 349D2, 349E, 349F, 352F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 5RC Tips Usage: Not Available Asset located in: Humble, TX
5658	Asset located in: Humble, TX 2024 JESON BKT 336-72 72 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 032 Usage: Not Available	_5669	2024 JESON BKT 336-60 60 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 024 Usage: Not Available Asset located in: Humble, TX
5659 5660	Asset located in: Humble, TX 2024 Jisan BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: 24042900256 Usage: Not Available Asset located in: Humble, TX 2024 Jisan BKT34572HD 72 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: 24062202047	_5670	2024 KJ AM3660 60 in 1.5 cyd Digging Excavator Bucket - Fits Cat 336 / 30 - 38 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5661	Usage: Not Available Asset located in: Humble, TX 2024 Jisan BKT34572SKEL 72 in Skeleton	5671	2024 Elephant BKT336D60HD 60 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: 24072900124
	Excavator Bucket - Fits Cat 345 (Unused) S/N: 24062202089 Usage: Not Available Asset located in: Humble, TX	5672	Usage: Not Available Asset located in: Humble, TX 2024 Jisan BKT336D60HD 60 in Digging
5662	Asset located III: Humble, TX 2024 JESON BKT 336-66 66 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 027 Usage: Not Available Asset located in: Humble, TX		Excavator Bucket - Fits Cat 336 (Unused) S/N: 24042900236 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5673 5674	2024 JESON BKT 220-54 54 in Digging Excavator Bucket - Fits Komatsu PC220 (Unused) S/N: JQ BKT 019 Usage: Not Available Asset located in: Humble, TX 2024 KJ AM2054 54 in 1.3 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused)	5681	2024 KJ AM2048 48 in 1.2 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		2024 KJ AM2048 48 in 1.2 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5675	2024 KJ AM2054 54 in 1.3 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused)		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5683	2024 Elephant BKT32048HD 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 24051503624 Usage: Not Available Asset located in: Humble, TX
5676	Asset located in: Humble, TX 2024 Elephant BKT22054HD 54 in Digging Excavator Bucket - Fits Komatsu PC200/220 (Unused) S/N: 2405150371	_ 5684	2024 Jisan BKT32048HD 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 240429002158 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5685	2024 JESON BKT320-48 48 in Digging Excavator Bucket - Fits Cat 320 (Unused)
5677	2024 Jisan BKT32054HD 54 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 24042900210 Usage: Not Available	S/N: JQBKT012 Usage: Not Available Asset located in : Humble, TX	Usage: Not Available Asset located in: Humble, TX
5678	Asset located in: Humble, TX 2024 Jisan BKT22054HD 54 in Digging Excavator Bucket - Fits Komatsu PC220 (Unused)	5686	2024 JESON BKT 320-48 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: JQ BKT 011 Usage: Not Available Asset located in: Humble, TX
	S/N: 2405150378 Usage: Not Available Asset located in : Humble, TX	5692	Teran BKT30742 42 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 1207
5679	Teran BKT325D48HD 48 in Digging Excavator Bucket - Fits Cat 325D (Unused) S/N: 0263 C/W: CB Linkage - 1.07m3 for Cat 325D, 324D,	C/W: For Cat 307/308 0.41 Cutters, Reinforcement Pla Usage: Not Available Asset located in: Humble, 5693 Teran BKT31242 42 in Dig Bucket - Fits Cat 312 (Unus S/N: 0812 C/W: 312 Linkage - 0.67m3 311F, 312D, 312D2, 312E, 3 314D, 314E, 314F, 315F wir Reinforcement Plates and Usage: Not Available	C/W: For Cat 307/308 0.41m3 with Side Cutters, Reinforcement Plates and 7HD Tips
	324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 6RC Tips Usage: Not Available Asset located in : Humble, TX		C/W: 312 Linkage - 0.67m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F,
5680	2024 JESON BKT 320-48 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: JQ BKT 013 Usage: Not Available Asset located in: Humble, TX		Reinforcement Plates and 5HD Tips

Lot #	Details	Lot #	Details
5694	Teran BKT32039HD 39 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 2505 C/W: B Linkage - 0.68m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 5HD Tips Usage: Not Available	5701	Teran BKT305C12 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2922 C/W: 0.08m3 With Side Cutters Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5702	EBI 60 in Digging Excavator Bucket - Fits Cat
5695	Teran BKT31236 36 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5382 C/W: 312 Linkage - 0.48m3 for Cat 312, 311D,		330CL, 330BL, 330DL S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and5HD Tips Usage: Not Available Asset located in : Humble, TX	5703	Cat 50 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5696	Teran BKT30736TRAPEZ 36 in Trapezoidal Excavator Bucket - Fits Cat 307 (Unused) S/N: Not Available C/W: For Cat 307/308 0.21m3 16/36in - 2 Tips	5704	Hensley 48 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	75 degree Angle Usage: Not Available Asset located in : Humble, TX	5705	CEI 48 in Digging Excavator Bucket - Fits Cat 330CL, 330BL, 330DL S/N: Not Available Usage: Not Available
5697	Teran BKT30730 30 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 2419		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: For Cat 307/308 0.27m3 with Side		Asset located in: Humble, TX
5698	Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Humble, TX Teran BKT31224 24 in Digging Excavator Bucket - Fits Cat 312 (Unused)	5706	42 in Digging Excavator Bucket - Fits John Deere 450LC S/N: 77031 Usage: Not Available Asset located in: Humble, TX
S/N C/V 311 314	S/N: 5566 C/W: 312 Linkage - 0.32m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 3HD Tips	5708	Cat 36 in Digging Excavator Bucket S/N: NBC29401 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5709	Cat 42 in Digging Excavator Bucket S/N: MHJ82307
5699	Teran BKT30724 24 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 01086 C/W: For Cat 307/308 0.21m3 With Side		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Cutters Reinforcement Plates and 4HD Tips Usage: Not Available Asset located in: Humble, TX	5710	Esco 38 in Digging Excavator Bucket - Fits Cat 330CL, 330BL, 330DL
5700	Teran BKT32018HD 18 in Digging Excavator Bucket - Fits Cat 320 (Unused)	_	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: 5593 C/W: B Linkage - 0.29m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 3HD Tips	5711	CP 36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5712	Hensley 36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5713	Geith 36 in Digging Excavator Bucket S/N: 454340 Usage: Not Available Asset located in: Humble, TX	5729	 Cat 24RB149 11 in .04 cyd Digging Excavator Bucket (Unused) S/N: 44229BK20035 C/W: 34.9 mm Diameter Pins, 196 mm Center of Pin Boss to Center of Pin Boss, 165 mm 	
5714	Cat 36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available		Inside to Inside Pin Boss Spacing Usage: Not Available Asset located in : Humble, TX	
	Asset located in: Humble, TX	5730	Cat 13 in Digging Excavator Bucket - Fits Cat	
5715	Cat 36 in Digging Excavator Bucket - Fits Cat 349E S/N: MH203217 Usage: Not Available		308 S/N: A4221BK23939 Usage: Not Available Asset located in : Humble, TX	
	Asset located in: Humble, TX	5731	Cat 13 in Digging Excavator Bucket	
5716	Cat 32 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5732	S/N: A4229BK21597 Usage: Not Available Asset located in : Humble, TX	
5717	CF 30 in Digging Excavator Bucket - Fits John Deere 450DLC S/N: 166561 Usage: Not Available Asset located in: Humble, TX	5732	Cat 24RB152 11 in .08 cyd Digging 305 12 BK Excavator Bucket (Unused) S/N: A422ABK30595 C/W: 44 mm Center of Pin Boss to Center of Pin Boss, 212 mm Inside to Inside Pin Boss Spacing	
5718	2018 Cat 30 in Digging Excavator Bucket - Fits		Usage: Not Available Asset located in: Humble, TX	
	Cat 336 S/N: MHC07375 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	5733	Quantity of (2) Mini Excavator Attachments (Unused) S/N: Not Available C/W: 20 in. bucket, 12 in grapple Usage: Not Available	
5719	Esco 24 in Digging Excavator Bucket - Fits Cat		Asset located in: Humble, TX	
	330CL, 330BL, 330DL S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5735	2024 Elephant BKT336D72SKEL 72 in Skeleton Excavator Bucket - Fits Cat 336 (Unused) S/N: 24062200418 Usage: Not Available Asset located in: Humble, TX	
5720	24 in Digging Excavator Bucket - Fits Cat 320 S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5736	2024 KJ AM3666S 66 in 2 cyd Skeleton Excavator Screening Bucket - Fits Cat 336 / 30 - 38 ton (Unused)	
5725	Cat 18 in Digging Excavator Bucket - Fits Cat 303 S/N: A4234BK30087 Usage: Not Available Asset located in: Humble, TX Cat 24RB148 18 in Digging Excavator Bucket	-	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	
	S/N: CH21BBK25556 Usage: Not Available Asset located in: Humble, TX	5737	Teran BKT336D66SKEL 66 in Skeleton Excavator Bucket - Fits Cat 336D (Unused) S/N: 0252	
5727	Cat 18 in Digging Excavator Bucket - Fits Cat 302 (Unused) S/N: CH21CBK25260 Usage: Not Available Asset located in: Humble, TX		336D2, 336E, 336F, 340D2, 340F with Cutters, Side Protectors, Heel Shrouds Protectors, Reinforcement Plates and - DB Linkage Usage: Not Available	Usage: Not Available
5728	Cat 18 in Digging Excavator Bucket - Fits Cat 302 S/N: 4422ABK20214 Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
5738	2024 Jisan BKT336D66SKEL 66 in Skeleton Excavator Bucket - Fits Cat 336 (Unused) S/N: 24062202078 Usage: Not Available Asset located in: Humble, TX 2024 Jisan BKT32060SKEL 60 in Skeleton	5749	Teran BKT30742SKEL 42 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 3025 C/W: 0.39m3 for Cat 307, 308 with 5 HD Tips Usage: Not Available Asset located in: Humble, TX	
	Excavator Bucket - Fits Cat 320 (Unused) S/N: 24062202062 Usage: Not Available Asset located in: Humble, TX	5751	2024 Jisan BKT32078DB 78 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 240622020102 Usage: Not Available Asset located in: Humble, TX	
5741	Teran BKT32054SKEL 54 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 0363 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6HD Tips 80mm Pins Usage: Not Available Asset Iooated in: Humble, TX	5758	Asset located III: Humble, TXTeran BKT32080CLN 80 in Cleanup ExcavatorBucket - Fits Cat 320 (Unused)S/N: 2200C/W: B Linkage - 0.74m3 for CAT 320, 319D,320D, 320E, 321D, 323E, 323F, 325FUsage: Not AvailableAsset located in: Humble, TXTeran BKTPC22072CLN 72 in Cleanup	
5742	Asset located in: Humble, TX 2024 Jisan BKT32048SKEL 48 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 24042900116 Usage: Not Available Asset located in: Humble, TX		Excavator Bucket - Fits Komatsu PC220 (Unused) S/N: 4901 C/W: 0.66m3 for Komatsu PC200, PC210, PC220, PC228, PC230, PC240, PC250, PC270, PC290 Usage: Not Available	
5743	Teran BKT31248SKEL 48 in Skeleton Excavator Bucket - Fits Cat 312 (Unused) S/N: 0482 C/W: 312 Linkage - 0.77m3 for CAT 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters and 5HD Tips Usage: Not Available Asset located in: Humble, TX	5760	Asset located in: Humble, TX Teran BKT325D72CLN 72 in Cleanup Excavator Bucket - Fits Cat 325D (Unused) S/N: 4911 C/W: CB Linkage - 0.66m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors	
5744	2024 JESON BKT320-48SKEL 48 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: JQBKTS004 Usage: Not Available Asset located in: Humble, TX		Reinforcement Plates and 7RC Tips Usage: Not Available Asset located in: Humble, TX Teran BKT32072CLN 72 in Cleanup Excavator Bucket - Fits Cat 320 (Unused)	
5745	2024 KJ AM2048S 48 in 1.28 cyd Skeleton Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available		S/N: 14105 C/W: B Linkage - 0.66m3 for Cat 320, 31 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available Asset located in : Humble, TX	C/W: B Linkage - 0.66m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available
5746	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ AM2048S 48 in 1.28 cyd Skeleton		Teran BKT31260CLN 60 in Cleanup Excavator Bucket - Fits Cat 312 (Unused) S/N: 1793 C/W: 312 Linkage - 0.38m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available	
	Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5763	Asset located in: Humble, TX Teran BKT30760CLN 60 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 3064 C/W: For Cat 307/308 0.29m3 Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5764	Teran BKT30748CLN 48 in Cleanup Excavator Bucket - Fits Cat 307 (Unused) S/N: 1122 C/W: For Cat 307/308 0.23m3 Usage: Not Available Asset located in: Humble, TX Teran BKT305C48CLN 48 in Cleanup	5779	Teran RIPPER325D Excavator Ripper - Fits Cat 325D (Unused) S/N: 1323 C/W: CB Linkage - for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F Usage: Not Available
5705	Excavator Bucket - Fits Cat 305 (Unused)		Asset located in: Humble, TX
5766	S/N: 01076 C/W: 0.15m3 Usage: Not Available Asset located in: Humble, TX Fleco 60 in Cleanup Excavator Bucket - Fits Link-Belt 145 S/N: 68568	5780	Teran RIPPER312 Excavator Ripper - Fits Cat 312 (Unused) S/N: 3599 C/W: 312 Linkage for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	5781	Teran RIPPER307 Excavator Ripper - Fits Cat
5767	Asset located in: Humble, TX Teran RIPPER390 Excavator Ripper - Fits Cat 390 (Unused) S/N: 0276 C/W: JC Linkage - for Cat 390D, 390	_	307 (Unused) S/N: Not Available C/W: For Cat 307/308 50mm Pin Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5782	2024 KJ AMR20 Excavator Ripper - Fits Cat
5768	Teran RIPPER374 Excavator Ripper - Fits Cat 374 (Unused) S/N: 1326 C/W: VB Linkage - for Cat 374, 374F Usage: Not Available Asset located in: Humble, TX		320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
5770	2024 Jisan RIPPER336D Excavator Ripper -	5783	2024 KJ AMR20 Excavator Ripper - Fits Cat
5775	Fits Cat 336D (Unused) S/N: 24062201619 Usage: Not Available Asset located in: Humble, TX Teran RIPPERJD450 Excavator Ripper - Fits John Deere 450 (Unused) S/N: 3126 C/W: For John Deere JD 450/ZX450 110mm	_	320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Pin	5784	Teran RIPPERMLT312 28 in Excavator Ripper -
	Usage: Not Available		Fits Cat 312 (Unused)
5776	Asset located in: Humble, TX 2024 Jisan RIPPER320 Excavator Ripper - Fits Cat 320 (Unused) S/N: 24042900487 Usage: Not Available Asset located in: Humble, TX	-	S/N: Not Available C/W: 312 Linkage for Cat 312 and 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Humble, TX
5777		5785	2024 Elephant RAKE32065 65 in Excavator
5777	2024 Elephant RIPPER320 Excavator Ripper - Fits Car 329 (Unused) S/N: 24062200329 Usage: Not Available Asset located in: Humble, TX		Rake - Fits Cat 320 (Unused) S/N: 24062200322 Usage: Not Available Asset located in: Humble, TX
5778	Teran RIPPERPC220 Excavator Ripper - Fits Komatsu PC220 (Unused) S/N: 0535 C/W: For Komatsu PC200, PC210, PC220, PC228, PC230, PC240, PC250, PC270, PC290 Usage: Not Available Asset located in: Humble, TX	- 5786	2024 KJ AMK20 65 in Excavator Rake - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5787	2024 KJ AMK20 65 in Excavator Rake - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5795	Teran THUMB7-8M 20 in Excavator Thumb - Fits Cat 307 (Unused) S/N: Not Available C/W: Manual Thumb for Cat 307, 308 and 7 - 8 Ton Excavators Usage: Not Available Asset located in: Humble, TX 2024 DE 3.5T-40 14 in Excavator Thumb
	Asset located in: Humble, TX	5796	(Unused)
5788	Teran RAKE305C44 44 in Excavator Rake - Fits Cat 305 (Unused) S/N: 0405 C/W: Root Rake with 13 Tines		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5797	2024 DE 15 in Excavator Thumb (Unused) S/N: Not Available Usage: Not Available
5789	2024 Jisan THUMB20-25H 30 in Excavator Thumb - Fits Cat 320 (Unused)		Asset located in: Humble, TX
	S/N: 24062201638 Usage: Not Available Asset located in : Humble, TX	5798	2024 DE 8T50 16 in Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5790	2024 Jisan THUMB20-25H 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: 24062201637 Usage: Not Available Asset located in: Humble, TX	5799	Cat 36 in Excavator Thumb - Fits Cat 336F (Unused) S/N: THC07725 Usage: Not Available Asset located in: Humble, TX
5791	2024 KJ AMT2025 Excavator Thumb - Fits Cat	5800	CEI 32 in Excavator Thumb - Fits Cat 330CL,
	320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	5801	330BL, 330DL S/N: Not Available Usage: Not Available Asset located in: Humble, TX 26 in Excavator Thumb S/N: Not Available Usage: Not Available
5792	2024 KJ AMT2025 Excavator Thumb - Fits Cat		Asset located in: Humble, TX
	320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5802	2024 Jisan QCCAT336D Excavator Coupler - Fits Cat 336 (Unused) S/N: 24042900753 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5803	2024 KJ AMQ36 Excavator Coupler - Fits Cat
5793	Teran THUMB20-25 M 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: 0707 C/W: 4 Tines - For Cat 320,325 and 20 - 25 Ton Excavators Usage: Not Available Asset located in: Humble, TX		336 / 30 - 38 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5794	Teran THUMB12 - 15 M 26 in Excavator Thumb	5804	2024 KJ AMQ45 Excavator Coupler - Fits Cat
	- Fits Cat 312 (Unused) S/N: 01034 C/W: For Cat 312, 315 and all 12-15 Ton Excavators 4 Tines Usage: Not Available Asset located in : Humble, TX		345 / 40 - 55 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5806	2024 Elephant QCCAT320 Excavator Coupler - Fits Cat 320 (Unused) S/N: 24062200345 Usage: Not Available Asset located in: Humble, TX	5817	2015 Furukawa Hydraulic Quick Coupler S/N: TAC701 Usage: Not Available Asset located in: Humble, TX John Deere Excavator Boom
5807	Teran QCCAT320 Hydraulic Excavator Coupler - Fits Cat 320 (Unused) S/N: 5209 C/W: B Linkage - 80mm Pins		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5819	Material Handler Stick S/N: Not Available C/W: 16 ft 4 in
5808	Teran QCCAT312 Hydraulic Excavator Coupler - Fits Cat 312 (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: 6158 C/W: 312 Linkage for Cat 311, 312, 314 - 65mm Pins Usage: Not Available Asset located in : Humble, TX	5820	Rotating Demolition Grapple S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5809	Teran QCCAT305 Excavator Coupler - Fits Cat 305 (Unused) S/N: 0512 C/W: For Cat 305 - 45mm Pins Usage: Not Available Asset located in: Humble, TX	5821	2024 Raytree REDM50 50 in Excavator Mulcher - Fits 12 - 20 ton (Unused) S/N: DM20240825150 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5810	Werk-Brau Backhoe Coupler - Fits Cat 420E (Unused)		Usage: Not Available Asset located in: Humble, TX
_	S/N: 5483611 Usage: Not Available Asset located in : Humble, TX		2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: EDM20240825151 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5811	Werk-Brau Quick Coupler - Fits Cat 420E (Unused) S/N: 5483511 Usage: Not Available Asset located in: Humble, TX		
5812	Cat Manual Quick Coupler (Unused) S/N: EG211202929 Usage: Not Available Asset located in : Humble, TX	5823	All-Star 45 in Excavator Mower (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5813	Cat 24RB147 Quick Coupler S/N: 2909417-46 Usage: Not Available Asset located in : Humble, TX	5824	All-Star 45 in Excavator Mower (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5814	Cat 24RB137 Excavator Mounting Bracket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5825	2024 Jisan JSC160 Plate Compactor Attachment - Fits Cat 320/325 (Unused) S/N: 24031104042 Usage: Not Available Asset located in: Humble, TX
5815	Cat 24RB146 Quick Coupler S/N: 2668887-01 Usage: Not Available Asset located in: Humble, TX	5826	2024 Jisan JSC50 Excavator Plate Compactor (Unused) S/N: 24042900415 Usage: Not Available
5816	Furukawa Hydraulic Quick Coupler S/N: TAC2105227539 Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5827	5827 2024 KJ AMC50 Excavator Plate Compactor - Fits Cat 307 / 4 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5834	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available Asset located in: Humble, TX
		5835	Quantity of (4) Teran 1066878 Bucket Pins (Unused) - Fits Cat 315
5828		5836	S/N: Not Available C/W: 70mm X 508mm for Komatsu PC160 Front & Rear - 315 Linkage Usage: Not Available Asset located in : Humble, TX Quantity of (9) 2024 AGT 12EX-ATA Mini
	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		Excavator Attachments (Unused) S/N: 12EX-ATA24080501C Usage: Not Available
5829A	Premier Excavator Auger S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5837	Asset located in: Humble, TX Quantity of (9) 2024 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA24080502C
5829	Tramac TR-9B Excavator Plate Compactor S/N: 6332009		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5838	Doosan Hydraulic Excavator Coupler S/N: Not Available Usage: Not Available
5830	Quantity of 2024 Landhero UBP-65-80 Universal Bucket Pin (Unused)		Asset located in: Humble, TX
mm & (4) 80 mm x 550 mm, ; THE PRODUC IMAGES SHOWN ARE FOR ILLUSTRATION	C/W: (4) 65 mm x 475 mm & (4) 70 mm x 475 mm & (4) 80 mm x 550 mm, ; THE PRODUCT	5839	Doosan Hydraulic Excavator Coupler S/N: 077049 Usage: Not Available Asset located in: Humble, TX
	EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	5840	164 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX .
5831	2024 Landhero UBP-90-100 Universal Bucket Pin (Unused)]	Asset located in: Lake Worth, TX
	S/N: Not Available C/W: (4) 90 mm x 650 mm, (2)100 mm x 750 mm, ;THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5841	Volvo 72 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5842	Cat 72 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5832	2024 Landhero UBP-25-60 Universal Bucket Pin (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5843	John Deere 60 in Q/C Wheel Loader Forks S/N: PHEXSC0601291 Usage: Not Available Asset located in: Humble, TX
		5844	60 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5833	Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311,314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Humble, TX	5845	JRB 60 in Wheel Loader Forks S/N: DEW3211 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5846	60 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX . Asset located in: Lake Worth, TX	5858	Cat 99 in 2.8 cyd Wheel Loader Bucket - Fits Cat 924G/930G (Unused) S/N: 14234BK20002 Usage: Not Available Asset located in: Humble, TX
5847	56 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX .	5859	Cat 94 in Q/C Backhoe Loader Bucket S/N: DD180408676 Usage: Not Available Asset located in: Humble, TX
5848	Asset located in: Lake Worth, TX JRB 54 in Wheel Loader Forks - Fits Komatsu WA250 S/N: 08051951641/6 Usage: Not Available Asset located in: Humble, TX	5860	Cat 24RB125 72 in 1.25 cyd General Purpose Wheel Loader Bucket (Unused) S/N: A4222BK23179 Usage: Not Available Asset located in: Humble, TX
5849	48 in Fork Attachment S/N: Not Available Usage: Not Available Asset located in: Humble, TX	_5861	CEI Single Barrel Multi-Shank Motor Grader Ripper - Fits Cat 140H, 120H, 143H, 12H S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5850	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5862	CEI Single Barrel Multi-Shank Motor Grader Ripper - Fits Cat 140H, 120H, 143H, 12H S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5851 5852	132 in 5 cyd Wheel Loader Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX Cat 24RB156 127 in Q/C 966 5.5YD BKT Wheel	5863	Asset located in: Humble, TX Allied 80000 lb Winch - Fits Cat D7 S/N: AW8LP3F2238C54 C/W: W/ Sweep Usage: Not Available Asset located in: Humble, TX
5853	Loader Bucket - Fits Cat 966 (Unused) S/N: 69H10265 Usage: Not Available Asset located in: Humble, TX Cat 127 in 5.25 cyd Q/C Wheel Loader Bucket -	5864	Paccar PA140-316V Crawler Tractor Winch - Fits D8 S/N: 1200533 Usage: Not Available
	Fits Cat 966H S/N: ARN05717 Usage: Not Available Asset located in: Humble, TX	5865	Asset located in: Humble, TX Paccar PA56 Crawler Tractor Winch - Fits D6 S/N: 1400478 Usage: Not Available Asset located in: Humble, TX
5854	124 in Wheel Loader Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5866	Carco 120 Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY
5855 5856	Cat 114 in 4.75 cyd Q/C Wheel Loader Bucket - Fits Cat 950M (Unused) S/N: Z1A27351 Usage: Not Available Asset located in: Humble, TX Cat 107 in Wheel Loader Bucket - Fits Cat 930	5867	Usage: Not Available Asset located in: Humble, TX Carco 120 Crawler Tractor Winch S/N: 12407 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5868	Asset located in: Humble, TX 120 in Dozer Rake
5857	John Deere 100 in Q/C Wheel Loader Bucket S/N: PXBUSGP270051 Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Details	Lot #	Details
224 in Semi-U Dozer Blade - Fits Cat D9R S/N: 3WL37742 C/W: to Fit D9 Usage: Not Available Asset located in : Humble, TX	5877	2022 Great Plains 1206NT-1975 12 ft No Till Drill S/N: GP-D1044A C/W: 6 in Spacing, Single Shoot, Rubber 2 in Packer
224 in Semi-U Dozer Blade - Fits Cat D7R S/N: Not Available C/W: to fit D7R Usage: Not Available Asset located in: Humble, TX	5878	Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX 2022 Land Pride NTS260782 84 in Slide Hitch
Wright 8B 2 Barrel Multi Shank Crawler Tractor Ripper S/N: W31H198 Usage: Not Available		No Till Seeder No Till Drill S/N: 1488276 C/W: 7 in Spacing, Single Shoot Usage: Not Available Asset located in : Humble, TX
Bush Hog RDTH84 3 Point Shredder Attachment S/N: 12-06021 Usage: Not Available Asset located in: Humble, TX	- 5879	2021 Rome DISC 12-36 8 ft 7 in Pull Behind Offset Disc S/N: 6TPCW-27 C/W: 32 in Wave Edge Front Discs, 27 in Wave Edge Rear Discs, 20 in Spacing, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP-
Rhino 15 ft Batwing Brush Cutter S/N: 10194 C/W: 1000 PTO Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		COMPANY Usage: Not Available Notes : LOCATED-IN-LIVINGSTON_LA SUBJECT TO LA TAX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Livingston, LA
	5880	8 ft Tandem Disc
Brown 76 in 3-Point Rotary Tree Cutter S/N: Not Available C/W: 1000 PTO Usage: Not Available		S/N: Not Available C/W: 28 in Deep Cone Front Discs, 26 in Deep Cone Rear Discs, 20 in Spacing Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE
•	5881	THE INSPECTION REPORT Asset located in: Humble, TX
S/N: 1XFRC20XAG0079967 C/W: 540 PTO Usage: Not Available Asset located in: Humble, TX		John Deere 8 ft 3-Point Tandem Breaking Dise S/N: Not Available C/W: 20 in Notched Front Discs, 18 in Notche Rear Discs, 9 in Spacing, Hitch Leveling, 9 ft
Bush Hog RDTH84 84 in 3-Point Tractor Mower S/N: Not Available		Disc, 7 ft 6 in Leveling Ground Ripper Usage: Not Available Asset located in: Humble, TX
Usage: Not Available Asset located in: Humble, TX	5882	2023 Armstrong Ag DHDP2422 120 in Tandem Disc Harrow
Bush Hog HOG2874 66 in 3-Point Brush Cutter Attachment S/N: Not Available C/W: 540 PTO Usage: Not Available		S/N: W2403 C/W: 21 in Notched Front Discs, 21 in Notched Rear Discs, 9 in Spacing Usage: Not Available Asset located in : Humble, TX
Asset located in: Humble, TX	5883	2013 John Deere 20 ft Flex Wing Rotary Mower
60 in Rotary Brush Cutter S/N: Not Available C/W: 60 in		S/N: 1P0CX20FJDP017009 C/W: 1000 PTO Usage: Not Available Asset located in : Humble, TX
Notes: LOCATED-IN-MIDLAND-TX	5884	2015 John Deere 20 ft Flex Wing Rotary Mower
Asset located in: Midland, TX		S/N: 1P0CX20FCFP017296 Usage: Not Available
		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	224 in Semi-U Dozer Blade - Fits Cat D9R S/N: 3WL37742 C/W: to Fit D9 Usage: Not Available Asset located in: Humble, TX 224 in Semi-U Dozer Blade - Fits Cat D7R S/N: Not Available C/W: to fit D7R Usage: Not Available Asset located in: Humble, TX Wright 8B 2 Barrel Multi Shank Crawler Tractor Ripper S/N: W31H198 Usage: Not Available Asset located in: Humble, TX Bush Hog RDTH84 3 Point Shredder Attachment S/N: 12-06021 Usage: Not Available Asset located in: Humble, TX Rhino 15 ft Batwing Brush Cutter S/N: 10109 PTO Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Brown 76 in 3-Point Rotary Tree Cutter S/N: Not Available C/W: 1000 PTO Usage: Not Available Asset located in: Humble, TX Frontier BC2060 69 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Frontier BC2060 69 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Frontier BC2060 69 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Bush Hog RDTH84 84 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Bush Hog RDTH84 84 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Bush Hog RDTH84 84 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Bush Hog RDTH84 84 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Bush Hog RDTH84 84 in 3-Point Tractor Mower S/N: Not Available Asset located in: Humble, TX Bush Hog HOG2874 66 in 3-Point Brush Cutter Asset located in: Humble, TX Bush Hog HOG2874 66 in 3-Point Brush Cutter Asset located in: Humble, TX 60 in Rotary Brush Cutter S/N: Not Available Asset located in: Humble, TX 60 in Rotary Brush Cutter S/N: Not Available Asset located in: Humble, TX 60 in Rotary Brush Cutter S/N: Not Available Asset located in: Humble, TX 60 in Rotary Brush Cutter S/N: Not Available Asset located in: Humble, TX	224 in Semi-U Dozer Blade - Fits Cat D9R5877S/N: 3WL37742C/W: to Fit D93000000000000000000000000000000000000

Lot #	Details	Lot #	Details
5885	John Deere M20 20 ft Flex Wing Rotary Mower S/N: Not Available C/W: 1000 PTO Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	5895	2024 Quantity of Landhonor BA-22-09W 108 in 3-Point Tractor Dozer (Unused) S/N: HL00006/HL00005 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5896	2019 Land Pride RB1672 72 in 3-Point Blade
5886	2021 Land Pride RC4715 15 ft Flex Wing Rotary Mower S/N: 1708501		S/N: 1400510 Usage: Not Available Asset located in : Humble, TX
	C/W: 540 PTO, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	5897	2024 Industrias America F07 7 ft Box Scraper (Unused) S/N: F07T202435333 Usage: Not Available
5887	Modern Ag MDC15 15 ft Batwing Brush Cutter S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Humble, TX	5898	Asset located in: Humble, TX 2024 Industrias America F10 10 ft Box Scraper (Unused) S/N: F10202435855 Usage: Not Available
5888	Krause 1650 14 ft Heavy Harrow S/N: 239	5899	Asset located in: Humble, TX
	C/W: 13 Bar, x 24 in Tines, Carbide Tips Usage: Not Available	0099	Quantity of Plow Parts S/N: Not Available Usage: Not Available
5000	Asset located in: Humble, TX		Asset located in: Humble, TX
5889	84 in 3-Point Gound Plane S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5900	Quantity of (2) Ag Attachments S/N: Not Available C/W: 540 PTO, 7 in Auger, 72 in Mower, 3 Point Hitch Mount
5890	Marathon AT-303042 Auto-Tie Horizontal Baler		Usage: Not Available Asset located in: Humble, TX
	S/N: 108602 Usage: Not Available Asset located in : Humble, TX	5901	AWS S/A Feed Trailer S/N: Not Available
5891	Landhonor NC-22-2C 72 in 3-Point Nut Collector		C/W: Torsion Axle, 235/85R16 Tires, 7 ft 1 in Body, 235/85R16 Tires Usage: Not Available
	S/N: Not Available Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5902	2024 Elephant EPB430BL Backhoe Hydraulic Breaker - Fits Cat 416 (Unused)
5892	Great Plains NTS2607 84 in No Till Seeder S/N: GPD1685L C/W: 3 Point Hitch ; EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY	5903	S/N: CP2407143 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2024 Elephant EPB430BL Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CP2407144
	Asset located in: Humble, TX		Usage: Not Available
5893	Quantity of (2) Hay Forks S/N: V2777 Usage: Not Available Asset located in : Humble, TX	5904	Asset located in: Humble, TX 2024 Jisan JSB400BL Backhoe Hydraulic Breaker - Fits JCB 3CX/4CX (Unused) S/N: 2404506
5894	2000 Eurospand S272 3-Point Fertilizer Spreader S/N: A0165 C/W: 540 PTO Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5905	Teran THH400BH Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAB00704C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are guilted with 2 Chisels Moil Deint M Type, 2	Breaker - Fits Case 580K/L/M (Unused S/N: CAP12973B52HRL C/W: For Backhoe Case 580K/L/M - G Tool With Auto - Lubrication Pre-Disp All New Teran Hydraulic Hammers at supplied with 2 Chisels Moil Point M Hoses, 1 Set of N2 Nitrogen Charging N2 Bottle and Pressure Gauge, 1 Spa Kit, Tool Box with Maintenance Tools Operations Manual Usage: Not Available Asset located in: Humble, TX5910Teran THH400B-580N Backhoe Hydr Breaker - Fits Case 580N (Unused) S/N: CAP13373B52HRL C/W: For Backhoe Case 580N - 68mr With Auto - Lubrication Pre-Dispositio New Teran Hydraulic Hammers are s with 2 Chisels Moil Point M Type, 2 H Set of N2 Nitrogen Charging Kit with and Pressure Gauge, 1 Spare Seal Kit with Maintenance Tools and Operation Manual Usage: Not Available Asset located in: Humble, TX5911Teran THH400B-JCB3CX Backhoe Hydr Breaker - Fits JCB 3CX (Unused) S/N: CAP13009B52HRL C/W: For Backhoe JCB3CX - 68mr T Auto - Lubrication Pre-Disposition - A Teran Hydraulic Hammers are suppli Chisels Moil Point M Type, 2 Hoses, N2 Nitrogen Charging Kit with N2 Bot Pressure Gauge, 1 Spare Seal Kit, Too With Auto - Lubrication Pre-Disposition - A Teran Hydraulic Hammers are suppli Chisels Moil Point M Type, 2 Hoses, N2 Nitrogen Charging Kit with N2 Bot Pressure Gauge, 1 Spare Seal Kit, Too with Maintenance Tools and Operation Manual Usage: Not Available Asset located in: Humble, TX	C/W: For Backhoe Case 580K/L/M - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available
	supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in : Humble, TX		S/N: CAP13373B52HRL C/W: For Backhoe Case 580N - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied
5906	Teran THH400B-JD410G Backhoe Hydraulic Breaker - Fits John Deere 410G (Unused) S/N: CAB00606C52HRL C/W: For Backhoe John Deere JD310G/410G - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic		Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Bo with Maintenance Tools and Operations Manual Usage: Not Available
	Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Humble, TX		, , ,
5907	Teran THH400B-JD410J/K Backhoe Hydraulic Breaker - Fits John Deere 410J/K (Unused) S/N: CAK16922A26HR C/W: For Backhoe John Deere JD310/410JK - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic		Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available
	Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Humble, TX		S/N: F9-08425 Usage: Not Available
5908	Teran THH400BT Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA0258B52HR C/W: For Backhoe Loaders CAT 416, 428, 444	-5913	Kent KF6 Hydraulic Breaker S/N: 3635 Usage: Not Available Asset located in : Humble, TX
	-68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure	5914	John Deere Backhoe Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in : Humble, TX	5915	2019 Stanley MB/XP4035 Hydraulic Breaker S/N: XP403500058 C/W: 5.6" Tool / chisel. Fits Excavators Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5916	2021 Connect Work Tools CH70SS Hydraulic Breaker S/N: CH70-22F-1164 C/W: 750 lb class	5930	Quantity of (4) Deehan # SH43118 35 Ton Snatch Blocks 32-38 MM WR S/N: Not Available Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX
5917	Bobcat HB980 Q/C Backhoe Hydraulic Breaker S/N: Not Available C/W: Fits Mini Excavator Usage: Not Available Asset located in: Humble, TX	-5931	Quantity of (4) Deehan # SH43118 35 Ton Snatch Blocks 32-38 MM WR S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5919	Cat 18 in Digging Excavator Bucket S/N: A621ABK20212 Usage: Not Available Asset located in: Humble, TX	- 5932	Quantity of (4) Dehaan # SH43118 35 Ton Snatch Blocks 32-38 MM WR S/N: Not Available Usage: Not Available
5921	Quantity of (2) 8 in Cribbing Backhoe Rear Bucket - Fits Cat 416 S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5933	Asset located in: Humble, TX Quantity of (4) Dehaan # SH43118 35 Ton Snatch Blocks 32-38 MM WR S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5922	8 in Cribbing Backhoe Rear Bucket - Fits Case 580 S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5934	Quantity of (2) Dragline Sheaves S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5923	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in : Humble, TX	- 5935	McKissick 160 ton 7 Sheave Load Block S/N: 1184 Usage: Not Available Asset located in: Humble, TX
5924	McKissick 3 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5936	6 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5925	Johnson 1 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-5937	Quantity of (2) McKissick Load Block S/N: Not Available C/W: (1) 50 ton, (1) 60 ton Usage: Not Available Asset located in : Humble, TX
5926	Pettibone 2 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5938	Quantity of (2) McKissick 60 ton 6 Sheave Load Block S/N: Not Available Usage: Not Available
5927	2 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5939	Asset located in: Humble, TX Quantity of (3) McKissick 60 ton 6 Sheave Load Block S/N: Not Available
5928	Quantity of (3) Crane Ball W/Hook S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: Assorted size Usage: Not Available Asset located in : Humble, TX	5940	Quantity of (6) McKissick 20 ton 3 Sheave Load Block S/N: Not Available
5929	Quantity of (4) Deehan #SH43118 35 Ton Snatch Blocks 32-38 MM WR		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5941	McKissick 40 ton 2 Sheave Load Block S/N: 1859 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5942	McKissick 40 ton 2 Sheave Load Block S/N: 1103 Usage: Not Available Asset located in: Humble, TX	5955	Quantity of (2) 65 ton 4 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5943	McKissick 90 ton 4 Sheave Load Block S/N: 11361 Usage: Not Available Asset located in: Humble, TX	5956	Quantity of (3) McKissick 60 ton 6 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5944	Quantity of 15 ton 2 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5957	Quantity of (5) McKissick 5 ton 5 Sheave Load Block S/N: Not Available
5945	Quantity of (3) McKissick 40 ton 4 Sheave Load Block		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5958	Quantity of (4) Load Block S/N: Not Available Usage: Not Available
5946	Quantity of (6) Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5959	Asset located in: Humble, TX McKissick 65 ton 4 Sheave Load Block S/N: 11865 Usage: Not Available
5947	Quantity of (5) Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5960	Asset located in: Humble, TX McKissick 40 ton 2 Sheave Load Block S/N: Not Available Usage: Not Available
5948	Quantity of (5) Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5961	Asset located in: Humble, TX McKissick 8 Sheave Load Block S/N: Not Available Usage: Not Available
5949	McKissick 45 ton 3 Sheave Load Block S/N: 1084 Usage: Not Available Asset located in: Humble, TX	5962	Asset located in: Humble, TX Quantity of (6) Caldwell GC20 20 Ton Beam Clamps S/N: Not Available
5950	Quantity of (2) McKissick 2 Sheave Load Block S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5963	Quantity of (6) Caldwell GC20 20 Ton Beam Clamps
5951	Quantity of (3) 65 ton 4 Sheave Load Block S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5952	Asset located in: Humble, TX Quantity of (2) McKissick Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5964	Quantity of (5) Caldwell # GC-20 20 Ton Beam Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5953	Quantity of (2) 65 ton 4 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5965	Quantity of (20) General # USC-3A Super Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5954	McKissick 90 ton 4 Sheave Load Block S/N: 11359 Usage: Not Available Asset located in: Humble, TX	5966	Quantity of General USC3A Beam Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5967	Quantity of (18) General # USC-3A Super Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5980	Grove 25 Ft Boom S/N: Not Available C/W: 3 section Usage: Not Available Asset located in: Humble, TX
5968	Quantity of (16) General # USC-3A Super Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5981 5982	Quantity of (2) Grove RT530 Boom Cylinder S/N: Not Available Usage: Not Available Asset located in: Humble, TX Grove RT530 Boom Cylinder
5969	Quantity of (15) General # USC-3A & (6) # USC- 4 Super Clamps S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5970	Asset located in: Humble, TX Quantity of (12) General # USC-4 & (5) # USC-5 Super Clamps	5983	15 ft Truss Jib Material Handling Arm - Fits Telehandler S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5984	Asset located in: Humble, TX 2017 Land Pride BB1260 60 in 3-Point Box Blade S/N: 1119943
5971	Quantity of General # USC-4 & # USC-5 Super Clamps Super Clamps S/N: Not Available Usage: Not Available	5095	Usage: Not Available Asset located in: Humble, TX Modern 60 in 3-Point Tractor Box Blade
5972	Asset located in: Humble, TX Quantity of General # USC-4 & # USC-5A Super Clamps Clamps	5985	S/N: 07884 Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		2024 Suihe F-10 10 ft Fork Extensions (Unuse S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5973	Quantity of (14) General # USC-4 & (6) # USC- 5A Super Clamps S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5974	Asset located in: Humble, TX Quantity of (6) General # USC5D-400 Super Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX		2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5975	Quantity of (20) General USC3A Beam Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5988	Asset located in: Humble, TX 2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available
5976	Quantity of (4) 55 Ton Shackle S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5977	Quantity of (8) 35 Ton Shackle S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5989	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5978	Quantity of (5) 17 Ton Shackle S/N: Not Available Usage: Not Available Asset located in : Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5990	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available Usage: Not Available	6000	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in
	Asset located in: Humble, TX		Usage: Not Available
5991	Quantity of (2) 2024 Wolverine EX-66-78L/84L		Asset located in: Humble, TX
	Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in: Humble, TX	6001	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX
5992	Quantity of (2) 2024 Wolverine EX-66-78L/84L Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in: Humble, TX	6002	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available
5993	Quantity of (2) 2024 Wolverine EX-66-78L/84L	6000	Asset located in: Humble, TX
	Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX	6003	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available
5994	Quantity of (2) 2024 Wolverine EX-66-78L/84L		Asset located in: Humble, TX
	Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available	6004	Quantity of (2) 2024 Wolverine EX-66-78L/84L (1) 78 in, (1) 84 in Fork Extensions (Unused) S/N: Not Available Usage: Not Available
5005	Asset located in: Humble, TX	6005	Asset located in: Humble, TX
5995	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in	6005	Mafco Equipment 111T Pneumatic Air Tugger S/N: A1071088 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6006	1990 Ingersoll Rand BU7A HAS001 - Hoist, Air
5996	Quantity of (2) 2024 Wolverine EX-66-78L/84L Sets of Fork Extensions (Unused) S/N: Not Available	6007	1,000 Cap Air Tugger S/N: BU7A.REK75756 Usage: Not Available Asset located in : Humble, TX
	C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in : Humble, TX		1991 Ingersoll Rand BU7A Air Tugger S/N: BU7A.RPL00112 Usage: Not Available
5997	Quantity of (2) 2024 Wolverine EX-66-78L/84L		Asset located in: Humble, TX
	Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in: Humble, TX	6008	1990 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger S/N: BU7A.RSA09841 Usage: Not Available Asset located in : Humble, TX
5998	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX	6009	2006 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger S/N: BU004442 Usage: Not Available Asset located in: Humble, TX
5999	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX	6010	2008 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger S/N: 10133 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6011	2008 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger S/N: BU010411 Usage: Not Available Asset located in: Humble, TX	6024	21 Ft Pipelayer Boom S/N: Not Available Usage: Not Available Asset located in: Humble, TX 20 ft Pipelayer Booms
6012	2012 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger S/N: BU019464 Usage: Not Available	6026	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6013	Asset located in: Humble, TX 2012 Ingersoll Rand BU7A Air Tugger S/N: BU019498	0020	20 Ft Pipelayer Boom S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6014	Usage: Not Available Asset located in: Humble, TX Winch	6027	Tailgate - Fits Articulated Dump Truck S/N: Not Available
0014	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6028	Usage: Not Available Asset located in: Humble, TX Tailgate - Fits Articulated Dump Truck
6015	Winch S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6016	Asset located in: Humble, TX Winch	6029	Tailgate - Fits Articulated Dump Truck S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6030	Asset located in: Humble, TX Cat Tailgate - Fits Cat 730C2 S/N: VG000056-1
6017	2005 Ingersoll-Rand FA25A20MX1 Air Tugger S/N: MW001935 Usage: Not Available	6001	Usage: Not Available Asset located in: Humble, TX
6018	Asset located in: Humble, TX 2005 Ingersoll-Rand FA25A20MX1 Air Tugger S/N: MW001937	6031	Quantity of Track Links S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) Teran 8E4518 44 Link Track Chains (Unused) - Fits Cat D8N/R/T S/N: Not Available C/W: Track Link Assy 44 Lks SALT For Cat D8N /R/T - (CR4525/44) Usage: Not Available Asset located in: Humble, TX Quantity of (2) Teran 6l9671 41 Link Track Chains (Unused) S/N: Not Available C/W: Track Link Assy 41 Lks SALT-HD 41 Lks 3
	Usage: Not Available Asset located in: Humble, TX	6032	
6019	1999 Gomaco 9500 172 in Soil Conditioner Attachment S/N: 905500054 Usage: Not Available Asset located in : Humble, TX		
6020	84 In. Milling Drum S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6033	
6021	Quantity of (3) Milling Drums S/N: Not Available C/W: (1) 28 in., (1) 30 in. & (1) 120 in.		/4 in BH For Cat D6H/R/T - (CR5534/41) (CR4810/41) Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6034	Quantity of (2) Teran 6Y2754 49 Link Track Chains (Unused) - Fits Cat 336DL
6022	67 in Smooth Shell Kit S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Track Link Assy 49 Lks for Cat 330/336DL /EL - (CR5926/49) (1187301) (2131971) (2019119) Usage: Not Available
6023	28 ft Pipelayer Boom S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6035	Quantity of (2) Teran 9W9353 49 in Link Track Chains (Unused) - Fits Cat 320 S/N: Not Available C/W: Track Link Assy 49 Lks Sealed and Greased (CR6288/49)(CR5350/49) (1591519) (1941608) Usage: Not Available	6046	Quantity of (2) Teran 7T6996 Idler w/Shaft (Unused) - Fits Cat D6R/T S/N: Not Available C/W: Idler W/ Shaft SM Dia for Cat D6R/T,D6H Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6047	Quantity of (8) Teran 1205746 S/F Rollers (Unused)
6036	Heavy Duty Forklift Jib S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: For Cat D6R/T,D6H/D - (CR6088) (CR3634) (1181617) (9G8029) (2313087) Usage: Not Available Asset located in: Humble, TX
6037	Heavy Duty Forklift Jib S/N: Not Available	6048	Quantity of (8) Teran 1205766 D/F Rollers
_	Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available
6038	Heavy Duty Forklift Jib S/N: Not Available Usage: Not Available		C/W: For Cat D6R/T,D6H/D - (CR6089) (CR3635) (1181618) (9G8034) (2313088) Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6049	Quantity of (8) Teran 9W8706 D/F Rollers
6039 6040	60 in Forklift Material Handling Arm S/N: Not Available Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available C/W: For Cat D8N/R/T - (CR4529) (1969946) Usage: Not Available Asset located in: Humble, TX
0040	2024 Suihe JF Forklift Material Handling Arm (Unused)	6050	
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	0050	Quantity of (8) Teran 9W8705 S/F Rollers (Unused) S/N: Not Available C/W: For Cat D8N/R/T - (CR4528) (1969947)
6041	Quantity of (2) Teran 1028152 Idlers (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: For Cat 336DL/EL, 330 - (CR6087) (CR5740) Usage: Not Available Asset located in: Humble, TX	6051	Quantity of (12) Teran 1634143 S/F Rollers (Unused) S/N: Not Available C/W: (1R8669) (1175045) (CR5109) (CR5572) Usage: Not Available
6042	Quantity of (2) Teran 1132907 Idlers (Unused) S/N: Not Available		Asset located in: Humble, TX
	C/W: (1028151) (CR5732) Usage: Not Available Asset located in: Humble, TX	6052	Quantity of (12) Teran 1634149 S/F Rollers (Unused) S/N: Not Available
6043	Quantity of (2) Teran 6T3216 Idler w/Shaft (Unused) S/N: Not Available C/W: Idler W/Shaft LG for Cat D6R/T, D6H -		C/W: For Cat 336DL/EL, 330 - (CR5897) (1175047) (1791486) Usage: Not Available Asset located in: Humble, TX
	(CR4616)(2024304)	6053	Quantity of (2) Teran 6Y5685 Sprockets
	Úsage: Not Available Asset located in: Humble, TX		(Unused) - Fits Cat 336DL/EL
6044	Quantity of (2) Teran 6Y0554 Idlers (Unused) -	-	S/N: Not Available C/W: For Cat 336DL/EL, 330 - (CR5861)
	Fits Cat D8N/R/T		Usage: Not Available
	S/N: Not Available C/W: REAR	6054	Asset located in: Humble, TX Quantity of (2) Teran 8E9805 Sprockets
	Usage: Not Available Asset located in: Humble, TX		(Unused) - Fits Cat 320
6045	Quantity of (2) Teran 6Y0557 Idlers (Unused) -	4	S/N: Not Available C/W: 16 Holes - (CR5602)
00-0	Fits Cat D8N/R/T S/N: Not Available C/W: FRONT Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6056	Quantity of (6) 48 in Forks S/N: 50571 Usage: Not Available	6069	Quantity of (7) Welding Deck Mount Stands S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6057	Quantity of (2) 90 in Lift Truck Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6071	Cat 30 In Auger Bit S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6058	Quantity of (2) 46 in Fork Attachment S/N: 9674/ZL00239 C/W: Kinshofer, Heiden Usage: Not Available Asset located in: Humble, TX	6072	Cat 24 In. Auger Bit (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6059	Kinshofer 46 in Crane Forks S/N: 50560 Usage: Not Available Asset located in: Humble, TX	6073	Cat 24 In. Auger Bit (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6060	72 in Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6074	Cat 15 In Auger Bit S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6061	96 in Lift Truck Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6075	Cat 9 in Auger Bit (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6062	Quantity of (6) Pipelayer Counterweight S/N: Not Available Usage: Not Available	6076	Cat 9 in Auger Bit (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6063	Asset located in: Humble, TX Quantity of (2) Pipelayer Counterweights S/N: Not Available Usage: Not Available	6077	Cat 6 in Auger Bit (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6064	Asset located in: Humble, TX Quantity of Crown Electric Forklift Masts S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6078	Handy HSRC12 12 in Skid Steer Rotating Pole Clamp S/N: RC220525244 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
6065	Guard S/N: Not Available Usage: Not Available	6079	THE INSPECTION REPORT Asset located in: Humble, TX Kenco Barrier Clamp
6066	Asset located in: Humble, TX Quantity of (3) 9 ft Jibs S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6067	Usage: Not Available Asset located in: Humble, TX Pipe Cradle	6080	Quantity of (5) Equipment Doors S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6081	Asset located in: Humble, TX ZF Friedrichshafen Transmission - Fits Doosan DA40
6068	Pipe Cradle S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		6082	Transmission - Fits Doosan DL300 S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6083	Quantity of (5) Hydraulic Cylinder S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6096	Quantity of (4) 235/80R16 Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Humble, TX
6084	8 in Hydraulic Cylinder (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6097	Quantity of (4) 205/75R15 Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available
6085	Hydraulic Cylinder S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available	6099	Teran R600H Walk Behind Roller (Unused)
<u> </u>	Asset located in: Humble, TX	-	S/N: 23090907 C/W: Model R600, Gasoline Engine Loncin
6086 6087	Quantity of (1) Crates of Caterpillar Parts - Fits Cat 3404 Diesel Motor S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX Ground Hog HD99-H Gasoline Tow-Behind	_	G390F/13HP, With EPA, Manual Start, Roller Size (Dia. X Width): 426X600mm, Drive type: Hydraulic Pump, Hydraulic Motor, Double Wheels Drive, Vibration type: Automatic, Double Wheels Vibration, Vibration Frequency: 75HZ, Centrifugal Force: 20KN, Water Tank Capacity: 20L, Travel Speed: 0-4 KM/H Usage: Not Available
	Power Auger		Asset located in: Humble, TX
	S/N: 0309137 C/W: (3) Bits, Ball Hitch Usage: Not Available Asset located in: Humble, TX	6100	2024 Powertek Q500 Walk-Behind Saw (Unused) S/N: Not Available C/W: 20 in Max Blade Diameter, 7 in Max
6088	Quantity of (2) Forks S/N: Not Available Usage: Not Available		Cutting Depth, Water Tank, Water Hose Connection, 1 Cylinder 13 hp Gasoline Engine Usage: Not Available
	Asset located in: Humble, TX	6101	Asset located in: Humble, TX
6090 6091	Case Backhoe Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) 26.5R25 Tires	6101	2024 Powertek Q500 Walk-Behind Saw (Unused) S/N: Not Available C/W: 20 in Max Blade Diameter, 7 in Max Cutting Depth, Water Tank, Water Hose Connection, 1 Cylinder 13 hp Gasoline Engine Usage: Not Available
	S/N: Not Available Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6102	2024 Powertek Q500 Walk-Behind Saw
6092 6093	Quantity of (4) 20.8R42 Tires S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Humble, TX Quantity of (4) Steel Truck Rims		(Unused) S/N: Not Available C/W: 20 in Max Blade Diameter, 7 in Max Cutting Depth, Water Tank, Water Hose Connection, 1 Cylinder 13 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	6103	2024 Landhonor LHR-Q300 Walk-Behind Saw (Unused)
	Asset located in: Humble, TX	4	S/N: Not Available
6094	Quantity of (4) Moffet Rims (3) Steel Truck Rims S/N: Not Available C/W: one pallet Usage: Not Available		C/W: 14 in Max Blade Diameter, 4 in Max Cutting Depth, Water Hose Connection, Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6104	Teran Q300H Walk-Behind Saw (Unused)
6095	Quantity of Wheels S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Model Q300, Gasoline Engine Loncin G200F/6.5HP, With EPA, 350mm Concrete Blade, Max Cutting Depth: 10cm, Adjustable Cutting Depth, Water Tank Capacity 12L KGS. Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6105	105 Diamond Products CC6571 Walk-Behind Saw S/N: 160434 C/W: 42 in Max Blade Diameter, 17 in Max Cutting Depth, Water Hose Connection, Hydraulic Blade Raise / Lower, Tier 4, 2019 US EPA Label, Kubota V2607 Diesel Engine, 500 Gallon Poly Tank, Tsurumi Water Pump, 16 Ft, T	6116	Dynapac BT82 Concrete Screed S/N: Not Available C/W: 40 ft Screed, Honda GX160 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Humble, TX
6107	A Utility Trailer Usage: 542 Hr Asset located in: Humble, TX Norton C1320SM Walk-Behind Concrete Saw	6117	Teran VH200F Concrete Vibrator (Unused) S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP Epa, Dynapac Coupling, With Vibrator Poker V50,
	S/N: 13011009 C/W: Honda GX390 1 Cylinder Gasoline Engine Usage: 47 Hr	6118	50mm Head Diameter, Flexible Pipe 6.0 Mts Usage: Not Available Asset located in: Humble, TX
6108A	Asset located in: Humble, TX Core Cut CC1800XL Walk-Behind Saw S/N: 159749 C/W: Water Hose Connection, 2019 US EPA Label, Honda 1 Cylinder Gasoline Engine Usage: Not Available	6120	Quantity of (2) Mustang CV3500 Concrete Vibrator (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Teran S60 Power Trowel (Unused)
6108	Asset located in: Humble, TX Soff-Cut X2500 Concrete Walk-Behind Saw S/N: Not Available C/W: Hydraulic Blade Raise / Lower, Honda 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: Not Available C/W: Model S60 With Gasoline Engine Loncin G200F/6.5HP With EPA, With Round Pan. Engine Pack Separately. Trowel Diameter 580mm, Speed Range 60-100 RPM Usage: Not Available Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	6121	2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071212 Usage: Not Available Asset located in : Humble, TX
6109	2015 Husqvarna 9045-FS513 Walk-Behind Saw		
6110B	S/N: 2015 0300004 Usage: Not Available Asset located in: Humble, TX 2024 Landhonor LHR-CM400 Portable	6122	2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071211 Usage: Not Available Asset located in: Humble, TX
	Concrete Mixer (Unused) S/N: ZWQK20240521R11 C/W: Lifan 168F-2 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6123	2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071216 Usage: Not Available Asset located in: Humble, TX
6110A	2024 Landhonor LHR-CM300 Portable Concrete Mixer (Unused) S/N: ZWQK20240521R05 C/W: Lifan 168F-2 1 Cylinder 6.5 hp Gasoline	6124	2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071218 Usage: Not Available Asset located in: Humble, TX
	Engine Usage: Not Available Asset located in: Humble, TX	6125	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071206 Usage: Not Available Asset located in: Humble, TX
6110	Kobalt Electric Portable Concrete Mixer S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6126	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071207 C/W: 7.5 Kw (10 hp) Usage: Not Available
6111	Gar-Bro Concrete Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	Asset located in: Hu 6127 2024 KUL JHC-280 E (Unused)	Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused)
6113	2020 Gar-Bro 454-R Concrete Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: 071220 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6128	2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071219 Usage: Not Available	6140	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071209 Usage: Not Available Asset located in : Humble, TX
6129	Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071217 Usage: Not Available Asset located in: Humble, TX	6141	Quantity of (2) AJLR LC90T Vibratory Plate Compactor S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6130	2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071213 Usage: Not Available	6142	Asset located in: Humble, TX Quantity of Pneumatic Fishing Tools S/N: Not Available
6131	Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused)		C/W: hose Usage: Not Available Asset located in : Humble, TX
	S/N: 071214 Usage: Not Available Asset located in: Humble, TX	6144	Quantity of (5) Concrete Drains S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6132	2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071215 Usage: Not Available Asset located in: Humble, TX	6145	Quantity of Concrete Pipe S/N: Not Available C/W: misc sizes Usage: Not Available Asset located in: Humble, TX
6133	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071210 Usage: Not Available Asset located in : Humble, TX	6146	Quantity of Concrete Culvert Headwalls S/N: Not Available C/W: Misc. Sizes Usage: Not Available
6134	2024 KUL JHC-588 Surface Grinder (Unused)		Asset located in: Humble, TX
6135	S/N: 071203 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071201 Usage: Not Available	6147	2018 Wacker RTSC3 Trench Compactor S/N: 24449681 C/W: 2017 US EPA Label, Kohler 1.02 L Diesel Engine, 22 in / 32 in Drums, Remote Control w/ Cord, Articulated Steering Usage: 305 Hr Asset located in: Humble, TX
6136	Asset located in: Humble, TX 2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071204 Usage: Not Available Asset located in: Humble, TX	6151	2015 Wacker RTLX-SC3 Trench Compactor S/N: 24277490 C/W: 2014 US EPA Label, Kohler 3 Cylinder 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control
6137	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071205 Usage: Not Available		Usage: 556 Hr Asset located in: Humble, TX 2016 Wacker RTLX-SC3 Trench Compactor
6138	Asset located in: Humble, TX 2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071208 Usage: Not Available Asset located in: Humble, TX	6152	S/N: 24332560 C/W: 2016 US EPA Label, Kohler 3 Cylinder 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 586 Hr Asset located in: Humble, TX
6139	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071202 Usage: Not Available Asset located in : Humble, TX	6153	2013 Bomag BMP 8500 Trench Compactor S/N: 101720121195 C/W: Kubota D1005 3 Cylinder Diesel Engine, 24 in Drums, Remote Control w/ Cord, Articulated Steering Usage: 665 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6154	5154 2017 Wacker Neuson Trench Compactor S/N: 24424276 C/W: 2017 US EPA Label, Kohler 3 Cylinder .40 kW 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 307 Hr	6162	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX		
6155	2024 Powertek C160 Reversible Vibratory Plate Compactor (Unused) S/N: Not Available C/W: 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6163	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6156	2024 Elephant EPC50 Excavator Plate Compactor - Fits Cat 307/307B/308/308B		Usage: Not Available Asset located in: Humble, TX
	(Unused) S/N: 24062200338 Usage: Not Available Asset located in : Humble, TX	6164	2024 SDLOOL SL90B Vibratory Plate Compactor (Unused) S/N: B35825 C/W: Loncin 1 Cylinder 196 cc Gasoline Engine,
6157	Teran C80T Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP, With EPA, Water Tank Plate Size: 53X50cm, Centrifugal Force: 14KN, Max. Compaction Depth: 30cm,		THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Efficiency: 500 m2/H, 90 Kgs. Usage: Not Available Asset located in : Humble, TX	6165	Mustang LF88D Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6158			
	C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX	6166	2024 Paladin PLD-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine
6159	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX	6167	TMG PC90 Vibratory Plate Compactor S/N: Not Available C/W: Loncin 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6160	2024 Landhonor LHR-PC90 Vibratory Plate		
	Compactor (Unused) S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6168	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6161	2024 Landhonor LHR-PC90 Heavy Duty Vibratory Plate Compactor (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	6169	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: US EPA Label, RM120-V 121 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6170	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 2024 US EPA Label, RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX Quantity of (4) 2024 JQ POWER JQ120	6178	2024 Machpro GTR-80 Jumping Jack Tamper (Unused) S/N: SLP2430080010 C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX 2024 Machpro GTR-80 Jumping Jack Tamper
	Jumping Jack Tamper (Unused) S/N: Not Available C/W: RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	0179	(Unused) S/N: SLP2430080011 C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6172	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 2024 US EPA Label, RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX Quantity of (4) 2024 JQ POWER JQ120	6180	Teran RM80 Jumping Jack Tamper (Unused) S/N: Not Available C/W: Tamping Rammer Gasoline Engine Loncin LC168F - 2H/6.5HP EPA, Luxury Type, No Wheels, W/ Yellow Cover, Tamping Force 10Kn, Max. Compaction Depth 45 cm, Efficiency 200 m2/H, Plate Size 345X285, Leap Height 65mm
0170	Jumping Jack Tamper (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
6174	C/W: 2024 US EPA Label, RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6181	Quantity of (3) Jumping Jack Tamper S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (1) Wacker, (2) Bomag Usage: Not Available
6174	5174 2024 Powertek RM80 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder 6.5 hp 196 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX
		6182	20 ft x 8 ft Trench Shield S/N: 1-2359 C/W: 6 in Thick Panels Usage: Not Available
6175	2024 Landhonor LHR-RM90 Jumping Jack		Asset located in: Humble, TX
	Tamper (Unused) S/N: Not Available C/W: Loncin LC168F-2H 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available	6183	20 ft x 8 ft Trench Shield S/N: 4-2203 C/W: 6 in Thick Panels Usage: Not Available Asset located in : Humble, TX
6176	Asset located in: Humble, TX 2024 Machpro GTR-80 Jumping Jack Tamper (Unused) S/N: SLP2430080009 C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine	-6184	16 ft x 8 ft Trench Shield S/N: 140688 C/W: 4 in Thick Panels Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	6185	16 ft x 8 ft Trench Shield S/N: Not Available
6177	Asset located in: Humble, TX 2024 Machpro GTR-80 Jumping Jack Tamper (Unused) S/N: SLP2430080012 C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX		C/W: 4 in Thick Panels Usage: Not Available Asset located in: Humble, TX
		6186	16 ft x 4 ft Trench Shield S/N: 4416241 C/W: 4 in Thick Panels Usage: Not Available Asset located in : Humble, TX
		6187	16 ft x 4 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6188	12 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels	6199	Quantity of (4) 10 Gauge Plate Steel Plates S/N: Not Available C/W: one bundle
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
6189	12 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Asset located in : Humble, TX	6200	Quantity of (8) 10 Gauge Steel Plates S/N: Not Available C/W: assorted size, one bundle Usage: Not Available Asset located in: Humble, TX
6190	12 ft x 8 ft Trench Shield	6201	Quantity of (11) 10 Gauge Steel Plates
	S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE	6202	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	0202	Quantity of (11) 10 Gauge Steel Plates S/N: Not Available C/W: assorted size, one bundle
6191	12 ft x 8 ft Trench Shield S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: 4 in Thick Panels, (0) Spreader Bars Usage: Not Available Asset located in: Humble, TX	6203	Quantity of (3) 3/8 in Steel Plates S/N: Not Available C/W: Assorted Size, One Bundle
6192	Quantity of (3) Pallets of Trench Box Spreaders S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
(102	C/W: Misc. Sizes Usage: Not Available Asset located in: Humble, TX	6204	Quantity of (4) 3/8 in Steel Plates S/N: Not Available Usage: Not Available
6193	Quantity of (2) Pallets of Trench Box Spreaders S/N: Not Available	6005	Asset located in: Humble, TX
	C/W: Misc. Sizes Usage: Not Available Asset located in: Humble, TX	6205	Quantity of (4) 3/8 in Steel Plates S/N: Not Available C/W: Assorted Size Usage: Not Available
6194	Quantity of (2) 2024 Kit Containers 5 ft x 7 ft 8 in (1 in Thick) Road Steel Plates (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6206	Quantity of (3) 3/16 in Steel Plates S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6195	Quantity of (2) 2023 Kit Containers 6 ft x 7 ft 5 in (.62 in Thick) Road Steel Plates (Unused) S/N: Not Available Usage: Not Available	6207	Quantity of (2) Diamond Plate Steel Plates S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX	6208	Asset located in: Humble, TX Quantity of (2) Diamond Plate Steel Plates
6196	Quantity of (5) Diamond Plate Steel Plates S/N: Not Available C/W: Assorted Size, One Pallett Usage: Not Available	0208	S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6209	Quantity of (5) 10 Gauge Steel Plates
6197	Quantity of (5) Diamond Plate Steel Plates S/N: Not Available C/W: Assorted Size, One Pallett		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6210 Q S	Quantity of (5) 10 Gauge Steel Plates S/N: Not Available
6198	Quantity of (9) 10 Gauge Steel Plates S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: One Bundle Usage: Not Available Asset located in : Humble, TX	6211	Quantity of (5) 10 Gauge Steel Plates S/N: Not Available Usage: Not Available
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6212	Quantity of (2) 4 Gauge Steel Plates S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6224	Freightliner Cascadia Sleeper Cab S/N: Not Available C/W: 60 in sleeper Usage: Not Available Asset located in: Humble, TX
6213	Quantity of (2) 89 Gauge Plate Steel Plates S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6225	Paccar Truck Cab - Fits Kenworth T600 S/N: Not Available Usage: Not Available
6214	Quantity of (3) 11 Gauge Steel Plates S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6226	Asset located in: Humble, TX 60 In Truck Sleeper - Fits Kenworth S/N: Not Available Usage: Not Available
6215	Quantity of (2) 2024 Kit Containers 5 ft x 8 ft 6 in (.62 in Thick) Road Steel Plates (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6227	Asset located in: Humble, TX Liftmore 3200REE Hydraulic Truck Crane S/N: 12-4205W120 Usage: Not Available Asset located in: Humble, TX
6216	Tulsa Rufnek Truck Winch S/N: Not Available C/W: Steel Usage: Not Available Asset located in : Humble, TX	6228	Liftmoore 3200REE Hydraulic Truck Crane S/N: 12-4206W120 C/W: 16 ft reach Usage: Not Available Asset located in: Humble, TX
6217	Braden Truck Winch S/N: Not Available C/W: Steel, headache rack Usage: Not Available	6229	Venturo CE1500 Mechanical Truck Crane S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6218	Asset located in: Humble, TX Braden Truck Winch S/N: Not Available C/W: Steel, headache rack Usage: Not Available	_6230	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 251 Usage: Not Available Asset located in: Humble, TX
6219	Asset located in: Humble, TX Tulsa Rufnek 30000 Lb Truck winch S/N: Not Available	6231	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 253 Usage: Not Available Asset located in : Humble, TX
6000	C/W: Steel, headache rack Usage: Not Available Asset located in: Humble, TX	6232	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 254 Usage: Not Available
6220	Braden HP130A Hydraulic Truck Winch S/N: 1153781 C/W: Steel, headache rack Usage: Not Available Asset located in: Humble, TX	6233	Asset located in: Humble, TX 2024 Neks Fifth Wheel Wrecker (Unused) S/N: 252 Usage: Not Available Asset located in: Humble, TX
6221	Tulsa Truck Winch S/N: Not Available C/W: Steel, headache rack Usage: Not Available Asset located in : Humble, TX	6234	Fleet Standard Model 7 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available
6222 6223	Freightliner Truck Cab S/N: Not Available Usage: Not Available Asset located in: Humble, TX Freightliner Day Truck Cab	6235	Asset located in: Humble, TX Fleet Standard Model 7 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6236	Asset located in: Humble, TX Fleet Standard Model 7 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6237	Fleet Standard Model 7 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6248	1995 Fontaine DT-1-20 S/A Booster Axle S/N: 13NM04106T1569890 C/W: Flip-Up, Air Ride Suspension Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6238	Fifth Wheel Wrecker		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6249	Single Axle S/N: Not Available Usage: Not Available
6239	Gray TSJ55 11000 Lb Truck Scissor Jack		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	6250	Single Axle S/N: Not Available
6240	Asset located in: Humble, TX Crysteel StingRay Dump Bed Hoist		C/W: Mack air ride suspension, ratio 2.93 Usage: Not Available
	S/N: Not Available C/W: To Fit Crysteel Manufacturing Inc		Asset located in: Humble, TX
	StingRay material hoist Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE	6251	Single Axle S/N: Not Available C/W: Air Ride Suspension, Fixed Fifth Wheel
			Usage: Not Available Asset located in: Humble, TX
6241	Asset located in: Humble, TX Tandem Axle	6252	Axle
0241	S/N: Not Available C/W: Volvo Air Ride Suspension, Aluminum Rims, Super Singles Usage: Not Available		S/N: Not Available C/W: Kenworth Air ride suspension, Spicer Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6253	Single Axle
6242	Tandem Axle S/N: Not Available C/W: Air Ride Suspension Usage: Not Available		S/N: Not Available C/W: Flex suspension, Spicer 3.36 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6254	Tandem Axle
6243	Allison Automatic Transmission S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Air Ride Suspension Usage: Not Available Asset located in : Humble, TX
6244	Asset located in: Humble, TX Tandem Truck Axle	6255	Single Axle
0244	S/N: Not Available C/W: Spring over beam suspension Usage: Not Available Asset located in: Humble, TX	0200	S/N: Not Available C/W: Airliner suspension Usage: Not Available Asset located in: Humble, TX
6245	Steerable Air Lift Axle	6256	Single Axle
0240	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Air Ride Suspension Usage: Not Available
6246	Steerable Air Lift Axle		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6257	Western Star Truck Hood S/N: Not Available Usage: Not Available
6247	T/A Assembly	6050	Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6258	Quantity of (4) Pallets of Car Parts S/N: Not Available C/W: Assorted Filters, Belts, Gaskets Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6259	Trail King Stinger S/N: Not Available C/W: Steel Usage: Not Available Asset located in: Humble, TX	6272	Quantity of (2) Fontaine Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6260	Quantity of (4) Flip Up Neck Extensions S/N: Not Available C/W: Steel Usage: Not Available	—6273 ————————————————————————————————————	Jost Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6261	Asset located in: Humble, TX 4 ft 6 in Neck Extension	6274	Quantity of (2) Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available	6275	Asset located in: Humble, TX Air Sliding Fifth Wheel
6262	Asset located in: Humble, TX Holland Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6263	Asset located in: Humble, TX Quantity of (2) Fifth Wheel S/N: Not Available	6276	Holland Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6264	C/W: (3) frame rail sections Usage: Not Available Asset located in: Humble, TX Holland Air Sliding Fifth Wheel	6277	Holland Fifth Wheel S/N: Not Available Usage: Not Available
0204	S/N: Not Available Usage: Not Available	6278	Asset located in: Humble, TX Holland Air Slide Fifth Wheel
6265	Asset located in: Humble, TX Holland Fifth Wheel		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6266	S/N: Not Available Usage: Not Available Asset located in: Humble, TX Air Sliding Fifth Wheel	6279	Jost Fifth Wheel S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6280	Asset located in: Humble, TX Holland Fifth Wheel Plate S/N: Not Available Usage: Not Available
6267	Fontaine Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available	6281	Asset located in: Humble, TX Quantity of (2) Fifth Wheel S/N: Not Available
6268	Asset located in: Humble, TX Holland Air Sliding Fifth Wheel S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6282	Fifth Wheel S/N: Not Available Usage: Not Available
6269	Holland Air Sliding Fifth Wheel S/N: Not Available C/W: w/Frame Usage: Not Available Asset located in: Humble, TX	6283	Asset located in: Humble, TX Air Sliding Fifth Wheel Frame S/N: Not Available Usage: Not Available
6270	Holland Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6284	Asset located in: Humble, TX Braden Winch S/N: Not Available Usage: Not Available
6271	Fontaine Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6285	Quantity of (2) Pallets of Frame Steps S/N: Not Available C/W: black, stainless steel Usage: Not Available Asset located in: Humble, TX	6297	Quantity of (2) Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6286	Quantity of (20) Stainless Grab Handles S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	-6298	Quantity of (3) Transfer Pumps (model TDX3E) (3) Hyd Motor Frame Mounted (1) Side mount tool box S/N: Not Available C/W: one pallet Usage: Not Available
6287	Quantity of (6) Saddle Tank Steps S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6299	Asset located in: Humble, TX Quantity of (3) Freightliner Wind Skirts S/N: Not Available C/W: One Pallet
6288	Quantity of (3) Pallets of Aluminum Deck Grading S/N: Not Available C/W: (15) 34 in x 35 in Usage: Not Available Asset located in: Humble, TX	6300	Usage: Not Available Asset located in: Humble, TX Quantity of Mud Flaps & Hangers S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6289	Hydraulic Pump S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6301	Quantity of (2) Magni H10I 22000 lb Hooks S/N: AC009414/AC008607 Usage: Not Available Asset located in: Humble, TX
6290	Quantity of Paccar Aluminum Cross Member S/N: Not Available C/W: one pallet Usage: Not Available	6302	Quantity of Truck Bumper S/N: 50558 Usage: Not Available Asset located in: Humble, TX
6291	Asset located in: Humble, TX Quantity of Quarter Fenders S/N: 50567 Usage: Not Available Asset located in: Humble, TX	-6303	Quantity of Leaf Springs S/N: 50563 Usage: Not Available Asset located in : Humble, TX
6292	Quantity of Steps S/N: 50565 Usage: Not Available Asset located in: Humble, TX	-6304	Quantity of Crossmembers S/N: 50568 Usage: Not Available Asset located in: Humble, TX
6293	Asset located III: Humble, TX Quantity of Frame Sections S/N: 50552 Usage: Not Available Asset located in: Humble, TX	-6306	Quantity of Quarter Fenders S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6294	Quantity of Crossmembers S/N: 50553 Usage: Not Available Asset located in: Humble, TX	6307	Quantity of Mudflaps S/N: Not Available C/W: brackets Usage: Not Available Asset located in: Humble, TX
6295	Brush Guard S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6308	Quantity of (2) Aluminum Diesel Fuel Tank S/N: Not Available C/W: (1) 120 gallon, (1) 100 gallon, mounting brackets Usage: Not Available
6296	Quantity of Chrome Bumper S/N: Not Available	6200	Asset located in: Humble, TX
	C/W: Assorted Type, One Pallett Usage: Not Available Asset located in : Humble, TX	6309	66 Gal Aluminum Fuel Tank S/N: 1104690060A042A Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6310	50 Gal Aluminum Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6322	Aluminum Truck Box S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6311	Wet Kit S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in : Humble, TX	6323	Asset located in: Humble, TX Quantity of (4) Truck Boxes S/N: Not Available Usage: Not Available
6312	Hydraulic Tank w/ Mounts S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6324	Asset located in: Humble, TX Truck Box S/N: Not Available C/W: Steel
6313	100 gal Aluminum Tank w/ saddle mounts, steps S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6325	Usage: Not Available Asset located in: Humble, TX Truck Box S/N: Not Available C/W: Steel Usage: Not Available
6314	Aluminum Diesel Tank S/N: 50551 Usage: Not Available Asset located in : Humble, TX	6326	Usage: Not Available Asset located in: Humble, TX Quantity of (2) Truck Boxes S/N: Not Available
6315	Mac 70 Gal Aluminum Fuel Tank S/N: V051730999 C/W: mounting kit Usage: Not Available	6327	C/W: Steel Usage: Not Available Asset located in: Humble, TX Quantity of L-Shaped Transfer Tank & Toolbox
6316	Asset located in: Humble, TX Peterbilt 60 Gal Aluminum Fuel Tank S/N: 11-04805-025T0300	_	S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX
	C/W: straps, mount bracelets, one pallet Usage: Not Available Asset located in : Humble, TX	6328	Quantity of (2) L-Shaped Transfer Tanks S/N: Not Available Usage: Not Available
6317	Wet Kit S/N: 50550 C/W: (1) PTO, (2) tanks, (2) pumps Usage: Not Available Asset located in : Humble, TX	6329	Asset located in: Humble, TX Quantity of (2) Pallets of Toolboxes S/N: Not Available Usage: Not Available
6318	Quantity of (2) Hydraulic Tank S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6331	Asset located in: Humble, TX Quantity of (2) Transfer Tanks S/N: Not Available C/W: 105 gal L-Shaped, rectangle, (1) Pallet Usage: Not Available
6319	Wet Kit S/N: Not Available C/W: pump, hydraulic tank, hoses Usage: Not Available Asset located in : Humble, TX	6332	Asset located in: Humble, TX Quantity of (3) Transfer Tanks S/N: Not Available C/W: (2) 105 gal L-shaped tanks, (1) rectangle tank
6320	Quantity of (2) Truck Boxes S/N: Not Available C/W: Steel Usage: Not Available	6333	Usage: Not Available Asset located in: Humble, TX Quantity of Transfer Tanks
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available C/W: L-shaped, Rectangle, (1) Pallet Usage: Not Available Asset located in : Humble, TX
6321	Quantity of Hose Reels S/N: Not Available C/W: nozzles Usage: Not Available Asset located in : Humble, TX	6334	Quantity of (4) Pallets of Toolboxes S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6335	Quantity of (2) 105 Gal L-Shaped Transfer Tanks S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX	6347	Quantity of Steel Side Mount Tool Boxes & Tank S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6336	Steel Hydraulic Tank	6348	Quantity of Tractor Air Lines
	S/N: 50564 C/W: hydraulic cylinder Usage: Not Available Asset located in: Humble, TX	0040	S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6337	Quantity of (2) DEF Tank S/N: 50562 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6349 6350	Quantity of Assorted Chains S/N: Not Available C/W: assorted length Usage: Not Available Asset located in: Humble, TX Quantity of (5) Tool Boxes
6338	Sturdy-Lite Truck Box S/N: 50556 C/W: Aluminum Usage: Not Available Asset located in: Humble, TX	6351	S/N: Not Available C/W: assorted size Usage: Not Available Asset located in : Humble, TX
6339	Quantity of (2) Truck Boxes S/N: 50566 C/W: Steel Usage: Not Available Asset located in: Humble, TX	0351	Quantity of (3) Pallets of L-Shaped Transfer Tanks S/N: Not Available C/W: (6) Tanks Usage: Not Available Asset located in : Humble, TX
6340	Steel Hydraulic Tank S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6352	Quantity of (2) Pallets of Transfer Tanks S/N: Not Available C/W: (2) L-Shaped tanks, (1) rectangle tank, (1) Tank/Toolbox combo Usage: Not Available
6341	Gooseneck Tongue S/N: 50557 C/W: Steel Usage: Not Available Asset located in: Humble, TX	6353	Asset located in: Humble, TX McNeilus 10 1/2 Cu Yd Mixer S/N: 9673641898 C/W: Tag Axle, Fenders, Chutes, Hydraulic Tank Usage: Not Available
6342	Differential S/N: Not Available Usage: Not Available	6354	Asset located in: Humble, TX Sliding Fifth Wheel Mount S/N: Not Available
6343	Asset located in: Humble, TX Differential S/N: Not Available	C/W: Sliding Fifth Wheel Mount Usage: Not Available Asset located in: Humble, TX	C/W: Sliding Fifth Wheel Mount Usage: Not Available
6344	Usage: Not Available Asset located in: Humble, TX 2013 Rockwell RR23-160 Differential S/N: 0112092	6355	Vacuum Pump S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6245	C/W: 3.58 Ratio Usage: Not Available Asset located in : Humble, TX	6356	Roots Vacuum Pump S/N: LR138512 Usage: Not Available
6345	Differential S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6357	Asset located in: Humble, TX Roots Vacuum Pump S/N: LR054538 Usage: Not Available
6346	Differential S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6358	Quantity of 6 ft 6 in Trailer Ramps (Unused) S/N: Not Available C/W: Steel Usage: Not Available Asset located in : Humble, TX	6367	2017 McNeilus 10.5 CY Mixer S/N: 9673141896 C/W: fenders, hydraulic tank, chutes, tag axle Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM
6359	Lund 56 In Flush Mount Toolbox S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6368	2017 McNeilus 10.5 CY Concrete Mixer Drum S/N: 92624-39575 C/W: 80 gal Steel, 3 chutes, frame rails,
6360	Braden AMS20 Truck Winch S/N: 800329 C/W: Headache Rack, Tail Roll, Steps Usage: Not Available Asset located in : Humble, TX		hydraulic tank, fenders, tag axle, accessories Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
6361	Quantity of (3) Pallets of Toolboxes 6369 S/N: Not Available 5000000000000000000000000000000000000	6369	2019 Beck 11 CY Concrete Mixer Drum S/N: F-19-32 Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL
6362	Quantity of (1) Pallets of L-Shaped Transfer Tank & Toolbox		OF THIS ITEM Asset located in: Humble, TX
	S/N: Not Available C/W: one pallet Usage: Not Available Asset located in : Humble, TX	6370	2015 McNeilus 10.5 CY Mixer S/N: 92656-39587 Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL
6363	Quantity of (3) Pallets of L-Shaped Transfer Tanks		OF THIS ITEM Asset located in: Humble, TX
6364	S/N: Not Available C/W: (5) Tanks Usage: Not Available Asset located in : Humble, TX	6371	Paint Striping Bed S/N: Not Available C/W: 12 ft Main Deck, 6 ft Upper Deck, Arrow Board & Tanks
	Altec AM60E-MH 20 Ft Bucket Truck Bed S/N: 0515DM5610 C/W: 18 ft utility bed, 60 ft reach, 600 lb limit, stabilizers, two man basket Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX 2015 McNeilus 10.5 CY Mixer Truck Body S/N: 92656-39587 C/W: Chutes, Fenders, Hydraulic Tank, Tag Axle Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX		Usage: Not Available Notes : BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in : Humble, TX
		6372	Additive Tank Truck Body S/N: Not Available C/W: Steel, 22 ft Body Length
6365			Usage: Not Available Notes : BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in : Humble, TX
		6373	2015 SP3027 Additive Tank Truck Body S/N: Not Available C/W: Steel, 22 ft Body Length, triplex pump, 2 in. centrifugal pump, 360 gallon tank, eye wash
6366	2015 McNeilus 10.5 cu yd Concrete Mixer S/N: 92660-39589 C/W: Steel, booster axle, fenders, chutes, hydraulic tank Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX		station Usage: Not Available Asset located in: Humble, TX
		6374	Brenner Tank Truck Body S/N: Not Available C/W: 4700 gal Stainless Steel, 19 ft 6 in Body Length Usage: Not Available Asset located in : Humble, TX
		6375	2016 Treater Kill Truck Body S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6376	dump box S/N: Not Available Usage: Not Available	6387	S/N: 98414 C/W: Palfinger ILD44 lift gate, roll up door, side
	Asset located in: Humble, TX		entry Usage: Not Available
6377	Truck Dump Body		Asset located in: Humble, TX
	S/N: Not Available	6388	Morgan 20 Ft Van Truck Body
	C/W: Steel, 16 ft Body Length Usage: Not Available	0000	S/N: Not Available
	Asset located in: Humble, TX		C/W: roll up door
6378	13 ft Dump Bed	_	Usage: Not Available
0070	S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available	6389	SpaceKap Utility Body
	Asset located in: Humble, TX		S/N: Not Available C/W: 6 ft 6 in Body Length
6379	Truck Dump Body		Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
	C/W: Steel, 15 ft Body Length, Manual Tarp Usage: Not Available	6390	9 Ft Mechanic Truck Bed
	Asset located in: Humble, TX		S/N: Not Available
6380	Heil Truck Dump Body		C/W: crane Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
	C/W: Steel, 15 ft Body Length, Electric Tarp Usage: Not Available	6391	2019 Hiab X-Duo 148 Hydraulic Truck Mounted
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Boom
	THE INSPECTION REPORT		S/N: 3L148DU00125
	Asset located in: Humble, TX		Usage: Not Available
6381	EZ Dumper 8 Ft 6 In Slide-In Dump Bed		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6382	S/N: 411163		Asset located in: Humble, TX
	C/W: Steel Usage: Not Available	6392	Iowa Molding Co 7500-22 Truck Booms
	Asset located in: Humble, TX		S/N: 7500151045 C/W: Stabilizers Usage: Not Available
	18 Ft Winch Truck Bed		
	S/N: Not Available		Asset located in: Humble, TX
	C/W: (2) Braden winches Usage: Not Available	6393	24 Ft Flatbed Dump
	Notes: BUYER RESPONSIBLE FOR REMOVAL		S/N: Not Available
	OF THIS ITEM		Usage: Not Available
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
6383	Winch Truck Bed	6394	24 Ft Flatbed Dump
	S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Lift cylinders
	Asset located in: Humble, TX		Usage: Not Available
6384	16 Ft Winch Truck Bed	┥	Asset located in: Humble, TX
0004	S/N: Not Available	6395	24 Ft Truck Flatbed
	C/W: Braden winch, Tulsa winch		S/N: 69480
	Usage: Not Available		C/W: Nalco Champion 3500 lb crane Usage: Not Available
	Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM		Asset located in: Humble, TX
	Asset located in: Humble, TX	6400	Dakota 168-FB 14 Ft Flatbed
6385	Kidron 22RUIASW90-SP 22 Ft Reefer Van Box		S/N: DB12063
	S/N: 01K00609		C/W: storage boxes
	C/W: Carrier Transcold reefer unit, roll up door,		Usage: Not Available Asset located in: Humble, TX
	side entry Usage: Not Available	6401	
	Asset located in: Humble, TX	6401	Ram 8 Ft 9 In LWB Truck Bed & Utility Top S/N: Not Available
6386	2011 Mickey CB18085 18 Ft Van Body	1	Usage: Not Available
	S/N: 1662V11		Asset located in: Humble, TX
	C/W: 4 Side Bays		
	Usage: Not Available Asset located in: Humble, TX		
	ASSELIUCALEU III. MUMDIE, IA	1	

Lot #	Details	Lot #	Details
6402	GMC Pickup Truck Bed S/N: Not Available C/W: 8 ft Body Length, slip in bed liner Usage: Not Available Asset located in: Humble, TX	6415	Cummins ISB Engine S/N: 46877187 C/W: 6 Cylinder 240 hp 6.7 L Diesel Engine Usage: Not Available Asset located in : Humble, TX
6404	Cat D379 Engine S/N: Not Available	6416	Cummins Engine S/N: Not Available
	C/W: 8 Cylinder Diesel Engine Usage: Not Available		C/W: 6 Cylinder Diesel Engine Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6405	Cat Engine S/N: 68Z00901 C/W: 8 Cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX	6417	Cummins QSB4.5 Engine S/N: 46718254 C/W: 2007 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available
6406	Cat 398 Engine		Asset located in: Humble, TX
	S/N: 36Z00964 C/W: 16 cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX	6418 6419	Cummins QSB4.5 Engine S/N: 73221792 C/W: 2011 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available
6407	Cat 3508 Engine		Asset located in: Humble, TX
	S/N: Not Available C/W: 8 Cylinder Diesel Engine Usage: Not Available		Cummins QSB4.5 Engine S/N: 73246394 C/W: 2011 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX		
6408	Cat 3126 Engine S/N: 7AS27820		
	C/W: 1998 US EPA Label, Cat 3126 6 Cylinder 246 hp 7.2 L Diesel Engine Usage: Not Available	6420	
6409	Asset located in: Humble, TX Cat Engine		
	S/N: Not Available C/W: Cat Diesel Engine		Asset located in: Humble, TX
	Usage: Not Available	6421	Cummins QSB4.5 Engine
	Asset located in: Humble, TX		S/N: 73283978 C/W: 2011 US EPA Label, 4 Cylinder 110 hp 4.5
6410	Engine S/N: Not Available		L Diesel Engine Usage: Not Available
	C/W: 6 Cylinder Diesel Engine Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6422	John Deere 4045TF150 Engine
6412	Cat 3306 Engine & Transmission S/N: 08Z82713 C/W: 6 Cylinder Diesel Engine Usage: Not Available		S/N: T04045TF150 C/W: 1997 US EPA Label, 4 Cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE	6423	Detroit Diesel Engine
	THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available C/W: 3 Cylinder Diesel Engine
6413	Cat Engine & Transmission S/N: 08773184		Usage: Not Available Asset located in: Humble, TX
	C/W: 6 Cylinder Diesel Engine	6424	Detroit Diesel Engine
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 4FD1177 C/W: 4 Cylinder Diesel Engine Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6425	Detroit Diesel Engine S/N: 3D180238 C/W: 4 Cylinder Diesel Engine Usage: Not Available	6436	Ford Automatic Transmission S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6426	Asset located in: Humble, TX Detroit Engine S/N: 3D187051 C/W: Diesel Engine Usage: Not Available Asset located in: Humble, TX	- 6437	1992 Detroit Diesel Series 60 Engine & Transmission S/N: Not Available C/W: 1992 US EPA Label, 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller transmission Usage: Not Available
6427	1988 Dresser Engine S/N: 44260194 C/W: Dresser D359T 6 Cylinder 130 hp 5.9 L Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6438	Asset located in: Humble, TX 2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6428	Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6439	Asset located in: Humble, TX 2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6429	2007 Nissan Frontier Engine S/N: Not Available C/W: 6 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6440	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 AGT ATK-B1000 10000 lb Two-Post Car Lift (Unused) S/N: ATK-B100024080501B
6430	Asset located in: Humble, TX Impco Engine S/N: Not Available C/W: IMRCO 4 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	_	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6431	International T444E Engine S/N: Not Available C/W: 2000 US EPA Label, B175 V8 175 hp 7.3 L Diesel Engine, automatic transmission Usage: Not Available Asset located in: Humble, TX	6441	2024 AGT ATK-B1000 10000 lb Two-Post Car Lift (Unused) S/N: ATK-B100024080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6432	Mitsubishi Truck Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX	6442	Usage: Not Available Asset located in: Humble, TX 2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available
6433	Moro Truck Vacuum Pump S/N: 50555 Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6435	Mack Manual Transmission S/N: Not Available Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6443	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6453	40 ft Bridge Platform (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6444	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Powertek PT620 Tire Changer (Unused)	6454	40 ft Bridge (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6455	25 ft Bridge Platform (Unused) S/N: Not Available Usage: Not Available
6445	2024 Powertek PT620 Tire Changer (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6456	Asset located in: Humble, TX 25 ft Bridge Platform (Unused) S/N: Not Available Usage: Not Available
6446	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042603H Usage: Not Available Asset located in : Humble, TX	6457	Asset located in: Humble, TX 25 Ft Bridge (Unused) S/N: Not Available Usage: Not Available
6447	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042601H Usage: Not Available Asset located in: Humble, TX	6458	Asset located in: Humble, TX 25 ft Bridge (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6448	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6459	25 Ft Loading Ramp (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		6460	25 Ft Loading Ramp (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES FOR ILLUSTRATION PURPOSE		6461	30 Ft Loading Ramp S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6462	2024 Hills Industrial 1205026 120 ft x 50 ft x 26 ft Double Truss Storage Building (Unused) S/N: Not Available
6450	2024 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATK-WB24A24042602H Usage: Not Available		C/W: Quantity of (5) Boxes - Builds (1) Storage Building Usage: Not Available Asset located in : Humble, TX
6451	Asset located in: Humble, TX Quantity of Coats (1) Coats 70X-8H-3 Tire Machine & (1) Coats 1250 Tire Balancer Tires S/N: Not Available Usage: Not Available	6463	2024 Hills Industrial 1205026 120 ft x 50 ft x 26 ft Double Truss Storage Building (Unused) S/N: Not Available C/W: Quantity of (5) Boxes - Builds (1) Storage Building Usage: Not Available
6452	Asset located in: Humble, TX Truck Scale S/N: Not Available Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA	6464	Asset located in: Humble, TX 2024 Hills Industrial 1005026 100 ft x 50 ft x 26 ft Double Truss Storage Building (Unused) S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6465 6466	2024 Suihe S5010023DP-750gPVC 100 ft x 50 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building. Usage: Not Available Asset located in: Humble, TX 2024 Suihe S408023DP-610gPVC 80 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available	6472	60 ft x 40 ft Storage Building S/N: Not Available C/W: 2 boxes, 450 GSM Fabric, Double Truss Frame Storage Building, Pipe: Hot-Dipped Galvanized Steel Base Flange as Foundation On The Ground Commercial Fabric PVC Cover Allows Natural Light In While Blocking Harmful UV Water Proof - UV - Fire - Wind - Snow Resistant Mechanical Doors At Both Ends Usage: Not Available Asset located in: Humble, TX
	C/W: Quantity of (3) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6473	2024 Suihe S306020DP-610gPVC 60 ft x 30 ft x 20ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6467	2024 Suihe S406423DP-610gPVC 64 ft x 40 ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building.	6474	2024 Suihe C504017DR-610gPVC 50 ft x 40 ft x 17 ft Storage Canopy (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Suihe S204016DP 40 ft x 20 ft x 16 ft
6468	Usage: Not Available Asset located in: Humble, TX 2024 Hills Industrial 804024 80 ft x 40 ft x 24 Ft Double Truss Storage Building (Unused)		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building Usage: Not Available Asset located in : Humble, TX	6476	2024 Suihe S204016DP 40 ft x 20 ft x 16 ft Storage Building (Unused) S/N: Not Available Usage: Not Available
6469	2024 Suihe S308515R-300gPE 85 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6477 6478	Asset located in: Humble, TX 40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: Dome Type Single Truss, 420 PE Fabric Usage: Not Available Asset located in: Humble, TX 40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available
6470	Asset located in: Humble, TX 2024 Suihe S408020R-500gPVC 40 ft x 80 ft x 20 ft Storage Building (Unused)	-	C/W: Dome Type Single Truss, 420 PE Fabric Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6479	40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6471	Usage: Not Available Asset located in: Humble, TX	6480	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available
0471	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6481	30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Shelter Dome, 420 PE Fabric Usage: Not Available Asset located in : Humble, TX

Details	Lot #	Details
2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT	6489	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
REPRESENTATION OF THE ACTUAL PRODUCT		Usage: Not Available
5	6.400	Asset located in: Humble, TX
2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX	6491	2024 Suihe C2040-300gPE Container Storage
MC3050 50 ft x 30 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
MC3050 50 ft x 30 ft Storage Building (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	6492	2024 Suihe C2040-300gPE Container Storage
2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	6493	2024 Suihe C2020-300gPE Container Storage
2024 Suihe C404015S-610gPVC 40 ft x 40 ft x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX	6494	Storage Canopy
2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6495	S/N: Not Available Usage: Not Available Asset located in : Humble, TX Suihe 20 ft x 20 ft Storage Canopy (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX MC3050 50 ft x 30 ft Storage Building (Unused) S/N: Not Available Usage: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available Asset located in: Humble, TX 2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available Asset located in: Humble, TX 2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available Asset located in: Humble, TX 2024 Suihe C404015S-610gPVC x 15 ft Contai	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX64902024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX6491MC3050 50 ft x 30 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Humble, TX64922024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION

Lot #	Details	Lot #	Details
6496	2024 Suihe P2040 40 ft x 20 ft Commercial Party Tent (Unused) S/N: Not Available C/W: (18) Removable Side Walls w/PVC Clear Windows, (2) Zipper Doors, 500 gsm PVC Coated Fabrics, Waterproof, Fire & UV Resistant, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6502	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed
	Asset located in: Humble, TX		(Unused)
6497	497 2024 Landhonor LHR-ST3040 40 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available	6504	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused)
6498	Asset located in: Humble, TX 2024 Landhonor LHR-ST3085 85 ft x 30 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	6505	Steel Container Roof Kit (Unused)
6499	Asset located in: Humble, TX 2024 Landhonor LHR-MS0608 6 Ft x 8 Ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset Located in: Humble TY		S/N: Not Available C/W: One Rack Usage: Not Available Asset located in : Humble, TX
		6506	Steel Container Roof Kit (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Humble, TX
6500	Asset located in: Humble, TX 2024 Landhonor LHR-MS0608 6 Ft x 8 Ft Shed	6507	2024 KJ K2430T 24 Ft x 30 Ft Metal Garage (Unused)
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
6501	2024 Landhonor LHR-MS0608 6 Ft x 8 Ft Shed	6508	2024 KJ K4230 Metal Storage (Unused)
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed ; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6509	2024 KJ K4230 Metal Storage Shed (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed ; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6518	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available	6519	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused)
6510	Asset located in: Humble, TX	-	S/N: Not Available Usage: Not Available
6510	2024 KJ K2430T Metal Garage (Unused) S/N: Not Available		Asset located in: Humble, TX
	C/W: Quantity of (2) Boxes - Builds (1) Metal Shed, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	6520	2024 Suihe GS2533 33 ft x 25 ft Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6511	2024 KJ K2430T Metal Garage (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: Quantity of (2) Boxes - Builds (1) Metal Shed, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6521	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6512	2024 DG2642 42 ft x 26 ft All Vertical Metal		
	Garage Building (Unused) S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available	6522	2024 KJ K3325 33 ft x 25 ft Metal Garage
6513	Asset located in: Humble, TX 2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6514	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6523	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available
6515	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6516	2024 DG2642 42 ft x 26 ft All Vertical Metal		Asset located in: Humble, TX
	Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6524	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage
6517	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6525	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6531 	2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K2119 22 ft x 23 ft Metal Garage
6526	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6527	Asset located in: Humble, TX 2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6533	2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6528	Usage: Not Available Asset located in: Humble, TX 2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available	6534	TMG MSC2030F 20 ft x 30 ft Metal Garage Shed S/N: Not Available C/W: One Crate Usage: Not Available
	C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX 2024 Agriquip DG2322 23 Ft x 22 Ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6529	2024 Suihe GS2322 23 ft x 22 ft Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6536	Usage: Not Available Asset located in: Humble, TX 2024 Agriquip DG2322 23 Ft x 22 Ft Double Metal Garage (Unused) S/N: Not Available
6530	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused)		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	6537	2024 Agriquip DG2323 23 Ft x 22Ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6538	2024 Agriquip DG2322 23 Ft x 22 Ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6545	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	THE ACTUAL PRODUCT Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6539	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6546	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6540	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6547	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6541	Asset located in: Humble, TX 2024 SUNTOP S2119 19 ft x 21 ft Double	6548	Asset located in: Humble, TX
0041	Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6542	2024 KJ K3030 30 ft x 30 ft x 14 ft Metal	6549	2024 Agriquip SG1420 Single Garage Metal
	Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6543	2024 Agriquip SG1420 Single Garage Metal	6550	2024 Agriquip SG1420 Single Garage Metal
	Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6544	2024 Agriquip SG1420 14 ft x 20 ft Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6551	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6552	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available	6559	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6553	2024 SUNTOP S1220 12 Ft x 20 Ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6560	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	THE ACTUAL PRODUCT Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6554	2024 SUNTOP S1220 12 Ft x 20 Ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: LOCATED-IN-HUMBLE-TX	6561	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6562	2024 Agriquip CP2030 30 ft x 20 ft Steel
6555	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6563	2024 Agriquip CP2030 30 ft x 20 ft Steel
6556	2024 KJ K2030 30 ft x 20 ft Metal Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6564	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Agriquip CP2030 30 ft x 20 ft Steel
6557	2024 KJ K2030 30 ft x 20 ft Metal Carport		Carport (Unused)
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6565	12 ft x 21 ft x 10 ft Carport (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		6566	12 ft x 21 ft x 10 ft Carport (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6567	18 ft x 21 ft x 10 ft Carport (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6576	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6568	24 ft x 21 ft x 10 ft Carport (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		
6569 6570	18 ft x 25 ft x 10 ft Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Diggit 20 ft x 20 ft Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6577	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6571	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6578	Asset located in: Humble, TX Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6572	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6579	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6573	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6580	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6574	2024 Agriquip CP2020 20 ft x 20 ft Steel658Carport (Unused)658S/N: Not AvailableC/W: THE PRODUCT IMAGES SHOWN AREFOR ILLUSTRATION PURPOSES ONLY AND	6581	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6582	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport (Unused) S/N: Not Available
6575	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6583	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)	6590	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused)
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6584	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6591	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6585	2024 CP1220 12 ft x 20 ft Steel Carport Shed	6592	2024 KJ K1119 11 ft x 19 ft Carport (Unused)
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6593	2024 KJ K1119 11 ft x 19 ft Carport (Unused)
6586	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6594	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX 2024 KJ K1119 11 ft x 19 ft Carport (Unused)
	Asset located in: Humble, TX		S/N: Not Available
6587	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6595	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available
	Asset located in: Humble, TX	4	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6588	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	6596	2024 KJ K1119 11 ft x 19 ft Carport (Unused)
	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6589	2024 Agriquip CP1220 20 ft x 12 ft Steel	1	MAY NOT BE AN EXACT REPRESENTATION OF
0003	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	,	1	

Lot #	Details	Lot #	Details	
6597	7 2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6605	2024 Landhonor LHR-CP1119 All-Steel Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available	6606	2024 Landhonor LHR-CP1119 19 ft x 11 ft All-	
6598	Asset located in: Humble, TX 2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	-	Steel Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6607	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
6599	2024 Suihe M122009P 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	6608	2024 SUNTOP S1912 12 ft x 20 ft Livestock	
6600	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	6609	2024 SUNTOP S2512 12 ft x 25 ft Livestock	
6601	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	6610	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused)	
6602	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX	6611	2024 KJ K1912 12 ft x 19 ft Livestock Shelter	
6603	2024 Landhonor LHR-MS1119 19 ft x 11 ft Metal Garage (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
6604	2024 Landhonor LHR-MS1119 19 ft x 11 ft Metal Garage (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX			

Lot #	Details	Lot #	Details
6612	5612 2024 KJ K1912 12 ft x 19 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6619	Eingp MSC1220F 20 ft x 12 ft Galvanized Metal Livestock Shelter (Unused) S/N: M12S223145 Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6620	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223677
6613	2024 KJ K1912 12 ft x 19 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	C/ FC M/ TH Us	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6621	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223602
6614	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	_	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	6625	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223405 C/W: THE PRODUCT IMAGES SHOWN ARE
6615 2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	Livestock Shelter (Unused) S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6626	2024 KJ K2215 7 ft 4 in x 5 ft 1 Person Skid- Mounted Portable Toilet (Unused) S/N: Not Available
6616	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONI
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6627	2024 Suihe ST-SH(b) 1 Person Portable Toilet (Unused) S/N: Not Available
6617	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6628	C/W: (1) Sinks, (1) Showers, (1) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe NT-SH(b) 1 Person Portable Toilet (Unused)
6618	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Toilet, Shower, Sink THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6629	6629 2024 Suihe NT-SH(a) 1 Person Portable Toilet (Unused) S/N: Not Available C/W: (1) Sinks, (1) Showers, (1) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY	6636	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6637	2024 Suihe NWB-H30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6630	2024 Suihe NT-SH(b) 1 Person Portable Toilet (Unused) S/N: Not Available C/W: Toilet, Shower, Sink THE PRODUCT		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6638	2024 Suihe NWB-H18DB-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6631	2024 Suihe NT-D 2 Person Portable Toilet (Unused) S/N: Not Available C/W: (2) Sinks, (2) Toilets, THE PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6639	2024 Suihe NWB-H18DR-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
6632	5632 2024 Suihe NT-D Portable Toilet (Unused) S/N: Not Available C/W: (2) Sinks, (2) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
		6640	2024 Suihe NWB-H35DS-7 7 ft 35-Drawer Tool Cabinet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6633	2024 Suihe NWB-H40DB-10 10 ft 40-Drawer Workbench (Unused) S/N: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6641	2024 Suihe NWB-30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6634	2024 Suihe NWB-H30DS 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6642	2024 Suihe NWB-30DS-10 Workbench S/N: Not Available
6635	2024 Suihe NWB-H30DS 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION (THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6643	2024 Suihe NWB-25DB-10 10 ft 25-Drawer Workbench (Unused)	6651	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused)
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6644	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6652	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6645	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6653	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6646	2024 Suihe NWB-20DS-7 7 ft 20-Drawer	6654	Quantity of (56) 2024 Suihe SP10-S-56 10 ft
0040	Workbench (Unused) S/N: Not Available	0004	Powder Coated Livestock Panel (Unused) S/N: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6647	2024 Suihe NWB-15DR-2 -10 10 ft 15-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6655	Quantity of (54) 2024 KJ K3830-56 10 ft Livestock Panel (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT
6648	2024 Suihe NWB-10DS-2-7 7 ft 10-Drawer Workbench (Unused)		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	6656	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6656	Quantity of (54) 2024 KJ K3856 10 ft Livestock Panel (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT
6649	2023 Titan West Bison XL Pen System S/N: Not Available C/W: Chute, Scale		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	6657	Quantity of 2024 Landhonor LHR-CP76 Corral
	Asset located in: Humble, TX		Livestock Panel (Unused)
6650	2024 Landhonor LHR-CSC10 10 Ft Cattle Squeeze Chute (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	ASSEL INCALED III. I IUIIINIE, IA	1	

Lot #	Details	Lot #	Details
6658	Quantity of (36) 2024 Landhonor LHR-SP07 7 ft x 3 ft Livestock Panel (Unused) S/N: Not Available C/W: 5 gates Usage: Not Available Asset located in: Humble, TX	6665	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY
6660	Quantity of (30) 2024 KJ K0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available		AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6666	-
6661	Quantity of (30) 2024 KJ K0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX		Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 f Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
6662	Quantity of (30) 2024 KJ K0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6668	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6663	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing S/N: Not Available C/W: (30) Fence Panels, (31) Post's w		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	/Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6664	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6670	Asset located in: Humble, TX Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6671	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6680	2024 Suihe NFG-20FGP-E 20 ft Wrought Iron Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6672	Quantity of (20) 2024 FENS FEN20 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: B44823 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6681	2024 Suihe NFG-20FGP-D 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6675	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6682	2024 Suihe SG 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6676 6677	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 GLWF1007 Welded Steel Fencing	6683	Quantity of (3) 2024 Suihe NFG-20FC-3 20 ft Wrought Iron Bi-Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6678	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S(N): Nat Available	6684	Quantity of (3) 2024 Suihe NFG-20FB-3 Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	6685	2024 KJ K0735D 20 ft x 7 ft Metal Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6679	Quantity of (20) Canex 10 ft x 7 ft Wrought Iron Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6686	2024 KJ K0735E 20 ft x 7 ft Metal Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6693 6694	Quantity of (8) 2024 Suihe SG-20D-8 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6694	Quantity of (2) 2024 KJ K0720-1 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate
6687	Quantity of (6) 2024 KJ K0720-6 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available	6695	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) 2024 Suihe NG-14T -2 14 ft x 7
6688	Asset located in: Humble, TX 2024 KJ K2007N 20 ft x 7 ft Metal Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	-	ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6696	Quantity of Premium Chain Link Fencing S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft
6689	Quantity of (8) 2024 Suihe NG-20D-8 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh Diameter: 3 MM Height =2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire Arms, Single: 92 Pieces Barbed Wire Arms, Double Arms: 8 Pieces Steel Bar: 48 Pieces T Wire: 1230 Pieces Line Wire: 3.5 MM (1950
6690	Quantity of (6) 2024 SUNTOP S0720 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available Asset located in : Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6697	Quantity of Premium Chain Link Fencing S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh Diameter: 3 MM Height =2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire Arms, Single: 92 Pieces Barbed Wire Arms, Double Arms: 8 Pieces Steel Bar: 48 Pieces Tie Wire: 1230 Pieces Line Wire: 3.5 MM (1950 Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available Asset located in: Humble, TX
6691	Quantity of (6) 2024 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		
6692	Quantity of (6) 2024 SUNTOP S207 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6698	Quantity of Premium Chain Link Fencing S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2	6703	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)
	Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh		S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Diameter: 3 MM Height =2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire		Asset located in: Humble, TX
6699	Arms, Single: 92 Pieces Barbed Wire Arms, Double Arms: 8 Pieces Steel Bar: 48 Pieces Tie Wire: 1230 Pieces Line Wire: 3.5 MM (1950 Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available Asset located in: Humble, TX Quantity of Premium Chain Link Fencing	6704	Quantity of (26) 2024 Suihe SF-D-26 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner	6705	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available
	Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M,		Asset located in: Humble, TX
	Diameter: 3 MM Height =2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire	6706	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available
	Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft		Asset located in: Humble, TX
Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available	6707	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available	
	Asset located in: Humble, TX	4	Usage: Not Available
6700	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)	6700	Asset located in: Humble, TX
	S/N: Not Available	6708	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused)
C/W: (2) Gates TH SHOWN ARE FOR ONLY AND MAY N	C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6709	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft
	Asset located in: Humble, TX		Galvanized Chain Link Site Fence (Unused) S/N: Not Available
6701	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)		Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
C/W: (2) SHOWN ONLY AN	C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6710	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6702	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused)	6711	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused)
	S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
		•	

Lot #	Details	Lot #	Details
6712	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6719	Quantity of (2) Pallets of Galvanized Fence Wright Co 12 2"x4"48" 100 ft. Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6720	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available
6713	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6721	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Quantity of (21) 2024 SUNTOP S4200 200 ft x
	Usage: Not Available Asset located in: Humble, TX		40 in Galvanized Farm Fencing (Unused) S/N: Not Available
6714	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	6722	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6715	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6723	Erie Industries QR4800 High Tensile Triple- layer Galvanized Barbed Wire (Unused)
6716	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available
6717	Quantity of (2) Pallets of Fixed Knot Fence Xtreme Black 12.0-12.5 6" 75" 330 Ft Fencing		Usage: Not Available Asset located in : Humble, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6725	2024 Kit Containers WB-90-243 26 in. x 90 ln. Workbench (Unused) S/N: Not Available Usage: Not Available
6718	Quantity of (2) Pallets of Fixed Knot Fence Xtreme Black 12.0-12.5 6" 75" 330 Ft Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6726	Asset located in: Humble, TX 2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6727	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6740	Quantity of (3) Steel Fab Tables S/N: Not Available C/W: (1) 49 in x 72 in, (1) 48 in x 72 in, (1) 48 in x 96 in Usage: Not Available Asset located in: Humble, TX
6728	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6741	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused) S/N: Not Available C/W: (9) Panels, (1) Panel w/gate Usage: Not Available
6729	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6742	Asset located in: Humble, TX Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused) S/N: Not Available C/W: (9) Panels, (1) Panel w/ Gate
6730	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available	6743	Usage: Not Available Asset located in: Humble, TX Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock
6701	Usage: Not Available Asset located in: Humble, TX Kit Containers WB-90-243 26 In. x 90 In.	- 0743	Panel (Unused) S/N: Not Available
6731	Workbench (Unused) S/N: Not Available		C/W: (9) Panels, (1) Panel w/ Gate Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6744	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused)
6732	2024 Kit Containers ST-57 29 in x 57 in Workbench (Unused) S/N: Not Available		S/N: Not Available C/W: (NO GATE) Usage: Not Available
	Usage: Not Available Asset located in : Humble, TX	6745	Asset located in: Humble, TX Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock
6733	2024 Kit Containers ST-57 29 In. x 57 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Panel (Unused) S/N: Not Available C/W: (NO GATE) Usage: Not Available Asset located in: Humble, TX
6734	2024 Kit Containers WB-60-190 26 In. x 60 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6746	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused) S/N: Not Available C/W: (9) Panels, (1) Panel w/ Gate Usage: Not Available Asset located in: Humble, TX
6735	2024 Kit Containers WB-60-190 26 in x 60 in Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6747	Quantity of (2) Print Shack Job Site Box S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6736	2024 Kit Containers WB-60-190 26 in x 60 in Workbench (Unused) S/N: Not Available Usage: Not Available	6748	Quantity of (2) Job Site Box S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6740A	Asset located in: Humble, TX Quantity of (25) 10 ft Livestock Panel S/N: Not Available C/W: (23) Panels, (2) Gated Panels Usage: Not Available Asset located in: Humble, TX	6749 	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
S, C, 1, G	5750 Quantity of (3) Job Site Boxes of Misc. Tools S/N: Not Available C/W: (3)Corded Die Grinder 1 1/2 in, Cordless 1 1/2 in Die Grinder, (3) Corded 4 1/2 in Angle Grinder, Corded 1/2 in Impact, Corded 1/2 in Hole Shooter, (2) Corded VSR Drill, Corded SDS Rotary Hammer, Bosch Laser Level, Grease Gun, Corded Deep cut band saw, Corded Band Saw, SDS Max Rotary Hammer, Rotary Hammer Drill, Welding Leads, (2) Cordless Band Saw, (2) Mag Drill Press Usage: Not Available	6760	Knaack 89 Jobsite Gangbox with Contractors Supplies S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6761	Job Site Box with Contents S/N: Not Available Usage: Not Available Asset located in: Humble, TX Justrite 60 Gal Flammable Storage Cabinet
6751	Asset located in: Humble, TX Quantity of (3) Knaack 89 Job Site Box S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: Contents Included Usage: Not Available Asset located in : Humble, TX	6763	Quantity of (3) Flammables Storage Cabinet S/N: Not Available Usage: Not Available
6752	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in: Humble, TX	6764	Asset located in: Humble, TX Durham 45 Gal Flammable Storage Cabinet S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6753	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in: Humble, TX	6765	Justrite 60 Gal Flammable Storage Cabinet S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6754	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in: Humble, TX	6766	Quantity of (3) Job Site Box S/N: Not Available C/W: Fall protection, chain hoists Usage: Not Available Asset located in : Humble, TX
6755	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in: Humble, TX	6767	Ridgid 48R-OS Job Site Box S/N: 1925312776 Usage: Not Available Asset located in: Humble, TX Erie Industries D2248 Chest Tool Box (Unused)
6756	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
6757	Knaack Job Site Box with Contents S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6774	Erie Industries D2248 Chest Tool Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6758	69 Jobsite Gangbox with Contractors Supplies S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Skid Mounted Heat Exchanger Puller
6759	Asset located in: Humble, TX Knaack 89 Jobsite Gangbox with Contractors Supplies S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-	S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6776	Quantity of Testing Equipment S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6801	Quantity of Lug and Thread Bolts S/N: Not Available C/W: assorted size, one crate Usage: Not Available Asset located in: Humble, TX
6777	Asset located in: Humble, TX Quantity of (4) Gas Cylinder Carts S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6802	Quantity of Quantity of Gaskets, Saddle Anchors, Couplings and Clamps S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX
6778	Quantity of (4) Cabinets S/N: Not Available C/W: (2) filing cabinets, (2) flammables cabinets Usage: Not Available Asset located in : Humble, TX	6803	Quantity of Steel Toe Rubber Boots S/N: Not Available C/W: assorted size, one crate Usage: Not Available Asset located in: Humble, TX
6782 6783	Quantity of (2) Blasting Tanks and (2) Sand Blaster S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (4) Pneumatic Sand Blaster	6804	Quantity of Tools and Hoses S/N: Not Available C/W: Jack Hammer, Hilti Drill Rig Kit, Magnetic Drill and Grease Guns, Air Hose, Discharge Hose, One Crate Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Quantity of Welding Equipment S/N: Not Available C/W: Welding Wire, Pressure Gauges, Welding Rods, Plasma Torch and Shims, One Crate Usage: Not Available Asset located in: Humble, TX
6784	Quantity of (4) Pneumatic Sand Blaster S/N: Not Available Usage: Not Available		
6785	Asset located in: Humble, TX Quantity of Hose S/N: Not Available C/W: (4) Pallets Usage: Not Available	_6806	Quantity of Fittings and Flanges S/N: Not Available C/W: assorted size, one crate Usage: Not Available Asset located in: Humble, TX
6786	Asset located in: Humble, TX Quantity of Hose S/N: Not Available C/W: (1) Tote Usage: Not Available	6807	Quantity of Fittings and Flanges S/N: Not Available C/W: assorted size, one pallet Usage: Not Available Asset located in: Humble, TX
6787	Asset located in: Humble, TX Quantity of (4) Pipe Rollers S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6808	Pallet of Misc. Tools S/N: Not Available C/W: Leaf blower, Circular Saws, angle grinders, hammer drill, impact, electric drills Usage: Not Available Asset located in: Humble, TX
6788 6789	Webb Tank Turner S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) Hydrostatic Test Pump	6809	Pallet of Tools S/N: Not Available C/W: Rivet Buster, Recip. Saw, Rebar Straightener Usage: Not Available
6800	S/N: Not Available Usage: Not Available Asset located in : Humble, TX Gray TSJ-55 5.5 Ton Transmission Jack S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6810	Asset located in: Humble, TX Quantity of Tools S/N: Not Available C/W: 1 Ton Chain Fall, 2 Ton Beam Clamp, (4) 2 Ton Chain Fall, (4) 3 Ton Come Along, 3 Ton Chain Fall, (2) 1 1/2 Ton Come Along, (2) 2 Ton Come Along, (5) 1 1/2 Ton Chain Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6811	Quantity of Tools S/N: Not Available C/W: Beam clamps, duct, one pallet Usage: Not Available Asset located in : Humble, TX	6821	Quantity of Tools S/N: Not Available C/W: (4) Misc Ladders, (2) Corded Light Tower Usage: Not Available Asset located in : Humble, TX
6812	Quantity of Tools S/N: Not Available C/W: (2) Miller Portble Welder, (2) Hilti Powder Actuated Decking Tool Usage: Not Available Asset located in: Humble, TX	6822	Quantity of Hand Tools & Gauges S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6813	Quantity of Tools S/N: Not Available C/W: 1 1/2 Ton Chain Fall, 1 1/2 Ton Come Along, 2 Ton Chain Fall, 3 Ton Chain Fall Usage: Not Available	-6823	Quantity of Tools S/N: Not Available C/W: (6) Hydraulic Pumps, (2) Pnuematic Air Guns Usage: Not Available Asset located in: Humble, TX
6814	Asset located in: Humble, TX Quantity of Harness with Twin SRL's S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of Tools	_6824 _	Quantity of Nylon Sling S/N: Not Available C/W: (4) Blue Endless Chockers, (4) Red Endless Chockers, (4) Orange Endless Chockers Usage: Not Available
	S/N: Not Available C/W: Grinders, Drills, Bandsaw, one pallet Usage: Not Available Asset located in: Humble, TX	6825	Asset located in: Humble, TX Quantity of Nylon Sling S/N: Not Available C/W: (6) Blue Endless Chockers, (6) Red
6816	Pallet of Misc. Tools S/N: Not Available C/W: (3) 3/4 in Cordless Impact, 1/2 in		Endless Chockers Usage: Not Available Asset located in : Humble, TX
6817	Cordless Impact, Drill Bit Case, Corded Band Saw, SDS Max Hammer Usage: Not Available Asset located in: Humble, TX Quantity of (2) Hilti DX9-ENP Powder Actuated	6826	Quantity of Wire Sling S/N: Not Available C/W: (15) 5/8 Wire Chockers, (15) 3/4 Wire Chockers Usage: Not Available
	Decking Tools S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	6827	Asset located in: Humble, TX Quantity of Chokers & Ratchet Straps S/N: Not Available C/W: assorted size, one pallet Usage: Not Available Asset located in: Humble, TX
6818	Pallet of Misc. Tools S/N: Not Available C/W: (2) 2 Gallon Shop Vacuum, Tubing Bender Kit, Powder Actuated Tool, Metal Cutting Saw 8 in, Mag Drill, Corded Band Saw Usage: Not Available Asset located in: Humble, TX	6828	Quantity of Wire Sling S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6819	Pallet of Misc. Tools S/N: Not Available C/W: Lincoln Suitcase Welder, Plasma Cutter, Core Drill, Battery Charger Usage: Not Available	_6829	Quantity of Nylon Sling S/N: Not Available C/W: (27) 2 in Nylon straps Usage: Not Available Asset located in: Humble, TX
6820	Asset located in: Humble, TX Quantity of Tools S/N: Not Available C/W: 8-12 in Beam Clamp, (2) 2-6 in Beam Clamp, Battery Box 12V with Chargers, (2) 36 in Bolt Cutter Usage: Not Available Asset located in: Humble, TX	6830	Quantity of Tools S/N: Not Available C/W: (2) air manifolds, rivet busters, chain hoist, one pallet Usage: Not Available Asset located in: Humble, TX
		6831	Quantity of (1) Crates of Tools S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6832 6833	BDS 200 Magnetic Drill w/Stand S/N: Not Available Usage: Not Available Asset located in: Humble, TX Nitrile Inside Diaphragm Air Pump	6844	Quantity of (2) Crates of Fall Protection & Cone Bases S/N: Not Available C/W: one stack Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6845	Quantity of Contractor Supplies S/N: Not Available
6834	Quantity of Tools S/N: Not Available C/W: One Pallet		C/W: Battery charger bases, gloves, one crate Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6846	Quantity of (2) Pallets of 16 In x 30 In Job Site Box
6835	Pallet of Tools S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6847	Quantity of (2) Pallets of 16 In x 30 In Job Site Box
6836	Quantity of Contractor Supplies S/N: Not Available C/W: Step Ladders, Shovels, Handles, Brooms, Stop Signs, (1) Pallet		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Àvailable Asset located in : Humble, TX	6848	Quantity of (2) Crates of Contractor Supplies S/N: Not Available
6837	Quantity of (2) Pallets of Cables, Hoses, Duct S/N: Not Available Usage: Not Available		C/W: tie wraps, rod ovens, shirts Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6849	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available
6838	Kruncher HS43515 Oil Filter Baler/Crusher S/N: 7011705 Usage: Not Available		C/W: Cases, Tool Boxes, Rain Coats Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6850	Quantity of Contractor Supplies
6839	Quantity of (6) Crates of Fall Protection S/N: Not Available C/W: three stacks Usage: Not Available Asset located in: Humble, TX	0830	S/N: Not Available C/W: Steps, Garden Cart, Transmission Jack, One Pallet Usage: Not Available
6840	Quantity of (2) Crates of Contractor Supplies		Asset located in: Humble, TX
	S/N: Not Available C/W: assorted tools, one stack Usage: Not Available Asset located in: Humble, TX	6851	Quantity of (1) Pallets of Tri Stands S/N: Not Available C/W: one pallet Usage: Not Available
6841	Quantity of (6) Crates of Fall Protection	-	Asset located in: Humble, TX
0041	S/N: Not Available C/W: three stacks Usage: Not Available	6852	Quantity of (2) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6853	
6842	Quantity of (1) Pallets of Tool Bags & Wire Wheels S/N: Not Available C/W: one pallet Usage: Not Available	0855	Quantity of Contractor Supplies S/N: Not Available C/W: hand tools, plastic, one crate Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6854	Quantity of (2) Crates of Fall Protection
6843	Quantity of (2) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6855 6856	Quantity of (1) Crates of Power Tools S/N: Not Available C/W: Bandsaws, Hammer Drills Usage: Not Available Asset located in: Humble, TX	6867	Quantity of (2) 45 gal Flammable Storage Cabinets S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
	Quantity of (4) Crates of Fall Protection S/N: Not Available C/W: two stacks Usage: Not Available Asset located in: Humble, TX	6873	E Pumps WNC-12TG Pump S/N: 16DW1074901 C/W: 12 in Intake, 12 in Discharge, Centrifugal Usage: Not Available Asset located in: Humble, TX
6857	Quantity of (3) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6874	Quantity of (4) Namco 574 Transfer Case S/N: Not Available Usage: Not Available
6858	Quantity of (3) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6875	Asset located in: Humble, TX Quantity of (3) Water Pump S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac
6859	Quantity of (4) Crates of Fall Protection S/N: Not Available C/W: two stacks		XC3000P, MQ QP4TK Usage: Not Available Asset located in: Humble, TX
6860	Usage: Not Available Asset located in: Humble, TX	6876	Water Pump S/N: Not Available C/W: Diaphragm
0800	S/N: Not Available C/W: two stacks		Usage: Not Available Asset located in: Humble, TX
6861	Usage: Not Available Asset located in: Humble, TX Quantity of (4) Crates of Fall Protection	6877	2017 Cornell 2 5H-RP-EM-16-3 Water Pump S/N: 215092 Usage: 1,611 Hr
	S/N: Not Available C/W: two stacks Usage: Not Available	6878	Asset located in: Humble, TX 2019 D&D 4SSS44 Hydraulic Driven Submersible Water Pump
6862	Asset located in: Humble, TX Quantity of (1) Pallets of Contractor Supplies S/N: Not Available	-	S/N: 4S616SS Usage: Not Available Asset located in : Humble, TX
	C/W: Toolboxes, Sockets Usage: Not Available Asset located in : Humble, TX	6879	2023 Bell 5BF2P5H0 Water Pump S/N: 15BF2P5H0 Usage: Not Available
6863 	Quantity of (1) Crates of Contractor SuppliesS/N: Not AvailableC/W: Socket SetsUsage: Not AvailableAsset located in: Humble, TXQuantity of (3) Crates of Fall Protection	6880A	Asset located in: Humble, TX Carver Electric Water Pump S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Centrifugal Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6880	2023 Bell 5BF2P5H0 Water Pump S/N: Not Available Usage: Not Available
6865	Quantity of (1) Pallets of Contractor Supplies S/N: Not Available C/W: Consumables Usage: Not Available Asset located in: Humble, TX	6881	Asset located in: Humble, TX Quantity of Concrete Mixer, Pressure Washer & Pump S/N: Not Available Usage: Not Available
6866	Quantity of (6) 16 In x 30 In Job Site Box S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6882	2023 Aurora 341A-SF Electric Skid-Mounted Water Pump S/N: 97F17888 C/W: 4 in Intake, 4 in Discharge, Centrifugal, Baldor 20 hp electric motor Usage: Not Available Asset located in: Humble, TX	6892	2015 Versamatic E3SA3R330C-ATEX Water Pump S/N: 2207853 C/W: 3 in Intake, 3 in Discharge, Self Priming Diaphragm Water Pump Usage: Not Available Asset located in: Humble, TX
6883	2013 KU6011 Electric Skid-Mounted Water Pump S/N: Not Available C/W: 4 in Intake, 4 in Discharge, Centrifugal, Teco 20 hp electric motor Usage: Not Available	6893	2022 Versamatic E3SA3R339CATEX Water Pump S/N: 38034612 Usage: Not Available Asset located in: Humble, TX
6884	Asset located in: Humble, TX 2017 Versamatic E2SA5T559C-HD-A Water Pump S/N: 7099508 Usage: Not Available Asset located in: Humble, TX	6894 6895	Quantity of Ladder S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (3) Crates of OTC 100 ton Track Press
6885	2016 Versamatic E2SA5T559C-HD-A Water Pump S/N: 2259305 Usage: Not Available	6896	S/N: Not Available C/W: three crates Usage: Not Available Asset located in: Humble, TX Clayborne 6000 Lb Engine Stand
6886	Asset located in: Humble, TX 2015 Versamatic E2SA5T559C-HD-A Water Pump S/N: 7039990 Usage: Not Available		S/N: 605 C/W: To Fit CLAYBORNE ENGINE STANDS 906 engine stand Usage: Not Available Asset located in: Humble, TX
6887	Asset located in: Humble, TX 2016 Versamatic E2SA5T5T9-HD Water Pump S/N: 7091887 Usage: Not Available Asset located in: Humble, TX	_6897	3000 Lb Engine Stand S/N: Not Available C/W: adapters Usage: Not Available Asset located in : Humble, TX
6888	2015 Versamatic E2SA5T5T9-HD Water Pump S/N: 7028779 C/W: 2 in Intake, 2 in Discharge, Self Priming Diaphragm Water Pump Usage: Not Available	6898 6899	Pioneer Pump Parts S/N: PP66S12LHF4L914 Usage: Not Available Asset located in: Humble, TX Quantity of Hose
6889	Asset located in: Humble, TX 2016 Versamatic E2SA5T5TS9C-HD Water Pump		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6890	S/N: 7082391 Usage: Not Available Asset located in: Humble, TX 2016 Versamatic E2SA5T5TS9C-HD Water	6900	Quantity of Hose S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Pump S/N: 7082390 Usage: Not Available Asset located in : Humble, TX	6901	Quantity of (4) Pallets of Hose S/N: Not Available C/W: misc sizes Usage: Not Available
6891	2015 Versamatic E3AA2R220C-ATEX Water Pump S/N: 2218578 C/W: Diaphragm Usage: Not Available Asset located in: Humble, TX	6902	Asset located in: Humble, TX Quantity of (4) Pallets of Hose S/N: Not Available C/W: Misc. Sizes Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6903	Quantity of (4) Pumps S/N: Not Available C/W: Diaphragm Usage: Not Available Asset located in : Humble, TX	6914A	Quantity of 5 in Coiled Tubing Reels S/N: Not Available C/W: (2) Coils Usage: Not Available Asset located in: Humble, TX
6904	Quantity of Lifting Equipment S/N: Not Available C/W: chain slings, chain hoist, shackles, come alongs Usage: Not Available	6914	Quantity of Concrete Tools S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6905	Asset located in: Humble, TX Quantity of (3) Crates of Discharge & Suction Hose	6915	Quantity of Surge Protectors S/N: Not Available Usage: Not Available
	S/N: Not Available C/W: assorted size Usage: Not Available Asset located in : Humble, TX	6916	Asset located in: Humble, TX Quantity of (4) Lakeside Serving Carts S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6906	Quantity of Nitrogen Charge Kits S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6917	Paccar Wiper Motor S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6907	Quantity of (6) Hose Reels S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6918	Asset located III. Humble, TX Quantity of (5) Saw Blades S/N: Not Available C/W: Assorted Sizes Usage: Not Available
6908	Quantity of (2) Pallets of Parts (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6919A	Asset located in: Humble, TX Quantity of (2) 5 in Coiled Tubing Reels S/N: Not Available
6909	6000 lb Pallet Jack S/N: 2005115167 Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX , .	6919	C/W: (2) Coils Usage: Not Available Asset located in: Humble, TX 22 Ft Skid Mounted Picnic Gazebo
6910	Asset located in: Midland, TX Quantity of (8) American Aluminum	_	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Accessories Cam-Lockers S/N: Not Available C/W: Aluminum Usage: Not Available Asset located in: Humble, TX	6920	Quantity of (2) Boxes of 1 In Adhesive Door Insulation S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6911	Quantity of Lifting Equipment S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6921	Quantity of (1) Pallets of Zippertubing S/N: Not Available C/W: one pallet Usage: Not Available
6912	Quantity of Contractor Supplies S/N: Not Available C/W: Wacker jumping jack tamper, test pump, generator set, Tsurumi 3 in. water pump Usage: Not Available Asset located in: Humble, TX	6922	Asset located in: Humble, TX Quantity of (1) Pallets of Traffic Light Signals S/N: Not Available C/W: Assorted SizeS & Type Usage: Not Available Asset located in: Humble, TX
6913	Quantity of Contractor Supplies S/N: Not Available C/W: (4) Chipping Hammers, (2) Electric Submersible Pumps Usage: Not Available Asset located in: Humble, TX	6923	Asset located in: Humble, TX Quantity of (14) Pallets of Water Line Fittings S/N: Not Available C/W: (6) control pans, (4) pallets of spacers, (6) pallets of assorted fittings, (5) pipe w /valves Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6924A 6924	Quantity of 6 in Coiled Tubing ReelsS/N: Not AvailableC/W: (2) CoilsUsage: Not AvailableAsset located in: Humble, TX2024 Commercial Portable Paint Room	6934	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6935	Quantity of Square D Electrical Supplies (Unused)
6925	Lennox Air Handler & Coils S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in : Humble, TX
6926 6927	Quantity of Assorted Remotes S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX Quantity of (12) Pallets of Pallet Racking	6936	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available
	S/N: Not Available C/W: (6) pallets of wire racks, (6) pallets of racks & cross arms, 48 in end frames Usage: Not Available Asset located in : Humble, TX	6937	Asset located in: Humble, TX Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load
6928A	Quantity of 5 in Coiled Tubing Reels S/N: Not Available		center covers, one pallet Usage: Not Available
	C/W: (2) Coils Usage: Not Available	6938	Asset located in: Humble, TX Quantity of Square D Electrical Supplies
6929	Asset located in: Humble, TX Quantity of (2) J.E. Adams Industrial Vacuum Cleaner S/N: Not Available Usage: Not Available Asset located in: Humble, TX	_	(Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX
	Hydro-Extractors 604FTE Aerial Hydraulic Tube Bundle Extractor S/N: 0100551216 Usage: Not Available Asset located in: Humble, TX	6939	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available
6930	10 Ft Bucket Rack S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6940	Asset located in: Humble, TX Quantity of Square D Electrical Supplies (Unused)
6931	Quantity of w/ Bolts Bolt Bin S/N: Not Available C/W: (6) Pallets Usage: Not Available		S/N: Not Available C/W: Main breakers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX
6932	Asset located in: Humble, TX Quantity of (4) Post Driver Frames S/N: Not Available Usage: Not Available Asset located in: Humble, TX	_6941	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, load center covers, one pallet Usage: Not Available
6933	Quantity of (2) Debris Boxes S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6942 6943	Quantity of Square D Circuit Breakers (Unused)S/N: Not AvailableC/W: Assorted size, (1) PalletUsage: Not AvailableAsset located in: Humble, TXQuantity of Square D Electrical Supplies	6951	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load center, Circuit breakers, Load center covers, (1) Pallet Usage: Not Available Asset located in: Humble, TX
	(Unused) S/N: Not Available C/W: Main breakers, circuit breakers, one pallet Usage: Not Available Asset located in: Humble, TX	6952	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in: Humble, TX
6944	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6953	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in: Humble, TX
6945	Asset located in: Humble, TX 945 Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, load	_6954	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in: Humble, TX
	center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6955	Bradford White D100L2503NA Natural Gas 100 gallon Water Heater (Unused) S/N: KE18280909
6946	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet		Usage: Not Available Asset located in: Humble, TX
6947	Usage: Not Available Asset located in: Humble, TX Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, Circuit breakers, (1) Pallet	6956	2006 Trane RTAC2504 Electric Air Cooler S/N: U06C06670 C/W: 3 Phase Motor Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6948	Usage: Not Available Asset located in: Humble, TX Quantity of Square D Electrical Supplies	6957	2000 Trane RTAA1254 Skid Mounted Air Cooler S/N: U00J03518 Usage: Not Available
	(Unused) S/N: Not Available C/W: Main breakers, Circuit breakers, (1) Pallet Usage: Not Available Asset located in : Humble, TX	6958	Asset located in: Humble, TX 1996 Trane RTAA090 Air Cooler S/N: U96K07816 Usage: Not Available Asset located in: Humble, TX
6949	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, one pallet Usage: Not Available Asset located in: Humble, TX	6959	2002 Trane RTAC2504 Electric Air Cooler S/N: U02G05789 C/W: 3 Phase Motor Usage: Not Available Asset located in: Humble, TX
6950	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, load	6960A	2016 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0043001 Usage: Not Available Asset located in: Humble, TX
	center covers, one pallet Usage: Not Available Asset located in : Humble, TX	6960	2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F-0653-008 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6961	2017 Caps PPKH-5TD-0NN20K Air Conditioner S/N: 16F-0680-017 Usage: Not Available Asset located in: Humble, TX	6972	Lennox ML17XC1-060-230A01 Air Conditioner (Unused) S/N: 1922J08536 Usage: Not Available Asset located in: Humble, TX
6962	2011 Goodman CPC060 Skid Mounted Air Conditioner S/N: 1005697488 Usage: Not Available Asset located in: Humble, TX	6973	Lennox ML18XC2-024-230A01 Air Conditioner (Unused) S/N: 1924F02574 Usage: Not Available
6963	2011 Goodman CPC060 Skid Mounted Air Conditioner S/N: 1103726704 Usage: Not Available Asset located in: Humble, TX	6974	Asset located in: Humble, TX Lennox ML18XC2-060-230A01 Air Conditioner (Unused) S/N: 1924D20399 Usage: Not Available
6964	2011 Goodman CPC060 Skid Mounted Air Conditioner S/N: 1103062379 Usage: Not Available Asset located in: Humble, TX	6975	Asset located in: Humble, TX Goodman GSX140481KD Air Conditioner (Unused) S/N: 2009940937 Usage: Not Available Asset located in: Humble, TX
6965	2010 Goodman CPC060 Skid Mounted Air Conditioner S/N: 802039059 Usage: Not Available Asset located in: Humble, TX	6976	Lennox EL16XC1-018-230A01 Air Conditioner (Unused) S/N: 5820E01177 Usage: Not Available Asset located in: Humble, TX
6966	Carrier 50TC Air Conditioner S/N: 3216P35809 Usage: Not Available Asset located in: Humble, TX	6977	Lennox EL16XC1-018-230A01 Air Conditioner (Unused) S/N: 5820J07371 Usage: Not Available
6967	2010 Goodman CPC060 Skid Mounted Air Conditioner S/N: 802039053 Usage: Not Available Asset located in: Humble, TX	6978	Asset located in: Humble, TX Lennox EL16XC1-018-230A01 Air Conditioner (Unused) S/N: 5820K11084
6968	Carrier 50TC Air Conditioner S/N: 2816P67978 Usage: Not Available	6979	Usage: Not Available Asset located in: Humble, TX Lennox EL16XC1-018-230A01 Air Conditioner (Unused)
6969A	Asset located in: Humble, TX Trane Air Conditioner S/N: Not Available Usage: Not Available	6980 6981 6982	(Unused) S/N: 5820K09981 Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Lennox EL16XC1-018-230A01 Air Conditioner (Unused) S/N: 5820L01900
6969	Carrier 50HC Air Conditioner S/N: 2013G30113 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX Trane XE1200 Air Conditioner S/N: Not Available
6970	Lennox ML14XC1-048-230A06 Air Conditioner (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: 1920B03149 Usage: Not Available Asset located in: Humble, TX		Lennox CBA250H-018-230-01 Air Conditioner (Unused) S/N: 1520K14245
6971	Lennox ML17XC1-036-230A01 Air Conditioner (Unused) S/N: 1923B02859 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6983	2017 Caps PPKH-10TD-0NN36 Air Conditioner S/N: 16F-0676-016 Usage: Not Available Asset located in : Humble, TX	6999	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00249 Usage: Not Available Asset located in : Humble, TX
6984	Quantity of (2) Pallets of AC Units S/N: Not Available C/W: Assorted Size Usage: Not Available	7000	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00612 Usage: Not Available Asset located in: Humble, TX
6985	Asset located in: Humble, TX 2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00337 Usage: Not Available	- 7001	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00637 Usage: Not Available Asset located in : Humble, TX
6987	Asset located in: Humble, TX 2017 MovinCool ClimatePro12 Air Conditioner S/N: 10160524H12 Usage: Not Available Asset located in: Humble, TX	-7002	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00236 Usage: Not Available Asset located in: Humble, TX
6988	Asset located in: Humble, TX 2016 MovinCool ClimatePro12 Air Conditioner S/N: 02160159H12 Usage: Not Available Asset located in: Humble, TX	-7003	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00590 Usage: Not Available Asset located in: Humble, TX
6989	Asset located in: Humble, TX 2016 MovinCool ClimatePro12 Air Conditioner S/N: 09150017H12 Usage: Not Available	-7004	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00196 Usage: Not Available Asset located in: Humble, TX
6991	Asset located in: Humble, TX 2012 MovinCool CP-X14 Air Conditioner S/N: 12213135X14 Usage: Not Available	- 7005	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00827 Usage: Not Available Asset located in : Humble, TX
6992	Asset located in: Humble, TX 2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0653006 Usage: Not Available	- 7006	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00714 Usage: Not Available Asset located in : Humble, TX
6993	Asset located in: Humble, TX 2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0653009 Usage: Not Available	- 7007	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00559 Usage: Not Available Asset located in: Humble, TX
6994	Asset located in: Humble, TX 2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0653014 Usage: Not Available Asset located in: Humble, TX	- 7008	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00298 Usage: Not Available Asset located in: Humble, TX
6996	2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0653005 Usage: Not Available	-7009	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00899 Usage: Not Available Asset located in: Humble, TX
6997	Asset located in: Humble, TX 2016 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0043006 Usage: Not Available Asset located in: Humble, TX	-7010	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00250 Usage: Not Available Asset located in: Humble, TX
6998	2015 Air Comman AC1600 Air Cooler S/N: AC29 Usage: 124 Hr	-7011	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00642 Usage: Not Available Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7012	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00698 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7013	2019 Airrex HSC-14 Air Conditioner	7027	2019 Airrex HSC-14 Air Conditioner
	S/N: 14HGSD00683 Usage: Not Available		S/N: 14GSD00024 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7014	2019 Airrex HSC-14 Air Conditioner	7028	2019 Airrex HSC-14 Air Conditioner
	S/N: 14HGSD00616		S/N: 14GSD00603
	Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
7015	Asset located in: Humble, TX 2019 Airrex HSC-14 Air Conditioner	7029	2019 Airrex HSC-14 Air Conditioner
7015	S/N: 14HGSD00643	/029	S/N: 14HGSD00651
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
7016	2019 Airrex HSC-14 Air Conditioner	7030	2019 Airrex HSC-14 Air Conditioner
	S/N: 14GSD00790 Usage: Not Available		S/N: 14HGSD00596 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7017	2019 Airrex HSC-14 Air Conditioner	7031	2018 Airrex HSC-14 Air Conditioner
	S/N: 14HGSD00707		S/N: 14HGRD00356
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
7018	2019 Airrex HSC-14 Air Conditioner	7032	2018 Airrex HSC-14 Air Conditioner
,,,,,	S/N: 14HGSC00414	/ 002	S/N: 14HGRD00152
	Usage: Not Available		Usage: Not Available
7010	Asset located in: Humble, TX	7000	Asset located in: Humble, TX
7019	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00538	7033	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00323
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7020	2019 Airrex HSC-14 Air Conditioner	7034	2018 Airrex HSC-14 Air Conditioner
	S/N: 14HGSD00546 Usage: Not Available		S/N: 14HGRE00821 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7021	2019 Airrex HSC-14 Air Conditioner	7035	2018 Airrex HSC-14 Air Conditioner
	S/N: 14GSD00584		S/N: 14HGRE00762
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
7022	2019 Airrex HSC-14 Air Conditioner	7036	2018 Airrex HSC-14 Air Conditioner
/ • = =	S/N: 14HGSC00210		S/N: 14HGDA00096
	Usage: Not Available		Usage: Not Available
7000	Asset located in: Humble, TX	7007	Asset located in: Humble, TX
7023	2019 Airrex HSC-14 Air Conditioner S/N: 14HGRE00806	7037	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00372
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7024	2019 Airrex HSC-14 Air Conditioner	7038	2018 Airrex HSC-14 Air Conditioner
	S/N: 14HGSD00737 Usage: Not Available		S/N: 14HGRD00410 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7025	2019 Airrex HSC-14 Air Conditioner	7039	2018 Airrex HSC-14 Air Conditioner
	S/N: 14HGSC00234		S/N: 14HGRD00069
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
7026	2019 Airrex HSC-14 Air Conditioner	7040	2018 Airrex HSC-14 Air Conditioner
,	S/N: 14HGSC00203		S/N: 14HGRD00481
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX	1	Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7041	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00834	7055	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00049
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7042	2018 Airrex HSC-14 Air Conditioner	7056	2017 Airrex HSC-14 Air Conditioner
	S/N: 14HGRE00794 Usage: Not Available		S/N: 14HGQD00145 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7043	2018 Airrex HSC-14 Air Conditioner	7057	2017 Airrex HSC-14 Air Conditioner
	S/N: 14HGRE00737		S/N: 14HGDA00078
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
7044	2018 Airrex HSC-14 Air Conditioner	7058	2017 Airrex HSC-14 Air Conditioner
/044	S/N: 14HGRE00808	/ 000	S/N: 14HGQD00064
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7045	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00363	7059	2016 Airrex HSC-14 Air Conditioner S/N: 14HGFC00052
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7046	2018 Airrex HSC-14 Air Conditioner	7060	2016 Airrex HSC-14 Air Conditioner
	S/N: 14HGRE00682 Usage: Not Available		S/N: 14HGFC00014 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7047	2018 Airrex HSC-14 Air Conditioner	7061	2015 Airrex HSC-14 Air Conditioner
	S/N: 14HGRE00784		S/N: 14HGEC00089
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
7048	2018 Airrex HSC-14 Air Conditioner	7062	2015 Airrex HSC-14 Air Conditioner
/010	S/N: 14HGRD00386	/ 002	S/N: 14HGEC00022
	Usage: Not Available		Usage: Not Available
70.40	Asset located in: Humble, TX	7060	Asset located in: Humble, TX
7049	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00023	7063	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00124
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7050	2017 Airrex HSC-14 Air Conditioner	7064	2015 Airrex HSC-14 Air Conditioner
	S/N: 14HGQD00041 Usage: Not Available		S/N: 14HGEC00034 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7051	2017 Airrex HSC-14 Air Conditioner	7065	2015 Airrex HSC-14 Air Conditioner
	S/N: 14HGQD00070 Usage: Not Available		S/N: 14HGEC00010 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7052	2017 Airrex HSC-14 Air Conditioner	7066	2015 Airrex HSC-14 Air Conditioner
	S/N: 14HGDA00067		S/N: 14HGEC00084
	Usage: Not Available Asset located in : Humble, TX		Usage: Not Available Asset located in: Humble, TX
7053	2017 Airrex HSC-14 Air Conditioner	7067	2014 Airrex HSC-14 Air Conditioner
,	S/N: 14HGDA00021		S/N: US14BC00191
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7054	2017 Airrex HSC-14 Air Conditioner S/N: 14HGQD00146	7068	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00260
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7069	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00288 Usage: Not Available	7083	2018 MovinCool ClimatePro12 Air Conditioner S/N: 07170869H12 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7070	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00224 Usage: Not Available Asset located in : Humble, TX	7084	2018 MovinCool ClimatePro12 Air Conditioner S/N: 05180281H12 Usage: Not Available Asset located in: Humble, TX
7071	2014 Airrex HSC-14 Air Conditioner	7085	2018 MovinCool ClimatePro12 Air Conditioner
/0/1	S/N: 14HGDC00135 Usage: Not Available	7085	S/N: 12171368H12 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7072	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00099 Usage: Not Available Asset located in: Humble, TX	7086	2017 MovinCool ClimatePro12 Air Conditioner S/N: 01170051H12 Usage: Not Available Asset located in: Humble, TX
7073	2016 Airrex HSC14-IND Air Conditioner S/N: 14HGCD00099 Usage: Not Available Asset located in : Humble, TX	7087	2017 MovinCool ClimatePro12 Air Conditioner S/N: 03170273H12 Usage: Not Available Asset located in: Humble, TX
7074	2016 Airrex HSC14-IND Air Conditioner S/N: US14BC00143 Usage: Not Available	7088	2016 MovinCool ClimatePro12 Air Conditioner S/N: 02160207H12 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7075	2018 Airrex HWC-19 Air Conditioner S/N: UW19RE00030 Usage: Not Available Asset located in: Humble, TX	7089	2016 MovinCool ClimatePro12 Air Conditioner S/N: 03160292H12 Usage: Not Available Asset located in: Humble, TX
7076	2017 Airrex HWC-19 Air Conditioner S/N: UW19QD00039 Usage: Not Available	7090	2016 MovinCool ClimatePro12 Air Conditioner S/N: 03160298H12 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7077	2017 Airrex HWC-19 Air Conditioner S/N: UW19QD00024 Usage: Not Available Asset located in: Humble, TX	7091	2017 MovinCool Office Pro 36 Air Conditioner S/N: 08170291360 Usage: Not Available Asset located in: Humble, TX
7078	2015 Airrex HWC-19 Air Conditioner S/N: UW19DC00006 Usage: Not Available Asset located in: Humble, TX	7092	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180416H12 Usage: Not Available Asset located in: Humble, TX
7079	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00117 Usage: Not Available Asset located in: Humble, TX	7093	2018 MovinCool ClimatePro12 Air Conditioner S/N: 03170189H12 Usage: Not Available Asset located in: Humble, TX
7080	2014 Airrex HWC-19 Air Conditioner S/N: UW19CD00007 Usage: Not Available Asset located in: Humble, TX	7094	2018 MovinCool ClimatePro12 Air Conditioner S/N: 08171083H12 Usage: Not Available Asset located in: Humble, TX
7081	2018 MovinCool ClimatePro12 Air Conditioner S/N: 01170080H12 Usage: Not Available Asset located in: Humble, TX	7095	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180383H12 Usage: Not Available Asset located in: Humble, TX
7082	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180419H12 Usage: Not Available Asset located in: Humble, TX	7096	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180407H12 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7097 7098	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180446H12 Usage: Not Available Asset located in: Humble, TX 2010 Trane TCH300E4 Air Conditioner	7109	Quantity of (4) Reco SC 110 Volt 17 Amp Electric Bearing Heater S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
	S/N: 102010454D Usage: Not Available Asset located in : Humble, TX	7110	Reco BC 220 Volt 30 Amp Electric Bearing Heater
7099	2019 Dewalt DXH190HD Space Heater S/N: LN34069519003893 Usage: Not Available Asset located in: Humble, TX	7111	S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of Assorted - 1/4 in Diameter Argon
7100	Quantity of Tornado Vacuum & Shop Fan S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Hose S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7101	Quantity of Pallet Racking S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7112	Quantity of Assorted - 1/4" Dia Argon Hose S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7102	Blackhawk 67586 2 Ton Portable Engine Hoist S/N: AM12698 Usage: Not Available Asset located in: Humble, TX	7113	Quantity of Vitaulic PFT-510 S/N: Not Available Usage: Not Available
7103	Quantity of Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7114	Asset located in: Humble, TX Quantity of Duct Hose S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7104	Quantity of Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7115	Merrill Bros. ES2600 8 Ton 2"-4" Grip Plate S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7105	Quantity of Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7116	20' x 20' Tent S/N: Not Available C/W: one pallet Usage: Not Available Asset located in : Humble, TX
7106	Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7117	Quantity of (2) ATD 7422W 20 Ton Air Bottle Jacks S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7107	Quantity of 12 Ton Bottle Jacks S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX Quantity of Tru-Cut SDS Max Drill Bits	7118	Quantity of (4) Michigan Pneumatic JAC-3 Vacuum Silicone Dust Extractors (Unused) S/N: Not Available C/W: one pallet Usage: Not Available
, 100	S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7119	Asset located in: Humble, TX Quantity of Assorted 8 ft - 20 ft Endless Slings S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7120	Quantity of Assorted Nylon Slings S/N: Not Available C/W: one pallet Usage: Not Available Asset located in : Humble, TX	7130	Quantity of Pipe Stands S/N: Not Available C/W: one crate Usage: Not Available Asset located in : Humble, TX
7121	SPX Power Team BC 10,000 / 120 Volt Dual Hyd Pump S/N: 2201AX320606 Usage: Not Available Asset located in: Humble, TX	7131	Quantity of Pipe Stands S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX
7122	Quantity of (1) Pallets of Erickson 817-6-LEDSL 120 Volt LED Lights S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7132	Quantity of 55 Gallon Plastic Trash Cans S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX Quantity of 3-Legged V-Head Jack Stands
7123	Quantity of (1) Pallets of Erickson 817-6-LEDSL 120 Volt LED Lights S/N: Not Available C/W: one pallet Usage: Not Available		S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX Quantity of (2) Vitaulic PFT-510 Cordless 18
7124	Asset located in: Humble, TX Quantity of Allmite 7337 3/4 in Hose Reels S/N: Not Available C/W: one pallet Usage: Not Available	7134	Volt Press Tools S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of Campsite Sink/Table
7125	Asset located in: Humble, TX Quantity of DryRod Electric Rod Caddy S/N: Not Available C/W: 15 lb, 120 Volt, One Pallet		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7126	Usage: Not Available Asset located in: Humble, TX Quantity of DryRod Boxes	7136	Quantity of (10) 2024 SKLP SK10 Equipment Seats (Unused) S/N: B44826 Usage: Not Available
, 120	S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7137	Asset located in: Humble, TX Portacool 72 In. Cooling Fan S/N: Not Available
7127	Enerpac CP1000 / CP2000/ CP3000 Power		Usage: Not Available Asset located in: Humble, TX
	Cable Pullers S/N: Not Available C/W: Storage Box Usage: Not Available Asset located in: Humble, TX	7138	Quantity of (4) Lighting Fixtures S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7128	Quantity of Survey Equipment, with Accessories S/N: Not Available C/W: Lecia Wild, Spectra LL500, tripods, Grade Rods Usage: Not Available Asset located in: Humble, TX	7140	Quantity of (6) Generator Set S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7129	Quantity of Lecia Survey Equipment & Accessories S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Humble, TX	7141	Hydraulic Body Frame Repair Kit S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7142	Speeflo Walk-Behind Paint Sprayer & Paint Striper S/N: PL4-1054 C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7153	Quantity of (3) Bottle Carts S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7143	Quantity of Contractor Supplies S/N: Not Available Usage: Not Available Asset located in: Humble, TX	_7154	Quantity of (3) Ridgid 460 Tri Stands S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7144	Quantity of (5) Hanging Lamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7155	Quantity of Contractor Supplies S/N: Not Available C/W: Discharge Hose, Cooler, Assorted parts, (1) Pallet Usage: Not Available
7145	Air Compressor S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7156	Asset located in: Humble, TX Taiko Back Flash Pump 84M3/HX20MTH Water Pump
7146	Electric Pressure Washer S/N: Not Available C/W: Electric Operated Usage: Not Available	-	S/N: A2D8617-2 C/W: 11 kW Engine, Teco 15 hp electric motor Usage: Not Available Asset located in: Humble, TX
7147	Asset located in: Humble, TX Generator Set S/N: 50548	7157	Quantity of Contractor Supplies S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7148	Usage: Not Available Asset located in: Humble, TX 2017 Tsurumi LB-480-62 Electric Submersible Water Pump	7158	Summit Mfg Hand Crank Hose Reel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: 16522148236 Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7159	Quantity of (8) Refrigerant Tank Racks S/N: Not Available C/W: one pallet Usage: Not Available
/149A	Greenlee 555 Series Electric Bender S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7160	Asset located in: Humble, TX Quantity of (2) Tankless Water Heaters S/N: Not Available Usage: Not Available
7149	Spartan 1065 Electric Sewer Snake S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7161	Asset located in: Humble, TX Quantity of EZ Cam E5200 Sewer Camera & Power Winch S/N: Not Available
7150	Quantity of (2) AWC D-1 Wire Reel S/N: D10417203/D10417204 Usage: Not Available		C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Humble, TX
7151	Asset located in: Humble, TX Quantity of (2) AWC D-1 Wire Reel S/N: D10417201/D10417202 Usage: Not Available Asset located in: Humble, TX	7162	Quantity of (4) Contractor Supplies S/N: Not Available C/W: 30 in x 30 in drain pan, sink machine sewer cable, cover drum, shoe covers, chain hoist, Spartan 300 (inoperable), pipe bender, condenser coil, tool box
7152	Quantity of (5) Tri Stands S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: Jackson, Ridgid, one pallet Usage: Not Available Asset located in : Humble, TX	7163	Taiko Back Flash Pump 56M3/Hx20MTH Water Pump S/N: A2D8621-1 C/W: 7.5 kW Engine, Teco 15 hp electric motor Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7164	Quantity of (6) Assorted Hose Reels S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7175	Quantity of Contractor Supplies S/N: Not Available C/W: DeWalt 14 in Chop Saw, Router Table Usage: Not Available
7165	24 in x 47 in Metal Ramp with Winch S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7176	Asset located in: Humble, TX Taiko Back Flash Pump 56M3/Hx20MTH Water Pump S/N: A2D8621-2
7166	Quantity of Contractor Supplies S/N: Not Available C/W: ProFlo Pump kit, PVC, Shop Vac, (1) Pallet Usage: Not Available	7177	C/W: Teco 15 hp electric motor Usage: Not Available Asset located in: Humble, TX Quantity of Contractor Supplies
7167	Asset located in: Humble, TX Quantity of (2) Electric Winches S/N: Not Available		S/N: Not Available C/W: Spartan 100 Sewer Snake Drums, Battery Charger, Parts, (1) Pallet Usage: Not Available
	C/W: Mount Brackets, (1) Pallet Usage: Not Available Asset located in: Humble, TX	7178	Asset located in: Humble, TX Quantity of Contractor Supplies
7168	Quantity of Contractor Supplies S/N: Not Available C/W: Ridgid K45 Drain Cleaners, Milwaukee Electric Drills, Tool Boxes, (1) Pallet Usage: Not Available		S/N: Not Available C/W: Hydraulic Jacks, Fire Extinguishers, Assorted parts, (1) Pallet Usage: Not Available Asset located in : Humble, TX
7169	Asset located in: Humble, TX Quantity of Power Tools S/N: Not Available C/W: Milwaukee Recip Saws, Drill, General Water Leak locator, (1) Pallet	7179	Quantity of Computer Desks (Unused) S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	7180	Quantity of Hand Crank Hose Reels S/N: Not Available C/W: General J-1600 electric high pressure
7170	Quantity of Contractor Supplies S/N: Not Available C/W: wires, stands, one pallet Usage: Not Available Asset located in: Humble, TX		drain cleaner, General CR-300 hose reel, Summit Mfg hose reel Usage: Not Available Asset located in : Humble, TX
7171	Quantity of Contractor Supplies S/N: Not Available Usage: Not Available	-7181	General CR-300 Cart-Reel S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7172	Asset located in: Humble, TX Taiko Back Flash Pump 84M3/HX20MTH Water Pump S/N: A2D8617-1 C/W: Teco 15 hp electric motor Usage: Not Available	-7182	Jet-Set J-2900 High Pressure Water Drain Jet S/N: 161757 C/W: Honda GX390 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7173	Asset located in: Humble, TX Quantity of Contractor Supplies S/N: Not Available C/W: Spartan Sewer Snake Drums, Cooler,	7183	Quantity of (2) General JM-1450-01 Electric Water Jet Drain Hose S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Extension Cord w/Reel, (1) Pallet Usage: Not Available Asset located in : Humble, TX	7184	General J-1600 Electric High Pressure Water Drain Jet Cleaner
7174	Quantity of LYTX Drive Cam Recorders (Unused) S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX		S/N: 159678 C/W: electric Usage: Not Available Asset located in : Humble, TX
		7185	Scotsman C0330MA Ice Machine S/N: 11031320010720 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7186	Scotsman Ice Machine S/N: 16011320012742 Usage: Not Available Asset located in: Humble, TX	7195	Quantity of GE (1) Refrigerator & (1) Stove S/N: Not Available C/W: Four Burner Gas Stove Usage: Not Available Asset located in: Humble, TX
7187	Ice-O-Matic CIM2046HR Ice Machine S/N: 19081280010893 Usage: Not Available Asset located in: Humble, TX	7196B	Crosley CFC224QWA Freezer S/N: WB60546259 Usage: Not Available
7188	Manitowoc ID0452A-161 Ice Machine S/N: 1101248931 Usage: Not Available Asset located in: Humble, TX	7196A	Asset located in: Humble, TX Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available
7189	Hoshizaki Ice Machine S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7196	Usage: Not Available Asset located in: Humble, TX Kenmore Side-By-Side Refrigerator S/N: Not Available Usage: Not Available
7190	Scotsman NS1322A-32 Ice Machine S/N: 14121320010384 C/W: (22 In. Wide, With UNUSED Cart) Usage: Not Available Asset located in: Humble, TX Hewlett-Packard 360 Computer Printers	7197A	Asset located in: Humble, TX Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available Usage: Not Available
	S/N: MY61869031 Usage: Not Available Asset located in : Humble, TX	7198	Asset located in: Humble, TX Quantity of (1) Refrigerator & (1) Stove S/N: Not Available
7192	Hewlett Packard 365 Computer Printers S/N: MY74M2900T Usage: Not Available Asset located in: Humble, TX		C/W: GE Glass Top Electric Stove, Fridgidaire Refrigerator, One Pallet Usage: Not Available Asset located in : Humble, TX
7193	OKI M64S Computer Printers S/N: 7BC3388A Usage: Not Available Asset located in: Humble, TX	7200	Middleby Marshall Pizza Conveyor Oven S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7194B	Quantity of (2) Whirlpool Stainless Steel Side by Side Refrigerator S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7201	Asset located in: Humble, TX 2022 Sierra Range SR-10-60 Natural Gas 60 in Open Burners Range S/N: Not Available Usage: Not Available
7194A	Quantity of (2) Whirlpool Stainless Steel Side by Side Refrigerator S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7203	Asset located in: Humble, TX Quantity of (2) Snack Vending Machines S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7194	Hewlett-Packard 260 Computer Printers S/N: MY41R69007 Usage: Not Available Asset located in: Humble, TX	7204	Vendo 470457005 Soda Vending Machine S/N: 229003 Usage: Not Available Asset located in: Humble, TX
7195B	Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7205	Quantity of (2) True Beverage Coolers S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7195A	Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-7206	Bradford White D100L2503NA Natural Gas 100 Gallon Water Heater S/N: KD18168659 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7207	Bradford White D80L399E3NA Natural Gas 80 Gallon Water Heater S/N: KA17646143 Usage: Not Available Asset located in: Humble, TX	7214	Lennox EL196UH045XE36B-01 Furnace (Unused) S/N: 5919J02491 Usage: Not Available Asset located in: Humble, TX
7208C	Quantity of (2) Whirlpool Stainless Steel Gas Ranges S/N: Not Available C/W: 5 Burners Usage: Not Available Asset located in: Humble, TX	7215	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5920H08834 Usage: Not Available Asset located in: Humble, TX
7208B	Quantity of (2) GE Stainless Steel Gas Ranges S/N: Not Available C/W: 4 Burners Usage: Not Available Asset located in: Humble, TX	-7216	Lennox EL196UH045XE36B-01 Furnace (Unused) S/N: 5920H08831 Usage: Not Available Asset located in: Humble, TX
7208A	Quantity of (2) GE Stainless Steel Gas Ranges S/N: Not Available C/W: 4 Burners Usage: Not Available Asset located in: Humble, TX	-7217	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02496 Usage: Not Available Asset located in: Humble, TX
7208	Bradford White D80L399E3NA Natural Gas 80 Gallon Water Heater S/N: KD18209520 Usage: Not Available Asset located in: Humble, TX	7218	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02486 Usage: Not Available Asset located in: Humble, TX
7209A	Quantity of (2) Whirlpool Stainless Steel Gas Ranges S/N: Not Available C/W: 5 Burners Usage: Not Available Asset located in: Humble, TX	7219	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02489 Usage: Not Available Asset located in: Humble, TX Lennox EL196UH045XE36B-01 Coils & Furnace
7209	Quantity of (2) Scotsman Touchfree Ice/Water Dispensers S/N: Not Available Usage: Not Available		(Unused) S/N: 5919J02490 Usage: Not Available Asset located in : Humble, TX
7210	Asset located in: Humble, TX Lennox CHX35-15/61C-6F-10 Coils & Furnace S/N: 1523L32357 Usage: Not Available Asset located in: Humble, TX	_7221	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5920H08835 Usage: Not Available Asset located in: Humble, TX
7211	Lennox CHX35-24A-6F-10 Coils & Furnace S/N: 1524D21415 Usage: Not Available Asset located in: Humble, TX	7222	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5918M07113 Usage: Not Available Asset located in: Humble, TX
7212	Lennox CX35-60C-6F-20 Coils & Furnace S/N: 1524C10791 Usage: Not Available Asset located in: Humble, TX Lennox EL196UH045XE36B-01 Coils & Furnace	7223	Goodman GM9S800803BNAA Coils & Furnace (Unused) S/N: 2208144387 Usage: Not Available
, 210	(Unused) S/N: 5918L01732 Usage: Not Available Asset located in: Humble, TX	7224	Asset located in: Humble, TX Goodman GM9S800803BNAA Coils & Furnace (Unused) S/N: 2208100905 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7225	Goodman GM9S800804CNAA Furnace (Unused) S/N: 2207421296 Usage: Not Available Asset located in: Humble, TX	7238	Hydraulic Control Panel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7226	Goodman GMES800604BNAA Coils & Furnace (Unused) S/N: 2104243911 Usage: Not Available Asset located in: Humble, TX	7240	Parker Hydraulic Hose Fabrication Machine S/N: Not Available C/W: hose, fittings Usage: Not Available Asset located in: Humble, TX 2016 Treater Kill Truck Body
7227	Goodman GMVC800603BNAA Furnace (Unused) S/N: 2209008947 Usage: Not Available	7241	S/N: 20160401 Usage: Not Available Asset located in: Humble, TX Pedestal Mount Material Handler
7228	Asset located in: Humble, TX Goodman GMVC800804CNAC Coils & Furnace (Unused) S/N: 2102515397	7242	S/N: 050528 Usage: Not Available Asset located in: Humble, TX Concrete Wash Out Box
7229	Usage: Not Available Asset located in: Humble, TX Lennox ML180UH070E36B-58 Furnace		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7230	S/N: 1723B21169 Usage: Not Available Asset located in: Humble, TX Lennox ML180UH070E36B-58 Furnace	7243	Durst Hydraulic Pumps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7230	S/N: 1723B21156 Usage: Not Available Asset located in: Humble, TX Quantity of (7) 16 ln x 30 ln Job Site Box	7244 7245 7246	Quantity of (4) Electric Motor S/N: Not Available C/W: Baldor 2 hp, Baldor Super E 30 hp, Dayton 10 hp, Siemens 55 hp, two pallets
7231	S/N: Not Available C/W: one pallet		Usage: Not Available Asset located in: Humble, TX
7232	Usage: Not Available Asset located in: Humble, TX Quantity of (3) Electric Floor Scrubbers S/N: Not Available		Quantity of (3) Electric Motor S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	C/W: (2) Windsor, (1) Tennant Usage: Not Available Asset located in : Humble, TX		DPF S/N: Not Available Usage: Not Available
7235	Quantity of (4) Vacuum Pumps S/N: Not Available C/W: (2) Fruitland, (2) NVE Usage: Not Available Asset located in: Humble, TX	7247	Asset located in: Humble, TX Parker PTO S/N: Not Available C/W: one box Usage: Not Available
7236B	Gasoline 72 In Portable Yard Chain Saw S/N: Not Available C/W: Honda GX630 2-cylinder Usage: Not Available Asset located in: Humble, TX	7248	Asset located in: Humble, TX Forrest 648 Shear S/N: F00965 Usage: Not Available Asset located in: Humble, TX
7236A	Oregon 520-120 Chain Saw Sharpener S/N: 682621 Usage: Not Available Asset located in : Humble, TX	7249	Electric Scissor Lift S/N: Not Available C/W: Solid Non-Marking Tires Usage: Not Available
7236	Saw Stop CNS175 Table Saw S/N: C123401263 C/W: 10 in Blade Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7250	Quantity of Freight Elevator Screens S/N: Not Available C/W: uprights Usage: Not Available Asset located in: Humble, TX	7263	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available
7252	Greenlee 556 Electric Pipe Bending Machine S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7264	Asset located in: Humble, TX Quantity of (2) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX Quantity of (5) Bundle of 7 ft x10 ft Wire Re- Mesh
7253	Quantity of 1 1/2 Ton Chain Hoists and (1) Self- dumping Hopper S/N: Not Available C/W: Self-dumping Hopper Usage: Not Available	7265	
7254	Asset located in: Humble, TX Gleason S281002 Hose Reel S/N: GU0178802 Usage: Not Available		S/N: Not Available C/W: 7 Ft x10 Ft Usage: Not Available Asset located in : Humble, TX
7256	Asset located in: Humble, TX Quantity of Assorted Sockets S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX	7266	Quantity of (3) Bundles of 7 ft x10 ft Wire Re- Mesh S/N: Not Available C/W: 7 ft x10 ft Usage: Not Available Asset located in: Humble, TX
7257	Current Tools 452 Electric 1/2 in - 6 in PVC Heater S/N: 2509 Usage: Not Available Asset located in: Humble, TX	7267	Quantity of (3) Bundles of 7 ft x10 ft Wire Re- Mesh S/N: Not Available C/W: 7 ft x10 ft Usage: Not Available Asset located in: Humble, TX
7258	Quantity of (4) 20,000 lb Heavy Duty Aluminum Ramps S/N: Not Available C/W: load levelers Usage: Not Available Asset located in: Humble, TX	7268	Quantity of (3) Bundles of 8 ft x 4 ft Wire Re- Mesh S/N: Not Available C/W: 8 ft x 4 ft Usage: Not Available Asset located in: Humble, TX
7259	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX	7269	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 ft x 8 ft Usage: Not Available Asset located in: Humble, TX
7260	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX	7270	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX
7261	Quantity of (3) Bundles of Wire Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX	7271	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available
7262	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7272	Quantity of (2) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX	7282	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7273	Quantity of (4) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available	-7283 7284	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (16) 3 5/8 in Square 12 Gauge
7274	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available	7285	Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (16) 3 5/8 in Square 12 Gauge
7275	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available	-	Steel (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7276	C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re-	7286	Quantity of (16) 3 5/8 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in : Humble, TX	7287	Quantity of (25) 2 3/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available
7277	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX	7288	Asset located in: Humble, TX Quantity of (25) 2 3/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7278	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX	7289	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7279	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7290	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7280	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7291	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7281	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7292	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7293	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7305	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7294	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7306	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7295	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7307	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7296	Quantity of (25) 2 3/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7308	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7297	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7309	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7298	Quantity of (10) 3 1/2 In Square Tubing S/N: Not Available C/W: one bundle Usage: Not Available Asset located in: Humble, TX	7310	Quantity of (61) 1 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7299	Quantity of 3-1-2" Square Tubing S/N: Not Available C/W: Assorted Length, One Bundle Usage: Not Available Asset located in: Humble, TX	7311	Quantity of (61) 1 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7300	Quantity of 4 In Pipe S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in: Humble, TX	7312	Quantity of (61) 1 5/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7301	Quantity of 4 In Pipe S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in: Humble, TX	7313	Quantity of (2) 3/4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (2) Bundles Usage: Not Available
7302	Quantity of 4 1/2 in Pipe S/N: Not Available C/W: one bundle Usage: Not Available Asset located in: Humble, TX	7314	Asset located in: Humble, TX Quantity of 3/4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles Usage: Not Available
7303	Quantity of 2-3/8 In. x 26 Ft Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7315	Asset located in: Humble, TX Quantity of 3/4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (2) Bundles
7304	2-3/8 Pipe S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7316	Quantity of 4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles Usage: Not Available	7327	Quantity of (4) Bundles of 1 1/2 in x 1/4 in x 20 ft Flat Bar (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7317	Quantity of 1 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles Usage: Not Available Asset located in: Humble, TX	7328	Quantity of (4) Bundles of 1 1/4 in x 1/4 in x 20 ft Flat Bar (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7318	Quantity of (3) 20 ft Angle Iron (Unused) S/N: Not Available C/W: (2) Bundles of 2 in, (1) Bundle of 1 in Usage: Not Available Asset located in : Humble, TX	7329	Quantity of (3) Bundles of 1 1/2 in x 1/4 in x 20 ft Flat Bar (Unused) S/N: Not Available C/W: (1) Bundle of Angle Iron Usage: Not Available
7319	Quantity of 1 in x 20 ft Angle Iron (Unused)		Asset located in: Humble, TX
7000	S/N: Not Available C/W: (3) Bundles Usage: Not Available Asset located in: Humble, TX	7330	Quantity of (3) Bundles of 1 1/2 n x 1/4 in x 20 ft Flat Bars (Unused) S/N: Not Available Usage: Not Available
7320	Quantity of 1 1/2 in x 40 ft Angle Iron (Unused) S/N: Not Available		Asset located in: Humble, TX
	C/W: (1) Bundles Usage: Not Available Asset located in: Humble, TX	7331	Quantity of (3) Bundles Of 1 1/2 In. x 1/4 In. x 20 Ft Flat Bars (Unused) S/N: Not Available Usage: Not Available
7321	Quantity of (2) Bundles of Angle Iron (Unused)		Asset located in: Humble, TX
7322	S/N: Not Available C/W: (1) Bundle of 3 in, (1) Bundle of 5 in Usage: Not Available Asset located in: Humble, TX Quantity of (3) 5 in x 20 ft Angle Iron (Unused)	7332	Quantity of (4) Bundles Of 20 Ft Flat Bar (Unused) S/N: Not Available C/W: (2) bundles of 3/4 in., (2) bundles of 1 1 /2 in.
	S/N: Not Available C/W: (3) Bundles Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7333	Quantity of 8 In. x 1/2 In. x 20 Ft Flat Bar (Unused)
7323	Quantity of 2 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (1) Bundles		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7334	Quantity of (2) Bundles of 1 1/2 In. x 20 Ft Flat
7324	Quantity of (2) Bundles of 2 In. x 20 Ft Angle Iron (Unused) S/N: Not Available Usage: Not Available		Bar (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7335	Quantity of (2) Bundles Of 1 1/2 In. x 20 Ft Flat
7325	Quantity of 5 In. x 20 Ft Angle Iron (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Bar (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7326		7336	Quantity of (2) Bundles Of 1 1/2 In. x 20 Ft Flat Bar (Unused) S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	7337	Quantity of (3) Bundles of 1 1/2 in x 1 1/2 in x 1 /8 in A36/529-50 24 ft Angle Iron (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7338	Quantity of (2) Bundles of 1 1/2 in x 1 1/2 in x 1 /8 in A36/529-50 40 ft Angle Iron (Unused) S/N: Not Available Usage: Not Available	7349	Quantity of (2) Bundles of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7339	Quantity of (2) Bundles of 4 In. x 44 Ft Standard I Beams (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7350	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7340	Quantity of (2) Bundles of 4 In. x 44 Ft Standard I Beams (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7351	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7341	Quantity of Bundles of 4 In. x 44 Ft Standard I Beams (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7352	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7342	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7353	Quantity of (2) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7343	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7354	Quantity of (3) Bundles of Rebar DA- 615 G60 C1 1/2" 40ft P02 R S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7344	Quantity of (2) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7355	Quantity of 5 In x 2 In Tubing S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in: Humble, TX
7345	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7356	Quantity of 4 In Pipe S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in : Humble, TX
7346	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7357	Quantity of 4 1/2 In Pipe S/N: Not Available C/W: assorted length, one bundle Usage: Not Available Asset located in : Humble, TX
7347	Quantity of (3) Bundles Of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available	7358	Quantity of 2-3/8 Pipe (Unused) S/N: Not Available C/W: 12 ft & 14 ft Usage: Not Available Asset located in : Humble, TX
7348	Asset located in: Humble, TX Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-7359	Quantity of 2-3/8 In. x 20 ft Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7360	Quantity of (13) Pallets of Metal Building Components S/N: Not Available C/W: corrugated metal, roll up doors, end caps Usage: Not Available Asset located in: Humble, TX	7371	2013 Current Tools 8890A Cable Puller and Tensioner S/N: PBD3225 Usage: Not Available Asset located in: Humble, TX
7361	Quantity of Log Posts S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-7372	Quantity of Klutch Brake & Slip Roller S/N: Not Available C/W: 48 in box & pan brake, 52 in slip roller, one pallet Usage: Not Available Asset located in: Humble, TX
7362	Quantity of 2-3/8 In. x 20 ft Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7373	Quantity of Ridgid Pony Threaders & Work Lights S/N: Not Available
7363	2020 Trinity 45KVA Transformer S/N: 2001513 Usage: Not Available Asset located in: Humble, TX	7374	C/W: one pallet Usage: Not Available Asset located in: Humble, TX Quantity of Contractor Supplies
7364	Quantity of 6 In. x 7 Ft Steel Channel (Unused) S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Stanley tool box, hose, scissor jacks, safety netting, one pallet Usage: Not Available
7065	Asset located in: Humble, TX	7075	Asset located in: Humble, TX
7365	Quantity of (3) Spill Containment Pallets S/N: Not Available C/W: 48 in x 48 in Usage: Not Available Asset located in: Humble, TX	7375	Quantity of Misc. Surplus Supplies S/N: Not Available C/W: Nail Guns, Bolts, Mirrors DeWalt Cordless Vacuum, Outlets Usage: Not Available
7366	AWS Quik Feed T/A 4.5 ton Feed Trailer		Asset located in: Humble, TX
	S/N: Not Available C/W: Ball Hitch, Torsion Axle, 235/85R16 Tires, 7 ft Body, 235/85R16 Tires, Howden 33 URAI Blower Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	7376	Quantity of Misc. Surplus Building Supplies S/N: Not Available C/W: Hose, Electrical Wire, Fluorescent Light Bulbs, Mop, Pictures, Baskets, Metal Shelf, Pole Saw Usage: Not Available Asset located in: Humble, TX Saw Stop 10 In. Table Saw
7367	2008 Fort Knox Defender Gun Safe S/N: 6637 C/W: Fireproof 37 in Wide x 66 in High x 27 in Deep	7377 7378	S/N: 1170900427 Usage: Not Available Asset located in: Humble, TX Quantity of (5) Roll-Up Cabinets
7368	Usage: Not Available Asset located in: Humble, TX Quantity of (4) Enerpac 400 Ton Ram w/ 6" Stroke		S/N: Not Available C/W: (2) Pallets Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7379	York 30 In x 35 In x 47 In Safe S/N: Not Available Usage: Not Available
7369	Quantity of (12) Ericson # 1067-BLC Buzz Boxes Ericson (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7383	Asset located in: Humble, TX Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX
7370	Quantity of (4) Boxes of Dearman # D249 Pipe	1	Asset located in: Midland, TX
	Alignment Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7384	Quantity of (4) Workshop Work Table S/N: Not Available Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX

Lot #	Details	Lot #	Details
7386	Portable Cool Boss CB-30L Evaporative Cooler S/N: 24443001126 Usage: Not Available Asset located in: Humble, TX	7399	300 gal Poly DEF Tank S/N: Not Available C/W: 120 V Transfer Pump Usage: Not Available Asset located in : Humble, TX
7387	Ridgid 12 in Miter Saw S/N: U043549453 Usage: Not Available Asset located in : Humble, TX	7400	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B43489
7388	Quantity of Ladders & Scaffolding S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7389	Quantity of Wet Saw & Buckets Of Trowels S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7401	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B44824 C/W: THE PRODUCT IMAGES SHOWN ARE
7390	Quantity of (2) Pneumatic Floor Nailers S/N: Not Available C/W: Husky, Numax Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7391	Asset located in: Humble, TX Quantity of Dehumidifier & Fan S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-7402	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B43490 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7392	Quantity of Light Bulbs (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		
7393	Quantity of (60) Plastic Road Barrels S/N: Not Available Usage: Not Available Asset located in: Humble, TX	- 7403	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B44825 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7394	Quantity of (2) Keen K450 Electric Rod Ovens S/N: 915337/915344 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7404	Quantity of (200) 2024 KJ K0310 Corrugated Galvalume Sheets Steel Plates (Unused)
7395	Quantity of (3) Bottle Carts S/N: Not Available C/W: (2) Sumner, (1) Harper Usage: Not Available Asset located in : Humble, TX	1	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7396	Quantity of (2) 45 In x 60 In Aluminum Covers S/N: Not Available	7405	Asset located in: Humble, TX Quantity of (200) 2024 KJ K0310 Corrugated
	Usage: Not Available Asset located in: Humble, TX	_	Galvalume Sheets Steel Plates (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7397	Power Breezer Misting Fan S/N: 52000019 Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7398	Quantity of (2) Crates of Fall Protection		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7406	Quantity of (200) 2024 KJ K0310 Corrugated Galvalume Sheets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7413	Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7407	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7414	Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7408	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7415 7416	Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused)
7409	Asset located in: Humble, TX Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7417	Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7410	Asset located in: Humble, TX Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	7418	Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	7419	Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7411	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7420	Quantity of Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	7421	Quantity of (50) 2024 KJ K0415 Hot Dip Galvanized Guardrail (Unused) S/N: Not Available
7412	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		C/W: 162 ft 5 in x 20 in, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7422 Quantity of (50) 2024 KJ K0415 Hot Dip Galvanized Guardrail (Unused) S/N: Not Available C/W: 162 ft 5 in x 20 in, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION	7433	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
7423	PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7434	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7423	7423 Quantity of (50) 2024 KJ K0415 Hot Dip Galvanized Guardrail (Unused) S/N: Not Available C/W: 162 ft 5 in x 20 in, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL	7435	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	PRODUCT Usage: Not Available Asset located in: Humble, TX	7436	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused) S/N: Not Available
7424	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7437	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused)
7425	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7426	Asset located in: Humble, TX Quantity of 2 in x 8 in x 20 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	_7438	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7427	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7439	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7428	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7440	Quantity of (7) Pallets of Landscape Sandstone S/N: Not Available Usage: Not Available
7429	Quantity of 2 in x 8 in x 20 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7441	Asset located in: Humble, TX Quantity of (7) Pallets of Landscape Sandstone Boulders S/N: Not Available
7430	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7442	Quantity of (6) Assorted Material Racks S/N: Not Available
7431	Quantity of Bundles of 2 In. x 4 In. x 13 Ft Lumber (Unused) S/N: Not Available		C/W: (1) set of 30 ln x 117 ln, (1) set of 36 ln x 168 ln, (1) set of 36 ln x 156 ln Usage: Not Available Asset located in : Humble, TX
C/W: 2 B Usage: N	C/W: 2 Bundles of 2 In. x 4 In. x 13 Ft Usage: Not Available Asset located in : Humble, TX	7443	Quantity of (6) 38 In x 110 In Steel Material Racks
7432	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7444	Quantity of (4) Material Racks S/N: Not Available C/W: (1) set of 38 in x 194 in, (1) set of 38 in x 94 in Usage: Not Available Asset located in: Humble, TX	7454	2024 Landhonor LHR-GAC40Y 20.6 cfm 40 gal Air Compressor (Unused) S/N: Not Available C/W: Briggs & Stratton XR 1 Cylinder 10 hp 306 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7445	Quantity of (10) Bundles of Crossties S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7455	2024 Landhonor LHR-GAC40T 20.6 cfm 40 gal Air Compressor (Unused) S/N: Not Available
7446	Quantity of (2) 16 Ft Pipeline Skids S/N: Not Available Usage: Not Available Asset located in : Humble, TX		C/W: Briggs & Stratton XR 1 Cylinder 10 hp 306 cc Gasoline Engine Usage: Not Available Asset located in : Humble, TX
7447	24 Ft Pipeline Skids S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7456	Eagle 9G30TRKE-H 18.5 cfm Skid-Mounted 30 gal Air Compressor (Unused) S/N: Not Available C/W: 150 psi Working Pressure, Honda GX270 1 Cylinder 9 hp Gasoline Engine Usage: Not Available
7448	Quantity of (2) Bottle Racks S/N: Not Available Usage: Not Available	7457	Asset located in: Humble, TX PowerTrain PT-14G30TRKE-V2 18.5 cfm 30 gal
7449	Asset located in: Humble, TX 16 Ft Pipeline Skids S/N: Not Available C/W: Lumber Usage: Not Available Asset located in: Humble, TX		Air Compressor (Unused) S/N: Not Available C/W: 175 psi Working Pressure, 1 Cylinder 14 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7450	Mega 1205T-ODP 18 cfm Electric 60 gal Air Compressor S/N: 2022011205 C/W: 5 hp Motor Usage: Not Available Asset located in: Humble, TX	7458	Quantity of (2) Makita MAC5200 6.5 cfm Electric 5.2 gal Air Compressor S/N: Not Available C/W: 120V, 3 hp Motor Usage: Not Available Asset located in: Humble, TX
7451	Iron Horse 11.2 cfm Electric 60 gal Air Compressor (Unused) S/N: Not Available C/W: 208/230V, 6.5 hp Motor Usage: Not Available Asset located in: Humble, TX	7459	PowerTrain PR-TT70G 11.2 cfm 10 gal Air Compressor (Unused) S/N: Not Available C/W: 1 Cylinder 7 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7452	2024 Landhonor LHR-GAC60 26.8 cfm 60 gal Air Compressor (Unused) S/N: Not Available C/W: Kohler Command Pro 1 Cylinder 14 hp 429 cc Gasoline Engine Usage: Not Available	7460	Quantity of (2) Makita MAC5200 6.5 cfm 5.2 gal Air Compressor S/N: Not Available C/W: 120V, 3 hp Motor Usage: Not Available Asset located in: Humble, TX
7453	Asset located in: Humble, TX 2024 Landhonor GAC60T 26.8 cfm 60 gal Air Compressor (Unused) S/N: Not Available C/W: 2023 US EPA Label, Loncin 302 cc Gasoline Engine	7461	Quantity of (6) Porter Cable 2.6 cfm 6 gal Air Compressor S/N: Not Available C/W: 120V Usage: Not Available Asset located in: Humble, TX
	Usage: Not Ăvailable Asset located in : Humble, TX	7462	Marathon 30 gal Air Compressor S/N: Not Available C/W: 200 psi Working Pressure, 5 hp Motor Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7463	Ingersoll Rand 20 gal Air Compressor S/N: Not Available C/W: Honda GX200 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7472	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244120 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine
7464	2014 Portacool PAC2K361S Air Compressor S/N: 381701-14		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7473	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244119
7465	2011 Quincy QSI370 Skid-Mounted Electric Air Compressor S/N: BU1104190001 C/W: 300 psi Working Pressure, 3 Phase, 75 hp		C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
	Motor Usage: 21,697 Hr Asset located in : Humble, TX	7474	Easy-Kleen Magnum Gold Pressure Washer (Unused)
7466	2024 Suihe PW Skid-Mounted Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose,	-	S/N: 244116 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Asset located in : Humble, TX	7475	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244121
7467	2024 Suihe PW Skid-Mounted Pressure Washer (Unused) S/N: Not Available		C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Asset located in : Humble, TX	7476	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244115 C/W: 4000 psi Rating, Water Heater, Hose,
7468	2024 KJ AM4000P Pressure Washer (Unused) S/N: Not Available		Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	C/W: 4000 psi Rating, Water Heater, 250 gal Water Supply, Hose, Spray Wand, 429 cc Gasoline Engine, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7477	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244117 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available
7469	Northstar Chemical Spay Rig	-	Asset located in: Humble, TX
	S/N: Not Available C/W: Kohler Command Pro 1 Cylinder Gasoline Engine, 55 gal Poly Tank, Hose, Reel Usage: Not Available Asset located in: Humble, TX	7478	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244122 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available
7470	Northstar Chemical Spay Rig		Asset located in: Humble, TX
	S/N: Not Available C/W: North Star 1 Cylinder Gasoline Engine, 55 gal Poly Tank, Hose, Reel Usage: Not Available Asset located in : Humble, TX	7479	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244114 C/W: 4000 psi Rating, Water Heater, Hose,
7471	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244118 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX		Spray Wand, 1 Cylinder 15 hp Gasoline Engin Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7480	2024 AGT HPW4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, PW420 1 Cylinder 13 hp Gasoline Engine Usage: Not Available	7489	Pressure Washer S/N: Not Available C/W: 2750 psi Rating, Honda GX200 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7481	Asset located in: Humble, TX 2024 AGT HPW4000 Pressure Washer	7490	2024 Powertek CUT-40 40 A Plasma Cutter (Unused) S/N: Not Available
Spray Wand, PW420 1 Cylinder 13 hp			C/W: Single Phase, 120 V/ 240 V Input, Welding Leads Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7491	2024 Powertek CUT-40 40 A Plasma Cutter (Unused)
7482	Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, 1 Cylinder Gasoline Engine Usage: Not Available		S/N: Not Available C/W: Single Phase, 120 V/ 240 V Input, Welding Leads Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	7492	Quantity of (2) 2024 Powertek MMA160 160 A Stick Electric Welder (Unused)
7483	S/N: Not Available C/W: 3200 psi Rating, 1 Cylinder Gasoline Engine		S/N: Not Available C/W: Single Phase, 120 V/ 230 V Input, Welding Leads Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX
7484	Quantity of (5) Murray 3200 PSI 2.5 GPM Pressure Washer S/N: Not Available C/W: Hose, Spray Wand, 1 Cylinder Gasoline Engine	-7493	2022 Lincoln Electric Invertec v276 Multi- Process Electric Welder S/N: U1220506197 C/W: Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7494	2022 Lincoln Electric 275 A Stick Electric
7485	Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, 1 Cylinder 208 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX	 	Welder S/N: U1220506195 C/W: 3 Phase, Single Phase, 208 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX
7486	Quantity of (4) Craftsman Pressure Washer	7502	Quantity of (2) 2024 Landhonor LHR-TWP80
	S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, 1 Cylinder 208 cc Gasoline Engine Usage: Not Available		Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp Gasoline Engine Usage: Not Available
7487	Asset located in: Humble, TX Shark 11038410 Pressure Washer	_	Asset located in: Humble, TX
/40/	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Quantity of (3) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available
7488	Simpson Pressure Washer S/N: 05241020220 C/W: 4400 psi Rating, Hose, Spray Wand, 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		C/W: 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
7504	Quantity of (3) 2024 Powertek PT50C Water Pump (Unused) S/N: Not Available C/W: 2 in Intake, 2 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available	7513	Quantity of (2) Fuel Boss 12 V Fuel Pump (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7514	Metered 12V Diesel Fuel Pump (Unused)
7505	Quantity of (3) 2024 Powertek PT80C Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available	7515	S/N: Not Available Usage: Not Available Asset located in: Humble, TX Fuel Boss Metered Fuel Pump (Unused) S/N: Not Available C/W: 50 ft hose reel, nozzle
	Asset located in: Humble, TX		Usage: Not Available
7506	Quantity of (3) Mustang MP4800 Electric Submersible Water Pump (Unused) S/N: Not Available C/W: 2 in Intake, Submersible Usage: Not Available Asset located in: Humble, TX	7516	Asset located in: Humble, TX Quantity of (4) Champion Inverter 4650 Watts Portable Generator Set S/N: Not Available C/W: 1 Cylinder Dual Fuel Engine Usage: Not Available Asset located in: Humble, TX
7507	Quantity of (3) Mustang MP4800 2 in Electric Submersible Water Pump (Unused) S/N: Not Available C/W: 2 in Intake, Submersible Usage: Not Available Asset located in: Humble, TX	7517A	Smarter Tools STGP7500DEB 6.0 kW Generator Set S/N: GPSD7500202 C/W: 2013 US EPA Label, 1 Cylinder 389 cc Gasoline Engine, /6.0 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V &
7508	2024 Landhonor LHR-DFP10 Transfer Fuel Pump (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		120 V Receptacles Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7509	2024 Landhonor LHR-DFP10 Transfer Fuel Pump (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7517	Quantity of (4) Champion Inverter 4650 Watts Portable Generator Set S/N: Not Available C/W: 1 Cylinder Dual Fuel Engine Usage: Not Available
7510	2024 Agriquip GLDP20 Fuel Pump (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7518	Asset located in: Humble, TX Quantity of (2) Craftsman 5.0 kW 5000 Watt Generator Set S/N: Not Available C/W: 1 Cylinder 306 cc Gasoline Engine, /5.0 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available
7511	2024 Agriquip GLDP20 Fuel Pump (Unused)	1	Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	7519	Quantity of (2) Craftsman 5.0 kW Generator Set S/N: Not Available C/W: Briggs & Stratton 1 Cylinder 306 cc Gasoline Engine, /5.0 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX
7512	Quantity of (2) 2024 Agriquip GLGP20 Fuel Pump (Unused) S/N: Not Available C/W: Hose, Nozzle THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7520	Quantity of (2) Craftsman 5 kW Generator Set S/N: Not Available C/W: Briggs & Stratton 306 cc Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7521	Quantity of (2) Champion 3.5 kW Generator Set S/N: Not Available C/W: Champion 1 Cylinder 224 cc Dual Fuel Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX	7529	Westinghouse 4500 Generator Set S/N: 45A0622B3477 C/W: Gasoline Engine, 120 V / 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Asset located in: Humble, TX
7522	Quantity of (2) Craftsman 5 kW Generator Set S/N: Not Available C/W: Briggs & Stratton 306 cc Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX	7530	Westinghouse iGen 4500 Generator Set S/N: 45A0621B14250 C/W: Gasoline Engine, 120 V / 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7323	Quantity of (5) Pallets of Generators & Pressure Washers S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac, Titan, North Star, Simpson, Ex-Cell, Mi-T-M, Power Ease Usage: Not Available Asset located in: Humble, TX	7531	Asset located in: Humble, TX Westinghouse iGen 4500 Generator Set S/N: 45A0622B3579 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Asset located in: Humble, TX
7524	Westinghouse iGen 4500 Generator Set S/N: 45A0622B3333 C/W: 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Asset located in: Humble, TX	7532	Westinghouse 7500 9.5 kW Generator Set S/N: 75A0621B6717 C/W: 2021 US EPA Label, CARB Compliant, Westinghouse 1 Cylinder 420 cc Gasoline Engine, /9.5 kW, Rated Single Phase Output, 240 V & 120 V Receptacles
7525	Westinghouse iGen 4500 Generator Set S/N: 45A0621B13309 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7533	Usage: Not Available Asset located in: Humble, TX Craftsman 3500 3.5 kW Generator Set (Unused) S/N: 417013857 C/W: Briggs & Stratton 1 Cylinder Engine Usage: Not Available
7526	Westinghouse IGen4500 Generator Set S/N: 45A1221B22693 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7534	Asset located in: Humble, TX Powerhorse 11050 Generator Set S/N: 08212167 C/W: Powerhorse 1 Cylinder 457 cc Gasoline Engine, 120 V / 250 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX
7527	Westinghouse IGen 4500 Generator Set S/N: 45A0621B14275 C/W: Gasoline Engine, / 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7535 7539	2021 Champion 7850 Generator Set S/N: 21MAY1810171 C/W: Champion 1 Cylinder 389 cc Dual Fuel Engine, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX Onan 4KYFA26100D 4 kW Generator Set
7528	Westinghouse IGen4500 Generator Set S/N: 45A0621B14272 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available		S/N: B953335555 C/W: Gasoline Engine, /4 kW, Rated Single Phase Output, 120 V Rated Voltage Usage: Not Available Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7540	2020 International Titan 4000 Hydroxyl Generator S/N: 33634 Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7541	2020 International Titan 4000 Hydroxyl Generator S/N: 33636 Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7551	I 2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
7542	2020 International Titan 4000 Hydroxyl Generator		Usage: Not Available Asset located in : Humble, TX
	S/N: 33633 Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX	7552	Quantity of 2024 Landhonor LHR-RC5400 5400 Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available Usage: Not Available
7543	Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7553	Asset located in: Humble, TX Quantity of 2024 Landhonor LHR-RC5400 5400 Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available Usage: Not Available
7544	Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7554	Asset located in: Humble, TX 2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7545	Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7546	Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7555	Quantity of (6) 5/16 In. Chain Sling S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7547	Quantity of (1) Pallets of 3/8 X 20 in Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available	_7556	Quantity of 2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7548	Asset located in: Humble, TX Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX Quantity of 5/16 in Chains		Quantity of (22) 2024 Suihe WS22 Webbing Sling (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7550	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7558	Quantity of 2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available
7550	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7559	Usage: Not Available Asset located in: Humble, TX Quantity of (24) 2024 Suihe R24 Ratchet
			Straps (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7560	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7566	Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7567	Quantity of (5) 2024 Suihe BC-9200 9200 lb
7561	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7568	Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	/ 500	Quantity of (38) 2024 Suihe S38 Shackle (Unused)
7562	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	7569	Quantity of (5) 2024 SKLP SK001 9200 lb
7563	Asset located in: Humble, TX Quantity of (42) 2024 SKLP SK003 Ratchet Straps (Unused) S/N: B43595 C/W: (32) 2 in x 27 ft, (16) 1.5 in x 27 ft, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTIVAL DROPOLOT	7570	Ratchet Binders & (10) 20 ft Chains (Unused) S/N: B43906 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Quantity of (38) 2024 Suihe S38 Shackle
	ACTUAL PRODUCT Usage: Not Available	/3/0	(Unused)
7564	Asset located in: Humble, TX Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	_	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT	7571	Quantity of 2024 Landhonor LHR-G209
7565	Usage: Not Available Asset located in: Humble, TX Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused)	-	Shackle (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7572	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7573	2024 SKLP SK-LL Laser Level (Unused) S/N: B44827 C/W: grade rod, tripod Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7574	IntelliRock Concrete Tester S/N: Not Available Usage: Not Available Asset located in: Humble, TX HS100 Bolt Tension Calibrator	7584	Wood Tuff 42 in Job Site Box S/N: Not Available C/W: 8 pcs Wokin/Valley tools set, (2) Valley 2 Ton Trolley Jack , (4)-Wokin 3 Ton Jack Stand, (2) Wokin 4 Ton Bottle Jack
/0/0	S/N: Not Available Usage: Not Available		Úśage: Not Available Asset located in: Humble, TX
7576	Asset located in: Humble, TX Nikon DTM-322 Total Station S/N: 815079 Usage: Not Available Asset located in: Humble, TX	7585	Wood Tuff 48 in Job Site Box S/N: Not Available C/W: 7 pcs Cub Cadet tool set, HT24E Hedge Trimmer CS160E Cordless Chainsaw, LB600E Leaf Blower, ST115 String Trimmer, Battery Charger
7577	Nikon NPL-322 Total Station S/N: D025332 Usage: Not Available		Usage: Not Available Asset located in: Humble, TX 2024 Powertek PT9500 Magnetic Drill (Unused)
7578	Asset located in: Humble, TX Quantity of Power Tools & Laser Levels	-	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: Levels, bandsaws, one pallet Usage: Not Available Asset located in : Humble, TX	7587	2024 Powertek G80A Electric Demolition Breaker (Unused) S/N: Not Available Usage: Not Available
7579	Quantity of (8) Spy 725 Pipe Locators S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7588	Quantity of (2) 2024 Powertek PT8810 1 In. Pneumatic Impact Wrench (Unused) S/N: Not Available Usage: Not Available Notes: . Asset located in: Humble, TX
7580	Quantity of (2) Spy 725 Pipe Locator S/N: Not Available C/W: batteries, chargers Usage: Not Available		
	Asset located in: Humble, TX	7589	2019 Hilti DD250E-BS Core Drill - Fits Hilti DD250
7581 Wood Tuff 48 in Job Site Box S/N: Not Available C/W: 15 pcs Craftsman Tool Set, 13" String Trimmer/Edger20 v Max Power Cleaner10" 20 v Cordless Chainsaw20 v Axial Blower 22" 20 v Hedge Trimmer20 v Led Automotive Hood Light20 v Task Light1/4" 20 v Brushless Impact Driver 20 v Led Light /Magnifying Lens1/2" Brushless Hammer Drill Kit 2 Batteries ChargerBag Usage: Not Available	S/N: Not Available C/W: 15 pcs Craftsman Tool Set, 13" String Trimmer/Edger20 v Max Power Cleaner10" 20 v Cordless Chainsaw20 v Axial Blower		S/N: Not Available Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	7590	Quantity of Sandblasting Equipment S/N: Not Available Usage: Not Available Asset located in : Humble, TX	
7582	Asset located in: Humble, TX Wood Tuff 42 in Job Site Box	7591	Quantity of Power Tools S/N: Not Available Usage: Not Available
	S/N: Not Available C/W: 158 pcs Wokin Tool Set, (1) Wokin 132		Asset located in: Humble, TX
	Piece SAE & Metric Tool Chest (1) Workin 13 Piece Combination and Wrench Set (1) Double Ring Spanners Set Usage: Not Available	7592	Quantity of (3) Arcan ALFJ48 3 Ton 48 In. Farm Jack (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7583	Wood Tuff 48 in Job Site Box S/N: Not Available C/W: 25 pcs Makita Power Tool Kit Usage: Not Available Asset located in: Humble, TX	7593	Quantity of (3) Wokin 3 Ton Floor Jack (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7594	Quantity of (2) Valley 22 Ton Air/Hydraulic Service Bottle Jack (Unused) S/N: Not Available Usage: Not Available	7605	Power Tools S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7595	Asset located in: Humble, TX Quantity of (2) Air Conditioner S/N: Not Available Usage: Not Available	7606	Quantity of (3) Metal Detectors S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7596	Asset located in: Humble, TX Quantity of (6) PowerTrain PT240 General Purpose Engine (Unused) S/N: Not Available	7607	Quantity of (1) Crates of Testers and Crimps S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX	7608	Quantity of (1) Pallets of Sockets and Pliers S/N: Not Available Usage: Not Available
7597	Quantity of (6) PowerTrain PT240 General Purpose Engine (Unused) S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7609	Asset located in: Humble, TX Quantity of 2 Unknown or N/A Hose Reels S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7598	Quantity of (4) 1 Gauge Booster Cables (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7610	Quantity of Readout Kit, Hydraulic Tester, Deadweight Tester S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7599	2024 Topcon RL-H5B Rotary Laser Level (Unused) S/N: Not Available C/W: Receiver, Tripod, Grade Rod, Batteries Usage: Not Available Asset located in: Humble, TX Quantity of (10) 14 in Diamond Blades	7611	Quantity of (16) 2024 Agriquip GLWH16 Auto Darkening Welding Helmets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7000	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7612	Asset located in: Humble, TX Quantity of (4) Mr. Heater 60000 BTU Forced Air Space Heater (Unused) S/N: Not Available
7601	Quantity of (3) Neon Signs (Unused) S/N: Not Available C/W: (1) Peterbilt, (2) Caterpillar Usage: Not Available	7613	Usage: Not Available Asset located in: Humble, TX HeatStar HS6000DF 599524 BTU Forced Air Direct Fired Industrial Space Heater S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7602	Asset located in: Humble, TX Quantity of (5) 25 ft 800 amp Booster Cable (Unused)		
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		HeatStar HS6000DF 599524 BTU Forced Air Direct Fired Industrial Space Heater S/N: Not Available
7603	Quantity of Power Tools S/N: Not Available C/W: DeWalt, Stihl, Milwaukee, one pallet Usage: Not Available Asset located in: Humble, TX	7615	Usage: Not Available Asset located in: Humble, TX HeatStar HS6000DF 599524 BTU Forced Air Direct Fired Industrial Space Heater
7604	Asset located III: Humble, TX Quantity of Power Tools S/N: Not Available C/W: Bosch, DeWalt, one pallet Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7616	Quantity of (4) Mr. Heater 60000 BTU Forced Air Space Heater (Unused) S/N: Not Available Usage: Not Available	7625	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
	Asset located in: Humble, TX	_	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7617	2024 Agriquip GLHP50 50 ton Air/Hydraulic Shop Press (Unused)		THE ACTUAL PRODUCT Usage: Not Available
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7626	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available
	Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7618	2024 Landhonor LHR-CIA400 400 lbs Cast Iron Anvil (Unused)		THE ACTUAL PRODUCT Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7627	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused)
7619	2024 Landhonor LHR-CIA400 400 lbs Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7620	2024 Landhonor LHR-CIA200 200 lbs Cast Iron	1	Asset located in: Humble, TX
	Anvil (Unused)	7628	2024 Landhonor LHR-EW20000 20000 lb
	S/N: Not Available	/020	Electric Winch (Unused)
	Usage: Not Available		S/N: Not Available
	Asset located in: Humble, TX	4	C/W: THE PRODUCT IMAGES SHOWN ARE
7621	2024 Suihe A200 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7600	
	THE ACTUAL PRODUCT Usage: Not Available	7629	2024 Powertek WW20000 20000 lb Heavy Duty Electric Wirelss Winch (Unused) S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
7622	2024 Landhonor LHR-CIA200 200 lbs Cast Iron		Asset located in: Humble, TX
	Anvil (Unused) S/N: Not Available	7630	Quantity of (2) 2024 Powertek WW13000 13000 lb Wireless Winch (Unused)
	Usage: Not Available Asset located in : Humble, TX		S/N: Not Available Usage: Not Available
7623	2024 Suihe WW 20000 lb Winch (Unused)		Asset located in: Humble, TX
	S/N: Not Available	7631	Wood Power 12000 lb Electric Winch (Unused)
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		S/N: Not Available
	MAY NOT BE AN EXACT REPRESENTATION OF		Usage: Not Available
	THE ACTUAL PRODUCT		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7632	Quantity of (6) Pallets of Waterproof Snow Gloves (Unused)
7624	2024 Suihe WW 20000 lb Winch (Unused)		S/N: Not Available
	S/N: Not Available		Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	7633	Quantity of (4) Pallets of Waterproof Snow
	THE ACTUAL PRODUCT Usage: Not Available		Gloves (Unused) S/N: Not Available
	Asset located in: Humble, TX		S/N: Not Available Usage: Not Available
		I	Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7634	Quantity of (6) Pallets of Waterproof Snow Gloves (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7643	Quantity of (5) 2024 Powertek 20T 20 Ton Air /Hyd Bottle Jack (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7635	Quantity of (6) Pallets of Waterproof Snow Gloves (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7644	Quantity of (14) A/C Compressors (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7636	Quantity of 2024 HUI NA RC Excavator Toys (Unused) S/N: Not Available Usage: Not Available Notes: .	7645	Golden Technologies BUZZAROUND EX Ride On Electric Mobility Scooter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7637	Asset located in: Humble, TX 2024 Agriquip GLGS40 40 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7646	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7638	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Agriquip GLGS40 40 Gun Safe (Unused)	7647	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7030	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7648	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7639	Asset located in: Humble, TX 2024 Agriquip GLGS14 14 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7649	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7640	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Agriguip GLGS14 14 Gun Safe (Unused)	7650	2024 Landhonor LHR-MG766 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7651	2024 CXT CS1 Massage Chair (Unused) S/N: 6-1 Usage: Not Available Asset located in : Humble, TX
7641	Asset located in: Humble, TX Quantity of (5) 2024 Powertek 300 ft x 2 in Lay Flat Water Hose (Unused)	7652	2024 CXT CS1 Massage Chair (Unused) S/N: 6-2 Usage: Not Available Asset located in : Humble, TX
7642	S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (4) 2024 Powertek 300 ft x 3 in Lay	7653	2024 CXT CS1 Massage Chair (Unused) S/N: 6-3 Usage: Not Available Asset located in: Humble, TX
, 042	Flat Water Hose (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7654	Asset located in: Humble, TX 2024 CXT CS1 Massage Chair (Unused) S/N: 6-4 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7655	2024 CXT CS1 Massage Chair (Unused) S/N: 6-5 Usage: Not Available Asset located in: Humble, TX	7666	Quantity of (2) BarcaLounger Jacque II Leathe Pedestal Chairs (Unused) S/N: Not Available C/W: Ottoman Usage: Not Available
7656	2024 CXT CS1 Massage Chair (Unused) S/N: 6-6 Usage: Not Available		Asset located in: Humble, TX Human Touch Robotic Leather Full-Body
7657	Asset located in: Humble, TX 2024 Human Touch Quies Zero Gravity Massage Chair Recliner S/N: Not Available		Massage Chair Recliner with Heat S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7450	Usage: Not Available Asset located in: Humble, TX	7668	Osaki Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available
7658	2024 Human Touch Certus Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7669	Asset located in: Humble, TX Quantity of (2) Human Touch HT5270 Massage Chair Recliner S/N: Not Available
7659	Human Touch ZeroG Electric Massage Chair Recliner		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7670	BarcaLounger Electric Patient Lift Power Leather Recliner (Unused) S/N: Not Available Usage: Not Available
7660	Human Touch AcuTouch 9500X Leather Full- Body Massage Chair Recliner	7674	Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7671	Svago SV395 Zero Gravity Massage Chair Recliner S/N: Not Available C/W: heat Usage: Not Available Asset located in: Humble, TX
7661	-		
		7672	Human Touch ZeroG 4.0 Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available
7662	Fjords Milan Power Leather Zero Gravity Recliner (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7673 Quantity of (2) Mac Motion Leather Re Chair (Unused) S/N: Not Available C/W: Ottoman Usage: Not Available Asset located in: Humble, TX	Chair (Unused) S/N: Not Available
7663	Quantity of (2) Human Touch Wholebody Massage Chair Recliners S/N: Not Available		Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7674	Osaki Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available
7664	Whole Body Massage Chair Recliner S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7675B	Human Touch Zero Gravity Massage Chair (Unused) 2 (Nu Nat Available
7665	Human Touch HT5020 Massage Chair Recliner S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7675A	Human Touch Zero Gravity Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7675	Quantity of (2) BarcaLounger Power Leather Recliners (Unused) S/N: Not Available C/W: foot rest Usage: Not Available Asset located in: Humble, TX	7687	Armor Titanium Series 24 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof 23 in Wide x 55 in High x 20 in Deep, 1400 DEGREE FIRE RATING, DIGITAL COMBINATION KEY PAD W/BACKUP KEY, ADDITIONAL DOOR POUCH STORAGE FEATURE FOR PISTOLS & OTHER VALUABLES, 5 LIVE ACTION LOCKING BOLTS Usage: Not Available Asset located in: Humble, TX
7676	ProForm Carbon Treadmill S/N: Not Available Usage: Not Available Asset located in: Humble, TX		
7677	ProForm Electric Treadmill S/N: PP910C0010103 C/W: To Fit PRO FORM Usage: Not Available Asset located in: Humble, TX	7688	Armor Titanium Series 64 64 Gun Safe S/N: Not Available C/W: Fireproof 40 in Wide x 58 in High x 25 in Deep Usage: Not Available Asset located in: Humble, TX
7678	Quantity of (7) Boxes of Kenwood Radios S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX	7689	Armor Titanium Series 40 40 Gun Safe (Unused) S/N: Not Available C/W: Fireproof 29 in Wide x 59 in High x 20 in Deep, 1400 DEGREE FIRE RATING, DIGITAL
7680	Osaki Maxium 3D Massage Chair S/N: Not Available Usage: Not Available Asset located in: Humble, TX		COMBINATION KEY PAD W/BACKUP KEY, ADDITIONAL DOOR POUCH STORAGE FEATURE FOR PISTOLS & OTHER VALUABLES, 5 LIVE ACTION LOCKING BOLTS Usage: Not Available
7681	Osaki Maxium 3D Massage Chair S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7690	Asset located in: Humble, TX 2024 Landhonor LHR-PSM26A 26 in Portable Sawmill (Unused) S/N: Not Available
7682	Quantity of (3) Video Slot Machines S/N: Not Available Usage: Not Available Asset located in : Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7683	Forklift Crane Simulator Consol S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7691	Asset located in: Humble, TX 2024 Landhonor PSM31A 31 in Portable Sawmill (Unused)
7684	Canon iPF650 24 in Large Format Printer S/N: AACF1539 Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7685	Quantity of (2) Sharp MXM266N Computer Printers		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7692	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available
7686	Armor Titanium Series 24 24 Gun Safe (Unused) S/N: Not Available		C/W: 22 in Mower Usage: Not Available Asset located in : Humble, TX
	C/W: Fireproof 23 in Wide x 55 in High x 20 in Deep, 1400 DEGREE FIRE RATING, DIGITAL COMBINATION KEY PAD W/BACKUP KEY, ADDITIONAL DOOR POUCH STORAGE FEATURE FOR PISTOLS & OTHER VALUABLES, 5 LIVE ACTION LOCKING BOLTS Usage: Not Available Asset located in: Humble, TX	7693	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7694	Billy Goat BC2600HEBH 28 in Walk-Behind Brush Cutter S/N: 070620015 C/W: Honda GV390 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7703 7704	Troy-Bilt Chipper Shredder Vacuum S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (3) Yard Force Edger
7695	Yardman Walk-Behind 20 In Rear Tine Garden Tiller	-	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7705	Troy-Bilt Chipper Shredder Vacuum S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7696	Asset located in: Humble, TX 2014 Barreto 1320H 21 in Walk Behind Rotary Tiller S/N: 14269	7706	Ryan Lawnaire V Walk-Behind 26 in Aerator S/N: Not Available C/W: Honda GX160 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	C/W: Gasoline Engine, Hydraulic Drive Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7707A	Cushman Top Dresser S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7697	Legend 20 in Rototiller S/N: Not Available C/W: 212 cc Engine Usage: Not Available Asset located in: Humble, TX	7707	Quantity of (2) 2024 Powertek EB-800-E Backpack Leaf Blower (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available
7698	2024 Landhonor LHR-PWC6 Tow-Behind Wood Chipper (Unused) S/N: Not Available	7708	Asset located in: Humble, TX Custombuilt 5 Ft 6 In. x 4 Ft Deer Stand
7699	Usage: Not Available Asset located in: Humble, TX 2024 Landhonor LHR-GLS34 Gasoline Log	-	(Unused) S/N: Not Available Usage: Not Available
	Splitter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7709A	Asset located in: Humble, TX Game Winner 9 Ft Deer Stand S/N: Not Available Usage: Not Available
7700	Legend 20 in Rototiller S/N: Not Available C/W: 212 cc Engine Usage: Not Available Asset located in: Humble, TX	7709	Asset located in: Humble, TX Custombuilt 5 Ft 6 In. x 4 Ft Deer Stand (Unused) S/N: Not Available Usage: Not Available
7701	Quantity of (18) Rhino Rugged Landscaping Tools (Unused) S/N: Not Available C/W: (3) # 12 Aluminum Scoop (3) 16" Drain Spade (3) Spade Fork (3) Roofer Spade (3) 10" Hoe (3) Round Point Shovel Usage: Not Available Asset located in: Humble, TX	7710	Asset located in: Humble, TX Quantity of (3) Bayou DeView 6 ft Sled Duck Blinds S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (3) 3000 lb Protein Feeders
7702	Quantity of (18) Rhino Rugged Landscaping Tools (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: (3) #12 Aluminum Scoop, (3) 16" Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10" Hoe, (3) Round Point Shovel Usage: Not Available Asset located in : Humble, TX	7712	Quantity of (2) Pen Feeder W/Fawn Tubes S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7713	Quantity of (2) 3000 lb Protein Feeders S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7725	Quantity of (2) TWS 50 lb Heavy Duty Road Feeders S/N: Not Available C/W: controls
7714	Quantity of (3) 3000 lb Protein Feeders S/N: Not Available Usage: Not Available	7726	Usage: Not Available Asset located in: Humble, TX Quantity of (3) 2022 Millenium MFD6-1-21 Tree
7715	Asset located in: Humble, TX Quantity of (3) 3000 lb Protein Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7727	Stands S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (3) Tripod Bow Blinds
7716	Quantity of (2) ASF Pen Feeder W/Fawn Tubes S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7719	Asset located in: Humble, TX Quantity of (2) Lamco 600 Stand & Fill Corn Feeders S/N: Not Available Usage: Not Available	7728	Quantity of (2) Wildgame Trapping Systems S/N: Not Available C/W: One Stack, Cameras, 8 Ft x 12 Ft Panels Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7729	Quantity of (2) Wildgame Trapping Systems S/N: Not Available C/W: One Stack, Camera, (24) 8 Ft x 12 Ft Panels
7720	Quantity of (4) Lamco 600 Stand & Fill Corn Feeders S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7730	68 in Hex Fire Pit S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7721	Lamco 300 Stand & Fill Corn Feeder S/N: Not Available Usage: Not Available	7731	ASF 28 in Hex Fire Pit S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7722	Asset located in: Humble, TX Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7732	Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available C/W: Raccoon Motif Usage: Not Available Asset located in: Humble, TX
7723	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7733	Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available C/W: Rabbit Motif Usage: Not Available
7724	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7734	Asset located in: Humble, TX Big Daddy Fire Pits Large Steel Fire Pit (Unused) S/N: Not Available Usage: Not Available
7725A	Quantity of (2) Dillon 600 Lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7735	Asset located in: Humble, TX Big Daddy Targets Large AR 500 Shooting Target (Unused) S/N: Not Available C/W: Bigfoot w/Fish Motif Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7736	Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available C/W: Turkey/Bird Motif Usage: Not Available Asset located in: Humble, TX	7748 7749	Quantity of (2) Steel Shooting Targets (Unused)S/N: Not AvailableUsage: Not AvailableAsset located in: Humble, TXQuantity of (2) Steel Shooting Targets (Unused)S(A): Net Available
7737	Big Daddy Targets Small AR 500 Shooting Target (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: Rabbits Usage: Not Available Asset located in : Humble, TX	7750	2024 Landhonor LDH-FPR36 Round Fire Pit Ring (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7738	Big Daddy Targets Large AR 500 Shooting Target (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7739	Big Daddy Targets Large AR 500 Shooting Target (Unused) S/N: Not Available C/W: Bigfoot/T-Rex motif Usage: Not Available	7751	Quantity of (5) Poly Triangles S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7740	Asset located in: Humble, TX Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available		55 In. Adjustable Height Propane Fire Pit Table (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7753	55 In. Adjustable Height Propane Fire Pit Table (Unused)
7741	Quantity of (3) Millenium Two Man Tree Strands S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7758	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused)
7742	Quantity of (3) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in : Humble, TX		S/N: Not Available C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in : Humble, TX
7743	Quantity of (2) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7759	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, 7 in Track Belts,
7744	Quantity of (2) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available		Manual Coupler, 40 in Bucket Usage: Not Available Asset located in : Humble, TX
7745	Asset located in: Humble, TX Quantity of (2) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7760	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available
7746	Bigfoot Steel Shooting Target (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7761	Asset located in: Humble, TX 2024 Powertek PT-450 Mini Compact Track Loader (Unused)
7747	T-Rex Steel Shooting Target (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		S/N: Not Available C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7762	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2403148097 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	7770	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT23202407000105 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Humble, TX
7763	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2403148256 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	7771	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT23202407000110 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Humble, TX
7764	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178353 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	7772	2024 AGT KTT23 Mini Compact Track Loader (Unused) S/N: KTT232024L0803001 C/W: Open Operator Station, Joystick Steering, 8 in Track Belts, 31 in Bucket, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
7765	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178379 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available		PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7773	2024 AGT KTT23 Mini Compact Track Loader (Unused)
7766	2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 24080206 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: 1 Hr Asset located in: Humble, TX	-	S/N: KTT232024L0803002 C/W: Open Operator Station, Joystick Steeri 8 in Track Belts, 31 in Bucket, THE BROCHU IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SE
7767	2024 NKL NMK-60 Mini Compact Track Loader (Unused)		ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	S/N: 24080205 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: Not Available Asset located in : Humble, TX	7774	2024 AGT LRT23 Mini Compact Track Load (Unused) S/N: LRT23202407190062 C/W: Open Operator Station, Joystick Steeri
7768	2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 071256 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: Not Available		THE PRODUCT IMAGES SHOWN AF ILLUSTRATION PURPOSES ONLY A
7769	Asset located in: Humble, TX 2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 24080201 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: Not Available Asset located in: Humble, TX	7775	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT23202408010005 C/W: Open Operator Station, Joystick Steering, 7 in Track Belts, Manual Coupler, 44 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7776	2024 AGT YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1420240801805 C/W: Open Operator Station, Manual Coupler, 38 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7783	2014 Ditch Witch RT16 Walk-Behind Trencher S/N: CMWRT16XKE0001029 C/W: Briggs & Stratton 2 Cylinder 16 hp Gasoline Engine, Hydrostatic Drive, 4 in Wide x 42 in Long Combination Trencher Chain Usage: 696 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
7777	2024 AGT YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1420240801794 C/W: Open Operator Station, Manual Coupler, 38 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 AGT QHT500FL Stand-On Mini Crawler	-7784	2021 Vermeer VX50 500 gal T/A Vacuum Excavation Unit S/N: 1M9FE1221MS284763 C/W: 12000 lb GVWR, Lunette Ring Hitch, Torsion Axle, Steel Debris Tank, Rear Hose Reel, 200 gal Fresh Water Tank, Full Open Tailgate, Hydraulic Tailgate Locks, Blower, Boiler, 235/80R16 Tires, Tier 4, 2021 US EPA Label, Kubota 4 Cylinder Diesel Engine Usage: 277 Hr Notes: LOCATED-IN-HOUSTON-TX ONLY THE TRAILER COMES WITH TITLE Asset located in: Humble, TX
	Dumper (Unused) S/N: QHT500FL202408016 C/W: Hydrostatic Drive, 1 Cylinder 6.5 hp Gasoline Engine, 7 in Rubber Tracks Usage: Not Available Asset located in: Humble, TX	7786 7787 7789 7790	2015 Vermeer BC1000XL Tow-Behind Wood Chipper S/N: 1VRY11198F1021751 C/W: 2014 US EPA Label, PSI 4 Cylinder 3.0 L Gasoline Engine, 12 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Lunette Ring Usage: Not Available Asset located in: Humble, TX 2013 Vermeer BC1000XL Tow-Behind Wood Chipper S/N: 1VRY11195D1019159 C/W: Cummins 4 Cylinder Diesel Engine, 12 in
7779	2024 AGT QHT500FL Stand-On Mini Crawler Dumper (Unused) S/N: QHT500FL202408019 C/W: Hydrostatic Drive, 1 Cylinder 6.5 hp Gasoline Engine, 7 in Rubber Tracks Usage: Not Available Asset located in: Humble, TX		
7780	2024 Landhero LDH-MCD500 Self-Loading Crawler Dumper (Unused) S/N: Not Available C/W: Briggs & Stratton 6.5 hp Gasoline Engine, 7 in Rubber Tracks, THE PRODUCT IMAGES		Feed Opening, Swivel Discharge Chute, S/A Trailer, Lunette Ring Usage: 191 Hr Asset located in: Humble, TX 2024 KULY YKL-35 Mini Excavator (Unused)
7781	SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Landhero Walk-Behind Mini Crawler Dumper		S/N: 24071030 C/W: 2024 US EPA Label, Swing Boom, 3 ft 9 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb Usage: 1 Hr
7782	S/N: Not Available C/W: Hydrostatic Drive, Briggs & Stratton 1 Cylinder 6.5 hp 208 cc Gasoline Engine, 7 in Rubber Tracks Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX Heracles H130 3-Wheel Mini Wheel Loader		Asset located in: Humble, TX 2023 AGT R35 Mini Excavator S/N: R3523080201E C/W: Enclosed Cab, Tier 4, 2023 US EPA Label, 3 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 20 in Digging Bucket Usage: 24 Hr Notes: LOCATED-IN-LIVINGSTON_LA_TX DEFICIENCIES NOTED - DI EASE SEE THE
	S/N: Not Available C/W: Open Operator Station, Auxiliary Hydraulics, Manual Coupler, 40 in Bucket, 18x8. 50x8 Tires Usage: Not Available Asset located in: Humble, TX		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Livingston, LA

Lot #	Details	Lot #	Details
7791	2024 NKL NW-18 Mini Excavator (Unused) S/N: 071243 C/W: Swing Boom, 2 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: 1 Hr Asset located in: Humble, TX	7797	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080222 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX
7792	S/N: QK18RXS-C24080201 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY	7798 7799	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080225 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX 2024 NKL NW-16 Mini Excavator (Unused)
			S/N: 24080223 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in : Humble, TX
7793	 B 2024 AGT QK18RXS-C Mini Excavator S/N: QK18RXS-C24080203 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE 	7800	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080224 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in : Humble, TX
7794	ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX 2024 AGT QK18K-C Mini Excavator (Unused)	7801	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080221 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available
	S/N: QK18K-C2408020002 C/W: THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS AND CAB CONFIGURATION PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE. Usage: Not Available	7802	Asset located in: Humble, TX 2024 NKL NW-16 Mini Excavator (Unused) S/N: 071235 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7803	2024 AGT QK16R Mini Excavator (Unused)
7795	2024 AGT NT18K Mini Excavator (Unused) S/N: NT18K2024J0716042 C/W: Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	-	S/N: QK16R202408020005 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN
7796	2024 NKL NW-16 Mini Excavator (Unused) S/N: 071232 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX		MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX

This catalog was created at November 5, 2024 03:25:12 AM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details
7804	2024 AGT QK16R Mini Excavator (Unused) S/N: QK16R202408020006 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	7810	2024 AGT H15 Mini Excavator (Unused) S/N: H1520240730000011 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
7805	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423119331 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7811	2024 AGT H15 Mini Excavator (Unused) S/N: H152024073000002 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE
7806	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423032738		ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	C/W: Straight Travel Pedal, Tier 2, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Humble, TX		2024 AGT H15 Mini Excavator (Unused) S/N: H15202404200000024 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available
7807	2024 FF Industrial FF-15 Mini Excavator (Unused)		Asset located in: Humble, TX
	S/N: 423069507 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7813	2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000261 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX
7808	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423069483 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7814	2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000251 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000260
7809	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423032740 C/W: Straight Travel Pedal, 2024 US EPA Label,		C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Humble, TX
2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Humble, TX	7816	2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000249 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7817	2024 AGT LS15R Mini Excavator (Unused) S/N: LS15R202407270166 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 AGT LS15R Mini Excavator (Unused)	7825	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423105531 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX
	S/N: LS15R202408010177 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Humble, TX	7826	(Unused) S/N: 423123895 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb
7819	2024 Machpro MP15 Mini Excavator S/N: SLP2415150202		Usage: Not Available Asset located in: Humble, TX
7820	C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 NKL NW-13Q Mini Excavator Mini	7827	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423119139 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb
, 010	Excavator (Unused) S/N: 071230 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available		Usage: 9 Hr Asset located in: Humble, TX
		7828	2024 AGT H13R Mini Excavator (Unused) S/N: H13R20240703C0582 C/W: Enclosed Cab, 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX 2024 AGT H13R Mini Excavator (Unused) S/N: H13R20240727V0411 C/W: Enclosed Cab, 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY
7821	Asset located in: Humble, TX 2024 NKL NW-13Q Mini Excavator (Unused) S/N: 24080220 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	_	
7822	2024 NKL NW-13Q Mini Excavator (Unused) S/N: 24080211 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: 3 Hr Asset located in: Humble, TX	7829	
7823	2024 NKL NW-13Q Mini Excavator (Unused) S/N: 24080213 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb	ACTUAL PRODUCT. THIS PRODUCT COI MULTIPLE COLOR VARIATIONS PLEASE ADDITONAL IMAGES OF EXACT MACHI Usage: Not Available	NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7830	2024 AGT QH13R Mini Excavator (Unused)
7824	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423119602 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		S/N: QH13R202408020052 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details	
7831 7832	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423050594 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423050617	7837	 2024 AGT H12R Mini Excavator (Unused) S/N: H12R20240730Q0495 C/W: 31 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available 	
	C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks,	7838	Asset located in: Humble, TX 2024 AGT H12R Mini Excavator (Unused)	
	16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	/030	S/N: H12R20240727M0430 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks,	
7833	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423050585 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	-	16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available	
7834	2024 FF Industrial FF-12 Mini Excavator		Asset located in: Humble, TX	
7834	(Unused) S/N: 423111877 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 AGT H12R Mini Excavator (Unused) S/N: H12R2024D07030007 C/W: 31 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in	7839	2024 AGT QH12R Mini Excavator (Unused) S/N: QH12R202407300027 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	
	Digging Bucket, Manual Thumb, THE	7840	2024 AGT QH12R Mini Excavator (Unused)	
	BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	7840	S/N: QH12R202408030024 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tra 16 in Digging Bucket, Manual Thumb, TH BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND M NOT BE AN EXACT REPRESENTATION C	S/N: QH12R202408030024 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE
7836	2024 AGT H12R Mini Excavator (Unused)		MULTIPLE COLOR VARIATIONS PLEASE SEE	
	S/N: H12R2024D07030001 C/W: 31 in Stick, Auxiliary Hydraulic Plumbing,		ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available	
	Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE		Asset located in: Humble, TX	
BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MA NOT BE AN EXACT REPRESENTATION OF ACTUAL PRODUCT. THIS PRODUCT COME MULTIPLE COLOR VARIATIONS PLEASE SI	BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available	7841	2024 AGT DM12-C Mini Excavator (Unused) S/N: DM12C202405N000047 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7842	2024 AGT MX12R Mini Excavator (Unused) S/N: MX12R202407000039 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 AGT MX12R Mini Excavator (Unused) S/N: MX12R2024J0000039 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks,	7848	2013 Moffett P6000 6000 lb 3x3 Truck Mounted Forklift S/N: M130299 C/W: 3 Stage Mast, 120 in Max Lift Height, 78 in Lowered Mast Height, 74 in Forks, Side Shift, Fork Rotation, Kubota V2203-M-ET02 35.9 kW 2.2 L Diesel Engine Usage: 345 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7849	2013 Yale GDP170VXNJUV156 16150 lb Pneumatic Tire Forklift S/N: B909V01509L
7844	2024 AGT MX12R Mini Excavator (Unused) S/N: MX12R2024J0000043 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available	-	C/W: 2 Stage Mast, 219.1 in Max Lift Height, 155 in Lowered Mast Height, 97 in Forks, Fork Positioner, GM Vortec 8 Cylinder 5.7 L LPG Engine Usage: 12,355 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	7852	2006 Cat DP50K 11000 lb Pneumatic Tire
7845	 7845 2024 AGT L12R Mini Excavator (Unused) S/N: L12R2024071900555 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX 7846 2024 AGT L12R Mini Excavator (Unused) 		Forklift S/N: AT28B51437 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 93 in Lowered Mast Height, 84 in Forks, Side Shift Usage: 14,325 Hr Asset located in: Humble, TX
		7853	Cat Pneumatic Tire Forklift S/N: Not Available C/W: 2 Stage Mast, 54 in Forks, Side Shift, 6 Cylinder Diesel Engine Usage: 5,541 Hr
7846			Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	S/N: L12R2024071900549 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in : Humble, TX	7854	2002 Toyota 7FDU45 10000 lb Pneumatic Tire Forklift S/N: 60330 C/W: 2 Stage Mast, 179 in Max Lift Height, 24 in Lowered Mast Height, 54 in Forks, Side Shift, Solid Pneumatic Tires, 2003 US EPA Label, Toyota 4.6 L Diesel Engine Usage: 2,387 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7847A	2016 Moffett M8 Rough Terrain Forklift S/N: P350908B Usage: Not Available Asset located in: Humble, TX	7856	2003 Toyota 7FGCU45 8850 lb Cushion Tire Forklift S/N: 64399 C/W: 3 Stage Mast, Full Free Lift, 199 in Max Lift Height, 96 in Lowered Mast Height, 48 in
7847	2024 Landhero LDH-KV16 Mini Excavator (Unused) S/N: Not Available C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		Forks, Side Shift, LPG Engine Usage: 7,558 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7857	2002 Hyster LP 8050 lb Pneumatic Tire Forklift S/N: E490168 C/W: 2 Stage Mast, 122 in Max Lift Height, 85 in Lowered Mast Height, 59 in Forks, Side Shift, 2002 US EPA Label, Vortec LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7863	2002 Toyota 7FGU35 7300 lb Pneumatic Tire Forklift S/N: 60406 C/W: 3 Stage Mast, Full Free Lift, 171.5 in Max Lift Height, 79 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, Vortec 4 Cylinder LPG Engine Usage: 1,559 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
7858	Clark C500-YS80 8000 lb Pneumatic Tire Forklift S/N: Y68500908715K0F C/W: 2 Stage Mast, 47 in Forks, 4 Cylinder LPG Engine Usage: 7,374 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2018 Toyota 8FGC35U 7250 lb Cushion Tire Forklift S/N: 13306 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2018 US EPA Label, Toyota 4 Cylinder 63 kW 3.68 L LPG Engine Usage: 1,843 Hr	
7859	Toyota 7FGU45 Pneumatic Tire Forklift S/N: 72832 C/W: 3 Stage Mast, Full Free Lift, 47 in Forks,		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, LPG Engine Usage: 7,006 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7865	2015 Toyota 8FGC35U 7250 lb Cushion Tire Forklift S/N: 11393 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 46 in Forks, Side Shift, 2015 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 1,046 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
7860	50 2014 Toyota 8FD35U 7700 lb Pneumatic Tire Forklift S/N: 10677 C/W: 3 Stage Mast, 187 in Max Lift Height, 90 in Lowered Mast Height, 48 in Forks, Side Shift,			
	Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4 Cylinder Diesel Engine Usage: 4,359 Hr Asset located in : Humble, TX	7866	2011 Toyota 7FGCU35 7250 lb Cushion Tire Forklift S/N: 71785 C/W: 3 Stage Mast, Full Free Lift, 187 in Max	
7861	2020 Cat DP40N1 7300 lb Pneumatic Tire Forklift S/N: AT12C00939 C/W: 3 Stage Mast, 187 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Fork Positioner, Solid Pneumatic Tires		Lift Height, 24 in Lowered Mast Height, 4 Forks, Side Shift, Toyota LPG Engine Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX	Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, Toyota LPG Engine Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 2,367 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2009 Toyota 7FGCU35 7250 lb Pneumatic Tire Forklift S/N: 71074 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: 1,241 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	
7862	2014 Toyota 8FG35U 7300 lb Pneumatic Tire Forklift S/N: 10805 C/W: 2 Stage Mast, 159.5 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 3.6 L LPG Engine Usage: 4,269 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
7868	2017 Toyota 8FD35U 7000 lb Pneumatic Tire Forklift	7873	2007 Komatsu FG15HT-20 6650 lb Pneumatic Tire Forklift
	S/N: 11945 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 87 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4 Cylinder 2.9 L Diesel Engine Usage: 3,989 Hr		S/N: 675065A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 2007 US EPA Label, Nissan 2.1 L LPG Engine Usage: Not Available
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7869	2015 Toyota 8FG35U 7000 lb Pneumatic Tire		Asset located in: Humble, TX
	Forklift S/N: 11051 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 44 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 63 kW 3.6 L LPG Engine Usage: 2,231 Hr Notes: LOCATED-IN-FORT-WORTH-TX	7874	2017 Goodsense FY30 6615 lb Pneumatic Tire Forklift S/N: 216015752 C/W: 3 Stage Mast, 189 in Max Lift Height, 88 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 3,283 Hr Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	7875	2024 Viper FY30T 6600 lb Pneumatic Tire
7870	2011 Toyota 7FGCU35 7000 lb Cushion Tire Forklift S/N: 71744 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 60 in Forks, Side Shift, Toyota LPG Engine Usage: 1,195 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Forklift (Unused) S/N: 23L3001155 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 1 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7871	2006 Toyota 7FGU35 7000 lb Pneumatic Tire Forklift S/N: 7FGU35-62055 C/W: 2 Stage Mast, 187 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, Tier 2, 2007 US EPA Label, 4 Cylinder 4.3 L Diesel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	7876	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3001156 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 1 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2024 Viper FY30T 6600 lb Pneumatic Tire
7872	2019 Hyundai 35D-9 6790 lb Cushion Tire Forklift S/N: HHKHHN44LK0000317 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 88 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Tier 4, 2019 US EPA Label, Kubota V3307 4 Cylinder 49.3 kW 3.3 L Diesel Engine Usage: 5,929 Hr Asset located in: Humble, TX		Forklift (Unused) S/N: 23L3000559 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, LPG Engine Usage: 3 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7878	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift S/N: 23L3001153 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 69 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	7885	Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: C1761 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Solid Pneumatic Tires, 2021 US EPA Label, Toyota 3 Cylinder 1.7 L Diesel Engine Usage: 468 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT	7886	2014 Toyota 8FDU30 5620 lb Pneumatic Tire
7879	Asset located in: Humble, TX 2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3000560 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 2 Hr		Forklift S/N: 60256 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 2,130 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE	7887	2024 Viper FY25BCS 5513 lb Pneumatic Tire
7881	THE INSPECTION REPORT Asset located in: Humble, TX 1991 Hyster H60XL 6050 lb Pneumatic Tire Forklift	-	Forklift (Unused) S/N: 222010019 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in
	S/N: C177B08519M C/W: 2 Stage Mast, 87 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, Isuzu 4 Cylinder Diesel Engine Usage: 7,172 Hr		Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 2 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7888	2024 Viper FY25C 5513 lb Pneumatic Tire
	Asset located in: Humble, TX		Forklift (Unused)
7882	Allis Chalmers ACP - 60 Pneumatic Tire Forklift S/N: AJB84020 Usage: Not Available Asset located in: Humble, TX		S/N: 222011085 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Solid Pneumatic Tires, 2023 US EPA Label, Kubata 4 Culinder 2 5 L LPC Engine
7883	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift S/N: 69999 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 86 in Lowered Mast Height, 46 in		Kubota 4 Cylinder 2.5 L LPG Engine Usage: 2 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 2,661 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7889	2016 Yale GLC060VX 5500 lb Cushion Tire Forklift S/N: C910V05302P C/W: 2 Stage Mast, Full Free Lift, 122.4 in Max Lift Height, 84 in Lowered Mast Height, 30 in Forks, Side Shift, Fork Positioner, 2016 US EPA
7884	2017 Toyota 8FGU30 5750 lb Pneumatic Tire		Label, PSI 4 Cylinder 2.4 L Dual Fuel Engine Usage: 14,437 Hr
	Forklift S/N: 69982 C/W: 3 Stage Mast, Full Free Lift, 187 in Max		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Lift Height, 86 in Lowered Mast Height, 48 in Forks Side Shift Fork Positioner Solid	70000	Asset located in: Humble, TX
	Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 1,513 Hr Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX	7890B	2016 Doosan D30S-7 5450 lb Pneumatic Tire Forklift S/N: FDADR193001589 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 86 in Lowered Mast Height, 41 in Forks, Side Shift, Tier 4, 2016 US EPA Label, Doosan 4 Cylinder 2.4 L Diesel Engine Usage: 9,339 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7890A	2011 Doosan D30S-5 5500 lb Pneumatic Tire Forklift S/N: FDA06124012246 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 85 in Lowered Mast Height, 47 in Forks, Side Shift, 2011 US EPA Label, Yanmar 4 Cylinder 3.3 L Diesel Engine Usage: 4,249 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7895	2004 Cat GP25K 5000 lb Pneumatic Tire Forklift S/N: AT17B95008 C/W: 3 Stage Mast, 188 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 10,950 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Toyota 7FGCU35 4900 lb Pneumatic Tire	
7890	2016 Yale GLC060VX 5500 lb Pneumatic Tire Forklift S/N: C910V05309P C/W: 2 Stage Mast, Full Free Lift, 122.4 in Max Lift Height, 84 in Lowered Mast Height, 30 in Forks, Side Shift, Fork Positioner, PSI 4 Cylinder 2.4 L LPG Engine Usage: 16,780 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Forklift S/N: 72810 C/W: 4 Stage Mast, Full Free Lift, 230 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Solid Pneumatic Tires, PSI 4 Cylinder LPG Engine Usage: 9,584 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	
7891	2014 Toyota 8FGU30 5350 lb Pneumatic Tire Forklift S/N: 60981 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 83 in Lowered Mast Height, Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 1,801 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7898	2018 Toyota 8FGU30 4850 lb Pneumatic Tire Forklift S/N: 72364 C/W: 4 Stage Mast, Full Free Lift, 240 in Max Lift Height, 84 in Lowered Mast Height, 72 in Forks, Side Shift, Fork Positioner, 2018 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,010 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
7892	2020 Toyota 8FGCU32 5000 lb Cushion Tire Forklift S/N: C0172 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 52 in Forks, Auxiliary Hydraulic Plumbing, 2020 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 4,027 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7915	2017 Yale 8FGCU25 4800 lb Pneumatic Tire Forklift S/N: A390V02093R C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2017 US EPA Label, PSI 4 Cylinder 2.4 L Dual Fuel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
7893	2018 Cat GP25N Pneumatic Tire Forklift S/N: AT35A06688 C/W: 3 Stage Mast, Full Free Lift, 41 in Forks, 2018 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 3,031 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	-7916	Forklift S/N: AF82F42143 C/W: 3 Stage Mast, Full Free Lift, 18 Lift Height, 82 in Lowered Mast Hei Forks, Side Shift, Tier 2, 2015 US EP CARB Compliant, GCT 4 Cylinder 2. Engine Usage: 10,521 Hr	S/N: AF82F42143 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.1 L LPG Engine Usage: 10,521 Hr
7894	2014 Cat PD 5000 Pneumatic Tire Forklift S/N: AT18C31486 C/W: 3 Stage Mast, Full Free Lift, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2013 US EPA Label, Mitsubishi 4 Cylinder Diesel Engine Usage: 2,133 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: DOES NOT SELL WITH LPG TANK Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7917	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift S/N: AF82F42126 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7923	2015 Cat DP25N Pneumatic Tire Forklift S/N: AT18E00354 C/W: 3 Stage Mast, Full Free Lift, 39 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 4,932 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	7924	Toyota 8FGCU25 4650 lb Cushion Tire Forklift
7918	2016 Mitsubishi FGC25 4750 lb Cushion Tire Forklift S/N: AF82F42142 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: 1,398 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: 00692 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2019 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 6,915 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	THE INSPECTION REPORT	7925	Heli CPYD25C-KU1H 4630 lb Cushion Tire
7919	Asset located in: Humble, TX 2020 Toyota 8FGCU30 4700 lb Cushion Tire Forklift S/N: C1939 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Auxiliary Hydraulic Plumbing, 2020 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available	-	Forklift S/N: 230252S4149 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: 3,970 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX	7926	Heli CPYD25-TY5 4630 lb Pneumatic Tire
7920	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2015 UniCarrier MCP1F2A25LV 4700 lb Cushion Tire Forklift	7926 	Forklift S/N: 230252S4148 C/W: 2 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2022
	Cushion The Forkint S/N: 9W6588 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2014 US EPA Label, GCT 4		US EPA Label, Kubota WG2503-L-ET 4 Cylinder 2.5 L LPG Engine Usage: 3,770 Hr Asset located in: Humble, TX
	Cylinder 2.1 L LPG Engine	7927	2012 Doosan G25P-5 4600 lb Pneumatic Tire
7921	Usage: 9,482 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2006 Toyota 7FGCU30 Pneumatic Tire Forklift		Forklift S/N: FGA0B133003317 C/W: 3 Stage Mast, 186 in Max Lift Height, 47 in Forks, Side Shift, 2012 US EPA Label, Doosan G424FE 4 Cylinder 2.4 L LPG Engine
	S/N: 69414 Usage: Not Available		Usage: 3,821 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	7928	2006 Yale 8FGCU25 4600 lb Pneumatic Tire
7922	2016 Doosan G25E5 4650 lb Pneumatic Tire Forklift S/N: FGA08179007307 C/W: 3 Stage Mast, Full Free Lift, 42 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		Forklift S/N: B875B04045D C/W: 3 Stage Mast, Full Free Lift, 194.9 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2006 US EPA Label, Mazda 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 9,086 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7929	2006 Yale GLC050VXNVSE088 4550 lb Cushion Tire Forklift S/N: A910V06796D C/W: 3 Stage Mast, Full Free Lift, 200.8 in Max	7934	2020 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: C2963 C/W: 3 Stage Mast, Full Free Lift, 189 in Max
	Lift Height, 86 in Lowered Mast Height, 46 in Forks, Side Shift, 2006 US EPA Label, Mazda F2-Z25D 4 Cylinder 2.2 L LPG Engine Usage: 3,322 Hr		Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 11,000 Hr
	Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	7935	2018 Toyota 8FGCU25 4500 lb Cushion Tire
7930	2023 Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift (Unused) S/N: 230253A2339 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: 2 Hr Asset located in: Humble, TX	-7933	Forklift S/N: 97108 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2018 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7931	2023 Heli CPYD25C-M1H 4520 lb Cushion Tire	-	Asset located in: Lake Worth, TX
	Forklift (Unused) S/N: 230253A2338 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: 1 Hr Asset located in: Humble, TX	7936	2018 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 91453 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 54 in Forks, Side Shift, 2018 US EPA Label, Toyota itieb02 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 7,967 Hr Notes: LOCATED-IN-FORT-WORTH-TX
7932	Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift		Asset located in: Lake Worth, TX
	S/N: 230252S4880 C/W: 3 Stage Mast, 185 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, Mitsubishi 4 Cylinder LPG Engine Usage: 2,183 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	7937	2013 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 48275 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Toyota 4YECS 38 kW 2.23 L LPG Engine Usage: 7,663 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7933	Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift	7938	2013 Toyota 8FGCU25 4500 lb Pneumatic Tire
	S/N: 230252S4879 C/W: 3 Stage Mast, 185 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, Mitsubishi 4 Cylinder LPG Engine Usage: 1,844 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Forklift S/N: 48395 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 41 in Forks, Side Shift, Solid Pneumatic Tires, 2013 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
		7939	2012 Toyota 8FGU25 4500 lb Cushion Tire
			Forklift S/N: 41900 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2012 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 3,872 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7940	2016 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 80196 C/W: 3 Stage Mast, Full Free Lift, 189 in Max	7946	2001 Daewoo D25S-3 Pneumatic Tire Forklift S/N: 90-05883 Usage: Not Available Asset located in : Humble, TX
7941	Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2011 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift	7948	7948 2023 Heli CPQYD25-M1H 4300 lb Pneumatic Tire Forklift S/N: 250252T5743 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Tier 4, 2022 US EPA Label, PSI 4 Cylinder 2.4 L Dual Fuel Engine
	S/N: 8FGU25-38751 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		Usage: 8 Hr Asset located in: Humble, TX
	Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2011 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 2,509 Hr	7949	2015 Doosan GC25E-5 4300 lb Cushion Tire Forklift S/N: FGA0L179001438 C/W: 3 Stage Mast, Full Free Lift, 189 in Max
	Asset located in: Humble, TX	4	Lift Height, 83 in Lowered Mast Height, 42 in
7942 2011 Toyota 8FGCU25 4500 lb Pneumat Forklift S/N: 35434	Forklift S/N: 35434		Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2016 US EPA Label, Hyundai 4 Cylinder 48.7 kW 2.4 L Dual Fuel Engine Usage: Not Available
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Toyota		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	4YECS 4 Cylinder 38 kW 2.23 L LPG Engine	7950	
	Usage: 8,619 Hr Notes : LOCATED-IN-FORT-WORTH-TX	/950	Doosan G25N7 4200 lb Pneumatic Tire Forklift S/N: FGA14-1290-00405
	Asset located in: Lake Worth, TX	-	C/W: 2 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, Solid Pneumatic Tires, 2017 US EPA Label, GCT K25 L 4 Cylinder 2.5 L LPG Engine Usage: Not Available
7943	3 2011 Toyota 8FGCU25 4500 lb Pneumatic Tire Forklift		
	S/N: 35829 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		Notes: LOCATED-IN-FORT-WORTH-TX
Lift	Lift Height, 83 in Lowered Mast Height, Side		Asset located in: Lake Worth, TX
	Shift, Solid Pneumatic Tires, 2011 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L	7951	2014 Mitsubishi FGC30N Cushion Tire Forklift
	LPG Éngine		S/N: AF83F40074 C/W: 3 Stage Mast, Full Free Lift, 187 in Max
	Usage: 6,562 Hr Notes: LOCATED-IN-FORT-WORTH-TX		Lift Height, 82 in Lowered Mast Height, 46 in
	Asset located in: Lake Worth, TX		Forks, Auxiliary Hydraulic Plumbing, 2014 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine
7944	2004 Toyota 7FGU25 4500 lb Pneumatic Tire Forklift		Usage: 13,363 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	S/N: 72662 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		THE INSPECTION REPORT Asset located in: Humble, TX
	Lift Height, 83 in Lowered Mast Height, 42 in	7952	2012 Doosan D25S-5 Pneumatic Tire Forklift
Forks, Side Shift, Solid Pneumatic Tires, 2004 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 1,672 Hr		S/N: FDA05124011538 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, Yanmar 3VNQA 4 Cylinder	
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		3.3 L Diesel Engine Usage: Not Available
7945	2001 Daewoo D25S-3 4500 lb Cushion Tire	1	Asset located in: Humble, TX
	Forklift S/N: 9005883	7953A	Bendi B40/48IC-180D 4000 lb Cushion Tire Forklift
	C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 85 in Lowered Mast Height, 37 in Forks, Auxiliary Hydraulic Plumbing, 2001 US EPA Label, 4 Cylinder Diesel Engine Usage: Not Available		S/N: B4048IC602B03928 C/W: 4 Stage Mast, 240 in Max Lift Height, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 4,703 Hr
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
7954	Nissan PJ02A25PV 3975 lb Pneumatic Tire Forklift S/N: PJ029H3529 C/W: 3 Stage Mast, 188 in Max Lift Height, 86 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Nissan 4 Cylinder LPG Engine Usage: 13,012 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7961	2009 Toyota 8FGCSU20 3450 lb Cushion Tire Forklift S/N: 14317 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2009 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 2,184 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7955	Asset located in: Humble, TX	7962A	2007 Tusk 3050 lb Cushion Tire Forklift
/900	2013 Toyota 8FGU25 3950 lb Pneumatic Tire Forklift S/N: 47294 C/W: 3 Stage Mast, 189 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Load Weigh System, 2013 US EPA Label, Toyota 4Y ECS 4 Cylinder 2.2 L Dual Fuel Engine		S/N: 6751587 C/W: 3 Stage Mast, 188 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Tier 2, 2007 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine Usage: 11,194 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 1,989 Km Asset located in: Humble, TX		Asset located in: Humble, TX
7956	1999 Hyster 3900 lb Pneumatic Tire Forklift S/N: D187V16183W C/W: 3 Stage Mast, 189 in Max Lift Height, 20 in Lowered Mast Height, 47 in Forks, Side Shift, LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	-7963	2018 Toyota 8FGU18 2750 lb Pneumatic Tire Forklift S/N: 65623 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2018 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 11,319 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
7958	2013 Toyota 8FGU25 Pneumatic Tire Forklift	1	THE INSPECTION REPORT
	S/N: 50159 Usage: 2,428 Hr Asset located in : Humble, TX	7964	Asset located in: Humble, TX 2003 Toyota 7FGCU20 2600 lb Cushion Tire Forklift
7959	2013 Toyota 8FGU25 3750 lb Pneumatic Tire Forklift S/N: 51434 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2013 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 7,579 Hr		S/N: 82748 C/W: 4 Stage Mast, Full Free Lift, 240 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2003 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 11,335 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX	7965	Clark GCS15 2450 lb Cushion Tire Forklift
7960	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2016 Doosan G25P-5 3650 lb Pneumatic Tire	-	S/N: G12703139236K0F C/W: 3 Stage Mast, 188 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift, 4 Cylinder LPG Engine
7900	Forklift S/N: FGA0B179004748 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in		Usage: 4,699 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		7966	2016 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 80655 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 4,954 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7967 7968A	2016 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 80661 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 4,642 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX Clark CMC20S Cushion Tire Forklift S/N: D901066 C/W: 3 Stage Mast, 85 in Lowered Mast Height, Side Shift, 4 Cylinder LPG Engine Usage: 4,995 Hr	7974	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused) S/N: 243810049 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in: Humble, TX 2024 JQ POWER JQ2T-MAX Electric Forklift (Unused) S/N: 24479003 C/W: 2 Stage Mast, 82 in Lowered Mast Height, 48 in Forks Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7976	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused) S/N: 24479030
7968	Toyota Cushion Tire Forklift S/N: A0533576 C/W: 3 Stage Mast, Full Free Lift, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 2014 US EPA Label, Toyota 4YECS 4 Cylinder		C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in: Humble, TX
	38 kW 2.23 L LPG Engine Usage: 7,072 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7977B	2011 Toyota 7FBCU18 2900 lb Electric Forklift S/N: 66322 C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V
7969	Clark C500-S80 Cushion Tire Forklift S/N: Not Available		Usage: 18,752 Hr Asset located in : Humble, TX
7970	C/W: 3 Stage Mast, 41 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 4,551 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX Toyota FGH15 Cushion Tire Forklift S/N: Not Available C/W: 2 Stage Mast, 103 in Lowered Mast	7977A	2011 Toyota 7FBCU18 2900 lb Electric Forklift S/N: 66292 C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Height, 36 in Forks, 4 Cylinder Gasoline Engine Usage: Not Available	7977	Asset located in: Humble, TX 2024 JQ POWER JQ2T-MAX 4400 lb Electric
7971	Asset located in: Humble, TX 2025 STL Industrial STL3NTEL 6610 lb Electric Forklift (Unused) S/N: 01A06250 C/W: 2 Stage Mast, 109 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 8 Hr		Forklift (Unused) S/N: 24479004 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in : Humble, TX Landoll P30 3000 lb Electric Forklift
	Asset located in: Humble, TX	7978	S/N: P30701A004415
7972	2025 STL Industrial STL2TN 4410 lb Electric Forklift (Unused) S/N: 01A06321 C/W: Single Stage Mast 109 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 38 Hr	7070	C/W: 3 Stage Mast, 180 in Max Lift Height, 102 in Lowered Mast Height, Forks, 48 V, Battery Charger Usage: 1,045 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7973	Asset located in: Humble, TX 2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused) S/N: 243470084 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in: Humble, TX	_7979	2019 Toyota 8FBE20U 2550 lb Electric Forklift S/N: 17657 C/W: 4 Stage Mast, Full Free Lift, 240 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V, Battery Watering System Usage: 8,871 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7980	STL Industrial STL1TN 2210 lb Electric Forklift (Unused)	7988A	Raymond 112TM-FRE-60L 6000 lb Electric Pallet Jack
	S/N: 24A0230 C/W: 2 Stage Mast, 109 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift		S/N: 1120452434 C/W: 6000 lb Capacity, 24 V Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	7989	Quantity of 3 Pallet Jack
7981	Crown Electric Forklift S/N: 1A336408 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 40 in Forks, Side Shift, 36 V, Battery Charger Usage: Not Available		S/N: Not Available C/W: Strongway 5500 lb, EZLift 5500 lb, Roughneck Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	7990	2015 JLG 1350SJP 4WD Diesel Telescopic
7982C	Crown RC3020-40 3300 lb Electric Forklift S/N: 1A254746 C/W: 3 Stage Mast, 226 in Max Lift Height, 93 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Asset located in: Humble, TX	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Boom Lift S/N: 0300210986 C/W: 135 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2015 US EPA Label, Deutz TCD2. 9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, IN445 /50D710 Tires Usage: 3,881 Hr
7982A	2007 Raymond 740R35TT 3500 lb Electric		Notes: LOCATED-IN-FORT-WORTH-TX
	Pallet Jack S/N: 74007AA07946		Asset located in: Lake Worth, TX
	C/W: 3500 lb Capacity, 36 V Usage: Not Available Asset located in: Humble, TX	7991	2016 Genie S125 4WD Diesel Telescopic Boom Lift S/N: S12516D-1439
7982	Hyundai 18BRP-9 3300 lb Electric Forklift S/N: HHKHHR06VH0000046 C/W: 3 Stage Mast, 240 in Max Lift Height, 107 in Lowered Mast Height, 47 in Forks, Side Shift, 36 V		C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Deutz 4 Cylinder 55.4 kW 2.9 L Diesel Engine, IN455/50D710 Tires Usage: 1,958 Hr
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	7992	2015 JLG 860SJ 4WD Diesel Telescopic Boom
7985A	Toyota 7HBW23 4500 lb Electric Pallet Jack S/N: 7HBW2335357 C/W: 4500 lb Capacity, 24 V Usage: Not Available Asset located in: Humble, TX	7992	Lift S/N: 0300207789 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 15-625 Tires
7986	Crown WP3035-45 4500 lb Electric Pallet Jack		Usage: 2,277 Hr Notes: LOCATED-IN-FORT-WORTH-TX
	S/N: 10131651 C/W: 4500 lb Capacity, 24 V		Asset located in: Lake Worth, TX
	Usage: Not Available	7994	2015 Snorkel TB-86J 4WD Diesel Telescopic
	Notes: LOCATED-IN-FORT-WORTH-TX		Boom Lift
7987	Asset located in: Lake Worth, TX Vestil 3000 lb Electric Pallet Jack S/N: 0507096 Usage: Not Available Asset located in: Humble, TX		S/N: TB86J04000026 C/W: 86 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, Kubota 4 Cylinder Diesel Engine, 15-625 Tires Usage: 1,410 Hr
7988B	Raymond 8210 4500 lb Electric Pallet Jack S/N: 8211613477 C/W: 4500 lb Capacity, 24 V Usage: Not Available Asset located in: Humble, TX		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
7995A	2007 Snorkel TB85JFA 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: SP07041RBLT C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine, 15-625 Tires Usage: 3,635 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	8005	2017 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S60H40279 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Deutz d2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355/55D625NHS Tires Usage: 3,012 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2014 Genie S-65 4WD Diesel Telescopic Boom
7995	Asset located in: Humble, TX 2014 Genie S85 4WD Diesel Telescopic Boom Lift S/N: S8514-11198 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2013 US EPA Label, Deutz TD2011L04I 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 3,259 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8009	Lift S/N: S601427122 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2013 US EPA Label, Deutz 4 Cylinder 49 hp 2.9 L Diesel Engine, 355/55D Tires Usage: 5,068 Hr Asset located in: Humble, TX 2015 Genie S60X 4WD Diesel Telescopic Boom Lift
7996	2016 JLG 800S 4WD Diesel Telescopic Boom Lift S/N: 0300204001 C/W: 80 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz 4 Cylinder 67 hp 2.9 L Diesel Engine, 15-625NHS Tires Usage: 2,471 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	8012	S/N: S60X15A-30386 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L Diesel Engine, 355/55D625 NHS Tires Usage: 5,608 Hr Asset located in: Humble, TX 2007 Genie S60 4WD Diesel Telescopic Boom Lift S/N: S600715807 C/W: 60.2 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2004 US EPA Label, Deutz 3
8000	2015 Haulotte HT67RTJ 4WD Diesel Telescopic Boom Lift S/N: TD500110 C/W: 67 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Kubota V2403-M-ET02e 4 Cylinder 36.5 kW 2.4 L Diesel Engine, 385/65-22.5 NHS Tires Usage: 3,641 Hr Asset located in: Humble, TX	8013	Cylinder Diesel Engine, 355/55D625 Tires Usage: 2,227 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300203642 C/W: 60 ft Max Platform Height, 1000 lb Max
8001	2015 Snorkel TB-66J 4WD Diesel Telescopic Boom Lift S/N: TB66J-04-000192 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform,	-	Weight Capacity, Power to Platform, Onboard Generator, 2015 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 NHS Tires Usage: 5,398 Hr Asset located in: Humble, TX
8004	Kubota 4 Cylinder Diesel Engine, 15-19.5 Tires Usage: 4,444 Hr Asset located in: Humble, TX 2006 JLG 660SJ 4WD Diesel Telescopic Boom Lift - Factory Reconditioned 2019 S/N: 030099927 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2008 US EPA Label, Deutz F4M2011 4 Cylinder 65 hp 3.1 L Diesel Engine, 15-19.5NHS Tires Usage: 666 Hr Asset located in: Humble, TX	8018	2013 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300170418 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2013 US EPA Label, Deutz D2011L04 4 Cylinder 40 hp Diesel Engine, 39X15-22.5 Tires Usage: 4,559 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8019	2006 Snorkel TB-60 4WD Diesel Telescopic Boom Lift S/N: JL06018RBLT C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 15-19.5 Tires, EQUIPMENT-FROM-UNITED-RENTALS Usage: 6,546 Hr Notes: LOCATED-IN-FORT-WORTH-TX AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND ; EQUIPMENT FROM UNITED RENTALS Asset located in: Lake Worth, TX	8027	2014 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300186158 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 33/16LLx16. 1 Tires Usage: 821 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8020	2018 JLG 460SJ 4WD Diesel Telescopic Boom Lift S/N: 0300240143 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Deutz D2.9L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5NHS Tires Usage: 2,792 Hr Asset located in: Humble, TX	8028	2007 JLG 400S 4WD Diesel Telescopic Boom Lift - Factory Reconditioned 2018 S/N: 0300114482 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Deutz 3 Cylinder 48 hp 2.3 L Diesel Engine, 12-16.5 Tires Usage: 2,097 Hr
8021	2018 JLG 460SJ 4WD Diesel Telescopic Boom Lift S/N: 0300240471 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 NHS Tires Usage: 1,716 Hr Asset located in: Humble, TX	8029	Asset located in: Humble, TX 2007 JLG 400S 4WD Diesel Telescopic Boom Lift - Factory Reconditioned 2018 S/N: 0300121542 C/W: 40 ft Max Lift Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, US EPA Label, Deutz 4 Cylinder 36.5 kW 2.3 L Diesel Engine, 12-16.5 Tires Usage: 1,183 Hr
8022	2017 JLG 460SJ 4WD Diesel Telescopic Boom Lift S/N: 0300235958 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 NHS Tires Usage: 3,313 Hr Asset located in: Humble, TX	8030	Asset located in: Humble, TX 2006 JLG 400S 4WD Diesel Telescopic Boom Lift - Factory Reconditioned 2018 S/N: 0300103683 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2008 US EPA Label, Deutz F3M2011 3 Cylinder 48 hp 2.3 L Diesel Engine, 12-16.5 Tires
8023	2016 Skyjack SJ45T Telescopic Boom Lift S/N: 98001773 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	8031	Usage: 887 Hr Asset located in: Humble, TX 2006 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300102015 C/W: 40 ft Max Platform Height, 100 lb Max Weight Capacity, Power to Platform, 2008 US
8025	Asset located in: Lake Worth, TX 2015 Genie S45 4WD Diesel Telescopic Boom Lift S/N: S4515-21167 C/W: 45 ft Max Platform Height, 500 lb Max		EPA Label, Deutz 4 Cylinder 36.5 kW 2.3 L Diesel Engine, 12-16.5 Tires Usage: 1,608 Hr Asset located in : Humble, TX
	Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12- 16.5 Foam-Filled Tires Usage: 4,235 Hr Asset located in: Humble, TX	8032	2015 Genie S40 4WD Diesel Telescopic Boom Lift S/N: S4015-20965 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D 2.9L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 NHS Foam-Filled Tires Usage: 4,678 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8033	2007 Genie S40 4WD Diesel Telescopic Boom Lift S/N: S4007-11887 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Deutz 3 Cylinder 48 hp 2.3 L Diesel Engine, 12-16.5 Tires Usage: 5,665 Hr Asset located in: Humble, TX	8042	2015 Genie Z62-40 4WD Diesel Articulating Boom Lift S/N: Z6215A-285 C/W: 61.11 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2014 US EPA Label, Deutz D2.9 L4 4 Cylinder 49 hp Diesel Engine, 355/55D625 Tires Usage: 2,965 Hr Asset located in: Humble, TX
8034	Nifty-Lift SD34DE 4WD Diesel Articulating Boom Lift S/N: 0428344 C/W: 34 ft Max Platform Height, 500 lb Max Weight Capacity, 3 Cylinder Diesel Engine, 26x12-16.5 NHS Tires Usage: Not Available	8043	2017 Haulotte HA61 RTJPRO 4WD Diesel Articulating Boom Lift S/N: 2018200 C/W: 61 ft Max Platform Height, 507 lb Max Weight Capacity, Jib, Power to Platform, 2021 US EPA Label, Kubota 4 Cylinder 36 kW 2.4 L Diesel Engine, Aperture Tires
8035	Asset located in: Humble, TX 2014 Genie ZX-135 4WD Diesel Articulating Boom Lift	-	Usage: 2,736 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	S/N: ZX135142503 C/W: 135 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, CARB Compliant, Deutz TD 2011 L04 3 Cylinder 55 kW 3.6 L Diesel Engine, 445/50D710 Tires Usage: 3,109 Hr Asset located in: Humble, TX	8044	2017 Haulotte HA61 RTJPRO 4WD Diesel Articulating Boom Lift S/N: 2018446 C/W: 61 ft Max Platform Height, 507 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, Kubota V2403 4 Cylinder 2.4 L Diesel Engine Usage: 1,402 Hr
8038	2018 JLG 800 AJ 4WD Diesel Articulating Boom Lift S/N: 0300239892 C/W: 80 ft Max Platform Height, 500 lb Max		Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
		8045	2020 MEC 60-J 4WD Diesel Articulating Boom Lift S/N: 14400498 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US
8039			EPA Label, Kubota V105-T-ET03 4 Cylinder 33 kW 1.5 L Diesel Engine, 315/55D20 Tires Usage: 3,295 Hr Asset located in: Humble, TX
	Weight Capacity, Jib, Power to Platform, 2013 US EPA Label, Deutz D2011L04 4 Cylinder 62 hp Diesel Engine, 445/55D19.5 Tires Usage: 4,252 Hr Asset located in : Humble, TX	8046	2019 MEC 60-J 4WD Diesel Articulating Boom Lift S/N: 14400451 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018 US EPA Label, Kubota V1505-T-ET03 4 Cylinder
8040	2014 Genie Z80/60 Articulating Boom Lift S/N: Z8014-5192 Usage: 4,998 Hr Asset located in: Humble, TX		33 kW 1.5 L Diesel Engine, 315/55D20 Tires Usage: 3,451 Hr Asset located in: Humble, TX
8041	2013 Genie Z-80 4WD Diesel Articulating Boom Lift S/N: Z8013-3945 C/W: 78 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz TD2011L04I 4 Cylinder 3.61 L Diesel Engine, 18-625 Tires Usage: 4,736 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	8047	2019 MEC 60-J 4WD Diesel Articulating Boom Lift S/N: 800242718 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Kubota V1505-T-ET03 4 Cylinder 33 kW 1.5 L Diesel Engine, 315/55D20 Tires Usage: 3,802 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8048	2019 MEC 60J-D Articulating Boom Lift S/N: 14400451D Usage: 3,165 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8049	2019 MEC 60J-D Articulating Boom Lift S/N: 14400421 Usage: 3,313 Hr Asset located in : Humble, TX	8056	2016 JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300220868 C/W: 45 ft Max Platform Height, 550 lb Max
8050	2012 JLG 600AJ 4WD Diesel Articulating Boom Lift S/N: 0300155087 C/W: 60 ft Max Platform Height, Jib, 2011 US EPA Label, Deutz 4 Cylinder Diesel Engine, 355		Weight Capacity, 2016 US EPA Label, Deutz D2. 9L4 4 Cylinder 2.9 L Diesel Engine, 33x15.50- 16.5 Tires Usage: 2,305 Hr Asset located in : Humble, TX
	/55D625 Tires Usage: 4,548 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8057	2015 JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300201471 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2014
8051	2018 Haulotte HA46 RTJO Articulating Boom Lift	-	US EPA Label, Deutz D 2.9L4 4 Cylinder 2.9 L Diesel Engine, 33x15.5-16.5 NHS Tires Usage: 2,047 Hr
	S/N: 2047881 Usage: Not Available Asset located in : Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8052	2016 Haulotte HA46 RTJO 4WD Diesel Articulating Boom Lift S/N: 2009339 C/W: 46 ft Max Platform Height, 507 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505-Ef01 4 Cylinder 18.5 kW 1.5 L Diesel Engine, 85x340 Aperture Tires Usage: 1,776 Hr	8058	2008 JLG 450AJ 4WD Diesel Articulating Boom Lift S/N: 0300125307 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2007 US EPA Label, Deutz D2011L03 3 Cylinder 49 hp 2.3 L Diesel Engine, 12-16.5 NHS Tires Usage: 1,727 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8059	JLG 450AJ Series II 4WD Diesel Articulating
8053	2016 Snorkel A46JRT 4WD Diesel Articulating Boom Lift S/N: A46JRT-04-000306 C/W: 46 ft Max Platform Height, 550 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505 3 Cylinder Diesel Engine, 355/55D625 Tires Usage: 1,981 Hr		Boom Lift S/N: Not Available C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz F3M1011F 3 Cylinder 47 hp 2.1 L Diesel Engine, 33x15.50-16.5 NHS Tires Usage: 4,038 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8054	Asset located in: Humble, TX 2012 Skyjack SJ46AJ 4WD Diesel Articulating	-	Asset located in: Humble, TX
	Boom Lift S/N: 95000382 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz 3 Cylinder 49 hp 2.3 L Diesel Engine, 315-55D20 Tires Usage: 1,657 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	8060	2020 Genie Z45/25 2WD Electric Articulating Boom Lift S/N: Z4525F61230 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 9-14.5 Tires Usage: 413 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Genie Z-45/25 L4WD Diesel Articulating
8055	2017 JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300228058 C/W: 45 ft Max Platform Height, 550 lb Max Weight Capacity, Jib, 2016 US EPA Label, CARB Compliant, Deutz D 2.9 L4 4 Cylinder 49 hp Diesel Engine, 12-16.5NHS Tires Usage: Not Available Asset located in: Humble, TX	8061	2017 Genie Z-45/25J 4WD Diesel Articulating Boom Lift S/N: Z4525N-58205 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz 4 Cylinder 36.4 kW 2.9 L Diesel Engine, 315//55D20 Tires Usage: 1,346 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8062	2012 Genie Z45/25 4WD Diesel Articulating Boom Lift S/N: Z452512A044282 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011L03 3 Cylinder 36.3 kW 2.3 L Diesel Engine, 355/55D625 NHS Tires Usage: 1,866 Hr Asset located in: Humble, TX	8069	2014 Genie Z40/23NRJ 2WD Electric Articulating Boom Lift S/N: Z40N14-2422 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22x7x17 3/4 Tires Usage: 1,492 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble TX	
8063	2005 Genie Z45/25 4WD Diesel Articulating		Asset located in: Humble, TX	
	Boom Lift S/N: Z45250525763 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2011 US EPA Label, Deutz F3L2011 3 Cylinder Diesel Engine, 355/55D625 Tires	8070	2015 Genie Z34/22N Articulating Boom Lift S/N: Z34N15-12305 Usage: 689 Hr Asset located in: Humble, TX 2019 Genie Z-30/20N RJ 2WD Electric	
	Usage: 4,087 Hr		Articulating Boom Lift	
8064	Asset located in: Humble, TX 2002 Genie Z45/25 4WD Dual Fuel Articulating Boom Lift S/N: Z452519952 C/W: 45.6 ft Max Platform Height, 500 lb Max	-	S/N: Z30NF-21178 C/W: 29.2 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22/7 /17.75 Solid Tires Usage: 289 Hr	
	Weight Capacity, Jib, Power to Platform, Dual		Asset located in: Humble, TX	
8065	Fuel Engine, 14-175 Tires Usage: 2,988 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2021 Genie Z45 4WD Electric Articulating	8072	2013 Genie Z-30/20NRJ 2WD Electric Articulating Boom Lift S/N: Z30N13-14418 C/W: 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22X7 Tires	
8003	Boom Lift		Usage: 803 Hr	
	S/N: Z45EM507 C/W: 45 ft Max Platform Height, 662 lb Max Weight Capacity, Jib, Power to Platform, 315 /55D20 Tires Usage: 8,916 Hr Asset located in: Humble, TX	8073	Asset located in: Humble, TX 2013 Genie TZ-34/20 Towable Lift S/N: TZ3413603 C/W: 34 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform Usage: Not Available	
8066	2015 Genie Z45/25DC Articulating Boom Lift		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	S/N: Z452515D-448		Asset located in: Humble, TX	
	Usage: 619 Hr Asset located in: Humble, TX	8075	2012 Genie GS-5390RT 4x4 Diesel Scissor Lift	
8067	2014 JLG E450AJ 2WD Electric Articulating Boom Lift S/N: 0300193405 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 240 /55 Tires Usage: 666 Hr Notes: LOCATED-IN-FORT-WORTH-TX	80/5	S/N: GS9012-47932 C/W: 53 ft Max Platform Height, 15 Weight Capacity, Platform Extensio Platform, Power Inverter, Stabilizers Control Box, 2011 US EPA Label, CA Compliant, Deutz D2011 L 03 3 Cyli kW 2.3 L Diesel Engine Usage: 1,112 Hr	S/N: GS9012-47932 C/W: 53 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Stabilizers, Upper Control Box, 2011 US EPA Label, CARB Compliant, Deutz D2011 L 03 3 Cylinder 36.3 kW 2.3 L Diesel Engine
	Asset located in: Lake Worth, TX	8076	2014 Genie GS4390 Diesel Scissor Lift	
8068	2017 JLG E400AJP 2WD Electric Articulating Boom Lift S/N: 0300224995 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 25x12 Solid Tires Usage: 615 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: GS901450021 C/W: 43 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Lake Worth, TX	

Lot #	Details	Lot #	Details
8078	2016 Genie GS4069RT Diesel Scissor Lift S/N: GS6916F9232 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Tier 4, 2015 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine Usage: 1,945 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX 2018 Skyjack SJ6826 RT 4x4 Diesel Scissor Lift	8084	2015 Haulotte Compact 3347E Electric Scissor Lift S/N: Not Available C/W: 33 ft Max Platform Height, 660 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 JLG 3248RS Electric Scissor Lift S/N: 200234867
	S/N: 37011905 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Tier 4, 2017 US EPA Label, Kubota D902-EF01 3 Cylinder 18.5 kW 0.89 L Diesel Engine Usage: 670 Hr Asset located in: Humble, TX	8086	C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 470 Hr Asset located in: Humble, TX 2015 JLG 3248RS Electric Scissor Lift
8080	2017 Skyjack SJ6826 RT 4x4 Diesel Scissor Lift S/N: 37010650 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D902- EF01 3 Cylinder 18.5 kW 0.8 L Diesel Engine Usage: 463 Hr Asset located in: Humble, TX	8087	S/N: 200237806 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 618 Hr Asset located in: Humble, TX 2019 Skyjack SJ4632 Electric Scissor Lift S/N: 70041183
8081	2014 JLG M4069LE Electric Scissor Lift S/N: 200231456 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 377 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 174 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
8082A	2016 Genie GS-4047 Scissor Lift S/N: GS4716D-1548 Usage: 539 Hr Asset located in: Humble, TX	8088	Skyjack SJ4632 Electric Scissor Lift S/N: Not Available C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 296 Hr
8082	2016 Genie GS-4047 4x4 Electric Scissor Lift S/N: GS4716D1548 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 556 Hr		Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX Skyjack Electric Scissor Lift
8083	Asset located in: Humble, TX 2024 STL Industrial STLSL40 Electric Scissor Lift (Unused) S/N: WT20240809QJ05 C/W: 39 ft 6 in Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX	-	S/N: Not Available C/W: Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8090	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266200 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 270 Hr	8096	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P-144334 C/W: Platform Extension, Power to Platform, Upper Control Box Usage: 414 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8097	2016 Genie GS3246 Electric Scissor Lift
8091	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266196 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 405 Hr		S/N: GS4616P139198 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	8098	2015 Genie GS3246 Electric Scissor Lift S/N: GS4615A-137246
8092	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266191 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box		C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in: Humble, TX
	Usage: 213 Hr	8099A	2015 Genie GS-3246 4x4 Electric Scissor Lift
8093	Asset located in: Humble, TX 2017 JLG 3246ES Electric Scissor Lift S/N: 0200266197 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 367 Hr	8099	S/N: GS4615A-137552 C/W: 32 ft Max Platform Height, 700 kg Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 604 Hr Asset located in : Humble, TX 2015 Genie GS3246 Electric Scissor Lift S/N: GS4615A-137574 C/W: 32 ft Max Platform Height, 700 lb Max
	Asset located in: Humble, TX		
8094	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266185 C/W: 31.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 338 Hr		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 594 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8100	2014 Genie GS3246 Electric Scissor Lift
8095A	2018 Genie GS3246 Electric Scissor Lift S/N: GS46P-147121 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 78 Hr		S/N: 116551 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 234 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8101	2007 JLG 3246ES Electric Scissor Lift
8095	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266203 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 373 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 0200163221 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 261 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8102	2016 Genie GS3232 Electric Scissor Lift S/N: GS3216A-142501 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 432 Hr Asset located in: Humble, TX 2014 Genie GS3232 Electric Scissor Lift	8109	2017 JLG 2646ES Electric Scissor Lift S/N: 200263036 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 378 Hr Asset located in: Humble, TX
	S/N: GS3214A-136205 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 352 Hr Asset located in: Humble, TX	8110	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263682 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 255 Hr Asset located in: Humble, TX
8104	2014 Genie GS3232 Electric Scissor Lift S/N: GS3214A-135415 C/W: 22 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 322 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8111 8112	2014 JLG 2646ES Scissor Lift S/N: M200007989 Usage: 354 Hr Asset located in: Humble, TX 2020 JLG 2632ES Electric Scissor Lift S/N: M200040404 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box
8105	S/N: GS3213A-113004 C/W: 22 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 142 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: 71 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8106		8113	2020 JLG 2632ES Electric Scissor Lift S/N: M200040389 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 101 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
S/N: S472 C/W: 26 f	S/N: S4726E-04-170300438 C/W: 26 ft Max Platform Height, Platform Extension, Power to Platform, Solid Non-		THE INSPECTION REPORT Asset located in: Humble, TX
	Marking Tires, Upper Control Box Usage: Not Available Asset located in : Humble, TX	8114	2019 JLG 2632ES Electric Scissor Lift S/N: MS00026094 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control
S/N C/V	2017 Skyjack SJIII4626 Electric Scissor Lift S/N: 70032974 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 364 Hr Asset located in: Humble, TX 2017 Genie GS2646 Electric Scissor Lift S/N: GS46P-143622 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Box Usage: 178 Hr Asset located in: Humble, TX
		8116	2016 JLG 2632ES Electric Scissor Lift S/N: M200002208 C/W: 25 ft 5 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box
S/N: GS46P-1 C/W: 26 ft Ma Weight Capac Platform, Soli Control Box Usage: 259 Hi Notes : DEFICI THE INSPECT			Usage: 75 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		8117	2016 JLG 2632ES Electric Scissor Lift S/N: 0200253047 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 447 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8118	2016 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27032135 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 185 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8126	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A-136096 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 458 Hr Asset located in: Humble, TX
8119	19 2016 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27027774 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 316 Hr	8127	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A136026 C/W: 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires Usage: 488 Hr Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8128	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A136135
8120	2019 Genie GS2632 Electric Scissor Lift S/N: GS32P163106 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box	8129	S/N: GS3214A136135 C/W: 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: 427 Hr Asset located in: Humble, TX
	Usage: 167 Hr Asset located in: Humble, TX	0129	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A118876 C/W: 500 lb Max Weight Capacity, Platform
8121	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A-139268 C/W: Platform Extension, Power to Platform, Upper Control Box		Extension, Solid Non-Marking Tires, Upper Control Box Usage: 380 Hr Asset located in: Humble, TX
	Usage: 608 Hr Asset located in: Humble, TX	8131	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A136458 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available
8122	2015 Genie GS2632 Scissor Lift S/N: GS3215A-139149 Usage: 497 Hr Asset located in: Humble, TX		
8123			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		8132	2013 Genie GS2632 Electric Scissor Lift S/N: GS3213A-112911 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
8124A	2015 Genie GS2632 Scissor Lift S/N: GS3215A-139144 Usage: 456 Hr Asset located in : Humble, TX		Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8124	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A139144 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 431 Hr Asset located in: Humble, TX	8133	2011 Genie GS2632 Electric Scissor Lift S/N: GS3211A97058 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available
8125	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A-135821 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 388 Hr Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8134	2011 Genie GS2632 Electric Scissor Lift S/N: GS3211A-97073 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 JLG 2630ES Electric Scissor Lift	8141	2019 Skyjack SJIII3219 Electric Scissor Lift S/N: 22144648 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 337 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	S/N: 0200232573 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 321 Hr Asset located in: Humble, TX		2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22089176 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box
8136	2011 JLG 2630ES Electric Scissor Lift S/N: 0200204774 C/W: 26 ft Max Platform Height, 500 lb Max		Usage: 215 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 389 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	Platform, Śolid Non-Marking Tires, Upper Control Box Usage: 389 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8143	2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22098919 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
8137	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252249 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 351 Hr Asset located in: Humble, TX 2016 JLC 2620ES Electric Science Lift	8144	2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22103849 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 364 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE
0130	 8138 2016 JLG 2630ES Electric Scissor Lift S/N: 0200252716 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 329 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 		INSPECTION REPORT Asset located in: Lake Worth, TX
		8146	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22058625 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in: Humble, TX
8139	2016 JLG 2630ES Scissor Lift	9147	2014 Skyjack SJIII-3219 Electric Scissor Lift
8140	S/N: 200253457 Usage: 144 Hr Asset located in: Humble, TX 2016 JLG 2632ES Electric Scissor Lift	8147	S/N: 22061962 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box
	S/N: 0200252784 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in : Humble, TX		Usage: 164 Hr Asset located in: Humble, TX
Control Usage: I		8148	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22066660 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 203 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8149	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22063992 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 238 Hr Asset located in: Humble, TX	8156	2016 JLG 1932R Electric Scissor Lift S/N: M200017595 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 131 Hr Asset located in: Humble, TX
8150	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: Not Available C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box Usage: 246 Hr Asset located in: Humble, TX	8157	2015 JLG 1932RS Electric Scissor Lift S/N: 0200247824 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in: Humble, TX
8151	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22064021 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 278 Hr	8158	2015 JLG 1932RS Electric Scissor Lift S/N: 0200251216 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 538 Hr Asset located in: Humble, TX
8152	Asset located in: Humble, TX 2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22070495 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 280 Hr	8159	2014 JLG 1932RS Electric Scissor Lift S/N: 200234812 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 34 Hr Asset located in: Humble, TX
Asset located in: Humble, TX 8153 2012 Skyjack SJIII-3219 Scissor Lif S/N: 22038665 C/W: 19 ft Max Platform Height, 55 Weight Capacity, Platform Extensio Platform, Upper Control Box	2012 Skyjack SJIII-3219 Scissor Lift S/N: 22038665 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	8160	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234442 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 563 Hr Asset located in: Humble, TX
	Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	8161	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235746 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
8154	2017 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-170403382 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to		Platform, Upper Control Box Usage: 483 Hr Asset located in : Humble, TX
0155	Platform, Śolid Non-Marking Tires, Upper Control Box Usage: 255 Hr Asset located in : Humble, TX	8162	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235705 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper
8155	2017 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-170303298 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 367 Hr Asset located in: Humble, TX		Control Box Usage: 495 Hr Asset located in : Humble, TX
		8163	2014 JLG 1932RS Electric Scissor Lift S/N: 200235742 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 165 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8164	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236017 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires Usage: 435 Hr Asset located in: Humble, TX	8172	2018 Genie GS1930 Electric Scissor Lift S/N: GS30P-172180 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 156 Hr Asset located in: Humble, TX
8165	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234077 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 553 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8173	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P167088 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX
8167	Asset located in: Humble, TX 2020 Genie GS1930 Electric Scissor Lift S/N: GS30P-191929 C/W: Platform Extension, Power to Platform, Upper Control Box Usage: 298 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	8174	2017 Genie GS-1930 Electric Scissor Lift S/N: GS30P167099 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 128 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8175	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P-169281
8168	2020 Genie GS1930 Electric Scissor Lift S/N: GS30P191148 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 395 Hr Asset located in: Humble, TX		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8169	2018 Genie GS1930 Electric Scissor Lift S/N: GS30P182807 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8176	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P-166125 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8170	2019 Genie GS1930 Electric Scissor Lift S/N: GS30P188159 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8177	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P167077 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 345 Hr Asset located in: Humble, TX
8171	Asset located in: Humble, TX 2018 Genie GS1930 Electric Scissor Lift S/N: GS30P-171391 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 181 Hr Asset located in: Humble, TX	8178	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P-167032 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 324 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8179	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P164379 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 86 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8186	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P159746 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 532 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	_8187	2015 Genie GS1930 Electric Scissor Lift
8180	2017 Genie GS1930 Electric Scissor Lift S/N: 164382 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 722 Hr		S/N: GS3015A148303 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 380 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX		
8181	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016A-151095 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control	8188	2015 Genie GS1930 Scissor Lift S/N: GS3015A-146189 Usage: 141 Hr Asset located in: Humble, TX
	Box Usage: 538 Hr	8189	2014 Genie GS1930 Electric Scissor Lift
	Asset located in: Humble, TX		S/N: GS3014A-138221 C/W: 500 lb Max Weight Capacity, Platform
S/N C/V Wei	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P151859 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to		Extension, Power to Platform, Upper Control Box Usage: 488 Hr Asset located in : Humble, TX
	Platform, Solid Non-Marking Tires, Upper Control Box Usage: 365 Hr Asset located in : Humble, TX	8190	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A138410 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
S/N: GS30 C/W: 19 ft Weight Ca Platform, I Usage: 56	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P153073 C/W: 19 ft Max Platform Height, 500 lb Max		Platform, Upper Control Box Usage: 463 Hr Asset located in: Humble, TX
	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 569 Hr Asset located in: Humble, TX	8191	2014 Genie GS1930 Scissor Lift S/N: GS3014A-138474 Usage: 362 Hr
8184	2016 Genie GS-1930 Electric Scissor Lift	1	Asset located in: Humble, TX
	S/N: GS3016A151094 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 494 Hr Asset located in : Humble, TX	8192	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A138039 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 425 Hr Asset located in: Humble, TX
8185A	2016 Genie GS1930 Scissor Lift	0102	2014 Genie GS1930 Electric Scissor Lift
	S/N: GS3016P-159746 Usage: 501 Hr Asset located in : Humble, TX	8193	S/N: GS3014A-138921 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
8185	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P-160058 C/W: 19 ft Max Platform Height, 500 lb Max		Platform, Solid Non-Marking Tires, Upper Control Box Usage: 459 Hr
	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	01045	Asset located in: Humble, TX
Usage: 360 Hr Asset located in: Humble, TX	8194B	2014 Genie GS1930 Scissor Lift S/N: GS3014A-138410 Usage: 423 Hr	
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8194A	2014 Genie GS1930 Scissor Lift	8201	2016 JLG 1930 ES Electric Scissor Lift
	S/N: GS3014A-137358 Usage: 341 Hr		S/N: M200003872 C/W: 19 ft Max Platform Height, 500 lb Max
	Asset located in: Humble, TX	-	Weight Capacity, Platform Extension, Solid Non-Marking Tires
8194	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A-128925		Usage: 97 Hr Asset located in: Humble, TX
	C/W: 19 ft Max Platform Height, 500 lb Max	8202	2015 JLG 1930 ES Electric Scissor Lift
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		S/N: 200248780
	Control Box Usage: 425 Hr		C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
	Asset located in: Humble, TX		Platform, Solid Non-Marking Tires, Upper Control Box
8195	2014 Genie GS1930 Electric Scissor Lift		Usage: 368 Hr
	S/N: GS3014A137358 C/W: 19 ft Max Platform Height, 500 lb Max		Asset located in: Humble, TX
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	8203	2017 JLG 1930ES Electric Scissor Lift S/N: M200006693
	Control Box Usage: 358 Hr		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Platform, Upper Control Box Usage: 199 Hr
	THE INSPECTION REPORT Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE
8196	2013 Genie GS1930 Electric Scissor Lift	-	THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: Not Available C/W: 500 lb Max Weight Capacity, Platform	8204	2017 JLG 1930ES Electric Scissor Lift
	Extension, Power to Platform, Upper Control		S/N: M200006663
	Box Usage: 357 Hr		C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
	Asset located in: Humble, TX		Platform, Solid Non-Marking Tires, Upper Control Box
8197	2013 Genie GS1930 Electric Scissor Lift S/N: GS3013A-125344		Usage: 251 Hr
	C/W: 19 ft Max Platform Height, 500 lb Max		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Asset located in: Humble, TX
	Control Box Usage: 497 Hr	8213	2024 Powertek PT-0.5-6 Electric Scissor Lift (Unused)
	Asset located in: Humble, TX		S/N: Not Available
8198	2011 Genie GS1930 Electric Scissor Lift		C/W: 26 ft Max Platform Height, 1100 lb Max Weight Capacity, Non-Marking Tires
	S/N: GS3011A102214 C/W: 19 ft Max Platform Height, 500 lb Max		Usage: Not Available Asset located in: Humble, TX
	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	8214	2019 Genie GS1330M Electric Scissor Lift
	Usage: 315 Hr		S/N: GS30MD-2718
8199	Asset located in: Humble, TX 2018 JLG 1930 ES Electric Scissor Lift	-	C/W: 13 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
0155	S/N: M200025037		Platform, Solid Non-Marking Tires, Upper Control Box
	C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to		Usage: 88 Hr
	Platform, Śolid Non-Marking Tires, Upper Control Box		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 322 Hr		Asset located in: Humble, TX
8200	Asset located in: Humble, TX 2016 JLG 1930 ES Electric Scissor Lift	8215	2019 MEC 1330SE Scissor Lift S/N: 16301223
8200	S/N: M200003937		Usage: 30 Hr
	C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid		Asset located in: Humble, TX
	Non-Marking Tires Usage: 444 Hr		
	Asset located in: Humble, TX		
	·	1	

Lot #	Details	Lot #	Details
8216	2018 MEC 1330SE Electric Scissor Lift S/N: 16302954 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8224	2015 JLG 36AM Vertical Mast Lift S/N: 0900036035 C/W: 36 ft Max Platform Height, 300 lb Max Weight Capacity, Power to Platform, Stabilizers, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8217	2018 MEC 1330SE Electric Scissor Lift S/N: 16301972 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to	8225	2014 Genie AWP30SDC Vertical Mast Lift S/N: AWP14-81378 Usage: Not Available Asset located in: Humble, TX
	Platform, Upper Control Box Usage: 243 Hr Asset located in: Humble, TX	8226	2017 JLG 30AM Vertical Mast Lift S/N: 0900037384 C/W: 30 ft Max Platform Height, 350 lb Max
8218	2018 MEC 1330SE Electric Scissor Lift S/N: 16301448 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		Weight Capacity, Power to Platform, Stabilizers, Upper Control Box Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8227	2017 Genie GR20 Vertical Mast Lift S/N: GRP-50132 C/W: 19 ft 9 in Max Platform Height, 350 lb
8219 8220	2018 MEC 1330SE Electric Scissor Lift S/N: 16301458 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box		Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 309 Hr Asset located in : Humble, TX
	Usage: 10 Hr Asset located in: Humble, TX		2016 Genie GR20 Vertical Mast Lift S/N: GR16P-44447 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 682 Hr Asset located in: Humble, TX
	2017 MEC 1330SE Electric Scissor Lift S/N: 16301222 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box		
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8229	2016 Genie GR20 Vertical Mast Lift S/N: GR16P-44415 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box
8221	2017 MEC 1330SE Electric Scissor Lift S/N: 16301226	8230	Usage: 753 Hr Asset located in: Humble, TX
	C/W: 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in : Humble, TX		2016 Genie GR20 Vertical Mast Lift S/N: GRP-45501 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box
8222	2017 MEC 1330SE Electric Scissor Lift S/N: 16301118		Usage: 328 Hr Asset located in: Humble, TX
	C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 49 Hr Asset located in: Humble, TX	8231	2015 Genie GR20 Vertical Mast Lift S/N: GR1537958 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension,
8223	2016 MEC 1330SE Scissor Lift S/N: 16301228 Usage: 37 Hr Asset located in: Humble, TX		Power to Platform, Upper Control Box Usage: 283 Hr Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8232	2016 JLG 20MVL Vertical Mast Lift S/N: 0130024155 C/W: 19 ft 5 in Max Platform Height, 300 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8240	JLG Vertical Mast Lift S/N: 0900035041 C/W: 25 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Stabilizers, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8233	2014 JLG 20MVL Vertical Mast Lift S/N: 0130021493 C/W: 19 ft 5 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX	8241 8242	2020 Genie SLA10 Material Hoist S/N: SLAP-77341 Usage: Not Available Asset located in: Humble, TX 2012 Cummins GTA50 600 kW Skid-Mounted Generator Set S/N: X11K452710
8234	2016 Skyjack SJ12 Vertical Mast Lift S/N: Not Available C/W: 12 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: Not Available Asset located in: Humble, TX		C/W: US EPA Label, Cummins GTA50 16 1035 hp 50 L Natural Gas Engine, /600 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8235	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41067 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 465 Hr Asset located in: Humble, TX	8243	Cummins 350DFCC 600 kW Skid-Mounted Generator Set S/N: RF19515356 C/W: Cummins VTA28GS2 12 Cylinder 900 hp Engine, 750 kVA/600 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 291 Hr
8236	2015 Genie GR-12 Vertical Mast Lift S/N: GR15-38803 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Solid		Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Onan 350DFCC 50266F 350 kW Skid-Mounted
8237	Non-Marking Tires, Úpper Control Box Usage: Not Available Asset located in: Humble, TX 2015 Genie GR-12 Vertical Mast Lift S/N: GR15-39082 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 376 Hr		Generator Set S/N: B910369338 C/W: Cummins NT855 6 Cylinder Diesel Engine, 437.5 kVA/350 kW Rated 3 Phase Output Usage: 387 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8238	Asset located in: Humble, TX 2014 Genie GR-12 Electric Vertical Mast Lift S/N: GR14-35810 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 328 Hr Asset located in: Humble, TX	8245	2003 Kohler 250RE0ZV 294 kW Skid-Mounted Generator Set S/N: 0776084 C/W: 2007 US EPA Label, Kohler D250 9.6A60 6 Cylinder Engine, /260 kW Rated 3 Phase Output, 120 V / 240 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8239	2014 Genie GR-12 Vertical Mast Lift S/N: GR14-35919 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 343 Hr Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8246	2012 Magnum MMG330 263 kW Skid-Mounted Generator Set S/N: 1221450 C/W: John Deere 6 Cylinder Diesel Engine, 329 kVA/263 kW Rated 3 Phase Output, 208 V / 480 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 8,429 Hr Asset located in: Humble, TX Cummins NT855 200kW Diesel Generator	8252	Generac SD60 60 kW Skid-Mounted Generator Set S/N: 3883733 C/W: Mitsubishi 4D34-T 4 Cylinder 3907 cc Diesel Engine, /60 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Generator Set S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8253	Kohler 50RZ 49 kW Skid-Mounted Generator Set S/N: 0675321
8248	1999 Olympian D159P1 150 kW Skid-Mounted Generator Set S/N: E2024B001 C/W: Perkins 6 Cylinder Diesel Engine, /150 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: 184 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		C/W: Ford LSG-875I-6005-A 8 Cylinder Gasoline Engine, 49 kVA,/49 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8254	1992 Cummins DGBA 37kW Diesel Generator Generator Set
8249			S/N: I910419145 Usage: Not Available Asset located in : Humble, TX
		8255	2013 Multiquip DCA45US12 36 kW Mobile Generator Set S/N: 8203020 C/W: Isuzu 4 Cylinder 2.9 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 280 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Evel Table
8250	 Marathon Magnaplus 363PSL3127 100 kW Skid-Mounted Generator Set S/N: MX1043210707 C/W: 6 Cylinder Diesel Engine, /100 kW Rated 3 Phase Output, 480 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 3,146 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 		Fuel Tank Usage: 38,994 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0051		8256	11 kW Skid-Mounted Generator Set S/N: Not Available C/W: Cat C2.2 4 Cylinder Diesel Engine, 120 V Rated Voltage Usage: 15 Hr Asset located in : Humble, TX
8251	2008 Kohler 60REOZJLB 62 kW Skid-Mounted Generator Set S/N: 2184957 C/W: 2007 US EPA Label, John Deere 4045TF 4 Cylinder 4.5 L Diesel Engine, 78 kVA/62 kW Rated 3 Phase Output, 139 V / 220 V / 240 V Rated Voltage, 120 V Receptacles, Bottom Mounted Fuel Tank Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8257	2008 Generac QT25 25 kW Skid-Mounted NG Generator Set S/N: 4514700 C/W: Mitsubishi 4 Cylinder Engine, 25 kVA,/25 kW, Rated Single Phase Output, 120 V / 208 V Rated Voltage Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8258	2009 Generac 11015510100 75 kW Skid- Mounted Generator Set S/N: 2102282 C/W: 2009 US EPA Label, Generac Power Systems WSG1068 10 Cylinder 6760 cc Natural Gas Engine, 94 kVA/75 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage Usage: 331 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Generac G0072900 26 kW Generator Set	8267 8268	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405670 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX Generac G0070433 22 KW Generator Set (Unused) S/N: 3011353871 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available
	S/N: 3014737691 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in : Humble, TX	8269	Asset located in: Humble, TX Generac G00704211 22 kW Generator Set S/N: 3014992389 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available
8260	Generac G0072900 26 KW Generator Set (Unused)		Asset located in: Humble, TX
8261	S/N: 3014737610 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX Generac G0072090 24 kW Generator Set	8270	Generac G0070433 22 kW Generator Set (Unused) S/N: 3011310896 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
	(Unused) S/N: 3015224571 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in : Humble, TX	8271	Generac G0070433 22 KW Generator Set (Unused) S/N: 3011353773 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available
8262	Generac G0072090 24 kW Generator Set (Unused)		Asset located in: Humble, TX
	S/N: 3015224570 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in : Humble, TX	8272	Generac G0070433 22 kW Generator Set S/N: 3011365373 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8263	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011524641 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8273	Generac G0070433 22 kW Generator Set (Unused) S/N: 3011353754 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8264	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405115 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8274	Generac G0070433 22 kW Generator Set S/N: 3011353779 C/W: Gwnerac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8265	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405492 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8275	Generac G0072280 18 KW Generator Set (Unused) S/N: 3010411534 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8266	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405499 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8276	2016 Multiquip DCA220SSJU4F Generator Set S/N: 8010873 Usage: 10,981 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8277 8278	2012 Magnum MMG175 175 kW Mobile Stand- By Generator Set S/N: 1215091 C/W: John Deere 6 Cylinder Diesel Engine, 185 kVA/148 kW Rated 3 Phase Output, 480 V Rated Voltage, 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: 793 Hr Asset located in: Humble, TX 2011 Cat 33304-XQ125 113 kW Mobile Generator Set	8282A	 A 2018 TechnoGen G100 108 kW Mobile Stand- By Generator Set S/N: 5632G1524JM002533 C/W: 2018 US EPA Label, Perkins 1104D 4 Cylinder 108.1 kW 4.4 L Diesel Engine, 135 kV/ /108 kW Rated 3 Phase Output, 480 V / 277 V Rated Voltage, 82.5 kVA,/66 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 5,493 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	S/N: Not Available C/W: Cat 4 Cylinder Diesel Engine, 141 kVA		THE INSPECTION REPORT Asset located in: Humble, TX
	/113 kW Rated 3 Phase Output, 480 V / 240 V Rated Voltage, 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 2,175 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8282	2006 Magnum MMG125 90 kW Mobile Generator Set S/N: 000078 C/W: 2005 US EPA Label, John Deere 6068TF275F 6 Cylinder 123 kW 6.8 L Diesel Engine, 124 kVA/ Rated 3 Phase Output, 208 V / 480 V Rated Voltage, /90 kW, Rated Single Phase Output, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A
8279	2013 Taylor Power TR100 100 kW Mobile Generator Set S/N: 25690 C/W: 2012 US EPA Label, Perkins 3362 4		Trailer, Ball Hitch, Surge Brakes Usage: Not Available
			Asset located in: Humble, TX
	Cylinder 116 kW 4.4 L Diesel Engine, 125 kVA /100 kW Rated 3 Phase Output, 80 V / 208 V / 240 V Rated Voltage, 79 kVA,/79 kW, Rated Single Phase Output, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: 1,407 Hr Asset located in: Humble, TX	8284	DMT DMT-600 60 kW Mobile Generator Set S/N: Not Available C/W: Cummins 4 Cylinder 3.9 L Diesel Engine, 75 kVA/60 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: 764 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
8280	2016 Multiquip DCA125SSIU4F 72 kW Mobile		THE INSPECTION REPORT Asset located in: Humble, TX
8281	Generator Set S/N: 7511312 C/W: 2016 US EPA Label, CARB Compliant, Isuzu BR-4HK1X 4 Cylinder 56 kW 5.1 L Diesel Engine, Requires Diesel Exhaust Fluid, 125 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /72 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 16,761 Hr Asset located in: Humble, TX 2014 Magnum MMG130 98 kW Mobile	8285	2022 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1429NL037179 C/W: 2015 US EPA Label, CARB Compliant, Isuzu BR-4JJ1X 4 Cylinder 56 kW Diesel Engine, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 21,096 Hr Asset located in: Humble, TX
	Portable Generator Set	8286	2017 Multiquip DCA-70SSIU4F Generator Set
	S/N: 5AJGS1829EB408174 C/W: 2012 US EPA Label, John Deere 4 Cylinder 130 kW 4.5 L Diesel Engine, 122 kVA /98 kW Rated 3 Phase Output, 480 V / 208 V Rated Voltage, 90 kVA,/90 kW, Rated Single Phase Output, 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 6,384 Hr Asset located in : Humble, TX	8287	S/N: 7353824 Usage: 7,237 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2017 Multiquip DCA-70SSIU4F Generator Set S/N: 7354082 Usage: 10,695 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
			Activities in Lake Worth, IA

Lot #	Details	Lot #	Details
8288	2017 Multiquip DCA-70SSIU4F Generator Set S/N: 7353963 Usage: 15,207 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8297	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353674 Usage: 17,557 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
8289	2017 MQ Power DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1424HL020245 C/W: 2016 US EPA Label, Isuzu 4 Cylinder 75 kW 2.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA, /40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 10,036 Hr Asset located in: Humble, TX	8298	2015 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1426FL018011 C/W: 2015 US EPA Label, Isuzu BR-4JJ1X 4 Cylinder 71 kW 2.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: 12,270 Hr Asset located in: Humble, TX
8290	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353236 Usage: 12,270 Hr Asset located in: Humble, TX	8299	2015 Wacker G50T4F 38 kW Mobile Generator Set S/N: 4TCSU1850FH190043
8291	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353490 Usage: 15,293 Hr Asset located in: Humble, TX		C/W: 2015 US EPA Label, Isuzu 4 Cylinder 56 kW Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom
8292	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353184 Usage: 21,096 Hr Asset located in : Humble, TX	8300	Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 1,835 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE
8293	2016 Multiquip DCA-70SSIU4F 56 kW Generator Set S/N: 7353493		THE INSPECTION REPORT Asset located in: Humble, TX 2017 Atlas Copco QAS 45 IT4/T4F Generator
	Usage: 12,107 Hr Asset located in: Humble, TX		Set S/N: HOP121334 Usage: 114,918 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2018 Multiquip DCA45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1229NL037461 C/W: 2018 US EPA Label, Isuzu 4LE2X 4 Cylinder 49 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: 6,472 Hr Asset located in: Humble, TX
8294	2016 MQ Power DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1423GL018775		
	C/W: 2016 US EPA Label, Isuzu 4 Cylinder 75 kW 2.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA, /40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 15,719 Hr Asset located in: Humble, TX	8301	
8295	2016 Multiquip DCA-70SSIU4F 56 kW Generator Set S/N: 7353539-L018778 Usage: 16,991 Hr Asset located in: Humble, TX		
8296	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353339 Usage: 12,506 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
8302	2017 Multiquip DCA45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1221HL021226 C/W: 2017 US EPA Label, Isuzu 4LE2X 4 Cylinder 49 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: 9,655 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8307	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 4GNBG0918HB045984 C/W: 2016 US EPA Label, Isuzu 4LE2T 4 Cylinder 30 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 5,173 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8303	2015 Multiquip DCA45SSIU4F Generator Set S/N: 7250402 Usage: 11,294 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8308	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: 7151786 C/W: 2015 US EPA Label, CARB Compliant, Isuzu BZ-4LE2 19 kW Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated
8304	2019 Airman MMD SDG25S Generator Set S/N: 1238E12341 Usage: 9,013 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 2,128 Hr Asset located in: Humble, TX
8305	2017 Multiquip DCA25SSIU4F 14.4 kW Mobile Generator Set S/N: 7152915 C/W: 2016 US EPA Label, Isuzu BZ-4LE2T 19 kW 2.2 L Diesel Engine, 25 kVA/ Rated 3 Phase Output, 480 V / 240 V Rated Voltage, /14.4 kW,	8309	2016 Multiquip DCA25SSIU4F Generator Set S/N: 7152111 Usage: 12,725 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Rated Single Phase Output, 240 V 7 120 V Rated Voltage, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 4,833 Hr Notes : LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX	8310 2016 Multiquip DCA25SSIU4F 20 Portable Generator Set S/N: 4GNBG0919GB041747 C/W: 2016 US EPA Label, Isuzu 4 Cylinder 2.1 L Diesel Engine, 25 k Rated 3 Phase Output, 240 V / 44 Voltage, 14.4 kVA,/14.4 kW, Rate Phase Output, 240 V / 120 V Rate 240 V & 120 V Receptacles, Sour	
8306	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set S/N: Not Available C/W: 2017 US EPA Label, Isuzu 4LE2T 4 Cylinder 30 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated		Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Ball Hitch Usage: 1,408 Hr
		Kohler 30RZ262 30 kW Mobile (LNG) Generator Set S/N: 1B9AB1112SA1B9051 C/W: Ford 4 Cylinder Natural Gas Engine, 38 kVA/30 kW Rated 3 Phase Output, 240 V / 277 V / 480 V Rated Voltage, 29 kVA,/29 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8313	Specialty Lighting BOSS-P-95 96 kW Mobile Generator Set S/N: 9886097 C/W: 6 Cylinder Diesel Engine, 120 kVA/96 kW Rated 3 Phase Output, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	8323	2010 Ingersoll Rand P250WJDU-T1 Air Compressor S/N: 417161UHUA23 C/W: 2010 US EPA Label, John Deere 4 Cylinder Diesel Engine, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 2,732 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	THE INSPECTION REPORT Asset located in: Humble, TX		THE INSPECTION REPORT Asset located in: Humble, TX
8314	2011 Quincy QSI-1500 Skid-Mounted Air Compressor S/N: BU1109290008 C/W: 3 Phase Usage: Not Available Asset located in: Humble, TX	8324	Ingersoll Rand SSR-EP150 670 cfm Skid- Mounted Electric Air Compressor S/N: F36749U99148 C/W: 128 psi Working Pressure, 3 Phase, 150 hp Motor Usage: Not Available
8315	2013 Hankison ACFS1000 Skid-Mounted Air Compressor S/N: ACFS10002 C/W: 160 psi Working Pressure Usage: Not Available Asset located in: Humble, TX	8325	Asset located in: Humble, TX Electric 240 gal Air Compressor S/N: Not Available C/W: Ingersoll Rand TS1A air dryer Usage: 9,366 Hr Asset located in: Humble, TX
8316	2013 Hankison ACFS1000 Skid-Mounted Air Compressor S/N: ACFS10004 C/W: 160 psi Working Pressure	8326	2019 Sullair 375HAF Air Compressor S/N: 201901210061 Usage: 4,631 Hr Asset located in : Lake Worth, TX
	Usage: Not Available Asset located in: Humble, TX	8327	2019 Sullair 375HAF 375 cfm Mobile Air Compressor
8317	2014 Quincy QSI-500I Skid-Mounted Air Compressor S/N: UTZ300466 C/W: 125 psi Working Pressure, 460V, 125 hp Motor Usage: 43,051 Hr Asset located in: Humble, TX	-	S/N: 201912130043 C/W: Perkins 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring Usage: 1,872 Hr Notes : LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8318	2016 Hankison ACFS450 Air Dryer S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8328	Asset located in: Lake Worth, TX 2019 Sullair 375HAF 375 cfm Mobile Air Compressor S/N: 201912190023
8319	2016 Hankison ACFS450 Air Dryer S/N: Not Available Usage: Not Available Asset located in: Humble, TX	-	C/W: Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX
8320	2016 Hankison ACFS450 Skid-Mounted Air Compressor S/N: 1000003124757 C/W: 100 psi Working Pressure Usage: Not Available Asset located in: Humble, TX	8329	2009 Ingersoll Rand 375 Mobile Air Compressor S/N: 4FVCCBBA49U408144 C/W: 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,021 Hr Asset located in: Humble, TX
8321	2016 Hankison ACFS450 Air Dryer S/N: Not Available Usage: Not Available Asset located in : Humble, TX	8330	2018 Doosan P425/HP375WCU-T4F Mobile Air Compressor S/N: 484388UBACF68
8322	2007 Quincy Compressors QSI-750 1385 cfm Skid-Mounted Electric Air Compressor S/N: UN107354 C/W: 3 Phase Usage: 17,853 Hr Asset located in: Humble, TX		C/W: 2014 US EPA Label, Cummins 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch Usage: 2,500 Hr Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
8332	2019 Allmand Max Air 185 Mobile Air Compressor S/N: B46E11882 C/W: 2018 US EPA Label, Yanmar 4 Cylinder 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 983 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8340	2017 Doosan C185WDZ-T4F 185 cfm Mobile Air Compressor S/N: 478832UKAAF23 C/W: 2016 US EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,398 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8341	2017 Doosan C185WDZ-T4F 185 cfm Mobile
8333	2018 Sullair 185DDPQ-KU4F 185 cfm Mobile Air Compressor S/N: 201802080070 C/W: 100 psi Working Pressure, 2017 US EPA Label, Kubota D1803-CR-T-EF01 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch		Air Compressor S/N: 4FVCABAA7HU478985 C/W: 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,022 Hr Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	8342	2016 Doosan C185WDZ-T4F Mobile Air
8334	Sullair 185DP0JD 185 cfm Mobile Air Compressor S/N: E04118506 C/W: 125 psi Working Pressure, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 899 Hr		Compressor S/N: 4FVCABAA6GU476983 C/W: 2016 US EPA Label, Deutz 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,696 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8343	2016 Doosan C185WDZ-T4F Mobile Air
8335	Sullair 185DP0JD 185 cfm Mobile Air Compressor S/N: E04118502 C/W: 125 psi Working Pressure, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 952 Hr		Compressor S/N: 447338UFAAF23 C/W: 200 psi Working Pressure, 2016 US EPA Label, CARB Compliant, Deutz D 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,453 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
8337	2018 Atlas Copco XAS185KD7 185 cfm Mobile Air Compressor S/N: HOP057044 C/W: 230 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Kubota D1803-CR-TI- EF02 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 665 Hr	8344	2016 Doosan C185WDZ-T4F 185 cfm Mobile Air Compressor S/N: 4FVCABAA9GU475536 C/W: 2015 US EPA Label, Deutz D2.9 L4 4 Cylinder 26.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 3,045 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8345	2014 Doosan C185WDZ Mobile Air Compressor
8338	2017 Atlas Copco XAS 185 Air Compressor S/N: HOP055449 Usage: 940 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: 4648630FYF23 C/W: 2014 US EPA Label, CARB Compliant, Deutz D 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,355 Hr Asset located in: Humble, TX
8339	2017 Doosan C185WDZ-T4F 185 cfm Mobile Air Compressor S/N: 4FVCABAA1HU479193 C/W: 2016 US EPA Label, Deutz D2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,196 Hr	8346	2014 Atlas Copco XAS185KD Mobile Air Compressor S/N: HOP048062 C/W: 160 psi Working Pressure, 2006 US EPA Label, Kubota V2403 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,419 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8347	2013 Atlas Copco XAS185JD Mobile Air Compressor S/N: 4500A1018DR046162 C/W: 250 psi Working Pressure, John Deere 4024TF281A 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Ball Hitch Usage: 2,227 Hr Asset located in: Humble, TX	8354	2010 Doosan C185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2010 US EPA Label, Kubota V2403 36.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,140 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8348	2012 Sullair 185DPQJD2 185 cfm Mobile Air		Asset located in: Humble, TX
	Compressor S/N: 201204240079 C/W: 2012 US EPA Label, John Deere 4024TF270G 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Ball Hitch Usage: 2,367 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8355	2007 Ingersoll Rand 185 cfm Mobile Air Compressor S/N: 4FVCABAA17U378993 C/W: 150 psi Working Pressure, 2006 US EPA Label, CARB Compliant, Kubota 4IRX3T2 4 Cylinder 46.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 729 Hr Asset located in: Humble, TX
8349	2012 Ingersoll Rand P185WJD T4i 185 cfm Mobile Air Compressor S/N: 437511UCWD75 C/W: 150 psi Working Pressure, 2012 US EPA Label, CARB Compliant, John Deere 4024TF281C 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,081 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8360	2006 Sullair 185 CFM 185 cfm Mobile Air Compressor S/N: 200607270106 C/W: 300 psi Working Pressure, 2006 US EPA Label, CARB Compliant, John Deere 4024TF270A 4 Cylinder 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 291 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8361	Sullair 185DPQ 185 cfm Mobile Air Compresso
8350	2011 Doosan C185WJD-T4I Mobile Air Compressor S/N: 427569UFVE43 C/W: 200 psi Working Pressure, 2011 US EPA Label, CARB Compliant, John Deere 4024TF281C 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 710 Hr		S/N: 0046151309 C/W: 300 psi Working Pressure, 2005 US EPA Label, CARB Compliant, John Deere 4024TF270A 4 Cylinder 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 539 Hr Asset located in : Humble, TX
	Asset located in: Humble, TX	8362	8362 Sullair 185DPQ 185 cfm Mobile Air Compress
8351	2012 Doosan C185WJD-T4I Mobile Air Compressor S/N: 4314506UIVE43 C/W: 200 psi Working Pressure, 2011 US EPA Label, CARB Compliant, John Deere 4024TF281C 4 Cylinder 37 kW 2.4 L Diesel		S/N: 004152325 C/W: 185 psi Working Pressure, 2005 US EPA Label, CARB Compliant, John Deere 4024TF270A 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 384 Hr Asset located in : Humble, TX
	Engine, S/A Trailer, Ball Hitch Usage: 2,197 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	8363	Sullair 185DPQJD 185 cfm Air Compressor S/N: 004152324 C/W: 300 psi Working Pressure, 2005 US EPA Label, CARB Compliant, John Deere 4024TF270A 4 Cylinder 45.5 kW 2.4 L Diesel
8352	2011 Ingersoll Rand P185WJD T4i 185 cfm Mobile Air Compressor S/N: 421650UAVD75		Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 73 Hr Asset located in : Humble, TX
	C/W: 2010 US EPA Label, John Deere 4024TF281C 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 262 Hr Asset located in : Humble, TX	8364	Sullair 185DPQJD 185 cfm Mobile Air Compressor S/N: 004145077 C/W: 2004 US EPA Label, John Deere 4024TF270A 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 222 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8365	2006 Atlas Copco XAS97JD 185 cfm Mobile Air Compressor S/N: 4500A10186R016162 C/W: 123 psi Working Pressure, 2006 US EPA Label, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,410 Hr Asset located in: Humble, TX	8370	Airman PDS185S-6C2 185 cfm Mobile Air Compressor S/N: MT51055 C/W: 200 psi Working Pressure, Yanmar 4TNV88-BDHKS 49 hp 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Humble, TX
8366	2005 Ingersoll Rand P185WJD 185 cfm Mobile	8371	2017 Atlas Copco XAS110KDPE Mobile Air
	Air Compressor S/N: 356253UDPB34 C/W: 2005 US EPA Label, John Deere 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 915 Hr Asset located in: Humble, TX		Compressor S/N: APP451793 C/W: 260 bar Working Pressure, 2016 US EPA Label, CARB Compliant, Kubota D902-EF01 3 Cylinder 0.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 913 Hr
8367	2001 Ingersoll Rand P185WD Mobile Air		Asset located in: Humble, TX
	Compressor S/N: 318800UAL219 C/W: 160 psi Working Pressure, Deutz 4 Cylinder 45.8 kW Diesel Engine, S/A Trailer, Lunette Ring Usage: 4,745 Hr	8372 8374	Air Compressor S/N: Not Available Usage: Not Available Asset located in: Humble, TX Air Compressor
8368A	Asset located in: Humble, TX 1998 Ingersoll Rand P185WJD 185 cfm Mobile	-	S/N: AIA1573182/AIA1573183 Usage: Not Available
	Air Compressor S/N: 286198UBI221		Asset located in: Humble, TX
	C/W: 1998 US EPA Label, John Deere 4045DF150 4 Cylinder 80 hp 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 97 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8375	2008 Zeks Compressed Air Solutions 800NCEA400 Electric Air Dryer S/N: 315719 C/W: 3 Phase Motor Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8376	Skid Mounted Power Swivel
8368	2001 Ingersoll Rand P185WJD T4i 185 cfm Mobile Air Compressor S/N: 319787UCL221		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	C/W: 150 psi Working Pressure, 2001 US EPA Label, CARB Compliant, John Deere 4045DF150B 60 kW 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 115 Hr Asset located in : Humble, TX	8377	Pumping Unit S/N: DLFT101U025 C/W: 6 in Intake, 2.5 in Discharge, Centrifugal Chemical Pump Usage: Not Available Asset located in: Humble, TX
8369	1996 Ingersoll Rand P-185 Mobile Air	8378	Pumping Unit
	Compressor S/N: 263224UCG327 C/W: 200 psi Working Pressure, 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,522 Hr Asset located in: Humble, TX		S/N: DLFT100U021 C/W: 5 in Intake, 3 in Discharge, Centrifugal Chemical Pump Usage: Not Available Asset located in : Humble, TX
8370A	Sullivan D185PJD 185 cfm Mobile Air Compressor S/N: 31354 C/W: 110 psi Working Pressure, 2012 US EPA Label, CARB Compliant, John Deere 4024TF281A 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 332 Hr Asset located in: Humble, TX	8379	2013 Gardner-Denver TEE Electric Skid Mounted Triplex Fluid Pump S/N: Q021219 C/W: Baldor 125 hp 3 Phase Motor, 4 in Inlet, 1.5 in Outlet Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX-TX ; RITCHIE- BROS-ENERGY Asset located in: Midland, TX

Lot #	Details	Lot #	Details
8380	2013 Gardner-Denver TEE Electric Skid Mounted Triplex Fluid Pump S/N: Q021220 C/W: Baldor 125 hp 3 Phase Motor, 4 in Inlet, 1.5 in Outlet Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX-TX ; RITCHIE-	8389	2012 Paco Pumps 10-25123 Electric Skid- Mounted Water Pump S/N: Not Available C/W: Centrifugal, Emerson 15 hp electric motor Usage: Not Available Asset located in: Humble, TX
	BROS-ENERGY Asset located in: Midland, TX	8390	2012 Paco Pumps 10-25123 Electric Skid- Mounted Water Pump
8381	Pump S/N: Not Available C/W: John Deere 4039 4 Cylinder Diesel Engine Usage: Not Available		S/N: Not Available C/W: 4 in Intake, 4 in Discharge, Centrifugal, Emerson 15 hp electric motor Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8391	Goodwin CD300M Trailer-Mounted Water Pump
8382	Roots RCSH Vacuum Pump S/N: PB527294 Usage: Not Available Asset located in: Humble, TX		S/N: 0435462 C/W: 12 in Intake, 12 in Discharge, Centrifugal Water Pump, 2004 US EPA Label, Cat C-9 6 Cylinder 345 hp 8.8 L Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes
8383	2015 Premier Mud Pump S/N: 1P9BP1635FV591763		Usage: 1,355 Hr Asset located in: Humble, TX
	C/W: 8 in Intake, 8 in Discharge, Self Priming	0000	-
	Centrifugal Water Pump, US ĔPA Label, CAŘB Compliant, John Deere 4045TF290A 4 Cylinder 56 kW 4.5 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 3,816 Hr Asset located in : Humble, TX	8392	2015 Cornell 8NNTRP4045TF2 Trailer- Mounted Water Pump S/N: 1P9BP1635FV591701 C/W: 8 in Intake, 8 in Discharge, Self Priming Centrifugal Water Pump, 2015 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes
8384	Tulsa Rig Iron Pump S/N: TT150-52		Usage: Not Available Asset located in: Humble, TX
	C/W: Triplex 2014 US EPA Label, Cummins 6 Cylinder Diesel Engine Usage: 642 Hr	8393	2017 Cornell 2 5H-RP-EM-16-3 Trailer-Mounted
8385	Asset located in: Humble, TX Pai PAI70HP3250 Skid Mounted Triplex Pump		Water Pump S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, 2004 US EPA Label
8385	Asset located in: Humble, TX Pai PAI70HP3250 Skid Mounted Triplex Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine Usage: 168 Hr		S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, 2004 US EPA Label, Deutz 4 Cylinder 75 hp Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Asset located in : Humble, TX
8385 8386	Asset located in: Humble, TX Pai PAI70HP3250 Skid Mounted Triplex Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine	-8394	S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, 2004 US EPA Label, Deutz 4 Cylinder 75 hp Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Asset located in : Humble, TX 2016 Cornell Trailer-Mounted Water Pump S/N: 1P9BP153XGV591048 C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 4 Cylinder 55 kW Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 1,159 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX Pai PAI70HP3250 Skid Mounted Triplex Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine Usage: 168 Hr Asset located in: Humble, TX 2005 Sykes 300D Skid-Mounted Water Pump S/N: 5301029053 C/W: 12 in Intake, 12 in Discharge, Centrifugal Water Pump, VOLVO PENTA TAD 721 VE 6 Cylinder Diesel Engine Usage: 4,304 Hr Asset located in: Humble, TX 2014 Cornell 4NNTL-RP-F85 Electric Skid-	-8394	S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, 2004 US EPA Label, Deutz 4 Cylinder 75 hp Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Asset located in : Humble, TX 2016 Cornell Trailer-Mounted Water Pump S/N: 1P9BP153XGV591048 C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 4 Cylinder 55 kW Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 1,159 Hr
8386	Asset located in: Humble, TX Pai PAI70HP3250 Skid Mounted Triplex Pump S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4 Cylinder Diesel Engine Usage: 168 Hr Asset located in: Humble, TX 2005 Sykes 300D Skid-Mounted Water Pump S/N: 5301029053 C/W: 12 in Intake, 12 in Discharge, Centrifugal Water Pump, VOLVO PENTA TAD 721 VE 6 Cylinder Diesel Engine Usage: 4,304 Hr Asset located in: Humble, TX	8394	S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, 2004 US EPA Label, Deutz 4 Cylinder 75 hp Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Asset located in : Humble, TX 2016 Cornell Trailer-Mounted Water Pump S/N: 1P9BP153XGV591048 C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 4 Cylinder 55 kW Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 1,159 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
8396	2016 Premier 4NNTLRP3CE1T Trailer-Mounted Water Pump S/N: 1P9BF1203GV591681 C/W: 4 in Intake, 4 in Discharge, Centrifugal Tier 4, 2015 US EPA Label, Kubota V1505-EF01 4 Cylinder 1.5 L Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 3,703 Hr Asset located in: Humble, TX	8404	2014 Premier 6NNTLRP Trailer-Mounted Water Pump S/N: 193174 C/W: 6 in Intake, 6 in Discharge, Centrifugal US EPA Label, Deutz D19 L04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 7,642 Hr Asset located in: Humble, TX
8397	2016 Premier 6NNTPPD914T80 Trailer- Mounted Water Pump S/N: 1P9BP1539GV501042 C/W: 6 in Intake, 6 in Discharge, Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 1,402 Hr Asset located in: Humble, TX	8405	2014 Premier 4NNTL-RP Trailer-Mounted Water Pump S/N: 140924 C/W: 4 in Intake, 4 in Discharge, Centrifugal Water Pump, Isuzu 3CE1-BDZP1E 3 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 5,465 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
8398	2016 Premier 6NNTPPD914T80 Water Pump		THE INSPECTION REPORT
	S/N: 160510 Usage: 1,514 Hr		Asset located in: Humble, TX
8399	Asset located in: Humble, TX 2015 Premier 6NNT-RP-D914L04 Water Pump S/N: 150404 Usage: 4,973 Hr Asset located in: Humble, TX	8406	2013 Premier 6NNT-RP Trailer-Mounted Water Pump S/N: 185050 C/W: 6 in Intake, 6 in Discharge, Centrifugal 2012 US EPA Label, Deutz D19 L04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes
8400	2015 Premier 8NNT-PP-4045TF2 Water Pump		Usage: 7,396 Hr
	S/N: 150551 Usage: 3,816 Hr		Asset located in: Humble, TX
8401	Asset located in: Humble, TX 2015 Premier 6NNT-RP-D914L04 Trailer- Mounted Water Pump S/N: 200198 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, US EPA Label, Deutz D19 L04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 5,718 Hr	8407	2013 Premier 6NNT-RP Trailer-Mounted Water Pump S/N: 185012 C/W: 4 in Intake, 4 in Discharge, Centrifugal Diesel Engine, S/A Trailer, Lunette Ring Usage: 4,163 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8408	2013 Cornell 6NNT-RP Trailer-Mounted Water
8402	2015 Premier 4NNT-PP-E25-S Skid-Mounted Water Pump S/N: 1P9BP1028FV591949 C/W: 4 in Intake, 4 in Discharge, Centrifugal Usage: 302 Hr Asset located in: Humble, TX		Pump S/N: 1P9BP1539PV591685 C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: Not Available
8403	2015 Premier 6NNT-RP-4045TF2 Trailer- Mounted Water Pump S/N: 91777		Notes: LOCATED-IN-HOUSTON-TX-HOU DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: 6 in Intake, 6 in Discharge, Centrifugal		Asset located in: Humble, TX
	John Deere Diesel Engine, S/A Trailer, Lunette Ring Usage: 5,996 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	8409	2010 Pioneer PP66S12L Trailer-Mounted Water Pump S/N: Not Available C/W: Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,177 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8410	Cornell Trailer-Mounted Water Pump S/N: Not Available C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8418	2007 Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder S/N: U1070900459 C/W: 2007 US EPA Label, Deutz 49 hp 3.1 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 339 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8411	Cornell 2.5H-RP-EM16-3 Trailer-Mounted Water Pump S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, Deutz 4 Cylinder 56 kW Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,612 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8419B 8419A 8419A	Asset located in: Humble, TX 2014 Lincoln Vantage 400 450 A Skid-Mounted Multi-Process Engine Driven Welder S/N: Not Available C/W: Tier 4, 2014 US EPA Label, CARB Compliant, Perkins 4 Cylinder Diesel Engine, Welding Leads Not Included, /17 kW Rated 3 Phase Output, 240 V Rated Voltage, /11 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: 3,596 Hr
8412	2011 Pioneer PP63C17L Trailer-Mounted Water Pump S/N: 17180 C/W: 6 in Intake, 3 in Discharge, Self Priming		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	Centrifugal Water Pump, US EPA Label, Deutz 6 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,794 Hr Asset located in : Humble, TX		Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder S/N: Not Available
8413	Gorman-Rupp 14C2F3L Trailer-Mounted Water Pump S/N: 1153239 C/W: 4 in Intake, 4 in Discharge, Centrifugal Water Pump, Deutz 3 Cylinder Diesel Engine, S /A Trailer, Lunette Ring Usage: 30 Hr Asset located in: Humble, TX		C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,448 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Lincoln Vantage 400 400 A Skid-Mounted
8414	Cat C4.4 NLB TRIPLEX WATER BLASTER Hydraulic Power Pack S/N: 44408721 C/W: 2010 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Multi-Process Engine Driven Welder S/N: U1160205208 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8415	2019 Lincoln Vantage 549 Engine Driven Welder S/N: U1190410051 Usage: Not Available Asset located in: Humble, TX	- 8421	2013 Miller Big Blue Turbo 600 A Mobile Multi- Process Engine Driven Welder S/N: MD330191E C/W: 2012 US EPA Label, CARB Compliant, Deutz TD2011L04 4 Cylinder 70 hp 3.6 L Diesel Engine, Welding Leads Not Included, S/A Trailer, Ball Hitch
8416	2019 Lincoln Vantage 549 Engine Driven Welder S/N: U0190600260 Usage: Not Available Asset located in: Humble, TX		Usage: 2,621 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8423	2019 Lincoln Vantage 549 525 A Mobile Multi- Process Engine Driven Welder S/N: U1190607480 C/W: Tier 4, 2019 US EPA Label, CARB Compliant, Deutz TD2.9L4 36 kW 2.0 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 240 V / 120 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 4,806 Hr	8434 8435	2015 Miller Maxstar 350 300 A TIG Electric Welder S/N: MF041076L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX 2015 Miller Maxstar 350 300 A TIG Electric
8424 8426	Asset located in: Humble, TX 2019 Lincoln Vantage 549 525 A Mobile Multi- Process Engine Driven Welder S/N: U0190800142 C/W: Tier 4, 2019 US EPA Label, CARB Compliant, Deutz TD 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 240 V / 130 V Rated Voltage, S/A Trailer, Ball Hitch Usage: 5,129 Hr Asset located in: Humble, TX Lincoln SA200 200 A Mobile Engine Driven	8436	Welder S/N: MF041071L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX Quantity of (3) Miller Auto-Axcess 300 A Electric Welder S/N: MH081022U; MH081012U C/W: 3 Phase, Single Phase, 115 V Input, Welding Leads Not Included Usage: Not Available
	Welder S/N: A98802 C/W: Diesel Engine, Welding Leads, 28 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8437	Asset located in: Humble, TX 2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME421320L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX
8427	1981 Miller SRH-555 500 A Skid-Mounted ARC Electric Welder S/N: JB492716 C/W: 3 Phase, 208 V/ 460 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX	8438	2015 Miller Maxstar 350 TIG 300 A TIG Electric Welder Electric Welder S/N: ME450710L C/W: 3 Phase, Single Phase, 115 V Input Usage: Not Available Asset located in: Humble, TX 2014 Miller Maxstar 350 300 A TIG Electric
8428	Miller Dimension 1000 Electric Welder S/N: Not Available C/W: 3 Phase, 230 V/ 460 V Input Usage: Not Available Asset located in: Humble, TX	- 8439	Welder S/N: ME421319L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX
8429 8431	Miller Dimension 1000 Electric Welder S/N: Not Available C/W: 3 Phase, 220 V/ 460 V Input Usage: Not Available Asset located in: Humble, TX 2018 Lincoln Vantage 322 400 A Skid-Mounted Multi-Process Electric Welder	8440	2015 Miller Maxstar 350 300 A TIG Electric Welder S/N: MF041075L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX
8432	S/N: U1181200871 C/W: Tier 4, 2018 US EPA Label, Kubota V1505- BG-EF02 4 Cylinder 1.5 L Diesel Engine, Welding Leads Not Included Usage: 1,326 Hr Asset located in: Humble, TX Quantity of (3) Miller Auto-Axcess E675 300 A Electric Welder S/N: MH081014U, MH081021U, MH081013U C/W: 3 Phase, Single Phase, 115 V Input, Welding Leads Not Included	8441	2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME450711L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX		

1	Detaile	1	Dataila
Lot #	Details	Lot #	Details
8442	2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME520036L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX	8450	Quantity of (5) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input Usage: Not Available Asset located in: Humble, TX
8443	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX	8451	2021 Terex RL4 6 kVA Light Tower S/N: 7FSBL1018MB946287 C/W: 2019 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch Usage: 1,223 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
8444	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX	8452	2019 Terex RL4 6 kVA Light Tower S/N: RL4J-10042 C/W: 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8445	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input Usage: Not Available Asset located in: Humble, TX	8453A	2020 Doosan 6 kW Light Tower S/N: 4FVLSBAA0LU497951 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 234 Hr Asset located in: Humble, TX
8446	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input Usage: Not Available Asset located in: Humble, TX	8453	2020 Terex RL4 6 kVA Light Tower S/N: 4ZJSA1017L1012470 C/W: 2019 US EPA Label, Kohler 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 848 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8447 8448	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX Quantity of (6) Lincoln Electric FlexTec Skid- Mounted Multi-Process Multi-Operator Welder	8454	Asset located in: Lake Worth, TX 2019 Wacker Neuson 6 kW Light Tower S/N: 5XFLV0413KM000437 C/W: 2018 US EPA Label, CARB Compliant, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,322 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input, Welding Leads Not Included Usage: Not Available Asset located in : Humble, TX	8455	2018 Doosan LCV6WKUB-60HZ-T4F 6 kW Light Tower S/N: 4FVLSBAA4JU487646 C/W: 2018 US EPA Label, Kubota D1005-BG-
8449	Quantity of (3) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX		EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch Usage: 1,346 Hr Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8456	456 2018 Magnum MLT6SMD 6 kW Light Tower S/N: 3003412000 C/W: 2018 US EPA Label, Mitsubishi I3e 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, S/A Trailer, Ball Hitch Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE	8463	2016 Magnum MLT3060 6 kW Light Tower S/N: 5AJLS1416GB602786 C/W: 2015 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, Electric Winch Raise and Lower, S /A Trailer, Lunette Ring Usage: 3,689 Hr Asset located in: Humble, TX
	INSPECTION REPORT Asset located in: Lake Worth, TX	8464	2014 Magnum MLT3060K 6 kW Light Tower
8457	2018 Magnum MLT6SMD Light Tower S/N: 7FSXL1017JB411999 C/W: 2018 US EPA Label, CARB Compliant, Mitsubishi L3E 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,107 Hr Asset located in: Humble, TX		S/N: 1410888 C/W: Tier 4, 2014 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 2,905 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8458	2018 Wanco WLTT 6 kW Light Tower S/N: 5F13D1017J1007641 C/W: Kubota 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 4,456 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8465	2014 Magnum MLT3060 6 kW Light Tower S/N: SAJK141XE3400269 C/W: 2013 US EPA Label, Mitsubishi L3E 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,522 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8459	2018 Magnum MLT6SK Light Tower		Asset located in: Humble, TX
S/N: 3003103485 Usage: 2,660 Hr Asset located in: Humble, TX 8461 2016 Doosan 6 kW Light Tower S/N: 4FVLSACA5GU474212	Usage: 2,660 Hr Asset located in: Humble, TX 2016 Doosan 6 kW Light Tower S/N: 4FVLSACA5GU474212 C/W: Tier 4, 2015 US EPA Label, Kubota D1005-	8467	2014 Magnum 6 kW Light Tower S/N: 1411833 C/W: 2014 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 4,501 Hr Asset located in: Humble, TX
	Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,739 Hr	8468	2014 Magnum 6 kW Light Tower S/N: 1411836 C/W: 2014 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, S/A Trailer, Ball Hitch
8462	2016 Magnum MLT6SK 6 kW Light Tower S/N: 5AILS1016GB601871 C/W: Tier 4, 2015 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Lunette Ring Usage: 5,242 Hr		Usage: 4,405 Hr Notes : LIGHT TOWER MAST AND LAMPS MISSING-PLEASE SEE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Asset located in: Humble, TX	8469	2013 Magnum MLT0360K 6 kW Light Tower
8463A	2016 Doosan 6 kVA Light Tower S/N: 472214UJZG08 C/W: Tier 4, 2015 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 2,343 Hr		S/N: 1306082 C/W: Tier 4, 2013 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 5,996 Hr Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8470	2013 Magnum MLT0360K 6 kW Light Tower S/N: 1307067 C/W: Tier 4, 2013 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 7,074 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8472	2007 Allmand 6 kW Light Tower	8483	2014 Wanco WTLMB Solar Message Board
	S/N: Not Available C/W: Kubota D902 3 Cylinder 0.9 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 3,132 Hr		S/N: 5F12S1610E1001836 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
	Asset located in: Humble, TX	8484	2014 Wanco WTMMB Solar Message Board S/N: 5F12S1616E1001016
8474	2006 Magnum 6 kW Light Tower S/N: 060474 C/W: Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,384 Hr		C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8485	2005 Message Board S/N: 5F12S161X51004131
8475	2006 Magnum Light Tower S/N: Not Available C/W: 3 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,853 Hr Asset located in: Humble, TX		C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
8476	2006 Magnum Light Tower	8486	2010 Solar Tech Silent Sentinel Message Board
	S/N: 060977 C/W: 2005 US EPA Label, CARB Compliant, Mitsubishi 3 Cylinder 13 hp Engine, 4 Lamps, S		S/N: 4GM1A091XA1523805 Usage: Not Available
	/A Trailer		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 1,690 Hr Asset located in : Humble, TX		Asset located in: Humble, TX
8478	2005 Magnum 6 kW Light Tower S/N: 056332 C/W: Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,739 Hr Asset located in: Humble, TX	-8487	2004 Solar Tech Message Board S/N: 4GM2M151X41408942 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Electric Brakes Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8479	2019 Construction Electrical Prod 5322	1	Asset located in: Humble, TX
	Portable Work Lights S/N: Not Available Usage: Not Available Asset located in : Humble, TX	8488	Electric Radar Speed Limit Sign S/N: 7L31E7219KF050272 Usage: Not Available Asset located in: Humble, TX
8480	2019 Construction Electrical Prod 5322 Portable Work Lights	8489	2015 Hill And Smith CONSAM Radar Speed
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Limit Sign S/N: 7L31E7218F050523 Usage: Not Available Asset located in: Humble, TX
8481	2016 Work Area Protection SMC1000T Solar	0400	
	Message Board S/N: 1P91D1213GG301356 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available	8490	2018 Synergy AF100 Automated Flagger S/N: 180504 C/W: Flagger A & B Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8491	Quantity of (250) 2024 AGT AGT-75TC Traffic Cones (Unused)
	Asset located in: Humble, TX	FOR ILLUSTRATION P MAY NOT BE AN EXA THE ACTUAL PRODUC Usage: Not Available	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
8482	2015 Message Board S/N: 5F12S1616F1002005 C/W: LED Lighting, Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Asset located in: Humble, TX	1	

Lot #	Details	Lot #	Details
8492	Quantity of (250) 2024 AGT AGT-75TC Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8499	Quantity of (300) 2024 KJ K1428 28 in Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
8493	Quantity of (250) 2024 Suihe TC-250 Traffic	8500	Quantity of (2) Pallets of 2024 CXT C-75
0490	93 Quantity of (250) 2024 Suffer TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		Traffic Cones (Unused) S/N: 7-1 Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available	8501	Quantity of (2) Pallets of 2024 CXT C-75 Traffic Cones (Unused)
	Asset located in: Humble, TX	4	S/N: 7-2 Usage: Not Available
8494	Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused)		Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMA FOR ILLUSTRATION PUR MAY NOT BE AN EXACT	
8495	Quantity of (300) 2024 KJ K1428 28 in Traffic	1	Usage: Not Available
0490	Cones (Unused)		Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8503	Quantity of Traffic Barrels & Bases S/N: Not Available C/W: road barricades Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8504	Quantity of (100) 2024 AGT AGT-TBB Delineators (Unused)
Cones (Unu S/N: Not Av C/W: THE F	Quantity of (300) 2024 KJ K1428 28 in Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		S/N: Not Available C/W: Bunting Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	8505	Quantity of (100) 2024 Agriquip GLTD45
	THE ACTUAL PRODUCT Usage: Not Available		Delineators (Unused)
	Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
8497	Quantity of (300) 2024 KJ K1428 28 in Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	FOR ILLUSTRATION PURPOSES ONLY MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Usage: Not Available	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	MAY NOT BE AN EXACT REPRESENTATION OF	8506	Quantity of (8) Water Wall Barrier
	THE ACTUAL PRODUCT		S/N: Not Available
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available
8498	Quantity of (300) 2024 KJ K1428 28 in Traffic	-	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Cones (Unused)	L	Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8507	Quantity of (6) Airport Barricades S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8508	AM-Tank 2300N 2376 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82540 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX	8515	AM-Tank 800 838 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82541 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
8509	AM-Tank 2300N 2376 gal Skid Mounted Steel	8516	AM-Tank 800 838 gal Skid Mounted Steel
	Diesel Fuel Tank (Unused) S/N: 82539 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX		Diesel Fuel Tank (Unused) S/N: 82542 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
8510	2024 4-Fuel.com 2330 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005265 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX	8517	2024 4-Fuel.com 838 gal Steel Fuel Tank (Unused) S/N: 000003533 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
8511	2024 4-Fuel.com 2330 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005266 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available	8518	750 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8519	AM-Tank 600 655 gal Skid Mounted Steel Diesel Fuel Tank (Unused)
8512	2024 4-Fuel.com 1100 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005267 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available		S/N: 82544 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8520	AM-Tank 600 655 gal Skid Mounted Steel
8513	2024 4-Fuel.com 838 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005268 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available		Diesel Fuel Tank (Unused) S/N: 82543 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8521	2014 Transcube 30TCG Skid Mounted Steel
8514	2024 4-Fuel.com 838 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005269 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX		Fuel Tank S/N: A60499814 Usage: Not Available Asset located in: Humble, TX
		8522	2013 Transcube 30TCG Fuel Tank S/N: D727197 Usage: Not Available Asset located in : Humble, TX
		8523	2017 Transcube 20TCG Fuel Tank S/N: 16006358 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8524	2017 Transcube 20TCG Fuel Tank S/N: 16006350 Usage: Not Available Asset located in : Humble, TX	8536	2024 4-Fuel.com 116 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005272 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle
8525	2017 Transcube 20TCG 525 gal Steel Fuel Tank S/N: Not Available Usage: Not Available	0507	Usage: Not Available Asset located in : Humble, TX
0506	Asset located in: Humble, TX	8537	2024 4-Fuel.com 116 gal Portable Poly Diesel Fuel Tank (Unused)
8526	2016 Transcube 20TCG Fuel Tank S/N: A61281759 Usage: Not Available Asset located in: Humble, TX	-	S/N: 000005273 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available
8527	2016 Transcube 20TCG Fuel Tank S/N: A61281757 Usage: Not Available Asset located in: Humble, TX	8538	Asset located in: Humble, TX AM-Tank 116 gal Portable Poly Fuel Tank (Unused) S/N: 10575Q
8528	2016 Transcube 20TCG 528 gal Skid Mounted Steel Fuel Tank S/N: A61281790 Usage: Not Available		C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX
8529	Asset located in: Humble, TX 2014 Transcube 20TCG 528 gal Trailer Mounted Steel Fuel Tank S/N: 431FS0729E5000430 C/W: 12 V Transfer Pump Usage: Not Available	8539 AM-Tank 116 gal Portable Poly D Tank (Unused) S/N: 10577Q C/W: 12 V Transfer Pump, 13 ft H Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	S/N: 10577Q C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		AM-Tank 116 gal Portable Poly Diesel Fuel Tank (Unused)
8531	Transcube 20TCG 986 L Skid Mounted Steel Fuel Tank S/N: A61282840 Usage: Not Available		S/N: 10574Q C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX
8532	Asset located in: Humble, TX 2012 Transcube 30TCG 792 gal Steel Fuel Tank S/N: 1046	8541	Teran TDT116GL Fuel Tank (Unused) S/N: 46544L C/W: Polyethylene tank for diesel fuel transport
	Usage: Not Available Asset located in: Humble, TX	_	equipped with a fuel transfer unit, 116 gal with 12V Pump (12GPM), 13ft Hose, Auto-Nozzle, Top Covering Lid.
8533	300 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX	8551 2024 4-Fuel.com 58 gal Portable Po Fuel Tank (Unused) S/N: 000005274 C/W: 12 V Transfer Pump, 13 ft Hos Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	S/N: 000005274
8534	2024 4-Fuel.com 116 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005270		Automatic Shut-Off Nozzle Usage: Not Available
	C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX		S/N: 000005275
8535	2024 4-Fuel.com 116 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005271 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX		Automatic Shut-Off Nozzle Usage: Not Available

Lot #	Details	Lot #	Details
8553	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005276 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX 2024 4-Fuel.com 58 gal Portable Poly Diesel	8561	AM-Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 12202E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX AM-Tank 29 gal Portable Poly Diesel Fuel Tank
0004	Fuel Tank (Unused) S/N: 000005277 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8302	(Unused) S/N: 12203E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8555	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005278 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8563	AM-Tank 29 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 12204E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8556	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005279 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX	8564 8565	4000 Gallon Vertical Steel Storage Tank S/N: 19116 Usage: Not Available Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank S/N: 19114
8557	AM-Tank 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 58002A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8566	Usage: Not Available Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank S/N: 19119 Usage: Not Available Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank
8558	AM-Tank 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 58003A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8568	S/N: 19117 Usage: Not Available Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank S/N: 19120 Usage: Not Available Asset located in: Humble, TX
8559	AM-Tank 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 58001A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8569 8570	4000 Gallon Vertical Steel Storage Tank S/N: 19115 Usage: Not Available Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank S/N: 19113
8560	AM-Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 12201E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8571	S/N: 19113 Usage: Not Available Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank S/N: 19118 C/W: A Usage: Not Available Asset located in: Humble, TX
		8572	40 Gal Aluminum Fuel Tank S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8573 8574	AM-Tank Sprayer 14 55 L 14 gal NH3 Tank (Unused) S/N: Not Available C/W: Poly Tank, 3 ft Pup Usage: Not Available Asset located in: Humble, TX AM-Tank Sprayer 29 110 L 29 gal NH3 Tank (Unused)	8581	2024 Raystone RMC36-60 36 in x 60 ft Portable Conveyor (Unused) S/N: MC20240825012 C/W: Pintle Ring, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available	8582	2008 Stewart Glapat 2787T30SP Electric
	Usage: Not Available Asset located in: Humble, TX	0302	Extendable Dock Conveyor S/N: 08223102
8575	250 gal Steel Oil Tank S/N: Not Available		C/W: Pallet Jack, Tubs, Chain Usage: Not Available
	C/W: graco pneumatic pump Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	8583	2024 Genius GSM-66IN 32 In. x 6 Ft Separator Magnet (Unused)
8576	2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused) S/N: M202408565		Magnet (Unused) S/N: GSM08101 Usage: Not Available Asset located in: Humble, TX
	C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring	8584	2024 Genius GSM-66IN 32 In. x 6 Ft Separator
	Asset located in: Humble, TX		Magnet (Unused) S/N: GSM08102
8577	2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused) S/N: M202408566 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
		8585	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
8578	2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused) S/N: M202408567 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available	8586	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8587	2024 KJ K315 Grizzly Screen (Unused) S/N: Not Available
8579	2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused) S/N: M202408568		C/W: 10 ft x 7 ft Screen Usage: Not Available Asset located in: Humble, TX
	C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Asset located in : Humble, TX	8588	2024 KJ K315 Grizzly Screen (Unused) S/N: Not Available C/W: 10 ft x 7 ft Screen
8580	2024 Raystone RMC36-60 36 in x 60 ft Portable Conveyor (Unused)	1	Usage: Not Available Asset located in : Humble, TX
	S/N: MC20240825011 C/W: Pintle Ring, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	8589	2024 Suihe VG Skid-Mounted Vibratory Screen (Unused) S/N: 00405395 C/W: 5 ft x 4 ft 6 in Double Deck Screen, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8590	2024 Paladin SMS-64-40G Skid-Mounted Screen (Unused) S/N: Not Available C/W: 4 ft 10 in x 4 ft 6 in Double Deck Screen Usage: Not Available Asset located in: Humble, TX	8603	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4013090 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX
8591	Topsoil Rock Screen (Unused) S/N: Not Available C/W: Single Deck Screen, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL	8604	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4015323 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX 2024 AGT 40 ft One-Way High Cube Multi-Door
	PRODUCT Usage: Not Available Asset located in: Humble, TX		Storage Container S/N: CFGU4013655 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box
8596	2024 Jisan 40 ft One-Way High Cube Multi- Door Storage Container S/N: JPCU2215010		Usage: Not Available Asset located in: Humble, TX
8597	C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in : Humble, TX	8606	2024 Suihe NC-40HQ-2 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0168420 C/W: 8 ft Wide, 9 ft 6 in High
0097	2024 Jisan 40 ft One-Way High Cube Multi- Door Storage Container S/N: JPCU2305942		Usage: Not Available Asset located in: Humble, TX
	C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	8607	2024 Suihe NC-40HQ -4 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0170726 C/W: 8 ft Wide, 9 ft 6 in High
8598	2024 40 ft High Cube Multi-Door Storage Container		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX 99 2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU2305578 C/W: One-Way Usage: Not Available Asset located in: Humble, TX 00 2024 40 ft High Cube Multi-Door Storage Container	8608	2024 Suihe NC-40HQ -3 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0167070
8599			C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in : Humble, TX
			2024 CTN 40HQ 40 ft One-Way High Cube Multi-Door Storage Container S/N: MMPU1040241 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box
8600			Usage: Not Available Asset located in: Humble, TX
	S/N: JPCU2213682 C/W: One-Way Usage: Not Available Asset located in : Humble, TX	8610	2024 Suihe NC-40HQ-2 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0168462 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box
8601	2024 40 ft High Cube Multi-Door Storage Container		Usage: Not Available Asset located in: Humble, TX
	S/N: JPCU2212578 C/W: One-Way Usage: Not Available Asset located in : Humble, TX	8611	2024 Suihe NC-40HQ-2 40 ft High Cube Multi- Door Storage Container S/N: LYPU0168436
8602	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4013038 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX		C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
		•	

Lot #	Details	Lot #	Details
8612	2024 Suihe NC-40HQ -4 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0170731 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available	8621	40 ft High Cube Storage Container S/N: IKSU8661283 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
8613	Asset located in: Humble, TX 2024 Suihe SC-40HQ -4 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYGU0171963 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX	_8622	40 ft High Cube Storage Container S/N: TCNU9624045 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8614	JESON 40 ft One-Way High Cube Storage Container S/N: HHXU3326668 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available	8623	40 ft High Cube Storage Container S/N: TRLU7025311 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
8615	Asset located in: Humble, TX 2024 ZHW 40 ft One-Way High Cube Multi- Door Storage Container S/N: CICU6661489	8624	40 ft High Cube Storage Container S/N: ZCSU8986893 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in : Humble, TX	8625	2007 CIMC 40 ft High Cube Storage Containe S/N: CMAU5102273 C/W: 8 ft Wide, 9 ft 6 in High
8616	2024 40 ft High Cube Multi-Door Storage Container		Usage: Not Available Asset located in: Humble, TX
	S/N: LYGU4147902 C/W: One-Way Usage: Not Available Asset located in : Humble, TX	8626	40 ft High Cube Storage Container S/N: APHU6652390 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available
8617A	40 ft Storage Container S/N: HHXU3289250 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in : Humble, TX	8627	Asset located in: Humble, TX 40 ft High Cube Storage Container S/N: CMAU5109508 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available
8617	2024 40 ft High Cube Multi-Door Storage Container		Asset located in: Humble, TX
	S/N: LYGU4147899 C/W: One-Way Usage: Not Available Asset located in: Humble, TX	8628	40 ft High Cube Storage Container S/N: CMAU4052250 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
8618	2009 40 ft High Cube Storage Container S/N: TCNU8813996 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX	8629	40 ft High Cube Storage Container S/N: TCLU5050785 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
8619	2004 40 ft High Cube Storage Container S/N: TDRU5550681 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX	8630	40 ft High Cube Storage Container S/N: TCLU9354852 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
8620	40 ft High Cube Storage Container S/N: TCNU9762466 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	8631	40 ft High Cube Storage Container S/N: TRLU6661134 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8632	40 ft High Cube Storage Container S/N: TCLU5438620 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	8643	40 ft Refrigerated Storage Container S/N: CBFU3468582 C/W: Carrier Reefer Unit Usage: Not Available Asset located in : Humble, TX
8633	40 ft High Cube Storage Container S/N: TCKU9956976 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	8644	2024 20 ft One-Way High Cube Multi-Door Storage Container S/N: VSLU2173753 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box, Fork Pockets
8634	40 ft High Cube Storage Container S/N: APHU6736762 C/W: 8 ft Wide, 9 ft 6 in High	8645	Usage: Not Available Asset located in: Humble, TX 2024 20 ft One-Way Multi-Door Storage
	Usage: Not Available Asset located in: Humble, TX		Container S/N: VSLU2173938
8635	40 ft High Cube Storage Container S/N: APHU6737028 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available	1	C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8646	2024 20 ft One-Way Multi-Door Storage
8636	40 ft High Cube Storage Container S/N: CMAU5059496 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available		Container S/N: VSLU2174071 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available
8637	Asset located in: Humble, TX		Asset located in: Humble, TX
	40 ft High Cube Storage Container S/N: APHU6593912 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	8647	2024 20 ft One-Way Multi-Door Storage Container S/N: VSLU2174153 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets
8638	40 ft High Cube Storage Container S/N: TRLU8264732		Usage: Not Available Asset located in: Humble, TX
	C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	8648	2024 20 ft One-Way Multi-Door Storage Container
8639	40 ft High Cube Storage Container	-	S/N: VSLU2174430 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork
0007	S/N: CMAU5242716 C/W: 8 ft Wide, 9 ft 6 in High		Pockets Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX	9640	Asset located in: Humble, TX 2024 20 ft One-Way Multi-Door Storage
8640	40 ft Storage Container S/N: TCLU5328270 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX	_8649	Container S/N: VSLU2173584 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available
8641	40 ft Storage Container	-	Asset located in: Humble, TX
0041	S/N: Not Available C/W: 8 ft Wide, 8 ft 6 in High Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8650	2024 SHANG 20 ft One-Way Storage Container S/N: ZXJU0137350 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX
8642	40 ft High Cube Refrigerated Storage Container S/N: TRIU8740325 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Carrier 69NT40 Reefer Unit Usage: Not Available Asset located in : Humble, TX	8651	20 ft Storage Container S/N: XHCU2623659 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
S/N: SF C/W: 8 Pocket: Usage:	20 ft High Cube Storage Container S/N: SPWU3005466 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE	8662	20 ft Standard Storage Container S/N: SPRU3088670 C/W: One-Way Usage: Not Available Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8663	20 ft Storage Container S/N: TCKU1570605 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets
8653	20 ft One-Way Storage Container S/N: CICU6417050 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available		Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Asset located in: Humble, TX	8664	20 ft Storage Container
8654	20 ft One-Way Storage Container S/N: CICU6417174 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork		S/N: TCKU3956053 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX
	Pockets Usage: Not Available	8665	20 ft Storage Container
8655	Asset located in: Humble, TX 20 ft One-Way Storage Container	-	S/N: TCKU1623794 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
	S/N: CICU6359709 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	8666	20 ft Storage Container
8656	20 ft One-Way Storage Container S/N: CICU6417045 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork	8667	S/N: TCKU1364559 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX
	Pockets Usage: Not Available		
8657	Asset located in: Humble, TX 20 ft One-Way Storage Container		20 ft Storage Container S/N: APZU3283270 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
	S/N: CICU6417106 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork		Asset located in: Humble, TX
	Pockets	8668	20 ft Storage Container
	Usage: Not Available Asset located in: Humble, TX	_	S/N: TCLU3105106 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
8658	20 ft Storage Container S/N: XHCU2623730 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Pockets Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	8669	20 ft Storage Container
8659	20 ft Standard Double-Ended Storage Container S/N: SPRU2613829 C/W: One-Way	-	S/N: TRHU3827244 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE
	Usage: Not Available		THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	0670	
8660	20 ft Standard Double-Ended Storage Container S/N: SPRU2614358 C/W: One-Way Usage: Not Available Asset located in: Humble, TX	8670	20 ft Storage Container S/N: APZU3294778 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX
8661	20 ft Standard Storage Container	8671	20 ft Storage Container
0001	S/N: SPRU3089845 C/W: One-Way Usage: Not Available Asset located in: Humble, TX		S/N: TCKU2518089 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8672	20 ft Storage Container S/N: TCKU3007102 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8683	20 ft Storage Container S/N: CMAU1462440 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
8673	20 ft Storage Container S/N: TCKU2940860		Asset located in: Humble, TX	
0674	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX	8684	20 ft Storage Container S/N: TCKU1923533 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available	
8674	20 ft Storage Container S/N: APZU3402553		Asset located in: Humble, TX	
	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8685	20 ft Standard Storage Container S/N: HSMT001531 Usage: Not Available Asset located in: Humble, TX	
8675	20 ft Storage Container S/N: TCKU1447458 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available	8686	2024 AGT 12 ft x 7 ft 12 ft One-Way Storage Container S/N: CFGU1005785	
8676	Asset located in: Humble, TX 20 ft Storage Container S/N: TTNU1361095 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available		C/W: Window, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Asset located in: Humble, TX	0.07	Asset located in: Humble, TX	
8677	20 ft Storage Container S/N: SUDU1343404 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX 20 ft Storage Container	8687	2024 AGT 12 ft x 7 ft 12 ft One-Way Storage Container S/N: CFGU1004900 C/W: Window, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	S/N: TTNU1979289 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets		Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in: Humble, TX	8688	2024 AGT 12 ft One-Way Storage Container S/N: CFGU1003247	
8679	20 ft Storage Container S/N: APZU3448826 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX		C/W: Window, THE PRODUCT IMAGES ARE FOR ILLUSTRATION PURPOSES AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL F Usage: Not Available	C/W: Window, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8680	20 ft Storage Container	8689	2024 Suihe NMC-12G 12 ft One-Way Storage	
	S/N: APZU3383509 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX		Container S/N: GMPU9014854 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available	
8681	20 ft Storage Container S/N: TCLU2211510		Asset located in: Humble, TX	
	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX	8690	2024 Suihe NMC-12G 12 ft One-Way Storage Container	
8682	20 ft Storage Container S/N: TCKU1449907 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available	C/W: 7 ft 3 in Wide, 8 ft 3 in High Door, Lock Box, Window, Fork Po Usage: Not Available	S/N: GMPU9021940 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in : Humble, TX	
	Asset located in: Humble, TX	8691	2024 12 ft Storage Container S/N: KJ12-024 C/W: One-Way, Man Door, Window Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8692	12 ft Storage Container S/N: Not Available C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX	8704	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 3 in Wide x 4 ft 9 in High Usage: Not Available Asset located in : Humble, TX
8695	2024 10 ft Storage Container S/N: KJ10A-015 C/W: One-Way, Man Door, Window Usage: Not Available Asset located in: Humble, TX	8705	Roll-Off Container (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
8696	2024 Suihe NMC-9G 9 ft One-Way Storage Container S/N: GMPU9020965 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8706	Roll-Off Container S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: Not Available
8697	2024 AGT 9 ft One-Way Storage Container S/N: CFGU1000021 C/W: Window Usage: Not Available Asset located in: Humble, TX	8708	Usage: Not Available Asset located in: Humble, TX Quantity of (2) 2024 Suihe N-1CY -2 3 ft 6 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available
8698	2024 AGT 9 ft One-Way Storage Container S/N: CFGU1000280 C/W: Window Usage: Not Available Asset located in: Humble, TX		C/W: 3 ft 6 in Long x 3 ft 8 in Wide x 3 ft 4 in High, Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
8699 8700	2024 AGT 9 ft x 6 ft 9 ft One-Way Storage Container S/N: CFGU1000633 C/W: 6 ft 8 in Wide, 7 ft 5 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX 9 ft Storage Container	8709	Quantity of (2) Erie Industries TG10 Self- Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	S/N: CFGU1001136 C/W: One-Way, Man Door, Window Usage: Not Available Asset located in : Humble, TX	8710	Asset located in: Humble, TX Quantity of (2) Erie Industries TG10 Self- Dumping Hopper (Unused)
8701	9 ft Storage Container S/N: AGT23030911 C/W: One-Way, Man Door, Window Usage: Not Available Asset located in: Humble, TX	8711	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
8702 8703	2024 Suihe NMC-8G 8 ft One-Way Storage Container S/N: GMPU9021447 C/W: 6 ft 8 in Wide, 7 ft 5 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX 16 ft Roll-Off Container (Unused) S/N: Not Available		Quantity of (2) Erie Industries TG10 Self- Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	C/W: 16 ft Long x 7 ft 3 in Wide x 4 ft 9 in High Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8713	2024 Kit Containers 2YFT-SDH 5 ft 3 in 2 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Humble, TX	8722	2019 Kubota Z122RKW Zero-Turn Lawn Mower S/N: 22672 C/W: Hydrostatic Drive, 2016 US EPA Label, 11x4.00-5 Front Tires, 18x7.50x10 Rear Tires, 42 in Mower Usage: 333 Hr Asset located in: Humble, TX
8714	2024 Kit Containers 2YFT-SDH 5 ft 3 in 2 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available	8723	Kubota Z122RKW-42 Zero-Turn Lawn Mower S/N: 20986 C/W: 2016 US EPA Label, 11x4.00-5 Front Tires, 18x7.5 Rear Tires, 42 in Mower Usage: Not Available Asset located in: Humble, TX
8715	Asset located in: Humble, TX 2024 Kit Containers 2YFT-SDH 5 ft 3 in 2 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Humble, TX	8724	Kubota ZD121160 Zero-Turn Lawn Mower S/N: 14174 C/W: Hydrostatic Drive, 15x6.00x6 Front Tires, 26x12.00x12 Rear Tires, 60 in Mower Usage: 1,382 Hr Asset located in: Humble, TX Kubota ZD1211 Zero-Turn Lawn Mower S/N: 13587
8716	2024 Kit Containers 1.5YFT-SDH 5 ft 2 in 1.5 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 2 in Long x 4 ft 2 in Wide x 3 ft 3 in		C/W: Hydrostatic Drive, 15x6.00x6 Front Tires, 26x12.00x16 Rear Tires, 60 in Mower Usage: 3,223 Hr Asset located in : Humble, TX
	High Usage: Not Available Asset located in : Humble, TX	8726	Kubota Z122EBR Zero-Turn Lawn Mower S/N: 19525 C/W: Hydrostatic Drive, 2016 US EPA Label, CARB Compliant, 13X5.00-6 Front Tires, 22x10-
8717	2024 Kit Containers 1.5YFT-SDH 5 ft 2 in 1.5 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 2 in Long x 4 ft 2 in Wide x 3 ft 3 in		14 Rear Tires, 48 in Mower Usage: 280 Hr Asset located in: Humble, TX
	High Usage: Not Available Asset located in: Humble, TX	8727 8728	2017 Kubota Z121SKH Zero-Turn Lawn Mowe S/N: 21732 C/W: Canopy, Hydrostatic Drive, 2016 US EPA Label, 11x4.00-5 Front Tires, 22x10-14 Rear
8718	2024 Kit Containers 1.5YFT-SDH 5 ft 2 in 1.5 cu yd Self-Dumping Hopper (Unused) S/N: Not Available		Tires, 48 in Mower Usage: 168 Hr Asset located in: Humble, TX
	C/W: 5 ft 2 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in : Humble, TX		2009 Kubota ZG222 Zero-Turn Lawn Mower S/N: 12120 C/W: Hydrostatic Drive, 2008 US EPA Label, 13x5.00x8 Front Tires, 23x10.50x12 Rear Tires,
8719	Quantity of (3) Self-Dumping Hopper S/N: Not Available Usage: Not Available Asset located in: Humble, TX		48 in Mower Usage: 105 Hr Asset located in: Humble, TX
8720	Kit Containers 4Y-DH Debris Box (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8729	2007 Kubota ZD331LP Zero-Turn Lawn Mower S/N: 10045 C/W: Hydrostatic Drive, 15x6.00x6 Front Tires, 26x12.00x12 Rear Tires, 72 in Mower Usage: 1,026 Hr
8721	2019 Kubota ZD1211 Zero-Turn Lawn Mower S/N: KBGGDCA0CKGM41563 C/W: Hydrostatic Drive, 2019 US EPA Label, 15x6.50-8 Front Tires, 26x12-16 Rear Tires, 60 in Mower Usage: 615 Hr Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8730	8730 John Deere 1445 4x4 Ride-On Lawn Mower S/N: Not Available C/W: CVT, 2007 US EPA Label, CARB Compliant, 24x12.00-12 Front Tires, 215/50-10 Rear Tires, 72 in Mower Usage: Not Available	8744	2024 DYC GFX-4 Electric Golf Cart (Unused) S/N: 202407366 C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: 2 Km Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8745	2024 DYC GFXX-4 Electric Golf Cart (Unused) S/N: 202407362 C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available
8731	John Deere Lawn Mower		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	8746	2024 DYC GFXX-4 Electric Golf Cart (Unused) S/N: 202407363
8732	2023 Cub Cadet Ride-On Lawn Mower	_	C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available
0/02	S/N: 1F21PK60338		Asset located in: Humble, TX
	C/W: Hydrostatic Drive, 13x5.00-6 Front Tires, 16x6.50-8 Rear Tires, 30 in Mower Usage: Not Available	8747	2024 DYC GFXX-4 Electric Golf Cart (Unused) S/N: 202407364 C/W: 4 Passenger, Canopy, Windshield, Lift Kit
	Asset located in: Humble, TX	-	Usage: Not Available
8733	2024 Cub Cadet Ride-On Lawn Mower		Asset located in: Humble, TX
	S/N: 1D09RK60042 C/W: Hydrostatic Drive, 13x5.00-6 Front Tires, 16x6.50-8 Rear Tires, 30 in Mower Usage: Not Available Asset located in : Humble, TX	8748	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8CPC001596 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
8737	2024 LANM LAM800 Remote Control Crawler Lawn Mower (Unused) S/N: LAM240829 C/W: 22 in Mower		Notes : Crate Condition, Excess Inventory Batteries May Be Dead
			Asset located in: Humble, TX
	Usage: Not Available	8749	2023 Kandi KS4PSLR-B Electric Golf Cart
	Asset located in: Humble, TX		
8739	2024 DYC GFZ-4 Electric Golf Cart (Unused) S/N: 3702020241153 C/W: 4 Passenger, Canopy, Windshield, Lift Kit		S/N: A07DE5W8TPC001611 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	Usage: 2 Km		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
	Asset located in: Humble, TX		Asset located in: Humble, TX
8740	2024 DYC GFZ-4 Electric Golf Cart (Unused) S/N: 3702020241154 C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: 1 Km Asset located in : Humble, TX	8750	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8APC001682 C/W: 48 Volt Canopy Usage: Not Available
8741	2024 DYC GFZ-4 Electric Golf Cart (Unused) S/N: 3702020241151		Notes : Crate Condition, Excess Inventory Batteries May Be Dead
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: 1 Km		Asset located in: Humble, TX
	Asset located in: Humble, TX	8751	2023 Kandi KS4PSLR-B Golf Cart (Unused)
8742			S/N: A07DE5W8CPC001610 C/W: 48 Volt Canopy Usage: Not Available
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: 3 Km		Notes : Crate Condition, Excess Inventory Batteries May Be Dead
0740	Asset located in: Humble, TX		Asset located in: Humble, TX
8743	2024 DYC GFX-4 Electric Golf Cart (Unused) S/N: 202407365 C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: 5 Km Asset located in : Humble, TX	8752	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8CPC001686 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory
			Batteries May Be Dead Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8753	2023 Kandi KS4PSLR-B Electric Golf Cart	8760	2023 Kandi KS4PSLR-BK Electric Golf Cart
	(Unused)		(Unused)
	S/N: A07DE5W8CPC001624 C/W: 4 Passenger, Canopy, Lift Kit		S/N: A07DE5W8CPC001629 C/W: 4 Passenger, Canopy, Lift Kit
	Usage: Not Available		Usage: Not Available
	Notes: Crate Condition, Excess Inventory		Notes: Crate Condition, Excess Inventory
	Batteries May Be Dead Asset located in: Humble, TX		Batteries May Be Dead Asset located in: Humble, TX
8754	2023 Kandi KS4PSLR-MB Electric Golf Cart	8761	2023 Kandi KS4PSLR-B Golf Cart (Unused)
0/04	(Unused)	0/01	S/N: A07DE5W8TPC001625
	S/N: A07DE5W8EPC001685		C/W: 48 Volt Canopy, Windshield, Lift Kit
	C/W: 4 Passenger, Canopy, Lift Kit		Usage: Not Available
	Usage: Not Available Notes: Crate Condition, Excess Inventory		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
	Batteries May Be Dead		Asset located in: Humble, TX
	Asset located in: Humble, TX	8762	2023 Kandi KS4PSLR-BK Electric Golf Cart
8755	2023 Kandi KS4PSLR-MB Electric Golf Cart		(Unused)
	(Unused)		S/N: A07DE5W8APC001634
	S/N: A07DE5W8HPC001684		C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available		Notes: Crate Condition, Excess Inventory
	Notes: Crate Condition, Excess Inventory		Batteries May Be Dead
	Batteries May Be Dead		Asset located in: Humble, TX
	Asset located in: Humble, TX	8763	2023 Kandi KS4PSLR-B Electric Golf Cart
8756	2023 Kandi KS4PSLR-B Electric Golf Cart		(Unused)
	(Unused)		S/N: A07DE5W8PPC001609
	S/N: A07DE5W8KPC001594 C/W: 4 Passenger, Canopy, Lift Kit		C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	Usage: Not Available		Notes: Crate Condition, Excess Inventory
	Notes: Crate Condition, Excess Inventory		Batteries May Be Dead
	Batteries May Be Dead Asset located in: Humble, TX	0744	Asset located in: Humble, TX
8757	2023 Kandi KS4PSLR-MB Golf Cart	8764	2023 Kandi KS4PSLR-B Golf Cart (Unused) S/N: A07DE5W8LPC001683
0/3/	S/N: A07DE5W8JPC001595		C/W: 48 Volt Canopy, Windshield, Lift Kit
	C/W: 48 Volt Canopy		Usage: Not Available
	Usage: Not Available		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
	Notes: Crate Condition, Excess Inventory Batteries May Be Dead		Asset located in: Humble, TX
	Asset located in: Humble, TX	8765	2023 Kandi KS4PSLR-B Golf Cart (Unused)
8758	2023 Kandi KS4PSLR-BK Golf Cart (Unused)		S/N: A07DE5W8PPC001626
	S/N: A07DE5W8EPC001668		C/W: 48 Volt Canopy, Windshield, Lift Kit
	C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available		Usage: Not Available Notes : Crate Condition, Excess Inventory
	Notes: Crate Condition, Excess Inventory		Batteries May Be Dead
	Batteries May Be Dead		Asset located in: Humble, TX
	Asset located in: Humble, TX	8766	2023 Kandi KS4PSLR-BK Electric Golf Cart
8759	2023 Kandi KS4PSLR-BK Golf Cart (Unused)		(Unused)
	S/N: A07DE5W8CPC001607		S/N: A07DE5W8TPC001642
	C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available		C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	Notes: Crate Condition, Excess Inventory		Notes: Crate Condition, Excess Inventory
	Batteries May Be Dead		Batteries May Be Dead
	Asset located in: Humble, TX		Asset located in: Humble, TX
		8767	2023 Kandi KS4PSLR-BK Golf Cart (Unused)
			S/N: A07DE5W8VPC001647 C/W: 48 Volt Canopy, Windshield, Lift Kit
			Usage: Not Available
			Notes: Crate Condition, Excess Inventory
			Batteries May Be Dead
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8768	2023 Kandi KS4PSLR-BK Electric Golf Cart (Unused) S/N: A07DE5W8VPC001664 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead Asset located in: Humble, TX	8777	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031887 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8769	2023 Kandi KS4PSLR-BK Electric Golf Cart	8778	2019 Club Car Precedent Electric Golf Cart
8709	(Unused) S/N: A07DE5W8TPC001608 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory	0,70	S/N: JE1949031888 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX
	Batteries May Be Dead Asset located in: Humble, TX	8779	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031890
8770	2023 Kandi KS4PSLR-BK Electric Golf Cart (Unused) S/N: A07DE5W8LPC001666 C/W: 4 Passenger, Canopy, Lift Kit		C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Notes : Crate Condition, Excess Inventory Batteries May Be Dead Asset located in : Humble, TX	8780	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031892 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available
8771	2023 Kandi KS4PSLR-BK Golf Cart (Unused) S/N: A07DE5W8LPC001649 C/W: 48 Volt Canopy, Windshield, Lift Kit		Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: Not Available		Asset located in: Humble, TX
	Notes : Crate Condition, Excess Inventory Batteries May Be Dead Asset located in : Humble, TX	8781	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031893 C/W: Battery Charger, 2 Passenger, Canopy, Windshield
8772	2023 Kandi KS4PSLR-MB Golf Cart (Unused) S/N: A07DE5W8APC001651 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes : Crate Condition, Excess Inventory Batteries May Be Dead	8782	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031895
8773	Asset located in: Humble, TX 2023 Kandi KS4PSLR-MB Golf Cart (Unused) S/N: A07DE5W8LPC001652	_	C/W: 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX
	C/W: 48 Volt Canopy, Windshield, Lift Kit	8783	2019 Club Car Precedent Electric Golf Cart
	Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead Asset located in: Humble, TX	0/03	S/N: JE1949031896 C/W: Battery Charger, 2 Passenger, Canopy, Windshield
8775	2019 Club Car Precedent Electric Golf Cart		Usage: Not Available Asset located in: Humble, TX
	S/N: JE1949031883 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX	8784	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031897 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available
8776	2019 Club Car Precedent Electric Golf Cart		Asset located in: Humble, TX
	S/N: JE1949031885 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in : Humble, TX	8785	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031898 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8786	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031899 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX 2019 Club Car Precedent Electric Golf Cart S/N: JE1949031900 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX	8800	2019 Kubota RTVX1140WH 4x4 Utility Vehicle S/N: A5KD2GDBLKG033786 C/W: Canopy, 4 Passenger, Windshield, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2019 US EPA Label, Kubota D1105 3 Cylinder 18.2 kW 1.1 L Diesel Engine Usage: 1,735 Hr Asset located in: Humble, TX 2019 Kubota RTVX1140WH 4x4 Utility Vehicle S/N: A5KD2GDBPKG031768 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, Tier 4, 2019 US	
8788	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031901 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available	8802	EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 2,498 Hr Asset located in: Humble, TX 2019 Kubota RTV-X1140 4x4 Utility Vehicle	
8789	Asset located in: Humble, TX 2019 Club Car Precedent Electric Golf Cart S/N: JE1949031902 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available	8803	S/N: A5KD2GDBPKG032578 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed Usage: 1,659 Hr Asset located in: Humble, TX 2018 Kubota RTV-X1140 4x4 Utility Vehicle	
8792	Asset located in: Humble, TX 2003 E-Z-Go Electric Golf Cart S/N: 1564032 C/W: 36 Volt Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Note: DEFICIENCIES NOTED, DI FASE SEE		S/N: A5KD2GDBEJG026788 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, Kubota D1105-EF02 3 Cylinder 1.1 L Diesel Engine Usage: 3,120 Hr Asset located in: Humble, TX	
8793	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX E-Z-Go Electric Golf Cart S/N: 2682928 C/W: 36 Volt Battery Charger, 2 Passenger,	8804	S/N: A5KD2GDBTJG026714 C/W: Open Operator Station, 4 Passeng Windshield, Brush Guard, Hitch Receive Electric Dump Bed, Tier 4, 2018 US EPA Kubota 3 Cylinder 1.1 L Diesel Engine	C/W: Open Operator Station, 4 Passenger, Windshield, Brush Guard, Hitch Receiver, Electric Dump Bed, Tier 4, 2018 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine
_	Canopy, Windshield, Utility Body Usage: Not Available Asset located in : Humble, TX		Usage: 1,871 Hr Asset located in: Humble, TX 2017 Kubota RTV-X1140 4x4 Utility Vehicle	
8794	2014 E-Z-Go Golf Cart S/N: 3054196 C/W: 4 Passenger, Canopy, 2013 US EPA Label, Kawasaki 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX		S/N: A5KD2GDBPHG020584 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2017 US EPA Label, Kubota D1105-EF02 3 Cylinder 1.1 L Diesel Engine Usage: 644 Hr Notes : OFF HIGHWAY USE ONLY	
8799	2020 Kubota RTV-X1140 4x4 Utility Vehicle		Asset located in: Humble, TX	
	S/N: A5KD2GDBKLG036018 C/W: Canopy, 4 Passenger, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2019 US EPA Label, Kubota D1105 3 Cylinder 18.2 kW 1.1 L Diesel Engine Usage: 2,252 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8806	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBHHG018974 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Electric Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 2,535 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8807	2017 Kubota RTV-X1140 4x4 Utility Vehicle	8815	2017 Kubota RTVX900 4x4 Utility Vehicle
	S/N: A5KD2GDBKHG020599 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota 3 Cylinder Diesel Engine, EQUIPMENT-FROM-A-PRIMORIS-SERVICES- CORP-COMPANY		S/N: A5KB2FDBHHG041270 C/W: Canopy, 2 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D902 3 Cylinder 0.9 L Diesel Engine Usage: Not Available
	Usage: 2,294 Hr		Asset located in: Humble, TX
8808	Asset located in: Humble, TX	8816	2017 Kubota RTV-X900 4x4 Utility Vehicle
0000	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBEHG017485 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, 2017 US EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 1,373 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: A5KB2FDBAHG043999 C/W: Canopy, 2 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D902 3 Cylinder 0.9 L Diesel Engine Usage: 2,094 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8817	2020 Cat CUV105D 4x4 Utility Vehicle
8809	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBCHG017309 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, 3 Cylinder Diesel Engine		S/N: 4UF30MPV5LT300425 C/W: Open Operator Station, 5 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.02 L Diesel Engine Usage: 1,342 Hr Asset located in: Humble, TX
	Usage: Not Available	8818	2020 Cat CUV105D Utility Cart
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 4UF30MPVXLT300498 C/W: Open Operator Station, 5 Passenger,
	Asset located in: Humble, TX	4	Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler
8810	2017 Kubota RTVX1140WH 4x4 Utility Vehicle S/N: A5KD2GDBEHG019947 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, Tier 4, Kubota D1105 3 Cylinder Diesel Engine Usage: 2,133 Hr		1.0 L Diesel Engine Usage: 912 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8819	2020 Cat CUV105D Utility Cart
8811	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBCHG018511 C/W: Canopy, Brush Guard, Manual Dump Bed, Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 2,852 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: GD500524 C/W: Open Operator Station, 5 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 1.0 L Diesel Engine Usage: 8,975 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX
8812	2017 Kubota 4x4 Utility Vehicle S/N: A5KD2GDBLHG018892 C/W: Canopy, 4 Passenger, Windshield, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: 3,717 Hr	8820	2020 Cat CUV105D 4x4 Crew Utility Vehicle S/N: 4UF30MPV1LT300423 C/W: Open Operator Station, 5 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 3 Cylinder 19 kW Diesel Engine Usage: 980 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8821	2020 Cat CUV105D 4x4 Utility Vehicle
8813	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBJHG019924 C/W: Canopy, 4 Passenger, Windshield, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 4UF30MPV4LT300433 C/W: Open Operator Station, 5 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.02 L Diesel Engine Usage: 9,553 Mi Asset located in : Humble, TX

Lot #	Details	Lot #	Details	
8822	2020 Cat CUV105D 4x4 Utility Vehicle S/N: 4UF30MPVXLT300478 C/W: Open Operator Station, 4 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.02 L Diesel Engine Usage: 1,064 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8829	2018 Kawasaki Mule 4x4 Utility Vehicle S/N: JKBAFSB12JB512343 C/W: Canopy, 6 Passenger, Rear Screen, Locking Front Differential, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, 3 Cylinder Gasoline Engine Usage: 1,862 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
8823	2020 Cat CUV1050 4x4 Utility Vehicle		· ·	
8824	S/N: 4UF30MPVXLT300002 C/W: Open Operator Station, 5 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 3 Cylinder 1.02 L Diesel Engine Usage: 1,294 Hr Asset located in: Humble, TX 2019 Polaris Pro XD 2000D 4x4 Utility Vehicle	8830	Vehicle S/N: JKAAFCB11HB501452 C/W: Canopy, 6 Passenger, Rear Screen, Locking Front Differential, Brush Guard, H Receiver, Manual Dump Bed, 2016 US EPA Label, Yanmar 3 Cylinder .99 L Diesel Eng Usage: 6,030 Mi	Vehicle S/N: JKAAFCB11HB501452 C/W: Canopy, 6 Passenger, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Manual Dump Bed, 2016 US EPA Label, Yanmar 3 Cylinder .99 L Diesel Engine
	S/N: 4XABBPD4XK8939340 C/W: Canopy, 2 Passenger, Manual Dump Bed,	8831	2017 Kawasaki 4x4 Utility Vehicle	
8825	Tier 4, 2019 US EPA Label, Kubota d902 3 Cylinder 18 kW .89 L Diesel Engine Usage: 1,413 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2018 Polaris Ranger 4x4 Utility Vehicle	8831	S/N: JKBAFSJ15HB504149 C/W: Canopy, 6 Passenger, Windshield, Locking Front Differential, Winch, Brush Guard, Manual Dump Bed, 2017 US EPA Label, CARB Compliant, 3 Cylinder 0.8 L Gasoline Engine Usage: 1,182 Hr	
0020	S/N: 4XARVAD18J8867867		Asset located in: Humble, TX	
	C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 2 Cylinder 1.0 L Diesel Engine	8832	2013 John Deere XUV560E S4 Utility Vehicle S/N: 17003161122276 Usage: Not Available Asset located in: Humble, TX	
		8833	John Deere Gator Utility Cart	
8826	Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2018 Polaris Ranger 4x4 Utility Vehicle	-	S/N: 4X2X089809 C/W: Open Operator Station, 2 Passenger, Manual Dump Bed, 1 Cylinder Gasoline Engi Usage: Not Available Asset located in : Humble, TX	
	S/N: 4XARVAD19J8867828 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 1.0 L Diesel Engine Usage: 1,409 Hr Notes: LOCATED-IN-FORT-WORTH-TX ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8834	2023 Massimo Buck 250 4x2 Utility Vehicle S/N: LL8ACMHF9P0A15353 C/W: Canopy, 2 Passenger, Windshield, Brush Guard, Manual Dump Bed, Linhai 1 Cylinder Gasoline Engine Usage: 266 Mi Asset located in: Humble, TX	
	Asset located in: Lake Worth, TX	8835	2024 CF Moto Uforce 4x4 Utility Vehicle	
8827	2018 Polaris Ranger 4x4 Utility Vehicle S/N: 4XARVAD14J8868966 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 2 Cylinder 1.0 L Diesel Engine Usage: Not Available		S/N: LCELV1ZA0RM000196 C/W: Enclosed Cab, 6 Passenger, Rear Screen, Winch, Manual Dump Bed, 2024 US EPA Label, CFMOTO POWER CO 962.6 cc Gasoline Engine Usage: 461 Mi Asset located in: Humble, TX	
	Notes: LOCATED-IN-FORT-WORTH-TX ;	8836A	Subaru 4x4 Utility Vehicle	
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		S/N: KS4350950 C/W: Enclosed Cab, Air Conditioner, 2 Passenger, Windshield, Rear Screen, Suburu Clover 4 4 Cylinder Gasoline Engine Usage: 99,500 Km	
			Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	
			ASSEL IUCALEU III. MUTIDIE, IA	

Lot #	Details	Lot #	Details
8836	Subaru Sambar 4x4 Utility Vehicle S/N: KS4128141 C/W: Enclosed Cab, 2 Passenger, Windshield, 4 Cylinder Gasoline Engine Usage: 60,481 Km Notes: DEFICIENCIES NOTED - PLEASE SEE	8844	2024 Meco MC16 Electric Three-Wheel Utility Vehicle (Unused) S/N: MC16240812 C/W: Enclosed Cab, Windshield, Brush Guard Usage: Not Available Asset located in: Humble, TX
	THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY	8845	2024 Meco MC16 Electric Three-Wheel Utility Vehicle
8837	Asset located in: Humble, TX Honda 4x4 Utility Vehicle S/N: HA42376292 C/W: Enclosed Cab, 2 Passenger, Windshield, Rear Screen, Gasoline Engine Usage: 65,852 Km Notes: NO TITLE AVAILABLE, SOLD WITH BILL	-	S/N: MC16240811 C/W: Enclosed Cab, 2 Passenger, Windshield, Manual Dump Bed Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	OF SALE ONLY-NO ETAG WILL BE ISSUED Asset located in: Humble, TX	8846	Asset located in: Humble, TX 2024 Meco M3 Electric Trike
8838	2024 Can-Am Commander 4x4 Side By Side S/N: 3JBAWAX43RE000051 C/W: Open Operator Station, 2 Passenger, Locking Front Differential, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, King Cobra	8847	S/N: M3240709 Usage: Not Available Asset located in: Humble, TX 2024 Meco M3 Electric Trike (Unused)
	Axles, 6 in Highlifter Portals Usage: 44 Hr		S/N: M3240710 Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	0040	
8839	2017 Polaris Razor RZP-XP4 1000 EPS 4x4 Side By Side S/N: 3NSVFE995HF786649 C/W: Canopy, 4 Passenger, 2017 US EPA Label, CARB Compliant, Polaris 999 cc Gasoline Engine Usage: 131 Hr	8848	Tao Motor D125 4x2 ATV (Unused) S/N: L9LACED33N1605345 C/W: Electric Start, 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	•	8849B	Tao Motor 4x2 110 CC 4 Stroke ATV (Unused)
8840	Asset located in: Humble, TX 2012 Polaris Outlaw 50 Four Wheeler S/N: RF3KA05A5CT020785 C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX 2021 Polaris Crostemen Ar4 I trillie: Vehicle	00498	S/N: L9NACFDJ7P1904824 C/W: Electric Start, 1 Cylinder Gasoline Engine, REMOTE CONTROL SPEED LIMITER / KILL SWITCH Usage: Not Available Notes : LOCATED-IN-HOUSTON-TX -
8841	2021 Polaris Sportsman 4x4 Utility Vehicle S/N: 4XASDE579MA740623 C/W: Open Operator Station, 2 Passenger, Winch, Hitch Receiver, 2021 US EPA Label, Polaris 1 Cylinder 44 hp 567 cc Gasoline Engine Usage: 34 Hr Asset located in: Humble, TX	8849A	Asset located in: Humble, TX Tao Motor 110 CC Boulder 4 Stroke ATV (Unused) S/N: L9NACFDJ4P1904859 C/W: Electric Start, 1 Cylinder Gasoline Engine, REMOTE CONTROL SPEED LIMITER / KILL
8842	2024 Meco M-F Electric Golf Cart (Unused) S/N: MF24062108 C/W: 4 Passenger, Windshield Usage: Not Available		SWITCH Usage: Not Available Notes : LOCATED-IN-HOUSTON-TX - Asset located in : Humble, TX
	Asset located in: Humble, TX	8849	Tao Motor B110 4x2 ATV (Unused)
8843	2024 Meco P4 Electric Utility Vehicle S/N: P4240705 C/W: Enclosed Cab, 4 Passenger, Windshield, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: L9NACFDJXP1904977 C/W: Electric Start, 1 Cylinder Gasoline Engine Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8850 8851	Razor 4x2 Electric Four Wheeler ATVS/N: 2107001C/W: 1 Forward GearsUsage: Not AvailableNotes: DEFICIENCIES NOTED - PLEASE SEETHE INSPECTION REPORTAsset located in: Humble, TX2020 Ford Mustang GT AutomobileS/N: 1FA6P8CF4L5158892	8855	 2016 Maserati Ghibli Automobile S/N: ZAM57XSA5G1173805 C/W: V6 3.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 151,867 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8852A	C/W: V8 5.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 39,970 Mi Notes : TITLE BRAND REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2019 Toyota Yaris Automobile		2016 Mercedes-Benz SLK300 Automobile S/N: WDDPK3JA7GF124359 C/W: 4 cyl Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 142,328 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 3MYDLBYV9KY519224 C/W: 4 cyl 1.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 122,032 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	8857	Asset located in: Humble, TX 2016 Nissan Sentra Automobile S/N: 3N1AB7AP6GY244287 C/W: 4 cyl 1.8 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Power Windows, Power Locks, Rear View Camera Usage: 134,867 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8852	2019 Kia Optima Automobile S/N: 5XXGT4L36KG355498 C/W: 4 cyl 2.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 137,417 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8860	2015 Chevrolet Camaro RS Automobile S/N: 2G1FF1E3XF9279806 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 123,798 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8853	2017 Nissan Altima Automobile S/N: 1N4AL3AP5HN317978 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 67,245 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8861	2015 Chevrolet Spark Automobile S/N: KL8CD6S93FC709764 C/W: 4 cyl 1.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 94,644 Mi Asset located in: Humble, TX
8854	Asset located in: Humble, TX 2017 Nissan Altima Automobile S/N: 1N4AL3AP7HN340310 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 103,311 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8863	2014 Maserati Ghibli Automobile S/N: ZAM57RTA1E1097670 C/W: V6 3.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 100,487 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8864 8865	2014 Toyota Corolla Automobile S/N: 5YFBURHE2EP016828 C/W: 4 cyl 1.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 210,831 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Honda Accord Automobile S/N: 1HGCT2B83EA008504	8870	 2013 Audi A7 Automobile S/N: WAU2GAFC5DN116540 C/W: V6 3.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 188,404 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	C/W: V6 3.5 L Gasoline Engine, 2014 US EPA		Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 191,896 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8871	2013 Chevrolet Spark Automobile S/N: KL8CB6S94DC565550 C/W: 4 cyl 1.2 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 162,122 Mi
8866	2014 Chevrolet SONIC Automobile		Asset located in: Humble, TX
	S/N: 1G1JA5SH0E4164942 C/W: 4 cyl 1.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 106,130 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8872	2013 Ford Fusion SE Automobile S/N: 3FA6P0H71DR254948 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Window Power Locks Usage: 142,832 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSIO
	Asset located in: Humble, TX		
8867	2014 Chevrolet Cruz Automobile S/N: 1G1PA5SH1E7283768 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Locks		AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
	Usage: 104,564 Mi Asset located in: Humble, TX	8873	2013 Ford Fusion SE Automobile
Asset located in: Humble, TX 8868 2014 Ford Taurus SE Automobile S/N: 1FAHP2D85EG102991 C/W: 6 cyl 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks	-	S/N: 3FA6P0H76DR351062 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 102,334 Mi Asset located in : Humble, TX	
	Usage: 163,220 Mi	8874	2013 Kia Optima SXL Automobile
8869	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2014 Toyota Camry LE Automobile		S/N: 5XXGR4A65DG147790 C/W: 4 cyl 2.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 132,668 Hr
	S/N: 4T1BF1FK7EU779527	0075	Asset located in: Humble, TX
	C/W: 4 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 85,988 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in : Humble, TX	8875	2013 Kia Optima GDI Automobile S/N: KNAGM4A7XD5422417 C/W: 4 cyl 2.4 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 153,887 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		8876	2013 Hyundai SONATA Automobile
			S/N: 5NPEB4AC8DH562561 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8877	2013 Nissan Sentra Automobile S/N: 3N1AB7AP4DL790448 C/W: Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 127,945 Mi Notes: TITLE COMES WITH REPOSSESSED VEHICLE AFFIDAVIT	8883	2012 Hyundai Veloster Automobile S/N: KMHTC6AD6CU052234 C/W: 4 cyl 1.6 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 65,183 Mi Notes: TITLE BRAND NOT ACTUAL MILEAGE REBUILT SALVAGE
	Asset located in: Humble, TX		Asset located in: Humble, TX
8879	2012 Dodge Charger SE Automobile S/N: 2C3CDXAT6CH146443 C/W: V8 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 106,391 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8884	2010 Mercedes-Benz E350 Automobile S/N: WDDHF5GB5AA080628 C/W: V6 3.5 L Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 141,127 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
8880	2012 Toyota Camry Automobile S/N: 4T1BF1FK0CU586066 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 202,597 Mi Notes: TITLE BRAND REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8885	2010 Honda Civic Automobile S/N: 2HGFG1B84AH524197 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 233,309 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8886	2010 Audi A5 Automobile
8881	2012 Mini Countryman Automobile S/N: WMWZC3C57CWL84316 C/W: 4 cyl Gasoline Engine, Automatic Transmission Usage: 128,096 Mi		S/N: WAUGFAFR5AA049180 C/W: 4 cyl 2.0 L Gasoline Engine, 6 Speed Manual Transmission, Air Conditioner, Power Windows, Power Locks Usage: 152,185 Mi Asset located in: Humble, TX
8882	Asset located in: Humble, TX	0007	
8882	2012 Chrysler 300 Automobile S/N: 2C3CCACG2CH199608 C/W: V6 3.6 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 102,133 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8887	2009 Mini Cooper S Automobile S/N: WMWMF73519TW84212 C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner Usage: 115,185 Mi Notes: LOCATED-IN-HOUSTON-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8883A	5	8888	2009 Mercedes-Benz C300 Automobile
	S/N: 3VWLX7AJ3BM346131 C/W: 5 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation Usage: 145,971 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: WDDGF54X99R051481 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 184,755 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Asset located in: Humble, TX	8889	2008 Mercedes-Benz SLK280 AWD Automobile
			S/N: WDBWK54F78F183985 C/W: V6 3.0 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 110,124 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
8890	2008 Lexus LS460 Automobile S/N: JTHBL46F885067879 C/W: V8 4.6 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 240,693 Mi Asset located in: Humble, TX	8900	2017 Nissan Pathfinder 4WD SUV S/N: 5N1DR2MM7HC666827 C/W: V6 3.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 177,097 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
8891	2008 Cadillac STS Automobile S/N: 1G6DW67V380103917		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: V6 3.6 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 99,172 Mi Asset located in: Humble, TX	8902	2016 Ford Explorer XLT 4WD SUV S/N: 1FM5K8D83GGC35441 C/W: V6 3.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,
8892	2008 Toyota Avalon Automobile S/N: 4T1BK36B68U285333		Rear View Camera, 3rd Row Usage: 237,346 Mi Asset located in: Humble, TX
	C/W: V6 3.5 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 209,124 Mi Asset located in : Humble, TX	8903	2016 GMC Acadia AWD SUV S/N: 1GKKVRKD9GJ165486 C/W: V6 3.6 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power
8895	2006 BMW 325i Automobile S/N: WBAVB13516PT16193 C/W: 6 cyl 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 199,257 Mi		Windows, Power Locks, Rear View Camera Usage: Not Available Notes : TITLE IS BRANDED AS NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX	8905	2013 Audi Q7 S Line Quattro AWD SUV S/N: WA1WMAFE0DD005019 C/W: V6 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 167,382 Mi Asset located in: Humble, TX
8897 2001 S/N: C/W: Cond	2001 Porsche Boxster Automobile S/N: WP0CA29821U622169 C/W: 5 Speed Manual Transmission, Air Conditioner, Power Windows		
	Usage: 93,713 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2011 Jeep Wrangler 4x4 SUV S/N: 1J4AA2D16BL639656 C/W: V6 3.8 L Gasoline Engine, Automatic
8898	2017 Chrysler Pacifica Minivan S/N: 2C4RC1EGXHR541231 C/W: V6 3.6 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 106,336 Mi		Transmission, Air Conditioner, Power Windows Usage: 79,110 Mi Notes : THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
8899	Asset located in: Humble, TX 2007 Honda Odyssey Minivan S/N: 5FNRL38247B066360 C/W: V6 3.5 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 159,880 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8907	2011 BMW X3 AWD SUV S/N: 5UXWX5C57BL702553 C/W: V6 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 157,739 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8908	2010 Infiniti EX35 Journey 2WD SUV S/N: JN1AJ0HR8AM755298 C/W: 6 cyl 3.5 L Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 149,618 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8909 8911	2007 Jeep Wrangler 4WD SUV S/N: 1J4FA541X7L209062 C/W: V6 3.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Winch Usage: 181,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2006 Chevrolet Tahoe Z71 4WD SUV S/N: 1GNEK13Z26R125089 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA	8916	2017 Chevrolet Tahoe 2WD SUV S/N: 1GNSCAKC7HR378571 C/W: V8 5.3 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 177,290 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
-0010	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 229,606 Mi Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in : Humble, TX	8917	2017 Chevrolet Tahoe LT 2WD SUV S/N: 1GNSCBKC2HR198629 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 151,279 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
8912	2005 Hummer H2 4WD SUV S/N: 5GRGN23UX5H104075 C/W: V8 6.0 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 117,230 Mi Asset located in: Humble, TX	8918	2017 Ford Escape 2WD SUV S/N: 1FMCU0GD9HUE71445 C/W: 3 cyl 1.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 175,892 Mi
8913	2005 Ford Excursion SUV S/N: 1FMSU45P95ED44832 C/W: V8 6.0 L Diesel Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: Not Available Asset located in: Humble, TX	8919	Asset located in: Humble, TX 2017 Ford Escape S 2WD SUV S/N: 1FMCU0F70HUB26560 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 134,079 Mi
8914	1995 Jeep Wrangler 4WD SUV S/N: 1J4FY29S0SP296922 C/W: 6 cyl 4.0 L Gasoline Engine, 1995 US EPA Label, Automatic Transmission, Bumper Mounted Winch Usage: 140,804 Mi		Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX
8915	Notes: TITLE BRANDS REBUILT SALVAGE RECONSTRUCTED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Infiniti QX80 2WD SUV S/N: JN8AZ2NF7K9682638 C/W: V8 5.6 L Gasoline Engine, 2019 US EPA	8920	2017 Dodge Journey 2WD SUV S/N: 3C4PDCGG9HT613806 C/W: V6 3.6 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 123,818 Mi Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 79,670 Mi Notes: . Asset located in: Humble, TX	8921	2017 Chevrolet Trax 2WD SUV S/N: 3GNCJKSB6HL220642 C/W: 1.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 131,519 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8922	2016 Land Rover Discovery Sport HSE Luxury 2WD SUV S/N: SALCT2BG9GH586387 C/W: 4 cyl 2.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 74,622 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8928A	2014 Nissan Pathfinder SV 2WD SUV S/N: 5N1AR2MNXEC680549 C/W: 3 cyl 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 159,299 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8928	2014 Nissan Pathfinder 2WD SUV
8923	2016 Nissan Pathfinder SV 2WD SUV S/N: 5N1AR2MN3GC666379 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 179,974 Mi Notes: TITLE BRAND REBUILT SALVAGE		S/N: 5N1AR2MN5EC683651 C/W: V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 224,141 Mi Asset located in : Humble, TX
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8929	2012 Ford Expedition 2WD SUV
	Asset located in: Humble, TX		S/N: 1FMJU1H59CEF62576 C/W: V8 5.4 L Gasoline Engine, 2012 US EPA
8924	2016 Chevrolet equinox LT 2WD SUV S/N: 2GNALCEK8G6106678 C/W: 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 171,388 Mi	-	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 239,704 Mi Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	0020	
8925	Asset located in: Humble, TX 2016 Nissan Rogue 2WD SUV S/N: KNMAT2MT9GP695821 C/W: 4 cyl 2.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera Usage: 114,068 Mi Notes: TITLE BRAND REBUILT SALVAGE Asset located in: Humble, TX	8930	2008 Ford Expedition 2WD SUV S/N: 1FMFU17578LA20080 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 219,864 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
8926	2015 Volvo XC60 2WD SUV		PRIOR TO BIDDING
	S/N: YV440MDB6F2589246 C/W: 4 cyl 2.0 L Gasoline Engine, 2015 US EPA	0001	Asset located in: Humble, TX
8927	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 75,598 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Nissan Pathfinder 2WD SUV	8931	2005 Land Rover Freelander SE 2WD SUV S/N: SALNY22295A478663 C/W: V6 2.5 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 80,530 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 5N1AR2MN1FC651426 C/W: V6 3.5 L Gasoline Engine, 2015 US EPA	8932	2001 Toyota Seguoia 2WD SUV
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 193,455 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	0302	S/N: 5TDZT38A91S031176 C/W: V8 4.7 L Gasoline Engine, 2001 US EPA Label, Automatic Transmission Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8933	2015 GMC Sierra 3500HD 4x4 Crew Cab Pickup S/N: 1GT424E87FF594285 C/W: 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Dual Rear Wheel, Spray-On Bed Liner, 13025 lb GVWR, 35x12. 5R22 Tires, 8 ft 2 in Bed Usage: 192,673 Mi Asset located in: Humble, TX	8941	2015 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BT2FED72610 C/W: 6.7 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, 11200 Ib GVWR, 275/70R18 Tires, 11 ft Bed Usage: 252,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8934	 34 2019 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BTXKED26758 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, 11500.0 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 130,404 Mi Notes: LOCATED-IN-MIDLAND-TX TEMPORARY TAGS WILL NOT BE ISSUED ; ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION 	− 8943	2015 GMC Sierra 3500HD 4x4 Crew Cab Pickup S/N: 1GT421CGXFF176442 C/W: 6.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 11000 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 243,107 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	(SEPTEMBER 24TH) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	8944	2006 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3D7LX39C16G197374 C/W: 5.9 L 6 Cylinder Diesel Engine, 2005 US EPA Label, Automatic Transmission, Air
8936	2018 Ford F-350 Lariat 4x4 Crew Cab Pickup S/N: 1FT8W3BT8JEB81203 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Drop-In Bed Liner, 11500 lb		Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 9900 Ib GVWR, 285/70R17 Tires, 6 ft 6 in Bed Usage: 234,998 Mi Asset located in : Humble, TX
8938	GVWR, 265/70R17 Tires, 8 ft Bed Usage: 203,151 Mi Asset located in: Humble, TX 2018 Ford F-350 XLT 4x4 Crew Cab Pickup		1999 Ford F-350 4x4 Crew Cab Pickup S/N: 1FTSW31F2XEA09050 C/W: Diesel Engine, Automatic Transmission, Air Conditioner, Power Windows, 9900 lb GVWR, 295/60R20 Tires, 8 ft Bed
	S/N: 1FT8W3BT2JEC44330 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack,	80.40	Usage: 263,566 Mi Asset located in : Humble, TX
	Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 11500 lb GVWR, 275/70R16 Tires, 8 ft Bed Usage: 186,195 Mi Asset located in: Humble, TX	8949	2015 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3CTXFEC89909 C/W: 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Fuel Tank /w Pump, 14000 lb GVWR, 245 (7EP17 Time & ft Pad
8940	S/N: 1FT8W3BT3GEB10449 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's		245/75R17 Tires, 8 ft Bed Usage: 285,539 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		8950	2014 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3AT0EEB33542 C/W: 6.7 L V8 Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weatherguard Tool Box, Drop-In Bed Liner, 275/65R18 Tires, 8 ft Bed Usage: 273,296 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8952	2008 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FTWW30R08EE26858 C/W: 6.4 L V8 Diesel Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, 10800 lb GVWR, 295/70R17 Tires, 8 ft Bed Usage: 187,270 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8959	2020 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CJ8LG218252 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Sliding Rear Window, Spray- On Bed Liner, 10000 lb GVWR, 33x12.50R18LT Tires, 6 ft 4 in Bed Usage: 75,047 Mi Notes: THE TITLE BRANDED REBUILT SALVAGE Asset located in: Humble, TX
8954	2023 Chevrolet Silverado 2500 HD 4x4 Crew Cab Pickup S/N: 1GC4YLE70PF124357 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Aluminum Truck Cap, 10650 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 28,217 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8960	2020 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2BT4LEC44242 C/W: 6.7 L 6 Cylinder Diesel Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 295/70R18 Tires, 8 ft Bed Usage: 137,586 Mi Notes: TITLE IS BRANDED REBUILT SALVAGE Asset located in: Humble, TX
8955	2022 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B61NEE16448 C/W: 6.2 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 13,178 Mi Asset located in: Humble, TX	8961	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2BT8KEC79123 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 183,607 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
8956	2022 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B6XNEE16447		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 6.2 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Aluminum Truck Cap, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 6 in Bed Usage: 28,320 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	8962	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B66KEC61987 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 295/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 227,465 Mi
8957	2021 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2BT8MEC30717 C/W: 6.7 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner,		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	10000.0 lb GVWR, 275/70R18 Tires, 6 ft 10 in Bed Usage: 173,470 Mi Notes : SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	8963	2018 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B68JEC20212 C/W: 6.2 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 285 /70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY
8958	2021 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5HJ8MG631248 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air		Usage: 107,816 Mi Notes: LOCATED-IN-LIVINGSTON_LA_TX Asset located in: Livingston, LA
	Conditioner, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 295/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 114,548 Mi Asset located in: Humble, TX	8964	2018 Chevrolet Silverado 2500HD 4x4 Crew Cab Pickup S/N: 1GC1KVEG4JF237140 Usage: 141,601 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8966 8967	2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B66GEB00353 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed, EQUIPMENT- FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 274,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B64GEB00352 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 10000 lb GVWR, 285/70R17	8973	2012 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UD5HL1CG335616 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Drop-In Bed Liner, 9600.0 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 188,853 Mi Notes: LOCATED-IN-MIDLAND-TX , TEMPORARY TAGS WILL NOT BE ISSUED ; ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (SEPTEMBER 24TH) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	Tires, 8 ft Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: 269,279 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2008 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FTSW21568EE26805 C/W: 5.4 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9600 lb GVWR, 285/70R17
8968	2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B68GEA13389 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed Usage: 319,792 Mi		Tires, 8 ft Bed Usage: 231,500 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Chevrolet 2500 LT 4x4 Crew Cab Pickup
8971	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Ford F-250 XLT 4x4 Crew Cab Pickup		S/N: 1GCHK23KX7F563795 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 235 /75R16 Tires, 6 ft 5 in Bed
	S/N: 1FT7W2B67FEB78431 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck		Usage: 494,489 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
8972	Cap, Drop-In Bed Liner, 10000 lb GVWR, 285 /70R17 Tires, 8 ft 2 in Bed Usage: 303,964 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2015 Ford F-250 4x4 Crew Cab Pickup	8976	2018 Chevrolet Silverado 2500HD 4x4 Extended Cab Pickup S/N: 1GC2KWEG9JZ193614 Usage: Not Available Notes: SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON
0972	S/N: 1FT7W2B6XFEC90169		Asset located in: Humble, TX
	C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, ProTech Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 7 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 82,923 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE	8977	2019 Chevrolet Silverado 2500 HD 4x4 Pickup S/N: 1GC1KREYXKF269480 C/W: 6.6 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, 10000 lb GVWR, 285/75R17 Tires, 6 ft 6 in Bed Usage: 156,562 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	THE INSPECTION REPORT Asset located in: Humble, TX		THE INSPECTION REPORT Asset located in: Humble, TX
	•	1	

Lot #	Details	Lot #	Details
8978	2007 GMC Sierra 2500HD 4x4 Pickup	8984	2019 GMC Sierra 2500HD 4x2 Crew Cab Pickup
	S/N: 1GTHK24K07E533693 C/W: 6.0 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Tool Box, 9200 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 290,260 Mi		S/N: 1GT11NEG4KF168471 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Headache Rack, UWS Tool Box, Drop-In Bed Liner, 9500 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 155,679 Mi
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8985	Asset located in: Humble, TX 2018 Chevrolet Silverado 2500HD 4x2 Crew
	Asset located in: Humble, TX	0900	Cab Pickup
8979	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE72NF195448 C/W: 6.6 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Husky Tool Box, Spray-On Bed Liner, 10300 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 31,641 Mi		S/N: 1GC1CUEG9JF251171 C/W: 6.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 9500 lb GVWR, 235/80R17 Tires, 8 ft Bed Usage: 169,186 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
8980	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE77NF194893 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, BetterBuilt Tool Box, Spray-On Bed Liner, 10300 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 43,420 Mi	8986	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A68HEE08398 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 198,862 Mi
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8987	2017 Ford F-250 XL 4x2 Crew Cab Pickup
8981	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE77NF194862 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, BETTER BUILT Tool Box, Spray-On Bed Liner, 10300 lb GVWR, 245/75R17 Tires Usage: 52,864 Mi	_	S/N: 1FT7W2A61HEE08405 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, WEATHER GUARD Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed Usage: 176,168 Mi Asset located in : Humble, TX
	Asset located in: Humble, TX	8988	2017 Ford F-250 XL 4x2 Crew Cab Pickup
8982	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE74NF193278 C/W: 6.6 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10300 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 54,099 Mi		S/N: 1FT7W2A68HEE08403 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 146,557 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
8983	2020 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ3LG121110 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 83,836 Mi Asset located in: Humble, TX	8989	2015 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A67FEB51084 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROMAXX Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft 1 in Bed Usage: 235,632 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8990	2012 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2AT0CEB65149 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: 170,624 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	8995	2012 Ford F-250 4x2 Pickup S/N: 1FTBF2A61CEC67791 C/W: 6.2 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Aluminum Truck Cap, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 142,273 Mi Asset located in: Humble, TX
	THE INSPECTION REPORT	8996	2019 Ford F-150 XLT 4x4 Crew Cab Pickup
8991A	Asset located in: Humble, TX 2011 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTFX1CF6BFB97784 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKL Tool Box, 7050 lb GVWR, 275/55R20 Tires, 6 ft 4 in Bed Usage: 264,781 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1FTEW1EP6KKC79591 C/W: 2.7 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 265/70R15 Tires, 6 ft Bed Usage: 106,950 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Asset located in: Humble, TX	8997	2019 Ford F-150 XL 4x4 Crew Cab Pickup
8991	2003 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FTNW20F93EA12644 C/W: 7.3 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 235/85R16 Tires, 8 ft Bed Usage: 391,947 Mi		S/N: 1FTEW1EP7KKD16356 C/W: 2.7 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6600 lb GVWR, 295/70R17 Tires, 5 ft 7 in Bed
	Asset located in: Humble, TX	1	Usage: 152,029 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
8992	2006 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 1FTSX20526EB78774 C/W: 5.4 L V8 Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 9200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 141,285 Mi Asset located in: Humble, TX	8998A 89989 8999	THE INSPECTION REPORT Asset located in: Humble, TX 2019 Ram 1500 Laramie 4x4 Crew Cab Pickup S/N: 1C6SRFJT3KN872325 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power
8993	2001 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 3FTNX20F01MA73479 C/W: V8 Diesel Engine, Automatic Transmission, Headache Rack, Spray-On Bed Liner, 8800 lb GVWR, 235/85R16 Tires, 8 ft 3 in Bed, Liftgate Usage: 316,136 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS		Adjustable Pedals, Power Windows, Power Sliding Rear Window, 7100 lb GVWR, 275 /65R18 Tires, 5 ft 9 in Bed Usage: 95,393 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2019 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTEW1E54KKC44045
	MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		C/W: 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air
	Asset located in: Humble, TX	-	Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Drop-In
8994	2019 Chevrolet Silverado 2500 HD 4x2 Pickup S/N: 1GC1CREG4KF178578 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 9500 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 122,591 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Bed Liner, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 227,201 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details	
9003	2015 Chevrolet Silverado 1500 4x4 Crew Cab Pickup S/N: 3GCUKREC0FG421899 C/W: 5.3 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power	9009	2018 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEH1JZ210048 Usage: Not Available Asset located in: Humble, TX	
	Windows, Tool Box, Drop-In Bed Liner, 7200 lb GVWR, 265/65R18 Tires, 6 ft 7 in Bed Usage: 259,941 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9010	2018 Chevrolet Silverado 1500 4x4 Dual Cab Pickup S/N: 1GCVKNEHXJZ203051 C/W: 4.3 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed	
9004	2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1ETXEKE30969 C/W: 3.5 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's	 Liner, 7100 lb GVWR, 265/70R17 T Bed Usage: 100,832 Mi Asset located in: Humble, TX 9011 2017 Ford F-150 XL 4x4 Extended of S/N: 1FTFX1EG9HKD52821 C/W: V6 Gasoline Engine, Automat Transmission, Air Conditioner, Pow Windows, Spray-On Bed Liner, 7050 265/70R17 Tires, 6 ft 6 in Bed Usage: 236,859 Mi Notes: DEFICIENCIES NOTED - PLE THE INSPECTION REPORT; TEXAS MUST STOP IN OFFICE TO SIGN RI DOCUMENTS Asset located in: Humble, TX 9012 2008 Chevrolet Silverado 1500 LT 4 Extended Cab Pickup S/N: 1GCEK19J88Z254046 C/W: 5.3 L V8 Gasoline Engine, 200 Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, P Windows, Drop-In Bed Liner, 7000 I /70R17 Tires, 6 ft 8 in Bed Usage: 160,448 Mi 	Bed Usage: 100,832 Mi Asset located in : Humble, TX	
	Seat, Power Windows, Headache Rack, RKI Tool Box, 7200 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 414,643 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		S/N: 1FTFX1EG9HKD52821 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 236,859 Mi	
9005	2013 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7NT5DS694534 C/W: 5.7 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air		THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	
	Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray- On Bed Liner, 6800 lb GVWR, 275/65R20 Tires, 6 ft Bed Usage: 288,905 Mi Asset located in : Humble, TX		2008 Chevrolet Silverado 1500 LT 4x4 Extended Cab Pickup S/N: 1GCEK19J88Z254046 C/W: 5.3 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air	
9006	2013 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTFW1EF0DKD53036 Usage: Not Available		Windows, Drop-In Bed Liner, 7000 lb GVWR, 265 /70R17 Tires, 6 ft 8 in Bed Usage: 160,448 Mi	
9007	Asset located in: Humble, TX 2007 Chevrolet Silverado 1500 4x4 Crew Cab Pickup S/N: 2GCEK13M171708177 C/W: 5.3 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 160,079 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	9013 9014	Asset located in: Humble, TX 2000 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 2GCEK19T3Y1253655 C/W: 5.3 L V8 Gasoline Engine, 2000 US EPA Label, Automatic Transmission, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6400 Ib GVWR, 265/75R16 Tires, 6 ft 7 in Bed Usage: 229,096 Mi Asset located in: Humble, TX	
	THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		Truck S/N: 1FTRX18	S/N: 1FTRX18L1WKA93387
9008	2019 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7FT2KS635615 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 147,448 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Ford 5.4 L Gasoline Engine, Automatic Transmission, 3600 lb Front Axle, 3200 lb Rears, 6250 lb GVWR, Spring Suspension, 139 in Wheelbase, Receiver Usage: 236,655 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
9015	2013 Ram 2500 4x4 Pickup S/N: 3C6LR5BL8DG536162 C/W: 6.7 L 6 Cylinder Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 9000 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 218,248 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9021	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF0HKE23722 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 4 ft 6 in Bed Usage: 119,473 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	9022	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF2HKE53076
9016	2021 Ford F-150 STX 4x2 Crew Cab Pickup S/N: 1FTEW1CP0MKD32808 C/W: 2.7 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed Usage: 110,465 Mi		C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, WEATHER GUARD Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 5 ft 7 in Bed Usage: 140,099 Mi
	Asset located in: Humble, TX		Asset located in: Humble, TX
9017	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1C50JKC10783 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Weatherguard Tool Box, Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed Usage: 165,997 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9023	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF6HKE23725 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 5 in Bed Usage: 142,764 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
9018	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C52JKC10770 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed Usage: 146,917 Mi	9024	2016 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6KT8GS238756 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6900 lb GVWR, 275/50R20 Tires, 6 ft Bed Usage: 165,538 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	0005	Asset located in: Humble, TX
9019	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C56JKC10769 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed Usage: 145,418 Hr Asset located in: Humble, TX	_9025	2016 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6KTXGS141803 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 6900 lb GVWR, 275/60R20 Tires, 6 ft Bed Usage: 219,251 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0020		9026	2016 Chevrolet 1500 4x2 Crew Cab Pickup
9020	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKE23730 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 8 in Bed Usage: 86,433 Mi Asset located in: Humble, TX		S/N: 3GCPCREC3GG233079 C/W: 5.3 L V8 Gasoline Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, 7000 lb GVWR, 5 ft 6 in Bed Usage: 269,698 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9027	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF4EKG33790 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 129,930 Mi Asset located in: Humble, TX	9033	2004 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTRW12W54KC24338 C/W: 4.6 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6800 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 53,387 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
9028	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF3EKG33800		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 133,616 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9034	2019 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTFX1C44KKE10558 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 7850 lb GVWR, 265/75R18 Tires, 8 ft Bed Usage: 204,106 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9029	2014 Ford F-150 XL 4x2 Crew Cab Pickup		Asset located in: Humble, TX
	S/N: 1FTFW1CF3EFC74649 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Spray-On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 260,242 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9035	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C86HKD42884 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 114,133 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
		-	THE INSPECTION REPORT
9030	12 Ford F-150 XLT 4x2 Crew Cab Pickup N: 1FTFW1CF4CFC37381		Asset located in: Humble, TX
	C/W: 5.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fiberglass Truck Cap, 7100 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 244,407 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9036	2014 Ford F-150 XLT 4x2 Extended Cab Pickup S/N: 1FTFX1CF2EKE98841 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fiberglass Truck Cap, 275/70R18 Tires, 6 ft Bed Usage: 180,328 Mi
	Asset located in: Humble, TX	0007	Asset located in: Humble, TX
9031	2012 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF8CFC37383 C/W: 5.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Fiberglass Truck Cap, 7100 lb GVWR, 255/65R17 Tires, 6 ft 0 in Bed Usage: 231,823 Mi Asset located in: Humble, TX	9037	2014 Ford F-150 XLT 4x2 Extended Cab Pickup S/N: 1FTFX1CF8EFD08775 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Fiberglass Truck Cap, 7100 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 247,324 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
9032	2011 GMC Sierra 1500 4x2 Crew Cab Pickup		
	S/N: 3GTP1UEA7BG361406	0000	Asset located in: Humble, TX
	C/W: 4.8 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 5 ft 8 in Bed Usage: 261,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9038	2013 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTFX1CF5DKG26987 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, 7100 lb GVWR, 265/65R17 Tires, 6 ft 2 in Bed Usage: 248,292 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9039	2010 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CW7AFA49587 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, RKI Tool Box, 6700 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 299,524 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9045	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH6FZ320612 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6700 lb GVWR, 255/70R17 Tires, 8 ft Bed Usage: 155,112 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
9040	2010 Chevrolet Silverado 1500 4x2 Extended Cab Pickup S/N: 1GCSCSE0XAZ284657 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Tonneau Cover, 6800 lb GVWR, 265/65R18 Tires, 6 ft Bed Usage: 172,463 Mi Notes: TITLE BRANDS REBUILT SALVAGE	9047	2011 Ford F-150 XL 4x2 Pickup S/N: 1FTNF1CF3BKD45587 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, WEATHER GUARD Tool Box, Drop- In Bed Liner, 7050 lb GVWR, 235/80R17 Tires, 8 ft 1 in Bed Usage: 201,941 Mi Asset located in: Humble, TX
9041	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2009 Chevrolet Silverado 1500 LT 4x2 Extended Cab Pickup	9048	2009 Ford F-150 XL 4x2 Pickup S/N: 1FTRF12W59KB51656 C/W: 4.6 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6750 lb GVWR,
	S/N: 1GCEC29039Z140354 C/W: 5.3 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air		265/70R17 Tires, 8 ft Bed Usage: 224,685 Mi Asset located in : Humble, TX
	Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 275/55R20 Tires, 6 ft 7 in Bed Usage: 140,470 Mi Asset located in : Humble, TX	9049	2009 Ford F-150 XL 4x2 Pickup S/N: 1FTRF12W89KB67589 C/W: 4.6 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, RKI Tool Box, Spray-On Bed Liner,
9042	2008 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTRX12W28FA46173 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Headache Rack, RKI Tool Box, Drop-In Bed Liner, 6700 lb GVWR,		6750 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 50,746 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	275/65R18 Tires, 6 ft 6 in Bed Usage: 275,804 Mi Asset located in : Humble, TX	9051	2022 Ford Ranger 4x2 Crew Cab Pickup S/N: 1FTER4EH9NLD35538 C/W: 2.3 L 4 Cylinder Gasoline Engine, 2022 US
9043	2018 Ford F-150 XL 4x2 Pickup S/N: 1FTMF1CB1JKF29935 C/W: 3.3 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Lund Fuel Tank /w Pump, RKI Tool	9052	EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6050 lb GVWR, 255/70/16 Tires, 5 ft Bed Usage: 41,346 Mi Asset located in : Humble, TX
	Box, Spray-On Bed Liner, 6170 lb GVWR, 265 /70R15 Tires, 8 ft Bed Usage: 90,218 Mi Asset located in : Humble, TX		 2019 Toyota Tacoma 4x2 Crew Cab Pickup S/N: 5TFAX5GN1KX141586 C/W: 2.7 L 4 Cylinder Gasoline Engine, 2019 L EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 5600 lb GVWR, 275/55R20 Tires, 5 ft Be Usage: 32,500 Mi Notes: TEXAS BUYERS MUST STOP IN OFFIC TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
9044	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEHXFZ385754 C/W: 4.3 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Sunroof, Tonneau Cover, Fiberglass Truck Cap, 6700 lb GVWR, 255/70R17 Tires, 8 ft 6 in Bed Usage: 167,909 Mi Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9053	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE4LN718477 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Aluminum Truck Cap, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 127,341 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9059	2016 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT6GN717452 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft 2 in Bed Usage: 131,524 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9054	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT0HN758693 C/W: 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air	9060	2016 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT0GN727989 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air
	Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 90,565 Mi Asset located in: Humble, TX		Conditioner, 4700 lb GVWR, 235/75R15 Tires, 6 ft 2 in Bed Usage: 119,834 Mi Asset located in: Humble, TX
9055	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT4HN756140 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 146,983 Mi Asset located in: Humble, TX	9061	2007 Toyota Tundra 4x2 Extended Cab Pickup S/N: 5TFRT54157X015223 C/W: 4.7 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6700 lb GVWR, 255/70R18 Tires, 6 ft 6 in Bed Usage: 286,967 Mi
9056	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT2HN774460 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	EPA Label, 5 Speed Manual Transmission, Air Conditioner, Leonard Tool Box, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 236,402 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in : Humble, TX	9063	2016 Forest River Wildwood 30 ft 7 in T/A Travel Trailer S/N: 4X4TWDC21GA256534 C/W: Sleeps 6 People, Single Slide Out, Power Leveling Jacks, Bumper Pull, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE
9057	2017 Nissan Frontier XE 4x2 Extended Cab	1	Asset located in: Humble, TX
	Pickup S/N: 1N6BD0CT0HN754966 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 99,319 Mi Asset located in: Humble, TX	9064	2023 XLR MicroBoost 29 LRLE 27 ft T/A Toy Hauler Travel Trailer S/N: 5ZT2XLUB0PZ795203 C/W: Air Conditioner, 11436 lb GVWR, Single Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX
9058	2016 Nissan Frontier 4x2 Extended Cab Pickup	9065	2023 XLR MicroBoost 29 LRLE 31 ft T/A Toy
	S/N: 1N6BD0CTXGN730432 C/W: 4 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Truck Cap, 4700 lb GVWR, 235 /75R15 Tires, 5 ft 8 in Bed Usage: 168,156 Mi Notes : . Asset located in : Humble, TX		Hauler Travel Trailer S/N: 5ZT2XLUB2PZ795199 C/W: Sleeps 4 People, 11346 lb GVWR, Single Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9066	2022 XLR MicroBoost 29 LRLE 27 ft T/A Toy Hauler Travel Trailer S/N: 5ZT2XLUB6NZ793596 C/W: 11540 lb GVWR, Single Slide Out, Power Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX	9074	1994 Lykal 12x54 54 ft x 12 ft Skid-Mounted Mobile Office S/N: LSW12540294506 C/W: (2) Kitchens, (2) Bedrooms w/(4) Beds, (2) Bathrooms, Air Conditioner, Laundry Usage: Not Available Notes : This Item is the buyers responsibility for LOADING and removal and it CAN NOT be
9067A	2000 Sea-Doo Bombardier GTX 10 ft Personal Watercraft w/2012 Zieman RBET80X16-12WD		relisted. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Trailer		Asset located in: Livingston, LA
	S/N: ZZN26948A000 C/W: 2 Passenger, Inboard Rotax 951 cc Engine, Reverse, Rearview Mirrors, S/A Trailer w/ S/N- 1M9BE1624CL516337, Ball Hitch Usage: Not Available Asset located in: Humble, TX	9075	2024 43 ft 6 in x 12 ft 2 in Portable Tri/A Mobile Office (Unused) S/N: 92409 C/W: (2) Offices, (1) Bathrooms, Air Conditioner, Spring Suspension, 8-14.5 Tires, Common Area Usage: Not Available
9067	2022 Forest River XLT29LRLE-79 34 ft T/A Travel Trailer S/N: 5ZT2XLUB7NZ794465		Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX
	C/W: 11540 lb GVWR, Single Slide Out, Power		Asset located in: Lake Worth, TX
	Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available Asset located in : Humble, TX	9076	30 ft x 10 ft 1 in Portable Mobile Office S/N: 24392 C/W: (2) Offices, (1) Bathrooms, Air Conditioner, Spring Suspension, 8-14.5 Tires Usage: Not Available
9068	S/N: MTW03829F697 C/W: 2 Passenger, Outboard Mercury 30 hp Engine, S/A Trailer w/ S/N- 1BTETHM1951000175, Ball Hitch, Engine VIN 0R700328 Usage: Not Available Notes: NO TITLE AVAILABLE FOR TRAILER, SOLD WITH BILL OF SALE ONLY		Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX
			Asset located in: Lake Worth, TX
		9077	40 ft x 8 ft High Cube Office Container (Unused) S/N: JUHU1202268 C/W: single walk door, 4 windows, A/C, lighting Usage: Not Available
0060	Asset located in: Humble, TX		Asset located in: Humble, TX
9069	1997 Bay Stealth 18 ft Fishing Boat w/1998 Vivian Industry Trailer S/N: 690A898 C/W: Fiberglass Hull, 4 Passenger Capacity, 18 ft Overall Length, Outboard Yamaha 115 hp Engine, S/A Trailer w/ S/N- 7901S0W1000769, Ball Hitch, 522948 VIN Yamaha 115 Usage: Not Available Asset located in : Humble, TX	9078	2024 Garper GP8-24 20 ft x 8 ft 3 in Portable S /A Mobile Office (Unused) S/N: 3ECG24C1XRGEP0171 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 225 /75R15 Tires Usage: Not Available Asset located in: Humble, TX
0070	· · · · · · · · · · · · · · · · · · ·	9079	2024 Garper GP8-24 20 ft x 8 ft S/A Mobile
9070	22 Ft x 7 Ft Floating Dock S/N: Not Available Usage: Not Available Asset located in : Humble, TX	_	Office (Unused) S/N: 3ECG24C1XRGEP0173 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 225
9071	26 ft 6 in x 7 ft Floating Dock S/N: Not Available		/75R15 Tires Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	9080	2024 Garper GP8-24 Mobile Office (Unused)
9072	26 ft 6 in x 7 ft Floating Dock S/N: Not Available Usage: Not Available Asset located in : Humble, TX	0000	S/N: 3ECG24C1XRGEP0172 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 225 /75R15 Tires Usage: Not Available
9073	12x60 Mobile Office S/N: 170754 Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9081	2024 20 m x 8 ft Office Container (Unused) S/N: CEOU2212875 C/W: (1) Walk in Door, Two Windows w /Security Bars, Fork Pockets, Laminate Flooring, SunScreen, R13 Insulation, (1) Pioneer HVAC Mini-Split, (1) Electric Panel, LED Ceiling Lights, Interior Outlets, Wiring done to National Electric Code (NEC)	9089	2023 HOS HF2N1 19 ft x 21 ft Folding Storage Building S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: Not Available	9090	2024 HOS HF2J 19 ft x 21 ft Folding House
	Asset located in: Humble, TX	-	S/N: Not Available Usage: Not Available
9082	2024 20 ft x 8 ft Office Container (Unused) S/N: NWRU3518174		Asset located in: Humble, TX
	S/N: NWR03518174 C/W: (1) Walk in Door, Two Windows w /Security Bars, Fork Pockets, Laminate Flooring, SunScreen, R13 Insulation, (1) Pioneer HVAC Mini-Split, (1) Electric Panel, LED Ceiling Lights, Interior Outlets, Wiring done to National Electric Code (NEC) Usage: Not Available Asset located in: Humble, TX	9092	2008 Etnyre R40TD3 Tri/A Lowboy Trailer S/N: 1E92992418E111108 C/W: 94000 lb GVWR, Air Ride Suspension, 16 ft Main Deck, 102 in Usable Deck Width, Manual Ramps, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9083	20 ft x 8 ft Office Container (Unused)	9093	2006 Trail King TK130HDG-573 Tri/A
	S/N: CBA100578661 C/W: Single walk door, 2 Windows, A/C, Lighting, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX	_	Removable Gooseneck Lowboy Trailer S/N: 1TKJ057386M014661 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, Plumbed
9084	Mobile Office		for Booster Axle, 28 ft Main Deck, 120 in Overall Deck Width, Honda Gas Powered Self Contained Hydraulic System, 235/75R17.5 Tires, 161280 lb GVWR, Spreader Bar Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		
9085	20 ft x 8 ft Mobile Office		Asset located in: Humble, TX
	S/N: 287409 7 C/W: (1) Offices, Air Conditioner Usage: Not Available Asset located in: Humble, TX	9094C	2024 Witzco RG-52 52 ton Lowboy Trailer S/N: 1W8A11E34RS000456 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft 6 in Main Deck, 102 in Usable Deck Width, 102 in Overall Deck
9086	2024 Suihe NMO-20FT-007D 20 ft x 7 ft Portable Office (Unused) S/N: Not Available Usage: Not Available		Width, 126 in Widening Width, Honda Gas Powered Self Contained Hydraulic System, 255 /70R22.5 Tires, 122540 lb GVWR Usage: Not Available
	Asset located in: Humble, TX		Notes : THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE
9087	2024 KJ K2019 20 ft x 19 ft Prefabricated Tiny		PURCHASER
	Home (Unused) S/N: Not Available	00045	Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	9094B 	2024 Witzco RG-52 52 ton Lowboy Trailer S/N: 1W8A11E30RS000454 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft 6 in Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Honda Gas Powered Self Contained Hydraulic System, 255
9088	2024 Suihe NMO 20 ft x 7 ft Office Container (Unused)		/70R22.5 Tires, 122540 lb GVWR Usage: Not Available Notes : THIS ITEM IS SUBJECT TO 12%
	S/N: Not Available Usage: Not Available Notes : LOCATED-IN-HOUSTON-TX-HOU		FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9094A	2024 Witzco RG-52 52 ton Lowboy Trailer S/N: 1W8A11E32RS000455 C/W: Spring Suspension, Mechanical Removable Gooseneck, 22 ft 6 in Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, Honda Gas Powered Self Contained Hydraulic System, 255 /70R22.5 Tires, 122540 lb GVWR Usage: Not Available Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE	9097	1992 Talbert T3BD85KHRGT1 43 ton Tri/A Beam Removable Gooseneck Lowboy Trailer S/N: 40FB0523XN1009896 C/W: 99400 lb GVWR, Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 25 ft 6 in Main Deck, 255/70R22. 5 Tires Usage: Not Available Asset located in: Humble, TX 2012 XL Specialized XL60 T/A Removable
	PURCHASER		Gooseneck Lowboy Trailer
9094	Asset located in: Humble, TX 2006 Loadcraft LCOLP60T4 60 ton Quad/A Lowboy Trailer S/N: 5ABB604026B060033 C/W: Air Ride Suspension, 44 ft 6 in Main Deck, 102 in Usable Deck Width, Deck Over Tires, Pickup Throat, Tail Roller, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	-	S/N: 4U3J04825CL011764 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, 8 ft 6 in Upper Deck, 29 ft Main Deck, 7 ft 5 in Rear Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Aluminum Outer Wheels, 255 /70R22.5 Tires, 74370 lb GVWR, Upper and Rear Deck are Aluminum decking Usage: Not Available Asset located in : Humble, TX
9095	2015 Eager Beaver 50GSL/BR Tri/A Removable	9099	1982 Phelan HS25H-N T/A Heavy-Haul Jeep
	Gooseneck Lowboy Trailer S/N: 112SB2518FL079783 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 24 ft Main Deck, 10 ft 6 in Rear Deck, 4 ft Fixed Dovetail, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, 225/70R22.5 Tires, 122500 lb GVWR Usage: Not Available		S/N: 1R9H39202C1010387 C/W: 69600 lb GVWR, Air Slide 5th Wheel, Spring Suspension, 11R22.5 Tires, 69600 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9100	2002 Trail King S/A Booster Axle
9096		9100	S/N: 1TKS005192M078078 C/W: Flip-Up, Air Ride Suspension, 255/70R22. 5 Tires Usage: Not Available Asset located in: Humble, TX
	Deck Width, 102 in Overall Deck Width, Pickup Throat, Tail Roller, 255/70R22.5 Tires	9101	2004 Landoll 435 48 ft T/A Sliding Axle Trailer
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1LH435UH441013578 C/W: Air Ride Suspension, 9 ft 8 in Upper Deck, 38 ft 2 in Main Deck, 94 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 245/70R17.5 Tires, Aluminum Ag Slide
9097B	2007 Lufkin 53 ft Quad/A Lowboy Oilfield		Out Extensions
	Trailer S/N: 1L01B534871164497 C/W: Air Ride Suspension, Lift 4th- Axles, 98 in Deck Width, 11 ft Upper Deck, 42 ft Main Deck, Tail Roller, Kicker Rollers, 255/70R22.5 Tires Usage: Not Available		Usage: Not Available Notes : Well Maintained Central Texas Paving Company - Fleet Realignment DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE	9102	2015 Ledwell LW48HT2-10-PB T/A Hydraulic
	THE INSPECTION REPORT	102	Tail Trailer
9097A	Asset located in: Humble, TX 2006 Witzco RG-35 35 ton T/A Lowboy Trailer S/N: 1W8A11D256S000373 C/W: Spring Suspension, 22 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, 255/70R22.5 Tires, 86400 lb GVWR Usage: Not Available Asset located in: Humble, TX		S/N: 1L9GA72A5FL033832 C/W: 80000 lb GVWR, Air Ride Suspension, 9 f Upper Deck, 39 ft Main Deck, 12 ft 2-Position Dovetail, 102 in Usable Deck Width, Winch, Upper Deck Ramps, 235/75R17.5 Tires Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9103	2015 Landoll 930C-48-15 T/A Hydraulic Tail Trailer S/N: 1LH930UH2F1C21747 C/W: Air Ride Suspension, 10 ft Upper Deck, 23 ft Main Deck, 15 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, Aluminum Wheels, 245 /70R17.5 Tires, 86300 lb GVWR, Right Weigh Load Scale Usage: Not Available	9109	2023 Great Dane FLD002400053 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1GR4M0627PH443584 C/W: 70000 lb GVWR, Air Ride Suspension, Air Brakes, 9 ft 6 in Upper Deck, 43 ft Main Deck, 96 in Usable Deck Width, Deck Over Tires, Aluminum Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2019 Fontaine HAILD22RSA 40000 lb 53 ft T/A
9104A	Asset located in: Humble, TX 2014 Trail King T/A Hydraulic Tail Trailer S/N: 1TKA04825EM034431 C/W: Air Ride Suspension, 6 ft 2 in Upper Deck, 30 ft Main Deck, 7 ft 6 in 2-Position Dovetail, 101 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R- 17.5 Tires Usage: Not Available Asset located in: Humble, TX		Spread Axle Single Drop Step Deck Trailer S/N: 13N2532C2K1530921 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 11 ft Upper Deck, 42 ft Main Deck, 102 in Usable Deck Width, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 245 /70R17.5 Tires Usage: Not Available Asset located in: Humble, TX
9104	2014 Landoll 930C-48-15 T/A Hydraulic Tail Trailer S/N: 1LH930UH0E1C21440 C/W: Air Ride Suspension, 10 ft Upper Deck, 23 ft Main Deck, 15 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 245/70R17.5 Tires, 86300 lb GVWR, Right Weigh Load Scale	9111	2014 Transcraft 53 ft Tri/A Step Deck Trailer S/N: 1TTE533S1E3768554 C/W: Air Ride Suspension, Lift Axles, Wood Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2014 Fontaine HCICD22RSA 80000 lb 53 ft T/A Spread Axle Single Drop Step Deck Trailer
9105	Usage: Not Available Asset located in: Humble, TX 2009 Ledwell T/A Hydraulic Tail Trailer S/N: 1L9GA72A79L033741 C/W: Air Ride Suspension, 9 ft 3 in Upper Deck, 30 ft 6 in Main Deck, 12 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Upper Deck Ramps, Aluminum Outer Wheels, 255/70R22.5 Tires Usage: Not Available	-	S/N: 13N2532C3E1565455 C/W: 65042 lb GVWR, Air Ride Suspension, Sliding Suspension, 10 ft Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9106	Asset located in: Humble, TX 2005 Ledwell T/A Hydraulic Tail Trailer S/N: 1L9GA72A95L033394 C/W: Air Ride Suspension, 7 ft Upper Deck, 27 ft Main Deck, 12 ft 2-Position Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9113	2013 Doonan 53 ft Tri/A Single Drop Step Deck Trailer S/N: 1D9BH533XD1609226 C/W: 110000 lb GVWR, Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Tail Roller, Kicker Rollers, Wood Flooring, 255/70R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9107	1986 Trail King 45 ft T/A Hydraulic Tail Trailer S/N: 1TKA0452XGM037025 C/W: Spring Suspension, 10 ft Upper Deck, 25 ft Main Deck, 10 ft 2-Position Dovetail, 94 in Usable Deck Width, 102 in Overall Deck Width, 12 in Widening Width, Storage Compartments, Deck Over Tires, 10R17.5 Tires Usage: Not Available Asset located in : Humble, TX	9114	Asset located in: Humble, TX 2004 Great Dane 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1GRDM06284M700769 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 10 ft 6 in Upper Deck, 42 ft 6 in Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9115	2000 Pro-Trak 53 ft T/A Step Deck Trailer S/N: 5BNDG5322YC001797 C/W: Spring Suspension, Electric Brakes, 9 ft Upper Deck, 39 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 225/75R16 Tires Usage: Not Available Asset located in: Humble, TX	9122	1996 Trail King 48 ft T/A Single Drop Step Deck Trailer S/N: 3TKB04820TP083069 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 5 in Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, 255 /70R22.5 Tires, 81475 lb GVWR Usage: Not Available Asset located in : Humble, TX
9116	2014 Ledwell LW48SDT2 48 ft T/A Single Drop Step Deck Trailer S/N: 1L9DA72A3EL033717 C/W: Air Ride Suspension, 9 ft 10 in Upper Deck, 37 ft 8 in Main Deck, 96 in Usable Deck Width, 99 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 70000 lb GVWR, Trailer Scale Usage: Not Available Asset located in: Humble, TX	9123 9124	1996 Trail King TK70LCS482 48 ft T/A Single Drop Step Deck Trailer S/N: 3TKB04827TP083067 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 81475 lb GVWR Usage: Not Available Asset located in: Humble, TX 1995 Trail King 48 ft T/A Single Drop Step
9117	2003 Fontaine 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N24830931518559 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 10 in Main Deck, 97 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9125	Deck Trailer S/N: 1TKB04826SM126101 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Wood Flooring, 275/70R22.5 Tires, 82340 lb GVWR Usage: Not Available Asset located in: Humble, TX 1995 Trail King TK70CS-432 48 ft T/A Single
9118	2001 Transcraft 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE4820811066690 C/W: Air Ride Suspension, 10 ft 10 in Upper Deck, 37 ft Main Deck, 97 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires Usage: Not Available		Drop Step Deck Trailer S/N: 1TKB04828SM126102 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 9 in Main Deck, 97 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 275/70R22.5 Tires, 82340 lb GVWR Usage: Not Available Asset located in: Humble, TX
9119	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1996 Fruehauf PSDAT2W48W 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1H2P04822TW007004 C/W: 91000 lb GVWR, Air Ride Suspension, Air Brakes, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck	9126	1986 Aztec 48 ft S/A Single Drop Step Deck Trailer S/N: 1AZBR1B38G1017407 C/W: Spring Suspension, 15 ft 5 in Upper Deck, 27 ft 3 in Main Deck, 6 ft 4 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, 10R17.5 Tires Usage: Not Available Asset located in: Humble, TX
	Width, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires Usage: Not Available Notes: . Asset located in: Humble, TX		1992 Fontaine 38 ft T/A Spread Axle Step Deck Trailer S/N: 13N248303N1554136 C/W: Air Ride Suspension, Air Brakes, 91 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Steel Decking, 255/70R22.5
9120	1996 Trail King TK70LCS-482 48 ft T/A Single Drop Step Deck Trailer S/N: 3TKB04829TP083068 C/W: Air Ride Suspension, Air Brakes, 9 ft 8 in Upper Deck, 37 ft 6 in Main Deck, 0 ft Rear Deck, 0 ft Dovetail, 96 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 81475 lb GVWR Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Humble, TX		Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9132	2013 Great Dane GPL-0024-00053 53 ft T/A Spread Axle Flatbed Trailer S/N: 1GRDM0625DH716744 C/W: Air Ride Suspension, 97 in Deck Width, 97 in Overall Width, Bulkhead, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9140	2013 Utility FS2CHS 48 ft T/A Flatbed Trailer S/N: 1UYFS2481DA506101 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 97 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9141	2012 Utility FS2CHS 48 ft T/A Flatbed Trailer S/N: 1UYFS2487CA402601
9133	2013 Great Dane 53 ft T/A Flatbed Trailer S/N: 1GRDM0629DH716696 C/W: 58000 lb GVWR, Air Ride Suspension, 94 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available	-	C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9142	2009 Utility FS2CHS 48 ft T/A Flatbed Trailer
9134	34 2013 Great Dane 53 ft T/A Flatbed Trailer S/N: 1GRDM0629DH716763 C/W: Air Ride Suspension, 96 in Deck Width, 99 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 58000 lb GVWR Usage: Not Available		S/N: 1UYFS24849A672202 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Wood Flooring, 11R22.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	9143	2005 Utility 48 ft T/A Flatbed Trailer
9135	1997 Kalyn Siebert 53 ft T/A Flatbed Trailer S/N: 1K9F53215V1005397 Usage: Not Available Asset located in : Humble, TX		S/N: 1UYFS24875A696326 C/W: 36300 lb GVWR, Walking Beam Suspension, 82 in Deck Width, 85 in Overall Width, Wood Flooring, 11R22.5 Tires Usage: Not Available
9136	023 Fontaine HAVSF12WSA T/A Spread Axle		Asset located in: Humble, TX
	Flatbed Trailer S/N: 13N148204P1552041 C/W: 70543 lb GVWR, Air Ride Suspension, Air Brakes, 98 in Deck Width, 102 in Overall Width, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	TrailerS/N: 1UYFS24874A313905C/W: 80000 lb GVWR, Air Ride Suspension Deck Width, 102 in Overall Width, Alew/Wood Strips Flooring, Aluminum OutWheels, 11R22.5 TiresUsage: Not AvailableNotes: LOCATED-IN-MIDLAND-TX ; SEIWITH A REPOSESSION AFFIDAVIT ANNOT BE ACCEPTED IN YOUR STATE. VWITH YOUR LOCAL DMV PRIOR TO BILAsset located in: Midland, TX91452003 Fontaine FTW-5-8048WSAWK 48	S/N: 1UYFS24874A313905 C/W: 80000 lb GVWR, Air Ride Suspension, 96 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 11R22.5 Tires
9138	2016 Fontaine XCALIBUR T/A 48 ft Extendable Flatbed Trailer S/N: 57J448200G3572398 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 97 in Overall Width, Extendable Deck, Wood Flooring, 11R22.5 Tires, 85600 lb GVWR Usage: Not Available		Notes:LOCATED-IN-MIDLAND-TX ; SIWITH A REPOSESSION AFFIDAVIT ANNOT BE ACCEPTED IN YOUR STATE.WITH YOUR LOCAL DMV PRIOR TO BAsset located in:Midland, TX91452003 Fontaine FTW-5-8048WSAWK 4
	Asset located in: Humble, TX		S/N: 13N14830X35917145
FI S/ C, in w, /7 Us Ni Ti	2013 Utility FS2CHA 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS2481DA697230 C/W: 73000 lb GVWR, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 295 /75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Air Ride Suspension, 97 in Deck Width, 97 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9146	1997 Lufkin FL-II-ST 48 ft T/A Flatbed Trailer S/N: 1L01B4820V1127376 C/W: Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 97 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9147 9148	1995 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B4821S1120514 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX 1995 Lufkin FL-II-ST 48 ft T/A Flatbed Trailer	9154	1999 Lufkin EX 45/75 T/A 45 ft - 75 ft Extendable Flatbed Trailer S/N: 1L01B4529X1136438 C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX
5140	S/N: 1L01B4826S1116989 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX	9155	1997 Utility 45 ft T/A Flatbed Trailer S/N: 1UYFS245XVA294001 C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in : Humble, TX
9149	1995 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B4824S1116991 C/W: Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 275 /80R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9156	1989 Fruehauf 42 ft T/A Flatbed Trailer S/N: 1H5P04226KM061220 C/W: Spring Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX
9150	1994 Lufkin FL-II-ST 48 ft T/A Flatbed Trailer S/N: 1L01B4827R1112198 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Humble, TX	9157	2003 AA Welding 40 ft T/A Gooseneck Flatbed Trailer S/N: 1UFGN42233T023646 C/W: Spring Suspension, Electric Brakes, 97.5 in Deck Width, 102 in Overall Width, Wood Flooring, 235/85R16 Tires, 18000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9151	2018 Transcraft 45 ft T/A Flatbed Trailer S/N: 1TTF452SXJ3086884 C/W: Air Ride Suspension, Sliding Suspension, 96 in Deck Width, 100 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9158	1981 SHPB 40 ft T/A Flatbed Trailer S/N: 0TCN269207 C/W: Spring Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in : Humble, TX
9152	2007 Transcraft 45 ft T/A Flatbed Trailer S/N: 1TTF4520071082510 C/W: 80000 lb GVWR, Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 100 in Overall Width, Wood Flooring, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Asset located in: Humble, TX	9159	2018 Dorsey 35 ft T/A Flatbed Trailer S/N: 5JYFB3620JED06364 C/W: Air Ride Suspension, 97 in Overall Width, Bulkhead, Wood Flooring, 11R22.5 Tires, 80000 Ib GVWR, Lift Truck Kit Usage: Not Available Asset located in: Humble, TX 1999 Smithco 34 ft T/A Side Dump Trailer
9153	1999 Transcraft TL2000 45 ft T/A Flatbed Trailer S/N: 1TTF45209X1061722 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 445/50R22.5 Super Single Tires, Rear Forklift Mount Usage: Not Available Asset located in: Humble, TX		S/N: 1S9SS4027XL476497 C/W: Spring Suspension, Dumps to Both Sides, 42 in Side Walls, Steel Body, Manual Roll Tarp, 425/65R22.5 Super Single Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9161 9163	 1998 Smithco 34 ft T/A Side Dump Trailer S/N: 1S9SS4020WL476324 C/W: Spring Suspension, Dumps to Right Side, 42 in Side Walls, Steel Body, Aluminum Wheels, 425/65R22.5 Super Single Tires, 74300 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2025 Atro 32 ft T/A Frameless Demolition End Dump Trailer (Unused) S/N: 3ELA6EH26SG000342 C/W: Spring Suspension, 32 ft Body, 56 in Side Walls, Steel Body, High Lift Tailgate, 11R24.5 	9166	2025 Atro 32 ft T/A Frameless Aggregate/ sand End Dump Trailer S/N: 3ELA6EH23SG000346 C/W: Spring Suspension, 32 ft Body, 44 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX
	Tires, 74957 lb GVWR Usage: Not Available Notes : THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in : Humble, TX		2025 Atro 32 ft T/A Frameless Aggregate / sand End Dump Trailer S/N: 3ELA6EH21SG000345 C/W: Spring Suspension, 32 ft Body, 44 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID
9164	2025 Atro 32 ft T/A Frameless Demolition End Dump Trailer (Unused) S/N: 3ELA6EH28SG000343 C/W: Spring Suspension, 32 ft Body, 56 in Side Walls, Steel Body, High Lift Tailgate, 11R24.5		IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX
	Tires, 74957 lb GVWR Usage: Not Available Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble TX	9168	2022 CTS EHRD-40 40 ft T/A Frameless End Dump Trailer S/N: 5TU344023NS000394 C/W: Spring Suspension, 40 ft Body, 69 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9165	Asset located in: Humble, TX 165 2025 Atro 32 ft T/A Frameless Aggregate /sand End Dump Trailer S/N: 3ELA6EH2XSG000344 C/W: Spring Suspension, 32 ft Body, 44 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE	-9169	2022 CTS EHRD-40 40 ft T/A Frameless End Dump Trailer S/N: 5TU344021NS000393 C/W: Spring Suspension, Air Brakes, 40 ft Body, 60 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
PURCHASER THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX	9170	2022 Hicks SL3729 37 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 1H9A37A23NM686001 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Lift 1st- Axles, 33 ft Body, 44 in Side Walls, Aluminum Body, Aluminum Wheels, 11R22.5 Tires, 66000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9171	2021 Load King RH3229 31 ft T/A Frameless Demolition End Dump Trailer S/N: 5LKD34228M4032368 C/W: Spring Suspension, 31 ft Body, 43 in Side Walls, Steel Body, Electric Roll Tarp, Air Lift Tailgate, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2017 Etnyre V2215 T/A Aluminum End Dump	9178	2007 CTS HRD32 32 ft T/A Frameless End Dump Trailer S/N: 5TU3432227S000185 C/W: 68000 lb GVWR, Spring Suspension, 32 ft Body, 52 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Outer Wheels, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX
	Trailer S/N: 1E9V22154HE111347 C/W: Air Ride Suspension, Air Brakes, Lift 1st- Axles, 34 ft Body, 45 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R22.5 Tires, 81020 Ib GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9179	2005 Clement HL3762MK2 37 ft T/A Frameless End Dump Trailer S/N: 5C2BB37B45M004825 C/W: 70000 lb GVWR, Spring Suspension, 37 ft Body, 76 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX 2003 Vantage 37 ft T/A Quarter Frame End
9173	2012 Vantage S-102-SS 39 ft T/A Aluminum Quarter Frame Aggregate/ sand End Dump Trailer S/N: 4E7AA3921CASA3651 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9181 20 S, C, Ri A 5 U 5 C, Ri S, C, Ri S, C, Ri S, C, Ri S, C, C, C, C, C, C, C, C, C, C	Dump Trailer S/N: 4EPAA37263AVA4581 C/W: 68000 lb GVWR, Aluminum Frame, Air Ride Suspension, 37 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 445/50R22. 5 Super Single Tires Usage: Not Available Asset located in: Humble, TX 2001 Travis 40 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 48X1F402611001564 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 40 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R22.5
End Dump Trailer	2011 MAC 40 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 5MADN4025BC020508	-	Tires Usage: Not Available Notes : TITLE BRAND REBUILT SALVAGE Asset located in : Humble, TX
	C/W: 80000 lb GVWR, Aluminum Frame, Air Ride Suspension, 40 ft Body, 58 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX	S/N: 5C2BB35BXXM001014 C/W: 66000 lb GVWR, Walking Beam Suspension, 35 ft Body, 48 in Side Walls Body, Electric Roll Tarp, Aluminum Oute Wheels, 285/75R24.5 Tires	C/W: 66000 lb GVWR, Walking Beam Suspension, 35 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, Aluminum Outer Wheels, 285/75R24.5 Tires
9176	2009 MAC 40 ft T/A Aluminum Quarter Frame End Dump Trailer		Usage: Not Available Asset located in: Humble, TX
	S/N: 5MADN40279C018138 C/W: 80000 lb GVWR, Aluminum Frame, Air Ride Suspension, 40 ft Body, 58 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R22.5 Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9183	1999 Clement 38 ft T/A Frameless End Dump Trailer S/N: 1C9BB38BXXM110609 C/W: Spring Suspension, 38 ft Body, 36 in Side Walls, Steel Body, Manual Roll Tarp, Aluminum Outer Wheels, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9177	2009 MAC 40 ft T/A End Dump Trailer S/N: 5MADN40299C018139 C/W: 80000 lb GVWR, Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9184	1998 Allco End Dump Trailer S/N: CA494684 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9185	 1997 Ravens 40 ft T/A End Dump Trailer S/N: 1R1D14023VJ097217 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Manual Roll Tarp, 2-Way Tailgate, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 	9192	2007 Manac 14 ft T/A Belly Dump Trailer S/N: 5MC1116277P006993 C/W: Spring Suspension, Clam Gate Electric Roll Tarp, 11R24.5 Tires, 68000 lb GVWR, 14 ft 10 in Lead Body, 6 ft 4 in Lead Side Walls Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX		· ·
9186	9186 1989 Montone 39 ft T/A End Dump Trailer S/N: 1M918DW29KD003534 C/W: Aluminum/Steel Combination Frame, Spring Suspension, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires	9193	2007 Manac T/A Belly Dump Trailer S/N: 5MC1116287P006713 C/W: Spring Suspension, Clam Gate Manual Roll Tarp Push Block, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	9194	2005 Carrocerias T/A Belly Dump Trailer
9187	Asset located in: Humble, TX 9187 1989 Montone 39 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 1M918DW83KD003467 C/W: Air Ride Suspension, Air Brakes, 39 ft Body, 56 in Side Walls, Aluminum Body,		S/N: 3C9BS40245G039358 C/W: Spring Suspension, Clam Gate Electric Roll Tarp, 11R24.5 Tires, 34000 lb GVWR, 15 ft 6 in Lead Body, 7 ft 4 in Lead Side Walls Usage: Not Available Asset located in : Humble, TX
	Aluminum Wheels, 11R24.5 Tires, 53 ft Aluminum Lead Body, 4 ft 8 in Lead Side Walls,	9195	1998 Beall BABDS421 T/A Aluminum Belly
9188	Manual Lead Tarp Usage: Not Available Asset located in: Humble, TX 1986 Allco 33 ft T/A Frameless End Dump Trailer S/N: 1S9S00005G0009142	-	Dump Trailer S/N: 1BN2P4025WB005259 C/W: Aluminum Frame, Air Ride Suspension, Clam Gate, 385/65R22.5 Tires, 21000 lb GVWR Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.
	C/W: Spring Suspension, 33 ft Body, 44 in Side		Asset located in: Livingston, LA
	Walls, Steel Body, High Lift Tailgate, 11R24.5 Tires Usage: Not Available Asset located in : Humble, TX	9197	1998 Beall BABDS521 T/A Aluminum Belly Dump Trailer S/N: 1BN2P3820WB005104
9189	2022 Armor Lite SBD-40 LTS T/A Belly Dump Trailer S/N: 56EA53K29NA000308 C/W: Spring Suspension, Clam Gate, Push Block, 11R24.5 Tires, Electric Lead Tarp Usage: Not Available		C/W: Aluminum Frame, Spring Suspension, Pintle Hitch, Clam Gate, Aluminum Wheels, 11R22.5 Tires, 64000 lb GVWR Usage: Not Available Notes : LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Livingston, LA
9190	THE INSPECTION REPORT Asset located in: Humble, TX 2022 DeLucio B3500 16 ft T/A Belly Dump Trailer	9198	1985 Lufkin Dp S/N: 1L4B40236F1013584 Usage: Not Available Asset located in : Humble, TX
9191	S/N: 7LVD5BA24ND010263 C/W: Spring Suspension, Clam Gate, Electric Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX 2020 R-Way 4021T T/A Belly Dump Trailer S/N: 1K9BF40F9LL366228	9199	1985 Beall BABDS301 T/A Aluminum Belly Dump Trailer S/N: 1BN2P3122FB001677 C/W: Aluminum Frame, Air Ride Suspension, Clam Gate, Aluminum Wheels, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA;
	C/W: Air Ride Suspension, Clam Gate, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA

Lot #	Details	Lot #	Details
9200	2016 Etnyre 31 ft 6 in Tri/A Aluminum Live Bottom Trailer S/N: 1E9V19967GE111009 C/W: Air Ride Suspension, Lift 1st- 2nd- Axles, 31 ft 6 in Body, 42 in Side Walls, Aluminum Body, Manual Roll Tarp, Split Swing Tailgate, 11R24.5 Tires, 81020 lb GVWR, Air Assisted Tailgate, Hendrickson Air Ride suspension Usage: Not Available Asset located in: Humble, TX	9207	2017 Southern Welding SWAL1000 1000 cft T /A Pneumatic Bulk Trailer S/N: 4S9V6TA20FT347847 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX , Asset located in: Lake Worth, TX
9201	2015 Peerless 48 ft x 102 in T/A Live Bottom Open-Top Chip Trailer S/N: 1PLE04824FPH59384 C/W: Air Ride Suspension, Air Brakes, Pearless, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9209	2019 Southern Trailer 150 bbl T/A Vacuum Tanker Trailer S/N: 4T9V6TA20KJ329227 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 63700 lb GVWR, Aluminum Tank, 63700 lb GVWR, Watson-Chalin Air-Ride Suspension Usage: Not Available Asset located in: Humble, TX
9202 2013 Do Trailer S/N: 5JN C/W: 67 Aluminu Tires Usage: N Notes: D	S/N: 5JYCV4824DE085009 C/W: 67470 lb GVWR, Spring Suspension, Aluminum Wheels, 455/50R22.5 Super Single	9210	2017 Southern Trailer T/A Vacuum Tanker Trailer S/N: 4S9V6TA22HG347005 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 63700 lb GVWR, Aluminum Tank, 63700 lb GVWR Usage: Not Available Asset located in: Humble, TX
9203	THE INSPECTION REPORT Asset located in: Humble, TX 1995 IMC 48 ft x 102 in T/A Live Bottom Chip Trailer S/N: 1M9L14826SC343840 C/W: Aluminum Frame, Spring Suspension, 285 /75R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	9211	2016 Southern Trailer T/A Vacuum Tanker Trailer S/N: 4S9V6TA20GG347048 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Humble, TX 2008 Proco PV1 T/A Vacuum Tanker Trailer
9204	THE INSPECTION REPORT Asset located in: Humble, TX 1994 Ledwell 48 ft x 102 in T/A Live Bottom Open-Top Chip Trailer S/N: 1L9LA72A3RL033475	-	S/N: 1P9KN36218K359458 C/W: Spring Suspension, 11R24.5 Tires, 68000 Ib GVWR, Steel Tank, Catwalk w/Guardrails, 68000 Ib GVWR Usage: Not Available Asset located in : Humble, TX
9206	C/W: Spring Suspension, Sliding Suspension, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2007 Neville Built 42 ft T/A Belly Dump Grain Trailer S/N: 1N9GT42287G175464 C/W: Spring Suspension, 2 Hoppers, Manual	9213	2007 Dragon 130 bbl T/A Vacuum Tanker Trailer S/N: 1UNST422X7L052426 C/W: Spring Suspension, 11R24.5 Tires, 70000 Ib GVWR, Steel Tank, Catwalk w/Guardrails, 70000 Ib GVWR Usage: Not Available Asset located in: Humble, TX
	Traps, 38 ft Steel Box, 54 in, Side Walls, Manual Roll Tarp, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9215	2007 Dragon 5460 gal T/A Vacuum Tanker Trailer (Inoperable) S/N: 1UNST42277L052674 C/W: Air Ride Suspension, 11R24.5 Tires, Steel Tank, Catwalk w/Guardrails, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA

Lot #	Details	Lot #	Details
9216	2018 TROX 6300 gal T/A Tanker Trailer S/N: 1T9TG4326J1867289 C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 50000 lb GVWR, Aluminum Tank, Catwalk w/Guardrails, 50000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9226	2011 Stephens MC407 8400 gal T/A Tanker Trailer S/N: 1S9AB15B9BH474099 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9217	2017 Heil CT12598 9200 gal T/A Tanker Trailer S/N: 5HTSA4421H7600873 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9227A	2010 Dragon 8400 gal T/A Tanker Trailer S/N: 1UNST4420AS078205 C/W: Air Ride Suspension, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, 70000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9218	2016 Heilx Tanker Trailer S/N: 5HTAB4422G7H81511 Usage: Not Available Asset located in: Humble, TX 2016 Heilx Tanker Trailer	9227	2011 Heil 8400 gal T/A Tanker Trailer S/N: 1S9AB15B3BH474101 C/W: 68000 lb GVWR, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank Usage: Not Available
9219	S/N: 5HTAB4420G7H81510 Usage: Not Available		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9220	Asset located in: Humble, TX 2016 Heilx Tanker Trailer S/N: 5HTAB4424G7H81512 Usage: Not Available Asset located in: Humble, TX	9228	2008 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB442587H74618 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R22.5 Tires, Aluminum Tank Usage: Not Available
9221	2016 Heilx Tanker Trailer S/N: 5HTAB4424G7H81509 Usage: Not Available Asset located in: Humble, TX	9229	Asset located in: Humble, TX 2008 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452085G22296 C/W: Air Ride Suspension, Aluminum Wheels,
9222	2014 Helix Tanker Trailer S/N: 5HTAB4423E7H79991 Usage: Not Available Asset located in: Humble, TX		11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in : Humble, TX
9223	2014 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB4429E7H79283 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available	9230	2007 PolarTank 6500 gal T/A Tanker Trailer S/N: 1PMS1432871032253 C/W: Air Ride Suspension, 295/75R22.5 Tires, 66000 lb GVWR, Insulated Stainless Steel Tank, 66000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9224	Asset located in: Humble, TX 2014 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB4426E7H79287 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R22.5 Tires, Aluminum Tank, 4 Compartments	9231	2006 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452265G21826 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	9232	2005 Vantage 1000 cft T/A Tanker Trailer
9225	2014 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB4423E7H79280 C/W: Aluminum Frame, Air Ride Suspension, 11R22.5 Tires, 68000 lb GVWR, Stainless Steel Tank, 4 Compartments, 68000 lb GVWR Usage: Not Available		S/N: 4E7PA42205PBA0492 C/W: 68000 lb GVWR, Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 445 /50R22.5 Super Single Tires, Aluminum Tank Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	9233	2005 Polar Tanker Trailer S/N: 1PMA3432251029058 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9234	2003 Heil MC407 8400 gal T/A Tanker Trailer	9241	2001 Heil MC407 8400 gal T/A Tanker Trailer
	S/N: 5HTDL452X35G14540 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available		S/N: 190DL452013G14014 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
9235	2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452135G14703 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9242	2001 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452913G14013 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9236	2002 Heil MC407 8400 gal T/A Tanker Trailer	9243	2000 Heil MC407 8400 gal T/A Tanker Trailer
,200	S/N: 5HTDL452235G14547 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available		S/N: 190DL452713G14012 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9244	2000 Heil MC407 8400 gal T/A Tanker Trailer
9237A	2003 Heil 8400 gal T/A Tanker Trailer S/N: 5HTDL452135G14541 C/W: Aluminum Frame, Spring Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, MC407 Code, Roper Hydraulic Powered Pump		S/N: 190DL452313G14010 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, 65000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	9245	2000 Heil MC407 8400 gal T/A Tanker Trailer
9237	Asset located in: Humble, TX 2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452835G14701 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR		S/N: 190DL452713G13992 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	9246	2001 Polar Tank MC407 8400 gal T/A Tanker Trailer
9238	Asset located in: Humble, TX 2002 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452335G14542 C/W: Spring Suspension, 11R24.5 Tires, 65000 Ib GVWR, Aluminum Tank, 65000 Ib GVWR Usage: Not Available Asset located in: Humble, TX		S/N: 1PMA3432515002827 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9239	•	9247	2000 Heil MC407 8400 gal T/A Tanker Trailer
7237	2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452935G14545 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available		S/N: 190DL4528Y3G13977 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	9248	2000 Heil MC407 8400 gal T/A Tanker Trailer
9240	2002 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452523G14513 C/W: Spring Suspension, 11R24.5 Tires, 65000 Ib GVWR, Aluminum Tank, 65000 Ib GVWR Usage: Not Available Asset located in: Humble, TX		S/N: 190DL4526Y3G13976 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9249	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452XY3G13978 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available Asset located in: Humble, TX	9258	2025 X-STAR 990 gal Portable Steel Fuel Tank (Unused) S/N: 1X9T7BA20SH039895 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
9250	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL4525Y3G13967 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available Asset located in: Humble, TX	9259	2025 X Star 990 gal Portable Steel Fuel Tank (Unused) S/N: 1X9T7BA29SH039894 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX 2024 Xstar 750 gal Portable Steel Fuel Tank
9251	1997 Trailmaster Tanker Trailer S/N: 190DL4428V3G13006 Usage: Not Available Asset located in: Humble, TX 1982 Polar 8000 gal T/A Tanker Trailer		(Unused) S/N: 1X9T7B828SH039892 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
9254	S/N: 1PMS34322C1005893 C/W: Spring Suspension, 285/75R24.5 Tires, 68000 lb GVWR, Stainless Steel Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX 1973 Lubbock MC331 T/A Tanker Trailer	9261	2025 Xstar 750 gal Portable Steel Fuel Tank (Unused) S/N: 1X9T7B82XSH039893 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
	S/N: 58389 C/W: Spring Suspension, 285/75R24.5 Tires, 66000 lb GVWR, Steel Tank, 66000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9263	2019 CFWS Pole Trailer S/N: 5SRUT322XKL190044 C/W: 10000 lb GVWR Lunette Ring Hitch, Spring Suspension, Electric Brakes, 6 Stanchions, 235/80R16 Tires, 10000 lb GVW
9255	2018 Multiquip WT5C 500 gal T/A Water Tank Trailer		Usage: Not Available Asset located in: Humble, TX
	S/N: 5SLBM1224JL024474 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 205/75R14 Tires, 7000 lb GVWR, Poly Tank, Multiquip Gasoline Powered Pump, 7000 lb GVWR Usage: Not Available Notes : TEXAS BUYERS MUST STOP IN OFFICE	9264	1973 Fruehauf Pole Trailer S/N: 127983 C/W: 65000 lb GVWR Lunette Ring Hitch, Spring Suspension, 1 Stanchions, 11R24.5 Tires Usage: Not Available Asset located in : Humble, TX
	TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9266	2020 Benlee TACVDD39S T/A Roll-Off Trailer S/N: 1B9A13927LB180200
9256	2017 Multiquip WT5C T/A Water Tank Trailer S/N: 4GNBM122GB043462 C/W: Lunette Ring Hitch, Spring Suspension, Surge Brakes, 205/75R14 Tires, 7000 lb GVWR, Poly Tank, Honda Gasoline Powered Pump,	9267	C/W: Air Ride Suspension, Air Brakes, Benlee Roll-Off Unit Hydraulic Roll Tarp, Aluminum Outer Wheels, 11R22.5 Tires Usage: Not Available Asset located in : Humble, TX
	7000 lb GVWR Usage: Not Available Asset located in : Humble, TX		2018 Benlee TASMDS26S T/A Roll-Off Trailer S/N: 1B9A12627JB180371 C/W: Spring Suspension, Electric Roll Tarp,
9257	2009 Wylie 200 gal S/A Water Tank Trailer S/N: 5VUTB10149P000009 C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, 2950 lb GVWR, Poly Tank, John Blue Gasoline Powered Pump, 2950 lb GVWR, W/ Hose Reel & Gun Usage: 24 Hr Asset located in: Humble, TX		11R22.5 Tires, 50000 lb GVWR Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details
9268	2018 Benlee TASMRS26S T/A Roll-Off Trailer S/N: 1B9A12625JB180059 C/W: Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	9277B	2013 48 ft 6 in Tri/A Container Trailer S/N: 1M9KP5936DS284143 C/W: Spring Suspension, 245/70R17.5 Tires, 36000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9269A	Asset located in: Lake Worth, TX 2000 Dragon T/A Roll-Off Trailer S/N: 1B9D14825YE183493 C/W: Air Ride Suspension, 11R22.5 Tires Usage: Not Available Asset located in: Humble, TX	_9278	2004 Pratt LSMR53X4 40 ft Tri/A Container Trailer S/N: 1P9CP40394H343011 C/W: Walking Beam Suspension, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9269 9270	2007 Dentoni T/A Roll-Off Trailer S/N: 1D9SR486571561018 C/W: Air Ride Suspension, 285/75R24.5 Tires Usage: Not Available Asset located in: Humble, TX 1995 Clement T/A Roll-Off Trailer	9281	2023 ACE SC804050L 18 ft T/A Container Trailer S/N: 3BZPN4021PC008329 C/W: 65000 lb GVWR, Air Ride Suspension, 295 /75R22.5 Tires Usage: Not Available
	S/N: 1C9EB36B2SM110256 C/W: Walking Beam Suspension, 11R24.5 Tires Usage: Not Available	0282	Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
9271	Asset located in: Humble, TX T/A Roll-Off Trailer S/N: 82147 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: LOCATED-IN-HOUSTON-TX	9283	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2536L2991424 C/W: Air Ride Suspension, Side Skirts, Swing Door, Carrier Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: 18,872 Hr Asset located in: Humble, TX
9272 Quantity of Trailer S/N: 3ELA C/W: Sprin 295/75R22 Usage: No Notes: THI FEDERAL I PURCHAS 9272 TO 9 IS RECEIVI BE APPLIE	Asset located in: Humble, TX Quantity of (5) 2025 Atro 40 ft T/A Container Trailer S/N: 3ELA6CR2XSG000282 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: THIS ITEM IS SUBJECT TO 12%	9284	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538L2991425 C/W: Air Ride Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER THE CLOSING TIME OF LOTS 9272 TO 9277 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT	9285	2020 Utility 53 ft T/A Refrigerated Trailer S/N: 1UYVS2539L2991515 Usage: Not Available Asset located in: Humble, TX
	WILL BE THE WINNER. Asset located in: Humble, TX	9287	2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer
9273	Quantity Of (5) 2025 Atro 40 Ft T/A Container Trailer (Unused) S/N: 3ELA6CR2XSG000184 C/W: 65000 lb GVWR, Spring Suspension, Air Brakes, 40 ft - Container Pins, 295/75R22.5 Tires Usage: Not Available		S/N: 1UYVS253XHM764345 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier Refrigeration Unit, 295/75R22.5 Tires Usage: 7,222 Hr Notes: LOCATED-IN-FORT-WORTH-TX, . Asset located in: Lake Worth, TX
	Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER ; THE CLOSING TIME OF LOTS 9272 TO 9277 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX	9288A	2017 CIMC 53 ft x 102 in T/A Refrigerated Trailer S/N: 527SR5326HM009310 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9288 9290	2017 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2533H6073405 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, 2017 Thermo King Precedent C- 600 Refrigeration Unit, Serial Number 60001221299,, 11R22.5 Tires, 65000 lb GVWR Usage: 27,750 Hr Asset located in: Humble, TX 2016 Great Dane 53 ft x 102 in T/A	 in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0624GE700391 C/W: Spring Suspension, Sliding Suspensio Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMEN' FROM-THE-PROFESSIONALLY-MAINTAINEI WALMART-FLEET Usage: 28,382 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCO NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 9294 2016 Great Dane 53 ft x 102 in T/A Multi-Te Refrigerated Trailer S/N: 1GRAA0624GE700424 C/W: Spring Suspension, Sliding Suspensio Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMEN' FROM-THE-PROFESSIONALLY-MAINTAINEI WALMART-FLEET Usage: 33,311 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX 9295 2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0628GE700393 C/W: Spring Suspension, Sliding Suspensio Roll-Up Door, Carrier Vector 8600MT Refrigerated Trailer S/N: 1GRAA0628GE700393 C/W: Spring Suspension, Sliding Suspensio Roll-Up Door, Carrier Vector 8600MT Refrigerated Trailer S/N: 1GRAA0628GE700393 C/W: Spring Suspension, Sliding Suspensio Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Serial Number 24012411 3-Zone, (2) Remote Evaporator, 275/80R22. Tires, EQUIPMENT-FROM-THE- PROFESSIONALLY-MAINTAINED-WALMAR 	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0624GE700391 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 28,382 Hr
	Refrigerated Trailer S/N: 1GRAA0629GE700371 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT		MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Refrigeration Unit, Shore Power, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 30,028 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX		S/N: 1GRAA0624GE700424 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-
9291 2016 Grea Refrigerate S/N: 1GRA C/W: Sprin Roll-Up Do	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625GE700450 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Serial Number 200420-		WALMART-FLEET Usage: 33,311 Hr Notes : FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET
	0930, 275/80R22.5 Tires, EQUIPMENT-FROM- THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Refrigerated Trailer S/N: 1GRAA0628GE700393 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Serial Number 2401241128, 3-Zone, (2) Remote Evaporator, 275/80R22.5
9292	Refrigerated Trailer S/N: 1GRAA0622GE700390 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote		Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 31,005 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9296	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0625GE700397 C/W: Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 27,470 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9297	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0626GE700425 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9302	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0624GE700388 C/W: Spring Suspension, Sliding Suspension, Carrier Refrigeration Unit, Shore Power, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 29,637 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9298	2016 Great Dane 53 ft x 102 in T/A	9303	2016 Great Dane ECM-1113-12053 53 ft x 102
9299	Refrigerated Trailer S/N: 1GRAA0621GE700395 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 26,629 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX 2016 Great Dane 53 ft x 102 in T/A Multi-Temp	-	in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0629GE700452 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, 2015 Carrier Vector 8600MT Refrigeration Unit, Serial Number RAN91430622,, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 24,180 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
5255	Refrigerated Trailer		Asset located in: Humble, TX
	S/N: 1GRAA0626GE700392 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Shore Power, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 28,679 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9304	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0627GE700370 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires, EQUIPMENT-FROM-THE- PROFESSIONALLY-MAINTAINED-WALMART- FLEET Usage: 27,870 Hr Notes: FROM THE PROFESSIONALLY
9300	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Refrigerated Trailer		MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1GRAA0625GE700254 C/W: Spring Suspension, Sliding Suspension,	0005	Asset located in: Humble, TX
0201	Roll-Up Door, Carrier Refrigeration Unit, 3-Zone, (3) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 25,344 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9305	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625GE700447 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: Not Available
9301	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0620GE700369 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 23,452 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX		Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9307	2015 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2539FM178510 C/W: Air Ride Suspension, Ducted Floor, Swing Door, Thermo King Spectrum SB Refrigeration Unit, Serial Number 6001163293, Shore Power, 3-Zone, (2) Remote Evaporator, 11R22.5 Tires Usage: 17,739 Hr Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	9313 9314	2004 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS25384U179709 C/W: Air Ride Suspension, Swing Door, Carrier Stealth Refrigeration Unit, 295/75R22.5 Tires, 65000 lb GVWR Usage: 28,677 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2005 Great Dane 7811-TZ-1A 50 ft x 102 in T/A Refrigerated Trailer
9308	2015 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2531FU280786 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Thermo King Smart Reefer 4 Refrigeration Unit, 295/75R22.5 Tires Usage: 22,679 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9316	S/N: 1GRAA00225W700616 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Brad Wall Mount Refrigeration Unit, Aluminum Outer Wheels, 11R22.5 Tires Usage: Not Available Asset located in : Humble, TX 2006 Hackney Keg Trailer 14 Bay Refrigerated S/A Beverage Trailer S/N: 1HHTRH2156M000596 C/W: Air Ride Suspension, 32 ft 8 in Insulated
9309	Asset located in: Humble, TX 2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XEM080407	9317	Body, 52 in Wide Bays, Side Pull-Out Steps, 295 /75R22.5 Tires, Shore power inlet Usage: Not Available Asset located in: Humble, TX 2005 Hackney Keg Trailer 14 Bay Refrigerated
	C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Carrier Genesis TM1000 Refrigeration Unit, Aluminum Wheels, 295 /75R22.5 Tires Usage: 28,053 Hr Asset located in: Humble, TX		S/A Beverage Trailer S/N: 1HHTRH2145M000121 C/W: Air Ride Suspension, Air Brakes, 31 ft Insulated Body, 52 in Wide Bays, 275/80R22.5 Tires, 36000 kg GVWR Usage: Not Available Asset located in: Humble, TX
9310	2013 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537DM491620 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier C22100 Advance Refrigeration Unit, 295/75R22.5 Tires Usage: 51,192 Hr Asset located in: Humble, TX	9318	2000 Mickey 14 Bay S/A Beverage Trailer S/N: 5CWRA3514YH998027 C/W: Spring Suspension, 34 ft 10 in Body, 52 in Wide Bays, Side Pull-Out Steps, 11R22.5 Tires, 38000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9311	2011 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537BM237905 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Roll-Up Door, Carrier X2 2500A Refrigeration Unit, Serial Number NAD91221989, 275/80R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9319	1998 Mickey 14 Bay S/A Beverage Trailer S/N: 1M9RB1910WH043134 C/W: Spring Suspension, 36 ft 5 in Body, 56 in Wide Bays, Side Pull-Out Steps, 11R22.5 Tires, 38000 lb GVWR Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9312	2007 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA06247W702054 C/W: Air Ride Suspension, Sliding Suspension, Brad Wall Mount Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires, With Contents Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9320	2009 Utility VS2DX 57 ft x 102 in T/A Van Trailer S/N: 1UYVS257X9P712538 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR, Hendrickson air-ride suspension Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9327A	2022 Vanguard 53 ft x 102 in T/A Van Trailer S/N: 5V8VC5327NM204623 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9321	2009 Utility VS2DX 57 ft x 102 in T/A Van Trailer S/N: 1UYVS257X9P712507 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9327	2023 Tysol 53 ft x 102 in T/A Van Trailer S/N: 3T9T6EU23PA206016 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 85000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9322	2023 Wabash DVHDHPC 53 ft T/A Van Trailer S/N: 1JJV532D2PL368933 C/W: Air Ride Suspension, Sliding Suspension, 68000 lb GVWR, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9333	2018 Stoughton ZTPVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5324JBA01604 C/W: 70000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9323	2023 Wabash DVCVHPC 53 ft T/A Van Trailer S/N: 1JJV532D9PL369030 C/W: Air Ride Suspension, Sliding Suspension, 68000 lb GVWR, Aluminum Roof, Hardwood Floor, Side Skirts, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9334	2017 Hyundai VC2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C5HT108034 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9324	2023 Wabash DVHDHPC 53 ft T/A Van Trailer S/N: 1JJV532D0PL368932 C/W: Air Ride Suspension, Sliding Suspension, 68000 lb GVWR, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2023 Wabash DVCVHPC 53 ft x 102 in T/A Van	9335	2016 Stoughton ZGPVW535TSCAR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532XGS681207 C/W: 70000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires Usage: Not Available
	Trailer S/N: 1JJV532D2PL369029 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX 2014 Great Dane 53 Ft T/A 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0625ED450212 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Flager, Cide Clivite, Dell Un Dear 275 (200022 5
9326	2023 Corpus 53 ft x 102 in T/A Van Trailer S/N: 3C9C5XZ29PA115002 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 85000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Floor, Side Skirts, Roll-Up Door, 275/80R22.5 Tires Usage: Not Available Notes : LOCATED-IN-LAKE WORTH-TX Asset located in : Lake Worth, TX

Lot #	Details	Lot #	Details	
9338	2014 Stoughton ZGPVW535TSC 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532XEB487340 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 275/80R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9345	2012 Stoughton ZGPVW535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5320CB280159 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR, Hendrickson Air-Ride Suspension Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	
9339	2014 Kentucky 53 ft x 102 in T/A Van Trailer S/N: 1KKVE5329EL234652 C/W: 65000 lb GVWR, Air Ride Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Swing Door, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2012 Great Dane CPL-3314-21053 53 ft x 102	9346	2012 Stoughton ZGPVW535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5325CB280156 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR	
9041	2012 Great Dane CPL-3314-21053 53 π x 102 in T/A Van Trailer S/N: 1GRAP0628CT567347 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb		Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	
	GVWR Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX ; Asset located in : Lake Worth, TX	9347	2012 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D0CL626750 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR	
9342	2012 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2537CP284609 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires		Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	
	Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9348	2012 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D6CL626672	
9343	2012 Hyundai VR2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C7CT326016 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	-	C/W: Air Ride Suspension, Sliding Sus Aluminum Roof, Hardwood Floor, Swir 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes : ; SELLER MAINTENANCE RECC	C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9354	2011 Wabash Dura-Plate 53 ft x 102 in T/A	
9344	2012 Stoughton ZGPVW535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5327CB280160 C/W: Air Ride Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION	9355A	Van Trailer S/N: 1JJV532D5BL370460 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2009 Trailmobile 53 ft x 102 in T/A Van Trailer	
	BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	5000A	S/N: 2MN01JAH891003512 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9356	Trailer S/N: 1JJV532W58L144414 C/W: Air Ride Suspension, Sliding Suspension,	9363	2005 Wabash 53 ft T/A Van Trailer S/N: 1JJV532W95L892837 Usage: Not Available Asset located in: Humble, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9364	2005 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W15L892640 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood/ aluminum,
9358	2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W17L976654 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available		Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9359	Asset located in: Humble, TX 2007 Wabash DVHDHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W17L091435 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tiree	9365 9366	2004 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W84L871511 C/W: Spring Suspension, Aluminum Roof, Aluminum Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Asset located in: Humble, TX
	Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		2003 Utility VS2RA 53 ft x 102 in T/A Van Trailer S/N: 1UYVS25303M836825 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Ducted Floor, Swing Door, 295 /75R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: TITLE BRAND REBUILT SALVAGE Asset located in: Humble, TX
9360	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06257K286264 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Eloor, Side Skirts, Boll-Up, Door, 295/75B22, 5	9367 9368A 9368A 9368	
	Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2002 Wabash 53 ft T/A Van Trailer S/N: 1JJV532W02L769116 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 11R22.5 Tires Usage: Not Available
9361	2006 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06256J612598 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Roll- Up Door, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-BYRAM-MS - EQUIPMENT- FROM-YELLOW-CORP Asset located in: Humble, TX		Asset located in: Humble, TX 2001 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W11L748001 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9362A	2006 Wabash 53 ft T/A Van Trailer S/N: 1JJV532W36L999190 Usage: Not Available		Asset located in: Humble, TX 2001 Wabash DVCVHPC 53 ft x 102 in T/A Van
9362	Asset located in: Humble, TX 2006 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W46L024889 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	-	Trailer S/N: 1JJV532W91L736937 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX

This catalog was created at November 5, 2024 03:25:12 AM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details	
9369	2001 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06291B078413 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP	9375	1998 Strick Commercial Trailer 53 ft T/A Van Trailer S/N: 1S12E9532WD433333 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9376	2022 Vanguard MaxCube 48 ft x 102 in T/A	
	Asset located in: Humble, TX		Van Trailer S/N: 5V8VA4827NT201123	
9370	2001 Lufkin TFV-IP ST 53 ft x 102 in T/A Van Trailer S/N: 1L01A532811146879 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX	
9371	2000 Strick 53 ft x 102 in T/A Van Trailer	9377	2015 Wabash DVCVHPC 48 ft x 102 in T/A Van	
9371	S/N: 1S12E9531YD455231 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Notes : LOCATED-IN-ROSHARON-TX-YELLOW ; EQUIPMENT-FROM-YELLOW-CORP	02700	Trailer S/N: 1JJV482D4FL869773 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	9378B	2006 Stoughton AVW-485T-S-AR 48 ft x 102 in T/A Van Trailer	
9372A	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W4YL695109 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available		S/N: 1DW1A48206S862401 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9378	Asset located in: Humble, TX 2008 Great Dane 48 ft x 102 in T/A Van Trailer	
	Asset located in: Humble, TX		S/N: 1GRAA96288B704385	
9372	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W2YL695917 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	-	Pintle Hitch, Translucent Roof, Hard	Usage: Not Available
	Asset located in: Humble, TX	9379	2002 Lufkin TFV-IP ST 48 ft x 102 in T/A Van	
9373	1999 Trailmobile 53 ft x 102 in T/A Van Trailer S/N: 1PT01JAH4X6010027 C/W: 65000 lb GVWR, Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 11R22.5 Tires Usage: Not Available Asset located in : Humble, TX		Trailer S/N: 1L01A482021149473 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
0374	-	9380	2001 Lufkin TFV-IP ST 48 ft x 102 in T/A Van	
9374	1999 Strick Corp 53 ft x 102 in T/A Van Trailer S/N: 1S12E9534XE445933 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX		Trailer S/N: 1L01A482811147985 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
		•		

Lot #	Details	Lot #	Details
9381	2001 Great Dane 7311TPS 48 ft x 102 in T/A Van Trailer S/N: 1GRAA962X1K237895 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available	9387	1992 Trailmobile 01AC-1UAL 48 ft x 102 in T/A Van Trailer S/N: 1PT01ACH4N9008187 C/W: 65000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Swing Door, 11R24.5 Tires Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	9388	1988 Pines 48 ft x 102 in T/A Van Trailer
9382	1999 Trailmobile 48 ft x 102 in T/A Van Trailer S/N: 1PT01JAH5X6013180 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available		S/N: 1PNX48280JKA30308 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: EQUIPMENT-FROM-YELLOW-CORP SELLING SCRAP NO TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION
9383	1998 Wabash 48 ft x 102 in T/A Van Trailer	_	REPORT
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	S/N: 1PNV482B6WK211649	0000	Asset located in: Humble, TX
	C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Notes: ; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX	9389	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ131004602 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 Ib GVWR Usage: Not Available
9384	1994 Wabash 48 ft x 102 in T/A Van Trailer		Asset located in: Humble, TX
9304	S/N: 1JJV482UXRL207037 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes : EQUIPMENT-FROM-YELLOW-CORP	9390	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ331004598 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	DEFICIENCIES NOTED - PLEASE SEE THE	9391	2003 Trailmobile 45 ft x 96 in T/A Van Trailer
	INSPECTION REPORT Asset located in: Humble, TX		S/N: 2MN011PJX31004596
9385	1993 Wabash 48 ft x 102 in T/A Van Trailer S/N: 1JJV482X1PL184576 C/W: Spring Suspension, Air Brakes, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP	9392	C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 Ib GVWR Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Notes : EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ231004592 C/W: Spring Suspension, Sliding Suspension, Hardwood Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR
9386	1994 Great Dane 7811TZ-1A 48 ft x 96 in T/A	1	Usage: Not Available
	Van Trailer S/N: 1GRAA9627RW061201 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Swing Door, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9393	Asset located in: Humble, TX 2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ331004603 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9394 9395	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJX31003335 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 Ib GVWR Usage: Not Available Asset located in: Humble, TX 2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ431004593 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, Aluminum	9402	1995 Hyundai HDM-45WH-V5300 45 ft x 102 in T/A Van Trailer S/N: 3H3V452C5ST000521 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Swing Door, 10.00-20 Tires, 65000 lb GVWR, Wooden Shelves, Storage Boxes & Metal Racks. Office In Front w/ Desk, Cabinets & A/C Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	9403	2011 Great Dane DST-1314-02199 42 ft x 102 in T/A Van Trailer
9396	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ131004597 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		S/N: 1GRAA842XBB706532 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Ramp, Curbside Door, Roll-Up Door, 225/70R22.5 Tires Usage: Not Available Notes : CAN ONLY BE PULLED WITH A S/A TRUCK DEFICIENCIES NOTED - PLEASE SEE
9397	2003 Trailmobile 45 ft x 96 in T/A Van Trailer		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 2MN011PJ231004589 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/80R22.5 Tires, 65000 Ib GVWR Usage: Not Available Asset located in: Humble, TX	9404	2016 Wabash 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D0GL957238 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP
9398	2003 Trailmobile 45 ft x 96 in T/A Van Trailer		Usage: Not Available Asset located in: Humble, TX
	S/N: 2MN011PJX31004601 C/W: Spring Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in : Humble, TX		2016 Wabash 40 ft S/A Van Trailer S/N: 1JJV401D9GL957190 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP
9400	1995 Hyundai HDM-45WH-V5300 45 ft x 102 in		Usage: Not Available
	T/A Van Trailer S/N: 3H3V452C5ST000535	9406	Asset located in: Humble, TX
	S/N: 3H3V452C5S1000535 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 10.00-20 Tires, 65000 lb GVWR, Steel Shelving, Tool Box, Hose Hooks Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9400	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D0KL140381 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA
9401	2011 Great Dane DST-1314-02199 42 ft x 102	9407	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van
	in T/A Van Trailer S/N: 1GRAA8423BB706534 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Roll-Up Door, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	2407	Trailer S/N: 1JJV281D0KL140414 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA

Lot #	Details	Lot #	Details
9408	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D6KL140434 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA 2019 Wabash DVDBHPC 28 ft x 102 in S/A Van	9414	2008 Great Dane PSL-1311-02028 28 ft x 102 in S/A Van Trailer S/N: 1GRAA561XAK210924 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Front/Rear Vents, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9409	Trailer S/N: 1JJV281D7KL140488 C/W: 40000 lb GVWR, Spring Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA 2019 Wabash DVDBHPC 28 ft x 102 in S/A Van	9415	2008 Great Dane SSL-1311-02028 28 ft x 102 in S/A Van Trailer S/N: 1GRAA561X8K202042 C/W: 34000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9411	Trailer S/N: 1JJV281D9KL140427 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA 2019 Wabash DVDBHPC 28 ft x 102 in S/A Van	9416	2005 Wabash 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W95L913113 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP SELLING SCRAP NI TITLE
2411	Trailer S/N: 1JJV281D8KL140466 C/W: 40000 lb GVWR, Spring Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA	9417	Asset located in: Humble, TX 2005 Wabash 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W05L913176 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP
9412	2017 Wabash 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D1HL987077 C/W: 40000 lb GVWR, Spring Suspension,	9418	Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX
	Pintle Hitch, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA_TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA		2001 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F41F770256 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX
9413	2013 Stoughton DVW-285S-C-WDG 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2819DS373133 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9419	2020 Wabash S/A Dolly S/N: 1JJD061X3LL228424 C/W: 20000 lb GVWR, Spring Suspension, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Notes: Selling BOS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9420	2006 Wabash S/A Dolly S/N: 1JJD101W66L987381 C/W: Spring Suspension, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-IAA 458 - BAYTOWN, TX , NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY ; LOCATED-IN-BAYTOWN-TX EQUIPMENT-FROM-YELLOW-CORP Asset located in: Baytown, TX	9429	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3364S1113947 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
9422	1988 Fruehauf ELF-1 S/A Dolly S/N: 1H2E00619JH058415		Asset located in: Humble, TX
	C/W: 20000 lb GVWR, Spring Suspension, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Notes : EQUIPMENT-FROM-YELLOW-CORP Asset located in : Humble, TX	9430	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3366S1113948 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND-
9423	Jeep Dolly T/A Dolly S/N: Not Available C/W: Spring Suspension, 445/65R22.5 Tires Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX		TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX 2025 Southland SL714-16KHD 14 ft T/A Dump
9425	2024 Texas Pride 16 ft T/A Gooseneck Dump Utility Trailer S/N: 7HCGD1628RB048350 C/W: 16000 lb GVWR, Spring Suspension, Steel Decking, Aluminum Wheels, 235/80R16 Tires, Manual Roll Tarp, Split Swing Tailgate Usage: Not Available Asset located in: Humble, TX		Utility Trailer (Unused) S/N: 2SFKL3362S1113946 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
9426	2024 Texas Pride DT716416KGN T/A Gooseneck Dump Utility Trailer		Asset located in: Humble, TX
	S/N: 7HCGD162XRB048351 C/W: 16000 lb GVWR, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9432 2025 Southland SL714-16KHD 1 Utility Trailer (Unused) S/N: 2SFKL3360S1113945 C/W: Ball Hitch, Spring Suspensi Brakes, 82 in Deck Width, 82 in C Ramp, Steel Decking, 235/85R16 Ib GVWR, EQUIPMENT-FROM-SO TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUT TRAILER CORP Asset located in: Humble, TX	S/N: 2SFKL3360S1113945 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND-
9427	2024 PJ Trailer 16 ft T/A Dump Utility Trailer S/N: 4P51D1623R1407265 C/W: 9899 lb GVWR, Spring Suspension, Ramp, Steel Decking, 225/75R15 Tires Usage: Not Available		Usage: Not Available Notes : EQUIPMENT FROM SOUTHLAND TRAILER CORP
	Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		
9428	2023 Texas Pride 16 ft T/A Dump Utility Trailer S/N: 7HCBD1623PB039496 C/W: 16000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 235 /85R16 Tires Usage: Not Available Asset located in: Humble, TX		S/N: 2SFKL4360S1116429 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9434	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4368S1113276 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split swing/ lift) Tail Gate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9439	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4361S1113443 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split swing/lift) Tailgate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9435	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4363S1113444 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split swing/lift) Tail Gate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9440	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4369S1116431 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9436	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4366S1113275 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	-9441	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL436XS1113294 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split-swing/lift) Tailgate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9437	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4369S1116414 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split swing/lift) Tailgate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9442	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4367S1116430 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9438	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL436XS1113277 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split-swing/lift) Tail Gate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	-9443	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4368S1113293 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, Two way (split-swing/ lift) Tailgate, Manual Tarp and Ramps ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9444	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4360S1116432 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP	9449	2025 Southland SL714-14KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3364S1113345 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 Ib GVWR, Two way (split-swing/lift) tailgate, manual tarp and ramps. Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
	Asset located in: Humble, TX		Asset located in: Humble, TX
9445	94452025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused)S/N: 2SFJL3367S1106986C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not AvailableNotes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9450	2025 Southland SL714-14KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1113344 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 Ib GVWR, Two way (split- swing/ lift) tailgate, manual tarp and ramps. ; EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
9446	2025 Southland SL714-14K 14 ft T/A Dump	- 	Asset located in: Humble, TX
Utility Trailer (Unused) S/N: 2SFJL336XS1110823 C/W: Ball Hitch, Spring Suspen Brakes, 82 in Deck Width, 82 in Ramp, Steel Decking, 235/80R ⁻	S/N: 2SFJL336XS1110823 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available	9451	2025 Ranco 7014 14 ft T/A Dump Utility Trailer S/N: 3EZBTC145SA003786 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9452	2025 Industrias America 7014R 14 ft T/A Dump Utility Trailer
9447	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1110778 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width,		S/N: 3EZBTC140SA003758 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Steel Decking, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Ramp, Steel Decking, 235/80R16 Tires, 14532	9453	2024 STL Industrial 14 ft T/A Dump Utility
0449	Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes : EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in : Humble, TX		Trailer (Unused) S/N: 4B9BD1421RM336007 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 71 in Deck Width, 98 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available
9448	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused)		Asset located in: Humble, TX
	S/N: 2SFJL3364S1111661 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes : EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in : Humble, TX	9454	2024 STL Industrial 14 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1425RM336009 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9455	2024 STL Industrial 14 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD142XRM336006 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX	9461	2018 Felling FT10DTHDG 12 ft T/A Dump Utility Trailer S/N: 5FTBD1227J1001245 C/W: Lunette Ring Hitch, Spring Suspension, 81 in Deck Width, 85 in Overall Width, Aluminum Flooring, 225/75R15 Tires, 9980 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9456	2024 STL Industrial 12 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1221RM336009 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX	9462	2018 Snake River DMP610-7K HD 10 ft T/A Dump Utility Trailer S/N: 5PTBD1021J1028298 C/W: 7380 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, 96 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX
9457	2024 STL Industrial 12 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1226RM336006 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX	9463	2018 Snake River 10 ft T/A Dump Utility Trailer S/N: 5PTBD1026J1028300 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, 96 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX
9458 2025 Ranco F Trailer S/N: 3EZBTC C/W: Ball Hito Brakes, 60 in Steel Decking	2025 Ranco FT510 10 ft T/A Dump Utility Trailer S/N: 3EZBTC109SA003920 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, 60 in Overall Width, Steel Decking, 225/75R15 Tires, 7000 lb	9464	2018 Snake River 10 ft T/A Dump Utility Trailer S/N: 5PTBD1020J1028325 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, Steel Decking, 225 /75R15 Tires, 7380 lb GVWR Usage: Not Available Asset located in: Humble, TX
	GVWR, Manual tarp, Two way (Split-Swing/ lift) Tailgate Usage: Not Available Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in : Humble, TX	S/N: 5PTBD1020J1028311 C/W: Ball Hitch, Spring Suspens	C/W: Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, Steel Decking, 225 /75R15 Tires, 7380 lb GVWR
9459	2025 Industrias America FT510 T/A Dump		Asset located in: Humble, TX
	Utility Trailer S/N: 3EZBTC102SA003919 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9466	2018 Snake River DMP610-7K HD 9 ft T/A Dump Utility Trailer S/N: 5PTBD1024J1028313 C/W: Spring Suspension, Surge Brakes, 72 in Deck Width, 72 in Overall Width, Steel Decking, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Asset located in: Humble, TX
9460	2020 Delco 10 ft T/A Dump Utility Trailer	9467	2017 Snake River DMP610-7K HD 10 ft T/A
	S/N: 5WWBD1023L6009385 C/W: 7000.0 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, 64 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX , TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Midland, TX	740/	Utility Trailer S/N: 5PTBD1021H1026514 C/W: 7380 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, 72 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: . Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9468	2017 Snake Rive Trailer DMP610-7KHD 9 ft T /A Dump Utility Trailer S/N: 5PTBD1029H1026518 C/W: 7380 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: . Asset located in: Humble, TX	9475	2025 Industrias America 167T 21 ft T/A Tilt Deck Trailer S/N: 3EZBTP229SA003875 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 16 ft Deck Tilting Length, 81 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9470	2024 Load Trailer 21000 lb 24 ft Tri/A Tilt Deck Trailer S/N: 4ZEGG2432R1297138 C/W: Torsion Axle, Electric Brakes, 17 ft 7 in Deck Tilting Length, 83 in Deck Width, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX	9476	2024 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2128RT012377 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 17 ft 6 in Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
9471	2025 Industrias America 167T 21 ft T/A Tilt Deck Trailer S/N: 3EZBTP222SA003877 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 11 in Deck Tilting Length, 82 in Deck Width, 14000 lb GVWR Usage: Not Available	9478	2011 Butler 18 ft T/A Tilt Deck Trailer S/N: 1BUD18201B1005986 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Deck Tilting Length, 82 in Deck Width, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9479	2013 Towmaster T-5DTSL Tilt Deck Trailer S/N: 4KNTT1214DL161091 Usage: Not Available Asset located in: Humble, TX
9472	2025 Industrias America 167T 22 ft T/A Tilt Deck Trailer (Unused) S/N: 3EZBTP220SA003876 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in Deck Tilting Length, 82 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9480	2022 Big Tex 25GN-40BK8SIR 40 ft T/A Gooseneck Flatbed Trailer S/N: 16V3F482XN6092414 C/W: Spring Suspension, Electric Brakes, 97 in Deck Width, 102 in Overall Width, 235/80R16 Tires, 25900 lb GVWR Usage: Not Available Asset located in: Humble, TX 2024 MP Custom 16000 lb 42 ft T/A
9473	Asset located in: Humble, TX 2021 Midsota TBWM-22 22 ft T/A Tilt Deck Trailer S/N: 5JWBS2222MA001707 C/W: Walking Beam Suspension, Electric Brakes, Winch, 18 ft Deck Tilting Length, 96 in Deck Width, 215/75R17.5 Tires, 17600 lb GVWR Usage: Not Available	9481	Gooseneck Equipment Trailer S/N: 4M9BG4024R1144358 C/W: 15900 lb GVWR, Aluminum Frame, Spring Suspension, Electric Brakes, 215/75R17.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9474	Asset located in: Humble, TX 2017 Felling Trailers 22 ft T/A Tilt Deck Trailer S/N: 5FTCE2922H2002692 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 18 ft Deck Tilting Length, 83 in Deck Width, 215/75R17.5 Tires, 19120 lb GVWR Usage: Not Available Asset located in: Humble, TX	9482B	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4025SM120810 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 5 ft Fixed Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9482A	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 5R8GF4027SM120811 C/W: Air Ride Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Electric Powered Self Contained Hydraulic System, Wood Flooring, 215/75R17.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9484	2024 RAWMAXX FDX-40-27K 40 ft T/A Gooseneck Equipment Trailer S/N: 3EVGF402XR1110864 C/W: 14000 lb GVWR, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
9482	2023 Maxey MAXX-D 14000 lb 40.5 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4020PM107096 C/W: 14000 lb GVWR, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 3 in Rear Deck, 5 ft 6 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA;	9487	2023 East 40 ft T/A Gooseneck Equipment Trailer S/N: 58SGF4024PE035546 C/W: 25000 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
	SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA	9488	2022 PJ Trailers 3F492 40 ft T/A Equipment Trailer
9483B	2024 5 Star ST-428 FB 32000 lb 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 4A93F4025RH220059 C/W: 36000 lb GVWR, Spring Suspension, Hydraulic Brakes, 40 ft Main Deck, 97.5 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/75R17.5 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX ; THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY PURCHASER	9489	S/N: 4P53F4924N1364159 C/W: 25900 lb GVWR, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2022 PJ Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 4P53F4922N1365245 C/W: 14500 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 97 in Usable
	Asset located in: Midland, TX		Deck Width, 102 in Overall Deck Width, Wood
9483A	2024 5 Star ST-428 FB 32000 lb 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 4A93F4023RH220058		Flooring, 235/75R17.5 Tires Usage: Not Available
	C/W: 36000 lb GVWR, Spring Suspension, Hydraulic Brakes, 40 ft Main Deck, 97.5 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/75R17.5 Tires Usage: Not Available Notes : LOCATED-IN-MIDLAND-TX ; THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY PURCHASER Asset located in : Midland, TX	9490	2022 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4027NM091928 C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 5 ft 8 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 25990 lb GVWR Usage: Not Available
9483	2024 PJ 40 ft T/A Gooseneck Equipment Trailer S/N: 4P53F4923R1406164 C/W: 14500 lb GVWR, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX		Notes: LOCATED-IN-MIDLAND-TX SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Midland, TX

Lot #	Details	Lot #	Details
9492	2010 PJ 40 ft T/A Gooseneck Equipment Trailer	9497A	2025 Maxey T/A Gooseneck Hydraulic Tail Trailer (Unused)
	S/N: 4P5FD4026A1148243 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 5 ft 6 in Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235 /80R16 Tires Usage: Not Available		S/N: 5R8GF3422SM120736 C/W: Spring Suspension, Electric Brakes, 22 ft Main Deck, 22 ft 2-Position Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, 40000 lb GVWR Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
9494	2025 PJ Trailers LS322 32 ft T/A Gooseneck Equipment Trailer S/N: 4P53F4128S1413399 C/W: 15680 lb GVWR, Spring Suspension, Electric Brakes, 32 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	9497	2024 Ranco G35R 35 ft T/A Gooseneck Equipment Trailer S/N: 3EZBGP353RA003331 C/W: Spring Suspension, Electric Brakes, 29 ft 10 in Main Deck, 5 ft 2-Position Dovetail, 96 in Usable Deck Width, 96 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9495	2025 Southland ETGT10-30 BT 36 ft T/A	9498	2025 Southland ETGT10-26BT 32 ft T/A
JTJU	Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9367S1113460 C/W: Spring Suspension, Electric Brakes, 30 ft Main Deck, 6 ft 2 in Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND		Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9367S1106556 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 6 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER- CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND
	TRAILER CORP		TRAILER CORP Asset located in: Humble, TX
	Asset located in: Humble, TX	9499	2025 Southland ETGT10-26BT 32 ft T/A
9496	2025 Southland ETGT10-30 BT 36 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9362S1116394 C/W: Spring Suspension, Electric Brakes, 36 ft Main Deck, 6 ft Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 9998 lb GVWR, EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP	5455	Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9363S1113455 C/W: Spring Suspension, Electric Brakes, 32 ft Main Deck, 6 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
	Asset located in: Humble, TX	0500	
9497B	2004 Ameritrail 33 ft Gooseneck Equipment Trailer S/N: 17YGN30234B028401 Usage: Not Available Asset located in: Humble, TX	9500	2025 Southland ETGT10-24 BT 30 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN8364S1117153 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 6 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235 /80R16 Tires, 25000 lb GVWR, EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9501A	Trailer (Unused) S/N: 5R8GF302XSM120859 C/W: Spring Suspension, Electric Brakes, 6 ft 10 in Upper Deck, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Electric Powered Self Contained Hydraulic System, Wood Flooring, 215/75R17.5 Tires, 30000 lb GVWR Usage: Not Available	9506	2024 Double A 24 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1UFGN2424RT012374 C/W: 14000 lb GVWR, Spring Suspension, Electric Brakes, 24 ft Main Deck, 83 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
		9507	2018 Big Tex 14GN-20BK+5MR 14000 lb 25 ft T /A Gooseneck Equipment Trailer
9501	Asset located in: Humble, TX 2025 Southland ETGT10-24 BT 30 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN8362S1117152 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 6 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood		S/N: 16VGX2025J6030122 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft 4 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
	Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER- CORP Usage: Not Available Notes : EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in : Humble, TX	9509	2009 Interstate Trailers 25 ft Tri/A Equipment Trailer S/N: 1JKDTA1849M009974 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 20 ft Main Deck, 5 ft 2-Position Dovetail, 100 in Usable Deck Width, 100 in Overail, Deck Width, Deck Over Ting, Spring
9502 2023 30 ft T S/N: 4R7GF3 C/W: 24000 Brakes, 30 ft Width, 101 ir	2023 30 ft T/A Gooseneck Equipment Trailer S/N: 4R7GF3025PN231122 C/W: 24000 lb GVWR, Torsion Axle, Electric Brakes, 30 ft Main Deck, 96 in Usable Deck Width, 101 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires		Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Electric Powered Self Contained Hydraulic System, Steel Decking, 245 /75R16 Tires, 33000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9510	2023 Econoline 20000 lb 30 ft T/A Equipment Trailer S/N: 42EDPRK23P1000294 C/W: 25500 lb GVWR, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 23 ft 9 in Main Deck, 5 ft 9 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
9503	 3 2024 Double A 26 ft T/A Gooseneck Equipment Trailer S/N: 1UFGN2627RT012379 C/W: Spring Suspension, Electric Brakes, 23 ft Main Deck, 3 ft Fixed Dovetail, 81 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX 5 2012 Big Tex 20000 lb 25 ft T/A Gooseneck Equipment Trailer S/N: 16VGX252XC2646286 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 102 in Usable Deck Width, 106 in Overall Deck Width, Deck Over Tires, Wood 		
		9511C	2016 Buler 23 ft T/A Equipment Trailer S/N: 1BUD23201G1008281
9505			C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 19 ft Main Deck, 4 ft Fixed Dovetail, 80 in Usable Deck Width, 80 in Overall Deck Width, Spring Assisted Ramps, Steel Decking, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Humble, TX
		9511B	2020 Novae ST923IT2API5-B-259 23 ft T/A Equipment Trailer S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 7 ft 6 in Upper Deck, 12 ft 4 in Main Deck, 3 ft 6 in Fixed Dovetail, 79 in Usable Deck Width, 79 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9511A	2014 Kaufman 24 ft T/A Equipment Trailer S/N: 5VGFH2523EL002177 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 19 ft 10 in Main Deck, 5 ft 2- Position Dovetail, 96 in Usable Deck Width, 96 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX	9515	2025 Southland LBAT7-24 23 ft T/A Equipment Trailer (Unused) S/N: 2SFJL5360S1117517 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 23 ft Main Deck, Wood Flooring, 235 /80R16 Tires, 15432 lb GVWR, EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
9511	2017 Interstate Trailers 24 ft T/A Equipment Trailer		Asset located in: Humble, TX
	S/N: 1JK0DT206HM015578 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 19 ft 9 in Main Deck, 5 ft 1 in 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25900 lb GVWR Usage: Not Available	9516A	2023 Maxey Maxx-D T/A Car Carrier Trailer S/N: 5R8BC2226PM106863 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 9990 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	Asset located in: Humble, TX	9516	2005 Shopmade 23 ft T/A Equipment Trailer
9512	1989 Interstate 20 ft T/A Equipment Trailer S/N: 1JKDAS320KA600511 C/W: Lunette Ring Hitch, Spring Suspension, 20 ft Main Deck, 6 ft Fixed Dovetail, 96 in Usable Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available	-	S/N: TR193769 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 19 ft Main Deck, 4 ft Fixed Dovetail, 96 in Usable Deck Width, 96 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, winch assisted ramps Usage: Not Available Notes: TITLE IS BRANED BOND TITLE Asset located in: Humble, TX
	Asset located in: Humble, TX	9517	2025 Southland LBAT7-20 19 ft T/A Equipment
9513	2012 Pro Pull 14 ft T/A Equipment Trailer S/N: 5WJUT1422CL00030 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 14 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Humble, TX		Trailer (Unused) S/N: 2SFJL4365S1117510 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 15432 lb GVWR, EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND
9514	2010 Mcelrath 12 ft T/A Equipment Trailer	1	TRAILER CORP
9515A	S/N: 1M9FE1224AS284977 C/W: Lunette Ring Hitch, Spring Suspension, 12 ft Main Deck, Manual Ramps, 215/75R17.5 Tires, 18000 lb GVWR Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2025 24 ft T/A Equipment Trailer (Unused)	9518	Asset located in: Humble, TX 2024 Double A 20 ft T/A Equipment Trailer (Unused) S/N: 1UFBU2022RT012375 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 20 ft Main Deck, 83 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires Usage: Not Available
	S/N: 5R8BC2422SM120863 C/W: Ball Hitch, Torsion Axle, Electric Brakes,		Asset located in: Humble, TX
	24 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/75R17.5 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9519	2024 Double A 20 ft T/A Equipment Trailer S/N: 1UFBU2026RT012380 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9520	2024 Double A 7000 lb 20 ft T/A Equipment Trailer S/N: 1UFBU202XRT012382 C/W: Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 82 in Usable Deck Width, 83 in Overall Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9525	2019 Pratt 14 ft T/A Equipment Trailer S/N: 1P9UT2120KN343276 C/W: 12000 lb GVWR, Ball Hitch, Torsion Axle, Surge Brakes, 70 in Usable Deck Width, 73.5 in Overall Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA
9521B	2015 Pike 33Q 16 ft T/A Equipment Trailer S/N: 1P9PF2520FM435465 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 14 ft 10 in Main Deck, 1 ft 10 in Fixed Dovetail, 75 in Usable Deck Width, 98 in Overall Deck Width, Manual Ramps, Steel Decking, 215 /75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9526	2019 MMDI 14 ft T/A Equipment Trailer S/N: 5631F2024KM001914 C/W: Ball Hitch, Torsion Axle, Surge Brakes, 14 ft Main Deck, 70 in Usable Deck Width, 70 in Overall Deck Width, Spring Assisted Ramps, Steel Decking, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Asset located in: Humble, TX 2021 MMDI E47H 7 ft S/A Equipment Trailer
9521A	2021 Delco 18 ft T/A Equipment Trailer S/N: 5WWBC1824M6018587 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 16 ft Main Deck, 2 ft Fixed Dovetail, 83 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires, 14000 lb GVWR		S/N: 5631F1418MM000960 C/W: 4400 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 49 in Usable Deck Width, 52 in Overall Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX
9521	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2024 Contract Manufacturing	9528	2024 Double A 20 ft T/A Utility Trailer (Unused S/N: 1UFBU2024RT012376 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 102 in Overall Width, Ramp, Wood Flooring, 23 /80R16 Tires
	TH7020BK4AR2B 20 ft T/A Equipment Trailer (Unused) S/N: 7RD1U2420R2320077 C/W: Ball Hitch, Spring Suspension, Wood Flooring, 205/75R15 Tires Usage: Not Available Asset located in: Humble, TX	9529	Usage: Not Available Asset located in: Humble, TX 2024 Double A 8320T7K 20 ft T/A Utility Trailer (Unused) S/N: 1UFBU2028RT012381 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Dack Width, 8 in Overall Width
9522	2024 Double A 7000 lb 12 ft S/A Equipment Trailer S/N: 1UFBU1213RT012383 C/W: Spring Suspension, 12 ft Main Deck, 77 in Usable Deck Width, 79 in Overall Deck Width, 235/80R16 Tires, 7000 lb GVWR	9530A 9530	Brakes, 72 in Deck Width, 8 in Overall Width, Ramp, Wood Flooring, 235/80R16 Tires, 14000 Ib GVWR Usage: Not Available Asset located in: Humble, TX 1999 Trailmaster 20 ft T/A Utility Trailer
9523	235/ 80K10 Tifes, 7000 ib GVWK Usage: Not Available Asset located in: Humble, TX 2019 MMDI 14 ft T/A Equipment Trailer S/N: 5631F2026KM001915 C/W: 9990 lb GVWR, Ball Hitch, Spring		S/N: 5BEBU2026XC112015 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Suspension, 14 ft Main Deck, 70 in Usable Deck Width, Manual Ramps, 225/75R15 Tires Usage: Not Available Notes: . Asset located in: Humble, TX		Asset located in: Humble, TX 2013 Ameritrail 20 ft T/A Utility Trailer S/N: 29DB053351 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires,
9524	2019 MMDI 14 ft T/A Equipment Trailer S/N: 5631F2028KM001852 C/W: 9990 lb GVWR, Ball Hitch, Spring Suspension, 14 ft Main Deck, 70 in Usable Deck Width, Manual Ramps, 225/75R15 Tires Usage: Not Available Notes: . Asset located in: Humble, TX		14000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9531 9532	2024 Double A 18 ft T/A Utility Trailer (Unused) S/N: 1UFBU182XRT012378 C/W: 9995 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Wood Flooring, 225 /75R15 Tires Usage: Not Available Asset located in: Humble, TX 2024 CM Trailers 76X16 16 ft T/A Utility Trailer	9538	2023 American Pride T/A 3 Car Open Car Carrier Trailer S/N: 4A93A4826PH220152 C/W: Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX 2020 Shipse T/A 4 Car Open Car Carrier Trailer
	S/N: 5VNBU1620RT253191 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 76 in Deck Width, 76 in Overall Width, Wood Flooring, 205/75R15 Tires, 4400 lb GVWR		S/N: 4S95F532XLS452129 C/W: Torsion Axle, Surge Brakes, Soft Ties, 245 /70R17.5 Tires, 12000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9544	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1929HA988357 C/W: Galvanized Frame Ball Hitch, Torsion
9533	2020 Longhorn 16 ft T/A Utility Trailer S/N: 5J2US1629LE023631 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available	-	Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX
	Asset located in: Humble, TX	9546	2017 Demco AT7000P T/A 1 Car Open Car
9534 9535	2017 Top Hat 16 ft T/A Utility Trailer S/N: 4R7BU1625HT167477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 205 /75R15 Tires, 6000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2025 Salvation 16 ft T/A Utility Trailer (Unused) S/N: 7GG1U1628SW023464 C/W: Ball Hitch, Spring Suspension, Electric	-	Carrier Trailer S/N: 15DPC1926HA988607 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX
	Brakes, 82 in Deck Width, 102 in Overall Width,	9549	2017 Demco AT7000P T/A 1 Car Open Car
	Wood Flooring, 205/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9549	Carrier Trailer S/N: 15DPC1927HA988535 C/W: Galvanized Frame Ball Hitch, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: . ; SELLER SUPPLIED MAINTENANCE
9536	S/N: 5E0AJ1444BG327001 C/W: Air Ride Suspension, Soft Ties, 265		RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX
Usage: No	/70R19.5 Tires, 45000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9551	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer
9537	2020 Texas Pride CA85335KGN Tri/A 6 Car Open Car Carrier Trailer S/N: 7HCGC5338LB018604 C/W: Spring Suspension, Chain Tie Downs, 235 /75R17.5 Tires, 48000 lb GVWR, Winch, Rear Hydraulic Ramp Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: 15DPC1929HA988326 C/W: Torsion Axle, Surge Brakes, Soft Ties, 225 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes : ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9553C	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988635 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9557	2015 T/A (1) Reel Trailer S/N: 4C9BS1628FW382017 C/W: 2014 US EPA Label, Honda 2 Cylinder Gasoline Engine, Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
	TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9558	2011 Butler S/A (1) Reel Trailer S/N: 1BUC1010XB1006035 C/W: Honda 2 Cylinder Gasoline Engine,
9553B	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988439 C/W: Galvanized Frame Ball Hitch, Torsion		Lunette Ring Hitch, Spring Suspension, Air Brakes, 235/75R17.5 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9559	2011 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK16N5B1000040 C/W: Electric Brakes, Hydraulic Reel Hoist, 12- 16.5 Tires, 7500 lb GVWR
9553A	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA988602 C/W: Galvanized Frame Ball Hitch, Torsion		Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9561	2010 Sauber 1506-NS S/A (1) Reel Trailer S/N: 1F9UZ0912AV048139 C/W: Galvanized Frame Lunette Ring Hitch, Torsion Axle, Electric Brakes, 175/80 R13
9553	2017 Dethmers AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1924HA988816		Tires, 2550 lb GVWR Usage: Not Available Asset located in : Humble, TX
	C/W: Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	9562	2003 White S/A (1) Reel Trailer S/N: FT29 C/W: Lunette Ring Hitch, Electric Brakes, 12- 16.5 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX
9554	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC192XHA988982 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9563	T/A (1) Reel Trailer S/N: TR203175 C/W: 2008 US EPA Label, Honda GX620 2 Cylinder Gasoline Engine, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
9555A	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1924HA989030 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX	-9564	2023 Stealthcargo 24 ft T/A Enclosed Trailer S/N: 5WFBC2421PT000503 C/W: Ball Hitch, Electric Brakes, 95 in Deck Width, 100 in Overall Width, Ramp, Side Door 225/75R15 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9556	2015 Demco T/A 1 Car Open Car Carrier Trailer S/N: 15DP19204FA987594 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 215/75R14 Tires Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9565	2023 T-Rex V8524D5K 24 ft T/A Enclosed Trailer S/N: 4T9BE2425PH367241 C/W: 9990 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 99 in Overall Width, Side Door 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX ; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Lake Worth, TX	9571	2018 ATC World Class Trailer QSTSB8522+42T5.2K 21 ft T/A Enclosed Trailer S/N: 5JX2C2629JD213033 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225 /75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9566	1998 Featherlite 24 ft T/A Enclosed Trailer		Asset located in: Midland, TX
	S/N: Not Available C/W: Ball Hitch, Torsion Axle, Electric Brakes, 92 in Overall Width, Ramp, Side Door Aluminum Wheels, 225/75R15 Tires Usage: Not Available Asset located in : Humble, TX	9572	2014 ATC World Class Trailer QSTSB8522+42T6.0K 21 ft T/A Enclosed Trailer S/N: 5JXJE2622EE197408 C/W: Aluminum/Steel Combination Frame, Ball
9567	2024 Spartan 22 ft T/A Enclosed Trailer S/N: 50XBE2022RA041313 C/W: 9990 lb GVWR, Ball Hitch, Torsion Axle, Electric Brakes, 95 in Deck Width, Ramp, Side Door 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX		Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 235 /80R16 Tires, 13200 lb GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
9568	2018 ATC World Class Trailer 21 ft T/A	9573	2025 Southland LARCT52-820F-86 20 ft T/A
	Enclosed Trailer S/N: 5JX2C2629JD213307 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225 /75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		Enclosed Trailer (Unused) S/N: 2SFFK4319S1108418 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
9569	2018 ATC World Class Trailer 21 ft T/A		Asset located in: Humble, TX
	Enclosed Trailer S/N: 5JX2C2622JD213309 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225 /75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	9574	2025 Southland LARCT52-822V-86 20 ft T/A Enclosed Trailer (Unused) S/N: 2SFPK4314S1112686 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 98 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND
9570	2018 ATC World Class Trailer		TRAILER CORP Asset located in: Humble, TX
	QSTSB8522+42T5.2K 21 ft T/A Enclosed Trailer S/N: 5JX2C2620JD213311 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225 /75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	9575A	Asset located In: Humble, TX 2022 Pace American 20 ft T/A Enclosed Trailer S/N: 53BPTEB20NR007391 C/W: Walking Beam Suspension, Electric Brakes, 94 in Deck Width, 96 in Overall Width, 225/75R15 Tires, 9900 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9575	2025 Southland LARCT52-822V-86 20 ft T/A Enclosed Trailer (Unused) S/N: 2SFPK4313S1117202 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 96 in Overall Width, Side Door 225/75R15 Tires, 11464 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER- CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9580	2012 Royal Cargo XRARCT60-8526-78 19 ft T /A Enclosed Trailer S/N: 2S9PK5310C3026709 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 235 /80R16 Tires, 6000 kg GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
9576	2021 W-W 20 ft T/A Enclosed Trailer S/N: 11W3C2025MW321313 C/W: 12000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 94 in Deck Width, 102 in Overall Width, Side Door 235/80R16 Tires, with contents Usage: Not Available Asset located in: Humble, TX 2010 Haulmark 20 ft T/A Enclosed Trailer	9581	2012 Royal Cargo XRARCT60-8526-78 19 ft T /A Enclosed Trailer S/N: 2S9PK5314C3026714 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door Aluminum Wheels, 235/80R16 Tires, 6000 kg GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX
5077	S/N: 16HGB2021AH181920 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 95 in Deck Width, Side Door 225/75R15 Tires,		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
10000 lb GVWR, Interior I Usage: Not Available Notes : TEXAS BUYERS N TO SIGN REQUIRED DOC	10000 lb GVWR, Interior Racking Usage: Not Available Notes : TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in : Humble, TX	9583	2025 Southland LCHT35-718V-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH3312S1118250 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 96 in Overall Width,
9578	 2025 Southland LARCT52-822V-86 19 ft T/A Enclosed Trailer (Unused) S/N: 2SFPK4314S1117564 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR, ; EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX 2012 Royal Cargo 19 ft T/A Enclosed Trailer S/N: 2S9PK5312C3026128 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 235 /80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX 		Side Door 205/75R15 Tires, 7815 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER- CORP Usage: Not Available Notes : EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in : Humble, TX
9579		9584	2025 Southland LCHT35-718V-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH3315S1116993 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 79 in Overall Width, Ramp, Side Door 205/75R15 Tires, 7815 lb GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9585	2025 Southland LCHT35-718V-86R 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH3318S1107981 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 79 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 7716 lb GVWR, ; EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9586	2023 Quality Cargo 16 ft T/A Enclosed Trailer S/N: 50ZBE1168PP040468 C/W: 7000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 84 in Overall Width, Ramp, Side Door 205 /75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE	9595A 9595	2018 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHULE420JY077081 C/W: 7000 lb GVWR, Spring Suspension, Electric Brakes, 78 in Deck Width, 78 in Overall Width, 205/75R15 Tires, Bumper Pull with Plywood Decking and Walls. Wooden Shelving. Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Cargo Mate 14 ft T/A Enclosed Trailer
	THE INSPECTION REPORT		S/N: 5NHULE426JY078137 C/W: Spring Suspension, Electric Brakes, 78 in
9587	S/N: 53BPTEA16PR011070 C/W: Ball Hitch, Spring Suspension, Electric		Deck Width, Ramp, Side Door 205/75R15 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Brakes, 66 in Deck Width, 66 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 2990 lb GVWR Usage: Not Available Asset located in : Humble, TX	9596	2015 Haulmark 14 ft T/A Enclosed Trailer S/N: 575PB1427FT276449 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 225/75R15 Tires, 10000 lb GVWR,
9590	2 007 Contract 16 ft T/A Enclosed Trailer S/N: 49TCB162171088037 C/W: Ball Hitch, Torsion Axle, Electric Brakes, '2 in Deck Width, 102 in Overall Width, Ramp,		Storage Boxes, Roof A/C Usage: Not Available Asset located in: Humble, TX
	225/75R15 Tires, 8600 lb GVWR Usage: Not Available Asset located in: Humble, TX	9597	2015 Haulmark 14 ft T/A Enclosed Trailer S/N: 575PB1425FT293931 C/W: Torsion Axle, Electric Brakes, 81 in Deck
9592			Width, 86 in Overall Width, 225/75R15 Tires, 10000 lb GVWR Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
		9598	2014 Haulmark 14 ft T/A Enclosed Trailer S/N: 575PB1425ET259955 C/W: Torsion Axle, Electric Brakes, Ringfeder, 81 in Deck Width, 86 in Overall Width, 205
9593	2023 Quality Cargo T/A Enclosed Trailer S/N: 50ZBE1428PP044822 C/W: 7000 lb GVWR, Spring Suspension, Electric Brakes, Ramp, 205/75R15 Tires Usage: Not Available		/75R15 Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Asset located in: Humble, TX	9599	2014 Haulmark 14 ft T/A Enclosed Trailer
9594	2020 Forest River 14 ft T/A Enclosed Trailer S/N: 5NHUCC420LY035601 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, Storage Boxes, Windows Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: 575PB1422ET259959 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 225/75R15 Tires, 10000 lb GVWR, Storage Boxes, Counter Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	THE INSPECTION REPORT	9600	2012 Haulmark 14 ft T/A Enclosed Trailer
9595B	Asset located in: Humble, TX 2016 Lark United MFG VT6X14SA 14 ft S/A Enclosed Trailer S/N: 571BE1417GM017644 C/W: 5200 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, Ramp, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX		S/N: 5NHUCC422CY018340 C/W: Torsion Axle, Electric Brakes, 81 in Deck Width, 86 in Overall Width, 235/75R15 Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9601 9602	2012 Forest River 14 ft T/A Enclosed Trailer S/N: 5NHUCC422CY014961 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 82 in Overall Width, Side Door 205/75R15 Tires, Job Site Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Continental 14 ft T/A Enclosed Trailer	9610	2025 Southland LCHS29-614V-72 11 ft S/A Enclosed Trailer (Unused) S/N: 2SFAL2260S1109661 C/W: Ball Hitch, Spring Suspension, 69 in Deck Width, 69 in Overall Width, Side Door 205 /75R14 Tires, 2996 lb GVWR, EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9603	S/N: 5NHUCC426CY014963 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, Storage boxes, Counter Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Cargo Mate 14 ft Enclosed Trailor		2018 Speed-Lift MDL6000BAFR T/A Trailer Mounted Loading Dock S/N: 4S9AFEKD8J1440100 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 225/75R15 Tires, 6,000 Lb capacity, Hatz 1B50 diesel, removable hitch Usage: 4 Hr Asset located in: Humble, TX
9603	2012 Cargo Mate 14 ft Enclosed Trailer S/N: 5NHUCC422CY016340 Usage: Not Available Asset located in: Humble, TX 2008 Cargo Mate 14 ft T/A Enclosed Trailer	9613A 9613	2013 MGT Remolque Quad/A Tank Transport Trailer S/N: 3A9SV4023DM216161 C/W: Torsion Axle, 235/80R16 Tires, 28000 lb GVWR
	S/N: 5NHUCM4248Y056836 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 67 in Deck Width, 67 in Overall Width, 205 /75R15 Tires, Storage boxes, Cabinets, Shelves Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX 2012 Scheuerle SPGV10094 3X3X3 Modular Trailer S/N: W09970XX8CPS17432 C/W: 256000 lb Trailer Capacity, 102 in Usable Deck Width, 102 in Overall Trailer Width, 69 ft
9605	2008 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHUCM42X8Y057571 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 82 in Overall Width, Side Door 205/75R15 Tires, Job Site Box Usage: Not Available		10 in Main Deck, Self-Contained Power Unit, 245/70R17.5 Tires, 256000 lb GVWR, 9 Steerable Hydraulic Lift Axles, Hydraulic Power Unit, Fifth Wheel Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9614	2008 Benlee TA3S8D48 T/A 48 ft Crushed Ca Trailer S/N: 1B9G348268B180496
9606	2005 Pace 14 ft T/A Enclosed Trailer S/N: 47ZUB14215X037834 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR,	9615	C/W: Air Ride Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX
	Paneling on walls, storage boxes, Roof A/C Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		2008 Benlee TA3S8D48 T/A 48 ft Scrap Car Trailer S/N: 1B9G348288B180497 C/W: Air Ride Suspension, 11R22.5 Tires, 22680 lb GVWR
9607	2008 Wells Cargo Trailers - Haul 13 ft T/A Enclosed Trailer S/N: 1W4200F2282063627 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 77 in Deck Width, 77 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, Steel Shelving Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX TITLE BRAND BOND TITLE Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9616	2004 Benlee TA3S8D45 T/A 45 ft Scrap Car Trailer S/N: 1B9G345254B180407 C/W: Air Ride Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE	9625	2007 Custom Built BBQ Pit Trailer S/N: 021607 C/W: Spring Suspension, Electric Brakes, 205 /75R14 Tires, 2 Barbecue Pits, 3 Tool Boxes, 4 Speakers, 1 Sink, 1 Propane Tank Holder, 2 Propane Burners Usage: Not Available Asset located in: Humble, TX
	INSPECTION REPORT Asset located in: Lake Worth, TX	9626B	Concession Caddy S/N: Not Available
9617	1993 Killebrew T/A Side Dump Fertilizer Trailer S/N: 1K0HD2365PA079042 C/W: Spring Suspension, 11R22.5 Tires, (4) Hoppers Usage: Not Available Asset located in : Humble, TX		C/W: Cooler, Storage Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
9618	1993 Killebrew T/A Side Dump Fertilizer Trailer S/N: 1K0HD2368PA079049 C/W: Spring Suspension, 11R22.5 Tires, (4) Hoppers Usage: Not Available	9626A	Concession Caddy S/N: Not Available C/W: Cooler, Storage Usage: Not Available Asset located in: Humble, TX
Asset locate 9619 2023 Sundor Gooseneck I S/N: 13SCG3 C/W: Alumin Brakes, 6 Ho Conditioner, Tires, 9990 I Four side do way rear doo Usage: Not A Asset locate	Asset located in: Humble, TX 2023 Sundowner Cargo 22GN 30 ft T/A Gooseneck Horse Trailer S/N: 13SCG3024P1CA4923 C/W: Aluminum Frame, Torsion Axle, Electric Brakes, 6 Horse, 46 in Stall Width, Air Conditioner, Aluminum Wheels, 235/80R16	9628	2016 Alkota HZ535DKS Pressure Washer S/N: 1A9BU1626GA520062 C/W: Water Heater, 325 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kubota D902 3 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX 2020 Northstar Mobile Pressure Washer
	Tires, 9990 lb GVWR, Rubber pads on floor, Four side doors, storage over gooseneck. Two way rear door Usage: Not Available Asset located in : Humble, TX	9630	S/N: 4K1PT4C11LK008613 C/W: 4000 psi Rating, Water Heater, 200 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda GX630 2 Cylinder Gasoline Engine
9620	2023 Crazy Monkey T/A Food Vending Trailer (Unused) S/N: 3J9A12185PM095667 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, A/C, Outside Water/Sink, Storage Racks, Wash, Drago Range with 2 Burners, 36" Griddle with Deep Fryer, (2) Storage Boxes, Vent Hood Usage: Not Available Asset located in: Humble, TX		Usage: 237 Hr Asset located in: Humble, TX
			2020 Northstar Mobile Pressure Washer S/N: 4K1BP162XLF002318 C/W: 4000 psi Rating, Water Heater, 525 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler 2 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
9621	2023 Crazy Monkey T/A Food Vending Trailer (Unused)	9631	2018 Mi-T-M HS-3505-1MGH-T Pressure Washer
	S/N: 3J9A12185PM095717 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, Outside Water/Sink, Avantco Range with 36" Griddle, (2) Drago Burners, Drago Deep Fryer, (3) Storage Boxes, Vent Hood, A/C Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: 3500 psi Rating, Water Heater, 200 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda GX630 2 Cylinder Gasoline Engine Usage: 428 Hr Asset located in: Humble, TX
0600		9632	2017 WPM T/A Hydro Blast Trailer S/N: 1WP12K15BP1700090
9622	2023 Crazy Monkey T/A 16 ft Concessions Trailer S/N: 3J9A12166PM095921 C/W: 8400 lb GVWR, Spring Suspension, 7.00- 15 Tires Usage: Not Available		C/W: Ball Hitch, Torsion Axle, Electric Brakes, Aluminum Outer Wheels, 235/80R16 Tires, (1) Diesel Tank, (1) Hydraulic Tank, (1) Liquid Tank. Usage: Not Available Notes : . DEFICIENCIES NOTED - PLEASE SEE
	Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9633	2010 Trane TCH300E400BB Trailer Mounted Air Conditioner S/N: 1020104540 C/W: 15 ft T/A Utility Trailer, Ball Hitch, Spring Suspension, 235/75R15, Usage: Not Available Asset located in: Humble, TX	9638	2018 John Deere 331G Compact Track Loader (Inoperable) S/N: 1T0331GKKJF331353 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE	
9634	2011 Parker 16 FT T/A Portable Cooling Station S/N: 13ZLS1621B1004572 C/W: (2) Tanks, Benches, Ball Hitch, Usage: Not Available		RECONSIGNED; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9639	2014 Bobcat T770 Compact Track Loader (Inoperable)	
9635	2011 Parker 16 FT T/A Portable Cooling Station S/N: 13ZLS1621B1005009 C/W: (1) Tank, Benches, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: AN8T13810 C/W: Open Operator Station, Manual O Usage: 972 Hr Notes : THIS INOPERABLE ITEM NEED REMOVED FROM THE YARD AND CAN RECONSIGNED DEFICIENCIES NOTED PLEASE SEE THE INSPECTION REPOR	C/W: Open Operator Station, Manual Coupler
9636	Tric Pipe Breaker Plumbing Supplies	0640P	2013 Takeuchi TL230 Compact Track Loader	
9637A	S/N: Not Available C/W: SPX Power Unit, Cable, Ridgid 2048 Job Side Box, 9 Ft S/A Trailer Usage: Not Available Asset located in: Humble, TX 2024 Cat 255 Two-Speed Compact Track	9640B	(Inoperable) S/N: 223102012 C/W: Enclosed Cab (Door missing), Air Conditioner, Air Ride Seat, US EPA Label, 12 in Track Belts, Manual Coupler Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	
	Loader (Inoperable) S/N: CAT00255CFL702984		THE INSPECTION REPORT	
	C/W: Enclosed Cab, 16 in Track Belts, Hydraulic Coupler Usage: Not Available Notes : NO WARRANTY AVAILABLE; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9640A	(Inoperable) S/N: JAFTR310TJM449154 C/W: Enclosed Cab (Door missing), Joystick Steering, 2018 US EPA Label, Requires Diese Exhaust Fluid, 13 in Track Belts, Manual	
9637	2024 Cat 299D3XE Two-Speed Compact Track Loader (Inoperable) S/N: CAT299D3CB6203268 C/W: Enclosed Cab, Air Ride Seat, 2024 US EDA Lobel Dequired Discol Exhaust Eluid 18 in	9640	Coupler Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	
	EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Notes: NO WARRANTY AVAILABLE ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		9640	2014 Bobcat T770 Compact Track Loader (Inoperable) S/N: AN8T13291 C/W: Open Operator Station, 17.5 in Track Belts, Manual Coupler Usage: Not Available
9638A	2020 Cat 289D3 Compact Track Loader S/N: CAT0289DKJX901425 C/W: Open Operator Station, Joystick Steering, 2019 US EPA Label, 14 in Track Belts, Manual Coupler, 72 in Bucket, Forks Usage: 2,799 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9641A 9641	2015 Bobcat T590 Compact Track Loader (Inoperable) S/N: ALJU15750 C/W: Open Operator Station, 2015 US EPA Label, Manual Coupler Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Bobcat T750 Compact Track Loader	9646	2011 Bobcat T190 Compact Track Loader (Inoperable) S/N: A3LN37970 C/W: Open Operator Station, 13 in Track Belts, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	(Inoperable) S/N: ATF612569	9647	2008 Bobcat T190 Compact Track Loader
	S/N: ATF6T2569 C/W: Open Operator Station, Manual Coupler Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		(Inoperable) S/N: A3LN12021 C/W: Open Operator Station Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9642	2014 Bobcat T590 Compact Track Loader		Asset located in: Humble, TX
9643	(Inoperable) S/N: ALJU11052 C/W: Open Operator Station, 2014 US EPA Label Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Bobcat T590 Compact Track Loader (Inoperable) S/N: A3NR12009 C/W: Open Operator Station, 7 Pin Electric Kit, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE	9648 9649	2008 Bobcat T190 Compact Track Loader (Inoperable) S/N: 531621127 C/W: Open Operator Station, 13 in Track Belts, Manual Coupler Usage: 3,506 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2005 Bobcat T190 Compact Track Loader (Inoperable) S/N: 527715476 C/W: Open Operator Station, 2004 US EPA Label
9645	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2005 Bobcat T250 Compact Track Loader	-	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	(Inoperable) S/N: 525612769 C/W: Open Operator Station, 17.5 in Track Belts, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9650	2002 Bobcat S250 Skid Steer Loader (Inoperable) S/N: 520711801 C/W: Open Operator Station, Manual Coupler, 62 in Bucket, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
		9651	John Deere 240 Skid Steer Loader (Inoperable) S/N: Not Available C/W: Open Operator Station, Aperture Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9653	Case 4230 2WD Tractor (Inoperable) S/N: 4230RXLJJE0916788 C/W: Enclosed Cab, Differential Lock, 8 Forward 4 Reverse, Synchro Mesh, Case IH 2255 Loader, 2 Rear Remotes, 540/1000 PTO, 10.00-16SL Front Tires, 18.4x30 Rear Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9655	2013 John Deere 544 K Wheel Loader (Inoperable) S/N: 1DW544KZHDE652302 C/W: Enclosed Cab, Air Conditioner, Ride Control, Manual Coupler, 20.5R25 Tires Usage: 17,716 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9656	1997 Volvo L90C Wheel Loader (Inoperable)
9654C	JCB 1CXT Tracked Backhoe Loader (Inoperable) S/N: JCB1CXT4CM2935203 C/W: Enclosed Cab, Air Conditioner, Manual Coupler, 71 in Loader Bucket, Side Shift, Quick Coupler, 24 in Backhoe Digging Bucket Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: L90CV62485 C/W: Enclosed Cab, Air Ride Seat, Hydraulic Coupler, 100 in Bucket, 20.5x25 Aperture Tires Usage: 3,558 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-FORT-WORTH-TX, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9654B	2005 Case 580M Series 2 4x4 Backhoe Loader		Asset located in: Lake Worth, TX
	(Inoperable) S/N: N4C382735 C/W: Open Operator Station, 82 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 4,724 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9657A	2018 Cat 966M Wheel Loader (Inoperable) S/N: CAT0966MHKJP02683 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Requires Diesel Exhaust Fluid, Pipe Grapple, 26.5-25 Tires Usage: 7,497 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9654A	Kubota M59 4x4 Backhoe Loader (Inoperable)		Asset located in: Humble, TX
	S/N: Not Available C/W: Open Operator Station, 12 in Loader Bucket, Thumb Bracket Usage: Not Available Notes : INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in : Lake Worth, TX	9657	1987 Cat 950 E Wheel Loader (Inoperable) S/N: 63R06348 C/W: Enclosed Cab, Forks, 23.5R25 Tires Usage: 19,359 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION
9654	2015 Cat 420F2IT 4x4 Backhoe Loader		REPORT
	(Inoperable) S/N: CAT0420ECHWD00276		Asset located in: Humble, TX
	S/N: CAT0420FCHWD00276 C/W: Open Operator Station, Backhoe Pilot Controls, Auxiliary Hydraulics, Hydraulic Coupler, Forks, Quick Coupler, 14 in Backhoe Digging Bucket, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9658A	2019 Cat D6 LGP Crawler Dozer (Inoperable) S/N: CAT000D6PKEW00309 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 158 in Wide Semi-U Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, SystemOne Undercarriage, Drawbar, Rear Auxiliary Hydraulics Usage: 4,998 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT ; LOT CAN BE BLAST & PAINTED FOR \$8,700.00 Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9658	2012 Komatsu D375A-6 Crawler Dozer (Inoperable) S/N: 60183 C/W: Enclosed Cab, Air Conditioner, Fire Suppression System, Auto Lube, 264 in Wide Semi-U Blade 28 in Single Grouser Track Shoes, Counterweight Usage: 22,174 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-HOUSTON-TX- HOU; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9662A 9662	1983 Ingersoll Rand SP-48 Smooth Drum Compactor S/N: 5525-S C/W: Open Operator Station, Swivel Operator Controls, Detroit Diesel Engine, 66 in Drum Usage: 551 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1999 Ingersoll Rand SD70D Smooth Drum Compactor (Inoperable) S/N: 156240 C/W: Open Operator Station, 2019 US EPA Label, Cummins 4B 4 Cylinder 95 hp Diesel
9659A	2020 Komatsu D51PX-24 Crawler Dozer (Inoperable) S/N: KMT0D133KKA010815 C/W: Enclosed Cab, Air Conditioner, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 132 in Wide PAT Blade, 28.5 in Single Grouser Track Shoes, Drawbar Usage: 8,255 Hr	9663	Engine, 66 in Drum Usage: 2,320 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Wacker Neuson RD12A Double Drum
	Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Roller (Inoperable) S/N: 20261415 C/W: Open Operator Station, 2014 US EPA Label, Honda Gasoline Engine, 34.5 in Compaction Width
9659	2008 Cat D6T XL Crawler Dozer (Inoperable) S/N: CAT00D6TPLAY00819 C/W: Enclosed Cab, Air Conditioner, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Counterweight, Drawbar		Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9664	Gradall GW362G3WD 4x2 Highway Wheeled Excavator (Inoperable) S/N: G01D710 C/W: 6 Speed Automatic Transmission, 3911.3 hrs Carrier Engine, Cummins B5.9 6 Cylinder 5.9 L Diesel Carrier Engine, Manual Quick Coupler, 60 in Cleanup Bucket Usage: 3,911 Hr
9660	1988 Ingersoll Rand SPF48 Padfoot Drum Compactor (Inoperable) S/N: 6353P C/W: Open Operator Station, Cummins 4 Cylinder Diesel Engine, 68 in Drum Usage: 3,144 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL	9665A	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-HOUSTON-TX- HOU, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2011 Yanmar ViO55-5B Tracked Excavator (Inoperable) S/N: YMRVIO55P9YY53653 C/W: Air Conditioner, 2009 US EPA Label, Swing Boom, 5 ft 7 in Stick, Backfill Blade, 16 in
9661	2014 Bomag BW124 Smooth Drum Compactor (Inoperable) S/N: 861832121166 C/W: Deutz D 2011 L031 3 Cylinder Diesel Engine, 48 in Drum Usage: 628 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Triple Grouser Track Shoes, 29 in Digging Bucket, Hydraulic Thumb Usage: 960 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9665	2004 Case CX460 Tracked Excavator (Inoperable) S/N: DAC461152 C/W: 13 ft 2 in Stick, 35 in Triple Grouser Track Shoes, 72 in Digging Bucket, Thumb Bracket Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	9668	2007 Vermeer RT350 4x4 Trencher (Inoperable) S/N: 1VRZ0826971000347 C/W: 3 Cylinder Diesel Engine, Hydrostatic Drive, 5 in Wide x 48 in Long Dirt Trencher Chain, Angle Blade Usage: 1,340 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	
	REPORT Asset located in: Humble, TX	9669	2006 Vermeer RT350 4x4 Trencher (Inoperable) S/N: 1VRZ0826161000227	
9666	2024 AGT QS12R Mini Excavator (Inoperable) S/N: 2402075082 C/W: 2 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 6 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: 165 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE	-	C/W: 3 Cylinder Diesel Engine, Hydr Drive, 3 in Wide x 60 in Long Dirt Tro Chain, Angle Blade Usage: 661 Hr Notes : THIS INOPERABLE ITEM NE REMOVED FROM THE YARD AND C RECONSIGNED	C/W: 3 Cylinder Diesel Engine, Hydrostatic Drive, 3 in Wide x 60 in Long Dirt Trencher Chain, Angle Blade Usage: 661 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	9671	2015 JCB 512-56 Telehandler (Inoperable)	
9667B	Asset located in: Humble, TX Morbark SP111HP3 Tow-Behind Wood Chipper (Inoperable) S/N: 4AYSZ1514PW001575 C/W: Perkins 4 Cylinder Gasoline Engine, 20 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch, Electric Brakes Usage: 116 Hr Asset located in: Humble, TX	9672	S/N: JCB5CH2GC02433958 C/W: Enclosed Cab, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 68 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, Solid Tires Usage: 2,818 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BI RECONSIGNED BUYER RESPONSIBLE FOR	
9667A	2006 Rayco Tow-Behind Wood Chipper (Inoperable)		REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	S/N: 1R98109176M210068 C/W: Briggs & Stratton Vanguard 2 Cylinder Gasoline Engine, 7 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch, Electric Brakes Usage: 1,209 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX 2010 Cat TL1255 Telehandler (Inoperable) S/N: TBN00662 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 13,944 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE	
9667	2001 Vermeer TG400AL Tri/A Tub Grinder (Inoperable) S/N: 1VRN462T111000511 C/W: Enclosed Cab, Cat 3406 6 Cylinder 599 hp 14.6 L Diesel Engine, 29 in Discharge Conveyor, Grapple Loader Boom, Tri/A Carrier,		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Spring Suspension, Hydraulic Leveling Usage: 3,536 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ALL THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9673	2009 Cat TL1255 Telehandler (Inoperable) S/N: TBN00544 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 9,415 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9674A	2014 SkyTrak 10054L Telehandler S/N: 0160063857 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, 17.5-25 Foam Filled Tires Usage: 7,252 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9677A	2005 Toyota 7FDU45 9500 lb Pneumatic Tire Forklift S/N: 60771 C/W: 2 Stage Mast, 179 in Max Lift Height, 120 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2005 US EPA Label, Toyota 6 Cylinder 76 hp 4.6 L Diesel Engine Usage: 21,081 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9674	2018 JLG 1055 Telehandler (Inoperable)		Asset located in: Lake Worth, TX
	S/N: 0160084305 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 59.5 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00- 24T Tires Usage: 9,551 Hr Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9677	1994 Princeton D4500 4500 lb 4x2 Truck Mounted Forklift (Inoperable) S/N: TP29560894 C/W: Single Stage Mast 102 in Lowered Mast Height, 39 in Forks, 3 Cylinder Diesel Engine Usage: 1,986 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9678B	2017 Toyota 02-7FDA50 Pneumatic Tire Forklift
9675A	2015 Case 586H 2WD 17100 lb 4x2 Rough Terrain Forklift S/N: NFC728059 C/W: 3 Stage Mast, 264 in Max Lift Height, 126 in Lowered Mast Height, 46 in Forks, Side Shift, FPT INDUSTRIAL 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX		S/N: 7FDA50-19614 C/W: 2 Stage Mast, 96 in Lowered Mast Height, 54 in Forks, 2007 US EPA Label, Toyota 14Z 6 Cylinder Diesel Engine Usage: 4,338 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
9675	2007 Cat TL943 Telehandler (Inoperable) S/N: TBL00786 C/W: Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 56 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 9,190 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9678A 9678	2017 Toyota 02-7FDA50 Pneumatic Tire Forklift (Inoperable) S/N: 7DFA50-13480 C/W: 2 Stage Mast, Full Free Lift, 86 in Lowered Mast Height, 49 in Forks, Toyota 6 Cylinder Diesel Engine Usage: 2,874 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Hyundai 70D-7E Pneumatic Tire Forklift (Inoperable) S/N: HHIHFQ11JB0000887 C/W: Enclosed Cab, Air Conditioner, Single
9676	1995 Princeton D-4500 4500 lb 4x2 Truck Mounted Forklift (Inoperable) S/N: 36730795 C/W: Single Stage Mast 96 in Lowered Mast Height, 47 in Forks, Hatz 3 Cylinder Diesel Engine Usage: 80 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Stage Mast 121 in Lowered Mast Height, 94 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9679	Cat VC60DSA 6000 lb Cushion Tire Forklift (Inoperable)	9683	2007 TCM FG2M5T 5000 lb Cushion Tire Forklift (Inoperable)
	S/N: 9SB394 C/W: 2 Stage Mast, 173 in Max Lift Height, 102 in Lowered Mast Height, Side Shift, 4 Cylinder Gasoline Engine Usage: Not Available		S/N: A31T54483 C/W: 2 Stage Mast, Full Free Lift, 130 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Nissan 4 Cylinder Gasoline Engine Usage: 3,712 Hr
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9680A	2016 Hyster H80FT 6550 lb Pneumatic Tire	-	Asset located in: Humble, TX
	Forklift (Inoperable) S/N: U005V04442P C/W: 3 Stage Mast, Full Free Lift, 90 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Diesel Engine Usage: 7,662 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9684	2016 Mitsubishi FGC25 4750 lb Cushion Tire Forklift (Inoperable) S/N: AF82F42137 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE
9680	2017 Toyota 62-8FDN30 Pneumatic Tire Forklift (Inoperable) S/N: 608FDN30-11739		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: Full Free Lift, 79 in Lowered Mast Height, 48 in Forks, Side Shift, Toyota 1DZ 4 Cylinder Diesel Engine Usage: 2,097 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
		9685	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift (Inoperable)
			S/N: AF82F42135 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine
	Asset located in: Humble, TX	4	Usage: Not Available
9681	2021 Doosan D30S7 5500 lb Pneumatic Tire Forklift (Inoperable) S/N: FDA0W-1930-03660 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2020 US EPA Label, Doosan 4	0.000	Asset located in: Humble, TX
	Cylinder Diesel Engine Usage: Not Available	9686	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: AF82F42145 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available
9682	1997 Toyota 42-6FGU25 5400 lb Pneumatic Tire Forklift (Inoperable)		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 63385 C/W: 2 Stage Mast, Full Free Lift, 180 in Max		Asset located in: Humble, TX
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 4 Cylinder Dual Fuel Engine Usage: 15,705 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9687	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift (Inoperable) S/N: AF82F42132 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble TX
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9688	Forklift (Inoperable) S/N: AF82F42133 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.1 L LPG Engine	9692A	Cat V50B Pneumatic Tire Forklift (Inoperable) S/N: 79M1490 C/W: 3 Stage Mast, 83 in Lowered Mast Height, 4 Cylinder LPG Engine Usage: 3,545 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 14,284 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE	9692	Cat T60D Cushion Tire Forklift (Inoperable)
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available C/W: 2 Stage Mast, 116 in Max Lift Height, 81 in Lowered Mast Height, 46 in Forks, 4 Cylinder LPG Engine
9689			Usage: 8,301 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine	9693A	2014 Toyota 8FGU25 3750 lb Pneumatic Tire
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Forklift S/N: 62320 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L Dual Fuel
9690A	2000 Hyster S50XM 4500 lb Cushion Tire		Engine Usage: 843 Hr
	Forklift (Inoperable) S/N: D187V20833X C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 35 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX
		9693	2008 Yale GLP040SVXNUSE084 3800 lb Cushion Tire Forklift (Inoperable) S/N: C810V03617F C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2008 US EPA Label, IMPCO 4 Cylinder 2.0 L LPG Engine Usage: Not Available
9690	Daewoo C25S-2 4500 lb Pneumatic Tire Forklift (Inoperable) S/N: 1200313 C/W: 3 Stage Mast, 188 in Max Lift Height, 84 in Lowered Mast Height, Side Shift, Solid		Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Pneumatic Tires, 4 Cylinder LPG Engine Usage: Not Available	9694	Cat Pneumatic Tire Forklift (Inoperable)
	Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: AT18C31139 C/W: 3 Stage Mast, 84 in Lowered Mast Heigh 72 in Forks, Solid Pneumatic Tires, 2010 US EPA Label, 4 Cylinder 3.3 L Diesel Engine Usage: Not Available
9691	Asset located in: Humble, TX 2002 Nissan Pneumatic Tire Forklift	-	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
9691	(Inoperable)		RECONSIGNED
	S/N: 9W3082 C/W: 3 Stage Mast, Full Free Lift, 187 in Max	00054	Asset located in: Humble, TX
	Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Nissan 4 Cylinder LPG Engine Usage: 3,835 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9695A	Raymond DSS300 3000 lb Electric Forklift (Inoperable) S/N: DSS-06-06881 C/W: 3 Stage Mast, 227 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available
			Asset located in: Humble, TX
		I	

Lot #	Details	Lot #	Details
9695	Nissan 50 Pneumatic Tire Forklift (Inoperable)	9697	2018 Ruthman SA31 Crawler Electric
	S/N: Not Available		Articulating Boom Lift (Inoperable)
	C/W: 2 Stage Mast, Full Free Lift, 60 in Lowered Mast Height, Solid Pneumatic Tires,		S/N: 08041863
	2007 US EPA Label, Nissan 4 Cylinder 2.1 L		C/W: 250 kg Max Weight Capacity, Jib, 10 in Rubber Tracks, extendable tracks
	LPG Engine		Usage: Not Available
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE		Notes: THIS INOPERABLE ITEM NEEDS TO BE
	REMOVED FROM THE YARD AND CAN NOT BE		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR
	RECONSIGNED DEFICIENCIES NOTED -		REMOVAL OF THIS ITEM ; DEFICIENCIES
	PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		NOTED - PLEASE SEE THE INSPECTION REPORT
	· · ·	-	Asset located in: Humble, TX
9696B	2019 Genie S-65XC 4WD Diesel Telescopic Boom Lift	9699B	2003 Genie GS4390 4x4 Dual Fuel Scissor Lift
	S/N: S65XCH-45403	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	(Inoperable)
	C/W: 65 ft Max Platform Height, 1000 lb Max		S/N: GS9003-41542
	Weight Capacity, Jib, Power to Platform, 2019 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp		C/W: 43 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to
	2.9 L Diesel Engine, 355/55D625 Tires		Platform, Upper Control Box, Ford LRG-4251-
	Usage: 372 Hr		6007 4 Cylinder Dual Fuel Engine
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Usage: 2,341 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX		THE INSPECTION REPORT
9696A	Skyjack SJ45T 4WD Diesel Telescopic Boom		Asset located in: Humble, TX
	Lift	9699A	2013 Genie GS-5390RT 4x4 Diesel Scissor Lift
	S/N: Not Available		(Inoperable)
	C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016		S/N: GS901349035 C/W: 53 ft Max Platform Height, 1500 lb Max
	US EPA Label, Deutz d2.914 4 Cylinder 49 hp		Weight Capacity, Platform Extension, Power to
	2.9 L Diesel Engine, 305/70D16.5 Tires Usage: 2,607 Hr		Platform, Štabilizers, Upper Control Box, US EPA Label, Deutz D2011L03I 3 Cylinder 49 hp
	Notes: LOCATED-IN-FORT-WORTH-TX ;		2.3 L Diesel Engine
	DEFICIENCIES NOTED - PLEASE SEE THE		Usage: 1,077 Hr
	INSPECTION REPORT Asset located in: Lake Worth, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9696	2017 Genie S-65 4WD Diesel Telescopic Boom	-	Asset located in: Humble, TX
	Lift (Inoperable)	9699	2016 Genie S60X 4WD Diesel Telescopic Boom
	S/N: S60D1009		Lift
	C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017		S/N: S60X16H-35216
	US EPA Label, Deutz D2.9L 4 Cylinder 2.9 L		C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2015 US
	Diesel Engine, 335/55 Tires Usage: 3,382 Hr		EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L
	Notes: LOCATED-IN-FORT-WORTH-TX ; THIS		Diesel Engine, Positive Air Shutoff, 355-55d Foam-Filled Tires
	INOPERABLE ITEM NEEDS TO BE REMOVED		Usage: 5,306 Hr
	FROM THE YARD AND CAN NOT BE RECONSIGNED ; BUYER RESPONSIBLE FOR		Notes: LOCATED-IN-FORT-WORTH-TX, BUYER
	REMOVAL OF THIS ITEM DEFICIENCIES		RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE
	NOTED - PLEASE SEE THE INSPECTION REPORT		INSPECTION REPORT
	Asset located in: Lake Worth, TX		Asset located in: Lake Worth, TX
9697A	2008 Genie S60 4WD Diesel Telescopic Boom	9700	2012 Genie GS-3390 RT 4x4 Diesel Scissor Lift
	Lift (Inoperable)	1	(Inoperable) S/N: GS901247923
	S/N: S600817791		C/W: 33 ft Max Platform Height, 2500 lb Max
	C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2007 US		Weight Capacity, Platform Extension, Power to
	EPA Label, Deutz D 2011 L 03 1 3 Cylinder 2.3		Platform, Stabilizers, Upper Control Box, 2011 US EPA Label, Deutz 3 Cylinder 36.3 kW Diesel
	L Diesel Engine, 355/55D625 NHS Ťires	1	Engine
	Usage: 5,110 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		Usage: 934 Hr
	THE INSPECTION REPORT	1	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
	Asset located in: Humble, TX	1	RECONSIGNED DEFICIENCIES NOTED -
		•	PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX

Details	Lot #	Details
2014 Genie GS2632 Electric Scissor Lift (Inoperable) S/N: Not Available C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX 2018 JLG 2632ES Electric Scissor Lift (Inoperable)	9705	2019 Polaris Ranger 4x4 Utility Vehicle (Inoperable) S/N: 4XABEPD44K8578646 C/W: Open Operator Station, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2019 US EPA Label, Kubota 3 Cylinder .89 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 145 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 JLG 1932RS Electric Scissor Lift S/N: 0200234901	9706	2019 Polaris Ranger 4x4 Utility Vehicle (Inoperable) S/N: 4XABEPD48K8578679 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kubota 3 Cylinder 0.89 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 547 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Snorkel Electric Scissor Lift (Inoperable) S/N: S3219E11190500798	9707	2018 Polaris Ranger XP 4x4 Utility Vehicle (Inoperable) S/N: 4XARVA879J8500197 C/W: Canopy, 6 Passenger, Windshield, Locking Front Differential, Brush Guard, Hitch Receiver, Manual Dump Bed, 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Accest located in: Humble TY	9708	RECONSIGNED ; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Polaris Ranger 4x4 Utility Vehicle (Inoperable) S/N: 4XARVAD18J8867609
2016 Genie GS1930 Electric Scissor Lift (Inoperable) S/N: GS30P-163981 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 602 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9709A	S/N: 4XARVAD 1838867609 C/W: Canopy, 6 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 3 Cylinder 1.0 L Diesel Engine Usage: 1,727 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2021 Kubota RTVX1140WH Utility Cart (Inoperable) S/N: A5KD2GDBVMG044240 C/W: Canopy, 4 Passenger, Windshield, Hitch Receiver, Hydraulic Dump Bed, 2021 US EPA Label, Kubota 3 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	2014 Genie GS2632 Electric Scissor Lift (Inoperable) S/N: Not Available C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX 2018 JLG 2632ES Electric Scissor Lift (Inoperable) S/N: M200016475 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 145 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 JLG 1932RS Electric Scissor Lift S/N: 0200234901 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 547 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Snorkel Electric Scissor Lift (Inoperable) S/N: S3219E11190500798 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Snorkel Electric Scissor Lift (Inoperable) S/N: S3219E11190500798 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Genie GS1930 Electric Scissor Lift (Inoperable) S/N: (5330P-163981 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 602 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	2014P7052014 Genie GS2632 Electric Scissor Lift (Inoperable)9705S/N: Not Available C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX97062018 JLG 2632ES Electric Scissor Lift (Inoperable) S/N: M200016475 C/W: Platform Extension, Power to Platform, Solid Non-Marking Tires Usage: 145 Hr9706Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX97072014 JLG 1932RS Electric Scissor Lift S/N: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 547 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX97072019 Snorkel Electric Scissor Lift S/N: S3219E11190500798 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES SOSTE Lift (Inoperable) S/N: GS30P-163981 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX97082016 Genie GS1930 Electric Scissor Lift (Inoperable) S/N: GS30P-163981 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to PLEASE SEE THE INSPECTION

Lot #	Details	Lot #	Details	
9709	2010 Polaris Ranger XP 4x4 Utility Vehicle (Inoperable) S/N: 4XATH76A7A2883297 C/W: Open Operator Station, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED OFF HIGHWAY USE ONLY DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9711	2010 Kubota RTV1140CPX 4x4 Utility Vehicle (Inoperable) S/N: A5KD1HDAPAG016329 C/W: Open Operator Station, 4 Passenger, Hydraulic Dump Bed, Tier 4, 2010 US EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
9710	2017 Kubota RTV-X1140 4x4 Utility Vehicle	9712C	Club Car XRT1200 4x2 Utility Vehicle	
	(Inoperable) S/N: A5KD2GDBTHG018882 C/W: Canopy, 4 Passenger, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: 3,205 Hr		S/N: AD0924-028187 C/W: Canopy, 2 Passenger, Windshield, Rear Screen, Brush Guard, Hitch Receiver, Manual Dump Bed, 1 Cylinder Gasoline Engine Usage: 6,547 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -	9712B	2019 Club Car Carry All 1700 4x4 Utility Vehicle (Inoperable)	
	PLEASE SEE THE INSPECTION REPORT		S/N: SD1913958838	
	Asset located in: Humble, TX		C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota 3 Cylinder	
9711C	C Bad Boy Buggies Electric Utility Cart (Inoperable) S/N: 00022 C/W: Canopy, 4 Passenger, Winch, Brush Guard, Hitch Receiver Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX		Diesel Engine Usage: 1,192 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
		9712	2014 E-Z-Go Golf Cart (Inoperable) S/N: 3054540 C/W: 4 Passenger, Canopy, Windshield, 2013 US EPA Label, Kawasaki 1 Cylinder Gasoline Engine	
9711B	Cushman Turf-Truckster Utility Cart (Inoperable) S/N: 99001959 C/W: Open Operator Station, 2 Passenger, Hydraulic Dump Bed, 3 Cylinder Gasoline Engine			Usage: 50 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 1,461 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		(Inoperable)	2016 Ford F-550 XL 4x4 Crew Cab Utility Truck (Inoperable) S/N: 1FD0W5HT4GED32168
9711A	Cushman Turf-Truckster Utility Cart	1	C/W: Ford 4V F-Series V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel	
	(Inoperable) S/N: 00003585 C/W: Open Operator Station, 2 Passenger, Hydraulic Dump Bed, 3 Cylinder Gasoline Engine Usage: 3,460 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Exhaust Fluid, Automatic Transmission, 7000 Ib Front Axle, 14706 Ib Rears, 19500 Ib GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, Knapheide 11 ft Body, Manual Stabilizers Usage: 221,984 Mi Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
9714A	2016 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HT2GEA46367 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9727 Engine hrs, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 165 in Wheelbase, IMT Body, Vanair 051243 Gasoline Air Compressor, Air Hose Reel Usage: 159,307 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9717	2014 Intenational 4300 4x2 Water Truck (Inoperable) S/N: 1HTMMAAM8EH467675 C/W: International MaxxForce DT 7.6 L Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 154 in Wheelbase, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
9714	2009 Chevrolet Silverado 2500 HD 4x2 Utility Truck (Inoperable) S/N: 1GBHC44K49E106632 C/W: V8 Gasoline Engine, Automatic Transmission, 4200 lb Front Axle, 6084 lb Rears, 9200 lb GVWR, 245/75R16, Spring Suspension, 142 in Wheelbase, Knapheide 8 ft Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9718 9719	
9715	2003 GMC C8500 4x2 Service Truck (Inoperable) S/N: 1GDP8E1C33F521918 C/W: 6 Cylinder Diesel Engine, Allison Automatic Transmission, 13220 lb Front Axle, 23000 lb Rears, 36220 lb GVWR, 11R22.5, Spring Suspension, 176 in Wheelbase, PTO, 14 ft Body, Hydraulic Stabilizers, IMT 5020 8600 lb 2 Section Crane, Hydraulic Air Compressor, Air Hose Reel Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE RE MOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX		RECONSIGNED . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Kenworth 6x4 Cab and Chassis (Inoperable) S/N: 38505 C/W: Cat C12 6 Cylinder Ultra Low Sulfur Diesel Engine, 15284 Engine hrs, Engine Brake, Aluminum Wheels, 385/65R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Chalmers Rubber Suspension, 250 in Wheelbase, 159 in Cab to Axle, 229 in Cab to End of Frame Usage: 610,040 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS UNIT IS BEING
9716	1975 Kaiser M725 6x6 Flatbed Water Truck (Inoperable) S/N: 05D14569M72511166 C/W: 6 Cylinder Diesel Engine, 863 Engine hrs, 5-Speed Manual Transmission, 9000 lb Front Axle, 30750 lb Rears, 11.00R20, Spring Suspension, 180 in Wheelbase, PTO, 12 ft x 96 in Bed, Pintle Hitch Usage: 5,214 Mi Notes: ; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9720	SOLD WITH A REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Freightliner M2106 4x2 Cab and Chassis (Inoperable) S/N: 1FVACWDT7CHBH8659 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 12575 Engine hrs, Allison 2200 Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.13:1 Axle Ratio, 25500 lb GVWR, 275/80R22.5, Spring Suspension, 282 in Wheelbase, 216 in Cab to Axle, 303 in Cab to End of Frame Usage: 232,031 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9721	2000 Volvo VNM 6x4 Cab and Chassis (Inoperable) S/N: 4V4MD2UF7YN238625 C/W: Cummins ISM 6 Cylinder Diesel 370 hp Engine, Eaton Fuller RTX-14710C 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor RT40-14 Drive Axles, 50350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 168 in Wheelbase, Wet Kit, 104 in Cab to Axle, 160 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE	9725 9726	2017 Chevrolet 3500 4x2 Cab and Chassis S/N: 1HA3GRCG6HN006966 C/W: V8 Gasoline Engine, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75/16, Spring Suspension, 140 in Wheelbase, 81 in Cab to Axle, 138 in Cab to End of Frame Usage: 306,314 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Chevrolet Express G3500 4x2 Cab and
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Chassis (Inoperable) S/N: 1GB3GRCG8G1279325 C/W: V8 Gasoline Engine, 20299 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16,
9722	2004 Ford F-650 XL 4x2 Cab and Chassis (Inoperable) S/N: 3FRNF65N84V683075 C/W: 6 Cylinder Diesel Engine, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, 186 in Cab to Axle, 271 in		Solution Reals, 12300 ib GVWR, 225/75R16, Spring Suspension, 134 in Wheelbase, 77 in Cab to Axle, 142 in Cab to End of Frame Usage: 351,994 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Cab to End of Frame Usage: 145,251 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX	9727	2016 Chevrolet Express Cab and Chassis (Inoperable) S/N: 1GB3GRCG261281149 Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE
9723	2022 Ram 4500 Laramie 4x4 Crew Cab Cab and Chassis (Inoperable) S/N: 3C7WRLFL7NG245810		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	C/W: 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 198 in Wheelbase, 87 in Cab to Axle, 138 in Cab to End of Frame Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM TITLE IS BRANDED AS NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9728	2016 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1GB3GRCG1G1277688 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225 /75R16, Spring Suspension, 142 in Wheelbase, 81 in Cab to Axle, 139 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	Asset located in: Humble, TX		Asset located in: Humble, TX
9724	2017 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1HA3GRCG7HN002344 C/W: V8 6.0 L Gasoline Engine, 2020 US EPA Label, 20290 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16, Spring Suspension, 132 in Wheelbase, 74 in Cab to Axle, 142 in Cab to End of Frame Usage: 343,000 Mi Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9729A	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3WKDD40X7KF257236 C/W: Cummins X15 15.0 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, Dana Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9729	2012 Mitsubishi Fuso 4x2 COE Cab and Chassis (Inoperable) S/N: JL6AMC1A2CK003922 C/W: Fuso F1C 4 Cylinder 3.0 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 12500 lb GVWR, 215 /85R16, Spring Suspension, 112 in Wheelbase, 92 in Cab to Axle, 156 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9732A	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGEDV1GSGV9636 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 522,814 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9730	2004 Kenworth T800 6x4 Winch Truck (Inoperable) S/N: 1XKDDT9X54R063169 C/W: Cat C10 6 Cylinder Ultra Low Sulfur Diesel 335 hp Engine, 3480 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Meritor RT-44-145 Drive Axles, 5.29:1 Axle Ratio, 56000 lb GVWR, Air Ride Cab, 11R22.5, Neway Air Ride Suspension, 172 in Wheelbase, Dual PTO, Tail Roll, Braden ANS20- 18B 21300 lb Winch Usage: 458,632 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9732	Asset located in: Humble, TX 2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M1AW02Y9GM076387 C/W: Mack MP7 6 Cylinder 10.8 L Ultra Low Sulfur Diesel 405 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 5441 Engine hrs, Engine Brake, Mack mDrive 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 232 in Wheelbase Usage: 646,382 Mi Notes: LOCATED-IN-LIVINGSTON_LA;
9731A	2015 Mack CHU 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M2AN07Y5FM018007 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Mack Automated Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Twin Y Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 429,571 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Livingston, LA 2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGED50FDGH0450 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO- 18E313A MHP 13-Speed Automated Transmission, Meritor RT-46-160 Drive Axles, 3.91:1 Axle Ratio, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel Dual Evel Tarks
9731	2013 Kenworth T800 8x4 Tri/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDP7EX2DJ353825 C/W: Cummins ISX12 6 Cylinder 11.9 L Ultra Low Sulfur Diesel 425 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, 19500 lb Front Axle, 60000 lb Rears, 4.89:1 Axle Ratio, 79500 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,704 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BI RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9734	2015 Freightliner Cascadia125 6x2 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKGGEDVXFSGK3419 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED EQUIPMENT-FROM-YELLOW- CORP ; LOCATED-IN-HUMBLE-TX-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9738	2011 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEDR2BSBD8644 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airliner Suspension, 188 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-HOUSTON-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9739	2015 Volvo VNL300 6x4 T/A Day Cab Truck
9736	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEDV1DLBV2601 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 195 in Wheelbase, Dual Fuel Tanks Usage: 588,339 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9740	Tractor (Inoperable) S/N: 4V4NC9EH8FN189707 C/W: Volvo D13J435 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 435 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, Aluminum Wheels, Air Ride Suspension, 196 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2014 International ProStar 6x4 T/A Day Cab
9737	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEBG1DSBY0263 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 183 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Truck Tractor (Inoperable) S/N: 3HSDJSNR1EN013864 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Hendrickson Air Ride Suspension, 184 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9741	2014 International Prostar 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR8EN013862 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 181 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9744	2009 Peterbilt 388 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPWDU9X09D784934 C/W: Cat C13 6 Cylinder 12.5 L Diesel Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 222 mm Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 304,207 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9742	2014 International ProStar 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR4EN013860 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 181 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 International ProStar+ 122 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1HSDJSJR7CJ660470 C/W: International Maxxforce 6 Cylinder Ultra Low Sulfur Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 212 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE	9745A 9745	2006 Mack CXN613 Vision 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M1AK07Y66N007508 C/W: Mack 6 Cylinder 11.9 L 480 hp Engine, 2005 US EPA Label, 27360 Engine hrs, Engine Brake, Mack 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 170 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 581,953 Mi Asset located in: Humble, TX 2007 Peterbilt 386 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPHD49X87N733035 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Low Low Air Leaf Air Ride Suspension, 194 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ** Title Remarks: DIESEL** **Title will be accompanied by a Repossession Affidavit and may not be accepted in your state. Please check with your local licensing agency** Asset located in: Humble, TX	9746A	Asset located in: Humble, TX 2009 Volvo VNM200 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4MC9EG09N283684 C/W: Volvo D13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller FR-14210B 10- Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, 275 /80R22.5 Front Tires, 275/80R22.5 Rear Tires, Volvo 4-Bag Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,125,769 Mi Notes: CANNOT VERIFY ODOMETER READING- VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9746	2008 Kenworth T800 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XKDDU9X78J228696 C/W: Cat C13 6 Cylinder 7.2 L Ultra Low Sulfur Diesel 350 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller FRO-14210C 10- Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, Meritor RT-40-145 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 11R22.5, Air Ride Suspension, 188 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9749	2015 Western Star 4900SA 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 5KJJALD13FPGB7643 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2014 US EPA Label, CARB Compliant, 13672 Engine hrs, Engine Brake, Eaton Fuller RTLO-1891 13-Speed Manual Transmission, Differential Lock, 16000 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 62000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 210 in Wheelbase, Dual Fuel Tanks Usage: 13,672 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9747	2002 Volvo VNM 6x4 T/A Day Cab Truck		Asset located in: Humble, TX
	Tractor (Inoperable) S/N: 4V4MC9RF92N324708 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 350 hp Engine, 2001 US EPA Label, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 2.93:1 Axle Ratio, 52000 lb GVWR, 295 /75R22.5, VOLVO Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 325,030 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA	9750	2013 Kenworth T800 8x4 Tri/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDP7EX4DJ353826 C/W: Cummins ISX12 6 Cylinder 11.9 L 425 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO- 16918B 18-Speed Manual Transmission, 19500 lb Front Axle, 60000 lb Rears, 4.89:1 Axle Ratio, 79500 lb GVWR, Air Ride Cab, 36 in Mid Roof Sleeper Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Air Ride Suspension, 260 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9748	2007 International 9400i 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 2HSCNAPR37C562767 C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 53220 lb GVWR, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA	9751	2012 Kenworth T800 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDD79X8CJ327697 C/W: Cummins 6 Cylinder Diesel Engine, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, MP44-14x5 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 36 in Mid Roof Sleeper Cab, 11R22.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, Headache Rack Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9752	2012 Kenworth T800 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDD79X7CJ315203 C/W: Cummins ISX11.9 350V 6 Cylinder 11.9 L Diesel 350 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Air Ride Cab, 28 in Flat Top Sleeper Cab, 11R22.5, Neway Air Ride Suspension, 198 in Wheelbase, Air Sliding 5th Wheel, Headache Rack Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9755	2023 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR6PSNH6231 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1750- OH 12-Speed Automated Transmission, 13300 Ib Front Axle, 40000 Ib Rears, 3.08:1 Axle Ratio, 53300 Ib GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Electric Sleeper Air Conditioner, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
9753	2007 Kenworth T800 6x4 T/A Sleeper Truck		RECONSIGNED Asset located in: Humble, TX
0754	Tractor (Inoperable) S/N: 1XKDDT9X17J198409 C/W: Cat C11 6 Cylinder 11.1 L Ultra Low Sulfur Diesel 385 hp Engine, 2006 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Meritor RT-44-145 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 36 in Flat Top Sleeper Cab, 11R22.5, Neway Air Ride Suspension, 200 in Wheelbase, PTO Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9756	2021 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDROMSMA8077 C/W: 13300 lb Front Axle, 40000 lb Rears, 3.08: 1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295 /75R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9754	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKYD49X2LJ388379 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 24479. Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 614,194 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9757	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR7LSLJ3051 C/W: Detroit DD15 6 Cylinder 14.5 L 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor DA-RT-40.0-4S Drive Axles, 3.23:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 594,374 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9758	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDRXKSKM0577 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1750-DH1 12- Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 2.41:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-FORT-WORTH-TX , BUYER'S RESPONSIBILITY FOR REMOVAL OF	9761A	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR5HDHU1687 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OA-1650 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 684,841 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX
	THIS ITEM, CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	9761	2018 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR4JSJN7411 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475
9759	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKYDP9X4JJ211637 C/W: Paccar 6 Cylinder Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO-16E313A-MHP ULT Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	9762B	hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
9760	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKYDP9X1GJ115635 C/W: 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX		S/N: 3AKJGLDR5HSHV9635 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14XP Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Tires, MIXED SIZE Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

This catalog was created at November 5, 2024 03:25:12 AM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details
9762A	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR8HSJG4013 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT-12-OA-1650 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 518,301 Mi Notes: PENSKE-FLEET-MAINTAINED ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	9766	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDV4GSHD4846 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9762	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR1HSGV7961 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Rear Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Lake Worth, TX	9767 9770	Asset located In: Humble, TX 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1FUJGLDR4GLGV6507 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 19718 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 199 in Wheelbase, Dual Fuel Tanks Usage: 634,624 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLD52ESFW7646 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 13-Speed Manual
9764	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLD58GSHD2016 C/W: Detroit DD15 6 Cylinder 14.8 L Gasoline 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12OA1750 Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 55300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Transmission, 12000 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Ramps, Dual Fuel Tanks Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

2016 International ProStar 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDJAPR9GN411978 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	9773A	1993 Freightliner FLD 120 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUPDCYB1PH491421 C/W: Cummins N14 6 Cylinder 14.0 L Diesel 430 hp Engine, Rockwell 9-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 192 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Asset located in : Humble, TX	
Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9773	2012 International Prostar 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1HSDJSJR3CJ562939	
Asset located in: Humble, TX 771 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDVXESFW0380 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 275/80R22.5. Airliner Air Ride Suspension, 230		C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2011 US EPA Label, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX	
	9774	2022 Peterbilt 579 4x2 S/A Day Cab Truck	
Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2001 Peterbilt 378 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPFDT9X41D558779 C/W: Cat C10 6 Cylinder 10.3 L Diesel 370 hp Engine, 2000 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 230 in Wheelbase, Headache Rack Usage: 246,390 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9774	Tractor (Inoperable) S/N: 1XPBAP8X8ND759395 C/W: Paccar MX-13 6 Cylinder 1 Engine, 2021 US EPA Label, Req Exhaust Fluid, Engine Brake, Aut Transmission, 12000 lb Front Ax Rears, 34700 lb GVWR, Air Ride (/80R22.5, Air Trac Air Ride Susp Wheelbase, Dual Fuel Tanks, EQ FROM-YELLOW-CORP Usage: 205,979 Mi Notes: THIS INOPERABLE ITEM REMOVED FROM THE YARD AN RECONSIGNED EQUIPMENT-FRO CORP ; DEFICIENCIES NOTED - F INSPECTION REPORT DEFICIEN	Tractor (Inoperable) S/N: 1XPBAP8X8ND759395 C/W: Paccar MX-13 6 Cylinder 12.9 L 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 275 /80R22.5, Air Trac Air Ride Suspension, 155 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 205,979 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED EQUIPMENT-FROM-YELLOW- CORP ; DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
Asset located in: Humble, TX	9775	2022 Peterbilt 579 4x2 S/A Day Cab Truck	
2018 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3HSDZAPR3JN566574 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Tractor (Inoperable) S/N: 1XPBAP8X5ND759337 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-FORT-WORTH-TX , LOCATED-IN-LAKE-WORTH-TX-HOU ; EQUIPMENT-FROM-YELLOW-CORP	
	Truck Tractor (Inoperable) S/N: 3HSDJAPR9GN411978 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12350 lb Grvnt Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 716,138 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AK.JGLDYXESFW0380 C/W: Detroit D013 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 275/80R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED GYONO US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 230 in Wheelbase, Headache Rack Usage: 246,390 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 International LT625 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 31SDZAPR3,JN566574 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride C	Truck Tractor (Inoperable)S/N: 3HSDJAPR9GN411978S/N: 3HSDJAPR9GN411978C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel400 hp Engine, 2015 US EPA Label, RequiresDiesel Exhaust Fluid, Engine Brake, AutomatedTransmission, 12350 Ib Front Axle, 40000 IbRears, 52350 Ib GVWR, Air Ride Cab, 72 in HighRise Sleeper Cab, Bunk Beds, AluminumWheels, 295/75R22.5, Air Ride Suspension,226 in Wheelbase, Air Silding 5th Wheel, DualFuel TanksUsage: 716,138 MiNotes: DEFICIENCIES NOTED - PLEASE SEETHE INSPECTION REPORTAsset located in: Humble, TX2014 Freightliner Cascadia 125 6x4 T/ASleeper Truck Tractor (Inoperable)S/N: 3AKJGLDVXESFW0380C/W: Detroit DD13 6 Cylinder 12.8 L Ultra LowSulfur Diesel 450 hp Engine, 2013 US EPALabel, Requires Diesel Exhaust Fluid, EngineBrake, Eaton Fuller FRW-15210B 10-SpeedManual Transmission, 12000 lb Front Axle,40000 lb Rears, Meritor MT-40-14X Drive Axles,2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab,70 in Mid Roof Sleeper Cab, Aluminum Wheels,275/80R22.5, Airliner Air Ride Suspension, 230Notes: THIS INOPERABLE ITEM NEEDS TO BEREMOVED FROM THE YARD AND CAN NOT BEReconSIGNEDAsset located in: Humble, TX2010 Peterbilt 378 6x4 T/A Day Cab TruckTractor (Inoperable)S/N: 1XPFDT9X41D558779C/W: Cat C10 6 Cylinder 10.3 L Diesel 370 hpFingine, 2000 US EPA Label, Engine Brake,Eaton Fuller Manual Transmission, 12000 lbFront Axle,	

Lot #	Details	Lot #	Details
9776	2022 Volvo VNR 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 4V4W19EG2NN607677 C/W: Volvo D13N-405 6 Cylinder 12.8 L 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 4009 Engine hrs, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 295/75R22.5, Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 142,422 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Peterbilt 337 4x2 S/A Day Cab Truck	9779	2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYA48X7EJ402449 C/W: 12000 Ib Front Axle, 22700 Ib Rears, 34700 Ib GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Tractor (Inoperable) S/N: 2XP2AN8X0BM126366 C/W: Paccar PX-8 6 Cylinder 8.3 L Ultra Low Sulfur Diesel 300 hp Engine, 2010 US EPA Label, Requires Diesel Exhaust Fluid, Allison 3000 Automatic Transmission, 12000 kg Front Axle, 22700 lb Rears, 4.78:1 Axle Ratio, 34700 lb GVWR, 275/80R22.5, Air Trac Air Ride Suspension, 160 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9780	Asset located in: Lake Worth, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGEDVXFLGH4646 C/W: 12000 lb Front Axle, 22700 lb Rears, 2.50: 1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE
9778	2018 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1XKYAP8X1JJ214313 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 430 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton FAOM15810S-EC3 Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, Paccar RS23-161 Drive Axles, 2.80:1 Axle Ratio, 35050 lb GVWR, Air Ride Cab, 295/75R22.5, Hendrickson HAS Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: 47,939 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	- Ri Ri Ri 9781 20 9781 20 C, C, C, C, C, C, C, C, C, C, C, C, C,	REMOVED FROM THE YARD AND CANNOT BE RELISTED ; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Lake Worth, TX 2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGBDV1GSGY0422 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT- 40-145 Drive Axles, 3.42:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 186 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9779A	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M1AW07YXFM043941 C/W: Mack MP8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Twin Y Air Ride Suspension, 186 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower Usage: 368,419 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9782	2014 Freightliner Cascadia 113 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 1FUBGADV7ELFR1039 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 2.67:1 Axle Ratio, Air Ride Cab, 275/80R22.5 Front Tires, MIXED Rear Tires, Airliner Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 810,762 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9785	2009 Volvo VNM200 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 4V4M19EG39N263824 C/W: Volvo D13 6 Cylinder 12.8 L Diesel Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,257,903 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; EQUIPMENT-FROM- YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9783	2014 International ProStar 6x4 S/A Day Cab	9786	2002 Volvo VNM 4x2 S/A Day Cab Truck
	Truck Tractor (Inoperable) S/N: 3HSDJSNR3EN013865 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Hendrickson Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	0797	Tractor (Inoperable) S/N: 4V4M19RF32N324628 C/W: Detroit Series 60 6 Cylinder 12.7 L Ultra Low Sulfur Diesel 470 hp Engine, 2001 US EPA Label, Eaton Fuller T-14607A 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.93:1 Axle Ratio, 32000 lb GVWR, 275 /80R22.5, Volvo Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2001 Value VMM200 4v2 S (A Day Cab Truck
9784	2014 International 4400 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HCMKAAN6EL034677 C/W: 6 Cylinder Engine, 2013 US EPA Label, 8836 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 322,649 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	-9787	2001 Volvo VNM200 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 4V4M19RF81N306642 C/W: Detroit Series 60 6 Cylinder 12.7 L Ultra Low Sulfur Diesel 350 hp Engine, 2000 US EPA Label, Eaton Fuller T-14607A 7-Speed Manual Transmission, 12000 lb Front Axle, 19000 lb Rears, 3.07:1 Axle Ratio, 32000 lb GVWR, 275 /80R22.5, Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 791,634 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9788	2002 International 9200i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 2HSCDAHN32C043192 C/W: 6 Cylinder Diesel Engine, Meritor 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 938,610 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9793	2007 International 7500 6x4 T/A Dump Truck (Inoperable) S/N: 1HTWNAZR17J519696 C/W: International DH330 6 Cylinder 9.3 L 330 hp Engine, 2006 US EPA Label, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Hendrickson Haulmaax Suspension, 196 in Wheelbase, PTO, OX Bodies 15 ft Long x 4 ft 8 in High Steel Body, Round Bottom, Electric Roll Tarp, Pintle Hitch Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE
9790	2005 Ottawa TY30 4x2 Spotter Truck (Inoperable)		RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
	S/N: 311154 C/W: Allison Automatic Transmission, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX	9794	2010 International 7400 6x4 Crew Cab T/A Dump Truck (Inoperable) S/N: 1HTWGAAR4AJ289665 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel Engine, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 11R22.5, Hendrickson Spring over Walking Beam Suspension, 238 in Wheelbase, PTO, Martin 10 ft Long x 0 ft 48 in
9791	1994 Ottawa 4x2 Spotter Truck (Inoperable) S/N: 1T9AA12S94A070507 C/W: 6 Cylinder Engine, Automatic Transmission, 295/75R22.5 Front Tires, 275 /80R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED		High Body, 10 cyd, Capacity, Pintle Hitch Usage: 91,700 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Asset located in: Humble, TX	9795	2012 International 4300 4x2 Flatbed Dump Truck (Inoperable)
9792	2018 Mack GU713 8x4 Tri/A Dump Truck (Inoperable) S/N: 1M2AX07C1JM037841 C/W: Mack MP8 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Spring Suspension, 200 in Wheelbase, PTO, 16 ft Long x 5 ft 1 in High Steel Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3HAMMAAL1CL629628 C/W: International MaxxForce DT 7.6 L Diesel Engine, 8400 Engine hrs, Eaton Fuller Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 238 in Wheelbase, 20 ft 6 in Long x 5 in High Steel Body, Flat Bed Usage: 256,752 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9796	2005 Peterbilt 330 4x2 Flatbed Truck (Inoperable)	9802	2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck (Inoperable)
	S/N: 2NPNHD7X45M848006 C/W: Cat C7 6 Cylinder 7.2 L Ultra Low Sulfur Diesel 350 hp Engine, 2004 US EPA Label, 1480 Engine hrs, Manual Transmission, 12000 lb		S/N: 1FD0W5HT1KEC07475 C/W: V8 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Degre 10600 lb C/W/D 225 (70010 5
	Front Axle, 21000 lb Rears, 4.88:1 Axle Ratio, 33000 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5, Low Air Leaf Air Ride Suspension, 178 in Wheelbase, 12 ft 2 in x 96 in Bed Usage: 333,409 Mi		14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 203 in Wheelbase, 11 ft 2 in x 94 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
9797	1999 Freightliner FL70 4x2 Flatbed Truck (Inoperable) S/N: 1FV3HJAC6XHB77403	9803	2016 Ford F-550 XL 4x4 Extended Cab Flatbed Truck (Inoperable)
	C/W: Cat 6 Cylinder Diesel Engine, Manual Transmission, 8000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 48 in Flat Top Sleeper Cab, 11R22.5, Airliner Air Ride Suspension, 304 in Wheelbase, PTO, 25 ft x 102 in Bed, Winch Usage: 591,906 Mi		S/N: 1FD0X5HT2GEB56704 C/W: Ford 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft 4
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		in x 92 in Bed Usage: 277,617 Mi Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9799A	2001 Ford F-650 XL 4x2 Flatbed Truck	-	Asset located in: Humble, TX
	(Inoperable) S/N: 3FDWF65H51MA77466 C/W: Cat 6 Cylinder Diesel Engine, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5 Front Tires, 10R22.5 Rear Tires, Spring Suspension, 176 in Wheelbase, 12 ft x 92 in Bed Usage: 86,528 Mi	9805	2017 Ford F-450 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD0W4HT4HED28150 C/W: Ford V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 203 in Wheelbase
	Asset located in: Humble, TX	RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
9800	2006 Ford F-650 4x2 Flatbed Truck (Inoperable) S/N: 3FRNF65FX6V331580 C/W: Cummins ISB 6 Cylinder 230 hp Engine, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 10R22.5, Spring Suspension, 160 in Wheelbase, 11 ft x		REMOVED FROM THE YARD AND C RECONSIGNED BUYER RESPONSIE REMOVAL OF THIS ITEM DEFICIEN NOTED - PLEASE SEE THE INSPEC REPORT
	96 in Bed, Pintle Hitch Usage: 127,777 Mi	9807	2017 Ford F-350 XL 4x2 Crew Cab Flatbed
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED		Truck (Inoperable) S/N: 1FD8W3G62HEB81111
	Asset located in: Humble, TX		C/W: Ford Power Stroke 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission,
9801	2020 Chevrolet Silverado 4x2 Crew Cab Flatbed Truck (Inoperable)		4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 96 in Bed, Receiver
	S/N: 1HTKJPVK7LH869504 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 Ib Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 199 in Wheelbase, 11 ft 4 in x 88 in Bed Usage: 193,499 Mi		Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in : Humble, TX
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details	
9808	2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H61GEB16957 C/W: Ford 6.2 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase, 9 ft 2 in x 94 in Bed, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 235,308 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9813	Liftmoore L-21 2000 lb on 2008 Ford F-350 4x4 Crew Cab Flatbed Truck with Crane (Inoperable) S/N: 1FTWW33R58EA12311 C/W: Ford 6.4 L Engine, 2008 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 9000 lb Rears, 13000 lb GVWR, 245/75R17, Spring Suspension, 172 in Wheelbase, 2000 lb Capacity, Rear Mounted, 3 ft 8 in - 3 Section Boom, 8 ft 10 in x 92 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	
9809	2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H63GEB16961 C/W: Ford 6.2 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase, 9 ft x 94 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9815	2011 Peterbilt 348 6x4 Vacuum Tanker Truck (Inoperable) S/N: 2NP3LN9X2BM129454 C/W: Paccar PX-8 8.3 L Diesel 330 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller 9LL Transmission, 14600 lb Front Axle, 40000 lb Rears, 4.33:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 12R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 256 in Wheelbase, PTO Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED **Vacuum Tank Missing**, BUYER RESPONSIBLE FOR REMOVAL OF THIS	
9810	2015 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H66FEC97097		ITEM ; DEFICIENCIES NOTED - PLEAS THE INSPECTION REPORT	ITEM ; DEFICIENCIES NOTED - PLEASE SEE
	C/W: V8 6.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase, 9 ft x 94 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX		2002 Rebel on 2002 Kenworth T-800 8x6 Vacuum Tanker Truck (Inoperable) S/N: 1NKDXBEX92R967220 C/W: Cat C15 6 Cylinder Diesel 490 hp Engine, 13328 Engine hrs, Engine Brake, Eaton Fuller 8- Speed Manual Transmission, Triple Differential Locks, Aluminum Wheels, 445/65 R 22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, AG400 Air Ride Suspension, 285 in Wheelbase, Steel Debris Tank, Front Hose Reel, Hydraulic	
9812	2006 Chevrolet 3500 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1GBJC33D56F219199 C/W: GM 6.6 L Diesel Engine, 2006 US EPA Label, Automatic Transmission, Dual Rear Wheel, 215/85R16, Spring Suspension, 166 in Wheelbase, 9 ft x 92 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Lift Tailgate, Wash Down System, Manual Tailgate Locks, 17 ft Boom, 9 in Suction Hose Cat Hydraulic Driven Pump, Blower, Cordless Remote Control Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Livingston, LA	

Lot #	Details	Lot #	Details
9818	(Inoperable) S/N: 1NKDL70X7EJ394269 C/W: Cummins ISX12 6 Cylinder 11.9 L Ultra Low Sulfur Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller RTO-14909ALL 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Rubber Suspension, 224 in Wheelbase, PTO, 3 Removable Chutes,	9821	2006 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMPAX6W063474 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit Diesel Engine, Aluminum Front Wheels, 315/80R22.5 Front Tires, 315 /80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2005 MCI J4500 6x2 56-Seat Coach
		-	(Inoperable) S/N: 2M93JMDAX5W063011 C/W: Air Conditioner, Automatic Transmission, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Front Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 315 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL
9819	2007 Mack CV713 6x4 Rear Loader Waste Collection Truck (Inoperable) S/N: 1M2AG12CX7M055888 C/W: Mack 6 Cylinder Diesel Engine, Automatic		OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, 315 /80R22.5, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 250 in Wheelbase, PTO, Mc Neilus Collection Body Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9823	2005 MCI J4500 6x2 56-Seat Coach (Inoperable) S/N: 2M93JMDA15W063012 C/W: Air Conditioner, Automatic Transmission, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 315 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9820	2005 Peterbilt 357 6x4 Roll-Off Truck (Inoperable) S/N: 1NPALU0X55D861506 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 18740 lb Front Axle, 44000 lb Rears, 62740.0 lb GVWR, 11R22.5, Dual Steering Boxes, Double Frame, Hendrickson Spring over Walking Beam Suspension, 270 in Wheelbase, PTO, 2005 Galbreath U5-0R-174 Roll-Off Body, 23 ft 4 in Hoist Usage: 147,489 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA	9824 9825A	 2006 BlueBird 4x2 School Bus (Inoperable) S/N: 1BABNCKA96F237961 C/W: Allison Automatic Transmission, Cat C7 6 Cylinder Diesel Engine, 11R22.5, Air Ride Suspension, 232 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2015 Hino 268 4x2 Van Truck (Inoperable) S/N: 5PVNE8JV4F4S53629 C/W: Hino 6 Cylinder 7.7 L 220 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 329,222 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9825	2019 Peterbilt 337 4x2 Van Truck (Inoperable) S/N: 2NP2HM7X3KM497054 C/W: Paccar PX-7 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, Dana Spicer Drive Axles, 6.17:1 Axle Ratio, 32000 lb GVWR, 275/80R22. 5, Reyco Spring Suspension, 276 in Wheelbase, Wabash 26 ft x 102 in Wide x 90 in High Body, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9827	2015 Ford F-750 4x2 Van Truck (Inoperable) S/N: 3FRNF7FA9FV745491 C/W: Ford 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 26000 lb GVWR, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 281 in Wheelbase, 26 ft x 102 in Wide x 104 in High Body, Liftgate Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9826A	Asset located in: Humble, TX 2018 International 4300 4x2 Van Truck (Inoperable) S/N: 3HAMMML1JL003751 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7883 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 273 in Wheelbase, Supreme 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 291,005 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9828	2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGAFF1H1142306 C/W: 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 74 in Wide x 52 in High Body, Curbside Door Usage: 175,542 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable)
9826	Asset located in: Humble, TX 2005 International 4300 4x2 Van Truck (Inoperable) S/N: 1HTMMAAN05H118468 C/W: International DT466 6 Cylinder Diesel Engine, 2004 US EPA Label, 16696 Engine hrs, Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 95 in High Body, Curbside Door, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: 414,813 Mi Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9830	S/N: 1GCWGAFF8H1140875 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 136 in Wheelbase, 6 ft x x 52 in High Body Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX 2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGAFF1H1140622 C/W: GM 4.8 L Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle,
9827A	Asset located In: Humble, TX 1997 Ford E-350 Cargo Van (Inoperable) S/N: 1FTJS34F9VHB85401 C/W: Diesel Engine, Automatic Transmission, Air Conditioner Usage: 344,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Automatic Transmission, 4100 ib Front Axie, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9831A	2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGAFF8H1140410 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 135 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 159,102 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9834	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB0G1148132 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 157,159 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9831	2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGAFF8H1143484 C/W: GM V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245 /75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 73 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9835	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFBXG1126686 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 169,399 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9832	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB8G1126637 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x x 52 in High Body Usage: 173,702 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9836	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB3G1129798 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9833	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB0G1150527 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 158 in Wheelbase, 6 ft x 72 in Wide x 53 in High Body Usage: 138,188 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9837	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFBXG1148025 C/W: Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 6 ft x x 52 in High Body Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB4G1148828 C/W: Gasoline Engine, Automatic Transmission, 245/75R16, Spring Suspension, 152 in Wheelbase, 11 ft x 72 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9839	2015 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGGCB8F1109093 C/W: GM 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 11 ft x 73 in Wide x 51 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9843	2000 Ford E-350 4x2 Ambulance (Inoperable) S/N: 1FDWE35F5YHA30596 C/W: Automatic Transmission, 4600 lb Front Axle, 7500 lb Rears, 10700 lb GVWR, V8 Diesel Engine, 225/75R16, Spring Suspension, 138 in Wheelbase, 12 ft Body Usage: 27,320 Mi Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
9840	2015 Chevrolet Express 2500 Cargo Van	9844	2011 International 4300SBA 4x2 Attenuator
2040	(Inoperable) S/N: 1GCWGGCB3F1108756 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9844	Truck (Inoperable) S/N: 1HTMMAAN2BH322958 C/W: International GDT255 6 Cylinder 7.6 L Diesel 255 hp Engine, 2009 US EPA Label, 8911 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295 /75R22.5, Air Ride Suspension, 272 in Wheelbase, Flatbed, Arrow Board, In-Cab Arrow Board Controller Usage: 177,195 Mi
9841		-	Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS
	 2016 Ram Promaster 4x2 Cargo Van (Inoperable) S/N: 3C6TRVAG1GE114870 C/W: 3.6 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 8550 lb GVWR, 225/75R16, Spring Suspension, 134 in Wheelbase, 10 ft x 		TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	78 in Wide x 66 in High Body, Curbside Door	9845	2016 Dodge Charger Automobile (Inoperable)
9842	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		S/N: 2C3CDXHG6GH302642 C/W: 3.6 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
	(Inoperable)		Asset located in: Humble, TX
	S/N: 1GBKG316191158061 C/W: Automatic Transmission, 4600 lb Front Axle, 9600 lb Rears, 14200 lb GVWR, GM 6.6 L Ultra Low Sulfur Diesel 250 hp Engine, 2009 US EPA Label, Dual Rear Wheel, 225/75R16, Spring Suspension, 160 in Wheelbase, 14 ft Body Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	9846	2016 Infiniti Q50 Automobile (Inoperable) S/N: JN1EV7AP4GM304465 C/W: V6 3.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TITLE COMES WITH REPOSSESSED AFFIDAVIT Asset located in: Humble, TX
	Asset located in: Humble, TX	9847	2014 Chevrolet Malibu Automobile (Inoperable)
			S/N: 1G11B5SL7EF225175 Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9848	2013 Kia Soul 2WD SUV (Inoperable) S/N: KNDJT2A5XD7527218 C/W: 4 cyl 1.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 144,571 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9850	1991 Chevrolet Camaro Automobile (Inoperable) S/N: 1G1FP23TXML136933 C/W: Gasoline Engine, 1991 US EPA Label, Automatic Transmission, Air Conditioner Usage: 135,263 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX
	Asset located in: Humble, TX	9851	1974 MG Classic Car (Inoperable)
9849C	2006 BMW 750i Automobile S/N: WBAHL835X6DT03804 C/W: V8 4.8 L Gasoline Engine, 2006 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation Usage: Not Available Notes: THE TITLE COMES WITH A REPO	-	S/N: GHD5UE345015 C/W: Gasoline Engine, Manual Transmission, Air Conditioner Usage: 78,057 Mi Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX
	AFFIDAVIT NOT ACCEPTED IN THESE STATES	9852	2014 Dodge Grand Caravan SE Minivan
9849B	AZ, FL, NE,NJ,NY, PA,UT Asset located in: Humble, TX	-	(Inoperable) S/N: 2C4RDGCG7ER331894 C/W: 3.6 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
	Usage: Not Available		RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Humble, TX
	THE INSPECTION REPORT	9853	2020 Chevrolet equinox 2WD SUV (Inoperable)
9849A	Asset located in: Humble, TX 2007 BMW 53i Automobile S/N: WBANE73527CM51279 C/W: 6 cyl 3.0 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 152,290 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: 3GNAXLEX8LS705964 C/W: Automatic Transmission, Air Conditioner, Power Windows Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX
	THE INSPECTION REPORT	9854	2017 Chevrolet equinox 2WD SUV (Inoperable)
9849	Asset located in: Humble, TX 2011 Dodge Charger R/T Automobile (Inoperable) S/N: 2B3CL5CT5BH521044 C/W: V8 5.7 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE	-	S/N: 2GNALDEK2H6254199 C/W: 4 cyl 2.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX
	REMOVED FROM THE YARD AND CAN NOT BE	9855	
	RECONSIGNED ; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	000	2015 Infiniti QX60 AWD SUV (Inoperable) S/N: 5N1AL0MM2FC526562 C/W: V6 3.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 173,376 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9857 9858	2011 Infiniti QX56 2WD SUV (Inoperable) S/N: JN8AZ2NF8B9501370 C/W: V8 5.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX 2001 Chevy Tahoe LS 2WD SUV (Inoperable)	9862	2018 Ford F-250 XLT 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2BT9JEB38172 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 8 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TITLE BRAND NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	S/N: 1GNEC13T61R214049 C/W: V8 5.3 L Gasoline Engine, 2001 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX	9863	Asset located in: Humble, TX 2018 Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6UR5HJ2JG348601 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 275 /70R18 Tires, 7 ft 11 in Bed Usage: 138,800 Mi	
9859	59 2017 GMC Sierra 3500HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GT42VCY2HF179435 C/W: 6.6 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Dual Rear Wheel,		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	Spray-On Bed Liner, 13025 lb GVWR, 235 /80R17 Tires, 8 ft Bed Usage: 154,646 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		(Inoperable) S/N: 1FT7W2B62HEC65768 C/W: 6.2 L V8 Gasoline Engine, Automa Transmission, Air Conditioner, Power D Seat, Power Windows, Spray-On Bed Lin 10000.0 lb GVWR, 265/70R17 Tires, 6 f Bed	S/N: 1FT7W2B62HEC65768 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000.0 lb GVWR, 265/70R17 Tires, 6 ft 8 in
9860	2008 Ford F-350 XL 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTSW31R08EE22354 C/W: 6.4 L V8 Diesel Engine, 2008 US EPA Label, Manual Transmission, Tool Box, 10000		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	
	label, Manual Transmission, Foor Box, Foor Ib GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9866	(Inoperable) S/N: 3C6UR5HL0FG601150 C/W: 6.7 L 6 Cylinder Diesel Engine, 20 EPA Label, Automatic Transmission, A	(Inoperable) S/N: 3C6UR5HL0FG601150 C/W: 6.7 L 6 Cylinder Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck
9861	2024 Ford F-250 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT8W2BT2REC24293 C/W: Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Cap, 10000 lb GVWR, 275/70R18 Tires, 11 ft Bed Usage: 252,991 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
9868	2010 Ford F-250 XL 4x2 Pickup (Inoperable) S/N: 1FTNF2A56AEA70133 C/W: 5.4 L Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 8800 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9872	(Inoperable) S/N: 1C6RR6KT3FS570733 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truc Cap, 6900 lb GVWR, 275/60R20 Tires, 5 ft 6 in Bed Usage: 285,201 Mi Notes: THIS INOPERABLE ITEM NEEDS TO B REMOVED FROM THE YARD AND CAN NOT E
9869	2001 Dodge Ram 2500 4x2 Pickup (Inoperable) S/N: 3B7KC26621M275049 C/W: 5.9 L 6 Cylinder Diesel Engine, 2000 US		RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	EPA Label, 5 Speed Manual Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 245/75R16 Tires, 8 ft 2 in Bed Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9873	2011 Ford F-150 XL 4x2 Pickup (Inoperable) S/N: 1FTNF1CF7BKD32647 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Weatherguard Tool Box, Drop-In Bed Liner, 7050 lb GVWR, 235/75R17 Tires, 8 f Bed Usage: 200,602 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9870A	2015 Ford F-150 XL 4x2 Pickup (Inoperable)		
	S/N: 1FTMF1C80FFB83932 C/W: 3.5 L V6 Gasoline Engine, 2015 US EPA		Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, UWS Tool Box, 6010 lb GVWR, 275/55R20 Tires, 6 ft 6 in Bed Usage: 153,343 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9874	2009 Ford F-150 XL 4x4 Extended Cab Pickup (Inoperable) S/N: 1FTPX14V99FB02963 C/W: 5.4 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed
9870	2017 Ford F-150 XL 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTEX1C84HKC50155 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA		Usage: 101,889 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Better Built Tool Box, 6100 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9875	2008 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCEC14C58Z255435 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
9871	2015 Ram 1500 ST 4x2 Crew Cab Pickup (Inoperable) S/N: 1C6RR6KT9FS651199		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 6900 lb GVWR, 275/60R20 Tires, 5 ft 6 in Bed Usage: 237,206 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9876	2007 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCEC14CX7Z520624 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9877A 9877	2018 Chevrolet Colorado 4x2 Extended Cab Pickup (Inoperable) S/N: 1GCHSBEN8J1244066 C/W: 3.6 L Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 5700 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2007 GMC Sierra 1500 4x2 Pickup (Inoperable) S/N: 3GTEC14X67G154695 C/W: 4.3 L V6 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air	9880 9881A 9881A 9881	2015 Wabash RFALHSA 53 ft T/A Refrigerated Trailer (Inoperable) S/N: 1JJV532B4FL840000 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 273,926 Mi Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		2000 Utility 53 ft x 96 in T/A Refrigerated Trailer (Inoperable) S/N: 1UYVS2531YU187916 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires Usage: 15,487 Hr
9878	 878 2003 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCEC14X33Z165549 C/W: 4.3 L V6 Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 		Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
			2014 Utility 53 ft x 102 in T/A Curtain Side Refrigerated Trailer (Inoperable) S/N: 1UYVS2536EM080405 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Serial Number 3419UA0268,, Aluminum Wheels, 295/75R22.5 Tires
9879	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer (Inoperable) S/N: 1GRAA0624GW702913 C/W: Air Ride Suspension, Ducted Floor, Swing Door, Thermo King SB-200 Refrigeration Unit,		Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Serial Number 01467R2023, 295/75R22.5 Tires Usage: 34,720 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9882	2019 Lark VT8520TA 20 ft T/A Enclosed Trailer (Inoperable) S/N: 571BE2024KM032616 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 95 in Deck Width, 102 in Overall Width, Side Door 225/75R15 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
9883	2019 LeeBoy L150 S/A 150 gal Asphalt Distributor Trailer (Inoperable) S/N: 1B9AA1117K1309158 C/W: Double Flue w/ LPG Burners, Hand Spray Wand, Pump w/ Honda Engine, Ball Hitch, Spring Suspension, 225/75R15 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9886	John Deere 2653A Ride-On Lawn Mower (Inoperable) S/N: TC2653D081681 C/W: Hydrostatic Drive, 1995 US EPA Label, 20x10.00x10 Front Tires, 20x10.00x8 Rear Tires Usage: 2,079 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9884B	Asset located in: Humble, TX 2014 John Deere 8700 Precision Cut Ride-On	9887	Cub Cadet Ride-On Lawn Mower (Inoperable) S/N: Not Available
	Fairway Lawn Mower (Inoperable) S/N: 1TC8700XJEF070083 C/W: Canopy, Hydrostatic Drive, 2013 US EPA Label, 26x12.00x12 Front Tires, 20x10.00x8 Rear Tires, 100 in Mower Usage: 3,239 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		C/W: Hydrostatic Drive, 2005 US EPA Label, 23x9.50-12 Rear Tires Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
00044	Asset located in: Humble, TX	9888	Cub Cadet Ride-On Lawn Mower (Inoperable)
9884A	E-Z-Go Electric Golf Cart (Inoperable) S/N: 3036943 C/W: 4 Passenger Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available C/W: Hydrostatic Drive, 2005 US EPA Label, 54 in Mower Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9884	Cushman Utility Cart (Inoperable)		Asset located in: Humble, TX
9885	S/N: 3154020 C/W: Open Operator Station, 2 Passenger Usage: 536 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX John Deere 2653A Ride-On Lawn Mower (Inoperable)	9889	Grasshopper 227 Zero-Turn Lawn Mower (Inoperable) S/N: 6714891 C/W: Hydrostatic Drive, 13x6.5-4.5 Front Tires, 24x12.00-12 Rear Tires, 50 in Mower Usage: 1,210 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: TC2653D090367 C/W: Hydrostatic Drive, 2000 US EPA Label,	0000	Asset located in: Humble, TX
	20X10.00-10 Front Tires, 20X10.00-8 Rear Tires, 72 in Mower Usage: 2,818 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9890	Grasshopper 225 Zero-Turn Lawn Mower (Inoperable) S/N: 6812024 C/W: Hydrostatic Drive, Tier 2, 23.50x10-12 Rear Tires, 50 in Mower Usage: 1,443 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9886A	John Deere F1445 Ride-On Lawn Mower (Inoperable)		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: TC1445D031630 C/W: Hydrostatic Drive, 2003 US EPA Label, 23x10.50x12 Front Tires, 18x8.50x10 Rear Tires, 72 in Mower Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9891	Asset located III: Humble, TX Engine (Inoperable) S/N: 264574 C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9892B	2007 Cat 3406A Engine (Inoperable) S/N: 3ER10114 C/W: 2007 US EPA Label, 6 Cylinder 14.6 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9896	350 kW Skid-Mounted Generator Set (Inoperable) S/N: 465520810 C/W: 8 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
9892A	Cat 3306 Engine (Inoperable)	9897	2012 Miscellaneous Generator 309 kVA Skid-	
	S/N: 7N3375 C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	Mounted Generator Set (Inoperable) S/N: 121002951 C/W: 2011 US EPA Label, John Deere 6090HF484a,B,C 6 Cylinder 315 kW 9.0 L Diesel Engine, 208 V / 480 V Rated Voltage Sound Attenuated, Bottom Mounted Fuel Ta Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO REMOVED FROM THE YARD AND CAN NOT RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	Mounted Generator Set (Inoperable) S/N: 121002951 C/W: 2011 US EPA Label, John Deere 6090HF484a,B,C 6 Cylinder 315 kW 9.0 L Diesel Engine, 208 V / 480 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available	
9892			REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	
			REPORT Asset located in: Humble, TX	
	RECONSIGNED DEFICIENCIES NOTED -	9898	Cummins DQAE5769141 275 kW Skid-	
	PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9090	Mounted Generator Set (Inoperable)	
9893	1999 International A250 Engine (Inoperable) S/N: Not Available C/W: Ford Transmission Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		S/N: 1060970124 C/W: Tier 1, Cummins QSM11-G2 6 Cylinder 470 hp 10.8 L Diesel Engine, /275 kW Rated 3 Phase Output, 139 V / 220 V / 230 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR	
9894	Cat 3508 900 kW Containerized Generator Set		REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	
	(Inoperable)		REPORT	
	S/N: 23Z04466 C/W: Cat 3500 8 Cylinder Diesel Engine		Asset located in: Humble, TX	
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9899	Stand-By Generator Set (Inoperable) S/N: SGM329W7X C/W: 2014 US EPA Label, John Deere 6068HFG82C,E,I 6 Cylinder 6.8 L Diesel E /180 kW Rated 3 Phase Output, 277 V / 4 Rated Voltage, Bottom Mounted Fuel Tar Usage: Not Available	S/N: SGM329W7X C/W: 2014 US EPA Label, John Deere 6068HFG82C,E,I 6 Cylinder 6.8 L Diesel Engine, /180 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage, Bottom Mounted Fuel Tank
9895	Pioneer Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Cat 6 Cylinder Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Asset located in: Humble, TX			

Lot #	Details	Lot #	Details	
9900	Aggreko XBSG200 168 kW Skid-Mounted Generator Set (Inoperable) S/N: Not Available	9904	2012 HiPower HRJW-115.T6 95 kW Skid- Mounted Generator Set (Inoperable) S/N: 111006440	
	C/W: 2013 US EPA Label, Cummins 6 Cylinder 476 hp 6.7 L Diesel Engine, 210 kVA/168 kW Rated 3 Phase Output, 380 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available		C/W: 2012 US EPA Label, John Deere 4045HF285 4 Cylinder 4.5 L Diesel Engine, 115 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 79 kVA,/ Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V &	
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION		120 V Receptacles, Bottom Mounted Fuel Tank Usage: 9,566 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR	
	REPORT Asset located in: Humble, TX		REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
9901	2014 HiPower HRNG 165 164 kVA Skid-		Asset located in: Humble, TX	
	Mounted Generator Set (Inoperable) S/N: U4130086 C/W: 6 Cylinder 8.1 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9905	Multiquip DCA125SSJE 72 kW Skid-Mounted Generator Set (Inoperable) S/N: 7500864 C/W: John Deere 6068TF 6 Cylinder 6.8 L Diesel Engine, 125 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /72 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted	
9902			Fuel Tank Usage: 524 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9906	2011 Magnum MMG150 Skid-Mounted Generator Set (Inoperable) S/N: 1105921	
9903	2011 HiPower HRJW-115 115 kVA Skid- Mounted Generator Set (Inoperable) S/N: 111003335 C/W: 2011 US EPA Label, John Deere 4 Cylinder Diesel Engine, 115 kVA/ Rated 3		6 Cylinder 6.8 L Diesel Engine, /145 kW F Phase Output, 208 V / 480 V Rated Volta 240 V & 120 V Receptacles, Sound Atten Bottom Mounted Fuel Tank Usage: 19,490 Hr	
kVA,/ Rated Single Phase V Rated Voltage, Sound Mounted Fuel Tank	Phase Output, 208 V / 480 V Rated Voltage, 79 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 14,678 Hr		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Notes: THIS INOPERABLE ITEM NEEDS TO BE	9907	Newage 100 kW Skid-Mounted Generator Set	
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		(Inoperable) S/N: Not Available C/W: Perkins 4 Cylinder 4.4 L Diesel Engine, 125 kVA/100 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: Not Available	
			Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
			Asset located in: Humble, TX	

This catalog was created at November 5, 2024 03:25:12 AM GMT. Please check our website for the most accurate and up-to-date information.

Lot #	Details	Lot #	Details
9908A 9908	Onan DFCE-3380744 400 kW Stand-By Generator Set (Inoperable) S/N: J990007923 C/W: Cummins D210 6 Cylinder Diesel Engine, 500 kVA/400 kW Rated 3 Phase Output Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2006 Cummins DGDK 125 kW Stand-By	9911	Cummins 100DGDB 100 kW Mobile Generator Set (Inoperable) S/N: F970640488 C/W: Cummins 6BT5.9 6 Cylinder 166 hp 5.9 L Diesel Engine, 125 kVA/100 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage, 67 kVA, /67 kW, Rated Single Phase Output, 120 V / 208 V Rated Voltage, T/A Trailer, Electric Brakes Usage: 962 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE
	Generator Set (Inoperable) S/N: E060925300 C/W: Cummins 6BTAA5.9-G-1 6 Cylinder 5.9 L Diesel Engine, 156 kVA/125 kW Rated 3 Phase	0012	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	125 kVA,/125 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9912	2018 TechnoGen G60 56 kW Mobile Generator Set (Inoperable) S/N: 16MBB1624HD076464 C/W: 2017 US EPA Label, FPT 4 Cylinder 67 kW Diesel Engine, 70 kVA/56 kW Rated 3 Phase Output, 480 V / 277 V / 208 V Rated Voltage, 52.5 kVA,/42 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Surge Brakes Usage: 16,045 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE
9909	2013 MQ Power 240 kW Mobile Generator Set (Inoperable) S/N: 5SLBG2022DL013736 C/W: 2013 US EPA Label, CARB Compliant,		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Cummins CPL1404 6 Cylinder 399 hp 8.9 L Diesel Engine, 240 V & 120 V Receptacles, Sound Attenuated, T/A Trailer, Ball Hitch, Electric Brakes Usage: 12,600 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED,BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9913	2006 Wacker Neuson G50C 38 kW Mobile Generator Set (Inoperable) S/N: 185945 C/W: 2006 US EPA Label, John Deere 4 Cylinder 50 kW 4.5 L Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 208 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: Not Available
9910	2016 Multiquip DCA220SSJU4F 220 kVA Mobile Generator Set (Inoperable) S/N: 5SLBG1821GL018610 C/W: 2016 US EPA Label, John Deere 6068HFG09 6 Cylinder 6.8 L Diesel Engine,		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Requires Diesel Exhaust Fluid, 220 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9914	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set (Inoperable) S/N: Not Available C/W: 2017 US EPA Label, Isuzu 4 Cylinder Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 2,375 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9915B	2016 Atlas Copco QAS25 20 kW Mobile Generator Set (Inoperable) S/N: 4500G1118GR121153 C/W: 2016 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 270 V / 480 V Rated Voltage, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9917	2010 Taylor TG30 27 kW Skid-Mounted Generator Set (Inoperable) S/N: 23289 C/W: 33 kVA/27 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 21,717 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9915A	Shindaiwa 15KVA 12 kW Mobile Generator Set (Inoperable) S/N: D163019000086 C/W: Tier 4, 2018 US EPA Label, CARB Compliant, Kubota D902-EF01 18.2 kW 0.8 L Diesel Engine, 15 kVA/12 kW Rated 3 Phase Output, 208 V / 220 V / 240 V Rated Voltage, 9 kVA,/9 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, S/A Trailer, Ball Hitch Usage: 3,474 Hr	-9918	Taylor TG30 27 kW Skid-Mounted Generator Set (Inoperable) S/N: 23285 C/W: 2010 US EPA Label, PSI 3.0 L Gasoline Engine, 33 kVA/27 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 15,875 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9919	Taylor TG30 27 kW Generator Set (Inoperable) S/N: 23350 C/W: 2010 US EPA Label, PSI 3.0 L Gasoline Engine, 33 kVA/27 kW Rated 3 Phase Output,
9915	5 2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set (Inoperable) S/N: 4GNBG0910PB066326 C/W: 2015 US EPA Label, Isuzu 4LE2T 4 Cylinder 30 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single		277 V / 480 V Rated Voltage Usage: 16,773 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 9,437 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9920	2012 Taylor TG30 19 kW Skid-Mounted Generator Set (Inoperable) S/N: 24767 C/W: 4 Cylinder Engine, 23 kVA/19 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 33,908 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9916	Marathon 90 kW Skid-Mounted Generator Set (Inoperable)		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 729063 C/W: 8 Cylinder 8.8 L Engine, 113 kVA/90 kW Rated 3 Phase Output, 120 V / 240 V / 480 V Rated Voltage, 66 kVA,/66 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9921	Generac G0072101 24 kW Generator Set (Inoperable) S/N: 3011405698 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9922 9923	Generator Set S/N: 5335344 C/W: 2 Cylinder Natural Gas Engine, /10 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Generac 5528 Skid-Mounted Stand-By Generator Set (Inoperable)	9927 9928A	2010 Ingersoll Rand P185WJD-T4I Air Compressor (Inoperable) S/N: 413641UEUD75 C/W: 200 psi Working Pressure, 2010 US EPA Label, John Deere AJDXL02.4074 4 Cylinder 2.4 L Diesel Engine, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 3,308 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	S/N: 5765553 C/W: 2 Cylinder Natural Gas Engine, 120 V / 240 V Rated Voltage, Sound Attenuated Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		Compressor (Inoperable) S/N: HOP057162 C/W: 125 psi Working Pressure, 2018 US Label, CARB Compliant, Kubota D1803-CF EF02 3 Cylinder 36.5 kW 1.9 L Diesel Engi /A Trailer, Ball Hitch Usage: 2,287 Hr	Compressor (Inoperable) S/N: HOP057162 C/W: 125 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Kubota D1803-CR-TI- EF02 3 Cylinder 36.5 kW 1.9 L Diesel Engine, S /A Trailer, Ball Hitch
9924	Generac 5883 10 kW Skid-Mounted Stand-By Generator Set		THE INSPECTION REPORT Asset located in: Humble, TX	
	S/N: 5569490 C/W: 2 Cylinder Natural Gas Engine, /10 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9928	2004 Ingersoll Rand P185WJDU Skid-Mounted Air Compressor S/N: Not Available C/W: US EPA Label, John Deere 4045DF150 4 Cylinder 4.5 L Diesel Engine Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
9925	2011 Atlas Copco XAS1600CD6 1600 cfm Mobile Air Compressor (Inoperable) S/N: APP188393 C/W: 100 psi Working Pressure, Cat C13 6 Cylinder 328 hp Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES	9929	Quantity of (2) Skid-Mounted Air Compressor (Inoperable) S/N: 29367 C/W: 200 psi Working Pressure, Honda Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	NOTED - PLEASE SEE THE INSPECTION REPORT	9930	Onan Generator Set (Inoperable)	
9926	Asset located in: Humble, TX 2010 Ingersoll Rand XP375WIR-T3 Air Compressor (Inoperable) S/N: 413388UDUC48 C/W: 250 psi Working Pressure, 2010 US EPA Label, John Deere AJDXL06.8117 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 8,982 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9931	S/N: Not Available C/W: 2 Cylinder Gasoline Engine Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in : Humble, TX Westinghouse 4500 Generator Set (Inoperable) S/N: 45A0622B3468 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
9932	Hydraulic Skid-Mounted Power Swivel (Inoperable) S/N: Not Available C/W: Cat C7 6 Cylinder 250 hp Diesel Engine Usage: 2,616 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9937	2010 Pioneer PP66S12L Trailer-Mounted Water Pump (Inoperable) S/N: 12811 C/W: Centrifugal 2012 US EPA Label, Deutz D914L04 4 Cylinder 78 hp 4.3 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 4,282 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9933	Hydraulic Skid-Mounted Power Swivel (Inoperable) S/N: Not Available C/W: Cat C7 6 Cylinder 225 hp Diesel Engine Usage: 1,482 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	-9938	Godwin Pumps Trailer-Mounted Water Pump (Inoperable) S/N: 16MPF06127D050360 C/W: 6 in Intake, 6 in Discharge, Centrifugal 2007 US EPA Label, John Deere 4045DF 4 Cylinder 60 kW 4.5 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9934	Hydraulic Skid Mounted Power Swivel (Inoperable) S/N: Not Available C/W: 2007 US EPA Label, CARB Compliant, John Deere 6090HF 6 Cylinder 9.0 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9939 9940A	Godwin Pumps CD100 Trailer-Mounted Water Pump (Inoperable) S/N: 9410012 C/W: 4 in Intake, 4 in Discharge, Centrifugal 3 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 4,274 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX 2014 Jetstream UNx 4200 Skid Mounted Water Pump (Inoperable) S/N: 4123009
9935	Logan Oil PS365512 Power Swivel (Inoperable) S/N: Not Available C/W: Cummins QSB 6.7 6 Cylinder 240 hp Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9940	C/W: Triplex 6 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Gorman-Rupp 10 in Skid-Mounted Water Pump (Inoperable) S/N: 03GBA383824 C/W: 10 in Intake, 10 in Discharge, Centrifugal Water Pump Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE
9936	Hydraulic Trailer Mounted Power Swivel (Inoperable) S/N: 1M9GU1421CD886022 C/W: Cat C4.4 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT B RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9941	2010 Industrial Vacuum Industrial Vacuum System (Inoperable) S/N: 1D9BV1526AW048060 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Roots Blower, 235/85R16 Tires, 2010 US EPA Label, John Deere 6068HF 6 Cylinder 6.8 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9946	2008 Lincoln Vantage 500 500 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1080210779 C/W: 2008 US EPA Label, Deutz 4 Cylinder 49 hp 3.1 L Diesel Engine, Welding Leads Not Included Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9942	Skid Mounted Hydraulic Power Pack (Inoperable) S/N: Not Available C/W: Kubota 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	-9949A	Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 2014 US EPA Label, 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, 120 V Rated Voltage Usage: 7,523 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9943	2016 Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1160205219 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9950C 9950B	Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 2016 US EPA Label, 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, 120 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Lincoln Electric 500 A Skid-Mounted Multi-
9944	2016 Lincoln Welding Equipment Engine Driven Welder (Inoperable) S/N: U1162025219 C/W: 4 Cylinder Diesel Engine Usage: 708 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,016 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9945	2014 Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141204866 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 8,706 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9950A	Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,664 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9951	2014 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141205934 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 6,367 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9956	2008 Lincoln Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1080705131 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, / 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 1,383 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9952	2014 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141205625 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, 120 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9957	2008 Lincoln Electric 400A 400 A Skid- Mounted Multi-Process (Inoperable) S/N: U1080705136 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 4,886 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9953	Asset located in: Humble, TX 2014 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process (Inoperable) S/N: U1140807442 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 3,822 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9959	2008 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1080907986 C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2008 Lincoln Vantage 400 400 A Skid-Mounted
9954	2014 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141206025 C/W: 4 Cylinder Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,409 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Multi-Process Engine Driven Welder (Inoperable) S/N: U1080210520 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 4,562 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9955	2009 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1090400570 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	-9960	2008 Lincoln Vantage 400 Engine Driven Welder (Inoperable) S/N: U1080210524 C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9962 9963	2007 Lincoln Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1070806989 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Lincoln Electric Vantage 400 400 A Skid-	9967A	2018 Miller Big Blue 500 Pro 500 A Mobile Engine Driven Welder (Inoperable) S/N: MJ011174R C/W: 2017 US EPA Label, CARB Compliant, Kubota V2403 36.0 kW 2.4 L Diesel Engine, 3 Phase, Single Phase, 120 V/ 240 V Input, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 4,211 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1070711281 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,395 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9967	Lincoln RA-250-V1903 300 A Skid-Mounted Engine Driven Welder (Inoperable) S/N: C1080500072 C/W: Tier 4, 2008 US EPA Label, CARB Compliant, Kubota V2003-M-BG-ET02e 4 Cylinder 24.3 kW 2.0 L Diesel Engine, Welding Leads Not Included, 40 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9964A 9964	Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,124 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Lincoln Electric Vantage 400 400 A Skid-	9968A	2019 Lincoln Vantage 549 525 A Mobile Multi- Process Engine Driven Welder S/N: U1190705538 C/W: Tier 4, 2019 US EPA Label, CARB Compliant, Deutz TD 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9968	2018 Lincoln Vantage 350 A Mobile Multi- Process Engine Driven Welder (Inoperable) S/N: U1180103785 C/W: Tier 4, Kubota V1505 4 Cylinder 1.5 L Diesel Engine, 3 Phase, Single Phase, 120 V/ 240 V Input, Welding Leads Not Included, /12.5 kW Rated 3 Phase Output, 240 V Rated Voltage, /11.5 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: 5,256 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE
9966	Lincoln SAE300 300 A Skid-Mounted Stick Engine Driven Welder (Inoperable) S/N: Not Available		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9969A	Lincoln Electric SAE-500 Stick Electric Welder S/N: C1110100084 C/W: Kubota 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: 4,060 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9969	Lincoln Mobile Electric Welder (Inoperable) S/N: Not Available	9976A	Husqvarna FS520 Walk-Behind Saw (Inoperable)
	C/W: Tier 4, 2018 US EPA Label, Kubota V1505 4 Cylinder 1.5 L Diesel Engine, Welding Leads Not Included, S/A Trailer, Ball Hitch Usage: 3,238 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: Not Available C/W: Water Hose Connection, 2016 US EPA Label, Honda GX630 2 Cylinder Gasoline Engine Usage: Not Available
			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
	Asset located in: Humble, TX	9976	2021 Wacker Neuson BS70-4 Jumping Jack Tamper (Inoperable)
9971	2017 Wacker RTLX-SC3 Trench Compactor (Inoperable) S/N: 424284 C/W: 2017 US EPA Label, Kohler 3 Cylinder 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 354 Hr		S/N: 11344031 C/W: 1 Cylinder Gasoline Engine Usage: Not Available
			Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE		Asset located in: Humble, TX
	RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9977D	Allmand Night-Lite NL5000 8 kW Light Tower S/N: 06000788 C/W: Tier 4, 2016 US EPA Label, Kubota 3
9972	2000 Rammax RW-1404MR Trench Compactor (Inoperable)	-	Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,133 Hr
	S/N: 329001 C/W: Hatz 2G40 2 Cylinder Diesel Engine, 33 in Drums Usage: 296 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
		9977C	2005 Magnum 6 kW Light Tower S/N: 057918 C/W: 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch
9973	1998 Rammax RW-1404MR Trench Compactor (Inoperable) S/N: 323528 C/W: Hatz 2G40 2 Cylinder Diesel Engine, 33 in Drums Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED		Usage: 5,481 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
		9977B	2007 Magnum 6 kW Light Tower
			S/N: 5AJLS16117B000424 C/W: Mitsubishi 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 3,222 Hr
	Asset located in: Humble, TX	-	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9974	Rammax Trench Compactor (Inoperable) S/N: Not Available		Asset located in: Humble, TX
	C/W: Hatz 2G40 2 Cylinder Diesel Engine, 33 in Drums Usage: Not Available	9977A	2014 Magnum 6 kW Light Tower S/N: 5AJLS1010EB411223 C/W: 2014 US EPA Label, Mitsubishi L3E 3
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -		Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,898 Hr
	PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9975	Portable Concrete Mixer (Inoperable)	1	Asset located in: Humble, TX
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	S/N: Not Available C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available		
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9977	20500 Lb Truck Mounted Knuckle Boom (Inoperable) S/N: 3221378 C/W: hydraulic outriggers, hydraulic tank Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR	9984B	Quantity of (2) Nobles Speed Scrub Walk- Behind Electric Floor Scrubber (Inoperable) S/N: Not Available C/W: 33 in Working Width Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	9984A	Quantity of Tennant T500E & T600E Electric Floor Scrubber (Inoperable) S/N: T600E11028226/T500E10921735 C/W: T600E, T500E Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9979	REPORT Asset located in: Humble, TX 2012 Wanco WVT3 Solar Message Board (Inoperable) S/N: 5F12S1211C1001024	-	
	C/W: Solar Powered, S/A Trailer, Ball Hitch, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-		Asset located in: Humble, TX
	CORP-COMPANY Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9984	Quantity of (2) Pressure Washer (Inoperable) S/N: Not Available C/W: Electric Operated Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9980A	2007 Allmand Light Tower (Inoperable) S/N: 2761PR		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9980	C/W: Tier 2, 2007 US EPA Label, Kubota D905- BG-ES01 3 Cylinder 0.8 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 4,413 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2000 American Solar Message Board	9985	Quantity of Generator & Pressure Washer (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, DXGNR6500 generator, Generac pressure washer Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9900	(Inoperable)		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1A9BS3313Y2228068 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX	9986	2011 Cat Pumps CT80020 Pressure Washer (Inoperable) S/N: AP3411213 C/W: Yamaha MZ300 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9982	Allison 3000RDSP Automatic Transmission (Inoperable)		Asset located in: Humble, TX
9983	S/N: 30-31570 Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX Eaton Fuller Manual Transmission (Inoperable) S/N: Not Available Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9987	Quantity of (4) DeWalt DXGNR6500 Generator Set (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1	

Lot #	Details	Lot #	Details
9988	Champion 7 kW Mobile Generator Set (Inoperable) S/N: 255230 C/W: Champion 1 Cylinder 389 cc Gasoline Engine, 120 V Receptacles Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9994	2017 Multiquip QP4TH 4 In Trash Water Pump (Inoperable) S/N: 4TH6060 C/W: Honda GX340 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9995	Quantity of (2) Generac T20-S Water Pump
9989	Quantity of Generac Generator & Water Pump (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, XC6500 generator, XC3000P pump Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		(Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0000		9996B	Power Breeze Swamp Cooler (Inoperable)
9990	Quantity of (2) Generac XC3000P Water Pump (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available		S/N: Not Available Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE	9996A	Power Breeze Swamp Cooler (Inoperable)
	RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: Not Available Usage: Not Available
9991	Asset located in: Humble, TX Quantity of Generac Generator & Pump		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	(Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, XC6500 generator, XC3000P pump Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9996	2017 Multiquip QP4TH 4 In Trash Water Pump (Inoperable) S/N: 4TH6073 C/W: Trash Pump, Honda GX340 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9992	2021 Multiquip QP4TH 4 In Trash Water Pump		Asset located in: Humble, TX
	(Inoperable) S/N: 4 TH7610 C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9998	2024 Suihe 203012R 30 ft x 20 ft Storage Building (Unused) S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Humble, TX
		9999	40 ft High Cube Refrigerated Storage Container
9993	Asset located in: Humble, TX 2017 Multiquip QP4TH WPT004 - 4" Trash Water Pump (Inoperable) S/N: 4TH6019 C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		(Inoperable) S/N: TCLU1015955 C/W: 8 ft Wide, 9 ft 6 in High, 2008 Thermo King Magnum 575 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
10000	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8668811 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Carrier 69NT40 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		
10001	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8125943 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Carrier 69NT40 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		
10002	40 ft Refrigerated Storage Container (Inoperable) S/N: Not Available Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		
10003	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TCLU1132252 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Thermo King Magnum-575 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		