

Houston, TX, USA - Nov 5, 2024

Lot #	Details	Lot #	Details
2	1998 Case 570L-XT 4x4 Landscape Loader S/N: JJG0225687 C/W: Open Operator Station, 80 in Bucket, 85 in Box Blade Usage: 7,219 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2015 Cat 420F2IT 4x4 Backhoe Loader S/N: CAT0420FVHWD00240 C/W: Open Operator Station, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 95 in Loader Bucket, Forks, 24 in Backhoe Digging Bucket Usage: 5,953 Hr	8	2019 JCB 3CX 4x4 Backhoe Loader S/N: 2823018 C/W: Open Operator Station, Auxiliary Hydraulics, 87 in Loader Bucket, 12 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 2,228 Hr Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2018 Case 580N Backhoe Loader S/N: JJGN580NVJC750594 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9	2018 Case 580N 4x4 Loader Backhoe Backhoe Loader
3	2011 Cat 420E 4x4 Backhoe Loader S/N: CAT0420ETDJL01215 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Control Pattern Changer, 94 in		S/N: JJGN580NAJC750516 Usage: Not Available Asset located in: Humble, TX
	Loader Bucket, 24 in Backhoe Digging Bucket Usage: 4,834 Hr Asset located in : Humble, TX	10	2016 Case 580N 4x4 Backhoe Loader S/N: JJGN580NCGC730093 C/W: Open Operator Station, Backhoe Pilot
4	2010 Cat 420E IT 4x4 Backhoe Loader S/N: CAT0420EVDAN00286 C/W: Open Operator Station, Control Pattern Changer, Auxiliary Hydraulics, Hydraulic Coupler, 94 in Loader Bucket, Extendable Stick, 24 in Backhoe Digging Bucket	11	Controls, Control Pattern Changer, Requires Diesel Exhaust Fluid, Manual Coupler, 81 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 1,127 Hr Asset located in: Humble, TX
	Usage: 3,006 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2014 Case 580N 4x4 Backhoe Loader S/N: JJGN580NLEC700996 C/W: Open Operator Station, Backhoe Pilot Controls, 83 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics
5	2014 Cat 416F Backhoe Loader S/N: CAT0416FKKSF01678 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6	2010 Case 590SM 4x4 Backhoe Loader		Asset located in: Lake Worth, TX
	S/N: JJGN590PHAC532537 C/W: Open Operator Station, Ride Control, Backhoe Pilot Controls, 92 in Multi-Purpose Loader Bucket, 24 in Backhoe Digging Bucket, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	12	2014 Case 580SN 4x4 Backhoe Loader S/N: JJGN58SNEFC720697 C/W: Enclosed Cab, Air Conditioner, Backhoe Pilot Controls, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 82 in Multi-Purpose Loader Bucket, Quick Coupler, 12 in Backhoe Digging Bucket, 24 in Bucket, Rear Auxiliary Hydraulics Usage: 2,509 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		13	2015 Case 580E Backhoe Loader S/N: J7GN58EPKFL716071 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
14	2011 John Deere 310J 4x4 Backhoe Loader S/N: 1T0310JKBD203454 C/W: Enclosed Cab, Air Conditioner, 86 in Loader Bucket, 36 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics, Thumb Bracket Usage: 3,855 Hr Asset located in: Humble, TX 2011 John Deere 310J Backhoe Loader	23	2003 John Deere 310G Backhoe Loader S/N: T0310GX912824 Usage: Not Available
		OED	Asset located in: Humble, TX
		25B	1997 John Deere 310E Backhoe Loader S/N: T0310EX830601
15		_	Usage: Not Available
10	S/N: 1T0310JXLB0201525		Asset located in: Humble, TX
	Usage: Not Available	25A	1992 Cat 416 4x2 Backhoe Loader S/N: 5PC15031
16	Asset located in: Humble, TX	_	C/W: Open Operator Station, 89 in Loader
16	2012 Volvo BL60B 4x4 Backhoe Loader S/N: VCE0B60BP02121355		Bucket, 24 in Backhoe Digging Bucket Usage: 4,526 Hr
	C/W: Open Operator Station, Manual Coupler,		Asset located in: Humble, TX
	87 in Loader Bucket, 22 in Backhoe Cleanup Bucket, Hydraulic Hammer	25	1997 Cat 416C Backhoe Loader
	Usage: Not Available		S/N: 4ZN02033
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	27	2015 John Deere 310KE 4x2 Backhoe Loader
17	2005 Cat 420D 4x4 Backhoe Loader S/N: CAT0420DLBLN12904 C/W: Open Operator Station, Backhoe Pilot Controls, Forks Usage: 5,937 Hr Asset located in: Humble, TX	2/	S/N: 1T0310EKKFG276262 C/W: Open Operator Station, Air Ride Seat, Powershift Transmission, Manual Coupler, 8 in Loader Bucket, Quick Coupler, 15 in Backl Digging Bucket, Rear Auxiliary Hydraulics Usage: 2,569 Hr
		_	Asset located in: Humble, TX
18	2002 Cat 420D Backhoe Loader S/N: CAT0420DAFDP08422 Usage: Not Available Asset located in: Humble, TX	28	2014 Case 580 Super N 4x2 Backhoe Loade S/N: JJGN580NLEC701386 C/W: Open Operator Station, Air Ride Seat, Backhoe Pilot Controls, Powershift
19	2007 Cat 416E 4x4 Backhoe Loader S/N: CAT0416ELSHA03427 C/W: Open Operator Station, 88 in Loader Bucket, Quick Coupler, 22 in Backhoe Digging Bucket		Transmission, 81 in Loader Bucket, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: 3,201 Hr Asset located in: Humble, TX
	Usage: Not Available	29	2008 John Deere 310J 4x2 Backhoe Loader S/N: T0310JX154217 C/W: Open Operator Station, Powershift
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		
20	2005 John Deere 710G Backhoe Loader S/N: T0710GX946489		Transmission, 2007 US EPA Label, 84 in Loader Bucket, 17 in Backhoe Digging Bucket Usage: 2,022 Hr
	Usage: Not Available	30	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
21	2008 John Deere 310J 4x4 Backhoe Loader S/N: T0310JX163704 C/W: Open Operator Station, 86 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics Usage: Not Available Asset located in: Humble, TX		2007 John Deere 310J 4x2 Backhoe Loader S/N: T0310JX143255 C/W: Open Operator Station, Backhoe Pilot Controls, 2007 US EPA Label, Manual Coupler, 84 in Loader Bucket, Quick Coupler, 24 in Backhoe Digging Bucket, Rear Auxiliary Hydraulics
22	2007 John Deere 310G 4x4 Backhoe Loader		Usage: Not Available
	S/N: T0310GX962137 C/W: Open Operator Station, 86 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: Not Available		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		
	Addet located III. Hallible, TA	I	

Details	Lot #	Details
Case 580 Super E 4x2 Backhoe Loader S/N: 9076692 C/W: Open Operator Station, Backhoe Pilot Controls, Manual Coupler, 81 in Loader Bucket, 23 in Backhoe, Manual Thumb Usage: 3,493 Hr	39	2021 LiuGong CLG890H Wheel Loader S/N: CLG890HZVML691006 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 136 in Bucket, 29.5-25 Tires Usage: 3,524 Hr Asset located in: Humble, TX
·	40	•
S/N: N6C400616 C/W: Open Operator Station, 81 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 3,423 Hr		2020 LiuGong CLG890H Wheel Loader S/N: CLG890HZHLL620715 Usage: Not Available Asset located in: Humble, TX 2008 Cat 980H Wheel Loader
Asset located in: Humble, IX	⊣ ™	S/N: CAT0980HJJMS04349
2021 Komatsu WA600-8 Wheel Loader S/N: 80280		Usage: Not Available Asset located in: Humble, TX
C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Traction Control, Requires Diesel Exhaust Fluid, Manual Coupler, 11.0 cyd 148 in Bucket, Auto Lube, 35/65R33 Tires Usage: 17,868 Hr Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	42	2015 Cat 972M Wheel Loader S/N: CAT0972MCA8P00498 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Requires Diesel Exhaust Fluid, 126 in Bucket, Auto Lube, 26.5-25 Tires Usage: 16,534 Hr Asset located in: Humble, TX
Asset located in: Midland, TX	46	2015 Cat 966M Wheel Loader
2018 John Deere 844K-III Wheel Loader S/N: 1DW844KCPJF691184 Usage: Not Available Asset located in: Humble, TX 2020 Doosan DL550-5 Wheel Loader S/N: DWGCWLBL II 1010264		S/N: CAT0966MJKJP01123 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick Steering, Requires Diesel Exhaust Fluid, 26.5- 25 Tires Usage: 7,584 Hr Asset located in: Humble, TX
C/W: Enclosed Cab, Air Conditioner, Rear View	40	
Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Manual Coupler, 136 in Bucket, Auto Lube, 29.5-25 Tires Usage: 3,302 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	48	2020 Volvo L110H Wheel Loader S/N: VCEL110HL0S631821 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, 23.5-25 Tires, Hydraulic Coupler, 118 in Bucket, Forks Usage: 5,534 Hr Notes: LOCATED-IN-EL PASO-TX; COMES
Asset located in: Humble, TX 2015 Cat 980M Wheel Loader		WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
S/N: CAT09080MEKRS0327		Asset located in: El Paso, TX
Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, 144 in Spade Nose Bucket, 29.5R25 Tires Usage: 11,389 Hr	49	2012 Komatsu WA380-7 Wheel Loader S/N: KMTWA118J36A64030 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 23.5R25 Tires Usage: 26,767 Hr
2018 Volvo L180H Wheel Loader		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
Usage: 5,270 Hr		Asset located in: Humble, TX
Asset located in: Humble, TX 2017 Case 1121G Wheel Loader S/N: NHF240450 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 144 in Bucket, Auto Lube, 26.5-25 Tires Usage: 6,394 Hr Asset located in: Humble, TX	50	2021 LiuGong CLG856H Wheel Loader S/N: CLG856HZJML691261 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 115 in Bucket, 23.5R25 Tires Usage: 2,551 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Case 580 Super E 4x2 Backhoe Loader S/N: 9076692 C/W: Open Operator Station, Backhoe Pilot Controls, Manual Coupler, 81 in Loader Bucket, 23 in Backhoe, Manual Thumb Usage: 3,493 Hr Asset located in: Humble, TX 2006 Case 580M Series 2 4x2 Backhoe Loader S/N: N6C400616 C/W: Open Operator Station, 81 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 3,423 Hr Asset located in: Humble, TX 2021 Komatsu WA600-8 Wheel Loader S/N: 80280 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Traction Control, Requires Diesel Exhaust Fluid, Manual Coupler, 11.0 cyd 148 in Bucket, Auto Lube, 35/65R33 Tires Usage: 17,868 Hr Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX 2018 John Deere 844K-III Wheel Loader S/N: 1DW844KCPJF691184 Usage: Not Available Asset located in: Humble, TX 2020 Doosan DL550-5 Wheel Loader S/N: DWGCWLBLJL1010264 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Manual Coupler, 136 in Bucket, Auto Lube, 29.5-25 Tires Usage: 3,302 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Cat 980M Wheel Loader S/N: CAT09080MEKRS0327 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, 144 in Spade Nose Bucket, 29.5R25 Tires Usage: 11,389 Hr Asset located in: Humble, TX 2018 Volvo L180H Wheel Loader S/N: VCEL180HE00005001 Usage: 5,270 Hr Asset located in: Humble, TX 2017 Case 1121G Wheel Loader S/N: WFEL180HE00005001 Usage: 6,394 Hr Asset located in: Humble, TX	Case 580 Super E 4x2 Backhoe Loader S/N: 9076692 C/W: Open Operator Station, Backhoe Pilot Controls, Manual Coupler, 81 in Loader Bucket, 23 in Backhoe, Manual Thumb Usage: 3,493 Hr Asset located in: Humble, TX 2006 Case 580M Series 2 4x2 Backhoe Loader S/N: N6C400616 C/W: Open Operator Station, 81 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 3,423 Hr Asset located in: Humble, TX 2021 Komatsu WA600-8 Wheel Loader S/N: 80280 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Traction Control, Requires Diesel Exhaust Fluid, Manual Coupler, 11.0 cyd 148 in Bucket, Auto Lube, 35/65R33 Tires Usage: 17,868 Hr Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX 2018 John Deere 844K-III Wheel Loader S/N: 1DW844KCPJF691184 Usage: Not Available Asset located in: Humble, TX 2020 Doosan DL550-5 Wheel Loader S/N: DWGCWLBLJL1010264 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Manual Coupler, 136 in Bucket, Auto Lube, 29.5-25 Tires Usage: 3,302 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Cat 980M Wheel Loader S/N: CAT09080MEKRS0327 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Joystick Steering, Requires Diesel Exhaust Fluid, 144 in Spade Nose Bucket, 29.5R25 Tires Usage: 11,389 Hr Asset located in: Humble, TX 2018 Volvo L180H Wheel Loader S/N: VCEL180HE00005001 Usage: 5,270 Hr Asset located in: Humble, TX 2017 Case 1121G Wheel Loader S/N: NHF240450 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 144 in Bucket, Auto Lube, 26.5-25 Tires Usage: 6,394 Hr

Lot #	Details	Lot #	Details
52	2022 Komatsu WA320-8 Wheel Loader S/N: KMTWA135JNA086688 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2022 US EPA Label, Hydraulic Coupler, 108 in Bucket, Forks, 20.5 R25 Tires Usage: 4,504 Hr	60	2017 Komatsu WA270-8 Wheel Loader S/N: KMTWA136CGA083044 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2016 US EPA Label, Hydraulic Coupler, 186 in Bucket, 20.5R25 Tires Usage: 22,331 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX		THE INSPECTION REPORT
53	2021 LiuGong CLG848H Wheel Loader		Asset located in: Humble, TX
	S/N: CLG848HZJML691727 Usage: Not Available Asset located in : Humble, TX	61	2014 Cat 930K Wheel Loader S/N: CAT0930KLRHN02781 C/W: Enclosed Cab, Air Conditioner, Rear View
54	2010 John Deere 624 K Wheel Loader S/N: 1DW624KZEA0631664 C/W: Enclosed Cab, Air Conditioner, 2010 US EPA Label, Manual Coupler, Forks, 20.5R25 Tires Usage: 24,584 Hr		Camera, Air Ride Seat, 2013 US EPA Label, Auxiliary Hydraulics, Hydraulic Coupler, 100 in Bucket, Forks, 20.5R25 Tires, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 9,005 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	62	2014 Cat 930K Wheel Loader
55	2016 Volvo L90H Wheel Loader S/N: L90HV623361 C/W: Enclosed Cab, Air Conditioner, 2015 US		S/N: CAT0930KKRHN03602 Usage: Not Available
	EPA Label, Requires Diesel Exhaust Fluid,		Asset located in: Humble, TX
	Hydraulic Coupler, 108 in Bucket, 20.5R25 Tires Usage: 8,006 Hr Notes: LOCATED-IN-EL PASO-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.	63	2014 Cat 930K Wheel Loader S/N: CAT0930KTRHN03712 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA_TX
	Asset located in: El Paso, TX	-	Asset located in: Livingston, LA
56	2014 Volvo L90G Wheel Loader S/N: VCE0L90GA0S617371 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 2014 US EPA Label, 20.5R25 Tires, 104 in Bucket Usage: 8,802 Hr Notes: LOCATED-IN-EL PASO-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.	64	2018 Case 621G Wheel Loader S/N: NJF243988 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 102 in Bucket, 20.5R25 Tires Usage: 9,999 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$9,800.00
	Asset located in: El Paso, TX		Asset located in: Humble, TX
57	2013 Volvo L90G Wheel Loader S/N: VCE0L90GC00004006 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Positive Air Shutoff, Manual Coupler, Pipe Forks, 20.5R25 Tires Usage: Not Available Asset located in: Humble, TX	65 	2010 John Deere 544 K Wheel Loader S/N: 1DW544KZKA0631756 C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 3 cyd 104 in Bucket, 20.5R25 Tires Usage: 13,725 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
58	2006 Volvo L90E Wheel Loader S/N: L90EV67684	-	Asset located in: Humble, TX
	C/W: Enclosed Cab, Air Conditioner, 102 in Bucket, 20.5R25 Tires Usage: 2,124 Hr	66	2021 LiuGong CLG835H Wheel Loader S/N: CLG835HZPML691208 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	67	2010 Komatsu WA250-6 Wheel Loader
59	2016 Case 721F High Lift Wheel Loader S/N: NGF235686 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Autoshift, Requires Diesel Exhaust Fluid,	67	S/N: KMTWA103V01075463 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 100 in Bucket, Forks, 20.5R25 Tires
	Hydraulic Coupler, 20.5R25 Tires Usage: 4,087 Hr Asset located in : Humble, TX		Usage: 17,972 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE

Lot #	Details	Lot #	Details
68	2007 Komatsu WA250-5 Wheel Loader S/N: KMTWA055E57A74458 C/W: Open Operator Station, Hydraulic Coupler, 102 in Bucket, 20.5-25 Tires Usage: 13,486 Hr Asset located in: Humble, TX	75	2003 John Deere 444H Wheel Loader S/N: DW444HX585856 C/W: Enclosed Cab, Air Conditioner, 2002 US EPA Label, 1.9 m3 94 in Bucket, 17.5-25 Tires Usage: 7,076 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
69	2014 Case 521F Wheel Loader S/N: NEF224229		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 20.5R25 Tires Usage: 525 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX	76	2017 CMI C550 Tracked Mulcher Tractor S/N: C550/GBJ01604 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Rear View Camera, 30 in Track Belts, 2017, FAE 500/U-250/C GB C450 10 ft 3 in, Mulcher Usage: 434 Hr
70	2020 Hitachi ZW50 Wheel Loader S/N: RYUNBD60A00005040		Notes: HOURS NOT REFLECTING ACTUAL HOURS Asset located in: Humble, TX
	C/W: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 66 in Bucket, 15.5/60-18 Tires Usage: 1,439 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	77	Blount 721E 4x4 Mulcher Tractor S/N: HA18652 C/W: Enclosed Cab, Air Ride Seat, FECON 8 ft 4 in, Mulcher
	Asset located in: Humble, TX		Usage: 12,001 Hr
71	2024 TRANER TR45 Wheel Loader (Unused) S/N: TR45240871 C/W: Open Operator Station, Manual Coupler, 39 in Bucket, 23x8.50-12 Tires Usage: Not Available Asset located in: Humble, TX	78	Asset located in: Humble, TX 2016 Cat 14M Motor Grader S/N: CAT0014MAR9J01752 C/W: Enclosed Cab, Air Conditioner, 16 ft / 4.88 m Moldboard, Combination Ripper /Scarifier, 20.5R25 Tires, EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE
72	2024 TRANER TR45 Wheel Loader (Unused) S/N: TR45240805		Usage: 1,195 Hr Asset located in: Humble, TX
	C/W: Open Operator Station, Manual Coupler, 39 in Bucket, 23x8.50-12 Tires Usage: Not Available Asset located in : Humble, TX	83 2014 Cat 140M2 VHP Plus Motor Grader S/N: CAT0140MHM9D01713 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Differential Loc 14 ft / 4.27 m Moldboard w/ 14 ft Extension, Push Block, Combination Ripper/Scarifier, 17 R25 Tires Usage: 8,318 Hr	
73A	2002 Cat 972G Wheel Loader S/N: CAT0972GE7LS00453 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 118 in Bucket, 26.5-25 Tires Usage: 22,738 Hr		14 ft / 4.27 m Moldboard w/ 14 ft Extension, Push Block, Combination Ripper/Scarifier, 17.5 R25 Tires
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	90	2016 Case 865B Motor Grader S/N: HBZN0865HGAF05510
	Asset located in: Humble, TX	4	C/W: Enclosed Cab, Air Conditioner, 12 ft /
73	2002 Cat 972G Wheel Loader S/N: CAT0972GJ7LS00461 C/W: Enclosed Cab, Air Conditioner, Command Control Steering, 128 in Bucket, 26.5-25 Tires Usage: 14,089 Hr		3.66 m Moldboard w/ 14 ft Extension, Front Auxiliary Hydraulics, Accumulators, Rear Auxiliary Hydraulics, 17.5-25 Tires Usage: 3,579 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	91	2016 Sany SMG200 Motor Grader
74	1993 Cat 936F Wheel Loader S/N: 8AJ01225 C/W: Enclosed Cab, 103 in Bucket, 20.5-25 Tires Usage: 13,401 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$5,700.00 Asset located in: Humble, TX		S/N: PY12200146 C/W: Enclosed Cab, Differential Lock, US EPA Label, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5-25 Tires Usage: 1,964 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
92	2000 Cat 160H Motor Grader S/N: 9EJ00851 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Combination Ripper/Scarifier, 17.5-25 Tires, EQUIPMENT- FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 20,645 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	102	2017 Volvo A45G Articulated Dump Truck S/N: VCE0A45GH00342035 C/W: Air Conditioner, Retarder, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, Auto Lube, 750/65R25 Tires Usage: 8,943 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT; LOT CAN BE BLAST & PAINTED FOR \$6,200.00	103	2015 Cat 745C Articulated Dump Truck S/N: CAT0745CETFK00507
94	Asset located in: Humble, TX 2004 Cat 140H VHP Plus Motor Grader S/N: CAT0140HJAPM01777 C/W: Enclosed Cab, Air Conditioner, 14 ft / 4.27 m Moldboard, Push Block, Ripper, 14.00	104	C/W: Air Conditioner, Retarder, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner, 29.5R25 Tires Usage: 11,591 Hr Asset located in: Humble, TX
	R24 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2020 John Deere 410E Articulated Dump Truck S/N: 1DW410ETALF705056 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires
95	1999 Cat 12H Motor Grader S/N: 4XM02120 C/W: Enclosed Cab, 14 ft / 4.27 m Moldboard,	105	Usage: 6,039 Hr Asset located in: Humble, TX 2018 John Deere 410E Articulated Dump Truck
	Combination Ripper/Scarifier, 17.5-25 Tires Usage: 8,958 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1DW410ETAHF683907 C/W: Air Conditioner, Retarder, Rear View Camera, Requires Diesel Exhaust Fluid, Heated Body, Tailgate, Steel Body Liner, 875/65R29 Tires
97	1992 Cat 120G Motor Grader S/N: 4HD01643		Usage: 5,365 Hr Asset located in: Humble, TX
	C/W: Enclosed Cab, 12 ft / 3.66 m Moldboard, Mid Mount Scarifier, 13.00-24 Tires Usage: Not Available Notes: LOT CAN BE BLAST & PAINTED FOR \$5,100.00 Asset located in: Humble, TX	106	2016 John Deere 410E Articulated Dump Truck S/N: 1DW410ET0GF674161 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Tailgate, 29.5 R25 Tires Usage: 9,996 Hr
98	2018 Cat 621K Motor Scraper S/N: CAT0621KPWTA00132 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 33.25R25 Tires Usage: 7,629 Hr Asset located in: Humble, TX	107	Asset located in: Humble, TX 2015 Volvo A40G Articulated Dump Truck S/N: VCE0A40GL00340887 C/W: Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, Tailgate, Auto Lube, 29.5R25 Tires Usage: 9,383 Hr Asset located in: Humble, TX
100	2017 Bell B50D Articulated Dump Truck S/N: B93A350DT07505419 C/W: Air Conditioner, Requires Diesel Exhaust Fluid, Tailgate, 875/65R29 Tires Usage: 8,729 Hr Asset located in: Humble, TX	108	2016 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016PFD010195 C/W: Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 29.5
101	2015 Bell B50D Articulated Dump Truck S/N: B93A350DC07505412 C/W: Air Conditioner, Retarder, 2013 US EPA		R25 Tires Usage: 10,883 Hr Asset located in : Humble, TX
	Label, Steel Body Liner, Auto Lube, 875/65R29 Tires Usage: 7,667 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	109	2016 Komatsu HM400-5 Articulated Dump Truck S/N: KMTHM016LFD010237 C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner, 29.5R25 Tires Usage: 10,133 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
110	2020 John Deere 310E Articulated Dump Truck S/N: 1DW310EXJLF708128 C/W: Air Conditioner, Retarder, 2020 US EPA Label, Tailgate, 23.5R25 Tires Usage: 4,355 Hr Asset located in: Humble, TX	118	2007 John Deere 400D Articulated Dump True S/N: BE400DT201795 C/W: Air Conditioner, Air Ride Seat, Tailgate, 29.5R25 Tires Usage: 25,724 Hr Notes: LOT CAN BE BLAST & PAINTED FOR
111	2021 Bell B30E Articulated Dump Truck S/N: B93A631EL0310030		\$9,400.00 Asset located in: Humble, TX
	C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2022 US EPA Label, Requires Diesel Exhaust Fluid, Auto Lube, 23.5 R25 Tires Usage: 3,532 Hr Asset located in : Humble, TX	119	2010 Terex TA30 Articulated Dump Truck S/N: A8971247 C/W: Air Conditioner, Air Ride Seat, 2010 US EPA Label Usage: 5,399 Hr Notes: LOT CAN BE BLAST & PAINTED FOR
112	2021 Bell B30E Articulated Dump Truck S/N: B93A631EE03010029		\$9,400.00 Asset located in : Humble, TX
	C/W: Air Conditioner, Retarder, Rear View Camera, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Auto Lube, 23.5 R25 Tires Usage: 3,429 Hr Asset located in : Humble, TX	120	2006 Terex TA30 Articulated Dump Truck S/N: A8941556 C/W: Air Ride Seat, Steel Body Liner, 23.5R25 Tires Usage: 40,191 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
113	2021 Bell B30E Articulated Dump Truck S/N: B93A631EJ03010023		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 23.5R25 Tires Usage: 4,530 Hr Asset located in : Humble, TX	121	2018 Morooka MST-1500VD Crawler Carrier S/N: A1505021 C/W: Enclosed Cab, Requires Diesel Exhaust Fluid, 9 ft 8 in Long x 3 ft High Flatbed Dump
114	2021 Bell B30E Articulated Dump Truck	1	Body, 26 in Rubber Tracks Usage: 1,356 Hr
	S/N: B93A631EH03010031		Asset located in: Humble, TX
	C/W: Air Conditioner, Engine Brake, Air Ride Seat, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Auto Lube, 23.5R25 Tires Usage: 4,255 Hr Asset located in: Humble, TX	122	2013 Morooka MST-1500VD Crawler Carrier S/N: A150107 C/W: Enclosed Cab, Air Conditioner, 7 ft Wide x 9 ft 6 in Long Flatbed, 24 in Rubber Tracks Usage: Not Available
115	2016 Cat 730C Articulated Dump Truck S/N: CAT0730CCTFF01310 C/W: Air Conditioner, Retarder, Rear View		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Camera, 2015 US EPA Label, Tailgate, Steel Body Liner, 23.5R25 Tires Usage: Not Available Asset located in : Humble, TX	124	IHI IC45-2 Crawler Carrier Flatbed Dump S/N: CE000796 C/W: Canopy, 10 ft Long Flatbed Dump Body,
116	2011 John Deere 400D Series II Articulated Dump Truck		23 in Rubber Tracks Usage: 1,510 Hr Asset located in : Humble, TX
	S/N: 1DW400DXHBD637782 C/W: Air Conditioner, Retarder, 2011 US EPA Label, Tailgate, 29.5R25 Tires Usage: 10,853 Hr	125	2013 John Deere 700K LGP Pipelayer w/ 2013 Midwestern M540 Conversion S/N: 1T0700KXTDE240484
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Canopy, 3 Lever Boom Control, 30 in Single Grouser Track Shoes, Hydraulic Hoists Usage: 1,345 Hr
117	2007 John Deere 400D Articulated Dump Truck S/N: DW400DT613796 C/W: Air Conditioner, Retarder, Tier 3, Tailgate, 29.5R25 Tires Usage: 24,962 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$9,400.00 Asset located in: Humble, TX	126	Asset located in: Humble, TX 2012 John Deere 700K LGP Pipelayer w/ 2012 Midwestern M540 Conversion S/N: 1T0700KXKCE231012 C/W: Canopy, 3 Lever Boom Control, 30 in Single Grouser Track Shoes, Hydraulic Hoists Usage: 1,877 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
127	2012 John Deere 700k LGP Pipelayer w/ 2012 Midwestern M540 Conversion S/N: 1T0700KXHCE230077 C/W: Canopy, 3 Lever Boom Control, 30 in Single Grouser Track Shoes, Hydraulic Hoists, Hydraulic Extendable Counterweight Usage: 1,393 Hr Asset located in: Humble, TX 2018 Komatsu D155AX-8 Crawler Dozer S/N: KMT0D126LHC100160 C/W: Enclosed Cab, Air Conditioner, Rear View	134	2021 Cat D6 LGP Crawler Dozer S/N: CAT000D6EKEW01021 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, Sweeps, 158 in Wide Semi-U Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 4,828 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$8,700.00 Asset located in: Humble, TX
	Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 208 in Wide Semi-U Blade 28 in Single Grouser Track Shoes, Counterweight Usage: 18,809 Hr Asset located in: Humble, TX	135	2021 Cat D6 Crawler Dozer S/N: CAT000D6JSA901012 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 2021 US EPA Label,
129	2012 Komatsu D155AX-6 Crawler Dozer S/N: KMTDD074PC2081273 C/W: Enclosed Cab, 162 in Wide Straight Blade w/ Dual Tilt, 22 in Single Grouser Track Shoes, 2 Cylinder Single-Shank Ripper Usage: Not Available		Requires Diesel Exhaust Fluid, 127 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, Drawbar, Rear Auxiliary Hydraulics Usage: 5,040 Hr Asset located in: Humble, TX
130A	Asset located in: Humble, TX 2012 Cat D8T Crawler Dozer S/N: CAT00D8TAMLN00675 C/W: Enclosed Cab, Air Conditioner, 156 in Wide Semi-U Blade w/ Single Tilt, 24 in Single Grouser Track Shoes, 4 Cylinder Single-Shank Ripper w/Hydraulic Pin Puller Usage: 15,228 Hr	136	2021 Cat D6 LGP Crawler Dozer S/N: CAT000D6JKEW00488 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 152 in Wide Semi-U Blade Single Grouser Track Shoes, Winch Usage: 5,416 Hr Asset located in: Humble, TX
130	Asset located in: Humble, TX 2019 Cat D8T Crawler Dozer S/N: CAT00D8TLAW400863 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 154 in Wide Semi-U Blade w/ Single Tilt, 26 in Single Grouser Track Shoes Usage: 5,261 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; LOT CAN BE BLAST & PAINTED FOR \$10,346.00	e	2020 Cat D6 LGP Crawler Dozer S/N: CAT000D6VKEW00462 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 151 in Wide Straight Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Drawbar Usage: 4,257 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$8,700.00 Asset located in: Humble, TX
133	Asset located in: Humble, TX 2021 Cat D7 LGP Crawler Dozer S/N: CAT00D7AHPM00155 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 166 in Wide U-Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, Counterweight, Drawbar, Rear Auxiliary Hydraulics Usage: 1,853 Hr	140	2016 Cat D6N LGP Crawler Dozer S/N: CAT00D6NVMG500574 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Pre-Wired for Grade Control, Sweeps, 154 in Wide PAT Blade, 34 in Single Grouser Track Shoes, Drawbar Usage: 10,344 Hr Asset located in: Humble, TX 2020 Cat D5 Crawler Dozer
	Notes: LOT CAN BE BLAST & PAINTED FOR \$9,200.00 Asset located in: Humble, TX		S/N: CAT000D5KZ6A00289 Usage: 2,895 Hr Asset located in : Humble, TX
		142	2015 Cat D6N XL Crawler Dozer S/N: CAT0066NCPER01072 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 122 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 10,608 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
143	2019 Cat D7E LGP Crawler Dozer S/N: CAT00D7EESSH00503 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Pre-Wired for Grade Control, 178 in Wide Semi-U Blade w/ Single Tilt, 36 in Single Grouser Track Shoes Usage: 3,396 Hr	150	2018 Komatsu D61EXI-24 Crawler Dozer S/N: KMT0D129HJBB60661 C/W: Enclosed Cab, Air Conditioner, 126 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: 9,951 Hr Asset located in: Humble, TX
	Notes: LOT CAN BE BLAST & PAINTED FOR \$9,200.00 Asset located in: Humble, TX	151	2018 Komatsu D61EXI-24 Crawler Dozer S/N: KMT0D129HJBB60580
144	2011 Cat D7E Crawler Dozer S/N: CAT00D7EATAN00415 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Sweeps, 168 in Wide Angle Blade w/ Dual Tilt, 24 in Single Grouser Track Shoes, Winch,		C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 128 in Wide PAT Blade, 24 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Rear Auxiliary Hydraulics Usage: 8,606 Hr Asset located in: Humble, TX
	Rear Auxiliary Hydraulics Usage: 827 Hr Asset located in : Humble, TX	152	2018 Dressta TD-15R Crawler Dozer S/N: LDM15RLGKJP000290
145	2020 Komatsu D65WX-18 Crawler Dozer		Usage: Not Available Asset located in : Humble, TX
	S/N: KMT0D127LKA091990 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, Auto Lube, 154 in Wide PAT Blade, 30 in Single Grouser Track Shoes, 1 Cylinder Multi- Shank Ripper Usage: 6,375 Hr	153	2018 John Deere 750K LGP Crawler Dozer S/N: 1T0750KXTJF327146 C/W: Enclosed Cab, Air Conditioner, 149 in Wide PAT Blade, 33.5 in Single Grouser Track Shoes Usage: 11,284 Hr Asset located in: Humble, TX
146	Asset located in: Humble, TX 2018 Komatsu D65EX-18 Crawler Dozer	154	2016 Liebherr PR 716 XL Crawler Dozer
140	S/N: KMT0D127PGA090580 C/W: Enclosed Cab, Air Conditioner, US EPA Label, Requires Diesel Exhaust Fluid, Sweeps, 151 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Drawbar, Rear Auxiliary Hydraulics Usage: 2,794 Hr	104	S/N: 1422-15404 C/W: Enclosed Cab, Air Conditioner, Pre-Wired for Grade Control, 120 in Wide PAT Blade, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper, Drawbar, Rear Auxiliary Hydraulics Usage: 1,872 Hr Asset located in: Humble, TX
147	Asset located in: Humble, TX	155	2019 Cat D6K2 LGP Crawler Dozer
147	2013 Komatsu D65PX-17 Crawler Dozer S/N: KMT0D117E01001609 C/W: Enclosed Cab, Air Conditioner, 2012 US EPA Label, Sweeps, 156 in Wide Straight Blade w/ Single Tilt, 36 in Single Grouser Track Shoes Usage: 3,553 Hr Asset located in: Humble, TX	100	S/N: CAT00D6KVEL703205 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Requires Diesel Exhaust Fluid, 135 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 4,691 Hr
148	2022 Komatsu D61PX-24 Crawler Dozer	156	Asset located in: Humble, TX
	S/N: KMT0D129HMBB65251 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires Diesel Exhaust Fluid, 150 in Wide PAT Blade, 34 in Single Grouser Track Shoes, Drawbar Usage: 4,016 Hr Asset located in: Humble, TX	156	2019 Cat D6K2 LGP Crawler Dozer S/N: CAT00D6KAEL703206 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 144 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 4,697 Hr Asset located in: Humble, TX
149	2019 Komatsu D61PX-24 Crawler Dozer	158	2022 John Deere 650KXLT Crawler Dozer
• • •	S/N: KMT0D129VJB60770 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 151 in Wide PAT Blade, 34 in Single Grouser Track Shoes, Drawbar		S/N: 1T0650KKJNF419254 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 154 Hr

Lot #	Details	Lot #	Details
159	2022 John Deere 650K XLT Crawler Dozer S/N: 1T0650KKANF421252 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 543 Hr Asset located in: Humble, TX	167	2002 Cat D6R XL Crawler Dozer S/N: CAT00D6RP5LN03349 C/W: Enclosed Cab, 124 in Wide Semi-U Blade w/ Single Tilt, 22 in Single Grouser Track Shoes, 1 Cylinder Multi-Shank Ripper Usage: Not Available Notes: LOT CAN BE BLAST & PAINTED FOR
160	2021 John Deere 650KXLT Crawler Dozer		\$6,500.00
160	S/N: 1T0650KKLMF401146		Asset located in: Humble, TX
	C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 105 in Wide PAT Blade, 18 in Single Grouser Track Shoes Usage: 1,081 Hr Asset located in: Humble, TX	168	1998 Cat D6R XL Crawler Dozer S/N: 4MN00473 C/W: Open Operator Station, 160 in Wide Angle Blade 24 in Single Grouser Track Shoes, Drawbar
161	2016 Cat D5K2 LGP Crawler Dozer S/N: CAT00D5KPKY202339 C/W: Enclosed Cab, Air Conditioner, Pre-Wired		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	for Grade Control, Trimble Grade Control		Asset located in: Humble, TX
	System, Sweeps, 120 in Wide PAT Blade, 26 in Single Grouser Track Shoes	169	2005 Cat D6N XL Crawler Dozer
	Usage: 2,541 Hr Asset located in: Humble, TX		S/N: AKM01683 C/W: Enclosed Cab, Air Conditioner, 129 in Wide Straight Blade 23.5 in Single Grouser
162	2013 Komatsu D39PX-23 Crawler Dozer		Track Shoes, Drawbar
	S/N: KMT0D122E01090309 C/W: Enclosed Cab, Air Conditioner, 2013 US EPA Label, 118 in Wide PAT Blade, 26 in Single		Usage: 5,733 Hr Asset located in: Humble, TX
		170	2004 Cat D5N LGP Crawler Dozer
	Grouser Track Shoes, Drawbar		S/N: CAT00D5NVAKD00887
	Usage: 6,522 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		C/W: Open Operator Station, 128 in Wide PAT Blade, 30 in Single Grouser Track Shoes,
	Asset located in: Humble, TX		Drawbar Usage: 7,156 Hr
163	2023 John Deere 450P XLT Crawler Dozer		Asset located in: Humble, TX
100	S/N: 1T0450PAPPMX02255 C/W: Open Operator Station, 2023 US EPA Label, 97 in Wide PAT Blade, 16 in Single Grouser Track Shoes Usage: 167 Hr Asset located in: Humble, TX	171	2003 John Deere 700H LGP Crawler Dozer S/N: T0700HX913761 C/W: Enclosed Cab, Air Conditioner, 132 in Wide PAT Blade, 30 in Single Grouser Track Shoes, Drawbar Usage: 8,417 Hr
164	2022 John Deere 450k Crawler Dozer (Unused)		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1T0450KXCPF434649 C/W: Open Operator Station, 97 in Wide PAT		Asset located in: Humble, TX
	Blade, 16 in Single Grouser Track Shoes	173	2006 Case 850K Crawler Dozer
	Usage: 37 Hr Asset located in : Humble, TX		S/N: CAL005375 C/W: Open Operator Station, 103 in Wide PAT
165	2022 John Deere 450K Crawler Dozer S/N: 1T0450KXANF422050 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 97 in Wide PAT Blade, 16 in		Blade, 18 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper Usage: 4,005 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE
	Single Grouser Track Shoes Usage: 222 Hr		THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	174	1996 Cat D5C LGP Crawler Dozer
166	2019 Cat D3K2 XL Crawler Dozer S/N: CAT00D3KCKF207150 C/W: Open Operator Station, Requires Diesel Exhaust Fluid, 102 in Wide PAT Blade, 16 in Single Grouser Track Shoes, Drawbar Usage: 3,502 Hr	''	S/N: 6ZL00517 C/W: Open Operator Station, 117.5 in Wide PAT Blade, 26 in Single Grouser Track Shoes Usage: 12,584 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
175	2008 Cat D3K LGP Crawler Dozer S/N: CAT00D3KHLLL00332 C/W: Open Operator Station, Sweeps, 122 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 3,534 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	182	2018 Hyundai HR 120C-9 Padfoot Drum Compactor S/N: 26012411E121323 C/W: Open Operator Station, 2018 US EPA Label, Deutz TCD 2012 L04 2V 4 Cylinder 4.0 L Diesel Engine Usage: Not Available Asset located in: Humble, TX
176	2008 Komatsu D-39PX-21 Crawler Dozer S/N: KMT0D014E01002355 C/W: Open Operator Station, 115 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	184	2015 Bomag BW177PDH-5 Padfoot Drum Compactor S/N: 101586051008 C/W: Open Operator Station, Tier 4, 2014 US EPA Label, Kubota V3307 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 6,406 Hr Asset located in: Humble, TX
177	Asset located in: Humble, TX 2007 Komatsu D-39PX-21 Crawler Dozer S/N: KMT0D014V01002317 C/W: Open Operator Station, 118 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 6,637 Hr Asset located in: Humble, TX	185 186	2020 Cat CS-66B Smooth Drum Compactor S/N: CATCS66BL48700649 C/W: Enclosed Cab, Air Conditioner, Cat 6 Cylinder Diesel Engine, 84 in Drum Usage: 2,639 Hr Asset located in: Humble, TX 2022 Ammann ARS110 Smooth Drum
178	2006 Komatsu D39PX-21 Crawler Dozer S/N: KMT0D014A01002030 C/W: Open Operator Station, 118 in Wide PAT Blade, 25 in Single Grouser Track Shoes Usage: 6,933 Hr Asset located in: Humble, TX	186	Compactor S/N: ACZ16382CN3037480 C/W: Open Operator Station, Tier 4, 2019 US EPA Label, Deutz TCD3.6L4 4 Cylinder 134 hp 3.6 L Diesel Engine, 84 in Drum Usage: 281 Hr
179	1998 Case 850G Crawler Dozer S/N: JJG0254307 C/W: Open Operator Station, 124 in Wide PAT Blade, 24 in Single Grouser Track Shoes, Drawbar Usage: 5,864 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	187	Asset located in: Humble, TX 2020 Wacker Neuson RC-110 Smooth Drum Compactor S/N: WNCR1101EHAA00345 C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 84 in Drum Usage: 1,238 Hr Asset located in: Humble, TX
180	1976 Cat 955L Crawler Loader S/N: 85J10684 C/W: Open Operator Station, 89 in Bucket, 17 in Double Grouser Track Shoes Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	188	2020 XCMG CV83PDU Smooth Drum Compactor S/N: XUG00831CLJE02088 Usage: Not Available Asset located in: Humble, TX
181	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX 2020 Wacker Neuson RC-110 Padfoot Drum Compactor S/N: WNCR1101PHAA00334	189	2018 Hamm H10i Smooth Drum Compactor S/N: WGH0H235EHAA00525 C/W: Open Operator Station, 2017 US EPA Label, Deutz TCD3.6L4 4 Cylinder 115 hp 3.6 L Diesel Engine, 84 in Drum Usage: 1,133 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	C/W: Open Operator Station, 2019 US EPA Label, Deutz 4 Cylinder 114 hp 3.6 L Diesel Engine, 82 in Drum Usage: 1,344 Hr Asset located in: Humble, TX	THE INSPECTION REPORT Asset located in: Humble, TX 2018 XCMG CV83PD Smooth Drum Compactor S/N: XUG00831TJJE04236 C/W: Enclosed Cab, Air Conditioner, Tier 3, 2018 US EPA Label, Cummins QSB3.3 4 Cylinder 99 hp 3.26 L Diesel Engine, 66 in Drum, Padfoot Shell Kit Usage: 308 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
190	2018 Hyundai HR120C-9 Smooth Drum Compactor S/N: 26012411E120272 Usage: Not Available Asset located in: Humble, TX	199	2018 Wacker Neuson RC-70 Smooth Drum Compactor S/N: WNCR0801PHAA00314 C/W: Open Operator Station, Air Ride Seat, Tie 4, 2017 US EPA Label, Kubota V3307-CR-T-EF
191	2003 Ingersoll Rand SD122DX Smooth Drum Compactor S/N: 174340		05 4 Cylinder 54.6 kW 3.3 L Diesel Engine, 67 in Drum Usage: 481 Hr Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	200	Dynapac CA1500D Smooth Drum Compactor
192	Asset located in: Humble, TX 2003 Dynapac CA262D Smooth Drum Compactor S/N: 67220548 C/W: Open Operator Station, 2016 US EPA Label, Cummins 6 Cylinder 148 hp 5.9 L Diesel Engine, 84 in Drum Usage: Not Available		S/N: 10000156L0A014071 C/W: Open Operator Station, 2014 US EPA Label, Cummins QSB3.3 100 hp 3.26 L Diesel Engine, 66 in Drum Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: 2016 ENGINE	201	Galion Smooth Drum Compactor
193	Asset located in: Humble, TX 1987 Ingersoll Rand SP-48 Smooth Drum Compactor S/N: 6086S		S/N: 490054 C/W: Open Operator Station, Detroit Diesel Engine, 66 in Drum Usage: 2,253 Hr
	C/W: Open Operator Station, Swivel Operator Controls, Cummins 4B 4 Cylinder 100 hp 3.0 L Diesel Engine, 66 in Drum		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 6,103 Hr Asset located in : Humble, TX	202	2011 Bomag BW190AD-4 Double Drum Roller S/N: 101920291023 C/W: Open Operator Station, 2010 US EPA Label, Deutz 4 Cylinder 134 hp 4.03 L Diesel Engine, 78.5 in Compaction Width, Water System Usage: 2,894 Hr Asset located in: Humble, TX
195	2020 Wacker Neuson RC-70 Smooth Drum Compactor S/N: WNCR1201PHAA00212 C/W: Open Operator Station, 2019 US EPA Label, Kubota 3307-cr-t-ew04 4 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum		
	Usage: 891 Hr Asset located in: Humble, TX	203	2014 Volvo DD110B Double Drum Roller
196	2020 Wacker Neuson RC-70 Smooth Drum Compactor S/N: WNCR1201AHAA00217 C/W: Open Operator Station, 2019 US EPA Label, Kubota v3307-cr-t-ew04 4 Cylinder 54.6	Label, Volvo 6 Cylinder 131 hp 4.0 L Diese Engine, 67 in Compaction Width, Water S Usage: 4,326 Hr Notes: DEFICIENCIES NOTED - PLEASE S	C/W: Open Operator Station, 2013 US EPA Label, Volvo 6 Cylinder 131 hp 4.0 L Diesel Engine, 67 in Compaction Width, Water System
	kW 3.3 L Diesel Engine, 66 in Drum Usage: 1,757 Hr		Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	204	2007 Cat CB-534D Double Drum Roller S/N: CATCB534JFGH00656 C/W: Open Operator Station, Swivel Operator
197	2020 Wacker Neuson RC-70 Smooth Drum Compactor S/N: WNCR1201PHAA00209 C/W: Open Operator Station, 2019 US EPA Label, Kubota V3307 3 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum		Controls, 2006 US EPA Label, Cat 3054C 4.4 L Diesel Engine, 67 in Compaction Width, Water System Usage: 2,142 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 1,155 Hr		Asset located in: Humble, TX
198	Asset located in: Humble, TX 2020 Wacker Neuson RC-70 Smooth Drum Compactor S/N: WNCR1201AHAA00203 C/W: Open Operator Station, 2019 US EPA Label, Kubota V3307 3 Cylinder 54.6 kW 3.3 L Diesel Engine, 66 in Drum Usage: 686 Hr Asset located in: Humble, TX	205	2016 Hamm HD12VV Double Drum Roller S/N: H2300845 C/W: Open Operator Station, 2016 US EPA Label, Kubota D1703 3 Cylinder 1.7 L Diesel Engine, 47 in Compaction Width, Water System Usage: 693 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
206	2013 Hamm HD12VV Double Drum Roller S/N: H2002240 C/W: Open Operator Station, Kubota 3 Cylinder 1.5 L Diesel Engine, 48 in Compaction Width Usage: 582 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	214	2019 Volvo EC250ELR Long Reach Tracked Excavator S/N: VCEC250EL00314014 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 33 ft 5 in Boom, 25 ft 2 in Stick, 31.5 in Triple Grouser Track Shoes, 60 in Cleanup Bucket Usage: 2,913 Hr
207	1998 Ingersoll Rand DD-24 Double Drum Roller S/N: 153638		Asset located in: Humble, TX
	C/W: Open Operator Station, Deutz F3L 1011 F Diesel Engine, 43 in Compaction Width Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	215	2016 John Deere 670G Tracked Excavator S/N: 1FF670GXPGF690005 Usage: Not Available Asset located in: Humble, TX
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	216	2017 Cat 349F Tracked Excavator
	Asset located in: Lake Worth, TX		S/N: CAT0349FHBZ200910
208	2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263JHAA00666 C/W: Open Operator Station, Tier 4, 2020 US EPA Label, Kubota D1105-EF05 3 Cylinder 1.1 L Diesel Engine, 39.5 in Compaction Width,		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket Usage: 9,365 Hr
	Water System Usage: 436 Hr	217	Asset located in: Humble, TX 2017 Cat 349FL Tracked Excavator
209	Asset located in: Humble, TX 2021 Hamm HD10CVV Double Drum Roller S/N: WGH0H263KHAA00668 C/W: Open Operator Station, 2020 US EPA Label, Kubota D1105 3 Cylinder 16.1 kW 1.5 L Diesel Engine, 39.5 in Compaction Width Usage: Not Available Asset located in: Humble, TX	217	S/N: CAT0349FHHPD10055 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, 35.5 in Triple Grouser Track Shoes, 66 in Digging Bucket Usage: 13,438 Hr Asset located in: Humble, TX
210	Hamm HD10CVV Double Drum Roller	218	2021 Hyundai HX480A L Tracked Excavator
	S/N: WGH0H263CHAA00679 C/W: Open Operator Station, Tier 4, 2020 US EPA Label, Kubota 3 Cylinder 16.1 kW 1.1 L Diesel Engine, Requires Diesel Exhaust Fluid, 39 in Compaction Width, Water System Usage: 233 Hr Asset located in: Humble, TX	218	S/N: HHKHKB04VE0000003 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 11 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 38 in Digging Bucket Usage: 4,419 Hr
212	2018 Fuchs MHL340 T4F Wheel Material		Asset located in: Humble, TX
	Handler	219	2016 John Deere 470GLC Tracked Excavator S/N: 1FF470GXKEE470858 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, Tier 4, 11 ft Stick, 35.5 in Triple Grouser Track Shoes, 72 in Digging Bucket, Catwalks Usage: 8,485 Hr Asset located in: Humble, TX
213	2007 Gradall XL4100 Wheel Excavator	220	2021 LiuGong CLG950E Tracked Excavator
	S/N: 4100000165 C/W: Air Conditioner, 13 ft Stick, 385/65R22.5 Tires, 60 in Cleanup Bucket Usage: 8,853 Hr Asset located in : Humble, TX		S/N: CLG950EZCME900509 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, 65 in Digging Bucket, Counterweight Removal System Usage: 3,295 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

	D	I	B : 1
Lot #	Details	Lot #	Details
221	2021 Cat 336 Tracked Excavator S/N: CAT00336HYBN20483 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, Pre-Wired for Grade Control, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 64 in Digging Bucket Usage: 4,794 Hr Asset located in: Humble, TX	227	2020 LiuGong 936E Tracked Excavator S/N: 888936EZKLU004041 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 58 in Digging Bucket Usage: 2,213 Hr Asset located in: Humble, TX
222	2021 Cat 336 Tracked Excavator	228	2019 XCMG XE360U Tracked Excavator
222	S/N: CAT00336KYBN20619 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 62 in Digging Bucket Usage: 6,944 Hr		S/N: XUGA360BKKKA00011 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Cab Screens, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 33 in Digging Bucket Usage: 1,539 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	229	2016 Komatsu PC360LC-11 Tracked Excavator
223	2017 Cat 336FL Tracked Excavator S/N: CAT0336FARKB10027 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 66 in Digging Bucket, Manual Thumb Usage: 9,435 Hr		S/N: A35327 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 40 in Digging Bucket Usage: 10,167 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	231	Kobelco SK350LC-10 Tracked Excavator
224	2012 Cat 336E L Tracked Excavator S/N: CAT0336EABZY01673 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2012 US EPA Label, 12 ft 6 in Stick, 33.5 in Triple Grouser Track Shoes, 65 in Digging Bucket Usage: 13,275 Hr Asset located in: Humble, TX	231	S/N: YC14605003 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 74 in Digging Bucket Usage: 4,748 Hr Asset located in: Humble, TX
225	2023 LiuGong 936F Tracked Excavator	232	2011 John Deere 350GLC Tracked Excavator
	S/N: CLG936FZEPE905812 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Surround View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 58 in Digging Bucket, Thumb Bracket	234	S/N: 1FF350GXCBE808042 C/W: Air Conditioner, Air Ride Seat, 13 ft Stick, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 272 Hr Asset located in: Humble, TX 2019 Cat 330FL Tracked Excavator
	Asset located in: Humble, TX		S/N: HCK20238
226	2022 LiuGong 936F Tracked Excavator S/N: CLG936FZJNE903739 C/W: Air Conditioner, Surround View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 10 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 60 in Digging Bucket Usage: 1,151 Hr Asset located in: Humble, TX		C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, 10 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 3,527 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
235	2018 Cat 326F L Tracked Excavator S/N: CAT0326FHFBR20375 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear View Camera, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 3,298 Hr	241	2020 LiuGong CLG925E Tracked Excavator S/N: CLG925EZELE070030 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 8 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket Usage: 3,555 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	242	2018 Hyundai 220L Tracked Excavator
236	Kobelco SK260LC-10 Tracked Excavator S/N: LL1610670 C/W: Air Conditioner, Control Pattern Changer, Rear View Camera, 2018 US EPA Label, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 56 in Digging Bucket, Thumb Bracket Usage: 5,590 Hr		S/N: HHKLKG01PJ0000763 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 36 in Cleanup Bucket Usage: 5,883 Hr
	Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
237	2022 John Deere 250G Tracked Excavator		Asset located in: Humble, TX
	S/N: 1FF250GXCNF611835 C/W: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 12 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket, Hydraulic Thumb Usage: 1,246 Hr Asset located in: Humble, TX	243	2020 Komatsu PC210LC-11 Tracked Excavator S/N: KMTPC257JKTC81129 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, 31.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 24 in Digging Bucket
238	2020 John Deere 245G LC Tracked Excavator	-	Usage: 7,642 Hr
230	S/N: 1FF245GXJLF801542 C/W: Air Conditioner, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 40 in Digging		Asset located in: Humble, TX
		244	2019 Kobelco SK210LC-10 Tracked Excavator S/N: YQ15S00578 Usage: Not Available Asset located in: Humble, TX
	Bucket, Hydraulic Thumb Usage: 2,822 Hr	245	2019 XCMG XE210U Tracked Excavator
239	Asset located in: Humble, TX 2017 Volvo ECR235EL Tracked Excavator S/N: VCECR235P00310736 C/W: Air Conditioner, Rear View Camera, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 24 in Rubber Tracks, 2021 SAS Extreme 35V3 235		S/N: XUGA210BLKKA00121 C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, 2019 US EPA Label, Require Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 23 in Digging Bucket Usage: 1,660 Hr Asset located in: Humble, TX
	Car Processor Usage: 4,865 Hr	246	2019 Cat 320 Tracked Excavator
	Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: CAT00320LHEX11718 C/W: Air Conditioner, Control Pattern Changer Rear & Side View Cameras, 2019 US EPA Labo
240	Asset located in: Lake Worth, TX 2020 LiuGong 925E Tracked Excavator S/N: 888925EZCLU004016	-	Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, 23.5 in Triple Grouser Track Shoes, 38 in Digging Bucket Usage: 3,091 Hr
	C/W: Air Conditioner, Control Pattern Changer, 2018 US EPA Label, Requires Diesel Exhaust		Asset located in: Humble, TX
	Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 54 in Digging Bucket Usage: 2,046 Hr Asset located in: Humble, TX	247	2019 Cat 320 Tracked Excavator S/N: CAT00320THEX12020 C/W: Air Conditioner, Air Ride Seat, Auxiliary Hydraulic Plumbing Usage: 4,036 Hr
			Asset located in: Lake Worth, TX
		248	2018 Cat 320 Tracked Excavator S/N: CAT00320VHEX00392 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
249	2022 Cat 320GC Tracked Excavator S/N: CAT00320CLKS20323 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in Triple Grouser Track Shoes, 37 in Digging Bucket Usage: 1,182 Hr Asset located in: Lake Worth, TX	258	2009 Cat 336DL Tracked Excavator S/N: CAT0336DLW3K00443 C/W: Air Conditioner, Straight Travel Pedal, Air Ride Seat, 20 ft Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes Usage: 88,514 Hr Notes: LOT CAN BE BLAST & PAINTED FOR \$9,600.00 Asset located in: Humble, TX
250	2019 Cat 320GC Tracked Excavator	259	2006 Cat 330CL Tracked Excavator
250	S/N: Not Available C/W: Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras, Requires Diesel Exhaust Fluid, 9 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 31 in		S/N: CAT0330CTCYA01139 C/W: Air Conditioner, Straight Travel Pedal, Cab Screens, 31.5 in Triple Grouser Track Shoes, Shear, LaBounty MSD3000 Hydraulic Shear - SN 700305 Usage: 5,833 Hr
	Triple Grouser Track Shoes, 40 in Digging Bucket Usage: 6,583 Hr		Notes: LOT CAN BE BLAST & PAINTED FOR \$10,600.00
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Humble, TX
251	THE INSPECTION REPORT Asset located in: Humble, TX 2015 Cat 320E LRR Tracked Excavator S/N: CAT0320EHTFX01291	260	2008 Komatsu PC 300 LC-8 Tracked Excavator S/N: A90468 C/W: Air Conditioner, Air Ride Seat, Rear View Camera, 10 ft 7 in Stick, 33.5 in Triple Grouser Track Shoes, 54 in Digging Bucket
	C/W: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear View Camera, 9 ft 6 in Stick, 31 in Triple Grouser Track Shoes, 40 in		Usage: 1,591 Hr
			Asset located in: Humble, TX
	Digging Bucket Usage: 5,535 Hr	261 	2009 Cat 321D Tracked Excavator
	Asset located in: Humble, TX		S/N: CAT0321DPNAS00381 C/W: Air Conditioner, 9 ft 6 in Stick, 23.5 in
252	2011 Komatsu PC200LC8 Tracked Excavator	7	Triple Grouser Track Shoes, 35 in Digging Bucket
	S/N: KMTPC180H54A89854 C/W: Air Conditioner, 2011 US EPA Label, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 29 in Digging Bucket, Thumb Bracket Usage: 13,292 Hr		Usage: 8,827 Hr
		060	Asset located in: Humble, TX
		262 2008 Komatsu PC200LC8 Tracked Excavator S/N: KMTPC180J54A88678 C/W: Air Conditioner, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 50 in Cleanup	2008 Komatsu PC200LC8 Tracked Excavator
	Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
	Asset located in: Humble, TX	_	Bucket Usage: 15,110 Hr
254	2018 Wacker Neuson ET145 Tracked Excavator		Asset located in: Humble, TX
	S/N: WNCE1102LPAL00590 C/W: Air Conditioner, Air Ride Seat, Swing	263	2007 Komatsu PC200LC8 Tracked Excavator
	Boom, 8 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 20 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket Usage: 1,724 Hr		S/N: KMTPC180C87C60745 C/W: Air Conditioner, 2006 US EPA Label, 9 ft 6 in Stick, 31.5 in Triple Grouser Track Shoes, 42 in Digging Bucket Usage: 8,839 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
256	2019 Volvo EC140EL Tracked Excavator S/N: 311897 Usage: 1,972 Hr	264	2006 Kobelco SK135SRLC-1E Tracked Excavator S/N: YH0403598
	Asset located in: Humble, TX	╛	C/W: Air Conditioner, 2005 US EPA Label, 9 ft 6
257	2010 Kobelco SK140SR-LC Tracked Excavator S/N: YH0507944 C/W: 9 ft 2 in Stick, Auxiliary Hydraulic Plumbing, 23.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 36 in Digging Bucket		in Stick, Auxiliary Hydraulic Plumbing, 27.5 in Triple Grouser Track Shoes, 24 in Digging Bucket Usage: 9,469 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: 9,542 Hr		THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
265	1997 John Deere 690E LC Tracked Excavator S/N: DW690EL564389 C/W: 9 ft 7 in Stick, 31.5 in Triple Grouser Track Shoes, Manual Quick Coupler, 42 in Digging Bucket Usage: 6,981 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	271	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308EEMC500732 C/W: Air Conditioner, Rear View Camera, Tier 4, 2018 US EPA Label, 5 ft 6 in Stick, Backfill Blade, 17.5 in Triple Grouser Track Shoes w /Rubber Inserts, 28 in Digging Bucket Usage: 2,209 Hr Asset located in: Humble, TX
266		272	2018 Cat 308E2 CR Tracked Excavator S/N: CAT0308ELMC500727
200	2020 Volvo ECR88D Tracked Excavator S/N: 216242 C/W: Air Conditioner, 6 ft 11 in Stick, Backfill Blade, 18 in Rubber Tracks, 22 in Digging Bucket Usage: 2,400 Hr		C/W: Air Conditioner, Rear View Camera, Tier 4, 2018 US EPA Label, 5 ft 6 in Stick, Backfill Blade, 18 in Triple Grouser Track Shoes w /Rubber Inserts, 27 in Digging Bucket Usage: 3,371 Hr
	Notes: LOCATED-IN-FORT-WORTH-TX;		Asset located in: Humble, TX
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	273	2019 Volvo ECR58D Mini Excavator S/N: 210698 C/W: Tier 4, Swing Boom, 5 ft Stick, Auxiliary
267	2019 Volvo ECR88D Tracked Excavator S/N: VCE00E88E00215347 C/W: Air Conditioner, Tier 4, 2019 US EPA Label, Swing Boom, 6 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17 in Rubber Tracks, Manual Quick Coupler, 23 in		Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 12 in Digging Bucket Usage: 1,576 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
		275	2003 Cat 308C Tracked Excavator
	Digging Bucket, Hydraulic Thumb Usage: 2,724 Hr Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	275	S/N: CAT308CACPE01252 C/W: Air Conditioner, 5 ft 5 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Triple Grouser Track Shoes, 28 in Digging Bucket, Hydraulic Thumb
268	2021 Bobcat E85 Mini Excavator	-	Usage: 2,545 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
200	S/N: B48414950		THE INSPECTION REPORT
	C/W: Enclosed Cab, Air Conditioner, 2020 US		Asset located in: Humble, TX
	EPA Label, Swing Boom, 7 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 17.5 in Rubber Tracks, 24 in Digging Bucket Usage: 968 Hr Asset located in : Humble, TX	276	2012 Case CX58C Mini Excavator S/N: PS02-00154 C/W: Enclosed Cab, 2011 US EPA Label, Swing Boom, 5 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Triple Grouser
269	2021 Bobcat E85 Mini Excavator		Track Shoes, 29 in Digging Bucket
	S/N: B48414940		Usage: 2,103 Hr
	C/W: Enclosed Cab, Air Conditioner, 2020 US EPA Label, 7 ft 5 in Stick, Auxiliary Hydraulic	077	Asset located in: Humble, TX
	Plumbing, Backfill Blade, 17.5 in Rubber	277	2017 Takeuchi TB260 Mini Excavator S/N: 126102558
	Tracks, 18 in Digging Bucket Usage: 989 Hr		C/W: 2017 US EPA Label, Swing Boom, 5 ft 10
	Asset located in: Humble, TX		in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, 24 in Cleanup
270	2017 Bobcat E85 Mini Excavator		Bucket
	S/N: B34T13537		Usage: 2,802 Hr
	C/W: Enclosed Cab, Air Conditioner, Control Pattern Changer, 2016 US EPA Label, 7 ft 4 in		Asset located in: Humble, TX
	Stick, Auxiliary Hydraulic Plumbing, Backfill	278	2015 Takeuchi TB260 Mini Excavator S/N: 126100966
	Blade, 18 in Rubber Tracks, Manual Quick Coupler, 23 in Digging Bucket		C/W: Enclosed Cab, Air Conditioner, Swing
	Usage: 1,011 Hr		Boom, 5 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber
	Asset located in: Humble, TX		Tracks, 18 in Digging Bucket Usage: 5,328 Hr

Lot #	Details	Lot #	Details	
279	2016 Takeuchi TB260 Mini Excavator S/N: 126101490 C/W: 2015 US EPA Label, Swing Boom, 5 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 15.5 in Rubber Tracks, 24 in Digging Bucket Usage: 2,729 Hr	287	2019 Cat 304E2 CR Mini Excavator S/N: CAT0304ELME407006 C/W: Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 14 in Rubber Tracks, 10 in Digging Bucket Usage: 2,477 Hr	
	Asset located in: Humble, TX	000	Asset located in: Humble, TX	
280	2018 Cat 305.5E2 Mini Excavator S/N: CAT3055ETWE205440 C/W: Enclosed Cab, 2023 US EPA Label, 5 ft 9 in Stick, Backfill Blade, 15.5 in Triple Grouser Track Shoes, 26 in Digging Bucket Usage: 833 Hr Asset located in: Humble, TX	288	2018 Sany SY35U Mini Excavator S/N: SY0033BJ19538 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 4 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 12 in Digging Bucket Usage: 2,418 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	
281	2017 Cat 305.5E2 Mini Excavator		THE INSPECTION REPORT	
	S/N: CAT3055EEWE203491 C/W: Enclosed Cab, Air Conditioner, 5 ft 9 in Stick, Backfill Blade, 15.5 in Triple Grouser Track Shoes, 26 in Digging Bucket Usage: 884 Hr Asset located in: Humble, TX	289	Asset located in: Humble, TX 2018 Bobcat E35i Mini Excavator S/N: B3Y212264 C/W: Control Pattern Changer, Tier 4, 2017 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket	
282	2017 Cat 305.5E2 Mini Excavator S/N: CAT3055EHWE202355		Usage: 1,915 Hr	
	C/W: Enclosed Cab, Air Conditioner, 5 ft 9 in		Asset located in: Humble, TX	
			S/N: B3Y212281 C/W: Control Pattern Changer, 2017 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary	
283	2016 Cat 305E2 CR Mini Excavator S/N: CAT0305ELH5M02800 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 5 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 2,135 Hr		Rubber Tracks, 16 in Cleanup Bucket Usage: 2,058 Hr	
		291	2020 Yanmar ViO35-6A Mini Excavator S/N: AL139 C/W: Control Pattern Changer, Swing Boom, 4	
284	Asset located in: Humble, TX 2017 Bobcat E50 Mini Excavator S/N: AJ1813546 C/W: Control Pattern Changer, 2016 US EPA		ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Hydraulic Quick Coupler, 24 in Digging Bucket Usage: 2,191 Hr Asset located in : Humble, TX	
	Label, Swing Boom, 5 ft Stick, Backfill Blade, 15.5 in Rubber Tracks, 24 in Digging Bucket, Hydraulic Thumb Usage: 2,705 Hr Asset located in : Humble, TX	292	2021 John Deere 35G Mini Excavator S/N: 1FF035GXCMK292519 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary	
285	2018 Cat 303.5E2CR Mini Excavator S/N: JWY03540 C/W: Swing Boom, 5 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Tilt Blade, 12 in Rubber Tracks, 24 in Digging Bucket Usage: 3,154 Hr Asset located in: Humble, TX		Rubber Tracks, Manual Quick Coupler, 2 Digging Bucket Usage: 919 Hr Notes : LOCATED-IN-FORT-WORTH-TX; WITH IRONCLAD ASSURANCE. SUBJEC TEXAS SALES TAX.	Usage: 919 Hr Notes : LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO
286	2012 Kubota KX121-3ST Mini Excavator S/N: JKUK1213H01H73481 C/W: Swing Boom, 5 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Tilt Blade, 12 in Double Grouser Track Shoes, 24 in Digging Bucket Usage: 4,566 Hr Asset located in: Humble, TX			

Lot #	Details	Lot #	Details
293	2021 John Deere 35G Mini Excavator S/N: 1FF035GXLMK292833 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 24 in Bucket Usage: 711 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.	300	2017 John Deere 35G Mini Excavator S/N: 1FF035GXKGK278058 C/W: Control Pattern Changer, 2016 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, 12 in Digging Bucket, Additional 29 in Cleanup Bucket Usage: 4,524 Hr Asset located in: Humble, TX 2013 John Deere 35D Mini Excavator
	Asset located in: Lake Worth, TX		S/N: 1FF035DXHCG270973 C/W: Control Pattern Changer, Swing Boom, 4
294	2021 John Deere 35G Mini Excavator S/N: 1FF035GXAMK292863 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, 11.5 in Rubber Tracks,		ft 4 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: 5,672 Hr Asset located in : Humble, TX
	Manual Quick Coupler, 24 in Digging Bucket Usage: 625 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX	301	2016 Bobcat E32 Mini Excavator S/N: B2VV12022 C/W: Control Pattern Changer, Tier 4, 2015 US EPA Label, Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler,
295	2021 John Deere 35G Mini Excavator		24 in Digging Bucket Usage: 3,704 Hr
	S/N: 1FF035GXJMK293071 C/W: Control Pattern Changer, 2021 US EPA		Asset located in: Humble, TX
	Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.5 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 543 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.	302A	2021 John Deere 30G Mini Excavator S/N: 1FF030GXPMK268252 C/W: 2021 US EPA Label, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket, Thumb Bracket Usage: 147 Hr Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	202	2016 Bobcat E32 Mini Excavator
296	2021 John Deere 35G Mini Excavator S/N: 1FF035GXKMK293067 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 11.75 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 723 Hr	302	S/N: B2VV12015 C/W: Swing Boom, 5 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: 3,337 Hr Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX		2015 John Deere 27D Mini Excavator S/N: 1FF027DXHEG259747 C/W: Control Pattern Changer, 2014 US EPA Label, Swing Boom, 3 ft 10 in Stick, Auxiliary
297	2017 John Deere 35G Mini Excavator S/N: 1FF035GXPHK279839 C/W: Control Pattern Changer, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 18 in Digging Bucket Usage: 774 Hr		Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, 33 in Cleanup Bucket, Additional 12 in Digging Bucket Usage: 6,082 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	304	2019 Kubota U27-4R1 Mini Excavator
298	2017 John Deere 35G Mini Excavator S/N: 1FF035GXCGK278385 C/W: Control Pattern Changer, Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Power Angle Blade, 11.5 in Rubber Tracks, 24 in Digging Bucket Usage: 4,241 Hr		S/N: WKFRGH1200Z041167 C/W: Tier 4, 2018 US EPA Label, Swing Boom, 4 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 600 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
305	2005 Bobcat 331G Mini Excavator S/N: 234313426 C/W: Control Pattern Changer, 2005 US EPA Label, Swing Boom, 3 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 12 in Rubber Tracks, Manual Quick Coupler, 18 in Digging Bucket Usage: 3,164 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	311	2021 John Deere 17G Mini Excavator S/N: 1FF017GXPMK231121 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Width Tracks, Manual Quick Coupler, 12 in Digging Bucket Usage: 341 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
306	2007 John Deere 50D Mini Excavator S/N: FF050DX245720	312	2021 John Deere 17G Mini Excavator
	C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 16 in Rubber Tracks, Manual Quick Coupler, 24 in Digging Bucket Usage: Not Available Asset located in: Humble, TX		S/N: 1FF017GXCMK231343 C/W: Control Pattern Changer, Swing Boom, 3 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Manual Quick Coupler, 12 in Digging Bucket Usage: 358 Hr
307	2005 John Deere 50D Mini Excavator S/N: FF050DX244276 C/W: Control Pattern Changer, Swing Boom, 4 ft 6 in Stick, Auxiliary Hydraulic Plumbing,		Notes : LOCATED-IN-FORT-WORTH-TX ; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
			Asset located in: Lake Worth, TX
	Backfill Blade, 16 in Rubber Tracks, 18 in Digging Bucket Usage: 10,447 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	313	2021 John Deere 17G Mini Excavator S/N: 1FF017GXKMK231508 C/W: Control Pattern Changer, 2021 US EPA Label, Swing Boom, 3 ft 1 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Expandable Wight
308	2021 Cat 301.8 Mini Excavator		Quick Coupler, 12 in Bucket Usage: 172 Hr
	S/N: CAT03018CH8X06213 C/W: Enclosed Cab, Air Conditioner, 2014 US EPA Label, Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 11.5 in Digging Bucket Usage: 31 Hr		Notes : LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
		314	Asset located in: Lake Worth, TX 2021 Kubota K008-3 Mini Excavator S/N: KBCAZ030TM3F44754
	Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		C/W: Swing Boom, 2 ft 11 in Stick, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket Usage: 810 Hr
	Asset located in: Midland, TX		Asset located in: Humble, TX
309	2019 Cat 301.7CR Mini Excavator S/N: CAT03017HJH701720 C/W: Swing Boom, 3 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 11 in Digging Bucket, EQUIPMENT-	315	2020 Rapidmix 600CV Concrete Plant S/N: RMXV601121143 C/W: Portable Aggregate Bins Usage: Not Available Asset located in: Humble, TX
	FROM-A-PRIMORIS-SERVICES-CORP- COMPANY	316	2008 Terex Pegson Metro HA Tracked Jaw
	Usage: 1,611 Hr		Crushing Plant
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 960520FGHA C/W: 6 ft x 12 ft Vibratory Grizzly Feeder 600
	Asset located in: Humble, TX	_	mm x 900 mm Jaw Crusher, 32 in Wide End Discharge Conveyor, Terex 30 in x 6 ft Cross
310	2018 Takeuchi TB216 Mini Excavator S/N: 216101280 C/W: Swing Boom, 3 ft 6 in Stick, Backfill Blade, 9 in Rubber Tracks, 12 in Digging Bucket		Belt Magnet, Cable Remote Control, Cat 6 Cylinder Diesel Engine, 16 in Triple Grouser Track Shoes Usage: 13,068 Hr
	Usage: 1,305 Hr Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details Lot# **Details** Lot # 317 2000 Terex HC125 125 ton Lattice-Boom 322 2011 Terex AC100/4L 120 ton 8x6 All Terrain **Crawler Crane** Crane S/N: WMG4215H0BZ030168 C/W: 170 ft Boom, 60 ft Jib, Self Erecting, C/W: Air Conditioner, Automatic Transmission, Auxiliary Hoist, Rooster Sheave, 3900 lb 3 Mercedes-Benz OM460LA 6 Cylinder Diesel Sheave 100 ton Hook Block, 850 lb 15 ton Carrier Engine, Air Conditioner, Tilt Cab, Anti Overhaul Ball, Counterweight Removal System, Two-Block, Terex Load Moment Indicator, Air Conditioner, Anti Two-Block, Wylie WW 250 Load Moment Indicator, 2012 US EPA Label, 44 in Track Shoes, Expandable Width Tracks Mercedes-Benz Diesel Upper Engine, 39.4 ft Minimum 194.9 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 52 ft Bifold Swingaway Hydraulic Offset Jib, 550 kg Usage: Not Available 50 ton Capacity Terex 3 Sheave Hook Block, Asset located in: Humble, TX 170 kg 8 ton Capacity Overhaul Ball, 28.82 lb Counterweight, Counterweight Removal 318 2006 Manitowoc 10000 100 ton Lattice-Boom System, 1 sheave block Crawler Crane Usage: 43.700 Km S/N: 10001060 C/W: 90 ft Boom, Self Erecting, Auxiliary Hoist, Rooster Sheave, Johnson 3856 lb 4 Sheave 75 Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY ton Hook Block, 698 lb 12 ton Overhaul Ball, Asset located in: Humble, TX 79600 lb Counterweight, Counterweight 323 2001 Grove GMK5120B 120 ton 10x8x8 All Removal System, Anti Two-Block, Load Moment Indicator, 2006 US EPA Label, 36 in **Terrain Crane** Track Shoes S/N: 1005901WG12190 C/W: Daimler - Chrysler G 240-16 16 Speed Automatic Transmission, 2025 hrs Carrier Usage: 10,664 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Engine, 2001 US EPA Label, Mercedes-Benz OM502LA V8 15.9 L Diesel Carrier Engine, Air Asset located in: Humble, TX Conditioner, Tilt Cab, Anti Two-Block, Load Moment Indicator, Merceds-Benz OM904LA 2005 Kobelco CK1000-II 100 ton Lattice-Boom 319 Diesel Upper Engine, 42 ft Minimum 167 ft **Crawler Crane** Maximum Boom Length, Auxiliary Hoist, 36 ft S/N: GH0201067 to 112 ft Bifold Swingaway Hydraulic Offset C/W: 160 ft Boom, 60 ft Luffing Jib, Self Jib, 1816 lb 80 ton Capacity Johnson 5 Sheave Erecting, Auxiliary Hoist, Rooster Sheave, Johnson 3 Sheave Hook Block, Overhaul Ball, Hook Block, 12 ton Capacity Overhaul Ball, 68300 lb Counterweight, Counterweight Counterweight Removal System, Air Conditioner, Anti Two-Block, Load Moment Indicator, 2005 US EPA Label, 36 in Track Removal System Usage: 153,731 Km Shoes, Expandable Width Tracks Usage: 17,816 Hr Asset located in: Humble, TX 324 2015 Link-Belt HTC8675 75 ton 8x4 Hydraulic Asset located in: Humble, TX Truck Crane 320 Link-Belt LS-138H II 80 ton Lattice-Boom S/N: P9K5-4779 C/W: Air Conditioner, Automatic Transmission, **Crawler Crane** Cummins ISX12 6 Cylinder Diesel Carrier S/N: CDB960V911 Engine, Requires Diesel Exhaust Fluid, Anti Two-Block, Link Belt Load Moment Indicator, 41 ft C/W: 90 ft Boom, Self Erecting, Auxiliary Hoist, Rooster Sheave, Johnson 4 Sheave Hook Minimum 127 ft Maximum Boom Length, Block, Overhaul Ball, 50706 lb Counterweight, Auxiliary Hoist, Rooster Sheave, 38 ft to 64 ft Counterweight Removal System, Greer GS820 Bifold Swingaway Offset Jib, 1082 lb 60 ton Capacity Johnson 4 Sheave Hook Block, Load Moment Indicator, 1999 US EPA Label, 36 in Track Shoes, Expandable Width Tracks Overhaul Ball, 18400 lb Counterweight, Usage: 5,899 Hr Counterweight Removal System Asset located in: Humble, TX Usage: 67,856 Mi 321 2000 Link-Belt HC-248 200 ton 10x4x2 Lattice-Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT **Boom Truck Crane** Asset located in: Humble, TX S/N: C5NJ04608 C/W: 180 ft Boom, 50 ft Luffing Jib, Auxiliary Hoist, Johnson 5 Sheave 100 ton Hook Block, Overhaul Ball, 88440 lb Counterweight, Counterweight Removal System, Eaton Fuller 8LL Manual Transmission, Detroit 6 Cylinder Diesel Carrier Engine, LSI GS820 Load Moment Indicator, 2000 US EPA Label, Isuzu Diesel Upper Engine, Spicer 4 Speed Auxiliary

Transmission Usage: Not Available

Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
325	2003 Grove TMS700E 60 ton 8x4 Hydraulic Truck Crane S/N: 223634 C/W: Eaton Fuller 9LL Manual Transmission, 8544 hrs Carrier Engine, Cummins ISM 6 Cylinder 10.8 L Diesel Carrier Engine, Anti Two-Block, PAT Load Moment Indicator, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 56 ft Bifold Swingaway Offset Jib, 800 lb 40 ton Capacity McKissick 3 Sheave Hook Block, 8.3 ton Capacity Overhaul Ball, 16500 lb Counterweight, Counterweight Removal System Usage: 209,207 Mi	329	2003 Grove TMS500E 40 ton 6x4 Hydraulic Truck Crane S/N: 223629 C/W: Allison Automatic Transmission, Cat 3126 6 Cylinder Diesel Carrier Engine, Anti Two-Block, PAT iFlex5 Load Moment Indicator, 29 ft Minimum 95 ft Maximum Boom Length, 26 ft to 45 ft Extendable Swingaway Offset Jib, 521 lb 25 ton Capacity Johnson 3 Sheave Hook Block, 7.5 ton Capacity Overhaul Ball, 8460 lb Counterweight Usage: 114,610 Mi Asset located in: Humble, TX	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	330	1989 Grove RT875 75 ton 4x4x4 Rough Terrain Crane S/N: 72415 C/W: Anti Two-Block, PAT DS 350 GW Load	
326	2003 Grove TMS700E 60 ton 8x4 Hydraulic Truck Crane S/N: 223635 C/W: Eaton Fuller 9LL Manual Transmission, 21276 hrs Carrier Engine, Cummins ISM 450 6 Cylinder 10.8 L Diesel Carrier Engine, Anti Two-Block, PAT Load Moment Indicator, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 796 lb 40 ton Capacity Johnson 3 Sheave Hook Block, 16500 lb Counterweight, Counterweight Removal		Moment Indicator, 4590 hrs Crane C Cat 6 Cylinder Diesel Engine, 36 ft N 114 ft Maximum Boom Length, Aux Rooster Sheave, 33 ft to 58 ft Exten Swingaway Jib, 1850 lb 75 ton Capa Johnson 6 Sheave Hook Block, Ove Usage: 4,590 Hr Notes: DEFICIENCIES NOTED - PLEA THE INSPECTION REPORT	Moment Indicator, 4590 hrs Crane Operation, Cat 6 Cylinder Diesel Engine, 36 ft Minimum 114 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 33 ft to 58 ft Extendable Swingaway Jib, 1850 lb 75 ton Capacity Johnson 6 Sheave Hook Block, Overhaul Ball Usage: 4,590 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	System Usage: 226,835 Mi Asset located in : Humble, TX	331	2013 Grove RT 765E Rough Terrain Crane S/N: 232495 Usage: Not Available	
327	2003 Grove TMS500E 40 ton 6x4 Hydraulic Truck Crane S/N: 223654 C/W: Allison Automatic Transmission, Cat 3126 6 Cylinder Diesel Carrier Engine, PAT iFlex5 Load Moment Indicator, 29 ft Minimum 95 ft Maximum Boom Length, Rooster Sheave, 26 ft to 45 ft Extendable Swingaway Offset Jib, 25 ton Capacity Johnson 3 Sheave Hook Block, 365 lb 7.7 ton Capacity Overhaul Ball, 8460 lb Counterweight Usage: 133,436 Mi Asset located in: Humble, TX	332	Asset located in: Humble, TX 2011 Grove RT765E-2 65 ton 4x4 Rough Terrain Crane S/N: 232205 C/W: Air Conditioner, Anti Two-Block, Hirschmann iScout Load Moment Indicator, 3708 hrs Crane Operation, Cummins QSB 6 Cylinder 240 hp 6.7 L Diesel Engine, 36 ft Minimum 110 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, Swingaway Jib, 1252 lb 66 ton Capacity Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball Usage: 3,708 Hr	
328	2003 Grove TMS500E 40 ton 6x4 Hydraulic Truck Crane S/N: 223655 C/W: Allison Automatic Transmission, Cat 3126 6 Cylinder Diesel Carrier Engine, Anti Two-Block, PAT Load Moment Indicator, 29 ft Minimum 95 ft Maximum Boom Length, 26 ft to 45 ft Extendable Swingaway Offset Jib, 550 lb 25 ton Capacity 3 Sheave Hook Block, 365 lb 7.5 ton Capacity Overhaul Ball Usage: 13,850 Hr Asset located in: Humble, TX	333	Asset located in: Humble, TX Terex RT665 65 ton 4x4x4 Rough Terrain Crane S/N: 16427 C/W: Air Conditioner, Anti Two-Block, Greer RCI 510 Load Moment Indicator, 1354 hrs Crane Operation, Cummins QSB6.7 6 Cylinder 215 hp 6.7 L Diesel Engine, 36 ft Minimum 111 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 1204 lb 60 ton Capacity Terex 5 Sheave Hook Block, 400 lb 12 ton Capacity Overhaul Ball, 14200 lb Counterweight Usage: 1,354 Hr Asset located in: Humble, TX	
		334	2006 Grove RT760E Rough Terrain Crane	
			S/N: 226196 Usage: Not Available	

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
335	2011 Grove RT650E Rough Terrain Crane S/N: 231622 Usage: Not Available Asset located in: Humble, TX	342A 	Grove RT58D 20 ton 4x4 Rough Terrain Crane S/N: 75982 C/W: Air Conditioner, Anti Two-Block, 878 hrs Crane Operation, Cumnins 6 Cylinder 5.9 L
336	2009 Grove RT650E Rough Terrain Crane S/N: 229898 Usage: Not Available Asset located in: Humble, TX		Diesel Engine, 28 ft Minimum 70 ft Maximum Boom Length, 23 ft to 23 ft Jib, 22 ton Capacity 3 Sheave Hook Block, 150 lb Overhaul Ball, Rear Steer Usage: 878 Hr Asset located in: Humble, TX
337	Grove RT600E 4x4 Rough Terrain Crane S/N: 233495 C/W: Air Conditioner, Anti Two-Block, PAT iFlex5 Load Moment Indicator, 2013 US EPA Label, Cummins QSB6.7 6 Cylinder 173 hp 6.7 L Diesel Engine, 34 ft Minimum 105 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 29 ft to 51 ft Extendable Swingaway Offset Jib, 992 lb 50 ton Capacity Johnson Hook Block, 354 lb 8.3 ton Capacity Overhaul Ball, Rear Steer Usage: Not Available Asset located in: Humble, TX	342	Terex CD225 25 ton 4x4x4 Rough Terrain Crane S/N: 12287 C/W: Air Conditioner, Anti Two-Block, Greer RCI510 Load Moment Indicator, 4972 hrs Crane Operation, Cummins 4 Cylinder Diesel Engine, 30 ft Minimum 72 ft Maximum Boom Length, 26 ft to 43 ft Extendable Offset Jib, 636 lb 25 ton Capacity Koehring 2 Sheave Hook Block, 250 lb 7 ton Capacity Overhaul Ball Usage: 4,972 Hr Asset located in: Humble, TX
338	2008 Link-Belt RTC 8050 II Rough Terrain Crane S/N: J6J8-9992 Usage: Not Available Asset located in: Humble, TX	_343	1995 Galion 15 ton 4x4x4 Rough Terrain Crane S/N: C200008U010610 C/W: Air Conditioner, Komatsu Dresser KDC 6 Cylinder Diesel Engine, 16 ft Minimum 60 ft Maximum Boom Length, 375 lb 15 ton Capacity Komatsu 2 Sheave Hook Block
339	2007 Grove RT535E 4x4x4 Rough Terrain Crane S/N: 226028 C/W: Anti Two-Block, Hirschmann Load		Usage: Not Available Asset located in: Humble, TX
240	Moment Indicator, 5635 hrs Crane Operation, 6 Cylinder Diesel Engine, 32 ft Minimum 102 ft Maximum Boom Length, Auxiliary Hoist, Rooster Sheave, 102 ft to 128 ft Swingaway Jib, 588 lb 35 ton Capacity Johnson 3 Sheave Hook Block, Overhaul Ball Usage: 5,635 Hr Asset located in: Humble, TX	344	2013 Broderson IC2003H 30000 lb 4x4x4 Carry Deck Crane S/N: 251913200 C/W: Anti Two-Block, Greer MG586 Load Moment Indicator, 3299 hrs Crane Operation, Diesel Engine, 12 ft Minimum 50 ft Maximum Boom Length, 16 ft Swingaway Jib, 204 lb 15 ton Capacity Johnson 2 Sheave Hook Block Usage: 3,299 Hr
340	2006 Grove RT535E 35 ton 4x4 Rough Terrain Crane S/N: 226218 C/W: Air Conditioner, Hirschmann Load Moment Indicator, 8287 hrs Crane Operation, 2006 US EPA Label, Cummins 6 Cylinder Engine, 32 ft Minimum 102 ft Maximum Boom Length, 26 ft to 45 ft Extendable Swingaway Offset Jib, 588 lb 35 ton Capacity Johnson 3 Sheave Hook Block Usage: 8,287 Hr Asset located in: Humble, TX		Asset located in: Humble, TX 2000 Grove YB4415XT 15 ton 4x4x4 Carry Deck Crane S/N: 221062 C/W: Anti Two-Block, Cummins 4 Cylinder 3.9 L Diesel Engine, 17 ft Minimum 40 ft Maximum Boom Length, 11 ton Capacity Crosby 1 Sheave Hook Block, 3 spd Electric Shift on Fly Transmission Usage: 5,005 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
341	2001 Terex RT335 35 ton 4x4x4 Rough Terrain Crane S/N: 12915 C/W: Anti Two-Block, Greer RCI 510 Load Moment Indicator, 6 Cylinder Diesel Engine, 30 ft Minimum 94 ft Maximum Boom Length, 685 lb 40 ton Capacity Johnson 4 Sheave Hook Block Usage: Not Available Asset located in: Humble, TX	346	THE INSPECTION REPORT Asset located in: Humble, TX 2019 Broderson IC-100-3A 10 ton 4x4x4 Carry Deck Crane S/N: 12057100 C/W: B3.3 4 Cylinder 74 hp 3.3 L Diesel Engine, 13 ft Minimum 33 ft Maximum Boom Length, 10 ft to 10 ft Swingaway Offset Jib, 122 lb 10 ton Capacity McKissick 1 Sheave Hook Block, 90 lb Overhaul Ball Usage: 1,448 Hr Asset located in: Humble, TX

	Details	l ot #	Detaile	
Lot # 347	2014 Broderson IC-80-3J 18000 lb 4x4x4 Carry Deck Crane S/N: 68283380 C/W: Anti Two-Block, Greer MG580 Load Moment Indicator, 4206 hrs Crane Operation, 4 Cylinder 74 hp 3.3 L Diesel Engine, 11 ft Minimum 30 ft Maximum Boom Length, 10 ft to 10 ft Swingaway Jib, 122 lb 10 ton Capacity McKissick 2 Sheave Hook Block, 80 lb Overhaul Ball Usage: 4,206 Hr Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX	353 356	Details 2019 Broderson IC-80-3K 8.5 ton 4x4x4 Carry Deck Crane S/N: 73715080 C/W: B3.3 4 Cylinder 3.3 L Diesel Engine, 12 ft Minimum 30 ft Maximum Boom Length, 10 ft to 10 ft Offset Jib, 122 lb 10 ton Capacity McKissick 1 Sheave Hook Block, 90 lb Overhaul Ball Usage: 1,288 Hr Asset located in: Humble, TX Elliott 32117R 64000 lb Straight Boom on 2014 Freightliner 108SD 6x4 Boom Truck S/N: 3ALHG5CY2EDFU9850	
348	2013 Broderson IC-80-3J 18000 lb 4x4x4 Carry Deck Crane S/N: 67101580 C/W: Anti Two-Block, Greer MG586 Load Moment Indicator, 789 hrs Crane Operation, 2012 US EPA Label, Kem Power 4 Cylinder 86 hp Gasoline Engine, 12 ft Minimum 30 ft Maximum Boom Length, 10 ft Swingaway Jib, 122 lb 10 ton Capacity McKissick 1 Sheave Hook Block Usage: Not Available Asset located in: Humble, TX		C/W: Cummins ISL9 6 Cylinder Ultra Low Sulfur Diesel 330 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 12855 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, TufTrac Spring Suspension, 272 in Wheelbase, PTO, 64000 lb Capacity, Rear Mounted, 28 ft - 117 ft 5 Section Boom, McKissick 251 lb 1 Sheave 15 ton Capacity Hook Block, 170 lb Overhaul Ball 7 ton Capacity, 24 ft Swingaway Offset Jib, Greer Insight Load Moment Indicator, Out and Down Outriggers, Rear	
349	2013 Broderson IC-80-3J 18000 lb Carry Deck Crane S/N: 65999380 C/W: Anti Two-Block, 4 Cylinder Diesel Engine, 12 ft Minimum 36 ft Maximum Boom Length, 10 ft to 10 ft Swingaway Jib, Overhaul Ball Usage: 1,471 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Outriggers, 5th Outrigger, 21 ft 6 in x 93 in Bed Usage: 241,402 Mi Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN	
350	2008 Broderson IC-80-3H 18000 lb 4x4 Carry Deck Crane S/N: 611040 C/W: Anti Two-Block, Greer MG586 Load Moment Indicator, 563 hrs Crane Operation, 4 Cylinder Diesel Engine, 12 ft Minimum 30 ft Maximum Boom Length, 10 ft Swingaway Jib, Crosby Hook Block Usage: 7,755 Hr Asset located in: Humble, TX		PRIOR TO REMOVAL OF UNIT DEFICIENCIES NOTED - PLEAS INSPECTION REPORT Asset located in: Humble, TX 356 2010 Hiab 144 B -3 HIDUO 904 Boom on 2011 Ford F-750 XL - S/N: 3FRXF7FG5BV545635 C/W: Cummins ISB 6 Cylinder	Asset located in: Humble, TX 2010 Hiab 144 B -3 HIDUO 9040 lb Knuckle Boom on 2011 Ford F-750 XL 4x2 Boom Truck S/N: 3FRXF7FG5BV545635 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 325 hp Engine, 2011 US EPA Label, Requires Diesel
351	2009 Grove YB4409-2 18000 lb Carry Deck Crane S/N: 321208 C/W: Air Conditioner, Anti Two-Block, LSI GS550 Load Moment Indicator, 1841 hrs Crane Operation, 4 Cylinder Diesel Engine, 12 ft Minimum 30 ft Maximum Boom Length, 30 ft to 48 ft Swingaway Jib, 100 lb 7 ton Capacity Johnson Hook Block Usage: 1,841 Hr Asset located in: Humble, TX		Exhaust Fluid, Automated Transmission, 1200 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 243 in Wheelbase, PTO, 9040 lb Capacity, Center Mounted, 5 ft - 35 ft 4 Section Boom, Out and Down Outriggers, 15 ft 10 in x 97 in Bed Usage: 45,502 Mi Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
358	IMT 4825 6400 lb Knuckle Boom on 1999 Ford F800 4x2 Boom Truck S/N: 3FEXF8014XMA17998	367	2021 Vermeer PD10R Crawler Mounted Post Driver S/N: 1VRR1008TM1001055
	C/W: Cummins ISB 6 Cylinder 5.9 L Diesel 215 hp Engine, 1998 US EPA Label, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring		C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks Usage: 3,329 Hr
	Suspension, 190 in Wheelbase, PTO, 6400 lb		Notes: LOCATED-IN-MIDLAND-TX
	Capacity, Front Mounted, 7 ft 6 in - 30 ft 5 in 3 Section Boom, Dual Controls, Straight Down		Asset located in: Midland, TX
	Outriggers, 8 ft x 96 in Bed, Winch, Pintle Hitch Usage: 107,048 Mi Notes : LOCATED-IN-FORT-WORTH-TX	368	2021 Vermeer PD10R Crawler Mounted Post Driver
	Asset located in: Lake Worth, TX		S/N: 1VRR1008CM1001054 C/W: 2020 US EPA Label, Deutz D2.9L4 4
359	2009 Cat 325D L Foundation Drill S/N: C3N00476		Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks
	C/W: Rear View Camera, Auxiliary Hydraulic		Usage: 2,869 Hr Notes: LOCATED-IN-MIDLAND-TX
	Plumbing, 31 in Triple Grouser Track Shoes, Lodrill 4 in Kelly, EQUIPMENT-FROM-A-		Asset located in: Midland, TX
	PRIMORIS-SERVICES-CORP-COMPANY Usage: 3,497 Hr	369	2021 Vermeer PD10R Crawler Mounted Post Driver
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1VRR1008LM1001051
	Asset located in: Livingston, LA		C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 36.4 kW 2.92 L Diesel Engine, Remote
363	2014 Ditch Witch JT30 Directional Drill		Control, 16 in Rubber Tracks
	S/N: CMWAT30XVE0000226 C/W: Open Operator Station, 4 Cylinder Diesel Engine, Mud Mixing System, Drill Rod Loading System 13 Drill Rods, 13 in Rubber Tracks, Comes With: Ditch Witch FM13v Mud Mixing		Usage: 4,084 Hr Notes : LOCATED-IN-MIDLAND-TX
			Asset located in: Midland, TX
		370	2012 Vermeer RT450 4x4 Trencher
	System		S/N: 1VRX07217C1000145 C/W: Canopy, Diesel Engine, Hydrostatic Drive, 5.5 in Wide x 6 ft 5 in Long Combination Trencher Chain, Vermeer Backhoe Attachment, Straight Blade, Side Shift Usage: 2,286 Hr
	Usage: 639 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
	Asset located in: Humble, TX		
364	2012 Ditch Witch JT2020 Mack 1 Directional		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Drill S/N: CMWJ2020TC0001612		Asset located in: Humble, TX
	C/W: Open Operator Station, 4 Cylinder Diesel	371	2007 Ditch Witch RT-40 4x4 Trencher
	Engine, Drill Rod Loading System 38 Drill Rods, 11 in Rubber Tracks		S/N: CMWRT40XK70002016
	Usage: 3,977 Hr Notes: LOCATED-IN-FORT-WORTH-TX RITCHIE-		C/W: 2007 US EPA Label, Deutz D2011L03 3 Cylinder 31.5 kW 2.33 L Diesel Engine,
	BROS-ENERGY		Hydrostatic Drive, 5.5 in Wide x 5 ft Long A322 Backhoe Attachment, Angle Blade, Discharge
	Asset located in: Lake Worth, TX		Conveyor, Side Shift Usage: 330 Hr
365	2015 Ditch Witch JT9 Directional Drill		Asset located in: Humble, TX
	S/N: CMWJT9XXEF0000100 C/W: Open Operator Station, 2014 US EPA	381	2007 Mauldin 1750C Track Asphalt Paver
	Label, Deutz td2.914 4 Cylinder 66 hp 2.9 L Diesel Engine, 9 in Rubber Tracks		S/N: 879G75TJS6Y201879
	Usage: 2,Ž48 Hr		C/W: Dual Controls, Propane Heated 7 ft 6 in - 16 ft Screed, 12 in Track Shoes w/Rubber Pads
	Notes: LOCATED-IN-FORT-WORTH-TX		Usage: Not Available
066	Asset located in: Lake Worth, TX	_	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
366	2021 Vermeer PD10R Crawler Mounted Post Driver		Asset located in: Humble, TX
	S/N: 1VRR1008CM1001076	382	2017 Case SV340 Skid Steer Loader
	C/W: 2020 US EPA Label, Deutz D2.9L4 4 Cylinder 36.4 kW 2.92 L Diesel Engine, Remote Control, 16 in Rubber Tracks Usage: 2,152 Hr		S/N: JAFSV340KHM440423 C/W: Enclosed Cab (Door missing), Joystick Steering, Hydraulic Coupler, Forks Usage: 5,253 Hr
	Notes: LOCATED-IN-MIDLAND-TX		Asset located in: Humble, TX
	Asset located in: Midland, TX		

Lot #	Details	Lot #	Details
383	2017 Case SV340 Skid Steer Loader	393	2022 Cat 226D3 Skid Steer Loader
	S/N: JAFSV340PHM440596 Usage: Not Available		S/N: CAT0226DTEK501124 C/W: Enclosed Cab, Air Conditioner, Joystick
	Asset located in: Humble, TX		Steering, Manual Coupler, 73 in Bucket Usage: 1,950 Hr
384	2017 Case SV340 Skid Steer Loader S/N: JAFSV340CHM437811 C/W: Enclosed Cab (Door missing), Joystick Steering, Hydraulic Coupler		Asset located in: Humble, TX
		395	2010 Bobcat S130 Skid Steer Loader
			S/N: A3KY37368
	Usage: 1,733 Hr Asset located in: Humble, TX		C/W: Enclosed Cab, Aperture Tires, Manual Coupler, 72 in Grapple Bucket, Grapple, Extra
385	2014 Bobcat S650 Skid Steer Loader	-	Bucket 67" Usage: 5,901 Hr
000	S/N: ALJ811941		Notes: DEFICIENCIES NOTED - PLEASE SEE
	C/W: Open Operator Station, 2014 US EPA Label, Manual Coupler, 73 in Bucket		THE INSPECTION REPORT
	Usage: 6,028 Hr		Asset located in: Humble, TX
	Asset located in: Humble, TX	396	2007 John Deere 325 Skid Steer Loader S/N: T00325A144100
386	2016 Bobcat S630 Skid Steer Loader		C/W: Open Operator Station, 77 in Bucket,
	S/N: AHGL12911 Usage: Not Available		Counterweight Kit Usage: 566 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
387	2021 Bobcat S66 Two-Speed Skid Steer Loader	397	2007 John Deere 325 Skid Steer Loader
	S/N: B4SA11821 C/W: Open Operator Station, 2020 US EPA		S/N: T00325A143484
	Label, Manual Coupler		C/W: Open Operator Station, Manual Coupler 74 in Bucket, Counterweight Kit
	Usage: 2,088 Hr Asset located in: Humble, TX		Usage: 10,117 Hr Asset located in: Humble, TX
388	2020 Bobcat S570 Skid Steer Loader	398	2006 John Deere 325 Skid Steer Loader
000	S/N: ALM429801	396	S/N: T00325A130381
	C/W: Open Operator Station, 2019 US EPA Label, Manual Coupler, 61 in Bucket		C/W: Open Operator Station, Manual Coupler,
	Usage: 1,484 Hr		73 in Bucket, Counterweight Kit Usage: 9,932 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
389	2013 Bobcat S570 Skid Steer Loader S/N: A7U711635	399	2000 John Deere 260 Two-Speed Skid Steer
	C/W: Open Operator Station, Aperture Tires,		Loader S/N: KV0260B261674
	Manual Coupler, Forks Usage: 880 Hr		C/W: Open Operator Station, Joystick Steering Manual Coupler, 72 in Bucket Usage: 519 Hr
	Asset located in: Humble, TX		
390	2015 Bobcat S550 Skid Steer Loader		Notes: LOCATED-IN-LIVINGSTON_LA;
	S/N: AHGM11975		SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE
	Usage: Not Available Asset located in : Humble, TX		INSPECTION REPORT
391	2022 Cat 226D3 Skid Steer Loader	 	Asset located in: Livingston, LA
071	S/N: CAT0226DVEK501311	400	2005 Cat 252B Skid Steer Loader S/N: CAT0252BASCP01005
	C/W: Enclosed Cab, Air Conditioner, Air Ride		C/W: Enclosed Cab, Joystick Steering, Aperture
	Seat, Joystick Steering, 14 Pin Electric Kit, Manual Coupler, 67 in Bucket		Tires, 8 Pin Electric Kit, Manual Coupler, 79 in Bucket
	Usage: 1,662 Hr		Usage: Not Available
202	Asset located in: Humble, TX	_	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
392	2022 Cat 226D3 Skid Steer Loader S/N: CAT0226DEEK501234		Asset located in: Humble, TX
	C/W: Enclosed Cab, Air Conditioner, Joystick	401	2006 Volvo MC80B Skid Steer Loader
	Steering, Manual Coupler, 68 in Bucket, Water System		S/N: VCEMC80B06112300
	Usage: 1,628 Hr		C/W: Open Operator Station, 2005 US EPA Label, Aperture Tires, Manual Coupler
	Asset located in: Humble, TX		Usage: 1,271 Hr
			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
402	2005 Cat 246B Skid Steer Loader S/N: CAT0246BTPAT01833 C/W: Enclosed Cab, Joystick Steering, 2004 US EPA Label, Aperture Tires, Manual Coupler, 73 in Bucket, Forks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	411	2022 Takeuchi TL12R2 Compact Track Loader S/N: 412103401 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Tier 4, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 72 in Bucket Usage: 3,366 Hr Asset located in: Humble, TX
404	2001 Bobcat 773 Skid Steer Loader	412	2021 Bobcat T76 Compact Track Loader
	S/N: 519020214 C/W: Open Operator Station, 2001 US EPA Label, Aperture Tires, Manual Coupler, 16 in Digging, Backhoe Usage: 1,853 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: B4CE14357 C/W: Open Operator Station, Joystick Steering, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 996 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
406	2024 Cat 299D3XE Two-Speed Compact Track	413	2021 Bobcat T76 Compact Track Loader
400	Loader S/N: CAT299D3HB6203289 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, 18 in Track Belts, 9 Pin Electric Kit, Manual Coupler, Counterweight Kit Usage: 20 Hr Notes: NO WARRANTY AVAILABLE;	S/N: B4CE14353 C/W: Open Operator Station, Joystick Steer US EPA Label, 12 in Track Belts, Manual Coupler, 79 in Usage: 1,105 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMMITH IRONCLAD ASSURANCE. SUBJECT TEXAS SALES TAX. Asset located in: Lake Worth, TX 414 2021 Bobcat T76 Compact Track Loader S/N: B4CE15366 C/W: Open Operator Station, Joystick Steer US EPA Label, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 1,133 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMMITH IRONCLAD ASSURANCE. SUBJECT TEXAS SALES TAX. Asset located in: Lake Worth, TX 415 2016 John Deere 333G Two-Speed Compact Track Loader S/N: 1T0333GKVGF303710 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Patter Changer, Requires Diesel Exhaust Fluid, 18 Track Belts, 7 Pin Electric Kit, Hydraulic Coupler, 83 in Bucket, Counterweight Kit Usage: 3,995 Hr Asset located in: Humble, TX 416 2012 John Deere 333D Two-Speed Compact Track Loader S/N: 1T0333DMPCD232059 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Patter Changer, 18 in Track Belts, 7 Pin Electric Kit	S/N: B4CE14353 C/W: Open Operator Station, Joystick Steering, US EPA Label, 12 in Track Belts, Manual Coupler, 79 in Usage: 1,105 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX.
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		•
407	Asset located in: Humble, TX 2024 Cat 299D3 XE Two-Speed Compact Track Loader S/N: CAT299D3HB6203292 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 17.5 in Track Belts, Manual Coupler, Counterweight Kit		
	Usage: 4 Hr Notes: NO WARRANTY AVAILABLE		
408	Asset located in: Humble, TX 2019 Cat 299D2 Two-Speed High Flow XPS Compact Track Loader S/N: CAT0299DEFD204748 C/W: Enclosed Cab, Air Conditioner, Ride Control, Joystick Steering, Self Leveling, Rear View Camera, Requires Diesel Exhaust Fluid, 18 in Track Belts, 14 Pin Electric Kit, Hydraulic		C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Pattern Changer, Requires Diesel Exhaust Fluid, 18 in Track Belts, 7 Pin Electric Kit, Hydraulic Coupler, 83 in Bucket, Counterweight Kit Usage: 3,995 Hr Asset located in: Humble, TX
	Coupler, 80 in Bucket Usage: 3,332 Hr Asset located in : Humble, TX		
409	2022 Takeuchi TL12R2 Two-Speed High Flow Compact Track Loader S/N: 412105204 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Self Leveling, Rear View Camera, Tier 4, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Hydraulic Coupler, 84 in Bucket Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, Control Pattern Changer, 18 in Track Belts, 7 Pin Electric Kit, Hydraulic Coupler, 67 in Bucket, Counterweight Kit Usage: 4,322 Hr

Lot #	Details	Lot #	Details
Track Loader S/N: 1T0331GMCHF311899 C/W: Open Operator Station, Air R Joystick Steering, Rear View Cam Diesel Exhaust Fluid, 18 in Track E Coupler, 83 in Bucket	S/N: 1T0331GMCHF311899 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, Rear View Camera, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler, 83 in Bucket	424	2019 Case TV450 Compact Track Loader S/N: NKM470236 C/W: Open Operator Station, 17.5 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, 77 in Bucket Usage: 1,622 Hr Asset located in: Humble, TX
	Usage: 3,339 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	2019 Bobcat T770 Compact Track Loader S/N: AT6321907 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 17.5 in Track	
418	2020 Cat 289D3 Two-Speed Compact Track Loader S/N: CAT0289DCJX901413 C/W: Open Operator Station, Joystick Steering, Tier 4, 2020 US EPA Label, 17.5 in Track Belts,	426	Belts, Manual Coupler, 67 in Bucket Usage: 2,566 Hr Asset located in: Humble, TX 2014 Bobcat T770 Two-Speed Compact Track Loader
	Manual Coupler, 78 in Bucket, Forks Usage: 3,285 Hr Asset located in : Humble, TX		S/N: AN8T13652 C/W: Open Operator Station, 17 in Track Belts, Manual Coupler, 78 in Bucket
419	2020 Cat 289D3 Compact Track Loader S/N: CAT0289DKJX901425 C/W: Open Operator Station, Joystick Steering, 2019 US EPA Label, 14 in Track Belts, Manual		Usage: 4,311 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Coupler, 72 in Bucket, Forks Usage: 2,799 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	427	2020 Wacker Neuson ST45 Compact Track Loader S/N: WNCS0606EPUM00714 Usage: Not Available
420	Asset located in: Humble, TX	4	Asset located in: Humble, TX
420	2019 Cat 289D3 Compact Track Loader S/N: CAT0289DAJX901544 Usage: 2,106 Hr Asset located in: Humble, TX 2019 Cat 289D3 Two-Speed Compact Track Loader S/N: CAT0289DKJX902266 C/W: Open Operator Station, Air Ride Seat,	428A	2022 Takeuchi TL10V2 Compact Track Loader S/N: 410005232 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, Tier 4, 2021 US EPA Label, 16 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 76 in Bucket Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX
	Joystick Steering, Rear View Camera, Tier 4, 2019 US EPA Label, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 4,129 Hr	428	Asset located in: Midland, TX 2011 Takeuchi TL240 Series 2 Compact Track Loader
	Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		S/N: 224001342 C/W: Open Operator Station, Joystick Steering, 2011 US EPA Label, 17 in Track Belts, 14 Pin Electric 2601 Us
422	2014 Cat 289D Two-Speed High Flow XPS		Usage: 2,601 Hr Asset located in: Humble, TX
	Compact Track Loader S/N: CAT0289DLTAW01963 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, Tier 4, 2014 US EPA Label, 18 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler, Forks, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: 5,742 Hr Asset located in: Humble, TX	429	2017 Takeuchi TL10V2-CR Compact Track Loader S/N: 410000418 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Joystick Steering, Tier 4, 2016 US EPA Label, 14 in Track Belts, Manual Coupler, 66 in Bucket Usage: 63 Hr
423	2014 Cat 289D Compact Track Loader S/N: TAW01963 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
430	2019 Bobcat T740 Compact Track Loader S/N: B3CA16445 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2019 US EPA Label, 17.5 in Track Belts, Manual Coupler, 82 in Bucket Usage: 1,851 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	438	2022 Cat 259 D3 Two-Speed High Flow Compact Track Loader S/N: CW916472 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Ride Control, Joystick Steering, Self Leveling, Rear View Camera, 2021 US EPA Label, 15.5 in Track Belts, 14 Pin Electric Kit, Hydraulic Coupler, 79 in Bucket Usage: 1,362 Hr Asset located in: Humble, TX
431	2021 Cat 279D3 Two-Speed Compact Track Loader S/N: CAT0279DHRB903137 C/W: Open Operator Station, Joystick Steering, 2021 US EPA Label, 17.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 79 in Bucket Usage: 1,117 Hr Asset located in: Humble, TX	439	2019 Cat 259 D3 Two-Speed Compact Track Loader S/N: CAT0259DPCW901608 C/W: Open Operator Station, Joystick Steering, Tier 4, 2023 US EPA Label, 15.5 in Track Belts, Manual Coupler, 80 in Bucket, Forks Usage: 2,314 Hr Asset located in: Humble, TX
432	2013 Cat 279C2 Two-Speed Compact Track Loader S/N: CAT0279CJKWB0075 C/W: Open Operator Station, Joystick Steering, 16 in Track Belts, 8 Pin Electric Kit, Manual Coupler, 80 in Bucket Usage: 4,273 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	440	2018 Cat 259D Two-Speed Compact Track Loader S/N: CAT0259DVFTL18483 C/W: Enclosed Cab, Air Conditioner, Joystick Steering, 2018 US EPA Label, 16 in Track Belts, 9 Pin Electric Kit, Hydraulic Coupler Usage: 1,993 Hr Asset located in: Humble, TX
433	2018 Case TV370 Compact Track Loader S/N: JAFTV370PJM448767 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 16 in Track Belts, Hydraulic Coupler, 80 in Bucket Usage: 3,055 Hr Asset located in: Humble, TX	442	2021 Bobcat T64 R-Series Compact Track Loader S/N: B4SD12335 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,234 Hr
434	2017 Bobcat T650 Compact Track Loader S/N: ALJG20820 C/W: Enclosed Cab (Door missing), 2016 US EPA Label, 12 in Track Belts, Manual Coupler,		Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
	73 in Bucket Usage: 2,192 Hr Asset located in: Humble, TX	443	2021 Bobcat T64 R-Series Compact Track Loader S/N: B4SD13060
435	2017 Kubota SVL75-2W Compact Track Loader S/N: 32169 Usage: 3,518 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	444	C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, 2021 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,300 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO
436	2017 Kubota SVL75-2 Compact Track Loader S/N: JKUCC752A01S30020 C/W: Open Operator Station, Joystick Steering,		TEXAS SALES TAX. Asset located in: Lake Worth, TX 2021 Bobcat T64 Compact Track Loader
467	15.5 in Track Belts, Manual Coupler Usage: 2,315 Hr Asset located in: Humble, TX		S/N: B4SD12333 C/W: Open Operator Station, Joystick Steering Control Pattern Changer, 2020 US EPA Label, 12.5 in Track Belts, Manual Coupler, 68 in Bucket Usage: 1,248 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COME WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX
437	2020 Bobcat T66 Compact Track Loader S/N: B4SB11862 C/W: Open Operator Station, Joystick Steering, 2020 US EPA Label, 12 in Track Belts, 7 Pin Electric Kit, Manual Coupler, 75 in Bucket, Counterweight Kit Usage: 1,400 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
445	2021 Bobcat T64 Compact Track Loader S/N: B4SD12390 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, Manual Coupler, 73 in Bucket Usage: 1,341 Hr Notes: LOCATED-IN-FORT-WORTH-TX; COMES WITH IRONCLAD ASSURANCE. SUBJECT TO TEXAS SALES TAX. Asset located in: Lake Worth, TX	458	2011 Cat 259B3 Two-Speed Compact Track Loader S/N: CAT0259BCYYZ01297 C/W: Open Operator Station, Joystick Steering, 12 in Track Belts, 67 in Bucket Usage: 6,817 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
446	2019 Bobcat T630 High Flow Compact Track Loader S/N: AJDT16716 C/W: Enclosed Cab (Door missing), Joystick Steering, 2019 US EPA Label, 15.5 in Track Belts, Manual Coupler, 77 in Bucket Usage: 1,455 Hr	459	2008 Takeuchi TL140 Compact Track Loader S/N: 21406595 C/W: Open Operator Station, Joystick Steering, 17 in Track Belts, Manual Coupler, 73 in Bucket Usage: 794 Hr Asset located in: Humble, TX
447	Asset located in: Humble, TX 2014 Bobcat T630 Compact Track Loader S/N: AJDT11279 C/W: Open Operator Station, 2014 US EPA	460	2005 ASV RC100 R-Series Compact Track Loader S/N: RSD01507 C/W: Enclosed Cab (Door missing), Air Conditioner, Joystick Steering, 18 in Track
	Label, 17 in Track Belts, Manual Coupler, 79 in Bucket Usage: 3,812 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	46.0	Belts, 8 Pin Electric Kit, Hydraulic Coupler, 72 in Bucket Usage: 1,748 Hr Asset located in: Humble, TX
448	Asset located in: Humble, TX 2016 Takeuchi TL8 Compact Track Loader S/N: 200803937 Usage: Not Available	461	2008 Bobcat T190 Compact Track Loader S/N: A3LN12027 C/W: Open Operator Station, 13 in Track Belts, Manual Coupler Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
449	2016 Takeuchi TL8 Compact Track Loader S/N: 200803826 C/W: Open Operator Station, Air Ride Seat, Joystick Steering, 15 in Track Belts, 14 Pin Electric Kit, Manual Coupler Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	462	2008 Bobcat T140 Compact Track Loader S/N: 529312573 C/W: Enclosed Cab (Door missing), Tier 2, 2015 US EPA Label, 12 in Track Belts, Manual Coupler, 66 in Usage: 6,414 Mi Asset located in: Humble, TX
	THE INSPECTION REPORT	463	2006 ASV RC30 Compact Track Loader
451	Asset located in: Humble, TX 2011 Takeuchi TL230 Series 2 Compact Track Loader S/N: 223100502 C/W: Enclosed Cab, Air Conditioner, Joystick		S/N: RSA02549 C/W: Open Operator Station, Joystick Steering, 9 in Track Belts, Manual Coupler, 48 in Bucket Usage: 1,586 Hr Asset located in : Humble, TX
	Steering, Tier 4, 2011 US EPA Label, 12.5 in Track Belts, 14 Pin Electric Kit, Manual Coupler, 72 in Bucket Usage: Not Available Asset located in: Humble, TX	464	2004 ASV RC30 Compact Track Loader S/N: RSA02171 C/W: Open Operator Station, Joystick Steering, 9 in Track Belts, Manual Coupler, 48 in Bucket Usage: 1,873 Hr
457	2017 Bobcat T550 Compact Track Loader	7	Asset located in: Humble, TX
	S/N: AJZV17895 C/W: Open Operator Station, Joystick Steering, Control Pattern Changer, Tier 4, 2017 US EPA Label, 12.5 in Track Belts, Manual Coupler, Hammer Usage: 1,962 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	465	Mahindra 2555ST 4WD Utility Tractor S/N: 55GCJ00311 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, Forward/ Reverse Shuttle, Mahindra 2555CL Loader w /Joystick, Quick Coupler, 1 Rear Remotes, 540 PTO, 3-Point Hitch, 12x16.5 Front Tires, 16.9 x24 Rear Tires Usage: 415 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
466	2003 Kubota MX5000E 2WD Utility Tractor S/N: 11584 C/W: 4 Forward 4 Reverse, Manual Transmission, 38.0 kW Engine, 2003 US EPA Label, TAS ML280 Loader, 61 in Bucket, 3-Point Hitch, 29x12.50-15 Front Tires, 44x18.00-20 Rear Tires Usage: 481 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	472	2016 Kubota BX2670 4WD Utility Tractor S/N: 25840 C/W: Differential Lock, Hydrostatic Drive, 2015 US EPA Label, Kubota LA243 Loader w /Joystick, 48 in Bucket, 60 in Mower Deck, 540 PTO, 3-Point Hitch, 18x8.50-10 Front Tires, 26x12.00-12 Rear Tires Usage: 140 Hr Asset located in: Humble, TX
467	·	473	2020 Kubota L2501D 4WD Utility Tractor
467	2019 John Deere 5045E 2WD Utility Tractor S/N: 1PY5045ELKK108917 C/W: Differential Lock, 2019 US EPA Label, John Deere 512 Loader, Quick Coupler, 74 in Bucket, 2 Mid-Mount Remotes, 1 Rear Remotes, 540 PTO, 3-Point Hitch w/ Quick Hitch, Frontier RC2072 72 in Mower, 7.50-16 Front Tires, 14.9-28 Rear Tires Usage: 1,136 Hr		S/N: KBUL6DDRHL8GA5665 C/W: Differential Lock, 8 Forward 4 Reverse, Manual Transmission, 2020 US EPA Label, Kubota LA526 Loader w/Joystick, Quick Coupler, Kubota L2248 66 in Bucket, HID Lights, 540 PTO, 3-Point Hitch, Drawbar, 7.2-16 Front Tires, 11.2x24 Rear Tires Usage: 392 Hr Notes: LOCATED-IN-FORT-WORTH-TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Lake Worth, TX
	THE INSPECTION REPORT	474	Kubota B6100E 2WD Utility Tractor
468	Asset located in: Humble, TX 2020 LS XR3135 4WD Utility Tractor S/N: 2259001198 C/W: Enclosed Cab, Air Conditioner, Air Ride Seat, Differential Lock, 12 Forward 12 Reverse,		S/N: 18326 C/W: Manual Transmission, 540 PTO, 18x8.50- 8 Front Tires, 29x12.50-15 Rear Tires Usage: Not Available Asset located in : Humble, TX
	Manual Transmission, 35 hp Engine, LS Loader w/Joystick, Quick Coupler, 66 in Bucket, 2 Rear Remotes, Exterior 3-Point Hitch Controls, 540 PTO, 3-Point Hitch, 7-14 Front Tires, 11.2x24 Rear Tires	476	2022 John Deere 5100M 2WD Tractor S/N: 1LV5100MLNM104106 Usage: Not Available Asset located in: Humble, TX
	Usage: 40 Hr Asset located in: Humble, TX	478	2006 John Deere 5303 2WD Tractor
469	1991 John Deere 1070 2WD Utility Tractor S/N: M01070A105151 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, 540 PTO, 3-Point Hitch, 62 in Mower, 6.50-16 Front Tires, 13.6-28 Rear Tires Usage: 568 Hr Asset located in: Humble, TX		S/N: PYS5303U005344 C/W: Canopy, 9 Forward 3 Reverse, SyncReverser, 1 Rear Remotes, 540 PTO, Drawbar, 7.50-16 Front Tires, 16.9-28 Rear Tires Usage: 2,289 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
470	2016 John Deere 3032E 4WD Utility Tractor S/N: 1LV3032EJGG106774 C/W: Canopy, Hydrostatic Drive, John Deere D160 Loader w/Joystick, Quick Coupler, John Deere 63 in Bucket, 540 PTO, 3-Point Hitch, Frontier BB5072 72 in Box Blade, 25x8.50-14 Front Tires, 15x19.5 Rear Tires Usage: 1,032 Hr Asset located in: Humble, TX Kubota L2900GST 4WD Utility Tractor	479	Mahindra 4540 2WD Tractor S/N: MBCNY2140 C/W: Differential Lock, 8 Forward 2 Reverse, Manual Transmission, Mahindra 4550-2L Loader w/Joystick, 59 in Bucket, 540 PTO, 3- Point Hitch, 225/90/16 Front Tires, 12.4x28 Rear Tires Usage: 417 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
4/1			Asset located in: Humble, TX
	S/N: 64654 C/W: Canopy, 8 Forward 8 Reverse, Glide Shift, 32 hp Engine, Kubota LA482 Loader w /Joystick, 60 in Bucket, 540 PTO, 3-Point Hitch, drawbar, 7-16 Front Tires, 12.4x24 Rear Tires Usage: 1,016 Hr Asset located in: Humble, TX	481B	2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MANM104105 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, PowrReverser, Forward/ Reverse Shuttle, 2022 US EPA Label, Requires Diesel Exhaust Fluid, John Deere 540M Loader w /Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, 320/85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,153 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

		_	
Lot #	Details	Lot #	Details
481A	2022 John Deere 5100M 4WD Tractor S/N: 1LV5100MHNM104107 C/W: Canopy, Differential Lock, 16 Forward 16 Reverse, Forward/ Reverse Shuttle, 2023 US EPA Label, Requires Diesel Exhaust Fluid, John Deere 540M Loader w/Joystick, Quick Coupler, 3 Rear Remotes, 540 PTO, Drawbar, 320 /85R24 Front Tires, 460/85R30 Rear Tires Usage: 2,182 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	485	Taylor Y-18-WOM 18000 lb Pneumatic Tire Forklift S/N: S2611690 C/W: 2 Stage Mast, 117 in Lowered Mast Height, 72 in Forks, Side Shift, Ford 6 Cylinder Gasoline Engine Usage: 5,539 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
481	2022 Case IH Farmall 120C 4WD Tractor	486	Hyster H190HD 17500 lb Pneumatic Tire Forklift
	S/N: ELRFC120ENLF50113 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, Forward/ Reverse Shuttle, Case IH L630 Loader w /Joystick, Skid Steer Coupler, 84 in Bucket, 1 Front Remotes, 3 Rear Remotes, 540 PTO, 3- Point Hitch, Drawbar, 380/85R24 Front Tires,		S/N: H007E02563H C/W: 2 Stage Mast, 212 in Max Lift Height, 156 in Lowered Mast Height, 92 in Forks, Side Shift, Cummins 6 Cylinder Diesel Engine Usage: 10,098 Hr Asset located in: Humble, TX
	460/85R34 Rear Tires Usage: 222 Hr	487	2014 Sellick S80J4I-2 8000 lb 4x4 Rough
	Asset located in: Humble, TX		Terrain Forklift
482	2018 John Deere 5065E 4WD Tractor S/N: 1PY5065EKJJ402021 C/W: Enclosed Cab, Air Conditioner, Differential Lock, 12 Forward 12 Reverse, PowrReverser, Forward/ Reverse Shuttle, John Deere 520M Loader w/Joystick, Quick Coupler, John Deere 70 in Bucket, 1 Rear Remotes, 540 PTO, 3-Point Hitch, Drawbar, Frontier LP1207 88 in Scraper Blade, 9.5x24 Front Tires, 16.9-28 Rear Tires, 48 in Forks, Hay Baler, Post Hole Auger		S/N: 9135402S8J4T C/W: Enclosed Cab, Single Stage Mast 144 in Max Lift Height, 24 in Lowered Mast Height, 6 in Forks, Auxiliary Hydraulic Plumbing, 2014 U EPA Label, Diesel Engine Usage: 11,227 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
		488A 	2008 Maximal 35M 7715 lb 4x4 Rough Terrain
	Asset located in: Humble, TX		Forklift
483	1999 Hyster H1050E 88000 lb Container Handler S/N: D117E01627W C/W: Enclosed Cab, Air Conditioner, 498 in Max Lift Height, 1998 US EPA Label, Cummins M11-		S/N: 1503501315 C/W: 3 Stage Mast, Full Free Lift, 119 in Lowered Mast Height, 72 in Forks, Side Shift, Cylinder Diesel Engine Usage: 3,551 Hr Asset located in: Humble, TX
	C 6 Cylinder 290 hp 11.0 L Diesel Engine Usage: 3,587 Hr	488	2015 Case 586H 2WD 17100 lb 4x2 Rough
	Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Terrain Forklift S/N: NFC728059 C/W: 3 Stage Mast, 264 in Max Lift Height, 126 in Lowered Mast Height, 46 in Forks, Side Shift,
484	2019 Kalmar DCG100-6T 22000 lb Pneumatic	+	FPT INDUSTRIAL 4 Cylinder Diesel Engine Usage: Not Available
707	Tire Forklift		Asset located in: Humble, TX
	S/N: B40500208 C/W: Enclosed Cab, Air Conditioner, Single Stage Mast 4750 mm Max Lift Height, 154 in Lowered Mast Height, 91 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2019 US EPA Label, CARB Compliant, Volvo penta 105 kW Diesel Engine, Requires Diesel Exhaust Fluid Usage: 12,598 Hr Asset located in: Humble, TX	489	Cat RC60 6000 lb 4x2 Rough Terrain Forklift S/N: 31A00998 C/W: 2 Stage Mast, 168 in Max Lift Height, 117 in Lowered Mast Height, 45 in Forks, Cat 4 Cylinder Diesel Engine Usage: 23,716 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
490	2018 JCB 51256S Telehandler S/N: JCB5CH2GTJ2754241 C/W: Enclosed Cab, Air Conditioner, 56 ft Max	497	2017 JLG 1255 Telehandler S/N: 0160082038 C/W: Open Operator Station, 55 ft Max Lift
	Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling,		Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 70 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28
	Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 3,507 Hr		Tires Usage: 2,088 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
491	2012 Genie 1256T Telehandler S/N: CPTJTCN0493 C/W: Open Operator Station, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 4,149 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	498	2012 Cat TL1255 Telehandler S/N: TBN01043 C/W: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 58 in Forks, Hydraulic Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires Usage: 6,744 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	400	·
492	2018 Cat TL1255D Telehandler S/N: ML701156 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 56 in Forks, Tilt Carriage, Hydraulic Coupler, Outriggers, Frame Leveling,	499	2005 JLG 1255 Telehandler S/N: 0160016005 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, 17.5-25 Tires Usage: 1,493 Hr Asset located in: Humble, TX
	Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 6,926 Hr	500	2017 Skyjack SJ1056 Telehandler S/N: 87310357
	Asset located in: Humble, TX		C/W: Open Operator Station, 56 ft Max Lift
493	2018 JLG 1255 Telehandler S/N: 0160086565 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 71 in		Height, 10000 lb Max Lift Capacity, 2016 US EPA Label, 72 in Forks, Outriggers, Frame Leveling, 13.00-24 Aperture Tires Usage: 3,348 Hr Asset located in : Humble, TX
404	Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75- 28 Tires Usage: 4,911 Hr Asset located in : Humble, TX	501	2015 Genie GTH-1056 Telehandler S/N: GTH1015E-11010 C/W: Open Operator Station, Air Ride Seat, 56 ft Max Lift Height, 10000 lb Max Lift Capacity, 96 in Forks, Outriggers, Frame Leveling, 14.00- 24 Aperture Tires
494	2017 JLG 1255 Telehandler S/N: 0160081296 Usage: 724 Hr Asset located in: Humble, TX		Usage: 3,645 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
495	2017 JLG 1255 Telehandler		Asset located in: Lake Worth, TX
	S/N: 160082036 C/W: Open Operator Station, Air Ride Seat, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Outriggers, Frame Leveling, 400/75-28 Tires Usage: 1,486 Hr Asset located in: Humble, TX	502	2019 Xtreme XR1055 Telehandler S/N: XR105511190594419 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires
496	2017 JLG 1255 Telehandler		Usage: 9,654 Hr
	S/N: 0160082037 C/W: Open Operator Station, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, 2017 US EPA Label, 60 in Forks, Tilt Carriage, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 4.00/75-28 Tires Usage: 1,721 Hr Asset located in: Humble, TX	503A	Asset located in: Humble, TX 2017 Cat TL1055D Telehandler S/N: ML500782 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Tilt Carriage, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 4,924 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
503	2017 JLG 1055 Telehandler S/N: 160084201 C/W: 55 ft Max Lift Height, 10000 lb Max Lift Capacity Usage: 6,144 Hr Asset located in: Humble, TX	511	2016 SkyTrak 10054 Telehandler S/N: 0160073991 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 3,995 Hr
504	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90868 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Diesel Exhaust Fluid, 59 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Tires Usage: 2,416 Hr Asset located in : Humble, TX	512	2016 SkyTrak 10054 Telehandler S/N: 0160074014 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic
505	2017 Gehl RS10-55 Telehandler S/N: RS1055CH90900 Usage: 3,531 Hr		Plumbing, 400/75-28 Tires Usage: 4,382 Hr Asset located in : Humble, TX
	Asset located in: Humble, TX	513	2014 SkyTrak 10054L Telehandler
506	2014 Gehl RS10-55 Telehandler S/N: RS1055JF0990472 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, 14.00-24 Foam Filled Tires Usage: 3,949 Hr Asset located in: Humble, TX		S/N: 0160063857 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, 17.5-25 Foam Filled Tires Usage: 7,252 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
507	2017 JLG 10054 Telehandler	T	Asset located in: Humble, TX
	S/N: 0160083016 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 72 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 2,379 Hr Asset located in: Humble, TX	514	2013 SkyTrak 10054 Telehandler S/N: 160049894 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2012 US EPA Label, 59 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00-24 Aperture Tires Usage: 4,191 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
508	2016 JLG 10054 Telehandler S/N: 0160077170	1	THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 71 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 5,630 Hr	515A 515	2017 Cat TL943D Telehandler S/N: MLJ00519 Usage: 5,151 Hr Asset located in: Humble, TX 2003 SkyTrak 10054 Telehandler
509	Asset located in: Humble, TX 2015 JLG 10054 Telehandler S/N: 0160070116 C/W: Open Operator Station, Air Ride Seat, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 47.5 in Forks, Manual Coupler, 17.5-25 Tires Usage: 6,092 Hr	515	S/N: 19899 C/W: Open Operator Station, 54 ft Max Lift Height, 10000 lb Max Lift Capacity, 2003 US EPA Label, 50 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Foam Filled Tires Usage: 2,844 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX		THE INSPECTION REPORT
510	2017 SkyTrak 10054 Telehandler S/N: 0160083012 C/W: Open Operator Station, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 400/75-28 Tires Usage: 2,996 Hr Asset located in: Humble, TX	516	Asset located in: Humble, TX 2017 Genie GTH-844 Telehandler S/N: GTH08E-10803 C/W: 44 ft Max Lift Height, 8000 lb Max Lift Capacity Usage: 2,936 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
517	2015 Terex GTH844 Telehandler S/N: GTH0815-20941 C/W: Open Operator Station, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2014 US EPA Label, 60 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 2,767 Hr Asset located in: Humble, TX	525	2015 SkyTrak 8042 Telehandler S/N: 0160070992 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Foam Filled Tires Usage: 282 Hr
518	2013 Genie GTH-844 Telehandler S/N: GTH081317186 C/W: Open Operator Station, 2013 US EPA Label, 47.5 in Forks, Frame Leveling, 13.00-24 Tires Usage: 2,903 Hr Asset located in: Humble, TX	526	Asset located in: Humble, TX 2015 SkyTrak 8042 Telehandler S/N: 160071767 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks Frame Leveling, 370/75-28 Tires Usage: 4,037 Hr Asset located in: Humble, TX
519	2018 Skyjack SJ843TH Telehandler S/N: 87111644 C/W: Enclosed Cab, 43 ft Max Lift Height, 8000 lb Max Lift Capacity, 2018 US EPA Label, 48 in Forks, Frame Leveling, 13.00-24 Aperture Tires Usage: 1,521 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	527 528	2014 SkyTrak 8042 Telehandler S/N: 160062239 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 42 in Forks 13.00-24 Solid Tires Usage: Not Available Asset located in: Humble, TX 2014 SkyTrak 8042 Telehandler
520	Ingersol Rand VR843 Telehandler S/N: 158070 C/W: Open Operator Station, 43 ft 1 in Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 6,462 Hr Asset located in: Humble, TX		S/N: 0160056453 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
521 522	2017 Gehl RS8-42 Telehandler S/N: RS842CJ18035 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 60 in Forks Usage: 3,189 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2017 JLG 8042 Telehandler	529	Asset located in: Humble, TX 2018 Skyjack SJ643 TH Telehandler S/N: 87111100 C/W: Open Operator Station, 43 ft Max Lift Height, 6000 lb Max Lift Capacity, 2018 US EPA Label, 48 in Forks, Tilt Carriage, Frame Leveling, 13.00-24 Aperture Tires Usage: 1,970 Hr
<i></i>	S/N: 0160082629 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 3,835 Hr Asset located in: Humble, TX	530	Asset located in: Humble, TX 530 2016 Skyjack SJ643 TH Telehandler S/N: 87110206 C/W: Open Operator Station, 43 ft Max Lift Height, 10000 lb Max Lift Capacity, 2016 U EPA Label, 48 in Forks, Tilt Carriage, Manus Coupler, Frame Leveling, Auxiliary Hydrauli Plumbing, 13.00-24 Tires
523	2014 JLG 8042 Telehandler S/N: 0160063819 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 2014 US EPA Label, 46 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 15.5-25 Foam Filled Tires		Usage: 2,183 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 JLG 6042 Telehandler S/N: 0160077805
524	Usage: 4,224 Hr Asset located in: Humble, TX 2015 SkyTrak 8042 Telehandler S/N: 0160065776 C/W: Open Operator Station, 42 ft Max Lift Height, 8000 lb Max Lift Capacity, 72 in Forks, Frame Leveling, 370/75-28 Tires Usage: 10,625 Hr Asset located in: Humble, TX		C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 370/75-28 Tires Usage: 2,618 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
532	2016 JLG 6042 Telehandler S/N: 0160076414 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Aperture Tires Usage: 3,312 Hr Asset located in: Humble, TX	539	2014 SkyTrak 6042 Telehandler S/N: 0160058038 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, 370/75-28 Tires Usage: 2,902 Hr Asset located in: Humble, TX
533	2016 JLG 6042 Telehandler	540	2013 SkyTrak 6042L Telehandler
555	S/N: 0160073484 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires	541	S/N: 160056198 C/W: Open Operator Station, 71.5 in Forks, Manual Coupler, Frame Leveling Usage: 4,295 Hr Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	341	2012 SkyTrak 6042L Telehandler S/N: 0160045502
534	2014 JLG 6042 Telehandler S/N: 0160056113 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 48 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, 13.00-24 Tires		C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 72 in Forks, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires Usage: 3,945 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 3,680 Hr		Asset located in: Humble, TX
	Asset located in: Humble, TX	542	2012 SkyTrak 6042L Telehandler
535	2013 JLG 6042 Telehandler S/N: 0160050487 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 48 in Forks, Frame Leveling, 13.00- 24 Tires Usage: Not Available	042	S/N: 0160045729 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2012 US EPA Label, 44 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX	_	THE INSPECTION REPORT
536	2013 JLG 6042 Telehandler S/N: 0160054638 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, Tier 4, 2014 US EPA Label, 72 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 3,291 Hr Asset located in: Humble, TX	543	Asset located in: Humble, TX 2014 Gehl RS6-42 Telehandler S/N: RS642JF0714865 C/W: Open Operator Station, 42 ft Max Lift Height, 6600 lb Max Lift Capacity, 2014 US EPA Label, 72 in Forks, Frame Leveling, 13.00- 24 Tires Usage: 2,501 Hr
537	2013 JLG 6042 Telehandler		Asset located in: Humble, TX
	S/N: 0160054824 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 72 in Forks, 13.00-24 Tires Usage: 4,812 Hr Asset located in : Humble, TX	544	2008 SkyTrak 6042 Telehandler S/N: 0160033198 C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2007 US EPA Label, 47 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, Auxiliary Hydraulic
538	2013 JLG 6042 Telehandler		Plumbing, 14.00-24 Tires
	S/N: 160056111		Usage: 4,109 Hr Asset located in: Humble, TX
	C/W: Open Operator Station, 42 ft Max Lift Height, 6000 lb Max Lift Capacity, 2013 US EPA Label, 96 in Forks, Frame Leveling, 13.00- 24 Tires Usage: 4,196 Hr Asset located in : Humble, TX	545	2019 Genie GTH-636 Telehandler S/N: GTH06E-12719 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 2019 US EPA Label, 72 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 330/85. 28 Tires Usage: 1,504 Hr Asset located in: Humble, TX

	B	1	B . 1
Lot #	Details	Lot #	Details
546	2015 Genie GTH-636 Telehandler S/N: GTH0615H10192 C/W: Open Operator Station, 36 ft Max Lift Height, 6000 lb Max Lift Capacity, 2015 US EPA Label, 48 in Forks, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-	556	2014 Gehl RS5-19 Telehandler S/N: RS519YF0351063 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 46 in Forks, 12-16.5 Tires Usage: 3,964 Hr
	28 Tires Usage: 2,964 Hr		Asset located in: Humble, TX
	Asset located in: Humble, TX	557	2014 Gehl RS5-19 Telehandler
547	Genie GTH-636 Telehandler S/N: Not Available Usage: 3,786 Hr Asset located in: Humble, TX		S/N: RS519YF0751114 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 48 in Forks, Manual Coupler, 12- 16.5 Foam Filled Tires Usage: 4,484 Hr
550	2019 Gehl RS6-34 Telehandler		Asset located in: Humble, TX
	S/N: RS634DF1022499 Usage: 3,946 Hr Asset located in : Humble, TX	558	2014 Gehl RS5-19 Telehandler S/N: RS519YF0751120
551	2006 Genie GTH-6622 Telehandler S/N: 15022 C/W: Open Operator Station, 6600 lb Max Lift Capacity, 2006 US EPA Label, 47 in Forks,		C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2014 US EPA Label, 47 in Forks, 12-16.5 Tires Usage: 4,109 Hr Asset located in: Humble, TX
	Hydraulic Coupler, 405/70R20 Tires	559A	Blaw-Knox CB-90 Self-Propelled Broom
	Usage: 3,789 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	3394	S/N: 86295 C/W: Enclosed Cab, Air Conditioner, 7 ft 9 in Broom, Water System, Tier 3, Kubota 4 Cylinde 3.6 L Diesel Engine Usage: 2,153 Hr
	Asset located in: Humble, TX	_	
552	1998 JCB 506C Telehandler S/N: SLP506COWE0585392		Asset located in: Humble, TX
	C/W: Open Operator Station, 6000 lb Max Lift Capacity, 48 in Forks, Manual Coupler, Frame Leveling, 13.00-24 Tires Usage: 6,893 Hr	559	2017 Lay-Mor SM450-ST Self-Propelled Broom S/N: 38447 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
553		560	Broce BW260 Self-Propelled Broom S/N: 202477 C/W: Open Operator Station, 8 ft 4 in Broom, Water System, Kubota 4 Cylinder Diesel Engine Usage: 23 Hr Asset located in: Humble, TX
	Usage: 700 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	561	Broce BW-260 Self-Propelled Broom S/N: 202473 C/W: Open Operator Station, 8 ft Broom, Water
554	2021 Genie GTH-5519 Telehandler S/N: GTH55M12836 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2021 US EPA Label, 47 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: Not Available Asset located in: Humble, TX		System, 2020 US EPA Label, Kubota V1505 4 Cylinder 18.2 kW 1.5 L Diesel Engine Usage: Not Available Asset located in : Humble, TX
		562	2018 Lay-Mor SM300 Self-Propelled Broom S/N: 39397 Usage: Not Available Asset located in: Humble, TX
555	2017 Genie GTH-5519 Telehandler S/N: GTH55M7090 C/W: Open Operator Station, 19 ft Max Lift Height, 5500 lb Max Lift Capacity, 2017 US EPA Label, 48 in Forks, Manual Coupler, Auxiliary Hydraulic Plumbing, 12-16.5 Tires Usage: 531 Hr Asset located in: Humble, TX	566	2013 Lay-Mor SM300 Self-Propelled Broom S/N: 34549 C/W: Open Operator Station, 8 ft Broom, Water System, 2012 US EPA Label, Kubota V1505- ET04 4 Cylinder 1.5 L Diesel Engine Usage: 1,524 Hr Asset located in: Humble, TX

	Details	Lot #	Details
567	2013 Lay-Mor SM300 Self-Propelled Broom S/N: 34422 C/W: Open Operator Station, 7 ft 9 in Broom, Water System, 2012 US EPA Label, Kubota 4 Cylinder 1.5 L Diesel Engine Usage: 1,034 Hr Asset located in: Humble, TX	571	2012 Ford F-550 Lariat 4x4 Crew Cab Utility Truck S/N: 1FD0W5HT9CED07485 C/W: 6 Cylinder 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, Aluminum Outer Wheels, 225/70R19.5, Spring
568	Elgin Broom Badger on 2020 Isuzu NRR Sweeper Truck S/N: JALE5W169L7306072 C/W: Isuzu 4HK1TC 5.2 L Diesel 210 hp Engine, 2019 US EPA Label, 4817 Engine hrs, Automatic Transmission, 7275 lb Front Axle	Elgin Broom Badger on 2020 Isuzu NRR Sweeper Truck S/N: JALE5W169L7306072 C/W: Isuzu 4HK1TC 5.2 L Diesel 210 hp Engine, 2019 US EPA Label, 4817 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Air Ride Suspension, 110 in Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, 60 in Rear Broom, Gutter Brooms, Water System, Hydraulic Dump, Rear-View Camera Usage: 65,975 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	Suspension, 176 in Wheelbase, 2012 ROYAL TRUCK BODY 9 ft 11 in Body Usage: 166,544 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Air Ride Suspension, 110 in Wheelbase, Kubota Auxiliary Engine, Vacuum Sweeper, 60 in Rear Broom, Gutter Brooms, Water System, Hydraulic Dump, Rear-View Camera Usage: 65,975 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2017 Chevrolet Silverado 3500 4x2 Utility Truck S/N: 1GB3CYCY4HF146791 C/W: GM Duramax V8 6.6 L Diesel Engine, 2017 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 9750 lb Rears, 13200.0 lb GVWR, Steel, 265/70R17, Spring Suspension, 138 in Wheelbase, Knapheide 9 ft Body Usage: 195,867 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
569	Tymco 600 on 2004 Freightliner FC80 Sweeper Truck		Asset located in: Humble, TX
	S/N: 1FVAB6BV34DN04457 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel Engine, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 144 in Wheelbase, PTO, John Deere Auxiliary Engine, Regenerative Air, Dual Controls, Front Spray Bar, 96 in Under Body Broom, Gutter Brooms, Water System, Hydraulic Dump Usage: 41,127 Mi Notes: ODOMETER DISCREPANCY UNIT SHOWS 41,127, TITLE SHOWS 42,909	573	2015 Ford F-350 XL 4x2 Utility Truck S/N: 1FDRF3GT4FEC32664 C/W: Ford 6 Cylinder 6.7 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4850 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 141 in Wheelbase, Knapheide 9 ft Body Usage: 184,838 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	574A	2010 Ford F-350 XL 4x2 Extended Cab Utility
570	2018 Ram 5500HD 4x4 Utility Truck S/N: 3C7WRNBL0JG224924 C/W: Cummins 6.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, Knapheide 11 ft Body, Ingersoll- Rand Gasoline Air Compressor Usage: 125,380 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		Truck S/N: 1FTWX3AR0AEA55282 C/W: Ford V8 6.4 L Diesel Engine, Automatic Transmission, 5000 lb Front Axle, 6693 lb Rears, 11000 lb GVWR, 275/65R18, Spring Suspension, 158 in Wheelbase, Stahl 8 ft 2 in Body Usage: 140,913 Mi Notes: TITLE BRAND "NOT ACTUAL MILEAGE" Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	574	2013 Chevrolet Silverado 3500HD 4x2 Utility Truck
571A	2012 Ford F-550 XL 4x2 Utility Truck S/N: 1FDUF5GT9CEB18399 C/W: Ford 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 225/70R19.5, Spring Suspension, 166 in Wheelbase, Knapheide 11 ft Body		S/N: 1GB3CZCGXDF128268 C/W: GM L96 6.0 L Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 138 in Wheelbase, 9 ft Body Usage: 234,877 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: 215,721 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		THE INSPECTION REPORT Asset located in: Humble, TX

			1 age 37 01 +37		
Lot #	Details	Lot #	Details		
575	2009 Chevrolet Silverado 3500HD 4x2 Extended Cab Utility Truck S/N: 1GBJC79K39E126737 C/W: V8 Gasoline Engine, Automatic Transmission, 4800 lb Front Axle, 8600 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 162 in Wheelbase, Omaha 9 ft Body Usage: 260,590 Mi Asset located in: Humble, TX	581A	581A	581A	2006 International 4200 4x2 Service Truck S/N: 1HTMPAFMX6H162955 C/W: International 6 Cylinder Diesel Engine, 2005 US EPA Label, 10069 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 15500 lb Rears, 23500 lb GVWR, 10R22.5, Spring Suspension, 187 in Wheelbase, 16 ft 5 in Body, Manual Stabilizers, IMT 3820-2H 7500 lb Crane Usage: 195,086 Mi Notes: LOCATED-IN-FORT-WORTH-TX
576	2006 Ford F-350 4x2 Utility Truck S/N: 1FDWF36P56EB81571 C/W: V8 6.0 L Diesel Engine, Automatic Transmission, 4400 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 245/75R17, Spring Suspension, 141 in Wheelbase, 9 ft Body Usage: 186,727 Mi Notes: LOCATED-IN-FORT-WORTH-TX, TEXAS BUYERS MUST STOP IN OFFICE TO SIGN	583	Asset located in: Lake Worth, TX 2004 Ford F-750 XL 4x2 Service Truck S/N: 3FRXF75334V618003 C/W: Cat 6 Cylinder Diesel Engine, 7-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, 13 ft 10 in Body, Hydraulic Stabilizers, Auto Crane		
577	REQUIRED DOCUMENTS Asset located in: Lake Worth, TX 2003 Chevrolet Silverado 2500 4x2 Utility Truck S/N: 1GBHC24U53E179019 C/W: V8 6.0 L Gasoline Engine, 2003 US EPA	584	2 Section Electric Crane, Wired Remote Control, Hydraulic Air Compressor Usage: 246,367 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		
	Label, Automatic Transmission, 4410 lb Front Axle, 6084 lb Rears, 9200 lb GVWR, Aluminum Wheels, 245/75R16, Spring Suspension, 135 in Wheelbase, 8 ft Body Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX 1998 Ford F800 4x2 Service Truck S/N: 1FDXF80E2WVA30115 C/W: Cummins ISC 6 Cylinder 8.3 L Diesel Engine, 8234 Engine hrs, 9-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb		
578	1999 Ford F-250 XL 4x2 Utility Truck S/N: 1FDNF20F3XED98673 C/W: V8 7.3 L Diesel Engine, Automatic Transmission, 265/75R16, Spring Suspension, 140 in Wheelbase, Koening 8 ft Body Usage: 170,782 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Humble, TX		Rears, 33000.0 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 14 ft 8 in Body, 5000 lb Hydraulic Crane, Gasoline Air Compressor, Air Hose Reel Usage: 289,213 Mi Notes: LOCATED-IN-LAKE-WORTH-TX-HOU; DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		
580	2017 Kenworth T300 4x2 Service Truck S/N: 2NKHHM6X9HM153755 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8294 Engine hrs, Engine Brake, Allison 3500 Automated Transmission, Differential Lock, 10000 lb Front Axle, 16000 lb Rears, Dana P22060S Drive Axles, 5.29:1 Axle Ratio, 26000 lb GVWR, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 157 in Wheelbase, PTO, 11 ft Body, Hydraulic Stabilizers, Auto Crane HC-10 10000 lb 2 Section Hydraulic Crane, Wired Remote Control, Auto Crane Hydraulic Air Compressor, Air Hose Reel Usage: 234,394 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	- 585	2022 Ram 5500 4x4 Service Truck S/N: 3C7WRNBL3NG352063 C/W: Cummins V8 6.7 L Ultra Low Sulfur Diesel Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 239 Engine hrs, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Outer Wheels, 225/70R19.5, Spring Suspension, 88 in Wheelbase, PTO, Palfinger Pal Pro 43 11 ft Body, Hydraulic Stabilizers, Palfinger PSC8029 8000 lb 3 Section Hydraulic Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor Usage: 5,218 Mi Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
586	2022 Ram 5500 4x4 Service Truck S/N: 3C7WRNBL8NG352060 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 360 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 599 Engine hrs, Exhaust Brake, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Front Wheels, 225/70R19.5 Front Tires, 225/70R19.5 Rear Tires, Spring Suspension, 169 in Wheelbase, PTO, Palfinger 13 ft 6 in Body, Hydraulic Stabilizers, Palfinger PSC8029 8000 lb 3 Section Electric Crane, Wireless Remote Control, Palfinger PRC45V Hydraulic Air Compressor, Air Hose Reel Usage: 15,279 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	591A	2017 Ford F-450 XL 4x4 Extended Cab Service Truck S/N: 1FD0X4HY1HEE48450 C/W: Ford Triton V10 6.8 L Gasoline Engine, 2017 US EPA Label, CARB Compliant, Ford-Factory Automatic Transmission, 6000 lb Front Axle, 12880 lb Rears, Ford-Factory Drive Axles, 16500 lb GVWR, 225/70R19.5 Front Tires, 225 /70R19.5 Rear Tires, Ford-Factory Spring Suspension, 192 in Wheelbase, Auto Crane 38K 13 ft 4 in Body, Manual Stabilizers, 2015 Auto Crane 4004EH 4000 lb 3 Section Hydraulic Crane, Wired Remote Control, Champion HGR7-3K Gasoline Air Compressor, Air Hose Reel Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2012 Ford F-550 4x4 Service Truck
587	Asset located in: Humble, TX 2017 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HYXHEE50935 C/W: Ford V8 6.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 245 /70R19.5, Spring Suspension, 169 in Wheelbase, Knapheide 13 ft 7 in Body, Manual Stabilizers, Stellar EC3200 3200 lb 2 Section Electric Crane, Wired Remote Control, Van Air Generator Set, Van Air Air Compressor, Van Arc Welder Usage: 211,059 Mi	591	S/N: 1FDUF5HT8CEB44863 C/W: Ford 6 Cylinder 6.7 L Diesel 300 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 245 /70R19.5, 168 in Wheelbase, 2012 Maintainer Maintainer 13 ft Body, Hydraulic Stabilizers, 2012 H650TT 6500 lb Hydraulic Crane, Wireless Remote Control, Vanair RC 40 Diesel Air Compressor, Miller Bobcat 250 1100 W 250 A Diesel Welder Usage: 245,356 Mi Notes: LOCATED-IN-FORT-WORTH-TX
589	Asset located in: Humble, TX 2015 Ford F-550 XL 4x4 Service Truck		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
590	S/N: 1FDUF5HY0FEB96388 C/W: Ford V8 6.2 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 167 in Wheelbase, 13 ft 6 in Body, Manual Stabilizers, IMT 3203i 4000 lb 3 Section Electric Crane, Wireless Remote Control, VANAIR Hydraulic Air Compressor Usage: 201,881 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Ram 5500 4x4 Crew Cab Service Truck S/N: 3C7WRNFL9EG269005	592	2016 Ford F-450 XL 4x4 Extended Cab Service Truck S/N: 1FD0X4HY2GEA92282 C/W: Ford Triton V10 6.8 L Gasoline Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Factory Ford P,R,N,D,3,2,1 Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, Ford-Factory Drive Axles, 16500 lb GVWR, 225/70R19.5, Ford-Factory Spring Suspension, 186 in Wheelbase, 13 ft 4 in Body, Manual Stabilizers, Auto Crane 6006EH 6000 lb 3 Section Hydraulic Crane, Wired Remote Control Usage: 156,934 Mi Notes: LOCATED-IN-MIDLAND-TX
	C/W: Cummins V8 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 6451 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 197 in Wheelbase, PTO, 13 ft Body, Manual Stabilizers, Auto Crane 5005H 5000 lb 3 Section Electric Crane Usage: 295,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	594	2007 Ford F-550 XL 4x2 Service Truck S/N: 1FDAF56P97EA85725 C/W: Ford Power Stroke V8 Diesel Engine, 2006 US EPA Label, 9849 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 13660 lb Rears, 19000 lb GVWR, 225/70R19.5, Spring Suspension, 167 in Wheelbase, 13 ft 4 in Body, Manual Stabilizers, 2006 Iowa Mold Tooling Co 2020 J505094 5000 lb 3 Section Electric Crane, Wired Remote Control Usage: 296,730 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
595A	2015 Ram 5500 4x2 Service Truck S/N: 3C7WRMBL4FG594937 C/W: Cummins V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, PTO, IMT Dominator 11 ft Body, (5) Hose Reels, Metered Nozzles, Hydraulic Hose Reel, Vanair Arc N Air Generator Set, Vanair 150 Hydraulic Air Compressor, Vanair Air N Arc Hydraulic Driven Welder Usage: Not Available Asset located in: Humble, TX	598A	2018 Kenworth T880 6600 gal 6x4 Tanker Truck S/N: 1NKZX4EX2JJ214143 C/W: Cummins X15 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 15448 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, Double Differential Locks, 20000 lb Front Axle, 46000 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 288 in Wheelbase, PTO, 2017 MAC LTT ARX-6600-1-407TM 6600 gal Aluminum Tank, Hydraulic Driven Pump Usage: 339,587 Mi
595	2016 Dodge Ram 3500 4x2 Service Truck S/N: 3C7WRSAL3GG140251		Asset located in: Humble, TX
	C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 235/80R17, Spring Suspension, 148 in Wheelbase, 9 ft Body, Champion Pneumatic HGR7-3K Gasoline Air Compressor, Air Hose Reel Usage: 290,275 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	598	2014 Ford F-450 4x4 Lube Truck S/N: 1FDUF4HY8EEB81615 C/W: V8 6.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4800 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225 /70R19.5, Spring Suspension, 133 in Wheelbase, 9 ft Body, 100 gal Oil Tanks, (3) Hose Reels, Metered Nozzles, Oil Recovery System, Vanair 20 cfm Gasoline Air Compressor, Air Hose Reel
597	2014 Peterbilt 365 3600 gal 6x6 Fuel Truck S/N: 1NPSM70X0ED235400		Usage: 181,705 Mi Asset located in : Humble, TX
	C/W: Cummins ISX12 6 Cylinder 12.0 L Ultra Low Sulfur Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11564 Engine hrs, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 22000 lb Front Axle, 44000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 214 in Wheelbase, 2013 Hanco 3600 gal Steel Tank, Fill-Rite PTO Driven Pump, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: 157,247 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	599	2015 Freightliner 114SD 4100 gal 6x4 Tanker Truck S/N: 3ALHG3DV2FDFZ7097 C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22117.9 Engine hrs, Engine Brake, Eaton Fuller FO-16E308LL VCS Ultrashift Automated Transmission, Differential Lock, 16000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.90:1 Axle Ratio, 56000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22. 5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Airliner Air Ride Suspension, 256 in Wheelbase, PTO, 2014 Tremcar Industries 4100 gal Steel Tank, 3 Compartments, TC406 Code, Catwalk w/Guardrails, Hydraulic Driven
598B	2018 Kenworth T880 5000 gal 8x4 Tanker Truck S/N: 1NKZX4EX5JJ205534		Pump, 2 Reels Usage: 303,096 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: Cummins CX15 15.9 L Diesel 565 hp Engine, 2017 US EPA Label, Requires Diesel		Asset located in: Humble, TX
	Exhaust Fluid, 10680 Engine hrs, Engine Brake, Eaton Fuller FRO-18210C 10-Speed Manual Transmission, Double Differential Locks, 14600 lb Front Axle, 46000 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 75600 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Steerable Air Lift Tag Axle, 8-Bag Air Ride Suspension, 282 in Wheelbase, PTO, Beall BABT502SB 5000 gal Aluminum Tank, 2 Compartments, . PTO Driven Pump, Pintle Hitch Usage: 599,393 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	600	2015 Freightliner 114SD 4100 gal 6x4 Fuel Truck S/N: 3ALHG3DV3FDFZ7089 C/W: Detroit DD13 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 13637 Engine hrs, Engine Brake, Eaton Fuller FO-16E208LL 8LL Automated Transmission, Differential Lock, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5, Dual Steering Boxes, Double Frame, Air Ride Suspension, 265 in Wheelbase, PTO, Tremcar Industries 4100 gal Steel Tank, Catwalk w /Guardrails, PTO Driven Pump Usage: 269,344 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
602	2015 Cat CT660S 4000 gal 6x4 Water Truck S/N: 3HTJGTKTXFN734043 C/W: Cat CT13 6 Cylinder Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 16000 lb Front Axle, 40000 lb Rears, 56000 lb GVWR, 315 /80R22.5 Front Tires, 11R24.5 Rear Tires, Spring Suspension, 198 in Wheelbase, PTO, 2014 Ledwell LW4000WT 4000 gal Steel Tank, PTO Driven Pump, 7 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	607	2017 Freightliner M2 106 4x2 Water Truck S/N: 1FVACXDT3HHJC7914 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 3713 Engine hrs, Allison 2500 Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 5.88:1 Axle Ratio, 20000 lb GVWR, 11R22.5, Spring Suspension, 162 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray Usage: 15,586 Mi Asset located in: Humble, TX 2015 Freightliner M2 106 4x2 Water Truck
603	2014 Cat CT660S SBA 6x4 Water Truck S/N: 3HTJGTKT1EN016671 C/W: Cat CT13 6 Cylinder Diesel Engine, 9421 Engine hrs, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Air Ride Suspension, 193 in Wheelbase, Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, EQUIPMENT- FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 75,964 Mi Asset located in: Humble, TX 2007 Kenworth T800 4000 gal 6x4 Water Truck S/N: 1XKDD09X67J168840 C/W: Cummins ISM 6 Cylinder Diesel 385 hp Engine, 2006 US EPA Label, 3463 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSH40P Drive Axles, 3.90:1 Axle Ratio, 52000 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 180 in Wheelbase, Smith 4000 gal Steel Tank, ATP PTO Driven Pump, Front Spray, Rear Spray, Side Spray Usage: 424,378 Mi Asset located in: Humble, TX	609	S/N: 3ALACXDT5FDGF1345 Usage: Not Available Asset located in: Humble, TX 2021 International MV607 2000 gal 4x2 Water Truck S/N: 3HAEUMMN2ML088996 C/W: Cummins B6.7 220 6.7 L Diesel 220 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 12350 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 272 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 7 ft 6 in, Spray Bar, Rear Spray, Side Spray
		610	Usage: 316,647 Mi Asset located in: Humble, TX 2021 International MV607 4x2 Water Truck S/N: 3HAEUMMN8ML088114 C/W: Unused Lands Powder Coated 2000 gal Steel Tank Usage: Not Available Asset located in: Humble, TX 2020 International MV607 2000 gal 4x2 Water Truck S/N: 1HTEUMMN5LH822907
605	1990 Kenworth W900 4000 gal 6x4 Water Truck S/N: 1NKWL50X0LS545697 C/W: Cummins LTA10 6 Cylinder Diesel 285 hp Engine, 1989 US EPA Label, 33385 Engine hrs, 18-Speed Manual Transmission, 20000 lb Front Axle, 42400 lb Rears, 11R22.5, Hendrickson Suspension, 262 in Wheelbase, PTO, Hydraulic Driven Pump, 7 ft, Spray Bar, Rear Spray, Side Spray Usage: 260,233 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Cummins B6.7 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 1155 Engine hrs, Exhaust Brake, Allison Automatic Transmission, 12350 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 157 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 6 ft 6 in, Spray Bar, Rear Spray, Side Spray Usage: 296,014 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
606	2018 Kenworth T370 6x4 Water Truck S/N: 2NKHLJ9X7JM189233 Usage: Not Available Asset located in: Humble, TX	612	2020 International MV607 2500 gal 4x2 Water Truck S/N: 1HTEUMMN8LH822903 C/W: Cummins B6.7 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, 2393 Engine hrs, Exhaust Brake, Allison Automatic Transmission, 12350 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Air Ride Suspension, 158 in Wheelbase, PTO, Lands 2500 gal Steel Tank, PTO Driven Pump, 6 ft 8 in, Spray Bar, Rear Spray, Side Spray Usage: 178,228 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
613	2020 International MV607 Water Truck S/N: 1HTEUMMN7LH822908 C/W: Unused Lands Powder Coated 2000 gal Steel Tank Usage: Not Available Asset located in: Humble, TX	620	2014 International 4300 DuraStar 2000 gal 4x2 Water Truck S/N: 1HTMNAALXEH762149 C/W: International MaxxForce DT 7.6 L Diesel 230 hp Engine, 2013 US EPA Label, 5136 Engine hrs, Automated Transmission, 9000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295	
614	2011 International 4400 SBA 2000 gal 4x2 Water Truck S/N: 3HCMKAAN1BL423772 C/W: 6 Cylinder Diesel Engine, 7912 Engine hrs, Allison Automatic Transmission, 295/75R22.5, Air Ride Suspension, 151 in Wheelbase, PTO, Lands 2000 gal Steel Tank, PTO Driven Pump,		/75R22.5, Spring Suspension, 151 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 8 ft, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 204,599 Mi Asset located in : Humble, TX	
	7 ft 8 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: 127,025 Mi Asset located in : Humble, TX		2012 International 4300 SBA 2000 gal 4x2 Water Truck S/N: 1HTMMAAN1CH587596 C/W: 6 Cylinder Ultra Low Sulfur Diesel Engine,	
615	2018 International 4300 SBA 2000 gal 4x2 Water Truck S/N: 1HTMMMMN0JH331136 C/W: Cummins B6.7 250 6 Cylinder 6.7 L 250 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5962 Engine hrs, Eaton Fuller Automatic Transmission, 12000 lb Front Axle,		9244 Engine hrs, Automatic Transmission, 12000 lb Front Axle, 22000 lb Rears, 32000 lb GVWR, 295/75R22.5, Spring Suspension, 167 in Wheelbase, PTO, Ledwell LW2000 Steel Tank, PTO Driven Pump, 5 ft, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 210,165 Mi Asset located in: Humble, TX	
	23000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 149 in Wheelbase, Unused Lands Powder Coated 2000 gal Steel Tank, PTO Driven Pump, 6 ft 8 in, Spray Bar, Rear Spray, Side Spray Usage: 230,881 Mi Asset located in: Humble, TX	622	2005 Freightliner M2106 4x2 Water Truck S/N: 1FVACXDC25HN87551 C/W: Cat C7 6 Cylinder Diesel Engine, 2 Engine hrs, 6-Speed Manual Transmission, 10000 lb Front Axle, 19000 lb Rears, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 150 in Wheelbase, PTO, Steel Tank, PTO Driven Pump, 7 ft 8 in, Spray Bar, Hose Reel, Front Spray, Rear Spray Usage: 26,735 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
616	2018 International 4300 2000 gal 4x2 Water Truck S/N: 1HTMMMML4JH350089 C/W: Cummins B6.7 220 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel			
	Exhaust Fluid, Eaton Fuller Automatic		Asset located in: Humble, TX	
	Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 158 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 7 ft 6 in, Spray Bar, Rear Spray, Side Spray Usage: 262,740 Mi		2000 International 4900 2000 gal 4x2 Water Truck S/N: 1HSSDAAN6YH299737 C/W: 6 Cylinder Diesel Engine, Allison Automatic Transmission, 10000 lb Front Axle,	
617	Asset located in: Humble, TX 2017 International 4300 SBA 4x2 Water Truck S/N: 1HTMMMMNXHH477909 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, 4516 Engine hrs, Automatic Transmission, 13000 lb		Front Wheels, 295/75R22.5, Spring Suspension, 152 in Wheelbase, Ste Pump w/ 1 Cylinder Engine, 8 ft, Sp Dribble Bar, Side Spray Usage: 146,070 Mi	
	Front Axle, 20000 lb Rears, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Spring Suspension, 163 in Wheelbase, Steel Tank, Berkeley PTO Driven Pump, 5 ft 6 in, Spray Bar, Front Spray, Rear Spray, Side Spray Usage: Not Available Asset located in: Humble, TX		S/N: 3FRNF7FAXDV784393 C/W: 6 Cylinder Diesel Engine, Requires Exhaust Fluid, 6-Speed Manual Transmi 12000 lb Front Axle, 21000 lb Rears, 25	2013 Ford F-750 XL 4x2 Water Truck
618	2014 International 4300 4x2 Water Truck S/N: 3HAMMAAN0EL764149 Usage: Not Available Asset located in: Humble, TX		Wheelbase, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 21,736 Mi Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
624	2012 Ford F-750 XL 2000 gal 4x2 Water Truck S/N: 3FRNF7FA6CV151775 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 159 in Wheelbase, 2012 Niece T 2000 2000 gal Steel Tank, PTO Driven Pump, Front Spray, Rear Spray, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 72,752 Mi Asset located in: Humble, TX	630	2020 International MV607 4x2 Cab and Chassis S/N: 3HAEUMML4LL626918 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9856 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Wheels, 11R22.5, 258 in Wheelbase, 185 in Cab to Axle, 288 in Cab to End of Frame Usage: 352,584 Mi Asset located in: Humble, TX 2019 International CV515 SFA 4x4 Crew Cab	
625	2007 Ford F-750 2000 gal 4x2 Water Truck S/N: 3FRXF75E07V510024 C/W: Dodge Cummins 6 Cylinder Diesel Engine, 6-Speed Manual Transmission, 10000 lb Front Axle, 21000 lb Rears, 31000 lb GVWR, 11R22.5, Spring Suspension, 160 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, 7 ft 7 in, Spray Bar, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: 23,676 Mi Asset located in: Humble, TX			Cab and Chassis S/N: 1HTKTSWK1KH067198 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, 6238.8 Engine hrs, Allison Automatic Transmission, 7500 lb Front Axle, 15000 lb Rears, 19500 lb GVWR, Aluminum Outer Wheels, 225/70R19.5 Front Tires, 225 /70R19.5 Rear Tires, Spring Suspension, 199 in Wheelbase, 86 in Cab to Axle, 137 in Cab to End of Frame Usage: 228,163 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
626	2007 Ford F-750 4x2 Water Truck	1	THE INSPECTION REPORT	
	S/N: 3FRXF75E47V510012 Usage: Not Available	620	Asset located in: Humble, TX	
	Asset located in: Humble, TX	632	2008 Kenworth T300 4x2 Cab and Chassis S/N: 2NKMHN7X38M223334	
628	2018 Kenworth T370 4x2 Cab and Chassis S/N: 2NKHHM7X3JM183693 C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5351.4 Engine hrs, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana P22060S Drive Axles, 5.29:1 Axle Ratio, 33000 lb GVWR, Aluminum Front Wheels, 11R22.5, Reyco Spring Suspension, 210 in Wheelbase, 140 in Cab to Axle, 174 in Cab to End of Frame Usage: 80,694 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		C/W: Paccar PX-8 6 Cylinder Diesel 260 hp Engine, 12718 Engine hrs, Engine Brake, Eaton Fuller FS08406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana 21060S Drive Axles, 4.88:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Reyco Spring Suspension, 234 in Wheelbase, PTO, Hydraulic System, 165 in Cab to Axle, 261 in Cab to End of Frame Usage: 439,073 Mi Asset located in: Humble, TX	
		634	2013 International 4300 SBA 4x2 Cab and Chassis	
	THE INSPECTION REPORT		S/N: 1HTMMAAN0DH156264	
629	Asset located in: Humble, TX 2017 Freightliner M2 106 4x2 Cab and Chassis S/N: 3ALACWDT6HDJG0552 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8987 Engine hrs, Allison 2000 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DARS19 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 204 in Cab to Axle, 283 in Cab to End of Frame		Lab Tra Rea Sus Usa Ass 634 201 S/N C/V 201	Label, 12618 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 220 Rears, 32000 lb GVWR, 295/75R22.5, S Suspension, 208 in Wheelbase Usage: 241,012 Mi Asset located in: Humble, TX 634 2016 Ram 5500 4x2 Cab and Chassis S/N: 3C7WRMBL3GG182557 C/W: Cummins 6 Cylinder 6.7 L Diesel I 2016 US EPA Label, Requires Diesel Ex
	Usage: 299,804 Mi Notes: . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX		Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 169 in Wheelbase, 88 in Cab to Axle, 134 in Cab to End of Frame Usage: 203,715 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
636	2011 Ford F-550 4x4 Cab and Chassis S/N: 1FDUF5HT3BEA38027 C/W: V8 6.7 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 166 in Wheelbase, 84 in Cab to Axle, 166 in Cab to End of Frame Usage: 347,560 Mi Asset located in: Humble, TX 2006 Chevrolet C5500 4x2 Cab and Chassis S/N: 1GBE5C32X6F424382	641	2014 Chevrolet Silverado 3500HD 4x4 Cab and Chassis S/N: 1GB3K0C80EF144665 C/W: V8 6.6 L Ultra Low Sulfur Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235 /80R17, Air Ride Suspension, 164 in Wheelbase, 84 in Cab to Axle, 137 in Cab to End of Frame Usage: 244,106 Mi Asset located in: Humble, TX
	C/W: V8 Diesel Engine, Automatic Transmission, 8000 lb Front Axle, 13500 lb Rears, 19500.0 lb GVWR, 245/70R19.5, Spring Suspension, 156 in Wheelbase, 84 in Cab to Axle, 161 in Cab to End of Frame, Pintle Hitch Usage: 279,560 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	642	2017 Ford F-350 XLT 4x2 Cab and Chassis S/N: 1FDRF3GT2HEF26664 C/W: Powerstroke V8 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75/17, Spring Suspension, 168 in Wheelbase, 85 in Cab to Axle, 130 in Cab to End of Frame Usage: 204,342 Mi Asset located in: Humble, TX
638	2017 Ford F-450 4x2 Cab and Chassis S/N: 1FDUF4GT8HEB92950 C/W: Ford Powerstroke V8 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6580 lb Front Axle, 12880 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 193 in Wheelbase, 106 in Cab to Axle, 155 in Cab to End of Frame Usage: 133,662 Mi Asset located in: Humble, TX	643	2017 Ford F-350 XLT 4x2 Cab and Chassis S/N: 1FDRF3GT6HEC46763 C/W: 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5250 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 170 in Wheelbase, 86 in Cab to Axle, 132 in Cab to End of Frame Usage: 128,655 Mi Asset located in: Humble, TX
639	2014 Ford F-450 4x2 Extended Cab Cab and Chassis S/N: 1FD0X4GTXEEB27489 C/W: Ford Powerstroke V8 6.7 L Diesel 300 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, Aluminum Outer Wheels, 225/70R19.5, Air Ride Suspension, 187 in Wheelbase, 84 in Cab to Axle, 132 in Cab to End of Frame Usage: 114,199 Mi Asset located in: Humble, TX	644	2016 Ram 3500 4x2 Cab and Chassis S/N: 3C7WRSBL0GG221142 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235 /80R17, Air Ride Suspension, 171 in Wheelbase, 87 in Cab to Axle, 135 in Cab to End of Frame Usage: 258,936 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
640	2018 Chevrolet Silverado 3500HD 4x4 Cab and Chassis S/N: 1GB3KYCYXJF117904 C/W: Chevrolet duramax V8 6.6 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, 235/80R17, Spring Suspension, 163 in Wheelbase, 84 in Cab to Axle, 135 in Cab to End of Frame Usage: 186,105 Mi Asset located in: Humble, TX	645	2006 Isuzu NPR 4x2 COE Cab and Chassis S/N: 4KLB4B1U46J802998 C/W: V8 6.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 7950 lb Rears, 12000 lb GVWR, Steel, 215 /85R16, Spring Suspension, 178 in Wheelbase, 160 in Cab to Axle, 203 in Cab to End of Frame Usage: 262,622 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
646	2006 Isuzu NPR 4x2 COE Cab and Chassis S/N: 4KLB4B1U56J800807 C/W: V8 6.0 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 7950 lb Rears, 12000 lb GVWR, Steel, 215 /85R16, Spring Suspension, 176 in Wheelbase, 160 in Cab to Axle, 203 in Cab to End of Frame Usage: 252,928 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	650	2004 International 5600i 6x4 Bed Truck S/N: 1HTXHAPTX4J092735 C/W: Cummins ISX 6 Cylinder 15 L Diesel 400 hp Engine, 2003 US EPA Label, Engine Brake, Spicer 6-Speed Manual Transmission, 4-Speed Auxiliary Transmission, 445/65R22.5 Front Tires, 12R24.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Walking Beam Suspension, 360 in Wheelbase, PTO, 24 ft x 108 in Bed, Tail Roll, Braden Winch, Tulsa Winch
647	2013 Freightliner M2 106 Base 4x2 Gin Pole Truck		Usage: 140,183 Mi Asset located in : Humble, TX
	S/N: 1FVACWDU5DHBZ0520 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2012 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7558.9 Engine hrs, L,2,3,D,N,R Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 193 in Wheelbase, PTO, Wet Kit, 15 ft 9 in x 96 in Bed, Tail Roll, 18 ft Gin Poles, Tulsa Winch, Receiver Hitch Usage: 7,558 Hr Notes: LOCATED-IN-MIDLAND-TX	651	2006 Chevrolet C4500 4x4 Rig-Up Truck S/N: 1GBE4C32X6F408847 C/W: GM V8 Gasoline Engine, Automatic Transmission, 8000 lb Front Axle, 13500 lb Rears, 17500 lb GVWR, 245/70R19.5, Spring Suspension, 151 in Wheelbase, PTO, 11 ft x 8 in Bed, Tail Roll, 9 ft 4 in Gin Poles, . Winch Usage: 115,048 Mi Asset located in: Humble, TX
		652	2013 Kenworth T800 8x4 Winch Truck S/N: 1XKDP4TX0DJ350357 C/W: Cummins ISX 6 Cylinder Engine, Requires
648	Asset located in: Midland, TX 2012 International 4300 DuraStar 4300 SBA 4X2 4x2 Gin Pole Truck S/N: 3HAMMAAL7CL634526 C/W: Navistar 6 Cylinder Diesel Engine, 2010 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 9742 Engine hrs, Eaton Fuller 6-Speed Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, NAVISTAR Drive Axles, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Navistar Spring	0 n) lb	Diesel Exhaust Fluid, 11770 Engine hrs, Eng Brake, 18-Speed Manual Transmission, Dou Differential Locks, 20000 lb Front Axle, 460 lb Rears, 88500 lb GVWR, 425/65R22.5 Fron Tires, 11R24.5 Rear Tires, Air Lift Pusher Ax Dual Steering Boxes, Double Frame, Air Ride Suspension, 243 in Wheelbase, 10 ft x 96 in Bed, Tail Roll, Rufnek 44066 Winch, Lowboy Ramps, EQUIPMENT-FROM-PUMPCO-ENER INFRASTRUCTURE Usage: 530,832 Mi Asset located in: Humble, TX
649	Suspension, 188 in Wheelbase, PTO, 15 ft x 100 in Bed, Tail Roll, 17 ft Gin Poles, RUFNEK Winch, Receiver Hitch Usage: 9,742 Hr Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	653	2006 International TranStar 8600 6x4 Winch Truck S/N: 1HSHXSBR96J266827 C/W: Cat C13 6 Cylinder 12.5 L Diesel 445 hp Engine, 2005 US EPA Label, 14224 Engine hrs,
	1998 Western Star 6900 8x4 Twin-Steer Bed Truck S/N: 2WLTMCCF0WK949894 C/W: Cat 3406 6 Cylinder 14.6 L Diesel Engine, 1997 US EPA Label, 215521 Engine hrs, Spicer 6-Speed Manual Transmission, 2-Speed Auxiliary Transmission, 36000 lb Front Axle, 58000 lb Rears, 94000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 12.00R24 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Rubber over Walking Beam Suspension, 387 in Wheelbase, PTO, 28 ft x 108 in Bed, Tail Roll, Tulsa Winch, Rufnek Winch Usage: 215,521 Hr Asset located in: Humble, TX		Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer RS404 Drive Axles, 4.33:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Steel, 11R22.5, International IROS Air Ride Suspension, 170 in Wheelbase, PTO, Rufnek Winch Usage: 344,385 Mi Asset located in: Humble, TX
		654	1995 Kenworth T800 6x4 Winch Truck S/N: 1XKDAR8X0SS680417 C/W: Detroit Series 60 6 Cylinder Diesel Engine, Engine Brake, Meritor RMX10-145A Manual Transmission, Differential Lock, Meritor RS23- 180 Drive Axles, 3.91:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Hendrickson Spring Suspension, 192 in Wheelbase, PTO, Wet Kit, Rufnek Winch Usage: 91,324 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
655	2012 Kenworth T800 6x4 Tri/A Day Cab Truck Tractor S/N: 1XKDD40X2CJ332521 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 27222 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 8LL Manual Transmission, Double Differential Locks, 14320 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 60320 lb GVWR, Aluminum Wheels, 425/65R22. 5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Hendrickson Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 819,498 Mi	659	2020 Kenworth W900 6x4 T/A Day Cab Truck Tractor S/N: 1XKWD40XXLR364224 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 525 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13850 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13200 lb Front Axle, 46000 lb Rears, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 242 in Wheelbase, Dual Fuel Tanks Usage: 442,671 Mi Asset located in: Humble, TX 2015 Kenworth W900 6x4 T/A Day Cab Truck
	Asset located in: Humble, TX		Tractor
656	2002 Peterbilt 379 8x4 Tri/A Day Cab Truck Tractor S/N: 1XP5DB0X72D586127 C/W: Cat 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 14060 lb Front Axle, 46000 lb Rears, 60060 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Lift Tag Axle, Air Trac Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel Usage: 586,182 Mi		S/N: 1XKWD49X7FJ447146 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18919 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.90:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 477,649 Mi
	Asset located in: Humble, TX		Asset located in: Humble, TX
657	2021 Western Star 4900EX 8x4 Heavy Haul Tri /A Sleeper Truck Tractor S/N: 5KJNABD18MPMG3713 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 13055.3 Engine hrs, Eaton Fuller RTLO-20918B 18-Speed Manual Transmission, 18000 lb Front Axle, 66000 lb Rears, Meritor RT- 46-160P Drive Axles, 3.73:1 Axle Ratio, 83300 lb GVWR, 82 in Mid Roof Sleeper Cab, 425 /65R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Airliner Air Ride Suspension, 291 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	661	2020 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X5LD711523 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 16359 Engine hrs, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer Drive Axles, 53200 lb GVWR, Air Ride Cab, 11R24.5, Air Trac Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 322,424 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Usage: 295,587 Mi Notes: LOCATED-IN-FORT-WORTH-TX PER THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN	663 2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X4JD468901	Tractor
	Asset located in: Lake Worth, TX		450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid,
658	2013 Kenworth T660 8x4 Tri/A Sleeper Truck Tractor S/N: 1XKAP40X7DJ368040 C/W: Cummins ISX15 15.0 L Diesel 550 hp Engine, Requires Diesel Exhaust Fluid, 14004.6 Engine hrs, Eaton Fuller RTLO-16918B 18-Speed Manual Transmission, 13200 lb Front Axle, 47200 lb Rears, Dana D46-170 Drive Axles, 3.73:1 Axle Ratio, 60400 lb GVWR, Air Ride Cab, 52 in Flat Top Sleeper Cab, 295 /75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Steerable Air Lift Tag Axle, Air Assist Front Suspension, 8-Bag Air Ride Suspension, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 487,312 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		13539 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 416,809 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
664	2018 Peterbilt 389 6x4 T/A Day Cab Truck Tractor S/N: 1XPXD49X6JD468916 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 212 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 355,698 Mi Asset located in: Humble, TX	668	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GYXNM010084 C/W: Mack 6 Cylinder Engine, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 15,901 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
665	2018 Peterbilt 389 6x4 T/A Day Cab Truck		Asset located in: Lake Worth, TX
666	Tractor S/N: 1XPXD49X1JD468919 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 14989 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R22.5 Front Tires, 11R24. 5 Rear Tires, Paccar Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 436,910 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Peterbilt 389 6x4 T/A Day Cab Truck	669	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY4NM010078 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 30,765 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Tractor		Asset located in: Lake Worth, TX
	S/N: 1XPXD49X2JD468914 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19070 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 217 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 530,638 Mi Asset located in: Humble, TX	670 2022 Mack Pinnac Tractor S/N: 1M1PN4GY4 C/W: Mack MP8 6 Engine, 2021 US E Exhaust Fluid, Eng Automated Transi Aluminum Wheels Suspension, 218 i	2022 Mack Pinnacle 6x4 T/A Day Cab Truck
667	2018 Peterbilt 389 6x4 T/A Day Cab Truck	_	Tanks
	Tractor S/N: 1XPXD49X0JD468913 C/W: Cummins X15 6 Cylinder 15 L Diesel 450		Usage: 33,279 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17059.2 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 217 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 539,017 Mi Asset located in: Humble, TX	671	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY6NM010079 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 36,266 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
672	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor	676	2015 Western Star 4900 6x4 T/A Day Cab Truck Tractor
	S/N: 1M1PN4GY3NM009634 C/W: Mack MP8 6 Cylinder 12.8 L 505 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks		S/N: 5KJJAED6XFLGK0865 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13300 lb Front Axle, 44000 lb Rears, 3.90:1 Axle Ratio, 57300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 527,030 Mi
	Usage: 36,603 Mi		Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	677	2018 Peterbilt 367 6x4 T/A Day Cab Truck Tractor
673	2022 Mack Pinnacle 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN4GY2NM010080 C/W: Mack MP8 6 Cylinder 12.8 L 445 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 218 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks		S/N: 1XPTD40XXJD458823 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 485 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7245 Engine hrs, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12000 lb Front Axle, 46000 lb Rears, 58000.0 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Trac Air Ride Suspension, 210 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 124,113 Mi Asset located in: Humble, TX
	Usage: 58,052 Mi	678	2012 Peterbilt 388 6x4 T/A Day Cab Truck
	Notes: LOCATED-IN-FORT-WORTH-TX		Tractor
674	Asset located in: Lake Worth, TX 2019 Mack P164T 6x4 T/A Day Cab Truck Tractor S/N: 1M1PN3GY0KM001707 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 217 in Wheelbase, Dual Fuel Tanks Usage: 1,888,265 Mi		S/N: 1XPWD49X1CD158459 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Leaf Air Ride Suspension, 208 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 414,329 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; DEFICIENCIES
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
675	2015 Western Star 4900 6x4 T/A Day Cab Truck Tractor S/N: 5KJJAED61FLGK0866 C/W: Detroit DD15 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, 13300 lb Front Axle, 44000 lb Rears, 57300 lb GVWR, Aluminum Wheels, 11R24.5, Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 613,663 Mi Asset located in: Humble, TX	679	2012 Peterbilt 388 6x4 T/A Day Cab Truck Tractor S/N: 1XPWDP9X9CD136792 C/W: Paccar MX 6 Cylinder Diesel 485 hp Engine, 33060 Engine hrs, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 230 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 930,756 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
680	2016 Peterbilt 365 6x4 T/A Day Cab Truck Tractor	684	2020 Kenworth T880 6x4 T/A Day Cab Truck Tractor
	S/N: 1XPSD79X1GD332553 C/W: Cummins ISX12 11.9 L Diesel 385 hp Engine, 21599 Engine hrs, Engine Brake, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension Usage: 434,349 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1XKZDP0X4LJ398821 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 510 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9622.8 Engine hrs, Engine Brake, Eaton Fuller RTLO-1891 18-Speed Manual Transmission, Double Differential Locks, Dana D40-170HP Drive Axles, 3.91:1 Axle Ratio, 59200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 204 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 399,094 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
681	2015 Peterbilt 365 6x4 T/A Day Cab Truck Tractor		THE INSPECTION REPORT Asset located in: Humble, TX
	Tractor S/N: 1XPSD79X4FD263176 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22218 Engine hrs, Eaton Fuller Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride	685	2020 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X4LJ426961 Usage: Not Available Asset located in: Humble, TX
	Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, Auto Lube Usage: 675,848 Mi Asset located in : Humble, TX	686	2018 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X1JJ215858 C/W: Paccar 6 Cylinder Diesel Engine, Require Diesel Exhaust Fluid, 8375 Engine hrs, Engine
682 2021 Trac S/N: C/W 455 Dies P016	2021 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9X4MJ466121 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P016F112C Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio,		Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 202 in Wheelbase, Air Sliding 5th Wheel Usage: 237,444 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5 Front Tires, 425/65R22.5		Asset located in: Humble, TX
	Super Singles Rear Tires, Paccar Air Ride Suspension, 201 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 344,741 Mi Asset located in : Humble, TX	687	2018 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP9XXJJ215860 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2017 US EPA Label, Requires
Tractor S/N: 1XKZDP0X2LJ34 C/W: Paccar MX-13 6 510 hp Engine, 2019 l Diesel Exhaust Fluid, 18-Speed Manual Tra Differential Locks, 13: lb Rears, 3.91:1 Axle f Aluminum Wheels, 11 Suspension, 208 in W Wheel, Dual Fuel Tank Usage: 383,381 Mi	2020 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZDP0X2LJ398820 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 510 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, Double Differential Locks, 13200 lb Front Axle, 46000 lb Rears, 3.91:1 Axle Ratio, 59200 lb GVWR,		Diesel Exhaust Fluid, 11097.5 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Paccar Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 238,110 Mi Asset located in: Humble, TX
	Aluminum Wheels, 11R24.5, 8-Bag Air Ride Suspension, 208 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	688	2018 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1NKZXPTX1JJ196609 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
Lot # 689	Details 2016 Kenworth T880 6x4 T/A Day Cab Truck Tractor S/N: 1XKZD49X5GJ482170 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16827 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 176 in Wheelbase Usage: 380,794 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	Lot # 697	Details 2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09YXDM013576 C/W: Mack MP8 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 214 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 500,177 Mi Notes: LOCATED-IN-FORT-WORTH-TX, THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN
690	Asset located in: Humble, TX 2016 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X3GJ495372 Usage: Not Available Asset located in: Humble, TX		ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN
691	2015 Kenworth T880 T/A Day Cab Truck Tractor S/N: 1XKZDP9X8FJ425865 Usage: Not Available		ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
694	Asset located in: Humble, TX 2016 Mack CHU613 6x4 T/A Day Cab Truck	698A	2013 Mack CHU613 6x4 T/A Day Cab Truck
	Tractor S/N: 1M1AN09Y9GM024279 C/W: Mack MP8 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 415 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Mack mDrive Automated Transmission, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 214 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 486,827 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	090A	Tractor S/N: 1M2AN07Y1DM014095 C/W: Mack MP8 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 29537 Engine hrs, Engine Brake, Mack Maxi Torque ES 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 221 in Wheelbase, Dual Fuel Tanks Usage: 747,931 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
696	2013 Mack CHU613 6x4 T/A Day Cab Truck	600	Asset located in: Humble, TX
	Tractor S/N: 1M1AN07Y1DM014683 C/W: Mack MP8 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 445 hp Engine, 2012 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320.0 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 419,295 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	698	2013 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y1DM015073 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 505 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18887 Engine hrs, Engine Brake, Mack MAXITORQUE 10-Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 598,672 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
699	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN07Y7CM009924 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 26293 Engine hrs, Engine Brake, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 220 in Wheelbase, PTO, Dual Fuel Tanks Usage: 675,788 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	704	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR5JN405659 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8240 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 52300 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Dual Fuel Tanks Usage: 252,460 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
700	2012 Mack CHU613 6x4 T/A Day Cab Truck Tractor	705	Asset located in: Humble, TX 2018 International HX620 6x4 T/A Day Cab
	S/N: 1M1AN07Y9CM010296 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 34419 Engine hrs, Engine Brake, Mack Maxitorque 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Aluminum Front Wheels, 11R24.5, Air Ride Suspension, 219 in Wheelbase, PTO, Dual Fuel Tanks Usage: 723,169 Mi Asset located in: Humble, TX		Truck Tractor S/N: 3HSDTAPR3JN405658 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12785 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, PTO, Dual Fuel Tanks Usage: 303,075 Mi
701	2010 Mack CHU613 6x4 T/A Day Cab Truck		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Tractor		Asset located in: Humble, TX
	S/N: 1M1AN07Y1AN006069 C/W: Mack MP8-485E 6 Cylinder 12.8 L Engine, 2009 US EPA Label, 23998 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 13220 lb Front Axle, 46000 lb Rears, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Wet Kit, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	706	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPR5JN405662 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 11700 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 206 in Wheelbase, PTO, Dual Fuel Tanks Usage: 361,409 Mi
702	2016 Freightliner Coronado 122 T/A Day Cab		Asset located in: Humble, TX
	Truck Tractor S/N: 3AKJGND68GDGZ0976 Usage: Not Available Asset located in: Humble, TX	707	2012 Cat CT660S T/A Day Cab Truck Tractor S/N: 1HTJGTKT7CJ635078 Usage: Not Available Asset located in: Humble, TX
703	2018 International HX620 6x4 T/A Day Cab Truck Tractor S/N: 3HSDTAPRXJN406712 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7334 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 205 in Wheelbase, PTO, Dual Fuel Tanks Usage: 217,611 Mi Asset located in: Humble, TX		AGGETOGREG III. HUITIDIC, 17A

Lot #	Details	Lot #	Details
708	2020 Peterbilt 567 6x4 T/A Day Cab Truck Tractor S/N: 1XPCDP9X8LD713489 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 385 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16.8 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 205 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 271,600 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIEFY WITH YOUR LOCAL DMV	712	2020 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 1FUJHLDR5LLLD8475 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15492 Engine hrs, Retarder, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 176 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 655,434 Mi Asset located in: Humble, TX 2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor
	PRIOR TO BIDDING Asset located in: Humble, TX		S/N: 3AKJHLDVXKSKE1224 Usage: 308,708 Mi
709	2019 Kenworth T-680 6x4 T/A Day Cab Truck Tractor		Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX
710	S/N: 1XKYDP9X0KJ251666 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar P016F112 Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Paccar MT40-14x3 Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275 /70R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel Usage: 597,206 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Mack AN64T 6x4 T/A Day Cab Truck	714	2019 Freightliner Cascadia 126 6x4 T/A Day Cab Truck Tractor S/N: 3AKJHLDVXKSKA4609 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1550-DH1 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel Usage: 617,540 Mi Asset located in: Humble, TX
710	Tractor S/N: 1M1AN2GY4KM003413 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16106 Engine hrs, Engine Brake, Mack Mdrive Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Wheels, 11R22.5, Air Ride Suspension, 187 in Wheelbase Usage: 594,033 Mi Asset located in: Humble, TX	715	2019 Freightliner Cascadia 125 T/A Day Cab Truck Tractor S/N: 3AKJGEDR9KSKJ9009 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 22104 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
711	2019 Mack AN64T 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN4GY6KM003456 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15036 Engine hrs, Engine Brake, Mack mDrive Automatic Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 189 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 743,483 Mi Asset located in: Humble, TX		Tanks Usage: 1,012,611 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX

			rage 34 01 43 /
Lot #	Details	Lot #	Details
716	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH9LN225162 C/W: Volvo D13 6 Cylinder Diesel 425 hp Engine, Requires Diesel Exhaust Fluid, 14177 Engine hrs, Volvo ATO2612F Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 421,049 Mi Asset located in: Humble, TX	720	2020 Volvo VNR64T300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH3LN225156 C/W: Volvo 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9320.7 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12500 lb Front Axle, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 308,397 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH0LN225146 C/W: Volvo D13M-425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11867 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 275/80R22.5, Air Ride Suspension, 172 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 443,912 Mi Asset located in: Humble, TX	721	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH9LN225159 C/W: Volvo D13M-425 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 11022 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 171 in Wheelbase, Dual Fuel Tanks Usage: 370,396 Mi Asset located in: Humble, TX
718	2020 Volvo VNR300 6x4 T/A Day Cab Truck Tractor S/N: 4V4WC9EH6LN225166 C/W: Volvo D13M-425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 13019 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 474,668 Mi Asset located in: Humble, TX 2020 Volvo VNR300 6x4 T/A Day Cab Truck	722	2020 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR5LN089778 C/W: Navistar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10571 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 431,510 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
/ 17	Tractor S/N: 4V4WC9EH7LN225175 C/W: Volvo D13M-425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12215.8 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 485,817 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	723	Asset located in: Humble, TX 2020 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR8LN089788 C/W: International 6 Cylinder Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, 7089 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 440,341 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
724	2020 International RH613 6x4 T/A Day Cab Truck Tractor S/N: 3HSDWTZR7LN845451 C/W: International 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10487 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 421,090 Mi Asset located in: Humble, TX	728	2020 International LT 6x4 T/A Day Cab Truck Tractor S/N: 3HSDZAPR8LN401039 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15239 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22. 5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 679,223 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
725	2020 International RH613 6x4 T/A Day Cab Truck Tractor		Asset located in: Humble, TX
	S/N: 3HSDWTZR2LN845471 C/W: International 6 Cylinder Diesel Engine, US EPA Label, Requires Diesel Exhaust Fluid, 6583 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 639,408 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	729	2019 International LT 6x4 T/A Day Cab Truck Tractor S/N: 3HCDZAPR3KL130218 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 11880 Engine hrs, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 275/80R22.5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 498,574 Mi Asset located in: Humble, TX
726	2020 International LT 6x4 T/A Day Cab Truck	730	2019 International 6x4 T/A Day Cab Truck
/20	Tractor S/N: 3HCDZAPR3LL322076 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 9264 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22. 5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 337,640 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	730	Tractor S/N: 3HSDZAPR8KN256213 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 8388 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, Thermo King TriPac Evolution Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 408,807 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
727	2020 International LT 6x4 T/A Day Cab Truck	1	THE INSPECTION REPORT
	Tractor S/N: 3HSDZAPR4LN113566		Asset located in: Humble, TX
	C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 673,372 Mi Asset located in: Humble, TX	732	2017 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYD40X1HJ175122 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2016 US EPA Label, 8867.7 Engine hrs, Engine Brake, Eaton Fuller FO-18E313A MHP Manual Transmission, 3.58:1 Axle Ratio, Air Ride Cab, Aluminum Wheels, 12R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 188 in Wheelbase, PTO Usage: 293,816 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
733	2017 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYDP9X4HJ145701 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 430 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Ultra Shift Plus Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Paccar DSP40 Drive Axles, 3.36:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Paccar 4-Bag Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT THE TITLE COMES WITH AN AFFIDAVIT TITLE CORRECTION NOT ALL STATES ACCEPT THEM	736	2018 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1JM088010 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15926 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 206 in Wheelbase Usage: 414,968 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
734	Asset located in: Humble, TX 2016 Kenworth T680 6x4 T/A Day Cab Truck Tractor S/N: 1XKYD40X8GJ115353 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, 16245.2		Tractor S/N: 1M1AW02Y6JM089069 C/W: Mack MP7 6 Cylinder 10.8 L 395 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9700 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission,
	Engine hrs, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, 12000 lb Front Axle, 45400 lb Rears, Meritor RT-40- 160 Drive Axles, 3.42:1 Axle Ratio, 57400 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel Usage: 773,399 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 202 in Wheelbase, Auto Lube Usage: 569,066 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
	Asset located in: Humble, TX		2017 Mack CXU613 6x4 T/A Day Cab Truck
735	2013 Kenworth T660 6x4 T/A Day Cab Truck Tractor S/N: 1XKAD49X3DJ354695 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 12214 Engine hrs, Engine Brake, Eaton Fuller FM-15E310B-LAS Automated Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP41 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Steel, 275 /80R22.5 Front Tires, MIXED Rear Tires, 8-Bag Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 327,222 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Tractor S/N: 1M1AW02Y0HM081110 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 2592 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 204 in Wheelbase Usage: 568,398 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
	Asset located in: Humble, TX	l ₇₃₉	2017 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y7HM084229 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10607 Engine hrs, Engine Brake, Mack mDRIVE Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 187 in Wheelbase, Dual Fuel Tanks Usage: 412,790 Mi

Lot #	Details	Lot #	Details
740	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1GM076383 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 405 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 18095 Engine hrs, Engine Brake, Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 193 in Wheelbase Usage: 495,686 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	745	2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y8EM043166 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 4220 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 285 /75R24.5, Air Ride Suspension, 192 in Wheelbase Usage: 525,664 Mi Asset located in: Humble, TX 2014 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y8EM042275
741	Asset located in: Livingston, LA		C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 19251 Engine hrs, Engine Brake, Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 285/75R24.5, Air Ride Suspension, 198 in Wheelbase Usage: 579,235 Mi
	Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 180 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel Usage: 213,409 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	747	Tractor S/N: 1M1AW09Y3DM028594 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 415 hp Engine, 2012 US EPA Label, Requires Dies Exhaust Fluid, Engine Brake, Eaton Fuller 10-
742	2016 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y1GM053119 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395	Speed Manual Transmission, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 193 in Wheelbase, Wet Kit, Air Sliding 5th Wheel Usage: 756,552 Mi Asset located in: Humble, TX	
	hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11146 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 238,391 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	750	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGEDV0JLJY5808 Usage: 478,255 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX
743	2015 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW07Y1FM043942 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 14527 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 189 in Wheelbase, PTO, Air Sliding 5th Wheel Usage: 293,769 Mi Asset located in: Humble, TX	751	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGEDR8JLJW4983 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 6751 Engine hrs, Engine Brake, Detroit DT12-DA-1650 HD 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,379 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
752	2018 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGEDR2JLJW4980 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-DA- 1650 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,652 Mi Asset located in: Humble, TX	756	2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV7HDHS9159 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 346,393 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION
753	2018 Freightliner Cascadia 125 6x4 T/A Day		BELOW SUPPLIED
754	Cab Truck Tractor S/N: 3AKJGEDV2JSJH2266 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 435 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OB-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 404,639 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX 2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor	757	2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV6HSHZ3222 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM- 15E310B Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 488,101 Mi Notes: LOCATED-IN-HOUSTON-TX , . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX
	S/N: 3AKJGEDV0HDHS9231 Usage: 279,565 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX	758	2016 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 1FUJGED50GLHL6329 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2015 US EPA
755	2017 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGEDV5HDHT8698 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 435 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11453 Engine hrs, Engine Brake, Eaton Fuller FO- 18E313A MHP Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 3.55:1 Axle Ratio, 52000.0 lb GVWR, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 465,451 Mi Asset located in: Humble, TX		Label, Requires Diesel Exhaust Fluid, 15219 Engine hrs, Engine Brake, Eaton Fuller FOM- 16E310C-LAS Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40- 14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 576,104 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX

Details Lot# **Details** Lot # 759 2016 Freightliner Cascadia 125 6x4 T/A Day 764 2015 Freightliner Cascadia 125 6x2 T/A Day **Cab Truck Tractor Cab Truck Tractor** S/N: 3AKGGEDV8FSGK3449 S/N: 3AKJGEDV8GSGV9634 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp Engine, 2016 US EPA Label, Requires Diesel C/W: Detroit 6 Cylinder Ultra Low Sulfur Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16464 Engine hrs, Engine Brake, Exhaust Fluid, 21446 Engine hrs, Eaton Fuller Detroit DT12OB1550 12-Speed Automated 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 3.25:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 11R22.5. Airliner Air Ride Suspension, 180 in Airliner Air Ride Suspension, 151 in Wheelbase, Wheelbase, Air Sliding 5th Wheel, Dual Fuel Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Tanks Usage: 5,254 Mi Usage: Not Available Notes: PENSKE-FLEET-MAINTAINED; SELLER Notes: LOCATED-IN-LIVINGSTON_LA SUBJECT TO LA TAX; SELLING WITH A BANKRUPTCY DOCUMENTS AND MAY NOT BE ACCEPTED IN SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; ALL INOPERABLE ITEMS THE INSPECTION REPORT NEED TO BE REMOVED FROM THE YARD BY SEPTEMBER 20th CAN NOT BE RECONSIGNED Asset located in: Humble, TX 761 2016 Freightliner Cascadia 125 6x2 T/A Day BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE **Cab Truck Tractor** INSPECTION REPORT S/N: 3AKGGEDVXGDHC4994 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 Asset located in: Livingston, LA hp Engine, 2016 US EPA Label, Requires Diesel 765 2015 Freightliner Cascadia 125 T/A Day Cab Exhaust Fluid, Detroit DT12-DB-1450 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 Truck Tractor S/N: 3AKGGLD54FSGP8291 20K R-SRS Drive Axles, 2.50:1 Axle Ratio, Usage: Not Available 52000 lb GVWR, 275/80R22.5, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX 767 2014 Freightliner Cascadia 125 6x4 T/A Day Usage: 738,601 Mi **Cab Truck Tractor** S/N: 3AKJGEBG8ESFY2250 C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Asset located in: Humble, TX 763 2015 Freightliner Cascadia 125 6x2 T/A Day Engine, 2013 US EPA Label, 721.3 Engine hrs, **Cab Truck Tractor** Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, 295 S/N: 3AKGGEDV8FSGK3628 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8724 Engine hrs, Engine Brake, /75R22.5, Air Ride Suspension, 185 in Eaton Fuller Automated Transmission, 12000 Wheelbase, Air Sliding 5th Wheel, Dual Fuel lb Front Axle, 40000 lb Rears, 52000.0 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 176 in Wheelbase, Air Sliding Tanks Usage: 49,154 Mi Asset located in: Humble, TX 5th Wheel, Dual Fuel Tanks, EQUIPMENT-768 2016 Freightliner Cascadia 113 6x2 T/A Day FROM-YELLOW-CORP Usage: 912,917 Mi **Cab Truck Tractor** Notes: CANNOT VERIFY ODOMETER READING-S/N: 1FUGGBDV5GLGY6228 VEHICLE IS EXEMPT FROM MILEAGE C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 DISCLOSURE; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FOM-16E310C-LAS Automated Transmission, Asset located in: Humble, TX Differential Lock, 12000 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 Drive Axles, 3.58:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 196 in Wheelbase, Wet Kit, Hydraulic System, Air Sliding 5th Wheel, **Blower** Usage: 421,943 Mi

Lot #	Details	Lot #	Details
769	2016 Freightliner Cascadia 113 6x4 T/A Day Cab Truck Tractor S/N: 3AKJGBDV7GDHA6151 C/W: Detroit DD13 6 Cylinder 12.8 L 380 hp Engine, Requires Diesel Exhaust Fluid, 17605 Engine hrs, Retarder, Detroit DT12-DB-1450 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Dual Fuel Tanks Usage: 520,442 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	777	2015 Volvo VNL 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EG4FN167226 C/W: Volvo D13J405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612D Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275/80R22.5, Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 841,931 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
770	2014 Freightliner COLUMBIA 120 6x2 T/A Day Cab Truck Tractor		S/N: 4V4MC9EG2JN888309 Usage: Not Available Asset located in : Humble, TX
	S/N: 3ALXA7A85EDFP8335 C/W: Cummins 6 Cylinder Diesel Engine, 25369 Engine hrs, Eaton Fuller 7-Speed Manual Transmission, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM- YELLOW-CORP Usage: 882,021 Mi Notes: EQUIPMENT-FROM-YELLOW-CORP; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	778	2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG3JN888318 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9874 Engine hrs, Automated Transmission, 12000 lb Front Axle, 18739 lb Rears, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Volvo Air Ride Suspension, 204 in Wheelbase, PTO Usage: 335,652 Mi Asset located in: Humble, TX
771	2014 Freightliner M2 112 6x4 T/A Day Cab Truck Tractor S/N: 3AKJC5DV8EDFZ3289 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	779	2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG7JN888306 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 11397 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 202 in Wheelbase, PTO, Blower Usage: 337,809 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
772	2016 Volvo VNL300 6x4 T/A Day Cab Truck Tractor S/N: 4V4NC9EH2GN967808 C/W: Volvo D13J455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 161024 Engine hrs, Eaton Fuller FRO-17210C 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 180 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: 596,344 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	780	2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG6JN888314 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 68 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478 lb GVWR, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: 363,236 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

			Page 61 01 45 /
Lot #	Details	Lot #	Details
781	2018 Volvo VNM 6x4 T/A Day Cab Truck Tractor S/N: 4V4MC9EG9JN888307 C/W: Volvo 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 12000 lb Front Axle, 37478 lb Rears, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 199 in Wheelbase Usage: 381,761 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	785	2017 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJSNR2HN461910 C/W: International 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 259,215 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
/0Z	2018 Volvo VNM T/A Day Cab Truck Tractor		Asset located in: Humble, TX
	S/N: 4V4MC9EG8JN888315 C/W: Volvo D13M405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT02612F Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: 391,770 Mi Asset located in: Humble, TX	786	2017 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR9HN710341 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12492 Engine hrs, Engine Brake, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Outer Wheels, 275/80R22.5, Air Ride Suspension, 177 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
783	2018 Volvo VNM200 6x4 T/A Day Cab Truck		Usage: 474,300 Mi
	Tractor		Asset located in: Humble, TX
784	S/N: 4V4MC9EG0JN888311 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT02612F Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: 401,947 Mi Asset located in: Humble, TX 2018 Volvo VNM200 6x4 T/A Day Cab Truck Tractor	787	2017 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HCDJAPR4HL722064 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 12386 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 405,908 Mi Asset located in: Humble, TX
	S/N: 4V4MC9EG9JN888310	700	· · · · · · · · · · · · · · · · · · ·
	C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F Automated Transmission, 12000 lb Front Axle, 37478 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 49478 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 204 in Wheelbase, PTO, Blower Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	788	2016 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR5GN135170 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 179 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 287,866 Mi

Lot #	Details	Lot #	Details
789	2016 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 3HSDJAPR5GN135167 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 179 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 335,198 Mi Asset located in: Humble, TX	792	2013 International ProStar Premium 6x4 T/A Day Cab Truck Tractor S/N: 1HSDJSJR7DJ307244 C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 430 hp Engine, 2012 US EPA Label, 16142 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 295 /75R22.5, Air Ride Suspension, 168 in Wheelbase Usage: 311,781 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
790A	2015 International Prostar 6x4 T/A Day Cab	793	2012 International Prostar 6x4 T/A Day Cab
	Truck Tractor S/N: 3HSDJAPR6FN745786 C/W: Cummins ISX15 15.0 L Ultra Low Sulfur Diesel 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 10566 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 267,490 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Truck Tractor S/N: 3HSDJSJR7CN094078 C/W: 6 Cylinder Diesel Engine, 34209 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 11R22.5, Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 689,264 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
 790	Asset located in: Lake Worth, TX 2016 International Prostar 6x4 T/A Day Cab	795A	2008 Kenworth T800 6x4 T/A Day Cab Truck
	Truck Tractor S/N: 1HSDJAPR1GH733654 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 25894 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 229,878 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Tractor S/N: 1XKDDU9X58J236098 C/W: Cat 6 Cylinder Diesel Engine, 21271 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Spicer DSP4140 Drive Axles, 3.70:1 Axle Ratio, 52000 lb GVWR, Aluminum Front Wheels, 11R22.5, 8-Bag Air Ride Suspension, 174 in Wheelbase Usage: 894,694 Mi Asset located in: Humble, TX
		795	2006 Peterbilt 379 6x4 T/A Day Cab Truck Tractor S/N: 1XP5DU9X96N636797 C/W: Cat C13 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 8LL Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 240 in Wheelbase, PTO, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 1,259,542 Mi Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX
791	2015 International Prostar 6x4 T/A Day Cab Truck Tractor S/N: 1HSDJAPR5FH704110 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 205 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 269,135 Mi Asset located in: Humble, TX		
		796	2005 Kenworth T800 6x4 T/A Day Cab Truck Tractor S/N: 1XKDDU9X25R094788 C/W: 6 Cylinder Diesel Engine, 4747 Engine hrs Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 203 in Wheelbase, Wet Kit, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 445,137 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
798	2009 Mack CHU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AN09Y19N005092 C/W: Mack MP8 6 Cylinder 12.8 L Diesel Engine, 2008 US EPA Label, 22028 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320.0 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Camelback Suspension, 220 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 829,975 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	805	2006 Mack CXN613 Vision 6x4 T/A Day Cab Truck Tractor S/N: 1M1AK07Y66N007508 C/W: Mack 6 Cylinder 11.9 L Ultra Low Sulfur Diesel 480 hp Engine, 2005 US EPA Label, 27360 Engine hrs, Engine Brake, Mack 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 170 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 581,953 Mi Asset located in: Humble, TX
799	2007 Freightliner FLD 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJALCK37DX39861	Cab Truck Tractor S/N: 1FUJA6CK79LAH0941 C/W: Detroit Series 60 6 Cylinder 14 Engine, 2008 US EPA Label, Requires Exhaust Fluid, 15762.4 Engine hrs, E. 10-Speed Manual Transmission, 120 Front Axle, 40000 lb Rears, 52000 lb Ride Cab, Aluminum Front Wheels, 1 Airliner Air Ride Suspension, 178 in V Air Sliding 5th Wheel, Dual Fuel Tank Usage: 225,283 Mi	S/N: 1M2AG12C54M009994 Usage: Not Available
	C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 2006 US EPA Label, 9401 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Meritor RT-44-145 Drive Axles, 3.90:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 210 in Wheelbase, Dual Fuel Tanks Usage: 621,288 Mi Asset located in: Humble, TX		2009 Freightliner Columbia 120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJA6CK79LAH0941 C/W: Detroit Series 60 6 Cylinder 14 L Diesel Engine, 2008 US EPA Label, Requires Diesel Exhaust Fluid, 15762.4 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5,
800A	Truck Tractor S/N: 2WKPDCJH0RK934343 C/W: Cummins N14 6 Cylinder Diesel 430 hp Engine, Engine Brake, Eaton Fuller RTL014613B 13-Speed Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, Spicer DS402 Drive Axles, 46000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Reyco Spring Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 871,471 Mi		Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 225,283 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
		808	2008 Freightliner Century Class CST120 T/A Day Cab Truck Tractor S/N: 1FUJBBCK68LZ69179 Usage: Not Available Asset located in: Midland, TX
802	Asset located in: Humble, TX 1993 Ford LT900 6x4 T/A Day Cab Truck Tractor S/N: 1FDYU90R4PVA38897 C/W: 6 Cylinder Diesel Engine, Eaton Fuller	810	2008 Freightliner Century Class CST120 T/A Day Cab Truck Tractor S/N: 1FUJBBCK78LAA3566 Usage: Not Available Asset located in: Midland, TX
	Manual Transmission, 50000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 170 in Wheelbase, PTO, Wet Kit, Headache Rack, Dual Fuel Tanks Usage: 10,823 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2005 Freightliner ST120 6x4 T/A Day Cab Truck Tractor S/N: 1FUJBBCG55LU03957 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 19647 Engine hrs, Engine Brake, Meritor 10- Speed Manual Transmission, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 173 in Wheelbase, Dual Fuel Tanks
803	1989 Kenworth W900 T/A Day Cab Truck Tractor S/N: 2XKWD29X9KM519259 Usage: Not Available Asset located in: Humble, TX		Usage: 640,000 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
811	2001 Freightliner Century Class CST120 6x4 T /A Day Cab Truck Tractor S/N: 1FUJA9A821LG82188 C/W: 6 Cylinder Diesel Engine, Engine Brake, Manual Transmission, Air Ride Cab, Aluminum Front Wheels, 275/80R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2008 Volvo VNM 6x4 T/A Day Cab Truck	816	2019 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X2KJ257006 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15779 Engine hrs, Engine Brake, 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 492,355 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	Tractor S/N: 4V4MC9EG68N262773		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Volvo D13 6 Cylinder Engine, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, 295/75R22. 5 Front Tires, 295/75R22.5 Rear Tires, Volvo 4-Bag Air Ride Suspension, 166 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,246,354 Mi Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	817	2019 Kenworth W900 6x4 T/A Sleeper Truck Tractor S/N: 1XKWD49X4KJ257007 C/W: Cummins X15 6 Cylinder 15 L Diesel 565 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17943 Engine hrs, Engine Brake, Eaton Fuller RTLO-18918B 18-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X4 Drive Axles, 3.25:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 76 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Paccar Air Ride Suspension, 282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 508,076 Mi Asset located in: Humble, TX
814	2007 International 9200 6x4 T/A Day Cab		
	Truck Tractor S/N: 2HSCEAHRX7C421158 C/W: Cummins ISM 6 Cylinder Diesel Engine,	818	
	27232 Engine hrs, Manual Transmission, Spicer RS404 Drive Axles, 2.85:1 Axle Ratio, Aluminum Wheels, 11R22.5, Air Ride Suspension, 192 in Wheelbase, Dual Fuel Tanks Usage: 837,012 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X7KD6111194 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 41823.6 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 63 in Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 309,780 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
815A	2009 International TranStar 8600 6x4 T/A Day Cab Truck Tractor S/N: 1HSHXAHR09J115073 C/W: Cummins 6 Cylinder Diesel Engine, 2008 US EPA Label, 24262 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295 /75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 361,724 Mi Asset located in: Humble, TX		
815	2007 International 9200 6x4 T/A Day Cab Truck Tractor S/N: 2HSCEAPR47C427393 C/W: Cummins 6 Cylinder Diesel Engine, 2006 US EPA Label, 21080 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 295/75R22.5, Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 545,745 Mi Asset located in: Humble, TX		

Details Lot# **Details** Lot # 819A 2016 Peterbilt 389 6x4 T/A Sleeper Truck 822 2016 Peterbilt 389 6x4 T/A Sleeper Truck Tractor Tractor S/N: 1XPXD49X3GD361783 S/N: 1XPXD49X3GD369706 C/W: Cummins ISX15 6 Cylinder 15 L Diesel Engine, 2015 US EPA Label, Requires Diesel C/W: Cummins ISX15 6 Cylinder Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 57373 Engine hrs, Engine Brake, Exhaust Fluid, 30543.6 Engine hrs, Engine Brake, 13-Speed Manual Transmission, 12000 Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 5320 lb Ib Front Axle, 38000 lb Rears, 50000 lb GVWR, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Leaf Air Ride Suspension, 281 GVWR, 63 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 261 in Wheelbase, Air Sliding 5th Wheel, Dual Tanks Fuel Tanks Usage: 423,399 Mi Usage: 685,630 Mi Notes: THIS UNIT RUNS BUT MAY HAVE Asset located in: Humble, TX DEFICIENCIES IN ITS POLLUTION CONTROL 823 2016 Peterbilt 389 6x4 T/A Sleeper Truck SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS Tractor 114.20 AND 114.50. THIS MAY APPLY IF YOU S/N: 1XPXD49XXGD369704 OPERATE THE UNIT PRIOR TO THE ADEQUATE C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 49169 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE Transmission, Air Ride Cab, 72 in Mid Roof PRIOR TO REMOVAL OF UNIT FROM YARD Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 255 in Wheelbase, Asset located in: Humble, TX Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 347,806 Mi 819 2019 Peterbilt 389 6x4 T/A Sleeper Truck Tractor Asset located in: Humble, TX S/N: 1XPXD49X9KD611200 824 2015 Peterbilt 389 6x4 T/A Sleeper Truck C/W: Cummins X15 6 Cylinder 15 L Diesel 450 Tractor hp Engine, 2019 US EPÁ Label, Requires Diesel Exhaust Fluid, 43831 Engine hrs, Engine Brake, S/N: 1XPXD49X1FD261079 Eaton Fuller 10-Speed Manual Transmission, C/W: Cummins 6 Cylinder Diesel Engine, 13200 lb Front Axle, 40000 lb Rears, 53200 lb Requires Diesel Exhaust Fluid, 34303.2 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, GVWR, 63 in High Rise Sleeper Cab. 11R24.5. Air Trac Air Ride Suspension, 260 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 445/50R22.5 Super Usage: 337,659 Mi Singles Rear Tires, Paccar Air Ride Suspension, Asset located in: Humble, TX 282 in Wheelbase, Air Sliding 5th Wheel, Dual 820 2016 Peterbilt 389 6x4 T/A Sleeper Truck **Fuel Tanks** Tractor Usage: 293,171 Mi S/N: 1XPXD49X3GD317203 Notes: DEFICIENCIES NOTED - PLEASE SEE C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 485 hp Engine, 2015 US EPA Label, Requires THE INSPECTION REPORT; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION Diesel Exhaust Fluid, 36297 Engine hrs, Engine REPORT Brake, 10-Speed Manual Transmission, 13200 Asset located in: Humble, TX lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 352,560 Mi Asset located in: Humble, TX 821 2016 Peterbilt 389 6x4 T/A Sleeper Truck **Tractor** S/N: 1XPXD49X5GD369710 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller

10-Speed Manual Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 262 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 396,833 Mi

Details Lot # 825 2015 Peterbilt 389 6x4 T/A Sleeper Truck Tractor S/N: 1XPXD49X9FD260780 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15440 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13201 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, 11R24.5, Paccar Air Ride Suspension, 282 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 713,133 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD **DEFICIENCIES NOTED - PLEASE SEE THE** INSPECTION REPORT

Asset located in: Humble, TX

826 2013 Peterbilt 367 6x4 T/A Sleeper Truck Tractor

S/N: 1XPTP4EX3DD197071 C/W: Cummins ISX15 15.0 L Diesel 525 hp Engine, 2015 US EPA Label, 28626 Engine hrs, Engine Brake, Manual Transmission, Differential Lock, 16000 lb Front Axle, 40666 lb Rears, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 385/65R22. 5 Front Tires, 11R24.5 Rear Tires, Air Trac Air Ride Suspension, 240 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,438,266 Mi

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

827 2019 Freightliner Coronado 122SD 6x4 T/A Sleeper Truck Tractor

S/N: 3AKJGNFG3KDKV9053 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17821 Engine hrs, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, Differential Lock, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53220 lb GVWR, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 502,082 Mi

Notes: PROFESSIONALLY-MAINTAINED-FLEET-

VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE

DOCUMENT SECTION BELOW Asset located in: Humble, TX

Lot # **Details**

828 2016 International LoneStar 6x4 T/A Sleeper **Truck Tractor**

S/N: 3HSCXAPR6GN111535 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 20473 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 698,966 Mi

Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX

829 2013 International Paystar 5900i 6x4 T/A Sleeper Truck Tractor

S/N: 1HSXYSJRXDJ078910 C/W: Cat C15 6 Cylinder Diesel 435 hp Engine, 48205 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Hendrickson Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 78,430 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Humble, TX

830 2013 International Paystar 5900i 6x4 T/A Sleeper Truck Tractor

S/N: 1HSXYSJR3DJ078909 C/W: Cat 6 Cylinder Diesel Engine, 2012 US EPA Label, 30336 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, 51 in Flat Top Sleeper Cab, 11R24.5, Hendrickson Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 431,459 Mi

Notes: THIS UNIT RUNS BUT MAY HAVE **DEFICIENCIES IN ITS POLLUTION CONTROL** SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD

Lot #	Details	Lot #	Details
831A	2010 Kenworth 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDU9X5AJ262884 C/W: Cat C13 6 Cylinder Diesel 445 hp Engine, 2009 US EPA Label, 31639 Engine hrs, Engine Brake, Eaton Fuller RTLO-16913A 13-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 3.55:1 Axle Ratio, 50000 lb GVWR, Air Ride Cab, 52 in Flat Top Sleeper Cab, 11R22.5, Air Ride Suspension, 226 in Wheelbase, Dual Fuel Tanks Usage: 1,131,845 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	834	2020 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBD49X0LD657204 C/W: Cummins ISX15 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 13148 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 38000 lb Rears, 51200 lb GVWR, Air Ride Cab, 80 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 546,016 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
831	2011 Western Star 4900 6x4 T/A Sleeper Truck Tractor		THE INSPECTION REPORT
832	S/N: 5KJJALDR2BPAX2524 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Engine Brake, Automated Transmission, Air Ride Cab, 34 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 195,951 Mi Asset located in: Humble, TX 2020 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR6LLLU6811 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1750- OH1 12-Speed Automated Transmission, 13000 lb Front Axle, 40000 lb Rears, 2.85:1	835	2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X9KD607207 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Paccar Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Front Wheels, 275/80R22.5 Front Tires, 11R22.5 Rear Tires, Paccar Air Ride Suspension, 242 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 488,776 Mi Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 431,325 Mi Asset located in: Humble, TX		2019 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X7KD607190 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14388.0 Engine hrs, Engine Brake, Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Paccar Air Ride Suspension, 239 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 564,878 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
833	2019 Western Star 5700XE 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR2KLKE6957 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1750-OH1 Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 68 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Comfort pro Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 605,703 Mi Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
837	2023 Kenworth T680 6x4 T/A Sleeper Truck Tractor	840	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor
	S/N: 1XKYD49X9PJ239781 C/W: Cummins X15 6 Cylinder 15 L Diesel 500 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 3500 Engine hrs, Engine Brake, Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Meritor Drive Axles, 2.79:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 166,668 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1XKYDP9X4LJ348287 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 15421 Engine hrs, Engine Brake, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Paccar Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 589,051 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	841	2019 Kenworth T680 6x4 T/A Sleeper Truck
838	2023 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X0PJ248970 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 456 hp Engine, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 12344 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295 /75R22.5, Paccar Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 343,012 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Tractor S/N: 1XKYD49X1KJ242070 C/W: Cummins X15 450SA 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10275 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.08:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Paccar Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 407,257 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
839	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X9LJ388380 C/W: Cummins X15 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 53200.0 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,254 Mi Asset located in: Humble, TX	842	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X0KJ999415 C/W: Paccar MX-13 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Paccar PO-16F112 Automated Transmission, Differential Lock, 5988 kg Front Axle, 18144 kg Rears, Paccar Drive Axles, 2.93:1 Axle Ratio, 24132 kg GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 11R22.5 Rear Tires, AG210 Air Ride Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 525,423 Mi
	•	•	Notes: LOCATED-IN-MIDLAND-TX.
			Apart located in: Midland TV

Asset located in: Midland, TX

Lot #	Details	Lot #	Details
843	2019 Kenworth T680 6x4 T/A Sleeper Truck Tractor	847	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor
	S/N: 1XKYD49X5KJ310239 C/W: Cummins X15 15 L Diesel 450 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Paccar Automated Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 53200 lb GVWR, Air Ride Cab, 76 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar 4-Bag Air Ride Suspension, 233 in Wheelbase, PTO, Dual Fuel Tanks Usage: Not Available		S/N: 3AKJHHDR1LSMG6164 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 16808 Engine hrs, Engine Brake, Detroit DT12-1650 12- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
	Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE		Usage: 449,805 Mi Notes : . DEFICIENCIES NOTED - PLEASE SEE
	INSPECTION REPORT Asset located in: Midland, TX		THE INSPECTION REPORT Asset located in: Humble, TX
844	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5NSNC7969 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 14698 Engine hrs, Engine Brake, Detroit DT12-1750- OHE 12-Speed Automated Transmission,	848	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR1LSMJ0214 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1650-OH1 12- Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb
	12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 278,457 Mi Notes: LOCATED-IN-FORT-WORTH-TX		GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 505,902 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG;
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
845	2022 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7NSNM0632 Usage: 314,215 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX	849	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR7LSLV7454 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 60 in
846	2021 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDV8MSMK2617 Usage: 825,003 Mi		Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 523,264 Mi
	Notes: PENSKE-FLEET-MAINTAINED; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
850	2020 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR4LSMJ0210 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel	854	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSLG2419 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low
	Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14504 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 11R22. 5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 534,243 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX		Sulfur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1750 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 500,910 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-
851	2020 Freightliner Cascadia 126 6x4 T/A		VEHICLE-PAG;
	Sleeper Truck Tractor S/N: 3AKJHHDRXLSLT5934 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18742 Engine hrs, Engine Brake, Eaton Fuller DT12-1750-DH1 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 663,899 Mi Notes: PENSKE-FLEET-MAINTAINED; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	055	Asset located in: Humble, TX
		855	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor
			S/N: 3AKJHHDR3KSKF3926 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1550 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Thermo King Tripac Auxiliary Power Unit, Aluminum Front Wheels, 275/80R22.5, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 551,919 Mi
853	2019 Freightliner Cascadia 126 6x4 T/A	856	Asset located in: Humble, TX 2019 Freightliner Cascadia 126 6x4 T/A
	Sleeper Truck Tractor S/N: 3AKJHHFG2KSLM8011 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 605 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 395 Engine hrs, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, 53300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, Dual Fuel Tanks Usage: 415,568 Mi Notes: LOCATED-IN-FORT-WORTH-TX PER THE DEALER ACTUAL MILEAGE IS HIGHER THAN SHOWING ON ODO AND ECM - TRUE MILEAGE IS UNKNOWN Asset located in: Humble, TX		Sleeper Truck Tractor S/N: 3AKJHHDR5KSKF5676 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 22183 Engine hrs, Engine Brake, Detroit DT12 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 610,297 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

			1 age /1 01 43/
Lot #	Details	Lot #	Details
857	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR2KSHU6374 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 13677 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Sleeper Air Conditioner, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 631,008 Mi Asset located in: Humble, TX	860	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 1FUJHHDR3KLKJ3572 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 14880 Engine hrs, Engine Brake, Detroit DT12-1750-OH1 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.85:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Electric Sleeper Air Conditioner, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 704,993 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
000	Sleeper Truck Tractor	861	2019 Freightliner Cascadia 126 6x4 T/A
	S/N: 3AKJHHDR3KSHU6450 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15649 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.28:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 692,413 Mi Asset located in: Humble, TX		Sleeper Truck Tractor S/N: 3AKJHHDR0KSKH3017 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 26157 Engine hrs, Engine Brake, Detroit DT12- 1650-DH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 724,578 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG;
859	2019 Freightliner Cascadia 126 6x4 T/A		Asset located in: Humble, TX
	Sleeper Truck Tractor S/N: 3AKJHHDR4KSKH3019 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 23189 Engine hrs, Engine Brake, Detroit DT12-1650-DH1 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 53220.0 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 700,170 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX	862	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR5KSKB5467 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 17897 Engine hrs, Engine Brake, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, Aluminum Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 744,509 Hr Asset located in: Humble, TX
		863	2019 Freightliner Cascadia 126 6x4 T/A
			Sleeper Truck Tractor S/N: 3AKJHHDR4KSHU6635 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel Engine, 2018 US EPA Label, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 828,837 Mi Notes: LOCATED-IN-FORT-WORTH-TX

Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
864	2019 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR0KSKY4314 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-1650- OH1 12-Speed Automated Transmission, Meritor MT-40-14X Drive Axles, 3.08:1 Axle Ratio, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 579,455 Mi Asset located in: Humble, TX	867	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDV1KLKD4452 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1550- OH1 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 438,561 Mi
865	2019 Freightliner Cascadia 126 6x4 T/A		Asset located in: Humble, TX
066	Sleeper Truck Tractor S/N: 3AKJHHDR0KSKY3762 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FAO-16810C 10- Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Thermo King Tri- Pac Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 455,917 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	868	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR5KDKM9522 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19103 Engine hrs, Engine Brake, Eaton Fuller FRM- 15210B 10-Speed Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000.0 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 524,983 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
866	2019 Freightliner Cascadia 125 6x4 T/A	869	2019 Freightliner Cascadia 125 6x4 T/A
	Sleeper Truck Tractor S/N: 3AKJGLFG8KSLE1713 C/W: Cummins ISX15 450 6 Cylinder 15.0 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12324 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 382,610 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG		Sleeper Truck Tractor S/N: 1FUJGLDV6KLKD4477 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12351 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Thermo King Auxiliary Power Unit, Aluminum Wheels, 11R22. 5, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,467 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	871	2019 Freightliner Cascadia 125 6x4 T/A
		1071	Sleeper Truck Tractor S/N: 3AKJGLDR1KDKM9520 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FR- 15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel Usage: 473,185 Mi

			Page 73 01 437
Lot #	Details	Lot #	Details
872	2019 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 1FUJGLDR8KLKG0906 Usage: 492,969 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	876	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV6KSKH9486 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23543 Engine hrs, Detroit DT12-1550- OH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000
873	2019 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLDR8KSKK1807 Usage: 513,382 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX		lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 720,855 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
874	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDVXKSKH9488 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 23103 Engine hrs, Retarder, 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 680,003 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	877	2020 Freightliner Cascadia 116 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHPDV8LSLF0404 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 22242 Engine hrs, Engine Brake, Detroit DT12-1550-DH1 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4S HH NFD Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 252,232 Mi Notes: LOCATED-IN-FORT-WORTH-TX-HOU
875	2019 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR3KDKG6301 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15355 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52000 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Bergstrom Electric Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 719,256 Mi Asset located in: Humble, TX	878	Asset located in: Lake Worth, TX 2019 Freightliner Cascadia 116 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHPDV2KSKF9689 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1550-DH1 12- Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0- 4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 48 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Air Sliding 5th Wheel Usage: 469,839 Mi Asset located in: Humble, TX

Details	Lot #	Details
2019 Volvo VNL780 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2KN211694 C/W: Volvo D13M455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 695,175 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	883	2020 Volvo VNL64T740 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH8LN258469 C/W: Volvo 6 Cylinder Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 14884 Engine hrs, Automatic Transmission, Differential Lock, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, 295/75R22.5, Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 625,732 Hr Notes: LOCATED-IN-HUMBLE-TX Asset located in: Humble, TX 2020 Volvo VNR640 6x4 T/A Sleeper Truck Tractor
Asset located in: Humble, TX 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH5KN211687 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, 25856.7	885	S/N: 4V4WC9EH9LN250451 Usage: 508,220 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in : Humble, TX
Speed Automated Transmission, Meritor MT- 40-14X Drive Axles, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,056 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Tractor S/N: 4V4WC9DHXLN270435 C/W: Volvo 6 Cylinder 10.8 L Diesel 425 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 10632 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, A Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295/75R22.5, Volvo
2019 Volvo VNL64760 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3KN214085 Usage: 552,095 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION		Corporate Air Air Ride Suspension, 203 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 317,822 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
BELOW SUPPLIED	886	2019 Volvo VNR400 6x4 T/A Sleeper Truck
2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6KN214100 C/W: Volvo D13H455 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16462 Engine hrs, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel Usage: 581,651 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Tractor S/N: 4V4WC9DH5KN217446 C/W: Volvo D11M 6 Cylinder 10.8 L Ultra Low Sulfur Diesel 425 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 42 in Flat Top Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Volvo Air Ride Suspension, 198 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 451,707 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	2019 Volvo VNL780 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2KN211694 C/W: Volvo D13M455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 695,175 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH5KN211687 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, 25856.7 Engine hrs, Engine Brake, Volvo ATO2612F 12-Speed Automated Transmission, Meritor MT- 40-14X Drive Axles, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,056 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Volvo VNL64760 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3KN214085 Usage: 552,095 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3KN214085 Usage: 552,095 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	2019 Volvo VNL780 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH2KN211694 C/W: Volvo D13M455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT02612F 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 50350 lb GWWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 695,175 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH5KN211687 C/W: Volvo D13M-455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2018 US EPA Label, 25856.7 Engine hrs, Engine Brake, Volvo AT02612F 12- Speed Automated Transmission, Meritor MT- 40-14X Drive Axles, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 812,056 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Volvo VNL64760 T/A Sleeper Truck Tractor S/N: 4V4NC9EH3KN214085 Usage: 552,095 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX 2019 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EH6KN214100 C/W: Volvo D13H455 6 Cylinder 12.8 L Ultra Low Sulfrur Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16462 Engine hrs, Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, 52500 lb GWWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 231 in Wheelbase, Air Sliding 5th Wheel Usage: 581,651 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
887	2020 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR4LN800109 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, 15026 Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Tripac Auxiliary Power Unit, 11R22.5, Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 571,619 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	891	2018 Western Star 5700 6x4 T/A Sleeper Truck Tractor S/N: 5KJJBHDR2JLJZ0716 C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 27535 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40009 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 653,881 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	REPORT	892	2017 Peterbilt 579 6x4 T/A Sleeper Truck Tractor
888	Asset located in: Humble, TX 2019 International LT625 T/A Sleeper Truck Tractor S/N: 3HSDZAPR4KN748835 Usage: 521,058 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX		S/N: 1XPBDP9X6HD417518 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 14401.9 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 13200 lb Front Axle, 38000 lb Rears, Meritor MR2014X Drive Axles, 3.08:1 Axle Ratio, 51200 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Bunk Beds, HP2000 Extreme Auxiliary Power Unit,
889	2019 International LT625 6x4 T/A Sleeper		Aluminum Wheels, 295/75R22.5, Paccar Air Ride Suspension, 244 in Wheelbase, Blower,
	Truck Tractor		Dual Fuel Tanks Usage: 645,132 Mi
	S/N: 3HSDZAPR8KN707107 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low		Asset located in: Humble, TX
890	Sulfur Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 507,769 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2019 International LT625 6x4 T/A Sleeper Truck Tractor	894	2016 Peterbilt 579 6x4 T/A Sleeper Truck Tractor S/N: 1XPBDP9X1GD298100 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automati Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in M Roof Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5t Wheel, Dual Fuel Tanks Usage: 595,513 Mi
	S/N: 3HSDZAPR7KN112927 C/W: Cummins X15 6 Cylinder 15.0 L Diesel	895	Asset located in: Humble, TX 2016 Peterbilt 579 6x4 T/A Sleeper Truck
	450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 18532 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 530,126 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Tractor S/N: 1XPBD49X2GD281174 C/W: Cummins 6 Cylinder Diesel Engine, 29303 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, 50000 lb GVWR, Air Ride Cab, 68 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 883,597 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
897	2014 Peterbilt 386 6x4 T/A Sleeper Truck Tractor S/N: 1XPHDP9X9ED208358 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 23336 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 38000 lb Rears, Spicer DSP40 Drive Axles, 50000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 245 in Wheelbase, Dual Fuel Tanks Usage: 883,374 Mi Notes: LOCATED-IN-FORT-WORTH-TX, THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY	901	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X5JJ135569 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2017 Kenworth T680 T/A Sleeper Truck Tractor S/N: 1XKYDP9X1HJ158213 Usage: 661,714 Mi Asset located in: Lake Worth, TX
	EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	903	2016 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYD49X3GJ473723 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 485 hp Engine, 2014 US EPA Label, Requires
898	Asset located in: Lake Worth, TX 2013 Peterbilt 386 T/A Sleeper Truck Tractor S/N: 1XPHD49X8DD173180 Usage: Not Available Notes: TITLE BRAND (BONDED TITLE) Asset located in: Humble, TX		Diesel Exhaust Fluid, 18566 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 42 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Paccar Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
899	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor		Usage: 563,861 Mi Asset located in: Humble, TX
	S/N: 1XKYDP9X6JJ210795 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 16372 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, 297/75R22.5, Paccar Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 592,164 Mi Notes: LOCATED-IN-HUMBLE-TX Asset located in: Humble, TX	Tractor S/N: 1XKYD49XXGJ101330 C/W: Cummins ISX15 450ST 6 Cyl Ultra Low Sulfur Diesel 450 hp Eng EPA Label, Requires Diesel Exhaus 30265 Engine hrs, Engine Brake, A Transmission, 12350 lb Front Axle Rears, 2.64:1 Axle Ratio, 50350 lb High Rise Sleeper Cab, Bunk Beds, Outer Wheels, 295/75R22.5, Air Rig Suspension, 224 in Wheelbase, Du Usage: 726,673 Mi	S/N: 1XKYD49XXGJ101330 C/W: Cummins ISX15 450ST 6 Cylinder 15 L Ultra Low Sulfur Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 30265 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, 2.64:1 Axle Ratio, 50350 lb GVWR, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 224 in Wheelbase, Dual Fuel Tanks Usage: 726,673 Mi
900	2018 Kenworth T680 6x4 T/A Sleeper Truck Tractor		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1XKYD49X5JJ208468 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Paccar Drive Axles, 2.64:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX-TX Asset located in: Lake Worth, TX	905	2015 Kenworth T680 6x4 T/A Sleeper Truck Tractor S/N: 1XKYDP9X9FJ449653 C/W: Paccar 6 Cylinder Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 23432 Engine hrs, Engine Brake, Automatic Transmission, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Comfort Pro Auxiliary Power Unit, 295/75R22.5, 8-Bag Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 810,190 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
906	2014 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKAD49X5EJ385237 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 515 hp Engine, 2005 US EPA Label, Requires Diesel Exhaust Fluid, 13956.5 Engine hrs, Engine Brake, Eaton Fuller FOM-16E310C-LAS 10-Speed Manual Transmission, 13200 lb Front Axle, Spicer DSP41 Drive Axles, 3.25:1 Axle Ratio, 47200 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 842,880 Mi Notes: LOCATED-IN-FORT-WORTH-TX	910	2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8FM051320 C/W: Mack MP7 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 8246 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Air Ride Suspension, 215 in Wheelbase Usage: 655,608 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
907	Asset located in: Lake Worth, TX 2013 Kenworth T660 6x4 T/A Sleeper Truck Tractor S/N: 1XKADP9X4DJ356635 C/W: Paccar MX 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20923 Engine hrs, Engine Brake, Eaton Fuller RTLO- 16913A 13-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 3.25:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, 62 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 11R22.5	– 911	2014 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8EM036878 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2013 US EPA Label, 26792 Engine hrs, Eaton Fuller 13-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5 Front Tires, 285 /75R24.5 Rear Tires, Air Ride Suspension, 217 in Wheelbase Usage: 871,001 Mi Asset located in: Humble, TX
908	Rear Tires, Air Assist Front Suspension, Paccar Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 831,886 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2013 Kenworth T700 6x4 T/A Sleeper Truck Tractor S/N: 1XKFDP9X0DJ331902 C/W: Paccar MX 6 Cylinder 12.9 L Diesel 485 hp Engine, 2012 US EPA Label, Requires Diesel	912	2013 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02Y8DM031484 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 13- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 285/75/24.5, Air Ride Suspension, 216 in Wheelbase Usage: Not Available
	Exhaust Fluid, 3267 Engine hrs, Eaton Fuller FOM-16E310C-LAS 13-Speed Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, Spicer DSP40 Drive Axles, 3.25:1 Axle Ratio, 53200 lb GVWR, 50 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Paccar Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 615,605 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		Asset located in: Humble, TX 2010 Mack CXU 613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW09Y5AN011379 C/W: Mack MP8 6 Cylinder 12.8 L 415 hp Engine, 2009 US EPA Label, 38733 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, 295/75R22.5, Air Ride Suspension, 221 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
909	2015 Mack CXU613 6x4 T/A Sleeper Truck Tractor S/N: 1M1AW02YXFM051321 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2014 US EPA Label, 20180 Engine hrs, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 13250 lb Front Axle, 40000 lb Rears, 53250 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5 Front Tires, 285/75R24.5 Rear Tires, Air Ride Suspension, 224 in Wheelbase Usage: 515,958 Mi Asset located in: Humble, TX		Usage: 700,969 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
914	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHFG6JSJJ1536 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19668 Engine hrs, Engine Brake, Eaton Fuller FAOM-15810S 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 531,460 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	918	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDV3JSJR8314 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-1650- OH1 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.79:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Carrier Auxiliary Power Unit, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Dual Fuel Tanks Usage: 788,655 Mi Asset located in: Humble, TX
	THE INSPECTION REPORT	920	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor
915	Asset located in: Humble, TX 2018 Freightliner Cascadia 126 T/A Sleeper Truck Tractor S/N: 3AKJHHDR1JSJW4259 Usage: 684,976 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	_	S/N: 3AKJHHFGXJSJW1596 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 25160 Engine hrs, Engine Brake, Eaton Fuller FAOM-15810S-EC Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Carrier ComfortPro Auxiliary Power Unit, Aluminum
916	2018 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor S/N: 3AKJHHDR8JSJR1197 C/W: Detroit DD15 6 Cylinder Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 13751 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 690,279 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX		Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 830,526 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
Trans Rears High Airlind Air Sli Fuel 1 Usago Notes VEHIO Asset		921	2018 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLDR6JDJS5628 Usage: 317,722 Mi Notes: PENSKE-FLEET-MAINTAINED; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
917	2018 Freightliner 126 6X4 T/A Sleeper Truck Tractor	922	Asset located in: Humble, TX 2018 Freightliner Cascadia 125 6x4 T/A
	S/N: 3AKJHHDR3JSJW4070 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 20312 Engine hrs, Detroit DT12- 1650-OH1-HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Meritor RT-40.0-4 HT Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 626,634 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	<i>322</i>	Sleeper Truck Tractor S/N: 3AKJGLDR0JSJH2516 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15289 Engine hrs, Detroit DT12- 0A-1650 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 527,071 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX

Details Lot # **Details** Lot # 923 2018 Freightliner Cascadia 125 6x4 T/A 926 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLDR1HLJG3300 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel S/N: 3AKJGLDR2JDJT9266 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 17275 Engine hrs, Engine Brake, Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Eaton Fuller FRO-16210C 10-Speed Manual 12000 lb Front Axle, 40000 lb Rears, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 34 in Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 236 in 228 in Wheelbase, Air Sliding 5th Wheel, Dual Wheelbase, Air Sliding 5th Wheel, Dual Fuel **Fuel Tanks** Tanks Usage: 458,699 Mi Usage: 540,539 Mi Notes: ; SELLER SUPPLIED MAINTENANCE Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX Asset located in: Humble, TX 924 2018 Freightliner Cascadia 125 6x4 T/A 927 2017 Freightliner Cascadia 125 6x4 T/A **Sleeper Truck Tractor** Sleeper Truck Tractor S/N: 1FUJGLDV0JLJK2907 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 S/N: 1FUJGLDR7HLJG3298 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 15724.4 Engine hrs, Engine hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 14135 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 Ib Front Axle, 40000 lb Rears, 52000 lb GVWR, Brake, Eaton Fuller FRO-15210C 10-Speed Air Ride Cab, 60 in Flat Top Sleeper Cab, Manual Transmission, 12000 lb Front Axle, Thermo King Auxiliary Power Unit, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 40000 lb Rears, Meritor RT-40-4 HT Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air 240 in Wheelbase, Air Sliding 5th Wheel, Dual Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, airliner Air Ride Fuel Tanks Usage: 540,841 Mi Suspension, 236 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX Usage: 582,475 Mi 925 2018 Freightliner Cascadia 125 6x4 T/A **Notes**: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT Sleeper Truck Tractor SECTION BELOW S/N: 1FUJGLDR1JLJK3289 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Asset located in: Humble, TX Sulfur Diesel 400 hp Engine, 2017 US EPA 929 2017 Freightliner Cascadia 125 6x4 T/A Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.47:1 Sleeper Truck Tractor S/N: 1FUJGLDR0HLHX4331 C/W: Detroit 6 Cylinder Diesel Engine, 2016 US Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in EPA Label, Requires Diesel Exhaust Fluid, High Rise Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride 17755 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Suspension, 224 in Wheelbase, Air Sliding 5th Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Comfort Pro Auxiliary Power Unit, Aluminum Wheels, Wheel, Dual Fuel Tanks Usage: 621,799 Mi 295/75R22.5, Airliner Air Ride Suspension, 240 Notes: CPC HAS BEEN REMOVED FROM THIS TRUCK AND STORED IN THE OFFICE in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX

Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Usage: 610,010 Mi

Lot #	Details	Lot #	Details
931	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	936	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
	S/N: 1FUJGLDV7HLHW1041 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, 24154 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.42:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 754,355 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3AKJGLDR5HSHV9635 C/W: Detroit DD15 6 Cylinder 14.8 L 505 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-DA 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14XP Drive Axles, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Thermo King Auxiliary Power Unit, Aluminum Wheels, 295/75R22.5 Front Tires, MIXED SIZE Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX
932	2017 Freightliner Cascadia 125 6x4 T/A		Asset located in: Lake Worth, TX
	Sleeper Truck Tractor S/N: 3AKJGLDRXHSJC8811 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OA- 1650 HD 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 824,733 Mi	937A	2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDR1HSHR5628 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Retarder, Detroit DT12-DA-1750 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks
933	Asset located in: Humble, TX 2017 Freightliner Cascadia 125 6x4 T/A	\dashv	Usage: 628,464 Mi
	Sleeper Truck Tractor		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 3AKJGLDRXHSGW4469 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 826,868 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	937	Asset located in: Humble, TX 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG2HSJA3080 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810S-EC Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.62:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 58 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 781,986 Mi Asset located in: Humble, TX
934	2017 Freightliner Cascadia 125 T/A Sleeper	938	2016 Freightliner Cascadia 125 6x4 T/A
	Truck Tractor S/N: 1FUJGLDV7HLGV8282 Usage: Not Available Asset located in: Humble, TX	938	Sleeper Truck Tractor S/N: 1FUJGLDR3GLHA5529 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, Requires Diesel
935	2017 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 1FUJGLDVXHLGV8275 Usage: Not Available Asset located in: Humble, TX		Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 106,432 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX

Lot #	Details	Lot #	Details
939	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor	943	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor
	S/N: 1FUJGLDR3GLGT8855 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 400 hp Engine, Requires Diesel Exhaust Fluid, 20296 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 2.41:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 641,028 Mi Notes: LOCATED-IN-MIDLAND-TX		S/N: 3AKJGLD66GSHC4487 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18886 Engine hrs, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Sleeper Air Conditioner, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 755,342 Mi
	Asset located in: Midland, TX		THE INSPECTION REPORT Asset located in: Humble, TX
941	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV3GSHC6947 C/W: Detroit DD13 6 Cylinder 12.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 26117 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22.5, Air Assist Front Suspension, Airliner Air Ride Suspension, 235 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 668,171 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	944	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD56GLGU2007 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 27811 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 812,953 Mi Notes: Asset located in: Livingston, LA
942	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLBG4GLHJ1460 C/W: Cummins ISX15 6 Cylinder 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAOM-15810C Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.62:1 Axle Ratio, 52350.0 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Suspension, 237 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 688,311 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	945	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLDV3GSHM3347 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 21834 Engine hrs, Engine Brake, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 693,914 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	946	2016 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLBGXGSHT7100 Usage: Not Available

Lot #	Details	Lot #	Details
947	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG6GSHT7580 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	951	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLBG2GSGZ5263 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 13961 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C-LAS Ultrashift Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.36:1 Axle Ratio, 53300 lb GVWR, 70 in High Rise Sleeper Cab, Thermo King Electric Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 557,375 Mi Asset located in: Humble, TX 2015 Freightliner Cascadia 125 6x4 T/A
948	2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD56GSGN1939 C/W: Detroit DD15 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 16757 Engine hrs, Engine Brake, Eaton Fuller FR-15210B 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Dual Fuel Tanks		Sleeper Truck Tractor S/N: 3AKJGLDV9FSGK2899 C/W: Detroit DD13 6 Cylinder 12.8 L 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22574 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 3.42:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 244 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 471,635 Mi Asset located in: Humble, TX
949	Usage: 701,624 Mi Asset located in: Humble, TX 49 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD56GSHP2843 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA- RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks	953	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD54FSFK4749 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 22930 Engine hrs, Engine Brake, Detroit 12-Speed Automated Transmission, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Axle Ratio, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 588,173 Mi Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
	Usage: 712,997 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	954	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGHDV8FSGL7536 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 17707 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 275/80R22. 5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 664,589 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Details Lot # **Details** Lot # 955 2015 Freightliner Cascadia 125 6x4 T/A 958 2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor Sleeper Truck Tractor S/N: 1FUJGLD51FLGD0566 S/N: 1FUJGLD54FLGE3862 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel C/W: Detroit 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-OA-1750 HD 12-Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-Rears, 52000 lb GVWR, Air Ride Cab, High Rise 4 Drive Axles, 2.85:1 Axle Ratio, 53300 lb Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 GVWR, Air Ride Cab, 70 in High Rise Sleeper /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Headache Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Rack, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: 724,909 Mi Notes: LOCATED-IN-MIDLAND-TX. Usage: 1,042,345 Mi Asset located in: Midland, TX Notes: DEFICIENCIES NOTED - PLEASE SEE 959 2015 Freightliner Cascadia 125 6x4 T/A THE INSPECTION REPORT Sleeper Truck Tractor Asset located in: Humble, TX S/N: 3AKJGLD6XFSAG2746 956 2015 Freightliner Cascadia 125 6x4 T/A C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 **Sleeper Truck Tractor** hp Engine, Requires Diesel Exhaust Fluid, S/N: 3AKJGLD52FSGK9029 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 24886 Engine hrs, Engine Brake, 24048 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.42:1 Axle Ratio, 12-Speed Automated Transmission, 12000 lb 52000.0 lb GVWR, Air Ride Cab, 70 in Mid Roof Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, Sleeper Cab, Aluminum Outer Wheels, 295 52000 lb GVWR, Air Ride Cab, 72 in High Rise /75R22.5, Airliner Air Ride Suspension, 240 in Sleeper Cab, Bunk Beds, Bunk Heater, Wheelbase, Air Sliding 5th Wheel, Dual Fuel Aluminum Outer Wheels, 275/80R22.5 Front Tanks Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Usage: 781,669 Mi Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Asset located in: Humble, TX 960 2015 Freightliner Cascadia 125 6x4 T/A Usage: 697,726 Mi Sleeper Truck Tractor Notes: LOCATED-IN-FORT-WORTH-TX BUYER'S RESPONSIBILITY FOR REMOVAL OF S/N: 3AKJGLD53FSGH9952 THIS; ITEM ADDITIONAL COMPONENTS AVAILABLE IN OFFICE - CPC; DEFICIENCIES C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 45413 Engine hrs, Engine Brake, NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 2.47: THE INSPECTION REPORT Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Asset located in: Lake Worth, TX High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Auxiliary Power Unit, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 224 in Wheelbase, Air Sliding 2015 Freightliner Cascadia 125 6x4 T/A 957 **Sleeper Truck Tractor** S/N: 3AKJGLDV1FSGC4111 5th Wheel, Dual Fuel Tanks C/W: Detroit DD13 6 Cylinder 12.8 L 500 hp Engine, 2014 US EPA Label, 15774 Engine hrs, Usage: 882,767 Mi Engine Brake, Eaton Fuller Automated Notes: DEFICIENCIES NOTED - PLEASE SEE Transmission, 12500 lb Front Axle, 40000 lb THE INSPECTION REPORT Rears, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Electric Sleeper Air Conditioner, Aluminum Wheels, 295 Asset located in: Humble, TX 961 2015 Freightliner Cascadia 125 6x4 T/A /75R22.5, Airliner Air Ride Suspension, 234 in Sleeper Truck Tractor Wheelbase, Air Sliding 5th Wheel, Dual Fuel S/N: 3AKJGLD66FSGL9720 Tanks C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2014 US EPA Label, Requires Diesel Usage: 709,282 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.36:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5 Front Tires, THE INSPECTION REPORT Asset located in: Humble, TX 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: 843,243 Mi

Lot #	Details	Lot #	Details
962	2015 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLD69FLGN1999 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO-16913A 13- Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 52300 lb GVWR, 58 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, 232 in Wheelbase, Air Sliding 5th Wheel Usage: 112,065 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	966	2014 Freightliner Cascadia 125 T/A Sleeper Truck Tractor S/N: 3AKJGLD58ESFK2646 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 27101 Engine hrs, Engine Brake, Eaton Fuller RTOCM-16909A 13-Speed Manual Transmission, 12350 lb Front Axle, 34000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 46350.0 lb GVWR, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 191,299 Mi
963	2015 Freightliner Cascadia 125 6x4 T/A	101-	Asset located in: Humble, TX
	Sleeper Truck Tractor S/N: 1FUJGLDV4FLGM6667 C/W: Detroit DD13 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18642 Engine hrs, Eaton Fuller 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.23:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 212 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 632,880 Mi Asset located in: Humble, TX	967	2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD50ESFY3229 C/W: Detroit 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 24797 Engine hrs, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Bunk Heater, Sleeper Air Conditioner, 295/75R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 816,732 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
964	2015 Freightliner Cascadia 125 6x4 T/A	7	THE INSPECTION REPORT
	Sleeper Truck Tractor S/N: 3AKJGLD55FSGB5654 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 33891 Engine hrs, Engine Brake, Detroit DT12-OA-1650 HD 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 986,645 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	968	Asset located in: Humble, TX 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 3AKJGLD52ESFR3485 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 22596 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 238 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: 899,662 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
965	2015 Freightliner Cascadia 125 6x2 T/A Sleeper Truck Tractor S/N: 1FUGGLDV6FLGC1453 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17671 Engine hrs, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 20K R-SRS Drive Axles, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 471,980 Mi		Asset located in: Humble, TX

Notes: DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT **Asset located in**: Humble, TX

Details Lot# **Details** Lot # 969 2013 Freightliner Cascadia 125 6x4 T/A 973 2015 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TH2FN912681 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2011 US EPA Label, CARB Sleeper Truck Tractor S/N: 1FUJGLDR0DSBR0012 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Compliant, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Label, Requires Diesel Exhaust Fluid, 25813 Transmission, 13200 lb Front Axle, 38000 lb Rears, 51200.0 lb GVWR, Air Ride Cab, 42 in Engine hrs, Engine Brake, Eaton Fuller RTOCM-16909A 9-Speed Manual Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.42:1 Axle Ratio, 53300.0 lb GVWR, 70 in High Rise Sleeper Cab, Bunk High Rise Sleeper Cab, Bunk Beds, 295/75R22. 5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 480,143 Mi Beds, Aluminum Wheels, 11R22.5 Front Tires, 445/50R22.5 Super Singles Rear Tires, Airliner Air Ride Suspension, 230 in Wheelbase, Air Notes: THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN Sliding 5th Wheel, Dual Fuel Tanks Usage: 967.604 Mi TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU Asset located in: Humble, TX OPERATE THE UNIT PRIOR TO THE ADEQUATE 970 2013 Freightliner Cascadia 6x4 T/A Sleeper RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY **Truck Tractor** EOUIPPED. BUYER OF THIS UNIT MUST SIGN S/N: 3AKJGLDR7DSBB5155 ACKNOWLEDGEMENT FORM OF THIS NOTICE C/W: 6 Cylinder Diesel 455 hp Engine, 27508.2 PRIOR TO REMOVAL OF UNIT FROM YARD Engine hrs, Engine Brake, Eaton Fuller FRO-**DEFICIENCIES NOTED - PLEASE SEE THE** 15210C 10-Speed Manual Transmission, INSPECTION REPORT 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Asset located in: Humble, TX Ride Cab, 60 in High Rise Sleeper Cab, Bunk 974A 2013 Volvo VNL 6x4 T/A Sleeper Truck Tractor Beds, Bunk Heater, Aluminum Rear Wheels, 295 S/N: 4V4NC9EJ0DN144762 C/W: Volvo D13H455 6 Cylinder 12.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires /75R22.5, Airliner Áir Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 128,090 Mi Diesel Exhaust Fluid, 35268 Engine hrs, Volvo ATO2612D Automated Transmission, 13200 lb Notes: ODOMETER DISCREPANCY-PLEASE Front Axle, 40000 lb Rears, Meritor MT-40-14X SEE INSPECTION REPORT DEFICIENCIES Drive Axles, 3.42:1 Axle Ratio, 53200 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride NOTED Asset located in: Humble, TX Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks 971 2013 Freightliner Cascadia 125 6x4 T/A Usage: 1,131,390 Mi Sleeper Truck Tractor **Notes**: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT S/N: 1FUJGLBG2DLBZ8110 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2012 US EPA Label, Requires Asset located in: Humble, TX Diesel Exhaust Fluid, 23467 Engine hrs, Eaton 974 2013 Volvo VNL 6x4 T/A Sleeper Truck Tractor Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 S/N: 4V4NC9TG1DN135981 C/W: Cummins ISX15 400ST 6 Cylinder 15 L Axle Ratio, 52000 kg GVWR, 58 in High Rise Sleeper Cab, 275/80R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Diesel 400 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb Usage: 566,759 Mi GVWR, Air Ride Cab, 77 in High Rise Sleeper Asset located in: Humble, TX Cab, Bunk Beds, Aluminum Outer Wheels, 295 /75R22.5, Air Ride Suspension, 216 in 972 2012 Freightliner Cascadia 125 6x4 T/A Wheelbase, Air Sliding 5th Wheel, Dual Fuel **Sleeper Truck Tractor** Tanks S/N: 1FUJGLDR9CSBU1938 Usage: 877,295 Mi C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Notes: THIS UNIT RUNS BUT MAY HAVE hp Engine, 27153 Engine hrs, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, **DEFICIENCIES IN ITS POLLUTION CONTROL** SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 12000 lb Front Axle, 40000 lb Rears, Meritor Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY 224 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** EQUIPPED. BUYER OF THIS UNIT MUST SIGN

ACKNOWLEDGEMENT FORM OF THIS NOTICE

PRIOR TO REMOVAL OF UNIT FROM YARD

Asset located in: Humble, TX

Usage: 856,871 Mi

Notes: LOCATED-IN-FORT-WORTH-TX

Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
976	2018 International LT625 6x4 T/A Sleeper Truck Tractor	980	2018 International LT625 6x4 T/A Sleeper Truck Tractor
	S/N: 3HSDZAPR3JN424032 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 56 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 415,632 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW		S/N: 3HSDZAPR2JN530990 C/W: Cummins X15 450SA 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 22612 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Wheels, 295/75R22.5, International IROS Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: 644,374 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	081	2018 International LT625 6x4 T/A Sleeper
977	2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR4JN524544 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Front Wheels, 295 /75R22.5 Front Tires, 275/80R22.5 Rear Tires, Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 433,846 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	981	Truck Tractor S/N: 3HSDZAPRXJN248578 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 19058 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 220 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 595,641 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Lake Worth, TX	982	2018 International LT625 T/A Sleeper Truck
978	2018 International LT625 T/A Sleeper Truck Tractor S/N: 3HSDZAPR7JN552421 Usage: 529,640 Mi Notes: ; SELLER MAINTENANCE RECORD	982	Tractor S/N: 3HSDZAPR7JN205056 C/W: Cummins Engine Usage: Not Available Asset located in: Humble, TX
	ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	983	2017 International Prostar+ 122 6x4 T/A
	Asset located in: Humble, TX		Sleeper Truck Tractor
979	2018 International LT625 6x4 T/A Sleeper Truck Tractor S/N: 3HSDZAPR3JN532408 C/W: Cummins X15 6 Cylinder 15.0 L Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 633,963 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3HSDJSNR4HN447796 C/W: Navistar A450MT 6 Cylinder 12.4 L Ultra Low Sulfur Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 16541 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Bunk Heater, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 428,511 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
984	2017 International Prostar+ 122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSNR5HN447757 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 16112 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, International IROS Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 478,931 Mi Asset located in: Humble, TX 2017 International ProStar 6x4 T/A Sleeper	989	2014 International ProStar+122 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPR7EN796955 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 17185 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 51 in Mid Roof Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 658,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Truck Tractor		Asset located in: Humble, TX
986	S/N: 3HSDJAPR9HN652182 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 19739 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Automated Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52350 lb GVWR, 73 in High Rise Sleeper Cab, Bunk Heater, Aluminum Wheels, 295/75R22.5, International IROS Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 766,372 Mi Asset located in: Humble, TX	990A	2012 International Prostar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR1CN094075 C/W: 6 Cylinder Diesel Engine, 27815 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5, Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Lowboy Ramps, Dual Fuel Tanks Usage: 798,884 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
900	2016 International ProStar T/A Sleeper Truck Tractor		Asset located in: Humble, TX
987	S/N: 3HSDJAPROGN004213 Usage: Not Available Asset located in: Humble, TX 2016 International Prostar+113 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJAPRXGN002713 C/W: Cummins ISX15 6 Cylinder 15 L Ultra Low Sulfur Diesel 400 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Front Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 229 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	990	2013 International ProStar 6x4 T/A Sleeper Truck Tractor S/N: 3HSDJSJR0DN273354 C/W: 12832 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 56 in High Rise Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 408,972 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2008 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X88D750381 C/W: Cummins ISX 6 Cylinder 15 L Diesel 400 hp Engine, 2005 US EPA Label, 33217 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 250 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 224,527 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
992	2008 Peterbilt 388 6x4 T/A Sleeper Truck Tractor S/N: 1XPWD40X88D750378 C/W: Cummins ISX15 6 Cylinder 15 L Diesel 500 hp Engine, 2007 US EPA Label, CARB Compliant, 3762 Engine hrs, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 14320 lb Front Axle, 46000 lb Rears, 60320 lb GVWR, Air Ride Cab, 44 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Air Trac Air Ride Suspension, 251 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 320,021 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	996	2000 Freightliner FLD 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUPC7WB1YLA88571 C/W: Cummins Signature Series 600 6 Cylinder 15.0 L Diesel 600 hp Engine, 1999 US EPA Label, Engine Brake, Eaton Fuller 18-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Aluminum Wheels, 11R24.5, Airliner Air Ride Suspension, 267 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 807,468 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
993	2009 Kenworth T800 6x4 T/A Sleeper Truck Tractor S/N: 1XKDDU9X49J256621 C/W: Cat C13 6 Cylinder Diesel Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller	998	2005 International 9400i T/A Sleeper Truck Tractor S/N: 3HSCNAPR95N002019 Usage: Not Available Asset located in: Humble, TX
	FR014210C Manual Transmission, Differential Lock, 12000 lb Front Axle, 44000 lb Rears, Meritor RT-40-145 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 38 in Flat Top Sleeper Cab, Aluminum Front Wheels, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 198 in Wheelbase, PTO, Headache Rack, Dual Fuel Tanks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	999	2005 International 9400i 6x4 T/A Sleeper Truck Tractor S/N: 2HSCNSBR55C033430 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 248 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 680,708 Mi
994	2008 Kenworth T800 6x4 T/A Sleeper Truck Tractor		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1XKDDU9X38J217145 C/W: Cat 6 Cylinder Diesel Engine, 22732.0 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Air Ride Cab, 28 in Flat Top Sleeper Cab, 275/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 204 in Wheelbase, PTO, Wet Kit, Headache Rack Usage: 298,453 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1000	2001 Peterbilt 379 6x4 T/A Sleeper Truck Tractor S/N: 1XP5DR9X61D538905 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 8017 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 36000 lb Rears, 48000 lb GVWR, Air Ride Cab, 63 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R24.5, Low Air Leaf Air Ride Suspension, 246 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 142,551 Mi
995	1999 Kenworth W900 6x4 T/A Sleeper Truck	-	Notes: DEFICIENCIES NOTED - PLEASE SEE
-	Tractor		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1XKWDR9XXXR815058 C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel Engine, Eaton Fuller 13-Speed Manual Transmission, Air Ride Cab, 72 in High Rise Sleeper Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 260 in Wheelbase, Headache Rack, Dual Fuel Tanks Usage: 945,634 Mi Asset located in: Humble, TX		2001 Peterbilt 379 T/A Sleeper Truck Tractor S/N: 1XP5DR9X01D550841 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1002A	1995 Freightliner FLD 120 T/A Sleeper Truck Tractor S/N: 1FUPDZYB7SH718722 C/W: Detroit 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 58 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R24.5, Air Ride Suspension, 246 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 687,717 Mi Asset located in: Humble, TX 1997 Peterbilt 378 6x4 T/A Sleeper Truck	1007	2009 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor S/N: 1FUJGLDR39LAK1703 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2008 US EPA Label, 25234 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 45400 lb Rears, 3.58:1 Axle Ratio, 57400 lb GVWR, Air Ride Cab 58 in Mid Roof Sleeper Cab, Bunk Heater, Thermo King TriPac Auxiliary Power Unit, Aluminum Wheels, 11R24.5 Front Tires, 285 /75R24.5 Rear Tires, Airliner Air Ride Suspension, 240 in Wheelbase, PTO, Air Sliding
1002	Tractor S/N: 1XPFDR8X6VN422657 C/W: 6 Cylinder Diesel Engine, Eaton Fuller 10-		5th Wheel, Dual Fuel Tanks Usage: 193,151 Mi Notes: WAS PREVIOUSLY SALVAGED BEFORE Asset located in: Humble, TX
	Speed Manual Transmission, 12000 lb Front Axle, 34000 lb Rears, 46000 lb GVWR, Air Ride Cab, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 232 in Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,396,556 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1008	2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CV89DAG6935 C/W: Mercedes-Benz 6 Cylinder Engine, 3767 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride
1004			Suspension, 225 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 468,087 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1009	2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CV29DAG6929 C/W: Mercedes Benz 6 Cylinder 12.8 L Diesel 450 hp Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 34 in Flat
1005	2005 Kenworth T600 T/A Sleeper Truck Tractor S/N: 1XKADB9XX5J085441 Usage: Not Available Asset located in: Humble, TX		Top Sleeper Cab, Aluminum Outer Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 538,849 Mi Asset located in: Humble, TX
1006	2000 Kenworth T2000 6x4 T/A Sleeper Truck Tractor S/N: 1XKTD69X2YJ839226 C/W: 6 Cylinder Diesel Engine, 4778 Engine hrs, 10-Speed Manual Transmission, 62 in Mid Roof Sleeper Cab, Bunk Beds, Aluminum Outer Wheels, 11R22.5, 8-Bag Air Ride Suspension, 233 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 407,466 Mi Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE AND SOLD WITH A BONDED TITLE. Asset located in: Humble, TX	1010	2009 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CV49DAG6933 C/W: Mercedes Benz 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, 2008 US EPA Label, 28415 Engine hrs, Engine Brake, 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 34 in Flat Top Sleeper Cab, 295/75R22.5, Airliner Air Ride Suspension, 222 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 688,850 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1011	2007 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK37LY88939 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel 455 hp Engine, 33617.5 Engine hrs, Engine Brake, Eaton Fuller FM—15D_10B-LST Automated Transmission, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5 Front Tires, 12R22.5 Rear Tires, Airliner Air Ride Suspension, 240 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 845,685 Mi Asset located in: Humble, TX	1015	2007 Freightliner CST120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJBBCK57PU33895 C/W: Detroit Series 60 14.0 L Diesel Engine, 2006 US EPA Label, 39949 Engine hrs, Engine Brake, Eaton Fuller 9-Speed Manual Transmission, 60 in High Rise Sleeper Cab, Aluminum Front Wheels, 295/75R22.5, Airliner Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,430,680 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
1012	2007 Freightliner Columbia 120 T/A Sleeper Truck Tractor S/N: 1FUJA6CK17LX78021 Usage: Not Available Asset located in: Humble, TX	1016	2009 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9EJX9N269596 C/W: Volvo D13F485 6 Cylinder 12.8 L Diesel 485 hp Engine, 2008 US EPA Label, Engine Brake, Volvo ATO2512C 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor RT-40-145 Drive Axles, 3.21:1	
1013	2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CK46LV45166 C/W: Detroit Series 60 6 Cylinder Ultra Low Sulfur Diesel Engine, 1166 Engine hrs, Meritor 10-Speed Manual Transmission, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Auxiliary Power Unit, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 287 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,525,547 Mi		Axle Ratio, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 818,186 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Volvo VNL 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9GH07N452013	
1014	Asset located in: Humble, TX 2006 Freightliner Columbia 120 6x4 T/A Sleeper Truck Tractor S/N: 1FUJA6CVX6DW53148 C/W: Mercedes Benz 6 Cylinder Diesel 450 hp Engine, 2005 US EPA Label, Engine Brake, Eaton Fuller 13-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 48 in Flat Top Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 215 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 958,555 Mi		C/W: Volvo 6 Cylinder 12.1 L Ultra Diesel 465 hp Engine, 2006 US EPA Exhaust Brake, Automatic Transm 12350 lb Front Axle, 38000 lb Rear GVWR, Air Ride Cab, 70 in High Ris Cab, Bunk Beds, Aluminum Wheels 5, Air Ride Suspension, 243 in Whe Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,310,650 Mi Notes: LOCATED-IN-FORT-WORTH	C/W: Volvo 6 Cylinder 12.1 L Ultra Low Sulfur Diesel 465 hp Engine, 2006 US EPA Label, Exhaust Brake, Automatic Transmission, 12350 lb Front Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. 5, Air Ride Suspension, 243 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,310,650 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1015A	Asset located in: Humble, TX 2007 Freightliner Century Class CST120 T/A Sleeper Truck Tractor S/N: 1FUJBBAV37LX21774 C/W: Cat C15 6 Cylinder Diesel Engine, 18993 Engine hrs, Engine Brake, Eaton Fuller Manual Transmission, Air Ride Cab, 60 in Mid Roof Sleeper Cab, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 240 in Wheelbase, Dual Fuel Tanks Usage: Not Available Asset located in: Humble, TX		2007 Volvo VNL670 6x4 T/A Sleeper Truck Tractor S/N: 4V4NC9TGX7N429657 C/W: Cummins 6 Cylinder 15 L 400 hp Engine, Engine Brake, Eaton Fuller RTO-16210B 10- Speed Manual Transmission, 12350 lb Front	
			Axle, 38000 lb Rears, 50350 lb GVWR, Air Ride Cab, 61 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Volvo Corporate Air Air Ride Suspension, 212 in Wheelbase, Dual Fuel Tanks Usage: 762,801 Mi Notes: LOCATED-IN-MIDLAND-TX . Asset located in: Midland, TX	

Lot #	Details	Lot #	Details
1020	2019 Freightliner Cascadia 126 4x2 S/A Day Cab Truck Tractor S/N: 3AKBHKDV1KSKE0316	1026	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor S/N: 4V4W19EG9KN901847
	C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15921 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.08:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride		C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 152 in
	Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 636,988 Mi		Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 784,694 Mi
	Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION		Notes: LOCATED-IN-LIVINGSTON_LA_TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	BELOW SUPPLIED Asset located in: Humble, TX		Asset located in: Livingston, LA
1021	2019 Freightliner Cascadia 126 4x2 S/A Day	1027	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor
	Cab Truck Tractor S/N: 3AKBHKDVXKSKE0279 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 15388 Engine hrs, Engine Brake, Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Detroit DA-RS-23.0-6 Drive Axles, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks		S/N: 4V4W19EG7KN901975 C/W: Volvo D13M 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 19516 Engine hrs, Engine Brake, Volvo AT2612F 12-Speed Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5, Volvo Air Ride Suspension, 152 in Wheelbase, Dual Fuel Tanks Usage: 809,812 Mi
	Usage: 733,234 Mi Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	BELOW SUPPLIED	1000	Asset located in: Humble, TX
1022	Asset located in: Humble, TX 2019 Freightliner Cascadia 116 4x2 S/A Day	1028	2019 Volvo VNR300 4x2 S/A Day Cab Truck Tractor
1022	Cab Truck Tractor S/N: 3AKBHSDV8KSKT8745 C/W: 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 15801 Engine hrs, Retarder, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel Usage: 725,415 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE		S/N: 4V4W19EG8KN901998 C/W: Volvo D13M-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F Automated Transmission, Differential Lock, 12000 lb Front Axle, 20000 lb Rears, Meritor RS23-160/161 Drive Axles, 32000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 152 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel
			Tanks Usage: 801,565 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE
	DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION		THE INSPECTION REPORT Asset located in: Humble, TX
	REPORT Asset located in: Humble, TX	1029	2019 Volvo VNR300 4x2 S/A Day Cab Truck
1023	2023 Volvo VNR300 S/A Day Cab Truck Tractor S/N: 4V4W19EG7PN616829 Usage: 68,000 Mi Asset located in: Humble, TX		Tractor S/N: 4V4W19EG2KN901933 C/W: Volvo D13M 6 Cylinder 12.8 L Diesel 405 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 16928 Engine hrs, Volvo
1024	2022 Volvo VNR300 S/A Day Cab Truck Tractor S/N: 4VAW19EGXNN285791 Usage: 150,000 Mi Asset located in: Humble, TX	12000 lb Front Axle, 20000 lb Rears GVWR, 275/80R22.5 Front Tires, 29 Rear Tires, Air Ride Suspension, 15 Wheelbase, Dual Fuel Tanks Usage: 718,615 Mi	
1025	2022 Volvo VNR300 S/A Day Cab Truck Tractor S/N: 4V4W19EHXNN286271		Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: 200,000 Mi Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1031	2013 Peterbilt 337 4x2 S/A Day Cab Truck Tractor S/N: 2XP2AN8X3DM195099 C/W: Paccar PX-8 6 Cylinder 8.3 L Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 12944.8 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Dana S23-170 Drive Axles, 5.25: 1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Trac Air Ride Suspension, 155 in Wheelbase Usage: 387,456 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1037	2018 Freightliner Cascadia 126 4x2 S/A Day Cab Truck Tractor S/N: 3AKBHLDV4JSJZ6353 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Detroit DT12-1450-DH1-8 HD 12- Speed Automated Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS-23-161 Drive Axles, 2.50:1 Axle Ratio, 35000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 518,001 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Tractor S/N: 1XKZAP8X9FJ457590		Asset located in: Humble, TX
1034	C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller F016E310C LAS 10-Speed Automatic Transmission, 12000 lb Front Axle, 22700 lb Rears, Paccar S23-170 Drive Axles, 3.21:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 154 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 611,352 Mi Asset located in: Humble, TX 2013 Kenworth T660 S/A Day Cab Truck	1039	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 3AKBGDDVXFSGB5613 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15260.2 Engine hrs, Engine Brake, Eaton Fuller FO-14E313A-MHP 13- Speed Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 323,473 Mi
1034	Tractor		Notes: DEFICIENCIES NOTED - PLEASE SEE
	S/N: 1XKAA48X1DJ354916		THE INSPECTION REPORT
	Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX
1005	·	1040	2015 Freightliner Cascadia 125 4x2 S/A Day
1035	2015 Kenworth T370 S/A Day Cab Truck Tractor S/N: 2NKHHJ7XXFM440189 Usage: Not Available Asset located in: Humble, TX		Cab Truck Tractor S/N: 1FUBGDD5XFLGB0116 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 4 hp Engine, 2014 US EPA Label, Requires Dies Exhaust Fluid, 21899 Engine hrs, Engine Brak Eaton Fuller 10-Speed Manual Transmission
1036	2011 Kenworth T370 4x2 S/A Day Cab Truck Tractor S/N: 2XKHAM8A4BM286773		Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 103,560 Mi
	C/W: Paccar PX-6 280 6 Cylinder 6.7 L Diesel 280 hp Engine, 2010 US EPA Label, Requires		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Diesel Exhaust Fluid, 6967 Engine hrs, Engine		Asset located in: Humble, TX
	Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air	1041	2015 Freightliner Cascadia 125 4x2 S/A Day
	Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 153 in Wheelbase Usage: 173,734 Mi Asset located in: Humble, TX		Cab Truck Tractor S/N: 1FUBGDD57FLGB0168 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21997 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 110,105 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
			THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1042	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0107 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21506 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 kg Rears, Meritor RS23 Drive Axles, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 187,415 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1046	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGB0220 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15922 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, 3.42:1 Axle Ratio, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 777,139 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
1043	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0312 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18454.5 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RA-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 250,355 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Cab Truck Tractor S/N: 1FUBGDD5XFLGB0097 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 2007 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 781,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	1048	2015 Freightliner Cascadia 125 4x2 S/A Day
1044	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57FLGJ1292 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 604,997 Mi Asset located in: Humble, TX		Cab Truck Tractor S/N: 1FUBGDD53FLGB0152 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19047.5 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 837,506 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1045	2015 Freightliner Cascadia 125 4x2 S/A Day		THE INSPECTION REPORT Asset located in: Humble, TX
	Cab Truck Tractor S/N: 1FUBGDD59FLGB0317 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14310 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 669,581 Mi Asset located in: Humble, TX	1049	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGB0122 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1348 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 842,477 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Freightliner Cascadia 125 4x2 S/A Day ruck Tractor FUBGDD54FLGB0001 Detroit DD15 6 Cylinder 14.8 L Diesel 505 gine, 2014 US EPA Label, Requires Diesel st Fluid, 17962.1 Engine hrs, Engine Eaton Fuller FRO-15210C 10-Speed al Transmission, 12000 lb Front Axle, lb Rears, Meritor RS23-186 Drive Axles, Axle Ratio, 33000 lb GVWR, Air Ride Cab, .5, Airliner Air Ride Suspension, 158 in base, Dual Fuel Tanks: 851,140 Millocated in: Humble, TX Freightliner Cascadia 125 4x2 S/A Day ruck Tractor FUBGDD55FLGB0413 Detroit DD15 6 Cylinder 14.8 L Diesel 455 gine, 2014 US EPA Label, Requires Diesel st Fluid, 17637 Engine hrs, Engine Brake, Fuller 10-Speed Manual Transmission, lb Front Axle, 21000 lb Rears, 3.42:1 atio, 33000 lb GVWR, Air Ride Cab, .5, Airliner Air Ride Suspension, 158 in base, Dual Fuel Tanks: 853,270 Mi DEFICIENCIES NOTED - PLEASE SEE	1054 1055	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0050 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18243 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 859,499 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0201 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19095 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor
FUBGDD54FLGB0001 Detroit DD15 6 Cylinder 14.8 L Diesel 505 Igine, 2014 US EPA Label, Requires Diesel St Fluid, 17962.1 Engine hrs, Engine Eaton Fuller FRO-15210C 10-Speed In Transmission, 12000 lb Front Axle, Ib Rears, Meritor RS23-186 Drive Axles, Axle Ratio, 33000 lb GVWR, Air Ride Cab, Is, Airliner Air Ride Suspension, 158 in Diase, Dual Fuel Tanks Interest Both Interest Bot		Cab Truck Tractor S/N: 1FUBGDD56FLGB0050 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18243 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 859,499 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD51FLGB0201 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19095 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission,
Detroit DD15 6 Cylinder 14.8 L Diesel 455 pine, 2014 US EPA Label, Requires Diesel st Fluid, 17637 Engine hrs, Engine Brake, Fuller 10-Speed Manual Transmission, lb Front Axle, 21000 lb Rears, 3.42:1 atio, 33000 lb GVWR, Air Ride Cab, .5, Airliner Air Ride Suspension, 158 in base, Dual Fuel Tanks: 853,270 Mi DEFICIENCIES NOTED - PLEASE SEE	1055	Cab Truck Tractor S/N: 1FUBGDD51FLGB0201 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19095 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission,
ISPECTION REPORT located in: Humble, TX	1055	RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,507 Mi Asset located in : Humble, TX
Freightliner Cascadia 125 4x2 S/A Day	1056	2015 Freightliner Cascadia 125 4x2 S/A Day
FUBGDD59FLGB0172 Detroit DD15 6 Cylinder 14.8 L Ultra Low Diesel 455 hp Engine, 2014 US EPA Requires Diesel Exhaust Fluid, 18572 hrs, Engine Brake, Eaton Fuller 10-Manual Transmission, 33000 lb GVWR, .5, Airliner Air Ride Suspension, 158 in base, Dual Fuel Tanks: 853,329 Mi DEFICIENCIES NOTED - PLEASE SEE ISPECTION REPORT		Cab Truck Tractor S/N: 1FUBGDD54FLGJ1265 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 872,990 Mi
located in: Humble, TX	1057	Asset located in: Humble, TX
Freightliner Cascadia 125 4x2 S/A Day Fuck Tractor FUBGDD55FLGJ1307 Detroit DD15 6 Cylinder 14.8 L Ultra Low Diesel 455 hp Engine, 2014 US EPA Requires Diesel Exhaust Fluid, 19322 eths, Engine Brake, Eaton Fuller FROC 10-Speed Manual Transmission, Ib Front Axle, 23000 lb Rears, Meritor Drive Axles, 3.42:1 Axle Ratio, 33000 lb, Air Ride Cab, 11R22.5, Airliner Air Ride Insion, 158 in Wheelbase, Dual Fuel Tanks et 858,405 Mi DEFICIENCIES NOTED - PLEASE SEE ISPECTION REPORT	105/	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGB0191 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 873,692 Mi Asset located in: Humble, TX
FOIL CO.T. FOIL CO.T.	etroit DD15 6 Cylinder 14.8 L Ultra Low Diesel 455 hp Engine, 2014 US EPA Requires Diesel Exhaust Fluid, 18572 hrs, Engine Brake, Eaton Fuller 10-Manual Transmission, 33000 lb GVWR, 5, Airliner Air Ride Suspension, 158 in base, Dual Fuel Tanks 853,329 Mi DEFICIENCIES NOTED - PLEASE SEE SPECTION REPORT ocated in: Humble, TX reightliner Cascadia 125 4x2 S/A Day uck Tractor FUBGDD55FLGJ1307 etroit DD15 6 Cylinder 14.8 L Ultra Low Diesel 455 hp Engine, 2014 US EPA Requires Diesel Exhaust Fluid, 19322 hrs, Engine Brake, Eaton Fuller FROD 10-Speed Manual Transmission, lb Front Axle, 23000 lb Rears, Meritor Drive Axles, 3.42:1 Axle Ratio, 33000 lb Air Ride Cab, 11R22.5, Airliner Air Ride Insion, 158 in Wheelbase, Dual Fuel Tanks 858,405 Mi DEFICIENCIES NOTED - PLEASE SEE	FUBGDD59FLGB0172 etroit DD15 6 Cylinder 14.8 L Ultra Low Diesel 455 hp Engine, 2014 US EPA Requires Diesel Exhaust Fluid, 18572 hrs, Engine Brake, Eaton Fuller 10-Manual Transmission, 33000 lb GVWR, 5, Airliner Air Ride Suspension, 158 in base, Dual Fuel Tanks 853,329 Mi DEFICIENCIES NOTED - PLEASE SEE SPECTION REPORT ocated in: Humble, TX reightliner Cascadia 125 4x2 S/A Day uck Tractor FUBGDD55FLGJ1307 etroit DD15 6 Cylinder 14.8 L Ultra Low Diesel 455 hp Engine, 2014 US EPA Requires Diesel Exhaust Fluid, 19322 hrs, Engine Brake, Eaton Fuller FRO-C 10-Speed Manual Transmission, lb Front Axle, 23000 lb Rears, Meritor Prive Axles, 3.42:1 Axle Ratio, 33000 lb Air Ride Cab, 11R22.5, Airliner Air Ride Resion, 158 in Wheelbase, Dual Fuel Tanks 858,405 Mi DEFICIENCIES NOTED - PLEASE SEE SPECTION REPORT

Lot #	Details	Lot #	Details
1058	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD55FLGJ1288 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18389 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 879,780 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1062	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0096 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19168.6 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 893,840 Mi Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor
1059	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0178 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18685 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Transmission, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 881,722 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1FUBGDD54FLGJ1184 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20771 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 898,557 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1060	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGB0066 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18727 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 882,386 Mi Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day	1064	Cab Truck Tractor S/N: 1FUBGDD57FLGJ1230 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19151.7 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 905,857 Mi Notes: ODOMETER DISCREPANCY UNIT SHOWS 905,857, TITLE SHOWS 923,782
	Cab Truck Tractor S/N: 1FUBGDD54FLGB0189 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20032 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275 /80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 885,785 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1065	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD5XFLGJ1187 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 17946 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 908,401 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1066	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0402 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21951 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.47:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 911,547 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1070	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD50FLGB0190 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20077 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 948,390 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day
1067	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0162 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19314 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks		Cab Truck Tractor S/N: 1FUBGDD54FLGB0340 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 3.42: 1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 949,669 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 921,973 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1072	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD58FLGB0163 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455
1068	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGB0169 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, 18791 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks	hp Engine, 2014 Exhaust Fluid, 2 Eaton Fuller FR Transmission, 330 11R22.5 Front Axle Ratio, 330 11R22.5 Front Airliner Air Ride Dual Fuel Tank Usage: 956,335 Notes: DEFICIE THE INSPECTIO Asset located i 1073 2015 Freightlin Cab Truck Trac S/N: 1FUBGDD C/W: Detroit DE Sulfur Diesel 45 Label, Requires Engine hrs, Eng 15210C 10-Spe 12000 lb Front 23-186 Drive Ax GVWR, Air Ride Suspension, 15 Usage: 956,831 Notes: DEFICIE THE INSPECTIO	hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22040 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 956,335 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 923,856 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD59FLGJ1178 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low
1069	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD52FLGB0434 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18038 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 935,396 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 1557 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 956,831 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

1 - 2 "	PA-II-	1 "	B.A.H.
Lot #	Details	Lot #	Details
1074	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0064 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20210 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 3.42:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 959,332 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	Cab Truck Tractor S/N: 1FUBGDD54FLGB0273 C/W: Detroit DD15 6 Cylinder 14.8 L 455 Engine, Requires Diesel Exhaust Fluid, 2 Engine hrs, Engine Brake, Eaton Fuller F 15210C 10-Speed Manual Transmissior 12000 lb Front Axle, 21000 lb Rears, Me RS23-186 Drive Axles, 3.42:1 Axle Ratio, lb GVWR, Air Ride Cab, 11R22.5, Airliner Ride Suspension, 158 in Wheelbase, Dur Tanks Usage: 1,061,567 Mi	S/N: 1FUBGDD54FLGB0273 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp Engine, Requires Diesel Exhaust Fluid, 22700 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,061,567 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1075	2015 Freightliner Cascadia 125 4x2 S/A Day	1	THE INSPECTION REPORT Asset located in: Humble, TX
10/5	Cab Truck Tractor S/N: 1FUBGDD53FLGJ1242 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 19775 Engine hrs, Engine Brake, Eaton Fuller FRO-	1079	2014 Freightliner Cascadia 125 S/A Day Cab Truck Tractor S/N: 1FUBGEBG0ELFT4306 Usage: Not Available Asset located in: Humble, TX
	15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 986,983 Mi	1080	2014 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD57ELFL7290 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2013 US EPA Label, Requires Diesel
1076	2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD56FLGB0260 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18869 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 991,149 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDD53FLGJ1192 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 20429.8 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 1,007,261 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Exhaust Fluid, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 682,222 Mi Asset located in: Humble, TX
		1081	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR8DLBX1020 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 3.42:1 Axle Ratio, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 642,780 Mi
1077			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1082	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR0DLBX1187 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19292 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 713,691 Mi Asset located in: Humble, TX

			1 age 70 01 437
Lot #	Details	Lot #	Details
1083	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR2DLBX0932 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18045 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 721,588 Mi Asset located in: Humble, TX	1087	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR6DLBX0996 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18679 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 746,424 Mi Asset located in: Humble, TX
1084	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX0995 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19781 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 164 in Wheelbase, Dual Fuel Tanks Usage: 724,505 Mi Asset located in: Humble, TX	1088	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR8DLBX0952 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18814 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23 Drive Axles, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 759,762 Mi
1085	2013 Freightliner Cascadia 125 4x2 S/A Day		Asset located in: Humble, TX
	Cab Truck Tractor S/N: 1FUBGDDR1DLBX0999 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19346 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 739,978 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1089	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR5DLBU9573 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 560 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18024.3 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 762,470 Mi
1086	2013 Freightliner Cascadia 125 4x2 S/A Day		Asset located in: Humble, TX
	Cab Truck Tractor S/N: 1FUBGDDR9DLBU9575 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 27663.8 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 745,581 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1090	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR6DLBX1131 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 17213.1 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 785,839 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1091	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR4DLBX0947 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 18831 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 795,751 Mi Asset located in: Humble, TX	1095	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7DLBU9574 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 17420.3 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 275/80R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 1,015,310 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1092	2013 Freightliner Cascadia 125 4x2 S/A Day		THE INSPECTION REPORT Asset located in: Humble, TX
	Cab Truck Tractor S/N: 1FLUBGDDR9DLBX1074 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 22139 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 818,005 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1096	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR3DLBX1068 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 19122 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 925,930 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1093	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor	1007	Asset located in: Humble, TX
	S/N: 1FUBGDDR4DLBX1001 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 21299 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS- 23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 275/80R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks	1097	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBU7060 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20334 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 907,140 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: 864,678 Mi Asset located in : Humble, TX		THE INSPECTION REPORT
1094	2013 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDRXDLBU6992 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20205 Engine hrs, Engine Brake, Eaton Fuller FRO- 15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295 /75R22.5 Rear Tires, Airliner Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 947,488 Mi Asset located in: Humble, TX	1098	Asset located in: Humble, TX 2012 Freightliner Cascadia 125 4x2 S/A Day Cab Truck Tractor S/N: 1FUBGDDR7CLBF2999 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18070.1 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Meritor RS-23-186 Drive Axles, 3.42:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 166 in Wheelbase, Dual Fuel Tanks Usage: 570,711 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details Lot# **Details** Lot # 1099 2017 Freightliner Cascadia 113 4x2 S/A Day 1102C 2014 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4M19EH1EN177088 C/W: Volvo D13H425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2013 US EPA Label, Requires **Cab Truck Tractor** S/N: 3AKBGADV1HSHX5191 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 hp Engine, 2016 US EPA Label, CARB Diesel Exhaust Fluid, Volvo ATO2612D Automated Transmission, 12350 lb Front Axle, Compliant, Requires Diesel Exhaust Fluid, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Air Ride 12599.8 Engine hrs, Engine Brake, Detroit Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 854,779 Mi Notes: TITLE COMES WITH AFFIDAVIT Suspension, 160 in Wheelbase, Dual Fuel CORRECTION Tanks, Gooseneck Ball Hitch Asset located in: Humble, TX Usage: 161,096 Mi 1102B 2014 Volvo VNL 4x2 S/A Day Cab Truck Tractor Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT S/N: 4V4M19EH9EN154061 C/W: Volvo D13H425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2013 US ÉPA Label, Requires Asset located in: Midland, TX Diesel Exhaust Fluid, 25603.7 Engine hrs, Engine Brake, ZF 12-Speed Automated Transmission, 12350 lb Front Axle, 20000 lb 1100 2015 Freightliner M2112 4x2 S/A Day Cab **Truck Tractor** Rears, Meritor RS23-160 Drive Axles, 32350 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride S/N: 3AKBC4CY4FDGK4422 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 370 Suspension, 156 in Wheelbase, Dual Fuel Tanks hp Engine, Requires Diesel Exhaust Fluid, Usage: 900,627 Mi 10632 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 4.30:1 Axle Ratio, 33000 lb Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT TITLE COMES WITH STATEMENT OF AFFIDAVIT GVWR, Air Ride Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 155 in Asset located in: Humble, TX Wheelbase, Dual Fuel Tanks 2015 Volvo VNL 4x2 S/A Day Cab Truck Tractor Usage: 362,827 Mi S/N: 4V4M19EH4FN184666 Notes: DEFICIENCIES NOTED - PLEASE SEE C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 425 hp Engine, 2014 US EPA Label, Requires THE INSPECTION REPORT Asset located in: Humble, TX Diesel Exhaust Fluid, 15123 Engine hrs, Engine Brake, Volvo ATO2612D Automated 1101 2014 Freightliner M2 112 4x2 S/A Day Cab Transmission, 12350 lb Front Axle, 20000 lb **Truck Tractor** Rears, Meritor RS23-160/161 Drive Axles S/N: 1FUBC4DV1EHFX8691 32350 lb GVWR, Air Ride Cab, 295/75R22.5, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 Volvo Air Ride Suspension, 156 in Wheelbase, hp Engine, 2013 US EPA Label, Requires Diesel **Dual Fuel Tanks** Exhaust Fluid, 20329 Engine hrs, Automated Usage: 579,823 Mi Transmission, 12000 lb Front Axle, 20000 lb Notes: TITLE COMES WITH A CORRECTION OF Rears, 2.67:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride **AFFIDAVIT** Suspension, 161 in Wheelbase, Dual Fuel Tanks Asset located in: Humble, TX Usage: 333,910 Mi 1102 2011 Freightliner M2106 4x2 S/A Day Cab Asset located in: Humble, TX **Truck Tractor** 1102D 2015 Volvo VNM 4x2 S/A Sleeper Truck Tractor S/N: 1FUBCYDT0BDAW9880 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 280 S/N: 4V4M19EH2FN184651 hp Engine, Requires Diesel Exhaust Fluid, C/W: Volvo D13J425 6 Cylinder 12.8 L Diesel 10583 Engine hrs, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 5.63:1 Axle Ratio, 34700 lb GVWR, Air 425 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 21415 Engine hrs, Automated Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, Ride Cab, Aluminum Outer Wheels, 295/75R22. 5 Front Tires, 275/80R22.5 Rear Tires, Airliner 275/80R22.5, Air Ride Suspension, 157 in Air Ride Suspension, 158 in Wheelbase Wheelbase, Dual Fuel Tanks Usage: 146,582 Mi Usage: 718,832 Mi

Asset located in: Humble, TX

Notes: TITLE COMES WITH STATEMENT OF FACTS CORRECTING THE TITLE

Lot #	Details	Lot #	Details
1103	2012 Volvo VNL300 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG6CN560842 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 32350 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 157 in Wheelbase, Dual Fuel Tanks Usage: 311,531 Mi Asset located in: Humble, TX	1109	2009 Sterling A9500 4x2 S/A Day Cab Truck Tractor S/N: 2FWBA2CK69AAJ3273 C/W: Detroit Series 60 6 Cylinder Diesel Engine, 19717 Engine hrs, Engine Brake, 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 160 in Wheelbase Usage: 428,446 Mi Asset located in: Humble, TX
1104	2012 Volvo VNL 4x2 S/A Day Cab Truck Tractor S/N: 4V4N19EG8CN560938 C/W: Volvo D13H405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 18486 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 20000 lb Rears, 32350 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 158 in Wheelbase, Dual Fuel Tanks Usage: 491,264 Mi Asset located in: Humble, TX	<u>_</u> 1110	2019 Freightliner Cascadia 125 4x2 S/A Sleeper Truck Tractor S/N: 3AKBGLFG8KSKU3824 C/W: Cummins X15 6 Cylinder 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Freightliner SmartShift Automated Transmission, 13300 lb Front Axle, 21000 lb Rears, 2.50:1 Axle Ratio, 34300 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, 295 /75R22.5, Airliner Air Ride Suspension, 222 in Wheelbase, Dual Fuel Tanks Usage: 851,098 Mi
1105	2010 International Durastar 4400 4x2 S/A Day Cab Truck Tractor		Notes: LOCATED-IN-LAKE WORTH-TX Asset located in: Lake Worth, TX
1107	S/N: 1HSMKAAN4AH236673 C/W: International Maxxforce 6 Cylinder 7.6 L Diesel 285 hp Engine, 2009 US EPA Label, 8236 Engine hrs, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 151 in Wheelbase Usage: 167,445 Hr Asset located in: Humble, TX 2009 Freightliner M2 106 4x2 S/A Day Cab Truck Tractor	1111	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5110PL041358 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 2401.1 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 130 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 5,068 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
	S/N: 1FUBCYBS39DAK0631 C/W: Cummins ISC 6 Cylinder Diesel 285 hp		THE INSPECTION REPORT Asset located in: Humble, TX
1108	Engine, 1250 Engine hrs, Eaton Fuller 7-Speed Manual Transmission, 12000 lb Front Axle, 22700 lb Rears, Alliance ARS-23.0-4 Drive Axles, 3.58:1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22. 5 Front Tires, 275/80R22.5 Rear Tires, Airliner Air Ride Suspension, 150 in Wheelbase Usage: 77,729 Mi Asset located in: Humble, TX 2005 International 9400i 4x2 S/A Day Cab	1112	2023 Capacity 4x2 Spotter Truck S/N: 4LMBF5114PL041363 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 2483.2 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 130 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th
1100	Truck Tractor S/N: 3HSCPSBN85N051359 C/W: Caterpillar C13 6 Cylinder 12.5 L Diesel 525 hp Engine, 2004 US EPA Label, 28255 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Air Ride Cab, 275/80R22. 5, Air Ride Suspension, 163 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 952,792 Mi Asset located in: Humble, TX		Wheel Usage: 10,506 Mi
		1113	Asset located in: Humble, TX 2021 Capacity 4x2 Spotter Truck S/N: 4LMBF5112ML029336 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 200 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 5069.7 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 130 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 11,355 Mi Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TY

			Fage 102 01 437
Lot #	Details	Lot #	Details
1115	2018 Ottawa 4x2 Spotter Truck S/N: 4LMSB2119JL031476 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 130 kW Engine, 5891 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 36000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 121 in Wheelbase Usage: 5,891 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1120	2016 Kalmar 4x2 Spotter Truck S/N: 343965 C/W: Cummins QSB6.7 6 Cylinder 6.7 L Diesel 173 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9167 Engine hrs, Allison Automatic Transmission, 11R22.5, 116 in Wheelbase, PTO, Wet Kit, Hydraulic Lift 5th Wheel Usage: 15,929 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
1116	2017 Ottawa T2 4x2 Spotter Truck S/N: 343967		Asset located in: Humble, TX
1117	Usage: 22,767 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX 2016 Ottawa T2 Spotter Truck	1121	2006 Ottawa Commando 30 4x2 Spotter Truck S/N: 313811 C/W: Cummins 6 Cylinder Diesel Engine, 2005 US EPA Label, 12577 Engine hrs, Allison Automatic Transmission, 295/75R22.5, 110 in Wheelbase, Hydraulic Lift 5th Wheel
1117	S/N: 11VJ813E3GA000806 Usage: 37,104 Mi		Usage: 12,577 Hr Asset located in : Humble, TX
	Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX		2004 Kalmar Industries Spotter Truck S/N: 308637 C/W: CAT Acert 6 Cylinder Diesel Engine, 22269 Engine hrs, Allison Automatic
1118	2017 Capacity 4x2 Spotter Truck S/N: 4LMSB2116HL031400 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 23834 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 30000 lb Rears, 295/75R22.5, 116 in Wheelbase, Hydraulic Lift 5th Wheel, EQUIPMENT-FROM-THE-PROFESSIONALLY-		Transmission, 12000 lb Front Axle, 24000 lb Rears, 36000.0 lb GVWR, 295/75R22.5, 116 in Wheelbase, Hydraulic Lift 5th Wheel Usage: 89,797 Mi Notes: LOCATED-IN-FORT-WORTH-TX; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Lake Worth, TX
	MAINTAINED-WALMART-FLEET Usage: 120,139 Mi	1123	2019 Peterbilt 567 12x4 Five Axle Dump Truck
	Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX		S/N: 1NPCLPEX9KD608543 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 455 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 6848 Engine hrs, Engine Brake, Eaton Fuller 8LL
1119	2017 Kalmar 4x2 Spotter Truck S/N: 11VJ813A7HA000175 C/W: Cummins ISB6.7 200 6 Cylinder 6.7 L Diesel 200 hp Engine, 2016 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 18306 Engine hrs, Allison Automatic Transmission, Differential Lock, 12000 lb Front Axle, 24000 lb Rears, 36000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, 118 in Wheelbase, PTO, Hydraulic Lift 5th Wheel Usage: 35,573 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Manual Transmission, 20000 lb Front Axle, 69996 lb Rears, 80000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 315/80R22.5 Front Tires, 295/80R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 282 in Wheelbase, PTO, 17 ft Long x 5 ft 5 in High Steel Body, Electric Roll Tarp, High-Lift Tailgate, Rear Hydraulics Usage: 152,092 Mi Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1124	Five Axle Dump Truck S/N: 3AKBHKDV1KSKD5150 C/W: Detroit DD13 12.8 L Diesel 525 hp Engine, 2018 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 8871 Engine hrs, Engine Brake, Detroit DT12-0A Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 3.42:1 Axle Ratio, 33000 lb GVWR, Aluminum Outer Wheels, 385/65R22 5 Front	1128	2017 Kenworth T880 10x4 Quad/A Dump Truck S/N: 1NKZXPTX9HJ158944 C/W: Paccar MX-13 Diesel Engine, Allison Automatic Transmission, Aluminum Wheels, 2 Steerable Air Lift Pusher Axle, Double Frame, Chalmers Rubber over Walking Beam Suspension, Electric Roll Tarp Usage: 503,515 Mi Asset located in: Humble, TX 2013 Kenworth T800 10x4 Quad/A Dump Truck
			S/N: 1XKDDP9X6DJ346539 C/W: Paccar 6 Cylinder Ultra Low Sulfur Diesel 455 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20195 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13200 lb Front Axle, 53200 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Double Frame, Paccar Air Ride
1125			Suspension, 246 in Wheelbase, PTO, 18 ft Long x 5 ft High Steel Body, Electric Roll Tarp Usage: 460,469 Mi
	S/N: 1XPFDT9X27D666651 C/W: Cat 6 Cylinder 11 1 L Diesel 385 hp		Asset located in: Humble, TX
	C/W: Cat 6 Cylinder 11.1 L Diesel 385 hp Engine, 2006 US EPA Label, 18114 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Air Trac Air Ride Suspension, 260 in Wheelbase, 18 ft 6 in Long x 5 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 283,202 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1130	2016 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 1FVSG5CY2GHGY9545 C/W: Cummins 6 Cylinder Diesel 370 hp Engine, Requires Diesel Exhaust Fluid, 19622 Engine hrs, Allison Automatic Transmission, Double Differential Locks, 18000 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 73000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385 /65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Air Lift Pusher Axles, TufTrac Spring Suspension, 224 in Wheelbase, OX Bodies 18 ft 5 in Long x 4 ft 8 in High Steel Body, Round Bottom
1126	2006 Peterbilt 567 14x4 Super 18 Five Axle		Usage: 469,348 Mi Asset located in : Humble, TX
1127	Dump Truck S/N: 1XPFDT9X86D644734 C/W: Diesel Engine, Engine Brake, 8LL Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 3 Steerable Air Lift Pusher Axle, Trailing Tag Axle, Air Trac Air Ride Suspension, 260 in Wheelbase, PTO, Strong 18 ft 6 in Long x 5 ft High Steel Body, Electric Roll Tarp Usage: 187,657 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Kenworth T880 10x4 Quad/A Dump Truck S/N: 1NKZXPTX6HJ158948 C/W: Paccar MX-13 Diesel Engine, Allison Automatic Transmission, Aluminum Wheels, 2 Steerable Air Lift Pusher Axle, Double Frame, Chalmers Rubber over Walking Beam Suspension, Electric Roll Tarp Usage: 503,176 Mi Asset located in: Humble, TX	1131	2016 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 1FVSG5CY4GHGY9546 C/W: Cummins ISL9 8.9 L Diesel 310 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 23070.9 Engine hrs, Allison Automatic Transmission, 18000 lb Front Axle, 55000 lb Rears, 73000 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Rubber over Walking Beam Suspension, 228 in Wheelbase, OX Bodies 18 ft Long x 4 ft 4 in High Steel Body, Round Bottom Usage: 646,213 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1132	Truck S/N: 3ALSG5CYXFDGK4978 C/W: Cummins ISL 6 Cylinder 8.9 L Diesel 380 hp Engine, 2014 US EPA Label, 209172 Engine hrs, Eaton Fuller RTO-14908LL 8LL Manual Transmission, 18000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 4.63:1 Axle Ratio, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Air Lift Pusher Axles, Air Lift Tag Axle, Spring Suspension, 224 in Wheelbase, PTO, OX Bodies 18 ft Long x 4 ft 5 in High Steel Body, Round Bottom, Electric Roll Tarp, Swing Tailgate Usage: 596,159 Mi	1135 1136B	2022 Peterbilt 579 8x4 Tri/A Dump Truck S/N: 1XPBAP8X1ND759271 C/W: Paccar 6 Cylinder Diesel Engine, 2021 US EPA Label, 5122.4 Engine hrs, Paccar 12-Speed Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Air Trac Air Ride Suspension, 258 in Wheelbase, 16 ft Long x 3 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 225,681 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX 2018 Kenworth T680 8x4 Tri/A Dump Truck
1133	Asset located in: Humble, TX 2015 Freightliner 108SD 10x4 Quad/A Dump Truck S/N: 3ALSG5CY8FDGK4977 C/W: Cummins ISL9 8.9 L Diesel 380 hp Engine, 10752 Engine hrs, Eaton Fuller 8LL Manual Transmission, Double Differential Locks, 18000 lb Front Axle, 56000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Steerable Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Air Ride Suspension, 228 in Wheelbase, PTO, OX Bodies 18 ft Long x 4 ft 4 in High Steel Body, Round Bottom	1136A	S/N: 1XKYAP8X4JJ209865 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 1 Engine hrs, Engine Brake, Automated Transmission, 12350 lb Front Axle, 45400 lb Rears, 35050 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Paccar Air Ride Suspension, 213 in Wheelbase, PTO, 16 ft 5 in Long x 4 ft 8 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 495,045 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Peterbilt 567 8x4 Tri/A Dump Truck
1134B	Usage: 621,809 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2000 Peterbilt 379 T/A Day Cab Truck Tractor S/N: 1XP5DR9X3YN499744	-	S/N: 1NPCXKEX7HD411323 C/W: Paccar MX11 6 Cylinder 10.8 L Diesel 430 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 20000 lb Front Axle, 59500 lb Rears, 79500 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 445/65R22.5 Front
1134	C/W: 8899 Engine hrs, Engine Brake, 10-Speed Manual Transmission, Aluminum Wheels, 11R24.5, Air Leaf Air Ride Suspension, 260 in Wheelbase, PTO Usage: 244,675 Mi Asset located in: Humble, TX 2016 Freightliner 108SD 10x4 Quad/A Dump Truck	-	Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber Suspension, 212 in Wheelbase, PTO, OX Bodies 15 ft Long x 3 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp, Pintle Hitch Usage: 242,185 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1FVSG5CYOGHGY9544 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 18200 Engine hrs, Allison Automatic Transmission, 18000 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 73000 lb GVWR, Air Ride Cab, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, 2 Air Lift Pusher Axles, TufTrac Suspension, 224 in Wheelbase, OX Bodies 18 ft 5 in Long x 4 ft 8 in High Steel Body, Round Bottom Usage: 514,329 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1136	Asset located in: Humble, TX 2017 Peterbilt 567 Tri/A Dump Truck S/N: 1XPCDP9X3HD363017 C/W: Paccar MX-13 6 Cylinder 12.9 L Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Allison Automatic Transmission, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, 16 ft 5 in Long x 4 ft 7 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 532,469 Mi

Lot #	Details	Lot #	Details
1137	2014 Mack CHU613 8x4 Tri/A Dump Truck S/N: 1M1AN07Y2EM016671 C/W: Mack MP8 12.8 L Diesel 445 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 3346 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 14320 lb Front Axle, 40000 lb Rears, 54320 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R24.5, Air Lift Pusher Axle, Air Ride Suspension, PTO, 16 ft 9 in Long x 4 ft 5 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 315,697 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1141A	2013 Kenworth T680 8x4 Tri/A Dump Truck S/N: 1XKYA58X1DJ355384 C/W: Cummins ISX15 15.0 L Diesel 400 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 20533.3 Engine hrs, Engine Brake, Eaton Fuller FM15E310B LAS 10-Speed Automatic Transmission, 12000 lb Front Axle, Dana S23-190 Drive Axles, 3.53:1 Axle Ratio, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Tag Axle, Double Frame, 8-Bag Air Ride Suspension, 228 in Wheelbase, PTO, 16 ft Long x 4 ft High Steel Body, Electric Roll Tarp Usage: 331,042 Mi Asset located in: Humble, TX
1138	· · · · · · · · · · · · · · · · · · ·	1141	2018 Kenworth T680 Tri/A Dump Truck S/N: 1XKYAPBX433214337 C/W: 16 ft Long Steel Body Usage: Not Available Asset located in: Humble, TX
1139	Transmission, 12000 lb Front Axle, 40000 lb Rears, 32000 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Volvo Corporate Air Air Ride Suspension, 16 ft 2 in Long x 3 ft 8 in High Body, Round Bottom, Electric Roll Tarp, Tailgate Chute Usage: 120,390 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX 2022 Volvo VNR 8x4 Tri/A Dump Truck	1143	2017 Freightliner Cascadia 125 8x4 Tri/A Dump Truck S/N: 3AKJGLBG2HSJA3077 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 31957 Engine hrs, Engine Brake, Eaton Fuller FOAM-15810S-EC Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.62:1 Axle Ratio, 52350 lb GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Airliner Air Ride Suspension, 233 in Wheelbase, PTO, 16 ft Long x 4 ft 8 in High Steel Body, Electric Roll Tarp Usage: 912,479 Mi Asset located in: Humble, TX
1139	S/N: 4V4W19EG0NN285766 C/W: Volvo D13N-405 6 Cylinder 12.8 L Diesel 405 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Volvo AT2612F 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 32000 lb		
	GVWR, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 224 in Wheelbase, PTO, 18 ft Long x 3 ft High Body, Round Bottom, Electric Roll Tarp, Tailgate Chute Usage: 264,306 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2014 Freightliner Cascadia 125 8x4 Tri/A Dump Truck S/N: 3AKBGEBG7ESFY3961 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 425 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM- 15E310B Automated Transmission, Meritor RS- 23-161 Drive Axles, 2.50:1 Axle Ratio, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Double Frame, Air Ride Suspension, 243 in Wheelbase, PTO, 18 ft Long x 4 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp Usage: 351,876 Mi Notes: TITLE BRAND REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1140	2022 Volvo VNR 8x4 Tri/A Dump Truck S/N: 4V4W19EG5NN285634 C/W: Volvo 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 405 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Brake, Volvo 12-Speed Automatic Transmission, 12000 lb Front Axle, 40000 lb Rears, 32000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22. 5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 224 in Wheelbase, PTO, 18 ft Long x 3 ft High Body, Round Bottom, Electric Roll Tarp, High-Lift Tailgate, Tailgate Chute Usage: 262,785 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		

Lot #	Details	Lot #	Details
1144	2007 Mack CL733 8x4 Tri/A Dump Truck S/N: 1M2AD64CX7M002918 C/W: Cummins ISX 565 6 Cylinder 15 L Diesel 565 hp Engine, 2006 US EPA Label, 29452 Engine hrs, Engine Brake, Mack Maxitorque ES 18-Speed Manual Transmission, 18740 lb Front Axle, 46000 lb Rears, 84740 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Rubber over Walking Beam Suspension, 238 in Wheelbase, Trail King 19 ft 5 in Long x 6 ft 9 in High Aluminium Body, Electric Roll Tarp Usage: 635,736 Mi Asset located in: Humble, TX	1148	2007 Sterling L9500 8x4 Tri/A Dump Truck S/N: 2FZHAZCV17AY14462 C/W: Mercedes-Benz 6 Cylinder Diesel 450 hp Engine, 2006 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 60000 lb Rears, 72000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 385/65R22. 5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Spring Suspension, 240 in Wheelbase, 16 ft 11 in Long x 5 ft 3 in High Steel Body, Electric Roll Tarp Usage: 449,746 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE
1145	2007 Mack CHN613 8x4 Tri/A Dump Truck S/N: 1M2AJ07Y17N009117 C/W: Mack 6 Cylinder Diesel Engine, 28705 Engine hrs, Mack 18-Speed Manual Transmission, 13220 lb Front Axle, 38000 lb Rears, 51220 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 385/65R22.5 Front Tires, 11R24.	1150	INSPECTION REPORT Asset located in: Livingston, LA 2014 Peterbilt 365 6x4 T/A Dump Truck S/N: 1XPSD79X2ED232393 C/W: Cummins ISX12 6 Cylinder 11.9 L Diesel 385 hp Engine, 2013 US EPA Label, Requires
	5 Rear Tires, Steerable Air Lift Pusher Axle, Camelback Suspension, 224 in Wheelbase, PTO, 16 ft Long x 5 ft High Body, Electric Roll Tarp Usage: 485,725 Mi Notes: LOCATED-IN-FORT-WORTH-TX THIS UNIT RUNS BUT MAY HAVE DEFICIENCIES IN ITS POLLUTION CONTROL SYSTEMS WITH LIABILITIES OUTLINED IN TEXAS ADMINISTRATIVE CODE SECTIONS 114.20 AND 114.50. THIS MAY APPLY IF YOU OPERATE THE UNIT PRIOR TO THE ADEQUATE RESTORATION OF ALL POLLUTION CONTROL SYSTEMS OR DEVICES AS ORIGINALLY EQUIPPED. BUYER OF THIS UNIT MUST SIGN ACKNOWLEDGEMENT FORM OF THIS NOTICE PRIOR TO REMOVAL OF UNIT FROM YARD		Diesel Exhaust Fluid, Eaton Fuller 9LL Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Air Trac Air Ride Suspension, 204 in Wheelbase, PTO, 14 ft Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 622,990 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		1151A 1151	2013 Mack CHU613 T/A Dump Truck S/N: 1M1AN07Y9DM011918 Usage: Not Available Asset located in: Humble, TX 2018 Mack CXU613 6x4 T/A Dump Truck
1146	Asset located in: Lake Worth, TX 2006 Mack CV713 8x4 Tri/A Dump Truck S/N: 1M2AG11C56M044796 C/W: 6 Cylinder Engine, 11087 Engine hrs, Mack Manual Transmission, 18000 lb Front Axle, 44000 lb Rears, Air Ride Cab, Aluminum Outer Wheels, 385/65R22.5 Front Tires, 11R22. 5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Camelback Spring Suspension, 234 in Wheelbase, PTO, 17 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 237,085 Mi Asset located in: Humble, TX		S/N: 1M1AW02Y7JM089842 C/W: Mack MP7 10.8 L Diesel 425 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 16315 Engine hrs, Engine Brake, Mack MDrive Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Aluminum Outer Wheels, 11R22.5, Air Ride Suspension, 186 in Wheelbase, PTO, 15 ft 8 in Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 612,316 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1147	2009 International Prostar 8x4 Tri/A Dump Truck S/N: 2HSCUAPR89C142346 C/W: Cummins ISX 6 Cylinder 15.0 L Diesel 450 hp Engine, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Aluminum Outer Wheels, 11R22.5 Front Tires, 11R24.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Ride Suspension, 232 in Wheelbase, PTO, 16 ft 5 in Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 836,555 Mi		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1152	2015 Freightliner Coronado 122 6x4 T/A Dump Truck S/N: 3AKJGND66FDGH1837 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 25061 Engine hrs, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Differential Lock, 14320 lb Front Axle, 44000 lb Rears, Meritor MT-44-14XP Drive Axles, 3.70:1 Axle Ratio, 58320 lb GVWR, Aluminum Outer Wheels, 11R24.5, Air Ride Suspension, 208 in Wheelbase, PTO, 14 ft 8 in Long x 3 ft 10 in High Steel Body, Electric Roll Tarp	1156	2016 Freightliner M2 106 4x2 T/A Dump Truck S/N: 3AKBCXCY9GDHS6544 C/W: Cummins 6 Cylinder Diesel 300 hp Engine, Requires Diesel Exhaust Fluid, 8371 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 5.38:1 Axle Ratio, 30000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, PTO, 12 ft Long x 2 ft High Body, Round Bottom, Electric Roll Tarp Usage: 162,263 Mi Asset located in: Humble, TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1157	2016 Freightliner M2 106 4x2 T/A Dump Truck S/N: 3AKBCXCY1GDHS6540 C/W: Cummins ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 6410 Engine hrs, Allison 3000
1153	2019 Freightliner Cascadia 125 6x4 T/A Dump Truck S/N: 3AKJGEFG8KSLC9220 C/W: Cummins X15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12175 Engine hrs, Engine Brake, Eaton Fuller FRO- 16210C 10-Speed Manual Transmission, Differential Lock, 12000 lb Front Axle, 40000 lb		Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles 5.38:1 Axle Ratio, 30000 lb GVWR, Air Ride Ca Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 158 in Wheelbase, PTO, 12 f Long x 2 ft High Steel Body, Round Bottom, Electric Roll Tarp Usage: 132,652 Mi Asset located in: Humble, TX
Rears, Meritor MT-40-14X Drive Axles, 3.90:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, PTO, 14 ft Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: 286,110 Mi Notes: TITLE BRANDED REBUILT SALVAGE Asset located in: Humble, TX	1159A	2002 Mack 6x2 T/A Dump Truck S/N: 1M2P264Y82M033850 C/W: Mack 6 Cylinder Diesel 300 hp Engine, 2002 US EPA Label, 40164.1 Engine hrs, Mack Maxitorque 7-Speed Manual Transmission, 11R24.5, Spring Suspension, 204 in Wheelbase, PTO, 15 ft Long x 4 ft 3 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 107,777 Mi	
1154	2015 Freightliner M2112 6x4 T/A Dump Truck		Asset located in: Humble, TX
	S/N: 1FUJC5DV1FHGS1137 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FM15E310B 10-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 172 in Wheelbase, PTO, 14 ft Long x 4 ft High Steel Body, Electric Roll Tarp Usage: 389,510 Mi Asset located in: Humble, TX	1159	2009 Freightliner FLD 120 6x4 T/A Dump Truck S/N: 1FUJALCK09DAH4306 C/W: Detroit Series 60 6 Cylinder 14.0 L Diesel Engine, 2008 US EPA Label, 1316 Engine hrs, Eaton Fuller 9LL Manual Transmission, Air Ride Cab, 11R24.5, Hendrickson Haulmaax Suspension, 190 in Wheelbase, PTO, Crown Beds 14 ft 10 in Long x 3 ft 10 in High Steel Body, Electric Roll Tarp Usage: 363,611 Mi Asset located in: Humble, TX
1155	2012 Freightliner M2112 6x4 T/A Dump Truck S/N: 1FUJC5DV4CHBR7500 C/W: Detroit 6 Cylinder 12.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 14414 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Airliner Air Ride Suspension, 174 in Wheelbase, PTO, 14 ft 8 in	-1160	2000 Mack CX613 6x4 T/A Dump Truck S/N: 1M1AE05Y5YW003263 C/W: Mack 6 Cylinder Diesel Engine, Eaton Fuller Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 184 in Wheelbase, PTO, Custom Fab Truck Rigging Inc 13 ft 6 in Long x 4 ft 4 in High Steel Body, Manual Roll Tarp Usage: Not Available
	Long x 4 ft 4 in High Steel Body, Flat Bed, Electric Roll Tarp Usage: 427,811 Mi Asset located in : Humble, TX		Notes: THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN SHOWN ON THE ODOMETER Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1161	2007 International 7600 6x4 Dump Truck S/N: 3HTWYAHT97N517132 C/W: Cummins 6 Cylinder Diesel Engine, 24950 Engine hrs, Engine Brake, Allison Automatic Transmission, Air Ride Cab, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Hendrickson Rubber over Walking Beam Suspension, 250 in Wheelbase, PTO, 17 ft 6 in Long x 5 ft High Steel Body, Round Bottom Usage: 536,048 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1166	1997 Mack RD690S 6x4 T/A Dump Truck S/N: 1M2P264Y3VM023442 C/W: Mack EM7 6 Cylinder Diesel 300 hp Engine, 1996 US EPA Label, 24550 Engine hrs, Manual Transmission, 11R24.5, Camelback Spring Suspension, 206 in Wheelbase, PTO, 14 ft Long x 3 ft 6 in High Steel Body, Flat Bed, Pintle Hitch Usage: 616,974 Mi Asset located in: Humble, TX 2021 Volvo VNR 4x2 S/A Dump Truck S/N: 4V4W19EG2MN285377
	THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Volvo D13 12.8 L 405 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Volvo AT2612F 12-Speed
1162	2006 International 7600 6x4 T/A Dump Truck S/N: 1HTWYAHT76J239980 C/W: 6 Cylinder Diesel Engine, Engine Brake, Automated Transmission, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Tag Axle, Dual Steering Boxes, Rubber over Walking Beam Suspension, 248 in Wheelbase, PTO, 18 ft Long x 6 ft 6 in High Steel Body, Round Bottom, Electric Roll Tarp		Automated Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 32000 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5 Front Tires, 295/75R22.5 Rear Tires, Volvo Air Ride Suspension, 151 in Wheelbase, PTO, 9 ft 11 in Long x 3 ft 10 in High Steel Body, Manual Roll Tarp Usage: 393,501 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 1,054,079 Km		Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1168	2013 International 4300 4x2 S/A Dump Truck
1164	Asset located in: Humble, TX 2005 International 7400 6x4 T/A Dump Truck S/N: 1HTWHAZT35J045640 C/W: 6 Cylinder Diesel Engine, 14363 Engine hrs, Automated Transmission, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 219 in Wheelbase, PTO, Wet Kit, 14 ft 8 in Long x 4 ft 3 in High Steel Body, Flat Bed, Manual Roll Tarp, Swing Tailgate Usage: 349,518 Mi Asset located in: Humble, TX		S/N: 3HAJTSKM1DL196932 C/W: International MaxxForce 7 6.4 L Diesel Engine, 2012 US EPA Label, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 157 in Wheelbase, PTO, America 10 ft Long x 2 ft High Steel Body, Electric Roll Tarp, Pintle Hitch Usage: 121,559 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1165	1992 Kenworth T800 6x4 T/A Dump Truck	11604	2006 Volvo VNM 4x2 S/A Dump Truck
1100	S/N: 1XKDDR9X1NS581437 C/W: Detroit Series 60 12.7 L Diesel 400 hp Engine, 1993 US EPA Label, Engine Brake, Eaton Fuller Manual Transmission, 11R24.5, Spring Suspension, 192 in Wheelbase, PTO, 16 ft Long x 4 ft 4 in High Steel Body, Electric Roll Tarp Usage: 59,003 Mi Asset located in: Humble, TX	1169A	S/N: 4V4M19GF86N424815 C/W: Volvo D12D365 6 Cylinder 12.1 L Diesel 365 hp Engine, 2005 US EPA Label, Engine Brake, Meritor M-13G10A-M13 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, Meritor RS-23-160 Drive Axles, 2.80:1 Axle Ratio, 32000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Assist Front Suspension, Air Ride Suspension, 156 in Wheelbase, PTO, 10 ft
1166A	1990 Mack RD688S 6x4 T/A Dump Truck		9 in Long x 4 ft 4 in High Steel Body, Manual Roll Tarp
	S/N: 1M2P142Y9LW008357 C/W: Mack E6 11.0 L Diesel 300 hp Engine, 5x2 Manual Transmission, 11R22.5 Front Tires, 11R24.5 Rear Tires, Camelback Spring Suspension, 189 in Wheelbase, PTO, Davis 13 ft Long x 4 ft High Body Usage: 230,841 Mi Notes: THIS UNIT IS BEING SOLD WITH A BONDED TITLE Asset located in: Humble, TX		Usage: 937,295 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1169	2011 International 4300 4x2 S/A Dump Truck S/N: 1HTMMAAMXBH283799 C/W: International 6 Cylinder 7.6 L Diesel 210 hp Engine, 2009 US EPA Label, 7644 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 157 in Wheelbase, PTO, 10 ft 6 in Long x 3 ft 4 in High Steel Body, Round Bottom Usage: 242,999 Mi Asset located in: Humble, TX	1175A	2014 Freightliner M2 112 6x4 Flatbed Truck S/N: 1FVHC5DV0EHFK2124 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, 10-Speed Manual Transmission, 14600 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.70:1 Axle Ratio, 54600 lb GVWR, 11R22.5, Double Frame, Airliner Air Ride Suspension, 274 in Wheelbase, 24 ft x 97 in Bed, Forklift Mount Kit Usage: 169,043 Mi Asset located in: Humble, TX
1170	2001 International 4900 4x2 S/A Dump Truck S/N: 1HTSDADN11H397720 C/W: International 6 Cylinder Diesel Engine, Engine Brake, Spicer 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 11R22.5, Double Frame, Spring Suspension, 178 in Wheelbase, Henderson 11 ft Long x 2 ft 3 in High Steel Body, Manual Roll Tarp Usage: 185,418 Mi Asset located in: Humble, TX	1175	2016 Freightliner 114SD 6x4 Flatbed Truck S/N: 1FVHG3DV9GHHA2564 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, US EPA Label, Requires Diesel Exhaust Fluid, 12241 Engine hrs, Engine Brake, Eaton Fuller FO-16E308LL Automatic Transmission, 18000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.73:1 Axle Ratio, 58000 lb GVWR, Aluminum Front Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension,
1171	1997 Chevrolet C7500 4x2 S/A Dump Truck S/N: 1GBL7H1J2VJ100072 C/W: Cat 6 Cylinder Diesel Engine, 6-Speed Manual Transmission, 3674 lb Front Axle,		274 in Wheelbase, 25 ft x 102 in Bed, Forklift Kit Usage: 331,513 Mi Asset located in : Humble, TX
	19000 lb Rears, 12292 lb GVWR, 11R22.5, Spring Suspension, 158 in Wheelbase, PTO, Warren 10 ft Long x 3 ft High Steel Body, Pintle Hitch Usage: 18,274 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1176	1176 2017 Freightliner M2106 6x4 Flatbed Truck S/N: 3ALHCYCY2HDHZ2124 C/W: Cummins ISL 6 Cylinder Diesel 260 hp Engine, Requires Diesel Exhaust Fluid, 5566 Engine hrs, Allison Automatic Transmission, 14600 lb Front Axle, 40000 lb Rears, 54600 ll GVWR, 12R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 274 in Wheelbase 24 ft x 96 in Bed
1172	2014 Peterbilt 337 4x2 Flatbed Dump Truck S/N: 2NP2HJ7X7EM246508 C/W: Paccar PX-9 6 Cylinder Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust		Usage: 173,661 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX
	Fluid, 14169 Engine hrs, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana S21-170 Drive Axles, 4.56: 1 Axle Ratio, 33000 lb GVWR, Aluminum Wheels, 11R22.5, Rayco Spring Suspension, 221 in Wheelbase, 20 ft Long x 8 ft 6 in High Steel Body Usage: 376,035 Mi Asset located in: Humble, TX	1177B	
1173	2003 International 4300 4x2 Flatbed Dump Truck S/N: 3HTMMAANX3N572469		95 in Bed, Pintle Hitch Usage: 571,329 Mi Asset located in: Humble, TX
	C/W: 6 Cylinder Diesel Engine, 13871 Engine hrs, Automatic Transmission, 295/75R22.5, Spring Suspension, 208 in Wheelbase, PTO, 18 ft Long Steel Body, Pintle Hitch Usage: 366,590 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1177A	2012 International 7400 6x4 Flatbed Truck S/N: 1HTWGAZR8CJ625504 C/W: 6 Cylinder Diesel Engine, 7279 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Air Ride Cab, 11R22.5, International IROS Air Ride Suspension, 255 in Wheelbase, 24 ft x 95 in Bed Usage: 85,585 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1177	Truck S/N: 3AKJGEBG1FDGP9053 C/W: Cummins ISX 6 Cylinder Ultra Low Sulfur Diesel 450 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 15644 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 52000 lb GVWR, Air Ride Cab, 295/75R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, 24 ft x 93 in Bed Usage: 307,264 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1181	2018 Freightliner M2106 4x2 Flatbed Truck S/N: 3ALACXFC2JDJK4404 C/W: Cummins B6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8207 Engine hrs, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 280 in Wheelbase, 25 ft x 100 in Bed Usage: 177,098 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	
1178	2017 Peterbilt 337 4x2 Flatbed Truck S/N: 2NP2HJ7X2HM388074 C/W: Paccar PX-9 6 Cylinder 8.9 L Diesel 345 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11816.5 Engine hrs, Engine Brake, Allison 3000 Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, Dana S21- 170 Drive Axles, 4.78:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22. 5, Paccar Air Ride Suspension, 196 in Wheelbase, 13 ft 6 in x 100 in Bed, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 471,723 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1182	2017 Freightliner M2 106 4x2 Flatbed Truck S/N: 3ALACWDT0HDHY0501 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 2891.5 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 25 ft x 96 in Bed, Liftgate Usage: 442,418 Mi Asset located in: Humble, TX 2017 Freightliner M2 106 4x2 Flatbed Truck S/N: 3ALACWDT2HDHY0502	
1179	Asset located in: Humble, TX 2019 Freightliner M2 106 4x2 Flatbed Truck S/N: 1FVACWFC8KHKS6229 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, Requires Diesel Exhaust Fluid, 3188 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 252 in Wheelbase, 24 ft x 98 in Bed Usage: 113,340 Mi	1184	hp Engine, Requires Diesel E 13141 Engine hrs, Allison 22 Transmission, 10000 lb Froi Rears, Detroit DARS19 Drive Ratio, 26000 lb GVWR, Air R /75R22.5, Airliner Air Ride S Wheelbase, 24 ft x 96 in Bed Usage: 368,761 Mi	C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 13141 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DARS19 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 96 in Bed, Liftgate
1180	Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX 2018 Freightliner M2 6x4 Flatbed Truck S/N: 3ALHCYFE5JDJJ9963 C/W: Cummins L9 6 Cylinder Diesel 300 hp		2015 Freightliner M2 106 4x2 Crew Cab Flatbed Truck S/N: 3ALACWDT2FDGR9125 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 6953 Engine hrs, Automated Transmission, 5.56:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, 11R22.5, Spring Suspension, 278 in Wheelbase, 24 ft 1 in x 102 in Bed	
	Engine, Requires Diesel Exhaust Fluid, 8582 Engine hrs, Allison 3000 Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 5.86:1 Axle Ratio, 54000 lb GVWR, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 265 in Wheelbase, 28 ft x 102 in Bed Usage: 285,022 Mi Asset located in: Humble, TX		Usage: 176,352 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1185	Truck S/N: 3ALACWDT0FDGR9124 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 278 in Wheelbase, 24 ft 5 in x 96 in Bed Usage: 198,899 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1189	2015 Freightliner M2 106 4x2 Flatbed Truck S/N: 3ALACWDT8FDGM1973 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 15220 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 18000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft x 101 in Bed Usage: 387,269 Mi Asset located in: Humble, TX
		1190	2016 International 4300 4x2 Flatbed Truck S/N: 3HAMMMML2GL738568
1186	Asset located in: Humble, TX 2015 Freightliner M2106 4x2 Flatbed Truck S/N: 3ALACWDT9FDGR3385 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 240 hp Engine, 6460 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DARS19 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 252 in Wheelbase,	1191	C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 295/75R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 271 in Wheelbase, 26 ft x 102 in Bed Usage: 116,035 Mi Asset located in: Humble, TX
	24 ft x 98 in Bed Usage: 272,705 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX		2013 International Terrastar 4x2 Flatbed Truck S/N: 1HTJSSKK2DH413833 C/W: Navistar V8 Diesel Engine, 4199 Engine hrs, Allison Automatic Transmission, Aluminum Wheels, 35X12.50R24, Spring Suspension, 159 in Wheelbase, 11 ft 4 in x 99
1187	·		in Bed Usage: 116,316 Mi Asset located in : Humble, TX
	220 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 12669 Engine hrs, Allison 2100 Automatic Transmission, 8000 lb Front Axle, 18000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Airliner Air Ride Suspension, 252 in Wheelbase, 24 ft 6 in x 96 in Bed Usage: 349,897 Mi Asset located in: Humble, TX	1192	2007 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAL57H528460 C/W: International 6 Cylinder 7.6 L Diesel 225 hp Engine, 2006 US EPA Label, 34419 Engine hrs, Eaton Fuller Manual Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 256 in Wheelbase, 25 ft 6 in x 96 in Bed, Liftgate Usage: 134,419 Mi Asset located in: Humble, TX
1188	2015 Freightliner M2 106 4x2 Flatbed Truck S/N: 3ALACWDT8FDGB2159 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 12402 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, 24 ft x 96 in Bed Usage: 383,049 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	1194	2006 International 4300 4x2 Flatbed Truck S/N: 1HTMMAAN06H196721 C/W: International DT466 6 Cylinder 7.6 L Ultra Low Sulfur Diesel 245 hp Engine, 2005 US EPA Label, Eaton Fuller 6-Speed Manual Transmission, 295/75R22.5, Spring Suspension, 189 in Wheelbase, 14 ft 3 in x 96 in Bed Usage: 28,351 Mi Asset located in: Humble, TX
		1195	2002 International 4700 4x2 Flatbed Truck S/N: 1HTSCABM12H547193 C/W: International C195CF 6 Cylinder 7.3 L Diesel 195 hp Engine, 2002 US EPA Label, Automatic Transmission, 11R22.5, Spring Suspension, 152 in Wheelbase, 12 ft x 96 in Bed Usage: 92,682 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1196	2001 International 4700 Flatbed Truck S/N: 1HTSCAAN01H330095 C/W: International DT466 6 Cylinder 7.6 L Diesel 215 hp Engine, 2000 US EPA Label, 7- Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 206 in Wheelbase, PTO, Flatbed, 16 ft 3 in x 96 in Bed Usage: 93,792 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1202	2019 Ram 5500 4x4 Flatbed Truck S/N: 3C7WRNBL4KG583128 C/W: immune B6.7 6 Cylinder 6.7 L Diesel 360 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 6020 Engine hrs, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 170 in Wheelbase, 11 ft 9 in x 96 in Bed Usage: 189,019 Mi Asset located in: Humble, TX 2019 Ford F-550 XL 4x4 Crew Cab Flatbed Truck
1197	2006 Hino 268 4x2 Flatbed Truck S/N: 5PVNE8JT462S12363 C/W: Hino 6 Cylinder Diesel Engine, Automatic Transmission, 11R22.5, Spring Suspension, 245 in Wheelbase, 23 ft 8 in x 94 in Bed Usage: 672,876 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1FD0W5HTXKEG80257 C/W: Ford 6.7 L Ultra Low Sulfur Diesel 330 h Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 12805 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 204 in Wheelbase, 11 ft x 94 in Bed, Better built 100 gal Fuel Tank /w Pump Usage: 106,726 Mi Notes: LOCATED-IN-MIDLAND-TX
1198	2010 Ford F-750 XLT 4x2 Crew Cab Flatbed Truck		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	S/N: 3FRNW7FC7AV266349 C/W: CUMMINS 6 Cylinder Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 266 in Wheelbase, 20 ft x 97 in Bed Usage: 269,595 Mi Asset located in: Humble, TX	Tru S/N C/N US 12 ² 700 GV 203 Tai Usa No DE INS	2018 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HTXJEC67057 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 12420 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, steel, 255/70R19.5, Spring Suspension
1199	2019 Ford F-650 4x2 Crew Cab Flatbed Truck S/N: 1FDPW6DX1KDF02529 C/W: 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 29000 lb GVWR, 11R22.5, Spring Suspension, 231 in Wheelbase, 13 ft 9 in x 99 in Bed Usage: 24,998 Mi		203 in Wheelbase, 11 ft 0 in x 96 in Bed, Fuel Tank Usage: 109,018 Mi Notes: LOCATED-IN-MIDLAND-TX, DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX 2016 Ford F-550 XL 4x4 Extended Cab Flatbed
	Asset located in: Humble, TX	1.200	Truck
1200	2008 Ford F-650 XL 4x2 Crew Cab Flatbed Truck S/N: 3FRNW65M68V640657 Usage: 52,000 Mi Asset located in: Humble, TX		S/N: 1FD0X5HT8GEC75339 C/W: 6.7 L Ultra Low Sulfur Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 8438 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft x 91 in
1201	2019 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL8KG700283 C/W: CUMMINS 6 Cylinder 6.7 L Diesel Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 196 in Wheelbase, 11 ft 4 in x 97 in Bed, 100 gallons Fuel Tank Usage: 69,808 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Bed, Fuel Tank Usage: 191,492 Mi Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX

Lot #	Details	Lot #	Details
1206	2016 Ford F-550 4x4 Flatbed Truck S/N: 1FDUF5HY7GEB63180 C/W: Ford V10 6.8 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 170 in Wheelbase, 12 ft x 96 in Bed, Receiver Usage: 140,727 Mi Notes: LOCATED-IN-FORT-WORTH-TX EQUIPMENT FROM UNITED RENTALS Asset located in: Lake Worth, TX	1210	2012 Ford F-550 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD0W5HT7CEC76740 C/W: V8 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, 7040 Engine hrs, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 178 in Wheelbase Usage: 135,734 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1207	2014 Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRNFL7EG274574		Asset located in: Humble, TX
	C/W: Cummins 6 Cylinder 6.7 L Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 12 ft x 96 in Bed Usage: 87,012 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1212	2015 Ford F-450 XLT 4x4 Crew Cab Flatbed Truck S/N: 1FD0W4HT5FEC81191 C/W: Ford V8 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6600 lb Front Axle, 225/70R19.5, Spring Suspension, 200 in Wheelbase, 11 ft 6 in x 86 in Bed Usage: 176,595 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1208	2014 Ram 5500 4x4 Crew Cab Flatbed Truck		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 3C7WRNFL7EG202855 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 196 in Wheelbase, 11 ft 10 in x 94 in Bed, Fuel Tank /w Pump Usage: 122,787 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1213	2015 Ram 4500 4x4 Crew Cab Flatbed Truck S/N: 3C7WRLEL4FG559370 C/W: Cummins V8 6.7 L Ultra Low Sulfur Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 245/70R19.5, Spring Suspension, 176 in Wheelbase, 9 ft 4 in x 90 in Bed Usage: 290,721 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1214	2011 Ford F-450 XL 4x4 Extended Cab Flatbed
1209	2012 Dodge Ram 5500 4x4 Crew Cab Flatbed Truck S/N: 3C7WDMEL2CG266695 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 20500 lb GVWR, 225 /70R19.5, Spring Suspension, 173 in Wheelbase, 9 ft 5 in x 96 in Bed Usage: 302,353 Mi		Truck S/N: 1FD0X4HTXBEC16943 C/W: V8 6.7 L Ultra Low Sulfur Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 12 ft x 92 in Bed Usage: 262,361 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1215	2019 Ford F-350 4x4 Crew Cab Flatbed Truck
1210A	2011 IMT 5-33 Knuckle Boom on 2011 Ford F-550 4x4 Flatbed Truck with Crane S/N: 1FDUF5HT6BEC54454 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, Front Mounted, 45 ft 2 Section Boom, Out and Down Outriggers, Liftgate, Receiver Usage: 206,876 Mi Asset located in: Lake Worth, TX		S/N: 1FD8W3HT5KEE24230 C/W: Ford V8 6.7 L Diesel 330 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5990 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75/17, Spring Suspension, 180 in Wheelbase, 9 ft x 89 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 134,504 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1216D	2015 Ford F-350 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HTXFED08897 C/W: V8 Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 12983 Engine hrs, Automatic Transmission, 5940 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 179 in Wheelbase, 10 ft x 96 in Bed Usage: 380,270 Mi Asset located in: Humble, TX	1217A	2007 Ford F-350 XL Flatbed Truck S/N: 1FDWF37P37EB40226 C/W: V8 6.0 L Diesel Engine, 2008 US EPA Label, 7893 Engine hrs, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 245/75R17, Spring Suspension, 165 in Wheelbase, 12 ft x 96 in Bed Usage: 221,797 Mi Asset located in: Humble, TX 2011 Ford F-350 XL 4x4 Crew Cab Flatbed
1216C	2018 Chevrolet Silverado 3500HD 4x4 Crew Cab Flatbed Truck S/N: 1GB4KYCY0JF281165 C/W: GM Duramax V8 6.6 L Diesel Engine, 2018 US EPA Label, Exhaust Brake, Allison Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 13200 lb GVWR, Steel, 245 /75R17, Spring Suspension, 172 in Wheelbase, 9 ft x 93 in Bed, Fuel Tank /w Pump Usage: 162,533 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1218	Truck S/N: 1FD8W3H66BED06441 C/W: Ford V8 6.2 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, 5200 lb Front Axle, 9750 lb Rears, 13300 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase Usage: 178,631 Mi Notes: TITLE BRAND NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Ram 5500 4x2 Crew Cab Flatbed Truck
1216B	Asset located in: Humble, TX 2017 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3HT9HEE36079 C/W: Ford 6.7 L Diesel 330 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 5600 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft x 94 in Bed, Fuel Tank /w Pump Usage: 181,755 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Ford F-350 XLT 4x2 Crew Cab Flatbed Truck S/N: 1FD8W3HT2JEC43102 C/W: V8 6.7 L Diesel Engine, Requires Diesel	1219	S/N: 3C7WRMELXHG520579 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 5715 Engine hrs, Automatic Transmission, 7250 lb Front Axle, 13509 lb Rears, 19000 lb GVWR, 225/70R19.5, Spring Suspension, 174 in Wheelbase, 9 ft x 98 in Bed, Fuel Tank /w Pump Usage: 82,336 Mi Asset located in: Humble, TX 2004 GMC C5500 4x2 Flatbed Truck S/N: 1GDE5C1234F514996 C/W: V8 Gasoline Engine, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 148 in Wheelbase, 11 ft 8 in x 97 in Bed, 100 Gal Fuel Tank /w Pump Usage: 225,977 Mi
1216	Exhaust Fluid, 8314 Engine hrs, Exhaust Brake, Automatic Transmission, 5600 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 171 in Wheelbase, 9 ft 6 in x 86 in Bed Usage: 268,666 Mi Asset located in: Humble, TX 2019 Ford F-350 XL 4x4 Crew Cab Flatbed Truck S/N: 1FD8W3H62KEF60857 C/W: V8 Gasoline Engine, Automatic Transmission, 14000 lb GVWR, 245/75R17, Spring Suspension, 180 in Wheelbase, 9 ft 5 in x 102 in Bed, EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 154,310 Mi Asset located in: Humble, TX	1220 1221A	2007 Ford F-450 XLT 4x2 Flatbed Truck S/N: 1FDXF46P47EA38543 C/W: V8 Diesel Engine, Automatic Transmission, 7000 lb Front Axle, 12000 lb Rears, 16000 lb GVWR, 225/70R19.5, Air Ride Suspension, 188 in Wheelbase, 13 ft x 89 in Bed Usage: 134,587 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Ram 3500 4x2 Crew Cab Flatbed Truck S/N: 3C63RPGL5EG165578 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2014 US EPA Label, Exhaust Brake, Automatic Transmission, 5500 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, Steel, 235/80R17, Spring Suspension, 169 in Wheelbase, 9 ft x 94 in Bed Usage: 312,654 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS

Lot #	Details	Lot #	Details
1221	2017 Ram 3500 4x2 Crew Cab Flatbed Truck S/N: 3C7WRSCL9HG677981 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 3491 Engine hrs, Automatic Transmission, 6000 lb Front Axle, 9850 lb Rears, 14000 lb GVWR, 235/80R17, Spring Suspension, 170 in Wheelbase, 10 ft 2 in x 96 in Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 136,451 Mi Asset located in: Humble, TX	1227	2012 Chevrolet Silverado 2500 HD 4x2 Crew Cab Flatbed Truck S/N: 1GC1CVCG5CF238915 C/W: V8 Gasoline Engine, Automatic Transmission, 4400 lb Front Axle, 6200 lb Rears, 9500 lb GVWR, 245/75R17, Spring Suspension, 168 in Wheelbase, 8 ft 6 in x 94 in Bed Usage: 215,973 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1223	2013 Chevrolet Silverado 3500HD 4x2 Crew Cab Flatbed Truck S/N: 1GB4CZCGXDF102113 C/W: GM 6.0 L Gasoline Engine, Automatic Transmission, 235/80R17, Spring Suspension, 172 in Wheelbase, 9 ft 4 in x 90 in Bed, Receiver Usage: 335,684 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1228	2008 Isuzu NPR 4x2 COE Flatbed Truck S/N: 4KLB4B1U68J800737 C/W: Chevrolet Vortec V8 6.0 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 12000 lb Rears, 18000 lb GVWR, 235/85/16, Spring Suspension, 134 in Wheelbase, 15 ft x 91 in Bed, Liftgate Usage: 238,983 Mi Asset located in: Humble, TX
1224	2012 Chevrolet Silverado 3500HD 4x2 Flatbed Truck S/N: 1GB3CZCL4CF165649 C/W: Chevy Duramax V8 6.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automated Transmission, 5600 lb Front Axle, 7050 lb Rears, 10800.0 lb GVWR, 235/80R17, Spring Suspension, 163 in Wheelbase, 11 ft 6 in x 93 in Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1231	2012 on 2013 Peterbilt 348 6x4 Vacuum Excavator Truck S/N: 2NP3LN9XXDM182583 C/W: Paccar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 19462 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Transmission, 14600 lb Front Axle, 40000 lb Rears, 3.55:1 Axle Ratio, 54600 lb GVWR, 11R22.5, Air Trac Air Ride Suspension, 222 in Wheelbase, PTO, Steel 24900 gal Debris Tank, Manual Tailgate Locks, Hydraulic Driven Pump Usage: 38,879 Mi Asset located in: Humble, TX
1225	2011 Ram 3500 4x2 Crew Cab Flatbed Truck S/N: 3D73M4CL2BG624594 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2011 US EPA Label, Automatic Transmission, 235/80R17, Spring Suspension, 170 in Wheelbase, 8 ft 10 in x 97 in Bed, Pintle Hitch Usage: 89,494 Mi Asset located in: Humble, TX 2008 Ford F-350 XL 4x2 Crew Cab Flatbed Truck S/N: 1FDWW36Y88EA76552 C/W: V10 6.8 L Gasoline Engine, 2008 US EPA	1233	2006 Guzzler on 2007 Sterling L9500 6x4 Vacuum Excavator Truck S/N: 2FZHAZDE47AY05611 C/W: Cat 6 Cylinder Diesel Engine, 15642 Engine hrs, Eaton Fuller 10-Speed Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring Suspension, 242 in Wheelbase, PTO, Steel Debris Tank, Fresh Water Tank, Hydraulic Lift Tailgate, PTO Driven Pump, Boiler Usage: 31,774 Mi Asset located in: Humble, TX
	Label, Automatic Transmission, 4700 lb Front Axle, 9750 lb Rears, 13000 lb GVWR, 245 /75R17, Spring Suspension, 178 in Wheelbase, 9 ft x 91 in Bed Usage: 174,830 Mi Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1235	Gap-Vac on 2002 Volvo VHD 6x4 Vacuum Excavator Truck S/N: 4V5KC9UF92N321981 C/W: Cummins ISM 10.8 L Diesel 325 hp Engine, Engine Brake, Eaton Fuller Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Spring over Walking Beam Suspension, 254 in Wheelbase, PTO, Steel Debris Tank, Front Hose Reel, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, PTO Driven Pump, 64000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details Lot# **Details** Lot # 1237 Vac-Con on 1999 International 2554 4x2 1242 2007 Prevac on 2007 Sterling Acterra 6x4 Vacuum Excavator Truck Vacuum Tanker Truck S/N: 1HTGBADR7XH604442 C/W: 6 Cylinder 8.7 L Diesel 250 hp Engine, US S/N: 2FZHCHDC97AX34568 C/W: Cat C7 7.2 L 210 hp Engine, 3517 Engine hrs, Eaton Fuller 18-Speed Manual EPA Label, 12756 Engine hrs, Allison Automated Transmission, 385/65R22.5 Front Transmission, Aluminum Wheels, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Double Frame, Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 235 in Rubber over Walking Beam Suspension, 219 in Wheelbase, Steel Debris Tank, Front Hose Reel, Fresh Water Tank, Manual Tailgate Locks, 11 ft Wheelbase, PTO, Steel 3000 gal Debris Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Boom, 8 in Suction Hose, Bean Pump w/ PTO Driven Pump Engine, Blower Usage: 29,156 Mi Usage: 101,605 Mi Asset located in: Humble, TX Notes: DEFICIENCIES NOTED - PLEASE SEE 1243 2017 Ram 5500 4x4 Vacuum Tanker Truck THE INSPECTION REPORT; RITCHIE-BROS-S/N: 3C7WRNCL3HG776832 **ENERGY DEFICIENCIES NOTED - PLEASE SEE** C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, THE INSPECTION REPORT 2017 US EPA Label, 6385 Engine hrs, Engine Asset located in: Humble, TX Brake, Automatic Transmission, 7250 lb Front 1239 Axle, 13500 lb Rears, 19500 lb GVWR, 245 Super Products on 2015 Freightliner 114SD /70R19.5, Spring Suspension, 194 in 6x4 Vacuum Tanker Truck Wheelbase, PTO, Steel Debris Tank, Rear Hose S/N: 1FVHG3CY1FHGK3761 Reel, Hydraulic Driven Pump, 19500 lb GVWR C/W: Cummins 8.9 L Ultra Low Sulfur Diesel Usage: 139,118 Mi Engine, Requires Diesel Exhaust Fluid, 4031 Asset located in: Humble, TX Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 40000 lb Rears, 60000 lb 1244 2008 Junjin JXZ33416HP 33 m on 2007 Mack GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear MR688S 6x4 Concrete Pump Truck Tires, Dual Steering Boxes, Double Frame, S/N: 1M2K197C17M039785 Rubber over Walking Beam Suspension, PTO, C/W: Mack 6 Cylinder Diesel Engine, 14858 Steel Debris Tank, Front Hose Reel, Fresh Engine hrs, Engine Brake, Mack T309 9LL Manual Transmission, 20000 lb Front Axle, 44000 lb Rears, 66000 lb GVWR, Aluminum Water Tank, Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Telescopic Boom, 6 in Suction Hose, PTO Driven Pump Wheels, 425/65R22.5 Front Tires, 11R22.5 Usage: 19,316 Mi Rear Tires, Dual Steering Boxes, Camelback Asset located in: Humble, TX Suspension, 212 in Wheelbase, PTO, 8436 Pump Hours, Radio and Cable Remote 1240 2007 Mack CHN613 6x4 Vacuum Tanker Truck Controls, Boom Light, Hopper Vibrator S/N: 1M1AJ06Y97N008500 Usage: 426,636 Mi C/W: Mack 6 Cylinder Diesel 427 hp Engine, 10492 Engine hrs, Mack 10-Speed Manual Asset located in: Humble, TX Transmission, Air Ride Cab, Aluminum Front 1245 Alliance on 2006 Mack 600 6x4 Concrete Wheels, 11R24.5 Front Tires, 11R24.5 Rear Pump Truck Tires, Camelback Spring over Walking Beam Suspension, 260 in Wheelbase, Steel Debris S/N: 1M2K197C36M029807 Tank, Gardner Denver PTO Driven Pump C/W: Mack E7 11.9 L Diesel Engine, 2006 US Usage: 120,284 Mi EPA Label, 18624.1 Engine hrs, Eaton Fuller 8-Speed Manual Transmission, 20000 lb Front Notes: TITLE BRAND REBUILT SALVAGE Axle, 44000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, Asset located in: Humble, TX 11R22.5 Rear Tires, Camelback Spring 1241 2007 Freightliner M2 106 6x4 Vacuum Tanker Suspension, 225 in Wheelbase, 268 Pump Truck Hours, Radio Remote Controls, Hopper Vibrator S/N: 1FVHCYDC67DX53455 Usage: Not Available C/W: Cat C7 6 Cylinder 7.2 L 350 hp Engine, 2006 US EPA Label, Eaton Fuller RT-8908LL Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT 8LL Manual Transmission, 16540 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, Asset located in: Humble, TX 4.11:1 Axle Ratio, 56540 lb GVWR, Air Ride Cab, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 204 in Wheelbase, Steel 3000 gal Debris Tank, Hydraulic Lift Tailgate, Manual Tailgate Locks, Summit Hydraulic Driven Pump Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

			Tage II, of let
Lot #	Details	Lot #	Details
1246	2022 Peterbilt 348 10x4 Volumetric Mixer Truck S/N: 2NP3LJ0X4NM792888 C/W: Paccar PX-9 6 Cylinder Ultra Low Sulfur Diesel 370 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 2456 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22. 5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Steerable Air Lift Pusher Axle, Steerable Air Lift Pusher Axle, Steerable Air Lift Tag Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 278 in Wheelbase, Strong Mixer Unit Usage: 39,742 Mi Asset located in: Humble, TX	1250	2014 Peterbilt 365 6x4 Mixer Truck S/N: 1NPSL70X4ED222376 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8224.6 Engine hrs, Engine Brake, Automatic Transmission, Differential Lock, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R24. 5 Rear Tires, Dual Steering Boxes, Double Frame, Rubber over Walking Beam Suspension, 225 in Wheelbase, PTO, Con-Tech 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 177,773 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1247	2022 Peterbilt 348 10x4 Volumetric Mixer Truck S/N: 2NP3LJ0X2NM792887 C/W: Paccar PX-9 8.9 L Engine, Requires Diesel Exhaust Fluid, 2456 Engine hrs, Engine Brake, Allison Automatic Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /45R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, Air Ride Suspension, 276 in Wheelbase, PTO Usage: 42,707 Mi Asset located in: Humble, TX	1251	2015 Western Star 4700 6x4 Mixer Truck S/N: 5KKHAXDV8FLGR9577 C/W: Detroit DD13 6 Cylinder Diesel Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 18740 Engine hrs, Engine Brake, Allison Automatic Transmission, Double Differential Locks, 22000 lb Front Axle, 46000 lb Rears, 68000 lb GVWR, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Walking Beam Suspension, 225 in Wheelbase, PTO, Con-Tech 8.4 m3 Mixer Unit, 3 Removable Chutes Usage: 195,716 Mi
1248	2022 Peterbilt 348 10x4 Volumetric Mixer Truck	1	Asset located in: Humble, TX
	S/N: 2NP3LJ0X6NM792889 C/W: Paccar PX-9 6 Cylinder Ultra Low Sulfur Diesel 370 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 2460 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, Aluminum Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Steerable Air Lift Pusher Axle, Air Lift Tag Axle, Dual Steering Boxes, Double Frame, Air Trac Air Ride Suspension, 278 in Wheelbase, Strong Mixer Unit Usage: 43,038 Mi Asset located in: Humble, TX	1252A	2012 Kenworth W900 6x4 Mixer Truck S/N: 1NKWX7EX8CJ326100 C/W: Cat ISX11.9 350V 6 Cylinder 11.9 L Diesel 350 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller Automated Transmission, 20000 lb Front Axle, 46000 lb Rears, 4.78:1 Axle Ratio, 92000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Air Lift Tag Axle, Trailing Tag Axle, Rubber over Walking Beam Suspension, 247 in Wheelbase, PTO, Con-Tech Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: Not Available
1249	2021 Kenworth T880 6x4 Mixer Truck		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1NKZLK0X8MJ455930 C/W: Paccar 6 Cylinder Diesel Engine, Requires		Asset located in: Humble, TX
	Diesel Exhaust Fluid, 4713 Engine hrs, Engine Brake, Eaton Fuller TO14909ALL 8LL Manual Transmission, 22000 lb Front Axle, 46000 lb Rears, 4.56:1 Axle Ratio, 68000 lb GVWR, Aluminum Wheels, 425/65R22.5 Front Tires, 11R24.5 Rear Tires, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 231 in Wheelbase, Beck 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 66,897 Mi Asset located in: Humble, TX	1252	2015 Western Star 4700 6x4 Mixer Truck S/N: 5KKHAXDV6FLGR9576 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 500 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 14870 Engine hrs, Engine Brake, Allison 4500 Automatic Transmission, 22000 lb Front Axle, 46000 lb Rears, Meritor RT-46- 160P Drive Axles, 4.89:1 Axle Ratio, 68000 lb GVWR, Air Ride Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 222 in Wheelbase, PTO, Con- Tech 11 cyd Mixer Unit Usage: 158,980 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
1253	2008 Mack GU813 6x4 Mixer Truck S/N: 1M2AX13C28M002196 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 335 hp Engine, 2007 US EPA Label, 6362 Engine hrs, Mack Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Camelback Suspension, 218 in Wheelbase, PTO, CBMW 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 442,601 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1257	2001 Freightliner FLD 120SD 6x4 Mixer Truck S/N: 1FVHALA8X1PJ93521 C/W: Cummins ISM 6 Cylinder Diesel 330 hp Engine, 2001 US EPA Label, Engine Brake, Eaton Fuller 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb Rears, Meritor RT-46-160 Drive Axles, 5.33:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Outer Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 252 in Wheelbase, PTO, McNeilus 11 cyd Mixer Unit, 3 Removable Chutes, Remote Control w/Cord Usage: 216,783 Mi
1254	2006 Mack CV500 6x4 Mixer Truck		Asset located in: Humble, TX
	S/N: 1M2AG11C06M046875 C/W: Mack 6 Cylinder Diesel Engine, 2005 US EPA Label, Mack Maxitorque T310 10-Speed Manual Transmission, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Camelback Spring Suspension, 228 in Wheelbase, Continental Mfg Co 10.5 cyd Mixer Unit, 2 Removable Chutes Usage: Not Available	1258	2002 International 5600i 6x4 Mixer Truck S/N: 1HTXHAHT42J045938 C/W: Cummins ISM 6 Cylinder Diesel Engine, Automatic Transmission, 385/65R22.5 Front Tires, 11R22.5 Rear Tires, Chalmers Suspension, 212 in Wheelbase, McNeilus 10.5 cyd Mixer Unit, 2 Removable Chutes, Remote Control w/Cord Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
1255		1259	2010 Mack Granite 6x2 Roll-Off Truck S/N: 1M2AX04CXAM007631 C/W: Mack MP7 6 Cylinder 10.8 L Diesel 370 hp Engine, 13709 Engine hrs, Allison Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, 315/80R22.5, Spring Suspension, 269 in Wheelbase, PTO, 23 ft Hoist, Winch Usage: 277,880 Mi Asset located in: Humble, TX
	in Wheelbase, PTO, 10.5 cyd Mixer Unit, 2 Removable Chutes, Remote Control w/Cord Usage: 86,978 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1260	2008 Kenworth T800 6x4 Roll-Off Truck S/N: 1NKDLU0X78J214825 C/W: Cat C13 6 Cylinder 12.5 L Diesel 470 hp Engine, 2007 US EPA Label, 20830 Engine hrs, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 18000 lb Front Axle, 46000 lb
1256	2000 Kenworth T800 6x4 Mixer Truck S/N: 1NKDL00X3YJ857987 C/W: Cummins 6 Cylinder Diesel Engine, Eaton Fuller 8LL Manual Transmission, Differential Lock, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Aluminum Front Wheels, 425 /65R22.5 Front Tires, 11R22.5 Rear Tires, Rubber over Walking Beam Suspension, 224 in Wheelbase, PTO, 10.5 cyd Mixer Unit, 3 Removable Chutes Usage: 75,071 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Rears, Spicer D46-170H Drive Axles, 4.30:1 Axle Ratio, 64000 lb GVWR, Air Ride Cab, Steel 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Spring over Walking Beam Suspension, 261 in Wheelbase, PTO, Galbreath U5-0R-174 Roll-Off Body, 23 ft Hoist Usage: Not Available Notes: THE AGE AND CONDITION OF THE TRUCK INDICATES MORE MILES THAN SHOWN ON THE ODOMETER DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1261	1995 Mack RD690S 6x4 Roll-Off Truck S/N: 1M2P264C7SM017840 C/W: Mack EM7 6 Cylinder Diesel 300 hp Engine, 1995 US EPA Label, Manual Transmission, 425/65R22.5 Front Tires, 11R22. 5 Rear Tires, Dual Steering Boxes, Double Frame, Spring Suspension, 270 in Wheelbase, PTO, 1993 Galbreath U5-0R-174 Roll-Off Body, 23 ft Hoist Usage: 323,331 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1265	2021 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X1MM743944 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000.0 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 97,157 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
1262	2022 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X6NM762006 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 3608 Engine hrs, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W-LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 85,024 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1266A	2017 Peterbilt 348 6x4 Flatbed Truck S/N: 2NP3LJ0X1HM416167 C/W: Paccar ISL9 6 Cylinder 8.9 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 14157 Engine hrs, Allison 3000 Automatic Transmission, 20000 lb Front Axle, 40000 lb Rears, 5.29:1 Axle Ratio, 60000 lb GVWR, Aluminum Outer Wheels, 315/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Paccar Air Ride Suspension, 256 in Wheelbase, PTO, 26 ft 10 in x 102 in Bed, Dovetail, Hydraulic Ramps Usage: 187,181 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1263	2022 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X0NM762003 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000.0 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 58,166 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1266	2021 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X1MM762705 C/W: Paccar PX-7 6 Cylinder 6.7 L 300 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRR6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 107,303 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
1264	2021 Peterbilt 337 4x2 Rollback Truck S/N: 2NP2HM6X1MM721863 C/W: Paccar PX-7 6 Cylinder 6.7 L 260 hp Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Air Ride Suspension, 222 in Wheelbase, PTO, Jerr-Dan 22SRD6T-W- LP Rollback Body, 22 ft x 102 in Bed, Ramsey HD234R 8000 lb Winch, Hydraulic Wheel Lift Usage: 96,938 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	1267	2017 International 7400 6x4 Rollback Truck S/N: 3HAWGSTR7HL577727 C/W: Navistar 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 254 in Wheelbase, Winch Usage: 202,328 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
1268	2020 Ram 5500 SLT 4x4 Rollback Truck S/N: 3C7WRNDL3LG136546 C/W: Cummins 6.7 L Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7250 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, Aluminum Wheels, 225/70R19.5, Spring Suspension, 205 in Wheelbase, Danco 12SR20 Rollback Body, 20 ft x 95 in Bed, Ramsey 8000 lb Winch, Hydraulic Wheel Lift Usage: 56,163 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	1273	1273 Altec DC47TR on 2018 Freightliner M2 106 4x Digger Derrick Truck S/N: 1FVACXFC0JHJU4676 C/W: Cummins B6.7 6 Cylinder 6.7 L 250 hp Engine, Requires Diesel Exhaust Fluid, Positive Air Shutoff, 6714 Engine hrs, Allison 3500 Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, Meritor MS21 Drive Axles, 5.5 1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, PTO, 47 ft Sheave Height, 23790 lb Capacity, Rear Mounted, 47 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guid Auxiliary Hydraulics, Boom Tip Mounted Winc Altec 15 ft Body, A-Outriggers, Rear Outriggers
1270	2019 Isuzu NRR 4x2 COE Rollback Truck S/N: JALE5W160K7304175 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Ultra		Hydraulic Hose Reel Usage: 95,262 Mi Asset located in : Humble, TX
	Low Sulfur Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 5916 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 178 in Wheelbase, PTO, Wet Kit, 21 ft 6 in x 96 in Bed, Aluminum Frame, 18000 lb Winch Usage: 196,476 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1274	2017 Altec L42A 42 ft on 2018 Freightliner M2 106 4x2 Bucket Truck S/N: 3ALACWFC1JDJG8898 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 13258 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 5.57:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Spring Suspension, 160 in Wheelbase, PTO, 400 lb Capacity, Center Mounted, Insulated One-Person Articulated Boom, Utility
1271	2008 International 7400 Digger Derrick Truck S/N: 1HTWGAAT38J578901 Usage: Not Available		Body, 14 ft x 96 in Bed, Pintle Hitch Usage: 342,197 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1275	Altec AA55 56 ft on 2017 International 4300
1272	2018 Altec DC47 TR on 2018 Freightliner M2 106 4x2 Digger Derrick Truck S/N: 1FVACXFC3JHJU6406 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 9415 Engine hrs, Allison Automatic Transmission, 13220 lb Front Axle, 21000 lb Rears, 5.57:1 Axle Ratio, 33000 lb GVWR, 11R22.5, Spring Suspension, 190 in Wheelbase, PTO, 35 ft Sheave Height, 23790 lb Capacity, Rear Mounted, 35 ft Reach, Insulated Upper Boom, 18 in Auger, Pole Guide, Auxiliary Hydraulics, Turret Mounted Winch, ALTEC 15 ft 4 in Body, A-Outriggers, Rear Outriggers, Hydraulic Hose Reel Usage: 58,799 Mi		4x2 Bucket Truck S/N: 1HTMMMMN2HH474566 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 10448 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Material Handling Jib, A- Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 95,724 Mi Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1276	2016 Altec AA55 56 ft on 2017 International
	Asset located in: Humble, TX		4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH161528 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11915 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Material Handling Jib, A- Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 126,409 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
1277	Altec on 2017 International 4300 SBA 4x2 Bucket Truck S/N: 1HTMMMMN8HH452524 C/W: Cummins 6 Cylinder 6.7 L Diesel 260 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 9695 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, Rear Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 92 in Bed Usage: 83,494 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1281	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH161903 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9071 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 61,809 Mi Asset located in: Humble, TX 2013 Terex Hi-Ranger 5TC-55 55 ft on 2014
1278	Asset located in: Humble, TX Altec on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN5HH161530 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8064 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, Rear Mounted, Insulated One-Person Articulated Boom, Utility Body, A- Outriggers, Rear Outriggers, 16 ft 2 in x 94 in Bed, Pintle Hitch Usage: 68,230 Mi Asset located in: Humble, TX		International 4300 4x2 Bucket Truck S/N: 1HTMMAAN4EH490900 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel 260 hp Engine, 2012 US EPA Label, 7225 Engine hrs, Manual Transmission, Differential Lock, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 169 in Wheelbase, PTO, 500 lb Capacity, Center Mounted, Articulating- Telescopic Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, 15 ft x 92 in Bed Usage: 49,143 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
1279	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN7HH474563 C/W: Cummins ISB 6 Cylinder 6.7 cid Ultra Low Sulfur Diesel 260 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9219 Engine hrs, Allison Automatic Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Air Assist Front Suspension, Spring Suspension, 196 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Two-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, Rear Outriggers, 14 ft x 94 in Bed, Pintle Hitch Usage: 97,165 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1283	2013 Altec L37M 37 ft on 2013 Ford F-650 XL 4x2 Bucket Truck S/N: 3FRWF6FCXDV763172 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 156 in Wheelbase, PTO, 350 lb Capacity, Center Mounted, One-Person Articulated Boom, Utility Body, Material Handling Jib, A-Outriggers, 13 ft 8 in x 96 in Bed, Pintle Hitch Usage: 333,245 Mi Asset located in: Humble, TX Altec AT37G 37 ft on 2020 Ford F-550 XL 4x2 Bucket Truck S/N: 1FDUF5GT8LEC32538
1280	2016 Altec AA55 56 ft on 2017 International 4300 4x2 Bucket Truck S/N: 1HTMMMMN5HH452528 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10216 Engine hrs, Allison Automatic Transmission, Differential Lock, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 193 in Wheelbase, PTO, 700 lb Capacity, Rear Mounted, Insulated One-Person Articulated Boom, Utility Body, Boom Tip Mounted Winch, A-Outriggers, Rear Outriggers, 16 ft 2 in x 94 in Bed, Pintle Hitch Usage: 80,523 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: V8 6.7 L Ultra Low Sulfur Diesel Engine, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 145 in Wheelbase, PTO, 350 lb Capacity, Center Mounted, One-Person Articulated Boom, Utility Body, Bumper Mounted Winch, 9 ft x 65 in Bed Usage: 129,564 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1285	Bucket Truck S/N: 3C7WRMDL7GG282240 C/W: Dodge Cummins 6 Cylinder 6.7 L Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 206 in Wheelbase, PTO, 360 lb Capacity, Center Mounted, One-Person Articulated Boom, Utility Body, Remote Control w/Cord, 17 ft 4 in x 94 in Bed Usage: 200,250 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1290	2013 Ford E-450 Econoline 4x2 Mini Bus S/N: 1FDFE4FS8DDA93047 C/W: Air Conditioner, Automatic Transmission, Ford 6.8 L Gasoline Engine, 2013 US EPA Label, 225/75R16, Spring Suspension, 188 in Wheelbase Usage: 178,763 Mi Notes: **Seats have been removed** DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Ford E-450 Econoline 4x2 25-Seat Transit Bus S/N: 1FDFE4FS3RDA40335
			S/N: 1FDFE4FS2BDA49235 C/W: Air Conditioner, Automatic Transmission,
1286		1292	V10 6.8 L Gasoline Engine, 2011 US EPA Labe 225/75R16, Air Ride Suspension, 202 in Wheelbase Usage: 311,992 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1999 Chevrolet Bus 4x4 8-Seat Crew Carrier Bus S/N: 1GBHG31R0X1081913
	Asset located in: Humble, TX		C/W: Air Conditioner, Automatic Transmission, V8 Gasoline Engine, 1999 US EPA Label, 40X15.
1287	2006 Versalift Tel29N-02 29 ft on 2006 Ford F-350 4x2 Bucket Truck S/N: 1FDWF36516EC11373 C/W: V8 5.4 L Gasoline Engine, 2006 US EPA Label, 9088 Engine hrs, Automatic Transmission, 4700 lb Front Axle, 9750 lb Rears, 14450 lb GVWR, 245/75R17, Spring Suspension, 165 in Wheelbase, 300 lb Capacity, Center Mounted, One-Person Articulating-Telescopic Boom, Utility Body, Onan CMM5500EFI 5500 kW Gasoline Generator Set, 11 ft x 96 in Bed, Pintle Hitch Usage: 118,572 Hr	1293	50R24, Spring Suspension, 144 in Wheelbase Usage: 180,934 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Ford Transit 350 XLT 15 Passenger Van S/N: 1FBVU4XG8JKB25388 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 66,098 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS
	Notes: . Asset located in: Humble, TX		MUST STOP IN OFFICE TO SIGN REQUIRED
1288	2005 Winnebago Journey Motor Home	\dashv	DOCUMENTS Asset located in: Humble, TX
	S/N: 4UZAAHDC95CU91450 C/W: Air Conditioner, Allison Automatic Transmission, Cat C7 6 Cylinder Diesel 350 hp Engine, Sleeps 4 People, Clothes Washer & Dryer, 27910 lb GVWR, 2 Slide Outs, Power Leveling Jacks, Air Ride Suspension Onan 7500 7.5 kW Generator Usage: 881 Mi	1294	2001 Ford E-350 XL 10 Passenger Van S/N: 1FBNE31L61HA49437 C/W: V8 5.4 L Gasoline Engine, 2001 US EPA Label, Automatic Transmission, Air Conditioner, Towing Hitch Usage: 123,239 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1295	2020 GMC Savana 2500 9 Passenger Van
1289	2006 Orion 4x2 44-Seat Transit Bus S/N: 1VHAH3H2166502546 C/W: Air Conditioner, Automatic Transmission, Cummins 6 Cylinder Diesel Engine, B305 /85R22.5, Air Assist Front Suspension, Air Ride Suspension, 284 in Wheelbase Usage: 379,161 Mi Asset located in: Humble, TX		S/N: 1GTW7BFG1L1273016 C/W: V8 6.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, Towing Hitch Usage: 47,055 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1296	2019 Chevrolet Express 4x2 12-Seat Passenger Van S/N: 1GAWGFFP5K1260235 C/W: Automatic Transmission, V6 4.3 L Gasoline Engine, 2019 US EPA Label, 245 /75R16, Spring Suspension, 136 in Wheelbase Usage: 106,560 Mi Asset located in: Humble, TX	1301	S/N: 3ALACWD23LDLW1703 C/W: Detroit DD8 7.7 L 260 hp Engine, 20 EPA Label, Requires Diesel Exhaust Fluid Allison 2500 Automatic Transmission, 10 Ib Front Axle, 19000 lb Rears, 5.56:1 Axle 26000 lb GVWR, Air Ride Cab, 11R22.5, A	S/N: 3ALACWD23LDLW1703 C/W: Detroit DD8 7.7 L 260 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 281 in Wheelbase, Morgan 28 ft x 102 in Wide x 97 in High Body, Liftgate
1297	2019 Chevrolet Express 4x2 12-Seat Passenger Van S/N: 1GAWGEFP9K1286394		Usage: 376,513 Mi Notes: LOCATED-IN-FORT-WORTH-TX , . Asset located in: Lake Worth, TX	
	C/W: Air Conditioner, Allison Automatic Transmission, 3756.3 hrs Carrier Engine, GM 4.3 L Gasoline Engine, 2019 US EPA Label, 245 /75R16, Spring Suspension, 136 in Wheelbase Usage: 121,212 Mi Asset located in: Humble, TX	1302	1302 2019 Freightliner M2106 4x2 S/N: 3ALACWFC2KDKB9102 C/W: Cummins 6 Cylinder Die Requires Diesel Exhaust Fluid Eaton Fuller Automatic Trans Front Axle, 19000 lb Rears, 5.26000 lb GVWR, 11R22.5, Airl Suspension, 270 in Wheelbas 102 in Wide x 103 in High Boo Usage: 238,924 Mi Notes: PROFESSIONALLY-MA VEHICLE-PAG; SELLER SUPP MAINTENANCE RECORD ATT DOCUMENT SECTION BELOW	C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 6153 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb
1298	2014 Ford E-150 4x2 8-Seat Passenger Van S/N: 1FMNE1BL3EDA18489 C/W: Automatic Transmission, V8 5.4 L Gasoline Engine, 2014 US EPA Label, 225 /75R16, Spring Suspension, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY Usage: 43,192 Mi Asset located in: Humble, TX 2016 Peterbilt 330 4x2 Van Truck			Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
1233	S/N: 2NPNHM6X2GM349371		Asset located in: Humble, TX	
	C/W: Paccar PX-7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 8796 Engine hrs, Automated Transmission, 10000 lb Front Axle, 17000 lb Rears, 4.88:1 Axle Ratio, 26000 lb GVWR, 295 /75R22.5, Paccar Air Ride Suspension, 275 in Wheelbase, Morgan 26 ft x 102 in Wide x 106 in High Body, Liftgate Usage: 198,811 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1303	2019 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC0KDKV8114 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 6965 Engine hrs, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.88:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Supreme 20 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 252,494 Mi	
1300	2020 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWD27LDLW1705 C/W: Detroit DD8 6 Cylinder 7.7 L 260 hp Engine, 2019 US EPA Label, Requires Diesel		Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	
	Exhaust Fluid, 7909 Engine hrs, Engine Brake, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Suspension, 281 in Wheelbase, Morgan 28 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 335,294 Mi Notes: LOCATED-IN-FORT-WORTH-TX, . Asset located in: Lake Worth, TX	1304	2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC0KDKD5251 C/W: Cummins B6.7 240 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9045.7 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.22:1 Axle Ratio, 26000 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 22 ft x 102 in Wide x 86 in High Body, Liftgate Usage: 357,096 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	

Lot #	Details	Lot #	Details
1305	2019 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFCXKDKL6105 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10198 Engine hrs, Allison 2500 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 537,307 Mi Asset located in: Humble, TX	1309	2018 Freightliner M2106 4x2 Extended Cab Moving Van Truck S/N: 3ALACWFC4JDKA3465 C/W: Cummins 6 Cylinder Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 7150 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 267 in Wheelbase, Kentucky Trailer 26 ft x 102 in Wide x 100 in High Body, Curbside Door Usage: 229,933 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
1306	306 2019 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFB3KDKH7212 C/W: Detroit DD5 4 Cylinder 5.1 L Diesel 230 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 272.9 Engine hrs, Allison 2200 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Meritor MS-19-14X Drive Axles, 5.86:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 189,467 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1310	Asset located in: Humble, TX 2018 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWFC3JDJH4086 C/W: 26 ft x x Body Usage: 265,062 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX
		1311	2018 Freightliner M2 106 Van Truck S/N: 3ALACWFC4JDJH4677 Usage: 236,671 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
1307	2019 Freightliner M2106 4x2 Van Truck	1	Asset located in: Humble, TX
	S/N: 3ALACWFC2KDKD5249 C/W: Cummins B6.7 6 Cylinder 6.7 L 240 hp Engine, Requires Diesel Exhaust Fluid, 11201 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Morgan 24 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 283,890 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1312	2018 Freightliner M2106 4x2 Van Truck S/N: 3ALACWFC0JDJR3604 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 7489 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, Aluminum Outer Wheels, 11R22.5, Airliner Air Ride Suspension, 216 in Wheelbase, Supreme 24 ft x 102 in Wide x 96 in High Body, Liftgate Usage: 348,022 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1308	2018 Freightliner M2106 4x2 Moving Van Truck S/N: 3ALACWFC6JDKA3452		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 6255 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, Aluminum Wheels, 255/70R22.5, Airliner Air Ride Suspension, 280 in Wheelbase, Kentucky 26 ft x 96 in Wide x 110 in High Body, Curbside Door Usage: 204,245 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	1314	2017 Freightliner M2106 4x2 Van Truck S/N: 3ALACWDTXHDJB3542 C/W: Cummins 6 Cylinder Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 96 in Wide x 106 in High Body Usage: 318,332 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1315	2016 Freightliner M2 106 Van Truck S/N: 3ALACWDT9GDHN4932 Usage: 236,437 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	1321 2 SC h E A 1 S C h E A 1	2013 Freightliner M2106 6x4 Van Truck S/N: 1FVHCYBS0DHFF4334 C/W: Cummins ISC 6 Cylinder Diesel 270 hp Engine, Requires Diesel Exhaust Fluid, 11413.8 Engine hrs, Allison Automatic Transmission, 14000 lb Front Axle, 40000 lb Rears, 54000 lb GVWR, 295/75R22.5, Airliner Air Ride	
1316	2016 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT2GHHN3194 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, 6945 Engine hrs, Allison 2200 Automatic Transmission, 8000 lb Front Axle, 18000 lb Rears, Detroit DA-RS-19.0-2 Drive Axles, 5.13:1 Axle Ratio, 26000 lb GVWR, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, Summit 26 ft x 102 in Wide x 104 in High Body, Liftgate Usage: 132,863 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Suspension, 264 in Wheelbase, Morgan 26 ft x 96 in Wide x 102 in High Body, Curbside Door, Liftgate Usage: 339,084 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Freightliner M2 106 4x2 Van Truck S/N: 1FVACWDT4CDBD8207 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 9682.3 Engine hrs, Eaton Fuller Automated Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor Drive Axles, 4.88:1 Axle Ratio, 26000 lb GVWR, Aluminum Outer	
1317	2016 Freightliner M2106 4x2 Van Truck S/N: 3ALACWDT1GDHR8066 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 4948.3 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000.0 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 143,232 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX		Wheels, 295/75R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 234,171 Mi Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2012 Freightliner M2 4x2 Van Truck S/N: 1FVACWBT9CDBK8764 C/W: Cummins ISC 6 Cylinder 8.3 L Diesel 260 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 7927 Engine hrs, Eaton Fuller FSO-6406A 6-Speed Manual Transmission, 8000 lb Front Axle, 17500 lb Rears, ARS-17.5-2 Drive Axles, 3.91:1 Axle Ratio, 25500 lb GVWR,	
1318	2016 Freightliner M2106 4x2 Van Truck S/N: 1FVACWDT5GHHN3187 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 9663 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 18000 lb Rears, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 263 in Wheelbase, Summit 26 ft x 102 in Wide x 94 in High Body, Liftgate Usage: 115,626 Mi Asset located in: Humble, TX		Suspension, 210 in Wheelbase, Morgan 102 in Wide x 91 in High Body Usage: 226,195 Mi Notes: DEFICIENCIES NOTED - PLEASE THE INSPECTION REPORT Asset located in: Humble, TX 1323 2018 Hino 338 4x2 Van Truck S/N: 5PVNV8JV3J4S58071 C/W: 6 Cylinder Diesel Engine, 2017 US Label, Requires Diesel Exhaust Fluid, 96 Engine hrs, Automatic Transmission, 12	Usage: 226,195 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Hino 338 4x2 Van Truck
1319	2015 Freightliner M2 106 4x2 Van Truck S/N: 3ALACWDT7FDGM6131 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 8450 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 278 in Wheelbase, Morgan 26 ft x 102 in Wide x 97 in High Body, Curbside Door, Liftgate Usage: 242,912 Mi Asset located in: Humble, TX		11R22.5, Spring Suspension, 290 in Wheelbash Morgan 28 ft x 102 in Wide x 103 in High Bod Liftgate Usage: 333,734 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1324	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV1L4S75725 C/W: Hino 6 Cylinder Diesel Engine, 7266 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 99 in High Body, Liftgate Usage: 213,561 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1328	2017 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV3H4S64734 C/W: 6 Cylinder Diesel Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Allison Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	1330	2014 Hino 268A Van Truck
1325	2020 Hino 268 4x2 Van Truck S/N: 5PVNJ8JV9L5S78351 C/W: Hino J08EBV 6 Cylinder 7.7 L 260 hp		S/N: 5PVNJ8JT7E4S55125 Usage: Not Available Asset located in : Humble, TX
	Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 97 in High Body, Liftgate Usage: 282,311 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	1331	2020 International MV607 4x2 Van Truck S/N: 3HAEUMMN4LL179234 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 3081 Engine hrs, Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000.0 lb GVWR, 11R22.5, Air Ride Suspension, 285 in Wheelbase, 28 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 135,826 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG;
1326	2018 Hino 268 4x2 Van Truck	1	Asset located in: Humble, TX
	S/N: 5PVNJ8JV2J4S69767 C/W: Hino 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 4785 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950.0 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 106 in High Body Usage: 125,655 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; Asset located in: Humble, TX	1332	2018 International 8600 SBA 4x2 Van Truck S/N: 3HTHWSNN3JN626221 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 370 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9141 Engine hrs, Engine Brake, Automated Transmission, 13000 lb Front Axle, 20000 lb Rears, 33000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R22.5, Air Ride Suspension, 265 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 314,311 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1327	2018 Hino 268 4x2 Van Truck		THE INSPECTION REPORT
	S/N: 5PVNE8JV4J4S56734 C/W: 6 Cylinder Diesel Engine, 2017 US EPA	1001	Asset located in: Humble, TX
	Label, Requires Diesel Exhaust Fluid, 7975 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 98 in High Body, Liftgate Usage: 333,665 Mi Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	1334	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML2KH514831 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 2934 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, supreme 26 ft x 102 in Wide x 97 in High Body, Liftgate Usage: 125,178 Mi Notes: ***Please See Seller Supplied Maintenance Record Attached in the Documentation Section Below*** Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1335	2019 International 4300 4x2 Cargo Van Truck S/N: 1HTMMMML0KH515489 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3441 Engine hrs, Eaton Fuller Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, Meritor MT-40-14X Drive Axles, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 96 in Wide x 97 in High Body, Walk-Up Ramp, Liftgate, Ball Hitch Usage: 152,143 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1339	2019 International 4300 4x2 Van Truck S/N: 1HTMMMML1KH581520 C/W: Cummins 6 Cylinder Engine, Requires Diesel Exhaust Fluid, 7716 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 269 in Wheelbase, Supreme 26 ft x 102 in Wide x 100 in High Body, Curbside Door, Walk-Up Ramp, Liftgate Usage: 204,957 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX
1336	2019 International 4300 4x2 Van Truck	1340	2018 International Durastar 4300 4x2 Cargo Van Truck
1330	S/N: 1HTMMMML0KH515492 C/W: Cummins B6.7 220 6 Cylinder 6.7 L 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3560 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 96 in High Body Usage: 159,115 Mi Notes: ***Please See Seller Supplied Maintenance Record Attached in the		S/N: 3HAMMMML8JL111283 C/W: Cummins B6.7 6 Cylinder 6.7 L 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 4731 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999.0 lb GVWR, 11R22.5, Air Ride Suspension, 271 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body Usage: 123,901 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Documentation Section Below*** DEFICIENCIES NOTED - PLEASE SEE THE		Asset located in: Humble, TX
	INSPECTION REPORT	1341	2018 International Durastar 4300 SBA 4x2 Van
	Asset located in: Humble, TX	4	Truck
1337	2019 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML6KH515089 C/W: Cummins 6 Cylinder 6.7 L Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 3786 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, International IROS Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 96 in Wide x 102 in High Body, Walk-Up Ramp Usage: 170,705 Mi		S/N: 1HTMMMML9JH589637 C/W: Cummins 6 Cylinder Diesel Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Aluminum Outer Wheels, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 233,934 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	1342	2018 International 4300 4x2 Van Truck
1338	2019 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML6KH515125 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, 4093 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 282 in Wheelbase, Morgan 24 ft x 102 in Wide x 91 in High Body, Walk-Up Ramp Usage: 170,361 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3HAMMML9JL003769 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 8873 Engine hrs, Eaton Fuller Automatic Transmission, 7937 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Air Ride Suspension, 272 in Wheelbase, 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 317,510 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
1343	2018 International 4300 SBA 4x2 Van Truck S/N: 1HTMMMML2JH463295 C/W: Cummins B6.7 220 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 9475 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 272 in Wheelbase, Mickey 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Ball Hitch Usage: 328,837 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1351 1352	2016 International 4300 SBA 4x2 Van Truck S/N: 3HAMMML0GL262692 C/W: Cummins 6 Cylinder 6.7 L Diesel 250 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 11102 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 252 in Wheelbase, Morgan 24 ft x 102 in Wide x 105 in High Body, Liftgate Usage: 260,824 Mi Asset located in: Humble, TX 2006 Freightliner M2 106 4x2 Van Truck	
1344	2018 International 4300 4x2 Van Truck S/N: 1HTMMMMN1JH212849 C/W: Cummins ISB6.7 6 Cylinder 6.7 L Diesel 260 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7529 Engine hrs, Eaton Fuller 6-Speed Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295/75R22.5, Spring Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 90 in High Body, Liftgate Usage: 288,944 Mi		S/N: 1FVACWCS36DW26014 C/W: Mercedes Benz MBE900-210 6 Cylinder 6.4 L Diesel 210 hp Engine, 2005 US EPA Label, 18792 Engine hrs, Allison 2100 Automatic Transmission, 5.13:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 252 in Wheelbase, Liftgate Usage: 572,052 Mi Notes: LOCATED-IN-FORT-WORTH-TX BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	Asset located in: Humble, TX	1353	2005 Freightliner M2106 4x2 Van Truck	
1340	S/N: 1HTMMMML8GH106888 C/W: Cummins ISB6.7 240 6 Cylinder 6.7 L Diesel 240 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 7190 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 270 in Wheelbase, Supreme 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Walk-Up Ramp, Liftgate		S/N: 1FVACWDC65HV11888 C/W: Cat C7 6 Cylinder Diesel 210 hp Engine, 12350 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 5.57:1 Axle Ratio, 26000 lb GVWR, 295 /75R22.5, Spring Suspension, 270 in Wheelbase, supreme 26 ft x 96 in Wide x 97 in High Body, Liftgate Usage: 349,547 Mi Asset located in: Humble, TX	
	Usage: 226,452 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1354A	2005 Hino 268 4x2 Van Truck S/N: 5PVNJ8JT352S10274	
1347	Asset located in: Humble, TX 2016 International 4300 4x2 Van Truck S/N: 1HTMMMML4GH081276 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 7781 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295/75R22.5, Air Ride Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Walk-Up Ramp, Liftgate Usage: 230,393 Mi		Diesel 220 hp Engine, 2004 US Automatic Transmission, 8000 19000 lb Rears, 25950 lb GVWF Front Tires, 11R22.5 Rear Tires Suspension, 253 in Wheelbase, INDUSTRIES 24 ft x 101 in Wide Body, Liftgate Usage: 418,349 Mi	Usage: 418,349 Mi Notes : TITLE BRAND WITH BONDED TITLE
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1354	2009 Hino Van Truck S/N: 5PVNJ8JV592S51738 Usage: Not Available	
1050	Asset located in: Humble, TX	-	Asset located in: Humble, TX	
1350	2016 International 4300 4x2 Van Truck S/N: 1HTMMMML0GH012990 C/W: Cummins 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 10795 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 295 /75R22.5, Air Ride Suspension, 272 in Wheelbase, Supreme 26 ft x 102 in Wide x 101 in High Body, Curbside Door, Liftgate Usage: 426,973 Mi Asset located in: Humble, TX	1355	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP9L1182263 C/W: V6 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6084 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 74 in High Body Usage: 89,341 Mi Notes: TITLE SHOWS NOT ACTUAL MILEAGE Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
1356	2020 GMC Savana G3500 4x2 Van Truck S/N: 1GD07RFP4L1158517 C/W: Vortec 6 Cylinder 4.3 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 6081 lb Rears, 9900 lb GVWR, 245/75R16, Spring Suspension, 140 in Wheelbase, Morgan 12 ft x 80 in Wide x 71 in High Body Usage: 93,097 Mi Notes: TITLE SHOW NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1361	2014 Ford E350 4x2 Van Truck S/N: 1FDWE3FL7EDA06369 C/W: V8 5.4 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4050 lb Front Axle, 6084 lb Rears, 10050 lb GVWR, 245 /75R16, Spring Suspension, 138 in Wheelbase, Supreme 12 ft x 79 in Wide x Body Usage: 246,541 Mi Notes: LOCATED-IN-LIVINGSTON_LA_TX,; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
1357	<u> </u>	1362	2019 Isuzu NRR 4x2 COE Van Truck
1337	2019 GMC Savana G3500 4x2 Van Truck S/N: 7GZ37TCG1KN006093 C/W: V8 6.0 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 14300 lb GVWR, 225 /75R16, Spring Suspension, 178 in Wheelbase, Morgan 16 ft x 96 in Wide x 76 in High Body, ball Usage: 104,391 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION	S/N: JALE5W161K7301687 C/W: Isuzu 4HK1TC 4 Cylinder 317 cio Low Sulfur Diesel 210 hp Engine, 2018 Label, Requires Diesel Exhaust Fluid, 7 Engine hrs, Automatic Transmission, 7 Front Axle, 13660 lb Rears, 19500 lb G /70R19.5, Spring Suspension, 149 in Wheelbase, Supreme 17 ft x 92 in Wid High Body, Curbside Door Usage: 111,909 Mi Notes: ; SELLER MAINTENANCE RECO	S/N: JALE5W161K7301687 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Ultra Low Sulfur Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7965 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225 /70R19.5, Spring Suspension, 149 in Wheelbase, Supreme 17 ft x 92 in Wide x 74 in High Body, Curbside Door Usage: 111,909 Mi
	BELOW SUPPLIED Asset located in: Humble, TX		ATTACHED IN THE DOCUMENT SECTION
1358	2022 Chevrolet Express 4x2 Van Truck	1	BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1HA3GTC70NN008060		Asset located in: Humble, TX
	C/W: V8 6.6 L Gasoline Engine, 2022 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300.0 lb GVWR, 225/75/16, Spring Suspension, 178 in Wheelbase, 16 ft x 96 in Wide x 81 in High Body, Curbside Door Usage: 32,657 Mi Notes: TITLE SHOWS ODOMETER READING NOT ACTUAL Asset located in: Humble, TX	1363	53 2019 Isuzu NRR 4x2 COE Van Truck S/N: JALE5W164K7301683 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Ultra Lo Sulfur Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19. Spring Suspension, 147 in Wheelbase, Supreme 17 ft x 96 in Wide x 90 in High Body
1359	2014 Chevrolet Express 3500 4x2 Van Truck S/N: 1GB3G3BG0E1186536 C/W: V8 6.0 L Gasoline Engine, 2014 US EPA Label, 4488 Engine hrs, Automatic Transmission, 8600 lb Rears, 225/75R18, Spring Suspension, 156 in Wheelbase, Supreme 15 ft x 96 in Wide x 88 in High Body]	Curbside Door
			Usage: 151,590 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 180,176 Mi	1364	2019 Isuzu NRR 4x2 COE Van Truck
1360	Asset located in: Humble, TX 2014 Chevrolet Express 3500 4x2 Van Truck S/N: 1GB3G3CG8E1101781 C/W: Chevrolet V8 6.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75/16, Spring Suspension, 161 in Wheelbase, 15 ft x 94 in Wide x 86 in High Body Usage: 203,953 Mi Notes: ODOMETER DISCREPANCY UNIT SHOWS 203,953, TITLE SHOWS 208,908 DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: JALE5W166K7303290 C/W: Isuzu 4HK1TC 4 Cylinder 5.2 L Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7042 Engine hrs, Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 152 in Wheelbase, Supreme 18 ft x 96 in Wide x 91 in High Body, Curbside Door, Liftgate Usage: 211,629 Mi Asset located in: Humble, TX

		_	
Lot #	Details	Lot #	Details
1365	2019 Isuzu NPR NPR HD 4x2 COE Van Truck S/N: JALC4W167K7007981 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 7175.5 Engine hrs, Exhaust Brake, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 14500 lb GVWR, 215/85R16, Spring Suspension, 152 in Wheelbase, Morgan 18 ft x 96 in Wide x 92 in High Body, Liftgate Usage: 161,545 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1371	2022 Freightliner MT55G 4x2 Step Van S/N: 4UZAC3GA1NCNE9666 C/W: V8 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 8000 lb Front Axle, 15000 lb Rears, 23000 lb GVWR, 245/70R19.5, Spring Suspension, 208 in Wheelbase, Morgan Olson P1200 22 ft x 96 in Wide x 81 in High Body Usage: 71,991 Mi Asset located in: Humble, TX 2021 Ford 4x2 Step Van S/N: 1F65F5KN7M0A13007 C/W: V8 7.3 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 7000 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225
1366	2019 Hino 195 Van Truck S/N: JHHGDM2H8KK001415 Usage: 138,269 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION		Wheelbase, 18 ft x 96 in Wide x 87 Usage: 39,196 Mi Asset located in : Humble, TX
	BELOW SUPPLIED Asset located in: Humble, TX	1373	S/N: 1FDWE3FS8JDC33457 Usage: 105,941 Mi
1367	2018 Hino 155 Van Truck S/N: JHHYDM1H4JK004624 Usage: 145,262 Mi		Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED
	Notes: ; SELLER MAINTENANCE RECORD		Asset located in: Humble, TX
1368	ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX 2016 Isuzu NRR 4x2 COE Van Truck S/N: JALE5W164G7300668 C/W: Isuzu 4HK1TC 4 Cylinder 317 cid Diesel 210 hp Engine, 2015 US EPA Label, Requires	1374A	2009 Ford E-350 Cargo Van S/N: 1FTSE34P29DA34949 C/W: V8 6.0 L Diesel Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner Usage: 152,095 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
	Diesel Exhaust Fluid, 6766 Engine hrs, '		Asset located in: Humble, TX
	Automatic Transmission, 7275 lb Front Axle, 13660 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 176 in Wheelbase, Morgan 20 ft x 96 in Wide x 85 in High Body Usage: 204,049 Mi Asset located in: Humble, TX	1374	2012 Ford E-350 Cargo Van S/N: 1FTNE1EW4CDB36459 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 181,379 Mi
1369	2016 Isuzu NPR 4x2 COE Van Truck S/N: JALB4W17XG7F00259 C/W: 4 Cylinder Diesel Engine, Requires Diesel		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Exhaust Fluid, Automatic Transmission, 5360	1376	Asset located in: Humble, TX 2021 Ford Transit 250 4v2 Cargo Van
1370	Ib Front Axle, 9880 lb Rears, 13000 lb GVWR, 215/85R16, Spring Suspension, 148 in Wheelbase, Marathon 16 ft x 96 in Wide x 82 in High Body Usage: 86,168 Mi Asset located in: Humble, TX 2014 Isuzu NPR Van Truck	13/6	2021 Ford Transit 250 4x2 Cargo Van S/N: 1FTBR1X86MKA08520 C/W: 4 Cylinder 3.5 L Gasoline Engine, 2021 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5515 lb Rears, 9070 lb GVWR, 235 /65R16, Spring Suspension, 145 in Wheelbase, 10 ft x x 80 in High Body
	S/N: JALC4W169E7004598 Usage: Not Available Asset located in: Humble, TX		Usage: 75,756 Mi Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1377	2020 Ford Transit 4x2 Cargo Van	1383	2017 Chevrolet Express 2500 4x2 Cargo Van
	S/N: 1FTYE1Y86LKA02784 C/W: V6 3.5 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, 4130 lb Front Axle, 5070 lb Rears, 8670 lb GVWR, 235/65R16, Spring Suspension, 129 in Wheelbase, 9 ft x 70 in Wide x 46 in High Body, Curbside Door Usage: 85,329 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION	1384	S/N: 1GCWGAFF1H1142659 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 136 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 185,264 Mi Asset located in: Humble, TX 2017 Chevrolet Express 2500 4x2 Cargo Van
	BELOW SUPPLIED Asset located in: Humble, TX		S/N: 1GCWGAFF3H1142081
1378	2017 BlueBird Transit Cargo Van S/N: 1FTYE1ZM2HKA58028 C/W: 6 cyl 3.7 L Gasoline Engine, 2017 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 252,865 Mi		C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x x 52 in High Body Usage: 190,385 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
1379	Asset located in: Humble, TX 2019 Ram ProMaster 2500 4x2 Cargo Van	1385	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF4H1140999 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA
	S/N: 3C6TRVDGXKE557829 C/W: V6 3.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 8900.0 lb GVWR, 225 /75R16, Spring Suspension, 159 in Wheelbase, 11 ft x x 76 in High Body, Curbside Door Usage: 44,182 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Label, 6834 Engine hrs, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 135 in Wheelbase, 5 ft x 55 in Wide x 48 in High Body Usage: 226,555 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	1386	2017 Chevrolet Express 2500 4x2 Cargo Van
1380	2017 Ram Promaster 4x2 Cargo Van S/N: ZFBERFAB3H6G90159 C/W: Dodge 4 Cylinder 2.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 215/55R16, Spring Suspension, 121 in Wheelbase, 7 ft x x 53 in High Body Usage: 207,325 Mi Notes: ODOMETER DISCREPANCY-UNIT		S/N: 1GCWGAFF3H1140783 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 136 in Wheelbase, 6 ft x 74 in Wide x 53 in High Body Usage: 189,868 Mi Asset located in: Humble, TX
	SHOWS 207,324, TITLE SHOWS 207,325	1387	2017 Chevrolet Express 2500 Cargo Van
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1GCWGAFF2H1142220 Usage: Not Available
4005	Asset located in: Humble, TX		Asset located in: Humble, TX
1381	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF6H1142494 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x x 52 in High Body Usage: 179,205 Mi Asset located in: Humble, TX	1388	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF1H1141690 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x x 52 in High Body Usage: 190,260 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1382	2017 Chevrolet Express 2500 Cargo Van S/N: 1GCWGAFF8H1141556 Usage: Not Available Asset located in: Humble, TX		THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1389	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF1H1143049 C/W: 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 72 in Wide x 51 in High Body Usage: 161,564 Mi Asset located in: Humble, TX	1397	2015 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGGCB6F1103552 C/W: V8 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 11 ft x x 53 in High Body Usage: 162,246 Mi Asset located in: Humble, TX
1390	2017 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGAFF8H1140231 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front	1398	2015 Chevrolet Express 2500 Cargo Van S/N: 1GCWGGCB0F1102378 Usage: Not Available Asset located in: Humble, TX
	Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 138 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 182,180 Mi Asset located in : Humble, TX	1399	2016 Ford Transit 250 4x2 Cargo Van S/N: 1FTYR2ZM4GKA77642 C/W: Ford V6 3.7 L Gasoline Engine, 2016 US EPA Label, Atlantic Transmission, 4130 lb
1392	2016 Chevrolet Express 2500 Cargo Van S/N: 1GCWGBFB9G1128195 Usage: Not Available Asset located in: Humble, TX		Front Axle, 5515 lb Rears, 9000 lb GVWR, 235 /65R16, Spring Suspension, 138 in Wheelbase, 9 ft x 78 in Wide x 56 in High Body Usage: 214,134 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1393	2016 Chevrolet Express 2500 4x2 Cargo Van		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1GCWGBFB3G1151011 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 7 ft x 73 in Wide x 52 in High Body Usage: 159,993 Mi Asset located in: Humble, TX	1400	2010 Ford E-250 Cargo Van S/N: 1FTNE2EL9ADA90300 C/W: V8 5.4 L Natural Gas Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner Usage: 98,382 Mi
1394	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFB2G1127282 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 200,214 Mi Asset located in: Humble, TX	S/N: 1GCGG25V271224188 C/W: V6 4.8 L Gasoline Engine, Label, Automatic Transmission 245/75R16, Spring Suspension, Wheelbase, 9 ft x x 54 in High B Usage: Not Available Notes: LOCATED-IN-FORT-WOF BUYERS MUST STOP IN OFFICI REQUIRED DOCUMENTS DEFIC - PLEASE SEE THE INSPECTION Asset located in: Lake Worth, T 1403 2019 International 4x2 Refriger S/N: 3HAEUMML6KL031017 C/W: Cummins B6.7 250 6 Cylin Diesel 250 hp Engine, 2018 US Requires Diesel Exhaust Fluid, hrs, Automatic Transmission, 1 Axle, 19000 lb Rears, 25999 lb of Air Ride Suspension, 242 in Wh Thermo King T-880R Reefer Un ft x 102 in Wide x 97 in High Bo Usage: 376,042 Mi Asset located in: Humble, TX	2007 Chevrolet 2500 Express 4x2 Cargo Van S/N: 1GCGG25V271224188 C/W: V6 4.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, 5360 lb GVWR, 245/75R16, Spring Suspension, 123 in Wheelbase, 9 ft x x 54 in High Body
1395	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFB6G1128242 C/W: V8 6.0 L Compressed Natural Gas (CNG)		REQUIRED DOCUMENTS DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 155 in Wheelbase, 11 ft x x 54 in High Body Usage: 150,088 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2019 International 4x2 Refrigerated Truck S/N: 3HAEUMML6KL031017 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 10761 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 242 in Wheelbase, Thermo King T-880R Reefer Unit, MORGAN 22
1396	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFB9G1128185 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, 11 ft x x 54 in High Body Usage: 166,437 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		ft x 102 in Wide x 97 in High Body, Liftgate Usage: 376,042 Mi

			1 age 133 01 437
Lot #	Details	Lot #	Details
1404	Truck S/N: 3ALACXFC1KDKT1218 C/W: Cummins 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, 9463 Engine hrs, Eaton Fuller 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Carrier Supra 860 Reefer Unit, 764 Reefer Engine Hours:, Morgan 26 ft x 96 in Wide x 102 in High Body, Liftgate Usage: 280,649 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	1407	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFC5JDJL6587 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 13930 Engine hrs, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, Detroit DA-RS-19.0-4 Drive Axles, 5.56:1 Axle Ratio, 26000 lb GVWR, Steel, 11R22.5, Spring Suspension, 270 in Wheelbase, Thermo King T-680R Reefer Unit, Supreme 26 ft x 102 in Wide x 103 in High Body Usage: 163,535 Mi Notes : PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
1405	2018 Freightliner M2 4x2 Refrigerated Truck		Asset located in: Humble, TX
1406	S/N: 3ALACWFC2JDJH3995 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller EDCO- 6F107A Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Thermo King Reefer Unit, Supreme 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 184,074 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1408	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFC0JDJH4501 C/W: Cummins 6 Cylinder Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 6405 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 268 in Wheelbase, Carrier Reefer Unit, Standby Power, Supreme 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 205,482 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
1400	2018 Freightliner M2 106 4x2 Refrigerated Truck		Asset located in: Humble, TX
	S/N: 3ALACXDT4JDJJ6808 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 240 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 11330.6 Engine hrs, Eaton Fuller FS-6406A 6-Speed Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, Detroit DA- RS-21.0-4 Drive Axles, 4.10:1 Axle Ratio, 33000 lb GVWR, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Carrier Supra 860 Reefer Unit, 10044 Reefer Total Hours:, Morgan 24 ft x 102 in Wide x 91 in High Body, Liftgate Usage: 425,322 Mi Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	1409	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACWFCXJDJH4019 C/W: 6 Cylinder 6.7 L Diesel 220 hp Engine, Requires Diesel Exhaust Fluid, 7591 Engine hrs, Eaton Fuller Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Thermo King Reefer Unit, 10449 Reefer Total Hours:, Supreme 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 206,210 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW
	Asset located in: Humble, TX	1	Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1410	2018 Freightliner M2 106 4x2 Refrigerated Truck S/N: 3ALACXFC3JDJH5759 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, Requires Diesel Exhaust Fluid, 4654 Engine hrs, Eaton Fuller EDCO-6F107A Automated Transmission, 12000 lb Front Axle, 21000 lb Rears, 5.56:1 Axle Ratio, 33000.0 lb	1414	2016 Hino 268 4x2 Refrigerated Truck S/N: 5PVNJ8JV3G4S60410 C/W: 26 ft x x Body Usage: 240,949 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX 2014 Chevrolet G4500 4x2 Ambulance
	GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 270 in Wheelbase, Carrier Supra 860 Reefer Unit, 12823 Reefer Engine Hours:, 19826 Reefer Total Hours:, Standby Power, Hackney 26 ft x 102 in Wide x 96 in High Body, Curbside Door, Liftgate Usage: 237,396 Mi Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; Asset located in: Humble, TX	1415	S/N: 1GB6G5CL3E1189337 C/W: 11553 Engine hrs, Automatic Transmission, 4600 lb Front Axle, 9700 lb Rears, 14200 lb GVWR, V8 6.6 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 225/75R16, Spring Suspension, 160 in Wheelbase, NORTHWESTERN EMERGENCY VEHICLES 14 ft 9 in Body Usage: 189,677 Mi
1411	2018 Freightliner M2106 4x2 Refrigerated Truck		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 3ALACWFC1JDJU2984 C/W: Cummins B6.7 6 Cylinder 6.7 L Diesel 240 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2100 Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 5.56:1 Axle Ratio, 26000 lb GVWR, 11R22.5, Air Ride Suspension, 270 in Wheelbase, Carrier SUPRA 760 Reefer Unit, Morgan 26 ft x 102 in Wide x 103 in High Body Usage: 480,883 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	1416	2013 Chevrolet Express G3500 4x2 Ambulance S/N: 1GB3G2CLXD1181820 C/W: 11429.2 Engine hrs, Automatic Transmission, 4600 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, GM Ultra Low Sulfur Diesel Engine, Requires Diesel Exhaust Fluid, 225/75R16, Spring Suspension, 138 in Wheelbase, Custom Works Inc 11 ft 9 in Body, First Aid Supplies Usage: 284,908 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
1412	2017 Freightliner M2 106 Refrigerated Truck S/N: 3ALACWDT5HDJB1617 Usage: 302,547 Mi Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	1417	2011 Dodge Ram 3500 4x2 Ambulance S/N: 3D6WF4ET4BG628154 C/W: Automatic Transmission, 5200 lb Front Axle, 9350 lb Rears, 12500 lb GVWR, Chrysler Group V8 5.7 L Gasoline Engine, 2011 US EPA Label, 235/80R17, Spring Suspension, 168 in Wheelbase, 12 ft Body
1413	2018 Hino 268 4x2 Refrigerated Truck		Usage: 191,018 Mi Asset located in: Humble, TX
	S/N: 5PVNJ8JV1J4S66780 C/W: 6 Cylinder Diesel Engine, Requires Diesel Exhaust Fluid, 8280 Engine hrs, Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Hendrickson Air Ride Suspension, 272 in Wheelbase, Thermo King T-880S Reefer Unit, 11228 Reefer Total Hours:, Standby Power, Morgan 26 ft x 102 in Wide x 103 in High Body, Curbside Door, Liftgate Usage: 166,547 Mi	1418	2005 Ford E-350 4x2 Ambulance S/N: 1FDWE35P15HA25769 C/W: Automatic Transmission, 4600 lb Front Axle, 7800 lb Rears, 11500 lb GVWR, V8 6.0 L Diesel Engine, 2005 US EPA Label, 225/75/16, Spring Suspension, 139 in Wheelbase, 12 ft Body Usage: 89,747 Mi Asset located in: Humble, TX
	Notes: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1419	2009 Chevrolet Express G3500 4x2 Ambulance S/N: 1GBHG396891181433 C/W: Automatic Transmission, 4600 lb Front Axle, 6084 lb Rears, 9600 lb GVWR, V8 6.6 L Diesel 250 hp Engine, 2009 US EPA Label, 245 /75/16, Spring Suspension, 155 in Wheelbase, 12 ft Body Usage: 227,847 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1420	2007 Chevrolet Express G3500 4x2 Ambulance S/N: 1GBHG396271250999 C/W: Automatic Transmission, 4600 lb Front Axle, 6084 lb Rears, 9600 lb GVWR, V8 6.6 L Diesel 250 hp Engine, 2007 US EPA Label, 245 /75/16, Spring Suspension, 155 in Wheelbase, 12 ft Body Usage: 163,544 Mi Asset located in: Humble, TX 2018 Chevrolet Tahoe 4WD SUV S/N: 1GNSKDEC4JR257440 C/W: 5.3 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch	1425	2007 Freightliner M2 106 4x2 Attenuator Truck S/N: 1FVACWDC17DZ43962 C/W: Cat C7 6 Cylinder Diesel 210 hp Engine, 4965.8 Engine hrs, Allison Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, Meritor RS-17-144 Drive Axles, 5.57:1 Axle Ratio, 25500 lb GVWR, Aluminum Wheels, 295/75R22.5, Spring Suspension, 230 in Wheelbase, Cone Body, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 229,512 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 112,866 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1426	Asset located in: Humble, TX 2009 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM59H693856 C/W: Navistar 6 Cylinder Diesel Engine, 2007 LIS EDA Label 14624 Engine hrs. Automatic
1422	2 2016 Chevrolet Tahoe 4x4 First Responders Vehicle S/N: 1GNSKDECXGR316130 C/W: Automatic Transmission, 3500 lb Front Axle, 3800 lb Rears, 7100 lb GVWR, V8 5.3 L		US EPA Label, 14624 Engine hrs, Automatic Transmission, 11R22.5, Spring Suspension, 255 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board Usage: 231,262 Mi Asset located in: Humble, TX
	Gasoline Engine, 2016 US EPA Label, 265 /65R17, Spring Suspension, 116 in Wheelbase Usage: 101,707 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	1427	2009 International 4300 4x2 Attenuator Truck S/N: 1HTMMAAM29H693135 C/W: International MaxxForce DT 7.6 L Diesel 210 hp Engine, 2008 US EPA Label, 14460 Engine hrs, Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, 25500 lb GVWR, 299
1423	2016 Chevrolet Tahoe Automobile S/N: 1GNSKDEC7GR320359 C/W: V8 5.3 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Towing Hitch Usage: 121,744 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		/75R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 254 in Wheelbase, Flatbed, In-Cab Attenuator Controller, Arrow Board, In- Cab Arrow Board Controller Usage: 311,582 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2004 International 4300SBA 4x2 Attenuator
1424	2008 Freightliner M2 106 4x2 Attenuator Truck S/N: 1FVACWDT58HZ60743 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 200 hp Engine, 1734 Engine hrs, Allison 2100 Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, Alliance ARS-17.5-2 Drive Axles, 4.56:1 Axle Ratio, 25500 lb GVWR, 245 /70R19.5, Spring Suspension, Cone Body, In- Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 297,982 Mi Asset located in: Humble, TX	1430	Truck S/N: 1HTMMAAM44H596852 C/W: International 6 Cylinder Diesel Engine, 19009 Engine hrs, Automatic Transmission, 11R22.5, Spring Suspension, Stake Side Flatbed, In-Cab Attenuator Controller, Arrow Board, In-Cab Arrow Board Controller Usage: 311,464 Mi Asset located in: Humble, TX 1968 Kaiser M35 4x4 2 1/2 Ton, Military Flatbed Truck S/N: 000000M35882 C/W: 6 Cylinder Diesel Engine, 1166 Engine hrs, 5-Speed Manual Transmission, 395/85R20, Spring Suspension, 147 in Wheelbase, 10 ft 2 in x 96 in Bed, Winch Usage: 30,999 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1431	2007 Kenworth T300 6x4 Wireline Truck S/N: 2NKMLD9X87M183479 C/W: Cat C7 6 Cylinder Diesel 300 hp Engine, 2006 US EPA Label, 9992 Engine hrs, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Differential Lock, Meritor Drive Axles, 5.29:1 Axle Ratio, 11R22.5, Hendrickson HAS Air Ride Suspension, 246 in Wheelbase Usage: 134,569 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA 2014 Freightliner 114SD 6x2 Car Carrier Truck	1435	2018 International 4300 4x2 Flatbed Truck with Conveyor S/N: 1HTMNMML7JH753531 C/W: Cummins B6.7 250 6 Cylinder 6.7 L Diesel 250 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 10098 Engine hrs, Automatic Transmission, 9000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, Aluminum Wheels, 295/75R22.5, Spring Suspension, 219 in Wheelbase, PTO, 22 ft x 9 in Bed Usage: 182,303 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
1402	S/N: 1FUFG3DV8EHFN6831		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, 11188 Engine hrs, Engine Brake, Eaton Fuller FO-16E310C-VAS Automatic Transmission, 14600 lb Front Axle, 40000 lb Rears, Meritor MR-20-005 Drive Axles, 3.21:1 Axle Ratio, 54600 lb GVWR, Aluminum Wheels, 295/60R22.5, Airliner Air Ride Suspension, 253 in Wheelbase, Soft Tie Downs, 54600 lb GVWR Usage: 894,653 Mi Asset located in: Humble, TX	1436	2018 Ford F-750 4x2 Hydraulic Ladder Utility Truck S/N: 1FDNF7DC5JDF06155 C/W: Ford Power Stroke 6.7 L Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Exhaust Brake, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 25999 lb GVWR, 11R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 179 in Wheelbase, PTO, Hydraulic Stabilizers
1433	2014 International 7400 SBA 4x2 Pressure		Usage: 145,640 Mi
	Truck S/N: 1HTWCAZN0EH771964 C/W: 6 Cylinder Diesel Engine, 2013 US EPA Label, 10478 Engine hrs, Eaton Fuller 8LL Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 11R22.5, Spring Suspension, 220 in Wheelbase, Weatherford W80 Triplex Pump, Fiberglass Reinforced Plastic Tank Usage: 105,762 Mi Asset located in: Humble, TX Knuckle Boom on 2013 WBM GU713 6x4 Grapple Truck	1.42=	Asset located in: Humble, TX
14044		1437	2022 Ford F-650 4x2 Air Compressor Truck S/N: 1FDNF6DC5NDF06236 C/W: Cummins 6 Cylinder 6.7 L Ultra Low Sulfur Diesel Engine, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 11R22.5, Spring Suspension, 260 in Wheelbase, 150 psi Working Pressure, Cummins 6 Cylinder Engine, 186 in Cab to Axle, 279 in Cab to End of Frame Doosan 935CFM Diesel Air Compressor S/N: 440490UEWE78 Usage: 32,298 Mi
1434A			
	S/N: 1M1AX09Y7DM017188		Asset located in: Humble, TX
	C/W: Mack 6 Cylinder Diesel Engine, 21603 Engine hrs, Engine Brake, Eaton Fuller 10- Speed Transmission, 13220 lb Front Axle, 40000 lb Rears, 53220 lb GVWR, Aluminum Wheels, 11R22.5, 224 in Wheelbase, PTO, Center Mounted, 3 Section Boom, Straight Down Outriggers, Air Slide Fifth Wheel Usage: 397,134 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2013 Isuzu NPR 1000 gal 4x2 COE Hydroseeder Truck S/N: 54DB4W1B4DS802458 C/W: Chevrolet V8 6.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, 4860 lb Front Axle, 8840 lb Rears, 12000 lb GVWR, 215/85R16, Spring Suspension, 154 in Wheelbase, 1000 gal Tank, Pump w/ Honda Engine, Hose Reel Usage: 213,336 Mi Asset located in: Humble, TX
		1439	2004 International 4300 4x2 Armored Truck S/N: 1HTMMAAM04H667724 C/W: 6 Cylinder Ultra Low Sulfur Diesel Engine, 37303 Engine hrs, Automatic Transmission, 11R22.5 Usage: 622,060 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
1440	2016 Ram 5500 4x2 Armored Truck S/N: 3C7WRMAJ7GG325476 C/W: V8 5.7 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 13500 lb Rears, 18000 lb GVWR, 225 /70R19.5, Spring Suspension, 143 in Wheelbase Usage: 140,572 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	5005	2024 Raytree RMBD50 50 in Drum Skid Steer Mulcher (Unused) S/N: LM20240825034 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5006	2024 Raytree RMBD50 50 in Drum Skid Steer
5000	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20240825346 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Mulcher (Unused) S/N: LM20240825035 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5001	2024 Raytree RMBD72 72 in Skid Steer	5007	2024 Handy HBDM72-G 72 in Skid Steer Mulcher (Unused)
0001	Mulcher (Unused) S/N: DRM20240825345 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		S/N: BDM202408466 Usage: Not Available Asset located in : Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Handy HBDM72-B 72 in Skid Steer Mulcher (Unused) S/N: BDM202408465 Usage: Not Available
5002	2024 Raytree RMBD72 72 in Skid Steer		Asset located in: Humble, TX
	Mulcher (Unused) S/N: DRM20240825349 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5009	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused) S/N: HM20240825025 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5010	2024 Raytree RMDM72 72 in Skid Steer Mulcher (Unused)
5003	2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused)	-	S/N: HM20240825026 Usage: Not Available Asset located in: Humble, TX
5004	S/N: DRM20240825348 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMBD72 72 in Skid Steer Mulcher (Unused) S/N: DRM20240825347	5011	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5012	2024 Top Cat SSFM81 66 in Skid Steer Mulcher (Unused) S/N: SSFM8124080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5014	2024 Top Cat SSDFM60 60 in Disc Skid Steer Mulcher (Unused) S/N: SSDFM6024080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5022	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07085 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5015	2024 Raytree RMDM70 60 in Disc Skid Steer Mulcher (Unused) S/N: DM20240825166 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5023	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07087 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5016	2024 Raytree RMDM70 60 in Disc Skid Steer Mulcher (Unused) S/N: DM20240825167 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5024	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07086 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5017	2023 Top Cat HDRC 72 in Skid Steer Brush Cutter (Unused) S/N: HDRC23092401D Usage: Not Available Asset located in: Humble, TX	5025	2024 Wolverine BC-13-72W 66 in Skid Steer Brush Cutter (Unused) S/N: ZW07102 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5018	2024 Handy HSBC72 72 in Skid Steer Brush Cutter (Unused) S/N: BC202408139 Usage: Not Available	5026	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine BC-13-72W 72 in Skid Steer
5019	Asset located in: Humble, TX 2024 Handy HSBC72 72 in Heavy Duty Skid Steer Brush Cutter (Unused) S/N: BC202408140 Usage: Not Available Asset located in: Humble, TX	5026	Brush Cutter (Unused) S/N: ZW07099 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5020	2024 Top Cat HFRC 72 in Skid Steer Brush Cutter (Unused) S/N: HFRC24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMC72 72 in Skid Steer Brush	5027	Asset located in: Humble, TX 2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Cutter (Unused) S/N: C20240825085 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5028	2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5029	5029 2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080603A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5038	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		5039	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5030	2024 Mower King SSRC72 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080604A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5040	2024 Industrias America SK72 72 in Skid Steer Brush Cutter (Unused) S/N: SK72202522508 Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSBC 66 in Skid Steer Brush Cutter (Unused) S/N: 001602290
5031			C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION CONTRACT THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5042	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5032	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080503B Usage: Not Available Asset located in: Humble, TX	5043	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5033	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080504B Usage: Not Available Asset located in: Humble, TX	5044	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5034	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080505B	5045	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5035	Usage: Not Available Asset located in: Humble, TX 2024 Mower King SSRC 72 in Skid Steer Brush Cutter (University)	5046	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Cutter (Unused) S/N: SSRC24080501B Usage: Not Available Asset located in: Humble, TX	5047	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available
5036	2024 Mower King SSRC 72 in Skid Steer Brush Cutter (Unused) S/N: SSRC24080502B Usage: Not Available Asset located in: Humble, TX	5048	Asset located in: Humble, TX All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5037	All-Star 72 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5049	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5050	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5058	58 2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW02669 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5051	Mid-State 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5050	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5052	All-Star 66 in Skid Steer Brush Cutter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5059	2024 Mower King SSBM72 72 in Skid Steer Sweeper (Unused) S/N: SSCM61S24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5053	2024 Landhonor ABC-13-125A Articulating Skid Steer Brush Cutter (Unused) S/N: HL00139 C/W: THE PRODUCT IMAGES SHOWN ARE	5060	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Mower King SSBM72 72 in Skid Steer
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Sweeper (Unused) S/N: SSCM61S24080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5054	Skid Steer Brush Cutter (Unused) S/N: HL00138		THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5061	All-Star 72 in Angle Skid Steer Broom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5062	All-Star 72 in Angle Skid Steer Broom (Unused)
5055	2024 Wolverine PBS-11-72W 72 in Skid Steer Sweeper (Unused) S/N: ZW00302		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5063	2024 Handy HAB72 72 in Angle Skid Steer Broom (Unused) S/N: AB202408104 Usage: Not Available Asset located in: Humble, TX
5056	Sweeper (Unused) S/N: ZW00291 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5064	2024 Handy HAB72 72 in Angle Skid Steer Broom (Unused) S/N: AB202408106 Usage: Not Available Asset located in: Humble, TX
5057	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5065	2024 Handy HAB72 72 in Angle Skid Steer Broom (Unused) S/N: AB202408105 Usage: Not Available
5057	2024 Wolverine BBS-11-72W 72 in Skid Steer Sweeper (Unused)		Asset located in: Humble, TX
	S/N: ZW02486 C/W: Quick Coupler Bracket Usage: Not Available Asset located in : Humble, TX	5066	2024 Mower King SSAB72 72 in Skid Steer Broom (Unused) S/N: SSAB7224080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5067	2024 Wolverine PAB-11-72W 72 in Angle Skid Steer Broom (Unused) S/N: ZW02647 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5075	2024 Suihe SSD-YS86 86 in Angle Skid Steer Dozer (Unused) S/N: 031789657 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5068	2022 Paladin 21572P/M 72 in Skid Steer Sweeper S/N: 202213153 Usage: Not Available Asset located in: Humble, TX	5076	2024 Wolverine DB-15-84W 84 in Angle Skid Steer Dozer (Unused) S/N: ZW00548 Usage: Not Available Asset located in: Humble, TX
5069	2024 Wolverine MBS-11-48W 48 in Mini Skid Steer Sweeper (Unused) S/N: ZW00341 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5077	2024 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: ZW00978 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5070 5071	2024 Handy HSD96 96 in PAT Skid Steer Dozer (Unused) S/N: SD202408290 Usage: Not Available Asset located in: Humble, TX 2024 Handy HSD96 96 in PAT Skid Steer Dozer	5078	2024 Wolverine SWDB-11-84W 84 in PAT Skid Steer Dozer (Unused) S/N: ZW01022 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	(Unused) S/N: SD202408288 Usage: Not Available Asset located in: Humble, TX	5079	Usage: Not Available Asset located in: Humble, TX 2024 Wolverine SWDB-11-84W 84 in PAT Skid
5072	2024 Handy HSD96 96 in PAT Skid Steer Dozer (Unused) S/N: SD202408289 Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY A MAY NOT BE AN EXACT REPRESENTAT THE ACTUAL PRODUCT Usage: Not Available
3073	2024 Raytree RSWD96 94 in PAT Skid Steer Dozer (Unused) S/N: SW20240825023 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5080	ASSET located III. Humble, TX All-Star 72 in Tilting Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5074	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSD-YS86 86 in Angle Skid Steer	5081	All-Star 72 in Tilting Skid Steer Dozer (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
307.	Dozer (Unused) S/N: 031789653 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5082	2024 Wolverine SP-15-84W 84 in Skid Steer Snow Pusher (Unused) S/N: AS00394 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5083 5084	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: ZW05775 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine TCR-12-48H 48 in Skid Steer	5090	2024 Handy HST48 48 in Skid Steer Trencher (Unused) S/N: TR202408610 C/W: 4 ft bar, 8 in. rock & dirt chain, crumbing shoe Usage: Not Available Asset located in: Humble, TX 2024 Suihe SST-1000/200 36 in Skid Steer Trencher (Unused) S/N: Not Available
	Trencher (Unused) S/N: ZW05807 C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2017 Bobcat LT313 40 in Skid Steer Trencher
5085	Asset located in: Humble, TX 2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: ZW05807	5092	S/N: 045414038 C/W: 6 in. combination chain, crumbing shoe Usage: Not Available Asset located in: Humble, TX
	C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5093	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408102 Usage: Not Available Asset located in: Humble, TX
5086	2024 Wolverine TCR-12-48H 48 in Skid Steer Trencher (Unused) S/N: Not Available C/W: Crumbing Shoe THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT	5094	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408103 Usage: Not Available Asset located in: Humble, TX
	REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5095	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408101 Usage: Not Available
5087	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused)		Asset located in: Humble, TX
	S/N: T20240825124 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5096	2024 Handy HSBM72 72 in Sickle Bar Skid Steer Mower (Unused) S/N: SBM202408104 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5097	2024 Wolverine SBM-12-72W 72 in Sickle Bar Skid Steer Mower (Unused)
5088	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20240825126 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5098	S/N: ZW02123 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine SBM-12-72W 72 in Sickle Bar
5089	2024 Raytree RMT48 48 in Skid Steer Trencher (Unused) S/N: T20240825125 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Skid Steer Mower (Unused) S/N: ZW02122 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5099	2024 Mower King SSEFGC175 70 in Flail Skid Steer Mower (Unused) S/N: SSEFGC17524080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5106	2024 AGT SSPC72 72 in Skid Steer Plate Compactor (Unused) S/N: SSPC7224080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5100	2024 Mower King SSEFGC175 70 in Skid Steer Mower (Unused) S/N: SSEFGC17524080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5107	2024 Raytree RMVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR20240825149 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5101	2024 Mower King SSEFGC175 70 in Skid Steer Mower (Unused) S/N: SSEFGC17524080503B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5108	2024 Raytree RMVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR20240825150 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5102	2024 Wolverine TBM-12-78W 78 in Skid Steer Mower (Unused) S/N: ZW00962 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5109 5110	2024 Handy HVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR202408458 Usage: Not Available Asset located in: Humble, TX 2024 Handy HVR76 76 in Skid Steer Vibratory Roller (Unused) S/N: VR202408459
5103 5104	2024 Wolverine TBM-12-78W 78 in Skid Steer Mower (Unused) S/N: ZW00961 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX AGT 48 in Mini Skid Steer Mower (Unused)	5111	Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSVR-72 72 in Skid Steer Vibratory Roller (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5105	S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Landhonor VPC-11-72W 72 in Skid Steer	5112	Asset located in: Humble, TX 2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202408202
	Plate Compactor (Unused) S/N: HL00971 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5113	Usage: Not Available Asset located in: Humble, TX 2024 Wolverine VR-11-66W 66 in Skid Steer Vibratory Roller (Unused) S/N: ZW01475 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5114	2024 Handy HGB86 96 in Heavy Duty Skid Steer Grader (Unused) S/N: GB86202408203 Usage: Not Available Asset located in: Humble, TX	5123	2024 Handy HSNC78 78 in Skid Steer Power Rake (Unused) S/N: SC202408102 Usage: Not Available Asset located in: Humble, TX
5115	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202408588 Usage: Not Available Asset located in: Humble, TX	5124	2024 Handy HSNC78 78 in Skid Steer Power Rake (Unused) S/N: SC202408103 Usage: Not Available Asset located in: Humble, TX
5116	2024 Handy HSGB96 96 in Skid Steer Grader (Unused) S/N: GB202408589 Usage: Not Available Asset located in: Humble, TX	5125	2024 Top Cat SSSCR72 72 in Skid Steer Power Rake (Unused) S/N: SSSCR7224080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5117	2024 Raytree RMGB96 96 in Skid Steer Grader S/N: GB20240825104 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5126	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Top Cat SSSCR72 72 in Skid Steer Power Rake (Unused) S/N: SSSCR7224080502B C/W: THE PRODUCT IMAGES SHOWN ARE
5118	2024 Raytree RMGB96 96 in Skid Steer Grader (Unused) S/N: GB20240825103 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Landhonor PR-12-72W 72 in Skid Steer
5119	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMGB96 96 in Skid Steer Grader (Unused) S/N: GB20240825105 C/W: THE PRODUCT IMAGES SHOWN ARE	5128	Power Rake (Unused) S/N: HL01001 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		•
5120	2024 Top Cat SSSG72 72 in Skid Steer Grader (Unused) S/N: SSSG7224080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Landhonor PR-12-72W 72 in Skid Steer Power Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5121	2024 Handy HSC78 78 in Skid Steer Power Rake (Unused) S/N: SC202408713 Usage: Not Available Asset located in: Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5122	2024 Handy HSNC78 78 in Skid Steer Power Rake (Unused) S/N: SC202408101 Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
5130	2024 Top Cat ECSSLR72 72 in Skid Steer Landscape Rake (Unused) S/N: ECSSLR7224080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5138 5139	2024 Trojan TH35 SSL Skid Steer Breaker (Unused) S/N: SB30YOM20247061 C/W: 2 moil point, tool box Usage: Not Available Asset located in: Humble, TX 2024 AGT SSHH680 Skid Steer Breaker
5131	Usage: Not Available Asset located in: Humble, TX 2024 Wolverine CB-11-750F Skid Steer Breaker		(Unused) S/N: SSHH68024080501B
3131	(Unused) S/N: ZW01434		C/W: 2 moil point, tool box Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5140	Asset located in: Humble, TX 2024 AGT SSHH680 Skid Steer Breaker (Unused) S/N: SSHH68024080502B
	Usage: Not Available Asset located in: Humble, TX		C/W: 2 moil point, tool box Usage: Not Available
5132	2024 Elephant EPB400SL Skid Steer Breaker		Asset located in: Humble, TX
	(Unused) S/N: CP2406083 Usage: Not Available Asset located in: Humble, TX	5141	2024 Raytree RMH680 Skid Steer Breaker (Unused) S/N: HH20240825144 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5133	2024 Elephant EPB400SL Skid Steer Breaker (Unused) S/N: CP2406084 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5142	2024 Raytree RMH680 Skid Steer Breaker
5134	2024 Jisan JSB400SL Skid Steer Breaker (Unused) S/N: CP2404286 Usage: Not Available Asset located in: Humble, TX 2024 Jisan JSB400SL Skid Steer Breaker		(Unused) S/N: HH20240825145 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available
0100	(Unused)		Asset located in: Humble, TX
	S/N: 2404284 Usage: Not Available Asset located in : Humble, TX	5143	Mini Skid Steer Breaker (Unused) S/N: Not Available
5136	Teran THH400B-SSL Skid Steer Breaker - Fits	1	Usage: Not Available Asset located in : Humble, TX
0100	Cat 226 (Unused) S/N: CAA00167C52HRL C/W: For Skid Steer Loader Cat 226-299 With Mounting Plate included -68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of	5144	Connect Work Tools CH70 Skid Steer Breaker (Unused) S/N: CH7022F1180 C/W: backhoe hydraulic breaker Usage: Not Available Asset located in: Humble, TX
	N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box	5145	Mini Skid Steer Breaker (Unused)
	with Maintenance Tools and Operations Manual Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5137	2024 Handy SHB680 Skid Steer Breaker (Unused) S/N: SHB202408553 Usage: Not Available Asset located in: Humble, TX	5146	Miva Mini Skid Steer Breaker (Unused) S/N: 03287 Usage: Not Available Asset located in: Humble, TX
		5147	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00006 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5148	2024 Landhonor CPD-12-84H Concrete Skid Steer Post Driver (Unused) S/N: HL00005 Usage: Not Available Asset located in: Humble, TX	5157	2024 Wolverine PD-12-08D Skid Steer Post Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
5149	2024 Jisan JSB400SLT Skid Steer Post Driver (Unused) S/N: 2406151		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in: Humble, TX	5158	2024 Raytree RMPP680 Skid Steer Post Driver (Unused)	
5150	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408120 Usage: Not Available Asset located in: Humble, TX		S/N: PP20240825137 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual THE PRODUCT IMAGES SHOWN ARE FOR	
5151	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408119 Usage: Not Available		ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
5152	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408121 Usage: Not Available Asset located in: Humble, TX	5159	2024 Raytree RMPP680 Skid Steer Post Driver (Unused) S/N: PP20240825138 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/	
5153	2024 Handy HPD680 Skid Steer Post Driver (Unused) S/N: PD202408122 Usage: Not Available Asset located in: Humble, TX		Maintenance Tools & Operations Manual THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
5154	2024 AGT PD680-PZ Skid Steer Post Driver		Asset located in: Humble, TX	
	(Unused) S/N: PD680-PZ24080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5160	(Unused) S/N: PP20240825139 C/W: 7.9" Domed Cup Inside Diameter, Hoses, (1) Set of N2 Nitrogen Charging N2 Bottle & Pressure Gauge, Tool Box Maintenance Tools & Operations Manu PRODUCT IMAGES SHOWN ARE FOR	S/N: PP20240825139 C/W: 7.9" Domed Cup Inside Diameter, (2) Hoses, (1) Set of N2 Nitrogen Charging Kit w/ N2 Bottle & Pressure Gauge, Tool Box w/ Maintenance Tools & Operations Manual THE
5155	2024 AGT PD680-PZ Skid Steer Post Driver (Unused) S/N: PD680-PZ24080602A		NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5161	2024 Handy HST72 72 in Skid Steer Tiller (Unused) S/N: ST202408102	
	Asset located in: Humble, TX		Usage: Not Available	
5156	2024 Wolverine PD-12-08D Skid Steer Post	E160	Asset located in: Humble, TX	
	Driver (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5162	2024 Handy HST72 72 in Skid Steer Tiller (Unused) S/N: ST202408103 Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5163	2024 Handy HST72 72 in Skid Steer Tiller (Unused) S/N: ST202408101 Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5164	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04413 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5173	2024 Raytree RTSG30 30 in Transverse Skid Steer Stump Grinder (Unused) S/N: TS20240825206 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5165	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04405 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5174	2024 Wolverine SG-13-08D 25 in Skid Steer Stump Grinder (Unused) S/N: ZW00737 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5166	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04404 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5175	2024 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5167	2024 Wolverine TL-12-72W 72 in Skid Steer Tiller (Unused) S/N: ZW04406 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5176	2024 Wolverine SG-13-08D 26 in Skid Steer Stump Grinder (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5168	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5177	2024 Raytree RMSG29 29 in Skid Steer Sturr Grinder (Unused) S/N: SG20240825266 C/W: THE PRODUCT IMAGES SHOWN ARE
5169	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5170	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5178	2024 Raytree RMSG29 29 in Skid Steer Stump Grinder (Unused) S/N: SG20240825267 C/W: THE PRODUCT IMAGES SHOWN ARE
5171	All-Star 68 in Skid Steer Tiller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5172	2024 Raytree RTSG30 30 in Transverse Skid Steer Stump Grinder (Unused) S/N: TS20240825205 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5179	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408899 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5180	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408900 Usage: Not Available Asset located in: Humble, TX	5190	Quantity of (2) 2024 Landhonor DGB-14-84D Skid Steer Backhoe (Unused) S/N: HL00467/HL00468 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
5181	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408901 Usage: Not Available	5191	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSBH Skid Steer Backhoe (Unused)
5182	Asset located in: Humble, TX 2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408902 Usage: Not Available Asset located in: Humble, TX	-	S/N: 202201879 C/W: 14 in Bucket THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5183	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408897 Usage: Not Available Asset located in: Humble, TX	5192	Asset located in: Humble, TX 2024 Suihe SSBG 75 in Skid Steer Landplane (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5184	2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408898 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5185	Asset located in: Humble, TX 2024 Handy HSSG27 27 in Skid Steer Stump Grinder (Unused) S/N: SG202408903 Usage: Not Available Asset located in: Humble, TX		2024 Suihe SSBG 72 in Skid Steer Landplan (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available
5186	2024 Top Cat ECSSSTG200 Skid Steer Stump Grinder (Unused) S/N: ECSSSTG20024080501B C/W: 3/4 in x 24 in Cutting Wheel Usage: Not Available Asset located in: Humble, TX	5194	Asset located in: Humble, TX 72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5187	2023 Top Cat ECSSSTG200 26 in Skid Steer Stump Grinder (Unused) S/N: ECSSSTG20023121801C Usage: Not Available	5195	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5188	Asset located in: Humble, TX 2024 AGT SSBKH Skid Steer Backhoe (Unused) S/N: SSBKH24080601A C/W: THE PRODUCT IMAGES SHOWN ARE	F107	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
5189	2024 AGT SSBKH Skid Steer Backhoe (Unused) S/N: SSBKH24080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5198	72 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		5199	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5200	Mid-State 80 in Skid Steer Landplane (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5209	2024 Landhonor CC-11-08V Skid Steer Concrete Crusher (Unused) S/N: HL00003 Usage: Not Available
5201	42 in Mini Skid Steer Landplane (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5210	2024 Mower King SSCM53 53 in Skid Steer Concrete Mixer (Unused) S/N: SSCM5324080601A
5202	2024 Handy HBC72 Skid Steer Concrete Crusher (Unused) S/N: CC202408138 Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5203		F011	
5203	2024 Handy HBC72 Skid Steer Concrete Crusher (Unused) S/N: CC202408137 Usage: Not Available Asset located in: Humble, TX	5211	2024 Mower King SSCM53 53 in Skid Steer Concrete Mixer (Unused) S/N: SSCM5324080501A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5204	2024 Handy HBC72 Skid Steer Concrete Crusher (Unused) S/N: CC202408136		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	5212	2024 AGT SSCM61S 48 in Skid Steer Concrete
	Asset located in: Humble, TX		Mixer (Unused)
5205	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20240825143 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5213	S/N: SSCM61S24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX		2024 AGT SSCM61S 48 in Skid Steer Concret
5206	2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20240825141 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Mixer (Unused) S/N: SSCM61S24080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	5214	2024 Suihe SSM 50 in Skid Steer Concrete
5207	Asset located in: Humble, TX 2024 Raytree RMBC72 72 in Skid Steer Block Crusher (Unused) S/N: BC20240825142 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5215	2024 Landhonor DCM-11-250G 48 in Skid Steer
5208	2024 Landhonor CC-11-08V Skid Steer Concrete Crusher (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5216	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5227	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5217	2024 Landhonor DCM-11-250G 48 in Skid Steer Concrete Mixer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5228	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5218 5219	2024 AGT SSCM61S 48 in Skid Steer Concrete Mixer (Unused) S/N: SSCM61S24042001C Usage: Not Available Asset located in: Humble, TX Wolverine 48 in Skid Steer Concrete Mixer S/N: Not Available Usage: Not Available	5229	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5222	Asset located in: Humble, TX 2024 Wolverine CCT-11-148V Concrete Placement Skid Steer Bucket (Unused) S/N: ZW00323 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5230	2024 Suihe SSR-78 78 in Skid Steer Root Rake (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5223	Asset located in: Humble, TX All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5231	All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available
5224	All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5233	Usage: Not Available Asset located in: Humble, TX All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available
5225	All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5234	Asset located in: Humble, TX All-Star 74 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available
5226	All-Star 84 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5235	Asset located in: Humble, TX All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5236	All-Star 78 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5249	2024 Kit Containers QT-SG-S76-V3 76 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5237	All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5250	Asset located in: Humble, TX All-Star 72 In Skeleton Skid Steer Grapple (Unused) S/N: Not Available
5238	All-Star 72 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5251	Usage: Not Available Asset located in: Humble, TX All-Star 72 in Skeleton Skid Steer Grapple (Unused)
5239	All-Star 68 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	5252	S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSRGB-72 72 in Skeleton Skid
5240	Asset located in: Humble, TX All-Star 68 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	3232	Steer Grapple (Unused) S/N: 001402236 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5241	All-Star 68 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5253	Asset located in: Humble, TX All-Star 68 in Skeleton Skid Steer Grapple Bucket (Unused) S/N: Not Available
5242	All-Star 68 in Heavy Duty Skid Steer Root Rake (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX All-Star 68 in Rock Skid Steer Grapple (Unused)
	Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE
5243	Mid-State 60 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available	E255	THE INSPECTION REPORT Asset located in: Humble, TX All-Star 68 in Skeleton Skid Steer Bucket
5244	Asset located in: Humble, TX Mid-State 48 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5255	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5245	Mid-State 48 In Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5256	All-Star 68 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5246	84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5257	All-Star 68 in Skeleton Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5247	84 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5258	Asset located in: Humble, TX All-Star 72 in Heavy Duty Rock Skid Steer Grapple (Unused)
5248	2024 Kit Containers QT-RR-70 70 in Skid Steer Root Rake (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5259	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5272	All-Star 68 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5260	All-Star 68 in Rock Skid Steer Grapple (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5273	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5261	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5274	All-Star 68 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5262	All-Star 68 in Heavy Duty Rock Skid Steer		Asset located in: Humble, TX
	Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5275	All-Star 68 in Heavy Duty Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5263	All-Star 68 in Heavy Duty Rock Skid Steer		Asset located in: Humble, TX
	Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5276	All-Star 60 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5264	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5277	2024 Kit Containers MSS-SG-S48 48 in Skeleton Mini Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5265	All-Star 68 in Rock Skid Steer Grapple (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5278	Kit Containers 48 in Skeleton Mini Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available
5266	All-Star 68 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available	5279	Asset located in: Humble, TX All-Star 48 in Root Skid Steer Grapple (Unused)
5267	Asset located in: Humble, TX All-Star 74 in Heavy Duty Root Skid Steer	- 32/9	S/N: Not Available Usage: Not Available
3207	Grapple (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5280	All-Star 48 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5268	All-Star 72 in Root Skid Steer Grapple (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5281	All-Star 48 in Rock Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5269	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5282	Asset located in: Humble, TX All-Star 48 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5270	All-Star 72 in Heavy Duty Root Skid Steer		Asset located in: Humble, TX
	Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5283	42 in Skeleton Mini Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available
5271	All-Star 72 in Root Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5284	36 in Skeleton Mini Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5293	All-Star 68 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5286	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: 006600596 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5294 5295 5296	All-Star 68 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00904
5287	2024 Suihe SSRGB-82 82 in Skid Steer Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine MSG-11-44W 44 in Mini Mini Skid Steer Grapple Bucket (Unused)
5288	Raptor 76 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: ZW00901 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5289 5290	All-Star 72 in Heavy Duty Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Wolverine GB-11-72W 72 in Skid Steer	5297	2024 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00907 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Grapple Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	Usage: Not Available Asset located in: Humble, TX 5298 2024 Wolverine MSG-11-44W 44 in M Steer Grapple Bucket (Unused) S/N: ZW00902 C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESENT THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	Asset located in: Humble, TX 2024 Wolverine MSG-11-44W 44 in Mini Skid Steer Grapple Bucket (Unused) S/N: ZW00902 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5291	2024 Wolverine GB-11-72W 72 in Skid Steer Grapple Bucket (Unused) S/N: ZW04239		THE ACTUAL PRODUCT Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Usage: Not Available
5292	Asset located in: Humble, TX All-Star 68 in Skid Steer Grapple Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5300	2024 Wolverine FGP-11-3500G 48 in Grapple Skid Steer Forks (Unused) S/N: ZW00350 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5301	74 in Skid Steer Grapple Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5310	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408355 C/W: 10 in., 12 in. & 18 in. bits Usage: Not Available
5302	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5311	Asset located in: Humble, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408353 C/W: 10 in, 12 in & 18 in Bits Usage: Not Available
5303	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5312	Asset located in: Humble, TX 2014 Pengo 24 in Skid Steer Auger S/N: Not Available Usage: Not Available
5304	All-Star Stump Skid Steer Grapple (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5313	Asset located in: Humble, TX 2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408356 C/W: 10 in 12 in 8 18 in Bite
5305	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20240825173 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in : Humble, TX
		5314	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408354 C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5315	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408357
5306	2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20240825174		C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in: Humble, TX
	C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5316	2024 Handy SSA18 Skid Steer Auger (Unused) S/N: SSA2408358 C/W: 10 in, 12 in & 18 in Bits Usage: Not Available Asset located in: Humble, TX
5307	Asset located in: Humble, TX 2024 Raytree RMA42 Skid Steer Auger (Unused) S/N: A20240825175 C/W: 10 in, 12 in, 18 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5317	2024 Mower King SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080501B C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5308	Asset located in: Humble, TX Mini Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 8 in., (1) 12 in. & (1) 16 in. bits Usage: Not Available Asset located in: Humble, TX	5318	2024 Mower King SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080502B C/W: (1) 6 in, (1)12 in, (1)14 in Auger Bits, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY
5309	Mini Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 8 in., (1) 12 in, & (1)16 in. bits Usage: Not Available Asset located in: Humble, TX		NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5319	2024 AGT SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080503B C/W: (1) 6 in, (1) 12 in, (1) 14 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5325	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: ZW08552/ZW08564 C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
5320	2024 AGT SSECAG-Y Skid Steer Auger (Unused) S/N: SSECAG-Y24080504B C/W: (1) 6 in, (1) 12 in, (1) 14 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5326	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
5321	2024 Suihe SSA Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5327	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: ZW08554/ZW08566 C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
5322	2024 Suihe SSA Skid Steer Auger (Unused)		Asset located in: Humble, TX	
E222	S/N: 002503372 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5328	2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
5323	2024 Suihe SSA Skid Steer Auger (Unused) S/N: 002503382		Asset located in: Humble, TX	
5324	C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe SSA Skid Steer Auger (Unused)	5329	5329 Q S S C P IL N A	Quantity of (2) 2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	S/N: 002503384 C/W: (1) 9 in, (1) 12 in, (1) 18 in Auger Bits THE		Asset located in: Humble, TX	
		5330	2024 Wolverine ADB-13-1218R Skid Steer Auger (Unused) S/N: Not Available C/W: (1) 12 in, (1) 18 in Auger Bits THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5331	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5338	2024 Landhonor RB-14-78W 78 in Rock Skid Steer Bucket (Unused) S/N: HL00223 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5332	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5339 5340	2024 Raytree RMVB78F 70 in (Unused) S/N: SB20240825306 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Wolverine SB-12-72W 72 in Screening
5333	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Skid Steer Bucket (Unused) S/N: ZW00665 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5334	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: ZW01305 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5341 5342	2024 Wolverine SB-12-72W 72 in Screening Skid Steer Bucket (Unused) S/N: ZW00673 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMVB78 70 in Skid Steer Bucket
5335	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: SB20240825303 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5336	2024 Wolverine MAD-12-12D Mini Skid Steer Auger (Unused) S/N: ZW01303 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5343	2024 Raytree RMVB78 70 in Skid Steer Bucket (Unused) S/N: SB20240825304 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5337	Asset located in: Humble, TX Skid Steer Auger S/N: Not Available Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	_5344	2024 Raytree RMVB78 70 in (Unused) S/N: SB20240825305 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5345	2024 Handy HVSB72 64 in Screening Skid Steer Bucket (Unused) S/N: VSB202408671 Usage: Not Available Asset located in: Humble, TX	5355	All-Star 72 In Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5346	2024 Handy HVSB72 64 in Screening Skid Steer Bucket (Unused) S/N: VSB202408672 Usage: Not Available Asset located in: Humble, TX	5356 5357	All-Star 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 72 in Skeleton Skid Steer Bucket
5347	2024 Landhonor RB-14-84W 84 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5358	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5348	Asset located in: Humble, TX Mid-State 84 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5359	Asset located in: Humble, TX 2024 Kit Containers QT-SB-L72 72 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5349	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5360	2024 Kit Containers QT-SB-H72-F 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5350	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5361	All-Star 72 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available
5351	All-Star 80 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5362	Usage: Not Available Asset located in: Humble, TX All-Star 72 in Skeleton Skid Steer Bucket (Unused)
5352	2024 Kit Containers QT-SB-H76-V3 76 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5363	S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 68 in Rock Skid Steer Bucket (Unused)
5353	Asset located in: Humble, TX 2024 Kit Containers QT-SB-L76-V3 76 in Skeleton Skid Steer Bucket (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available
5354	2024 Landhonor RB-14-72W 72 in Rock Skid Steer Bucket (Unused) S/N: HL00223 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5365	Usage: Not Available Asset located in: Humble, TX All-Star 68 in Rock Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		5366	All-Star 68 in Skeleton Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5367	2024 Top Cat 4IN1BCT 72 in Multi-Purpose Skid Steer Bucket (Unused) S/N: 4IN1BCT24080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5374	2024 Wolverine MCB-11-48W 48 in Multi- Purpose Skid Steer Bucket (Unused) S/N: ZW01061 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
5368	2024 Top Cat 4IN1BCT 72 in Multi-Purpose Skid Steer Bucket (Unused) S/N: 4IN1BCT24080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5375	2024 Kit Containers QT-SNB-84 84 in Snow /Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers QT-SNB-84 84 in Snow /Litter Skid Steer Bucket (Unused)	
5369	Asset located in: Humble, TX 2024 Suihe SSB-4 72 in Multi-Purpose Skid	-	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	
	Steer Bucket (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5377		Mid-State 84 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available
5370	Asset located in: Humble, TX 2024 Suihe SSB-4 72 in Multi-Purpose Skid Steer Bucket (Unused) S/N: Not Available	5378	Mid-State 78 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX Mid-State 84 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	
5371	2024 Wolverine MCB-11-48W 48 in Multi- Purpose Mini Skid Steer Bucket (Unused) S/N: ZW01067 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	Asset located in: Humble, TX 5380 Mid-State 78 in Snow/Litter Skid Ste (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 5381 All-Star 74 in Snow/Litter Skid Steer (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 5382 All-Star 74 in Snow/Litter Skid Steer (Unused) S/N: Not Available Usage: Not Available Usage: Not Available Usage: Not Available Asset located in: Humble, TX	5380 Mid-State 78 in Snow/Litter Skid St (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 5381 All-Star 74 in Snow/Litter Skid Stee	Mid-State 78 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 74 in Snow/Litter Skid Steer Bucket
5372	Asset located in: Humble, TX 2024 Wolverine MCB-11-48W 48 in Multi- Purpose Mini Skid Steer Bucket (Unused)		S/N: Not Available Usage: Not Available	
	S/N: ZW01017 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX	
5373	2024 Wolverine MCB-11-48W 48 in Multi- Purpose Skid Steer Bucket (Unused) S/N: ZW01073 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	 5383	Mid-State 72 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5384	Mid-State 72 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5395	All-Star 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
5385	All-Star 68 in Snow/Litter Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5396	Teran BKT26272 72 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 0374 C/W: 0.45m3 with 8 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Humble, TX
5386	Mid-State 84 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX	5397	Mid-State 68 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
5387	All-Star 80 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX	5398	All-Star 68 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
5388	All-Star 80 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX	5399	2024 Landhonor RB-14-66W 66 in Rock Skid Steer Bucket (Unused) S/N: HL00220 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5389	Teran BKT26278 78 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: 4160 C/W: 0.5m3 with 8HD Tips for CAT 226 - 299 Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5390	Asset located in: Humble, TX 2024 Kit Containers QT-DB-T78 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth	5400	2024 Kit Containers QT-DB-S66 66 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5401	Mid-State 60 in Skid Steer Bucket (Unused) S/N: Not Available
5391	All-Star 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available		C/W: teeth Usage: Not Available Asset located in : Humble, TX
5392	Asset located in: Humble, TX All-Star 78 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available	5402	Teran BKT26260 60 in Skid Steer Bucket - Fits Cat 226 (Unused) S/N: Not Available C/W: 0.35m3 with 7 HD Tips to fit Cat 226 - 299 Usage: Not Available Asset located in: Humble, TX
5393	Asset located in: Humble, TX Mid-State 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX	5403	2024 Wolverine TDB-11-84W 84 in Skid Steer Bucket (Unused) S/N: ZW00607 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5394	All-Star 74 in Skid Steer Bucket (Unused) S/N: Not Available C/W: teeth Usage: Not Available Asset located in: Humble, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

	Dataila	l ot #	Details
Lot #	Details	Lot #	
5404	2024 Wolverine TDB-11-84W 84 in Skid Steer Bucket (Unused)	5414	All-Star 72 in Skid Steer Bucket (Unused) S/N: Not Available
	S/N: ZW00610		Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	5415	Mid-State 72 in Skid Steer Bucket (Unused)
	THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5405	Cat 74 in Skid Steer Bucket (Unused)	5416	Mid-State 72 in Skid Steer Bucket (Unused)
	S/N: A4229BK20432		S/N: Not Available
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in : Humble, TX
5406	Mid-State 80 in Skid Steer Bucket (Unused)	5417	All-Star 72 in Skid Steer Bucket (Unused)
3400	S/N: Not Available	3417	S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5407	2024 Kit Containers QT-DB-S78 78 in Skid	5418	2024 Wolverine TDB-11-72W 72 in Skid Steer
	Steer Bucket (Unused) S/N: Not Available		Bucket (Unused) S/N: ZW00628
	Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE
	Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5408	Mid-State 78 in Skid Steer Bucket (Unused)	5440	THE ACTUAL PRODUCT
	S/N: Not Available		Usage: Not Available
	Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX
5409	2024 Wolverine TDB-11-78W 78 in Skid Steer	5419	2024 Wolverine TDB-11-72W 72 in Skid Steer Bucket (Unused)
0407	Bucket (Unused)		S/N: ZW00623
	S/N: ZW00624		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		MAY NOT BE AN EXACT REPRESENTATION OF
	MAY NOT BE AN EXACT REPRESENTATION OF		THE ACTUAL PRODUCT Usage: Not Available
	THE ACTUAL PRODUCT Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5420	Mid-State 68 in Skid Steer Bucket (Unused)
5410	2024 Wolverine TDB-11-78W 78 in Skid Steer		S/N: Not Available
	Bucket (Unused)		Usage: Not Available
	S/N: ZW00628 C/W: THE PRODUCT IMAGES SHOWN ARE		Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND	5421	Mid-State 68 in Skid Steer Bucket (Unused)
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5422	2024 Kit Containers QT-DB-T66 66 in Skid
5411	All-Star 78 in Skid Steer Bucket (Unused)		Steer Bucket (Unused)
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5412	All-Star 74 in Skid Steer Bucket (Unused)	5423	2024 Wolverine TDB-11-66W 66 in Skid Steer
	S/N: Not Available		Bucket (Unused)
	Usage: Not Available		S/N: ZW00611
	Asset located in: Humble, TX	_	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5413	74 in Skid Steer Bucket (Unused)		MAY NOT BE AN EXACT REPRESENTATION OF
	S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
		1	

Lot #	Details	Lot #	Details
5424	2024 Wolverine TDB-11-66W 66 in Skid Steer Bucket (Unused) S/N: ZW00607 C/W: THE PRODUCT IMAGES SHOWN ARE	5439	68 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5440	68 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5425	All-Star 60 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5441	68 in Skid Steer Bucket S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
5426	Mid-State 60 in Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5442	THE INSPECTION REPORT Asset located in: Humble, TX 66 in Skid Steer Bucket S/N: Not Available
5430	80 in Snow/Litter Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5443	Usage: Not Available Asset located in: Humble, TX 67 in Skid Steer Bucket S/N: Not Available
5431	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available	5444	C/W: teeth Usage: Not Available Asset located in: Humble, TX Quantity of (3) Skid Steer Bucket
5432	Asset located in: Humble, TX 80 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: (1) 67 in., (1) 74 in. & (1) 80 in. Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
5433	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	5445	Asset located in: Humble, TX Quantity of (3) Skid Steer Bucket S/N: Not Available C/W: (2) 67 in. & (1) 80 in. Usage: Not Available
5434	80 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5446	Asset located in: Humble, TX 2019 Bobcat 6731418 Skid Steer Bucket S/N: BS91502 Usage: Not Available Asset located in: Humble, TX
5435	74 in Skid Steer Bucket S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	5447 5448	Wolverine 48 in 4-in-1 Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers QT-TS-40 Stump Skid
5436	Asset located in: Humble, TX Bobcat 72 in Skid Steer Bucket S/N: 6732305 C/W: teeth Usage: Not Available	5449	Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Skid Steer Tree Spade (Unused)
5437	Asset located in: Humble, TX Cat 74 in Skid Steer Bucket S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5438	Asset located in: Humble, TX 68 in Skid Steer Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5450	Skid Steer Tree Spade (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5451 5452	All-Star Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star Stump Skid Steer Bucket (Unused)	5462	2024 AGT STSD10 Skid Steer Seeder (Unused) S/N: STSD1024080601A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Usage: Not Available Asset located in: Humble, TX
5453	All-Star Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5463	2024 AGT STSD10 Skid Steer Seeder (Unused) S/N: STSD1024080602A C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5454	All-Star Stump Skid Steer Bucket (Unused) S/N: Not Available Usage: Not Available	5464	Usage: Not Available Asset located in: Humble, TX 2024 Raytree RMLS18T 18 ton Skid Steer Log
5455	Asset located in: Humble, TX 2024 Kit Containers QT-RD Skid Steer Root Digger (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Splitter (Unused) S/N: LS20240825010 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5456	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408255 Usage: Not Available Asset located in: Humble, TX	5465	Asset located in: Humble, TX 2024 Landhonor HAG-12-24Q 88 in Skid Steel Bale Accumulator Grapple (Unused) S/N: HL00674 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5457	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408256 Usage: Not Available		
5458	Asset located in: Humble, TX 2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408258 Usage: Not Available Asset located in: Humble, TX	5466	2024 Landhonor HAG-12-24Q 88 in Skid Steer Bale Accumulator Grapple (Unused) S/N: HL00675 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5459	2024 Handy HLS35 Skid Steer Log Splitter (Unused) S/N: LS202408257		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5467	2024 Landhonor RG-11-5000G Skid Steer Rotating Tree Clamp (Unused) S/N: HL00308
5460	2024 Handy HFB52 52 in Skid Steer Feller Buncher (Unused) S/N: FB202408112 Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5461	2024 Handy HSRP72 72 in Skid Steer Rock Picker (Unused) S/N: RP202408461 Usage: Not Available Asset located in: Humble, TX	5468	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused) S/N: LS20240825009 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5469	2024 Raytree RMLS18T 18 ton Skid Steer Log Splitter (Unused) S/N: LS20240825011 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	5478	2024 Landhonor FW-13-15000G 15000 Lb Skid Steer Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5479	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00124
5470	2024 Wolverine BSH-12-75D Skid Steer Bale Squeeze (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: ZW00365 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5480	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL0122 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5481	2024 Landhonor TP2-13-08D Skid Steer Post
5471	Erskine CM18 18 in Skid Steer Planer S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Puller (Unused) S/N: HL00123 Usage: Not Available Asset located in: Humble, TX
5472	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused) S/N: HL00005 Usage: Not Available Asset located in: Humble, TX	5482	2024 Landhonor TP2-13-08D Skid Steer Post Puller (Unused) S/N: HL00121 Usage: Not Available Asset located in: Humble, TX
5473	2024 Landhonor DPC-21-13W Skid Steer Pole Clamp (Unused) S/N: HL00003 Usage: Not Available	5483	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5474	Asset located in: Humble, TX 2024 Top Cat ECSSRB Skid Steer Tree Shear (Unused) S/N: ECSSRB24080501B	5484	All-Star Skid Steer Tree Shear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5485	All-Star Skid Steer Post Puller (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5486	All-Star Skid Steer Post Puller (Unused)
5475	2024 Handy HSRC12 12 in Rotating Skid Steer Pole Clamp (Unused)		S/N: Not Available Usage: Not Available
	S/N: RC202408621		Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5487	2024 Industrias America Skid Steer Post Puller (Unused)
5476	2024 Handy HRTH43 43 in Skid Steer Rock Handler (Unused)	1	S/N: HPOST202421214 Usage: Not Available Asset located in : Humble, TX
	S/N: RTH202408489 Usage: Not Available Asset located in : Humble, TX	5488	2024 Industrias America Skid Steer Post Puller (Unused)
5477	2024 Landhonor RP-12-72W 72 in Skid Steer Rock Picker (Unused)		S/N: POST202421192 Usage: Not Available Asset located in : Humble, TX
	S/N: HL00006 Usage: Not Available Asset located in : Humble, TX	5489	2024 Industrias America Skid Steer Post Puller (Unused) S/N: HPOST202421209 Usage: Not Available
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5490	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5501	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408277 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	
5491	2024 Kit Containers QT-TB-60 Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES	
5492	All-Star Tree Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	
5493	All-Star Tree Skid Steer Boom (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5503	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04749 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES	
5494	2024 Landhonor HRB-11-127A 42 in Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00005 Usage: Not Available		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in : Humble, TX	
5495	Asset located in: Humble, TX 2024 Landhonor HRB-11-127A 42 in Hydraulic Rotating Skid Steer Forks (Unused) S/N: HL00006 Usage: Not Available Asset located in: Humble, TX		2024 Wolverine PFA-11-3300G 48 in Skid Ste Forks (Unused) S/N: ZW04809 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUC	
5496	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408272 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	5505	5505 2024 Wolverine PFA-11-3300 Forks (Unused) S/N: ZW04816	Asset located in: Humble, TX 2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused)
5497	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408276 C/W: Fork Positioner Usage: Not Available		SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
5498	Asset located in: Humble, TX 2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408273 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX 2024 Handy HF2T 48 in Skid Steer Forks	5506	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04813 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	(Unused) S/N: HF202408274 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	5507	2024 Wolverine PFA-11-3300G 48 in Skid Steer Forks (Unused) S/N: ZW04821 C/W: Fork Positioner, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES	
5500	2024 Handy HF2T 48 in Skid Steer Forks (Unused) S/N: HF202408275 C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5508	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	5517	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5509	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available Asset located in: Humble, TX	5518 5519	JBX 4000 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX JBX 4000 48 in Skid Steer Forks (Unused)
5510	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available	5520	S/N: Not Available Usage: Not Available Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available
5511	Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available C/W: Fork Positioner Usage: Not Available	5521	Usage: Not Available Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available
5512	Asset located in: Humble, TX Quantity of (10) 2024 Mower King SA 48 in Skid Steer Forks (Unused) S/N: SA24080601A-04A/SA24080401B-06B Usage: Not Available	5522	Usage: Not Available Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
5513	Asset located in: Humble, TX 2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: HI 00030	5523	Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available
	S/N: HL00930 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5524	Asset located in: Humble, TX All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5514	2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: HL00931 C/W: THE PRODUCT IMAGES SHOWN ARE	5525	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5526	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5515	2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: HL00932 C/W: THE PRODUCT IMAGES SHOWN ARE	5527	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5528	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5516	2024 Landhonor PF-11-3500G 48 in Skid Steer Forks (Unused) S/N: HL00929 C/W: THE PRODUCT IMAGES SHOWN ARE	5529	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5530	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5531	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5542	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available	
5532	2024 Kit Containers MSS-45-FF-42 42 in Mini		Asset located in: Humble, TX	
	Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5544	2024 Trojan SPF15 48 in Skid Steer Forks (Unused) S/N: 124435 Usage: Not Available	
5533	2024 Kit Containers MSS-45-FF-42 42 in Mini		Asset located in: Humble, TX	
	Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5545	All-Star 60 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
5534	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5546	2024 Wolverine MPF-11-2500G 30 in Mini Skid Steer Forks (Unused) S/N: ZW01074 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5535	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in: Humble, TX	5547	2024 Wolverine MPF-11-2500G 30 in Mini Skid	
5536	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Steer Forks (Unused) S/N: ZW01078 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
5537	2024 Kit Containers QT-45-FF-42 42 in Skid		Asset located in: Humble, TX	
	Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5548	2024 Wolverine MPF-11-2500G 30 in Mini Skid Steer Forks (Unused) S/N: ZW01075 C/W: THE PRODUCT IMAGES SHOWN ARE	
5538	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
5539	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5549	Steer Forks (Unused) S/N: ZW01076 C/W: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONLY	
5540	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused)			Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5550	2024 Wolverine MPF-11-2500G 30 in Mini Skid Steer Forks (Unused)	
5541	2024 Kit Containers QT-45-FF-42 42 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: ZW01077 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5551	Bradco 60 in Skid Steer Forks S/N: 458961 Usage: Not Available	5565	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5552	All-Star 48 in Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5566	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01293 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5553	36 in Mini Skid Steer Forks (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5554	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5567	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01291 C/W: THE PRODUCT IMAGES SHOWN ARE
5555	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5556	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5568	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01284 C/W: THE PRODUCT IMAGES SHOWN ARE
5557	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5558	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5569	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01285 C/W: THE PRODUCT IMAGES SHOWN ARE
5559	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5560	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5570	2024 Landhonor BS-12-2500G 45 in Skid Steer Bale Spear (Unused) S/N: HL01292 C/W: THE PRODUCT IMAGES SHOWN ARE
5561	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5562	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5571	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5563	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5572	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5564	All-Star Skid Steer Fork Frame (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5573	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5574	All-Star Skid Steer Bale Spear (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5583	2024 Kit Containers QT-TM 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available Usage: Not Available
5575	All-Star Skid Steer Bale Spear (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5584	All-Star 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available Usage: Not Available
5576	All-Star Skid Steer Bale Spear (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5585	All-Star 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available Usage: Not Available
	·	_	Asset located in: Humble, TX
5577	Armstrong 42 in Skid Steer Bale Spear S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5586	All-Star 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available Usage: Not Available
5578	2024 Landhonor UHA-16-3000G 2 in Skid Steer		Asset located in: Humble, TX
	Hitch Receiver (Unused) S/N: HL01146 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5587	All-Star 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		5588	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: HL00673
5579	Asset located in: Humble, TX 2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: HL01145 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5589	2024 Landhonor PHA-16-2C Skid Steer 3-Point Adapter (Unused) S/N: HL00674
5580	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused) S/N: HL01148 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5590	2024 Kit Containers 2YFT-SST 2 cu yd Skid Steer Dump Hopper (Unused) S/N: Not Available
5581	2024 Landhonor UHA-16-3000G 2 in Skid Steer Hitch Receiver (Unused)		Usage: Not Available Asset located in : Humble, TX
	S/N: HL01147 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	5591	2024 Kit Containers 2YFT-SST 2 cu yd Skid Steer Dump Hopper (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5592	Quantity of (10) Kit Containers QT-F-BLANK
5582	2024 Kit Containers QT-TM 2 in Skid Steer Receiver Hitch (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5593	Quantity of (4) 2024 Landhonor UAP-16-45W Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available	5603	2024 Jisan JSV765S Rotating Demolition Pulverizer - Fits Cat 320/325 (Unused) S/N: 24042901023 Usage: Not Available Asset located in: Humble, TX
5594	Asset located in: Humble, TX Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available	5604	2024 Elephant JXJMQC345 51 in Excavator Grapple - Fits Cat 345 (Unused) S/N: 24062200311 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5605	2024 Elephant JXJMQC336 46 in Excavator Grapple - Fits Cat 336 (Unused)
5595	Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate (Unused)		S/N: 2406220038 Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5606	2024 Jisan JXJMQC320 41 in Excavator Grapple - Fits Cat 320 (Unused) S/N: 2406220167
5596	Quantity of (10) 2024 Kit Containers QT-F- BLANK Skid Steer Attachment Mounting Plate		Usage: Not Available Asset located in : Humble, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5607	2024 KJ AMSR60 Excavator Grapple - Fits Cat 307 / 5 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5597	Quantity of (5) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5598	Asset located in: Humble, TX Quantity of (4) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5608	2024 KJ AMSR60 Excavator Grapple - Fits Cat 307 / 5 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
5599	Quantity of (3) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Humble, TX Teran THH3500 Hydraulic Breaker - Fits Cat
	Asset located in: Humble, TX		345 (Unused) S/N: Not Available
5600	Quantity of (4) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: For CAT 345/349EL/352FL "TB" Linkage - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And
5601	All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available		Operations Manual. Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5610	2024 JESON HM3300 Hydraulic Breaker (Unused)
5602	Quantity of (5) All-Star Skid Steer Attachment Mounting Plate (Unused) S/N: Not Available		S/N: JQHM010 Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Usage: Not Available Asset located in: Humble, TX	5611	2024 Jisan JSB3200B Hydraulic Breaker - Fits Cat 330/336 (Unused) S/N: 2407191 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5612	2024 JESON HM3200 Hydraulic Breaker (Unused) S/N: JQHM011 Usage: Not Available Asset located in: Humble, TX	5620	Teran THH1600B Hydraulic Breaker - Fits Cat 315 (Unused) S/N: CAM205D14HZ C/W: For Cat 315 - 125mm Tool - and all 15 Ton Excavators - Box Type - With Auto - Lubrication Pre-Disposition. Box Type - All New
5613	2024 JESON HM3150 Hydraulic Breaker (Unused) S/N: JQHM006 Usage: Not Available Asset located in: Humble, TX		Teran Hydraulic Hammers are supplied with: 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual Usage: Not Available
5614	2024 JQ POWER JQB3000STB Hydraulic Breaker - Fits Cat 320/325 (Unused) S/N: 814055724 Usage: Not Available Asset located in: Humble, TX	5621	Asset located in: Humble, TX 2024 Jisan JSB800B Hydraulic Breaker - Fits Cat 311/312/314 (Unused) S/N: 2407217
5615	·	_	Usage: Not Available Asset located in: Humble, TX
55.5	Cat 320 (Unused) S/N: CEH637D14HZ C/W: For all 18-25 Ton 332mm FS - With Auto- Lubrication Pre-Disposition Box Type Cat 320 B Linkage, Komatsu PC200/220 (80mm 12.90 in (330 mm) Face Spread 18.00 in (450 mm) Front pin to back)- All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set Of N2 Nitrogen Charging Kit With N2 Bottle And Pressure Gauge, 1 Spare Seal Kit, Toil Box With Maintenance Tools And Operations Manual. Usage: Not Available	5622	2024 KJ AMB100 Hydraulic Breaker - Fits Cat 312 / 11 - 16 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		5623	2024 KJ AMB100 Hydraulic Breaker - Fits Cat 312 / 11 - 16 ton (Unused)
5616	Asset located in: Humble, TX 2024 Jisan JSB2200B Hydraulic Breaker - Fits Cat 320/325 (Unused) S/N: CP2404394 Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5617	2024 Jisan JSB2200T Hydraulic Breaker - Fits	5624	2024 KJ AMB68 Hydraulic Breaker - Fits Cat
	Cat 320/325 (Unused) S/N: 2406134 Usage: Not Available Asset located in: Humble, TX		304 / 4 - 7 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5618	2024 Elephant EPB2200B Hydraulic Breaker - Fits Cat 320/325 (Unused) S/N: CP2407162		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble TX	5625	2024 KJ AMB68 Hydraulic Breaker - Fits Cat
5619	Asset located in: Humble, TX 2024 Elephant EPB2200T Hydraulic Breaker - Fits Cat 320/325 (Unused) S/N: CP2406052 Usage: Not Available Asset located in: Humble, TX		304 / 4 - 7 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		5626	2024 KJ AMB68 Hydraulic Breaker - Fits Cat 304 / 4 - 7 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5627	2024 Elephant EPB800T Hydraulic Breaker - Fits Cat 311/312/314 (Unused) S/N: CP2406100 Usage: Not Available Asset located in: Humble, TX	5637	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1222/CH7022G1209 Usage: Not Available Asset located in: Humble, TX
5628	2024 JESON HM3070 Hydraulic Breaker (Unused) S/N: JQHM012 Usage: Not Available Asset located in: Humble, TX	5638	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1212/CH7022G1223 Usage: Not Available Asset located in: Humble, TX
5629	2024 Jisan JSB430B Hydraulic Breaker - Fits Cat 307/307B/308/308B (Unused) S/N: 2404466 Usage: Not Available Asset located in: Humble, TX	5639	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1207/CH7022G1210 Usage: Not Available Asset located in: Humble, TX
5630	2024 Jisan JSB400B Hydraulic Breaker - Fits Cat 304/305 (Unused) S/N: CP2404209 Usage: Not Available Asset located in: Humble, TX	5640	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1208/CH7022G1221 Usage: Not Available Asset located in: Humble, TX
5631	2024 Jisan JSB400B Hydraulic Breaker - Fits Cat 304/305 (Unused) S/N: 2404208 Usage: Not Available Asset located in: Humble, TX	5641	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1219/CH7022G1220 Usage: Not Available Asset located in: Humble, TX
5632	Teran THH400B-CAT308 Hydraulic Breaker - Fits Cat 307 (Unused) S/N: CAA0137B54HR C/W: For Mini Excavators CAT 307/308 - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available	5642	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: 22G1227/22G1216 Usage: Not Available Asset located in: Humble, TX
		5643	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1226/CH7022G1225 Usage: Not Available Asset located in: Humble, TX
5633	Asset located in: Humble, TX 2024 Elephant EPB400T Hydraulic Breaker - Fits Cat 304/305 (Unused) S/N: CP2406111 Usage: Not Available	5644	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: 22G1217/22G1218 Usage: Not Available Asset located in: Humble, TX
5634	Asset located in: Humble, TX 2024 Elephant EPB400T Hydraulic Breaker - Fits Cat 304/305 (Unused)	5645	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1229/CH7022G1230 Usage: Not Available
	S/N: CP2406110 Usage: Not Available Asset located in : Humble, TX	5646	Asset located in: Humble, TX Quantity of (2) Connect Work Tools CH70-22G
5635	2024 Trojan TH50 Hydraulic Breaker (Unused) S/N: SB40YOM20246078 C/W: 2 moil point, tool box Usage: Not Available		Hydraulic Breaker (Unused) S/N: 22G1228/22G1213 Usage: Not Available Asset located in: Humble, TX
5636	Asset located in: Humble, TX 2024 Trojan Th35 Hydraulic Breaker (Unused) S/N: SB30YOM20246070 C/W: 2 moil point, tool box Usage: Not Available Asset located in: Humble, TX	5647	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1224/CH7022G1211 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5648	Quantity of (2) Connect Work Tools CH70-22G Hydraulic Breaker (Unused) S/N: CH7022G1214/CH7022G1215 Usage: Not Available	5659	2024 Jisan BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: 24042900256 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5649	Quantity of (2) Connect Work Tools CH70 Hydraulic Breaker S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5660	2024 Jisan BKT34572HD 72 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: 24062202047 Usage: Not Available Asset located in: Humble, TX
5650	Quantity of (2) Connect Work Tools CH70 Hydraulic Breaker S/N: CH7021J1139/CH7021H1093 Usage: Not Available Asset located in: Humble, TX	5661	2024 Jisan BKT34572SKEL 72 in Skeleton Excavator Bucket - Fits Cat 345 (Unused) S/N: 24062202089 Usage: Not Available Asset located in: Humble, TX
5651	2023 FRD FX475QTV Hydraulic Breaker S/N: FX4752383 Usage: Not Available Asset located in: Humble, TX	5662	2024 JESON BKT 336-66 66 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 027 Usage: Not Available
5652	2020 TOKU TNB-151 Hydraulic Breaker S/N: 151LU215383 Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	5663	Asset located in: Humble, TX 2024 JESON BKT 345-66 66 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: JQ BKT 036 Usage: Not Available Asset located in: Humble, TX
5653	Cat H95 Backhoe Hydraulic Breaker S/N: D9H00414 Usage: Not Available Asset located in: Humble, TX	5664	2024 JESON BKT 345-66 66 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: JQ BKT 035
5654	Kent KHB8G Hydraulic Breaker S/N: HB8G1864		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5665	2024 JESON BKT 336-66 66 in Digging Excavator Bucket - Fits Cat 336 (Unused)
5655	Quantity of (2) Kota 350 Mini Hydraulic Breaker S/N: Not Available Usage: Not Available		S/N: JQ BKT 026 Usage: Not Available Asset located in : Humble, TX
5656	Asset located in: Humble, TX Cat H120ES Hydraulic Breaker S/N: HHE01524 Usage: Not Available Asset located in: Humble, TX	5666	2024 Jisan BKT36066HD 66 in Digging Excavator Bucket - Fits Komatsu PC360 (Unused) S/N: 240622020118 Usage: Not Available Asset located in: Humble, TX
5657	Teran BKT336D72HD 72 in Digging Excavator Bucket - Fits Cat 336D (Unused) S/N: 4279 C/W: DB Linkage - 2.00m3 for Cat 336D, 336D2, 336E, 336F, 340D2, 340F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 6RC Tips - DB Linkage Usage: Not Available Asset located in: Humble, TX	5668	Teran BKT34560HD 60 in Digging Excavator Bucket - Fits Cat 345 (Unused) S/N: 1351 C/W: TB Linkage - 2.17m3 for CAT 345, 345D /349D, 349D2, 349E, 349F, 352F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 5RC Tips Usage: Not Available Asset located in: Humble, TX
5658	2024 JESON BKT 336-72 72 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 032 Usage: Not Available Asset located in: Humble, TX	5669	2024 JESON BKT 336-60 60 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: JQ BKT 024 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5670	2024 KJ AM3660 60 in 1.5 cyd Digging Excavator Bucket - Fits Cat 336 / 30 - 38 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5678	2024 Jisan BKT22054HD 54 in Digging Excavator Bucket - Fits Komatsu PC220 (Unused) S/N: 2405150378 Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5679	Teran BKT325D48HD 48 in Digging Excavator Bucket - Fits Cat 325D (Unused) S/N: 0263
5671	2024 Elephant BKT336D60HD 60 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: 24072900124 Usage: Not Available Asset located in: Humble, TX		C/W: CB Linkage - 1.07m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 6RC Tips Usage: Not Available
5672	2024 Jisan BKT336D60HD 60 in Digging Excavator Bucket - Fits Cat 336 (Unused) S/N: 24042900236 Usage: Not Available Asset located in: Humble, TX	5680	Asset located in: Humble, TX 2024 JESON BKT 320-48 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: JQ BKT 013 Usage: Not Available Asset located in: Humble, TX
5673	2024 JESON BKT 220-54 54 in Digging Excavator Bucket - Fits Komatsu PC220 (Unused) S/N: JQ BKT 019 Usage: Not Available Asset located in: Humble, TX	5681	2024 KJ AM2048 48 in 1.2 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5674	2024 KJ AM2054 54 in 1.3 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5682	2024 KJ AM2048 48 in 1.2 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
5675	2024 KJ AM2054 54 in 1.3 cyd Digging Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5683	2024 Elephant BKT32048HD 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 24051503624 Usage: Not Available Asset located in: Humble, TX
5676	2024 Elephant BKT22054HD 54 in Digging Excavator Bucket - Fits Komatsu PC200/220 (Unused) S/N: 2405150371 Usage: Not Available	5684	2024 Jisan BKT32048HD 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 240429002158 Usage: Not Available Asset located in: Humble, TX
5677	Asset located in: Humble, TX 2024 Jisan BKT32054HD 54 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 24042900210 Usage: Not Available Asset located in: Humble, TX	5685	2024 JESON BKT320-48 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: JQBKT012 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5686	2024 JESON BKT 320-48 48 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: JQ BKT 011 Usage: Not Available Asset located in: Humble, TX	5699	Teran BKT30724 24 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 01086 C/W: For Cat 307/308 0.21m3 With Side Cutters Reinforcement Plates and 4HD Tips Usage: Not Available
5692	Teran BKT30742 42 in Digging Excavator		Asset located in: Humble, TX
	S/N: 1207 C/W: For Cat 307/308 0.41m3 with Side Cutters, Reinforcement Plates and 7HD Tips Usage: Not Available Asset located in: Humble, TX	5700	Teran BKT32018HD 18 in Digging Excavator Bucket - Fits Cat 320 (Unused) S/N: 5593 C/W: B Linkage - 0.29m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip
5693	Teran BKT31242 42 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 0812		Protectors, Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in : Humble, TX
	C/W: 312 Linkage - 0.67m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Humble, TX	5701	Teran BKT305C12 12 in Digging Excavator Bucket - Fits Cat 305 (Unused) S/N: 2922 C/W: 0.08m3 With Side Cutters Reinforcement Plates and 3HD Tips
5694	Teran BKT32039HD 39 in Digging Excavator		Usage: Not Available Asset located in : Humble, TX
	Bucket - Fits Cat 320 (Unused) S/N: 2505 C/W: B Linkage - 0.68m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 5HD Tips Usage: Not Available	5702	EBI 60 in Digging Excavator Bucket - Fits Cat 330CL, 330BL, 330DL S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5703	Cat 50 in Digging Excavator Bucket S/N: Not Available
5695	Teran BKT31236 36 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5382 C/W: 312 Linkage - 0.48m3 for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 5HD Tips		Usage: Not Available Asset located in: Humble, TX
		5704	Hensley 48 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5705	CEI 48 in Digging Excavator Bucket - Fits Cat 330CL, 330BL, 330DL
5696	Teran BKT30736TRAPEZ 36 in Trapezoidal Excavator Bucket - Fits Cat 307 (Unused) S/N: Not Available C/W: For Cat 307/308 0.21m3 16/36in - 2 Tips 75 degree Angle	5706	S/N: Not Available Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX 42 in Digging Excavator Bucket - Fits John
5697	Teran BKT30730 30 in Digging Excavator Bucket - Fits Cat 307 (Unused) S/N: 2419 C/W: For Cat 307/308 0.27m3 with Side	5706	Deere 450LC S/N: 77031 Usage: Not Available Asset located in: Humble, TX
	Cutters, Reinforcement Plates and 5HD Tips Usage: Not Available Asset located in: Humble, TX	5707	42 in Excavator Bucket S/N: Not Available Usage: Not Available
5698	Teran BKT31224 24 in Digging Excavator Bucket - Fits Cat 312 (Unused) S/N: 5566 C/W: 312 Linkage - 0.32m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters, Reinforcement Plates and 3HD Tips Usage: Not Available Asset located in: Humble, TX	5708	Asset located in: Humble, TX Cat 36 in Digging Excavator Bucket S/N: NBC29401 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5709	Cat 42 in Digging Excavator Bucket S/N: MHJ82307 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	5721	2021 Teran BKT32024HD 24 Inch Heavy Duty Excavator Bucket S/N: 2932 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5722	2021 Teran BKT32024HD 24 Inch Heavy Duty
5710	Esco 38 in Digging Excavator Bucket - Fits Cat 330CL, 330BL, 330DL S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5723	Excavator Bucket S/N: 4980 Usage: Not Available Asset located in: Humble, TX
5711	CP 36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5725	2021 Teran BKT336D24HD 24 Inch Heavy Duty Excavator Bucket S/N: 1281 Usage: Not Available Asset located in: Humble, TX
5712	Hensley 36 in Digging Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5724	2021 Teran BKT32024HD 24 Inch Heavy Duty Excavator Bucket S/N: 5761 Usage: Not Available
5713	Geith 36 in Digging Excavator Bucket S/N: 454340 Usage: Not Available Asset located in: Humble, TX	5725	Asset located in: Humble, TX Cat 18 in Digging Excavator Bucket - Fits Cat 303 S/N: A4234BK30087
5714	Cat 36 in Digging Excavator Bucket S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
5715	Usage: Not Available Asset located in: Humble, TX Cat 36 in Digging Excavator Bucket - Fits Cat 349E	5726	Cat 24RB148 18 in Digging Excavator Bucket S/N: CH21BBK25556 Usage: Not Available Asset located in: Humble, TX
	S/N: MH203217 Usage: Not Available Asset located in : Humble, TX	5727	Cat 18 in Digging Excavator Bucket - Fits Cat 302 (Unused) S/N: CH21CBK25260
5716	Cat 32 in Digging Excavator Bucket S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5728	Cat 18 in Digging Excavator Bucket - Fits Cat 302
5717	CF 30 in Digging Excavator Bucket - Fits John Deere 450DLC S/N: 166561		S/N: 4422ABK20214 Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	5729	Cat 24RB149 11 in .04 cyd Digging Excavator
5718	Asset located in: Humble, TX 2018 Cat 30 in Digging Excavator Bucket - Fits Cat 336 S/N: MHC07375 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Lleage: Net Available		Bucket (Unused) S/N: 44229BK20035 C/W: 34.9 mm Diameter Pins, 196 mm Center of Pin Boss to Center of Pin Boss, 165 mm Inside to Inside Pin Boss Spacing Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5730	Cat 13 in Digging Excavator Bucket - Fits Cat
5719	Esco 24 in Digging Excavator Bucket - Fits Cat 330CL, 330BL, 330DL S/N: Not Available Usage: Not Available	3/30	308 S/N: A4221BK23939 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5731	Cat 13 in Digging Excavator Bucket
5720	24 in Digging Excavator Bucket - Fits Cat 320 S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: A4229BK21597 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
5732	Cat 24RB152 11 in .08 cyd Digging 305 12 BKT Excavator Bucket (Unused) S/N: A422ABK30595 C/W: 44 mm Center of Pin Boss to Center of Pin Boss, 212 mm Inside to Inside Pin Boss Spacing Usage: Not Available	5742 5743	2024 Jisan BKT32048SKEL 48 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 24042900116 Usage: Not Available Asset located in: Humble, TX Teran BKT31248SKEL 48 in Skeleton
	Asset located in: Humble, TX	07 .0	Excavator Bucket - Fits Cat 312 (Unused)
5733	Quantity of (2) Mini Excavator Attachments (Unused) S/N: Not Available C/W: 20 in. bucket, 12 in grapple Usage: Not Available Asset located in: Humble, TX		S/N: 0482 C/W: 312 Linkage - 0.77m3 for CAT 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F with Side Cutters and 5HD Tips Usage: Not Available Asset located in: Humble, TX
5735	2024 Elephant BKT336D72SKEL 72 in Skeleton Excavator Bucket - Fits Cat 336 (Unused) S/N: 24062200418 Usage: Not Available Asset located in: Humble, TX	5744	2024 JESON BKT320-48SKEL 48 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: JQBKTS004 Usage: Not Available Asset located in: Humble, TX
5736	2024 KJ AM3666S 66 in 2 cyd Skeleton Excavator Screening Bucket - Fits Cat 336 / 30 - 38 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5745	2024 KJ AM2048S 48 in 1.28 cyd Skeleton Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5737	Teran BKT336D66SKEL 66 in Skeleton Excavator Bucket - Fits Cat 336D (Unused) S/N: 0252 C/W: DB Linkage - 1.55m3 for CAT 336D, 336D2, 336E, 336F, 340D2, 340F with Side Cutters, Side Protectors, Heel Shrouds, Lip Protectors, Reinforcement Plates and 5RC Tips - DB Linkage Usage: Not Available Asset located in: Humble, TX	5746	2024 KJ AM2048S 48 in 1.28 cyd Skeleton Excavator Bucket - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5738 5740	2024 Jisan BKT336D66SKEL 66 in Skeleton Excavator Bucket - Fits Cat 336 (Unused) S/N: 24062202078 Usage: Not Available Asset located in: Humble, TX 2024 Jisan BKT32060SKEL 60 in Skeleton	5749	Teran BKT30742SKEL 42 in Skeleton Excavator Bucket - Fits Cat 307 (Unused) S/N: 3025 C/W: 0.39m3 for Cat 307, 308 with 5 HD Tips Usage: Not Available Asset located in: Humble, TX
	Excavator Bucket - Fits Cat 320 (Unused) S/N: 24062202062 Usage: Not Available Asset located in: Humble, TX	5750	Esco 60 in Skeleton Excavator Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5741	Teran BKT32054SKEL 54 in Skeleton Excavator Bucket - Fits Cat 320 (Unused) S/N: 0363 C/W: B Linkage - 1.02m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates And 6HD Tips 80mm Pins Usage: Not Available Asset located in: Humble, TX	5751	2024 Jisan BKT32078DB 78 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 240622020102 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
5758	Teran BKT32080CLN 80 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 2200 C/W: B Linkage - 0.74m3 for CAT 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available	5766	Fleco 60 in Cleanup Excavator Bucket - Fits Link-Belt 145 S/N: 68568 Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	5767	Teran RIPPER390 Excavator Ripper - Fits Cat	
5759	Teran BKTPC22072CLN 72 in Cleanup Excavator Bucket - Fits Komatsu PC220 (Unused) S/N: 4901 C/W: 0.66m3 for Komatsu PC200, PC210,		390 (Unused) S/N: 0276 C/W: JC Linkage - for Cat 390D, 390 Usage: Not Available Asset located in : Humble, TX	
	PC220, PC228, PC230, PC240, PC250, PC270, PC290 Usage: Not Available Asset located in: Humble, TX	5768	Teran RIPPER374 Excavator Ripper - Fits Cat 374 (Unused) S/N: 1326 C/W: VB Linkage - for Cat 374, 374F Usage: Not Available	
5760	Teran BKT325D72CLN 72 in Cleanup		Asset located in: Humble, TX	
	Excavator Bucket - Fits Cat 325D (Unused) S/N: 4911 C/W: CB Linkage - 0.66m3 for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F, 330D2, 330F, 335F With Side Cutters Side Protectors Heel Shrouds Lip Protectors Reinforcement Plates and 7RC Tips	5770	2024 Jisan RIPPER336D Excavator Ripper - Fits Cat 336D (Unused) S/N: 24062201619 Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in: Humble, TX	5775	Teran RIPPERJD450 Excavator Ripper - Fits John Deere 450 (Unused)	
5761	Teran BKT32072CLN 72 in Cleanup Excavator Bucket - Fits Cat 320 (Unused) S/N: 14105 C/W: B Linkage - 0.66m3 for Cat 320, 319D, 320D, 320E, 321D, 323E, 323F, 325F Usage: Not Available		S/N: 3126 C/W: For John Deere JD 450/ZX Pin Usage: Not Available Asset located in : Humble, TX	S/N: 3126 C/W: For John Deere JD 450/ZX450 110mm Pin Usage: Not Available
	Asset located in: Humble, TX		Cat 320 (Unused)	
5762	Teran BKT31260CLN 60 in Cleanup Excavator Bucket - Fits Cat 312 (Unused) S/N: 1793	5777	S/N: 24042900487 Usage: Not Available Asset located in : Humble, TX	
	C/W: 312 Linkage - 0.38m3 for Cat 312,311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Humble, TX		2024 Elephant RIPPER320 Excavator Ripper - Fits Car 329 (Unused) S/N: 24062200329 Usage: Not Available	
5763	Teran BKT30760CLN 60 in Cleanup Excavator		Asset located in: Humble, TX	
5764	Bucket - Fits Cat 307 (Unused) S/N: 3064 C/W: For Cat 307/308 0.29m3 Usage: Not Available Asset located in: Humble, TX Teran BKT30748CLN 48 in Cleanup Excavator	5778	Teran RIPPERPC220 Excavator Ripper - Fits Komatsu PC220 (Unused) S/N: 0535 C/W: For Komatsu PC200, PC210, PC220, PC228, PC230, PC240, PC250, PC270, PC290 Usage: Not Available Asset located in: Humble, TX	
	Bucket - Fits Cat 307 (Unused) S/N: 1122 C/W: For Cat 307/308 0.23m3 Usage: Not Available Asset located in: Humble, TX	5779	Teran RIPPER325D Excavator Ripper - Fits Cat 325D (Unused) S/N: 1323 C/W: CB Linkage - for Cat 325D, 324D, 324E, 326D2, 326F, 328D, 329D, 329D2, 329E, 329F,	
5765	Teran BKT305C48CLN 48 in Cleanup Excavator Bucket - Fits Cat 305 (Unused) S/N: 01076 C/W: 0.15m3 Usage: Not Available Asset located in: Humble, TX		330D2, 330F, 335F Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
5780	Teran RIPPER312 Excavator Ripper - Fits Cat 312 (Unused) S/N: 3599 C/W: 312 Linkage for Cat 312, 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Humble, TX Teran RIPPER307 Excavator Ripper - Fits Cat	5787	2024 KJ AMK20 65 in Excavator Rake - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	307 (Unused) S/N: Not Available C/W: For Cat 307/308 50mm Pin Usage: Not Available Asset located in: Humble, TX	5788	Teran RAKE305C44 44 in Excavator Rake - Fits Cat 305 (Unused) S/N: 0405 C/W: Root Rake with 13 Tines Usage: Not Available Asset located in: Humble, TX	
5782	2024 KJ AMR20 Excavator Ripper - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5789 5790	2024 Jisan THUMB20-25H 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: 24062201638 Usage: Not Available Asset located in: Humble, TX 2024 Jisan THUMB20-25H 30 in Excavator Thumb - Fits Cat 320 (Unused)	
5783	2024 KJ AMR20 Excavator Ripper - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	5791	S/N: 24062201637 Usage: Not Available Asset located in: Humble, TX 2024 KJ AMT2025 Excavator Thumb - Fits Cat	
5784	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Teran RIPPERMLT312 28 in Excavator Ripper - Fits Cat 312 (Unused)	5792	FOR ILLUSTRATION PURPOSES ONI MAY NOT BE AN EXACT REPRESEN THE ACTUAL PRODUCT Usage: Not Available	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	S/N: Not Available C/W: 312 Linkage for Cat 312 and 311D, 311F, 312D, 312D2, 312E, 312F, 313D2, 313F, 314D, 314E, 314F, 315F Usage: Not Available Asset located in: Humble, TX		2024 KJ AMT2025 Excavator Thumb - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
5785	2024 Elephant RAKE32065 65 in Excavator Rake - Fits Cat 320 (Unused) S/N: 24062200322 Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	Usage: Not Available Asset located in: Humble, TX
5786	Asset located in: Humble, TX 2024 KJ AMK20 65 in Excavator Rake - Fits Cat 320 / 17 - 24 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5793	Teran THUMB20-25 M 30 in Excavator Thumb - Fits Cat 320 (Unused) S/N: 0707 C/W: 4 Tines - For Cat 320,325 and 20 - 25 Ton Excavators Usage: Not Available Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5794	Teran THUMB12 - 15 M 26 in Excavator Thumb - Fits Cat 312 (Unused) S/N: 01034 C/W: For Cat 312, 315 and all 12-15 Ton Excavators 4 Tines Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
5795	Teran THUMB7-8M 20 in Excavator Thumb - Fits Cat 307 (Unused) S/N: Not Available C/W: Manual Thumb for Cat 307, 308 and 7 - 8 Ton Excavators Usage: Not Available Asset located in: Humble, TX	5806 5807	2024 Elephant QCCAT320 Excavator Coupler- Fits Cat 320 (Unused) S/N: 24062200345 Usage: Not Available Asset located in: Humble, TX Teran QCCAT320 Hydraulic Excavator Coupler
5796	2024 DE 3.5T-40 14 in Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		- Fits Cat 320 (Unused) S/N: 5209 C/W: B Linkage - 80mm Pins Usage: Not Available Asset located in: Humble, TX
5797	2024 DE 15 in Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5808 	Teran QCCAT312 Hydraulic Excavator Coupler - Fits Cat 312 (Unused) S/N: 6158 C/W: 312 Linkage for Cat 311, 312, 314 - 65mm Pins Usage: Not Available
5798	2024 DE 8T50 16 in Excavator Thumb (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5809	Asset located in: Humble, TX Teran QCCAT305 Excavator Coupler - Fits Cat 305 (Unused)
5799	Cat 36 in Excavator Thumb - Fits Cat 336F (Unused) S/N: THC07725 Usage: Not Available		S/N: 0512 C/W: For Cat 305 - 45mm Pins Usage: Not Available Asset located in : Humble, TX
5800	Asset located in: Humble, TX CEI 32 in Excavator Thumb - Fits Cat 330CL, 330BL, 330DL S/N: Not Available	5810	Werk-Brau Backhoe Coupler - Fits Cat 420E (Unused) S/N: 5483611 Usage: Not Available Asset located in: Humble, TX
5801	Usage: Not Available Asset located in: Humble, TX 26 in Excavator Thumb S/N: Not Available	5811	Werk-Brau Quick Coupler - Fits Cat 420E (Unused) S/N: 5483511 Usage: Not Available
5802	Usage: Not Available Asset located in: Humble, TX 2024 Jisan QCCAT336D Excavator Coupler -	5812	Asset located in: Humble, TX Cat Manual Quick Coupler (Unused) S/N: EG211202929
	Fits Cat 336 (Unused) S/N: 24042900753 Usage: Not Available Asset located in: Humble, TX	5813	Usage: Not Available Asset located in: Humble, TX Cat 24RB147 Quick Coupler
5803	2024 KJ AMQ36 Excavator Coupler - Fits Cat 336 / 30 - 38 ton (Unused) S/N: Not Available	5813	S/N: 2909417-46 Usage: Not Available Asset located in : Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Cat 24RB137 Excavator Mounting Bracket (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5804	2024 KJ AMQ45 Excavator Coupler - Fits Cat 345 / 40 - 55 ton (Unused) S/N: Not Available	5815	Cat 24RB146 Quick Coupler S/N: 2668887-01 Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5816	Furukawa Hydraulic Quick Coupler S/N: TAC2105227539 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5817	2015 Furukawa Hydraulic Quick Coupler S/N: TAC701 Usage: Not Available Asset located in: Humble, TX	5827	2024 KJ AMC50 Excavator Plate Compactor - Fits Cat 307 / 4 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
5818	John Deere Excavator Boom S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5819	Material Handler Stick S/N: Not Available C/W: 16 ft 4 in Usage: Not Available Asset located in: Humble, TX	5828	2024 KJ AMC50 Excavator Plate Compactor - Fits Cat 307 / 4 - 9 ton (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
5820	Rotating Demolition Grapple S/N: Not Available Usage: Not Available Asset located in: Humble TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
5821	Asset located in: Humble, TX 2024 Raytree REDM50 50 in Excavator Mulcher - Fits 12 - 20 ton (Unused) S/N: DM20240825150 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	- 5829A 5829	Premier Excavator Auger S/N: Not Available Usage: Not Available Asset located in: Humble, TX Tramac TR-9B Excavator Plate Compactor S/N: 6332009 Usage: Not Available
	Usage: Not Available Asset located in : Humble, TX	5830	Asset located in: Humble, TX
5822	2024 Raytree REDM50 50 in Excavator Mulcher Attachment - Fits 12 - 20 ton (Unused) S/N: EDM20240825151 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of 2024 Landhero UBP-65-80 Universal Bucket Pin (Unused) S/N: Not Available C/W: (4) 65 mm x 475 mm & (4) 70 mm x 475 mm & (4) 80 mm x 550 mm,; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
5823	All-Star 45 in Excavator Mower (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5831	Asset located in: Humble, TX 2024 Landhero UBP-90-100 Universal Bucket Pin (Unused) S/N: Not Available
5824 5825	All-Star 45 in Excavator Mower (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Jisan JSC160 Plate Compactor		C/W: (4) 90 mm x 650 mm, (2)100 mm x 750 mm, ;THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
0020	Attachment - Fits Cat 320/325 (Unused) S/N: 24031104042 Usage: Not Available Asset located in: Humble, TX	Pin (Unused)	2024 Landhero UBP-25-60 Universal Bucket
5826	2024 Jisan JSC50 Excavator Plate Compactor (Unused) S/N: 24042900415 Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		5833	Quantity of (4) Teran 0860523 Bucket Pins (Unused) - Fits Cat 311,314 S/N: Not Available C/W: 65mm x 410mm Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5834	Quantity of (4) Teran 0875805 Bucket Pins (Unused) - Fits Cat 320 S/N: Not Available C/W: 80mm x 545mm - B Linkage Front & Rear Usage: Not Available	5846	60 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX . Asset located in: Lake Worth, TX
5835	Asset located in: Humble, TX Quantity of (4) Teran 1066878 Bucket Pins (Unused) - Fits Cat 315 S/N: Not Available C/W: 70mm X 508mm for Komatsu PC160 Front & Rear - 315 Linkage Usage: Not Available	-5847 5848	56 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX . Asset located in: Lake Worth, TX JRB 54 in Wheel Loader Forks - Fits Komatsu
5836	Asset located in: Humble, TX Quantity of (9) 2024 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA24080501C Usage: Not Available	5849	WA250 S/N: 08051951641/6 Usage: Not Available Asset located in: Humble, TX 48 in Fork Attachment
5837	Asset located in: Humble, TX Quantity of (9) 2024 AGT 12EX-ATA Mini Excavator Attachments (Unused) S/N: 12EX-ATA24080502C Usage: Not Available	5850	S/N: Not Available Usage: Not Available Asset located in: Humble, TX 48 in Backhoe Forks S/N: Not Available
5838	Asset located in: Humble, TX Doosan Hydraulic Excavator Coupler S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5851	Usage: Not Available Asset located in: Humble, TX 132 in 5 cyd Wheel Loader Bucket S/N: Not Available Usage: Not Available
5839	Doosan Hydraulic Excavator Coupler S/N: 077049 Usage: Not Available Asset located in: Humble, TX	5852	Asset located in: Humble, TX Cat 24RB156 127 in Q/C 966 5.5YD BKT Wheel Loader Bucket - Fits Cat 966 (Unused) S/N: 69H10265
5840	164 in Q/C Wheel Loader Forks - Fits Volvo L90 S/N: Not Available Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX . Asset located in: Lake Worth, TX	5853	Usage: Not Available Asset located in: Humble, TX Cat 127 in 5.25 cyd Q/C Wheel Loader Bucket - Fits Cat 966H S/N: ARN05717 Usage: Not Available
5841	Volvo 72 in Wheel Loader Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX Cat 72 in Q/C Wheel Loader Forks	5854	Asset located in: Humble, TX 124 in Wheel Loader Bucket S/N: Not Available Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5855	Asset located in: Humble, TX Cat 114 in 4.75 cyd Q/C Wheel Loader Bucket - Fits Cat 950M (Unused)
5843	John Deere 60 in Q/C Wheel Loader Forks S/N: PHEXSC0601291 Usage: Not Available Asset located in: Humble, TX		S/N: Z1A27351 Usage: Not Available Asset located in: Humble, TX Cat 107 in Wheel Loader Bucket - Fits Cat 930
5844	60 in Q/C Wheel Loader Forks S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5845	Asset located in: Humble, TX JRB 60 in Wheel Loader Forks S/N: DEW3211 Usage: Not Available Asset located in: Humble, TX	5857	John Deere 100 in Q/C Wheel Loader Bucket S/N: PXBUSGP270051 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5858	Cat 99 in 2.8 cyd Wheel Loader Bucket - Fits Cat 924G/930G (Unused) S/N: 14234BK20002 Usage: Not Available Asset located in: Humble, TX	5869	224 in Semi-U Dozer Blade - Fits Cat D9R S/N: 3WL37742 C/W: to Fit D9 Usage: Not Available Asset located in: Humble, TX
5859	Cat 94 in Q/C Backhoe Loader Bucket S/N: DD180408676 Usage: Not Available Asset located in: Humble, TX	5870	224 in Semi-U Dozer Blade - Fits Cat D7R S/N: Not Available C/W: to fit D7R Usage: Not Available Asset located in: Humble, TX
5860	Cat 24RB125 72 in 1.25 cyd General Purpose Wheel Loader Bucket (Unused) S/N: A4222BK23179 Usage: Not Available Asset located in: Humble, TX	5871	Wright 8B 2 Barrel Multi Shank Crawler Tractor Ripper S/N: W31H198 Usage: Not Available Asset located in: Humble, TX
5861	CEI Single Barrel Multi-Shank Motor Grader Ripper - Fits Cat 140H, 120H, 143H, 12H S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5872A	Bush Hog RDTH84 3 Point Shredder Attachment S/N: 12-06021 Usage: Not Available Asset located in: Humble, TX
5862	CEI Single Barrel Multi-Shank Motor Grader Ripper - Fits Cat 140H, 120H, 143H, 12H S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5872	Rhino 15 ft Batwing Brush Cutter S/N: 10194 C/W: 1000 PTO Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
5863	Allied 80000 lb Winch - Fits Cat D7 S/N: AW8LP3F2238C54 C/W: W/ Sweep Usage: Not Available	5873	THE INSPECTION REPORT Asset located in: Humble, TX Brown 76 in 3-Point Rotary Tree Cutter
5864	Asset located in: Humble, TX Paccar PA140-316V Crawler Tractor Winch - Fits D8		S/N: Not Available C/W: 1000 PTO Usage: Not Available Asset located in : Humble, TX
	S/N: 1200533 Usage: Not Available Asset located in: Humble, TX	5874	Frontier BC2060 69 in 3-Point Tractor Mower S/N: 1XFRC20XAG0079967 C/W: 540 PTO
5865	Paccar PA56 Crawler Tractor Winch - Fits D6 S/N: 1400478 Usage: Not Available	5875A	Usage: Not Available Asset located in: Humble, TX Bush Hog RDTH84 84 in 3-Point Tractor Mower
5866	Asset located in: Humble, TX Carco 120 Crawler Tractor Winch S/N: Not Available C/W: EQUIPMENT-FROM-A-PRIMORIS-	58/5A 	S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Humble, TX
	SERVICES-CORP-COMPANY Usage: Not Available Asset located in : Humble, TX	5875	Bush Hog HOG2874 66 in 3-Point Brush Cutter Attachment S/N: Not Available
5867	Carco 120 Crawler Tractor Winch S/N: 12407 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY	5876	C/W: 540 PTO Usage: Not Available Asset located in : Humble, TX
5868	Usage: Not Available Asset located in: Humble, TX 120 in Dozer Rake S/N: Not Available		60 in Rotary Brush Cutter S/N: Not Available C/W: 60 in Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX
	Usage: Not Available Asset located in: Humble, TX		Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX

Lot #	Details	Lot #	Details
5877	2022 Great Plains 1206NT-1975 12 ft No Till Drill S/N: GP-D1044A C/W: 6 in Spacing, Single Shoot, Rubber 2 in Packer Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL	5885 5886	John Deere M20 20 ft Flex Wing Rotary Mower S/N: Not Available C/W: 1000 PTO Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	OF THIS ITEM Asset located in: Humble, TX		2021 Land Pride RC4715 15 ft Flex Wing
5878	2022 Land Pride NTS260782 84 in Slide Hitch No Till Seeder No Till Drill S/N: 1488276 C/W: 7 in Spacing, Single Shoot Usage: Not Available		Rotary Mower S/N: 1708501 C/W: 540 PTO, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX
5879	Asset located in: Humble, TX 2021 Rome DISC 12-36 8 ft 7 in Pull Behind Offset Disc S/N: 6TPCW-27 C/W: 32 in Wave Edge Front Discs, 27 in Wave	5887	Modern Ag MDC15 15 ft Batwing Brush Cutter S/N: Not Available C/W: 540 PTO Usage: Not Available Asset located in: Humble, TX
	Edge Deer Diese 20 in Chasing FOUIDMENT	5888	Krause 1650 14 ft Heavy Harrow S/N: 239 C/W: 13 Bar, x 24 in Tines, Carbide Tips Usage: Not Available Asset located in: Humble, TX
	Asset located in: Livingston, LA	5889	84 in 3-Point Gound Plane
5880	S/N: Not Available C/W: 28 in Deep Cone Front Discs, 26 in Deep Cone Rear Discs, 20 in Spacing Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
		5890	Marathon AT-303042 Auto-Tie Horizontal Baler S/N: 108602 Usage: Not Available Asset located in: Humble, TX
5881	Asset located in: Humble, TX John Deere 8 ft 3-Point Tandem Breaking Disc S/N: Not Available C/W: 20 in Notched Front Discs, 18 in Notched Rear Discs, 9 in Spacing, Hitch Leveling, 9 ft Disc, 7 ft 6 in Leveling Ground Ripper	5891	Landhonor NC-22-2C 72 in 3-Point Nut Collector S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5892	Great Plains NTS2607 84 in No Till Seeder S/N: GPD1685L
5882	2023 Armstrong Ag DHDP2422 120 in Tandem Disc Harrow S/N: W2403 C/W: 21 in Notched Front Discs, 21 in Notched Rear Discs, 9 in Spacing Usage: Not Available Asset located in: Humble, TX	5893	C/W: 3 Point Hitch; EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Quantity of (2) Hay Forks
5883	2013 John Deere 20 ft Flex Wing Rotary Mower S/N: 1P0CX20FJDP017009 C/W: 1000 PT0	5893	S/N: V2777 Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5894	2000 Eurospand S272 3-Point Fertilizer
5884	2015 John Deere 20 ft Flex Wing Rotary Mower S/N: 1P0CX20FCFP017296 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Spreader S/N: A0165 C/W: 540 PTO Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5895 5896 5897	2024 Quantity of Landhonor BA-22-09W 108 in 3-Point Tractor Dozer (Unused) S/N: HL00006/HL00005 Usage: Not Available Asset located in: Humble, TX 2019 Land Pride RB1672 72 in 3-Point Blade S/N: 1400510 Usage: Not Available Asset located in: Humble, TX 2024 Industrias America F07 7 ft Box Scraper (Unused) S/N: F07T202435333 Usage: Not Available Asset located in: Humble, TX	5905	Teran THH400BH Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAB00704C52HRL C/W: For Backhoe Loaders CAT 416, 428, 444 - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations ManualWith Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual
5898	2024 Industrias America F10 10 ft Box Scraper (Unused)		Operations Manual Usage: Not Available
	S/N: F10202435855		Asset located in: Humble, TX
	Usage: Not Available	5906	Teran THH400B-JD410G Backhoe Hydraulic
5899	Asset located in: Humble, TX Quantity of Plow Parts S/N: Not Available Usage: Not Available	F007	Breaker - Fits John Deere 410G (Unused) S/N: CAB00606C52HRL C/W: For Backhoe John Deere JD310G/410G - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic
	Asset located in: Humble, TX		Hammers are supplied with 2 Chisels Moil
5900	Quantity of (2) Ag Attachments S/N: Not Available C/W: 540 PTO, 7 in Auger, 72 in Mower, 3 Point Hitch Mount Usage: Not Available		Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5901	AWS S/A Feed Trailer S/N: Not Available C/W: Torsion Axle, 235/85R16 Tires, 7 ft 1 in Body, 235/85R16 Tires Usage: Not Available Asset located in: Humble, TX	5907	Teran THH400B-JD410J/K Backhoe Hydraulic Breaker - Fits John Deere 410J/K (Unused) S/N: CAK16922A26HR C/W: For Backhoe John Deere JD310/410JK - 68mm Tool With Auto - Lubrication Pre- Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil
5902	2024 Elephant EPB430BL Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CP2407143 Usage: Not Available		Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
5903	2024 Elephant EPB430BL Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CP2407144 Usage: Not Available Asset located in: Humble, TX	5908	Teran THH400BT Backhoe Hydraulic Breaker - Fits Cat 416 (Unused) S/N: CAA0258B52HR C/W: For Backhoe Loaders CAT 416, 428, 444 -68mm Tool With Auto - Lubrication Pre- Diagnosition All New Toron Hydraulic
5904	2024 Jisan JSB400BL Backhoe Hydraulic Breaker - Fits JCB 3CX/4CX (Unused) S/N: 2404506 Usage: Not Available Asset located in: Humble, TX		Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5909	Teran THH400B-580K/M Backhoe Hydraulic Breaker - Fits Case 580K/L/M (Unused) S/N: CAP12973B52HRL C/W: For Backhoe Case 580K/L/M - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Humble, TX	5916	2021 Connect Work Tools CH70SS Hydraulic Breaker S/N: CH70-22F-1164 C/W: 750 lb class Usage: Not Available Asset located in: Humble, TX
		5917	Bobcat HB980 Q/C Backhoe Hydraulic Breaker S/N: Not Available C/W: Fits Mini Excavator Usage: Not Available Asset located in: Humble, TX
5910	Teran THH400B-580N Backhoe Hydraulic Breaker - Fits Case 580N (Unused) S/N: CAP13373B52HRL C/W: For Backhoe Case 580N - 68mm Tool	 5919	Cat 18 in Digging Excavator Bucket S/N: A621ABK20212 Usage: Not Available Asset located in: Humble, TX
	With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations	5921	Quantity of (2) 8 in Cribbing Backhoe Rear Bucket - Fits Cat 416 S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5911	Manual Usage: Not Available Asset located in: Humble, TX Teran THH400B-JCB3CX Backhoe Hydraulic	5922	8 in Cribbing Backhoe Rear Bucket - Fits Case 580 S/N: Not Available Usage: Not Available
	Breaker - Fits JCB 3CX (Unused) S/N: CAP13009B52HRL C/W: For Backhoe JCB3CX - 68mm Tool With Auto - Lubrication Pre-Disposition - All New Teran Hydraulic Hammers are supplied with 2 Chisels Moil Point M Type, 2 Hoses, 1 Set of N2 Nitrogen Charging Kit with N2 Bottle and Pressure Gauge, 1 Spare Seal Kit, Tool Box with Maintenance Tools and Operations Manual Usage: Not Available Asset located in: Humble, TX 2018 FRD F9FSP Q/C Backhoe Hydraulic Breaker S/N: F9-08425		Asset located in: Humble, TX
		5923	48 in Backhoe Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		5924	McKissick 3 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		5925 Johnson 1 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX 5926 Pettibone 2 Sheave Hook Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	Johnson 1 Sheave Hook Block
5912			Usage: Not Available
5913	Usage: Not Available Asset located in: Humble, TX Kent KF6 Hydraulic Breaker		S/N: Not Available
0310	S/N: 3635		Asset located in: Humble, TX
F01.4	Usage: Not Available Asset located in: Humble, TX	5927	2 Sheave Hook Block S/N: Not Available Usage: Not Available
5914	John Deere Backhoe Hydraulic Breaker S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available	5928	Quantity of (3) Crane Ball W/Hook
5915	Asset located in: Humble, TX 2019 Stanley MB/XP4035 Hydraulic Breaker S/N: XP403500058		S/N: Not Available C/W: Assorted size Usage: Not Available
	C/W: 5.6" Tool / chisel. Fits Excavators		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5929	Quantity of (4) Deehan #SH43118 35 Ton Snatch Blocks 32-38 MM WR S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5930	Quantity of (4) Deehan # SH43118 35 Ton Snatch Blocks 32-38 MM WR S/N: Not Available	5942	McKissick 40 ton 2 Sheave Load Block S/N: 1103 Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5943	McKissick 90 ton 4 Sheave Load Block
5931	Quantity of (4) Deehan # SH43118 35 Ton		S/N: 11361
	Snatch Blocks 32-38 MM WR		Usage: Not Available
	S/N: Not Available Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5944	Quantity of 15 ton 2 Sheave Load Block
5932	Quantity of (4) Dehaan # SH43118 35 Ton		S/N: Not Available Usage: Not Available
0702	Snatch Blocks 32-38 MM WR		Asset located in: Humble, TX
	S/N: Not Available	5945	Quantity of (3) McKissick 40 ton 4 Sheave
	Usage: Not Available		Load Block
	Asset located in: Humble, TX		S/N: Not Available
5933	Quantity of (4) Dehaan # SH43118 35 Ton Snatch Blocks 32-38 MM WR		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available	5946	Quantity of (6) Load Block
	Usage: Not Available	3940	S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
5934	Quantity of (2) Dragline Sheaves		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	5947	Quantity of (5) Load Block
	Asset located in: Humble, TX		S/N: Not Available
5935	McKissick 160 ton 7 Sheave Load Block		Usage: Not Available Asset located in : Humble, TX
3933	S/N: 1184	5948	Quantity of (5) Load Block
	Usage: Not Available		S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
5936	6 Sheave Load Block	5949	Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available		McKissick 45 ton 3 Sheave Load Block
	Asset located in: Humble, TX		S/N: 1084 Usage: Not Available
5937	Quantity of (2) McKissick Load Block		Asset located in: Humble, TX
0,00	S/N: Not Available	5950	
	C/W: (1) 50 ton, (1) 60 ton		S/N: Not Available
	Usage: Not Available Asset located in : Humble, TX		Usage: Not Available
5938			Asset located in: Humble, TX
3936	Quantity of (2) McKissick 60 ton 6 Sheave Load Block	5951	Quantity of (3) 65 ton 4 Sheave Load Block
	S/N: Not Available		S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5952	Quantity of (2) McKissick Load Block
5939	Quantity of (3) McKissick 60 ton 6 Sheave	0,502	S/N: Not Available
	Load Block S/N: Not Available		Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	5953	Quantity of (2) 65 ton 4 Sheave Load Block
5940	Quantity of (6) McKissick 20 ton 3 Sheave		S/N: Not Available Usage: Not Available
	Load Block		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	5954	McKissick 90 ton 4 Sheave Load Block
	Asset located in: Humble, TX		S/N: 11359
5941	McKissick 40 ton 2 Sheave Load Block	\neg	Usage: Not Available
J741	S/N: 1859		Asset located in: Humble, TX
	Usage: Not Available		
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
5955	Quantity of (2) 65 ton 4 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5967	Quantity of (18) General # USC-3A Super Clamps S/N: Not Available Usage: Not Available
5956	Quantity of (3) McKissick 60 ton 6 Sheave		Asset located in: Humble, TX
	Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5968	Quantity of (16) General # USC-3A Super Clamps S/N: Not Available Usage: Not Available
5957	Quantity of (5) McKissick 5 ton 5 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5969	Asset located in: Humble, TX Quantity of (15) General # USC-3A & (6) # USC-4 Super Clamps S/N: Not Available Usage: Not Available
5958	Quantity of (4) Load Block		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX McKissick 65 ton 4 Sheave Load Block	5970	Quantity of (12) General # USC-4 & (5) # USC-5 Super Clamps S/N: Not Available Usage: Not Available
0,00	S/N: 11865		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5971	Quantity of General # USC-4 & # USC-5 Super Clamps Super Clamps
5960	McKissick 40 ton 2 Sheave Load Block S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	5972	Quantity of General # USC-4 & # USC-5A Supe Clamps Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5961	McKissick 8 Sheave Load Block S/N: Not Available Usage: Not Available Asset located in: Humble, TX		
5962	Quantity of (6) Caldwell GC20 20 Ton Beam Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5973	Quantity of (14) General # USC-4 & (6) # USC-5A Super Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5963	Quantity of (6) Caldwell GC20 20 Ton Beam Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5974	Quantity of (6) General # USC5D-400 Super Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5964	Quantity of (5) Caldwell # GC-20 20 Ton Beam Clamps S/N: Not Available Usage: Not Available	5975	Quantity of (20) General USC3A Beam Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	5976	Quantity of (4) 55 Ton Shackle
5965	Quantity of (20) General # USC-3A Super Clamps		S/N: Not Available Usage: Not Available Asset located in: Humble, TV
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	5977	Asset located in: Humble, TX Quantity of (8) 35 Ton Shackle S/N: Not Available
5966	Quantity of General USC3A Beam Clamps S/N: Not Available		Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	5978	Quantity of (5) 17 Ton Shackle S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
5980	Grove 25 Ft Boom S/N: Not Available C/W: 3 section Usage: Not Available Asset located in: Humble, TX	5990	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
5981	Quantity of (2) Grove RT530 Boom Cylinder S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5991	Quantity of (2) 2024 Wolverine EX-66-78L/84L Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in.
5982	Grove RT530 Boom Cylinder S/N: Not Available Usage: Not Available Asset located in: Humble, TX	5992	Usage: Not Available Asset located in: Humble, TX Quantity of (2) 2024 Wolverine EX-66-78L/84L Sets of Fork Extensions (Unused)
5983	15 ft Truss Jib Material Handling Arm - Fits Telehandler S/N: Not Available Usage: Not Available		Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in: Humble, TX
5984	Asset located in: Humble, TX 2017 Land Pride BB1260 60 in 3-Point Box Blade S/N: 1119943 Usage: Not Available Asset located in: Humble, TX	5993	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX
5985	Modern 60 in 3-Point Tractor Box Blade S/N: 07884 Usage: Not Available Asset located in: Humble, TX	5994	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available
5986	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5995	Asset located in: Humble, TX Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX
5987	2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	5996	Quantity of (2) 2024 Wolverine EX-66-78L/84L Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in: Humble, TX
5988	Usage: Not Available Asset located in: Humble, TX 2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	5997	Quantity of (2) 2024 Wolverine EX-66-78L/84L Sets of Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in., (1) 84 in. Usage: Not Available Asset located in: Humble, TX
5989	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe F-10 10 ft Fork Extensions (Unused) S/N: Not Available	5998	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	5999	Asset located in: Humble, TX Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6000	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available	6011	2008 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger S/N: BU010411 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6012	2012 Ingersoll Rand BU7A HAS001 - Hoist, Air
6001	Quantity of (2) 2024 Wolverine EX-66-78L/84L Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available	6013	1,000 Cap Air Tugger S/N: BU019464 Usage: Not Available Asset located in: Humble, TX 2012 Ingersoll Rand BU7A Air Tugger
	Asset located in: Humble, TX	-	S/N: BU019498
6002	Quantity of (2) 2024 Wolverine EX-66-78L/84L		Usage: Not Available
	Fork Extensions (Unused) S/N: Not Available		Asset located in: Humble, TX
	C/W: (1) 78 in, (1) 84 in Usage: Not Available Asset located in: Humble, TX	6014	Winch S/N: Not Available Usage: Not Available
6003	Quantity of (2) 2024 Wolverine EX-66-78L/84L		Asset located in: Humble, TX
0000	Fork Extensions (Unused) S/N: Not Available C/W: (1) 78 in, (1) 84 in Usage: Not Available	6015	Winch S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6016	Winch
6004	Quantity of (2) 2024 Wolverine EX-66-78L/84L (1) 78 in, (1) 84 in Fork Extensions (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6017	2005 Ingersoll-Rand FA25A20MX1 Air Tugger S/N: MW001935
6005	Mafco Equipment 111T Pneumatic Air Tugger S/N: A1071088		Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6018	2005 Ingersoll-Rand FA25A20MX1 Air Tugger S/N: MW001937
6006	1990 Ingersoll Rand BU7A HAS001 - Hoist, Air 1,000 Cap Air Tugger		Usage: Not Available Asset located in: Humble, TX
	S/N: BU7A.REK75756 Usage: Not Available Asset located in : Humble, TX	6019	1999 Gomaco 9500 172 in Soil Conditioner Attachment
6007	1991 Ingersoll Rand BU7A Air Tugger	-	S/N: 905500054 Usage: Not Available
0007	S/N: BU7A.RPL00112		Asset located in: Humble, TX
	Usage: Not Available	6020	84 In. Milling Drum
	Asset located in: Humble, TX		S/N: Not Available
6008	1990 Ingersoll Rand BU7A HAS001 - Hoist, Air		Usage: Not Available
	1,000 Cap Air Tugger		Asset located in: Humble, TX
	S/N: BU7A.RSA09841 Usage: Not Available	6021	Quantity of (3) Milling Drums
	Asset located in: Humble, TX		S/N: Not Available C/W: (1) 28 in., (1) 30 in. & (1) 120 in.
6009	2006 Ingersoll Rand BU7A HAS001 - Hoist, Air		Usage: Not Available
0005	1,000 Cap Air Tugger		Asset located in: Humble, TX
	S/N: BU004442	6022	67 in Smooth Shell Kit
	Usage: Not Available		S/N: Not Available
	Asset located in: Humble, TX	_	Usage: Not Available
6010	2008 Ingersoll Rand BU7A HAS001 - Hoist, Air	4222	Asset located in: Humble, TX
	1,000 Cap Air Tugger S/N: 10133	6023	28 ft Pipelayer Boom S/N: Not Available
			SANCINAL AVAILAND
	Usage: Not Available		Usage: Not Available

Lot #	Details	Lot #	Details
6024	21 Ft Pipelayer Boom S/N: Not Available Usage: Not Available Asset located in: Humble, TX 20 ft Pipelayer Booms	6035	Quantity of (2) Teran 9W9353 49 in Link Track Chains (Unused) - Fits Cat 320 S/N: Not Available C/W: Track Link Assy 49 Lks Sealed and Greased (CR6288/49)(CR5350/49) (1591519)
00_0	S/N: Not Available Usage: Not Available Asset located in: Humble, TX		(1941608) Usage: Not Available Asset located in: Humble, TX
6026	20 Ft Pipelayer Boom S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6036	Heavy Duty Forklift Jib S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6027	Tailgate - Fits Articulated Dump Truck S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6037	Heavy Duty Forklift Jib S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6028	Tailgate - Fits Articulated Dump Truck S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6038 	Heavy Duty Forklift Jib S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6029	Tailgate - Fits Articulated Dump Truck S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6039 	60 in Forklift Material Handling Arm S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6030	Cat Tailgate - Fits Cat 730C2 S/N: VG000056-1 Usage: Not Available Asset located in: Humble, TX	6040	2024 Suihe JF Forklift Material Handling Arm (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6031	Quantity of Track Links S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) Teran 8E4518 44 Link Track	6041	Quantity of (2) Teran 1028152 Idlers (Unused) S/N: Not Available C/W: For Cat 336DL/EL, 330 - (CR6087) (CR5740) Usage: Not Available
	Chains (Unused) - Fits Cat D8N/R/T S/N: Not Available C/W: Track Link Assy 44 Lks SALT For Cat D8N /R/T - (CR4525/44) Usage: Not Available Asset located in: Humble, TX	6042	Asset located in: Humble, TX Quantity of (2) Teran 1132907 Idlers (Unused) S/N: Not Available C/W: (1028151) (CR5732) Usage: Not Available Asset located in: Humble, TX
6033	Quantity of (2) Teran 6l9671 41 Link Track Chains (Unused) S/N: Not Available C/W: Track Link Assy 41 Lks SALT-HD 41 Lks 3 /4 in BH For Cat D6H/R/T - (CR5534/41) (CR4810/41) Usage: Not Available Asset located in: Humble, TX	6043	Quantity of (2) Teran 6T3216 Idler w/Shaft (Unused) S/N: Not Available C/W: Idler W/Shaft LG for Cat D6R/T, D6H - (CR4616)(2024304) Usage: Not Available Asset located in: Humble, TX
6034	Quantity of (2) Teran 6Y2754 49 Link Track Chains (Unused) - Fits Cat 336DL S/N: Not Available C/W: Track Link Assy 49 Lks for Cat 330/336DL /EL - (CR5926/49) (1187301) (2131971)	6044	Quantity of (2) Teran 6Y0554 Idlers (Unused) - Fits Cat D8N/R/T S/N: Not Available C/W: REAR Usage: Not Available Asset located in: Humble, TX
	(2019119) Usage: Not Available Asset located in: Humble, TX	6045	Quantity of (2) Teran 6Y0557 Idlers (Unused) - Fits Cat D8N/R/T S/N: Not Available C/W: FRONT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6046	Quantity of (2) Teran 7T6996 Idler w/Shaft (Unused) - Fits Cat D6R/T S/N: Not Available C/W: Idler W/ Shaft SM Dia for Cat D6R/T,D6H	6056	Quantity of (6) 48 in Forks S/N: 50571 Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6057	Quantity of (2) 90 in Lift Truck Forks S/N: Not Available
6047	Quantity of (8) Teran 1205746 S/F Rollers (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: For Cat D6R/T,D6H/D - (CR6088) (CR3634) (1181617) (9G8029) (2313087) Usage: Not Available Asset located in : Humble, TX	6058	Quantity of (2) 46 in Fork Attachment S/N: 9674/ZL00239 C/W: Kinshofer, Heiden Usage: Not Available
6048	Quantity of (8) Teran 1205766 D/F Rollers		Asset located in: Humble, TX
00.10	(Unused) S/N: Not Available C/W: For Cat D6R/T,D6H/D - (CR6089) (CR3635) (1181618) (9G8034) (2313088) Usage: Not Available	6060	Kinshofer 46 in Crane Forks S/N: 50560 Usage: Not Available Asset located in: Humble, TX 72 in Forks
6049	Asset located in: Humble, TX Quantity of (8) Teran 9W8706 D/F Rollers (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: For Cat D8N/R/T - (CR4529) (1969946) Usage: Not Available Asset located in : Humble, TX	6061	96 in Lift Truck Forks S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6050	Quantity of (8) Teran 9W8705 S/F Rollers (Unused) S/N: Not Available C/W: For Cat D8N/R/T - (CR4528) (1969947)	6062	Quantity of (6) Pipelayer Counterweight S/N: Not Available Usage: Not Available
	Usage: Not Available	1010	Asset located in: Humble, TX
6051	Asset located in: Humble, TX Quantity of (12) Teran 1634143 S/F Rollers (Unused) S/N: Not Available	6063	Quantity of (2) Pipelayer Counterweights S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: (1R8669) (1175045) (CR5109) (CR5572) Usage: Not Available Asset located in: Humble, TX	6064	Quantity of Crown Electric Forklift Masts S/N: Not Available Usage: Not Available
6052	Quantity of (12) Teran 1634149 S/F Rollers		Asset located in: Humble, TX
	(Unused) S/N: Not Available C/W: For Cat 336DL/EL, 330 - (CR5897) (1175047) (1791486) Usage: Not Available	6065	Guard S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6066	Quantity of (3) 9 ft Jibs
6053	Quantity of (2) Teran 6Y5685 Sprockets (Unused) - Fits Cat 336DL/EL S/N: Not Available	6067	S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	C/W: For Cat 336DL/EL, 330 - (CR5861) Usage: Not Available Asset located in: Humble, TX		Pipe Cradle S/N: Not Available Usage: Not Available
6054	Quantity of (2) Teran 8E9805 Sprockets (Unused) - Fits Cat 320 S/N: Not Available C/W: 16 Holes - (CR5602) Usage: Not Available Asset located in: Humble, TX	6068	Asset located in: Humble, TX Pipe Cradle S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6069	Quantity of (7) Welding Deck Mount Stands S/N: Not Available Usage: Not Available	6083	Quantity of (5) Hydraulic Cylinder S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6071	Cat 30 In Auger Bit	6084	8 in Hydraulic Cylinder (Unused)
	S/N: Not Available		S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6072	Cat 24 In. Auger Bit (Unused)	6085	Hydraulic Cylinder
	S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6073	Cat 24 In. Auger Bit (Unused)	6086	Quantity of (1) Crates of Caterpillar Parts - Fits
	S/N: Not Available		Cat 3404 Diesel Motor
	Usage: Not Available		S/N: Not Available
	Asset located in: Humble, TX	_	C/W: one crate Usage: Not Available
6074	Cat 15 In Auger Bit		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	6087	Ground Hog HD99-H Gasoline Tow-Behind
	Asset located in: Humble, TX		Power Auger
6075	Cat 9 in Auger Bit (Unused)		S/N: 0309137
	S/N: Not Available		C/W: (3) Bits, Ball Hitch Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6088	Quantity of (2) Forks
6076	Cat 9 in Auger Bit (Unused)		S/N: Not Available
	S/N: Not Available Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6077	Cat 6 in Auger Bit (Unused)	6090	Case Backhoe Hydraulic Breaker
	S/N: Not Available		S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6091	Quantity of (2) 26.5R25 Tires
6078	Handy HSRC12 12 in Skid Steer Rotating Pole	6092	S/N: Not Available
	Clamp S/N: RC220525244		Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Quantity of (4) 20.8R42 Tires
	THE INSPECTION REPORT		S/N: Not Available C/W: All Tires with Wheels
	Asset located in: Humble, TX	_	Usage: Not Available
6079	Kenco Barrier Clamp		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	6093	Quantity of (4) Steel Truck Rims
	Asset located in: Humble, TX		S/N: Not Available
6080	Quantity of (5) Equipment Doors		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available	6094	Quantity of (4) Moffet Rims (3) Steel Truck
	Usage: Not Available	0094	Rims
4004	Asset located in: Humble, TX	_	S/N: Not Available
6081	ZF Friedrichshafen Transmission - Fits Doosan		C/W: one pallet
	DA40 S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	6005	•
	Asset located in: Humble, TX	6095	Quantity of Wheels S/N: Not Available
6082	Transmission - Fits Doosan DL300		C/W: (1) Pallet
	S/N: Not Available		Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	1	

Lot #	Details	Lot #	Details
6096	Quantity of (4) 235/80R16 Tires (Unused) S/N: Not Available C/W: All Tires with Wheels Usage: Not Available Asset located in: Humble, TX	6104	Teran Q300H Walk-Behind Saw (Unused) S/N: Not Available C/W: Model Q300, Gasoline Engine Loncin G200F/6.5HP, With EPA, 350mm Concrete Blade, Max Cutting Depth: 10cm, Adjustable Cutting Depth, Water Tank Capacity 12L KGS.
6097	Quantity of (4) 205/75R15 Tires (Unused) S/N: Not Available C/W: All Tires with Wheels		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6105	Diamond Products CC6571 Walk-Behind Saw S/N: 160434 C/W: 42 in Max Blade Diameter, 17 in Max
6098	Quantity of Tires S/N: Not Available Usage: Not Available Asset located in : Humble, TX		Cutting Depth, Water Hose Connection, Hydraulic Blade Raise / Lower, Tier 4, 2019 US EPA Label, Kubota V2607 Diesel Engine, 500 Gallon Poly Tank, Tsurumi Water Pump, 16 Ft, T
6099	Teran R600H Walk Behind Roller (Unused)		/A Utility Trailer Usage: 542 Hr
	S/N: 23090907 C/W: Model R600, Gasoline Engine Loncin		Asset located in: Humble, TX
	G390F/13HP, With EPA, Manual Start, Roller Size (Dia. X Width): 426X600mm, Drive type: Hydraulic Pump, Hydraulic Motor, Double Wheels Drive, Vibration type: Automatic, Double Wheels Vibration, Vibration Frequency: 75HZ, Centrifugal Force: 20KN, Water Tank	6107	Norton C1320SM Walk-Behind Concrete Saw S/N: 13011009 C/W: Honda GX390 1 Cylinder Gasoline Engine Usage: 47 Hr
		61004	Asset located in: Humble, TX
	Capacity: 20L, Travel Speed: 0-4 KM/H Usage: Not Available	6108A	Core Cut CC1800XL Walk-Behind Saw S/N: 159749 C/W: Water Hose Connection, 2019 US EPA
6100	Asset located in: Humble, TX 2024 Powertek Q500 Walk-Behind Saw		Label, Honda 1 Cylinder Gasoline Engine Usage: Not Available
	(Unused) S/N: Not Available C/W: 20 in Max Blade Diameter, 7 in Max Cutting Depth, Water Tank, Water Hose Connection, 1 Cylinder 13 hp Gasoline Engine Usage: Not Available	6100	Asset located in: Humble, TX
		6108	Soff-Cut X2500 Concrete Walk-Behind Saw S/N: Not Available C/W: Hydraulic Blade Raise / Lower, Honda 1 Cylinder Gasoline Engine
	Asset located in: Humble, TX		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
6101	2024 Powertek Q500 Walk-Behind Saw (Unused) S/N: Not Available C/W: 20 in Max Blade Diameter, 7 in Max Cutting Depth, Water Tank, Water Hose Connection, 1 Cylinder 13 hp Gasoline Engine		THE INSPECTION REPORT Asset located in: Humble, TX
		6109	2015 Husqvarna 9045-FS513 Walk-Behind Saw S/N: 2015 0300004 Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX	C110D	Asset located in: Humble, TX
6102	2024 Powertek Q500 Walk-Behind Saw	6110B	2024 Landhonor LHR-CM400 Portable Concrete Mixer (Unused)
	(Unused) S/N: Not Available		S/N: ZWQK20240521R11 C/W: Lifan 168F-2 1 Cylinder 6.5 hp Gasoline Engine
	C/W: 20 in Max Blade Diameter, 7 in Max Cutting Depth, Water Tank, Water Hose		Usage: Not Available
	Connection, 1 Cylinder 13 hp Gasoline Engine Usage: Not Available	64404	Asset located in: Humble, TX
	Asset located in: Humble, TX	6110A	2024 Landhonor LHR-CM300 Portable Concrete Mixer (Unused)
6103	2024 Landhonor LHR-Q300 Walk-Behind Saw (Unused) S/N: Not Available C/W: 14 in Max Blade Diameter, 4 in Max Cutting Donth, Water Hose Connection, Longin		S/N: ZWQK20240521R05 C/W: Lifan 168F-2 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available
	Cutting Depth, Water Hose Connection, Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine	6110	Asset located in: Humble, TX
	G200F 1 Cylinder 6.5 hp Gasoline Engine	6110	Vahalt Flactria Dartahla Cananta Minan
	G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6110	Kobalt Electric Portable Concrete Mixer S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Gar-Bro Concrete Bucket S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2020 Gar-Bro 454-R Concrete Bucket S/N: Not Available Usage: Not Available Usage: Not Available Asset located in: Humble, TX Dynapac BT82 Concrete Screed S/N: Not Available C/W: 40 ft Screed, Honda GX160 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX Teran VH200F Concrete Vibrator (Unused) S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP Epa, Dynapac Coupling, With Vibrator Poker V50, 50mm Head Diameter, Flexible Pipe 6.0 Mts Usage: Not Available Asset located in: Humble, TX Quantity of (2) Mustang CV3500 Concrete Vibrator (Unused) S/N: Not Available Usage: Not Available Usage: Not Available	6126 6127 6128 6129	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071207 C/W: 7.5 Kw (10 hp) Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071220 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071219 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071217 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071217 Usage: Not Available Asset located in: Humble, TX
S/N: Not Available Usage: Not Available Asset located in: Humble, TX Dynapac BT82 Concrete Screed S/N: Not Available C/W: 40 ft Screed, Honda GX160 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX Teran VH200F Concrete Vibrator (Unused) S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP Epa, Dynapac Coupling, With Vibrator Poker V50, 50mm Head Diameter, Flexible Pipe 6.0 Mts Usage: Not Available Asset located in: Humble, TX Quantity of (2) Mustang CV3500 Concrete Vibrator (Unused) S/N: Not Available	6128	2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071220 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071219 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071217 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) Asset located in: Humble, TX
S/N: Not Available C/W: 40 ft Screed, Honda GX160 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX Teran VH200F Concrete Vibrator (Unused) S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP Epa, Dynapac Coupling, With Vibrator Poker V50, 50mm Head Diameter, Flexible Pipe 6.0 Mts Usage: Not Available Asset located in: Humble, TX Quantity of (2) Mustang CV3500 Concrete Vibrator (Unused) S/N: Not Available	6129	Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071219 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071217 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused)
S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP Epa, Dynapac Coupling, With Vibrator Poker V50, 50mm Head Diameter, Flexible Pipe 6.0 Mts Usage: Not Available Asset located in: Humble, TX Quantity of (2) Mustang CV3500 Concrete Vibrator (Unused) S/N: Not Available		2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071217 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Electric Surface Grinder (Unused)
Vibrator (Unused) S/N: Not Available	6130	(Unused)
Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
Teran S60 Power Trowel (Unused) S/N: Not Available C/W: Model S60 With Gasoline Engine Loncin G200F/6.5HP With EPA, With Round Pan. Engine Pack Separately. Trowel Diameter 580mm, Speed Range 60-100 RPM	6131	2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071214 Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071212		2024 KUL JHC-280 Electric Surface Grinder (Unused) S/N: 071215 Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071211	6133	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071210 Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071216	6134	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071203 Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071218	6135	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071201 Usage: Not Available Asset located in: Humble, TX
Asset located in: Humble, TX 2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071206 Usage: Not Available Asset located in: Humble, TX	6136	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071204 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071205 Usage: Not Available
	Asset located in: Humble, TX Teran S60 Power Trowel (Unused) S/N: Not Available C/W: Model S60 With Gasoline Engine Loncin G200F/6.5HP With EPA, With Round Pan. Engine Pack Separately. Trowel Diameter 580mm, Speed Range 60-100 RPM Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071212 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071211 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071216 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071216 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071218 Usage: Not Available Asset located in: Humble, TX	Asset located in: Humble, TX Teran S60 Power Trowel (Unused) S/N: Not Available C/W: Model S60 With Gasoline Engine Loncin G200F/6.5HP With EPA, With Round Pan. Engine Pack Separately. Trowel Diameter 580mm, Speed Range 60-100 RPM Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071212 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071211 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071216 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071216 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-280 Surface Grinder (Unused) S/N: 071218 Usage: Not Available Asset located in: Humble, TX 2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071206 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6138	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071208 Usage: Not Available Asset located in: Humble, TX	6151	2015 Wacker RTLX-SC3 Trench Compactor S/N: 24277490 C/W: 2014 US EPA Label, Kohler 3 Cylinder 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control
6139	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071202 Usage: Not Available		Usage: 556 Hr Asset located in : Humble, TX
	Asset located in: Humble, TX		2016 Wacker RTLX-SC3 Trench Compactor
6140	2024 KUL JHC-588 Surface Grinder (Unused) S/N: 071209 Usage: Not Available Asset located in: Humble, TX		S/N: 24332560 C/W: 2016 US EPA Label, Kohler 3 Cylinder 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 586 Hr
6141	Quantity of (2) AJLR LC90T Vibratory Plate		Asset located in: Humble, TX
	Compactor S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6153	2013 Bomag BMP 8500 Trench Compactor S/N: 101720121195 C/W: Kubota D1005 3 Cylinder Diesel Engine, 24 in Drums, Remote Control w/ Cord, Articulated Steering Usage: 665 Hr Asset located in: Humble, TX
6142	Quantity of Pneumatic Fishing Tools S/N: Not Available C/W: hose Usage: Not Available Asset located in: Humble, TX	6154	2017 Wacker Neuson Trench Compactor S/N: 24424276 C/W: 2017 US EPA Label, Kohler 3 Cylinder .40 kW 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 307 Hr
6144	Quantity of (5) Concrete Drains S/N: Not Available Usage: Not Available		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	6155	2024 Powertek C160 Reversible Vibratory Plate Compactor (Unused)
6145	Quantity of Concrete Pipe S/N: Not Available C/W: misc sizes Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6146	Quantity of Concrete Culvert Headwalls S/N: Not Available C/W: Misc. Sizes Usage: Not Available Asset located in: Humble, TX	6156	2024 Elephant EPC50 Excavator Plate Compactor - Fits Cat 307/307B/308/308B (Unused) S/N: 24062200338 Usage: Not Available
6147	2018 Wacker RTSC3 Trench Compactor S/N: 24449681 C/W: 2017 US EPA Label, Kohler 1.02 L Diesel Engine, 22 in / 32 in Drums, Remote Control w/ Cord, Articulated Steering Usage: 305 Hr Asset located in: Humble, TX		Asset located in: Humble, TX Teran C80T Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin Engine 200F / 6.5 HP, With EPA, Water Tank Plate Size: 53X50cm, Centrifugal Force: 14KN, Max. Compaction Depth: 30cm,
6148	2016 Wacker Neuson RT Trench Compactor S/N: 24313313 Usage: Not Available		Efficiency: 500 m2/H, 90 Kgs. Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6158	2024 Landhonor LHR-PC90 Vibratory Plate
6149	2017 Wacker Neuson RT Trench Compactor S/N: 24377382 C/W: 2015 US EPA Label, Kohler 3 Cylinder 1.0 L Diesel Engine, 22 in / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 616 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Compactor (Unused) S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6159	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6166	2024 Paladin PLD-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6160	2024 Landhonor LHR-PC90 Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available	6167	TMG PC90 Vibratory Plate Compactor S/N: Not Available C/W: Loncin 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX 2024 Landhonor LHR-PC90 Vibratory Plate
6161	Asset located in: Humble, TX 2024 Landhonor LHR-PC90 Heavy Duty Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin G200F 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available		Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6162	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2024 Landhonor LHR-PC90 Vibratory Plate	6169	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: US EPA Label, RM120-V 121 cc Gasoline
	Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Engine Usage: Not Available Asset located in : Humble, TX
6163	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Landhonor LHR-PC90 Vibratory Plate	6170	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 2024 US EPA Label, RM120V 1 Cylinder Gasoline Engine Usage: Not Available
	Compactor (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6164	2024 SDLOOL SL90B Vibratory Plate Compactor (Unused) S/N: B35825 C/W: Loncin 1 Cylinder 196 cc Gasoline Engine, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 2024 US EPA Label, RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
6165	Usage: Not Available Asset located in: Humble, TX Mustang LF88D Vibratory Plate Compactor (Unused) S/N: Not Available C/W: Loncin 1 Cylinder 196 cc Gasoline Engine	6173	Quantity of (4) 2024 JQ POWER JQ120 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 2024 US EPA Label, RM120V 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6174	2024 Powertek RM80 Jumping Jack Tamper (Unused) S/N: Not Available C/W: 1 Cylinder 6.5 hp 196 cc Gasoline Engine Usage: Not Available

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6175	2024 Landhonor LHR-RM90 Jumping Jack Tamper (Unused) S/N: Not Available C/W: Loncin LC168F-2H 1 Cylinder 6.5 hp Gasoline Engine Usage: Not Available	6184	16 ft x 8 ft Trench Shield S/N: 140688 C/W: 4 in Thick Panels Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6185	16 ft x 8 ft Trench Shield
6176	2024 Machpro GTR-80 Jumping Jack Tamper (Unused) S/N: SLP2430080009	6186	S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Asset located in : Humble, TX
	C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX		16 ft x 4 ft Trench Shield S/N: 4416241 C/W: 4 in Thick Panels Usage: Not Available
6177	2024 Machpro GTR-80 Jumping Jack Tamper		Asset located in: Humble, TX
	(Unused) S/N: SLP2430080012 C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6187	16 ft x 4 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Asset located in: Humble, TX
6178	2024 Machpro GTR-80 Jumping Jack Tamper (Unused) S/N: SLP2430080010 C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine	6188	12 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	6189	12 ft x 8 ft Trench Shield
6179	Asset located in: Humble, TX 2024 Machpro GTR-80 Jumping Jack Tamper (Unused)		S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available
	S/N: SLP2430080011		Asset located in: Humble, TX
6100	C/W: Loncin LC168 1 Cylinder 5.5 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	6190	12 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
6180	Teran RM80 Jumping Jack Tamper (Unused) S/N: Not Available C/W: Tamping Rammer Gasoline Engine Loncin LC168F - 2H/6.5HP EPA, Luxury Type, No Wheels, W/ Yellow Cover, Tamping Force 10Kn, Max. Compaction Depth 45 cm, Efficiency 200 m2/H, Plate Size 345X285, Leap Height 65mm Usage: Not Available		THE INSPECTION REPORT Asset located in: Humble, TX
		6191	12 ft x 8 ft Trench Shield S/N: Not Available C/W: 4 in Thick Panels, (0) Spreader Bars Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6192	Quantity of (3) Pallets of Trench Box Spreaders
6181	Quantity of (3) Jumping Jack Tamper S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (1) Wacker, (2) Bomag Usage: Not Available		S/N: Not Available C/W: Misc. Sizes Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6193	Quantity of (2) Pallets of Trench Box Spreaders
6182	20 ft x 8 ft Trench Shield S/N: 1-2359 C/W: 6 in Thick Panels Usage: Not Available	6194	S/N: Not Available C/W: Misc. Sizes Usage: Not Available Asset located in: Humble, TX Quantity of (2) 2024 Kit Containers 5 ft x 7 ft 8
	Asset located in: Humble, TX		in (1 in Thick) Road Steel Plates (Unused)
6183	20 ft x 8 ft Trench Shield S/N: 4-2203 C/W: 6 in Thick Panels Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6195	Quantity of (2) 2023 Kit Containers 6 ft x 7 ft 5 in (.62 in Thick) Road Steel Plates (Unused) S/N: Not Available	6207	Quantity of (2) Diamond Plate Steel Plates S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6208	Quantity of (2) Diamond Plate Steel Plates
6196	Quantity of (5) Diamond Plate Steel Plates S/N: Not Available		S/N: Not Available Usage: Not Available
	C/W: Assorted Size, One Pallett		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6209	Quantity of (5) 10 Gauge Steel Plates
6197	Quantity of (5) Diamond Plate Steel Plates	_	S/N: Not Available Usage: Not Available
0197	S/N: Not Available		Asset located in: Humble, TX
	C/W: Assorted Size, One Pallett	6210	Quantity of (5) 10 Gauge Steel Plates
	Usage: Not Available Asset located in : Humble, TX	0210	S/N: Not Available
6100	•		Usage: Not Available
6198	Quantity of (9) 10 Gauge Steel Plates S/N: Not Available		Asset located in: Humble, TX
	C/W: One Bundle	6211	Quantity of (5) 10 Gauge Steel Plates
	Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
6199	Quantity of (4) 10 Gauge Plate Steel Plates S/N: Not Available	6212	Quantity of (2) 4 Gauge Steel Plates
	C/W: one bundle		S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6200	Quantity of (8) 10 Gauge Steel Plates	6213	Quantity of (2) 89 Gauge Plate Steel Plates
	S/N: Not Available C/W: assorted size, one bundle		S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6214	Quantity of (3) 11 Gauge Steel Plates
6201	Quantity of (11) 10 Gauge Steel Plates		S/N: Not Available
	S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6215	Quantity of (2) 2024 Kit Containers 5 ft x 8 ft 6
6202	Quantity of (11) 10 Gauge Steel Plates	0215	in (.62 in Thick) Road Steel Plates (Unused)
	S/N: Not Available		S/N: Not Available
	C/W: assorted size, one bundle Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX	1014	Asset located in: Humble, TX
6203	Quantity of (3) 3/8 in Steel Plates	6216	Tulsa Rufnek Truck Winch S/N: Not Available
	S/N: Not Available		C/W: Steel
	C/W: Assorted Size, One Bundle Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6204	Quantity of (4) 3/8 in Steel Plates	6217	Braden Truck Winch
	S/N: Not Available		S/N: Not Available C/W: Steel, headache rack
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6205	Quantity of (4) 3/8 in Steel Plates	6218	Braden Truck Winch
	S/N: Not Available C/W: Assorted Size		S/N: Not Available C/W: Steel, headache rack
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6206	Quantity of (3) 3/16 in Steel Plates	6219	Tulsa Rufnek 30000 Lb Truck winch
	S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Steel, headache rack
	Asset located in: Humble, TX		Usage: Not Available
		ı	Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6220	Braden HP130A Hydraulic Truck Winch S/N: 1153781 C/W: Steel, headache rack Usage: Not Available	6233	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 252 Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6234	Fleet Standard Model 7 Fifth Wheel Wrecker
6221	Tulsa Truck Winch S/N: Not Available C/W: Steel, headache rack Usage: Not Available Asset located in: Humble, TX	6235	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Fleet Standard Model 7 Fifth Wheel Wrecker
6222	Freightliner Truck Cab S/N: Not Available Usage: Not Available Asset located in: Humble, TX	0233	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6223	Freightliner Day Truck Cab S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6236	Fleet Standard Model 7 Fifth Wheel Wrecker (Unused) S/N: Not Available Usage: Not Available
6224	Freightliner Cascadia Sleeper Cab S/N: Not Available	6237	Asset located in: Humble, TX Fleet Standard Model 7 Fifth Wheel Wrecker
	C/W: 60 in sleeper Usage: Not Available Asset located in : Humble, TX		(Unused) S/N: Not Available Usage: Not Available
6225	Paccar Truck Cab - Fits Kenworth T600		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6238	Fifth Wheel Wrecker S/N: Not Available
6226	60 In Truck Sleeper - Fits Kenworth		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6239	Gray TSJ55 11000 Lb Truck Scissor Jack S/N: Not Available Usage: Not Available
6227	Liftmore 3200REE Hydraulic Truck Crane		Asset located in: Humble, TX
	S/N: 12-4205W120 Usage: Not Available Asset located in : Humble, TX	6240	Crysteel StingRay Dump Bed Hoist S/N: Not Available
6228	Liftmoore 3200REE Hydraulic Truck Crane S/N: 12-4206W120 C/W: 16 ft reach		C/W: To Fit Crysteel Manufacturing Inc StingRay material hoist Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: Not Available Asset located in : Humble, TX		THE INSPECTION REPORT Asset located in: Humble, TX
6229	Venturo CE1500 Mechanical Truck Crane S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6241	Tandem Axle S/N: Not Available C/W: Volvo Air Ride Suspension, Aluminum Rims, Super Singles Usage: Not Available
6230	2024 Neks Fifth Wheel Wrecker (Unused)		Asset located in: Humble, TX
	S/N: 251 Usage: Not Available Asset located in : Humble, TX	6242	Tandem Axle S/N: Not Available C/W: Air Ride Suspension
6231	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 253		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6243	Allison Automatic Transmission
6232	2024 Neks Fifth Wheel Wrecker (Unused) S/N: 254 Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6244	Tandem Truck Axle S/N: Not Available C/W: Spring over beam suspension Usage: Not Available Asset located in: Humble, TX	6256	Single Axle S/N: Not Available C/W: Air Ride Suspension Usage: Not Available Asset located in: Humble, TX
6245	Steerable Air Lift Axle S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6257	Western Star Truck Hood S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6246	Steerable Air Lift Axle S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6258	Quantity of (4) Pallets of Car Parts S/N: Not Available C/W: Assorted Filters, Belts, Gaskets Usage: Not Available
6247	T/A Assembly S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6259	Asset located in: Humble, TX Trail King Stinger S/N: Not Available C/W: Steel Usage: Not Available
6248	1995 Fontaine DT-1-20 S/A Booster Axle S/N: 13NM04106T1569890 C/W: Flip-Up, Air Ride Suspension Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6260	Asset located in: Humble, TX Quantity of (4) Flip Up Neck Extensions S/N: Not Available C/W: Steel Usage: Not Available Asset located in: Humble, TX
6249	Single Axle S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6261	4 ft 6 in Neck Extension S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6250	Single Axle S/N: Not Available C/W: Mack air ride suspension, ratio 2.93 Usage: Not Available Asset located in: Humble, TX	6262 6263	Holland Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6251	Single Axle S/N: Not Available C/W: Air Ride Suspension, Fixed Fifth Wheel Usage: Not Available		Quantity of (2) Fifth Wheel S/N: Not Available C/W: (3) frame rail sections Usage: Not Available Asset located in: Humble, TX
6252	Asset located in: Humble, TX Axle S/N: Not Available C/W: Kenworth Air ride suspension, Spicer Usage: Not Available	6264	Holland Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX Holland Fifth Wheel
6253	Asset located in: Humble, TX Single Axle S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6254	C/W: Flex suspension, Spicer 3.36 Usage: Not Available Asset located in: Humble, TX Tandem Axle	6266	Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available
UZU4	S/N: Not Available C/W: Air Ride Suspension Usage: Not Available Asset located in: Humble, TX	6267	Asset located in: Humble, TX Fontaine Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6255	Single Axle S/N: Not Available C/W: Airliner suspension Usage: Not Available Asset located in: Humble, TX	6268	Asset located in: Humble, TX Holland Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6269	Holland Air Sliding Fifth Wheel S/N: Not Available C/W: w/Frame Usage: Not Available Asset located in: Humble, TX	6282	Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6270	Holland Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6283 6284	Air Sliding Fifth Wheel Frame S/N: Not Available Usage: Not Available Asset located in: Humble, TX Braden Winch
6271	Fontaine Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6272	Quantity of (2) Fontaine Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	—6285	Quantity of (2) Pallets of Frame Steps S/N: Not Available C/W: black, stainless steel Usage: Not Available Asset located in: Humble, TX
6273	Jost Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6286	Quantity of (20) Stainless Grab Handles S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6274	Quantity of (2) Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6287	Quantity of (6) Saddle Tank Steps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6275	Air Sliding Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6288	Quantity of (3) Pallets of Aluminum Deck Grading S/N: Not Available
6276	Holland Fifth Wheel S/N: Not Available Usage: Not Available		C/W: (15) 34 in x 35 in Usage: Not Available Asset located in : Humble, TX
6277	Asset located in: Humble, TX Holland Fifth Wheel S/N: Not Available Usage: Not Available	6289	Hydraulic Pump S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6278	Asset located in: Humble, TX Holland Air Slide Fifth Wheel S/N: Not Available Usage: Not Available	6290	Quantity of Paccar Aluminum Cross Member S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6279	Asset located in: Humble, TX Jost Fifth Wheel S/N: Not Available Usage: Not Available	6291	Quantity of Quarter Fenders S/N: 50567 Usage: Not Available Asset located in : Humble, TX
6280	Asset located in: Humble, TX Holland Fifth Wheel Plate S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6292	Quantity of Steps S/N: 50565 Usage: Not Available Asset located in : Humble, TX
6281	Asset located in: Humble, TX Quantity of (2) Fifth Wheel S/N: Not Available Usage: Not Available	6293	Quantity of Frame Sections S/N: 50552 Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6294	Quantity of Crossmembers S/N: 50553 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6295	Brush Guard S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6307	Quantity of Mudflaps S/N: Not Available C/W: brackets Usage: Not Available Asset located in: Humble, TX
6296	Quantity of Chrome Bumper S/N: Not Available C/W: Assorted Type, One Pallett Usage: Not Available Asset located in: Humble, TX	6308	Quantity of (2) Aluminum Diesel Fuel Tank S/N: Not Available C/W: (1) 120 gallon, (1) 100 gallon, mounting brackets Usage: Not Available
6297	Quantity of (2) Fifth Wheel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6309	Asset located in: Humble, TX 66 Gal Aluminum Fuel Tank S/N: 1104690060A042A Usage: Not Available
6298	Quantity of (3) Transfer Pumps (model TDX3E) (3) Hyd Motor Frame Mounted (1) Side mount tool box S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	6310	Asset located in: Humble, TX 50 Gal Aluminum Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6299	Quantity of (3) Freightliner Wind Skirts S/N: Not Available C/W: One Pallet Usage: Not Available	6311	Wet Kit S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Humble, TX
6300	Asset located in: Humble, TX Quantity of Mud Flaps & Hangers S/N: Not Available Usage: Not Available	6312	Hydraulic Tank w/ Mounts S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6301	Asset located in: Humble, TX Quantity of (2) Magni H10I 22000 lb Hooks S/N: AC009414/AC008607 Usage: Not Available Asset located in: Humble, TX	6313	100 gal Aluminum Tank w/ saddle mounts, steps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6302	Quantity of Truck Bumper S/N: 50558 Usage: Not Available Asset located in: Humble, TX	6314	Aluminum Diesel Tank S/N: 50551 Usage: Not Available Asset located in: Humble, TX
6303	Quantity of Leaf Springs S/N: 50563 Usage: Not Available Asset located in: Humble, TX	6315	Mac 70 Gal Aluminum Fuel Tank S/N: V051730999 C/W: mounting kit Usage: Not Available
6304	Quantity of Crossmembers S/N: 50568 Usage: Not Available Asset located in: Humble, TX	6316	Asset located in: Humble, TX Peterbilt 60 Gal Aluminum Fuel Tank S/N: 11-04805-025T0300 C/W: straps, mount bracelets, one pallet Usage: Not Available
6305 6306	Front Bumper & Side Skirt - Fits T880 S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of Quarter Fenders	6317	Asset located in: Humble, TX Wet Kit S/N: 50550 C/W: (1) PTO, (2) tanks, (2) pumps Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6318	Asset located in: Humble, TX Quantity of (2) Hydraulic Tank S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6319	Wet Kit	6330	Truck Tractor Fuel Tank
0015	S/N: Not Available	0330	S/N: Not Available
	C/W: pump, hydraulic tank, hoses		Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6331	Quantity of (2) Transfer Tanks
6320	Quantity of (2) Truck Boxes S/N: Not Available		S/N: Not Available
	C/W: Steel		C/W: 105 gal L-Shaped, rectangle, (1) Pallet Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE	6332	Quantity of (3) Transfer Tanks
	THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available
6221		-	C/W: (2) 105 gal L-shaped tanks, (1) rectangle
6321	Quantity of Hose Reels S/N: Not Available		tank Usage: Not Available
	C/W: nozzles		Asset located in: Humble, TX
	Usage: Not Available	6333	Quantity of Transfer Tanks
	Asset located in: Humble, TX	_	S/N: Not Available
6322	Aluminum Truck Box		C/W: L-shaped, Rectangle, (1) Pallet
	S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE	6004	·
	THE INSPECTION REPORT	6334	Quantity of (4) Pallets of Toolboxes S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
6323	Quantity of (4) Truck Boxes		Asset located in: Humble, TX
	S/N: Not Available	6335	Quantity of (2) 105 Gal L-Shaped Transfer Tanks
	Usage: Not Available		
	Asset located in: Humble, TX	_	S/N: Not Available
6324	Truck Box	6336	C/W: (1) Pallet Usage: Not Available
	S/N: Not Available C/W: Steel		Asset located in: Humble, TX
	Usage: Not Available		Steel Hydraulic Tank
	Asset located in: Humble, TX		S/N: 50564
6325	Truck Box		C/W: hydraulic cylinder
	S/N: Not Available C/W: Steel	6337	Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available		Quantity of (2) DEF Tank
	Asset located in: Humble, TX	0337	S/N: 50562
6326	Quantity of (2) Truck Boxes		Usage: Not Available
	S/N: Not Available		Notes: DEFICIENCIES NOTED - PLEASE SEE
	C/W: Steel Usage: Not Available		THE INSPECTION REPORT
	Asset located in: Humble, TX	5000	Asset located in: Humble, TX
6327	Quantity of L-Shaped Transfer Tank & Toolbox	6338	Sturdy-Lite Truck Box
0327	S/N: Not Available		S/N: 50556 C/W: Aluminum
	C/W: (1) Pallet		Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6339	Quantity of (2) Truck Boxes
6328	Quantity of (2) L-Shaped Transfer Tanks		S/N: 50566 C/W: Steel
	S/N: Not Available Usage: Not Available		C/W: Steel Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6329	Quantity of (2) Pallets of Toolboxes	6340	Steel Hydraulic Tank
5527	S/N: Not Available		S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6341	Gooseneck Tongue S/N: 50557 C/W: Steel Usage: Not Available Asset located in: Humble, TX	6352	Quantity of (2) Pallets of Transfer Tanks S/N: Not Available C/W: (2) L-Shaped tanks, (1) rectangle tank, (1) Tank/Toolbox combo Usage: Not Available Asset located in: Humble, TX
6342	Differential	1050	
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6353	McNeilus 10 1/2 Cu Yd Mixer S/N: 9673641898 C/W: Tag Axle, Fenders, Chutes, Hydraulic Tank Usage: Not Available
6343	Differential		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6354	Sliding Fifth Wheel Mount S/N: Not Available C/W: Sliding Fifth Wheel Mount
6344	2013 Rockwell RR23-160 Differential S/N: 0112092		Usage: Not Available Asset located in: Humble, TX
	C/W: 3.58 Ratio Usage: Not Available Asset located in : Humble, TX	6355	Vacuum Pump S/N: Not Available
6345	Differential		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6356	Roots Vacuum Pump S/N: LR138512 Usage: Not Available
6346	Differential		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6357	Roots Vacuum Pump S/N: LR054538
6347	Quantity of Steel Side Mount Tool Boxes &		Usage: Not Available Asset located in: Humble, TX
	Tank S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	6358	Quantity of 6 ft 6 in Trailer Ramps (Unused) S/N: Not Available C/W: Steel Usage: Not Available Asset located in: Humble, TX
6348	Quantity of Tractor Air Lines S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	6359	Lund 56 In Flush Mount Toolbox S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6349	Quantity of Assorted Chains S/N: Not Available C/W: assorted length Usage: Not Available Asset located in: Humble, TX	6360	Braden AMS20 Truck Winch S/N: 800329 C/W: Headache Rack, Tail Roll, Steps Usage: Not Available Asset located in: Humble, TX
6350	Quantity of (5) Tool Boxes S/N: Not Available C/W: assorted size Usage: Not Available	6361	Quantity of (3) Pallets of Toolboxes S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6351	Asset located in: Humble, TX Quantity of (3) Pallets of L-Shaped Transfer Tanks S/N: Not Available C/W: (6) Tanks Usage: Not Available	6362	Quantity of (1) Pallets of L-Shaped Transfer Tank & Toolbox S/N: Not Available
			C/W: one pallet Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6363	·
		10303	Quantity of (3) Pallets of L-Shaped Transfer Tanks S/N: Not Available C/W: (5) Tanks Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6364	Altec AM60E-MH 20 Ft Bucket Truck Bed S/N: 0515DM5610 C/W: 18 ft utility bed, 60 ft reach, 600 lb limit, stabilizers, two man basket Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM	6372	Additive Tank Truck Body S/N: Not Available C/W: Steel, 22 ft Body Length Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
	Asset located in: Humble, TX	6373	2015 SP3027 Additive Tank Truck Body
6365	2015 McNeilus 10.5 CY Mixer Truck Body S/N: 92656-39587 C/W: Chutes, Fenders, Hydraulic Tank, Tag Axle Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM		S/N: Not Available C/W: Steel, 22 ft Body Length, triplex pump, 2 in. centrifugal pump, 360 gallon tank, eye wash station Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6374	Brenner Tank Truck Body
6366	2015 McNeilus 10.5 cu yd Concrete Mixer S/N: 92660-39589 C/W: Steel, booster axle, fenders, chutes, hydraulic tank Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM	6375	S/N: Not Available C/W: 4700 gal Stainless Steel, 19 ft 6 in Body Length Usage: Not Available Asset located in: Humble, TX 2016 Treater Kill Truck Body
	Asset located in: Humble, TX		S/N: Not Available Usage: Not Available
6367	2017 McNeilus 10.5 CY Mixer		Asset located in: Humble, TX
	S/N: 9673141896 C/W: fenders, hydraulic tank, chutes, tag axle Usage: Not Available Notes : BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM	6376	dump box S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6377	Truck Dump Body
6368	2017 McNeilus 10.5 CY Concrete Mixer Drum S/N: 92624-39575 C/W: 80 gal Steel, 3 chutes, frame rails, hydraulic tank, fenders, tag axle, accessories		S/N: Not Available C/W: Steel, 16 ft Body Length Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX	6378	13 ft Dump Bed S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6369	2019 Beck 11 CY Concrete Mixer Drum	6070	· · · · · · · · · · · · · · · · · · ·
0309	S/N: F-19-32 Usage: Not Available Notes : BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM	6379	Truck Dump Body S/N: Not Available C/W: Steel, 15 ft Body Length, Manual Tarp Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6380	Heil Truck Dump Body
6370	2015 McNeilus 10.5 CY Mixer S/N: 92656-39587 Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX		S/N: Not Available C/W: Steel, 15 ft Body Length, Electric Tarp Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6371	Paint Striping Bed S/N: Not Available C/W: 12 ft Main Deck, 6 ft Upper Deck, Arrow Board & Tanks Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX	6381	EZ Dumper 8 Ft 6 In Slide-In Dump Bed S/N: 411163 C/W: Steel Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6382	18 Ft Winch Truck Bed S/N: Not Available C/W: (2) Braden winches Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM	6392	lowa Molding Co 7500-22 Truck Booms S/N: 7500151045 C/W: Stabilizers Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6393	24 Ft Flatbed Dump S/N: Not Available
6383	Winch Truck Bed S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6394	24 Ft Flatbed Dump
6384	16 Ft Winch Truck Bed S/N: Not Available C/W: Braden winch, Tulsa winch		S/N: Not Available C/W: Lift cylinders Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX	6395	24 Ft Truck Flatbed S/N: 69480 C/W: Nalco Champion 3500 lb crane Usage: Not Available
6385	Kidron 22RUIASW90-SP 22 Ft Reefer Van Box	1	Asset located in: Humble, TX
	S/N: 01K00609 C/W: Carrier Transcold reefer unit, roll up door, side entry Usage: Not Available Asset located in : Humble, TX	6400	Dakota 168-FB 14 Ft Flatbed S/N: DB12063 C/W: storage boxes Usage: Not Available Asset located in: Humble, TX
6386	2011 Mickey CB18085 18 Ft Van Body S/N: 1662V11 C/W: 4 Side Bays Usage: Not Available Asset located in: Humble, TX	6401	Ram 8 Ft 9 In LWB Truck Bed & Utility Top S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6387	2014 Delta-Waseca 26 Ft Van Truck Body S/N: 98414 C/W: Palfinger ILD44 lift gate, roll up door, side entry Usage: Not Available	6402	GMC Pickup Truck Bed S/N: Not Available C/W: 8 ft Body Length, slip in bed liner Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6404	Cat D379 Engine
6388	Morgan 20 Ft Van Truck Body S/N: Not Available C/W: roll up door Usage: Not Available		S/N: Not Available C/W: 8 Cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6405	Cat Engine
6389	SpaceKap Utility Body S/N: Not Available C/W: 6 ft 6 in Body Length Usage: Not Available		S/N: 68Z00901 C/W: 8 Cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	6406	Cat 398 Engine
6390	9 Ft Mechanic Truck Bed S/N: Not Available C/W: crane		S/N: 36Z00964 C/W: 16 cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6407	
6391	2019 Hiab X-Duo 148 Hydraulic Truck Mounted Boom S/N: 3L148DU00125 Usage: Not Available	6407	Cat 3508 Engine S/N: Not Available C/W: 8 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6408	Cat 3126 Engine S/N: 7AS27820 C/W: 1998 US EPA Label, Cat 3126 6 Cylinder 246 hp 7.2 L Diesel Engine Usage: Not Available

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6409	Cat Engine S/N: Not Available C/W: Cat Diesel Engine Usage: Not Available Asset located in: Humble, TX	6421	Cummins QSB4.5 Engine S/N: 73283978 C/W: 2011 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available Asset located in: Humble TY
6410	Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX	6422	Asset located in: Humble, TX John Deere 4045TF150 Engine S/N: T04045TF150 C/W: 1997 US EPA Label, 4 Cylinder Diesel Engine Usage: Not Available
6412	Cat 3306 Engine & Transmission S/N: 08Z82713 C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6423	Asset located in: Humble, TX Detroit Diesel Engine S/N: Not Available C/W: 3 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX
6413	Cat Engine & Transmission S/N: 08773184 C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	6424	Detroit Diesel Engine S/N: 4FD1177 C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX Detroit Diesel Engine S/N: 3D180238
6415	Cummins ISB Engine S/N: 46877187 C/W: 6 Cylinder 240 hp 6.7 L Diesel Engine Usage: Not Available		C/W: 4 Cylinder Diesel Engine Usage: Not Available Asset located in : Humble, TX
6416	Asset located in: Humble, TX Cummins Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine	6426	Detroit Engine S/N: 3D187051 C/W: Diesel Engine Usage: Not Available Asset located in : Humble, TX
6417	Usage: Not Available Asset located in: Humble, TX Cummins QSB4.5 Engine S/N: 46718254 C/W: 2007 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available Asset located in: Humble, TX	6427	1988 Dresser Engine S/N: 44260194 C/W: Dresser D359T 6 Cylinder 130 hp 5.9 L Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6418	Cummins QSB4.5 Engine S/N: 73221792 C/W: 2011 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available Asset located in: Humble, TX	6428	Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
6419	Cummins QSB4.5 Engine S/N: 73246394 C/W: 2011 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available Asset located in: Humble, TX Cummins QSB4.5 Engine	6429	Asset located in: Humble, TX 2007 Nissan Frontier Engine S/N: Not Available C/W: 6 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 46744958 C/W: 2007 US EPA Label, 4 Cylinder 110 hp 4.5 L Diesel Engine Usage: Not Available Asset located in : Humble, TX	6430	Asset located in: Humble, TX Impco Engine S/N: Not Available C/W: IMRCO 4 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6431	International T444E Engine S/N: Not Available C/W: 2000 US EPA Label, B175 V8 175 hp 7.3 L Diesel Engine, automatic transmission Usage: Not Available Asset located in: Humble, TX	6441	2024 AGT ATK-B1000 10000 lb Two-Post Car Lift (Unused) S/N: ATK-B100024080502B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT
6432	Mitsubishi Truck Engine S/N: Not Available C/W: 6 Cylinder Diesel Engine Usage: Not Available	6442	Usage: Not Available Asset located in: Humble, TX 2024 Agriquip GLTC24 Tire Changer (Unused)
	Asset located in: Humble, TX	0442	S/N: Not Available
6433	Moro Truck Vacuum Pump S/N: 50555 Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6435	Mack Manual Transmission	T	Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6443	2024 Agriquip GLTC24 Tire Changer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6436	Ford Automatic Transmission S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6437	1992 Detroit Diesel Series 60 Engine &	6444	2024 Powertek PT620 Tire Changer (Unused)
0437	Transmission S/N: Not Available C/W: 1992 US EPA Label, 6 Cylinder 12.7 L	0-1-1	S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Diecel Engine Eaton Fuller transmission	6445	2024 Powertek PT620 Tire Changer (Unused) S/N: Not Available
6438		1	Usage: Not Available Asset located in: Humble, TX
	Car Lift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6446	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042603H Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6447	2024 AGT ATK-TC24 Tire Changer (Unused) S/N: ATK-TC2424042601H Usage: Not Available
6439	2024 Agriquip GLTP4500 10000 lb Two-Post Car Lift (Unused)		Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6448	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6440	2024 AGT ATK-B1000 10000 lb Two-Post Car	1	Asset located in: Humble, TX
	Lift (Unused) S/N: ATK-B100024080501B C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6449	2024 Agriquip GLWB8100 Wheel Balancer (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6450	2024 AGT ATK-WB24A Wheel Balancer (Unused) S/N: ATK-WB24A24042602H Usage: Not Available Asset located in: Humble, TX	6462	2024 Hills Industrial 1205026 120 ft x 50 ft x 26 ft Double Truss Storage Building (Unused) S/N: Not Available C/W: Quantity of (5) Boxes - Builds (1) Storage Building Usage: Not Available
6451	Quantity of Coats (1) Coats 70X-8H-3 Tire		Asset located in: Humble, TX
	Machine & (1) Coats 1250 Tire Balancer Tires S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6463	2024 Hills Industrial 1205026 120 ft x 50 ft x 26 ft Double Truss Storage Building (Unused) S/N: Not Available
6452	Truck Scale S/N: Not Available Usage: Not Available		C/W: Quantity of (5) Boxes - Builds (1) Storage Building Usage: Not Available Asset located in : Humble, TX
	Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6464	2024 Hills Industrial 1005026 100 ft x 50 ft x 26 ft Double Truss Storage Building (Unused) S/N: Not Available
	Asset located in: Livingston, LA	_	C/W: Quantity of (4) Boxes - Builds (1) Storage Building
6453	40 ft Bridge Platform (Unused) S/N: Not Available		Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6465	2024 Suihe S5010023DP-750gPVC 100 ft x 50
6454	40 ft Bridge (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		ft x 23 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (4) Boxes - Builds (1) Storage Building. Usage: Not Available
6455	25 ft Bridge Platform (Unused)	_	Asset located in: Humble, TX
0455	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6466	2024 Suihe S408023DP-610gPVC 80 ft x 40 x 23 ft Storage Building (Unused) S/N: Not Available
6456	25 ft Bridge Platform (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX		C/W: Quantity of (3) Boxes - Builds (1) Storage Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6457	25 Ft Bridge (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6467	2024 Suihe S406423DP-610gPVC 64 ft x 40 ft x 23 ft Storage Building (Unused)
6458	25 ft Bridge (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage Building. Usage: Not Available Asset located in : Humble, TX
6459	25 Ft Loading Ramp (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6468	2024 Hills Industrial 804024 80 ft x 40 ft x 24 Ft Double Truss Storage Building (Unused) S/N: Not Available C/W: Quantity of (3) Boxes - Builds (1) Storage
6460	25 Ft Loading Ramp (Unused) S/N: Not Available		Building Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6469	2024 Suihe S308515R-300gPE 85 ft x 30 ft x
6461	30 Ft Loading Ramp S/N: Not Available Usage: Not Available Asset located in: Humble, TX		15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION (THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6470	2024 Suihe S408020R-500gPVC 40 ft x 80 ft x 20 ft Storage Building (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage	6479	40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Building, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6480	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES
6471	2024 Suihe S306515R-300gPE 65 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6481	30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Shelter Dome, 420 PE Fabric Usage: Not Available
6472	60 ft x 40 ft Storage Building		Asset located in: Humble, TX
	S/N: Not Available C/W: 2 boxes, 450 GSM Fabric, Double Truss Frame Storage Building, Pipe: Hot-Dipped Galvanized Steel Base Flange as Foundation On The Ground Commercial Fabric PVC Cover Allows Natural Light In While Blocking Harmful UV Water Proof - UV - Fire - Wind - Snow Resistant Mechanical Doors At Both Ends Usage: Not Available Asset located in: Humble, TX	6482	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12 ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6473	2024 Suihe S306020DP-610gPVC 60 ft x 30 ft	6483	2024 Suihe 203012R-300gPE 30 ft x 20 ft x 12
<u> </u>	x 20ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	0483	ft Storage Building (Unused) S/N: Not Available C/W: Dome Frame, PE Fabric, 2-Year PE Estimated Service Life, THE PRODUCT IMAG SHOWN ARE FOR ILLUSTRATION PURPOSE
6474	2024 Suihe C504017DR-610gPVC 50 ft x 40 ft x 17 ft Storage Canopy (Unused) S/N: Not Available Usage: Not Available		ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6475	Asset located in: Humble, TX 2024 Suihe S204016DP 40 ft x 20 ft x 16 ft Storage Building (Unused)	6484	MC3050 50 ft x 30 ft Storage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available	6485	MC3050 50 ft x 30 ft Storage Building (Unused)
6476	Asset located in: Humble, TX 2024 Suihe S204016DP 40 ft x 20 ft x 16 ft Storage Building (Unused)	6485	S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6486	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available
6477	40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: Dome Type Single Truss, 420 PE Fabric Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6478	40 ft x 30 ft x 15 ft Storage Building (Unused) S/N: Not Available C/W: Dome Type Single Truss, 420 PE Fabric Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
6487	2024 Suihe C404015S-610gPVC 40 ft x 40 ft x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6494	Storage Canopy S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
		6495	Suihe 20 ft x 20 ft Storage Canopy (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
6488	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6496	2024 Suihe P2040 40 ft x 20 ft Commercial Party Tent (Unused) S/N: Not Available C/W: (18) Removable Side Walls w/PVC Clear Windows, (2) Zipper Doors, 500 gsm PVC Coated Fabrics, Waterproof, Fire & UV Resistant, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
6489	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused)		Usage: Not Available Asset located in: Humble, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6497	2024 Landhonor LHR-ST3040 40 ft x 30 ft Storage Building (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION	
6490	2024 Suihe C404015S-610gPVC x 15 ft Container Storage Canopy (Unused)		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Landhonor LHR-ST3085 85 ft x 30 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
6491	2024 Suihe C2040-300gPE Container Storage Canopy (Unused)		Usage: Not Available Asset located in : Humble, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6499	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN AR FOR ILLUSTRATION PURPOSES ONLY AN MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6492	2024 Suihe C2040-300gPE Container Storage Canopy (Unused)		Usage: Not Available Asset located in: Humble, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6500	2024 Landhonor LHR-MS0608 6 Ft x 8 Ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
6493	2024 Suihe C2020-300gPE Container Storage Canopy (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
6501 6502	2024 Landhonor LHR-MS0608 6 Ft x 8 Ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed	6508	2024 KJ K4230 Metal Storage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K4230 Metal Storage Shed (Unused)
0302	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed; THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6503	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6510	2024 KJ K2430T Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6504	2024 Landhonor PLD-MS0604P 6 ft x 4 ft Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6511	2024 KJ K2430T Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6505	Steel Container Roof Kit (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Humble, TX	6512 	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6506	Steel Container Roof Kit (Unused) S/N: Not Available C/W: One Rack Usage: Not Available Asset located in: Humble, TX	6513	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6507	2024 KJ K2430T 24 Ft x 30 Ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Metal Shed, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6514	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6515	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6516	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
6517	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6524	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K3325 33 ft x 25 ft Metal Garage	
6519	2024 DG2642 42 ft x 26 ft All Vertical Metal Garage Building (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6525	(Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	
6520	2024 Suihe GS2533 33 ft x 25 ft Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
6521	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6527	(Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) S Building THE PRODUCT IMAGES SHOW	
6522	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6528	6528 2024 KJ K3325 33 ft x 25 ft Metal Gara (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Building THE PRODUCT IMAGES SHOV	•
6523	2024 KJ K3325 33 ft x 25 ft Metal Garage (Unused) S/N: Not Available C/W: Quantity of (2) Boxes - Builds (1) Storage Building THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
		6529	2024 Suihe GS2322 23 ft x 22 ft Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
6530	2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6537	2024 Agriquip DG2323 23 Ft x 22Ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6531	2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6538	2024 Agriquip DG2322 23 Ft x 22 Ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6532	2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6539	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6533	2024 KJ K2119 22 ft x 23 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6540	2024 Agriquip DG2322 Double Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6534 6535	TMG MSC2030F 20 ft x 30 ft Metal Garage Shed S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Humble, TX 2024 Agriquip DG2322 23 Ft x 22 Ft Double Metal Garage (Unused)	6541	2024 SUNTOP S2119 19 ft x 21 ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6526	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 KJ K3030 30 ft x 30 ft x 14 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
6536	2024 Agriquip DG2322 23 Ft x 22 Ft Double Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6543	Usage: Not Available Asset located in: Humble, TX 2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6544	2024 Agriquip SG1420 14 ft x 20 ft Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6551	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6545	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6552	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6546	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6553	2024 SUNTOP S1220 12 Ft x 20 Ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6547	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6554	2024 SUNTOP S1220 12 Ft x 20 Ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: LOCATED-IN-HUMBLE-TX
6548	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Agriquip SG1420 Single Garage Metal	6555	Asset located in: Humble, TX 2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
0049	Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 KJ K2030 30 ft x 20 ft Metal Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6550	2024 Agriquip SG1420 Single Garage Metal Shed (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6557	2024 KJ K2030 30 ft x 20 ft Metal Carport (Unused) S/N: Not Available	6565	12 ft x 21 ft x 10 ft Carport (Unused) S/N: Not Available Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF	6566	12 ft x 21 ft x 10 ft Carport (Unused)
	THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6559	2024 Agriquip CP2030 30 ft x 20 ft Steel	6567	18 ft x 21 ft x 10 ft Carport (Unused)
	Carport (Unused)		S/N: Not Available
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND	6560	Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6568	24 ft x 21 ft x 10 ft Carport (Unused) S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6560	2024 Agriquip CP2030 30 ft x 20 ft Steel	6569	18 ft x 25 ft x 10 ft Carport (Unused)
	Carport (Unused)		S/N: Not Available
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND	6570	
	MAY NOT BE AN EXACT REPRESENTATION OF	05/0	Diggit 20 ft x 20 ft Carport (Unused) S/N: Not Available
	THE ACTUAL PRODUCT Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6561	2024 Agriquip CP2030 30 ft x 20 ft Steel	6571	2024 Agriquip CP2020 20 ft x 20 ft Steel
	Carport (Unused)		Carport (Unused)
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
	FOR ILLUSTRATION PURPOSES ONLY AND		FOR ILLUSTRATION PURPOSES ONLY AND
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
6562	2024 Agriquip CP2030 30 ft x 20 ft Steel	6572	2024 Agriquip CP2020 20 ft x 20 ft Steel
	Carport (Unused) S/N: Not Available		Carport (Unused) S/N: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE		C/W: THE PRODUCT IMAGES SHOWN ARE
	FOR ILLUSTRATION PURPOSES ONLY AND		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		THE ACTUAL PRODUCT
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6563	2024 Agriquip CP2030 30 ft x 20 ft Steel	6573	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused)
	Carport (Unused) S/N: Not Available		S/N: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE		C/W: THE PRODUCT IMAGES SHOWN ARE
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	THE ACTUAL PRODUCT		THE ACTUAL PRODUCT
	Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
<u> </u>	Asset located in: Humble, TX	6574	· · · · · · · · · · · · · · · · · · ·
6564	2024 Agriquip CP2030 30 ft x 20 ft Steel Carport (Unused)	6574	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused)
	S/N: Not Available		S/N: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE		C/W: THE PRODUCT IMAGES SHOWN ARE
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
	THE ACTUAL PRODUCT		THE ACTUAL PRODUCT
	Usage: Not Available		Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	l	ASSEL IOCALEU III. MUITIDIE, IX

Lot #	Details	Lot #	Details	
6575	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6582	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available	
6576	2024 Agriquip CP2020 20 ft x 20 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6584	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available	
6577	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		C/W: THE PRODUCT IMAGES SHOWN FOR ILLUSTRATION PURPOSES ONL' MAY NOT BE AN EXACT REPRESENT THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6578	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONLY	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6586	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available	
6579	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONI	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6587	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available	
6580	Erie Industries MSC2020F 20 ft x 20 ft All-Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6588	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available	
6581	2024 Landhonor LHR-CP2020F 20 ft x 20 ft All- Steel Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
6589	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6596	2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	6597	2024 KJ K1119 11 ft x 19 ft Carport (Unused)	
6590	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	6598	2024 KJ K1119 11 ft x 19 ft Carport (Unused)	
6591	2024 Agriquip CP1220 20 ft x 12 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	6599	<u>=</u> D	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT		2024 Suihe M122009P 20 ft x 12 ft Steel	
	Usage: Not Available Asset located in: Humble, TX		Carport (Unused)	
6592	2024 KJ K1119 11 ft x 19 ft Carport (Unused)		S/N: Not Available Usage: Not Available	
0392	S/N: Not Available		Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6600	2024 SUNTOP S1119 19 ft x 11 ft x 9 ft Steel Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	
6593	2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	FOR ILLUSTRATION PURPOSES ONLY AND	6604	Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	FOR ILLUSTRATION PURPOSES ONLY AN MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available	Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6594	2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6602	2024 KJ K1220 20 ft x 12 ft Metal Garage (Unused)	
	Asset located in: Humble, TX	4	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6595	2024 KJ K1119 11 ft x 19 ft Carport (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT	6603	2024 Landhonor LHR-MS1119 19 ft x 11 ft	
	Usage: Not Available Asset located in: Humble, TX	0003	Metal Garage (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
6604	2024 Landhonor LHR-MS1119 19 ft x 11 ft Metal Garage (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6612	2 2024 KJ K1912 12 ft x 19 ft Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O
6605	2024 Landhonor LHR-CP1119 All-Steel Carport (Unused) S/N: Not Available Usage: Not Available	6613	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K1912 12 ft x 19 ft Livestock Shelter
	Asset located in: Humble, TX		(Unused)
6606	2024 Landhonor LHR-CP1119 19 ft x 11 ft All- Steel Carport (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6607	2024 SUNTOP S1912 12 ft x 20 ft Livestock		Asset located in: Humble, TX
	Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6614	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6608	2024 SUNTOP S1912 12 ft x 20 ft Livestock Shelter (Unused)		Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6615	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6609	2024 SUNTOP S2512 12 ft x 25 ft Livestock		Asset located in: Humble, TX
	Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6616	2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6610	2024 SUNTOP S2512 12 ft x 25 ft Livestock Shelter (Unused)		Asset located in: Humble, TX
6611	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 KJ K1912 12 ft x 19 ft Livestock Shelter		2024 Agriquip LS1220 12 ft x 20 ft Metal Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	(Unused)	6618	2024 Agriquip LS1220 12 ft x 20 ft Metal
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Livestock Shelter (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6619	Eingp MSC1220F 20 ft x 12 ft Galvanized Metal Livestock Shelter (Unused) S/N: M12S223145 Usage: Not Available Asset located in: Humble, TX Erie Industries MSC1220F 12 ft x 20 ft	6626	2024 KJ K2215 7 ft 4 in x 5 ft 1 Person Skid- Mounted Portable Toilet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
0020	Livestock Shelter (Unused) S/N: M12S223677 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		6627	2024 Suihe ST-SH(b) 1 Person Portable Toilet (Unused) S/N: Not Available C/W: (1) Sinks, (1) Showers, (1) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY
6621	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223602		NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	6628	Asset located in: Humble, TX 2024 Suihe NT-SH(b) 1 Person Portable Toilet
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	0028	(Unused) S/N: Not Available C/W: Toilet, Shower, Sink THE PRODUCT
6622	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223744 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT PERPESSINTATION OF		IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
		6629	2024 Suihe NT-SH(a) 1 Person Portable Toilet (Unused) S/N: Not Available
6623	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223534 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF		C/W: (1) Sinks, (1) Showers, (1) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6630	2024 Suihe NT-SH(b) 1 Person Portable Toilet (Unused)
6624	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223697 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: Toilet, Shower, Sink THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6631	2024 Suihe NT-D 2 Person Portable Toilet
6625	Erie Industries MSC1220F 12 ft x 20 ft Livestock Shelter (Unused) S/N: M12S223405 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available C/W: (2) Sinks, (2) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6632	2024 Suihe NT-D Portable Toilet (Unused) S/N: Not Available C/W: (2) Sinks, (2) Toilets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX 2024 Suihe NWB-H40DB-10 10 ft 40-Drawer	6640	2024 Suihe NWB-H35DS-7 7 ft 35-Drawer Tool Cabinet (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6641	2024 Suihe NWB-30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6634	2024 Suihe NWB-H30DS 9 ft 6 in 30-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Suihe NWB-H30DS 9 ft 6 in 30-Drawer Workbench (Unused)	6642	2024 Suihe NWB-30DS-10 Workbench S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		2024 Suihe NWB-25DB-10 10 ft 25-Drawer Workbench (Unused) S/N: Not Available
6636	2024 Suihe NWB-H30DS -9.5 9 ft 6 in 30- Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6637	2024 Suihe NWB-H30DS-10 10 ft 30-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6644	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6638	2024 Suihe NWB-H18DB-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6645	2024 Suihe NWB-18DS-2B-10 10 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6639	2024 Suihe NWB-H18DR-7 7 ft 18-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6646	2024 Suihe NWB-20DS-7 7 ft 20-Drawer Workbench (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
6647	2024 Suihe NWB-15DR-2 -10 10 ft 15-Drawer Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Suihe NWB-10DS-2-7 7 ft 10-Drawer Workbench (Unused) S/N: Not Available	6655	Quantity of (54) 2024 KJ K3830-56 10 ft Livestock Panel (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		6656 Quantity of (54) 2024 KJ K3856 10 ft Lives Panel (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOS	Quantity of (54) 2024 KJ K3856 10 ft Livestock Panel (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT
6649	2023 Titan West Bison XL Pen System S/N: Not Available C/W: Chute, Scale		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in : Humble, TX	6657	Quantity of 2024 Landhonor LHR-CP76 Corral	
6650	2024 Landhonor LHR-CSC10 10 Ft Cattle Squeeze Chute (Unused) S/N: Not Available		Livestock Panel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available	6658	Quantity of (36) 2024 Landhonor LHR-SP07 7	
6651	Asset located in: Humble, TX Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	6660	ft x 3 ft Livestock Panel (Unused) S/N: Not Available C/W: 5 gates Usage: Not Available Asset located in: Humble, TX	
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of (30) 2024 KJ K0710-30 10 ft x 7 f Powder Coated Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6652	Quantity of (56) 2024 SUNTOP S0510 10 ft x 5 ft Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6661	Quantity of (30) 2024 KJ K0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6653	Quantity of (56) 2024 Suihe NP10-54-2 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	6662	THE ACTUAL PRODUCT Usage: Not Available	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of (30) 2024 KJ K0710-30 10 ft x 7 Powder Coated Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
6654	Quantity of (56) 2024 Suihe SP10-S-56 10 ft Powder Coated Livestock Panel (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX			

Lot #	Details	Lot #	Details	
6663	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6669	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft	
	Asset located in: Humble, TX		Fencing (Unused)	
6664	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY	6671	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	
6665	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w /Connectors THE PRODUCT IMAGES SHOWN		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION O THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6672	Powder Coated Fencing (Unused) S/N: B44823 C/W: THE PRODUCT IMAGES SHOWN ARE	
6666	Quantity of (30) 2024 SUNTOP S0710-30 10 ft x 7 ft Powder Coated Fencing (Unused) S/N: Not Available C/W: (30) Fence Panels, (31) Post's w	6674		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	/Connectors THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		6673 Quantity of (22) Erie Industries F10 10 ft x Wrought Iron Site Fence S/N: Not Available C/W: (22) Fence Panels, (23) Post, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MA	Quantity of (22) Erie Industries F10 10 ft x 7 ft Wrought Iron Site Fence S/N: Not Available C/W: (22) Fence Panels, (23) Post, THE PRODUCT IMAGES SHOWN ARE FOR
6667	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE			NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of (22) Erie Industries F10 10 ft x 7 ft Wrought Iron Site Fence S/N: Not Available C/W: (22) Fence Panels, (23) Post, THE	
6668	Quantity of (24) 2024 Suihe F-X-24-4 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF TACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
6675	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6682	2024 Suihe SG 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6676	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6683	Quantity of (3) 2024 Suihe NFG-20FC-3 20 ft Wrought Iron Bi-Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6677	2024 GLWF1007 Welded Steel Fencing		Asset located in: Humble, TX
	(Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6684	Quantity of (3) 2024 Suihe NFG-20FB-3 Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: Metal Support Base Parts THE PRODUC IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
6678	Quantity of (20) 2024 Agriquip GLWF1007 10 ft x 7 ft Fencing (Unused) S/N: Not Available		PRODUCT Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		2024 KJ K0735D 20 ft x 7 ft Metal Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
6679	Quantity of (20) Canex 10 ft x 7 ft Wrought Iron Fencing (Unused) S/N: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6686	2024 KJ K0735E 20 ft x 7 ft Metal Farm Driveway Gate (Unused)
6680	2024 Suihe NFG-20FGP-E 20 ft Wrought Iron Bi- Parting Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6687	Quantity of (6) 2024 KJ K0720-6 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate
6681	2024 Suihe NFG-20FGP-D 20 ft Wrought Iron Bi- Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6688	2024 KJ K2007N 20 ft x 7 ft Metal Farm Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6689 6690	Quantity of (8) 2024 Suihe NG-20D-8 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (6) 2024 SUNTOP S0720 20 ft x 7 ft	6696	S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh Diameter: 3 MM Height = 2.1 M X 15.2 M (20
	Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Rolls) Barbed Wire 3000 Feet Barbed Wire Arms, Single: 92 Pieces Barbed Wire Arms, Double Arms: 8 Pieces Steel Bar: 48 Pieces Tie Wire: 1230 Pieces Line Wire: 3.5 MM (1950 Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available Asset located in: Humble, TX
6691	·	6607	
0091	Quantity of (6) 2024 SUNTOP S0720 20 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6697	Quantity of Premium Chain Link Fencing S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh Diameter: 3 MM Height = 2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire
	Asset located in: Humble, TX	4	Arms, Single: 92 Pieces Barbed Wire Arms,
6692	Quantity of (6) 2024 SUNTOP S207 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		Double Arms: 8 Pieces Steel Bar: 48 Pieces Tie Wire: 1230 Pieces Line Wire: 3.5 MM (1950 Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available Asset located in: Humble, TX
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6698	Quantity of Premium Chain Link Fencing S/N: Not Available
6693	Asset located in: Humble, TX Quantity of (8) 2024 Suihe SG-20D-8 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh Diameter: 3 MM Height = 2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire Arms, Single: 92 Pieces Barbed Wire Arms,
6694	Quantity of (2) 2024 KJ K0720-1 20 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Double Arms: 8 Pieces Steel Bar: 48 Pieces Tie Wire: 1230 Pieces Line Wire: 3.5 MM (1950 Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available
6695	Quantity of (2) 2024 Suihe NG-14T -2 14 ft x 7 ft Wrought Iron Bi-Parting Driveway Gate (Unused) S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6699	Quantity of Premium Chain Link Fencing S/N: Not Available C/W: Each Project Is 1000 Feet, Includes 2 Gates Each Gate Is 20 Feet (Double Sided Sliding) 1000 ft - 20 Feet X 2 Gate = 960 ft Post: 60 X 1.5 MM X 2.6 M,92 Pieces Corner Post: 8 Pieces Top Rails: 38 X 1.5 MM X 3 M, 98 Pieces Chain Link Mesh 60 X 60 mm Mesh Diameter: 3 MM Height = 2.1 M X 15.2 M (20 Rolls) Barbed Wire 3000 Feet Barbed Wire Arms, Single: 92 Pieces Barbed Wire Arms, Double Arms: 8 Pieces Steel Bar: 48 Pieces Tie	6705	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6706	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Wire: 1230 Pieces Line Wire: 3.5 MM (1950 Feet), 2 Lines Wire Tighter: 72 Pieces 20 ft Gate: 2 Sets (Includes Gate Post) Top Rails Connector: 28 Pieces Clamps: 400 Pieces Usage: Not Available	6707	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX	1=00	Asset located in: Humble, TX
6700	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6708	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6709	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused)
6701	Asset located in: Humble, TX 2024 SUNTOP G500 500 ft x 7 ft Chain Link	-	S/N: Not Available Usage: Not Available
0/01	Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Asset located in: Humble, TX
		6710	Quantity of (20) 2024 GLCF1006 10 ft x 6 ft Galvanized Chain Link Site Fence (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6711	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6
6702	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	6712	ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX		Quantity of (20) 2024 SUNTOP S0610 10 ft x 6
6703	2024 SUNTOP G500 500 ft x 7 ft Chain Link Galvanized Fencing (Unused) S/N: Not Available C/W: (2) Gates THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6713	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6
6704	Quantity of (26) 2024 Suihe SF-D-26 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6714	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6721	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6715	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6722	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6716	Quantity of (20) 2024 SUNTOP S0610 10 ft x 6 ft Chain Link Temporary Site Fence (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6723	Erie Industries QR4800 High Tensile Triple- layer Galvanized Barbed Wire (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6717	Quantity of (2) Pallets of Fixed Knot Fence Xtreme Black 12.0-12.5 6" 75" 330 Ft Fencing (Unused) S/N: Not Available Usage: Not Available	6724	2024 Kit Containers WB-90-243 26 in x 90 in Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6718	Asset located in: Humble, TX Quantity of (2) Pallets of Fixed Knot Fence Xtreme Black 12.0-12.5 6" 75" 330 Ft Fencing (Unused) S/N: Not Available Usage: Not Available	6725 6726	2024 Kit Containers WB-90-243 26 in. x 90 ln. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers WB-90-243 26 ln. x 90 ln.
6719	Asset located in: Humble, TX Quantity of (2) Pallets of Galvanized Fence Wright Co 12 2"x4"48" 100 ft. Fencing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6727	Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused)
6720	Quantity of (21) 2024 SUNTOP S4200 200 ft x 40 in Galvanized Farm Fencing (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6728	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6729	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details		
6730	2024 Kit Containers WB-90-243 26 In. x 90 In. Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6743	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused) S/N: Not Available C/W: (9) Panels, (1) Panel w/ Gate Usage: Not Available		
6731	Kit Containers WB-90-243 26 In. x 90 In.		Asset located in: Humble, TX		
	Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6744	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused) S/N: Not Available C/W: (NO GATE) Usage: Not Available		
6732	2024 Kit Containers ST-57 29 in x 57 in Workbench (Unused)		Asset located in: Humble, TX		
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6745	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused) S/N: Not Available C/W: (NO GATE)		
6733	2024 Kit Containers ST-57 29 In. x 57 In. Workbench (Unused)		Usage: Not Available Asset located in: Humble, TX		
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6746	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused)		
6734	2024 Kit Containers WB-60-190 26 In. x 60 In. Workbench (Unused) S/N: Not Available		S/N: Not Available C/W: (9) Panels, (1) Panel w/ Gate Usage: Not Available Asset located in : Humble, TX		
	Usage: Not Available Asset located in : Humble, TX	6747	Quantity of (2) Print Shack Job Site Box		
6735	2024 Kit Containers WB-60-190 26 in x 60 in Workbench (Unused)	1	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6748	Quantity of (2) Job Site Box S/N: Not Available Usage: Not Available		
6736	2024 Kit Containers WB-60-190 26 in x 60 in		Asset located in: Humble, TX		
	Workbench (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6749	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available		
6740A	Quantity of (25) 10 ft Livestock Panel		Asset located in: Humble, TX		
	S/N: Not Available C/W: (23) Panels, (2) Gated Panels Usage: Not Available Asset located in : Humble, TX	6750	Quantity of (3) Job Site Boxes of Misc. Tools S/N: Not Available C/W: (3)Corded Die Grinder 1 1/2 in, Cordless 1 1/2 in Die Grinder, (3) Corded 4 1/2 in Angle		
6740	Quantity of (3) Steel Fab Tables S/N: Not Available C/W: (1) 49 in x 72 in, (1) 48 in x 72 in, (1) 48 in x 96 in Usage: Not Available Asset located in: Humble, TX				Grinder, Corded 1/2 in Impact, Corded 1/2 in Hole Shooter, (2) Corded VSR Drill, Corded SDS Rotary Hammer, Bosch Laser Level, Grease Gun, Corded Deep cut band saw, Corded Band Saw, SDS Max Rotary Hammer, Rotary Hammer Drill, Welding Leads, (2) Cordless Band Saw, (2) Mag Drill Press Usage: Not Available
6741	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock Panel (Unused)		Asset located in: Humble, TX		
	S/N: Not Available C/W: (9) Panels, (1) Panel w/gate Usage: Not Available Asset located in: Humble, TX	6751	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available		
6742	Quantity of (10) 2024 24 ft x 5 Ft 8 In Livestock	6750	Asset located in: Humble, TX		
	Panel (Unused) S/N: Not Available C/W: (9) Panels, (1) Panel w/ Gate Usage: Not Available Asset located in: Humble, TX	6752	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6753	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available	6765	Justrite 60 Gal Flammable Storage Cabinet S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6766	Quantity of (3) Job Site Box
6754	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Asset located in: Humble, TX	0700	S/N: Not Available C/W: Fall protection, chain hoists Usage: Not Available Asset located in: Humble, TX
6755	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available	6767	Ridgid 48R-OS Job Site Box S/N: 1925312776 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6768	Erie Industries D6028 Chest Tool Box (Unused)
6756	Quantity of (3) Knaack 89 Job Site Box S/N: Not Available C/W: Contents Included Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6769	Erie Industries D2248 1 ft 8 in x 3 ft 6 in Chest
6757	Knaack Job Site Box with Contents S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6769	Tool Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION
6758	69 Jobsite Gangbox with Contractors Supplies S/N: Not Available Usage: Not Available		THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6770	Erie Industries D2248 1 ft 8 in x 3 ft 6 in Chest
6759 6760	Knaack 89 Jobsite Gangbox with Contractors Supplies S/N: Not Available Usage: Not Available Asset located in: Humble, TX Knaack 89 Jobsite Gangbox with Contractors	6770 	Tool Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Supplies		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6771	Erie Industries D2248 1 ft 8 in x 3 ft 6 in Chest Tool Box (Unused) S/N: Not Available
6761	Job Site Box with Contents S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
6762	Justrite 60 Gal Flammable Storage Cabinet		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6772	Erie Industries D2248 Chest Tool Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
6763	Quantity of (3) Flammables Storage Cabinet S/N: Not Available Usage: Not Available Asset located in: Humble, TX		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
6764	Durham 45 Gal Flammable Storage Cabinet S/N: Not Available Usage: Not Available Asset located in: Humble, TX		7.000.1000.00 111.1.010, 17

Lot #	Details	Lot #	Details
6773	Erie Industries D2248 Chest Tool Box (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	6787	Quantity of (4) Pipe Rollers S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		6788	Webb Tank Turner S/N: Not Available Usage: Not Available
6774	Erie Industries D2248 Chest Tool Box (Unused)		Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	6789	Quantity of (2) Hydrostatic Test Pump S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	6790	Quantity of (2) welding tables S/N: Not Available
6775	Asset located in: Humble, TX Skid Mounted Heat Exchanger Puller S/N: Not Available		Usage: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	6791	Quantity of (2) Welding Tables S/N: Not Available Usage: Not Available
6776	Quantity of Testing Equipment		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6792	Qty of shelving (2 pallets) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6777	Quantity of (4) Gas Cylinder Carts S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6793	Qty of jackstands (2 pallets) S/N: Not Available Usage: Not Available Asset located in : Humble, TX
6778		6794	· · · · · · · · · · · · · · · · · · ·
0//6	Quantity of (4) Cabinets S/N: Not Available C/W: (2) filing cabinets, (2) flammables cabinets	0/94	Quantity of (2) drill presses S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6795	Qty of electrical spider boxes (1 pallet)
6782	Quantity of (2) Blasting Tanks and (2) Sand Blaster		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6796	electric roller S/N: Not Available
6783	Quantity of (4) Pneumatic Sand Blaster		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6797	Quantity of (4) metal storage boxes S/N: Not Available
6784	Quantity of (4) Pneumatic Sand Blaster		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6798	Summit 2000 Table Saw S/N: Not Available
6785	Quantity of Hose	1	Usage: Not Available
J, 00	S/N: Not Available C/W: (4) Pallets Usage: Not Available	6799	Asset located in: Humble, TX Shop lift S/N: Not Available
	Asset located in: Humble, TX	_	Usage: Not Available
6786	Quantity of Hose S/N: Not Available C/W: (1) Tote Usage: Not Available Asset located in: Humble, TX	6800	Asset located in: Humble, TX Gray TSJ-55 5.5 Ton Transmission Jack S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6801	Quantity of Lug and Thread Bolts S/N: Not Available C/W: assorted size, one crate Usage: Not Available Asset located in: Humble, TX	6811	Quantity of Tools S/N: Not Available C/W: Beam clamps, duct, one pallet Usage: Not Available Asset located in: Humble, TX
6802	Quantity of Quantity of Gaskets, Saddle Anchors, Couplings and Clamps S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX	6812	Quantity of Tools S/N: Not Available C/W: (2) Miller Portble Welder, (2) Hilti Powder Actuated Decking Tool Usage: Not Available Asset located in: Humble, TX
6803	Quantity of Steel Toe Rubber Boots S/N: Not Available C/W: assorted size, one crate Usage: Not Available Asset located in: Humble, TX	6813	Quantity of Tools S/N: Not Available C/W: 1 1/2 Ton Chain Fall, 1 1/2 Ton Come Along, 2 Ton Chain Fall, 3 Ton Chain Fall Usage: Not Available Asset located in: Humble, TX
6804	Quantity of Tools and Hoses S/N: Not Available C/W: Jack Hammer, Hilti Drill Rig Kit, Magnetic Drill and Grease Guns, Air Hose, Discharge Hose, One Crate Usage: Not Available	6814	Quantity of Harness with Twin SRL's S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6805	Asset located in: Humble, TX Quantity of Welding Equipment S/N: Not Available C/W: Welding Wire, Pressure Gauges, Welding	6815	Quantity of Tools S/N: Not Available C/W: Grinders, Drills, Bandsaw, one pallet Usage: Not Available Asset located in: Humble, TX
6806	Rods, Plasma Torch and Shims, One Crate Usage: Not Available Asset located in: Humble, TX Quantity of Fittings and Flanges S/N: Not Available	6816	Pallet of Misc. Tools S/N: Not Available C/W: (3) 3/4 in Cordless Impact, 1/2 in Cordless Impact, Drill Bit Case, Corded Band Saw, SDS Max Hammer
	C/W: assorted size, one crate Usage: Not Available Asset located in : Humble, TX		Usage: Not Available Asset located in: Humble, TX
6807	Quantity of Fittings and Flanges S/N: Not Available C/W: assorted size, one pallet Usage: Not Available Asset located in: Humble, TX	6817	Quantity of (2) Hilti DX9-ENP Powder Actuated Decking Tools S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
6808	Pallet of Misc. Tools S/N: Not Available C/W: Leaf blower, Circular Saws, angle grinders, hammer drill, impact, electric drills Usage: Not Available Asset located in: Humble, TX	6818	Pallet of Misc. Tools S/N: Not Available C/W: (2) 2 Gallon Shop Vacuum, Tubing Bender Kit, Powder Actuated Tool, Metal Cutting Saw 8 in, Mag Drill, Corded Band Saw Usage: Not Available Asset located in: Humble, TX
6809	Pallet of Tools S/N: Not Available C/W: Rivet Buster, Recip. Saw, Rebar Straightener Usage: Not Available Asset located in: Humble, TX	6819	Pallet of Misc. Tools S/N: Not Available C/W: Lincoln Suitcase Welder, Plasma Cutter, Core Drill, Battery Charger Usage: Not Available Asset located in: Humble, TX
6810	Quantity of Tools S/N: Not Available C/W: 1 Ton Chain Fall, 2 Ton Beam Clamp, (4) 2 Ton Chain Fall, (4) 3 Ton Come Along, 3 Ton Chain Fall, (2) 1 1/2 Ton Come Along, (2) 2 Ton Come Along, (5) 1 1/2 Ton Chain Usage: Not Available Asset located in: Humble, TX	6820	Quantity of Tools S/N: Not Available C/W: 8-12 in Beam Clamp, (2) 2-6 in Beam Clamp, Battery Box 12V with Chargers, (2) 36 in Bolt Cutter Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6821	Quantity of Tools S/N: Not Available C/W: (4) Miss Ladders (2) Corded Light Tower	6832	BDS 200 Magnetic Drill w/Stand S/N: Not Available
	C/W: (4) Misc Ladders, (2) Corded Light Tower Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6833	Nitrile Inside Diaphragm Air Pump
6822	Quantity of Hand Tools & Gauges		S/N: Not Available
	S/N: Not Available C/W: one pallet		Usage: Not Available
	Usage: Not Available	1001	Asset located in: Humble, TX
	Asset located in: Humble, TX	6834	Quantity of Tools
6823	Quantity of Tools		S/N: Not Available C/W: One Pallet
	S/N: Not Available		Usage: Not Available
	C/W: (6) Hydraulic Pumps, (2) Pnuematic Air Guns		Asset located in: Humble, TX
	Usage: Not Available	6835	Pallet of Tools
	Asset located in: Humble, TX	_	S/N: Not Available Usage: Not Available
6824	Quantity of Nylon Sling		Asset located in: Humble, TX
	S/N: Not Available C/W: (4) Blue Endless Chockers, (4) Red	6836	Quantity of Contractor Supplies
	Endless Chockers, (4) Orange Endless		S/N: Not Available
	Chockers Usage: Not Available		C/W: Step Ladders, Shovels, Handles, Brooms, Stop Signs, (1) Pallet
	Asset located in: Humble, TX		Usage: Not Available
6825	Quantity of Nylon Sling		Asset located in: Humble, TX
	S/N: Not Available	6837	Quantity of (2) Pallets of Cables, Hoses, Duct
	C/W: (6) Blue Endless Chockers, (6) Red Endless Chockers		S/N: Not Available Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6838	Kruncher HS43515 Oil Filter Baler/Crusher
6826	Quantity of Wire Sling	6839	S/N: 7011705
	S/N: Not Available C/W: (15) 5/8 Wire Chockers, (15) 3/4 Wire		Usage: Not Available
	Chockers		Asset located in: Humble, TX
	Usage: Not Available		Quantity of (6) Crates of Fall Protection
	Asset located in: Humble, TX		S/N: Not Available C/W: three stacks
6827	Quantity of Chokers & Ratchet Straps S/N: Not Available		Usage: Not Available
	C/W: assorted size, one pallet		Asset located in: Humble, TX
	Usage: Not Available	6840	Quantity of (2) Crates of Contractor Supplies
	Asset located in: Humble, TX	4	S/N: Not Available C/W: assorted tools, one stack
6828	Quantity of Wire Sling		Usage: Not Available
	S/N: Not Available C/W: one pallet		Asset located in: Humble, TX
	Usage: Not Available	6841	Quantity of (6) Crates of Fall Protection
	Asset located in: Humble, TX	_	S/N: Not Available C/W: three stacks
6829	Quantity of Nylon Sling		Usage: Not Available
	S/N: Not Available C/W: (27) 2 in Nylon straps		Asset located in: Humble, TX
	Usage: Not Available	6842	Quantity of (1) Pallets of Tool Bags & Wire
	Asset located in: Humble, TX	_	Wheels
6830	Quantity of Tools		S/N: Not Available C/W: one pallet
	S/N: Not Available C/W: (2) air manifolds, rivet busters, chain		Usage: Not Available
	hoist, one pallet		Asset located in: Humble, TX
	Usage: Not Available	6843	Quantity of (2) Crates of Fall Protection
	Asset located in: Humble, TX	_	S/N: Not Available
6831	Quantity of (1) Crates of Tools		Usage: Not Available Asset located in: Humble, TX
	O /N N A 'I I		
	S/N: Not Available Usage: Not Available		Acceptated in Flamsie, 170

Lot #	Details	Lot #	Details
6844	Quantity of (2) Crates of Fall Protection & Cone Bases S/N: Not Available C/W: one stack Usage: Not Available	6855	Quantity of (1) Crates of Power Tools S/N: Not Available C/W: Bandsaws, Hammer Drills Usage: Not Available Asset located in: Humble, TX
6845	Asset located in: Humble, TX Quantity of Contractor Supplies S/N: Not Available C/W: Battery charger bases, gloves, one crate Usage: Not Available	6856	Quantity of (4) Crates of Fall Protection S/N: Not Available C/W: two stacks Usage: Not Available Asset located in: Humble, TX
6846	Asset located in: Humble, TX Quantity of (2) Pallets of 16 In x 30 In Job Site Box	6857	Quantity of (3) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6858	Quantity of (3) Crates of Fall Protection S/N: Not Available
6847	Quantity of (2) Pallets of 16 In x 30 In Job Site Box		Usage: Not Available Asset located in: Humble, TX
6848	S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) Crates of Contractor Supplies	6859	Quantity of (4) Crates of Fall Protection S/N: Not Available C/W: two stacks Usage: Not Available
	S/N: Not Available C/W: tie wraps, rod ovens, shirts Usage: Not Available Asset located in : Humble, TX	6860	Asset located in: Humble, TX Quantity of (4) Crates of Fall Protection S/N: Not Available C/W: two stacks
6849	Quantity of (3) Pallets of Contractor Supplies S/N: Not Available C/W: Cases, Tool Boxes, Rain Coats	6861	Usage: Not Available Asset located in: Humble, TX
6850	Usage: Not Available Asset located in: Humble, TX Quantity of Contractor Supplies		Quantity of (4) Crates of Fall Protection S/N: Not Available C/W: two stacks Usage: Not Available
0000	S/N: Not Available C/W: Steps, Garden Cart, Transmission Jack, One Pallet Usage: Not Available Asset located in: Humble, TX	6862	Asset located in: Humble, TX Quantity of (1) Pallets of Contractor Supplies S/N: Not Available C/W: Toolboxes, Sockets Usage: Not Available
6851	Quantity of (1) Pallets of Tri Stands S/N: Not Available C/W: one pallet Usage: Not Available	6863	Asset located in: Humble, TX Quantity of (1) Crates of Contractor Supplies S/N: Not Available C/W: Socket Sets
6852	Asset located in: Humble, TX Quantity of (2) Crates of Fall Protection		Usage: Not Available Asset located in: Humble, TX
6853	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6864	Quantity of (3) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Quantity of Contractor Supplies S/N: Not Available C/W: hand tools, plastic, one crate Usage: Not Available Asset located in: Humble, TX	6865	Quantity of (1) Pallets of Contractor Supplies S/N: Not Available C/W: Consumables Usage: Not Available
6854	Quantity of (2) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6866	Asset located in: Humble, TX Quantity of (6) 16 In x 30 In Job Site Box S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6867	Quantity of (2) 45 gal Flammable Storage Cabinets S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	6883	2013 KU6011 Electric Skid-Mounted Water Pump S/N: Not Available C/W: 4 in Intake, 4 in Discharge, Centrifugal, Teco 20 hp electric motor Usage: Not Available Asset located in: Humble, TX
6873	E Pumps WNC-12TG Pump S/N: 16DW1074901 C/W: 12 in Intake, 12 in Discharge, Centrifugal Usage: Not Available Asset located in: Humble, TX	6884	2017 Versamatic E2SA5T559C-HD-A Water Pump S/N: 7099508 Usage: Not Available
6874	Quantity of (4) Namco 574 Transfer Case S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6885	Asset located in: Humble, TX 2016 Versamatic E2SA5T559C-HD-A Water Pump S/N: 2259305
6875	Quantity of (3) Water Pump S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac XC3000P, MQ QP4TK Usage: Not Available Asset located in: Humble, TX	6886	Usage: Not Available Asset located in: Humble, TX 2015 Versamatic E2SA5T559C-HD-A Water Pump S/N: 7039990 Usage: Not Available
6876	Water Pump S/N: Not Available C/W: Diaphragm Usage: Not Available Asset located in: Humble, TX	6887	Asset located in: Humble, TX 2016 Versamatic E2SA5T5T9-HD Water Pump S/N: 7091887 Usage: Not Available Asset located in: Humble, TX
6877	2017 Cornell 2 5H-RP-EM-16-3 Water Pump S/N: 215092 Usage: 1,611 Hr Asset located in : Humble, TX	6888	2015 Versamatic E2SA5T5T9-HD Water Pump S/N: 7028779 C/W: 2 in Intake, 2 in Discharge, Self Priming Diaphragm Water Pump
6878	2019 D&D 4SSS44 Hydraulic Driven Submersible Water Pump S/N: 4S616SS Usage: Not Available	6889	Usage: Not Available Asset located in: Humble, TX 2016 Versamatic E2SA5T5TS9C-HD Water Pump
6879	Asset located in: Humble, TX 2023 Bell 5BF2P5H0 Water Pump S/N: 15BF2P5H0		S/N: 7082391 Usage: Not Available Asset located in : Humble, TX
6880	Usage: Not Available Asset located in: Humble, TX 2023 Bell 5BF2P5H0 Water Pump	6890	2016 Versamatic E2SA5T5TS9C-HD Water Pump S/N: 7082390 Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	6001	Asset located in: Humble, TX
6881	Quantity of Concrete Mixer, Pressure Washer & Pump S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	6891	2015 Versamatic E3AA2R220C-ATEX Water Pump S/N: 2218578 C/W: Diaphragm Usage: Not Available Asset located in: Humble, TX
6882	THE INSPECTION REPORT Asset located in: Humble, TX 2023 Aurora 341A-SF Electric Skid-Mounted Water Pump S/N: 97F17888 C/W: 4 in Intake, 4 in Discharge, Centrifugal, Baldor 20 hp electric motor Usage: Not Available Asset located in: Humble, TX	6892	2015 Versamatic E3SA3R330C-ATEX Water Pump S/N: 2207853 C/W: 3 in Intake, 3 in Discharge, Self Priming Diaphragm Water Pump Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6893	2022 Versamatic E3SA3R339CATEX Water Pump S/N: 38034612 Usage: Not Available Asset located in: Humble, TX	6904	Quantity of Lifting Equipment S/N: Not Available C/W: chain slings, chain hoist, shackles, come alongs Usage: Not Available Asset located in: Humble, TX
6894	Quantity of Ladder S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6905	Quantity of (3) Crates of Discharge & Suction Hose S/N: Not Available C/W: assorted size
6895	Quantity of (3) Crates of OTC 100 ton Track Press		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: three crates Usage: Not Available Asset located in : Humble, TX	6906	Quantity of Nitrogen Charge Kits S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6896	Clayborne 6000 Lb Engine Stand S/N: 605 C/W: To Fit CLAYBORNE ENGINE STANDS 906 engine stand Usage: Not Available Asset located in: Humble, TX	6907	Quantity of (6) Hose Reels S/N: Not Available Usage: Not Available Asset located in: Humble, TX
6897	3000 Lb Engine Stand S/N: Not Available C/W: adapters Usage: Not Available	6908 	Quantity of (2) Pallets of Parts (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	6909	6000 lb Pallet Jack S/N: 2005115167
6898	Pioneer Pump Parts S/N: PP66S12LHF4L914 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX , . Asset located in: Midland, TX
6899	Quantity of Hose S/N: Not Available Usage: Not Available Asset located in: Humble, TX	<u>6910</u>	Quantity of (8) American Aluminum Accessories Cam-Lockers S/N: Not Available C/W: Aluminum Usage: Not Available
6900	Quantity of Hose S/N: Not Available Usage: Not Available Asset located in: Humble, TX	6911	Asset located in: Humble, TX Quantity of Lifting Equipment S/N: Not Available Usage: Not Available
6901	Quantity of (4) Pallets of Hose S/N: Not Available C/W: misc sizes Usage: Not Available Asset located in: Humble, TX	6912	Asset located in: Humble, TX Quantity of Contractor Supplies S/N: Not Available C/W: Wacker jumping jack tamper, test pump, generator set, Tsurumi 3 in. water pump Usage: Not Available
6902	Quantity of (4) Pallets of Hose S/N: Not Available C/W: Misc. Sizes Usage: Not Available	6913	Asset located in: Humble, TX Quantity of Contractor Supplies
6903	Asset located in: Humble, TX Quantity of (4) Pumps S/N: Not Available		S/N: Not Available C/W: (4) Chipping Hammers, (2) Electric Submersible Pumps Usage: Not Available Asset located in : Humble, TX
	C/W: Diaphragm Usage: Not Available Asset located in : Humble, TX	6914A	Quantity of 5 in Coiled Tubing Reels S/N: Not Available C/W: (2) Coils Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6914	Quantity of Concrete Tools S/N: Not Available Usage: Not Available	6924	2024 Commercial Portable Paint Room S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6915	Quantity of Surge Protectors	6925	Lennox Air Handler & Coils
	S/N: Not Available		S/N: Not Available
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6916	Quantity of (4) Lakeside Serving Carts	6926	Quantity of Assorted Remotes
	S/N: Not Available Usage: Not Available		S/N: Not Available C/W: one pallet
	Asset located in: Humble, TX		Usage: Not Available
6917	Paccar Wiper Motor		Asset located in: Humble, TX
	S/N: Not Available	6927	Quantity of (12) Pallets of Pallet Racking
	Usage: Not Available		S/N: Not Available C/W: (6) pallets of wire racks, (6) pallets of
	Asset located in: Humble, TX	_	racks & cross arms, 48 in end frames
6918	Quantity of (5) Saw Blades		Usage: Not Available
	S/N: Not Available C/W: Assorted Sizes		Asset located in: Humble, TX
	Usage: Not Available	6928A	Quantity of 5 in Coiled Tubing Reels
	Asset located in: Humble, TX	6929	S/N: Not Available C/W: (2) Coils
6919A	Quantity of (2) 5 in Coiled Tubing Reels		Usage: Not Available
	S/N: Not Available C/W: (2) Coils		Asset located in: Humble, TX
	Usage: Not Available		Quantity of (2) J.E. Adams Industrial Vacuum
	Asset located in: Humble, TX		Cleaner S/N: Not Available
6919	22 Ft Skid Mounted Picnic Gazebo		Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	6930A	Hydro-Extractors 604FTE Aerial Hydraulic Tube
6920	Quantity of (2) Boxes of 1 In Adhesive Door	6930	Bundle Extractor
0920	Insulation		S/N: 0100551216 Usage: Not Available
	S/N: Not Available		Asset located in: Humble, TX
	Usage: Not Available		10 Ft Bucket Rack
	Asset located in: Humble, TX		S/N: Not Available
6921	Quantity of (1) Pallets of Zippertubing		Usage: Not Available
	S/N: Not Available C/W: one pallet		Asset located in: Humble, TX
	Usage: Not Available	6931	Quantity of w/ Bolts Bolt Bin
	Asset located in: Humble, TX		S/N: Not Available C/W: (6) Pallets
6922	Quantity of (1) Pallets of Traffic Light Signals		Usage: Not Available
	S/N: Not Available C/W: Assorted SizeS & Type		Asset located in: Humble, TX
	Usage: Not Available	6932	Quantity of (4) Post Driver Frames
	Asset located in: Humble, TX		S/N: Not Available
6923	Quantity of (14) Pallets of Water Line Fittings		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available	6933	·
	C/W: (6) control pans, (4) pallets of spacers, (6) pallets of assorted fittings, (5) pipe w	0933	Quantity of (2) Debris Boxes S/N: Not Available
	/valves		Usage: Not Available
	Usage: Not Available Asset located in : Humble, TX		Asset located in: Humble, TX
6924A	Quantity of 6 in Coiled Tubing Reels	6934	Quantity of Square D Electrical Supplies
092 4A	S/N: Not Available		(Unused)
	C/W: (2) Coils		S/N: Not Available C/W: Indoor load centers, circuit breakers, load
	Usage: Not Available		center covers, one pallet
	Asset located in: Humble, TX		Usage: Not Available
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6935	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6944	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX
6936	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6945	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX
6937	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6946	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in: Humble, TX Quantity of Square D Electrical Supplies
6938	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load centers, circuit breakers, load center covers, one pallet	6948	(Unused) S/N: Not Available C/W: Main breakers, Circuit breakers, (1) Pallet Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX		Quantity of Square D Electrical Supplies (Unused) S/N: Not Available
6939	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available		C/W: Main breakers, Circuit breakers, (1) Pallet Usage: Not Available Asset located in: Humble, TX
6940	C/W: Indoor load centers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX Quantity of Square D Electrical Supplies	6949	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, one pallet Usage: Not Available
	(Unused) S/N: Not Available C/W: Main breakers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6950	Asset located in: Humble, TX Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, load center covers, one pallet
6941	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	C/W: Main breakers, circuit breakers, load center covers, one pallet Usage: Not Available Asset located in: Humble, TX	6951	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Indoor load center, Circuit breakers, Load
6942	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet	6952	center covers, (1) Pallet Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX		Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size (1) Pallet
6943	Quantity of Square D Electrical Supplies (Unused) S/N: Not Available C/W: Main breakers, circuit breakers, one pallet Usage: Not Available Asset located in: Humble, TX		C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
6953	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in: Humble, TX	6964	2011 Goodman CPC060 Skid Mounted Air Conditioner S/N: 1103062379 Usage: Not Available Asset located in: Humble, TX
6954	Quantity of Square D Circuit Breakers (Unused) S/N: Not Available C/W: Assorted size, (1) Pallet Usage: Not Available Asset located in: Humble, TX	6965	2010 Goodman CPC060 Skid Mounted Air Conditioner S/N: 802039059 Usage: Not Available Asset located in: Humble, TX
6955	Bradford White D100L2503NA Natural Gas 100 gallon Water Heater (Unused) S/N: KE18280909 Usage: Not Available Asset located in: Humble, TX	6966	Carrier 50TC Air Conditioner S/N: 3216P35809 Usage: Not Available Asset located in: Humble, TX
6956	2006 Trane RTAC2504 Electric Air Cooler S/N: U06C06670 C/W: 3 Phase Motor Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	6967 6968 6969A	2010 Goodman CPC060 Skid Mounted Air Conditioner S/N: 802039053 Usage: Not Available Asset located in: Humble, TX Carrier 50TC Air Conditioner
6957	Asset located in: Humble, TX 2000 Trane RTAA1254 Skid Mounted Air Cooler		S/N: 2816P67978 Usage: Not Available Asset located in: Humble, TX
	S/N: U00J03518 Usage: Not Available Asset located in : Humble, TX		Trane Air Conditioner S/N: Not Available Usage: Not Available
6958	1996 Trane RTAA090 Air Cooler S/N: U96K07816 Usage: Not Available Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
6959	2002 Trane RTAC2504 Electric Air Cooler S/N: U02G05789 C/W: 3 Phase Motor Usage: Not Available	6969	Carrier 50HC Air Conditioner S/N: 2013G30113 Usage: Not Available Asset located in: Humble, TX
6960A	Asset located in: Humble, TX 2016 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0043001 Usage: Not Available Asset located in: Humble, TX	6970	Lennox ML14XC1-048-230A06 Air Conditioner (Unused) S/N: 1920B03149 Usage: Not Available Asset located in: Humble, TX
6960	2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F-0653-008 Usage: Not Available Asset located in: Humble, TX	6971	Lennox ML17XC1-036-230A01 Air Conditioner (Unused) S/N: 1923B02859 Usage: Not Available Asset located in: Humble, TX
6961	2017 Caps PPKH-5TD-0NN20K Air Conditioner S/N: 16F-0680-017 Usage: Not Available Asset located in: Humble, TX	6972	Lennox ML17XC1-060-230A01 Air Conditioner (Unused) S/N: 1922J08536 Usage: Not Available
6962	2011 Goodman CPC060 Skid Mounted Air Conditioner S/N: 1005697488 Usage: Not Available Asset located in: Humble, TX	6973	Asset located in: Humble, TX Lennox ML18XC2-024-230A01 Air Conditioner (Unused) S/N: 1924F02574
6963	2011 Goodman CPC060 Skid Mounted Air Conditioner S/N: 1103726704 Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
6974	Lennox ML18XC2-060-230A01 Air Conditioner (Unused) S/N: 1924D20399	6986	2018 MovinCool ClimatePro12 Air Conditioner S/N: 01180009H12 Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6987	2017 MovinCool ClimatePro12 Air Conditioner
6975	Goodman GSX140481KD Air Conditioner		S/N: 10160524H12
	(Unused)		Usage: Not Available
	S/N: 2009940937 Usage: Not Available	6988	Asset located in: Humble, TX
	Asset located in: Humble, TX	6988	2016 MovinCool ClimatePro12 Air Conditioner S/N: 02160159H12
6976	Lennox EL16XC1-018-230A01 Air Conditioner		Usage: Not Available
	(Unused)		Asset located in: Humble, TX
	S/N: 5820E01177 Usage: Not Available	6989	2016 MovinCool ClimatePro12 Air Conditioner
	Asset located in: Humble, TX		S/N: 09150017H12 Usage: Not Available
6977	Lennox EL16XC1-018-230A01 Air Conditioner	-	Asset located in: Humble, TX
0377	(Unused)	6990	2012 MovinCool CP-X14 Air Conditioner
	S/N: 5820J07371	0990	S/N: 1222-1317
	Usage: Not Available		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6978	Lennox EL16XC1-018-230A01 Air Conditioner (Unused)	6991	2012 MovinCool CP-X14 Air Conditioner
	S/N: 5820K11084		S/N: 12213135X14 Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6992	2017 Caps PPKV-20TD-0NN72 Air Conditioner
6979	Lennox EL16XC1-018-230A01 Air Conditioner		S/N: 16F0653006
	(Unused) S/N: 5820K09981		Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	6993	2017 Caps PPKV-20TD-0NN72 Air Conditioner S/N: 16F0653009
6980	Lennox EL16XC1-018-230A01 Air Conditioner		Usage: Not Available
	(Unused)	6994	Asset located in: Humble, TX
	S/N: 5820L01900 Usage: Not Available		2017 Caps PPKV-20TD-0NN72 Air Conditioner
	Asset located in: Humble, TX		S/N: 16F0653014
6981	Trane XE1200 Air Conditioner		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available	6995	2017 Caps PPKV-20TD-0NN72 Air Conditioner
	Usage: Not Available		S/N: 16F-0653-017
	Asset located in: Humble, TX	_	Usage: Not Available
6982	Lennox CBA250H-018-230-01 Air Conditioner (Unused)		Asset located in: Humble, TX
	S/N: 1520K14245	6996	2017 Caps PPKV-20TD-0NN72 Air Conditioner
	Usage: Not Available		S/N: 16F0653005 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
6983	2017 Caps PPKH-10TD-0NN36 Air Conditioner	6997	2016 Caps PPKV-20TD-0NN72 Air Conditioner
	S/N: 16F-0676-016 Usage: Not Available		S/N: 16F0043006
	Asset located in: Humble, TX		Usage: Not Available
6984	Quantity of (2) Pallets of AC Units	-	Asset located in: Humble, TX
	S/N: Not Available	6998	2015 Air Comman AC1600 Air Cooler
	C/W: Assorted Size Usage: Not Available		S/N: AC29 Usage: 124 Hr
	Asset located in: Humble, TX		Notes: LOCATED-IN-FORT-WORTH-TX
6985	2019 Airrex HSC-14 Air Conditioner	\dashv	Asset located in: Lake Worth, TX
2200	S/N: 14GSD00337		
	Usage: Not Available		
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
6999	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00249 Usage: Not Available	7013	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00683 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7000	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00612 Usage: Not Available Asset located in: Humble, TX	7014	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00616 Usage: Not Available Asset located in: Humble, TX
7001	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00637 Usage: Not Available Asset located in: Humble, TX	7015	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00643 Usage: Not Available Asset located in: Humble, TX
7002	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00236 Usage: Not Available Asset located in: Humble, TX	7016	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00790 Usage: Not Available Asset located in: Humble, TX
7003	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00590 Usage: Not Available Asset located in: Humble, TX	7017	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00707 Usage: Not Available Asset located in: Humble, TX
7004	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00196 Usage: Not Available Asset located in: Humble, TX	7018	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00414 Usage: Not Available Asset located in: Humble, TX
7005	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00827 Usage: Not Available Asset located in: Humble, TX	7019	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00538 Usage: Not Available Asset located in: Humble, TX
7006	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00714 Usage: Not Available Asset located in: Humble, TX	7020	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00546 Usage: Not Available Asset located in: Humble, TX
7007	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00559 Usage: Not Available Asset located in: Humble, TX	7021	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00584 Usage: Not Available Asset located in: Humble, TX
7008	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00298 Usage: Not Available Asset located in: Humble, TX	7022	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00210 Usage: Not Available Asset located in: Humble, TX
7009	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00899 Usage: Not Available Asset located in: Humble, TX	7023	2019 Airrex HSC-14 Air Conditioner S/N: 14HGRE00806 Usage: Not Available Asset located in: Humble, TX
7010	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00250 Usage: Not Available Asset located in: Humble, TX	7024	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00737 Usage: Not Available Asset located in: Humble, TX
7011	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00642 Usage: Not Available Asset located in: Humble, TX	7025	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00234 Usage: Not Available Asset located in: Humble, TX
7012	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00698 Usage: Not Available Asset located in: Humble, TX	7026	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSC00203 Usage: Not Available Asset located in: Humble, TX

Lot#	Details	Lot #	Details
7027	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00024 Usage: Not Available	7041	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00834 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7028	2019 Airrex HSC-14 Air Conditioner S/N: 14GSD00603 Usage: Not Available Asset located in: Humble, TX	7042	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00794 Usage: Not Available Asset located in: Humble, TX
7029	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00651 Usage: Not Available Asset located in: Humble, TX	7043	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00737 Usage: Not Available Asset located in: Humble, TX
7030	2019 Airrex HSC-14 Air Conditioner S/N: 14HGSD00596 Usage: Not Available Asset located in: Humble, TX	7044	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00808 Usage: Not Available Asset located in: Humble, TX
7031	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00356 Usage: Not Available Asset located in: Humble, TX	7045	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00363 Usage: Not Available Asset located in: Humble, TX
7032	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00152 Usage: Not Available Asset located in: Humble, TX	7046	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00682 Usage: Not Available Asset located in: Humble, TX
7033	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00323 Usage: Not Available Asset located in: Humble, TX	7047	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00784 Usage: Not Available Asset located in: Humble, TX
7034	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00821 Usage: Not Available Asset located in: Humble, TX	7048	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00386 Usage: Not Available Asset located in: Humble, TX
7035	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRE00762 Usage: Not Available Asset located in: Humble, TX	7049	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00023 Usage: Not Available Asset located in: Humble, TX
7036	2018 Airrex HSC-14 Air Conditioner S/N: 14HGDA00096 Usage: Not Available Asset located in: Humble, TX	7050	2017 Airrex HSC-14 Air Conditioner S/N: 14HGQD00041 Usage: Not Available Asset located in: Humble, TX
7037	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00372 Usage: Not Available Asset located in: Humble, TX	7051	2017 Airrex HSC-14 Air Conditioner S/N: 14HGQD00070 Usage: Not Available Asset located in: Humble, TX
7038	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00410 Usage: Not Available Asset located in: Humble, TX	7052	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00067 Usage: Not Available Asset located in: Humble, TX
7039	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00069 Usage: Not Available Asset located in: Humble, TX	7053	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00021 Usage: Not Available Asset located in: Humble, TX
7040	2018 Airrex HSC-14 Air Conditioner S/N: 14HGRD00481 Usage: Not Available Asset located in: Humble, TX	7054	2017 Airrex HSC-14 Air Conditioner S/N: 14HGQD00146 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7055	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00049 Usage: Not Available	7069	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00288 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7056	2017 Airrex HSC-14 Air Conditioner S/N: 14HGQD00145 Usage: Not Available Asset located in: Humble, TX	7070	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00224 Usage: Not Available Asset located in: Humble, TX
7057	2017 Airrex HSC-14 Air Conditioner S/N: 14HGDA00078 Usage: Not Available Asset located in: Humble, TX	7071	2014 Airrex HSC-14 Air Conditioner S/N: 14HGDC00135 Usage: Not Available Asset located in: Humble, TX
7058	2017 Airrex HSC-14 Air Conditioner S/N: 14HGQD00064 Usage: Not Available Asset located in: Humble, TX	7072	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00099 Usage: Not Available Asset located in: Humble, TX
7059	2016 Airrex HSC-14 Air Conditioner S/N: 14HGFC00052 Usage: Not Available Asset located in: Humble, TX	7073	2016 Airrex HSC14-IND Air Conditioner S/N: 14HGCD00099 Usage: Not Available Asset located in: Humble, TX
7060	2016 Airrex HSC-14 Air Conditioner S/N: 14HGFC00014 Usage: Not Available Asset located in: Humble, TX	7074	2016 Airrex HSC14-IND Air Conditioner S/N: US14BC00143 Usage: Not Available Asset located in: Humble, TX
7061	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00089 Usage: Not Available Asset located in: Humble, TX	7075	2018 Airrex HWC-19 Air Conditioner S/N: UW19RE00030 Usage: Not Available Asset located in: Humble, TX
7062	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00022 Usage: Not Available Asset located in: Humble, TX	7076	2017 Airrex HWC-19 Air Conditioner S/N: UW19QD00039 Usage: Not Available Asset located in: Humble, TX
7063	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00124 Usage: Not Available Asset located in: Humble, TX	7077	2017 Airrex HWC-19 Air Conditioner S/N: UW19QD00024 Usage: Not Available Asset located in: Humble, TX
7064	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00034 Usage: Not Available Asset located in: Humble, TX	7078	2015 Airrex HWC-19 Air Conditioner S/N: UW19DC00006 Usage: Not Available Asset located in: Humble, TX
7065	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00010 Usage: Not Available Asset located in: Humble, TX	7079	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00117 Usage: Not Available Asset located in: Humble, TX
7066	2015 Airrex HSC-14 Air Conditioner S/N: 14HGEC00084 Usage: Not Available Asset located in: Humble, TX	7080	2014 Airrex HWC-19 Air Conditioner S/N: UW19CD00007 Usage: Not Available Asset located in: Humble, TX
7067	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00191 Usage: Not Available Asset located in: Humble, TX	7081	2018 MovinCool ClimatePro12 Air Conditioner S/N: 01170080H12 Usage: Not Available Asset located in: Humble, TX
7068	2014 Airrex HSC-14 Air Conditioner S/N: US14BC00260 Usage: Not Available Asset located in: Humble, TX	7082	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180419H12 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7083	2018 MovinCool ClimatePro12 Air Conditioner S/N: 07170869H12 Usage: Not Available	7097	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180446H12 Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7084	2018 MovinCool ClimatePro12 Air Conditioner S/N: 05180281H12 Usage: Not Available	7098	2010 Trane TCH300E4 Air Conditioner S/N: 102010454D Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7085	2018 MovinCool ClimatePro12 Air Conditioner S/N: 12171368H12 Usage: Not Available Asset located in: Humble, TX	7099	2019 Dewalt DXH190HD Space Heater S/N: LN34069519003893 Usage: Not Available Asset located in: Humble, TX
7086	2017 MovinCool ClimatePro12 Air Conditioner S/N: 01170051H12 Usage: Not Available Asset located in: Humble, TX	7100	Quantity of Tornado Vacuum & Shop Fan S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7087	2017 MovinCool ClimatePro12 Air Conditioner S/N: 03170273H12 Usage: Not Available Asset located in: Humble, TX	7101	Quantity of Pallet Racking S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7088	2016 MovinCool ClimatePro12 Air Conditioner S/N: 02160207H12 Usage: Not Available Asset located in: Humble, TX	7102	Blackhawk 67586 2 Ton Portable Engine Hoist S/N: AM12698 Usage: Not Available Asset located in: Humble, TX
7089	2016 MovinCool ClimatePro12 Air Conditioner S/N: 03160292H12 Usage: Not Available Asset located in: Humble, TX	7103	Quantity of Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet Usage: Not Available
7090	2016 MovinCool ClimatePro12 Air Conditioner S/N: 03160298H12 Usage: Not Available Asset located in: Humble, TX	7104	Asset located in: Humble, TX Quantity of Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet
7091	2017 MovinCool Office Pro 36 Air Conditioner S/N: 08170291360	7105	Usage: Not Available Asset located in: Humble, TX Overtity of Asserted Tennogo & Lifts
	Usage: Not Available Asset located in: Humble, TX	7105	Quantity of Assorted Tonnage & Lifts S/N: Not Available C/W: one pallet
7092	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180416H12 Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7106	Assorted Tonnage & Lifts S/N: Not Available
7093	2018 MovinCool ClimatePro12 Air Conditioner S/N: 03170189H12 Usage: Not Available Asset located in: Humble, TX		C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7094	2018 MovinCool ClimatePro12 Air Conditioner S/N: 08171083H12 Usage: Not Available Asset located in: Humble, TX	7107	Quantity of 12 Ton Bottle Jacks S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7095	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180383H12 Usage: Not Available Asset located in: Humble, TX	7108	Quantity of Tru-Cut SDS Max Drill Bits S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7096	2018 MovinCool ClimatePro12 Air Conditioner S/N: 06180407H12 Usage: Not Available Asset located in: Humble, TX		Asset located III. MUHDIE, 17

Lot #	Details	Lot #	Details
7109	Quantity of (4) Reco SC 110 Volt 17 Amp Electric Bearing Heater S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7120	Quantity of Assorted Nylon Slings S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7110	Reco BC 220 Volt 30 Amp Electric Bearing Heater S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7121 7122	SPX Power Team BC 10,000 / 120 Volt Dual Hyd Pump S/N: 2201AX320606 Usage: Not Available Asset located in: Humble, TX Quantity of (1) Pallets of Erickson 817-6-LEDSL
7111	Quantity of Assorted - 1/4 in Diameter Argon Hose S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX		120 Volt LED Lights S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7112	Quantity of Assorted - 1/4" Dia Argon Hose S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7123	Quantity of (1) Pallets of Erickson 817-6-LEDSL 120 Volt LED Lights S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7113	Quantity of Vitaulic PFT-510 S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7124	Quantity of Allmite 7337 3/4 in Hose Reels S/N: Not Available C/W: one pallet Usage: Not Available
7114	Quantity of Duct Hose S/N: Not Available Usage: Not Available Asset located in: Humble, TX Merrill Bros. ES2600 8 Ton 2"-4" Grip Plate	7125	Asset located in: Humble, TX Quantity of DryRod Electric Rod Caddy S/N: Not Available C/W: 15 lb, 120 Volt, One Pallet Usage: Not Available Asset located in: Humble, TX
7116	S/N: Not Available Usage: Not Available Asset located in: Humble, TX 20' x 20' Tent S/N: Not Available	7126	Quantity of DryRod Boxes S/N: Not Available C/W: one pallet Usage: Not Available
7117	C/W: one pallet Usage: Not Available Asset located in: Humble, TX Quantity of (2) ATD 7422W 20 Ton Air Bottle	7127	Asset located in: Humble, TX Enerpac CP1000 / CP2000/ CP3000 Power Cable Pullers S/N: Not Available
,	Jacks S/N: Not Available C/W: one pallet Usage: Not Available	7128	C/W: Storage Box Usage: Not Available Asset located in: Humble, TX Quantity of Survey Equipment, with
7118	Asset located in: Humble, TX Quantity of (4) Michigan Pneumatic JAC-3 Vacuum Silicone Dust Extractors (Unused) S/N: Not Available C/W: one pallet Usage: Not Available		Accessories S/N: Not Available C/W: Lecia Wild, Spectra LL500, tripods, Grade Rods Usage: Not Available Asset located in: Humble, TX
7119	Asset located in: Humble, TX Quantity of Assorted 8 ft - 20 ft Endless Slings S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7129	Quantity of Lecia Survey Equipment & Accessories S/N: Not Available C/W: One Pallet Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7130	Quantity of Pipe Stands S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX	7142	Speeflo Walk-Behind Paint Sprayer & Paint Striper S/N: PL4-1054 C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7131	Quantity of Pipe Stands S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX	7143	Quantity of Contractor Supplies S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7132	Quantity of 55 Gallon Plastic Trash Cans S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7144	Quantity of (5) Hanging Lamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7133	Quantity of 3-Legged V-Head Jack Stands S/N: Not Available C/W: one crate Usage: Not Available	7145	Air Compressor S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7134	Asset located in: Humble, TX Quantity of (2) Vitaulic PFT-510 Cordless 18 Volt Press Tools S/N: Not Available	7146	Electric Pressure Washer S/N: Not Available C/W: Electric Operated Usage: Not Available Asset located in: Humble, TX
7135	Usage: Not Available Asset located in: Humble, TX Quantity of Campsite Sink/Table S/N: Not Available	7147	Generator Set S/N: 50548 Usage: Not Available Asset located in: Humble, TX
7136	Usage: Not Available Asset located in: Humble, TX Quantity of (10) 2024 SKLP SK10 Equipment Seats (Unused) S/N: B44826	7148	2017 Tsurumi LB-480-62 Electric Submersible Water Pump S/N: 16522148236 Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX
	Usage: Not Available Asset located in : Humble, TX		Asset located in: Lake Worth, TX
7137	Portacool 72 In. Cooling Fan S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7149A	Greenlee 555 Series Electric Bender S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7138	Quantity of (4) Lighting Fixtures S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7149	Spartan 1065 Electric Sewer Snake S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7140	Quantity of (6) Generator Set S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7150 7151	Quantity of (2) AWC D-1 Wire Reel S/N: D10417203/D10417204 Usage: Not Available Asset located in: Humble, TX Quantity of (2) AWC D-1 Wire Reel S/N: D10417201/D10417202
7141	Asset located in: Humble, TX Hydraulic Body Frame Repair Kit S/N: Not Available Usage: Not Available	7152	Usage: Not Available Asset located in: Humble, TX Quantity of (5) Tri Stands S/N: Not Available

Lot #	Details	Lot #	Details
7153	Quantity of (3) Bottle Carts S/N: Not Available C/W: one pallet Usage: Not Available	7164	Quantity of (6) Assorted Hose Reels S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7165	24 in x 47 in Metal Ramp with Winch
7154	Quantity of (3) Ridgid 460 Tri Stands S/N: Not Available C/W: one pallet Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7166	Quantity of Contractor Supplies
7155	Quantity of Contractor Supplies S/N: Not Available C/W: Discharge Hose, Cooler, Assorted parts, (1) Pallet Usage: Not Available	7167	S/N: Not Available C/W: ProFlo Pump kit, PVC, Shop Vac, (1) Pallet Usage: Not Available Asset located in: Humble, TX Quantity of (2) Electric Winches
7156	Asset located in: Humble, TX Taiko Back Flash Pump 84M3/HX20MTH Water Pump	-	S/N: Not Available C/W: Mount Brackets, (1) Pallet Usage: Not Available Asset located in : Humble, TX
	S/N: A2D8617-2 C/W: 11 kW Engine, Teco 15 hp electric motor Usage: Not Available Asset located in : Humble, TX	7168	Quantity of Contractor Supplies S/N: Not Available C/W: Ridgid K45 Drain Cleaners, Milwaukee Electric Drills, Tool Boxes, (1) Pallet
7157	Quantity of Contractor Supplies S/N: Not Available Usage: Not Available	7169	Usage: Not Available Asset located in: Humble, TX Quantity of Power Tools
7158	Asset located in: Humble, TX Summit Mfg Hand Crank Hose Reel S/N: Not Available Usage: Not Available		S/N: Not Available C/W: Milwaukee Recip Saws, Drill, General Water Leak locator, (1) Pallet Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7159	Quantity of (8) Refrigerant Tank Racks S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7170	Quantity of Contractor Supplies S/N: Not Available C/W: wires, stands, one pallet Usage: Not Available Asset located in: Humble, TX
7160	Quantity of (2) Tankless Water Heaters S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7171	Quantity of Contractor Supplies S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7161	Quantity of EZ Cam E5200 Sewer Camera & Power Winch S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7172	Taiko Back Flash Pump 84M3/HX20MTH Water Pump S/N: A2D8617-1 C/W: Teco 15 hp electric motor Usage: Not Available Asset located in: Humble, TX
7162	Quantity of (4) Contractor Supplies S/N: Not Available C/W: 30 in x 30 in drain pan, sink machine sewer cable, cover drum, shoe covers, chain hoist, Spartan 300 (inoperable), pipe bender, condenser coil, tool box	7173	Quantity of Contractor Supplies S/N: Not Available C/W: Spartan Sewer Snake Drums, Cooler, Extension Cord w/Reel, (1) Pallet Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7174	Quantity of LYTX Drive Cam Recorders
7163	Taiko Back Flash Pump 56M3/Hx20MTH Water Pump S/N: A2D8621-1 C/W: 7.5 kW Engine, Teco 15 hp electric motor Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7175	Quantity of Contractor Supplies S/N: Not Available C/W: DeWalt 14 in Chop Saw, Router Table Usage: Not Available	7186	Scotsman Ice Machine S/N: 16011320012742 Usage: Not Available Asset located in: Humble, TX
7176	Asset located in: Humble, TX Taiko Back Flash Pump 56M3/Hx20MTH Water Pump	7187	Ice-O-Matic CIM2046HR Ice Machine S/N: 19081280010893 Usage: Not Available
	S/N: A2D8621-2 C/W: Teco 15 hp electric motor Usage: Not Available Asset located in : Humble, TX	7188	Asset located in: Humble, TX Manitowoc ID0452A-161 Ice Machine S/N: 1101248931
7177	Quantity of Contractor Supplies S/N: Not Available C/W: Spartan 100 Sewer Snake Drums, Battery Charger, Parts, (1) Pallet Usage: Not Available	7189	Usage: Not Available Asset located in: Humble, TX Hoshizaki Ice Machine S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7178	Quantity of Contractor Supplies S/N: Not Available C/W: Hydraulic Jacks, Fire Extinguishers, Assorted parts, (1) Pallet Usage: Not Available	7190	Scotsman NS1322A-32 Ice Machine S/N: 14121320010384 C/W: (22 In. Wide, With UNUSED Cart) Usage: Not Available Asset located in: Humble, TX
7179	Asset located in: Humble, TX Quantity of Computer Desks (Unused) S/N: Not Available C/W: (1) Pallet Usage: Not Available	_ ₇₁₉₁	Hewlett-Packard 360 Computer Printers S/N: MY61869031 Usage: Not Available Asset located in: Humble, TX
7180	Asset located in: Humble, TX Quantity of Hand Crank Hose Reels	7192 7193	Hewlett Packard 365 Computer Printers S/N: MY74M2900T
7100	S/N: Not Available C/W: General J-1600 electric high pressure		Usage: Not Available Asset located in: Humble, TX
	drain cleaner, General CR-300 hose reel, Summit Mfg hose reel Usage: Not Available		OKI M64S Computer Printers S/N: 7BC3388A Usage: Not Available
7181	Asset located in: Humble, TX General CR-300 Cart-Reel	7194B	Asset located in: Humble, TX Quantity of (2) Whirlpool Stainless Steel Side
7101	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7 1 940	by Side Refrigerator S/N: Not Available Usage: Not Available
7182	Jet-Set J-2900 High Pressure Water Drain Jet		Asset located in: Humble, TX
	S/N: 161757 C/W: Honda GX390 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Humble, TX	7194A	Quantity of (2) Whirlpool Stainless Steel Side by Side Refrigerator S/N: Not Available Usage: Not Available
7183	Quantity of (2) General JM-1450-01 Electric Water Jet Drain Hose S/N: Not Available	7194	Asset located in: Humble, TX Hewlett-Packard 260 Computer Printers S/N: MY41R69007
	Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX
7184	General J-1600 Electric High Pressure Water Drain Jet Cleaner S/N: 159678 C/W: electric Usage: Not Available Asset located in: Humble, TX	7195B	Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7185	Scotsman C0330MA Ice Machine S/N: 11031320010720 Usage: Not Available Asset located in: Humble, TX	7195A	Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7195	Quantity of GE (1) Refrigerator & (1) Stove S/N: Not Available C/W: Four Burner Gas Stove Usage: Not Available Asset located in: Humble, TX	7206	Bradford White D100L2503NA Natural Gas 100 Gallon Water Heater S/N: KD18168659 Usage: Not Available Asset located in: Humble, TX
7196B	Crosley CFC224QWA Freezer S/N: WB60546259 Usage: Not Available Asset located in: Humble, TX	7207	Bradford White D80L399E3NA Natural Gas 80 Gallon Water Heater S/N: KA17646143 Usage: Not Available
7196A 7196	Quantity of (6) Whirlpool Stainless Steel Dishwashers S/N: Not Available Usage: Not Available Asset located in: Humble, TX Kenmore Side-By-Side Refrigerator	7208C	Asset located in: Humble, TX Quantity of (2) Whirlpool Stainless Steel Gas Ranges S/N: Not Available C/W: 5 Burners Usage: Not Available Asset located in: Humble, TX
7197A	S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (6) Whirlpool Stainless Steel Dishwashers	7208B	Quantity of (2) GE Stainless Steel Gas Ranges S/N: Not Available C/W: 4 Burners Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7208A	Asset located in: Humble, TX Quantity of (2) GE Stainless Steel Gas Ranges S/N: Not Available
7197	Hobart commercial kitchen mixer S/N: Not Available Usage: Not Available		C/W: 4 Burners Usage: Not Available Asset located in : Humble, TX
7198	Asset located in: Humble, TX Quantity of (1) Refrigerator & (1) Stove S/N: Not Available C/W: GE Glass Top Electric Stove, Fridgidaire Refrigerator, One Pallet Usage: Not Available Asset located in: Humble, TX	7208 7209A	Bradford White D80L399E3NA Natural Gas 80 Gallon Water Heater S/N: KD18209520 Usage: Not Available Asset located in: Humble, TX Quantity of (2) Whirlpool Stainless Steel Gas Ranges
7200	Middleby Marshall Pizza Conveyor Oven S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	S/N: Not Available C/W: 5 Burners Usage: Not Available Asset located in : Humble, TX	S/N: Not Available C/W: 5 Burners Usage: Not Available
7201	THE INSPECTION REPORT Asset located in: Humble, TX 2022 Sierra Range SR-10-60 Natural Gas 60 in	7209	Quantity of (2) Scotsman Touchfree Ice/Water Dispensers S/N: Not Available
7201	Open Burners Range S/N: Not Available	7010	Usage: Not Available Asset located in: Humble, TX
7203	Usage: Not Available Asset located in: Humble, TX Quantity of (2) Snack Vending Machines	7210	Lennox CHX35-15/61C-6F-10 Coils & Furnace S/N: 1523L32357 Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7211	Lennox CHX35-24A-6F-10 Coils & Furnace S/N: 1524D21415
7204	Vendo 470457005 Soda Vending Machine S/N: 229003 Usage: Not Available	7212	Usage: Not Available Asset located in: Humble, TX Lennox CX35-60C-6F-20 Coils & Furnace
7205	Asset located in: Humble, TX Quantity of (2) True Beverage Coolers S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: 1524C10791 Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
7213	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5918L01732 Usage: Not Available Asset located in: Humble, TX	7224	Goodman GM9S800803BNAA Coils & Furnace (Unused) S/N: 2208100905 Usage: Not Available Asset located in: Humble, TX
7214	Lennox EL196UH045XE36B-01 Furnace (Unused) S/N: 5919J02491 Usage: Not Available Asset located in: Humble, TX	7225	Goodman GM9S800804CNAA Furnace (Unused) S/N: 2207421296 Usage: Not Available Asset located in: Humble, TX
7215	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5920H08834 Usage: Not Available Asset located in: Humble, TX	7226	Goodman GMES800604BNAA Coils & Furnace (Unused) S/N: 2104243911 Usage: Not Available Asset located in: Humble, TX
7216	Lennox EL196UH045XE36B-01 Furnace (Unused) S/N: 5920H08831 Usage: Not Available Asset located in: Humble, TX	7227	Goodman GMVC800603BNAA Furnace (Unused) S/N: 2209008947 Usage: Not Available Asset located in: Humble, TX
7217	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02496 Usage: Not Available Asset located in: Humble, TX	7228	Goodman GMVC800804CNAC Coils & Furnace (Unused) S/N: 2102515397 Usage: Not Available Asset located in: Humble, TX
7218	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02486 Usage: Not Available	7229	Lennox ML180UH070E36B-58 Furnace S/N: 1723B21169 Usage: Not Available Asset located in: Humble, TX
7219	Asset located in: Humble, TX Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02489	7230	Lennox ML180UH070E36B-58 Furnace S/N: 1723B21156 Usage: Not Available Asset located in: Humble, TX
7220	Usage: Not Available Asset located in: Humble, TX Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5919J02490	7231	Quantity of (7) 16 In x 30 In Job Site Box S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX
7221	Usage: Not Available Asset located in: Humble, TX Lennox EL196UH045XE36B-01 Coils & Furnace (Unused)	7232	Quantity of (3) Electric Floor Scrubbers S/N: Not Available C/W: (2) Windsor, (1) Tennant Usage: Not Available
	S/N: 5920H08835 Usage: Not Available Asset located in : Humble, TX	7233	Asset located in: Humble, TX JET Band Saw S/N: Not Available
7222	Lennox EL196UH045XE36B-01 Coils & Furnace (Unused) S/N: 5918M07113	7234	Usage: Not Available Asset located in: Humble, TX Gardner-Denver Hydraulic Cooler
	Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7223	Goodman GM9S800803BNAA Coils & Furnace (Unused) S/N: 2208144387 Usage: Not Available Asset located in: Humble, TX	7235	Quantity of (4) Vacuum Pumps S/N: Not Available C/W: (2) Fruitland, (2) NVE Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7236B	Gasoline 72 In Portable Yard Chain Saw S/N: Not Available C/W: Honda GX630 2-cylinder Usage: Not Available Asset located in: Humble, TX	7247	Parker PTO S/N: Not Available C/W: one box Usage: Not Available Asset located in: Humble, TX
7236A	Oregon 520-120 Chain Saw Sharpener S/N: 682621 Usage: Not Available Asset located in: Humble, TX	7248	Forrest 648 Shear S/N: F00965 Usage: Not Available Asset located in: Humble, TX
7236	Saw Stop CNS175 Table Saw S/N: C123401263 C/W: 10 in Blade Usage: Not Available Asset located in: Humble, TX	7249	Electric Scissor Lift S/N: Not Available C/W: Solid Non-Marking Tires Usage: Not Available Asset located in: Humble, TX
7238	Hydraulic Control Panel S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7250	Quantity of Freight Elevator Screens S/N: Not Available C/W: uprights Usage: Not Available Asset located in: Humble, TX
7239	Parker Hydraulic Hose Fabrication Machine S/N: Not Available C/W: hose, fittings Usage: Not Available Asset located in: Humble, TX	7252	Greenlee 556 Electric Pipe Bending Machine S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7240	2016 Treater Kill Truck Body S/N: 20160401 Usage: Not Available Asset located in: Humble, TX	7253	Quantity of 1 1/2 Ton Chain Hoists and (1) Self- dumping Hopper S/N: Not Available C/W: Self-dumping Hopper Usage: Not Available
7241	Pedestal Mount Material Handler S/N: 050528 Usage: Not Available Asset located in: Humble, TX	7254	Asset located in: Humble, TX Gleason S281002 Hose Reel S/N: GU0178802
7242	Concrete Wash Out Box S/N: Not Available Usage: Not Available	7256	Usage: Not Available Asset located in: Humble, TX Quantity of Assorted Sockets
7243	Asset located in: Humble, TX Durst Hydraulic Pumps S/N: Not Available Usage: Not Available		S/N: Not Available C/W: one crate Usage: Not Available Asset located in: Humble, TX
7244	Asset located in: Humble, TX Quantity of (4) Electric Motor S/N: Not Available C/W: Baldor 2 hp, Baldor Super E 30 hp, Dayton 10 hp, Siemens 55 hp, two pallets	7257	Current Tools 452 Electric 1/2 in - 6 in PVC Heater S/N: 2509 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7258	Quantity of (4) 20,000 lb Heavy Duty Aluminum Ramps
7245	Quantity of (3) Electric Motor S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: load levelers Usage: Not Available Asset located in : Humble, TX
7246	DPF S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7259	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7260	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX	7270	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX
7261	Quantity of (3) Bundles of Wire Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX	7271	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX
7262	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX	7272	Quantity of (2) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX
7263	Quantity of (3) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX	7273	Quantity of (4) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available
7264	Quantity of (2) Bundles of 20 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 20 ft x 8 ft Usage: Not Available Asset located in: Humble, TX	7274	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available
7265	Quantity of (5) Bundle of 7 ft x10 ft Wire Re- Mesh S/N: Not Available C/W: 7 Ft x10 Ft Usage: Not Available Asset located in: Humble, TX	7275	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available
7266	Quantity of (3) Bundles of 7 ft x10 ft Wire Re- Mesh S/N: Not Available C/W: 7 ft x10 ft Usage: Not Available Asset located in: Humble, TX	7276	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available
7267	Quantity of (3) Bundles of 7 ft x10 ft Wire Re- Mesh S/N: Not Available C/W: 7 ft x10 ft Usage: Not Available Asset located in: Humble, TX	7277	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available
7268	Quantity of (3) Bundles of 8 ft x 4 ft Wire Re- Mesh S/N: Not Available C/W: 8 ft x 4 ft Usage: Not Available Asset located in: Humble, TX	7278	Asset located in: Humble, TX Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 Ft x 8 Ft Usage: Not Available Asset located in: Humble, TX
7269	Quantity of (3) Bundles of 4 ft x 8 ft Wire Re- Mesh S/N: Not Available C/W: 4 ft x 8 ft Usage: Not Available Asset located in: Humble, TX	7279	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7280	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available	7291	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7281	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7292	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7282	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7293	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7283	Quantity of (16) 4 in Square Galvanized 12 Gauge Tubing (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7294	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7284	Quantity of (16) 3 5/8 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7295	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7285	Quantity of (16) 3 5/8 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7296	Quantity of (25) 2 3/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7286	Quantity of (16) 3 5/8 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7297	Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7287	Quantity of (25) 2 3/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7298	Quantity of (10) 3 1/2 In Square Tubing S/N: Not Available C/W: one bundle Usage: Not Available Asset located in: Humble, TX
7288	Quantity of (25) 2 3/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7299	Quantity of 3-1-2" Square Tubing S/N: Not Available C/W: Assorted Length, One Bundle Usage: Not Available Asset located in: Humble, TX
7289	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available Usage: Not Available	7300	Quantity of 4 In Pipe S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in: Humble, TX
7290	Asset located in: Humble, TX Quantity of (25) 2 1/4 in Square 12 Gauge Steel (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7301	Quantity of 4 In Pipe S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7302	Quantity of 4 1/2 in Pipe S/N: Not Available C/W: one bundle Usage: Not Available Asset located in: Humble, TX	7313	Quantity of (2) 3/4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (2) Bundles Usage: Not Available
7303	Quantity of 2-3/8 In. x 26 Ft Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7314	Asset located in: Humble, TX Quantity of 3/4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles
7304	2-3/8 Pipe S/N: Not Available Usage: Not Available	7315	Usage: Not Available Asset located in: Humble, TX Quantity of 3/4 in x 20 ft Angle Iron (Unused)
7305	Asset located in: Humble, TX Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused)		S/N: Not Available C/W: (2) Bundles Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7316	Quantity of 4 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles
7306	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available		Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX		Quantity of 1 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles
7307	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused) S/N: Not Available		Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX		Quantity of (3) 20 ft Angle Iron (Unused) S/N: Not Available C/W: (2) Bundles of 2 in, (1) Bundle of 1 in
7308	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused)		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7319	Quantity of 1 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles
7309	Quantity of (19) 2 7/8 in OD Schedule-10 Steel Pipe (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7320	Quantity of 1 1/2 in x 40 ft Angle Iron (Unused) S/N: Not Available C/W: (1) Bundles Usage: Not Available
7310	Quantity of (61) 1 7/8 in OD Schedule-10 Steel Pipe (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7321	Quantity of (2) Bundles of Angle Iron (Unused) S/N: Not Available C/W: (1) Bundle of 3 in, (1) Bundle of 5 in Usage: Not Available
7311	Quantity of (61) 1 7/8 in OD Schedule-10 Steel Pipe (Unused)		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7322	Quantity of (3) 5 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (3) Bundles Usage: Not Available
7312	Quantity of (61) 1 5/8 in OD Schedule-10 Steel Pine (Unused)		Asset located in: Humble, TX
	Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7323	Quantity of 2 in x 20 ft Angle Iron (Unused) S/N: Not Available C/W: (1) Bundles Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7324	Quantity of (2) Bundles of 2 In. x 20 Ft Angle Iron (Unused) S/N: Not Available Usage: Not Available	7335	Quantity of (2) Bundles Of 1 1/2 In. x 20 Ft Flat Bar (Unused) S/N: Not Available Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
7325	Quantity of 5 In. x 20 Ft Angle Iron (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7336	Quantity of (2) Bundles Of 1 1/2 In. x 20 Ft Flat Bar (Unused) S/N: Not Available Usage: Not Available
7326	Quantity of 1 1/2 In. x 40 Ft Angle Iron		Asset located in: Humble, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7337	Quantity of (3) Bundles of 1 1/2 in x 1 1/2 in x 1 /8 in A36/529-50 24 ft Angle Iron (Unused) S/N: Not Available Usage: Not Available
7327	Quantity of (4) Bundles of 1 1/2 in x 1/4 in x 20		Asset located in: Humble, TX
	ft Flat Bar (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7338	Quantity of (2) Bundles of 1 1/2 in x 1 1/2 in x 1 /8 in A36/529-50 40 ft Angle Iron (Unused) S/N: Not Available Usage: Not Available
7328	Quantity of (4) Bundles of 1 1/4 in x 1/4 in x 20	7000	Asset located in: Humble, TX
	ft Flat Bar (Unused) S/N: Not Available Usage: Not Available	7339	Quantity of (2) Bundles of 4 In. x 44 Ft Standard I Beams (Unused) S/N: Not Available
7000	Asset located in: Humble, TX	_	Usage: Not Available Asset located in: Humble, TX
7329	Quantity of (3) Bundles of 1 1/2 in x 1/4 in x 20 ft Flat Bar (Unused) S/N: Not Available C/W: (1) Bundle of Angle Iron Usage: Not Available Asset located in: Humble, TX	7340	Quantity of (2) Bundles of 4 In. x 44 Ft Standard I Beams (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7330	Quantity of (3) Bundles of 1 1/2 n x 1/4 in x 20 ft Flat Bars (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7341	Quantity of Bundles of 4 In. x 44 Ft Standard I Beams (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7331	Quantity of (3) Bundles Of 1 1/2 In. x 1/4 In. x 20 Ft Flat Bars (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7342	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7332	Quantity of (4) Bundles Of 20 Ft Flat Bar (Unused) S/N: Not Available C/W: (2) bundles of 3/4 in., (2) bundles of 1 1 /2 in. Usage: Not Available	7343 7344	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) Bundles of Galvanized Solar
7222	Asset located in: Humble, TX	- '` 	Piers 6 in x 10 ft 3 in (Unused)
7333	Quantity of 8 In. x 1/2 In. x 20 Ft Flat Bar (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available
	Usage: Not Available	7045	Asset located in: Humble, TX
7334	Asset located in: Humble, TX Quantity of (2) Bundles of 1 1/2 In. x 20 Ft Flat Bar (Unused) S/N: Not Available Usage: Not Available	7345	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7346	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft 3 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7357	Quantity of 4 1/2 In Pipe S/N: Not Available C/W: assorted length, one bundle Usage: Not Available Asset located in: Humble, TX
7347	Quantity of (3) Bundles Of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7358	Quantity of 2-3/8 Pipe (Unused) S/N: Not Available C/W: 12 ft & 14 ft Usage: Not Available Asset located in: Humble, TX
7348	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7359 7360	Quantity of 2-3/8 In. x 20 ft Pipe (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (13) Pallets of Metal Building
7349	Quantity of (2) Bundles of Galvanized Solar Piers 6 in x 8 ft 6 in (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7300	Components S/N: Not Available C/W: corrugated metal, roll up doors, end caps Usage: Not Available Asset located in: Humble, TX
7350	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7361 7362	Quantity of Log Posts S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of 2-3/8 ln. x 20 ft Pipe (Unused)
7351	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available	7302	S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7363	2020 Trinity 45KVA Transformer S/N: 2001513 Usage: Not Available
7352	Quantity of (3) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7364	Asset located in: Humble, TX Quantity of 6 In. x 7 Ft Steel Channel (Unused) S/N: Not Available Usage: Not Available
7353	Quantity of (2) Bundles of Galvanized Solar Piers 6 in x 10 ft (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7365	Asset located in: Humble, TX Quantity of (3) Spill Containment Pallets S/N: Not Available C/W: 48 in x 48 in Usage: Not Available Asset located in: Humble, TX
7354	Quantity of (3) Bundles of Rebar DA- 615 G60 C1 1/2" 40ft P02 R S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7366	AWS Quik Feed T/A 4.5 ton Feed Trailer S/N: Not Available C/W: Ball Hitch, Torsion Axle, 235/85R16 Tires, 7 ft Body, 235/85R16 Tires, Howden 33 URAI Blower
7355	Quantity of 5 In x 2 In Tubing S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset Jacated in: Humble, TV		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7356	Asset located in: Humble, TX Quantity of 4 In Pipe S/N: Not Available C/W: Assorted Lengths, One Bundle Usage: Not Available Asset located in: Humble, TX	7367	2008 Fort Knox Defender Gun Safe S/N: 6637 C/W: Fireproof 37 in Wide x 66 in High x 27 in Deep Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7368	Quantity of (4) Enerpac 400 Ton Ram w/ 6" Stroke S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7378	Quantity of (5) Roll-Up Cabinets S/N: Not Available C/W: (2) Pallets Usage: Not Available Asset located in: Humble, TX
7369	Quantity of (12) Ericson # 1067-BLC Buzz Boxes Ericson (Unused) S/N: Not Available Usage: Not Available	7379	York 30 In x 35 In x 47 In Safe S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7370	Asset located in: Humble, TX Quantity of (4) Boxes of Dearman # D249 Pipe Alignment Clamps S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7383	Quantity of (2) Workshop Work Table S/N: Not Available Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
7371	2013 Current Tools 8890A Cable Puller and Tensioner S/N: PBD3225 Usage: Not Available Asset located in: Humble, TX	7384 7386	Quantity of (4) Workshop Work Table S/N: Not Available Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX Portable Cool Boss CB-30L Evaporative Cooler
7372	Quantity of Klutch Brake & Slip Roller S/N: Not Available C/W: 48 in box & pan brake, 52 in slip roller, one pallet		S/N: 24443001126 Usage: Not Available Asset located in : Humble, TX
7373	Usage: Not Available Asset located in: Humble, TX Quantity of Ridgid Pony Threaders & Work	7387 -	Ridgid 12 in Miter Saw S/N: U043549453 Usage: Not Available Asset located in: Humble, TX
	Lights S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7388	Quantity of Ladders & Scaffolding S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX
7374	Quantity of Contractor Supplies S/N: Not Available C/W: Stanley tool box, hose, scissor jacks, safety netting, one pallet Usage: Not Available Asset located in: Humble, TX	7389 7390	Quantity of Wet Saw & Buckets Of Trowels S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (2) Pneumatic Floor Nailers
7375	Quantity of Misc. Surplus Supplies S/N: Not Available C/W: Nail Guns, Bolts, Mirrors DeWalt Cordless Vacuum, Outlets Usage: Not Available	7390	S/N: Not Available C/W: Husky, Numax Usage: Not Available Asset located in: Humble, TX Quantity of Dehumidifier & Fan
7376	Asset located in: Humble, TX Quantity of Misc. Surplus Building Supplies S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	C/W: Hose, Electrical Wire, Fluorescent Light Bulbs, Mop, Pictures, Baskets, Metal Shelf, Pole Saw Usage: Not Available Asset located in : Humble, TX	7392	Quantity of Light Bulbs (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7377	Saw Stop 10 In. Table Saw S/N: I170900427 Usage: Not Available Asset located in: Humble, TX	7393	Quantity of (60) Plastic Road Barrels S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7394	Quantity of (2) Keen K450 Electric Rod Ovens S/N: 915337/915344 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7403	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B44825 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF
7395	Quantity of (3) Bottle Carts S/N: Not Available C/W: (2) Sumner, (1) Harper	7404	Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7404	Quantity of (200) 2024 KJ K0310 Corrugated Galvalume Sheets Steel Plates (Unused)
7396	Quantity of (2) 45 In x 60 In Aluminum Covers S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7397	Power Breezer Misting Fan S/N: 52000019		Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7405	Quantity of (200) 2024 KJ K0310 Corrugated Galvalume Sheets Steel Plates (Unused)
7398	Quantity of (2) Crates of Fall Protection S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7399	300 gal Poly DEF Tank S/N: Not Available		Asset located in: Humble, TX
	C/W: 120 V Transfer Pump Usage: Not Available Asset located in: Humble, TX	7406	Quantity of (200) 2024 KJ K0310 Corrugated Galvalume Sheets (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7400	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B43489 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7407	Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels S/N: Not Available
7401	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B44824 C/W: THE PRODUCT IMAGES SHOWN ARE		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7408	Asset located in: Humble, TX Quantity of (100) 2024 SUNTOP S3048 Corrugated Galvalume Steel Panels
	Asset located in: Humble, TX	S/N: Not Available C/W: THE PRODUCT IMAGES SHOW FOR ILLUSTRATION PURPOSES ONL MAY NOT BE AN EXACT REPRESEN' THE ACTUAL PRODUCT Usage: Not Available	S/N: Not Available
7402	Quantity of (100) 2024 SKLP SKL100 Galvalume Steel Sheets (Unused) S/N: B43490 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND		FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
	MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7409	Quantity of (200) 2024 SUNTOP S3048C
	Usage: Not Available Asset located in: Humble, TX		Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7410	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7418	Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7419	Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available	
7411	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused)		Usage: Not Available Asset located in : Humble, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7420	Quantity of Kit Containers 12 Ft Corrugated Tir (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	7421	Quantity of (50) 2024 KJ K0415 Hot Dip	
7412	Quantity of (200) 2024 SUNTOP S3048C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Galvanized Guardrail (Unused) S/N: Not Available C/W: 162 ft 5 in x 20 in, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
7413	Quantity of (100) 2024 SUNTOP S2134C	7422	Quantity of (50) 2024 KJ K0415 Hot Dip	
	Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		Galvanized Guardrail (Unused) S/N: Not Available C/W: 162 ft 5 in x 20 in, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
7414	Quantity of (100) 2024 SUNTOP S2134C Corrugated PPGI Steel Panels (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7423	Galvanized Guardrail (Unused) S/N: Not Available C/W: 162 ft 5 in x 20 in, THE PRODUC IMAGES SHOWN ARE FOR ILLUSTRA PURPOSES ONLY AND MAY NOT BE	S/N: Not Available C/W: 162 ft 5 in x 20 in, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7415	Quantity of 2024 Kit Containers 12 Ft		Asset located in: Humble, TX	
	Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
7416	Quantity of 2024 Kit Containers 12 Ft	7425	,	
7410	Corrugated Tin (Unused) S/N: Not Available Usage: Not Available	7425	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
7417	Asset located in: Humble, TX Quantity of 2024 Kit Containers 12 Ft Corrugated Tin (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	742 6	Quantity of 2 in x 8 in x 20 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7427	Quantity of 2 in x 8 in x 16 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7439	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8" S/N: Not Available Usage: Not Available
7428	Quantity of 2 in x 8 in x 16 ft Decking Lumber		Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7440	Quantity of (7) Pallets of Landscape Sandstone S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7429	Quantity of 2 in x 8 in x 20 ft Decking Lumber S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7441	Quantity of (7) Pallets of Landscape Sandstone Boulders S/N: Not Available
7430	Quantity of 2 in x 8 in x 16 ft Decking Lumber		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7442	Quantity of (6) Assorted Material Racks
7431	Quantity of Bundles of 2 In. x 4 In. x 13 Ft Lumber (Unused) S/N: Not Available		S/N: Not Available C/W: (1) set of 30 ln x 117 ln, (1) set of 36 ln x 168 ln, (1) set of 36 ln x 156 ln Usage: Not Available Asset located in: Humble, TX
	C/W: 2 Bundles of 2 In. x 4 In. x 13 Ft Usage: Not Available	7443	Quantity of (6) 38 ln x 110 ln Steel Material
	Asset located in: Humble, TX		Racks
7432	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available	7444	Quantity of (4) Material Racks S/N: Not Available C/W: (1) set of 38 in x 194 in, (1) set of 38 in x 94 in Usage: Not Available
7433	Asset located in: Humble, TX Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused) S/N: Not Available		
	Usage: Not Available Asset located in: Humble, TX	7445	Asset located in: Humble, TX Quantity of (10) Bundles of Crossties
7434	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused)		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7446	Quantity of (2) 16 Ft Pipeline Skids S/N: Not Available
7435	Quantity of 1 1/4 in Sch 40 Electrical Conduit		Usage: Not Available Asset located in : Humble, TX
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7447	24 Ft Pipeline Skids S/N: Not Available Usage: Not Available
7436	Quantity of 1 1/4 in Sch 40 Electrical Conduit	7440	Asset located in: Humble, TX
	(Unused) S/N: Not Available	7448	Quantity of (2) Bottle Racks S/N: Not Available Usage: Not Available
	Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX
7437	Quantity of 1 1/4 in Sch 40 Electrical Conduit (Unused)	7449	16 Ft Pipeline Skids S/N: Not Available C/W: Lumber
	S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7450	Mega 1205T-ODP 18 cfm Electric 60 gal Air
7438	Quantity of (10) Pallets of Charcoal Lueders Roughbacks Thin Stone Verneer Stone 4"-8"		Compressor S/N: 2022011205
	S/N: Not Available Usage: Not Available		C/W: 5 hp Motor Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7451	Iron Horse 11.2 cfm Electric 60 gal Air Compressor (Unused) S/N: Not Available C/W: 208/230V, 6.5 hp Motor Usage: Not Available Asset located in: Humble, TX	7460	Quantity of (2) Makita MAC5200 6.5 cfm 5.2 gal Air Compressor S/N: Not Available C/W: 120V, 3 hp Motor Usage: Not Available Asset located in: Humble, TX
7452	2024 Landhonor LHR-GAC60 26.8 cfm 60 gal Air Compressor (Unused) S/N: Not Available C/W: Kohler Command Pro 1 Cylinder 14 hp 429 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7461 	Quantity of (6) Porter Cable 2.6 cfm 6 gal Air Compressor S/N: Not Available C/W: 120V Usage: Not Available Asset located in: Humble, TX Marathon 30 gal Air Compressor
7453	2024 Landhonor GAC60T 26.8 cfm 60 gal Air Compressor (Unused) S/N: Not Available C/W: 2023 US EPA Label, Loncin 302 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7463	S/N: Not Available C/W: 200 psi Working Pressure, 5 hp Motor Usage: Not Available Asset located in: Humble, TX Ingersoll Rand 20 gal Air Compressor S/N: Not Available
7454	2024 Landhonor LHR-GAC40Y 20.6 cfm 40 gal Air Compressor (Unused)	7464	C/W: Honda GX200 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available C/W: Briggs & Stratton XR 1 Cylinder 10 hp 306 cc Gasoline Engine Usage: Not Available Asset located in : Humble, TX		2014 Portacool PAC2K361S Air Compressor S/N: 381701-14 Usage: Not Available Asset located in: Humble, TX
7455	2024 Landhonor LHR-GAC40T 20.6 cfm 40 gal Air Compressor (Unused) S/N: Not Available C/W: Briggs & Stratton XR 1 Cylinder 10 hp 306 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7465	2011 Quincy QSI370 Skid-Mounted Electric Air Compressor S/N: BU1104190001 C/W: 300 psi Working Pressure, 3 Phase, 75 hp Motor Usage: 21,697 Hr Asset located in: Humble, TX
7456	Eagle 9G30TRKE-H 18.5 cfm Skid-Mounted 30 gal Air Compressor (Unused) S/N: Not Available C/W: 150 psi Working Pressure, Honda GX270 1 Cylinder 9 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7466	2024 Suihe PW Skid-Mounted Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7457	PowerTrain PT-14G30TRKE-V2 18.5 cfm 30 gal Air Compressor (Unused) S/N: Not Available C/W: 175 psi Working Pressure, 1 Cylinder 14 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX Quantity of (2) Makita MAC5200 6.5 cfm	7467	2024 Suihe PW Skid-Mounted Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, Jiring Dong JF420 1 Cylinder 420 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
	Electric 5.2 gal Air Compressor S/N: Not Available C/W: 120V, 3 hp Motor Usage: Not Available Asset located in: Humble, TX	7468 2024 KJ AM4000P Pressure Was S/N: Not Available C/W: 4000 psi Rating, Water Hea Water Supply, Hose, Spray Wand, Gasoline Engine, THE PRODUCT SHOWN ARE FOR ILLUSTRATION ONLY AND MAY NOT BE AN EXA	2024 KJ AM4000P Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, 250 gal Water Supply, Hose, Spray Wand, 429 cc
7459	PowerTrain PR-TT70G 11.2 cfm 10 gal Air Compressor (Unused) S/N: Not Available C/W: 1 Cylinder 7 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX		SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available

Lot #	Details	Lot #	Details
7469	Northstar Chemical Spay Rig S/N: Not Available C/W: Kohler Command Pro 1 Cylinder Gasoline Engine, 55 gal Poly Tank, Hose, Reel Usage: Not Available Asset located in: Humble, TX	7478	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244122 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7470	Northstar Chemical Spay Rig S/N: Not Available C/W: North Star 1 Cylinder Gasoline Engine, 55 gal Poly Tank, Hose, Reel Usage: Not Available Asset located in: Humble, TX	7479	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244114 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine
7471	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244118 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7480	Usage: Not Available Asset located in: Humble, TX 2024 AGT HPW4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, PW420 1 Cylinder 13 hp Gasoline
7472	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244120		Engine Usage: Not Available Asset located in : Humble, TX
	C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in : Humble, TX	7481	2024 AGT HPW4000 Pressure Washer (Unused) S/N: Not Available C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, PW420 1 Cylinder 13 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, 1 Cylinder Gasoline Engine
7473	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244119 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine		
	Usage: Not Available Asset located in: Humble, TX		
7474	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244116 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available	7483	Usage: Not Available Asset located in: Humble, TX Quantity of (5) Murray Pressure Washer S/N: Not Available C/W: 3200 psi Rating, 1 Cylinder Gasoline
7475	Asset located in: Humble, TX Easy-Kleen Magnum Gold Pressure Washer		Engine Usage: Not Available Asset located in: Humble, TX
	(Unused) S/N: 244121 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7484	Quantity of (5) Murray 3200 PSI 2.5 GPM Pressure Washer S/N: Not Available C/W: Hose, Spray Wand, 1 Cylinder Gasoline Engine Usage: Not Available
7476	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244115 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7485	Asset located in: Humble, TX Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, 1 Cylinder 208 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7477	Easy-Kleen Magnum Gold Pressure Washer (Unused) S/N: 244117 C/W: 4000 psi Rating, Water Heater, Hose, Spray Wand, 1 Cylinder 15 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7486	Quantity of (4) Craftsman Pressure Washer S/N: Not Available C/W: 2800 psi Rating, Hose, Spray Wand, 1 Cylinder 208 cc Gasoline Engine Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7487	Shark 11038410 Pressure Washer S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7503	Quantity of (3) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal 1	
7488	Simpson Pressure Washer		Cylinder 7 hp Gasoline Engine Usage: Not Available	
	S/N: 05241020220 C/W: 4400 psi Rating, Hose, Spray Wand, 1		Asset located in: Humble, TX	
	Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	7504	Quantity of (3) 2024 Powertek PT50C Water Pump (Unused)	
	THE INSPECTION REPORT Asset located in: Humble, TX		S/N: Not Available C/W: 2 in Intake, 2 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine	
7489	Pressure Washer		Usage: Not Available Asset located in: Humble, TX	
	S/N: Not Available C/W: 2750 psi Rating, Honda GX200 1 Cylinder Gasoline Engine Usage: Not Available	7505	Quantity of (3) 2024 Powertek PT80C Water Pump (Unused) S/N: Not Available	
7490	Asset located in: Humble, TX 2024 Powertek CUT-40 40 A Plasma Cutter (Unused)	1	C/W: 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp 212 cc Gasoline Engine Usage: Not Available	
	S/N: Not Available	7506	Asset located in: Humble, TX	
	C/W: Single Phase, 120 V/ 240 V Input, Welding Leads Usage: Not Available	7506	Quantity of (3) Mustang MP4800 Electric Submersible Water Pump (Unused) S/N: Not Available	
	Asset located in: Humble, TX		C/W: 2 in Intake, Submersible Usage: Not Available	
7491	2024 Powertek CUT-40 40 A Plasma Cutter (Unused)	7507	Asset located in: Humble, TX	
	S/N: Not Available C/W: Single Phase, 120 V/ 240 V Input, Welding Leads Usage: Not Available Asset located in: Humble, TX		Quantity of (3) Mustang MP4800 2 in Electric Submersible Water Pump (Unused) S/N: Not Available C/W: 2 in Intake, Submersible Usage: Not Available	
7492	Quantity of (2) 2024 Powertek MMA160 160 A		Asset located in: Humble, TX	
	Stick Electric Welder (Unused) S/N: Not Available C/W: Single Phase, 120 V/ 230 V Input, Welding Leads Usage: Not Available	7508	2024 Landhonor LHR-DFP10 Transfer Fuel Pump (Unused) S/N: Not Available Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
7493	2022 Lincoln Electric Invertec v276 Multi- Process Electric Welder S/N: U1220506197 C/W: Welding Leads Not Included Usage: Not Available	7509	2024 Landhonor LHR-DFP10 Transfer Fuel Pump (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	7510	2024 Agriquip GLDP20 Fuel Pump (Unused)	
7494	2022 Lincoln Electric 275 A Stick Electric Welder S/N: U1220506195 C/W: 3 Phase, Single Phase, 208 V Input, Welding Leads Not Included Usage: Not Available			S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7500	Asset located in: Humble, TX	7511	2024 Agriquip GLDP20 Fuel Pump (Unused)	
7502	Quantity of (2) 2024 Landhonor LHR-TWP80 Water Pump (Unused) S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Centrifugal 1 Cylinder 7 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	

1 - + "	Dataila	1 "	Dataila
Lot #	Details	Lot #	Details
7512	Quantity of (2) 2024 Agriquip GLGP20 Fuel Pump (Unused) S/N: Not Available C/W: Hose, Nozzle THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7519 7520	Quantity of (2) Craftsman 5.0 kW Generator Set S/N: Not Available C/W: Briggs & Stratton 1 Cylinder 306 cc Gasoline Engine, /5.0 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX
7513	Quantity of (2) Fuel Boss 12 V Fuel Pump	/3ZU	Quantity of (2) Craftsman 5 kW Generator Set S/N: Not Available
	(Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: Briggs & Stratton 306 cc Engine, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX
7514	Metered 12V Diesel Fuel Pump (Unused)	7521	Quantity of (2) Champion 3.5 kW Generator Set
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX		S/N: Not Available C/W: Champion 1 Cylinder 224 cc Dual Fuel Engine, 240 V & 120 V Receptacles Usage: Not Available
7515	Fuel Boss Metered Fuel Pump (Unused)		Asset located in: Humble, TX
	S/N: Not Available C/W: 50 ft hose reel, nozzle Usage: Not Available Asset located in : Humble, TX	7522	Quantity of (2) Craftsman 5 kW Generator Set S/N: Not Available C/W: Briggs & Stratton 306 cc Engine, 240 V & 120 V Receptacles
7516	Quantity of (4) Champion Inverter 4650 Watts Portable Generator Set		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: 1 Cylinder Dual Fuel Engine Usage: Not Available Asset located in : Humble, TX	7523	Quantity of (5) Pallets of Generators & Pressure Washers S/N: Not Available C/W: 1 Cylinder Gasoline Engine, (2) Generac, Titan, North Star, Simpson, Ex-Cell, Mi-T-M, Power Ease Usage: Not Available
7517A	Smarter Tools STGP7500DEB 6.0 kW Generator Set S/N: GPSD7500202		
	C/W: 2013 US EPA Label, 1 Cylinder 389 cc		Asset located in: Humble, TX
	Gasoline Engine, /6.0 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available	7524	Westinghouse iGen 4500 Generator Set S/N: 45A0622B3333 C/W: 120 V Rated Voltage, 120 V Receptacles Usage: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
	Asset located in: Humble, TX	7525	Westinghouse iGen 4500 Generator Set
7517	Quantity of (4) Champion Inverter 4650 Watts Portable Generator Set S/N: Not Available		S/N: 45A0621B13309 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available
	C/W: 1 Cylinder Dual Fuel Engine Usage: Not Available		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
7518	Quantity of (2) Craftsman 5.0 kW 5000 Watt	7526	Westinghouse IGen4500 Generator Set
	Generator Set S/N: Not Available C/W: 1 Cylinder 306 cc Gasoline Engine, /5.0 kW, Rated Single Phase Output, 120 V / 240 V		S/N: 45A1221B22693 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available
	Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	1	Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7527	Westinghouse IGen 4500 Generator Set S/N: 45A0621B14275 C/W: Gasoline Engine, / 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7535	2021 Champion 7850 Generator Set S/N: 21MAY1810171 C/W: Champion 1 Cylinder 389 cc Dual Fuel Engine, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	7539	Onan 4KYFA26100D 4 kW Generator Set	
7528	Westinghouse IGen4500 Generator Set S/N: 45A0621B14272 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available	7003	S/N: B953335555 C/W: Gasoline Engine, /4 kW, Rated Single Phase Output, 120 V Rated Voltage Usage: Not Available Asset located in: Humble, TX	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7540	2020 International Titan 4000 Hydroxyl Generator	
7500	Asset located in: Humble, TX	\dashv	S/N: 33634 Usage: Not Available	
7529	Westinghouse 4500 Generator Set S/N: 45A0622B3477 C/W: Gasoline Engine, 120 V / 120 V Rated Voltage, 120 V Receptacles		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	Usage: Not Available Asset located in : Humble, TX	7541	2020 International Titan 4000 Hydroxyl Generator	
7530	Westinghouse iGen 4500 Generator Set S/N: 45A0621B14250 C/W: Gasoline Engine, 120 V / 120 V Rated Voltage, 120 V Receptacles		S/N: 33636 Usage: Not Available Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX	Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7542	2020 International Titan 4000 Hydroxyl Generator S/N: 33633	
7531	Asset located in: Humble, TX Westinghouse iGen 4500 Generator Set S/N: 45A0622B3579		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Asset located in : Humble, TX		Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available	
7532	Westinghouse 7500 9.5 kW Generator Set		Asset located in: Humble, TX	
	S/N: 75A0621B6717 C/W: 2021 US EPA Label, CARB Compliant, Westinghouse 1 Cylinder 420 cc Gasoline Engine, /9.5 kW, Rated Single Phase Output, 240 V & 120 V Receptacles Usage: Not Available	7544	Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	7545	Quantity of Chains and Ratchet Binders	
7533	Craftsman 3500 3.5 kW Generator Set (Unused) S/N: 417013857 C/W: Briggs & Stratton 1 Cylinder Engine		S/N: Not Available C/W: one pallet Usage: Not Available Asset located in : Humble, TX	
	Usage: Not Available Asset located in : Humble, TX	7546	Quantity of Chains and Ratchet Binders S/N: Not Available	
7534	Powerhorse 11050 Generator Set S/N: 08212167		C/W: one pallet Usage: Not Available	
	C/W: Powerhorse 1 Cylinder 457 cc Gasoline Engine, 120 V / 250 V Rated Voltage, 240 V & 120 V Receptacles Usage: Not Available Asset located in : Humble, TX	7547	Asset located in: Humble, TX Quantity of (1) Pallets of 3/8 X 20 in Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7548	Quantity of Chains and Ratchet Binders S/N: Not Available C/W: one pallet Usage: Not Available Asset located in: Humble, TX	7557	Sling (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7549	Quantity of 5/16 in Chains S/N: Not Available Usage: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7550	Asset located in: Humble, TX	7558	Quantity of 2024 Landhonor LHR-WS22
7550	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Webbing Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7559	Quantity of (24) 2024 Suihe R24 Ratchet Straps (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE
7551	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	7560	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT
7552	Quantity of 2024 Landhonor LHR-RC5400 5400 Ib Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		IMAGÈS SHOWN ARÈ FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7553	Quantity of 2024 Landhonor LHR-RC5400 5400 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7561	Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION
7554	2024 Landhonor LHR-RC9200 9200 lb Ratchet Binders w/20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE	7562	PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Quantity of 2024 Landhonor LHR-RF24 27 ft Ratchet Straps (Unused) S/N: Not Available C/W: (16) 5 ton and (8) 3 ton, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION
7555	Quantity of (6) 5/16 In. Chain Sling S/N: Not Available Usage: Not Available Asset located in: Humble, TX		PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
7556	Quantity of 2024 Landhonor LHR-WS22 Webbing Sling (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7563	Asset located in: Humble, TX Quantity of (42) 2024 SKLP SK003 Ratchet Straps (Unused) S/N: B43595 C/W: (32) 2 in x 27 ft, (16) 1.5 in x 27 ft, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7564	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7571	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7572	Quantity of 2024 Landhonor LHR-G209 Shackle (Unused) S/N: Not Available
7565	Quantity of (5) 2024 Suihe BC-5400 5400 lb Ratchet Binders and (10) 20 ft Chains (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7573	2024 SKLP SK-LL Laser Level (Unused) S/N: B44827 C/W: grade rod, tripod Usage: Not Available Asset located in: Humble, TX
7566	Asset located in: Humble, TX Quantity of (5) 2024 Suihe BC-9200 9200 lb	7574	IntelliRock Concrete Tester S/N: Not Available Usage: Not Available
	Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available		Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7575	HS100 Bolt Tension Calibrator S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7576	Nikon DTM-322 Total Station
7567	67 Quantity of (5) 2024 Suihe BC-9200 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		S/N: 815079 Usage: Not Available Asset located in : Humble, TX
		7577	Nikon NPL-322 Total Station S/N: D025332 Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7578	Quantity of Power Tools & Laser Levels
7568	Quantity of (38) 2024 Suihe S38 Shackle (Unused) S/N: Not Available		S/N: Not Available C/W: Levels, bandsaws, one pallet Usage: Not Available Asset located in : Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7579	Quantity of (8) Spy 725 Pipe Locators S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7560	Asset located in: Humble, TX	7580	Quantity of (2) Spy 725 Pipe Locator
7569	Quantity of (5) 2024 SKLP SK001 9200 lb Ratchet Binders & (10) 20 ft Chains (Unused) S/N: B43906 C/W: THE PRODUCT IMAGES SHOWN ARE		S/N: Not Available C/W: batteries, chargers Usage: Not Available Asset located in : Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7581	Wood Tuff 48 in Job Site Box S/N: Not Available C/W: 15 pcs Craftsman Tool Set, 13" String Trimmer/Edger20 v Max Power Cleaner10" 20 v Cordless Chainsaw20 v Axial Blower
7570	Quantity of (38) 2024 Suihe S38 Shackle (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		20 v Cordiess Chainsaw20 v Axiai Blower- 22" 20 v Hedge Trimmer20 v Led Automot Hood Light20 v Task Light1/4" 20 v Brushless Impact Driver 20 v Led Light /Magnifying Lens1/2" Brushless Hammer Drill Kit 2 Batteries ChargerBag Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7582	Wood Tuff 42 in Job Site Box S/N: Not Available C/W: 158 pcs Wokin Tool Set, (1) Wokin 132 Piece SAE & Metric Tool Chest (1) Workin 13 Piece Combination and Wrench Set (1) Double Ring Spanners Set	7592	Quantity of (3) Arcan ALFJ48 3 Ton 48 In. Farm Jack (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7593	Quantity of (3) Wokin 3 Ton Floor Jack (Unused)
7583	Wood Tuff 48 in Job Site Box S/N: Not Available C/W: 25 pcs Makita Power Tool Kit		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7594	Quantity of (2) Valley 22 Ton Air/Hydraulic Service Bottle Jack (Unused)
7584	Wood Tuff 42 in Job Site Box S/N: Not Available C/W: 8 pcs Wokin/Valley tools set, (2) Valley 2		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Ton Trolley Jack , (4)-Wokin 3 Ton Jack Stand, (2) Wokin 4 Ton Bottle Jack Usage: Not Available Asset located in : Humble, TX	7595	Quantity of (2) Air Conditioner S/N: Not Available Usage: Not Available Apart located in: Humble TV
7585	Wood Tuff 48 in Job Site Box S/N: Not Available C/W: 7 pcs Cub Cadet tool set, HT24E Hedge Trimmer CS160E Cordless Chainsaw, LB600E Leaf Blower, ST115 String Trimmer, Battery Charger Usage: Not Available	7596	Asset located in: Humble, TX Quantity of (6) PowerTrain PT240 General Purpose Engine (Unused) S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7597	Quantity of (6) PowerTrain PT240 General
7586	2024 Powertek PT9500 Magnetic Drill (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Purpose Engine (Unused) S/N: Not Available C/W: 1 Cylinder 2.4 hp Gasoline Engine Usage: Not Available Asset located in: Humble, TX
7587	2024 Powertek G80A Electric Demolition Breaker (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7598	Quantity of (4) 1 Gauge Booster Cables (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7588	Quantity of (2) 2024 Powertek PT8810 1 In. Pneumatic Impact Wrench (Unused) S/N: Not Available Usage: Not Available Notes: . Asset located in: Humble, TX	7599	2024 Topcon RL-H5B Rotary Laser Level (Unused) S/N: Not Available C/W: Receiver, Tripod, Grade Rod, Batteries Usage: Not Available Asset located in: Humble, TX
7589	2019 Hilti DD250E-BS Core Drill - Fits Hilti DD250 S/N: Not Available Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	7600	Quantity of (10) 14 in Diamond Blades (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7500	Asset located in: Lake Worth, TX	7601	Quantity of (3) Neon Signs (Unused)
7590	Quantity of Sandblasting Equipment S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: (1) Peterbilt, (2) Caterpillar Usage: Not Available
7591	Quantity of Power Tools	 	Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7602	Quantity of (5) 25 ft 800 amp Booster Cable (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7603	Quantity of Power Tools S/N: Not Available C/W: DeWalt, Stihl, Milwaukee, one pallet Usage: Not Available Asset located in: Humble, TX	7614	HeatStar HS6000DF 599524 BTU Forced Air Direct Fired Industrial Space Heater S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7604	Quantity of Power Tools S/N: Not Available C/W: Bosch, DeWalt, one pallet Usage: Not Available Asset located in: Humble, TX	7615	HeatStar HS6000DF 599524 BTU Forced Air Direct Fired Industrial Space Heater S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7605	Power Tools S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7616	Quantity of (4) Mr. Heater 60000 BTU Forced Air Space Heater (Unused) S/N: Not Available Usage: Not Available
7606	Quantity of (3) Metal Detectors S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7617	Asset located in: Humble, TX 2024 Agriquip GLHP50 50 ton Air/Hydraulic Shop Press (Unused) S/N: Not Available
7607 7608	Quantity of (1) Crates of Testers and Crimps S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (1) Pallets of Sockets and Pliers		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7618 7619	Asset located in: Humble, TX 2024 Landhonor LHR-CIA400 400 lbs Cast Iro Anvil (Unused) S/N: Not Available
7609	Quantity of 2 Unknown or N/A Hose Reels S/N: Not Available Usage: Not Available		Usage: Not Available Asset located in: Humble, TX 2024 Landhonor LHR-CIA400 400 lbs Cast Iron
7610	Asset located in: Humble, TX Quantity of Readout Kit, Hydraulic Tester, Deadweight Tester S/N: Not Available		Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7611	Usage: Not Available Asset located in: Humble, TX Quantity of (16) 2024 Agriquip GLWH16 Auto Darkening Welding Helmets (Unused) S/N: Not Available	7620	2024 Landhonor LHR-CIA200 200 lbs Cast Iron Anvil (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7621	2024 Suihe A200 200 lb Cast Iron Anvil (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND
7612	Quantity of (4) Mr. Heater 60000 BTU Forced Air Space Heater (Unused) S/N: Not Available		MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7622	2024 Landhonor LHR-CIA200 200 lbs Cast Iron Anvil (Unused)
7613	HeatStar HS6000DF 599524 BTU Forced Air Direct Fired Industrial Space Heater S/N: Not Available Usage: Not Available Asset located in: Humble, TX		S/N: Not Available Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details	
7623	2024 Suihe WW 20000 lb Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7631	Wood Power 12000 lb Electric Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
		7632	Quantity of (6) Pallets of Waterproof Snow Gloves (Unused) S/N: Not Available	
7624	2024 Suihe WW 20000 lb Winch (Unused) S/N: Not Available		Usage: Not Available Asset located in : Humble, TX	
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7633	Quantity of (4) Pallets of Waterproof Snow Gloves (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	
7625	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND	7634 7635	Quantity of (6) Pallets of Waterproof Snow Gloves (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Quantity of (6) Pallets of Waterproof Snow Gloves (Unused) S/N: Not Available	
7626	Asset located in: Humble, TX 2024 Landhonor LHR-EW20000 20000 lb	-	Usage: Not Available Asset located in: Humble, TX	
	Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7636	Quantity of 2024 HUI NA RC Excavator Toys (Unused) S/N: Not Available Usage: Not Available Notes: . Asset located in: Humble, TX	
7627	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	7637	2024 Agriquip GLGS40 40 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available Asset located in: Humble, TX	7638	2024 Agriquip GLGS40 40 Gun Safe (Unused)	
7628	2024 Landhonor LHR-EW20000 20000 lb Electric Winch (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		FOR ILLUSTRATION PURPOSES ONLY: MAY NOT BE AN EXACT REPRESENTA THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7639	2024 Agriquip GLGS14 14 Gun Safe (Unused) S/N: Not Available	
7629	2024 Powertek WW20000 20000 lb Heavy Duty Electric Wirelss Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	
7630	Quantity of (2) 2024 Powertek WW13000 13000 lb Wireless Winch (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX			

Lot #	Details	Lot #	Details
7640	2024 Agriquip GLGS14 14 Gun Safe (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF	7651	2024 CXT CS1 Massage Chair (Unused) S/N: 6-1 Usage: Not Available Asset located in: Humble, TX
	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7652	2024 CXT CS1 Massage Chair (Unused) S/N: 6-2 Usage: Not Available
7641	Quantity of (5) 2024 Powertek 300 ft x 2 in Lay		Asset located in: Humble, TX
	Flat Water Hose (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7653	2024 CXT CS1 Massage Chair (Unused) S/N: 6-3 Usage: Not Available Asset located in: Humble, TX
7642	Quantity of (4) 2024 Powertek 300 ft x 3 in Lay Flat Water Hose (Unused) S/N: Not Available Usage: Not Available	7654	2024 CXT CS1 Massage Chair (Unused) S/N: 6-4 Usage: Not Available Asset located in: Humble, TX
7643	Asset located in: Humble, TX Quantity of (5) 2024 Powertek 20T 20 Ton Air /Hyd Bottle Jack (Unused) S/N: Not Available	7655	2024 CXT CS1 Massage Chair (Unused) S/N: 6-5 Usage: Not Available Asset located in: Humble, TX
7644	Usage: Not Available Asset located in: Humble, TX Quantity of (14) A/C Compressors (Unused)	7656	2024 CXT CS1 Massage Chair (Unused) S/N: 6-6 Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7657	Asset located in: Humble, TX 2024 Human Touch Quies Zero Gravity
7645	Golden Technologies BUZZAROUND EX Ride On Electric Mobility Scooter (Unused) S/N: Not Available		Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7658	2024 Human Touch Certus Zero Gravity Massage Chair Recliner
7646	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	7659	Human Touch ZeroG Electric Massage Chair Recliner
7647	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7660	Human Touch AcuTouch 9500X Leather Full- Body Massage Chair Recliner
7648	2024 Landhonor LHR-LSN20F Two Person Indoor Infrared Sauna Room (Unused) S/N: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7661	Human Touch Gravis Zero Gravity Massage Chair Recliner
7649	2024 Landhonor LHR-LSN30F Three Person Indoor Infrared Sauna Room (Unused) S/N: Not Available		S/N: Not Available C/W: heat Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7662	Fjords Milan Power Leather Zero Gravity
7650	2024 Landhonor LHR-MG766 Massage Chair (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7002	Recliner (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7663	Quantity of (2) Human Touch Wholebody Massage Chair Recliners S/N: Not Available Usage: Not Available	7674	Osaki Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7675	Quantity of (2) BarcaLounger Power Leather
7664	Whole Body Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7673	Recliners (Unused) S/N: Not Available C/W: foot rest Usage: Not Available Asset located in: Humble, TX
' 665	Human Touch HT5020 Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7676	ProForm Carbon Treadmill S/N: Not Available Usage: Not Available
7666	Quantity of (2) BarcaLounger Jacque II Leather Pedestal Chairs (Unused) S/N: Not Available C/W: Ottoman Usage: Not Available Asset located in: Humble, TX	7677	Asset located in: Humble, TX ProForm Electric Treadmill S/N: PP910C0010103 C/W: To Fit PRO FORM Usage: Not Available Asset located in: Humble, TX
7667	Human Touch Robotic Leather Full-Body Massage Chair Recliner with Heat S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7678	Quantity of (7) Boxes of Kenwood Radios S/N: Not Available C/W: (1) Pallet Usage: Not Available Asset located in: Humble, TX
7668	Osaki Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7680	Osaki Maxium 3D Massage Chair S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7669	Quantity of (2) Human Touch HT5270 Massage Chair Recliner S/N: Not Available Usage: Not Available	7681	Osaki Maxium 3D Massage Chair S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7670	Asset located in: Humble, TX BarcaLounger Electric Patient Lift Power Leather Recliner (Unused) S/N: Not Available	7682	Quantity of (3) Video Slot Machines S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7671	Usage: Not Available Asset located in: Humble, TX Svago SV395 Zero Gravity Massage Chair	7683	Forklift Crane Simulator Consol S/N: Not Available Usage: Not Available
071	Recliner		Asset located in: Humble, TX
	S/N: Not Available C/W: heat Usage: Not Available Asset located in : Humble, TX	7684	Canon iPF650 24 in Large Format Printer S/N: AACF1539 Usage: Not Available Asset located in: Humble, TX
7672	Human Touch ZeroG 4.0 Zero Gravity Massage Chair Recliner S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7685	Quantity of (2) Sharp MXM266N Computer Printers S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7673	Quantity of (2) Mac Motion Leather Recliner Chair (Unused) S/N: Not Available C/W: Ottoman Usage: Not Available Asset located in: Humble, TX		ACCUPATION IN FIGURE 17

Lot #	Details	Lot #	Details	
7686	Armor Titanium Series 24 24 Gun Safe (Unused) S/N: Not Available C/W: Fireproof 23 in Wide x 55 in High x 20 in Deep, 1400 DEGREE FIRE RATING, DIGITAL COMBINATION KEY PAD W/BACKUP KEY, ADDITIONAL DOOR POUCH STORAGE FEATURE FOR PISTOLS & OTHER VALUABLES, 5 LIVE ACTION LOCKING BOLTS Usage: Not Available Asset located in: Humble, TX	7693 7694	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower Usage: Not Available Asset located in: Humble, TX Billy Goat BC2600HEBH 28 in Walk-Behind Brush Cutter S/N: 070620015 C/W: Honda GV390 1 Cylinder Gasoline Engine	
7687	Armor Titanium Series 24 24 Gun Safe (Unused)		Usage: Not Available Asset located in: Humble, TX	
	S/N: Not Available C/W: Fireproof 23 in Wide x 55 in High x 20 in Deep, 1400 DEGREE FIRE RATING, DIGITAL COMBINATION KEY PAD W/BACKUP KEY, ADDITIONAL DOOR POUCH STORAGE FEATURE FOR PISTOLS & OTHER VALUABLES, 5 LIVE ACTION LOCKING BOLTS Usage: Not Available Asset located in: Humble, TX	7695	Yardman Walk-Behind 20 In Rear Tine Garden Tiller S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
7688	Armor Titanium Series 64 64 Gun Safe S/N: Not Available C/W: Fireproof 40 in Wide x 58 in High x 25 in Deep Usage: Not Available Asset located in: Humble, TX	7696	2014 Barreto 1320H 21 in Walk Behind Rotary Tiller S/N: 14269 C/W: Gasoline Engine, Hydraulic Drive Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	
7689	Armor Titanium Series 40 40 Gun Safe		Asset located in: Lake Worth, TX	
	(Unused) S/N: Not Available C/W: Fireproof 29 in Wide x 59 in High x 20 in Deep, 1400 DEGREE FIRE RATING, DIGITAL COMBINATION KEY PAD W/BACKUP KEY, ADDITIONAL DOOR POUCH STORAGE FEATURE FOR PISTOLS & OTHER VALUABLES, 5 LIVE ACTION LOCKING BOLTS Usage: Not Available	7697	Legend 20 in Rototiller S/N: Not Available C/W: 212 cc Engine Usage: Not Available Asset located in: Humble, TX 2024 Landhonor LHR-PWC6 Tow-Behind Wood Chipper (Unused) S/N: Not Available	
7690	Asset located in: Humble, TX 2024 Landhonor LHR-PSM26A 26 in Portable	-	Usage: Not Available Asset located in: Humble TX	
7690	Sawmill (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	Splitter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 7700 Legend 20 in Rototiller S/N: Not Available C/W: 212 cc Engine Usage: Not Available Asset located in: Humble, TX 7701 Quantity of (18) Rhino Rugged Tools (Unused) S/N: Not Available C/W: (3) # 12 Aluminum Scoop	7699 2024 Landhonor LHR-GLS34 Gasolii Splitter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX 7700 Legend 20 in Rototiller S/N: Not Available C/W: 212 cc Engine Usage: Not Available	2024 Landhonor LHR-GLS34 Gasoline Log Splitter (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX Legend 20 in Rototiller
7691	2024 Landhonor PSM31A 31 in Portable Sawmill (Unused) S/N: Not Available			C/W: 212 cc Engine Usage: Not Available
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: (3) # 12 Aluminum Scoop (3) 16" Drain Spade (3) Spade Fork (3) Roofer Spade (3) 10" Hoe (3) Round Point Shovel	
7692	Quantity of (6) Yard Force Walk-Behind Lawn Mower S/N: Not Available C/W: 22 in Mower Usage: Not Available Asset located in: Humble, TX		•	

Lot #	Details	Lot #	Details
7702	Quantity of (18) Rhino Rugged Landscaping Tools (Unused) S/N: Not Available C/W: (3) #12 Aluminum Scoop, (3) 16" Drain Spade, (3) Spade Fork, (3) Roofer Spade, (3) 10" Hoe, (3) Round Point Shovel Usage: Not Available	7712	Quantity of (2) Pen Feeder W/Fawn Tubes S/N: Not Available Usage: Not Available Asset located in: Humble, TX
		7713	Quantity of (2) 3000 lb Protein Feeders S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
7703	Troy-Bilt Chipper Shredder Vacuum S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7714	Asset located in: Humble, TX Quantity of (3) 3000 lb Protein Feeders S/N: Not Available Usage: Not Available
7704	Quantity of (3) Yard Force Edger S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7715	Asset located in: Humble, TX Quantity of (3) 3000 lb Protein Feeders S/N: Not Available Usage: Not Available
7705	Troy-Bilt Chipper Shredder Vacuum S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7716	Asset located in: Humble, TX Quantity of (2) ASF Pen Feeder W/Fawn Tubes S/N: Not Available Usage: Not Available
7706	Ryan Lawnaire V Walk-Behind 26 in Aerator S/N: Not Available C/W: Honda GX160 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX	7719	Asset located in: Humble, TX Quantity of (2) Lamco 600 Stand & Fill Corn Feeders S/N: Not Available Usage: Not Available
7707A	Cushman Top Dresser S/N: Not Available		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	7720	Quantity of (4) Lamco 600 Stand & Fill Corn
7707	Quantity of (2) 2024 Powertek EB-800-E Backpack Leaf Blower (Unused) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX		Feeders S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7708	Custombuilt 5 Ft 6 In. x 4 Ft Deer Stand (Unused) S/N: Not Available Usage: Not Available	7721	Lamco 300 Stand & Fill Corn Feeder S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7709A	Asset located in: Humble, TX Game Winner 9 Ft Deer Stand S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7722	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7709	Custombuilt 5 Ft 6 In. x 4 Ft Deer Stand (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7723	Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7710	Quantity of (3) Bayou DeView 6 ft Sled Duck Blinds S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7724	Big Daddy Feeders 500 LB Stand & Fill Solar Deer Feeder (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7711	Quantity of (3) 3000 lb Protein Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7725A	Quantity of (2) Dillon 600 Lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7725	Quantity of (2) TWS 50 lb Heavy Duty Road Feeders S/N: Not Available C/W: controls Usage: Not Available Asset located in: Humble, TX	7736	Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available C/W: Turkey/Bird Motif Usage: Not Available Asset located in: Humble, TX
7726	Quantity of (3) 2022 Millenium MFD6-1-21 Tree Stands S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7737	Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available C/W: Rabbits Usage: Not Available Asset located in: Humble, TX
7727	Quantity of (3) Tripod Bow Blinds S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7738	Big Daddy Targets Large AR 500 Shooting Target (Unused) S/N: Not Available Usage: Not Available
7728	Quantity of (2) Wildgame Trapping Systems S/N: Not Available C/W: One Stack, Cameras, 8 Ft x 12 Ft Panels Usage: Not Available	7740	Asset located in: Humble, TX Big Daddy Targets Large AR 500 Shooting Target (Unused)
7729	Asset located in: Humble, TX Quantity of (2) Wildgame Trapping Systems S/N: Not Available C/W: One Stack, Camera, (24) 8 Ft x 12 Ft		S/N: Not Available C/W: Bigfoot/T-Rex motif Usage: Not Available Asset located in : Humble, TX
7700	Panels Usage: Not Available Asset located in: Humble, TX		Big Daddy Feeders 700 LB Solar Deer Feeder w/ Timer (Unused) S/N: Not Available Usage: Not Available
7730	68 in Hex Fire Pit S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX Quantity of (3) Millenium Two Man Tree Strands
7731	ASF 28 in Hex Fire Pit S/N: Not Available Usage: Not Available		S/N: Not Available Usage: Not Available Asset located in : Humble, TX
7732	Asset located in: Humble, TX Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available	7742	Quantity of (3) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7733	C/W: Raccoon Motif Usage: Not Available Asset located in: Humble, TX	7743	Quantity of (2) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX
// 3 3	Big Daddy Targets Small AR 500 Shooting Target (Unused) S/N: Not Available C/W: Rabbit Motif Usage: Not Available Asset located in: Humble, TX	7744	Quantity of (2) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7734	Big Daddy Fire Pits Large Steel Fire Pit (Unused) S/N: Not Available Usage: Not Available	7745	Quantity of (2) Dillon 600 lb Fiberglass Feeders S/N: Not Available Usage: Not Available Asset located in: Humble, TX
7735	Asset located in: Humble, TX Big Daddy Targets Large AR 500 Shooting Target (Unused) S/N: Not Available	7746	Bigfoot Steel Shooting Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	C/W: Bigfoot w/Fish Motif Usage: Not Available Asset located in: Humble, TX	7747	T-Rex Steel Shooting Target (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7748	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7756	Erie Industries SCL850 Mini Compact Track Loader (Unused) S/N: SCL850562C2363 C/W: Open Operator Station, Bucket, THE
7749	Quantity of (2) Steel Shooting Targets (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE
7750	2024 Landhonor LDH-FPR36 Round Fire Pit Ring (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7757	Erie Industries SCL850 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, Bucket, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY
7751	Quantity of (5) Poly Triangles S/N: Not Available Usage: Not Available Asset located in: Humble, TX		NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
7752	55 In. Adjustable Height Propane Fire Pit Table (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	7758	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket
7753	55 In. Adjustable Height Propane Fire Pit Table (Unused)		Usage: Not Àvailable Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	7759	2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available
7754	Erie Industries SCL850 Mini Compact Track Loader (Unused) S/N: SCL850562C2337 C/W: Open Operator Station, Bucket, THE		C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Humble, TX
	BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX		2024 Landhero LDH-T460 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Humble, TX
7755	Erie Industries SCL850 Mini Compact Track Loader (Unused) S/N: SCL8500024 C/W: Open Operator Station, Bucket, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	7761	2024 Powertek PT-450 Mini Compact Track Loader (Unused) S/N: Not Available C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Bucket Usage: Not Available Asset located in: Humble, TX 2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2403148097 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7763	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2403148256 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	7771	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT23202407000110 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Humble, TX
7764	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178353 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available Asset located in: Humble, TX	7772	2024 AGT KTT23 Mini Compact Track Loader (Unused) S/N: KTT232024L0803001 C/W: Open Operator Station, Joystick Steering, 8 in Track Belts, 31 in Bucket, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL
7765	2024 JQ POWER JQ400 Mini Compact Track Loader (Unused) S/N: 2404178379 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 44 in Bucket Usage: Not Available		PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX 2024 AGT KTT23 Mini Compact Track Loader
7766	Asset located in: Humble, TX 2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 24080206 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: 1 Hr Asset located in: Humble, TX		(Unused) S/N: KTT232024L0803002 C/W: Open Operator Station, Joystick Steering 8 in Track Belts, 31 in Bucket, THE BROCHURI IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE
7767	2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 24080205		ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: Not Available Asset located in: Humble, TX	7774	2024 AGT LRT23 Mini Compact Track Loader (Unused) S/N: LRT23202407190062 C/W: Open Operator Station, Joystick Steering,
7768	2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 071256 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: Not Available Asset located in: Humble, TX		7 in Track Belts, Manual Coupler, 44 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
7769	2024 NKL NMK-60 Mini Compact Track Loader (Unused) S/N: 24080201 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 40 in Multi-Purpose Bucket Usage: Not Available Asset located in: Humble, TX	(Unused) S/N: LRT23202408010005 C/W: Open Operator Station, Joy 7 in Track Belts, Manual Coupler THE PRODUCT IMAGES SHOWN ILLUSTRATION PURPOSES ONL	S/N: LRT23202408010005 C/W: Open Operator Station, Joystick Steering, 7 in Track Belts, Manual Coupler, 44 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE
7770	2024 AGT CRT23 Mini Compact Track Loader (Unused) S/N: CRT23202407000105 C/W: Open Operator Station, 7 in Track Belts, Manual Coupler, 32 in Bucket Usage: Not Available Asset located in: Humble, TX		Usage: Not Available

Lot #	Details	Lot #	Details
7776	2024 AGT YSRT14 Mini Compact Track Loader (Unused) S/N: YSRT1420240801805 C/W: Open Operator Station, Manual Coupler, 38 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7783	2014 Ditch Witch RT16 Walk-Behind Trencher S/N: CMWRT16XKE0001029 C/W: Briggs & Stratton 2 Cylinder 16 hp Gasoline Engine, Hydrostatic Drive, 4 in Wide x 42 in Long Combination Trencher Chain Usage: 696 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7777	2024 AGT YSRT14 Mini Compact Track Loader	- 7784	2021 Vermeer VX50 500 gal T/A Vacuum Excavation Unit
	(Unused) S/N: YSRT1420240801794 C/W: Open Operator Station, Manual Coupler, 38 in Bucket, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		S/N: 1M9FE1221MS284763 C/W: 12000 lb GVWR, Lunette Ring Hitch, Torsion Axle, Steel Debris Tank, Rear Hose Reel, 200 gal Fresh Water Tank, Full Open Tailgate, Hydraulic Tailgate Locks, Blower, Boiler, 235/80R16 Tires, Tier 4, 2021 US EPA Label, Kubota 4 Cylinder Diesel Engine Usage: 277 Hr Notes: LOCATED-IN-HOUSTON-TX ONLY THE
7778	2024 AGT QHT500FL Stand-On Mini Crawler	1	TRAILER COMES WITH TITLE
	Dumper (Unused)	7705	Asset located in: Humble, TX
	S/N: QHT500FL202408016 C/W: Hydrostatic Drive, 1 Cylinder 6.5 hp	7785	2022 Ditch Witch HX30G 500 gal T/A Vacuum Excavation Unit
	Gasoline Engine, 7 in Rubber Tracks Usage: Not Available Asset located in : Humble, TX		S/N: 1DST522N2N1701879 C/W: Spring Suspension, Electric Brakes, Steel Debris Tank, 500 gal Fresh Water Tank,
7779	2024 AGT QHT500FL Stand-On Mini Crawler Dumper (Unused) S/N: QHT500FL202408019 C/W: Hydrostatic Drive, 1 Cylinder 6.5 hp Gasoline Engine, 7 in Rubber Tracks		Hydraulic Lift Tailgate, Hydraulic Tailgate Locks, Blower, 235/80R16 Tires, 2022 US EPA Label, Vanguard NBSXS.9932VB 2 Cylinder 31 hp 896 cc Gasoline Engine Usage: 162 Hr
	Usage: Not Ăvailable		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
7780	2024 Landhero LDH-MCD500 Self-Loading Crawler Dumper (Unused) S/N: Not Available C/W: Briggs & Stratton 6.5 hp Gasoline Engine, 7 in Rubber Tracks, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	7786	2015 Vermeer BC1000XL Tow-Behind Wood Chipper S/N: 1VRY11198F1021751 C/W: 2014 US EPA Label, PSI 4 Cylinder 3.0 L Gasoline Engine, 12 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Lunette Ring Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7787	2013 Vermeer BC1000XL Tow-Behind Wood
7781	Landhero Walk-Behind Mini Crawler Dumper S/N: Not Available C/W: Hydrostatic Drive, Briggs & Stratton 1 Cylinder 6.5 hp 208 cc Gasoline Engine, 7 in Rubber Tracks Usage: Not Available		Chipper S/N: 1VRY11195D1019159 C/W: Cummins 4 Cylinder Diesel Engine, 12 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Lunette Ring Usage: 191 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7789	2024 KULY YKL-35 Mini Excavator (Unused)
	Asset located in: Humble, TX	// 0 3	S/N: 24071030
7782	Heracles H130 3-Wheel Mini Wheel Loader S/N: Not Available C/W: Open Operator Station, Auxiliary Hydraulics, Manual Coupler, 40 in Bucket, 18x8. 50x8 Tires Usage: Not Available Asset located in: Humble, TX		C/W: 2024 US EPA Label, Swing Boom, 3 ft 9 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb Usage: 1 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7790	2023 AGT R35 Mini Excavator S/N: R3523080201E C/W: Enclosed Cab, Tier 4, 2023 US EPA Label, 3 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 9 in Rubber Tracks, Manual Quick Coupler, 20 in Digging Bucket Usage: 24 Hr	7796	2024 NKL NW-16 Mini Excavator (Unused) S/N: 071232 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX
	Notes: LOCATED-IN-LIVINGSTON_LA_TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA 2024 NKL NW-18 Mini Excavator (Unused) S/N: 071243 C/W: Swing Boom, 2 ft 10 in Stick, Auxiliary	7797	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080222 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary
7791			Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in : Humble, TX
	Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: 1 Hr Asset located in : Humble, TX	7798	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080225 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber
7792	2024 AGT QK18RXS-C Mini Excavator S/N: QK18RXS-C24080201 C/W: Enclosed Cab, Air Conditioner, Swing		Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in : Humble, TX
	Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE	7799	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080223 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX
	ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	7800	2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080224 C/W: Swing Boom, 2 ft 7 in Stick, Auxiliary
7793	2024 AGT QK18RXS-C Mini Excavator S/N: QK18RXS-C24080203 C/W: Enclosed Cab, Air Conditioner, Swing Boom, 2 ft 7 in Stick, Auxiliary Hydraulic		Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX
	Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available		2024 NKL NW-16 Mini Excavator (Unused) S/N: 24080221 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7802	2024 NKL NW-16 Mini Excavator (Unused)
7794	2024 AGT QK18K-C Mini Excavator (Unused) S/N: QK18K-C2408020002 C/W: THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT	Plumbing, Backfill Blade, 7 16 in Digging Bucket, Hydrogage: Not Available Asset located in: Humble, 7803 2024 AGT QK16R Mini Exc S/N: QK16R20240802000 C/W: 2 ft 7 in Stick, Auxilia Plumbing, Backfill Blade, 7 17 in Digging Bucket, Hydrogament BROCHURE IMAGES SHOWN ILLUSTRATION PURPOSE NOT BE AN EXACT REPRE ACTUAL PRODUCT. THIS MULTIPLE COLOR VARIAT ADDITONAL IMAGES OF EUsage: Not Available	C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb
	COMES IN MULTIPLE COLOR VARIATIONS AND CAB CONFIGURATION PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE. Usage: Not Available Asset located in: Humble, TX		2024 AGT QK16R Mini Excavator (Unused) S/N: QK16R202408020005 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb, THE
7795	2024 AGT NT18K Mini Excavator (Unused) S/N: NT18K2024J0716042 C/W: Swing Boom, 3 ft 2 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7804	2024 AGT QK16R Mini Excavator (Unused) S/N: QK16R202408020006 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Hydraulic Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	7810	2024 AGT H15 Mini Excavator (Unused) S/N: H1520240730000011 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
7805	2024 FF Industrial FF-15 Mini Excavator	7811	2024 AGT H15 Mini Excavator (Unused)
	(Unused) S/N: 423119331 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		S/N: H1520240730000002 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE
7806	2024 FF Industrial FF-15 Mini Excavator (Unused)		ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	S/N: 423032738 C/W: Straight Travel Pedal, Tier 2, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available	7812	2024 AGT H15 Mini Excavator (Unused) S/N: H15202404200000024 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb
7807	Asset located in: Humble, TX 2024 FF Industrial FF-15 Mini Excavator	-	Usage: Not Available Asset located in: Humble, TX
,007	(Unused) S/N: 423069507 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7813	2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000261 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX
7808	2024 FF Industrial FF-15 Mini Excavator	7814	2024 AGT MX15R Mini Excavator (Unused)
7000	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423069483 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb		S/N: MX15R202407000251 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	7815	2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000260
7809	2024 FF Industrial FF-15 Mini Excavator (Unused) S/N: 423032740 C/W: Straight Travel Pedal, 2024 US EPA Label, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 14 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX
		7816	2024 AGT MX15R Mini Excavator (Unused) S/N: MX15R202407000249 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7817	2024 AGT LS15R Mini Excavator (Unused) S/N: LS15R202407270166 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7825	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423105531 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available
7818	2024 AGT LS15R Mini Excavator (Unused)		Asset located in: Humble, TX
7819	S/N: LS15R202408010177 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 Machpro MP15 Mini Excavator	7826	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423123895 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available
7019	S/N: SLP2415150202		Asset located in: Humble, TX
	C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX 2024 NKL NW-13Q Mini Excavator Mini	7827	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423119139 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb
	Excavator (Unused)		Usage: 9 Hr
	S/N: 071230 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic	7020	Asset located in: Humble, TX
	Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7828	2024 AGT H13R Mini Excavator (Unused) S/N: H13R20240703C0582 C/W: Enclosed Cab, 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb,
7821	2024 NKL NW-13Q Mini Excavator (Unused) S/N: 24080220 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		THE BROCHURĒ ĪMĀGES SHOWN ILLUSTRATION PURPOSES ONLY NOT BE AN EXACT REPRESENTA ACTUAL PRODUCT. THIS PRODU- MULTIPLE COLOR VARIATIONS F ADDITONAL IMAGES OF EXACT N Usage: Not Available
7000	<u> </u>	-	Asset located in: Humble, TX
7822	2024 NKL NW-13Q Mini Excavator (Unused) S/N: 24080211 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: 3 Hr Asset located in: Humble, TX	7829	2024 AGT H13R Mini Excavator (Unused) S/N: H13R20240727V0411 C/W: Enclosed Cab, 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE
7823	2024 NKL NW-13Q Mini Excavator (Unused) S/N: 24080213 C/W: 2 ft 8 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available		ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	7830	2024 AGT QH13R Mini Excavator (Unused)
7824	2024 FF Industrial FF-13 Mini Excavator (Unused) S/N: 423119602 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		S/N: QH13R202408020052 C/W: Enclosed Cab, 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7831	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423050594 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7837	2024 AGT H12R Mini Excavator (Unused) S/N: H12R20240730Q0495 C/W: 31 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN	
7832	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423050617 C/W: 2 for 7 in Stick, Auxiliary Hydraulic		MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	
	Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in : Humble, TX		2024 AGT H12R Mini Excavator (Unused) S/N: H12R20240727M0430 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks,	
7833	2024 FF Industrial FF-12 Mini Excavator (Unused) S/N: 423050585 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX		16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available	
7834	2024 FF Industrial FF-12 Mini Excavator	7000	Asset located in: Humble, TX	
	(Unused) S/N: 423111877 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7839	2024 AGT QH12R Mini Excavator (Unused) S/N: QH12R202407300027 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN	
7835	2024 AGT H12R Mini Excavator (Unused) S/N: H12R2024D07030007 C/W: 31 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in		MULTIPLE COLOR VARIATIONS PLEASE S ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available	MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE
	Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX		2024 AGT QH12R Mini Excavator (Unused) S/N: QH12R202408030024 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE	
7836	2024 AGT H12R Mini Excavator (Unused) S/N: H12R2024D07030001 C/W: 31 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in		ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	
	Digging Bucket, Manual Thumb, THE	7841	2024 AGT DM12-C Mini Excavator (Unused) S/N: DM12C202405N000047 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Hydraulic Thumb Usage: 2 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7842	2024 AGT MX12R Mini Excavator (Unused) S/N: MX12R202407000039 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7848	2013 Moffett P6000 6000 lb 3x3 Truck Mounted Forklift S/N: M130299 C/W: 3 Stage Mast, 120 in Max Lift Height, 78 in Lowered Mast Height, 74 in Forks, Side Shift Fork Rotation, Kubota V2203-M-ET02 35.9 kW 2.2 L Diesel Engine
7843	2024 AGT MX12R Mini Excavator (Unused) S/N: MX12R2024J0000039 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available		Usage: 345 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Yale GDP170VXNJUV156 16150 lb Pneumatic Tire Forklift
7844	Asset located in: Humble, TX 2024 AGT MX12R Mini Excavator (Unused) S/N: MX12R2024J0000043 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available		S/N: B909V01509L C/W: 2 Stage Mast, 219.1 in Max Lift Height, 155 in Lowered Mast Height, 97 in Forks, Fork Positioner, GM Vortec 8 Cylinder 5.7 L LPG Engine Usage: 12,355 Hr Asset located in: Humble, TX
7845	Asset located in: Humble, TX 2024 AGT L12R Mini Excavator (Unused) S/N: L12R2024071900555 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX	7852	2006 Cat DP50K 11000 lb Pneumatic Tire Forklift S/N: AT28B51437 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 93 in Lowered Mast Height, 84 in Forks, Side Shift Usage: 14,325 Hr Asset located in: Humble, TX
		7853	Cat Pneumatic Tire Forklift S/N: Not Available C/W: 2 Stage Mast, 54 in Forks, Side Shift, 6 Cylinder Diesel Engine Usage: 5,541 Hr
7846	2024 AGT L12R Mini Excavator (Unused) S/N: L12R2024071900549 C/W: 2 ft 7 in Stick, Auxiliary Hydraulic		Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
70474	Plumbing, Backfill Blade, 7 in Rubber Tracks, 17 in Digging Bucket, Manual Thumb, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN MULTIPLE COLOR VARIATIONS PLEASE SEE ADDITONAL IMAGES OF EXACT MACHINE Usage: Not Available Asset located in: Humble, TX		2002 Toyota 7FDU45 10000 lb Pneumatic Tire Forklift S/N: 60330 C/W: 2 Stage Mast, 179 in Max Lift Height, 24 in Lowered Mast Height, 54 in Forks, Side Shift, Solid Pneumatic Tires, 2003 US EPA Label, Toyota 4.6 L Diesel Engine Usage: 2,387 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE
7847A	2016 Moffett M8 Rough Terrain Forklift S/N: P350908B Usage: Not Available		INSPECTION REPORT Asset located in: Lake Worth, TX
7847	2024 Landhero LDH-KV16 Mini Excavator (Unused) S/N: Not Available C/W: 2 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 7 in Rubber Tracks, 16 in Digging Bucket, Manual Thumb Usage: Not Available Asset located in: Humble, TX	7855	2005 Toyota 7FDU45 9500 lb Pneumatic Tire Forklift S/N: 60771 C/W: 2 Stage Mast, 179 in Max Lift Height, 120 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2005 US EPA Label, Toyota 6 Cylinder 76 hp 4.6 L Diesel Engine Usage: 21,081 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

	Details	1 0+ #	Dataila
Lot #	Details	Lot #	Details
7856	2003 Toyota 7FGCU45 8850 lb Cushion Tire Forklift S/N: 64399	7862	2014 Toyota 8FG35U 7300 lb Pneumatic Tire Forklift S/N: 10805
	C/W: 3 Stage Mast, Full Free Lift, 199 in Max Lift Height, 96 in Lowered Mast Height, 48 in Forks, Side Shift, LPG Engine Usage: 7,558 Hr		C/W: 2 Stage Mast, 159.5 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		3.6 L LPG Engine Usage: 4,269 Hr
	Asset located in: Humble, TX		Notes: LOCATED-IN-FORT-WORTH-TX
7857	2002 Hyster LP 8050 lb Pneumatic Tire Forklift	7060	Asset located in: Lake Worth, TX
	S/N: E490168 C/W: 2 Stage Mast, 122 in Max Lift Height, 85 in Lowered Mast Height, 59 in Forks, Side Shift,	7863	2002 Toyota 7FGU35 7300 lb Pneumatic Tire Forklift
	2002 US EPA Label, Vortec LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: 60406 C/W: 3 Stage Mast, Full Free Lift, 171.5 in Max Lift Height, 79 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, Vortec
	THE INSPECTION REPORT Asset located in: Humble, TX		4 Cylinder LPG Engine Usage: 1,559 Hr
7858	Clark C500-YS80 8000 lb Pneumatic Tire	1	Notes: LOCATED-IN-FORT-WORTH-TX
, 500	Forklift		Asset located in: Lake Worth, TX
	S/N: Y68500908715K0F C/W: 2 Stage Mast, 47 in Forks, 4 Cylinder LPG	7864	2018 Toyota 8FGC35U 7250 lb Cushion Tire Forklift
	Engine Usage: 7,374 Hr		S/N: 13306 C/W: 3 Stage Mast, Full Free Lift, 187 in Max
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2018 US EPA Label, Toyota
7859	Toyota 7FGU45 Pneumatic Tire Forklift	_	Cylinder 63 kW 3.68 L LPG Engine Usage: 1,843 Hr
	S/N: 72832 C/W: 3 Stage Mast, Full Free Lift, 47 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Tires, LPG Engine Usage: 7,006 Hr	7865	2015 Toyota 8FGC35U 7250 lb Cushion Tire Forklift
	Notes: LOCATED-IN-FORT-WORTH-TX		S/N: 11393 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 46 in Forks, Side Shift, 2015 US EPA Label, Toyota 4
7860	Asset located in: Lake Worth, TX 2014 Toyota 8FD35U 7700 lb Pneumatic Tire	_	
	Forklift S/N: 10677		Cylinder 3.6 L LPG Engine Usage: 1,046 Hr
	C/W: 3 Stage Mast, 187 in Max Lift Height, 90		Notes: LOCATED-IN-FORT-WORTH-TX
	in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label,		Asset located in: Lake Worth, TX
	Toyota 4 Cylinder Diesel Engine Usage: 4,359 Hr	7866	2011 Toyota 7FGCU35 7250 lb Cushion Tire Forklift
	Asset located in: Humble, TX	_	S/N: 71785
7861	2020 Cat DP40N1 7300 lb Pneumatic Tire Forklift S/N: AT12C00939 C/W: 3 Stage Mast, 187 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Fork Positioner, Solid Pneumatic Tires		C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, Toyota LPG Engine Usage: Not Available
			Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 2,367 Hr Notes : LOCATED-IN-FORT-WORTH-TX		Asset located in: Lake Worth, TX
	Asset located in: Lake Worth, TX		
	·	1	

Lot #	Details	Lot #	Details
7867	2009 Toyota 7FGCU35 7250 lb Pneumatic Tire Forklift S/N: 71074 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 46 in Forks, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: 1,241 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	7872 7873	2019 Hyundai 35D-9 6790 lb Cushion Tire Forklift S/N: HHKHHN44LK0000317 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 88 in Lowered Mast Height, 41 in Forks, Side Shift, Fork Positioner, Tier 4, 2019 US EPA Label, Kubota V3307 4 Cylinder 49.3 kW 3.3 L Diesel Engine Usage: 5,929 Hr Asset located in: Humble, TX 2007 Komatsu FG15HT-20 6650 lb Pneumatic
7868	2017 Toyota 8FD35U 7000 lb Pneumatic Tire Forklift S/N: 11945 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 87 in Lowered Mast Height, 48 in Forks, Side Shift, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4 Cylinder 2.9 L Diesel Engine Usage: 3,989 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7874	Tire Forklift S/N: 675065A C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 2007 US EPA Label, Nissan 2.1 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7869	2015 Toyota 8FG35U 7000 lb Pneumatic Tire Forklift S/N: 11051 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 44 in Forks, Side Shift, Solid Pneumatic Tires, 2015 US EPA Label, Toyota 4 Cylinder 63 kW 3.6 L LPG Engine Usage: 2,231 Hr Notes: LOCATED-IN-FORT-WORTH-TX	7875	2017 Goodsense FY30 6615 lb Pneumatic Tire Forklift S/N: 216015752 C/W: 3 Stage Mast, 189 in Max Lift Height, 88 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2016 US EPA Label, 4 Cylinder 2.5 L LPG Engine Usage: 3,283 Hr Asset located in: Humble, TX 2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused)
7870	Asset located in: Lake Worth, TX 2011 Toyota 7FGCU35 7000 lb Cushion Tire Forklift S/N: 71744 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 60 in Forks, Side Shift, Toyota LPG Engine Usage: 1,195 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: 23L3001155 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 1 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2024 Viper FY30T 6600 lb Pneumatic Tire
7871	2006 Toyota 7FGU35 7000 lb Pneumatic Tire Forklift S/N: 7FGU35-62055 C/W: 2 Stage Mast, 187 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, Tier 2, 2007 US EPA Label, 4 Cylinder 4.3 L Diesel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX		Forklift (Unused) S/N: 23L3001156 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 1 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7877	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3000559 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, LPG Engine Usage: 3 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7884	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift S/N: 69982 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 86 in Lowered Mast Height, 48 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 42 kW 2.23 L LPG Engine Usage: 1,513 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7878	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift S/N: 23L3001153 C/W: 3 Stage Mast, Full Free Lift, 188 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 69 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7885	Toyota 8FDU30 5620 lb Pneumatic Tire Forklift S/N: C1761 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 89 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Solid Pneumatic Tires, 2021 US EPA Label, Toyota 3 Cylinder 1.7 L Diesel Engine Usage: 468 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX		2014 Toyota 8FDU30 5620 lb Pneumatic Tire Forklift
7879	2024 Viper FY30T 6600 lb Pneumatic Tire Forklift (Unused) S/N: 23L3000560 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 88 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 2 Hr		S/N: 60256 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 88 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 3 Cylinder 1.79 L Diesel Engine Usage: 2,130 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2024 Viper FY25BCS 5513 lb Pneumatic Tire Forklift (Unused)
7881	Asset located in: Humble, TX 1991 Hyster H60XL 6050 lb Pneumatic Tire Forklift S/N: C177B08519M C/W: 2 Stage Mast, 87 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, Isuzu 4 Cylinder Diesel Engine Usage: 7,172 Hr		S/N: 222010019 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2023 US EPA Label, 4 Cylinder LPG Engine Usage: 2 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2024 Viper FY25C 5513 lb Pneumatic Tire Forklift (Unused)
7882	Allis Chalmers ACP - 60 Pneumatic Tire Forklift S/N: AJB84020 Usage: Not Available Asset located in: Humble, TX		S/N: 222011085 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, Solid Pneumatic Tires, 2023 US EPA Label,
7883	2017 Toyota 8FGU30 5750 lb Pneumatic Tire Forklift S/N: 69999 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 86 in Lowered Mast Height, 46 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2017 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 2,661 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Kubota 4 Cylinder 2.5 L LPG Engine Usage: 2 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7889	2016 Yale GLC060VX 5500 lb Cushion Tire Forklift	7892	2020 Toyota 8FGCU32 5000 lb Cushion Tire Forklift
	S/N: C910V05302P C/W: 2 Stage Mast, Full Free Lift, 122.4 in Max Lift Height, 84 in Lowered Mast Height, 30 in Forks, Side Shift, Fork Positioner, 2016 US EPA Label, PSI 4 Cylinder 2.4 L Dual Fuel Engine Usage: 14,437 Hr		S/N: C0172 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 52 in Forks, Auxiliary Hydraulic Plumbing, 2020 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: 4,027 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7890B	2016 Doosan D30S-7 5450 lb Pneumatic Tire Forklift S/N: FDADR193001589 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 86 in Lowered Mast Height, 41 in Forks, Side Shift, Tier 4, 2016 US EPA Label, Doosan 4 Cylinder 2.4 L Diesel Engine Usage: 9,339 Hr	7893	2018 Cat GP25N Pneumatic Tire Forklift S/N: AT35A06688 C/W: 3 Stage Mast, Full Free Lift, 41 in Forks, 2018 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 3,031 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
70004	Asset located in: Humble, TX	7894	2014 Cat PD 5000 Pneumatic Tire Forklift
7890A	2011 Doosan D30S-5 5500 lb Pneumatic Tire Forklift S/N: FDA06124012246 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 85 in Lowered Mast Height, 47 in Forks, Side Shift, 2011 US EPA Label, Yanmar 4 Cylinder 3.3 L Diesel Engine Usage: 4,249 Hr		S/N: AT18C31486 C/W: 3 Stage Mast, Full Free Lift, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2013 US EPA Label, Mitsubishi 4 Cylinder Diesel Engine Usage: 2,133 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
	Asset located in: Humble, TX	7895	2004 Cat GP25K 5000 lb Pneumatic Tire Forklift
7890	2016 Yale GLC060VX 5500 lb Pneumatic Tire Forklift S/N: C910V05309P C/W: 2 Stage Mast, Full Free Lift, 122.4 in Max Lift Height, 84 in Lowered Mast Height, 30 in Forks, Side Shift, Fork Positioner, PSI 4 Cylinder 2.4 L LPG Engine Usage: 16,780 Hr		S/N: AT17B95008 C/W: 3 Stage Mast, 188 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 10,950 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7897	2012 Toyota 7FGCU35 4900 lb Pneumatic Tire Forklift
7891	2014 Toyota 8FGU30 5350 lb Pneumatic Tire Forklift S/N: 60981 C/W: 3 Stage Mast, Full Free Lift, 171 in Max Lift Height, 83 in Lowered Mast Height, Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 1,801 Hr		S/N: 72810 C/W: 4 Stage Mast, Full Free Lift, 230 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Solid Pneumatic Tires, PSI 4 Cylinder LPG Engine Usage: 9,584 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	Notes: LOCATED-IN-FORT-WORTH-TX	7898	2018 Toyota 8FGU30 4850 lb Pneumatic Tire
	Asset located in: Lake Worth, TX	1 ***	Forklift S/N: 72364 C/W: 4 Stage Mast, Full Free Lift, 240 in Max Lift Height, 84 in Lowered Mast Height, 72 in Forks, Side Shift, Fork Positioner, 2018 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 2,010 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
7899	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19411W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7905	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19410W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
7900	2022 Hyster S50FT 4800 lb Cushion Tire	7906	2022 Hyster S50FT 4650 lb Cushion Tire
	Forklift S/N: H187V19415W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Forklift S/N: H187V19419W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7901	2022 Hyster S50FT 4650 lb Cushion Tire	T	Asset located in: Humble, TX
	Forklift S/N: H187V19418W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7907	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19406W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7902	2022 Hyster S50FT 4800 lb Cushion Tire		Asset located in: Humble, TX
	Forklift S/N: H187V19408W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7908	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19414W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7903	2022 Hyster S50FT 4800 lb Cushion Tire		Asset located in: Humble, TX
	Forklift S/N: H187V19417W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7909	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19416W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7904	2022 Hyster S50FT 4650 lb Cushion Tire		Asset located in: Humble, TX
	Forklift S/N: H187V19400W C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
7910	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19401W	7916	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift S/N: AF82F42143
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine		C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.1 L LPG
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Engine Usage: 10,521 Hr Notes: DOES NOT SELL WITH LPG TANK
7011	Asset located in: Humble, TX	7017	Asset located in: Humble, TX
7911	2022 Hyster S50FT 4800 lb Cushion Tire Forklift S/N: H187V19413W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	7917	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift S/N: AF82F42126 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available
	THE INSPECTION REPORT Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7912	2022 Hyster S50FT 4800 lb Cushion Tire		Asset located in: Humble, TX
	Forklift S/N: H187V19412W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7918	2016 Mitsubishi FGC25 4750 lb Cushion Tire Forklift S/N: AF82F42142 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: 1,398 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7913	2022 Hyster S50FT 4800 lb Cushion Tire Forklift		Asset located in: Humble, TX
	S/N: H187V19409W C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7919	2020 Toyota 8FGCU30 4700 lb Cushion Tire Forklift S/N: C1939 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 24 in Lowered Mast Height, 45 in Forks, Auxiliary Hydraulic Plumbing, 2020 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine
7914	2022 Hyster S50FT 4650 lb Cushion Tire Forklift S/N: H187V19407W		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in		Asset located in: Lake Worth, TX
	Forks, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7920	2015 UniCarrier MCP1F2A25LV 4700 lb Cushion Tire Forklift S/N: 9W6588 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2014 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine
7915	2017 Yale 8FGCU25 4800 lb Pneumatic Tire		Usage: 9,482 Hr
	Forklift S/N: A390V02093R		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: 3 Stage Mast, Full Free Lift, 189 in Max		Asset located in: Humble, TX
	Lift Height, 81 in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, 2017 US EPA Label, PSI 4 Cylinder 2.4 L Dual Fuel Engine Usage: Not Available	7921	2006 Toyota 7FGCU30 Pneumatic Tire Forklift S/N: 69414 Usage: Not Available
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7922	2016 Doosan G25E5 4650 lb Pneumatic Tire Forklift S/N: FGA08179007307 C/W: 3 Stage Mast, Full Free Lift, 42 in Forks, Side Shift, Solid Pneumatic Tires, LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	7928	2006 Yale 8FGCU25 4600 lb Pneumatic Tire Forklift S/N: B875B04045D C/W: 3 Stage Mast, Full Free Lift, 194.9 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2006 US EPA Label, Mazda 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 9,086 Hr Notes: LOCATED-IN-FORT-WORTH-TX	
7923	2015 Cat DP25N Pneumatic Tire Forklift	Ī	Asset located in: Lake Worth, TX	
	S/N: AT18E00354 C/W: 3 Stage Mast, Full Free Lift, 39 in Forks, Auxiliary Hydraulic Plumbing, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: 4,932 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	7929	2006 Yale GLC050VXNVSE088 4550 lb Cushion Tire Forklift S/N: A910V06796D C/W: 3 Stage Mast, Full Free Lift, 200.8 in Max Lift Height, 86 in Lowered Mast Height, 46 in Forks, Side Shift, 2006 US EPA Label, Mazda F2-Z25D 4 Cylinder 2.2 L LPG Engine Usage: 3,322 Hr Notes: LOCATED-IN-FORT-WORTH-TX	
7924	Toyota 8FGCU25 4650 lb Cushion Tire Forklift		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	S/N: 00692 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		Asset located in: Lake Worth, TX	
	Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Fork Positioner, 2019 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 6,915 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7930	2023 Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift (Unused) S/N: 230253A2339 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine	
7925	Heli CPYD25C-KU1H 4630 lb Cushion Tire		Usage: 2 Hr	
	Forklift S/N: 230252S4149 C/W: 3 Stage Mast, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift,	7931	Asset located in: Humble, TX 2023 Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift (Unused)	
	2022 US EPA Label, Kubota 4 Cylinder 2.5 L LPG Engine Usage: 3,970 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7932	Lift Height, 84 in Lowered Mast Forks, Auxiliary Hydraulic Plumb 2022 US EPA Label, PSI 4 Cylind Engine	C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2022 US EPA Label, PSI 4 Cylinder 2.4 L LPG Engine
7926	Heli CPYD25-TY5 4630 lb Pneumatic Tire		Usage: 1 Hr	
	Forklift S/N: 230252S4148 C/W: 2 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2022 US EPA Label, Kubota WG2503-L-ET 4 Cylinder 2.5 L LPG Engine Usage: 3,770 Hr Asset located in: Humble, TX		Asset located in: Humble, TX Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift S/N: 230252S4880 C/W: 3 Stage Mast, 185 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, Mitsubishi 4 Cylinder LPG Engine Usage: 2,183 Hr	
7927	2012 Doosan G25P-5 4600 lb Pneumatic Tire Forklift S/N: FGA0B133003317 C/W: 3 Stage Mast, 186 in Max Lift Height, 47 in Forks, Side Shift, 2012 US EPA Label, Doosan G424FE 4 Cylinder 2.4 L LPG Engine Usage: 3,821 Hr Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
7933	Heli CPYD25C-M1H 4520 lb Cushion Tire Forklift S/N: 230252S4879 C/W: 3 Stage Mast, 185 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 2022 US EPA Label, Mitsubishi 4 Cylinder LPG Engine Usage: 1,844 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7938	2013 Toyota 8FGCU25 4500 lb Pneumatic Tire Forklift S/N: 48395 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 81 in Lowered Mast Height, 41 in Forks, Side Shift, Solid Pneumatic Tires, 2013 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7934	2020 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: C2963 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 47 in Forks, Side Shift, US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 11,000 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7939	2012 Toyota 8FGU25 4500 lb Cushion Tire Forklift S/N: 41900 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2012 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 3,872 Hr Asset located in: Humble, TX
7935	Asset located in: Humble, TX 2018 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 97108 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 47 in Forks, Side Shift, 2018 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available	7940	2016 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 80196 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2016 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
7006	Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	7941	2011 Toyota 8FGU25 4500 lb Pneumatic Tire Forklift S/N: 8FGU25-38751 C/W: 3 Stage Mast, Full Free Lift, 189 in Max
7936	2018 Toyota 8FGCU25 4500 lb Cushion Tire Forklift S/N: 91453 C/W: 3 Stage Mast, 189 in Max Lift Height, 24 in Lowered Mast Height, 54 in Forks, Side Shift,		Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2011 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 2,509 Hr Asset located in: Humble, TX
7937	2018 US EPA Label, Toyota itieb02 4 Cylinder 38 kW 2.2 L LPG Engine Usage: 7,967 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2013 Toyota 8FGCU25 4500 lb Cushion Tire	7942	2011 Toyota 8FGCU25 4500 lb Pneumatic Tire Forklift S/N: 35434 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine
	Forklift S/N: 48275 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in		Usage: 8,619 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Forks, Side Shift, Toyota 4YECS 38 kW 2.23 L LPG Engine Usage: 7,663 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7943	2011 Toyota 8FGCU25 4500 lb Pneumatic Tire Forklift S/N: 35829 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, Side Shift, Solid Pneumatic Tires, 2011 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 6,562 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
7944	2004 Toyota 7FGU25 4500 lb Pneumatic Tire Forklift S/N: 72662 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, 2004 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 1,672 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7951 7952	2014 Mitsubishi FGC30N Cushion Tire Forklift S/N: AF83F40074 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 46 in Forks, Auxiliary Hydraulic Plumbing, 2014 US EPA Label, GCT 4 Cylinder 2.5 L LPG Engine Usage: 13,363 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Doosan D25S-5 Pneumatic Tire Forklift	
7945	2001 Daewoo D25S-3 4500 lb Cushion Tire Forklift S/N: 9005883 C/W: 3 Stage Mast, Full Free Lift, 186 in Max Lift Height, 85 in Lowered Mast Height, 37 in Forks, Auxiliary Hydraulic Plumbing, 2001 US EPA Label, 4 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7953A	S/N: FDA05124011538 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 47 in Forks, Side Shift, Solid Pneumatic Tires, 2012 US EPA Label, Yanmar 3VNQA 4 Cylinder 3.3 L Diesel Engine Usage: Not Available Asset located in: Humble, TX Bendi B40/48IC-180D 4000 lb Cushion Tire Forklift S/N: B4048IC602B03928 C/W: 4 Stage Mast, 240 in Max Lift Height, 81	
7946	2001 Daewoo D25S-3 Pneumatic Tire Forklift S/N: 90-05883 Usage: Not Available Asset located in: Humble, TX		in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 4,703 Hr Asset located in: Humble, TX	
7948	3 2023 Heli CPQYD25-M1H 4300 lb Pneumatic Tire Forklift S/N: 250252T5743 C/W: 3 Stage Mast, Full Free Lift, 185 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Tier 4,	7953	2012 Doosan G25P-5 Pneumatic Tire Forklift S/N: FGA0B-1330-02925 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	
	2022 US EPA Label, PSI 4 Cylinder 2.4 L Dual Fuel Engine Usage: 8 Hr Asset located in : Humble, TX	7954	Forklift S/N: PJ029H3529 C/W: 3 Stage Mast, 188 in Max Lift H in Lowered Mast Height, 42 in Forks, Solid Pneumatic Tires, Nissan 4 Cylir Engine Usage: 13,012 Hr Notes: DEFICIENCIES NOTED - PLEA: THE INSPECTION REPORT Asset located in: Humble, TX 7955 2013 Toyota 8FGU25 3950 lb Pneum Forklift S/N: 47294	
7949	2015 Doosan GC25E-5 4300 lb Cushion Tire Forklift S/N: FGA0L179001438 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Auxiliary Hydraulic Plumbing, Side Shift, 2016 US EPA Label, Hyundai 4 Cylinder 48.7 kW 2.4 L Dual Fuel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX			Usage: 13,012 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Toyota 8FGU25 3950 lb Pneumatic Tire Forklift
7950	Doosan G25N7 4200 lb Pneumatic Tire Forklift S/N: FGA14-1290-00405 C/W: 2 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, Solid Pneumatic Tires, 2017 US EPA Label, GCT K25 L 4 Cylinder 2.5 L LPG Engine		in Lowered Mast Height, 42 in Forks, Side Shift, Load Weigh System, 2013 US EPA Label, Toyota 4Y ECS 4 Cylinder 2.2 L Dual Fuel Engine Usage: 1,989 Km Asset located in: Humble, TX	
	Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7956	1999 Hyster 3900 lb Pneumatic Tire Forklift S/N: D187V16183W C/W: 3 Stage Mast, 189 in Max Lift Height, 20 in Lowered Mast Height, 47 in Forks, Side Shift, LPG Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
7957	2014 Toyota 8FGU25 3750 lb Pneumatic Tire Forklift S/N: 62320 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L Dual Fuel Engine Usage: 843 Hr Asset located in: Humble, TX	7963	2018 Toyota 8FGU18 2750 lb Pneumatic Tire Forklift S/N: 65623 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2018 US EPA Label, Toyota 4YECS 4 Cylinder 2.23 L LPG Engine Usage: 11,319 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
7958	2013 Toyota 8FGU25 Pneumatic Tire Forklift		Asset located in: Humble, TX
	S/N: 50159 Usage: 2,428 Hr Asset located in : Humble, TX	7964	2003 Toyota 7FGCU20 2600 lb Cushion Tire Forklift S/N: 82748
7959	2013 Toyota 8FGU25 3750 lb Pneumatic Tire Forklift S/N: 51434 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 83 in Lowered Mast Height, 40 in Forks, Side Shift, Solid Pneumatic Tires, 2013 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine		C/W: 4 Stage Mast, Full Free Lift, 240 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2003 US EPA Label, Toyota 4 Cylinder 2.23 L LPG Engine Usage: 11,335 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: 7,579 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	7965	Clark GCS15 2450 lb Cushion Tire Forklift S/N: G12703139236K0F C/W: 3 Stage Mast, 188 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift,
7960	Asset located in: Lake Worth, TX 2016 Doosan G25P-5 3650 lb Pneumatic Tire Forklift S/N: FGA0B179004748 C/W: 3 Stage Mast, Full Free Lift, 189 in Max		4 Cylinder LPG Engine Usage: 4,699 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Lift Height, 83 in Lowered Mast Height, 48 in Forks, Solid Pneumatic Tires, Mitsubishi 4 Cylinder 2.4 L LPG Engine Usage: 5,317 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7966	2016 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 80655 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 2016 US EPA Label, Toyota
7961	2009 Toyota 8FGCSU20 3450 lb Cushion Tire Forklift S/N: 14317 C/W: 3 Stage Mast, Full Free Lift, 189 in Max	7967	4YECS 4 Cylinder 2.2 L LPG Engine Usage: 4,954 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Lift Height, 24 in Lowered Mast Height, 42 in Forks, 2009 US EPA Label, Toyota 4YECS 4 Cylinder 2.2 L LPG Engine Usage: 2,184 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2016 Toyota 8FGCU25 1700 lb Cushion Tire Forklift S/N: 80661 C/W: 4 Stage Mast, Full Free Lift, 276 in Max Lift Height, 24 in Lowered Mast Height, 42 in Forks, Side Shift, 4 Cylinder LPG Engine
7962A	<u> </u>		Usage: 4,642 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	in Lowered Mast Height, 40 in Forks, Side Shift, Tier 2, 2007 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine Usage: 11,194 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7968A	Clark CMC20S Cushion Tire Forklift S/N: D901066 C/W: 3 Stage Mast, 85 in Lowered Mast Height, Side Shift, 4 Cylinder LPG Engine Usage: 4,995 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
7968	Toyota Cushion Tire Forklift S/N: A0533576 C/W: 3 Stage Mast, Full Free Lift, 81 in Lowered Mast Height, 42 in Forks, Side Shift, 2014 US EPA Label, Toyota 4YECS 4 Cylinder 38 kW 2.23 L LPG Engine Usage: 7,072 Hr	7976	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused) S/N: 24479030 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in: Humble, TX	
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	7977B	2011 Toyota 7FBCU18 2900 lb Electric Forklift S/N: 66322	
7969	Clark C500-S80 Cushion Tire Forklift S/N: Not Available C/W: 3 Stage Mast, 41 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: 4,551 Hr Notes: LOCATED-IN-FORT-WORTH-TX	7977A	C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: 18,752 Hr Asset located in: Humble, TX 2011 Toyota 7FBCU18 2900 lb Electric Forklift	
7070	Asset located in: Lake Worth, TX Tayota FCH15 Cushing Tire Forklift	-	S/N: 66292 C/W: 3 Stage Mast, 189 in Max Lift Height, 82	
7970	Toyota FGH15 Cushion Tire Forklift S/N: Not Available C/W: 2 Stage Mast, 103 in Lowered Mast Height, 36 in Forks, 4 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX		in Lowered Mast Height, 42 in Fork 36 V Usage: Not Available Notes : DEFICIENCIES NOTED - PLI THE INSPECTION REPORT	in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
7971	2025 STL Industrial STL3NTEL 6610 lb Electric Forklift (Unused)	7977	2024 JQ POWER JQ2T-MAX 4400 lb Electric	
	S/N: 01A06250 C/W: 2 Stage Mast, 109 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 8 Hr Asset located in : Humble, TX		Forklift (Unused) S/N: 24479004 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in: Humble, TX	
7972	2025 STL Industrial STL2TN 4410 lb Electric Forklift (Unused) S/N: 01A06321 C/W: Single Stage Mast 109 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks, Side Shift Usage: 38 Hr Asset located in: Humble, TX	7978	Landoll P30 3000 lb Electric Forklift S/N: P30701A004415 C/W: 3 Stage Mast, 180 in Max Lift Height, 102 in Lowered Mast Height, Forks, 48 V, Battery Charger Usage: 1,045 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
7973	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused)		Asset located in: Humble, TX	
	S/N: 243470084 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in: Humble, TX	7979	2019 Toyota 8FBE20U 2550 lb Electric Forklift S/N: 17657 C/W: 4 Stage Mast, Full Free Lift, 240 in Max Lift Height, 83 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V, Battery Watering System Usage: 8,871 Hr	
7974	2024 JQ POWER JQ2T-MAX 4400 lb Electric Forklift (Unused)		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	S/N: 243810049 C/W: 2 Stage Mast, 120 in Max Lift Height, 82 in Lowered Mast Height, 48 in Forks Usage: 4 Km Asset located in : Humble, TX	7980	STL Industrial STL1TN 2210 lb Electric Forklift (Unused) S/N: 24A0230 C/W: 2 Stage Mast, 109 in Max Lift Height, 82	
7975	2024 JQ POWER JQ2T-MAX Electric Forklift (Unused)	1	in Lowered Mast Height, 42 in Forks, Side Shift Usage: Not Available Asset located in : Humble, TX	
	S/N: 24479003	7981	Crown Electric Forklift	
	C/W: 2 Stage Mast, 82 in Lowered Mast Height, 48 in Forks Usage: Not Available Asset located in : Humble, TX	7,301	S/N: 1A336408 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 40 in Forks, Side Shift, 36 V, Battery Charger Usage: Not Available	
			Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
7982C	Crown RC3020-40 3300 lb Electric Forklift S/N: 1A254746 C/W: 3 Stage Mast, 226 in Max Lift Height, 93 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V	7987	Vestil 3000 lb Electric Pallet Jack S/N: 0507096 Usage: Not Available Asset located in: Humble, TX	
7982A	Usage: Not Available Asset located in: Humble, TX 2007 Raymond 740R35TT 3500 lb Electric	7988B	Raymond 8210 4500 lb Electric Pallet Jack S/N: 8211613477 C/W: 4500 lb Capacity, 24 V	
7302A	Pallet Jack		Usage: Not Available Asset located in : Humble, TX	
	S/N: 74007AA07946 C/W: 3500 lb Capacity, 36 V Usage: Not Available	7988A	Raymond 112TM-FRE-60L 6000 lb Electric Pallet Jack S/N: 1120452434	
7982	Asset located in: Humble, TX Hyundai 18BRP-9 3300 lb Electric Forklift S/N: HHKHHR06VH0000046	-	C/W: 6000 lb Capacity, 24 V Usage: Not Available Asset located in: Humble, TX	
	C/W: 3 Stage Mast, 240 in Max Lift Height, 107 in Lowered Mast Height, 47 in Forks, Side Shift, 36 V Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	7989	Quantity of 3 Pallet Jack S/N: Not Available C/W: Strongway 5500 lb, EZLift 5500 lb, Roughneck Usage: Not Available Asset located in: Humble, TX	
7983	Erie Industries PHT620 Walk-Behind Electric Forklift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	7990	Boom Lift S/N: 0300210986 C/W: 135 ft Max Platform Height, 500 Weight Capacity, Jib, Extendable Axles to Platform, 2015 US EPA Label, Deutz	S/N: 0300210986 C/W: 135 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2015 US EPA Label, Deutz TCD2. 9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, IN445 /50D710 Tires Usage: 3,881 Hr
7984	Erie Industries PHT620 Walk-Behind Electric Forklift (Unused)		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	F 2016 Genie S125 4WD D Lift S/N: S12516D-1439 C/W: 125 ft Max Platforr Weight Capacity, Jib, Po US EPA Label, Deutz 4 C Diesel Engine, IN455/50 Usage: 1,958 Hr Notes: DEFICIENCIES NOTHE INSPECTION REPO Asset located in: Humble	Lift S/N: S12516D-1439 C/W: 125 ft Max Platform Height, 500 Weight Capacity, Jib, Power to Platfo US EPA Label, Deutz 4 Cylinder 55.4	S/N: S12516D-1439 C/W: 125 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Deutz 4 Cylinder 55.4 kW 2.9 L Diesel Engine, IN455/50D710 Tires
7985A	Toyota 7HBW23 4500 lb Electric Pallet Jack S/N: 7HBW2335357 C/W: 4500 lb Capacity, 24 V		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	Usage: Not Available Asset located in : Humble, TX		2015 JLG 860SJ 4WD Diesel Telescopic Boom	
7985	Erie Industries PHT620 Walk-Behind Electric Forklift (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		Lift S/N: 0300207789 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2015 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 15-625 Tires Usage: 2,277 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
7986	Crown WP3035-45 4500 lb Electric Pallet Jack S/N: 10131651 C/W: 4500 lb Capacity, 24 V Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX			

Lot #	Details	Lot #	Details
7994	2015 Snorkel TB-86J 4WD Diesel Telescopic Boom Lift S/N: TB86J04000026 C/W: 86 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, Kubota 4 Cylinder Diesel Engine, 15-625 Tires Usage: 1,410 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8001	2015 Snorkel TB-66J 4WD Diesel Telescopic Boom Lift S/N: TB66J-04-000192 C/W: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Kubota 4 Cylinder Diesel Engine, 15-19.5 Tires Usage: 4,444 Hr Asset located in: Humble, TX 2015 Skyjack SJ66T 4WD Diesel Telescopic
7995	2014 Genie S85 4WD Diesel Telescopic Boom Lift S/N: S8514-11198 C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2013 US EPA Label, Deutz TD2011L04I 4 Cylinder 74 hp 3.6 L Diesel Engine, 18-625 Tires Usage: 3,259 Hr	8003	Boom Lift S/N: 97001313 C/W: 66 ft Max Lift Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz 2.9L4 4 Cylinder 2.9 L Diesel Engine, 385/65D19.5 Tires Usage: 4,329 Hr Asset located in: Humble, TX 2013 Skyjack SJ66T 4WD Diesel Telescopic
7996	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2016 JLG 800S 4WD Diesel Telescopic Boom Lift S/N: 0300204001 C/W: 80 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz 4 Cylinder 67 hp 2.9 L Diesel Engine, 15-625NHS Tires Usage: 2,471 Hr		Boom Lift S/N: 97000552 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 20' US EPA Label, Deutz 4 Cylinder 3.6 L Diesel Engine, 365/65D19.5 Tires Usage: 3,112 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	8004	Asset located in: Humble, TX 2006 JLG 660SJ 4WD Diesel Telescopic Boon Lift - Factory Reconditioned 2019 S/N: 030099927 C/W: 66 ft Max Platform Height, 500 lb Max
7997	2016 Genie Z-80/60 4WD Diesel Articulating Boom Lift S/N: Z80165809 C/W: 78 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2015 US EPA Label, Deutz	8005	Weight Capacity, Jib, Power to Platform, Onboard Generator, 2008 US EPA Label, Deutz F4M2011 4 Cylinder 65 hp 3.1 L Diesel Engine, 15-19.5NHS Tires Usage: 666 Hr Asset located in: Humble, TX
	TD2.9L4 4 Cylinder 74 hp 2.9 L Diesel Engine, 18-625 NHS Tires Usage: 2,501 Hr Asset located in : Humble, TX		2017 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S60H40279 C/W: 65 ft Max Platform Height, 500 lb Max
7998	2014 Genie S-80X Telescopic Boom Lift S/N: S80X14-11199 Usage: Not Available Asset located in: Humble, TX		Weight Capacity, Jib, Power to Platforn US EPA Label, Deutz d2.9L4 4 Cylinder 2.9 L Diesel Engine, 355/55D625NHS T Usage: 3,012 Hr
8000	2015 Haulotte HT67RTJ 4WD Diesel Telescopic Boom Lift S/N: TD500110 C/W: 67 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Kubota V2403-M-ET02e 4 Cylinder 36.5 kW 2.4 L Diesel Engine, 385/65-22.5 NHS Tires Usage: 3,641 Hr Asset located in : Humble, TX	8006	Asset located in: Lake Worth, TX 2019 Genie S-65XC 4WD Diesel Telescopic Boom Lift S/N: S65XCH-45403 C/W: 65 ft Max Platform Height, 1000 lb Max Weight Capacity, Jib, Power to Platform, 2019 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355/55D625 Tires Usage: 372 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8007	2014 Genie S-65 4WD Diesel Telescopic Boom Lift S/N: S601427122 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2013 US EPA Label, Deutz 4 Cylinder 49 hp 2.9 L Diesel Engine, 355/55D Tires Usage: 5,068 Hr Asset located in: Humble, TX 2015 Skyjack SJ61T 4WD Diesel Telescopic	8013	2015 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300203642 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2015 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39x15- 22.5 NHS Tires Usage: 5,398 Hr Asset located in: Humble, TX
8009	Boom Lift S/N: 97001310 C/W: 61 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 15x19.5 NHS Tires Usage: 3,275 Hr Asset located in: Humble, TX 2015 Genie S60X 4WD Diesel Telescopic Boom	8014	2014 JLG 600S 4WD Gasoline Telescopic Boom Lift S/N: 0300191782 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Power Solutions International 4 Cylinder 3.0 L Gasoline Engine, 355/55D625 Tires Usage: 2,408 Hr
	Lift S/N: S60X15A-30386 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L Diesel Engine, 355/55D625 NHS Tires Usage: 5,608 Hr Asset located in: Humble, TX	8015	Asset located in: Humble, TX 2014 JLG 600S 4WD Gasoline Telescopic Boom Lift S/N: 0300190988 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, PSI 4 Cylinder 3.0 L Gasoline Engine, 39x15-22.5 Tires Usage: 4,237 Hr
8010	2015 Genie S60X 4WD Diesel Telescopic Boom		Asset located in: Humble, TX
	Lift S/N: S60X15A-30646 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D 2.9 L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 355-55D/625 Tires Usage: 4,366 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8016	2014 JLG 600A 4WD Diesel Telescopic Boom Lift S/N: 300188438 C/W: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, CARB Compliant, Deutz TD 2.9 L4 4 Cylinder 50 kW 2.9 L Diesel Engine, 355 /55D625 NHS Tires Usage: 2,815 Hr Asset located in: Humble, TX
8011	2008 Genie S60 4WD Diesel Telescopic Boom Lift S/N: S600817791 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2007 US EPA Label, Deutz D 2011 L 03 1 3 Cylinder 2.3 L Diesel Engine, 355/55D625 NHS Tires Usage: 5,110 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Genie S60 4WD Diesel Telescopic Boom	8018	2013 JLG 600S 4WD Diesel Telescopic Boom Lift S/N: 0300170418 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2013 US EPA Label, Deutz D2011L04 4 Cylinder 40 hp Diesel Engine, 39X15-22.5 Tires Usage: 4,559 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Lift S/N: S600715807 C/W: 60.2 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2004 US EPA Label, Deutz 3 Cylinder Diesel Engine, 355/55D625 Tires Usage: 2,227 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8019	2006 Snorkel TB-60 4WD Diesel Telescopic Boom Lift S/N: JL06018RBLT C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 15-19.5 Tires, EQUIPMENT-FROM-UNITED-RENTALS Usage: 6,546 Hr Notes: LOCATED-IN-FORT-WORTH-TX AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND; EQUIPMENT FROM UNITED RENTALS Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8020	2018 JLG 460SJ 4WD Diesel Telescopic Boom Lift S/N: 0300240143 C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Deutz D2.9L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5NHS Tires Usage: 2,792 Hr Asset located in: Humble, TX 2018 JLG 460SJ 4WD Diesel Telescopic Boom Lift	8027	2014 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300186158 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 33/16LLx16. 1 Tires Usage: 821 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 0300240471		Asset located in: Humble, TX
	C/W: 46 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 NHS Tires Usage: 1,716 Hr Asset located in: Humble, TX	8028	2007 JLG 400S 4WD Diesel Telescopic Boom Lift - Factory Reconditioned 2018 S/N: 0300114482 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard
8022	2017 JLG 460SJ 4WD Diesel Telescopic Boom		Generator, Deutz 3 Cylinder 48 hp 2.3 L Diesel Engine, 12-16.5 Tires
	Lift S/N: 0300235958		Usage: 2,097 Hr
	C/W: 46 ft Max Platform Height, 600 lb Max	8020	Asset located in: Humble, TX 2007 JLG 400S 4WD Diesel Telescopic Boom
	Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz D 2.9 L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 NHS Tires Usage: 3,313 Hr Asset located in: Humble, TX	8029	Lift - Factory Reconditioned 2018 S/N: 0300121542 C/W: 40 ft Max Lift Height, 500 lb Max Weight Capacity, Power to Platform, Onboard Generator, US EPA Label, Deutz 4 Cylinder 36.5
8023	2016 Skyjack SJ45T Telescopic Boom Lift S/N: 98001773 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity	8030	kW 2.3 L Diesel Engine, 12-16.5 Tires Usage: 1,183 Hr Asset located in: Humble, TX
	Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2006 JLG 400S 4WD Diesel Telescopic Boom Lift - Factory Reconditioned 2018 S/N: 0300103683
8025	2015 Genie S45 4WD Diesel Telescopic Boom Lift S/N: S4515-21167 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2014 US EPA Label, Deutz		C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2008 US EPA Label, Deutz F3M2011 3 Cylinder 48 hp 2.3 L Diesel Engine, 12-16.5 Tires Usage: 887 Hr Asset located in: Humble, TX
	D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, 12- 16.5 Foam-Filled Tires Usage: 4,235 Hr	8031	2006 JLG 400S 4WD Diesel Telescopic Boom Lift
	Asset located in: Humble, TX	_	S/N: 0300102015 C/W: 40 ft Max Platform Height, 100 lb Max
8026	2019 JLG 400S 4WD Diesel Telescopic Boom Lift S/N: 0300262629 C/W: 40 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, 2019 US		Weight Capacity, Power to Platform, 2008 US EPA Label, Deutz 4 Cylinder 36.5 kW 2.3 L Diesel Engine, 12-16.5 Tires Usage: 1,608 Hr Asset located in: Humble, TX
	EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 Tires Usage: 1,729 Hr Asset located in : Humble, TX	8032	2015 Genie S40 4WD Diesel Telescopic Boom Lift S/N: S4015-20965 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2014 US EPA Label, Deutz D 2.9L4 4 Cylinder 2.9 L Diesel Engine, 12-16.5 NHS Foam-Filled Tires Usage: 4,678 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8033	2007 Genie S40 4WD Diesel Telescopic Boom Lift S/N: S4007-11887 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Deutz 3 Cylinder 48 hp 2.3 L Diesel Engine, 12-16.5 Tires Usage: 5,665 Hr Asset located in: Humble, TX	8042	2015 Genie Z62-40 4WD Diesel Articulating Boom Lift S/N: Z6215A-285 C/W: 61.11 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2014 US EPA Label, Deutz D2.9 L4 4 Cylinder 49 hp Diesel Engine, 355/55D625 Tires Usage: 2,965 Hr Asset located in: Humble, TX
8034	Nifty-Lift SD34DE 4WD Diesel Articulating	8043	2017 Haulotte HA61 RTJPRO 4WD Diesel
	Boom Lift S/N: 0428344 C/W: 34 ft Max Platform Height, 500 lb Max Weight Capacity, 3 Cylinder Diesel Engine, 26x12-16.5 NHS Tires Usage: Not Available Asset located in: Humble, TX		Articulating Boom Lift S/N: 2018200 C/W: 61 ft Max Platform Height, 507 lb Max Weight Capacity, Jib, Power to Platform, 2021 US EPA Label, Kubota 4 Cylinder 36 kW 2.4 L Diesel Engine, Aperture Tires Usage: 2,736 Hr Notes: LOCATED-IN-FORT-WORTH-TX
8035	2014 Genie ZX-135 4WD Diesel Articulating Boom Lift		Asset located in: Lake Worth, TX
	S/N: ZX135142503 C/W: 135 ft Max Platform Height, 600 lb Max Weight Capacity, Jib, Extendable Axles, Power to Platform, 2012 US EPA Label, CARB Compliant, Deutz TD 2011 L04 3 Cylinder 55 kW 3.6 L Diesel Engine, 445/50D710 Tires Usage: 3,109 Hr Asset located in: Humble, TX	8044	2017 Haulotte HA61 RTJPRO 4WD Diesel Articulating Boom Lift S/N: 2018446 C/W: 61 ft Max Platform Height, 507 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, Kubota V2403 4 Cylinder 2.4 L Diesel Engine Usage: 1,402 Hr
8038	2018 JLG 800 AJ 4WD Diesel Articulating		Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE
	Boom Lift S/N: 0300239892		INSPECTION REPORT
	C/W: 80 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017	9045	Asset located in: Lake Worth, TX
8039	US EPA Label, Deutz 4 Cylinder Diesel Engine, 15-625 Tires Usage: 3,201 Hr Asset located in: Humble, TX 2013 JLG 800 AJ 4WD Diesel Articulating	8045	2020 MEC 60-J 4WD Diesel Articulating Boom Lift S/N: 14400498 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Kubota V105-T-ET03 4 Cylinder 33
0039	Boom Lift		kW 1.5 L Diesel Engine, 315/55D20 Tires Usage: 3,295 Hr
	S/N: 0300175680 C/W: 80 ft Max Platform Height, 500 lb Max		Asset located in: Humble, TX
	Weight Capacity, Jib, Power to Platform, 2013 US EPA Label, Deutz D2011L04 4 Cylinder 62 hp Diesel Engine, 445/55D19.5 Tires Usage: 4,252 Hr Asset located in: Humble, TX		2019 MEC 60-J 4WD Diesel Articulating Boom Lift S/N: 14400451 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2018
8040	2014 Genie Z80/60 Articulating Boom Lift S/N: Z8014-5192 Usage: 4,998 Hr Asset located in: Humble, TX		US EPA Label, Kubota V1505-T-ET03 4 Cylinder 33 kW 1.5 L Diesel Engine, 315/55D20 Tires Usage: 3,451 Hr Asset located in: Humble, TX
8041	2013 Genie Z-80 4WD Diesel Articulating Boom	8047	2019 MEC 60-J 4WD Diesel Articulating Boom
UU 4 I	Lift S/N: Z8013-3945 C/W: 78 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz TD2011L04I 4 Cylinder 3.61 L Diesel Engine, 18-625 Tires Usage: 4,736 Hr		Lift S/N: 800242718 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, US EPA Label, Kubota V1505-T-ET03 4 Cylinder 33 kW 1.5 L Diesel Engine, 315/55D20 Tires Usage: 3,802 Hr Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8048	2019 MEC 60J-D Articulating Boom Lift
	Asset located in: Humble, TX		S/N: 14400451D Usage: 3,165 Hr

Lot #	Details	Lot #	Details
8049	2019 MEC 60J-D Articulating Boom Lift S/N: 14400421 Usage: 3,313 Hr Asset located in: Humble, TX	8056	2016 JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300220868 C/W: 45 ft Max Platform Height, 550 lb Max Weight Capacity, 2016 US EPA Label, Deutz D2 9L4 4 Cylinder 2.9 L Diesel Engine, 33x15.50- 16.5 Tires Usage: 2,305 Hr Asset located in: Humble, TX
8050	2012 JLG 600AJ 4WD Diesel Articulating Boom Lift S/N: 0300155087 C/W: 60 ft Max Platform Height, Jib, 2011 US EPA Label, Deutz 4 Cylinder Diesel Engine, 355 /55D625 Tires Usage: 4,548 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		
		8057	2015 JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300201471 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2014
8051	2018 Haulotte HA46 RTJO Articulating Boom Lift S/N: 2047881 Usage: Not Available Asset located in: Humble, TX		US EPA Label, Deutz D 2.9L4 4 Cylinder 2.9 L Diesel Engine, 33x15.5-16.5 NHS Tires Usage: 2,047 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8052	2016 Haulotte HA46 RTJO 4WD Diesel Articulating Boom Lift S/N: 2009339 C/W: 46 ft Max Platform Height, 507 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505-Ef01 4 Cylinder 18.5 kW 1.5 L Diesel Engine, 85x340 Aperture Tires Usage: 1,776 Hr Asset located in: Humble, TX	8058	2008 JLG 450AJ 4WD Diesel Articulating Boom Lift S/N: 0300125307 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2007 US EPA Label, Deutz D2011L03 3 Cylinder 49 hp 2.3 L Diesel Engine, 12-16.5 NHS Tires Usage: 1,727 Hr Asset located in: Humble, TX JLG 450AJ Series II 4WD Diesel Articulating
8053	2016 Snorkel A46JRT 4WD Diesel Articulating Boom Lift S/N: A46JRT-04-000306 C/W: 46 ft Max Platform Height, 550 lb Max Weight Capacity, Jib, Power to Platform, Tier 4, 2015 US EPA Label, Kubota V1505 3 Cylinder Diesel Engine, 355/55D625 Tires Usage: 1,981 Hr Asset located in: Humble, TX	8059	Boom Lift S/N: Not Available C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz F3M1011F 3 Cylinder 47 hp 2.1 L Diesel Engine, 33x15.50-16.5 NHS Tires Usage: 4,038 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8054	2012 Skyjack SJ46AJ 4WD Diesel Articulating Boom Lift S/N: 95000382 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz 3 Cylinder 49 hp 2.3 L Diesel Engine, 315-55D20 Tires Usage: 1,657 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	8060	Asset located in: Humble, TX 2020 Genie Z45/25 2WD Electric Articulating Boom Lift S/N: Z4525F61230 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 9-14.5 Tires Usage: 413 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Genie Z-45/25J 4WD Diesel Articulating
8055	2017 JLG 450AJ Series II 4WD Diesel Articulating Boom Lift S/N: 0300228058 C/W: 45 ft Max Platform Height, 550 lb Max Weight Capacity, Jib, 2016 US EPA Label, CARB Compliant, Deutz D 2.9 L4 4 Cylinder 49 hp Diesel Engine, 12-16.5NHS Tires Usage: Not Available Asset located in: Humble, TX	0001	Boom Lift S/N: Z4525N-58205 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz 4 Cylinder 36.4 kW 2.9 L Diesel Engine, 315//55D20 Tires Usage: 1,346 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8062	2012 Genie Z45/25 4WD Diesel Articulating Boom Lift S/N: Z452512A044282 C/W: 46 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2012 US EPA Label, Deutz D2011L03 3 Cylinder 36.3 kW 2.3 L Diesel Engine, 355/55D625 NHS Tires Usage: 1,866 Hr Asset located in: Humble, TX 2005 Genie Z45/25 4WD Diesel Articulating	8069	2014 Genie Z40/23NRJ 2WD Electric Articulating Boom Lift S/N: Z40N14-2422 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22x7x17 3/4 Tires Usage: 1,492 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Boom Lift S/N: Z45250525763 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2011 US EPA Label, Deutz F3L2011 3 Cylinder Diesel Engine, 355/55D625 Tires Usage: 4,087 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8070 8071	2015 Genie Z34/22N Articulating Boom Lift S/N: Z34N15-12305 Usage: 689 Hr Asset located in: Humble, TX 2019 Genie Z-30/20N RJ 2WD Electric Articulating Boom Lift S/N: Z30NF-21178 C/W: 29.2 ft Max Platform Height, 500 lb Max
8064	Asset located in: Humble, TX 2002 Genie Z45/25 4WD Dual Fuel Articulating Boom Lift S/N: Z452519952	-	Weight Capacity, Jib, Power to Platform, 22/7 /17.75 Solid Tires Usage: 289 Hr Asset located in : Humble, TX
	C/W: 45.6 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Dual Fuel Engine, 14-175 Tires Usage: 2,988 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8072	2013 Genie Z-30/20NRJ 2WD Electric Articulating Boom Lift S/N: Z30N13-14418 C/W: 30 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 22X7 Tires Usage: 803 Hr Asset located in: Humble, TX
8065	2021 Genie Z45 4WD Electric Articulating Boom Lift S/N: Z45EM507 C/W: 45 ft Max Platform Height, 662 lb Max Weight Capacity, Jib, Power to Platform, 315 /55D20 Tires Usage: 8,916 Hr Asset located in: Humble, TX	8073	2013 Genie TZ-34/20 Towable Lift S/N: TZ3413603 C/W: 34 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8066	2015 Genie Z45/25DC Articulating Boom Lift S/N: Z452515D-448 Usage: 619 Hr Asset located in: Humble, TX	8075	2012 Genie GS-5390RT 4x4 Diesel Scissor Lift S/N: GS9012-47932 C/W: 53 ft Max Platform Height, 1500 lb Max
8067	2014 JLG E450AJ 2WD Electric Articulating Boom Lift S/N: 0300193405 C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 240 /55 Tires	8076	Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Stabilizers, Upper Control Box, 2011 US EPA Label, CARB Compliant, Deutz D2011 L 03 3 Cylinder 36.3 kW 2.3 L Diesel Engine Usage: 1,112 Hr Asset located in: Humble, TX
	Usage: 666 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		2014 Genie GS4390 Diesel Scissor Lift S/N: GS901450021 C/W: 43 ft Max Platform Height, 1500 lb Max
8068	2017 JLG E400AJP 2WD Electric Articulating Boom Lift S/N: 0300224995 C/W: 40 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 25x12 Solid Tires Usage: 615 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Weight Capacity, Platform Extension, Power Platform, Foam Filled Tires, Upper Control E 2014 US EPA Label, Deutz D2.9L4 4 Cylinde 49 hp 2.9 L Diesel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8078	2016 Genie GS4069RT Diesel Scissor Lift S/N: GS6916F9232 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Tier 4, 2015 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine Usage: 1,945 Hr Notes: AERIAL UNITS REQUIRE PROPER SAFETY HARNESS, LANYARD, AND PPE TO FUNCTION TEST AND LOAD Asset located in: Humble, TX	8084	2015 Haulotte Compact 3347E Electric Scissor Lift S/N: Not Available C/W: 33 ft Max Platform Height, 660 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8079	2018 Skyjack SJ6826 RT 4x4 Diesel Scissor Lift S/N: 37011905 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Tier 4, 2017 US EPA Label, Kubota D902-EF01 3 Cylinder 18.5 kW 0.89 L Diesel Engine Usage: 670 Hr	8085	2014 JLG 3248RS Electric Scissor Lift S/N: 200234867 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 470 Hr Asset located in: Humble, TX 2015 JLG 3248RS Electric Scissor Lift
8080	Asset located in: Humble, TX 2017 Skyjack SJ6826 RT 4x4 Diesel Scissor Lift S/N: 37010650 C/W: 26 ft Max Platform Height, 1250 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D902- EF01 3 Cylinder 18.5 kW 0.8 L Diesel Engine		S/N: 200237806 C/W: 32 ft Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 618 Hr Asset located in : Humble, TX
	Usage: 463 Hr Asset located in: Humble, TX	8087	2019 Skyjack SJ4632 Electric Scissor Lift S/N: 70041183
8081	2014 JLG M4069LE Electric Scissor Lift S/N: 200231456 C/W: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 377 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Weight Capacity, Platform Extens Platform, Stabilizers, Solid Non-N Upper Control Box Usage: 174 Hr Notes: LOCATED-IN-FORT-WORT
	Asset located in: Humble, TX	8088	Skyjack SJ4632 Electric Scissor Lift
8082A	2016 Genie GS-4047 Scissor Lift S/N: GS4716D-1548 Usage: 539 Hr Asset located in: Humble, TX		S/N: Not Available C/W: 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Ticks, Upper Control Box
8082	2016 Genie GS-4047 4x4 Electric Scissor Lift S/N: GS4716D1548 C/W: 40 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	8089	Usage: 296 Hr Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	Control Box Usage: 556 Hr Asset located in: Humble, TX		Skyjack Electric Scissor Lift S/N: Not Available C/W: Platform Extension, Power to Platform,
8083	2024 STL Industrial STLSL40 Electric Scissor Lift (Unused) S/N: WT20240809QJ05 C/W: 39 ft 6 in Max Platform Height, 705 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX		Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8090	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266200 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box	8096	2017 Genie GS3246 Electric Scissor Lift S/N: GS46P-144334 C/W: Platform Extension, Power to Platform, Upper Control Box Usage: 414 Hr Asset located in: Humble, TX
	Usage: 270 Hr Asset located in : Humble, TX	8097	2016 Genie GS3246 Electric Scissor Lift
8091	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266196 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 405 Hr		S/N: GS4616P139198 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2015 Genie GS3246 Electric Scissor Lift
8092	Asset located in: Humble, TX 2017 JLG 3246ES Electric Scissor Lift S/N: 0200266191 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box	8098	S/N: GS4615A-137246 C/W: 32 ft Max Platform Height, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in : Humble, TX
	Usage: 213 Hr Asset located in: Humble, TX	8099A 8099	2015 Genie GS-3246 4x4 Electric Scissor Lift S/N: GS4615A-137552
8093	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266197 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		C/W: 32 ft Max Platform Height, 700 kg Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 604 Hr Asset located in : Humble, TX
	Control Box Usage: 367 Hr Asset located in : Humble, TX		2015 Genie GS3246 Electric Scissor Lift S/N: GS4615A-137574 C/W: 32 ft Max Platform Height, 700 lb Max
8094	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266185 C/W: 31.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 338 Hr		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 594 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	8100	2014 Genie GS3246 Electric Scissor Lift
8095A	2018 Genie GS3246 Electric Scissor Lift S/N: GS46P-147121 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 78 Hr	_ 8100	S/N: 116551 C/W: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 234 Hr Asset located in : Humble, TX
	Asset located in: Humble, TX	8101	2007 JLG 3246ES Electric Scissor Lift
8095	2017 JLG 3246ES Electric Scissor Lift S/N: 0200266203 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 373 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 0200163221 C/W: 31.75 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 261 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8102	2016 Genie GS3232 Electric Scissor Lift S/N: GS3216A-142501 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box Usage: 432 Hr Asset located in: Humble, TX	8109	2017 JLG 2646ES Electric Scissor Lift S/N: 200263036 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 378 Hr	
8103	2014 Genie GS3232 Electric Scissor Lift		Asset located in: Humble, TX	
	S/N: GS3214A-136205 C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 352 Hr Asset located in: Humble, TX	8110	2017 JLG 2646ES Electric Scissor Lift S/N: 0200263682 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 255 Hr Asset located in: Humble, TX	
8104	2014 Genie GS3232 Electric Scissor Lift	8111	2014 JLG 2646ES Scissor Lift	
	S/N: GS3214A-135415 C/W: 22 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	8111	S/N: M200007989 Usage: 354 Hr Asset located in: Humble, TX	
	Control Box	0110	2020 JLG 2632ES Electric Scissor Lift	
8105	Usage: 322 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Genie GS3232 Electric Scissor Lift	8112	S/N: M200040404 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 71 Hr	
8105	S/N: GS3213A-113004 C/W: 22 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
			Asset located in: Humble, TX	
	Control Box Usage: 142 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2020 JLG 2632ES Electric Scissor Lift S/N: M200040389 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 101 Hr	
8106	2017 Snorkel S4726E Electric Scissor Lift S/N: S4726E-04-170300438 C/W: 26 ft Max Platform Height, Platform		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX	8114	8114 2019 JLG 2632ES Electric Scissor Lift S/N: MS00026094 C/W: 500 lb Max Weight Capacity, Platfor	2019 JLG 2632ES Electric Scissor Lift
8107	2017 Skyjack SJIII4626 Electric Scissor Lift S/N: 70032974 C/W: 26 ft Max Platform Height, 1000 lb Max		Box Usage: 178 Hr Asset located in: Humble, TX	
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 364 Hr Asset located in : Humble, TX		2016 JLG 2632ES Electric Scissor Lift S/N: M200002208 C/W: 25 ft 5 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	
9 0 7 0 1 1	2017 Genie GS2646 Electric Scissor Lift S/N: GS46P-143622 C/W: 26 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 259 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: 75 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
		8117	2016 JLG 2632ES Electric Scissor Lift S/N: 0200253047 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 447 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8118	2016 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27032135 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 185 Hr Notes: LOCATED-IN-FORT-WORTH-TX	8126	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A-136096 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 458 Hr
	Asset located in: Lake Worth, TX		Asset located in: Humble, TX
8119	2016 Skyjack SJ III 3226 Electric Scissor Lift S/N: 27027774 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 316 Hr	8127	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A136026 C/W: 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires Usage: 488 Hr Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX	8128	2014 Genie GS2632 Electric Scissor Lift
8120	Asset located in: Lake Worth, TX 2019 Genie GS2632 Electric Scissor Lift S/N: GS32P163106 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		S/N: GS3214A136135 C/W: 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box Usage: 427 Hr Asset located in : Humble, TX
	Control Box Usage: 167 Hr Asset located in: Humble, TX	8129	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A118876 C/W: 500 lb Max Weight Capacity, Platform
8121	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A-139268 C/W: Platform Extension, Power to Platform, Upper Control Box		Extension, Solid Non-Marking Tires, Upper Control Box Usage: 380 Hr Asset located in : Humble, TX
	Usage: 608 Hr	8131	2014 Genie GS2632 Electric Scissor Lift
8122	Asset located in: Humble, TX 2015 Genie GS2632 Scissor Lift S/N: GS3215A-139149 Usage: 497 Hr Asset located in: Humble, TX	8131	S/N: GS3214A136458 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available
8123	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A-140827 C/W: 500 lb Max Weight Capacity, Platform		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Extension, Power to Platform, Upper Control	8132	2013 Genie GS2632 Electric Scissor Lift
	Box Usage: 499 Hr Asset located in : Humble, TX	8132	S/N: GS3213A-112911 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
8124A	2015 Genie GS2632 Scissor Lift S/N: GS3215A-139144 Usage: 456 Hr		Platform, Upper Control Box Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
8124	2015 Genie GS2632 Electric Scissor Lift S/N: GS3215A139144 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 431 Hr Asset located in: Humble, TX	8133	2011 Genie GS2632 Electric Scissor Lift S/N: GS3211A97058 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available
8125	2014 Genie GS2632 Electric Scissor Lift S/N: GS3214A-135821 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 388 Hr Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8134	2011 Genie GS2632 Electric Scissor Lift S/N: GS3211A-97073 C/W: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8141	2019 Skyjack SJIII3219 Electric Scissor Lift S/N: 22144648 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 337 Hr Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8135	2014 JLG 2630ES Electric Scissor Lift		Asset located in: Lake Worth, TX
	S/N: 0200232573 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 321 Hr Asset located in: Humble, TX	8142	2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22089176 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 215 Hr
8136	2011 JLG 2630ES Electric Scissor Lift		Notes: LOCATED-IN-FORT-WORTH-TX
	S/N: 0200204774 C/W: 26 ft Max Platform Height, 500 lb Max		Asset located in: Lake Worth, TX
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 389 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8143	2016 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22098919 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in: Humble, TX
8137	2016 JLG 2632ES Electric Scissor Lift	8144	2016 Skyjack SJIII-3219 Electric Scissor Lift
	S/N: 0200252249 C/W: 25 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 351 Hr Asset located in: Humble, TX	0144	S/N: 22103849 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 364 Hr Notes : LOCATED-IN-FORT-WORTH-TX
8138	2016 JLG 2630ES Electric Scissor Lift S/N: 0200252716		DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: 25 ft 4 in Max Platform Height, 500 lb	04.44	Asset located in: Lake Worth, TX
	Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 329 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8146	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22058625 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available
8139	2016 JLG 2630ES Scissor Lift	01.47	Asset located in: Humble, TX
	S/N: 200253457 Usage: 144 Hr	8147	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22061962
	Asset located in: Humble, TX		C/W: 19 ft Max Platform Height, 550 lb Max
8140	2016 JLG 2632ES Electric Scissor Lift S/N: 0200252784 C/W: 25.4 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	8148	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 164 Hr Asset located in : Humble, TX
	Control Box Usage: Not Available Asset located in: Humble, TX		2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22066660 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 203 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8149	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22063992 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 238 Hr Asset located in: Humble, TX	8156	2016 JLG 1932R Electric Scissor Lift S/N: M200017595 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 131 Hr Asset located in: Humble, TX
8150	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: Not Available C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Solid Non- Marking Tires, Upper Control Box Usage: 246 Hr Asset located in: Humble, TX	8157	2015 JLG 1932RS Electric Scissor Lift S/N: 0200247824 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Asset located in: Humble, TX
8151	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22064021 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 278 Hr Asset located in: Humble, TX	8158	2015 JLG 1932RS Electric Scissor Lift S/N: 0200251216 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 538 Hr Asset located in: Humble, TX
8152	2014 Skyjack SJIII-3219 Electric Scissor Lift S/N: 22070495 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 280 Hr	8159 8160	2014 JLG 1932RS Electric Scissor Lift S/N: 200234812 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 34 Hr Asset located in: Humble, TX 2014 JLG 1932RS Electric Scissor Lift
8153	Asset located in: Humble, TX 2012 Skyjack SJIII-3219 Scissor Lift S/N: 22038665 C/W: 19 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	8160 8161	S/N: 0200234442 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 563 Hr Asset located in: Humble, TX
8154	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-170403382 C/W: 19 ft Max Platform Height, 550 lb Max		2014 JLG 1932RS Electric Scissor Lift S/N: 0200235746 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 483 Hr Asset located in: Humble, TX
8155	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 255 Hr Asset located in: Humble, TX 2017 Snorkel S3219E Electric Scissor Lift S/N: S3219E-04-170303298 C/W: 19 ft Max Platform Height, 550 lb Max	8162	2014 JLG 1932RS Electric Scissor Lift S/N: 0200235705 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 495 Hr Asset located in: Humble, TX
	Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 367 Hr Asset located in: Humble, TX	8163	2014 JLG 1932RS Electric Scissor Lift S/N: 200235742 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 165 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8164	2014 JLG 1932RS Electric Scissor Lift S/N: 0200236017 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires Usage: 435 Hr Asset located in: Humble, TX	8171	2018 Genie GS1930 Electric Scissor Lift S/N: GS30P-171391 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 181 Hr Asset located in: Humble, TX	
8165	2014 JLG 1932RS Electric Scissor Lift	8172	2018 Genie GS1930 Electric Scissor Lift	
0100	S/N: 0200234077 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 553 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8173	S/N: GS30P-172180 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 156 Hr Asset located in: Humble, TX	
	Asset located in: Humble, TX		S/N: GS30P167088 C/W: 19 ft Max Platform Height, 500 lb Max	
8166	2014 JLG 1932RS Electric Scissor Lift S/N: 0200234901 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX	
	Control Box Usage: 547 Hr	8174	2017 Genie GS-1930 Electric Scissor Lift	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: GS30P167099 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper	
8167	2020 Genie GS1930 Electric Scissor Lift		Control Box	
	S/N: GS30P-191929 C/W: Platform Extension, Power to Platform, Upper Control Box		Usage: 128 Hr Asset located in : Humble, TX	
		8175		
	Usage: 298 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2017 Genie GS1930 Electric Scissor Lift S/N: GS30P-169281 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to	
	Asset located in: Humble, TX		Platform, Solid Non-Marking Tires, Upper Control Box	
8168	2020 Genie GS1930 Electric Scissor Lift S/N: GS30P191148 C/W: 19 ft Max Platform Height, 550 lb Max		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box		Asset located in: Humble, TX	
	Usage: 395 Hr	8176	2017 Genie GS1930 Electric Scissor Lift	
	Asset located in: Humble, TX		S/N: GS30P-166125	
8169	2018 Genie GS1930 Electric Scissor Lift S/N: GS30P182807 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		C/W: 19 ft Max Platform Height, Weight Capacity, Platform Extens Platform, Solid Non-Marking Tire Control Box Usage: Not Available Notes : DEFICIENCIES NOTED - Pl THE INSPECTION REPORT	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
	THE INSPECTION REPORT	8177	2017 Genie GS1930 Electric Scissor Lift	
	Asset located in: Humble, TX		S/N: GS30P167077	
8170	2019 Genie GS1930 Electric Scissor Lift S/N: GS30P188159 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power t Platform, Solid Non-Marking Tires, Upper Control Box Usage: 345 Hr Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
8178	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P-167032 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	8185A	2016 Genie GS1930 Scissor Lift S/N: GS3016P-159746 Usage: 501 Hr Asset located in: Humble, TX
	Usage: 324 Hr Asset located in: Humble, TX	8185	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P-160058
8179	2017 Genie GS1930 Electric Scissor Lift S/N: GS30P164379 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box		C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 360 Hr Asset located in : Humble, TX
	Usage: 86 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8186	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P159746 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper
8180A	2017 Genie GS1930 Scissor Lift S/N: GS30P-167077 Usage: 345 Hr		Control Box Usage: 532 Hr Asset located in: Humble, TX
8180	Asset located in: Humble, TX 2017 Genie GS1930 Electric Scissor Lift S/N: 164382 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 722 Hr Asset located in: Humble, TX	8187	2015 Genie GS1930 Electric Scissor Lift S/N: GS3015A148303 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 380 Hr Asset located in: Humble, TX
8181	81 2016 Genie GS1930 Electric Scissor Lift S/N: GS3016A-151095 C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control	8188	2015 Genie GS1930 Scissor Lift S/N: GS3015A-146189 Usage: 141 Hr Asset located in: Humble, TX
	Box Usage: 538 Hr Asset located in : Humble, TX	8189	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A-138221 C/W: 500 lb Max Weight Capacity, Platform
8182	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P151859 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Extension, Power to Platform, Upper Control Box Usage: 488 Hr Asset located in : Humble, TX
	Control Box Usage: 365 Hr Asset located in: Humble, TX	8190	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A138410 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to
8183	2016 Genie GS1930 Electric Scissor Lift S/N: GS3016P153073 C/W: 19 ft Max Platform Height, 500 lb Max		Platform, Upper Control Box Usage: 463 Hr Asset located in : Humble, TX
	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 569 Hr Asset located in : Humble, TX	8191	2014 Genie GS1930 Scissor Lift S/N: GS3014A-138474 Usage: 362 Hr Asset located in: Humble, TX
8184	2016 Genie GS-1930 Electric Scissor Lift S/N: GS3016A151094 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 494 Hr Asset located in: Humble, TX		2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A138039 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 425 Hr Asset located in: Humble, TX
8185B	2016 Genie GS1930 Scissor Lift S/N: GS3016P-153073 Usage: 568 Hr Asset located in: Humble, TX		

Lot #	Details	Lot #	Details	
8193	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A-138921 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 459 Hr Asset located in: Humble, TX	8199	2018 JLG 1930 ES Electric Scissor Lift S/N: M200025037 C/W: 18.8 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 322 Hr Asset located in: Humble, TX	
8194B	2014 Genie GS1930 Scissor Lift	8200	2016 JLG 1930 ES Electric Scissor Lift	
	S/N: GS3014A-138410 Usage: 423 Hr Asset located in : Humble, TX		S/N: M200003937 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid	
8194A	2014 Genie GS1930 Scissor Lift S/N: GS3014A-137358		Non-Marking Tires Usage: 444 Hr Asset located in : Humble, TX	
	Usage: 341 Hr Asset located in: Humble, TX	8201	2016 JLG 1930 ES Electric Scissor Lift	
8194	2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A-128925 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		S/N: M200003872 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires Usage: 97 Hr Asset located in : Humble, TX	
	Control Box Usage: 425 Hr	8202	2015 JLG 1930 ES Electric Scissor Lift	
	Asset located in: Humble, TX		S/N: 200248780 C/W: 18.8 ft Max Platform Height, 500 lb Max	
8195	5 2014 Genie GS1930 Electric Scissor Lift S/N: GS3014A137358 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper		Weight Capacity, Platform Extension, Power t Platform, Solid Non-Marking Tires, Upper Control Box Usage: 368 Hr Asset located in: Humble, TX	
	Control Box Usage: 358 Hr	8203	2017 JLG 1930ES Electric Scissor Lift	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: M200006693 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to	
8196	2013 Genie GS1930 Electric Scissor Lift	1	Platform, Üpper Control Box Usage: 199 Hr	
	S/N: Not Available C/W: 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Box Usage: 357 Hr	8204	2017 JLG 1930ES Electric Scissor Lift	
	Asset located in: Humble, TX		S/N: M200006663	
8197	2013 Genie GS1930 Electric Scissor Lift S/N: GS3013A-125344 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to			C/W: 18.75 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 251 Hr
	Platform, Śolid Ńon-Marking Tires, Upper Control Box		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	Usage: 497 Hr		Asset located in: Humble, TX	
8198	2011 Genie GS1930 Electric Scissor Lift S/N: GS3011A102214 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	8205	2021 LiuGong S1930DE Electric Scissor Lift S/N: K0036518 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available	
	Usage: 315 Hr Asset located in: Humble, TX		Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
			Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
8206	2021 LiuGong S1930DE Electric Scissor Lift S/N: K0036538 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 58 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	8212	2021 LiuGong S1930E Electric Scissor Lift S/N: K0036688 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	
	THE INSPECTION REPORT Asset located in: Humble, TX		THE INSPECTION REPORT Asset located in: Humble, TX	
8207	2021 LiuGong S1930DE Electric Scissor Lift S/N: K0032058 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8213	2024 Powertek PT-0.5-6 Electric Scissor Lift (Unused) S/N: Not Available C/W: 26 ft Max Platform Height, 1100 lb Max Weight Capacity, Non-Marking Tires Usage: Not Available Asset located in: Humble, TX 2019 Genie GS1330M Electric Scissor Lift	
	Asset located in: Humble, TX		S/N: GS30MD-2718	
8208	2021 LiuGong S1930DE Electric Scissor Lift S/N: K0036618 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		C/W: 13 ft Max Platform Height, 500 Weight Capacity, Platform Extension, Platform, Solid Non-Marking Tires, U Control Box Usage: 88 Hr Notes : DEFICIENCIES NOTED - PLEA: THE INSPECTION REPORT	C/W: 13 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 88 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX	8215	2019 MEC 1330SE Scissor Lift	
8209	2021 LiuGong S1930DE Electric Scissor Lift S/N: K0036628 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8216	S/N: 16301223 Usage: 30 Hr Asset located in: Humble, TX 2018 MEC 1330SE Electric Scissor Lift S/N: 16302954 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box	
8210	Asset located in: Humble, TX 2021 LiuGong S1930DE Electric Scissor Lift S/N: K0036558 C/W: 26 ft Max Platform Height, 505 lb Max		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
8211	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2021 LiuGong S1930E Electric Scissor Lift	8217	Asset located in: Humble, TX 2018 MEC 1330SE Electric Scissor Lift S/N: 16301972 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 243 Hr Asset located in: Humble, TX	
	S/N: K0036678 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8218	2018 MEC 1330SE Electric Scissor Lift S/N: 16301448 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 MEC 1330SE Electric Scissor Lift S/N: 16301458 C/W: 13 ft Max Platform Height, 530 lb Max	
			Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 10 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
8220	2017 MEC 1330SE Electric Scissor Lift S/N: 16301222 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	8228	2016 Genie GR20 Vertical Mast Lift S/N: GR16P-44447 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 682 Hr Asset located in: Humble, TX	
	THE INSPECTION REPORT Asset located in: Humble, TX	8229	2016 Genie GR20 Vertical Mast Lift	
8221	2017 MEC 1330SE Electric Scissor Lift S/N: 16301226 C/W: 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available		Max Weight Capacity, Platform Ext Power to Platform, Upper Control I Usage: 753 Hr	C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box
	Asset located in: Humble, TX	8230	2016 Genie GR20 Vertical Mast Lift	
8222	2017 MEC 1330SE Electric Scissor Lift S/N: 16301118 C/W: 13 ft Max Platform Height, 530 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 49 Hr		S/N: GRP-45501 C/W: 19 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Solid Non- Marking Tires, Upper Control Box Usage: 328 Hr Asset located in : Humble, TX	
	Asset located in: Humble, TX	8231	2015 Genie GR20 Vertical Mast Lift S/N: GR1537958	
8223	2016 MEC 1330SE Scissor Lift S/N: 16301228 Usage: 37 Hr Asset located in: Humble, TX		C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 283 Hr	
8224	2015 JLG 36AM Vertical Mast Lift		Asset located in: Humble, TX	
·	S/N: 0900036035 C/W: 36 ft Max Platform Height, 300 lb Max Weight Capacity, Power to Platform, Stabilizers, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8232	2016 JLG 20MVL Vertical Mast Lift S/N: 0130024155 C/W: 19 ft 5 in Max Platform Height, 300 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
0005	Asset located in: Humble, TX		Asset located in: Humble, TX	
8225	2014 Genie AWP30SDC Vertical Mast Lift S/N: AWP14-81378 Usage: Not Available Asset located in: Humble, TX	8233	2014 JLG 20MVL Vertical Mast Lift S/N: 0130021493 C/W: 19 ft 5 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension,	
8226	2017 JLG 30AM Vertical Mast Lift S/N: 0900037384 C/W: 30 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform,		Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in : Humble, TX	
	Stabilizers, Upper Control Box Usage: Not Available	8234	2016 Skyjack SJ12 Vertical Mast Lift	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: Not Available C/W: 12 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to	
8227	Asset located in: Humble, TX 2017 Genie GR20 Vertical Mast Lift		Platform, Solid Non-Marking Tires Usage: Not Available Asset located in : Humble, TX	
	S/N: GRP-50132 C/W: 19 ft 9 in Max Platform Height, 350 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: 309 Hr Asset located in: Humble, TX	8235	2016 Genie GR-12 Vertical Mast Lift S/N: GR16P41067 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 465 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8236	2015 Genie GR-12 Vertical Mast Lift S/N: GR15-38803 C/W: 19 ft 9 in Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX 2015 Genie GR-12 Vertical Mast Lift S/N: GR15-39082 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension,	8243	Cummins 350DFCC 600 kW Skid-Mounted Generator Set S/N: RF19515356 C/W: Cummins VTA28GS2 12 Cylinder 900 hp Engine, 750 kVA/600 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 291 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Power to Platform, Upper Control Box Usage: 376 Hr Asset located in: Humble, TX	8244	Onan 350DFCC 50266F 350 kW Skid-Mounted Generator Set S/N: B910369338
8238	2014 Genie GR-12 Electric Vertical Mast Lift S/N: GR14-35810 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 328 Hr	8245	C/W: Cummins NT855 6 Cylinder Diesel Engine, 437.5 kVA/350 kW Rated 3 Phase Output Usage: 387 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX		2003 Kohler 250RE0ZV 294 kW Skid-Mounted
8239	2014 Genie GR-12 Vertical Mast Lift S/N: GR14-35919 C/W: 11 ft 4 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 343 Hr Asset located in: Humble, TX		Generator Set S/N: 0776084 C/W: 2007 US EPA Label, Kohler D250 9.6A60 6 Cylinder Engine, /260 kW Rated 3 Phase Output, 120 V / 240 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8240	JLG Vertical Mast Lift		Asset located in: Humble, TX
	S/N: 0900035041 C/W: 25 ft Max Platform Height, 350 lb Max Weight Capacity, Power to Platform, Stabilizers, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8246	2012 Magnum MMG330 263 kW Skid-Mounted Generator Set S/N: 1221450 C/W: John Deere 6 Cylinder Diesel Engine, 329 kVA/263 kW Rated 3 Phase Output, 208 V / 480 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 8,429 Hr
8241	2020 Genie SLA10 Material Hoist		Asset located in: Humble, TX
	S/N: SLAP-77341 Usage: Not Available Asset located in : Humble, TX	8247	Cummins NT855 200kW Diesel Generator Generator Set S/N: Not Available
8242	2012 Cummins GTA50 600 kW Skid-Mounted		Usage: Not Available Asset located in: Humble, TX
	Generator Set S/N: X11K452710 C/W: US EPA Label, Cummins GTA50 16 1035 hp 50 L Natural Gas Engine, /600 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8248	1999 Olympian D159P1 150 kW Skid-Mounted Generator Set S/N: E2024B001 C/W: Perkins 6 Cylinder Diesel Engine, /150 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: 184 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8249	Multiquip KD-150V 135 kVA Stand-By Generator Set S/N: 67396810 C/W: US EPA Label, Iveco F4GE0685D 6 Cylinder 286 hp 6.8 L Diesel Engine, 135 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, Bottom Mounted Fuel Tank Usage: 2,217 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8255	2013 Multiquip DCA45US12 36 kW Mobile Generator Set S/N: 8203020 C/W: Isuzu 4 Cylinder 2.9 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 280 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 38,994 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8250	Marathon Magnaplus 363PSL3127 100 kW		Asset located in: Humble, TX
	Skid-Mounted Generator Set S/N: MX1043210707 C/W: 6 Cylinder Diesel Engine, /100 kW Rated 3 Phase Output, 480 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 3,146 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	8256	11 kW Skid-Mounted Generator Set S/N: Not Available C/W: Cat C2.2 4 Cylinder Diesel Engine, 120 V Rated Voltage Usage: 15 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT	8257	2008 Generac QT25 25 kW Skid-Mounted NG
8251	Generator Set S/N: 2184957 C/W: 2007 US EPA Label, John Deere 4045TF 4 Cylinder 4.5 L Diesel Engine, 78 kVA/62 kW Rated 3 Phase Output, 139 V / 220 V / 240 V Rated Voltage, 120 V Receptacles, Bottom Mounted Fuel Tank Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Generator Set S/N: 4514700 C/W: Mitsubishi 4 Cylinder Engine, 25 kVA,/25 kW, Rated Single Phase Output, 120 V / 208 V Rated Voltage Usage: Not Available Asset located in: Humble, TX
		8258	2009 Generac 11015510100 75 kW Skid- Mounted Generator Set S/N: 2102282 C/W: 2009 US EPA Label, Generac Power Systems OSG1068 04 kWA/75 kW Peted 2
8252	Asset located in: Humble, TX Generac SD60 60 kW Skid-Mounted Generator Set S/N: 3883733 C/W: Mitsubishi 4D34-T 4 Cylinder 3907 cc Diesel Engine, /60 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Natural Gas Engine, 94 kVA/75 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage Usage: 331 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		8259	Generac G0072900 26 kW Generator Set S/N: 3014737691 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8253	Asset located in: Humble, TX Kohler 50RZ 49 kW Skid-Mounted Generator Set S/N: 0675321 C/W: Ford LSG-875I-6005-A 8 Cylinder Gasoline Engine, 49 kVA,/49 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage	8260	Generac G0072900 26 KW Generator Set (Unused) S/N: 3014737610 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
0054	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8261	Generac G0072090 24 kW Generator Set (Unused) S/N: 3015224571 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available
8254	1992 Cummins DGBA 37kW Diesel Generator Generator Set		Asset located in: Humble, TX
	S/N: I910419145 Usage: Not Available Asset located in : Humble, TX	8262	Generac G0072090 24 kW Generator Set (Unused) S/N: 3015224570 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8263	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011524641 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8273	Generac G0070433 22 kW Generator Set (Unused) S/N: 3011353754 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8264	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405115 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8274 8275	Generac G0070433 22 kW Generator Set S/N: 3011353779 C/W: Gwnerac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX Generac G0072280 18 KW Generator Set
8265	Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405492 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available		(Unused) S/N: 3010411534 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX
8266	Asset located in: Humble, TX Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405499 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available	8276 8277	2016 Multiquip DCA220SSJU4F Generator Set S/N: 8010873 Usage: 10,981 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2012 Magnum MMG175 175 kW Mobile Stand-
8267	Asset located in: Humble, TX Generac G0072101 24 KW Generator Set (Unused) S/N: 3011405670 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX		By Generator Set S/N: 1215091 C/W: John Deere 6 Cylinder Diesel Engine, 185 kVA/148 kW Rated 3 Phase Output, 480 V Rated Voltage, 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: 793 Hr
8268	Generac G0070433 22 KW Generator Set		Asset located in: Humble, TX
8269	(Unused) S/N: 3011353871 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX Generac G00704211 22 kW Generator Set S/N: 3014992389	Generator Set S/N: Not Available C/W: Cat 4 Cylinder Dies /113 kW Rated 3 Phase (Rated Voltage, 120 V Rat 120 V Receptacles, Soun	S/N: Not Available C/W: Cat 4 Cylinder Diesel Engine, 141 kVA /113 kW Rated 3 Phase Output, 480 V / 240 V Rated Voltage, 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom
	C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in : Humble, TX		Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 2,175 Hr
8270	Generac G0070433 22 kW Generator Set (Unused) S/N: 3011310896	THE INSPECTION REPORT	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX	8279	2013 Taylor Power TR100 100 kW Mobile Generator Set S/N: 25690
8271	Generac G0070433 22 KW Generator Set (Unused) S/N: 3011353773 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX		C/W: 2012 US EPA Label, Perkins 3362 4 Cylinder 116 kW 4.4 L Diesel Engine, 125 kVA /100 kW Rated 3 Phase Output, 80 V / 208 V / 240 V Rated Voltage, 79 kVA,/79 kW, Rated Single Phase Output, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: 1,407 Hr
8272	Generac G0070433 22 kW Generator Set S/N: 3011365373 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8280	2016 Multiquip DCA125SSIU4F 72 kW Mobile Generator Set S/N: 7511312 C/W: 2016 US EPA Label, CARB Compliant, Isuzu BR-4HK1X 4 Cylinder 56 kW 5.1 L Diesel Engine, Requires Diesel Exhaust Fluid, 125 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /72 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 16,761 Hr Asset located in: Humble, TX	8285	2022 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1429NL037179 C/W: 2015 US EPA Label, CARB Compliant, Isuzu BR-4JJ1X 4 Cylinder 56 kW Diesel Engine, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 120 V Receptacles, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: 21,096 Hr Asset located in: Humble, TX
8281	2014 Magnum MMG130 98 kW Mobile	8286	2017 Multiquip DCA-70SSIU4F Generator Set
	Portable Generator Set S/N: 5AJGS1829EB408174 C/W: 2012 US EPA Label, John Deere 4 Cylinder 130 kW 4.5 L Diesel Engine, 122 kVA /98 kW Rated 3 Phase Output, 480 V / 208 V		S/N: 7353824 Usage: 7,237 Hr Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX
	Rated Voltage, 90 kVA,/90 kW, Rated Single Phase Output, 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 6,384 Hr	8287	2017 Multiquip DCA-70SSIU4F Generator Set S/N: 7354082 Usage: 10,695 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Asset located in: Humble, TX	8288	2017 Multiquip DCA-70SSIU4F Generator Set
8282A 2018 T By Gen S/N: 56 C/W: 2 Cylinde /108 k Rated Phase 240 V Botton Lunette Usage: Notes: THE IN	2018 TechnoGen G100 108 kW Mobile Stand-By Generator Set S/N: 5632G1524JM002533 C/W: 2018 US EPA Label, Perkins 1104D 4 Cylinder 108.1 kW 4.4 L Diesel Engine, 135 kVA /108 kW Rated 3 Phase Output, 480 V / 277 V Rated Voltage, 82.5 kVA,/66 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 5,493 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 7353963 Usage: 15,207 Hr Notes : LOCATED-IN-FORT-WORTH-TX Asset located in : Lake Worth, TX
		8289	2017 MQ Power DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1424HL020245 C/W: 2016 US EPA Label, Isuzu 4 Cylinder 75 kW 2.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA, /40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes
8282	2006 Magnum MMG125 90 kW Mobile		Usage: 10,036 Hr
	Generator Set S/N: 000078 C/W: 2005 US EPA Label, John Deere 6068TF275F 6 Cylinder 123 kW 6.8 L Diesel Engine, 124 kVA/ Rated 3 Phase Output, 208 V / 480 V Rated Voltage, /90 kW, Rated Single Phase Output, 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch, Surge Brakes Usage: Not Available	8290	Asset located in: Humble, TX 2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353236 Usage: 12,270 Hr Asset located in: Humble, TX
		8291	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353490 Usage: 15,293 Hr Asset located in: Humble, TX
•••	Asset located in: Humble, TX	8292	2016 Multiquip DCA-70SSIU4F Generator Set
8284	DMT DMT-600 60 kW Mobile Generator Set S/N: Not Available C/W: Cummins 4 Cylinder 3.9 L Diesel Engine, 75 kVA/60 kW Rated 3 Phase Output, 120 V / 208 V Rated Voltage, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: 764 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 7353184 Usage: 21,096 Hr Asset located in: Humble, TX
		8293	2016 Multiquip DCA-70SSIU4F 56 kW Generator Set S/N: 7353493 Usage: 12,107 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8294	2016 MQ Power DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1423GL018775 C/W: 2016 US EPA Label, Isuzu 4 Cylinder 75 kW 2.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,	8300	2017 Atlas Copco QAS 45 IT4/T4F Generator Set S/N: H0P121334 Usage: 114,918 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
8295	/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 15,719 Hr Asset located in: Humble, TX 2016 Multiquip DCA-70SSIU4F 56 kW	8301	2018 Multiquip DCA45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1229NL037461 C/W: 2018 US EPA Label, Isuzu 4LE2X 4 Cylinder 49 kW 2.1 L Diesel Engine, 45 kVA/36 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom
	Generator Set S/N: 7353539-L018778 Usage: 16,991 Hr Asset located in: Humble, TX		Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: 6,472 Hr Asset located in: Humble, TX
8296	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353339 Usage: 12,506 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8302	2017 Multiquip DCA45SSIU4F 36 kW Mobile Generator Set S/N: 5SLBG1221HL021226 C/W: 2017 US EPA Label, Isuzu 4LE2X 4 Cylinder 49 kW 2.1 L Diesel Engine, 45 kVA/36
8297	2016 Multiquip DCA-70SSIU4F Generator Set S/N: 7353674 Usage: 17,557 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 26 kVA,/26 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: 9,655 Hr
8298	2015 Multiquip DCA-70SSIU4F 56 kW Mobile Generator Set S/N: 5SLBG1426FL018011		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
C/W: 2015 US EF Cylinder 71 kW 2 Diesel Exhaust F Phase Output, 24 kVA,/40 kW, Rato / 120 V Rated Vo	C/W: 2015 US EPA Label, Isuzu BR-4JJ1X 4 Cylinder 71 kW 2.9 L Diesel Engine, Requires Diesel Exhaust Fluid, 70 kVA/56 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 40 kVA,/40 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom	8303	2015 Multiquip DCA45SSIU4F Generator Set S/N: 7250402 Usage: 11,294 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: 12,270 Hr Asset located in : Humble, TX	8304	2019 Airman MMD SDG25S Generator Set S/N: 1238E12341 Usage: 9,013 Hr Notes: LOCATED-IN-FORT-WORTH-TX
8299	2015 Wacker G50T4F 38 kW Mobile Generator		Asset located in: Lake Worth, TX
	Set S/N: 4TCSU1850FH190043 C/W: 2015 US EPA Label, Isuzu 4 Cylinder 56 kW Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Surge Brakes Usage: 1,835 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8305	2017 Multiquip DCA25SSIU4F 14.4 kW Mobile Generator Set S/N: 7152915 C/W: 2016 US EPA Label, Isuzu BZ-4LE2T 19 kW 2.2 L Diesel Engine, 25 kVA/ Rated 3 Phase Output, 480 V / 240 V Rated Voltage, /14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 4,833 Hr Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
8306	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set	8313	Specialty Lighting BOSS-P-95 96 kW Mobile Generator Set
	S/N: Not Available C/W: 2017 US EPA Label, Isuzu 4LE2T 4 Cylinder 30 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single		S/N: 9886097 C/W: 6 Cylinder Diesel Engine, 120 kVA/96 kW Rated 3 Phase Output, Bottom Mounted Fuel Tank, T/A Trailer, Ball Hitch Usage: Not Available
	Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer,		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Lunette Ring		Asset located in: Humble, TX
	Usage: 2,347 Hr Asset located in: Humble, TX	8314	2011 Quincy QSI-1500 Skid-Mounted Air
8307	· · · · · · · · · · · · · · · · · · ·	\dashv	Compressor S/N: BU1109290008
0307	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set		C/W: 3 Phase
	S/N: 4GNBG0918HB045984		Usage: Not Available
	C/W: 2016 US EPA Label, Isuzu 4LE2T 4	201 -	Asset located in: Humble, TX
	Cylinder 30 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single	8315	2013 Hankison ACFS1000 Skid-Mounted Air Compressor
	Phase Output, 240 V / 120 V Rated Voltage,		S/N: ACFS10002
	240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer,		C/W: 160 psi Working Pressure Usage: Not Available
	Lunette Ring	8316	Asset located in: Humble, TX
	Usage: 5,173 Hr		2013 Hankison ACFS1000 Skid-Mounted Air
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Compressor
	Asset located in: Humble, TX		S/N: ACFS10004 C/W: 160 psi Working Pressure
8308	2016 Multiquip DCA25SSIU4F 20 kW Mobile		Usage: Not Available
	Generator Set S/N: 7151786	0217	Asset located in: Humble, TX
	C/W: 2015 US EPA Label, CARB Compliant,	8317	2014 Quincy QSI-500I Skid-Mounted Air Compressor
	Isuzu BZ-4LE2 19 kW Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated		S/N: UTZ300466
	Voltage, 14.4 kVA,/14.4 kW, Rated Single		C/W: 125 psi Working Pressure, 460V, 125 hp Motor
	Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted		Usage: 43,051 Hr
	Fuel Tank, S/A Trailer, Lunette Ring		Asset located in: Humble, TX
	Usage: 2,128 Hr Asset located in: Humble, TX	8318	2016 Hankison ACFS450 Air Dryer
8309		8319	S/N: Not Available Usage: Not Available
0309	2016 Multiquip DCA25SSIU4F Generator Set S/N: 7152111		Asset located in: Humble, TX
	Usage: 12,725 Hr		2016 Hankison ACFS450 Air Dryer
	Notes: LOCATED-IN-FORT-WORTH-TX	0015	S/N: Not Available
	Asset located in: Lake Worth, TX	4	Usage: Not Available
8310	2014 Multiquip DCA25SSIU4F Portable Generator Set		Asset located in: Humble, TX
	S/N: 7152210-41747	8320	2016 Hankison ACFS450 Skid-Mounted Air
	Usage: 1,408 Hr		Compressor S/N: 1000003124757
	Asset located in: Humble, TX		C/W: 100 psi Working Pressure
8312	Kohler 30RZ262 30 kW Mobile (LNG)		Usage: Not Available
	Generator Set S/N: 1B9AB1112SA1B9051	9224	Asset located in: Humble, TX
	C/W: Ford 4 Cylinder Natural Gas Engine, 38	8321	2016 Hankison ACFS450 Air Dryer S/N: Not Available
	kVA/30 kW Rated 3 Phase Output, 240 V / 277 V / 480 V Rated Voltage, 29 kVA,/29 kW, Rated		Usage: Not Available
	Single Phase Output, 120 V / 240 V Rated		Asset located in: Humble, TX
	Voltage, S/A Trailer, Ball Hitch Usage: Not Available	8322	2007 Quincy Compressors QSI-750 1385 cfm
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Skid-Mounted Electric Air Compressor
	THE INSPECTION REPORT		S/N: UN107354 C/W: 3 Phase
	Asset located in: Humble, TX		Usage: 17,853 Hr
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8323	2010 Ingersoll Rand P250WJDU-T1 Air Compressor S/N: 417161UHUA23 C/W: 2010 US EPA Label, John Deere 4 Cylinder Diesel Engine, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 2,732 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8332	2019 Allmand Max Air 185 Mobile Air Compressor S/N: B46E11882 C/W: 2018 US EPA Label, Yanmar 4 Cylinder 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 983 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	· · · · · · · · · · · · · · · · · · ·	8333	2018 Sullair 185DDPQ-KU4F 185 cfm Mobile
8324	Ingersoll Rand SSR-EP150 670 cfm Skid- Mounted Electric Air Compressor S/N: F36749U99148 C/W: 128 psi Working Pressure, 3 Phase, 150 hp Motor Usage: Not Available Asset located in: Humble, TX		Air Compressor S/N: 201802080070 C/W: 100 psi Working Pressure, 2017 US EPA Label, Kubota D1803-CR-T-EF01 3 Cylinder 36.5 kW 1.8 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Humble, TX
8325	Electric 240 gal Air Compressor	0224	
8326	S/N: Not Available C/W: Ingersoll Rand TS1A air dryer Usage: 9,366 Hr Asset located in: Humble, TX 2019 Sullair 375HAF Air Compressor	8334	Sullair 185DP0JD 185 cfm Mobile Air Compressor S/N: E04118506 C/W: 125 psi Working Pressure, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 899 Hr
	S/N: 201901210061 Usage: 4,631 Hr		Asset located in: Humble, TX Sullair 185DP0JD 185 cfm Mobile Air
	Asset located in: Lake Worth, TX	8335	Compressor
8327	2019 Sullair 375HAF 375 cfm Mobile Air Compressor S/N: 201912130043 C/W: Perkins 4.4 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring		S/N: E04118502 C/W: 125 psi Working Pressure, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 952 Hr Asset located in : Humble, TX
	Usage: 1,872 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	8337	2018 Atlas Copco XAS185KD7 185 cfm Mobile Air Compressor S/N: HOP057044 C/W: 230 psi Working Pressure, 2018 US EPA
8328	2019 Sullair 375HAF 375 cfm Mobile Air	1	Label, CARB Compliant, Kubota D1803-CR-TI-
0320	Compressor S/N: 201912190023 C/W: Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Lunette Ring	/A Trailer, Lunette Ring Usage: 665 Hr Asset located in: Humble, TX	Usage: 665 Hr
	Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8338	2017 Atlas Copco XAS 185 Air Compressor S/N: HOP055449 Usage: 940 Hr Notes: LOCATED-IN-FORT-WORTH-TX
8329	2009 Ingersoll Rand 375 Mobile Air		Asset located in: Lake Worth, TX
	Compressor S/N: 4FVCCBBA49U408144 C/W: 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,021 Hr Asset located in: Humble, TX	8339	2017 Doosan C185WDZ-T4F 185 cfm Mobile Air Compressor S/N: 4FVCABAA1HU479193 C/W: 2016 US EPA Label, Deutz D2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch
8330	2018 Doosan P425/HP375WCU-T4F Mobile Air Compressor S/N: 484388UBACF68 C/W: 2014 US EPA Label, Cummins 4 Cylinder 4.5 L Diesel Engine, Requires Diesel Exhaust Fluid, S/A Trailer, Ball Hitch Usage: 2,500 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		Usage: 2,196 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8340	2017 Doosan C185WDZ-T4F 185 cfm Mobile Air Compressor S/N: 478832UKAAF23 C/W: 2016 US EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,398 Hr Asset located in: Humble, TX	8347	2013 Atlas Copco XAS185JD Mobile Air Compressor S/N: 4500A1018DR046162 C/W: 250 psi Working Pressure, John Deere 4024TF281A 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Ball Hitch Usage: 2,227 Hr Asset located in: Humble, TX
8341	2017 Doosan C185WDZ-T4F 185 cfm Mobile	8348	2012 Sullair 185DPQJD2 185 cfm Mobile Air
0341	Air Compressor S/N: 4FVCABAA7HU478985 C/W: 2016 US EPA Label, Deutz D2.9L4 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,022 Hr Asset located in: Humble, TX	8348	Compressor S/N: 201204240079 C/W: 2012 US EPA Label, John Deere 4024TF270G 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Ball Hitch Usage: 2,367 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
8342	2016 Doosan C185WDZ-T4F Mobile Air		THE INSPECTION REPORT Asset located in: Humble, TX
	Compressor S/N: 4FVCABAA6GU476983 C/W: 2016 US EPA Label, Deutz 4 Cylinder 49 hp 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,696 Hr Asset located in: Humble, TX	8349	2012 Ingersoll Rand P185WJD T4i 185 cfm Mobile Air Compressor S/N: 437511UCWD75 C/W: 150 psi Working Pressure, 2012 US EPA Label, CARB Compliant, John Deere
8343	2016 Doosan C185WDZ-T4F Mobile Air Compressor S/N: 447338UFAAF23 C/W: 200 psi Working Pressure, 2016 US EPA Label, CARB Compliant, Deutz D 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, S/A		4024TF281C 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,081 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
	Trailer, Ball Hitch Usage: 2,453 Hr Asset located in : Humble, TX	8350 e	2011 Doosan C185WJD-T4I Mobile Air Compressor S/N: 427569UFVE43
8344	2016 Doosan C185WDZ-T4F 185 cfm Mobile Air Compressor S/N: 4FVCABAA9GU475536 C/W: 2015 US EPA Label, Deutz D2.9 L4 4 Cylinder 26.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch		C/W: 200 psi Working Pressure, 2011 Label, CARB Compliant, John Deere
	Usage: 3,045 Hr	8351	2012 Doosan C185WJD-T4I Mobile Air
8345	Asset located in: Humble, TX 2014 Doosan C185WDZ Mobile Air Compressor S/N: 4648630FYF23 C/W: 2014 US EPA Label, CARB Compliant, Deutz D 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,355 Hr Asset located in: Humble, TX		Compressor S/N: 4314506UIVE43 C/W: 200 psi Working Pressure, 2011 US EPA Label, CARB Compliant, John Deere 4024TF281C 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,197 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8346	2014 Atlas Copco XAS185KD Mobile Air		Asset located in: Humble, TX
	Compressor S/N: HOP048062 C/W: 160 psi Working Pressure, 2006 US EPA Label, Kubota V2403 4 Cylinder 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,419 Hr Asset located in: Humble, TX	8352	2011 Ingersoll Rand P185WJD T4i 185 cfm Mobile Air Compressor S/N: 421650UAVD75 C/W: 2010 US EPA Label, John Deere 4024TF281C 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 262 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8354	2010 Doosan C185 185 cfm Mobile Air Compressor S/N: Not Available C/W: 2010 US EPA Label, Kubota V2403 36.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 4,140 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8364	Sullair 185DPQJD 185 cfm Mobile Air Compressor S/N: 004145077 C/W: 2004 US EPA Label, John Deere 4024TF270A 4 Cylinder 2.4 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 222 Hr Asset located in: Humble, TX 2006 Atlas Copco XAS97JD 185 cfm Mobile	
8355	2007 Ingersoll Rand 185 cfm Mobile Air Compressor S/N: 4FVCABAA17U378993 C/W: 150 psi Working Pressure, 2006 US EPA Label, CARB Compliant, Kubota 4IRX3T2 4 Cylinder 46.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 729 Hr	8366	Air Compressor S/N: 4500A10186R016162 C/W: 123 psi Working Pressure, 200	Air Compressor S/N: 4500A10186R016162 C/W: 123 psi Working Pressure, 2006 US EPA Label, John Deere 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,410 Hr
8358	Asset located in: Humble, TX 2007 Sullair P185 Air Compressor S/N: 200710190034 Usage: Not Available Asset located in: Humble, TX 2006 Sullair 185 CFM 185 cfm Mobile Air		Air Compressor S/N: 356253UDPB34 C/W: 2005 US EPA Label, John Deere 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 915 Hr Asset located in: Humble, TX	
0300	Compressor S/N: 200607270106 C/W: 300 psi Working Pressure, 2006 US EPA Label, CARB Compliant, John Deere 4024TF270A 4 Cylinder 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Ball Hitch Usage: 291 Hr Asset located in: Humble, TX	8367	2001 Ingersoll Rand P185WD Mobile Air Compressor S/N: 318800UAL219 C/W: 160 psi Working Pressure, Deutz 4 Cylinder 45.8 kW Diesel Engine, S/A Trailer, Lunette Ring Usage: 4,745 Hr Asset located in: Humble, TX	
8361	Sullair 185DPQ 185 cfm Mobile Air Compressor S/N: 0046151309 C/W: 300 psi Working Pressure, 2005 US EPA Label, CARB Compliant, John Deere 4024TF270A 4 Cylinder 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 539 Hr Asset located in: Humble, TX	8368A 8368	1998 Ingersoll Rand P185WJD 185 cfm Mobile Air Compressor S/N: 286198UBI221 C/W: 1998 US EPA Label, John Deere 4045DF150 4 Cylinder 80 hp 4.5 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 97 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
8362	Sullair 185DPQ 185 cfm Mobile Air Compressor S/N: 004152325 C/W: 185 psi Working Pressure, 2005 US EPA Label, CARB Compliant, John Deere 4024TF270A 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 384 Hr Asset located in: Humble, TX		2001 Ingersoll Rand P185WJD T4i 185 cfm Mobile Air Compressor S/N: 319787UCL221 C/W: 150 psi Working Pressure, 2001 US EPA Label, CARB Compliant, John Deere 4045DF150B 60 kW 4.5 L Diesel Engine, S/A Trailer, Lunette Ring	
8363	Sullair 185DPQJD 185 cfm Air Compressor S/N: 004152324 C/W: 300 psi Working Pressure, 2005 US EPA Label, CARB Compliant, John Deere 4024TF270A 4 Cylinder 45.5 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: 73 Hr Asset located in: Humble, TX	8369	Usage: 115 Hr Asset located in: Humble, TX 1996 Ingersoll Rand P-185 Mobile Air Compressor S/N: 263224UCG327 C/W: 200 psi Working Pressure, 4 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 1,522 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8370A	Sullivan D185PJD 185 cfm Mobile Air Compressor S/N: 31354 C/W: 110 psi Working Pressure, 2012 US EPA Label, CARB Compliant, John Deere 4024TF281A 4 Cylinder 37 kW 2.4 L Diesel Engine, S/A Trailer, Lunette Ring Usage: 332 Hr Asset located in: Humble, TX	8379	2013 Gardner-Denver TEE Electric Skid Mounted Triplex Fluid Pump S/N: Q021219 C/W: Baldor 125 hp 3 Phase Motor, 4 in Inlet, 1.5 in Outlet Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX-TX; RITCHIE-BROS-ENERGY Asset located in: Midland, TX
8370	Airman PDS185S-6C2 185 cfm Mobile Air Compressor S/N: MT51055 C/W: 200 psi Working Pressure, Yanmar 4TNV88-BDHKS 49 hp 2.1 L Diesel Engine, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Humble, TX	8380	2013 Gardner-Denver TEE Electric Skid Mounted Triplex Fluid Pump S/N: Q021220 C/W: Baldor 125 hp 3 Phase Motor, 4 in Inlet, 1.5 in Outlet Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX-TX; RITCHIE-BROS-ENERGY
8371	2017 Atlas Copco XAS110KDPE Mobile Air Compressor		Asset located in: Midland, TX
	S/N: APP451793 C/W: 260 bar Working Pressure, 2016 US EPA Label, CARB Compliant, Kubota D902-EF01 3 Cylinder 0.8 L Diesel Engine, S/A Trailer, Ball Hitch	8381	Pump S/N: Not Available C/W: John Deere 4039 4 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX
	Usage: 913 Hr	8382	Roots RCSH Vacuum Pump
	Asset located in: Humble, TX	8383	S/N: PB527294
8372	Air Compressor		Usage: Not Available Asset located in : Humble, TX
	S/N: Not Available Usage: Not Available		2015 Premier Mud Pump
	Asset located in: Humble, TX		S/N: 1P9BP1635FV591763
8373	skid mounted pressure tank S/N: Not Available Usage: Not Available Asset located in: Humble, TX		C/W: 8 in Intake, 8 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, CARB Compliant, John Deere 4045TF290A 4 Cylinder 56 kW 4.5 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes
8374	Air Compressor	1	Usage: 3,816 Hr
	S/N: AIA1573182/AIA1573183		Asset located in: Humble, TX
	Usage: Not Available	8384	Tulsa Rig Iron Pump
8375	Asset located in: Humble, TX 2008 Zeks Compressed Air Solutions 800NCEA400 Electric Air Dryer		S/N: TT150-52 C/W: Triplex 2014 US EPA Label, Cummins 6 Cylinder Diesel Engine Usage: 642 Hr
	S/N: 315719 C/W: 3 Phase Motor		Asset located in: Humble, TX
	Usage: Not Available	8385	Pai PAI70HP3250 Skid Mounted Triplex Pump
	Asset located in: Humble, TX	_	S/N: 1025666 C/W: 2003 US EPA Label, John Deere 4045 4
8376	Skid Mounted Power Swivel		Cylinder Diesel Engine
	S/N: Not Available Usage: Not Available		Usage: 168 Hr
	Asset located in: Humble, TX	0001	Asset located in: Humble, TX
8377	Pumping Unit S/N: DLFT101U025	—8386	2005 Sykes 300D Skid-Mounted Water Pump S/N: 5301029053 C/W: 12 in Intake, 12 in Discharge, Centrifugal
	C/W: 6 in Intake, 2.5 in Discharge, Centrifugal Chemical Pump Usage: Not Available		Water Pump, VOLVO PENTA TAD 721 VE 6 Cylinder Diesel Engine Usage: 4,304 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
8378	Pumping Unit		·
	S/N: DLFT100U021 C/W: 5 in Intake, 3 in Discharge, Centrifugal Chemical Pump Usage: Not Available Asset located in : Humble, TX		

Lot #	Details	Lot #	Details
8387	2014 Cornell 4NNTL-RP-F85 Electric Skid- Mounted Water Pump S/N: 195121 C/W: 4 in Intake, 4 in Discharge, Baldor Super E 25 hp electric motor Usage: 1,006 Hr Asset located in: Humble, TX	8394	2016 Cornell Trailer-Mounted Water Pump S/N: 1P9BP153XGV591048 C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 4 Cylinder 55 kW Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 1,159 Hr
8388	2012 Paco Pumps 10-25123 Skid-Mounted Electric Water Pump		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: Not Available C/W: 4 in Intake, 4 in Discharge, Centrifugal, Emerson 15 hp electric motor Usage: Not Available Asset located in: Humble, TX	8395	2016 Premier 6NNTPPD914L04 Trailer- Mounted Water Pump S/N: 1P9BP1385GV591036 C/W: 6 in Intake, 6 in Discharge, Centrifugal US
8389	2012 Paco Pumps 10-25123 Electric Skid- Mounted Water Pump S/N: Not Available C/W: Centrifugal, Emerson 15 hp electric motor Usage: Not Available		EPA Label, Deutz 914 L 04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 10,218 Hr Asset located in : Humble, TX
8390	Asset located in: Humble, TX 2012 Paco Pumps 10-25123 Electric Skid- Mounted Water Pump	8396	2016 Premier 4NNTLRP3CE1T Trailer-Mounted Water Pump S/N: 1P9BF1203GV591681 C/W: 4 in Intake, 4 in Discharge, Centrifugal
	S/N: Not Available C/W: 4 in Intake, 4 in Discharge, Centrifugal, Emerson 15 hp electric motor Usage: Not Available		Tier 4, 2015 US EPA Label, Kubota V1505-EF01 4 Cylinder 1.5 L Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 3,703 Hr
	Asset located in: Humble, TX	<u> </u>	Asset located in: Humble, TX
8391	Goodwin CD300M Trailer-Mounted Water Pump S/N: 0435462 C/W: 12 in Intake, 12 in Discharge, Centrifugal Water Pump, 2004 US EPA Label, Cat C-9 6 Cylinder 345 hp 8.8 L Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes Usage: 1,355 Hr	8397	2016 Premier 6NNTPPD914T80 Trailer- Mounted Water Pump S/N: 1P9BP1539GV501042 C/W: 6 in Intake, 6 in Discharge, Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 1,402 Hr
	Asset located in: Humble, TX		Asset located in: Humble, TX
8392	2015 Cornell 8NNTRP4045TF2 Trailer- Mounted Water Pump S/N: 1P9BP1635FV591701 C/W: 8 in Intake, 8 in Discharge, Self Priming Centrifugal Water Pump, 2015 US EPA Label, John Deere 4 Cylinder 4.5 L Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: Not Available	8398	2016 Premier 6NNTPPD914T80 Water Pump S/N: 160510 Usage: 1,514 Hr Asset located in: Humble, TX
		8399	2015 Premier 6NNT-RP-D914L04 Water Pump S/N: 150404 Usage: 4,973 Hr
	Asset located in: Humble, TX	8400	Asset located in: Humble, TX
8393	2017 Cornell 2 5H-RP-EM-16-3 Trailer-Mounted Water Pump S/N: Not Available C/W: 4 in Intake, 3 in Discharge, Self Priming	8400	2015 Premier 8NNT-PP-4045TF2 Water Pump S/N: 150551 Usage: 3,816 Hr Asset located in: Humble, TX
	Centrifugal Water Pump, 2004 US EPA Label, Deutz 4 Cylinder 75 hp Diesel Engine, S/A Trailer, Lunette Ring Usage: Not Available Asset located in : Humble, TX	8401	2015 Premier 6NNT-RP-D914L04 Trailer-Mounted Water Pump S/N: 200198 C/W: 6 in Intake, 6 in Discharge, Centrifugal Water Pump, US EPA Label, Deutz D19 L04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 5,718 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8402	2015 Premier 4NNT-PP-E25-S Skid-Mounted Water Pump S/N: 1P9BP1028FV591949 C/W: 4 in Intake, 4 in Discharge, Centrifugal Usage: 302 Hr Asset located in: Humble, TX	8408	2013 Cornell 6NNT-RP Trailer-Mounted Water Pump S/N: 1P9BP1539PV591685 C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge	
8403	2015 Premier 6NNT-RP-4045TF2 Trailer- Mounted Water Pump S/N: 91777 C/W: 6 in Intake, 6 in Discharge, Centrifugal John Deere Diesel Engine, S/A Trailer, Lunette Ring		Brakes Usage: Not Available Notes: LOCATED-IN-HOUSTON-TX-HOU DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Usage: 5,996 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX		2010 Pioneer PP66S12L Trailer-Mounted Water Pump S/N: Not Available C/W: Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring	
8404	2014 Premier 6NNTLRP Trailer-Mounted Water Pump		Usage: 1,177 Hr Asset located in: Humble, TX	
	S/N: 193174 C/W: 6 in Intake, 6 in Discharge, Centrifugal US EPA Label, Deutz D19 L04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 7,642 Hr Asset located in: Humble, TX	8410	Cornell Trailer-Mounted Water Pump S/N: Not Available C/W: 6 in Intake, 6 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 4 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: Not Available	
8405	2014 Premier 4NNTL-RP Trailer-Mounted Water Pump S/N: 140924		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	C/W: 4 in Intake, 4 in Discharge, Centrifugal Water Pump, Isuzu 3CE1-BDZP1E 3 Cylinder Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 5,465 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8411	Cornell 2.5H-RP-EM16-3 Trailer-Mounted Water Pump S/N: Not Available C/W: 3 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, Deutz 4 Cylinder 56 kW Diesel Engine, S/A Trailer, Lunette Ring Usage: 1,612 Hr	
8406	2013 Premier 6NNT-RP Trailer-Mounted Water Pump		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
8407	S/N: 185050 C/W: 6 in Intake, 6 in Discharge, Centrifugal 2012 US EPA Label, Deutz D19 L04 4 Cylinder 74 hp Diesel Engine, S/A Trailer, Lunette Ring, Surge Brakes Usage: 7,396 Hr Asset located in: Humble, TX 2013 Premier 6NNT-RP Trailer-Mounted Water	8412	8412	2011 Pioneer PP63C17L Trailer-Mounted Water Pump S/N: 17180 C/W: 6 in Intake, 3 in Discharge, Self Priming Centrifugal Water Pump, US EPA Label, Deutz 6 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 2,794 Hr Asset located in: Humble, TX
	Pump S/N: 185012 C/W: 4 in Intake, 4 in Discharge, Centrifugal Diesel Engine, S/A Trailer, Lunette Ring Usage: 4,163 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8413	Gorman-Rupp 14C2F3L Trailer-Mounted Water Pump S/N: 1153239 C/W: 4 in Intake, 4 in Discharge, Centrifugal Water Pump, Deutz 3 Cylinder Diesel Engine, S /A Trailer, Lunette Ring Usage: 30 Hr Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
8414	Cat C4.4 NLB TRIPLEX WATER BLASTER Hydraulic Power Pack S/N: 44408721 C/W: 2010 US EPA Label, Cat C4.4 4 Cylinder 4.4 L Diesel Engine Usage: 427 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8419	2016 Lincoln Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder S/N: U1160205208 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
8415	2019 Lincoln Vantage 549 Engine Driven Welder	8421	2013 Miller Big Blue Turbo 600 A Mobile Multi-	
	S/N: U1190410051 Usage: Not Available Asset located in : Humble, TX		Process Engine Driven Welder S/N: MD330191E C/W: 2012 US EPA Label, CARB Compliant, Deutz TD2011L04 4 Cylinder 70 hp 3.6 L Diesel	
8416	2019 Lincoln Vantage 549 Engine Driven Welder S/N: U0190600260		Engine, Welding Leads Not Included, S/A Trailer, Ball Hitch Usage: 2,621 Hr	
	Usage: Not Available Asset located in : Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
8418	2007 Lincoln Electric Vantage 500 500 A Skid-		Asset located in: Humble, TX	
	Mounted Multi-Process Engine Driven Welder S/N: U1070900459 C/W: 2007 US EPA Label, Deutz 49 hp 3.1 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 339 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8422	2019 Lincoln Vantage 549 525 A Mobile Multi- Process Engine Driven Welder S/N: U1190705538 C/W: Tier 4, 2019 US EPA Label, CARB Compliant, Deutz TD 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
8419B	2014 Lincoln Vantage 400 450 A Skid-Mounted		Asset located in: Humble, TX	
	Multi-Process Engine Driven Welder S/N: Not Available C/W: Tier 4, 2014 US EPA Label, CARB Compliant, Perkins 4 Cylinder Diesel Engine, Welding Leads Not Included, /17 kW Rated 3 Phase Output, 240 V Rated Voltage, /11 kW Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: 3,596 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	8423	2019 Lincoln Vantage 549 525 A Mobile Multi-Process Engine Driven Welder S/N: U1190607480 C/W: Tier 4, 2019 US EPA Label, CARB Compliant, Deutz TD2.9L4 36 kW 2.0 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 240 V / 120 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 4,806 Hr Asset located in: Humble, TX 2019 Lincoln Vantage 549 525 A Mobile Multi-	
	Asset located in: Humble, TX	8424	Process Engine Driven Welder	
8419A	Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,448 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		C C 2 Ir R U	S/N: U0190800142 C/W: Tier 4, 2019 US EPA Label, CARB Compliant, Deutz TD 2.9 L4 4 Cylinder 36.4 kW 2.9 L Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 240 V / 130 V Rated Voltage, S/A Trailer, Ball Hitch Usage: 5,129 Hr Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8426	Lincoln SA200 200 A Mobile Engine Driven	
	Asset located III. Hulliple, TA	I	Welder S/N: A98802 C/W: Diesel Engine, Welding Leads, 28 V Rated Voltage, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8427	1981 Miller SRH-555 500 A Skid-Mounted ARC Electric Welder S/N: JB492716 C/W: 3 Phase, 208 V/ 460 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX	8437	2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME421320L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX
8428	Miller Dimension 1000 Electric Welder S/N: Not Available C/W: 3 Phase, 230 V/ 460 V Input Usage: Not Available Asset located in: Humble, TX	8438	2015 Miller Maxstar 350 TIG 300 A TIG Electric Welder Electric Welder S/N: ME450710L C/W: 3 Phase, Single Phase, 115 V Input Usage: Not Available
8429	Miller Dimension 1000 Electric Welder S/N: Not Available C/W: 3 Phase, 220 V/ 460 V Input Usage: Not Available Asset located in: Humble, TX Lincoln Electric SAE-500 Stick Electric Welder	8439	Asset located in: Humble, TX 2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME421319L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller
0430	S/N: C1110100084 C/W: Kubota 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: 4,060 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8440	Usage: Not Available Asset located in: Humble, TX 2015 Miller Maxstar 350 300 A TIG Electric Welder S/N: MF041075L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller
8431			Usage: Not Available Asset located in: Humble, TX
	S/N: U1181200871 C/W: Tier 4, 2018 US EPA Label, Kubota V1505- BG-EF02 4 Cylinder 1.5 L Diesel Engine, Welding Leads Not Included Usage: 1,326 Hr Asset located in: Humble, TX	8441	2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME450711L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available
8432	Quantity of (3) Miller Auto-Axcess E675 300 A		Asset located in: Humble, TX
8434	Electric Welder S/N: MH081014U, MH081021U, MH081013U C/W: 3 Phase, Single Phase, 115 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX 2015 Miller Maxstar 350 300 A TIG Electric	8442	2014 Miller Maxstar 350 300 A TIG Electric Welder S/N: ME520036L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX
8435	Welder S/N: MF041076L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX 2015 Miller Maxstar 350 300 A TIG Electric Welder		Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX
	S/N: MF041071L C/W: 3 Phase, Single Phase, 115 V Input, Wire Feeder, Tip Tig Controller Usage: Not Available Asset located in: Humble, TX	8444	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads
8436	Quantity of (3) Miller Auto-Axcess 300 A Electric Welder S/N: MH081022U; MH081012U C/W: 3 Phase, Single Phase, 115 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX		Not Included Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8445	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input Usage: Not Available Asset located in: Humble, TX	8453A	2020 Doosan 6 kW Light Tower S/N: 4FVLSBAA0LU497951 C/W: Tier 4, 2019 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 234 Hr
8446	Quantity of (6) Lincoln Electric FlexTec 450 A		Asset located in: Humble, TX
8447	Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input Usage: Not Available Asset located in: Humble, TX	8453	2020 Terex RL4 6 kVA Light Tower S/N: 4ZJSA1017L1012470 C/W: 2019 US EPA Label, Kohler 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 848 Hr Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
0447	Quantity of (6) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator		Asset located in: Lake Worth, TX
0440	Welder S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX	8454	2019 Wacker Neuson 6 kW Light Tower S/N: 5XFLV0413KM000437 C/W: 2018 US EPA Label, CARB Compliant, Kohler 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 9,322 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
8448	Quantity of (6) Lincoln Electric FlexTec Skid- Mounted Multi-Process Multi-Operator Welder S/N: Not Available		THE INSPECTION REPORT Asset located in: Humble, TX
8449	C/W: 3 Phase, 380 V/ 575 V Input, Welding Leads Not Included Usage: Not Available Asset located in: Humble, TX Quantity of (3) Lincoln Electric FlexTec 450 A	8455	2018 Doosan LCV6WKUB-60HZ-T4F 6 kW Light Tower S/N: 4FVLSBAA4JU487646 C/W: 2018 US EPA Label, Kubota D1005-BG- EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S
	Skid-Mounted Multi-Process Multi-Operator Welder		/A Trailer, Ball Hitch Usage: 1,346 Hr Asset located in : Humble, TX
	S/N: Not Available C/W: 3 Phase, 38 V/ 28 V Input, Welding Leads Not Included Usage: Not Available Asset located in : Humble, TX	8456	2018 Magnum MLT6SMD 6 kW Light Tower S/N: 3003412000 C/W: 2018 US EPA Label, Mitsubishi l3e 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps,
8450	Quantity of (5) Lincoln Electric FlexTec 450 A Skid-Mounted Multi-Process Multi-Operator Welder S/N: Not Available C/W: 3 Phase, 380 V/ 575 V Input		LÉD Lighting, S/A Trailer, Ball Hitch Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	Usage: Not Available		2018 Magnum MLT6SMD Light Tower
8451	Asset located in: Humble, TX 2021 Terex RL4 6 kVA Light Tower S/N: 7FSBL1018MB946287 C/W: 2019 US EPA Label, Mitsubishi L3E 3 Cylinder 8 kW 1.0 L Diesel Engine, 4 Lamps, S /A Trailer, Ball Hitch Usage: 1,223 Hr		S/N: 7FSXL1017JB411999 C/W: 2018 US EPA Label, CARB Compliant, Mitsubishi L3E 3 Cylinder 19 kW 1.0 L Diesel Engine, 4 Lamps, LED Lighting, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,107 Hr Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8458	2018 Wanco WLTT 6 kW Light Tower S/N: 5F13D1017J1007641
8452	2019 Terex RL4 6 kVA Light Tower S/N: RL4J-10042 C/W: 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Kubota 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 4,456 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8459	2018 Magnum MLT6SK Light Tower S/N: 3003103485 Usage: 2,660 Hr Asset located in: Humble, TX	8465	2014 Magnum MLT3060 6 kW Light Tower S/N: SAJK141XE3400269 C/W: 2013 US EPA Label, Mitsubishi L3E 3 Cylinder Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch
8460	Allmand Night-Lite NL5000 8 kW Light Tower S/N: 06000788 C/W: Tier 4, 2016 US EPA Label, Kubota 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,133 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8466	Usage: 3,522 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Magnum 6 kW Light Tower S/N: 5AJLS1010EB411223 C/W: 2014 US EPA Label, Mitsubishi L3E 3
8461	Asset located in: Humble, TX 2016 Doosan 6 kW Light Tower S/N: 4FVLSACA5GU474212 C/W: Tier 4, 2015 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball		Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 1,898 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8462	Hitch Usage: 1,739 Hr Asset located in: Humble, TX 2016 Magnum MLT6SK 6 kW Light Tower S/N: 5AILS1016GB601871 C/W: Tier 4, 2015 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel	8467	2014 Magnum 6 kW Light Tower S/N: 1411833 C/W: 2014 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 4,501 Hr Asset located in: Humble, TX
	Engine, 4 Lamps, Power Receptacles, S/A Trailer, Lunette Ring Usage: 5,242 Hr Asset located in: Humble, TX		2014 Magnum 6 kW Light Tower S/N: 1411836 C/W: 2014 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, S/A Trailer, Ball Hitch
8463A	2016 Doosan 6 kVA Light Tower S/N: 472214UJZG08 C/W: Tier 4, 2015 US EPA Label, Kubota D1005- BG-EF02 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 2,343 Hr		Usage: 4,405 Hr Notes: LIGHT TOWER MAST AND MISSING-PLEASE SEE INSPECTION DEFICIENCIES NOTED - PLEASE SINSPECTION REPORT
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8469	2013 Magnum MLT0360K 6 kW Light Tower S/N: 1306082 C/W: Tier 4, 2013 US EPA Label, CARB
8463	2016 Magnum MLT3060 6 kW Light Tower S/N: 5AJLS1416GB602786 C/W: 2015 US EPA Label, Mitsubishi L3E 3 Cylinder 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, Electric Winch Raise and Lower, S	8470	Compliant, Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 5,996 Hr Asset located in : Humble, TX
	/A Trailer, Lunette Ring Usage: 3,689 Hr Asset located in: Humble, TX		2013 Magnum MLT0360K 6 kW Light Tower S/N: 1307067 C/W: Tier 4, 2013 US EPA Label, CARB
8464	S/N: 1410888 C/W: Tier 4, 2014 US EPA Label, CARB Compliant, Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, Power		Compliant, Kubota D1005-BG-EF02 3 Cylinder 10.8 kW 1.0 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 7,074 Hr Asset located in : Humble, TX
		8471	2007 Magnum 6 kW Light Tower S/N: 5AJLS16117B000424 C/W: Mitsubishi 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 3,222 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8472	2007 Allmand 6 kW Light Tower S/N: Not Available C/W: Kubota D902 3 Cylinder 0.9 L Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 3,132 Hr	8480	2019 Construction Electrical Prod 5322 Portable Work Lights S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8481	2016 Work Area Protection SMC1000T Solar
8473	Asset located in: Humble, TX 2007 Allmand Light Tower S/N: 2761PR C/W: Tier 2, 2007 US EPA Label, Kubota D905-BG-ES01 3 Cylinder 0.8 L Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch		Message Board S/N: 1P91D1213GG301356 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 4,413 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8482	Asset located in: Humble, TX 2015 Message Board S/N: 5F12S1616F1002005 C/W: LED Lighting, Solar Powered, Hydraulic
8474	2006 Magnum 6 kW Light Tower S/N: 060474 C/W: Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 6,384 Hr		Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8475	Asset located in: Humble, TX 2006 Magnum Light Tower S/N: Not Available C/W: 3 Cylinder Diesel Engine, S/A Trailer, Ball Hitch Usage: 2,853 Hr	8483	2014 Wanco WTLMB Solar Message Board S/N: 5F12S1610E1001836 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8484	2014 Wanco WTMMB Solar Message Board S/N: 5F12S1616E1001016 C/W: Solar Powered, Hydraulic Raise and
8476	2006 Magnum Light Tower S/N: 060977 C/W: 2005 US EPA Label, CARB Compliant,		Lower, S/A Trailer, Ball Hitch Usage: Not Available Asset located in : Humble, TX
	Mitsubishi 3 Cylinder 13 hp Engine, 4 Lamps, S /A Trailer Usage: 1,690 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8485	2005 Message Board S/N: 5F12S161X51004131 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
8477	2005 Magnum 6 kW Light Tower S/N: 057918		THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 3 Cylinder Diesel Engine, 4 Lamps, S/A Trailer, Ball Hitch Usage: 5,481 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8486	2010 Solar Tech Silent Sentinel Message Board S/N: 4GM1A091XA1523805 Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8478	2005 Magnum 6 kW Light Tower	8487	<u> </u>
0470	S/N: 056332 C/W: Diesel Engine, 4 Lamps, Power Receptacles, S/A Trailer, Ball Hitch Usage: 3,739 Hr Asset located in: Humble, TX	0407	2004 Solar Tech Message Board S/N: 4GM2M151X41408942 C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Electric Brakes Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
8479	2019 Construction Electrical Prod 5322 Portable Work Lights		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8488	Electric Radar Speed Limit Sign S/N: 7L31E7219KF050272 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8489	2015 Hill And Smith CONSAM Radar Speed Limit Sign S/N: 7L31E7218F050523 Usage: Not Available Asset located in: Humble, TX 2018 Synergy AF100 Automated Flagger S/N: 180504 C/W: Flagger A & B	8496	Quantity of (300) 2024 KJ K1428 28 in Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	8497	Quantity of (300) 2024 KJ K1428 28 in Traffic
8491	Quantity of (250) 2024 AGT AGT-75TC Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	8498	Quantity of (300) 2024 KJ K1428 28 in Traffic
8492	Quantity of (250) 2024 AGT AGT-75TC Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8499	Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Quantity of (300) 2024 KJ K1428 28 in Traffic
0400	Asset located in: Humble, TX		Cones (Unused)
8493	Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8500	
8494	Quantity of (250) 2024 Suihe TC-250 Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE		Traffic Cones (Unused) S/N: 7-1 Usage: Not Available Asset located in: Humble, TX
	FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8501	Quantity of (2) Pallets of 2024 CXT C-75 Traffic Cones (Unused) S/N: 7-2 Usage: Not Available Asset located in: Humble, TX
8495	Quantity of (300) 2024 KJ K1428 28 in Traffic	8502	Quantity of (252) 2024 Agriquip GL28TC
0430	Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8503	Traffic Cones (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Quantity of Traffic Barrels & Bases
			S/N: Not Available C/W: road barricades Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8504 8505	Quantity of (100) 2024 AGT AGT-TBB Delineators (Unused) S/N: Not Available C/W: Bunting Usage: Not Available Asset located in: Humble, TX Quantity of (100) 2024 Agriquip GLTD45	8512	2024 4-Fuel.com 1100 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005267 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available
	Delineators (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8513	Asset located in: Humble, TX 2024 4-Fuel.com 838 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005268 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
8506 8507	Quantity of (8) Water Wall Barrier S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Quantity of (6) Airport Barricades	8514	2024 4-Fuel.com 838 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005269 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	8515	Asset located in: Humble, TX AM-Tank 800 838 gal Skid Mounted Steel
8508	AM-Tank 2300N 2376 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82540 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available		Diesel Fuel Tank (Unused) S/N: 82541 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
8509	Asset located in: Humble, TX AM-Tank 2300N 2376 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82539 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment	8516 8517 8518	AM-Tank 800 838 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82542 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX
8510	Usage: Not Available Asset located in: Humble, TX 2024 4-Fuel.com 2330 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005265 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: 000003533 C/W: 120 V Transfer Pump, 13 ft Meter, Automatic Shut-Off Nozzle Containment Usage: Not Available Asset located in: Humble, TX
8511	2024 4-Fuel.com 2330 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 000005266 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel		S/N: Not Available C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX
		8519	AM-Tank 600 655 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82544 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8520	AM-Tank 600 655 gal Skid Mounted Steel Diesel Fuel Tank (Unused) S/N: 82543 C/W: 120 V Transfer Pump, 13 ft Hose, Fuel Meter, Automatic Shut-Off Nozzle, Spill Containment Usage: Not Available	8531 8532	Transcube 20TCG 986 L Skid Mounted Steel Fuel Tank S/N: A61282840 Usage: Not Available Asset located in: Humble, TX 2012 Transcube 30TCG 792 gal Steel Fuel Tank
8521	Asset located in: Humble, TX 2014 Transcube 30TCG Skid Mounted Steel		S/N: 1046 Usage: Not Available
	Fuel Tank S/N: A60499814 Usage: Not Available Asset located in: Humble, TX	8533	Asset located in: Humble, TX 300 gal Skid Mounted Steel Fuel Tank (Unused) S/N: Not Available C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle
8522	2013 Transcube 30TCG Fuel Tank S/N: D727197 Usage: Not Available Asset located in: Humble, TX	8534	Usage: Not Available Asset located in: Humble, TX 2024 4-Fuel.com 116 gal Portable Poly Diesel
8523	2017 Transcube 20TCG Fuel Tank S/N: 16006358 Usage: Not Available Asset located in: Humble, TX		Fuel Tank (Unused) S/N: 000005270 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8524	2017 Transcube 20TCG Fuel Tank S/N: 16006350 Usage: Not Available Asset located in: Humble, TX	8535	2024 4-Fuel.com 116 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005271 C/W: 12 V Transfer Pump, 13 ft Hose,
8525	2017 Transcube 20TCG 525 gal Steel Fuel Tank S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8526	2016 Transcube 20TCG Fuel Tank S/N: A61281759 Usage: Not Available Asset located in: Humble, TX	8536	2024 4-Fuel.com 116 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005272 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle
8527	2016 Transcube 20TCG Fuel Tank S/N: A61281757 Usage: Not Available	8537	Usage: Not Available Asset located in: Humble, TX 2024 4-Fuel.com 116 gal Portable Poly Diesel
8528	Asset located in: Humble, TX 2016 Transcube 20TCG 528 gal Skid Mounted Steel Fuel Tank S/N: A61281790 Usage: Not Available		Fuel Tank (Unused) S/N: 000005273 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8529	Asset located in: Humble, TX 2014 Transcube 20TCG 528 gal Trailer Mounted Steel Fuel Tank S/N: 431FS0729E5000430 C/W: 12 V Transfer Pump Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8538 8539	AM-Tank 116 gal Portable Poly Fuel Tank (Unused) S/N: 10575Q C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX AM-Tank 116 gal Portable Poly Diesel Fuel
8530	Asset located in: Humble, TX 2015 Transcube 20TCG Fuel Tank S/N: A60756307 Usage: Not Available Asset located in: Humble, TX	_	Tank (Unused) S/N: 10577Q C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8540	AM-Tank 116 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 10574Q C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8557	AM-Tank 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 58002A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8541	Teran TDT116GL Fuel Tank (Unused)	8558	AM-Tank 58 gal Portable Poly Diesel Fuel Tank
0341	S/N: 46544L C/W: Polyethylene tank for diesel fuel transport equipped with a fuel transfer unit, 116 gal with 12V Pump (12GPM), 13ft Hose, Auto-Nozzle, Top Covering Lid. Usage: Not Available Asset located in: Humble, TX		(Unused) S/N: 58003A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8551	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005274 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8559	AM-Tank 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 58001A C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8552	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005275 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8560	AM-Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 12201E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8553	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005276 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8561	AM-Tank 29 gal Portable Poly Fuel Tank (Unused) S/N: 12202E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8554	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005277 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	8562	AM-Tank 29 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 12203E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8555	2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005278 C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available	8563	AM-Tank 29 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 12204E C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
8556	Asset located in: Humble, TX 2024 4-Fuel.com 58 gal Portable Poly Diesel Fuel Tank (Unused) S/N: 000005279	8564	4000 Gallon Vertical Steel Storage Tank S/N: 19116 Usage: Not Available Asset located in : Humble, TX
	C/W: 12 V Transfer Pump, 13 ft Hose, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX	8565	4000 Gallon Vertical Steel Storage Tank S/N: 19114 Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8566	4000 Gallon Vertical Steel Storage Tank S/N: 19119 Usage: Not Available Asset located in: Humble, TX	8577	2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused) S/N: M202408566 C/W: Lattice Frame, Folding End Section,
8567	4000 Gallon Vertical Steel Storage Tank S/N: 19117		Manual Raise, Pintle Ring Usage: Not Available
	Usage: Not Available	8578	Asset located in: Humble, TX 2024 Vickwest PRS36-60 36 in x 60 ft Portable
8568	Asset located in: Humble, TX 4000 Gallon Vertical Steel Storage Tank S/N: 19120 Usage: Not Available Asset located in: Humble, TX	6576	Radial Stacking Conveyor (Unused) S/N: M202408567 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available
8569	4000 Gallon Vertical Steel Storage Tank S/N: 19115 Usage: Not Available Asset located in : Humble, TX	8579	Asset located in: Humble, TX 2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused) S/N: M202408568
8570	4000 Gallon Vertical Steel Storage Tank S/N: 19113 Usage: Not Available Asset located in: Humble, TX		C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Asset located in : Humble, TX
8571	4000 Gallon Vertical Steel Storage Tank S/N: 19118 C/W: A Usage: Not Available Asset located in: Humble, TX	8580	2024 Raystone RMC36-60 36 in x 60 ft Portable Conveyor (Unused) S/N: MC20240825011 C/W: Pintle Ring, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT
8572	40 Gal Aluminum Fuel Tank S/N: Not Available Usage: Not Available		REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
8573	Asset located in: Humble, TX AM-Tank Sprayer 14 55 L 14 gal NH3 Tank (Unused) S/N: Not Available C/W: Poly Tank, 3 ft Pup Usage: Not Available Asset located in: Humble, TX	8581	2024 Raystone RMC36-60 36 in x 60 ft Portable Conveyor (Unused) S/N: MC20240825012 C/W: Pintle Ring, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
8574	AM-Tank Sprayer 29 110 L 29 gal NH3 Tank (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8582	Asset located in: Humble, TX 2008 Stewart Glapat 2787T30SP Electric Extendable Dock Conveyor S/N: 08223102 C/W: Pallet Jack, Tubs, Chain Usage: Not Available
8575	250 gal Steel Oil Tank S/N: Not Available C/W: graco pneumatic pump Usage: Not Available Asset located in: Humble, TX	8583	Asset located in: Humble, TX 2024 Genius GSM-66IN 32 In. x 6 Ft Separator Magnet (Unused) S/N: GSM08101
8576	2024 Vickwest PRS36-60 36 in x 60 ft Portable Radial Stacking Conveyor (Unused)		Usage: Not Available Asset located in: Humble, TX
	S/N: M202408565 C/W: Lattice Frame, Folding End Section, Manual Raise, Pintle Ring Usage: Not Available Asset located in : Humble, TX	8584	2024 Genius GSM-66IN 32 In. x 6 Ft Separator Magnet (Unused) S/N: GSM08102 Usage: Not Available
	, too too too too too too too too too to	0505	Asset located in: Humble, TX
		8585	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset Joseph In: Humble TV

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8586	2024 Landhonor SM-66-3206E 32 in x 6 ft Permanent Separator Magnet (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8594	4 Erie Industries GF480 Trommel Screen (Unused) S/N: GF480J24N030907 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION C
8587	2024 KJ K315 Grizzly Screen (Unused) S/N: Not Available C/W: 10 ft x 7 ft Screen Usage: Not Available Asset located in: Humble, TX	8595	THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX Erie Industries GF480 Screen (Unused)
8588	2024 KJ K315 Grizzly Screen (Unused) S/N: Not Available C/W: 10 ft x 7 ft Screen Usage: Not Available Asset located in: Humble, TX		S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
8589	2024 Suihe VG Skid-Mounted Vibratory Screen (Unused) S/N: 00405395 C/W: 5 ft x 4 ft 6 in Double Deck Screen, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8596 8597	Asset located in: Humble, TX 2024 Jisan 40 ft One-Way High Cube Multi- Door Storage Container S/N: JPCU2215010 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX 2024 Jisan 40 ft One-Way High Cube Multi-
8590	Usage: Not Available Asset located in: Humble, TX 2024 Paladin SMS-64-40G Skid-Mounted Screen (Unused) S/N: Not Available		Door Storage Container S/N: JPCU2305942 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
8591	C/W: 4 ft 10 in x 4 ft 6 in Double Deck Screen Usage: Not Available Asset located in: Humble, TX Erie Industries GF150 Skid-Mounted Vibratory Topsoil Rock Screen (Unused) S/N: Not Available	8598	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU2305963 C/W: One-Way Usage: Not Available Asset located in: Humble, TX
	C/W: Single Deck Screen, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8599	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU2305578 C/W: One-Way Usage: Not Available Asset located in: Humble, TX
8592	Erie Industries GF480 Trommel Screen (Unused) S/N: GF48F01426 C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available	8600 8601	2024 40 ft High Cube Multi-Door Storage Container S/N: JPCU2213682 C/W: One-Way Usage: Not Available Asset located in: Humble, TX 2024 40 ft High Cube Multi-Door Storage
8593	Asset located in: Humble, TX Erie Industries GF480 Trommel Screen (Unused) S/N: GF48F01726 C/W: THE PRODUCT IMAGES SHOWN ARE		Container S/N: JPCU2212578 C/W: One-Way Usage: Not Available Asset located in: Humble, TX
	C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8602	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4013038 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8603	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4013090 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX	8612	2024 Suihe NC-40HQ -4 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0170731 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
8604	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4015323 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX	8613	2024 Suihe SC-40HQ -4 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYGU0171963 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX
8605	2024 AGT 40 ft One-Way High Cube Multi-Door Storage Container S/N: CFGU4013655 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX	8614	JESON 40 ft One-Way High Cube Storage Container S/N: HHXU3326668 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available
8606	2024 Suihe NC-40HQ-2 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0168420 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX	8615	Asset located in: Humble, TX 2024 ZHW 40 ft One-Way High Cube Multi- Door Storage Container S/N: CICU6661489 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX
8607	2024 Suihe NC-40HQ -4 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0170726 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX	8616	2024 40 ft High Cube Multi-Door Storage Container S/N: LYGU4147902 C/W: One-Way Usage: Not Available Asset located in: Humble, TX
8608	2024 Suihe NC-40HQ -3 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0167070 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX	8617A	40 ft Storage Container S/N: HHXU3289250 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX
8609	2024 CTN 40HQ 40 ft One-Way High Cube Multi-Door Storage Container S/N: MMPU1040241 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available Asset located in: Humble, TX	8617	2024 40 ft High Cube Multi-Door Storage Container S/N: LYGU4147899 C/W: One-Way Usage: Not Available Asset located in: Humble, TX
8610	2024 Suihe NC-40HQ-2 40 ft One-Way High Cube Multi-Door Storage Container S/N: LYPU0168462 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box Usage: Not Available	8618	2009 40 ft High Cube Storage Container S/N: TCNU8813996 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
8611	Asset located in: Humble, TX 2024 Suihe NC-40HQ-2 40 ft High Cube Multi- Door Storage Container S/N: LYPU0168436 C/W: 8 ft Wide, 9 ft 6 in High	8619	2004 40 ft High Cube Storage Container S/N: TDRU5550681 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	8620	40 ft High Cube Storage Container S/N: TCNU9762466 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8621	40 ft High Cube Storage Container S/N: IKSU8661283 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX	8632	40 ft High Cube Storage Container S/N: TCLU5438620 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX
0622		0622	· · · · · · · · · · · · · · · · · · ·
8622	40 ft High Cube Storage Container S/N: TCNU9624045 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8633	40 ft High Cube Storage Container S/N: TCKU9956976 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX 40 ft High Cube Storage Container
	Asset located in: Humble, TX	8634	S/N: APHU6736762
8623	40 ft High Cube Storage Container S/N: TRLU7025311 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available		C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8635	40 ft High Cube Storage Container S/N: APHU6737028
8624	40 ft High Cube Storage Container S/N: ZCSU8986893 C/W: 8 ft Wide, 9 ft 6 in High		C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	8636	40 ft High Cube Storage Container
8625	2007 CIMC 40 ft High Cube Storage Container S/N: CMAU5102273 C/W: 8 ft Wide, 9 ft 6 in High		S/N: CMAU5059496 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX	8637	40 ft High Cube Storage Container
8626	40 ft High Cube Storage Container S/N: APHU6652390 C/W: 8 ft Wide, 9 ft 6 in High	8638	S/N: APHU6593912 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available Asset located in: Humble, TX		40 ft High Cube Storage Container
8627	40 ft High Cube Storage Container S/N: CMAU5109508 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available		S/N: TRLU8264732 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8639	•
8628	40 ft High Cube Storage Container S/N: CMAU4052250 C/W: 8 ft Wide, 9 ft 6 in High		S/N: CMAU5242716 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	8640	40 ft Storage Container
8629	Asset located in: Humble, TX 40 ft High Cube Storage Container S/N: TCLU5050785 C/W: 8 ft Wide, 9 ft 6 in High		S/N: TCLU5328270 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	8641	40 ft Storage Container
8630	Asset located in: Humble, TX 40 ft High Cube Storage Container S/N: TCLU9354852		S/N: Not Available C/W: 8 ft Wide, 8 ft 6 in High Usage: Not Available
	C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8631	40 ft High Cube Storage Container	8642	40 ft High Cube Refrigerated Storage Container
5551	S/N: TRLU6661134 C/W: 8 ft Wide, 9 ft 6 in High Usage: Not Available Asset located in: Humble, TX	0042	S/N: TRIU8740325 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Carrier 69NT40 Reefer Unit Usage: Not Available

Lot #	Details	Lot #	Details
8643	40 ft Refrigerated Storage Container S/N: CBFU3468582 C/W: Carrier Reefer Unit Usage: Not Available Asset located in: Humble, TX	8652	20 ft High Cube Storage Container S/N: SPWU3005466 C/W: 8 ft Wide, 9 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available
8644	2024 20 ft One-Way High Cube Multi-Door Storage Container S/N: VSLU2173753		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 8 ft Wide, 9 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8653	20 ft One-Way Storage Container S/N: CICU6417050 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets
8645	2024 20 ft One-Way Multi-Door Storage		Usage: Not Available Asset located in : Humble, TX
	Container S/N: VSLU2173938 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8654	20 ft One-Way Storage Container S/N: CICU6417174 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX
8646	2024 20 ft One-Way Multi-Door Storage Container	8655	20 ft One-Way Storage Container
	S/N: VSLU2174071 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available	8033	S/N: CICU6359709 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in : Humble, TX
06.47	Asset located in: Humble, TX	8656	20 ft One-Way Storage Container
8647	2024 20 ft One-Way Multi-Door Storage Container S/N: VSLU2174153 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available	8030	S/N: CICU6417045 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8657	20 ft One-Way Storage Container
8648	2024 20 ft One-Way Multi-Door Storage Container S/N: VSLU2174430 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets		S/N: CICU6417106 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in : Humble, TX
	Usage: Not Available	8658	20 ft Storage Container
8649	Asset located in: Humble, TX 2024 20 ft One-Way Multi-Door Storage Container S/N: VSLU2173584 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork	-	S/N: XHCU2623730 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in : Humble, TX
	Pockets Usage: Not Available Asset located in: Humble, TX	8659	20 ft Standard Double-Ended Storage Container S/N: SPRU2613829 C/W: One-Way Usage: Not Available
8650	2024 SHANG 20 ft One-Way Storage Container		Asset located in: Humble, TX
	S/N: ZXJU0137350 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in : Humble, TX	8660	20 ft Standard Double-Ended Storage Container S/N: SPRU2614358 C/W: One-Way Usage: Not Available
8651	20 ft Storage Container S/N: XHCU2623659 C/W: 8 ft Wide, 8 ft 6 in High, Lock Box, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8661	Asset located in: Humble, TX 20 ft Standard Storage Container S/N: SPRU3089845 C/W: One-Way Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8662	20 ft Standard Storage Container S/N: SPRU3088670 C/W: One-Way Usage: Not Available	8672	20 ft Storage Container S/N: TCKU3007102 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
8663	8 20 ft Storage Container S/N: TCKU1570605 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	8673	20 ft Storage Container S/N: TCKU2940860 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	8674	20 ft Storage Container
8664	20 ft Storage Container S/N: TCKU3956053 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets		S/N: APZU3402553 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available	8675	20 ft Storage Container
8665	Asset located in: Humble, TX 20 ft Storage Container S/N: TCKU1623794 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets		S/N: TCKU1447458 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX
0666	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8676	20 ft Storage Container S/N: TTNU1361095 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
8666	20 ft Storage Container S/N: TCKU1364559	8677	Asset located in: Humble, TX
	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX		20 ft Storage Container S/N: SUDU1343404 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
8667	20 ft Storage Container S/N: APZU3283270		Asset located in: Humble, TX
	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in : Humble, TX	8678	20 ft Storage Container S/N: TTNU1979289 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available
8668	20 ft Storage Container S/N: TCLU3105106		Asset located in: Humble, TX
	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8679	20 ft Storage Container S/N: APZU3448826 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	8680	20 ft Storage Container
8669	20 ft Storage Container S/N: TRHU3827244 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available	0000	S/N: APZU3383509 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8681	20 ft Storage Container
	Asset located in: Humble, TX		S/N: TCLU2211510 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets
8670	20 ft Storage Container		Usage: Not Available
	S/N: APZU3294778 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available	8682	Asset located in: Humble, TX 2
	Asset located in: Humble, TX		S/N: TCKU1449907 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets
8671	20 ft Storage Container S/N: TCKU2518089 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX		Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8683	20 ft Storage Container S/N: CMAU1462440 C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8691	2024 12 ft Storage Container S/N: KJ12-024 C/W: One-Way, Man Door, Window Usage: Not Available Asset located in: Humble, TX	
8684	Asset located in: Humble, TX 20 ft Storage Container S/N: TCKU1923533	8692	12 ft Storage Container S/N: Not Available C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available	
	C/W: 8 ft Wide, 8 ft 6 in High, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8693	Asset located in: Humble, TX Erie Industries 12HC 12 ft One-Way Storage	
0605	·	\dashv	Container	
8685	20 ft Standard Storage Container S/N: HSMT001531 Usage: Not Available		S/N: SQ5183062 C/W: 7 ft Wide, Single Walk Door, Window, Fork Pockets, THE BROCHURE IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY	
8686	Asset located in: Humble, TX 2024 AGT 12 ft x 7 ft 12 ft One-Way Storage Container S/N: CFGU1005785 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR	8694	AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN SLIGHT COLOR VARIATIONS. Usage: Not Available Asset located in: Humble, TX	
	ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8094	Erie Industries 12HC 12 ft One-Way Storage Container S/N: SV6180036 C/W: 7 ft Wide, Single Walk Door, Window, Fork Pockets, THE BROCHURE IMAGES SHOWN	
8687	2024 AGT 12 ft x 7 ft 12 ft One-Way Storage Container S/N: CFGU1004900 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX		ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT. THIS PRODUCT COMES IN SLIGHT COLOR VARIATIONS. Usage: Not Available Asset located in: Humble, TX	
		8695	2024 10 ft Storage Container S/N: KJ10A-015 C/W: One-Way, Man Door, Window Usage: Not Available	
8688	2024 AGT 12 ft One-Way Storage Container S/N: CFGU1003247 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT	8696	Asset located in: Humble, TX 2024 Suihe NMC-9G 9 ft One-Way Storage Container S/N: GMPU9020965 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available	8697	2024 AGT 9 ft One-Way Storage Container	
8689	Asset located in: Humble, TX 2024 Suihe NMC-12G 12 ft One-Way Storage Container S/N: GMPU9014854 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk		S/N: CFGU1000021 C/W: 6 ft 8 in Wide, 7 ft 5 in Door, Lock Box, Window, For Usage: Not Available	S/N: CFGU1000021 C/W: 6 ft 8 in Wide, 7 ft 5 in High, Single Walk Door, Lock Box, Window, Fork Pockets
	Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in : Humble, TX	8698	2024 AGT 9 ft One-Way Storage Container S/N: CFGU1000280 C/W: 6 ft 8 in Wide, 7 ft 5 in High, Single Walk	
8690	2024 Suihe NMC-12G 12 ft One-Way Storage Container S/N: GMPU9021940 C/W: 7 ft 3 in Wide, 8 ft 3 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX		Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8699	2024 AGT 9 ft x 6 ft 9 ft One-Way Storage Container S/N: CFGU1000633 C/W: 6 ft 8 in Wide, 7 ft 5 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX 9 ft Storage Container	8709	Quantity of (2) Erie Industries TG10 Self- Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
0700	S/N: CFGU1001136		Asset located in: Humble, TX
	C/W: One-Way, Man Door, Window Usage: Not Available Asset located in : Humble, TX	8710	Quantity of (2) Erie Industries TG10 Self- Dumping Hopper (Unused) S/N: Not Available
8701	9 ft Storage Container S/N: AGT23030911 C/W: One-Way, Man Door, Window Usage: Not Available Asset located in: Humble, TX		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX
8702	2024 Suihe NMC-8G 8 ft One-Way Storage	8711	Quantity of (2) Erie Industries TG10 Self-
	Container S/N: GMPU9021447 C/W: 6 ft 8 in Wide, 7 ft 5 in High, Single Walk Door, Lock Box, Window, Fork Pockets Usage: Not Available Asset located in: Humble, TX	8711	Dumping Hopper (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT
8703	16 ft Roll-Off Container (Unused)	_	Usage: Not Available
0,00	S/N: Not Available C/W: 16 ft Long x 7 ft 3 in Wide x 4 ft 9 in High Usage: Not Available Asset located in: Humble, TX	8712	Asset located in: Humble, TX Quantity of (2) Erie Industries TG10 Self- Dumping Hopper (Unused) S/N: Not Available
8704	16 ft Roll-Off Container (Unused) S/N: Not Available C/W: 16 ft Long x 7 ft 3 in Wide x 4 ft 9 in High Usage: Not Available		C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
8705	Roll-Off Container (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8713	2024 Kit Containers 2YFT-SDH 5 ft 3 in 2 cu ye Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 1 in Wide x 3 ft 10 in
8706	Roll-Off Container S/N: Not Available Usage: Not Available		High Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	8714	2024 Kit Containers 2YFT-SDH 5 ft 3 in 2 cu yd
8707	2024 Kit Containers 4Y-DH Debris Box (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX		Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Humble, TX
8708	Quantity of (2) 2024 Suihe N-1CY -2 3 ft 6 in 1 cyd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 3 ft 6 in Long x 3 ft 8 in Wide x 3 ft 4 in High, Fork Pockets, THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	8715	2024 Kit Containers 2YFT-SDH 5 ft 3 in 2 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 3 in Long x 4 ft 1 in Wide x 3 ft 10 in High Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8716	2024 Kit Containers 1.5YFT-SDH 5 ft 2 in 1.5 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 2 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available Asset located in: Humble, TX	8725 8726	Kubota ZD1211 Zero-Turn Lawn Mower S/N: 13587 C/W: Hydrostatic Drive, 15x6.00x6 Front Tires, 26x12.00x16 Rear Tires, 60 in Mower Usage: 3,223 Hr Asset located in: Humble, TX Kubota Z122EBR Zero-Turn Lawn Mower
8717	2024 Kit Containers 1.5YFT-SDH 5 ft 2 in 1.5 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 2 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available		S/N: 19525 C/W: Hydrostatic Drive, 2016 US EPA Label, CARB Compliant, 13X5.00-6 Front Tires, 22x10- 14 Rear Tires, 48 in Mower Usage: 280 Hr Asset located in: Humble, TX
8718	Asset located in: Humble, TX 2024 Kit Containers 1.5YFT-SDH 5 ft 2 in 1.5 cu yd Self-Dumping Hopper (Unused) S/N: Not Available C/W: 5 ft 2 in Long x 4 ft 2 in Wide x 3 ft 3 in High Usage: Not Available		2017 Kubota Z121SKH Zero-Turn Lawn Mower S/N: 21732 C/W: Canopy, Hydrostatic Drive, 2016 US EPA Label, 11x4.00-5 Front Tires, 22x10-14 Rear Tires, 48 in Mower Usage: 168 Hr Asset located in: Humble, TX
8719	Asset located in: Humble, TX Quantity of (3) Self-Dumping Hopper S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8728	2009 Kubota ZG222 Zero-Turn Lawn Mower S/N: 12120 C/W: Hydrostatic Drive, 2008 US EPA Label, 13x5.00x8 Front Tires, 23x10.50x12 Rear Tires, 48 in Mower Usage: 105 Hr
8720	Kit Containers 4Y-DH Debris Box (Unused) S/N: Not Available Usage: Not Available Asset located in: Humble, TX	8729	Asset located in: Humble, TX 2007 Kubota ZD331LP Zero-Turn Lawn Mowe S/N: 10045 C/W: Hydrostatic Drive, 15x6.00x6 Front Tires
8721	2019 Kubota ZD1211 Zero-Turn Lawn Mower S/N: KBGGDCA0CKGM41563 C/W: Hydrostatic Drive, 2019 US EPA Label, 15x6.50-8 Front Tires, 26x12-16 Rear Tires, 60 in Mower Usage: 615 Hr		26x12.00x12 Rear Tires, 72 in Mower Usage: 1,026 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX John Deere 1445 4x4 Ride-On Lawn Mower
8722	Asset located in: Humble, TX 2019 Kubota Z122RKW Zero-Turn Lawn Mower S/N: 22672 C/W: Hydrostatic Drive, 2016 US EPA Label, 11x4.00-5 Front Tires, 18x7.50x10 Rear Tires, 42 in Mower Usage: 333 Hr Asset located in: Humble, TX		S/N: Not Available C/W: CVT, 2007 US EPA Label, CARB Compliant, 24x12.00-12 Front Tires, 215/50-10 Rear Tires, 72 in Mower Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8723	Kubota Z122RKW-42 Zero-Turn Lawn Mower S/N: 20986 C/W: 2016 US EPA Label, 11x4.00-5 Front Tires, 18x7.5 Rear Tires, 42 in Mower Usage: Not Available	8731	John Deere Lawn Mower S/N: Not Available Usage: Not Available Asset located in: Humble, TX
8724	Asset located in: Humble, TX Kubota ZD121160 Zero-Turn Lawn Mower S/N: 14174 C/W: Hydrostatic Drive, 15x6.00x6 Front Tires, 26x12.00x12 Rear Tires, 60 in Mower	8732	2023 Cub Cadet Ride-On Lawn Mower S/N: 1F21PK60338 C/W: Hydrostatic Drive, 13x5.00-6 Front Tires, 16x6.50-8 Rear Tires, 30 in Mower Usage: Not Available Asset located in: Humble, TX
	Usage: 1,382 Hr Asset located in: Humble, TX	8733	2024 Cub Cadet Ride-On Lawn Mower S/N: 1D09RK60042 C/W: Hydrostatic Drive, 13x5.00-6 Front Tires, 16x6.50-8 Rear Tires, 30 in Mower Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8737	2024 LANM LAM800 Remote Control Crawler	8747	2024 DYC GFXX-4 Electric Golf Cart (Unused)
	Lawn Mower (Unused)		S/N: 202407364
	S/N: LAM240829 C/W: 22 in Mower		C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX	8748	2023 Kandi KS4PSLR-B Electric Golf Cart
8738	Bad Boy Buggies Electric Utility Cart		(Unused)
	S/N: 00022		S/N: A07DE5W8CPC001596
	C/W: Canopy, 4 Passenger, Winch, Brush Guard, Hitch Receiver		C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	Usage: Not Available		Notes: Crate Condition, Excess Inventory
	Notes: DEFICIENCIES NOTED - PLEASE SEE		Batteries May Be Dead
	THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY		Asset located in: Humble, TX
	Asset located in: Humble, TX	8749	2023 Kandi KS4PSLR-B Electric Golf Cart
8739	2024 DYC GFZ-4 Electric Golf Cart (Unused)		(Unused) S/N: A07DE5W8TPC001611
	S/N: 3702020241153		C/W: 4 Passenger, Canopy, Lift Kit
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: 2 Km		Usage: Not Available
	Asset located in: Humble, TX		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
8740	2024 DYC GFZ-4 Electric Golf Cart (Unused)		Asset located in: Humble, TX
0, 10	S/N: 3702020241154	8750	2023 Kandi KS4PSLR-B Electric Golf Cart
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit		(Unused)
	Usage: 1 Km Asset located in: Humble, TX		S/N: A07DE5W8APC001682
8741	2024 DYC GFZ-4 Electric Golf Cart (Unused)	_	C/W: 48 Volt Canopy Usage: Not Available
0/41	S/N: 3702020241151		Notes: Crate Condition, Excess Inventory
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit		Batteries May Be Dead
	Usage: 1 Km		Asset located in: Humble, TX
07.40	Asset located in: Humble, TX	8751	2023 Kandi KS4PSLR-B Golf Cart (Unused)
8742	2024 DYC GFX-4 Electric Golf Cart (Unused) S/N: 202407367		S/N: A07DE5W8CPC001610 C/W: 48 Volt Canopy
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit		Usage: Not Available
	Usage: 3 Km		Notes: Crate Condition, Excess Inventory
	Asset located in: Humble, TX	_	Batteries May Be Dead Asset located in: Humble, TX
8743	2024 DYC GFX-4 Electric Golf Cart (Unused) S/N: 202407365	8752	2023 Kandi KS4PSLR-B Electric Golf Cart
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit	0732	(Unused)
	Usage: 5 Km		S/N: A07DE5W8CPC001686
	Asset located in: Humble, TX	_	C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
8744	2024 DYC GFX-4 Electric Golf Cart (Unused)		Notes: Crate Condition, Excess Inventory
	S/N: 202407366 C/W: 4 Passenger, Canopy, Windshield, Lift Kit		Batteries May Be Dead
	Usage: 2 Km		Asset located in: Humble, TX
	Asset located in: Humble, TX	8753	2023 Kandi KS4PSLR-B Electric Golf Cart
8745	2024 DYC GFXX-4 Electric Golf Cart (Unused)		(Unused)
	S/N: 202407362 C/W: 4 Passenger, Canopy, Windshield, Lift Kit		S/N: A07DE5W8CPC001624 C/W: 4 Passenger, Canopy, Lift Kit
	Usage: Not Available		Usage: Not Available
_	Asset located in: Humble, TX		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
8746	2024 DYC GFXX-4 Electric Golf Cart (Unused)		Asset located in: Humble, TX
	S/N: 202407363	8754	2023 Kandi KS4PSLR-MB Electric Golf Cart
	C/W: 4 Passenger, Canopy, Windshield, Lift Kit Usage: Not Available		(Unused)
	Asset located in: Humble, TX		S/N: A07DE5W8EPC001685
			C/W: 4 Passenger, Canopy, Lift Kit
			Usage: Not Available

Lot #	Details	Lot #	Details
8755	2023 Kandi KS4PSLR-MB Electric Golf Cart (Unused) S/N: A07DE5W8HPC001684 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available	8763	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8PPC001609 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	Notes : Crate Condition, Excess Inventory Batteries May Be Dead		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
	Asset located in: Humble, TX		Asset located in: Humble, TX
8756	2023 Kandi KS4PSLR-B Electric Golf Cart (Unused) S/N: A07DE5W8KPC001594 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available	8764	2023 Kandi KS4PSLR-B Golf Cart (Unused) S/N: A07DE5W8LPC001683 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory
	Notes: Crate Condition, Excess Inventory Batteries May Be Dead		Batteries May Be Dead
	•	0745	Asset located in: Humble, TX
8757	Asset located in: Humble, TX 2023 Kandi KS4PSLR-MB Golf Cart S/N: A07DE5W8JPC001595 C/W: 48 Volt Canopy Usage: Not Available	8765	2023 Kandi KS4PSLR-B Golf Cart (Unused) S/N: A07DE5W8PPC001626 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead
	Notes: Crate Condition, Excess Inventory Batteries May Be Dead		Asset located in: Humble, TX
	Asset located in: Humble, TX	8766	2023 Kandi KS4PSLR-BK Electric Golf Cart
8758	2023 Kandi KS4PSLR-BK Golf Cart (Unused) S/N: A07DE5W8EPC001668 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available	0,00	(Unused) S/N: A07DE5W8TPC001642 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available
	Notes: Crate Condition, Excess Inventory Batteries May Be Dead		Notes: Crate Condition, Excess Inventory Batteries May Be Dead
	Asset located in: Humble, TX		Asset located in: Humble, TX
8759	2023 Kandi KS4PSLR-BK Golf Cart (Unused) S/N: A07DE5W8CPC001607 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available	8767	2023 Kandi KS4PSLR-BK Golf Cart (Unused) S/N: A07DE5W8VPC001647 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available
	Notes: Crate Condition, Excess Inventory Batteries May Be Dead Asset located in: Humble, TX		Notes: Crate Condition, Excess Inventory Batteries May Be Dead Asset located in: Humble, TX
0760		0760	·
8760	2023 Kandi KS4PSLR-BK Electric Golf Cart (Unused) S/N: A07DE5W8CPC001629 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory	8768	2023 Kandi KS4PSLR-BK Electric Golf Cart (Unused) S/N: A07DE5W8VPC001664 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory
	Batteries May Be Dead		Batteries May Be Dead
	Asset located in: Humble, TX		Asset located in: Humble, TX
8761	2023 Kandi KS4PSLR-B Golf Cart (Unused) S/N: A07DE5W8TPC001625 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead Asset located in: Humble, TX	8769	2023 Kandi KS4PSLR-BK Electric Golf Cart (Unused) S/N: A07DE5W8TPC001608 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead
8762	2023 Kandi KS4PSLR-BK Electric Golf Cart		Asset located in: Humble, TX
	(Unused) S/N: A07DE5W8APC001634 C/W: 4 Passenger, Canopy, Lift Kit Usage: Not Available		
	Notes: Crate Condition, Excess Inventory Batteries May Be Dead		

Lot #	Details	Lot #	Details
8770	023 Kandi KS4PSLR-BK Electric Golf Cart Jnused) /N: A07DE5W8LPC001666 /W: 4 Passenger, Canopy, Lift Kit sage: Not Available otes: Crate Condition, Excess Inventory	8779	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031890 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX
	Batteries May Be Dead Asset located in: Humble, TX	8780	2019 Club Car Precedent Electric Golf Cart
8771	2023 Kandi KS4PSLR-BK Golf Cart (Unused) S/N: A07DE5W8LPC001649 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead		S/N: JE1949031892 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8772	Asset located in: Humble, TX 2023 Kandi KS4PSLR-MB Golf Cart (Unused) S/N: A07DE5W8APC001651 C/W: 48 Volt Canopy, Windshield, Lift Kit Usage: Not Available Notes: Crate Condition, Excess Inventory Batteries May Be Dead Asset located in: Humble, TX	8781	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031893 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8773		8782	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031895 C/W: 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX
	Batteries May Be Dead Asset located in: Humble, TX	8783	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031896 C/W: Battery Charger, 2 Passenger, Canopy
8775	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031883 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available	8784	Windshield Usage: Not Available Asset located in: Humble, TX 2019 Club Car Precedent Electric Golf Cart
8776	Asset located in: Humble, TX 2019 Club Car Precedent Electric Golf Cart S/N: JE1949031885 C/W: Battery Charger, 2 Passenger, Canopy, Windshield		S/N: JE1949031897 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX
8777	Usage: Not Available Asset located in: Humble, TX 2019 Club Car Precedent Electric Golf Cart S/N: JE1949031887 C/W: Battery Charger, 2 Passenger, Canopy, Windshield	8785	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031898 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2019 Club Car Precedent Electric Golf Cart S/N: JE1949031899 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available
8778	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031888 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX	8787	Asset located in: Humble, TX 2019 Club Car Precedent Electric Golf Cart S/N: JE1949031900 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8788	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031901 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX	8802	2019 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBPKG032578 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed Usage: 1,659 Hr Asset located in: Humble, TX	
8789	2019 Club Car Precedent Electric Golf Cart S/N: JE1949031902 C/W: Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Asset located in: Humble, TX	8803	2018 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBEJG026788 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, Kubota D1105-EF02 3 Cylinder 1.1 L Diesel Engine Usage: 3,120 Hr	
8792	2003 E-Z-Go Electric Golf Cart S/N: 1564032 C/W: 36 Volt Battery Charger, 2 Passenger, Canopy, Windshield Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX 2018 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBTJG026714 C/W: Open Operator Station, 4 Passenger, Windshield, Brush Guard, Hitch Receiver, Electric Dump Bed, Tier 4, 2018 US EPA Label, Kubota 3 Cylinder 1.1 L Diesel Engine Usage: 1,871 Hr Asset located in: Humble, TX	
8793	E-Z-Go Electric Golf Cart S/N: 2682928 C/W: 36 Volt Battery Charger, 2 Passenger, Canopy, Windshield, Utility Body Usage: Not Available Asset located in: Humble, TX	8805	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBPHG020584 C/W: Canopy, 4 Passenger, Brush Guard, Hitc Receiver, Manual Dump Bed, 2017 US EPA Label, Kubota D1105-EF02 3 Cylinder 1.1 L Diesel Engine	
8794	2014 E-Z-Go Golf Cart S/N: 3054196 C/W: 4 Passenger, Canopy, 2013 US EPA		Usage: 644 Hr Notes: OFF HIGHWAY USE ONLY Asset located in: Humble, TX	
	Label, Kawasaki 1 Cylinder Gasoline Engine Usage: Not Available Asset located in : Humble, TX	8806	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBHHG018974 C/W: Canopy, 4 Passenger, Windshield, Brush	
8799	2020 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBKLG036018 C/W: Canopy, 4 Passenger, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2019 US EPA Label, Kubota D1105 3 Cylinder 18.2 kW 1.1 L Diesel Engine		Guard, Electric Dump Bed, Tier 4, 20 Label, Kubota D1105 3 Cylinder 1.1 Engine Usage: 2,535 Hr Notes : DEFICIENCIES NOTED - PLE THE INSPECTION REPORT	Guard, Electric Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 2,535 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: 2,252 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8807	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBKHG020599 C/W: Canopy, 4 Passenger, Brush Guard, Hitch	
8800	2019 Kubota RTVX1140WH 4x4 Utility Vehicle S/N: A5KD2GDBLKG033786 C/W: Canopy, 4 Passenger, Windshield, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4,	8808	EPA Label, Kubota 3 Cylinder Diesel E	Usage: 2,294 Hr
	2019 US EPA Label, Kubota D1105 3 Cylinder 18.2 kW 1.1 L Diesel Engine Usage: 1,735 Hr Asset located in : Humble, TX		2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBEHG017485 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, 2017 US EPA Label,	
8801	2019 Kubota RTVX1140WH 4x4 Utility Vehicle S/N: A5KD2GDBPKG031768 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, Tier 4, 2019 US EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 2,498 Hr Asset located in: Humble, TX		Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 1,373 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
8809	2017 Kubota RTV-X1140 4x4 Utility Vehicle S/N: A5KD2GDBCHG017309 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, 3 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8817	2020 Cat CUV105D 4x4 Utility Vehicle S/N: 4UF30MPV5LT300425 C/W: Open Operator Station, 5 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.02 L Diesel Engine Usage: 1,342 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	8818	2020 Cat CUV105D Utility Cart
8810	2017 Kubota RTVX1140WH 4x4 Utility Vehicle S/N: A5KD2GDBEHG019947 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Manual Dump Bed, Tier 4, Kubota D1105 3 Cylinder Diesel Engine Usage: 2,133 Hr Asset located in: Humble, TX		S/N: 4UF30MPVXLT300498 C/W: Open Operator Station, 5 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.0 L Diesel Engine Usage: 912 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8811	2017 Kubota RTV-X1140 4x4 Utility Vehicle		Asset located in: Humble, TX
	S/N: A5KD2GDBCHG018511 C/W: Canopy, Brush Guard, Manual Dump Bed, Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: 2,852 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8819	2020 Cat CUV105D Utility Cart S/N: GD500524 C/W: Open Operator Station, 5 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 1.0 L Diesel Engine Usage: 8,975 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
8812	2017 Kubota 4x4 Utility Vehicle	1	THE INSPECTION REPORT
0012	S/N: A5KD2GDBLHG018892 C/W: Canopy, 4 Passenger, Windshield, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: 3,717 Hr Asset located in: Humble, TX	8820	Asset located in: Humble, TX 2020 Cat CUV105D 4x4 Crew Utility Vehicle S/N: 4UF30MPV1LT300423 C/W: Open Operator Station, 5 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 3 Cylinder 19 kW Diesel Engine Usage: 980 Hr
8813	2017 Kubota RTV-X1140 4x4 Utility Vehicle	1	Asset located in: Humble, TX
0013	S/N: A5KD2GDBJHG019924 C/W: Canopy, 4 Passenger, Windshield, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: Not Available	8821	2020 Cat CUV105D 4x4 Utility Vehicle S/N: 4UF30MPV4LT300433 C/W: Open Operator Station, 5 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.02 L Diesel Engine Usage: 9,553 Mi Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8822	2020 Cat CUV105D 4x4 Utility Vehicle
8815	Asset located in: Humble, TX 2017 Kubota RTVX900 4x4 Utility Vehicle S/N: A5KB2FDBHHG041270 C/W: Canopy, 2 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, CARB Compliant, Kubota D902 3 Cylinder 0.9 L Diesel Engine	8822	S/N: 4UF30MPVXLT300478 C/W: Open Operator Station, 4 Passenger, Windshield, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 1.02 L Diesel Engine Usage: 1,064 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: Not Available	8823	2020 Cat CUV1050 4x4 Utility Vehicle
8816	Asset located in: Humble, TX 2017 Kubota RTV-X900 4x4 Utility Vehicle S/N: A5KB2FDBAHG043999 C/W: Canopy, 2 Passenger, Windshield, Brush Guard, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D902 3 Cylinder 0.9 L Diesel Engine Usage: 2,094 Hr Asset located in: Humble, TX		S/N: 4UF30MPVXLT300002 C/W: Open Operator Station, 5 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2018 US EPA Label, Kohler 3 Cylinder 1.02 L Diesel Engine Usage: 1,294 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8824	2019 Polaris Pro XD 2000D 4x4 Utility Vehicle S/N: 4XABBPD4XK8939340 C/W: Canopy, 2 Passenger, Manual Dump Bed, Tier 4, 2019 US EPA Label, Kubota d902 3 Cylinder 18 kW .89 L Diesel Engine Usage: 1,413 Hr Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	8831	2017 Kawasaki 4x4 Utility Vehicle S/N: JKBAFSJ15HB504149 C/W: Canopy, 6 Passenger, Windshield, Locking Front Differential, Winch, Brush Guard, Manual Dump Bed, 2017 US EPA Label, CARB Compliant, 3 Cylinder 0.8 L Gasoline Engine Usage: 1,182 Hr Asset located in: Humble, TX
8825	2018 Polaris Ranger 4x4 Utility Vehicle S/N: 4XARVAD18J8867867 C/W: Canopy, 4 Passenger, Windshield, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 2 Cylinder 1.0 L Diesel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8832	2013 John Deere XUV560E S4 Utility Vehicle S/N: 17003161122276 Usage: Not Available Asset located in: Humble, TX
		8833	John Deere Gator Utility Cart S/N: 4X2X089809 C/W: Open Operator Station, 2 Passenger, Manual Dump Bed, 1 Cylinder Gasoline Engine Usage: Not Available Asset located in: Humble, TX
8826	S/N: 4XARVAD19J8867828 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 1.0 L Diesel Engine Usage: 1,409 Hr	8834	2023 Massimo Buck 250 4x2 Utility Vehicle S/N: LL8ACMHF9P0A15353 C/W: Canopy, 2 Passenger, Windshield, Brush Guard, Manual Dump Bed, Linhai 1 Cylinder Gasoline Engine Usage: 266 Mi Asset located in: Humble, TX
	Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	8835	2024 CF Moto Uforce 4x4 Utility Vehicle S/N: LCELV1ZA0RM000196 C/W: Enclosed Cab, 6 Passenger, Rear Scree
8827	2018 Polaris Ranger 4x4 Utility Vehicle S/N: 4XARVAD14J8868966 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA		Winch, Manual Dump Bed, 2024 US EPA Label, CFMOTO POWER CO 962.6 cc Gasoline Engine Usage: 461 Mi Asset located in : Humble, TX
	Label, Kohler 2 Cylinder 1.0 L Diesel Engine Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	8836A	Subaru 4x4 Utility Vehicle S/N: KS4350950 C/W: Enclosed Cab, Air Conditioner, 2 Passenger, Windshield, Rear Screen, Suburu Clover 4 4 Cylinder Gasoline Engine Usage: 99,500 Km
8829	2018 Kawasaki Mule 4x4 Utility Vehicle S/N: JKBAFSB12JB512343		Notes: NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX
	C/W: Canopy, 6 Passenger, Rear Screen, Locking Front Differential, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, 3 Cylinder Gasoline Engine Usage: 1,862 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8836	Subaru Sambar 4x4 Utility Vehicle S/N: KS4128141 C/W: Enclosed Cab, 2 Passenger, Windshield, 4 Cylinder Gasoline Engine Usage: 60,481 Km Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE
8830	2017 Kawasaki Mule Pro-DXT 4x4 Utility Vehicle		AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX
	S/N: JKAAFCB11HB501452 C/W: Canopy, 6 Passenger, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Manual Dump Bed, 2016 US EPA Label, Yanmar 3 Cylinder .99 L Diesel Engine Usage: 6,030 Mi Asset located in: Humble, TX	8837	Honda 4x4 Utility Vehicle S/N: HA42376292 C/W: Enclosed Cab, 2 Passenger, Windshield, Rear Screen, Gasoline Engine Usage: 65,852 Km Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY- NO ETAG WILL BE ISSUED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8838	2024 Can-Am Commander 4x4 Side By Side S/N: 3JBAWAX43RE000051	8846	2024 Meco M3 Electric Trike S/N: M3240709
	C/W: Open Operator Station, 2 Passenger,		Usage: Not Available
	Locking Front Differential, Winch, Brush Guard, Hitch Receiver, Manual Dump Bed, King Cobra		Asset located in: Humble, TX
	Axles, 6 in Highlifter Portals	8847	2024 Meco M3 Electric Trike (Unused)
	Usage: 44 Hr		S/N: M3240710 Usage: Not Available
0000	Asset located in: Humble, TX	-	Asset located in: Humble, TX
8839	2017 Polaris Razor RZP-XP4 1000 EPS 4x4 Side By Side	8848	Tao Motor D125 4x2 ATV (Unused)
	S/N: 3NSVFE995HF786649 C/W: Canopy, 4 Passenger, 2017 US EPA Label, CARB Compliant, Polaris 999 cc Gasoline Engine		S/N: L9LACED33N1605345 C/W: Electric Start, 1 Cylinder Gasoline Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
	Usage: 131 Hr		THE INSPECTION REPORT
	Asset located in: Humble, TX	_	Asset located in: Humble, TX
8840	2012 Polaris Outlaw 50 Four Wheeler S/N: RF3KA05A5CT020785	8849B	Tao Motor 4x2 110 CC 4 Stroke ATV (Unused)
	C/W: 1 Cylinder Gasoline Engine Usage: Not Available		S/N: L9NACFDJ7P1904824 C/W: Electric Start, 1 Cylinder Gasoline Engine, REMOTE CONTROL SPEED LIMITER / KILL
	Asset located in: Humble, TX	_	SWITCH Usage: Not Available
8841	2021 Polaris Sportsman 4x4 Utility Vehicle		Notes: LOCATED-IN-HOUSTON-TX -
	S/N: 4XASDE579MA740623 C/W: Open Operator Station, 2 Passenger,		Asset located in: Humble, TX
	Winch, Hitch Receiver, 2021 US EPA Label, Polaris 1 Cylinder 44 hp 567 cc Gasoline Engine Usage: 34 Hr	8849A	Tao Motor 110 CC Boulder 4 Stroke ATV (Unused)
	Asset located in: Humble, TX		S/N: L9NACFDJ4P1904859 C/W: Electric Start, 1 Cylinder Gasoline Engine REMOTE CONTROL SPEED LIMITER / KILL SWITCH
8842	2024 Meco M-F Electric Golf Cart (Unused) S/N: MF24062108		
	C/W: 4 Passenger, Windshield Usage: Not Available		Usage: Not Available Notes: LOCATED-IN-HOUSTON-TX -
	Asset located in: Humble, TX		Asset located in: Humble, TX
8843	2024 Meco P4 Electric Utility Vehicle	8849	Tao Motor B110 4x2 ATV (Unused)
	S/N: P4240705 C/W: Enclosed Cab, 4 Passenger, Windshield, THE PRODUCT IMAGES SHOWN ARE FOR		S/N: L9NACFDJXP1904977 C/W: Electric Start, 1 Cylinder Gasoline Engine Usage: Not Available
	ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: Not Available		Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8850	Razor 4x2 Electric Four Wheeler ATV S/N: 2107001 C/W: 1 Forward Gears
2011	Asset located in: Humble, TX	4	Usage: Not Available
8844	2024 Meco MC16 Electric Three-Wheel Utility Vehicle (Unused)		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: MC16240812		Asset located in: Humble, TX
	C/W: Enclosed Cab, Windshield, Brush Guard Usage: Not Available	8851	2020 Ford Mustang GT Automobile
	Asset located in: Humble, TX		S/N: 1FA6P8CF4L5158892
8845			C/W: V8 5.0 L Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 39,970 Mi
			Notes: TITLE BRAND REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX

		1.	
Lot #	Details	Lot #	Details
8852A	2019 Toyota Yaris Automobile S/N: 3MYDLBYV9KY519224 C/W: 4 cyl 1.5 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 122,032 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8857	2016 Nissan Sentra Automobile S/N: 3N1AB7AP6GY244287 C/W: 4 cyl 1.8 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Power Windows, Power Locks, Rear View Camera Usage: 134,867 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0050	·	8859	2015 Chevrolet Camaro Convertible
8852	2019 Kia Optima Automobile S/N: 5XXGT4L36KG355498 C/W: 4 cyl 2.4 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 137,417 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: 2G1FD3D38F9285588 C/W: V6 3.6 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE
	THE INSPECTION REPORT		INSPECTION REPORT
0050	Asset located in: Humble, TX	0060	Asset located in: Humble, TX
8853	2017 Nissan Altima Automobile S/N: 1N4AL3AP5HN317978 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows Usage: 67,245 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8860	2015 Chevrolet Camaro RS Automobile S/N: 2G1FF1E3XF9279806 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 123,798 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
8854	2017 Nissan Altima Automobile		Asset located in: Humble, TX
	S/N: 1N4AL3AP7HN340310 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 103,311 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8861	2015 Chevrolet Spark Automobile S/N: KL8CD6S93FC709764 C/W: 4 cyl 1.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 94,644 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	8863	2014 Maserati Ghibli Automobile
8855	2016 Maserati Ghibli Automobile S/N: ZAM57XSA5G1173805 C/W: V6 3.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 151,867 Mi		S/N: ZAM57RTA1E1097670 C/W: V6 3.0 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 100,487 Mi Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8864	2014 Toyota Corolla Automobile S/N: 5YFBURHE2EP016828 C/W: 4 cyl 1.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air
8856	2016 Mercedes-Benz SLK300 Automobile S/N: WDDPK3JA7GF124359 C/W: 4 cyl Diesel Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 142,328 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 210,831 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details	Lot #	Details
2014 Honda Accord Automobile S/N: 1HGCT2B83EA008504 C/W: V6 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 191,896 Mi	8871	2013 Chevrolet Spark Automobile S/N: KL8CB6S94DC565550 C/W: 4 cyl 1.2 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 162,122 Mi
Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	0070	Asset located in: Humble, TX
Asset located in: Humble, TX	88/2	
2014 Chevrolet SONIC Automobile S/N: 1G1JA5SH0E4164942 C/W: 4 cyl 1.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 106,130 Mi		S/N: 3FA6P0H71DR254948 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 142,832 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS
Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
2014 Chevrolet Cruz Automobile		Asset located in: Humble, TX
S/N: 1G1PA5SH1E7283768 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Locks Usage: 104,564 Mi Asset located in : Humble, TX	8873	2013 Ford Fusion SE Automobile S/N: 3FA6P0H76DR351062 C/W: 4 cyl 2.5 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 102,334 Mi
2014 Ford Taurus SE Automobile		Asset located in: Humble, TX
S/N: 1FAHP2D85EG102991	9974	2013 Kia Optima SXL Automobile
C/W: 6 cyl 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 163,220 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED	3074	S/N: 5XXGR4A65DG147790 C/W: 4 cyl 2.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 132,668 Hr Asset located in: Humble, TX
Asset located in: Humble, TX	8875	2013 Kia Optima GDI Automobile
2014 Toyota Camry LE Automobile S/N: 4T1BF1FK7EU779527 C/W: 4 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,		S/N: KNAGM4A7XD5422417 C/W: 4 cyl 2.4 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 153,887 Mi
Rear View Camera Usage: 85,988 Mi		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	0076	•
Asset located in: Humble, TX	8876	2013 Hyundai SONATA Automobile S/N: 5NPEB4AC8DH562561 Usage: Not Available
		Asset located in: Humble, TX
C/W: V6 3.0 L Gasoline Engine, 2013 US EPA	8877	2013 Nissan Sentra Automobile
Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 188,404 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX	0077	S/N: 3N1AB7AP4DL790448 C/W: Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 127,945 Mi Notes: TITLE COMES WITH REPOSSESSED VEHICLE AFFIDAVIT Asset located in: Humble, TX
	2014 Honda Accord Automobile S/N: 1HGCT2B83EA008504 C/W: V6 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 191,896 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Chevrolet SONIC Automobile S/N: 1G1JA5SH0E4164942 C/W: 4 cyl 1.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 106,130 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Chevrolet Cruz Automobile S/N: 1G1PA5SH1E7283768 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Locks Usage: 104,564 Mi Asset located in: Humble, TX 2014 Ford Taurus SE Automobile S/N: 1FAHP2D85EG102991 C/W: 6 cyl 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 163,220 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2014 Toyota Camry LE Automobile S/N: 4T1BF1FK7EUT79527 C/W: 4 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 85,988 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2013 Audi A7 Automobile S/N: WAU2GAFC5DN116540 C/W: V6 3.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 85,988 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	2014 Honda Accord Automobile S/N: 1HGCT2B83EA008504 C/W: V6 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 191,896 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Chevrolet SONIC Automobile S/N: 161,JA5SH0E4164942 C/W: 4 cyl 1.8 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 106,130 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Chevrolet Cruz Automobile S/N: 1G1PA5SH1E7283768 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Locks Usage: 104,564 Mi Asset located in: Humble, TX 2014 Ford Taurus SE Automobile S/N: 1FAHP2D85EG102991 C/W: 6 cyl 3.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 163,220 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2014 Toyota Camry LE Automobile S/N: 4T1BF1FK7EU779527 C/W: 4 cyl 2.5 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 85,988 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2013 Audi A7 Automobile S/N: WAU2GAFC5DN116540 C/W: V6 3.0 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 188,404 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Lot #	Details	Lot #	Details
8879	2012 Dodge Charger SE Automobile	8885	2010 Honda Civic Automobile
	S/N: 2C3CDXAT6CH146443 C/W: V8 5.7 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air		S/N: 2HGFG1B84AH524197 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power
	Conditioner, Power Windows, Power Locks Usage: 106,391 Mi		Windows, Power Locks Usage: 233,309 Mi
	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
8880	2012 Toyota Camry Automobile	8886	2010 Audi A5 Automobile
	S/N: 4T1BF1FK0CU586066 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 202,597 Mi		S/N: WAUGFAFR5AA049180 C/W: 4 cyl 2.0 L Gasoline Engine, 6 Speed Manual Transmission, Air Conditioner, Power Windows, Power Locks Usage: 152,185 Mi
	Notes: TITLE BRAND REBUILT SALVAGE		Asset located in: Humble, TX
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8887	2009 Mini Cooper S Automobile
	Asset located in: Humble, TX		S/N: WMWMF73519TW84212
8881	2012 Mini Countryman Automobile		C/W: 4 cyl Gasoline Engine, Automatic Transmission, Air Conditioner
	S/N: WMWZC3C57CWL84316		Usage: 115,185 Mi
	C/W: 4 cyl Gasoline Engine, Automatic Transmission		Notes: LOCATED-IN-HOUSTON-TX DEFICIENCIES NOTED - PLEASE SEE THE
	Usage: 128,096 Mi		INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
8882	2012 Chrysler 300 Automobile	8888	2009 Mercedes-Benz C300 Automobile
	S/N: 2C3CCACG2CH199608 C/W: V6 3.6 L Gasoline Engine, 2012 US EPA		S/N: WDDGF54X99R051481 C/W: V6 Gasoline Engine, Automatic
	Label, Automatic Transmission, Air		Transmission, Air Conditioner, Power
	Conditioner, Power Windows, Power Locks Usage: 102,133 Mi		Windows, Power Locks Usage: 184,755 Mi
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
8883A	2011 Volkswagen Jetta Automobile	8889	2008 Mercedes-Benz SLK280 AWD Automobil
	S/N: 3VWLX7AJ3BM346131 C/W: 5 cyl 2.5 L Gasoline Engine, 2014 US EPA		S/N: WDBWK54F78F183985 C/W: V6 3.0 L Gasoline Engine, 2008 US EPA
	Label, Automatic Transmission, Air		Label, Automatic Transmission, Air
	Conditioner, Power Windows, Power Locks, Navigation		Conditioner, Power Windows, Power Locks Usage: 110,124 Mi
	Usage: 145,971 Mi		Notes: DEFICIENCIES NOTED - PLEASE SEE
	Notes: DEFICIENCIES NOTED - PLEASE SEE		THE INSPECTION REPORT
	THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX
8883	2012 Hyundai Veloster Automobile	8890	2008 Lexus LS460 Automobile
0000	S/N: KMHTC6AD6CU052234		S/N: JTHBL46F885067879 C/W: V8 4.6 L Gasoline Engine, 2008 US EPA
	C/W: 4 cyl 1.6 L Gasoline Engine, 2012 US EPA		Label, Automatic Transmission, Air
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks,		Conditioner, Power Windows, Power Locks, Rear View Camera
	Rear View Camera, Navigation		Usage: 240,693 Mi
	Usage: 65,183 Mi Notes: TITLE BRAND NOT ACTUAL MILEAGE		Asset located in: Humble, TX
	REBUILT SALVAGE	8891	2008 Cadillac STS Automobile
	Asset located in: Humble, TX	_	S/N: 1G6DW67V380103917 C/W: V6 3.6 L Gasoline Engine, 2008 US EPA
8884	2010 Mercedes-Benz E350 Automobile		Label, Automatic Transmission, Air
	S/N: WDDHF5GB5AA080628 C/W: V6 3.5 L Gasoline Engine, 2010 US EPA		Conditioner, Power Windows, Power Locks Usage: 99,172 Mi
	O/ VV. VO 0.0 L Gasonne Lingine, 2010 00 Li /		Asset located in: Humble, TX
	Label, Automatic Transmission, Air		
	Conditioner, Power Windows, Power Locks		

Details	Lot #	Details
2008 Toyota Avalon Automobile S/N: 4T1BK36B68U285333 C/W: V6 3.5 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 209,124 Mi Asset located in: Humble, TX	8902	2016 Ford Explorer XLT 4WD SUV S/N: 1FM5K8D83GGC35441 C/W: V6 3.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 237,346 Mi
2006 BMW 750i Automobile		Asset located in: Humble, TX
S/N: WBAHL835X6DT03804 C/W: V8 4.8 L Gasoline Engine, 2006 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation Usage: Not Available Notes: THE TITLE COMES WITH A REPO AFFIDAVIT NOT ACCEPTED IN THESE STATES AZ, FL, NE,NJ,NY, PA,UT Asset located in: Humble, TX	8903	2016 GMC Acadia AWD SUV S/N: 1GKKVRKD9GJ165486 C/W: V6 3.6 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: Not Available Notes: TITLE IS BRANDED AS NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
· · · · · · · · · · · · · · · · · · ·	8905	2013 Audi Q7 S Line Quattro AWD SUV
S/N: WBAVB13516PT16193 C/W: 6 cyl 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 199,257 Mi Notes: THIS UNIT IS BEING SOLD WITH A	0300	S/N: WA1WMAFE0DD005019 C/W: V6 Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 167,382 Mi
REBUILT SALVAGE TITLE		Asset located in: Humble, TX
Asset located in: Humble, TX	8906	2011 Jeep Wrangler 4x4 SUV
97 2001 Porsche Boxster Automobile S/N: WP0CA29821U622169 C/W: 5 Speed Manual Transmission, Air Conditioner, Power Windows Usage: 93 713 Mi		S/N: 1J4AA2D16BL639656 C/W: V6 3.8 L Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows Usage: 79,110 Mi Notes : THIS UNIT IS BEING SOLD WITH A
Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
· · · · · · · · · · · · · · · · · · ·	_	Asset located in: Humble, TX
S/N: 2C4RC1EGXHR541231 C/W: V6 3.6 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 106,336 Mi Asset located in: Humble, TX	8907	2011 BMW X3 AWD SUV S/N: 5UXWX5C57BL702553 C/W: V6 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 157,739 Mi
2007 Honda Odyssey Minivan		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
S/N: 5FNRL38247B066360		Asset located in: Humble, TX
Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 159,880 Mi	8908	2010 Infiniti EX35 Journey 2WD SUV S/N: JN1AJ0HR8AM755298 C/W: 6 cyl 3.5 L Gasoline Engine, 2010 US EPA
Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 149,618 Mi
2017 Nissan Pathfinder 4WD SUV		Asset located in: Humble, TX
C/W: V6 3.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 177,097 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	8909	2007 Jeep Wrangler 4WD SUV S/N: 1J4FA541X7L209062 C/W: V6 3.8 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Winch Usage: 181,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	2008 Toyota Avalon Automobile S/N: 4T1BK36B68U285333 C/W: V6 3.5 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 209,124 Mi Asset located in: Humble, TX 2006 BMW 750i Automobile S/N: WBAHL835X6DT03804 C/W: V8 4.8 L Gasoline Engine, 2006 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation Usage: Not Available Notes: THE TITLE COMES WITH A REPO AFFIDAVIT NOT ACCEPTED IN THESE STATES AZ, FL, NE,NJ,NY, PA,UT Asset located in: Humble, TX 2006 BMW 325i Automobile S/N: WBAVB13516PT16193 C/W: 6 cyl 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 199,257 Mi Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX 2001 Porsche Boxster Automobile S/N: WP0CA29821U622169 C/W: 5 Speed Manual Transmission, Air Conditioner, Power Windows Usage: 93,713 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Chrysler Pacifica Minivan S/N: 2CARC1EGXHR541231 C/W: V6 3.6 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 106,336 Mi Asset located in: Humble, TX 2007 Honda Odyssey Minivan S/N: 5FNRL38247B066360 C/W: V6 3.5 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 159,880 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Honda Odyssey Minivan S/N: 5FNRL38247B066360 C/W: V6 3.5 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 159,880 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	2008 Toyota Avalon Automobile S/N: 4T1BK36B68U285333 C/W: V6 3.5 L Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Locks Usage: 209,124 Mi Asset located in: Humble, TX 2006 BMW 750i Automobile S/N: WBAHL835X6DT03804 C/W: V8 4.8 L Gasoline Engine, 2006 US EPA Label, CARB Compiliant, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Navigation Usage: Not Available Notes: THE TITLE COMES WITH A REPO AFFIDAVIT NOT ACCEPTED IN THESE STATES AZ, FL, NE, NJ,NY, PA,UT Asset located in: Humble, TX 2006 BMW 325i Automobile S/N: WBAWB13516PT16193 C/W: 6 cyl 3.0 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 199,257 Mi Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX 2001 Porsche Boxster Automobile S/N: WP0CA29821U622169 C/W: 5 Speed Manual Transmission, Air Conditioner, Power Windows Usage: 93,713 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Chrysler Pacifica Minivan S/N: 2C4RC1EGXHRS41231 C/W: V6 3.6 L Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 106,336 Mi Asset located in: Humble, TX 2007 Honda Odyssey Minivan S/N: 5FNRL38247B066360 C/W: V6 3.5 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 159,880 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2017 Nissan Pathfinder 4WD SUV S/N: 5SN1DR2MM7HC666827 C/W: V6 3.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 177,097 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE

Lot #	Details	Lot #	Details
8911	2006 Chevrolet Tahoe Z71 4WD SUV S/N: 1GNEK13Z26R125089 C/W: V8 5.3 L Gasoline Engine, 2006 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 229,606 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING	8917	2017 Chevrolet Tahoe LT 2WD SUV S/N: 1GNSCBKC2HR198629 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row, Towing Hitch Usage: 151,279 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2017 Ford Escape 2WD SUV S/N: 1FMCU0GD9HUE71445
8912	Asset located in: Humble, TX 2005 Hummer H2 4WD SUV S/N: 5GRGN23UX5H104075 C/W: V8 6.0 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 117,230 Mi	8919	C/W: 3 cyl 1.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 175,892 Mi Asset located in: Humble, TX 2017 Ford Escape S 2WD SUV
8913	Asset located in: Humble, TX 2005 Ford Excursion SUV S/N: 1FMSU45P95ED44832 C/W: V8 6.0 L Diesel Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: Not Available Asset located in: Humble, TX	_	S/N: 1FMCU0F70HUB26560 C/W: 4 cyl 2.5 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 134,079 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
8914	1995 Jeep Wrangler 4WD SUV S/N: 1J4FY29S0SP296922		Asset located in: Humble, TX
	C/W: 6 cyl 4.0 L Gasoline Engine, 1995 US EPA Label, Automatic Transmission, Bumper Mounted Winch Usage: 140,804 Mi Notes: TITLE BRANDS REBUILT SALVAGE RECONSTRUCTED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8920	2017 Dodge Journey 2WD SUV S/N: 3C4PDCGG9HT613806 C/W: V6 3.6 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 123,818 Mi Asset located in: Humble, TX
8915	2019 Infiniti QX80 2WD SUV	8921	2017 Chevrolet Trax 2WD SUV
8916	S/N: JN8AZ2NF7K9682638 C/W: V8 5.6 L Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation, 3rd Row Usage: 79,670 Mi Notes: Asset located in: Humble, TX 2017 Chevrolet Tahoe 2WD SUV	-	S/N: 3GNCJKSB6HL220642 C/W: 1.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 131,519 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0710	S/N: 1GNSCAKC7HR378571	8922	2016 Land Rover Discovery Sport HSE Luxury
	C/W: V8 5.3 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 177,290 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX		2WD SUV S/N: SALCT2BG9GH586387 C/W: 4 cyl 2.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, Navigation Usage: 74,622 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8923	2016 Nissan Pathfinder SV 2WD SUV S/N: 5N1AR2MN3GC666379 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera Usage: 179,974 Mi Notes: TITLE BRAND REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE	8928	2014 Nissan Pathfinder 2WD SUV S/N: 5N1AR2MN5EC683651 C/W: V6 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 224,141 Mi Asset located in: Humble, TX
	INSPECTION REPORT Asset located in: Humble, TX	8929	2012 Ford Expedition 2WD SUV
8924	2016 Chevrolet equinox LT 2WD SUV S/N: 2GNALCEK8G6106678 C/W: 4 cyl 2.4 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 171,388 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1FMJU1H59CEF62576 C/W: V8 5.4 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 239,704 Mi Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX
8925	Asset located in: Humble, TX	8930	2008 Ford Expedition 2WD SUV S/N: 1FMFU17578LA20080
8925	2016 Nissan Rogue 2WD SUV S/N: KNMAT2MT9GP695821 C/W: 4 cyl 2.5 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Rear View Camera Usage: 114,068 Mi Notes: TITLE BRAND REBUILT SALVAGE Asset located in: Humble, TX 2015 Volvo XC60 2WD SUV		C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 219,864 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV
8926	S/N: YV440MDB6F2589246		PRIOR TO BIDDING
	C/W: 4 cyl 2.0 L Gasoline Engine, 2015 US EPA		Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 75,598 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8931	2005 Land Rover Freelander SE 2WD SUV S/N: SALNY22295A478663 C/W: V6 2.5 L Gasoline Engine, 2005 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 80,530 Mi
8927	2015 Nissan Pathfinder 2WD SUV S/N: 5N1AR2MN1FC651426		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: V6 3.5 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air		Asset located in: Humble, TX
	Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 193,455 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8932	2001 Toyota Sequoia 2WD SUV S/N: 5TDZT38A91S031176 C/W: V8 4.7 L Gasoline Engine, 2001 US EPA Label, Automatic Transmission Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX DEFICIENCIES
8928A	2014 Nissan Pathfinder SV 2WD SUV	1	NOTED - PLEASE SEE THE INSPECTION
	S/N: 5N1AR2MNXEC680549 C/W: 3 cyl 3.5 L Gasoline Engine, 2014 US EPA		REPORT Asset located in: Lake Worth, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, 3rd Row Usage: 159,299 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8933	2015 GMC Sierra 3500HD 4x4 Crew Cab Pickup S/N: 1GT424E87FF594285 C/W: 6.6 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Sunroof, Power Sliding Rear Window, Dual Rear Wheel, Spray-On Bed Liner, 13025 lb GVWR, 35x12. 5R22 Tires, 8 ft 2 in Bed Usage: 192,673 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8934	2019 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BTXKED26758 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, 11500.0 lb GVWR, 275/70R18 Tires, 8 ft 2 in Bed Usage: 130,404 Mi Notes: LOCATED-IN-MIDLAND-TX TEMPORARY TAGS WILL NOT BE ISSUED; ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (SEPTEMBER 24TH) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX	8943	2015 GMC Sierra 3500HD 4x4 Crew Cab Pickup S/N: 1GT421CGXFF176442 C/W: 6.0 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 11000 lb GVWR, 265/70R18 Tires, 8 ft Bed Usage: 243,107 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2006 Dodge Ram 3500 4x4 Crew Cab Pickup S/N: 3D7LX39C16G197374 C/W: 5.9 L 6 Cylinder Diesel Engine, 2005 US
8936	2018 Ford F-350 Lariat 4x4 Crew Cab Pickup S/N: 1FT8W3BT8JEB81203 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Sunroof, Drop-In Bed Liner, 11500 lb GVWR, 265/70R17 Tires, 8 ft Bed		EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 9900 Ib GVWR, 285/70R17 Tires, 6 ft 6 in Bed Usage: 234,998 Mi Asset located in: Humble, TX
	Usage: 203,151 Mi Asset located in : Humble, TX	8945	1999 Ford F-350 4x4 Crew Cab Pickup S/N: 1FTSW31F2XEA09050 C/W: Diesel Engine, Automatic Transmission,
8938	2018 Ford F-350 XLT 4x4 Crew Cab Pickup S/N: 1FT8W3BT2JEC44330 C/W: 6.7 L 6 Cylinder Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack,		Air Conditioner, Power Windows, 9900 lb GVWR, 295/60R20 Tires, 8 ft Bed Usage: 263,566 Mi Asset located in: Humble, TX
	Fuel Tank /w Pump, RKI Tool Box, Drop-In Bed Liner, 11500 lb GVWR, 275/70R16 Tires, 8 ft Bed Usage: 186,195 Mi	8948	2018 Ram 3500 4x2 Crew Cab Pickup S/N: 3C7WRSCL7JG331563 Usage: Not Available Asset located in: Humble, TX
8940	Asset located in: Humble, TX 2016 Ford F-350 4x4 Crew Cab Pickup S/N: 1FT8W3BT3GEB10449 C/W: 6.7 L V8 Diesel Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Fuel Tank /w Pump, Weather Guard Tool Box, Spray-On Bed Liner, 11500 lb GVWR, 325/65R18 Tires, 6 ft 6 in Bed Usage: 147,921 Mi Asset located in: Humble, TX	8949	2015 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3CTXFEC89909 C/W: 6.7 L Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Dual Rear Wheel, Fuel Tank /w Pump, 14000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 285,539 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
8941	2015 Ford F-350 XL 4x4 Crew Cab Pickup S/N: 1FT8W3BT2FED72610 C/W: 6.7 L V8 Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank, 11200 lb GVWR, 275/70R18 Tires, 11 ft Bed Usage: 252,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8950	2014 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FT8W3AT0EEB33542 C/W: 6.7 L V8 Diesel Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weatherguard Tool Box, Drop-In Bed Liner, 275/65R18 Tires, 8 ft Bed Usage: 273,296 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
8952	2008 Ford F-350 XL 4x2 Crew Cab Pickup S/N: 1FTWW30R08EE26858 C/W: 6.4 L V8 Diesel Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, 10800 lb GVWR, 295/70R17 Tires, 8 ft Bed Usage: 187,270 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8959	2020 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UR5CJ8LG218252 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Sliding Rear Window, Spray- On Bed Liner, 10000 lb GVWR, 33x12.50R18LT Tires, 6 ft 4 in Bed Usage: 75,047 Mi Notes: THE TITLE BRANDED REBUILT SALVAGE
8954	2023 Chevrolet Silverado 2500 HD 4x4 Crew		Asset located in: Humble, TX
	Cab Pickup S/N: 1GC4YLE70PF124357 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Aluminum Truck Cap, 10650 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 28,217 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8960	2020 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2BT4LEC44242 C/W: 6.7 L 6 Cylinder Diesel Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 295/70R18 Tires, 8 ft Bed Usage: 137,586 Mi Notes: TITLE IS BRANDED REBUILT SALVAGE Asset located in: Humble, TX
8955	2022 Ford F-250 XL 4x4 Crew Cab Pickup	8961	2019 Ford F-250 XL 4x4 Crew Cab Pickup
	S/N: 1FT7W2B61NEE16448 C/W: 6.2 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 13,178 Mi Asset located in: Humble, TX		S/N: 1FT7W2BT8KEC79123 C/W: 6.7 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 183,607 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
8956	2022 Ford F-250 4x4 Crew Cab Pickup		THE INSPECTION REPORT
	S/N: 1FT7W2B6XNEE16447 C/W: 6.2 L V8 Gasoline Engine, 2022 US EPA		Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Aluminum Truck Cap, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 8 ft 6 in Bed Usage: 28,320 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8962	2019 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B66KEC61987 C/W: 6.2 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10000 lb GVWR, 295/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 227,465 Mi
8957	2021 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2BT8MEC30717 C/W: 6.7 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner,		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	10000.0 lb GVWR, 275/70R18 Tires, 6 ft 10 in Bed	8963	2018 Ford F-250 XL 4x4 Crew Cab Pickup
	Usage: 173,470 Mi Notes: SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1FT7W2B68JEC20212 C/W: 6.2 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 10000 lb GVWR, 285 /70R17 Tires, 6 ft 10 in Bed, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP- COMPANY
8958	2021 Ram 2500 4x4 Crew Cab Pickup		Usage: 107,816 Mi
	S/N: 3C6UR5HJ8MG631248 C/W: 6.4 L V8 Gasoline Engine, 2021 US EPA		Notes: LOCATED-IN-LIVINGSTON_LA_TX
	Label, Automatic Transmission, Air	8964	Asset located in: Livingston, LA 2018 Chevrolet Silverado 2500HD 4x4 Crew
	Conditioner, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 295/70R18 Tires, 8 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 114,548 Mi Asset located in: Humble, TX	8904	Cab Pickup S/N: 1GC1KVEG4JF237140 Usage: 141,601 Mi Asset located in: Humble, TX

Details	Lot #	Details
2017 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B67HEF34525 Usage: Not Available Asset located in: Humble, TX	8973	2012 Ram 2500 4x4 Crew Cab Pickup S/N: 3C6UD5HL1CG335616 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fuel Tank /w Pump, Drop-In Bed Liner, 9600.0 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 188,853 Mi Notes: LOCATED-IN-MIDLAND-TX, TEMPORARY TAGS WILL NOT BE ISSUED; ITEMS AT OFFSITE LOCATION MUST BE PICKED UP WITHIN 14 DAYS OF THE AUCTION (SEPTEMBER 24TH) OR WILL BE SUBJECT TO 3RD PARTY STORAGE FEES DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B66GEB00353 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed, EQUIPMENT- FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 274,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		
2016 Ford F-250 XL 4x4 Crew Cab Pickup	T	Asset located in: Midland, TX
S/N: 1FT7W2B64GEB00352 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 10000 lb GVWR, 285/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: 269,279 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	8974	2008 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FTSW21568EE26805 C/W: 5.4 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Spray-On Bed Liner, 9600 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 231,500 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
2016 Ford F-250 XL 4x4 Crew Cab Pickup	2075	·
S/N: 1FT7W2B68GEA13389 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed Usage: 319,792 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	89/5	2007 Chevrolet 2500 LT 4x4 Crew Cab Pickup S/N: 1GCHK23KX7F563795 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 235 /75R16 Tires, 6 ft 5 in Bed Usage: 494,489 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
•	0076	·
S/N: 1FT7W2B67FEB78431 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, Drop-In Bed Liner, 10000 Ib GVWR, 285 /70R17 Tires, 8 ft 2 in Bed Usage: 303,964 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	8976	2018 Chevrolet Silverado 2500HD 4x4 Extended Cab Pickup S/N: 1GC2KWEG9JZ193614 Usage: Not Available Notes: SUNSTATE EQUIPMENT CO. RENTAL PEOPLE YOU CAN DEPEND ON Asset located in: Humble, TX 2019 Chevrolet Silverado 2500 HD 4x4 Pickup
Asset located in: Humble, TX		S/N: 1GC1KREYXKF269480
2015 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B6XFEC90169 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, ProTech Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 7 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 82,923 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: 6.6 L V8 Diesel Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, 10000 lb GVWR, 285/75R17 Tires, 6 ft 6 in Bed Usage: 156,562 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	2017 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B67HEF34525 Usage: Not Available Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B66GEB00353 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed Usage: 274,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B64GEB00352 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 10000 lb GVWR, 285/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 269,279 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B68GEA13389 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed Usage: 319,792 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Ford F-250 XL 14x4 Crew Cab Pickup S/N: 1FT7W2B67FEB78431 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, Drop-In Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 8 ft 2 in Bed Usage: 303,964 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2015 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B67FEB78431 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, Drop-In Bed Liner, 10000 lb GVWR, 285/70R17 Tires, 8 ft 2 in Bed Usage: 303,964 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	2017 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B67HEF34525 Usage: Not Available Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B66GEB00353 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed, EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 274,968 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B64GEB00352 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, 10000 lb GVWR, 285/70R17 Tires, 8 ft Bed, EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 269,279 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Ford F-250 XL 4x4 Crew Cab Pickup S/N: 1FT7W2B68GEA13389 C/W: 6.2 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 285/70R17 Tires, 6 ft 11 in Bed Usage: 319,792 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Ford F-250 XLT 4x4 Crew Cab Pickup S/N: 1FT7W2B67FEB78431 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, Drop-In Bed Liner, 10000 lb GVWR, 285 7/0R17 Tires, 8 ft 2 in Bed Usage: 303,964 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2015 Ford F-250 4x4 Crew Cab Pickup S/N: 1FT7W2B6XFEC90169 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, ProTech Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 245/75R17 Tires, 7 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 82,232 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
8978	2007 GMC Sierra 2500HD 4x4 Pickup S/N: 1GTHK24K07E533693 C/W: 6.0 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Tool Box, 9200 lb GVWR, 265 /70R17 Tires, 8 ft Bed Usage: 290,260 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	8984 8985	2019 GMC Sierra 2500HD 4x2 Crew Cab Pickup S/N: 1GT11NEG4KF168471 C/W: 6.0 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Headache Rack, UWS Tool Box, Drop-In Bed Liner, 9500 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 155,679 Mi Asset located in: Humble, TX
8979	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE72NF195448 C/W: 6.6 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Husky Tool Box, Spray-On Bed Liner, 10300 lb GVWR, 245 /75R17 Tires, 8 ft Bed Usage: 31,641 Mi Asset located in: Humble, TX		Cab Pickup S/N: 1GC1CUEG9JF251171 C/W: 6.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 9500 lb GVWR, 235/80R17 Tires, 8 ft Bed Usage: 169,186 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0000		10006	·
8980	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE77NF194893 C/W: 6.6 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, BetterBuilt Tool Box, Spray-On Bed Liner, 10300 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 43,420 Mi	8986	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A68HEE08398 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 198,862 Mi
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
8981	Asset located in: Humble, TX 2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE77NF194862 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, BETTER BUILT Tool Box, Spray-On Bed Liner, 10300 lb GVWR, 245/75R17 Tires Usage: 52,864 Mi	8987	2017 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A61HEE08405 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, WEATHER GUARD Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 3 in Bed Usage: 176,168 Mi Asset located in: Humble, TX
	Asset located in: Humble, TX	8988	2017 Ford F-250 XL 4x2 Crew Cab Pickup
8982	2022 Chevrolet Silverado 2500 HD 4x2 Crew Cab Pickup S/N: 1GC4WLE74NF193278 C/W: 6.6 L V8 Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 10300 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 54,099 Mi	0900	S/N: 1FT7W2A68HEE08403 C/W: 6.2 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 146,557 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	<u> </u>	Asset located in: Humble, TX
8983	2020 Ram 2500 4x2 Crew Cab Pickup S/N: 3C6UR4HJ3LG121110 C/W: 6.4 L V8 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Drop-In Bed Liner, 10000 lb GVWR, 265/70R17 Tires, 8 ft 1 in Bed Usage: 83,836 Mi Asset located in: Humble, TX	8989	2015 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2A67FEB51084 C/W: 6.2 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, PROMAXX Fuel Tank /w Pump, RKI Tool Box, 10000 lb GVWR, 245/75R17 Tires, 8 ft 1 in Bed Usage: 235,632 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
8990	2012 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FT7W2AT0CEB65149 C/W: 6.7 L 6 Cylinder Diesel Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 245/75R17 Tires, 8 ft 2 in Bed Usage: 170,624 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE	8995	2012 Ford F-250 4x2 Pickup S/N: 1FTBF2A61CEC67791 C/W: 6.2 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Aluminum Truck Cap, 10000 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 142,273 Mi Asset located in: Humble, TX	
	THE INSPECTION REPORT	8996	2019 Ford F-150 XLT 4x4 Crew Cab Pickup	
8991A	Asset located in: Humble, TX 2011 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTFX1CF6BFB97784 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, RKL Tool Box, 7050 lb GVWR, 275/55R20 Tires, 6 ft 4 in Bed Usage: 264,781 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1FTEW1EP6KKC79591 C/W: 2.7 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 265/70R15 Tires, 6 ft Bed Usage: 106,950 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	Asset located in: Humble, TX	8997	2019 Ford F-150 XL 4x4 Crew Cab Pickup	
8991	2003 Ford F-250 XL 4x2 Crew Cab Pickup S/N: 1FTNW20F93EA12644 C/W: 7.3 L V8 Diesel Engine, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 235/85R16 Tires, 8 ft Bed Usage: 391,947 Mi Asset located in: Humble, TX		S/N: 1FTEW1EP7KKD16356 C/W: 2.7 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6600 lb GVWR, 295/70R17 Tires, 5 ft 7 in Bed Usage: 152,029 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE	
8992	2006 Ford F-250 XL 4x2 Extended Cab Pickup		THE INSPECTION REPORT	
	S/N: 1FTSX20526EB78774 C/W: 5.4 L V8 Gasoline Engine, 2006 US EPA		Asset located in: Humble, TX	
	Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 9200 lb GVWR, 245/75R17 Tires, 8 ft Bed Usage: 141,285 Mi Asset located in: Humble, TX	8998A	S/N: 1C6SRFJT3KN872325 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power	
8993	2001 Ford F-250 XL 4x2 Extended Cab Pickup S/N: 3FTNX20F01MA73479 C/W: V8 Diesel Engine, Automatic Transmission, Headache Rack, Spray-On Bed Liner, 8800 lb GVWR, 235/85R16 Tires, 8 ft 3 in Bed, Liftgate		Sliding Rear Window, 7100 lb GVWR, 27 /65R18 Tires, 5 ft 9 in Bed Usage: 95,393 Mi Notes : DEFICIENCIES NOTED - PLEASE THE INSPECTION REPORT	Usage: 95,393 Mi Notes : DEFICIENCIES NOTED - PLEASE SEE
	Usage: 316,136 Mi	8999	2019 Ford F-150 4x4 Crew Cab Pickup	
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	צצנס	S/N: 1FTEW1E54KKC44045 C/W: 5.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power	
8994	2019 Chevrolet Silverado 2500 HD 4x2 Pickup S/N: 1GC1CREG4KF178578 C/W: 6.0 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, RKI Tool Box, 9500 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 122,591 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Adjustable Pedals, Power Windows, Drop-In Bed Liner, 7000 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 227,201 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9003	2015 Chevrolet Silverado 1500 4x4 Crew Cab Pickup S/N: 3GCUKREC0FG421899 C/W: 5.3 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power	9009	2018 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 1GCVKNEH1JZ210048 Usage: Not Available Asset located in: Humble, TX
	Windows, Tool Box, Drop-In Bed Liner, 7200 lb GVWR, 265/65R18 Tires, 6 ft 7 in Bed Usage: 259,941 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9010	2018 Chevrolet Silverado 1500 4x4 Dual Cab Pickup S/N: 1GCVKNEHXJZ203051 C/W: 4.3 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 6 ft 5 in
9004	2014 Ford F-150 XLT 4x4 Crew Cab Pickup S/N: 1FTFW1ETXEKE30969 C/W: 3.5 L V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's		Bed Usage: 100,832 Mi Asset located in : Humble, TX
	Seat, Power Windows, Headache Rack, RKI Tool Box, 7200 lb GVWR, 275/65R18 Tires, 5 ft 7 in Bed Usage: 414,643 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9011	2017 Ford F-150 XL 4x4 Extended Cab Pickup S/N: 1FTFX1EG9HKD52821 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 7050 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 236,859 Mi
9005	2013 Ram 1500 4x4 Crew Cab Pickup S/N: 1C6RR7NT5DS694534 C/W: 5.7 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	Conditioner, Power Driver's Seat, Power Windows, Power Sliding Rear Window, Spray-On Bed Liner, 6800 lb GVWR, 275/65R20 Tires, 6 ft Bed Usage: 288,905 Mi Asset located in: Humble, TX	9012	2008 Chevrolet Silverado 1500 LT 4x4 Extended Cab Pickup S/N: 1GCEK19J88Z254046 C/W: 5.3 L V8 Gasoline Engine, 2008 US EPA Label, Automatic Transmission, Air
9006	2013 Ford F-150 4x4 Crew Cab Pickup S/N: 1FTFW1EF0DKD53036 Usage: Not Available		Conditioner, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 7000 lb GVWR, 26: /70R17 Tires, 6 ft 8 in Bed Usage: 160,448 Mi
9007	Asset located in: Humble, TX	9013	Asset located in: Humble, TX 2000 Chevrolet Silverado 1500 4x4 Extended Cab Pickup S/N: 2GCEK19T3Y1253655 C/W: 5.3 L V8 Gasoline Engine, 2000 US EPA Label, Automatic Transmission, Power Driver's Seat, Power Windows, Drop-In Bed Liner, 6400 lb GVWR, 265/75R16 Tires, 6 ft 7 in Bed Usage: 229,096 Mi Asset located in: Humble, TX
	THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9014	1998 Ford F-150 4x4 Extended Cab Hunting Truck S/N: 1FTRX18L1WKA93387
9008	2019 Ram 1500 4x4 Extended Cab Pickup S/N: 1C6RR7FT2KS635615 C/W: 5.7 L V8 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6900 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 147,448 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Ford 5.4 L Gasoline Engine, Automatic Transmission, 3600 lb Front Axle, 3200 lb Rears, 6250 lb GVWR, Spring Suspension, 139 in Wheelbase, Receiver Usage: 236,655 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9015	2013 Ram 2500 4x4 Pickup S/N: 3C6LR5BL8DG536162 C/W: 6.7 L 6 Cylinder Diesel Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Fuel Tank /w Pump, Tool Box, Spray-On Bed Liner, 9000 lb GVWR, 285/70R17 Tires, 8 ft Bed Usage: 218,248 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9021	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF0HKE23722 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 4 ft 6 in Bed Usage: 119,473 Mi Asset located in: Humble, TX 2017 Ford F-150 XLT 4x2 Crew Cab Pickup
9016	2021 Ford F-150 STX 4x2 Crew Cab Pickup S/N: 1FTEW1CP0MKD32808 C/W: 2.7 L V6 Gasoline Engine, 2021 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6400 lb GVWR, 275/60R20 Tires, 5 ft 8 in Bed Usage: 110,465 Mi Asset located in: Humble, TX		S/N: 1FTEW1CF2HKE53076 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, WEATHER GUARD Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265/70R17 Tires, 5 ft 7 in Bed Usage: 140,099 Mi Asset located in: Humble, TX
9017	2018 Ford F-150 4x2 Crew Cab Pickup S/N: 1FTEW1C50JKC10783 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Weatherguard Tool Box, Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed Usage: 165,997 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9023	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CF6HKE23725 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 5 in Bed Usage: 142,764 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
9018	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C52JKC10770 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Headache Rack, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/70R18 Tires, 6 ft 7 in Bed Usage: 146,917 Mi	9024	2016 Ram 1500 4x2 Crew Cab Pickup S/N: 1C6RR6KT8GS238756 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6900 lb GVWR, 275/50R20 Tires, 6 ft Bed Usage: 165,538 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9025	2016 Ram 1500 4x2 Crew Cab Pickup
9019	2018 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1C56JKC10769 C/W: 5.0 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Weatherguard Tool Box, Spray-On Bed Liner, 6950 lb GVWR, 265/60R18 Tires, 6 ft Bed Usage: 145,418 Hr Asset located in: Humble, TX		S/N: 1C6RR6KTXGS141803 C/W: 5.7 L V8 Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 6900 lb GVWR, 275/60R20 Tires, 6 ft Bed Usage: 219,251 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9026	2016 Chevrolet 1500 4x2 Crew Cab Pickup
9020	2017 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTEW1CFXHKE23730 C/W: 5.0 L V8 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Headache Rack, Weather Guard Tool Box, Spray-On Bed Liner, 6800 lb GVWR, 265 /70R17 Tires, 5 ft 8 in Bed Usage: 86,433 Mi Asset located in: Humble, TX		S/N: 3GCPCREC3GG233079 C/W: 5.3 L V8 Gasoline Engine, 2016 US EPA Label, CARB Compliant, Automatic Transmission, Air Conditioner, Power Windows, Tonneau Cover, 7000 lb GVWR, 5 ft 6 in Bed Usage: 269,698 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9027	2014 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTFW1CF4EKG33790 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 129,930 Mi Asset located in: Humble, TX	9033	2004 Ford F-150 XLT 4x2 Crew Cab Pickup S/N: 1FTRW12W54KC24338 C/W: 4.6 L V8 Gasoline Engine, 2004 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 6800 lb GVWR, 265/70R17 Tires, 6 ft Bed Usage: 53,387 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
9028	2014 Ford F-150 XLT 4x2 Crew Cab Pickup		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1FTFW1CF3EKG33800 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 133,616 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9034	2019 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTFX1C44KKE10558 C/W: 3.5 L V6 Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 7850 lb GVWR, 265/75R18 Tires, 8 ft Bed Usage: 204,106 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9029	2014 Ford F-150 XL 4x2 Crew Cab Pickup		Asset located in: Humble, TX
	S/N: 1FTFW1CF3EFC74649 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, Spray-On Bed Liner, 7100 lb GVWR, 265/70R17 Tires, 5 ft 6 in Bed Usage: 260,242 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9035	2017 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1C86HKD42884 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Weather Guard Tool Box, Spray-On Bed Liner, 265/70R17 Tires, 6 ft Bed, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: 114,133 Mi
	Asset located in: Humble, TX		Notes: DEFICIENCIES NOTED - PLEASE SEE
9030	2012 Ford F-150 XLT 4x2 Crew Cab Pickup	1	THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 1FTFW1CF4CFC37381 C/W: 5.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fiberglass Truck Cap, 7100 lb GVWR, 265/70R17 Tires, 7 ft Bed Usage: 244,407 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9036	2014 Ford F-150 XLT 4x2 Extended Cab Pickup S/N: 1FTFX1CF2EKE98841 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Fiberglass Truck Cap, 275/70R18 Tires, 6 ft Bed Usage: 180,328 Mi Asset located in: Humble, TX
9031	2012 Ford F-150 XLT 4x2 Crew Cab Pickup	9037	2014 Ford F-150 XLT 4x2 Extended Cab Pickup
	S/N: 1FTFW1CF8CFC37383 C/W: 5.0 L V8 Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Fiberglass Truck Cap, 7100 lb GVWR, 255/65R17 Tires, 6 ft 0 in Bed Usage: 231,823 Mi Asset located in: Humble, TX	9037	S/N: 1FTFX1CF8EFD08775 C/W: 5.0 L V8 Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Adjustable Pedals, Power Windows, Fiberglass Truck Cap, 7100 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: 247,324 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE
9032	2011 GMC Sierra 1500 4x2 Crew Cab Pickup		THE INSPECTION REPORT
-	S/N: 3GTP1UEA7BG361406 C/W: 4.8 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 245/70R17 Tires, 5 ft 8 in Bed Usage: 261,224 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9038	Asset located in: Humble, TX 2013 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTFX1CF5DKG26987 C/W: 5.0 L V8 Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air Conditioner, Headache Rack, 7100 lb GVWR, 265/65R17 Tires, 6 ft 2 in Bed Usage: 248,292 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9039	2010 Ford F-150 XL 4x2 Extended Cab Pickup S/N: 1FTEX1CW7AFA49587 C/W: 4.6 L V8 Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Fuel Tank /w Pump, RKI Tool Box, 6700 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 299,524 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9045	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH6FZ320612 C/W: V6 Gasoline Engine, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6700 lb GVWR, 255/70R17 Tires, 8 ft Bed Usage: 155,112 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
9040	2010 Chevrolet Silverado 1500 4x2 Extended Cab Pickup S/N: 1GCSCSE0XAZ284657 C/W: V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Tonneau Cover, 6800 lb GVWR, 265/65R18 Tires, 6 ft Bed Usage: 172,463 Mi Notes: TITLE BRANDS REBUILT SALVAGE DEFICIENCIES NOTED - PLEASE SEE THE	9046	2015 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCNCPEH5FZ270933 C/W: 4.3 L V6 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Fiberglass Truck Cap, 6700 lb GVWR, 265/70R17 Tires, 8 ft Bed, Pump, Tank, Reel Usage: 194,254 Mi Asset located in: Humble, TX 2011 Ford F-150 XL 4x2 Pickup
9041	Asset located in: Humble, TX 2009 Chevrolet Silverado 1500 LT 4x2 Extended Cab Pickup S/N: 1GCEC29039Z140354 C/W: 5.3 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air		S/N: 1FTNF1CF3BKD45587 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, WEATHER GUARD Tool Box, Drop- In Bed Liner, 7050 lb GVWR, 235/80R17 Tires, 8 ft 1 in Bed Usage: 201,941 Mi Asset located in: Humble, TX
9042	Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 6800 lb GVWR, 275/55R20 Tires, 6 ft 7 in Bed Usage: 140,470 Mi Asset located in: Humble, TX 2008 Ford F-150 4x2 Extended Cab Pickup S/N: 1FTRX12W28FA46173 C/W: V8 Gasoline Engine, Automatic	9048	2009 Ford F-150 XL 4x2 Pickup S/N: 1FTRF12W59KB51656 C/W: 4.6 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, Drop-In Bed Liner, 6750 lb GVWR, 265/70R17 Tires, 8 ft Bed Usage: 224,685 Mi
9043	Transmission, Air Conditioner, Headache Rack, RKI Tool Box, Drop-In Bed Liner, 6700 lb GVWR, 275/65R18 Tires, 6 ft 6 in Bed Usage: 275,804 Mi Asset located in: Humble, TX 2018 Ford F-150 XL 4x2 Pickup		Asset located in: Humble, TX 2009 Ford F-150 XL 4x2 Pickup S/N: 1FTRF12W89KB67589 C/W: 4.6 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Air Conditioner, RKI Tool Box, Spray-On Bed Liner, 6750 lb GVWR, 265/70R17 Tires, 8 ft Bed
	S/N: 1FTMF1CB1JKF29935 C/W: 3.3 L V6 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Lund Fuel Tank /w Pump, RKI Tool Box, Spray-On Bed Liner, 6170 lb GVWR, 265		Usage: 50,746 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9044	/70R15 Tires, 8 ft Bed Usage: 90,218 Mi Asset located in: Humble, TX 2015 Chevrolet Silverado 1500 4x2 Pickup	9050	2017 Toyota Tacoma 4x4 Pickup S/N: 5TFCZ5AN2HX070371 Usage: Not Available Asset located in: Humble, TX
	S/N: 1GCNCPEHXFZ385754 C/W: 4.3 L V6 Gasoline Engine, US EPA Label, Automatic Transmission, Air Conditioner, Sunroof, Tonneau Cover, Fiberglass Truck Cap, 5700 lb GVWR, 255/70R17 Tires, 8 ft 6 in Bed Jsage: 167,909 Mi Asset located in: Humble, TX	9051	2022 Ford Ranger 4x2 Crew Cab Pickup S/N: 1FTER4EH9NLD35538 C/W: 2.3 L 4 Cylinder Gasoline Engine, 2022 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6050 lb GVWR, 255/70/16 Tires, 5 ft Bed Usage: 41,346 Mi Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9052	2019 Toyota Tacoma 4x2 Crew Cab Pickup S/N: 5TFAX5GN1KX141586 C/W: 2.7 L 4 Cylinder Gasoline Engine, 2019 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 5600 lb GVWR, 275/55R20 Tires, 5 ft Bed Usage: 32,500 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9057	2017 Nissan Frontier XE 4x2 Extended Cab Pickup S/N: 1N6BD0CT0HN754966 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 99,319 Mi Asset located in: Humble, TX
9053A	2018 Chevrolet Colorado 4x2 Extended Cab Pickup S/N: 1GCHSBEN8J1244066 Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		S/N: 1N6BD0CTXGN730432 C/W: 4 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Truck Cap, 4700 lb GVWR, 235 /75R15 Tires, 5 ft 8 in Bed Usage: 168,156 Mi Notes: Asset located in: Humble, TX
9053	2020 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6ED0CE4LN718477 C/W: 3.8 L V6 Gasoline Engine, 2020 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Aluminum Truck Cap, 6012 lb GVWR, 265/70R16 Tires, 6 ft Bed Usage: 127,341 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9059	2016 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT6GN717452 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft 2 in Bed Usage: 131,524 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9054	2017 Nissan Frontier 4x2 Extended Cab Pickup	1	Asset located in: Humble, TX
	S/N: 1N6BD0CT0HN758693 C/W: 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Tonneau Cover, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 90,565 Mi Asset located in: Humble, TX	9060	2016 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT0GN727989 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, 4700 lb GVWR, 235/75R15 Tires, 6 ft 2 in Bed Usage: 119,834 Mi Asset located in: Humble, TX
9055	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT4HN756140 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 146,983 Mi Asset located in: Humble, TX	9061	2007 Toyota Tundra 4x2 Extended Cab Pickup S/N: 5TFRT54157X015223 C/W: 4.7 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Spray-On Bed Liner, 6700 lb GVWR, 255/70R18 Tires, 6 ft 6 in Bed Usage: 286,967 Mi
9056	2017 Nissan Frontier 4x2 Extended Cab Pickup S/N: 1N6BD0CT2HN774460 C/W: 2.5 L 4 Cylinder Gasoline Engine, 2017 US		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	EPA Label, 5 Speed Manual Transmission, Air Conditioner, Leonard Tool Box, Drop-In Bed Liner, 4700 lb GVWR, 235/75R15 Tires, 6 ft Bed Usage: 236,402 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9063	2016 Forest River Wildwood 30 ft 7 in T/A Travel Trailer S/N: 4X4TWDC21GA256534 C/W: Sleeps 6 People, Single Slide Out, Power Leveling Jacks, Bumper Pull, Spring Suspension, Electric Brakes, 205/75R15 Tires Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9064	2023 XLR MicroBoost 29 LRLE 27 ft T/A Toy Hauler Travel Trailer S/N: 5ZT2XLUB0PZ795203	9070	22 Ft x 7 Ft Floating Dock S/N: Not Available Usage: Not Available
	C/W: Air Conditioner, 11436 lb GVWR, Single Slide Out, Power Awning, Bumper Pull, Spring		Asset located in: Humble, TX
	Suspension, Electric Brakes, 225/75R15 Tires Usage: Not Available	9071	26 ft 6 in x 7 ft Floating Dock S/N: Not Available
	Asset located in: Humble, TX		Usage: Not Available
9065	2023 XLR MicroBoost 29 LRLE 31 ft T/A Toy		Asset located in: Humble, TX
	Hauler Travel Trailer S/N: 5ZT2XLUB2PZ795199 C/W: Sleeps 4 People, 11346 lb GVWR, Single	9072	26 ft 6 in x 7 ft Floating Dock S/N: Not Available
			Usage: Not Available
	Slide Out, Power Awning, Bumper Pull, Spring Suspension, Electric Brakes, 225/75R15 Tires		Asset located in: Humble, TX
	Usage: Not Available	9073	12x60 Mobile Office S/N: 170754
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
9066	2022 XLR MicroBoost 29 LRLE 27 ft T/A Toy	9074	1994 Lykal 12x54 54 ft x 12 ft Skid-Mounted Mobile Office
	Hauler Travel Trailer S/N: 5ZT2XLUB6NZ793596		S/N: LSW12540294506
	C/W: 11540 lb GVWR, Single Slide Out, Power		C/W: (2) Kitchens, (2) Bedrooms w/(4) Beds, (2) Bathrooms, Air Conditioner, Laundry
	Awning, Bumper Pull, Torsion Axle Suspension, Electric Brakes, 225/75R15 Tires	_	Usage: Not Available
	Usage: Not Available		Notes: This Item is the buyers responsibility for LOADING and removal and it CAN NOT be relisted. DEFICIENCIES NOTED - PLEASE SEE
00674	Asset located in: Humble, TX 2000 Sea-Doo Bombardier GTX 10 ft Personal Watercraft w/2012 Zieman RBET80X16-12WD		
9067A			THE INSPECTION REPORT Asset located in: Livingston, LA
	Trailer	9075	2024 43 ft 6 in x 12 ft 2 in Portable Tri/A
	S/N: ZZN26948A000 C/W: 2 Passenger, Inboard Rotax 951 cc		Mobile Office (Unused)
	Engine, Reverse, Rearview Mirrors, S/A Trailer w/ S/N- 1M9BE1624CL516337, Ball Hitch		S/N: 92409 C/W: (2) Offices, (1) Bathrooms, Air
	Usage: Not Available		Conditioner, Spring Suspension, 8-14.5 Tires, Common Area
	Asset located in: Humble, TX	4	Usage: Not Available
9067	2022 Forest River XLT29LRLE-79 34 ft T/A Travel Trailer S/N: 5ZT2XLUB7NZ794465		Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX
			Asset located in: Lake Worth, TX
	C/W: 11540 lb GVWR, Single Slide Out, Power Awning, Bumper Pull, Torsion Axle Suspension,	9076	30 ft x 10 ft 1 in Portable Mobile Office
	Electric Brakes, 225/75R15 Tires Usage: Not Available		S/N: 24392 C/W: (2) Offices, (1) Bathrooms, Air
	Asset located in: Humble, TX		Conditioner, Spring Suspension, 8-14.5 Tire Usage: Not Available
9068	1996 War Eagle 15 ft Bass Boat w/ Trailer S/N: MTW03829F697		Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX
	C/W: 2 Passenger, Outboard Mercury 30 hp		Asset located in: Lake Worth, TX
	Engine, S/A Trailer w/ S/N- 1BTETHM1951000175, Ball Hitch, Engine VIN	9077	40 ft x 8 ft High Cube Office Container
	0R700328 Usage: Not Available		(Unused)
	Notes: NO TITLE AVAILABLE FOR TRAILER,		S/N: JUHU1202268 C/W: single walk door, 4 windows, A/C, lighting
	SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX		Usage: Not Available Asset located in : Humble, TX
9069	1997 Bay Stealth 18 ft Fishing Boat w/1998	9078	2024 Garper GP8-24 20 ft x 8 ft 3 in Portable S
	Vivian Industry Trailer		/A Mobile Office (Unused)
	S/N: 690A898 C/W: Fiberglass Hull, 4 Passenger Capacity, 18		S/N: 3ECG24C1XRGEP0171 C/W: (1) Offices, (1) Bathrooms, Air
	ft Overall Length, Outboard Yamaha 115 hp		Conditioner, Ball Hitch, Spring Suspension, 225
	Engine, S/A Trailer w/ S/N- 7901S0W1000769, Ball Hitch, 522948 VIN Yamaha 115		/75R15 Tires Usage: Not Available
	Usage: Not Available		Asset located in: Humble, TX
	Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9079	2024 Garper GP8-24 20 ft x 8 ft S/A Mobile Office (Unused) S/N: 3ECG24C1XRGEP0173 C/W: (1) Offices, (1) Bathrooms, Air Conditioner, Ball Hitch, Spring Suspension, 225 /75R15 Tires Usage: Not Available Asset located in: Humble, TX	9088	2024 Suihe NMO 20 ft x 7 ft Office Container (Unused) S/N: Not Available Usage: Not Available Notes: LOCATED-IN-HOUSTON-TX-HOU Asset located in: Humble, TX 2023 HOS HF2N1 19 ft x 21 ft Folding Storage
9080	2024 Garper GP8-24 Mobile Office (Unused) S/N: 3ECG24C1XRGEP0172 Usage: Not Available Asset located in: Humble, TX	9009	Building S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9081	2024 20 m x 8 ft Office Container (Unused)		Asset located in: Humble, TX
	S/N: CEOU2212875 C/W: (1) Walk in Door, Two Windows w /Security Bars, Fork Pockets, Laminate Flooring, SunScreen, R13 Insulation, (1) Pioneer HVAC Mini-Split, (1) Electric Panel, LED	9090	2024 HOS HF2J 19 ft x 21 ft Folding House S/N: Not Available Usage: Not Available Asset located in: Humble, TX
	Ceiling Lights, Interior Outlets, Wiring done to National Electric Code (NEC) Usage: Not Available Asset located in : Humble, TX	9092	2008 Etnyre R40TD3 Tri/A Lowboy Trailer S/N: 1E92992418E111108 C/W: 94000 lb GVWR, Air Ride Suspension, 16 ft Main Deck, 102 in Usable Deck Width,
9082	2024 20 ft x 8 ft Office Container (Unused) S/N: NWRU3518174 C/W: (1) Walk in Door, Two Windows w /Security Bars, Fork Pockets, Laminate	9093	Manual Ramps, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	Flooring, SunScreen, R13 Insulation, (1) Pioneer HVAC Mini-Split, (1) Electric Panel, LED Ceiling Lights, Interior Outlets, Wiring done to National Electric Code (NEC) Usage: Not Available Asset located in: Humble, TX		2006 Trail King TK130HDG-573 Tri/A Removable Gooseneck Lowboy Trailer S/N: 1TKJ057386M014661 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, Flip-Up Neck Extension, T/A Pin-On Booster Axle, Plumbed
9083	20 ft x 8 ft Office Container (Unused) S/N: CBA100578661 C/W: Single walk door, 2 Windows, A/C, Lighting, Lock Box, Fork Pockets Usage: Not Available		for Booster Axle, 28 ft Main Deck, 120 in Overall Deck Width, Honda Gas Powered Self Contained Hydraulic System, 235/75R17.5 Tires, 161280 lb GVWR, Spreader Bar Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
9084	Asset located in: Humble, TX Mobile Office		THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: Not Available Usage: Not Available Asset located in : Humble, TX	9094C	2024 Witzco RG-52 52 ton Lowboy Trailer S/N: 1W8A11E34RS000456 Usage: Not Available
9085	20 ft x 8 ft Mobile Office S/N: 287409 7 C/W: (1) Offices, Air Conditioner Usage: Not Available Asset located in: Humble, TX	9094B	Asset located in: Humble, TX 2024 Witzco RG-52 52 ton Lowboy Trailer S/N: 1W8A11E30RS000454 Usage: Not Available Asset located in: Humble, TX
9086	2024 Suihe NMO-20FT-007D 20 ft x 7 ft Portable Office (Unused) S/N: Not Available Usage: Not Available	9094A	2024 Witzco RG-52 52 ton Lowboy Trailer S/N: 1W8A11E32RS000455 Usage: Not Available Asset located in: Humble, TX
9087	Asset located in: Humble, TX 2024 KJ K2019 20 ft x 19 ft Prefabricated Tiny Home (Unused) S/N: Not Available C/W: THE PRODUCT IMAGES SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY AND MAY NOT BE AN EXACT REPRESENTATION OF THE ACTUAL PRODUCT Usage: Not Available Asset located in: Humble, TX	9094	2006 Loadcraft LCOLP60T4 60 ton Quad/A Lowboy Trailer S/N: 5ABB604026B060033 C/W: Air Ride Suspension, 44 ft 6 in Main Deck 102 in Usable Deck Width, Deck Over Tires, Pickup Throat, Tail Roller, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9095	2015 Eager Beaver 50GSL/BR Tri/A Removable Gooseneck Lowboy Trailer S/N: 112SB2518FL079783 C/W: Air Ride Suspension, Hydraulic Removable Gooseneck, 24 ft Main Deck, 10 ft 6 in Rear Deck, 4 ft Fixed Dovetail, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, 225/70R22.5 Tires, 122500 lb GVWR Usage: Not Available Asset located in: Humble, TX	9099	1982 Phelan HS25H-N T/A Heavy-Haul Jeep S/N: 1R9H39202C1010387 C/W: 69600 lb GVWR, Air Slide 5th Wheel, Spring Suspension, 11R22.5 Tires, 69600 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2002 Trail King S/A Booster Axle
9096	2001 Holden HRD50 50 ton Tri/A Lowboy Trailer S/N: 12HRD55321N506652 C/W: 1249920 lb GVWR, Walking Beam Suspension, 40 ft Main Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, Pickup		S/N: 1TKS005192M078078 C/W: Flip-Up, Air Ride Suspension, 255/70R22. 5 Tires Usage: Not Available Asset located in : Humble, TX
	Throat, Tail Roller, 255/70R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9101	2004 Landoll 435 48 ft T/A Sliding Axle Trailer S/N: 1LH435UH441013578 C/W: Air Ride Suspension, 9 ft 8 in Upper Deck, 38 ft 2 in Main Deck, 94 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 245/70R17.5 Tires, Aluminum Ag Slide
9097B	2007 Lufkin 53 ft Quad/A Lowboy Oilfield Trailer S/N: 1L01B534871164497 C/W: Air Ride Suspension, Lift 4th- Axles, 98 in Deck Width, 11 ft Upper Deck, 42 ft Main Deck, Tail Roller, Kicker Rollers, 255/70R22.5 Tires Usage: Not Available		Out Extensions Usage: Not Available Notes: Well Maintained Central Texas Paving Company - Fleet Realignment DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9102	02 2015 Ledwell LW48HT2-10-PB T/A Hydrauli Tail Trailer
9097A	2006 Witzco RG-35 35 ton T/A Lowboy Trailer S/N: 1W8A11D256S000373 C/W: Spring Suspension, 22 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, 126 in Widening Width, 255/70R22.5 Tires,		S/N: 1L9GA72A5FL033832 C/W: 80000 lb GVWR, Air Ride Suspension, 9 ft Upper Deck, 39 ft Main Deck, 12 ft 2-Position Dovetail, 102 in Usable Deck Width, Winch, Upper Deck Ramps, 235/75R17.5 Tires Usage: Not Available
	86400 lb GVWR Usage: Not Available	9103	Asset located in: Humble, TX 2015 Landoll 930C-48-15 T/A Hydraulic Tail
9097	Asset located in: Humble, TX 1992 Talbert T3BD85KHRGT1 43 ton Tri/A Beam Removable Gooseneck Lowboy Trailer S/N: 40FB0523XN1009896 C/W: 99400 lb GVWR, Air Ride Suspension, Hydraulic Removable Gooseneck, Plumbed for Booster Axle, 25 ft 6 in Main Deck, 255/70R22. 5 Tires Usage: Not Available Asset located in: Humble, TX		Trailer S/N: 1LH930UH2F1C21747 C/W: Air Ride Suspension, 10 ft Upper Deck, 23 ft Main Deck, 15 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, Aluminum Wheels, 245 /70R17.5 Tires, 86300 lb GVWR, Right Weigh Load Scale Usage: Not Available Asset located in: Humble, TX
9098	2012 XL Specialized XL60 T/A Removable Gooseneck Lowboy Trailer S/N: 4U3J04825CL011764 C/W: Air Ride Suspension, Mechanical Removable Gooseneck, 8 ft 6 in Upper Deck, 29 ft Main Deck, 7 ft 5 in Rear Deck, 102 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Aluminum Outer Wheels, 255 /70R22.5 Tires, 74370 lb GVWR, Upper and Rear Deck are Aluminum decking Usage: Not Available Asset located in: Humble, TX	9104A	2014 Trail King T/A Hydraulic Tail Trailer S/N: 1TKA04825EM034431 C/W: Air Ride Suspension, 6 ft 2 in Upper Deck, 30 ft Main Deck, 7 ft 6 in 2-Position Dovetail, 101 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, 10R- 17.5 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9104	2014 Landoll 930C-48-15 T/A Hydraulic Tail Trailer S/N: 1LH930UH0E1C21440 C/W: Air Ride Suspension, 10 ft Upper Deck, 23 ft Main Deck, 15 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Deck Over Tires, 245/70R17.5 Tires, 86300 lb GVWR, Right Weigh Load Scale Usage: Not Available Asset located in: Humble, TX	9112	2014 Fontaine HCICD22RSA 80000 lb 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N2532C3E1565455 C/W: 65042 lb GVWR, Air Ride Suspension, Sliding Suspension, 10 ft Upper Deck, 43 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires Usage: Not Available
9105	2009 Ledwell T/A Hydraulic Tail Trailer		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	S/N: 1L9GA72A79L033741 C/W: Air Ride Suspension, 9 ft 3 in Upper Deck, 30 ft 6 in Main Deck, 12 ft 2-Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Winch, Upper Deck Ramps, Aluminum Outer Wheels, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9113	2013 Doonan 53 ft Tri/A Single Drop Step Deck Trailer S/N: 1D9BH533XD1609226 C/W: 110000 lb GVWR, Air Ride Suspension, 11 ft Upper Deck, 42 ft Main Deck, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Tail Roller, Kicker Rollers, Wood
9106	2005 Ledwell T/A Hydraulic Tail Trailer		Flooring, 255/70R22.5 Tires Usage: Not Available
	S/N: 1L9GA72A95L033394 C/W: Air Ride Suspension, 7 ft Upper Deck, 27 ft Main Deck, 12 ft 2-Position Dovetail, 93 in		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over	9114	Asset located in: Humble, TX 2004 Great Dane 53 ft T/A Spread Axle Single
	Tires, 255/70R22.5 Tires Usage: Not Available		Drop Step Deck Trailer
9107	Asset located in: Humble, TX 1986 Trail King 45 ft T/A Hydraulic Tail Trailer S/N: 1TKA0452XGM037025 C/W: Spring Suspension, 10 ft Upper Deck, 25 ft Main Deck, 10 ft 2-Position Dovetail, 94 in Usable Deck Width, 102 in Overall Deck Width, 12 in Widening Width, Storage Compartments, Deck Over Tires, 10R17.5 Tires		S/N: 1GRDM06284M700769 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 10 ft 6 in Upper Deck, 42 ft 6 in Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX	9115	2000 Pro-Trak 53 ft T/A Step Deck Trailer S/N: 5BNDG5322YC001797
9109	2023 Great Dane FLD002400053 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1GR4M0627PH443584 C/W: 70000 lb GVWR, Air Ride Suspension, Air Brakes, 9 ft 6 in Upper Deck, 43 ft Main Deck, 96 in Usable Deck Width, Deck Over Tires,		C/W: Spring Suspension, Electric Brakes, 9 ft Upper Deck, 39 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 225/75R16 Tires Usage: Not Available Asset located in: Humble, TX
	Aluminum Flooring, 255/70R22.5 Tires Usage: Not Available	9116	2014 Ledwell LW48SDT2 48 ft T/A Single Drop
9110	Asset located in: Humble, TX 2019 Fontaine HAILD22RSA 40000 lb 53 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 13N2532C2K1530921 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 11 ft Upper Deck, 42 ft Main Deck, 102 in Usable Deck Width, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 245 /70R17.5 Tires Usage: Not Available		Step Deck Trailer S/N: 1L9DA72A3EL033717 C/W: Air Ride Suspension, 9 ft 10 in Upper Deck, 37 ft 8 in Main Deck, 96 in Usable Deck Width, 99 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 70000 lb GVWR, Trailer Scale Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9117	2003 Fontaine 48 ft T/A Spread Axle Single Drop Step Deck Trailer
9111	2014 Transcraft 53 ft Tri/A Step Deck Trailer S/N: 1TTE533S1E3768554 C/W: Air Ride Suspension, Lift Axles, Wood Flooring, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	S/N: 13N24830931518559 C/W: Air Ride Suspension, ft 10 in Main Deck, 97 in Us in Overall Deck Width, Deck Flooring, 255/70R22.5 Tires Usage: Not Available	S/N: 13N24830931518559 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 10 in Main Deck, 97 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires

Lot #	Details	Lot #	Details	
9118	2001 Transcraft 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1TTE4820811066690 C/W: Air Ride Suspension, 10 ft 10 in Upper Deck, 37 ft Main Deck, 97 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9124	1995 Trail King 48 ft T/A Single Drop Step Deck Trailer S/N: 1TKB04826SM126101 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Wood Flooring, 275/70R22.5 Tires, 82340 lb GVWR Usage: Not Available Asset located in: Humble, TX 1995 Trail King TK70CS-432 48 ft T/A Single Drop Step Deck Trailer	
9119	1996 Fruehauf PSDAT2W48W 48 ft T/A Spread Axle Single Drop Step Deck Trailer S/N: 1H2P04822TW007004 C/W: 91000 lb GVWR, Air Ride Suspension, Air Brakes, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Aluminum w/Wood Strips Flooring, 255/70R22.5 Tires	9126	S/N: 1TKB04828SM126102 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 9 in Main Deck, 97 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 275/70R22.5 Tires, 82340 lb GVWR Usage: Not Available Asset located in: Humble, TX 1986 Aztec 48 ft S/A Single Drop Step Deck	
	Usage: Not Available Notes: . Asset located in: Humble, TX		Trailer S/N: 1AZBR1B38G1017407	
9120	1996 Trail King TK70LCS-482 48 ft T/A Single Drop Step Deck Trailer S/N: 3TKB04829TP083068 C/W: Air Ride Suspension, Air Brakes, 9 ft 8 in Upper Deck, 37 ft 6 in Main Deck, 0 ft Rear		C/W: Spring Suspension, 15 ft 5 in Upper Deck, 27 ft 3 in Main Deck, 6 ft 4 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, 10R17.5 Tires Usage: Not Available Asset located in: Humble, TX	
	Deck, 0 ft Dovetail, 96 in Usable Deck Width, 97 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 81475 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX	9127	1992 Fontaine 38 ft T/A Spread Axle Step Deck Trailer S/N: 13N248303N1554136 C/W: Air Ride Suspension, Air Brakes, 91 in Usable Deck Width, 96 in Overall Deck Width, Manual Ramps, Steel Decking, 255/70R22.5	
9121	1996 Trail King 48 ft Step Deck Trailer S/N: 1TKJ05322TM123951 Usage: Not Available		Asset located in	Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX		2022 Utility FS2CHA 53 ft T/A Spread Axle	
9122	1996 Trail King 48 ft T/A Single Drop Step Deck Trailer S/N: 3TKB04820TP083069 C/W: Air Ride Suspension, 10 ft Upper Deck, 37 ft 5 in Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, 255 /70R22.5 Tires, 81475 lb GVWR Usage: Not Available		Flatbed Trailer S/N: 1UYFS2530N5498621 C/W: 73000 lb GVWR, Air Ride Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	9132	2013 Great Dane GPL-0024-00053 53 ft T/A	
9123	1996 Trail King TK70LCS482 48 ft T/A Single Drop Step Deck Trailer S/N: 3TKB04827TP083067 C/W: Air Ride Suspension, 10 ft Upper Deck, 38 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Wood Flooring, 255/70R22.5 Tires, 81475 lb GVWR Usage: Not Available Asset located in: Humble, TX	0122	Spread Axle Flatbed Trailer S/N: 1GRDM0625DH716744 C/W: Air Ride Suspension, 97 in Deck Width, 97 in Overall Width, Bulkhead, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 Great Dane 53 ft T/A Flatbed Trailer	
		9133	2013 Great Dane 53 ft T/A Flatbed Trailer S/N: 1GRDM0629DH716696 C/W: 58000 lb GVWR, Air Ride Suspension, 94 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9134	2013 Great Dane 53 ft T/A Flatbed Trailer S/N: 1GRDM0629DH716763 C/W: Air Ride Suspension, 96 in Deck Width, 99 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 58000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9141	2012 Utility FS2CHS 48 ft T/A Flatbed Trailer S/N: 1UYFS2487CA402601 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires, 73000 lb GVWR Usage: Not Available
9135	1997 Kalyn Siebert 53 ft T/A Flatbed Trailer		Asset located in: Humble, TX
	S/N: 1K9F53215V1005397 Usage: Not Available Asset located in : Humble, TX	9142	2009 Utility FS2CHS 48 ft T/A Flatbed Trailer S/N: 1UYFS24849A672202 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Wood
9136	2023 Fontaine HAVSF12WSA T/A Spread Axle Flatbed Trailer S/N: 13N148204P1552041		Flooring, 11R22.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in : Humble, TX
	C/W: 70543 lb GVWR, Air Ride Suspension, Air	01.40	·
	Brakes, 98 in Deck Width, 102 in Overall Width, 295/75R22.5 Tires Usage: Not Available Asset located in : Humble, TX	9143	2005 Utility 48 ft T/A Flatbed Trailer S/N: 1UYFS24875A696326 C/W: 36300 lb GVWR, Walking Beam Suspension, 82 in Deck Width, 85 in Overall Width, Wood Flooring, 11R22.5 Tires
9137	2018 Transcraft 40000 lb 48 ft T/A Spread		Usage: Not Available
	Axle Flatbed Trailer S/N: 1TTF482C0J3086368	01.44	Asset located in: Humble, TX
	C/W: Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, 11R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9144	2004 Utility 48 ft T/A Spread Axle Flatbed Trailer S/N: 1UYFS24874A313905 C/W: 80000 lb GVWR, Air Ride Suspension, 96 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Outer Wheels, 11R22.5 Tires
	Asset located in: Humble, TX		Usage: Not Available
9138	2016 Fontaine XCALIBUR T/A 48 ft Extendable Flatbed Trailer S/N: 57J448200G3572398 C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 97 in Overall Width, Extendable Deck, Wood Flooring, 11R22.5 Tires, 85600 lb GVWR Usage: Not Available		Notes: LOCATED-IN-MIDLAND-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING
			Asset located in: Midland, TX
		9145	2003 Fontaine FTW-5-8048WSAWK 48 ft T/A Spread Axle Flatbed Trailer S/N: 13N14830X35917145
	Asset located in: Humble, TX	4	C/W: Air Ride Suspension, 97 in Deck Width, 97
9139	2013 Utility FS2CHA 48 ft T/A Spread Axle Flatbed Trailer	in Overall Width, Wood Flooring, 11R22.5 - 80000 lb GVWR Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SE THE INSPECTION REPORT	
	S/N: 1UYFS2481DA697230 C/W: 73000 lb GVWR, Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Aluminum		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	w/Wood Strips Flooring, Aluminum Wheels, 295 /75R22.5 Tires		Asset located in: Humble, TX
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9146	1997 Lufkin FL-II-ST 48 ft T/A Flatbed Trailer S/N: 1L01B4820V1127376 C/W: Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 97 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR
9140	2013 Utility FS2CHS 48 ft T/A Flatbed Trailer		Usage: Not Available
	S/N: 1UYFS2481DA506101		Asset located in: Humble, TX
	C/W: Spring Suspension, Sliding Suspension, 97 in Deck Width, 97 in Overall Width, Bulkhead, Wood Flooring, 295/75R22.5 Tires, 73000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9147	1995 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B4821S1120514 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires Usage: Not Available
			Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9148	1995 Lufkin FL-II-ST 48 ft T/A Flatbed Trailer S/N: 1L01B4826S1116989 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	9155	1997 Utility 45 ft T/A Flatbed Trailer S/N: 1UYFS245XVA294001 C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	0156	·
9149	1995 Lufkin 48 ft T/A Flatbed Trailer S/N: 1L01B4824S1116991 C/W: Air Ride Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 275 /80R22.5 Tires, 80000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9156	1989 Fruehauf 42 ft T/A Flatbed Trailer S/N: 1H5P04226KM061220 C/W: Spring Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9150	1994 Lufkin FL-II-ST 48 ft T/A Flatbed Trailer S/N: 1L01B4827R1112198 C/W: Air Ride Suspension, Sliding Suspension, 98 in Deck Width, 102 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	9157	2003 AA Welding 40 ft T/A Gooseneck Flatbed Trailer S/N: 1UFGN42233T023646 C/W: Spring Suspension, Electric Brakes, 97.5 in Deck Width, 102 in Overall Width, Wood Flooring, 235/85R16 Tires, 18000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9151	Asset located in: Humble, TX 2018 Transcraft 45 ft T/A Flatbed Trailer S/N: 1TTF452SXJ3086884 C/W: Air Ride Suspension, Sliding Suspension, 96 in Deck Width, 100 in Overall Width, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR	9158	1981 SHPB 40 ft T/A Flatbed Trailer S/N: 0TCN269207 C/W: Spring Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX
9152	Usage: Not Available Asset located in: Humble, TX 2007 Transcraft 45 ft T/A Flatbed Trailer S/N: 1TTF4520071082510 C/W: 80000 lb GVWR, Air Ride Suspension, Sliding Suspension, 97 in Deck Width, 100 in Overall Width, Wood Flooring, Aluminum Wheels, 445/50R22.5 Super Single Tires Usage: Not Available Asset located in: Humble, TX	9159	2018 Dorsey 35 ft T/A Flatbed Trailer S/N: 5JYFB3620JED06364 C/W: Air Ride Suspension, 97 in Overall Width, Bulkhead, Wood Flooring, 11R22.5 Tires, 80000 lb GVWR, Lift Truck Kit Usage: Not Available Asset located in: Humble, TX 1999 Smithco 34 ft T/A Side Dump Trailer S/N: 1S9SS4027XL476497 C/W: Spring Suspension, Dumps to Both Sides,
9153	1999 Transcraft TL2000 45 ft T/A Flatbed Trailer S/N: 1TTF45209X1061722 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, 97 in Deck Width, 102 in Overall Width, Aluminum w/Wood Strips Flooring, Aluminum Wheels, 445/50R22.5 Super Single Tires, Rear Forklift Mount Usage: Not Available Asset located in: Humble, TX	9161	42 in Side Walls, Steel Body, Manual Roll Tarp, 425/65R22.5 Super Single Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1998 Smithco 34 ft T/A Side Dump Trailer S/N: 1S9SS4020WL476324 C/W: Spring Suspension, Dumps to Right Side,
9154	1999 Lufkin EX 45/75 T/A 45 ft - 75 ft Extendable Flatbed Trailer S/N: 1L01B4529X1136438 C/W: Spring Suspension, Sliding Suspension, 92 in Deck Width, 96 in Overall Width, Wood Flooring, 295/75R22.5 Tires, 80000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Humble, TX		42 in Side Walls, Steel Body, Aluminum Whee 425/65R22.5 Super Single Tires, 74300 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9163	2025 Atro 32 ft T/A Frameless Demolition End Dump Trailer (Unused) S/N: 3ELA6EH26SG000342 C/W: Spring Suspension, 32 ft Body, 56 in Side Walls, Steel Body, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX	9167	2025 Atro 32 ft T/A Frameless Aggregate / sand End Dump Trailer S/N: 3ELA6EH21SG000345 C/W: Spring Suspension, 32 ft Body, 44 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX
9164	2025 Atro 32 ft T/A Frameless Demolition End Dump Trailer (Unused) S/N: 3ELA6EH28SG000343 C/W: Spring Suspension, 32 ft Body, 56 in Side Walls, Steel Body, High Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE	9168	2022 CTS EHRD-40 40 ft T/A Frameless End Dump Trailer S/N: 5TU344023NS000394 C/W: Spring Suspension, 40 ft Body, 69 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9165	APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX 2025 Atro 32 ft T/A Frameless Aggregate	9169	2022 CTS EHRD-40 40 ft T/A Frameless End Dump Trailer S/N: 5TU344021NS000393 C/W: Spring Suspension, Air Brakes, 40 ft Body, 60 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires, 68000 lb GVWR
0166	/sand End Dump Trailer S/N: 3ELA6EH2XSG000344 C/W: Spring Suspension, 32 ft Body, 44 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2022 Hicks SL3729 37 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 1H9A37A23NM686001 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Lift 1st- Axles, 33 ft Body, 44 in Side Walls, Aluminum Body, Aluminum Wheels, 11R22.5 Tires, 66000 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX
9166	2025 Atro 32 ft T/A Frameless Aggregate/sand End Dump Trailer S/N: 3ELA6EH23SG000346 C/W: Spring Suspension, 32 ft Body, 44 in Side Walls, Steel Body, Air Lift Tailgate, 11R24.5 Tires, 74957 lb GVWR Usage: Not Available Notes: THE CLOSING TIME OF LOTS 9163 TO 9167 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE	9171	Asset located in: Lake Worth, TX 2021 Load King RH3229 31 ft T/A Frameless Demolition End Dump Trailer S/N: 5LKD34228M4032368 C/W: Spring Suspension, 31 ft Body, 43 in Side Walls, Steel Body, Electric Roll Tarp, Air Lift Tailgate, 11R24.5 Tires, 75000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX	9172	2017 Etnyre V2215 T/A Aluminum End Dump Trailer S/N: 1E9V22154HE111347 C/W: Air Ride Suspension, Air Brakes, Lift 1st- Axles, 34 ft Body, 45 in Side Walls, Aluminum Body, Electric Roll Tarp, 11R22.5 Tires, 81020 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9173	2012 Vantage S-102-SS 39 ft T/A Aluminum Quarter Frame Aggregate/ sand End Dump Trailer S/N: 4E7AA3921CASA3651 C/W: Aluminum Frame, Air Ride Suspension, Lift 1st- Axles, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, Aluminum Outer Wheels, 295/75R22.5 Tires, 84000 lb GVWR Usage: Not Available Notes: THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9180	2003 Vantage 37 ft T/A Quarter Frame End Dump Trailer S/N: 4EPAA37263AVA4581 C/W: 68000 lb GVWR, Aluminum Frame, Air Ride Suspension, 37 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 445/50R22. 5 Super Single Tires Usage: Not Available Asset located in: Humble, TX	
9174		9181	2001 Travis 40 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 48X1F402611001564 C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 40 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R22.5 Tires	
9174	2011 MAC 40 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 5MADN4025BC020508 C/W: 80000 lb GVWR, Aluminum Frame, Air Ride Suspension, 40 ft Body, 58 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum	9182	Usage: Not Available Notes: TITLE BRAND REBUILT SALVAGE Asset located in: Humble, TX 1999 Clement 35 ft T/A End Dump Trailer	
9176	Wheels, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2009 MAC 40 ft T/A Aluminum Quarter Frame		S/N: 5C2BB35BXXM001014 C/W: 66000 lb GVWR, Walking Beam Suspension, 35 ft Body, 48 in Side Walls, Steel Body, Electric Roll Tarp, Aluminum Outer Wheels, 285/75R24.5 Tires	
3170	End Dump Trailer S/N: 5MADN40279C018138 C/W: 80000 lb CVWB, Aluminum Frame, Air	2122	Usage: Not Available Asset located in: Humble, TX	
		Walls, Steel Body, Manual Roll Tarp, Ali	Trailer S/N: 1C9BB38BXXM110609 C/W: Spring Suspension, 38 ft Body, 36 in Side Walls, Steel Body, Manual Roll Tarp, Aluminum Outer Wheels, 295/75R22.5 Tires, 66000 lb GVWR	
9177	Asset located in: Humble, TX 2009 MAC 40 ft T/A End Dump Trailer	-	Usage: Not Available Asset located in : Humble, TX	
	S/N: 5MADN40299C018139 C/W: 80000 lb GVWR, Aluminum Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Electric Roll Tarp, Aluminum Wheels, 11R22.5 Tires Usage: Not Available	9184	1998 Allco End Dump Trailer S/N: CA494684 Usage: Not Available Asset located in: Humble, TX	
	Asset located in: Humble, TX	9185	1997 Ravens 40 ft T/A End Dump Trailer S/N: 1R1D14023VJ097217	
9178	2007 CTS HRD32 32 ft T/A Frameless End Dump Trailer S/N: 5TU3432227S000185 C/W: 68000 lb GVWR, Spring Suspension, 32 ft Body, 52 in Side Walls, Steel Body, Electric Roll Tarp, High Lift Tailgate, Aluminum Outer Wheels, 11R24.5 Tires Usage: Not Available	(F F F F F F F F F	C/W: Aluminum/Steel Combinat Ride Suspension, 40 ft Body, 60 Aluminum Body, Manual Roll Tai Tailgate, 11R24.5 Tires, 80000 lk Usage: Not Available	C/W: Aluminum/Steel Combination Frame, Air Ride Suspension, 40 ft Body, 60 in Side Walls, Aluminum Body, Manual Roll Tarp, 2-Way Tailgate, 11R24.5 Tires, 80000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
0170	Asset located in: Humble, TX	9186	1989 Montone 39 ft T/A End Dump Trailer	
9179	2005 Clement HL3762MK2 37 ft T/A Frameless End Dump Trailer S/N: 5C2BB37B45M004825 C/W: 70000 lb GVWR, Spring Suspension, 37 ft Body, 76 in Side Walls, Steel Body, Electric Roll Tarp, Swing Tailgate, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX		S/N: 1M918DW29KD003534 C/W: Aluminum/Steel Combination Frame, Spring Suspension, 39 ft Body, 54 in Side Walls, Aluminum Body, Manual Roll Tarp, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
	1989 Montone 39 ft T/A Aluminum Quarter Frame End Dump Trailer S/N: 1M918DW83KD003467 C/W: Air Ride Suspension, Air Brakes, 39 ft Body, 56 in Side Walls, Aluminum Body, Aluminum Wheels, 11R24.5 Tires, 53 ft Aluminum Lead Body, 4 ft 8 in Lead Side Walls, Manual Lead Tarp Usage: Not Available	9194	2005 Carrocerias T/A Belly Dump Trailer S/N: 3C9BS40245G039358 C/W: Spring Suspension, Clam Gate Electric Roll Tarp, 11R24.5 Tires, 34000 lb GVWR, 15 ft 6 in Lead Body, 7 ft 4 in Lead Side Walls Usage: Not Available Asset located in: Humble, TX
		9195	1998 Beall BABDS421 T/A Aluminum Belly Dump Trailer
9188	Asset located in: Humble, TX 1986 Allco 33 ft T/A Frameless End Dump Trailer S/N: 1S9S00005G0009142		S/N: 1BN2P4025WB005259 C/W: Aluminum Frame, Air Ride Suspension, Clam Gate, 385/65R22.5 Tires, 21000 lb GVWR Usage: Not Available
	C/W: Spring Suspension, 33 ft Body, 44 in Side Walls, Steel Body, High Lift Tailgate, 11R24.5 Tires		Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.
	Usage: Not Available	0107	Asset located in: Livingston, LA 1998 Reall RARDS521 T/A Aluminum Relly
9189	Asset located in: Humble, TX 2022 Armor Lite SBD-40 LTS T/A Belly Dump Trailer S/N: 56EA53K29NA000308 C/W: Spring Suspension, Clam Gate, Push Block, 11R24.5 Tires, Electric Lead Tarp	9197	1998 Beall BABDS521 T/A Aluminum Belly Dump Trailer S/N: 1BN2P3820WB005104 C/W: Aluminum Frame, Spring Suspension, Pintle Hitch, Clam Gate, Aluminum Wheels, 11R22.5 Tires, 64000 lb GVWR Usage: Not Available
	Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.
	Asset located in: Humble, TX	0100	Asset located in: Livingston, LA
9190	2022 DeLucio B3500 16 ft T/A Belly Dump Trailer S/N: 7LVD5BA24ND010263 C/W: Spring Suspension, Clam Gate, Electric	9198	1985 Lufkin Dp S/N: 1L4B40236F1013584 Usage: Not Available
			Asset located in: Humble, TX
9191	Roll Tarp, Aluminum Outer Wheels, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX 2020 R-Way 4021T T/A Belly Dump Trailer S/N: 1K9BF40F9LL366228 C/W: Air Ride Suspension, Clam Gate, 11R22.5 Tires, 80000 lb GVWR	9199	1985 Beall BABDS301 T/A Aluminum Belly Dump Trailer S/N: 1BN2P3122FB001677 C/W: Aluminum Frame, Air Ride Suspension, Clam Gate, Aluminum Wheels, 295/75R22.5 Tires, 66000 lb GVWR Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.
	Usage: Not Available		Asset located in: Livingston, LA
	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9200	2016 Etnyre 31 ft 6 in Tri/A Aluminum Live
9192	2007 Manac 14 ft T/A Belly Dump Trailer S/N: 5MC1116277P006993 C/W: Spring Suspension, Clam Gate Electric Roll Tarp, 11R24.5 Tires, 68000 lb GVWR, 14 ft 10 in Lead Body, 6 ft 4 in Lead Side Walls Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	3200	Bottom Trailer S/N: 1E9V19967GE111009 C/W: Air Ride Suspension, Lift 1st- 2nd- Axles, 31 ft 6 in Body, 42 in Side Walls, Aluminum Body, Manual Roll Tarp, Split Swing Tailgate, 11R24.5 Tires, 81020 lb GVWR, Air Assisted Tailgate, Hendrickson Air Ride suspension Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9201	2015 Peerless 48 ft x 102 in T/A Live Bottom
9193	2007 Manac T/A Belly Dump Trailer S/N: 5MC1116287P006713 C/W: Spring Suspension, Clam Gate Manual Roll Tarp Push Block, 11R24.5 Tires, 68000 lb GVWR Usage: Not Available		Open-Top Chip Trailer S/N: 1PLE04824FPH59384 C/W: Air Ride Suspension, Air Brakes, Pearless, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
	Asset located in: Humble, TX	I	THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9202	2013 Dorsey 48 ft x 102 in T/A Open-Top Chip Trailer S/N: 5JYCV4824DE085009 C/W: 67470 lb GVWR, Spring Suspension, Aluminum Wheels, 455/50R22.5 Super Single Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9209	2019 Southern Trailer 150 bbl T/A Vacuum Tanker Trailer S/N: 4T9V6TA20KJ329227 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 63700 lb GVWR, Aluminum Tank, 63700 lb GVWR, Watson-Chalin Air-Ride Suspension Usage: Not Available Asset located in: Humble, TX 2017 Southern Trailer T/A Vacuum Tanker
9203	1995 IMC 48 ft x 102 in T/A Live Bottom Chip	9210	Trailer
7200	Trailer S/N: 1M9L14826SC343840 C/W: Aluminum Frame, Spring Suspension, 285 /75R24.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE		S/N: 4S9V6TA22HG347005 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 63700 lb GVWR, Aluminum Tank, 63700 lb GVWR Usage: Not Available Asset located in: Humble, TX
	THE INSPECTION REPORT Asset located in: Humble, TX	9211	2016 Southern Trailer T/A Vacuum Tanker Trailer
9204	1994 Ledwell 48 ft x 102 in T/A Live Bottom Open-Top Chip Trailer S/N: 1L9LA72A3RL033475 C/W: Spring Suspension, Sliding Suspension, 295/75R22.5 Tires, 65000 lb GVWR	9212	S/N: 4S9V6TA20GG347048 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX		2008 Proco PV1 T/A Vacuum Tanker Trailer S/N: 1P9KN36218K359458
9205	2017 Timpte Super Hopper 42 ft T/A Belly Dump Grain Trailer S/N: 1TDH42229HB156037 C/W: 65000 lb GVWR, Aluminum Frame, Air Ride Suspension, Air Brakes, Hydraulic Traps,		C/W: Spring Suspension, 11R24.5 Tires, 68000 lb GVWR, Steel Tank, Catwalk w/Guardrails, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	42 ft Aluminum Box, 72 in, Side Walls, Electric Roll Tarp, Aluminum Wheels, 445/50R22.5 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	lb GVWR, Steel Tank, Catwalk w/Guardrail	Trailer
9206	2007 Neville Built 42 ft T/A Belly Dump Grain Trailer		Usage: Not Available Asset located in: Humble, TX
	S/N: 1N9GT42287G175464 C/W: Spring Suspension, 2 Hoppers, Manual Traps, 38 ft Steel Box, 54 in, Side Walls, Manual Roll Tarp, 11R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9215	2007 Dragon 5460 gal T/A Vacuum Tanker Trailer (Inoperable) S/N: 1UNST42277L052674 C/W: Air Ride Suspension, 11R24.5 Tires, Steel Tank, Catwalk w/Guardrails, EQUIPMENT- FROM-A-PRIMORIS-SERVICES-CORP-
9207	7 2017 Southern Welding SWAL1000 1000 cft T /A Pneumatic Bulk Trailer S/N: 4S9V6TA20FT347847 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, Aluminum Tank Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX, Asset located in: Lake Worth, TX	9216	COMPANY Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA 2018 TROX 6300 gal T/A Tanker Trailer S/N: 1T9TG4326J1867289
		•	C/W: Aluminum Frame, Air Ride Suspension, 11R24.5 Tires, 50000 lb GVWR, Aluminum Tank, Catwalk w/Guardrails, 50000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9217	2017 Heil CT12598 9200 gal T/A Tanker Trailer S/N: 5HTSA4421H7600873 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9227A	2010 Dragon 8400 gal T/A Tanker Trailer S/N: 1UNST4420AS078205 C/W: Air Ride Suspension, 11R24.5 Tires, 70000 lb GVWR, Aluminum Tank, 70000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9218	2016 Heilx Tanker Trailer S/N: 5HTAB4422G7H81511 Usage: Not Available Asset located in: Humble, TX	9227 	2011 Heil 8400 gal T/A Tanker Trailer S/N: 1S9AB15B3BH474101 C/W: 68000 lb GVWR, Air Ride Suspension, 11R24.5 Tires, Aluminum Tank Usage: Not Available
9219	2016 Heilx Tanker Trailer S/N: 5HTAB4420G7H81510 Usage: Not Available Asset located in: Humble, TX	9228	Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2008 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB442587H74618
9220	2016 Heilx Tanker Trailer S/N: 5HTAB4424G7H81512 Usage: Not Available Asset located in: Humble, TX		C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R22.5 Tires, Aluminum Tank Usage: Not Available Asset located in : Humble, TX
9221	2016 Heilx Tanker Trailer S/N: 5HTAB4424G7H81509 Usage: Not Available Asset located in : Humble, TX	9229	2008 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452085G22296 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR
9222	2014 Helix Tanker Trailer S/N: 5HTAB4423E7H79991 Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
9223	Asset located in: Humble, TX 2014 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB4429E7H79283 C/W: Aluminum Frame, Air Ride Suspension, Air Brakes, Aluminum Wheels, 11R22.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR	9230	2007 PolarTank 6500 gal T/A Tanker Trailer S/N: 1PMS1432871032253 C/W: Air Ride Suspension, 295/75R22.5 Tires 66000 lb GVWR, Insulated Stainless Steel Ta 66000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9224	Usage: Not Available Asset located in: Humble, TX 2014 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB4426E7H79287 C/W: Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 11R22.5 Tires, Aluminum	9231	2006 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452265G21826 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9225	Tank, 4 Compartments Usage: Not Available Asset located in: Humble, TX 2014 Heil 9200 gal T/A Tanker Trailer S/N: 5HTAB4423E7H79280 C/W: Aluminum Frame, Air Ride Suspension, 11R22.5 Tires, 68000 lb GVWR, Stainless Steel	9232	2005 Vantage 1000 cft T/A Tanker Trailer S/N: 4E7PA42205PBA0492 C/W: 68000 lb GVWR, Aluminum Frame, Air Ride Suspension, Aluminum Wheels, 445 /50R22.5 Super Single Tires, Aluminum Tank Usage: Not Available Asset located in: Humble, TX
	Tank, 4 Compartments, 68000 lb GVWR Usage: Not Available Asset located in : Humble, TX		2005 Polar Tanker Trailer S/N: 1PMA3432251029058 Usage: Not Available
9226	2011 Stephens MC407 8400 gal T/A Tanker Trailer S/N: 1S9AB15B9BH474099 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9234	Asset located in: Humble, TX 2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452X35G14540 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9235	2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452135G14703 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9244	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452313G14010 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9236	2002 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452235G14547 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9245	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452713G13992 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9237	2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452835G14701 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9246	2001 Polar Tank MC407 8400 gal T/A Tanker Trailer S/N: 1PMA3432515002827 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 68000 lb GVWR, Aluminum Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9238	2002 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452335G14542 C/W: Spring Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9247	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL4528Y3G13977 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9239	2003 Heil MC407 8400 gal T/A Tanker Trailer S/N: 5HTDL452935G14545 C/W: Spring Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available Asset located in: Humble, TX	9248	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL4526Y3G13976 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available
9240	2002 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452523G14513 C/W: Spring Suspension, 11R24.5 Tires, 65000 Ib GVWR, Aluminum Tank, 65000 Ib GVWR Usage: Not Available Asset located in: Humble, TX 2001 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452013G14014	9249 9250 9251	Asset located in: Humble, TX 2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452XY3G13978 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available
	C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, Aluminum Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX 2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL4525Y3G13967 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum
9242	2001 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452913G14013 C/W: Air Ride Suspension, Aluminum Wheels, 11R24.5 Tires, 65000 lb GVWR, Aluminum		Tank, Roper Hydraulic Powered Pump, 65000 lb GVWR, Tool box Usage: Not Available Asset located in : Humble, TX
	Tank, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		1997 Trailmaster Tanker Trailer S/N: 190DL4428V3G13006 Usage: Not Available
9243	2000 Heil MC407 8400 gal T/A Tanker Trailer S/N: 190DL452713G14012 C/W: Air Ride Suspension, 11R24.5 Tires, 65000 lb GVWR, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9253	1982 Polar 8000 gal T/A Tanker Trailer S/N: 1PMS34322C1005893 C/W: Spring Suspension, 285/75R24.5 Tires, 68000 lb GVWR, Stainless Steel Tank, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9261	2025 Xstar 750 gal Portable Steel Fuel Tank (Unused) S/N: 1X9T7B82XSH039893 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX
9254	1973 Lubbock MC331 T/A Tanker Trailer	9263	2019 CFWS Pole Trailer
	S/N: 58389 C/W: Spring Suspension, 285/75R24.5 Tires, 66000 lb GVWR, Steel Tank, 66000 lb GVWR Usage: Not Available Asset located in : Humble, TX		S/N: 5SRUT322XKL190044 C/W: 10000 lb GVWR Lunette Ring Hitch, Spring Suspension, Electric Brakes, 6 Stanchions, 235/80R16 Tires, 10000 lb GVWR Usage: Not Available
9255	2018 Multiquip WT5C 500 gal T/A Water Tank		Asset located in: Humble, TX
	Trailer S/N: 5SLBM1224JL024474 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 205/75R14 Tires, 7000 lb GVWR, Poly Tank, Multiquip Gasoline Powered Pump, 7000 lb GVWR	9264	1973 Fruehauf Pole Trailer S/N: 127983 C/W: 65000 lb GVWR Lunette Ring Hitch, Spring Suspension, 1 Stanchions, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9265	2024 PJ Trailers D7142 T/A Roll-Off Trailer S/N: 4P53D2328R1401125 C/W: 15680 lb GVWR, Spring Suspension, Electric Brakes, Manual Roll Tarp, Aluminum
9256	2017 Multiquip WT5C T/A Water Tank Trailer S/N: 4GNBM122GB043462 C/W: Lunette Ring Hitch, Spring Suspension, Surge Brakes, 205/75R14 Tires, 7000 lb GVWR, Poly Tank, Honda Gasoline Powered Pump, 7000 lb GVWR		Wheels, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2020 Benlee TACVDD39S T/A Roll-Off Trailer
0257	Usage: Not Available Asset located in: Humble, TX 2009 Wylie 200 gal S/A Water Tank Trailer S/N: 5VUTB10149P000009 C/W: Ball Hitch, Spring Suspension, 205/75R15		S/N: 1B9A13927LB180200 C/W: Air Ride Suspension, Air Brakes, Benlee Roll-Off Unit Hydraulic Roll Tarp, Aluminum
9257			Outer Wheels, 11R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	Tires, 2950 lb GVWR, Poly Tank, John Blue Gasoline Powered Pump, 2950 lb GVWR, W/ Hose Reel & Gun Usage: 24 Hr Asset located in : Humble, TX	9267 2018 Benlee TASMDS26S T/A Roll-Off Tra S/N: 1B9A12627JB180371 C/W: Spring Suspension, Electric Roll Tarp 11R22.5 Tires, 50000 lb GVWR	2018 Benlee TASMDS26S T/A Roll-Off Trailer S/N: 1B9A12627JB180371 C/W: Spring Suspension, Electric Roll Tarp, 11R22.5 Tires, 50000 lb GVWR
9258	2025 X-STAR 990 gal Portable Steel Fuel Tank (Unused) S/N: 1X9T7BA20SH039895		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	9268	2018 Benlee TASMRS26S T/A Roll-Off Trailer S/N: 1B9A12625JB180059 C/W: Spring Suspension, Air Brakes, 11R22.5 Tires
9259	2025 X Star 990 gal Portable Steel Fuel Tank (Unused)		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
	S/N: 1X9T7BA29SH039894 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in : Humble, TX	9269A	2000 Dragon T/A Roll-Off Trailer S/N: 1B9D14825YE183493 C/W: Air Ride Suspension, 11R22.5 Tires Usage: Not Available
9260	2024 Xstar 750 gal Portable Steel Fuel Tank		Asset located in: Humble, TX
	(Unused) S/N: 1X9T7B828SH039892 C/W: 12 V Transfer Pump, Automatic Shut-Off Nozzle Usage: Not Available Asset located in: Humble, TX	9269	2007 Dentoni T/A Roll-Off Trailer S/N: 1D9SR486571561018 C/W: Air Ride Suspension, 285/75R24.5 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9270	1995 Clement T/A Roll-Off Trailer S/N: 1C9EB36B2SM110256 C/W: Walking Beam Suspension, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX	9282	2022 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 3UTVS2536N8451727 C/W: Air Ride Suspension, Sliding Suspension Side Skirts, Ducted Floor, Swing Door, 2020
9271	T/A Roll-Off Trailer S/N: 82147 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: LOCATED-IN-HOUSTON-TX		Thermo King Precedent S-600 Refrigeration Unit, Serial Number 6001327716,, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: 8,204 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9272	Asset located in: Humble, TX Quantity of (5) 2025 Atro 40 ft T/A Container Frailer S/N: 3ELA6CR2XSG000282 C/W: Spring Suspension, 40 ft - Container Pins, 295/75R22.5 Tires, 65000 lb GVWR Jsage: Not Available Notes: THE CLOSING TIME OF LOTS 9272 TO	9283	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2536L2991424 C/W: Air Ride Suspension, Side Skirts, Swing Door, Carrier Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: 18,872 Hr Asset located in: Humble, TX
0070	9277 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX	9284	2020 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538L2991425 C/W: Air Ride Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires
9273	Quantity Of (5) 2025 Atro 40 Ft T/A Container Trailer (Unused) S/N: 3ELA6CR2XSG000184 C/W: 65000 lb GVWR, Spring Suspension, Air Brakes, 40 ft - Container Pins, 295/75R22.5 Tires Usage: Not Available		Usage: Not Available Asset located in: Humble, TX
		9285	2020 Utility 53 ft T/A Refrigerated Trailer S/N: 1UYVS2539L2991515 Usage: Not Available Asset located in: Humble, TX
	Notes: THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY THE PURCHASER THE CLOSING TIME OF LOTS 9272 TO 9277 ARE TIED TOGETHER. IF A BID IS RECEIVED, THEN A TIME EXTENSION WILL BE APPLIED TO ALL LOTS. ONCE THE TIME CLOSES THE HIGH BIDDER ON EACH LOT WILL BE THE WINNER. Asset located in: Humble, TX	9286	2017 CIMC 53 ft x 102 in T/A Refrigerated Trailer S/N: 527SR5326HM009310 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available
9277B	2013 48 ft 6 in Tri/A Container Trailer S/N: 1M9KP5936DS284143 C/W: Spring Suspension, 245/70R17.5 Tires, 36000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9287	Asset located in: Humble, TX 2017 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS253XHM764345 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Side Skirts, Ducted Floor, Swing
9278	2004 Pratt LSMR53X4 40 ft Tri/A Container Trailer S/N: 1P9CP40394H343011 C/W: Walking Beam Suspension, 255/70R22.5 Tires, 68000 lb GVWR		Door, Carrier Refrigeration Unit, 295/75R22.5 Tires Usage: 7,222 Hr Notes: LOCATED-IN-FORT-WORTH-TX, . Asset located in: Lake Worth, TX
	Usage: Not Available Asset located in: Humble, TX	9288	2017 Utility 53 ft x 102 in T/A Refrigerated Trailer
9281	2023 ACE SC804050L 18 ft T/A Container Trailer S/N: 3BZPN4021PC008329 C/W: 65000 lb GVWR, Air Ride Suspension, 295 /75R22.5 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		S/N: 1UYVS2533H6073405 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, 2017 Thermo King Precedent C- 600 Refrigeration Unit, Serial Number 60001221299,, 11R22.5 Tires, 65000 lb GVWF Usage: 27,750 Hr Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9289	2016 Utility 53 ft x 102 in T/A Refrigerated Trailer	9293	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Multi-Temp Refrigerated Trailer
	S/N: 1UYVS2538GU615320 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier 7500X4 Refrigeration Unit, Serial Number N/A, Aluminum Wheels, 295 /75R22.5 Tires Usage: 14,454 Hr		S/N: 1GRAA0624GE700391 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 28,382 Hr
	Asset located in: Lake Worth, TX		Notes: FROM THE PROFESSIONALLY
9290	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer		MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1GRAA0629GE700371		Asset located in: Humble, TX
	C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Shore Power, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: 30,028 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET	9294	2016 Great Dane 53 ft x 102 in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0624GE700424 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET
	Asset located in: Humble, TX		Usage: 33,311 Hr
9291	Refrigerated Trailer S/N: 1GRAA0625GE700450 C/W: Spring Supposion Sliding Supposion		Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET
			Asset located in: Humble, TX
		9295	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0628GE700393 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Serial Number 2401241128, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE- PROFESSIONALLY-MAINTAINED-WALMART- FLEET Usage: Not Available
	Asset located in: Humble, TX	4	Notes: FROM THE PROFESSIONALLY
9292	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0622GE700390		MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT		Asset located in: Humble, TX
	Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 31,005 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9296	in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0625GE700397 C/W: Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: 27,470 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9297	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0626GE700425 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: Not Available Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9302	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0624GE700388 C/W: Spring Suspension, Sliding Suspension, Carrier Refrigeration Unit, Shore Power, 3-Zone, (2) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY- MAINTAINED-WALMART-FLEET Usage: 29,637 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9298	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0621GE700395 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 26,629 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX	9303	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0629GE700452 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, 2015 Carrier Vector 8600MT Refrigeration Unit, Serial Number RAN91430622,, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: 24,180 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION
9299	2016 Great Dane 53 ft x 102 in T/A Multi-Temp Refrigerated Trailer S/N: 1GRAA0626GE700392 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, Shore Power, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: 28,679 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX		REPORT Asset located in: Humble, TX 2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0627GE700370 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: 27,870 Hr Notes: FROM THE PROFESSIONALLY
9300	2016 Great Dane ECM-1113-12053 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625GE700254 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Refrigeration Unit, 3-Zone, (3) Remote Evaporator, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: 25,344 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX		MAINTAINED WALMART FLEET DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0625GE700447 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, 275/80R22.5 Tires, EQUIPMENT-FROM-THE-PROFESSIONALLY-MAINTAINED-WALMART-FLEET Usage: Not Available
9301	2016 Great Dane 53 ft x 102 in T/A Refrigerated Trailer S/N: 1GRAA0620GE700369 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Vector 8600MT Refrigeration Unit, 3-Zone, (2) Remote Evaporator, 295/75R22.5 Tires, EQUIPMENT- FROM-THE-PROFESSIONALLY-MAINTAINED- WALMART-FLEET Usage: 23,452 Hr Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX		Notes: FROM THE PROFESSIONALLY MAINTAINED WALMART FLEET Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9306	2016 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2538GU451907 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Side Skirts, 2015 Thermo King 3000R Refrigeration Unit, Serial Number 6001196770,, 295/75R22.5 Tires Usage: 15,487 Hr Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE	9311	2011 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537BM237905 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Roll-Up Door, Carrier X2 2500A Refrigeration Unit, Serial Number NAD91221989, 275/80R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2007 Great Dane 53 ft x 102 in T/A
	INSPECTION REPORT	9312	Refrigerated Trailer
9307	Asset located in: Lake Worth, TX 7 2015 Utility 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2539FM178510 C/W: Air Ride Suspension, Ducted Floor, Swing Door, Thermo King Spectrum SB Refrigeration Unit, Serial Number 6001163293,, Shore Power, 3-Zone, (2) Remote Evaporator, 11R22.5 Tires Usage: 17,739 Hr		S/N: 1GRAA06247W702054 C/W: Air Ride Suspension, Sliding Suspension, Brad Wall Mount Refrigeration Unit, Aluminum Outer Wheels, 295/75R22.5 Tires, With Contents Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: PROFESSIONALLY-MAINTAINED-FLEET- VEHICLE-PAG; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	9313	2004 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS25384U179709
	Asset located in: Humble, TX		C/W: Air Ride Suspension, Swing Door, Ca Stealth Refrigeration Unit, 295/75R22.5 Til
9308	2015 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2531FU280786 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Thermo King Smart Reefer 4 Refrigeration Unit, 295/75R22.5 Tires Usage: 22,679 Hr		65000 lb GVWR Usage: 28,677 Hr Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
		9314	Asset located in: Humble, TX 2005 Great Dane 7811-TZ-1A 50 ft x 102 in T/A Refrigerated Trailer
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 1GRAA00225W700616 C/W: Air Ride Suspension, Sliding Suspension, Side Skirts, Brad Wall Mount Refrigeration Unit, Aluminum Outer Wheels, 11R22.5 Tires
9309	2014 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer		Usage: Not Available Asset located in: Humble, TX
	S/N: 1UYVS253XEM080407 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Curbside Door, Ducted Floor, Swing Door, Carrier Genesis TM1000 Refrigeration Unit, Aluminum Wheels, 295 /75R22.5 Tires Usage: 28,053 Hr Asset located in: Humble, TX	9315	2000 Utility 53 ft x 96 in T/A Refrigerated Trailer S/N: 1UYVS2531YU187916 C/W: Spring Suspension, Sliding Suspension, Roll-Up Door, Carrier Refrigeration Unit, 295 /75R22.5 Tires Usage: 15,487 Hr Notes: THIS UNIT IS BEING SOLD WITH A
9310	2013 Utility VS2RA 53 ft x 102 in T/A Refrigerated Trailer S/N: 1UYVS2537DM491620		REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Side Skirts, Ducted Floor, Swing Door, Carrier C22100 Advance	9316	Asset located in: Humble, TX 2006 Hackney Keg Trailer 14 Bay Refrigerated
	Swing Door, Carrier C22100 Advance Refrigeration Unit, 295/75R22.5 Tires Usage: 51,192 Hr Asset located in : Humble, TX	9510	S/A Beverage Trailer S/N: 1HHTRH2156M000596 C/W: Air Ride Suspension, 32 ft 8 in Insulated Body, 52 in Wide Bays, Side Pull-Out Steps, 295 /75R22.5 Tires, Shore power inlet Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9317	2005 Hackney Keg Trailer 14 Bay Refrigerated S/A Beverage Trailer S/N: 1HHTRH2145M000121 C/W: Air Ride Suspension, Air Brakes, 31 ft Insulated Body, 52 in Wide Bays, 275/80R22.5 Tires, 36000 kg GVWR Usage: Not Available	9324	2023 Wabash DVHDHPC 53 ft T/A Van Trailer S/N: 1JJV532D0PL368932 C/W: Air Ride Suspension, Sliding Suspension, 68000 lb GVWR, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available
	Asset located in: Humble, TX		Asset located in: Humble, TX
9318	2000 Mickey 14 Bay S/A Beverage Trailer S/N: 5CWRA3514YH998027 C/W: Spring Suspension, 34 ft 10 in Body, 52 in Wide Bays, Side Pull-Out Steps, 11R22.5 Tires, 38000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9325	2023 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D2PL369029 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2023 Corpus 53 ft x 102 in T/A Van Trailer
9319	1998 Mickey 14 Bay S/A Beverage Trailer S/N: 1M9RB1910WH043134 C/W: Spring Suspension, 36 ft 5 in Body, 56 in Wide Bays, Side Pull-Out Steps, 11R22.5 Tires, 38000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9326 9327A	S/N: 3C9C5XZ29PA115002 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 85000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9320	Asset located in: Humble, TX 2009 Utility VS2DX 57 ft x 102 in T/A Van Trailer S/N: 1UYVS257X9P712538 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR, Hendrickson air-ride suspension Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9327	S/N: 5V8VC5327NM204623 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2023 Tysol 53 ft x 102 in T/A Van Trailer
9321	Asset located in: Humble, TX 2009 Utility VS2DX 57 ft x 102 in T/A Van Trailer S/N: 1UYVS257X9P712507 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		S/N: 3T9T6EU23PA206016 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 85000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer
9322	2023 Wabash DVHDHPC 53 ft T/A Van Trailer S/N: 1JJV532D2PL368933 C/W: Air Ride Suspension, Sliding Suspension, 68000 lb GVWR, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available		S/N: 1UYVS2533L3961520 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9323	Asset located in: Humble, TX 2023 Wabash DVCVHPC 53 ft T/A Van Trailer S/N: 1JJV532D9PL369030 C/W: Air Ride Suspension, Sliding Suspension, 68000 lb GVWR, Aluminum Roof, Hardwood Floor, Side Skirts, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX		2020 Utility VS2DX 53 ft T/A Van Trailer S/N: 1UYVS2531L3961595 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9331	2020 Utility VS2DX 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2532L7961064 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX 2020 Utility VS2DX 53 ft x 102 in T/A Van	9338	2014 Stoughton ZGPVW535TSC 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532XEB487340 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Doo 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	Trailer S/N: 1UYVS2534L3961509 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX 2014 Kentucky 53 ft x 102 in T/A Van Trailer S/N: 1KKVE5329EL234652 C/W: 65000 lb GVWR, Air Ride Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Swing Door, 255/70R22.5 Tires Usage: Not Available Asset located in: Humble, TX	
9333	2018 Stoughton ZTPVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5324JBA01604 C/W: 70000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9340	2012 Great Dane CPL331421053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0623CT568048 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX	
9334	2017 Hyundai VC2530152-AJS 53 ft x 102 in T /A Van Trailer S/N: 3H3V532C5HT108034 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX		Asset located in: Lake Worth, TX 2012 Great Dane CPL-3314-21053 53 ft x 102 in T/A Van Trailer S/N: 1GRAP0628CT567347 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR	
9335	2016 Stoughton ZGPVW535TSCAR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A532XGS681207		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; Asset located in: Lake Worth, TX	
	C/W: 70000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 275/80R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9342	2012 Utility 53 ft x 102 in T/A Van Trailer S/N: 1UYVS2537CP284609 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available	
9336	2016 Utility VS2DX 53 ft x 102 in T/A Van Trailer		Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	
	S/N: 1UYVS2535GG724302 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9343	9343 2012 Hyundai VR2530152-AJS 53 /A Van Trailer S/N: 3H3V532C7CT326016 C/W: Air Ride Suspension, Sliding Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires,	2012 Hyundai VR2530152-AJS 53 ft x 102 in T /A Van Trailer
9337	2014 Great Dane 53 Ft T/A 53 ft x 102 in T/A Van Trailer S/N: 1GRAA0625ED450212 C/W: 68000 lb GVWR, Aluminum/Steel Combination Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 275/80R22.5 Tires Usage: Not Available Notes: LOCATED-IN-LAKE WORTH-TX Asset located in: Lake Worth, TX		Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	

Lot #	Details	Lot #	Details
9344	2012 Stoughton ZGPVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5327CB280160 C/W: Air Ride Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED DEFICIENCIES NOTED -	9350	2011 Wabash 53 Ft Van Trailer S/N: 1JJV532D5BL498696 Usage: Not Available Asset located in: Humble, TX
		9351	2011 Wabash 53 Ft Van Trailer S/N: 1JJV532D1BL498730 Usage: Not Available Asset located in: Humble, TX
9345	PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9352	2011 Wabash 53 Ft Van Trailer S/N: 1JJV532D5BL498746 Usage: Not Available
9040	2012 Stoughton ZGPVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5320CB280159 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR,	9353	Asset located in: Humble, TX 2011 Wabash 53 Ft Van Trailer S/N: 1JJV532D0BL498654 Usage: Not Available Asset located in: Humble, TX
	Hendrickson Air-Ride Suspension Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	9354	2011 Wabash Dura-Plate 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D5BL370460 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, 295/75R22.5
9346	2012 Stoughton ZGPVW-535T-S-C-AR 53 ft x 102 in T/A Van Trailer S/N: 1DW1A5325CB280156 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 70000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9355A	2009 Trailmobile 53 ft x 102 in T/A Van Trailer S/N: 2MN01JAH891003512 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available
9347	Asset located in: Humble, TX 2012 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D0CL626750 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door,	9355	Asset located in: Humble, TX 2011 Vanguard 53 Ft Van Trailer S/N: 5V8VC5324BM101946 Usage: Not Available Asset located in: Humble, TX
	295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	9356	2008 Wabash DVCVHPC 53 ft x 96 in T/A Van Trailer S/N: 1JJV532W58L144414 C/W: Air Ride Suspension, Sliding Suspension Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR
9348	2012 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532D6CL626672 C/W: Air Ride Suspension, Sliding Suspension,		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Aluminum Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX		2007 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W17L976654 C/W: 68000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9349	2012 Wabash 53 Ft Van Trailer S/N: 1JJV532D6CL606583 Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9359	2007 Wabash DVHDHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W17L091435 C/W: 68000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Side Skirts, Swing Door, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	9365 9366	2004 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W84L871511 C/W: Spring Suspension, Aluminum Roof, Aluminum Floor, Side Skirts, Swing Door, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Asset located in: Humble, TX 2003 Utility VS2RA 53 ft x 102 in T/A Van
	THE INSPECTION REPORT Asset located in: Humble, TX		Trailer S/N: 1UYVS25303M836825
9360	2007 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06257K286264 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5		C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Ducted Floor, Swing Door, 295 /75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes : EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9367A	2002 Strick 53 ft T/A Van Trailer S/N: 1S12E95392E477396 Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9367	2002 Wabash 53 ft T/A Van Trailer
9361	2006 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06256J612598 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Roll- Up Door, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available		S/N: 1JJV532W02L769116 C/W: 68000 lb GVWR, Air Ride Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 11R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	Notes : LOCATED-IN-BYRAM-MS - EQUIPMENT-FROM-YELLOW-CORP	9368A	Trailer S/N: 1JJV532W11L748001
	Asset located in: Humble, TX	4	
9362A	2006 Wabash 53 ft T/A Van Trailer S/N: 1JJV532W36L999190 Usage: Not Available		C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available
9362	Asset located in: Humble, TX 2006 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W46L024889		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9368	2001 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W91L736937 C/W: 68000 lb GVWR, Spring Suspension,
9363	2005 Wabash 53 ft T/A Van Trailer S/N: 1JJV532W95L892837		Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available
	Usage: Not Available Asset located in : Humble, TX	2050	Asset located in: Humble, TX
9364	2005 Wabash DVCVHPC 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W15L892640 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood/ aluminum, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	_9369	2001 Great Dane 53 ft x 102 in T/A Van Trailer S/N: 1GRAA06291B078413 C/W: Air Ride Suspension, Air Brakes, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9370	2001 Lufkin TFV-IP ST 53 ft x 102 in T/A Van Trailer S/N: 1L01A532811146879 C/W: Air Ride Suspension, Sliding Suspension,	9375A 9375 9376	1987 Great Dane 53 Ft Van Trailer S/N: 1GRAA0628JB106606 Usage: Not Available Asset located in : Humble, TX	
	Aluminum Roof, Hardwood Floor, Swing Door, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX		5 1998 Strick Commercial Trailer 53 ft T/A Van Trailer S/N: 1S12E9532WD433333	
9371	2000 Strick 53 ft x 102 in T/A Van Trailer S/N: 1S12E9531YD455231 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, EQUIPMENT-FROM-		Translucent Roof, Hardwood Floor, Roll-U Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available	C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-ROSHARON-TX-YELLOW; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX		2022 Vanguard MaxCube 48 ft x 102 in T/A Van Trailer S/N: 5V8VA4827NT201123 C/W: 68000 lb GVWR, Spring Suspension, Air Brakes, Aluminum Roof, Hardwood Floor, Roll-	
9372B	2000 Wabash 53 Ft Van Trailer S/N: 1JJV532W2YL736212 Usage: Not Available Asset located in: Humble, TX		Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX	
9372A	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W4YL695109 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, 275/80R22.5 Tires, 68000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9377	2015 Wabash DVCVHPC 48 ft x 102 in T/A Van Trailer S/N: 1JJV482D4FL869773 C/W: Aluminum Frame, Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available	
	Asset located in: Humble, TX		Asset located in: Humble, TX	
9372	2000 Wabash 53 ft x 102 in T/A Van Trailer S/N: 1JJV532W2YL695917 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires, 68000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9378B	2006 Stoughton AVW-485T-S-AR 48 ft x 102 in T/A Van Trailer S/N: 1DW1A48206S862401 C/W: Air Ride Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 11R24.5 Tires, 70000 lb GVWR Usage: Not Available	
9373	1999 Trailmobile 53 ft x 102 in T/A Van Trailer	2070	Asset located in: Humble, TX	
	S/N: 1PT01JAH4X6010027 C/W: 65000 lb GVWR, Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Swing Door, 11R22.5 Tires Usage: Not Available Asset located in: Humble, TX	9378	2008 Great Dane 48 ft x 102 in T/A Van Trailer S/N: 1GRAA96288B704385 C/W: Spring Suspension, Sliding Suspension, Pintle Hitch, Translucent Roof, Hardwood w /Aluminum Strips, Roll-Up Door, 295/75R22.5 Tires, 68000 lb GVWR	
9374B	1999 Stoughton 53 ft T/A Van Trailer		Usage: Not Available Asset located in : Humble, TX	
	S/N: 1DW1A5325XS300833 Usage: Not Available Asset located in : Humble, TX	9379	2002 Lufkin TFV-IP ST 48 ft x 102 in T/A Van Trailer	
9374A	1999 Stoughton 53 Ft Van Trailer S/N: 1DW1A5324XS300838 Usage: Not Available Asset located in: Humble, TX		S/N: 1L01A482021149473 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available	
9374	1999 Strick Corp 53 ft x 102 in T/A Van Trailer S/N: 1S12E9534XE445933 C/W: 65000 lb GVWR, Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9380	2001 Lufkin TFV-IP ST 48 ft x 102 in T/A Van Trailer S/N: 1L01A482811147985 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2001 Great Dane 7311TPS 48 ft x 102 in T/A	9386	1994 Great Dane 7811TZ-1A 48 ft x 96 in T/A Van Trailer S/N: 1GRAA9627RW061201 C/W: Air Ride Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Swing Door, 285/75R24.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Van Trailer S/N: 1GRAA962X1K237895 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX	9387	1992 Trailmobile 01AC-1UAL 48 ft x 102 in T/A Van Trailer S/N: 1PT01ACH4N9008187 C/W: 65000 lb GVWR, Spring Suspension, Sliding Suspension, Aluminum Roof, Swing Door, 11R24.5 Tires Usage: Not Available Asset located in: Humble, TX
9382	1999 Trailmobile 48 ft x 102 in T/A Van Trailer S/N: 1PT01JAH5X6013180 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Roll-Up Door, 11R22.5 Tires, 65000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9388	1988 Pines 48 ft x 102 in T/A Van Trailer S/N: 1PNX48280JKA30308 C/W: Spring Suspension, Air Brakes, Sliding Suspension, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP SELLING SCRAP NO TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION
9383	1998 Wabash 48 ft x 102 in T/A Van Trailer S/N: 1PNV482B6WK211649 C/W: Spring Suspension, Sliding Suspension,	9389	REPORT Asset located in: Humble, TX
	Translucent Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Notes: ; EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX		2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ131004602 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available
9384	1994 Wabash 48 ft x 102 in T/A Van Trailer		Asset located in: Humble, TX
	S/N: 1JJV482UXRL207037 C/W: Spring Suspension, Sliding Suspension, Translucent Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE	9390	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ331004598 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	INSPECTION REPORT Asset located in: Humble, TX	9391	2003 Trailmobile 45 ft x 96 in T/A Van Trailer
9385	1993 Wabash 48 ft x 102 in T/A Van Trailer S/N: 1JJV482X1PL184576 C/W: Spring Suspension, Air Brakes, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available	9392	S/N: 2MN011PJX31004596 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ231004592 C/W: Spring Suspension, Sliding Suspension, Hardwood Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9393	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ331004603 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9401	2011 Great Dane DST-1314-02199 42 ft x 102 in T/A Van Trailer S/N: 1GRAA8423BB706534 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Curbside Door, Roll-Up Door, 255/70R22.5 Tires, 68000 lb GVWR Usage: Not Available
9394	2003 Trailmobile 45 ft x 96 in T/A Van Trailer		Asset located in: Humble, TX
7374	S/N: 2MN011PJX31003335 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9402	
9395	2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ431004593 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available		Metal Racks. Office In Front w/ Desk, Cabinets & A/C Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9396	Asset located in: Humble, TX 2003 Trailmobile 45 ft x 96 in T/A Van Trailer S/N: 2MN011PJ131004597 C/W: Spring Suspension, Sliding Suspension, Aluminum Floor, Swing Door, Aluminum Wheels, 275/80R22.5 Tires, 65000 lb GVWR Usage: Not Available		2011 Great Dane DST-1314-02199 42 ft x 102 in T/A Van Trailer S/N: 1GRAA842XBB706532 C/W: Air Ride Suspension, Aluminum Roof, Hardwood Floor, Ramp, Curbside Door, Roll-Up Door, 225/70R22.5 Tires Usage: Not Available
9397	Asset located in: Humble, TX 2003 Trailmobile 45 ft x 96 in T/A Van Trailer		Notes: CAN ONLY BE PULLED WITH A S/A TRUCK DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 2MN011PJ231004589		Asset located in: Humble, TX
9398	C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/80R22.5 Tires, 65000 Ib GVWR Usage: Not Available Asset located in: Humble, TX 2003 Trailmobile 45 ft x 96 in T/A Van Trailer	9404	2016 Wabash 40 ft x 102 in S/A Van Trailer S/N: 1JJV401D0GL957238 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Hardwood Floor, Lift Gate, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP
3330	S/N: 2MN011PJX31004601		Usage: Not Available Asset located in: Humble, TX
	C/W: Spring Suspension, Aluminum Roof, Aluminum Floor, Swing Door, Aluminum Wheels, 295/75R22.5 Tires, 65000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9405	2016 Wabash 40 ft S/A Van Trailer S/N: 1JJV401D9GL957190 C/W: Spring Suspension, Aluminum Roof, Hardwood Floor, Lift Gate, Roll-Up Door, 295
9399	2003 Heil MC407 45 ft T/A Van Trailer S/N: 5HTDL452135G14541 Usage: Not Available		/75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP Usage: Not Available Asset located in : Humble, TX
	Asset located in: Humble, TX	9406	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van
9400	1995 Hyundai HDM-45WH-V5300 45 ft x 102 in T/A Van Trailer S/N: 3H3V452C5ST000535 C/W: Spring Suspension, Sliding Suspension, Aluminum Roof, Hardwood Floor, Swing Door, 10.00-20 Tires, 65000 lb GVWR, Steel Shelving, Tool Box, Hose Hooks Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Trailer S/N: 1JJV281D0KL140381 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA

Lot #	Details	Lot #	Details
9407	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D0KL140414 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX.	9413	2013 Stoughton DVW-285S-C-WDG 28 ft x 102 in S/A Van Trailer S/N: 1DW1A2819DS373133 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
	Asset located in: Livingston, LA	9414	2008 Great Dane PSL-1311-02028 28 ft x 102
9408	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D6KL140434 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA		in S/A Van Trailer S/N: 1GRAA561XAK210924 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Front/Rear Vents, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9409	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D7KL140488 C/W: 40000 lb GVWR, Spring Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA	9415	in S/A Van Trailer S/N: 1GRAA561X8K202042 C/W: 34000 lb GVWR, Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires Usage: Not Available Asset located in: Humble, TX
9410	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D9KL140427 C/W: 40000 lb GVWR, Spring Suspension, Sliding Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA	9416	2005 Wabash 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W95L913113 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Translucent Roof, Hardwood Floor, Roll- Up Door, 295/75R22.5 Tires, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP SELLING SCRAP NI TITLE Asset located in: Humble, TX
9411	2019 Wabash DVDBHPC 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D8KL140466 C/W: 40000 lb GVWR, Spring Suspension, Pintle Hitch, Side Skirts, 295/75R22.5 Tires Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA	9417	2005 Wabash 28 ft x 102 in S/A Van Trailer S/N: 1JJV281W05L913176 C/W: Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP
9412	2017 Wabash 28 ft x 102 in S/A Van Trailer S/N: 1JJV281D1HL987077 C/W: 40000 lb GVWR, Spring Suspension, Pintle Hitch, Aluminum Roof, Hardwood Floor, Side Skirts, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA_TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9418	Asset located in: Humble, TX 2001 Fruehauf 28 ft x 102 in S/A Van Trailer S/N: 1JJV281F41F770256 C/W: Spring Suspension, Air Brakes, Pintle Hitch, Aluminum Roof, Hardwood Floor, Roll-Up Door, 295/75R22.5 Tires, EQUIPMENT-FROM- YELLOW-CORP Usage: Not Available Asset located in: Humble, TX
	Asset located in: Livingston, LA	9419	2020 Wabash S/A Dolly S/N: 1JJD061X3LL228424 C/W: 20000 lb GVWR, Spring Suspension, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: Selling BOS Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9420	2006 Wabash S/A Dolly S/N: 1JJD101W66L987381 C/W: Spring Suspension, 275/80R22.5 Tires, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: LOCATED-IN-IAA 458 - BAYTOWN, TX, NO TITLE AVAILABLE, SOLD WITH BILL OF	9428	2023 Texas Pride 16 ft T/A Dump Utility Trailer S/N: 7HCBD1623PB039496 C/W: 16000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, Steel Decking, 235 /85R16 Tires Usage: Not Available Asset located in: Humble, TX
	SALE ONLY; LOCATED-IN-BAYTOWN-TX EQUIPMENT-FROM-YELLOW-CORP Asset located in: Baytown, TX	9429	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused)
9421	1989 Fruehauf ELF-1 Dolly S/N: 1H2E00616KH028676 C/W: EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX		S/N: 2SFKL3364S1113947 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND
9422	1988 Fruehauf ELF-1 S/A Dolly S/N: 1H2E00619JH058415		TRAILER CORP Asset located in: Humble, TX
	C/W: 20000 lb GVWR, Spring Suspension, 295 /75R22.5 Tires, EQUIPMENT-FROM-YELLOW- CORP	9430	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused)
	Usage: Not Available Notes: EQUIPMENT-FROM-YELLOW-CORP Asset located in: Humble, TX		S/N: 2SFKL3366S1113948 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597
9423	Jeep Dolly T/A Dolly S/N: Not Available C/W: Spring Suspension, 445/65R22.5 Tires Usage: Not Available Notes: NO TITLE AVAILABLE, SOLD WITH BILL	9431	Ib GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
	OF SALE ONLY Asset located in: Humble, TX		Asset located in: Humble, TX 2025 Southland SL714-16KHD 14 ft T/A Dump
9424	2022 Big Tex 21 ft Dump Utility Trailer S/N: 16V1D2122N5116206 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	9431	Utility Trailer (Unused) S/N: 2SFKL3362S1113946 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP
9425	2024 Texas Pride 16 ft T/A Gooseneck Dump Utility Trailer S/N: 7HCGD1628RB048350 C/W: 16000 lb GVWR, Spring Suspension, Steel		Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
	Decking, Aluminum Wheels, 235/80R16 Tires, Manual Roll Tarp, Split Swing Tailgate Usage: Not Available Asset located in: Humble, TX	9432	2025 Southland SL714-16KHD 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL3360S1113945
9426	2024 Texas Pride DT716416KGN T/A Gooseneck Dump Utility Trailer S/N: 7HCGD162XRB048351 C/W: 16000 lb GVWR, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9427	2024 PJ Trailer 16 ft T/A Dump Utility Trailer S/N: 4P51D1623R1407265 C/W: 9899 lb GVWR, Spring Suspension, Ramp, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		

Lot #	Details	Lot #	Details
9433	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4360S1116429 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9438	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL436XS1113277 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split-swing/lift) Tail Gate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9434	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4368S1113276 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split swing/ lift) Tail Gate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9439	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4361S1113443 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split swing/lift) Tailgate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9435	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4363S1113444 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split swing/lift) Tail Gate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9440	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4369S1116431 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9436	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4366S1113275 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9441	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL436XS1113294 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split-swing/lift) Tailgate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9437	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4369S1116414 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split swing/lift) Tailgate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9442	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4367S1116430 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9444	2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFKL4368S1113293 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 lb GVWR, Two way (split-swing/lift) Tailgate, Manual Tarp and Ramps; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX 2025 Southland SL714-16KHS 14 ft T/A Dump Utility Trailer (Unused)	9448	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3364S1111661 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX 2025 Southland SL714-14KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3364S1113345
	S/N: 2SFKL4360S1116432 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/85R16 Tires, 17597 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR, Two way (split-swing/lift) tailgate, manual tarp and ramps. Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
9445	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3367S1106986 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP	– 9450	2025 Southland SL714-14KHS 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3362S1113344 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 lb GVWR, Two way (split-swing/lift) tailgate, manual tarp and ramps.; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
	Asset located in: Humble, TX		Asset located in: Humble, TX
9446	2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL336XS1110823 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 15432 Ib GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available	9451	2025 Ranco 7014 14 ft T/A Dump Utility Trailer S/N: 3EZBTC145SA003786 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Steel Decking, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: EQUIPMENT FROM SOUTHLAND	9452	2025 Industrias America 7014R 14 ft T/A
	TRAILER CORP		Dump Utility Trailer S/N: 3EZBTC140SA003758
9447	Asset located in: Humble, TX 2025 Southland SL714-14K 14 ft T/A Dump Utility Trailer (Unused) S/N: 2SFJL3369S1110778 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 82 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires, 14532 lb GVWR, EQUIPMENT-FROM-SOUTHLAND- TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX		C/W: Ball Hitch, Spring Suspension, Electric Brakes, 81 in Deck Width, Steel Decking, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in : Humble, TX
<u> </u>		9453	2024 STL Industrial 14 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1421RM336007 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 71 in Deck Width, 98 in Overall Width, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9454	2024 STL Industrial 14 ft T/A Dump Utility Trailer (Unused) S/N: 4B9BD1425RM336009 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX	9460	2020 Delco 10 ft T/A Dump Utility Trailer S/N: 5WWBD1023L6009385 C/W: 7000.0 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, 64 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX, TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
9455	2024 STL Industrial 14 ft T/A Dump Utility		Asset located in: Midland, TX
9456	Trailer (Unused) S/N: 4B9BD142XRM336006 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX	9461	2018 Felling FT10DTHDG 12 ft T/A Dump Utility Trailer S/N: 5FTBD1227J1001245 C/W: Lunette Ring Hitch, Spring Suspension, 81 in Deck Width, 85 in Overall Width, Aluminum Flooring, 225/75R15 Tires, 9980 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX
9430	2024 STL Industrial 12 ft T/A Dump Utility Trailer (Unused)		Asset located in: Lake Worth, TX
9457	S/N: 4B9BD1221RM336009 C/W: 12800 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX 2024 STL Industrial 12 ft T/A Dump Utility	9462	2018 Snake River DMP610-7K HD 10 ft T/A Dump Utility Trailer S/N: 5PTBD1021J1028298 C/W: 7380 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, 96 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX
	Trailer (Unused)	9463	
	S/N: 4B9BD1226RM336006 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 100 in Overall Width, Ramp, Steel Decking, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX		2018 Snake River 10 ft T/A Dump Utility Trailer S/N: 5PTBD1026J1028300 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, 96 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available
9458	2025 Ranco FT510 10 ft T/A Dump Utility		Asset located in: Humble, TX
	Trailer S/N: 3EZBTC109SA003920 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, 60 in Overall Width, Steel Decking, 225/75R15 Tires, 7000 lb GVWR, Manual tarp, Two way (Split-Swing/ lift) Tailgate	9464	2018 Snake River 10 ft T/A Dump Utility Trailer S/N: 5PTBD1020J1028325 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, Steel Decking, 225 /75R15 Tires, 7380 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE	9465	2018 Snake River 10 ft T/A Dump Utility Trailer
	TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX		S/N: 5PTBD1020J1028311 C/W: Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, Steel Decking, 225
9459	2025 Industrias America FT510 T/A Dump Utility Trailer		/75R15 Tires, 7380 lb GVWR Usage: Not Available Asset located in : Humble, TX
	S/N: 3EZBTC102SA003919 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9466	2018 Snake River DMP610-7K HD 9 ft T/A Dump Utility Trailer S/N: 5PTBD1024J1028313 C/W: Spring Suspension, Surge Brakes, 72 in Deck Width, 72 in Overall Width, Steel Decking, 225/75R15 Tires, 7380 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9467	67 2017 Snake River DMP610-7K HD 10 ft T/A Utility Trailer S/N: 5PTBD1021H1026514 C/W: 7380 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, 72 in Overall Width, Steel Decking, 225/75R15 Tires Usage: Not Available	9474	2017 Felling Trailers 22 ft T/A Tilt Deck Trailer S/N: 5FTCE2922H2002692 C/W: Lunette Ring Hitch, Torsion Axle, Electric Brakes, 18 ft Deck Tilting Length, 83 in Deck Width, 215/75R17.5 Tires, 19120 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: . Asset located in: Humble, TX	9475	2025 Industrias America 167T 21 ft T/A Tilt Deck Trailer S/N: 3EZBTP229SA003875
9468	2017 Snake Rive Trailer DMP610-7KHD 9 ft T /A Dump Utility Trailer S/N: 5PTBD1029H1026518 C/W: 7380 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 72 in Deck Width, Steel Decking, 225/75R15 Tires		C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 16 ft Deck Tilting Length, 81 in Deck Width, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Notes: . Asset located in: Humble, TX	9476	2024 Double A 21 ft T/A Tilt Deck Trailer (Unused) S/N: 1UFBU2128RT012377
9470	2024 Load Trailer 21000 lb 24 ft Tri/A Tilt Deck Trailer S/N: 4ZEGG2432R1297138 C/W: Torsion Axle, Electric Brakes, 17 ft 7 in Deck Tilting Length, 83 in Deck Width, 235 /80R16 Tires		C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 17 ft 6 in Deck Tilting Length, 76 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in: Humble, TX	on, Electric	2023 Big Tex 20 ft T/A Tilt Deck Trailer S/N: 16V1C252XP2271331 C/W: Ball Hitch, Spring Suspension, 16 ft Dec
9471	2025 Industrias America 167T 21 ft T/A Tilt Deck Trailer S/N: 3EZBTP222SA003877 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 11 in		Tilting Length, 72 in Deck Width, 235/80R16 Tires Usage: Not Available Asset located in : Humble, TX
	Deck Tilting Length, 82 in Deck Width, 14000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9478	2011 Butler 18 ft T/A Tilt Deck Trailer S/N: 1BUD18201B1005986 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Deck Tilting Length, 82 in Deck Width, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available
9472	2025 Industrias America 167T 22 ft T/A Tilt	7	Asset located in: Humble, TX
	Deck Trailer (Unused) S/N: 3EZBTP220SA003876 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Storage Compartments, 15 ft 10 in	9479	2013 Towmaster T-5DTSL Tilt Deck Trailer S/N: 4KNTT1214DL161091 Usage: Not Available Asset located in: Humble, TX
	Deck Tilting Length, 82 in Deck Width, 235 /80R16 Tires, 14000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9480	2022 Big Tex 25GN-40BK8SIR 40 ft T/A Gooseneck Flatbed Trailer S/N: 16V3F482XN6092414 C/W: Spring Suspension, Electric Brakes, 97 in Deck Width, 102 in Overall Width, 235/80R16 Tires, 25900 lb GVWR
9473	2021 Midsota TBWM-22 22 ft T/A Tilt Deck		Usage: Not Available
	Trailer		Asset located in: Humble, TX
	S/N: 5JWBS2222MA001707 C/W: Walking Beam Suspension, Electric Brakes, Winch, 18 ft Deck Tilting Length, 96 in Deck Width, 215/75R17.5 Tires, 17600 lb GVWR Usage: Not Available Asset located in: Humble, TX	9481	2024 MP Custom 16000 lb 42 ft T/A Gooseneck Equipment Trailer S/N: 4M9BG4024R1144358 C/W: 15900 lb GVWR, Aluminum Frame, Spring Suspension, Electric Brakes, 215/75R17.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX
			Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9482B	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4025SM120810 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 5 ft Fixed Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9483	2024 PJ 40 ft T/A Gooseneck Equipment Trailer S/N: 4P53F4923R1406164 C/W: 14500 lb GVWR, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
9482A	2025 Maxey 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 5R8GF4027SM120811 C/W: Air Ride Suspension, Electric Brakes, 28 ft Main Deck, 12 ft 2-Position Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Electric Powered Self Contained Hydraulic System, Wood Flooring, 215/75R17.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9484	2024 RAWMAXX FDX-40-27K 40 ft T/A Gooseneck Equipment Trailer S/N: 3EVGF402XR1110864 C/W: 14000 lb GVWR, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
9482	2023 Maxey MAXX-D 14000 lb 40.5 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4020PM107096 C/W: 14000 lb GVWR, Spring Suspension, Electric Brakes, 35 ft Main Deck, 5 ft 3 in Rear Deck, 5 ft 6 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX.	9487	2023 East 40 ft T/A Gooseneck Equipment Trailer S/N: 58SGF4024PE035546 C/W: 25000 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2022 PJ Trailers 3F492 40 ft T/A Equipment
9483B	Asset located in: Livingston, LA 2024 5 Star ST-428 FB 32000 lb 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 4A93F4025RH220059 C/W: 36000 lb GVWR, Spring Suspension, Hydraulic Brakes, 40 ft Main Deck, 97.5 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/75R17.5 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY PURCHASER Asset located in: Midland, TX	9489 2	Trailer S/N: 4P53F4924N1364159 C/W: 25900 lb GVWR, Spring Suspension, Electric Brakes, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX 2022 PJ Trailers 40 ft T/A Gooseneck Equipment Trailer S/N: 4P53F4922N1365245 C/W: 14500 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Wood
9483A	2024 5 Star ST-428 FB 32000 lb 40 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 4A93F4023RH220058 C/W: 36000 lb GVWR, Spring Suspension, Hydraulic Brakes, 40 ft Main Deck, 97.5 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/75R17.5 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX THIS ITEM IS SUBJECT TO 12% FEDERAL EXCISE TAX TO BE PAID BY PURCHASER Asset located in: Midland, TX		Flooring, 235/75R17.5 Tires Usage: Not Available Asset located in : Humble, TX

Lot #	Details	Lot #	Details
9490	2022 Maxey 40 ft T/A Gooseneck Equipment Trailer S/N: 5R8GF4027NM091928 C/W: Spring Suspension, Electric Brakes, 40 ft Main Deck, 5 ft 8 in Fixed Dovetail, 96 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/85R16 Tires, 25990 lb GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Midland, TX	9496	2025 Southland ETGT10-30 BT 36 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9362S1116394 C/W: Spring Suspension, Electric Brakes, 36 ft Main Deck, 6 ft Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 9998 lb GVWR, EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX 2004 Ameritrail 33 ft Gooseneck Equipment
9491	2023 Trailmaxx 40 ft T/A Gooseneck Equipment Trailer S/N: 7WL3H4027TM000406 C/W: 12000 lb GVWR, Spring Suspension, Electric Brakes, 40 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX	9497B 9497A 9497	Trailer S/N: 17YGN30234B028401 Usage: Not Available Asset located in: Humble, TX 2025 Maxey T/A Gooseneck Hydraulic Tail Trailer (Unused) S/N: 5R8GF3422SM120736 C/W: Spring Suspension, Electric Brakes, 22 ft Main Deck, 22 ft 2-Position Dovetail, 93 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires,
9492	2010 PJ 40 ft T/A Gooseneck Equipment Trailer S/N: 4P5FD4026A1148243 C/W: Spring Suspension, Electric Brakes, 34 ft 6 in Main Deck, 5 ft 6 in Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX		Electric Powered Self Contained Hydraulic System, 215/75R17.5 Tires, 40000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2024 Ranco G35R 35 ft T/A Gooseneck Equipment Trailer S/N: 3EZBGP353RA003331 C/W: Spring Suspension, Electric Brakes, 29 ft 10 in Main Deck, 5 ft 2-Position Dovetail, 96 in Usable Deck Width, 96 in Overall Deck Width,
9494	2025 PJ Trailers LS322 32 ft T/A Gooseneck Equipment Trailer S/N: 4P53F4128S1413399 C/W: 15680 lb GVWR, Spring Suspension, Electric Brakes, 32 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Manual Ramps, Wood Flooring, 235 /80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		Storage Compartments, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires, 20000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2025 Southland ETGT10-26BT 32 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9367S1106556 C/W: Spring Suspension, Electric Brakes, 26 ft Main Deck, 6 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood
9495	2025 Southland ETGT10-30 BT 36 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9367S1113460 C/W: Spring Suspension, Electric Brakes, 30 ft Main Deck, 6 ft 2 in Fixed Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX		Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9499	2025 Southland ETGT10-26BT 32 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN9363S1113455 C/W: Spring Suspension, Electric Brakes, 32 ft Main Deck, 6 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM- SOUTHLAND-TRAILER-CORP Usage: Not Available	9503	2024 Double A 26 ft T/A Gooseneck Equipment Trailer S/N: 1UFGN2627RT012379 C/W: Spring Suspension, Electric Brakes, 23 ft Main Deck, 3 ft Fixed Dovetail, 81 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9504	2023 Big Tex 22GN35BK 40 ft T/A Gooseneck Equipment Trailer S/N: 16V3F4825P6210694 C/W: Spring Suspension, Electric Brakes, 35 ft
9500	2025 Southland ETGT10-24 BT 30 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 2SFLN8364S1117153 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 6 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width,	9505	Main Deck, 5 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, 97 in Overall Deck Width, Storage Compartments, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 23900 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235 /80R16 Tires, 25000 lb GVWR, EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX		2012 Big Tex 20000 lb 25 ft T/A Gooseneck Equipment Trailer S/N: 16VGX252XC2646286 C/W: Spring Suspension, Electric Brakes, 25 ft Main Deck, 102 in Usable Deck Width, 106 in Overall Deck Width, Deck Over Tires, Wood Flooring, 235/80R16 Tires, 22500 lb GVWR Usage: Not Available
9501A	2025 Maxey 30 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 5R8GF302XSM120859 C/W: Spring Suspension, Electric Brakes, 6 ft		Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
	10 in Upper Deck, 25 ft Main Deck, 5 ft Fixed Dovetail, 97 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Manual Ramps, Electric Powered Self Contained Hydraulic System, Wood Flooring, 215/75R17.5 Tires, 30000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9506	2024 Double A 24 ft T/A Gooseneck Equipment Trailer (Unused) S/N: 1UFGN2424RT012374 C/W: 14000 lb GVWR, Spring Suspension, Electric Brakes, 24 ft Main Deck, 83 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
9501	2025 Southland ETGT10-24 BT 30 ft T/A	0507	2018 Big Tex 14GN-20BK+5MR 14000 lb 25 ft T
	Gooseneck Equipment Trailer (Unused) S/N: 2SFLN8362S1117152 C/W: Spring Suspension, Electric Brakes, 24 ft Main Deck, 6 ft 2 in 2-Position Dovetail, 97 in Usable Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25000 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND	9507	/A Gooseneck Equipment Trailer S/N: 16VGX2025J6030122 C/W: Spring Suspension, Electric Brakes, 20 ft Main Deck, 5 ft 4 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX
	TRAILER CORP	9509	2009 Interstate Trailers 25 ft Tri/A Equipment Trailer
9502	Asset located in: Humble, TX 2023 30 ft T/A Gooseneck Equipment Trailer S/N: 4R7GF3025PN231122 C/W: 24000 lb GVWR, Torsion Axle, Electric Brakes, 30 ft Main Deck, 96 in Usable Deck Width, 101 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX		S/N: 1JKDTA1849M009974 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 20 ft Main Deck, 5 ft 2-Position Dovetail, 100 in Usable Deck Width, 100 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Electric Powered Self Contained Hydraulic System, Steel Decking, 245 /75R16 Tires, 33000 lb GVWR Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9510	2023 Econoline 20000 lb 30 ft T/A Equipment Trailer S/N: 42EDPRK23P1000294 C/W: 25500 lb GVWR, Lunette Ring Hitch, Spring Suspension, Electric Brakes, 23 ft 9 in Main Deck, 5 ft 9 in Fixed Dovetail, 98 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires	9513	2012 Pro Pull 14 ft T/A Equipment Trailer S/N: 5WJUT1422CL00030 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 14 ft Main Deck, 96 in Usable Deck Width, 102 in Overall Deck Width, Deck Over Tires, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Humble, TX	
	Usage: Not Available	9514	2010 Mcelrath 12 ft T/A Equipment Trailer S/N: 1M9FE1224AS284977	
9511C	Asset located in: Humble, TX 2016 Buler 23 ft T/A Equipment Trailer S/N: 1BUD23201G1008281 C/W: Lunette Ring Hitch, Spring Suspension, Air Brakes, 19 ft Main Deck, 4 ft Fixed Dovetail, 80 in Usable Deck Width, 80 in Overall Deck Width, Spring Assisted Ramps, Steel Decking, 215/75R17.5 Tires, 22000 lb GVWR Usage: Not Available	9515A	C/W: Lunette Ring Hitch, Spring Suspension, 12 ft Main Deck, Manual Ramps, 215/75R17.5 Tires, 18000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2025 24 ft T/A Equipment Trailer (Unused)	
9511B	Asset located in: Humble, TX 2020 Novae ST923IT2API5-B-259 23 ft T/A Equipment Trailer S/N: 5JW2U2320L3262538 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 7 ft 6 in Upper Deck, 12 ft 4 in	9515	S/N: 5R8BC2422SM120863 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 24 ft Main Deck, 97 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235/75R17.5 Tires, 22000 lb GVWR Usage: Not Available Asset located in: Humble, TX	
	Main Deck, 3 ft 6 in Fixed Dovetail, 79 in Usable Deck Width, 79 in Overall Deck Width, Storage Compartments, Manual Ramps, Wood Flooring, 215/75R17.5 Tires, 25900 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2025 Southland LBAT7-24 23 ft T/A Equipment Trailer (Unused) S/N: 2SFJL5360S1117517 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 23 ft Main Deck, Wood Flooring, 235/80R16 Tires, 15432 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP	
9511A	2014 Kaufman 24 ft T/A Equipment Trailer S/N: 5VGFH2523EL002177 C/W: Lunette Ring Hitch, Spring Suspension,	9516A	Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	
	Electric Brakes, 19 ft 10 in Main Deck, 5 ft 2- Position Dovetail, 96 in Usable Deck Width, 96 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Manual Ramps, Wood Flooring, 235/80R16 Tires Usage: Not Available		2023 Maxey Maxx-D T/A Car Carrier Trailer S/N: 5R8BC2226PM106863 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 215/75R17.5 Tires, 9990 lb GVWR Usage: Not Available	
9511	Asset located in: Humble, TX 2017 Interstate Trailers 24 ft T/A Equipment Trailer	-	Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	S/N: 1JK0DT206HM015578 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, 19 ft 9 in Main Deck, 5 ft 1 in 2- Position Dovetail, 102 in Usable Deck Width, 102 in Overall Deck Width, Storage Compartments, Winch, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 235/80R16 Tires, 25900 lb GVWR Usage: Not Available Asset located in: Humble, TX	9516	S/N: TR193769 C/W: Ball Hitch, Spring Suspension, E Brakes, 19 ft Main Deck, 4 ft Fixed Do in Usable Deck Width, 96 in Overall D Wood Flooring, 235/80R16 Tires, wir assisted ramps Usage: Not Available Notes: TITLE IS BRANED BOND TITL	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 19 ft Main Deck, 4 ft Fixed Dovetail, 96 in Usable Deck Width, 96 in Overall Deck Width, Wood Flooring, 235/80R16 Tires, winch assisted ramps
9512	1989 Interstate 20 ft T/A Equipment Trailer S/N: 1JKDAS320KA600511 C/W: Lunette Ring Hitch, Spring Suspension, 20 ft Main Deck, 6 ft Fixed Dovetail, 96 in Usable Deck Width, Storage Compartments, Deck Over Tires, Spring Assisted Ramps, Wood Flooring, 215/75R17.5 Tires Usage: Not Available Asset located in: Humble, TX		Asset located III. Fluitible, TA	

Lot #	Details	Lot #	Details
Trailer S/N: 25 C/W: B Brakes /80R16 FROM- Usage:	C25 Southland LBAT7-20 19 ft T/A Equipment railer (Unused) (N: 2SFJL4365S1117510 (W: Ball Hitch, Spring Suspension, Electric rakes, Manual Ramps, Wood Flooring, 235-10R16 Tires, 15432 lb GVWR, EQUIPMENT-ROM-SOUTHLAND-TRAILER-CORP sage: Not Available (otes: EQUIPMENT FROM SOUTHLAND	9521	2024 Contract Manufacturing TH7020BK4AR2B 20 ft T/A Equipment Trailer (Unused) S/N: 7RD1U2420R2320077 C/W: Ball Hitch, Spring Suspension, Wood Flooring, 205/75R15 Tires Usage: Not Available Asset located in: Humble, TX
	TRAILER CORP Asset located in: Humble, TX	9522	2024 Double A 7000 lb 12 ft S/A Equipment Trailer
9518	•		S/N: 1UFBU1213RT012383 C/W: Spring Suspension, 12 ft Main Deck, 77 in Usable Deck Width, 79 in Overall Deck Width, 235/80R16 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	83 in Usable Deck Width, 102 in Overall Deck Width, Manual Ramps, Wood Flooring, 235 /80R16 Tires Usage: Not Available Asset located in : Humble, TX	9523	2019 MMDI 14 ft T/A Equipment Trailer S/N: 5631F2026KM001915 C/W: 9990 lb GVWR, Ball Hitch, Spring Suspension, 14 ft Main Deck, 70 in Usable Deck Width, Manual Ramps, 225/75R15 Tires
9519	2024 Double A 20 ft T/A Equipment Trailer S/N: 1UFBU2026RT012380 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 18 ft Main Deck, 2 ft Fixed Dovetail, 83	9524	Usage: Not Available Notes: . Asset located in: Humble, TX
	in Usable Deck Width, Manual Ramps, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in : Humble, TX		2019 MMDI 14 ft T/A Equipment Trailer S/N: 5631F2028KM001852 C/W: 9990 lb GVWR, Ball Hitch, Spring Suspension, 14 ft Main Deck, 70 in Usable
9520	2024 Double A 7000 lb 20 ft T/A Equipment Trailer S/N: 1UFBU202XRT012382 C/W: Spring Suspension, Electric Brakes, 18 ft	9525	Deck Width, Manual Ramps, 225/75R15 Tires Usage: Not Available Notes: . Asset located in: Humble, TX
	Main Deck, 2 ft Fixed Dovetail, 82 in Usable Deck Width, 83 in Overall Deck Width, Manual Ramps, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in : Humble, TX		2019 Pratt 14 ft T/A Equipment Trailer S/N: 1P9UT2120KN343276 C/W: 12000 lb GVWR, Ball Hitch, Torsion Axle, Surge Brakes, 70 in Usable Deck Width, 73.5 in Overall Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires
9521B	2015 Pike 33Q 16 ft T/A Equipment Trailer S/N: 1P9PF2520FM435465 C/W: Ball Hitch, Spring Suspension, Electric		Usage: Not Available Notes: ; SUBJECT TO LOUISIANA SALES TAX. Asset located in: Livingston, LA
	Brakes, 14 ft 10 in Main Deck, 1 ft 10 in Fixed Dovetail, 75 in Usable Deck Width, 98 in Overall Deck Width, Manual Ramps, Steel Decking, 215 /75R17.5 Tires, 16000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9526	2019 MMDI 14 ft T/A Equipment Trailer S/N: 5631F2024KM001914 C/W: Ball Hitch, Torsion Axle, Surge Brakes, 14 ft Main Deck, 70 in Usable Deck Width, 70 in Overall Deck Width, Spring Assisted Ramps,
9521A	A 2021 Delco 18 ft T/A Equipment Trailer S/N: 5WWBC1824M6018587 C/W: Boll Hitch Spring Supposion Floatric		Steel Decking, 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Asset located in: Humble, TX
		9527	2021 MMDI E47H 7 ft S/A Equipment Trailer S/N: 5631F1418MM000960 C/W: 4400 lb GVWR, Ball Hitch, Spring Suspension, Surge Brakes, 7 ft Main Deck, 49 in Usable Deck Width, 52 in Overall Deck Width, Manual Ramps, Steel Decking, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9528	2024 Double A 20 ft T/A Utility Trailer (Unused) S/N: 1UFBU2024RT012376 C/W: 14000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 83 in Deck Width, 102 in Overall Width, Ramp, Wood Flooring, 235 /80R16 Tires Usage: Not Available	9534	2017 Top Hat 16 ft T/A Utility Trailer S/N: 4R7BU1625HT167477 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Wood Flooring, 205 /75R15 Tires, 6000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9535	2025 Salvation 16 ft T/A Utility Trailer
9529	2024 Double A 8320T7K 20 ft T/A Utility Trailer (Unused) S/N: 1UFBU2028RT012381 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 72 in Deck Width, 8 in Overall Width, Ramp, Wood Flooring, 235/80R16 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX	- 9535	S/N: 7GG1U1628SW023464 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Wood Flooring, 205/75R15 Tires, 4400 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
9530A	1999 Trailmaster 20 ft T/A Utility Trailer		Asset located in: Humble, TX
	S/N: 5BEBU2026XC112015 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires, 12000 lb GVWR Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9536	2011 Cottrell T/A 7 Car Open Car Carrier Trailer S/N: 5E0AJ1444BG327001 C/W: Air Ride Suspension, Soft Ties, 265 /70R19.5 Tires, 45000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9537	2020 Texas Pride CA85335KGN Tri/A 6 Car
9530	2013 Ameritrail 20 ft T/A Utility Trailer S/N: 29DB053351 C/W: Ball Hitch, Spring Suspension, Electric Brakes, Wood Flooring, 225/90R16 Tires, 14000 lb GVWR, EQUIPMENT-FROM-A- PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX		Open Car Carrier Trailer S/N: 7HCGC5338LB018604 C/W: Spring Suspension, Chain Tie Downs, 235 /75R17.5 Tires, 48000 lb GVWR, Winch, Rear Hydraulic Ramp Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX LOCATED-IN-FORT-WORTH-TX
9531	2024 Double A 18 ft T/A Utility Trailer (Unused) S/N: 1UFBU182XRT012378 C/W: 9995 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Wood Flooring, 225 /75R15 Tires Usage: Not Available Asset located in: Humble, TX	9538	Asset located in: Lake Worth, TX 2023 American Pride T/A 3 Car Open Car Carrier Trailer S/N: 4A93A4826PH220152 C/W: Spring Suspension, Electric Brakes, 235 /80R16 Tires Usage: Not Available Asset located in: Humble, TX
9532	2024 CM Trailers 76X16 16 ft T/A Utility Trailer S/N: 5VNBU1620RT253191 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 76 in Deck Width, 76 in Overall Width, Wood Flooring, 205/75R15 Tires, 4400 lb GVWR Usage: Not Available	9539	2020 Shipse T/A 4 Car Open Car Carrier Trailer S/N: 4S95F532XLS452129 C/W: Torsion Axle, Surge Brakes, Soft Ties, 245 /70R17.5 Tires, 12000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC192XHA989016
9533	2020 Longhorn 16 ft T/A Utility Trailer S/N: 5J2US1629LE023631 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 77 in Deck Width, Ramp, Wood Flooring, 205/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX		C/W: 7000 lb GVWR, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details	
9542	2017 Demco AT7000P Car Carrier Trailer S/N: 15DPC1926HA988719 Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	9549	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA988535 C/W: Galvanized Frame Ball Hitch, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available	
9543	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1928HA988396		Notes: . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	
	C/W: 7000 lb GVWR, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX	9550	Asset located in: Humble, TX 2017 Demco AT7000P Car Carrier Trailer S/N: 15DPC1923HA988791 Usage: Not Available Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	
9544	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer		Asset located in: Humble, TX	
	S/N: 15DPC1929HA988357 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes : ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	9551	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1929HA988326 C/W: Torsion Axle, Surge Brakes, Soft Ties, 225 /75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW	
9545	Asset located in: Humble, TX 2017 Demco AT7000P Car Carrier Trailer	4	Asset located in: Humble, TX	
	S/N: 15DPC1929HA988634 Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	9552	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1921HA988465 C/W: 7000 lb GVWR, Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires Usage: Not Available	
9546	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1926HA988607 C/W: Galvanized Frame Ball Hitch, Torsion		Notes: LOCATED-IN-FORT-WORTH-TX SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Lake Worth, TX	
9547	Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX 2017 Demco AT7000P Car Carrier Trailer	9553C	9553C 20 Ca S/ C/ Ax 70 Us	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988635 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE
JU-1,	S/N: 15DPC1923HA988709 Usage: Not Available		TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	Notes: . ; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW Asset located in: Humble, TX	9553B	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1920HA988439	
9548	2017 Demco AT7000P Car Carrier Trailer S/N: 15DPC1925HA988520 Usage: Not Available Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW		C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tir 7000 lb GVWR Usage: Not Available Asset located in : Humble, TX	

Lot #	Details	Lot #	Details
9553A	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC1927HA988602 C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX	9559	2011 Wheeler Reeler S/A (1) Reel Trailer S/N: 5E3SK16N5B1000040 C/W: Electric Brakes, Hydraulic Reel Hoist, 12- 16.5 Tires, 7500 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9553	2017 Dethmers AT7000P T/A 1 Car Open Car	0561	·
3000	Carrier Trailer S/N: 15DPC1924HA988816 C/W: Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Notes: ; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED	9561 9562	2010 Sauber 1506-NS S/A (1) Reel Trailer S/N: 1F9UZ0912AV048139 C/W: Galvanized Frame Lunette Ring Hitch, Torsion Axle, Electric Brakes, 175/80 R13 Tires, 2550 lb GVWR Usage: Not Available Asset located in: Humble, TX 2003 White S/A (1) Reel Trailer
	Asset located in: Humble, TX		S/N: FT29
9554	2017 Demco AT7000P T/A 1 Car Open Car Carrier Trailer S/N: 15DPC192XHA988982		C/W: Lunette Ring Hitch, Electric Brakes, 12- 16.5 Tires, EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires,	0560	Asset located in: Humble, TX
9555A	7000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2017 Demco AT7000P T/A 1 Car Open Car	9563	T/A (1) Reel Trailer S/N: TR203175 C/W: 2008 US EPA Label, Honda GX620 2 Cylinder Gasoline Engine, Spring Suspension, Electric Brakes, 235/80R16 Tires
7000,1	Carrier Trailer S/N: 15DPC1924HA989030		Usage: Not Available
		0564	Asset located in: Humble, TX
9555	C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in: Humble, TX 2017 Demco AT7000P T/A 1 Car Open Car	9564	2023 Stealthcargo 24 ft T/A Enclosed Trailer S/N: 5WFBC2421PT000503 C/W: Ball Hitch, Electric Brakes, 95 in Deck Width, 100 in Overall Width, Ramp, Side Door 225/75R15 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE
	Carrier Trailer S/N: 15DPC1926HA988350		THE INSPECTION REPORT
	C/W: Galvanized Frame Ball Hitch, Torsion Axle, Surge Brakes, Soft Ties, 225/75R15 Tires, 7000 lb GVWR Usage: Not Available Asset located in : Humble, TX	9565	Asset located in: Humble, TX 2023 T-Rex V8524D5K 24 ft T/A Enclosed Trailer S/N: 4T9BE2425PH367241
9556	2015 Demco T/A 1 Car Open Car Carrier Trailer S/N: 15DP19204FA987594 C/W: Galvanized Frame Ball Hitch, Torsion		C/W: 9990 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 99 in Overall Width, Side Door 225/75R15 Tires Usage: Not Available
	Axle, Surge Brakes, Soft Ties, 215/75R14 Tires Usage: Not Available Asset located in: Humble, TX		Notes: LOCATED-IN-FORT-WORTH-TX; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS
9557	2015 T/A (1) Reel Trailer	T	Asset located in: Lake Worth, TX
	S/N: 4C9BS1628FW382017 C/W: 2014 US EPA Label, Honda 2 Cylinder Gasoline Engine, Ball Hitch, Spring Suspension, Electric Brakes, 235/80R16 Tires Usage: Not Available Asset located in: Humble, TX	S C 9 W U	1998 Featherlite 24 ft T/A Enclosed Trailer S/N: Not Available C/W: Ball Hitch, Torsion Axle, Electric Brakes, 92 in Overall Width, Ramp, Side Door Aluminum Wheels, 225/75R15 Tires Usage: Not Available
9558	2011 Butler S/A (1) Reel Trailer S/N: 1BUC1010XB1006035 C/W: Honda 2 Cylinder Gasoline Engine, Lunette Ring Hitch, Spring Suspension, Air Brakes, 235/75R17.5 Tires, 10000 lb GVWR Usage: Not Available Asset located in: Humble, TX		Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9567	2024 Spartan 22 ft T/A Enclosed Trailer S/N: 50XBE2022RA041313 C/W: 9990 lb GVWR, Ball Hitch, Torsion Axle, Electric Brakes, 95 in Deck Width, Ramp, Side Door 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX	9572	9572 2014 ATC World Class Trailer QSTSB8522+42T6.0K 21 ft T/A Enclosed Trailer S/N: 5JXJE2622EE197408 C/W: Aluminum/Steel Combination Frame, Ba Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 235	
9568	2018 ATC World Class Trailer 21 ft T/A Enclosed Trailer S/N: 5JX2C2629JD213307 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225 /75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		/80R16 Tires, 13200 lb GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX 2025 Southland LARCT52-820F-86 20 ft T/A Enclosed Trailer (Unused) S/N: 2SFFK4319S1108418 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb	
9569	2018 ATC World Class Trailer 21 ft T/A Enclosed Trailer S/N: 5JX2C2622JD213309 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225		GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	
	/75R15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX		2025 Southland LARCT52-822V-86 20 ft T/A Enclosed Trailer (Unused) S/N: 2SFPK4314S1112686 C/W: Ball Hitch, Spring Suspension, Electric	
9570	2018 ATC World Class Trailer QSTSB8522+42T5.2K 21 ft T/A Enclosed Trailer S/N: 5JX2C2620JD213311 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225 /75R15 Tires, 9990 lb GVWR	9575A 9575	Ramp, Side Door 225/75R15 Tires, 1 GVWR, EQUIPMENT-FROM-SOUTHL/ TRAILER-CORP Usage: Not Available Notes : EQUIPMENT FROM SOUTHL/ TRAILER CORP	Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND
	Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		S/N: 53BPTEB20NR007391 C/W: Walking Beam Suspension, Electric Brakes, 94 in Deck Width, 96 in Overall Width, 225/75R15 Tires, 9900 lb GVWR	
9571	2018 ATC World Class Trailer QSTSB8522+42T5.2K 21 ft T/A Enclosed Trailer		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	S/N: 5JX2C2629JD213033 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 225/75R15 Tires, 9990 lb GVWR Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		2025 Southland LARCT52-822V-86 20 ft T/A Enclosed Trailer (Unused) S/N: 2SFPK4313S1117202 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 96 in Overall Width, Side Door 225/75R15 Tires, 11464 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9576	2021 W-W 20 ft T/A Enclosed Trailer S/N: 11W3C2025MW321313 C/W: 12000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 94 in Deck Width, 102 in Overall Width, Side Door 235/80R16 Tires, with contents Usage: Not Available Asset located in: Humble, TX	9581	2012 Royal Cargo XRARCT60-8526-78 19 ft T /A Enclosed Trailer S/N: 2S9PK5314C3026714 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door Aluminum Wheels, 235/80R16 Tires, 6000 kg GVWR Usage: Not Available
9577	2010 Haulmark 20 ft T/A Enclosed Trailer S/N: 16HGB2021AH181920 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 95 in Deck Width, Side Door 225/75R15 Tires,		Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX
	10000 lb GVWR, Interior Racking Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	9583	2025 Southland LCHT35-718V-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH3312S1118250 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 96 in Overall Width, Side Door 205/75R15 Tires, 7815 lb GVWR,
9578	2025 Southland LARCT52-822V-86 19 ft T/A Enclosed Trailer (Unused) S/N: 2SFPK4314S1117564 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 96 in Deck Width, 96 in Overall Width, Ramp, Side Door 225/75R15 Tires, 11464 lb GVWR, ; EQUIPMENT-FROM-SOUTHLAND-		EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
	TRAILÉR-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX	9584	2025 Southland LCHT35-718V-86 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH3315S1116993 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 79 in Overall Width,
9579	2012 Royal Cargo 19 ft T/A Enclosed Trailer S/N: 2S9PK5312C3026128 C/W: Aluminum/Steel Combination Frame, Ball Hitch, Torsion Axle, Electric Brakes, 97 in Deck Width, 97 in Overall Width, Side Door 235 /80R16 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Midland, TX		Ramp, Side Door 205/75R15 Tires, 7815 lb GVWR, EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP DEFICIENCIES NOTED -PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9585	2025 Southland LCHT35-718V-86R 16 ft T/A Enclosed Trailer (Unused) S/N: 2SFFH3318S1107981
9580			C/W: Ball Hitch, Spring Suspension, Electric Brakes, 79 in Deck Width, 79 in Overall Width, Ramp, Side Door Aluminum Wheels, 205/75R15 Tires, 7716 lb GVWR, ; EQUIPMENT-FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP Asset located in: Humble, TX
		9586	2023 Quality Cargo 16 ft T/A Enclosed Trailer S/N: 50ZBE1168PP040468 C/W: 7000 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 80 in Deck Width, 84 in Overall Width, Ramp, Side Door 205 /75R15 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX

Lot #	Details	Lot #	Details
9587	2023 Pace 12 ft S/A Enclosed Trailer S/N: 53BPTEA16PR011070 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 66 in Deck Width, 66 in Overall Width, Ramp, Side Door Aluminum Wheels, 205 /75R15 Tires, 2990 lb GVWR Usage: Not Available Asset located in: Humble, TX	9595B	2016 Lark United MFG VT6X14SA 14 ft S/A Enclosed Trailer S/N: 571BE1417GM017644 C/W: 5200 lb GVWR, Ball Hitch, Spring Suspension, Electric Brakes, 60 in Deck Width, Ramp, 225/75R15 Tires Usage: Not Available Asset located in: Humble, TX
9588 9589	2020 Carry-On 7X16 Enclosed Trailer S/N: 4YMBC1621LT010101 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX 2013 Lark United 7X16 16 ft Enclosed Trailer	9595A	2018 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHULE420JY077081 C/W: 7000 lb GVWR, Spring Suspension, Electric Brakes, 78 in Deck Width, 78 in Overall Width, 205/75R15 Tires, Bumper Pull with Plywood Decking and Walls. Wooden Shelving. Usage: Not Available
3003	S/N: 5RTBE1628DD034600 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available Asset located in: Humble, TX	9595	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 Cargo Mate 14 ft T/A Enclosed Trailer
9590	2007 Contract 16 ft T/A Enclosed Trailer S/N: 49TCB162171088037 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 72 in Deck Width, 102 in Overall Width, Ramp, 225/75R15 Tires, 8600 lb GVWR	9596	S/N: 5NHULE426JY078137 C/W: Spring Suspension, Electric Brakes, 78 in Deck Width, Ramp, Side Door 205/75R15 Tires, 14000 lb GVWR Usage: Not Available Asset located in: Humble, TX
	Usage: Not Available Asset located in : Humble, TX		2015 Haulmark 14 ft T/A Enclosed Trailer S/N: 575PB1427FT276449
9591	2018 Interstate 7X14 15 ft Enclosed Trailer S/N: 1UK500F28J1095011 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available		C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 225/75R15 Tires, 10000 lb GVWR, Storage Boxes, Roof A/C Usage: Not Available
	Asset located in: Humble, TX	0.50=	Asset located in: Humble, TX
9592	2024 Southland LCHT35-716-86V-NOSE 14 ft T /A Enclosed Trailer (Unused) S/N: 2SFFH3310R1092757 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 82 in Deck Width, 102 in Overall Width, Ramp, Side Door 205/75R15 Tires Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND	⊣ 9597	2015 Haulmark 14 ft T/A Enclosed Trailer S/N: 575PB1425FT293931 C/W: Torsion Axle, Electric Brakes, 81 in Deck Width, 86 in Overall Width, 225/75R15 Tires, 10000 lb GVWR Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	TRAILER CORP Asset located in: Humble, TX	9598	2014 Haulmark 14 ft T/A Enclosed Trailer
9593	2023 Quality Cargo T/A Enclosed Trailer S/N: 50ZBE1428PP044822 C/W: 7000 lb GVWR, Spring Suspension, Electric Brakes, Ramp, 205/75R15 Tires Usage: Not Available Asset located in: Humble, TX		S/N: 575PB1425ET259955 C/W: Torsion Axle, Electric Brakes, Ringfeder, 81 in Deck Width, 86 in Overall Width, 205 /75R15 Tires Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9594	2020 Forest River 14 ft T/A Enclosed Trailer		Asset located in: Humble, TX
	S/N: 5NHUCC420LY035601 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, Storage Boxes, Windows Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9599	2014 Haulmark 14 ft T/A Enclosed Trailer S/N: 575PB1422ET259959 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 225/75R15 Tires, 10000 lb GVWR, Storage Boxes, Counter Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9600 9601	2012 Haulmark 14 ft T/A Enclosed Trailer S/N: 5NHUCC422CY018340 C/W: Torsion Axle, Electric Brakes, 81 in Deck Width, 86 in Overall Width, 235/75R15 Tires Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2012 Forest River 14 ft T/A Enclosed Trailer S/N: 5NHUCC422CY014961	9607	2008 Wells Cargo Trailers - Haul 13 ft T/A Enclosed Trailer S/N: 1W4200F2282063627 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 77 in Deck Width, 77 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, Steel Shelving Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX
	C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 82 in Overall Width, Side Door 205/75R15 Tires, Job Site Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2023 Fast Cargo EV7 12 ft Enclosed Trailer S/N: 7NBBE1221P1006369 Usage: Not Available Asset located in: Lake Worth, TX
9602	Asset located in: Humble, TX 2012 Continental 14 ft T/A Enclosed Trailer S/N: 5NHUCC426CY014963 C/W: Ball Hitch, Torsion Axle, Electric Brakes,	9609 9610 9612 9613A	2015 Arising 7X12 12 ft Enclosed Trailer S/N: 5YCBE1228FH021263 C/W: EQUIPMENT-FROM-A-PRIMORIS- SERVICES-CORP-COMPANY Usage: Not Available
	80 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, Storage boxes, Counter Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX 2025 Southland LCHS29-614V-72 11 ft S/A Enclosed Trailer (Unused) S/N: 2SFAL2260S1109661 C/W: Ball Hitch, Spring Suspension, 69 in Deck
9603	2012 Cargo Mate 14 ft Enclosed Trailer S/N: 5NHUCC422CY016340 Usage: Not Available Asset located in: Humble, TX		Width, 69 in Overall Width, Side Door 205 /75R14 Tires, 2996 lb GVWR, EQUIPMENT- FROM-SOUTHLAND-TRAILER-CORP Usage: Not Available Notes: EQUIPMENT FROM SOUTHLAND TRAILER CORP
9604	2008 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHUCM4248Y056836 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 67 in Deck Width, 67 in Overall Width, 205 /75R15 Tires, Storage boxes, Cabinets, Shelves Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX 2018 Speed-Lift MDL6000BAFR T/A Trailer Mounted Loading Dock S/N: 4S9AFEKD8J1440100 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 225/75R15 Tires, 6,000 Lb capacity, Hatz 1B50 diesel, removable hitch Usage: 4 Hr Asset located in: Humble, TX
9605	2008 Cargo Mate 14 ft T/A Enclosed Trailer S/N: 5NHUCM42X8Y057571 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 82 in Overall Width, Side Door 205/75R15 Tires, Job Site Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2013 MGT Remolque Quad/A Tank Transport Trailer S/N: 3A9SV4023DM216161 C/W: Torsion Axle, 235/80R16 Tires, 28000 lb GVWR Usage: Not Available Asset located in: Humble, TX
9606	Asset located in: Humble, TX 2005 Pace 14 ft T/A Enclosed Trailer S/N: 47ZUB14215X037834 C/W: Ball Hitch, Torsion Axle, Electric Brakes, 80 in Deck Width, 80 in Overall Width, Side Door 205/75R15 Tires, 7000 lb GVWR, Paneling on walls, storage boxes, Roof A/C Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9613	2012 Scheuerle SPGV10094 3X3X3 Modular Trailer S/N: W09970XX8CPS17432 C/W: 256000 lb Trailer Capacity, 102 in Usable Deck Width, 102 in Overall Trailer Width, 69 ft 10 in Main Deck, Self-Contained Power Unit, 245/70R17.5 Tires, 256000 lb GVWR, 9 Steerable Hydraulic Lift Axles, Hydraulic Power Unit, Fifth Wheel Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9614	2008 Benlee TA3S8D48 T/A 48 ft Crushed Car Trailer S/N: 1B9G348268B180496 C/W: Air Ride Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX 2008 Benlee TA3S8D48 T/A 48 ft Scrap Car Trailer	9621	2023 Crazy Monkey T/A Food Vending Trailer (Unused) S/N: 3J9A12185PM095717 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, Outside Water/Sink, Avantco Range with 36" Griddle, (2) Drago Burners, Drago Deep Fryer, (3) Storage Boxes, Vent Hood, A/C Usage: Not Available Asset located in: Humble, TX
	S/N: 1B9G348288B180497 C/W: Air Ride Suspension, 11R22.5 Tires, 22680 lb GVWR Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX TITLE BRAND BOND TITLE Asset located in: Lake Worth, TX	9622	2023 Crazy Monkey T/A 16 ft Concessions Trailer S/N: 3J9A12166PM095921 C/W: 8400 lb GVWR, Spring Suspension, 7.00- 15 Tires Usage: Not Available Notes: LOCATED-IN-MIDLAND-TX Asset located in: Midland, TX
9616	2004 Benlee TA3S8D45 T/A 45 ft Scrap Car Trailer S/N: 1B9G345254B180407 C/W: Air Ride Suspension, Air Brakes, 11R22.5 Tires Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	9623	2021 Margo Concessions Trailer S/N: 3A9M1C329MM050514 C/W: 2260 lb GVWR, Ball Hitch, Spring Suspension, 195R15C Tires, LPG Usage: Not Available Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS; LOCATED-IN-FORT-WORTH-TX Asset located in: Lake Worth, TX
9617	1993 Killebrew T/A Side Dump Fertilizer Trailer S/N: 1K0HD2365PA079042 C/W: Spring Suspension, 11R22.5 Tires, (4) Hoppers Usage: Not Available Asset located in: Humble, TX	9624	2020 TFT T/A Concessions Trailer S/N: 3A9M1FD28LM050504 C/W: 2260 lb GVWR, Aluminum/Steel Combination Frame, Ball Hitch, Spring Suspension, Electric Brakes, 195R15C Tires Usage: Not Available Notes: . DEFICIENCIES NOTED - PLEASE SEE
9618	1993 Killebrew T/A Side Dump Fertilizer Trailer S/N: 1K0HD2368PA079049 C/W: Spring Suspension, 11R22.5 Tires, (4)	0625	THE INSPECTION REPORT Asset located in: Humble, TX
9619	Hoppers Usage: Not Available Asset located in: Humble, TX 2023 Sundowner Cargo 22GN 30 ft T/A Gooseneck Horse Trailer S/N: 13SCG3024P1CA4923	9625	2007 Custom Built BBQ Pit Trailer S/N: 021607 C/W: Spring Suspension, Electric Brakes, 205 /75R14 Tires, 2 Barbecue Pits, 3 Tool Boxes, 4 Speakers, 1 Sink, 1 Propane Tank Holder, 2 Propane Burners Usage: Not Available
	C/W: Aluminum Frame, Torsion Axle, Electric Brakes, 6 Horse, 46 in Stall Width, Air Conditioner, Aluminum Wheels, 235/80R16 Tires, 9990 lb GVWR, Rubber pads on floor, Four side doors, storage over gooseneck. Two way rear door Usage: Not Available Asset located in: Humble, TX	9626B	Asset located in: Humble, TX Concession Caddy S/N: Not Available C/W: Cooler, Storage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9620	2023 Crazy Monkey T/A Food Vending Trailer (Unused) S/N: 3J9A12185PM095667 C/W: Ball Hitch, Spring Suspension, Electric Brakes, 7.00-15 Tires, 7000 lb GVWR, A/C, Outside Water/Sink, Storage Racks, Wash, Drago Range with 2 Burners, 36" Griddle with Deep Fryer, (2) Storage Boxes, Vent Hood Usage: Not Available Asset located in: Humble, TX	9626A	Concession Caddy S/N: Not Available C/W: Cooler, Storage Usage: Not Available Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9626	S/A BBQ trailer S/N: Not Available C/W: Ball Hitch, Spring Suspension, 205/75R15 Tires, Two benches with storage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9633	2010 Trane TCH300E400BB Trailer Mounted Air Conditioner S/N: 1020104540 C/W: 15 ft T/A Utility Trailer, Ball Hitch, Spring Suspension, 235/75R15, Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9634	2011 Parker 16 FT T/A Portable Cooling Station
9627	2023 Power Wash Store Pressure Washer S/N: 5RHCT101XPH003995 C/W: 225 gal Water Supply, Hose, Trailer Mounted, Honda GX390 1 Cylinder 389 cc Gasoline Engine, Spring Suspension, Ball Hitch, Wood Flooring Usage: Not Available Asset located in: Humble, TX	9635	S/N: 13ZLS1621B1004572 C/W: (2) Tanks, Benches, Ball Hitch, Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Parker 16 FT T/A Portable Cooling Station
9628	2016 Alkota HZ535DKS Pressure Washer S/N: 1A9BU1626GA520062 C/W: Water Heater, 325 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kubota D902 3 Cylinder Diesel Engine Usage: Not Available Asset located in: Humble, TX	9636	S/N: 13ZLS1621B1005009 C/W: (1) Tank, Benches, Ball Hitch Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Tric Pipe Breaker Plumbing Supplies
9629 2 S O V	2020 Northstar Mobile Pressure Washer S/N: 4K1PT4C11LK008613 C/W: 4000 psi Rating, Water Heater, 200 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda GX630 2 Cylinder Gasoline Engine		S/N: Not Available C/W: SPX Power Unit, Cable, Ridgid 2048 Job Side Box, 9 Ft S/A Trailer Usage: Not Available Asset located in : Humble, TX
	Usage: 237 Hr Asset located in : Humble, TX	9637A	2024 Cat 255 Two-Speed Compact Track Loader (Inoperable) S/N: CAT00255CFL702984
9630	2020 Northstar Mobile Pressure Washer S/N: 4K1BP162XLF002318 C/W: 4000 psi Rating, Water Heater, 525 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Kohler 2 Cylinder Gasoline Engine Usage: Not Available		C/W: Enclosed Cab, 16 in Track Belts, Hydraulic Coupler Usage: Not Available Notes : NO WARRANTY AVAILABLE; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
9631	2018 Mi-T-M HS-3505-1MGH-T Pressure Washer S/N: Not Available C/W: 3500 psi Rating, Water Heater, 200 gal Water Supply, Hose, Spray Wand, Trailer Mounted, Honda GX630 2 Cylinder Gasoline Engine Usage: 428 Hr Asset located in: Humble, TX 2017 WPM T/A Hydro Blast Trailer	9637	2024 Cat 299D3XE Two-Speed Compact Track Loader (Inoperable) S/N: CAT299D3CB6203268 C/W: Enclosed Cab, Air Ride Seat, 2024 US EPA Label, Requires Diesel Exhaust Fluid, 18 in Track Belts, Manual Coupler Usage: Not Available Notes: NO WARRANTY AVAILABLE; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9032	S/N: 1WP12K15BP1700090		Asset located in: Humble, TX
	C/W: Ball Hitch, Torsion Axle, Electric Brakes, Aluminum Outer Wheels, 235/80R16 Tires, (1) Diesel Tank, (1) Hydraulic Tank, (1) Liquid Tank. Usage: Not Available Notes: . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9638	2018 John Deere 331G Compact Track Loader (Inoperable) S/N: 1T0331GKKJF331353 C/W: Open Operator Station, Joystick Steering, Requires Diesel Exhaust Fluid, 18 in Track Belts Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9639	2014 Bobcat T770 Compact Track Loader (Inoperable) S/N: AN8T13810 C/W: Open Operator Station, Manual Coupler Usage: 972 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9642	2014 Bobcat T590 Compact Track Loader (Inoperable) S/N: ALJU11052 C/W: Open Operator Station, 2014 US EPA Label Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
9640B	2013 Takeuchi TL230 Compact Track Loader (Inoperable) S/N: 223102012 C/W: Enclosed Cab (Door missing), Air Conditioner, Air Ride Seat, US EPA Label, 12 in Track Belts, Manual Coupler Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9643	2013 Bobcat T590 Compact Track Loader (Inoperable) S/N: A3NR12009 C/W: Open Operator Station, 7 Pin Electric Kit, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -	
9640A	2018 Case TR310 Compact Track Loader		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	(Inoperable) S/N: JAFTR310TJM449154 C/W: Enclosed Cab (Door missing), Joystick Steering, 2018 US EPA Label, Requires Diesel Exhaust Fluid, 13 in Track Belts, Manual Coupler Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9645	2005 Bobcat T250 Compact Track Loader (Inoperable) S/N: 525612769 C/W: Open Operator Station, 17.5 in Track Belts, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT B RECONSIGNED DEFICIENCIES NOTED -	
9640	2014 Bobcat T770 Compact Track Loader		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	(Inoperable) S/N: AN8T13291 C/W: Open Operator Station, 17.5 in Track Belts, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9646	· · · · · · · · · · · · · · · · · · ·	
9641A	2015 Bobcat T590 Compact Track Loader		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	(Inoperable) S/N: ALJU15750 C/W: Open Operator Station, 2015 US EPA Label, Manual Coupler Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9647	9647 2008 Bobcat T190 Compact Track Lo (Inoperable) S/N: A3LN12021 C/W: Open Operator Station Usage: Not Available Notes: THIS INOPERABLE ITEM NEED REMOVED FROM THE YARD AND CAN	2008 Bobcat T190 Compact Track Loader (Inoperable) S/N: A3LN12021 C/W: Open Operator Station
9641	2013 Bobcat T750 Compact Track Loader (Inoperable) S/N: ATF612569 C/W: Open Operator Station, Manual Coupler Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details	
9648	2008 Bobcat T190 Compact Track Loader (Inoperable) S/N: 531621127 C/W: Open Operator Station, 13 in Track Belts, Manual Coupler Usage: 3,506 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9653	9653 Case 4230 2WD Tractor (Inoperable) S/N: 4230RXLJJE0916788 C/W: Enclosed Cab, Differential Lock, 8 Forward 4 Reverse, Synchro Mesh, Case IH 2255 Loader, 2 Rear Remotes, 540/1000 PTC 10.00-16SL Front Tires, 18.4x30 Rear Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO B REMOVED FROM THE YARD AND CAN NOTE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION	
9649	2005 Bobcat T190 Compact Track Loader		REPORT	
	(Inoperable)		Asset located in: Humble, TX	
	S/N: 527715476 C/W: Open Operator Station, 2004 US EPA Label Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9654C	JCB 1CXT Tracked Backhoe Loader (Inoperable) S/N: JCB1CXT4CM2935203 C/W: Enclosed Cab, Air Conditioner, Manual Coupler, 71 in Loader Bucket, Side Shift, Quick Coupler, 24 in Backhoe Digging Bucket Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE	
	Asset located in: Humble, TX		THE INSPECTION REPORT	
9650	2002 Bobcat S250 Skid Steer Loader (Inoperable)		Asset located in: Humble, TX	
	S/N: 520711801 C/W: Open Operator Station, Manual Coupler, 62 in Bucket, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9654B	2005 Case 580M Series 2 4x4 Backhoe Loader (Inoperable) S/N: N4C382735 C/W: Open Operator Station, 82 in Loader Bucket, 23 in Backhoe Digging Bucket Usage: 4,724 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
9651	John Deere 240 Skid Steer Loader (Inoperable)	9654A	Kubota M59 4x4 Backhoe Loader (Inoperable)	
	S/N: Not Available C/W: Open Operator Station, Aperture Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Bucket, Thumb Bracket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REI FROM YARD BY JANUARY 17TH AND C	C/W: Open Operator Station, 12 in Loader Bucket, Thumb Bracket Usage: Not Available Notes: INOPERABLE ITEM MUST BE REMOVED FROM YARD BY JANUARY 17TH AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR
9652	2006 John Deere 5525 2WD Tractor		Asset located in: Lake Worth, TX	
	(Inoperable) S/N: LV5525T252147 C/W: Canopy, Differential Lock, 9 Forward 3 Reverse, SyncShuttle, 2006 US EPA Label, 2 Rear Remotes, 540 PTO, Drawbar, 11L-15 Front Tires, 480/80R30 Rear Tires, Rear Wheel Weights Usage: 6,688 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9654	2015 Cat 420F2IT 4x4 Backhoe Loader (Inoperable) S/N: CAT0420FCHWD00276 C/W: Open Operator Station, Backhoe Pilot Controls, Auxiliary Hydraulics, Hydraulic Coupler, Forks, Quick Coupler, 14 in Backhoe Digging Bucket, EQUIPMENT-FROM-A-PRIMORIS-SERVICES-CORP-COMPANY Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

	Details	Lot #	Details
9655	2013 John Deere 544 K Wheel Loader (Inoperable) S/N: 1DW544KZHDE652302 C/W: Enclosed Cab, Air Conditioner, Ride Control, Manual Coupler, 20.5R25 Tires Usage: 17,716 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9658	2012 Komatsu D375A-6 Crawler Dozer (Inoperable) S/N: 60183 C/W: Enclosed Cab, Air Conditioner, Fire Suppression System, Auto Lube, 264 in Wide Semi-U Blade 28 in Single Grouser Track Shoes, Counterweight Usage: 22,174 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-HOUSTON-TX- HOU; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9656	1997 Volvo L90C Wheel Loader (Inoperable)		Asset located in: Humble, TX
	S/N: L90CV62485 C/W: Enclosed Cab, Air Ride Seat, Hydraulic Coupler, 100 in Bucket, 20.5x25 Aperture Tires Usage: 3,558 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-FORT-WORTH-TX, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	9659A	2020 Komatsu D51PX-24 Crawler Dozer (Inoperable) S/N: KMT0D133KKA010815 C/W: Enclosed Cab, Air Conditioner, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 132 in Wide PAT Blade, 28.5 in Single Grouser Track Shoes, Drawbar Usage: 8,255 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS
9657A		-	TO BE REMOVED FROM THE YARD AND CAN
J00/A	S/N: CAT0966MHKJP02683 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Joystick		NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX
	Steering, Requires Diesel Exhaust Fluid, Pipe Grapple, 26.5-25 Tires Usage: 7,497 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9659	2008 Cat D6T XL Crawler Dozer (Inoperable) S/N: CAT00D6TPLAY00819 C/W: Enclosed Cab, Air Conditioner, 24 in Single Grouser Track Shoes, SystemOne Undercarriage, Counterweight, Drawbar Usage: Not Available
9657	1987 Cat 950 E Wheel Loader (Inoperable) S/N: 63R06348 C/W: Enclosed Cab, Forks, 23.5R25 Tires Usage: 19,359 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9660	1988 Ingersoll Rand SPF48 Padfoot Drum Compactor (Inoperable)
	Asset located in: Humble, TX		S/N: 6353P C/W: Open Operator Station, Cummins 4
9658A	S/N: CAT000D6PKEW00309 C/W: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Pre-Wired for Grade Control, Requires Diesel Exhaust Fluid, 158 in Wide Semi-U Blade w/ Single Tilt, 36 in Single Grouser Track Shoes, SystemOne		Cylinder Diesel Engine, 68 in Drum Usage: 3,144 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Undercarriage, Drawbar, Rear Auxiliary Hydraulics	9661	2014 Bomag BW124 Smooth Drum Compactor
	Usage: 4,998 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT; LOT CAN BE BLAST & PAINTED FOR \$8,700.00 Asset located in: Humble, TX		(Inoperable) S/N: 861832121166 C/W: Deutz D 2011 L031 3 Cylinder Diesel Engine, 48 in Drum Usage: 628 Hr
		•	Notes THO MODERADIE TELL VICES TO SE
		•	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9662A	1983 Ingersoll Rand SP-48 Smooth Drum Compactor S/N: 5525-S C/W: Open Operator Station, Swivel Operator Controls, Detroit Diesel Engine, 66 in Drum Usage: 551 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 1999 Ingersoll Rand SD70D Smooth Drum	9665	2004 Case CX460 Tracked Excavator (Inoperable) S/N: DAC461152 C/W: 13 ft 2 in Stick, 35 in Triple Grouser Tracl Shoes, 72 in Digging Bucket, Thumb Bracket Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BI RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES
7002	Compactor (Inoperable) S/N: 156240 C/W: Open Operator Station, 2019 US EPA Label, Cummins 4B 4 Cylinder 95 hp Diesel	9666	NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2024 AGT QS12R Mini Excavator (Inoperable)
	Engine, 66 in Drum Usage: 2,320 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 2402075082 C/W: 2 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 6 in Rubber Tracks, 12 in Digging Bucket, Manual Thumb Usage: 165 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset Josefed in: Humble TX
9663	2014 Wacker Neuson RD12A Double Drum	06670	Asset located in: Humble, TX
	Roller (Inoperable) S/N: 20261415 C/W: Open Operator Station, 2014 US EPA Label, Honda Gasoline Engine, 34.5 in Compaction Width Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	9667B	Morbark SP111HP3 Tow-Behind Wood Chipper (Inoperable) S/N: 4AYSZ1514PW001575 C/W: Perkins 4 Cylinder Gasoline Engine, 20 in Feed Opening, Swivel Discharge Chute, S/A Trailer, Ball Hitch, Electric Brakes Usage: 116 Hr Asset located in: Humble, TX
	Asset located in: Humble, TX	9667A 	2006 Rayco Tow-Behind Wood Chipper (Inoperable)
9664	Gradall GW362G3WD 4x2 Highway Wheeled Excavator (Inoperable) S/N: G01D710 C/W: 6 Speed Automatic Transmission, 3911.3 hrs Carrier Engine, Cummins B5.9 6 Cylinder 5.9 L Diesel Carrier Engine, Manual Quick Coupler, 60 in Cleanup Bucket Usage: 3,911 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE		S/N: 1R98109176M210068 C/W: Briggs & Stratton Vanguar Gasoline Engine, 7 in Feed Oper Discharge Chute, S/A Trailer, Ba Electric Brakes Usage: 1,209 Hr Notes: DEFICIENCIES NOTED - THE INSPECTION REPORT
	REMOVED FROM THE YARD AND CAN NOT BE	9667	2001 Vermeer TG400AL Tri/A Tub Grinder
	RECONSIGNED LOCATED-IN-HOUSTON-TX- HOU, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		(Inoperable) S/N: 1VRN462T111000511 C/W: Enclosed Cab, Cat 3406 6 Cylinder 599
	Asset located in: Humble, TX	_	hp 14.6 L Diesel Engine, 29 in Discharge Conveyor, Grapple Loader Boom, Tri/A Carrier,
9665A	2011 Yanmar ViO55-5B Tracked Excavator (Inoperable) S/N: YMRVIO55P9YY53653 C/W: Air Conditioner, 2009 US EPA Label, Swing Boom, 5 ft 7 in Stick, Backfill Blade, 16 in Triple Grouser Track Shoes, 29 in Digging Bucket, Hydraulic Thumb Usage: 960 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Spring Suspension, Hydraulic Leveling Usage: 3,536 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM ALL THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9668 9669B	2007 Vermeer RT350 4x4 Trencher (Inoperable) S/N: 1VRZ0826971000347 C/W: 3 Cylinder Diesel Engine, Hydrostatic Drive, 5 in Wide x 48 in Long Dirt Trencher Chain, Angle Blade Usage: 1,340 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2015 Lay-Mor SM300 Self-Propelled Broom (Inoperable) S/N: 35690	9671	2015 JCB 512-56 Telehandler (Inoperable) S/N: JCB5CH2GC02433958 C/W: Enclosed Cab, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 68 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, Solid Tires Usage: 2,818 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: Open Operator Station, 8 ft Broom, Water System, 2011 US EPA Label, Kubota V1505-	0.470	Asset located in: Humble, TX
	ETO4 4 Cylinder 1.5 L Diesel Engine Usage: 816 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9672	2010 Cat TL1255 Telehandler (Inoperable) S/N: TBN00662 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 17.5-25 Tires
9669A	2016 Lay-Mor SM300 Self-Propelled Broom (Inoperable) S/N: 36706 C/W: Open Operator Station, 8 ft Broom, Water System, 2015 US EPA Label, Kubota D1105- EF05 3 Cylinder 1.1 L Diesel Engine Usage: 973 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		Usage: 13,944 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	THE INSPECTION REPORT	9673	2009 Cat TL1255 Telehandler (Inoperable)
9669	Asset located in: Humble, TX 2006 Vermeer RT350 4x4 Trencher (Inoperable) S/N: 1VRZ0826161000227 C/W: 3 Cylinder Diesel Engine, Hydrostatic Drive, 3 in Wide x 60 in Long Dirt Trencher Chain, Angle Blade Usage: 661 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE		S/N: TBN00544 C/W: Enclosed Cab, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydrau Plumbing, 17.5-25 Tires Usage: 9,415 Hr Notes: THIS INOPERABLE ITEM NEEDs TO B REMOVED FROM THE YARD AND CAN NOT RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES
	RECONSIGNED Asset located in: Humble, TX		NOTED - PLEASE SEE THE INSPECTION REPORT
9670	2008 Broce RJ350 Self-Propelled Broom		Asset located in: Humble, TX
	(Inoperable) S/N: 406178 C/W: Open Operator Station, 2007 US EPA Label, John Deere 4045DF 4 Cylinder 4.5 L Diesel Engine Usage: 3,045 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9674	2018 JLG 1055 Telehandler (Inoperable) S/N: 0160084305 C/W: Open Operator Station, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 2017 US EPA Label, Requires Diesel Exhaust Fluid, 59.5 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 14.00- 24T Tires Usage: 9,551 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9675	2007 Cat TL943 Telehandler (Inoperable) S/N: TBL00786 C/W: Open Operator Station, 43 ft Max Lift Height, 9000 lb Max Lift Capacity, 56 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing, 13.00-24 Tires, EQUIPMENT-FROM-PUMPCO-ENERGY- INFRASTRUCTURE Usage: 9,190 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9678	2011 Hyundai 70D-7E Pneumatic Tire Forklift (Inoperable) S/N: HHIHFQ11JB0000887 C/W: Enclosed Cab, Air Conditioner, Single Stage Mast 121 in Lowered Mast Height, 94 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires, 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
9676	1995 Princeton D-4500 4500 lb 4x2 Truck Mounted Forklift (Inoperable) S/N: 36730795 C/W: Single Stage Mast 96 in Lowered Mast Height, 47 in Forks, Hatz 3 Cylinder Diesel Engine Usage: 80 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	-9679	Cat VC60DSA 6000 lb Cushion Tire Forklift (Inoperable) S/N: 9SB394 C/W: 2 Stage Mast, 173 in Max Lift Height, 102 in Lowered Mast Height, Side Shift, 4 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9680 ift	2016 Hyster H80FT 6550 lb Pneumatic Tire Forklift (Inoperable) S/N: U005V04442P C/W: 3 Stage Mast, Full Free Lift, 90 in Lowered Mast Height, 42 in Forks, Side Shift, Solid Pneumatic Tires, Diesel Engine Usage: 7,662 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
9677	1994 Princeton D4500 4500 lb 4x2 Truck Mounted Forklift (Inoperable) S/N: TP29560894 C/W: Single Stage Mast 102 in Lowered Mast Height, 39 in Forks, 3 Cylinder Diesel Engine Usage: 1,986 Hr			
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Asset located in: Humble, TX 2017 Toyota 62-8FDN30 Pneumatic Tire Forklift (Inoperable) S/N: 608FDN30-11739 C/W: Full Free Lift, 79 in Lowered Mast Height, 48 in Forks, Side Shift, Toyota 1DZ 4 Cylinder Diesel Engine	
9678B	2017 Toyota 02-7FDA50 Pneumatic Tire Forklift S/N: 7FDA50-19614 C/W: 2 Stage Mast, 96 in Lowered Mast Height, 54 in Forks, 2007 US EPA Label, Toyota 14Z 6 Cylinder Diesel Engine Usage: 4,338 Hr		Usage: 2,097 Hr Notes: THIS INOPERABLE ITEM REMOVED FROM THE YARD AN RECONSIGNED DEFICIENCIES N	Usage: 2,097 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2021 Doosan D30S7 5500 lb Pneumatic Tire Forklift (Inoperable)	
9678A	2017 Toyota 02-7FDA50 Pneumatic Tire Forklift (Inoperable) S/N: 7DFA50-13480 C/W: 2 Stage Mast, Full Free Lift, 86 in Lowered Mast Height, 49 in Forks, Toyota 6 Cylinder Diesel Engine Usage: 2,874 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: FDA0W-1930-03660 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Side Shift, 2020 US EPA Label, Doosan 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details
9682 9683	1997 Toyota 42-6FGU25 5400 lb Pneumatic Tire Forklift (Inoperable) S/N: 63385 C/W: 3 Stage Mast, Full Free Lift, 189 in Max Lift Height, 82 in Lowered Mast Height, 4 Cylinder Dual Fuel Engine Usage: 15,705 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 TCM FG2M5T 5000 lb Cushion Tire Forklift (Inoperable) S/N: A31T54483 C/W: 2 Stage Mast, Full Free Lift, 130 in Max Lift Height, 84 in Lowered Mast Height, 48 in Forks, Nissan 4 Cylinder Gasoline Engine	Forklift (Inoperable) S/N: AF82F42132 C/W: 3 Stage Mast, Full Free Lift, 187 in Ma Lift Height, 82 in Lowered Mast Height, 42 i Forks, Side Shift, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO REMOVED FROM THE YARD AND CAN NOT RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 9688 2016 Mitsubishi FGC25 4750 lb Cushion Tir Forklift (Inoperable) S/N: AF82F42133 C/W: 3 Stage Mast, Full Free Lift, 187 in Ma Lift Height, 82 in Lowered Mast Height, 42 i	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift (Inoperable) S/N: AF82F42132 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Mitsubishi FGC25 4750 lb Cushion Tire Forklift (Inoperable) S/N: AF82F42133 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in
9684	Usage: 3,712 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Mitsubishi FGC25 4750 lb Cushion Tire Forklift (Inoperable)	_	Forks, Side Shift, Tier 2, 2015 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.1 L LPG Engine Usage: 14,284 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9685	S/N: AF82F42137 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, CARB Compliant, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Mitsubishi FGC25N 4750 lb Cushion Tire	9689	2016 Mitsubishi FGC25 4750 lb Cushion Tire Forklift (Inoperable) S/N: AF82F42125 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Forklift (Inoperable) S/N: AF82F42135 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 84 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9690A	2000 Hyster S50XM 4500 lb Cushion Tire Forklift (Inoperable) S/N: D187V20833X C/W: 3 Stage Mast, 189 in Max Lift Height, 82 in Lowered Mast Height, 35 in Forks, Side Shift, 4 Cylinder LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9686	2016 Mitsubishi FGC25N 4750 lb Cushion Tire Forklift S/N: AF82F42145 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Tier 2, 2015 US EPA Label, GCT 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	- 9690	Daewoo C25S-2 4500 lb Pneumatic Tire Forklift (Inoperable) S/N: 1200313 C/W: 3 Stage Mast, 188 in Max Lift Height, 84 in Lowered Mast Height, Side Shift, Solid Pneumatic Tires, 4 Cylinder LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9691 9692A	2002 Nissan Pneumatic Tire Forklift (Inoperable) S/N: 9W3082 C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, Nissan 4 Cylinder LPG Engine Usage: 3,835 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Cat V50B Pneumatic Tire Forklift (Inoperable)	9695 9696A	Nissan 50 Pneumatic Tire Forklift (Inoperable) S/N: Not Available C/W: 2 Stage Mast, Full Free Lift, 60 in Lowered Mast Height, Solid Pneumatic Tires, 2007 US EPA Label, Nissan 4 Cylinder 2.1 L LPG Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Skyjack SJ45T 4WD Diesel Telescopic Boom
9692	S/N: 79M1490 C/W: 3 Stage Mast, 83 in Lowered Mast Height, 4 Cylinder LPG Engine Usage: 3,545 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Cat T60D Cushion Tire Forklift (Inoperable)		Lift S/N: Not Available C/W: 45 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 2016 US EPA Label, Deutz d2.9l4 4 Cylinder 49 hp 2.9 L Diesel Engine, 305/70D16.5 Tires Usage: 2,607 Hr Notes: LOCATED-IN-FORT-WORTH-TX; DEFICIENCIES NOTED - PLEASE SEE THE
7072	S/N: Not Available		INSPECTION REPORT
	C/W: 2 Stage Mast, 116 in Max Lift Height, 81 in Lowered Mast Height, 46 in Forks, 4 Cylinder	0605	Asset located in: Lake Worth, TX
9693	LPG Engine Usage: 8,301 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2008 Yale GLP040SVXNUSE084 3800 lb	9696	2017 Genie S-65 4WD Diesel Telescopic Boo Lift (Inoperable) S/N: S60D1009 C/W: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, 201 US EPA Label, Deutz D2.9L 4 Cylinder 2.9 L Diesel Engine, 335/55 Tires Usage: 3,382 Hr Notes: LOCATED-IN-FORT-WORTH-TX; THIS
	Cushion Tire Forklift (Inoperable) S/N: C810V03617F C/W: 3 Stage Mast, Full Free Lift, 187 in Max Lift Height, 83 in Lowered Mast Height, 48 in Forks, Side Shift, 2008 US EPA Label, IMPCO 4 Cylinder 2.0 L LPG Engine Usage: Not Available		INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		2018 Ruthman SA31 Crawler Electric Articulating Boom Lift (Inoperable) S/N: 08041863 C/W: 250 kg Max Weight Capacity, Jib, 10 in
9694	Asset located in: Humble, TX Cat Pneumatic Tire Forklift (Inoperable) S/N: AT18C31139 C/W: 3 Stage Mast, 84 in Lowered Mast Height, 72 in Forks, Solid Pneumatic Tires, 2010 US EPA Label, 4 Cylinder 3.3 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Rubber Tracks, extendable tracks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9695A	Raymond DSS300 3000 lb Electric Forklift (Inoperable) S/N: DSS-06-06881 C/W: 3 Stage Mast, 227 in Max Lift Height, 82 in Lowered Mast Height, 42 in Forks, Side Shift, 36 V Usage: Not Available Asset located in: Humble, TX		

Lot #	Details	Lot #	Details
9698	2007 Snorkel TB85JFA 4WD Diesel Telescopic Boom Lift (Inoperable) S/N: SP07041RBLT C/W: 85 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Deutz 4 Cylinder Diesel Engine, 15-625 Tires Usage: 3,635 Hr Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9700	2012 Genie GS-3390 RT 4x4 Diesel Scissor Lift (Inoperable) S/N: GS901247923 C/W: 33 ft Max Platform Height, 2500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, 2011 US EPA Label, Deutz 3 Cylinder 36.3 kW Diesel Engine Usage: 934 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9699B	699B 2003 Genie GS4390 4x4 Dual Fuel Scissor Lift (Inoperable) S/N: GS9003-41542 C/W: 43 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box, Ford LRG-4251-6007 4 Cylinder Dual Fuel Engine Usage: 2,341 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE	9701A	2014 Genie GS2632 Electric Scissor Lift (Inoperable) S/N: Not Available C/W: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Solid Non-Marking Tires, Upper Control Box Usage: Not Available Asset located in: Humble, TX
9699A	Asset located in: Humble, TX 2013 Genie GS-5390RT 4x4 Diesel Scissor Lift (Inoperable) S/N: GS901349035 C/W: 53 ft Max Platform Height, 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, US EPA Label, Deutz D2011L03I 3 Cylinder 49 hp 2.3 L Diesel Engine Usage: 1,077 Hr	9701	2018 JLG 2632ES Electric Scissor Lift (Inoperable) S/N: M200016475 C/W: Platform Extension, Power to Platform Solid Non-Marking Tires Usage: 145 Hr Notes: THIS INOPERABLE ITEM NEEDS TO REMOVED FROM THE YARD AND CAN NOT RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2019 Snorkel Electric Scissor Lift (Inoperable S/N: S3219E11190500798 C/W: 19 ft Max Platform Height, 550 lb Max
9699	2016 Genie S60X 4WD Diesel Telescopic Boom Lift S/N: S60X16H-35216 C/W: 60 ft Max Platform Height, 500 lb Max Weight Capacity, Power to Platform, 2015 US EPA Label, Deutz D2.9 L4 4 Cylinder 2.9 L Diesel Engine, Positive Air Shutoff, 355-55d Foam-Filled Tires Usage: 5,306 Hr Notes: LOCATED-IN-FORT-WORTH-TX, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Lake Worth, TX	9703	Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2021 LiuGong S1930DE Electric Scissor Lift (Inoperable) S/N: K0036658 C/W: 26 ft Max Platform Height, 505 lb Max Weight Capacity, Platform Extension, Power to Platform, Upper Control Box Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details	
9704	2016 Genie GS1930 Electric Scissor Lift (Inoperable) S/N: GS30P-163981 C/W: 19 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box Usage: 602 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9709A 9709	(Inoperable) S/N: A5KD2GDBVMG044240 C/W: Canopy, 4 Passenger, Windshield, H Receiver, Hydraulic Dump Bed, 2021 US E Label, Kubota 3 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE S THE INSPECTION REPORT Asset located in: Humble, TX 9709 2010 Polaris Ranger XP 4x4 Utility Vehicle	S/N: A5KD2GDBVMG044240 C/W: Canopy, 4 Passenger, Windshield, Hitch Receiver, Hydraulic Dump Bed, 2021 US EPA Label, Kubota 3 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2010 Polaris Ranger XP 4x4 Utility Vehicle
	Asset located in: Humble, TX	-	(Inoperable) S/N: 4XATH76A7A2883297	
9705	2019 Polaris Ranger 4x4 Utility Vehicle (Inoperable) S/N: 4XABEPD44K8578646 C/W: Open Operator Station, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Tier 4, 2019 US EPA Label, Kubota 3 Cylinder .89 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE		C/W: Open Operator Station, 2 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BI RECONSIGNED OFF HIGHWAY USE ONLY DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	
	RECONSIGNED	9710	Asset located in: Humble, TX 2017 Kubota RTV-X1140 4x4 Utility Vehicle	
9706	Asset located in: Humble, TX 2019 Polaris Ranger 4x4 Utility Vehicle (Inoperable) S/N: 4XABEPD48K8578679 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kubota 3 Cylinder 0.89 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2018 Polaris Ranger XP 4x4 Utility Vehicle		(Inoperable) S/N: A5KD2GDBTHG018882 C/W: Canopy, 4 Passenger, Rear Screen, Locking Front Differential, Brush Guard, Hitch Receiver, Hydraulic Dump Bed, Tier 4, 2017 US EPA Label, Kubota D1105 3 Cylinder 18.5 kW 1.1 L Diesel Engine Usage: 3,205 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	(Inoperable) S/N: 4XARVA879J8500197 C/W: Canopy, 6 Passenger, Windshield, Locking Front Differential, Brush Guard, Hitch Receiver, Manual Dump Bed, 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9711B 9711A	Cushman Turf-Truckster Utility Cart (Inoperable) S/N: 99001959 C/W: Open Operator Station, 2 Passenger, Hydraulic Dump Bed, 3 Cylinder Gasoline Engine Usage: 1,461 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Cushman Turf-Truckster Utility Cart (Inoperable) S/N: 00003585	
	· · · · · · · · · · · · · · · · · · ·	4	C/W: Open Operator Station, 2 Passenger,	
9708	2018 Polaris Ranger 4x4 Utility Vehicle (Inoperable) S/N: 4XARVAD18J8867609 C/W: Canopy, 6 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, 2019 US EPA Label, Kohler 3 Cylinder 1.0 L Diesel Engine Usage: 1,727 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Hydraulic Dump Bed, 3 Cylinder Gasoline Engine Usage: 3,460 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	

Lot #	Details	Lot #	Details		
9711	2010 Kubota RTV1140CPX 4x4 Utility Vehicle (Inoperable) S/N: A5KD1HDAPAG016329 C/W: Open Operator Station, 4 Passenger, Hydraulic Dump Bed, Tier 4, 2010 US EPA Label, Kubota D1105 3 Cylinder 1.1 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9713	(Inoperable) S/N: 1FD0W5HT4GED32168 C/W: Ford 4V F-Series V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWF 225/70R19.5, Spring Suspension, 200 in Wheelbase, Knapheide 11 ft Body, Manual Stabilizers Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO B REMOVED FROM THE YARD AND CAN NOT B	S/N: 1FD0W5HT4GED32168 C/W: Ford 4V F-Series V8 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 200 in Wheelbase, Knapheide 11 ft Body, Manual Stabilizers	
9712C	Club Car XRT1200 4x2 Utility Vehicle S/N: AD0924-028187		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		
	C/W: Canopy, 2 Passenger, Windshield, Rear Screen, Brush Guard, Hitch Receiver, Manual Dump Bed, 1 Cylinder Gasoline Engine Usage: 6,547 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9714A	2016 Ford F-550 XL 4x4 Service Truck S/N: 1FDUF5HT2GEA46367 C/W: Ford Power Stroke 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, 9727 Engine hrs, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring		
9712B	2019 Club Car Carry All 1700 4x4 Utility Vehicle (Inoperable) S/N: SD1913958838 C/W: Canopy, 4 Passenger, Brush Guard, Hitch Receiver, Manual Dump Bed, Kubota 3 Cylinder Diesel Engine Usage: 1,192 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		Suspension, 165 in Wheelbase, IMT I Vanair 051243 Gasoline Air Compres Hose Reel Usage: 159,307 Mi Notes : DEFICIENCIES NOTED - PLEA THE INSPECTION REPORT Asset located in : Humble, TX	Usage: 159,307 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	
	THE INSPECTION REPORT	9714	2009 Chevrolet Silverado 2500 HD 4x2 Utility Truck (Inoperable)		
9712A	(Inoperable) S/N: LTA0051817 C/W: Canopy, 2 Passenger, Windshield, Manual Dump Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Manual	C/W: V8 Gasoline Transmission, 42 Rears, 9200 lb GV Suspension, 142 Body Usage: Not Availa Notes: THIS INOI REMOVED FROM RECONSIGNED D PLEASE SEE THE	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9712	2014 E-Z-Go Golf Cart (Inoperable)		Asset located in: Humble, TX		
	S/N: 3054540 C/W: 4 Passenger, Canopy, Windshield, 2013 US EPA Label, Kawasaki 1 Cylinder Gasoline Engine Usage: 50 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9715	2003 GMC C8500 4x2 Service Truck (Inoperable) S/N: 1GDP8E1C33F521918 C/W: 6 Cylinder Diesel Engine, Allison Automatic Transmission, 13220 lb Front Axle, 23000 lb Rears, 36220 lb GVWR, 11R22.5, Spring Suspension, 176 in Wheelbase, PTO, 14 ft Body, Hydraulic Stabilizers, IMT 5020 8600 lb 2 Section Crane, Hydraulic Air Compressor, Air Hose Reel Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE RE MOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM		

Lot #	Details	Lot #	Details
9716	1975 Kaiser M725 6x6 Flatbed Water Truck (Inoperable) S/N: 05D14569M72511166 C/W: 6 Cylinder Diesel Engine, 863 Engine hrs, 5-Speed Manual Transmission, 9000 lb Front Axle, 30750 lb Rears, 11.00R20, Spring Suspension, 180 in Wheelbase, PTO, 12 ft x 96 in Bed, Pintle Hitch Usage: 5,214 Mi Notes: ; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 Intenational 4300 4x2 Water Truck	9720	2012 Freightliner M2106 4x2 Cab and Chassis (Inoperable) S/N: 1FVACWDT7CHBH8659 C/W: Cummins ISB 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, 12575 Engine hrs, Allison 2200 Automatic Transmission, 8000 lb Front Axle, 17500 lb Rears, Meritor MS-17-14X Drive Axles, 5.13:1 Axle Ratio, 25500 lb GVWR, 275/80R22.5, Spring Suspension, 282 in Wheelbase, 216 in Cab to Axle, 303 in Cab to End of Frame Usage: 232,031 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	(Inoperable) S/N: 1HTMMAAM8EH467675 C/W: International MaxxForce DT 7.6 L Diesel Engine, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Spring Suspension, 154 in Wheelbase, Steel Tank, PTO Driven Pump, Hose Reel, Front Spray, Rear Spray, Side Spray Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX	9721	Asset located in: Humble, TX 2000 Volvo VNM 6x4 Cab and Chassis (Inoperable) S/N: 4V4MD2UF7YN238625 C/W: Cummins ISM 6 Cylinder Diesel 370 hp Engine, Eaton Fuller RTX-14710C 10-Speed Manual Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor RT40-14 Drive Axles, 50350 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 295/75R22.5, Air Ride Suspension, 168 in Wheelbase, Wet Kit, 104 in Cab to Axle, 160 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE
9718	2011 International 4400SBA 2000 gal 4x2 Water Truck (Inoperable) S/N: 1HSMKAAN8BH358390 C/W: International 6 Cylinder Diesel Engine, 10838 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 20000 lb Rears, 30000 lb GVWR, Air Ride Cab, 295/75R22.5, Air Ride Suspension, 152 in Wheelbase, PTO, 2000 gal Steel Tank, PTO Driven Pump, Rear Spray, Side Spray Usage: 235,207 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED . DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9722	2004 Ford F-650 XL 4x2 Cab and Chassis (Inoperable) S/N: 3FRNF65N84V683075 C/W: 6 Cylinder Diesel Engine, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/80R22.5 Front Tires, 11R22.5 Rear Tires, Spring Suspension, 260 in Wheelbase, 186 in Cab to Axle, 271 in Cab to End of Frame Usage: 145,251 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9719	Kenworth 6x4 Cab and Chassis (Inoperable) S/N: 38505 C/W: Cat C12 6 Cylinder Ultra Low Sulfur Diesel Engine, 15284 Engine hrs, Engine Brake, Aluminum Wheels, 385/65R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Chalmers Rubber Suspension, 250 in Wheelbase, 159 in Cab to Axle, 229 in Cab to End of Frame Usage: 610,040 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9723	Asset located in: Humble, TX 2022 Ram 4500 Laramie 4x4 Crew Cab Cab and Chassis (Inoperable) S/N: 3C7WRLFL7NG245810 C/W: 7000 lb Front Axle, 12000 lb Rears, 16500 lb GVWR, 225/70R19.5, Spring Suspension, 198 in Wheelbase, 87 in Cab to Axle, 138 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM TITLE IS BRANDED AS NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9724	2017 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1HA3GRCG7HN002344 C/W: V8 6.0 L Gasoline Engine, 2020 US EPA Label, 20290 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16, Spring Suspension, 132 in Wheelbase, 74 in Cab to Axle, 142 in Cab to End of Frame Usage: 343,000 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9729A	2019 Kenworth T800 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3WKDD40X7KF257236 C/W: Cummins X15 15.0 L 450 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FAO-16810C 10-Speed Automated Transmission, 14320 lb Front Axle, 46000 lb Rears, Dana Drive Axles, 3.73:1 Axle Ratio, 60320 lb GVWR, Air Ride Cab, 11R24.5, Air Ride Suspension, 216 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, Dual Fuel Tanks Usage: Not Available Asset located in: Humble, TX
	Asset located in: Humble, TX	9729	2012 Mitsubishi Fuso 4x2 COE Cab and
9725	2017 Chevrolet 3500 4x2 Cab and Chassis S/N: 1HA3GRCG6HN006966 C/W: V8 Gasoline Engine, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75/16, Spring Suspension, 140 in Wheelbase, 81 in Cab to Axle, 138 in Cab to End of Frame Usage: 306,314 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Chassis (Inoperable) S/N: JL6AMC1A2CK003922 C/W: Fuso F1C 4 Cylinder 3.0 L Diesel Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 5360 lb Front Axle, 9880 lb Rears, 12500 lb GVWR, 215 /85R16, Spring Suspension, 112 in Wheelbase, 92 in Cab to Axle, 156 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE
	Asset located in: Humble, TX	_	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9726	2016 Chevrolet Express G3500 4x2 Cab and		Asset located in: Humble, TX
	Chassis (Inoperable) S/N: 1GB3GRCG8G1279325 C/W: V8 Gasoline Engine, 20299 Engine hrs, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225/75R16, Spring Suspension, 134 in Wheelbase, 77 in Cab to Axle, 142 in Cab to End of Frame Usage: 351,994 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9730	2004 Kenworth T800 6x4 Winch Truck (Inoperable) S/N: 1XKDDT9X54R063169 C/W: Cat C10 6 Cylinder Ultra Low Sulfur Diesel 335 hp Engine, 3480 Engine hrs, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, Meritor RT-44-145 Drive Axles, 5.29:1 Axle Ratio, 56000 lb GVWR, Air Ride Cab, 11R22.5, Neway Air Ride Suspension, 172 in Wheelbase, Dual PTO, Tail Roll, Braden ANS20- 18B 21300 lb Winch Usage: 458,632 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE
9727	2016 Chevrolet Express Cab and Chassis (Inoperable)		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	S/N: 1GB3GRCG261281149		Asset located in: Humble, TX
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2016 Chevrolet Express G3500 4x2 Cab and Chassis (Inoperable) S/N: 1GB3GRCG1G1277688 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4300 lb Front Axle, 8600 lb Rears, 12300 lb GVWR, 225 /75R16, Spring Suspension, 142 in Wheelbase, 81 in Cab to Axle, 139 in Cab to End of Frame Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9731A	2015 Mack CHU 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1M2AN07Y5FM018007 C/W: Mack MP8 6 Cylinder 12.8 L Diesel 445 hp Engine, 2014 US EPA Label, Requires Diesel
9728			Exhaust Fluid, Mack Automated Transmission, 14320 lb Front Axle, 38000 lb Rears, 52320 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R24.5, Twin Y Air Ride Suspension, 220 in Wheelbase, Dual Fuel Tanks Usage: 429,571 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Details Lot# **Details** Lot # 9731 2013 Kenworth T800 8x4 Tri/A Sleeper Truck 9732A 2016 Freightliner Cascadia 125 6x4 T/A Day Tractor (Inoperable) Cab Truck Tractor (Inoperable) S/N: 1XKDP7EX2DJ353825 S/N: 3AKJGEDV1GSGV9636 C/W: Cummins ISX12 6 Cylinder 11.9 L Ultra Low Sulfur Diesel 425 hp Engine, 2012 US EPA C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Label, Requires Diesel Exhaust Fluid, Engine Engine Brake, Detroit DT12-OB-1550 12-Speed Brake, Eaton Fuller RTLO-16918B 18-Speed Automated Transmission, 12000 lb Front Axle, Manual Transmission, 19500 lb Front Axle, 60000 lb Rears, 4.89:1 Axle Ratio, 79500 lb 40000 lb Rears, 3.25:1 Axle Ratio, 52000 lb GVWR, 11R22.5, Airliner Air Ride Suspension, GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, 425/65R22.5 Front Tires, 11R22.5 Rear 178 in Wheelbase, Air Sliding 5th Wheel, Dual **Fuel Tanks** Tires, Dual Steering Boxes, Double Frame, Usage: 522,814 Mi Hendrickson Air Ride Suspension, 260 in **Notes**: PROFESSIONALLY-MAINTAINED-FLEET-VEHICLE-PAG; DEFICIENCIES NOTED -Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks PLEASE SEE THE INSPECTION REPORT Usage: Not Available Asset located in: Humble, TX Notes: THIS INOPERABLE ITEM NEEDs TO BE 9732 2016 Mack CXU613 6x4 T/A Day Cab Truck REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Tractor (Inoperable) Asset located in: Humble, TX S/N: 1M1AW02Y9GM076387 C/W: Mack MP7 6 Cylinder 10.8 L Ultra Low 2018 Freightliner Cascadia 125 6x4 T/A Day 9732C Sulfur Diesel 405 hp Engine, 2016 US EPA Cab Truck Tractor (Inoperable) Label, Requires Diesel Exhaust Fluid, 5441 S/N: 3AKJGEDV3JSJH1983 Engine hrs, Engine Brake, Mack mDrive 12-C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 525 Speed Automated Transmission, 12000 lb hp Engine, 2017 US EPA Label, Requires Diesel Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 232 in Wheelbase Exhaust Fluid, 8275 Engine hrs, Detroit DT12-OB-1550 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Usage: 646,382 Mi Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Notes: LOCATED-IN-LIVINGSTON_LA 11R22.5, Airliner Air Ride Suspension, 178 in SUBJECT TO LOUISIANA SALES TAX. THIS Wheelbase, Air Sliding 5th Wheel, Dual Fuel INOPERABLE ITEM NEEDS TO BE REMOVED Tanks FROM THE YARD AND CAN NOT BE Usage: 283.337 Mi RECONSIGNED DEFICIENCIES NOTED -Notes: BUYER'S RESPONSIBILITY FOR PLEASE SEE THE INSPECTION REPORT REMOVAL OF THIS ITEM; SELLER MAINTENANCE RECORD ATTACHED IN THE Asset located in: Livingston, LA 9733 2015 Freightliner Cascadia 125 6x4 T/A Day DOCUMENT SECTION BELOW SUPPLIED Cab Truck Tractor (Inoperable) Asset located in: Humble, TX S/N: 3AKJGED50FDGH0450 9732B 2018 Freightliner Cascadia 125 6x4 T/A Day C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, 2014 US EPA Label, Requires Diesel Cab Truck Tractor (Inoperable) Exhaust Fluid, Engine Brake, Eaton Fuller FO-S/N: 3AKJGEDV9JDJH2317 C/W: Detroit DD13 6 Cylinder 12.8 L 435 hp 18E313A MHP 13-Speed Automated Engine, 2018 US EPA Label, Requires Diesel Transmission, Meritor RT-46-160 Drive Axles, 3.91:1 Axle Ratio, Air Ride Cab, Steel, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Exhaust Fluid, Detroit DT12-OB-1550 HD 12-Speed Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.08:1 Axle Ratio, 52000 lb Usage: 527,704 Mi GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Notes: THIS INOPERABLE ITEM NEEDS TO BE Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED Usage: 327,535 Mi PLEASE SEE THE INSPECTION REPORT Notes: BUYER'S RESPONSIBILITY FOR Asset located in: Humble, TX REMOVAL OF THIS ITEM; SELLER

MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED

			1 ugo 12 1 01 13 /
Lot #	Details	Lot #	Details
9734	2015 Freightliner Cascadia125 6x2 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKGGEDVXFSGK3419 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 410 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 2.50:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 275/80R22.5 Front Tires, 295/75R22. 5 Rear Tires, Airliner Air Ride Suspension, 175 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED EQUIPMENT-FROM-YELLOW-CORP; LOCATED-IN-HUMBLE-TX-TX	9736	2013 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1FUJGEDV1DLBV2601 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X4 Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 195 in Wheelbase, Dual Fuel Tanks Usage: 588,339 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Asset located in: Humble, TX
9735A	Asset located in: Humble, TX 2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGEDVXFSGB7394 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, 4583 Engine hrs, Engine Brake, Eaton Fuller Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 178 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 494,093 Mi Notes: BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; SELLER MAINTENANCE RECORD ATTACHED IN THE DOCUMENT SECTION BELOW SUPPLIED Asset located in: Humble, TX	9737	Cab Truck Tractor (Inoperable) S/N: 1FUJGEBG1DSBY0263 C/W: Cummins ISX15 6 Cylinder 15.0 L Ultra Low Sulfur Diesel 450 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-15210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 3.55:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 183 in Wheelbase, PTO, Wet Kit, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9735	2015 Freightliner Cascadia 125 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3AKJGEDV8FDGN8552 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 450 hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 180 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Cab Truck Tractor (Inoperable) S/N: 1FUJGEDR2BSBD8644 C/W: Detroit DD15 6 Cylinder 14.8 L Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller FRO-15210C 10- Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.73:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Airliner Suspension, 188 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-HOUSTON-TX DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

		•	
Lot #	Details	Lot #	Details
9739	2015 Volvo VNL300 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 4V4NC9EH8FN189707 C/W: Volvo D13J435 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 435 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid, Volvo ATO2612D 12-Speed Automated Transmission, 12350 lb Front Axle, 38000 lb Rears, Meritor MT-40-14X Drive Axles, 3.25:1 Axle Ratio, 50350 lb GVWR, Air Ride Cab, Aluminum Wheels, Air Ride Suspension, 196 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	9742	2014 International ProStar 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR4EN013860 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 181 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9743	2012 International ProStar+ 122 6x4 T/A Day
9740	2014 International ProStar 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR1EN013864 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 275/80R22.5 Rear Tires, Hendrickson Air Ride Suspension, 184 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Cab Truck Tractor (Inoperable) S/N: 1HSDJSJR7CJ660470 C/W: International Maxxforce 6 Cylinder Ultra Low Sulfur Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Ride Suspension, 212 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED ** Title Remarks: DIESEL** **Title will be accompanied by a Repossession Affidavit and may not be accepted in your state. Please check with your local licensing agency** Asset located in: Humble, TX
9741	2014 International Prostar 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR8EN013862 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10- Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 181 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9744	2009 Peterbilt 388 6x4 T/A Day Cab Truck Tractor (Inoperable) S/N: 1XPWDU9X09D784934 C/W: Cat C13 6 Cylinder 12.5 L Diesel Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Wheels, 11R24.5, Air Trac Air Ride Suspension, 222 mm Wheelbase, PTO, Wet Kit, Air Sliding 5th Wheel, Headache Rack Usage: 304,207 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Details Lot# **Details** Lot # 9745 2007 Peterbilt 386 6x4 T/A Day Cab Truck 9747 2002 Volvo VNM 6x4 T/A Day Cab Truck Tractor (Inoperable) Tractor (Inoperable) S/N: 1XPHD49X87N733035 S/N: 4V4MC9RF92N324708 C/W: Cummins 6 Cylinder Ultra Low Sulfur C/W: Detroit Series 60 6 Cylinder 12.7 L Diesel 350 hp Engine, 2001 US EPA Label, Eaton Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 12000 lb Front Fuller 7-Speed Manual Transmission, 12000 lb Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Front Axle, 40000 lb Rears, Planetary Drive Cab, Aluminum Front Wheels, 11R22.5, Low Axles, 2.93:1 Axle Ratio, 52000 lb GVWR, 295 Low Air Leaf Air Ride Suspension, 194 in Wheelbase, PTO, Air Sliding 5th Wheel, Blower, /75R22.5, VOLVO Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP **Dual Fuel Tanks** Usage: 325,030 Mi Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE Notes: LOCATED-IN-LIVINGSTON_LA; REMOVED FROM THE YARD AND CAN NOT BE SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED RECONSIGNED FROM THE YARD AND CAN NOT BE Asset located in: Humble, TX RECONSIGNED BUYER RESPONSIBLE FOR 9746A 2009 Volvo VNM200 6x4 T/A Day Cab Truck REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION Tractor (Inoperable) REPORT S/N: 4V4MC9EG09N283684 C/W: Volvo D13 6 Cylinder Diesel Engine, Asset located in: Livingston, LA Engine Brake, Eaton Fuller FR-14210B 10-9748 2007 International 9400i 6x4 T/A Day Cab Speed Manual Transmission, 12000 lb Front Axle, 37478 lb Rears, 49478.0 lb GVWR, 275 Truck Tractor (Inoperable) /80R22.5 Front Tires, 275/80R22.5 Rear Tires, S/N: 2HSCNAPR37C562767 Volvo 4-Bag Air Ride Suspension, 165 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel C/W: Cummins 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, 13220 lb Front Axle, 40000 lb Tanks Rears, Planetary Drive Axles, 53220 lb GVWR, Usage: 1,125,769 Mi 11R24.5, Air Ride Suspension, 206 in Notes: CANNOT VERIFY ODOMETER READING-Wheelbase, PTO, Air Sliding 5th Wheel, Dual VEHICLE IS EXEMPT FROM MILEAGE Fuel Tanks DISCLOSURE; EQUIPMENT-FROM-YELLOW-Usage: Not Available CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS Asset located in: Humble, TX INOPERABLE ITEM NEEDS TO BE REMOVED 9746 2008 Kenworth T800 6x4 T/A Day Cab Truck FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -Tractor (Inoperable) PLEASE SEE THE INSPECTION REPORT S/N: 1XKDDU9X78J228696 C/W: Cat C13 6 Cylinder 7.2 L Ultra Low Sulfur Asset located in: Livingston, LA Diesel 350 hp Engine, 2006 US EPA Label, 9749 2015 Western Star 4900SA 6x4 T/A Sleeper Engine Brake, Eaton Fuller FRO-14210C 10-Truck Tractor (Inoperable) Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, Meritor RT-40-145 Drive S/N: 5KJJALD13FPGB7643 C/W: Detroit DD16 6 Cylinder 15.6 L Diesel 600 hp Engine, 2014 US EPA Label, CARB Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 11R22.5, Air Ride Suspension, 188 in Compliant, 13672 Engine hrs, Engine Brake, Eaton Fuller RTLO-1891 13-Speed Manual Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE

Transmission, Differential Lock, 16000 lb Front Axle, 46000 lb Rears, 3.73:1 Axle Ratio, 62000 Ib GVWR, Air Ride Cab, 36 in Flat Top Sleeper Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 11R22.5 Rear Tires, Airliner Air Ride Suspension, 210 in Wheelbase, Dual Fuel Tanks Usage: 13,672 Hr

Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

REMOVED FROM THE YARD AND CAN NOT BE

RECONSIGNED DEFICIENCIES NOTED

Asset located in: Humble, TX

PLEASE SEE THE INSPECTION REPORT

Lot #	Details	Lot #	Details
9750	2013 Kenworth T800 8x4 Tri/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDP7EX4DJ353826 C/W: Cummins ISX12 6 Cylinder 11.9 L 425 hp Engine, 2012 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller RTLO- 16918B 18-Speed Manual Transmission, 19500 lb Front Axle, 60000 lb Rears, 4.89:1 Axle Ratio, 79500 lb GVWR, Air Ride Cab, 36 in Mid Roof Sleeper Cab, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Hendrickson Air Ride Suspension, 260 in Wheelbase, PTO, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE	9753	2007 Kenworth T800 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDDT9X17J198409 C/W: Cat C11 6 Cylinder 11.1 L Ultra Low Sulfur Diesel 385 hp Engine, 2006 US EPA Label, Eaton Fuller 10-Speed Manual Transmission, Meritor RT-44-145 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 36 in Flat Top Sleeper Cab, 11R22.5, Neway Air Ride Suspension, 200 in Wheelbase, PTO Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	RECONSIGNED Asset located in: Humble, TX	9754	2020 Kenworth T680 6x4 T/A Sleeper Truck Tractor (Inoperable)
9751	2012 Kenworth T800 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDD79X8CJ327697 C/W: Cummins 6 Cylinder Diesel Engine, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 44000 lb Rears, MP44-14x5 Drive Axles, 4.63:1 Axle Ratio, 56000 lb GVWR, 36 in Mid Roof Sleeper Cab, 11R22.5, Hendrickson Air Ride Suspension, 204 in Wheelbase, Headache Rack Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 1XKYD49X2LJ388379 C/W: Cummins X15 6 Cylinder 15 L Diesel 450 hp Engine, 2019 US EPA Label, Requires Diesel Exhaust Fluid, 24479. Engine hrs, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5, Air Ride Suspension, 232 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: 614,194 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9752	2012 Kenworth T800 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 1XKDD79X7CJ315203 C/W: Cummins ISX11.9 350V 6 Cylinder 11.9 L Diesel 350 hp Engine, 2011 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller 10-Speed Manual Transmission, Double Differential Locks, 12000 lb Front Axle, 44000 lb Rears, 56000 lb GVWR, Air Ride Cab, 28 in Flat Top Sleeper Cab, 11R22.5, Neway Air Ride Suspension, 198 in Wheelbase, Air Sliding 5th Wheel, Headache Rack Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9755	2023 Freightliner Cascadia 126 6x4 T/A Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR6PSNH6231 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel hp Engine, 2022 US EPA Label, Requires Die Exhaust Fluid, Engine Brake, Detroit DT12-1 OH 12-Speed Automated Transmission, 13: lb Front Axle, 40000 lb Rears, 3.08:1 Axle R: 53300 lb GVWR, Air Ride Cab, 58 in High Ris Sleeper Cab, Bunk Beds, Bunk Heater, Elect Sleeper Air Conditioner, Aluminum Wheels, /75R22.5, Airliner Air Ride Suspension, 235 Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO REMOVED FROM THE YARD AND CAN NOT RECONSIGNED Asset located in: Humble, TX

Details Lot# **Details** Lot # 9756 2021 Freightliner Cascadia 126 6x4 T/A 9759 2018 Kenworth T680 6x4 T/A Sleeper Truck Sleeper Truck Tractor (Inoperable) Tractor (Inoperable) S/N: 1XKYDP9X4JJ211637 S/N: 3AKJHHDR0MSMA8077 C/W: 13300 lb Front Axle, 40000 lb Rears, 3.08: 1 Axle Ratio, 53300 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295 C/W: Paccar 6 Cylinder Ultra Low Sulfur Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FO-16E313A-MHP /75R22.5, Airliner Air Ride Suspension, 235 in ULT Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Axles, 3.08:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 62 in High Rise Sleeper Cab, Aluminum Wheels, 275/80R22.5 Front Tires, Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE 295/75R22.5 Rear Tires, Paccar Air Ride REMOVED FROM THE YARD AND CAN NOT BE Suspension, 236 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks RECONSIGNED DEFICIENCIES NOTED PLEASE SEE THE INSPECTION REPORT Usage: Not Available Asset located in: Humble, TX Notes: THIS INOPERABLE ITEM NEEDs TO BE 9757 2020 Freightliner Cascadia 126 6x4 T/A REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-MIDLAND-TX Sleeper Truck Tractor (Inoperable) S/N: 3AKJHHDR7LSLJ3051 Asset located in: Midland, TX C/W: Detroit DD15 6 Cylinder 14.5 L 455 hp 9760 2016 Kenworth T680 6x4 T/A Sleeper Truck Engine, 2020 US EPA Label, Requires Diesel Tractor (Inoperable) Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 13200 lb Front Axle, 40000 lb Rears, Meritor DA-RT-40.0-4S Drive Axles, 3.23:1 Axle Ratio, S/N: 1XKYDP9X1GJ115635 C/W: 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, 72 in High Rise 53200 lb GVWR, Air Ride Cab, 60 in High Rise Sleeper Cab, Bunk Beds, 295/75R22.5, Air Ride Suspension, 241 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Sleeper Cab, Bunk Beds, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 227 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available Tanks Notes: LOCATED-IN-FORT-WORTH-TX THIS Usage: 594,374 Mi INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE REMOVED FROM THE YARD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR RELISTED; BUYER'S RESPONSIBILITY FOR RFMOVAL REMOVAL DEFICIENCIES NOTED - PLEASE SEE Asset located in: Lake Worth, TX THE INSPECTION REPORT 9761A 2017 Freightliner Cascadia 125 6x4 T/A Asset located in: Humble, TX Sleeper Truck Tractor 9758 2019 Freightliner Cascadia 126 6x4 T/A S/N: 3AKJGLDR5HDHU1687 Sleeper Truck Tractor (Inoperable) C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 S/N: 3AKJHHDRXKSKM0577 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit DT12-OA-1650 12-Speed C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 505 hp Engine, Requires Diesel Exhaust Fluid, Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb Engine Brake, Detroit DT12-1750-DH1 12-Speed Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, 4 Drive Axles, 2.41:1 Axle Ratio, 53300 lb Air Sliding 5th Wheel, Dual Fuel Tanks GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22. Usage: 684,841 Mi 5, Airliner Air Ride Suspension, 235 in Wheelbase, Air Sliding 5th Wheel, Headache Notes: PENSKE-FLEET-MAINTAINED: SELLER SUPPLIED MAINTENANCE RECORD Rack, Dual Fuel Tanks ATTACHED IN THE DOCUMENT SECTION Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE Asset located in: Humble, TX REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED LOCATED-IN-FORT-WORTH-TX BUYER'S RESPONSIBILITY FOR REMOVAL OF

THIS ITEM, CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE

Asset located in: Lake Worth, TX

INSPECTION REPORT

Details Lot# **Details** Lot # 9761 2018 Freightliner Cascadia 125 6x4 T/A 9764 2016 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDR4JSJN7411 S/N: 3AKJGLD58GSHD2016 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2017 US EPA Label, Requires Diesel C/W: Detroit DD15 6 Cylinder 14.8 L Gasoline 455 hp Engine, 2015 US EPA Label, Requires Exhaust Fluid, Engine Brake, Detroit 12-Speed Diesel Exhaust Fluid, Detroit DT120A1750 Automated Transmission, 12350 lb Front Axle, Automated Transmission, 13300 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive 40000 lb Rears, 52350.0 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, 295/75R22.5 Front Tires, Axles, 3.08:1 Axle Ratio, 55300 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk 445/50R22.5 Super Singles Rear Tires, Airliner Beds, Bunk Heater, Aluminum Wheels, 11R22. Air Ride Suspension, 230 in Wheelbase, Air 5, Airliner Air Ride Suspension, 228 in Sliding 5th Wheel, Dual Fuel Tanks Wheelbase, Air Sliding 5th Wheel, Dual Fuel Usage: Not Available Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION PLEASE SEE THE INSPECTION REPORT **REPORT** Asset located in: Humble, TX Asset located in: Humble, TX 9765 2016 Freightliner Cascadia 125 6x4 T/A 9762A 2017 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 1FUJGLD5XGLGU2219 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 S/N: 3AKJGLDR8HSJG4013 hp Engine, 2015 US EPA Label, Requires Diesel C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 hp Engine, Requires Diesel Exhaust Fluid, Exhaust Fluid, 24994 Engine hrs, Engine Brake, Engine Brake, Detroit DT-12-0A-1650 12-Speed Automated Transmission, 13220 lb Front Axle, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, Differential Lock, 12350 lb Front Axle, 40000 lb Rears, Planetary Drive Axles, 2.53:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 40000 lb Rears, 3.08:1 Axle Ratio, 53220 lb GVWR, Air Ride Cab, 70 in High Rise Sleeper Cab, Bunk Beds, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th 60 in High Rise Sleeper Cab, Bunk Beds, Aluminum Wheels, MIXED, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Wheel, Dual Fuel Tanks Usage: 518,301 Mi Usage: 730,665 Mi Notes: PENSKE-FLEET-MAINTAINED; SELLER Notes: LOCATED-IN-LIVINGSTON_LA SUPPLIED MAINTENANCE RECORD SUBJECT TO LOUISIANA SALES TAX. THIS ATTACHED IN THE DOCUMENT SECTION INOPERABLE ITEM NEEDS TO BE REMOVED **BELOW** FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR Asset located in: Humble, TX REMOVAL OF THIS ITEM DEFICIENCIES 2017 Freightliner Cascadia 125 6x4 T/A 9762 NOTED - PLEASE SEE THE INSPECTION Sleeper Truck Tractor (Inoperable) REPORT S/N: 3AKJGLDR1HSGV7961 Asset located in: Livingston, LA C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 400 9766 2016 Freightliner Cascadia 125 6x4 T/A hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, 12500 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 72 in High Rise Sleeper Cab, Bunk Beds, Aluminum Rear Sleeper Truck Tractor (Inoperable) S/N: 3AKJGLDV4GSHD4846 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 Wheels, 295/75R22.5 Front Tires, 445/50R22.5 hp Engine, Requires Diesel Exhaust Fluid, Super Singles Rear Tires, Airliner Air Ride

S/N: 3AKJGLDV4GSHD4846 C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 435 hp Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 12500 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 2.64:1 Axle Ratio, 52500 lb GVWR, Air Ride Cab, 72 in Mid Roof Sleeper Cab, Aluminum Wheels, 295 /75R22.5, Airliner Air Ride Suspension, 234 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks

Usage: Not Available

Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Dual Fuel Tanks Usage: Not Available

Notes: LOCATED-IN-FORT-WORTH-TX THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING

Asset located in: Lake Worth, TX

Page 430 of 457 **Details** Lot# **Details** Lot # 9767 2016 Freightliner Cascadia 125 6x4 T/A 9770 2014 Freightliner Cascadia 125 6x4 T/A Sleeper Truck Tractor (Inoperable) Sleeper Truck Tractor (Inoperable) S/N: 1FUJGLDR4GLGV6507 S/N: 3AKJGLD52ESFW7646 C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 475 hp Engine, 2013 US EPA Label, Requires Diesel C/W: Detroit DD15 6 Cylinder 14.8 L 400 hp Engine, Requires Diesel Exhaust Fluid, 19718 Engine hrs, Engine Brake, Detroit 12-Speed Exhaust Fluid, Eaton Fuller 13-Speed Manual Automated Transmission, 12000 lb Front Axle, Transmission, 12000 lb Front Axle, 40000 lb 40000 lb Rears, Meritor MT-40-14X Drive Axles, Rears, 52500 lb GVWR, Air Ride Cab, 72 in High 2.47:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, Rise Sleeper Cab, Sleeper Air Conditioner, Auxiliary Power Unit, Aluminum Outer Wheels, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, 48 in Mid Roof Sleeper Cab, Aluminum Wheels, 295/75R22.5, Airliner Air Ride Suspension, 199 in Wheelbase, Dual Fuel Tanks Airliner Air Ride Suspension, 230 in Wheelbase, Air Sliding 5th Wheel, Headache Rack, Lowboy Usage: 634,624 Mi Ramps, Dual Fuel Tanks Notes: DEFICIENCIES NOTED - PLEASE SEE Usage: Not Available THE INSPECTION REPORT Notes: THIS INOPERABLE ITEM NEEDs TO BE Asset located in: Humble, TX REMOVED FROM THE YARD AND CAN NOT BE 2016 Freightliner Cascadia 125 6x4 T/A 9768 RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE Sleeper Truck Tractor (Inoperable) RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE S/N: 3AKJGLD5XGSHJ8963 C/W: Detroit DD15 6 Cylinder 14.8 L 455 hp THE INSPECTION REPORT Engine, Requires Diesel Exhaust Fluid, Engine Brake, Detroit 12-Speed Automated Transmission, 13220 lb Front Axle, 40000 lb Rears, Detroit DA-RT-40.0-4 Drive Axles, 2.53:1 Asset located in: Humble, TX 2016 International ProStar 6x4 T/A Sleeper 9771A Truck Tractor (Inoperable) Axle Ratio, 53220 lb GVWR, Air Ride Cab, High Rise Sleeper Cab, Bunk Beds, Aluminum Front S/N: 3HSDJAPR9GN411978 C/W: Cummins ISX15 6 Cylinder 15.0 L Diesel 400 hp Engine, 2015 US EPA Label, Requires Wheels, 11R22.5, Airliner Air Ride Suspension, 228 in Wheelbase, Air Sliding 5th Wheel, Dual Diesel Exhaust Fluid, Engine Brake, Automated **Fuel Tanks** Transmission, 12350 lb Front Axle, 40000 lb Usage: 696,122 Mi Rears, 52350 lb GVWR, Air Ride Cab, 72 in High Asset located in: Humble, TX Rise Sleeper Cab, Bunk Beds, Aluminum 9769 2015 Freightliner Cascadia 125 6x4 T/A Wheels, 295/75R22.5, Air Ride Suspension, 226 in Wheelbase, Air Sliding 5th Wheel, Dual Sleeper Truck Tractor (Inoperable) **Fuel Tanks** S/N: 3AKJGLD52FSGR9064 Usage: 716,138 Mi C/W: Detroit DD15 6 Cylinder 14.8 L Diesel 455 Notes: DEFICIENCIES NOTED - PLEASE SEE hp Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, 16718 Engine hrs, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb THE INSPECTION REPORT Asset located in: Humble, TX 9771 2014 Freightliner Cascadia 125 6x4 T/A Rears, Detroit DA-RT-40.0-4 Drive Axles, 3.31:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 60 in Sleeper Truck Tractor (Inoperable) High Rise Sleeper Cab, Bunk Beds, Steel, 295

/75R22.5, Airliner Air Ride Suspension, 235 in

Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE

RECONSIGNED CPC HAS BEEN REMOVED

OFFICE DEFICIENCIES NOTED - PLEASE SEE

FROM THIS TRUCK AND STORED IN THE

Wheelbase, Dual Fuel Tanks

THE INSPECTION REPORT

Asset located in: Humble, TX

Usage: 947.610 Mi

S/N: 3AKJGLDVXESFW0380 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRW-15210B 10-Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, Meritor MT-40-14X Drive Axles, 2.64:1 Axle Ratio, 52000 lb GVWR, Air Ride Cab, 70 in Mid Roof Sleeper Cab, Aluminum Wheels, 275/80R22.5, Airliner Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks Usage: Not Available

Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED

Details Lot# **Details** Lot # 9772A 2001 Peterbilt 378 6x4 T/A Day Cab Truck 9774 2022 Peterbilt 579 4x2 S/A Day Cab Truck Tractor (Inoperable) Tractor (Inoperable) S/N: 1XPFDT9X41D558779 S/N: 1XPBAP8X8ND759395 C/W: Cat C10 6 Cylinder 10.3 L Diesel 370 hp Engine, 2000 US EPA Label, Engine Brake, C/W: Paccar MX-13 6 Cylinder 12.9 L 405 hp Engine, 2021 US EPA Label, Requires Diesel Eaton Fuller Manual Transmission, 12000 lb Exhaust Fluid, Engine Brake, Automated Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Transmission, 12000 lb Front Axle, 22700 lb Ride Cab, 36 in Flat Top Sleeper Cab, Rears, 34700 lb GVWR, Air Ride Cab, 275 Aluminum Outer Wheels, 11R24.5, Air Ride /80R22.5, Air Trac Air Ride Suspension, 155 in Suspension, 230 in Wheelbase, Headache Rack Wheelbase, Dual Fuel Tanks, EQUIPMENT-Usage: 246,390 Mi FROM-YELLOW-CORP Usage: 205,979 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE Asset located in: Humble, TX RECONSIGNED EQUIPMENT-FROM-YELLOW-9772 2018 International LT625 6x4 T/A Sleeper CORP; DEFICIENCIES NOTED - PLEASE SEE INSPECTION REPORT DEFICIENCIES NOTED -Truck Tractor (Inoperable) PLEASE SEE THE INSPECTION REPORT S/N: 3HSDZAPR3JN566574 C/W: Cummins X15 6 Cylinder 15.0 L Diesel 450 hp Engine, 2017 US EPA Label, Requires Asset located in: Humble, TX 9775 2022 Peterbilt 579 4x2 S/A Day Cab Truck Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 13200 lb Front Axle, 40000 lb Tractor (Inoperable) Rears, 53200 lb GVWR, Air Ride Cab, 56 in Mid Roof Sleeper Cab, 295/75R22.5, Air Ride Suspension, 230 in Wheelbase, Dual Fuel Tanks S/N: 1XPBAP8X5ND759337 C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Sulfur Diesel 405 hp Engine, 2021 US EPA Usage: Not Available Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5, Air Trac Air Ride Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Suspension, 152 in Wheelbase, Dual Fuel Asset located in: Humble, TX Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available 9773A 1993 Freightliner FLD 120 6x4 T/A Day Cab Notes: THIS INOPERABLE ITEM NEEDS TO BE Truck Tractor (Inoperable) REMOVED FROM THE YARD AND CAN NOT BE S/N: 1FUPDCYB1PH491421 RECONSIGNED LOCATED-IN-FORT-WORTH-TX C/W: Cummins N14 6 Cylinder 14.0 L Diesel , LOCATED-IN-LAKE-WORTH-TX-HOU; 430 hp Engine, Rockwell 9-Speed Manual EOUIPMENT-FROM-YELLOW-CORP Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 192 in Asset located in: Lake Worth, TX 9776 2022 Volvo VNR 4x2 S/A Day Cab Truck Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tractor (Inoperable) Tanks Usage: Not Available S/N: 4V4W19EG2NN607677 C/W: Volvo D13N-405 6 Cylinder 12.8 L 405 hp Asset located in: Humble, TX Engine, 2021 US EPA Label, Requires Diesel 9773 2012 International Prostar 6x4 T/A Day Cab Exhaust Fluid, 4009 Engine hrs, Automated Transmission, 12000 lb Front Axle, 20000 lb Truck Tractor (Inoperable) Rears, 32000 lb GVWR, 295/75R22.5, Air Ride S/N: 1HSDJSJR3CJ562939 Suspension, 152 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP C/W: International MaxxForce 13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2011 US EPA Label, 13200 lb Front Axle, 40000 lb Rears, 53200 lb GVWR, Air Ride Cab, Aluminum Wheels, 315/80R22.5 Front Tires, 455/55R22.5 Usage: 142,422 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED . DEFICIENCIES NOTED Super Singles Rear Tires, Air Ride Suspension, 200 in Wheelbase, Air Sliding 5th Wheel, Dual PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE

RECONSIGNED

Details Lot# **Details** Lot # 2011 Peterbilt 337 4x2 S/A Day Cab Truck 9780A 2015 Freightliner Cascadia 125 4x2 S/A Day 9777 Tractor (Inoperable) Cab Truck Tractor (Inoperable) S/N: 1FUBGDDV6FLGP7106 C/W: Detroit DD13 6 Cylinder 12.8 L 410 hp S/N: 2XP2AN8X0BM126366 C/W: Paccar PX-8 6 Cylinder 8.3 L Ultra Low Sulfur Diesel 300 hp Engine, 2010 US EPA Engine, 2015 US EPA Label, Requires Diesel Label, Requires Diesel Exhaust Fluid, Allison Exhaust Fluid, Engine Brake, Eaton Fuller FO-14E310C-LAS Automated Transmission, 12000 3000 Automatic Transmission, 12000 kg Front Axle, 22700 lb Rears, 4.78:1 Axle Ratio, 34700 lb GVWR, 275/80R22.5, Air Trac Air Ride lb Front Axle, 23000 lb Rears, Meritor RS-23-161 Drive Axles, 3.58:1 Axle Ratio, 33000 lb Suspension, 160 in Wheelbase GVWR, Air Ride Cab, Aluminum Wheels, 11R22. Usage: Not Available 5, Airliner Air Ride Suspension, 190 in Wheelbase, Dual Fuel Tanks Notes: THIS INOPERABLE ITEM NEEDs TO BE Usage: 131,229 Mi REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Notes: .; SELLER SUPPLIED MAINTENANCE RECORD ATTACHED IN THE DOCUMENT Asset located in: Humble, TX SECTION BELOW DEFICIENCIES NOTED -9778 2018 Kenworth T680 4x2 S/A Day Cab Truck PLEASE SEE THE INSPECTION REPORT Tractor (Inoperable) Asset located in: Humble, TX S/N: 1XKYAP8X1JJ214313 9780 2015 Freightliner Cascadia 125 4x2 S/A Day C/W: Paccar MX-13 6 Cylinder 12.9 L Ultra Low Cab Truck Tractor (Inoperable) Sulfur Diesel 430 hp Engine, 2017 US EPA S/N: 1FUBGEDVXFLGH4646 Label, Requires Diesel Exhaust Fluid, Eaton FAOM15810S-EC3 Automated Transmission, 12350 lb Front Axle, 22700 lb Rears, Paccar RS23-161 Drive Axles, 2.80:1 Axle Ratio, 35050 C/W: 12000 lb Front Axle, 22700 lb Rears, 2.50: 1 Axle Ratio, 34700 lb GVWR, Air Ride Cab, 295 /75R22.5, Airliner Air Ride Suspension, 158 in lb GVWR, Air Ride Cab, 295/75R22.5, Wheelbase, Air Sliding 5th Wheel, Dual Fuel Hendrickson HAS Air Ride Suspension, 154 in **Tanks** Wheelbase, Dual Fuel Tanks, EQUIPMENT-Usage: Not Available FROM-YELLOW-CORP Notes: LOCATED-IN-FORT-WORTH-TX THIS Usage: 47,939 Mi INOPERABLE ITEM NEEDS TO BE REMOVED Notes: THIS INOPERABLE ITEM NEEDs TO BE FROM THE YARD AND CAN NOT BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED . DEFICIENCIES NOTED -RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE PLEASE SEE THE INSPECTION REPORT RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL Asset located in: Humble, TX Asset located in: Lake Worth, TX 9779A 2015 Mack CXU613 6x4 T/A Day Cab Truck 9781 2016 Freightliner Cascadia 113 6x4 T/A Day Tractor (Inoperable) Cab Truck Tractor (Inoperable) S/N: 1M1AW07YXFM043941 C/W: Mack MP8 6 Cylinder Diesel Engine, S/N: 3AKJGBDV1GSGY0422 Requires Diesel Exhaust Fluid, Engine Brake, C/W: Detroit DD13 6 Cylinder 12.8 L Diesel 470 Mack Automated Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, 11R22.5, Twin Y Air Ride Suspension, 186 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Eaton Fuller FRO-16210C 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, Meritor RT-40-145 Drive Axles, 3.42:1 Axle Ratio, 52350 lb in Wheelbase, PTO, Air Sliding 5th Wheel, Blower GVWR, Air Ride Cab, 11R22.5, Airliner Air Ride Suspension, 186 in Wheelbase Usage: 368,419 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE Usage: Not Available THE INSPECTION REPORT Notes: THIS INOPERABLE ITEM NEEDs TO BE Asset located in: Humble, TX REMOVED FROM THE YARD AND CAN NOT BE 9779 RECONSIGNED DEFICIENCIES NOTED -2014 Kenworth T680 4x2 S/A Day Cab Truck Tractor (Inoperable) PLEASE SEE THE INSPECTION REPORT S/N: 1XKYA48X7EJ402449 Asset located in: Humble, TX C/W: 12000 lb Front Axle, 22700 lb Rears, 34700 lb GVWR, Air Ride Cab, 295/75R22.5 Front Tires, 455/55R22.5 Super Singles Rear Tires, Air Ride Suspension, 161 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: LOCATED-IN-FORT-WORTH-TX THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE

RECONSIGNED INOPERABLE ITEM MUST BE REMOVED FROM THE YARD AND CANNOT BE RELISTED; BUYER'S RESPONSIBILITY FOR REMOVAL DEFICIENCIES NOTED - PLEASE SEE

THE INSPECTION REPORT

Asset located in: Lake Worth, TX

Details 2014 Freightliner Cascadia 113 4x2 S/A Day	Lot #	Details
	0705	
Cab Truck Tractor (Inoperable) S/N: 1FUBGADV7ELFR1039 C/W: Detroit DD13 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 500 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 2.67:1 Axle Ratio, Air Ride Cab, 275/80R22.5 Front Tires, MIXED Rear Tires, Airliner Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 810,762 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9785	2009 Volvo VNM200 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 4V4M19EG39N263824 C/W: Volvo D13 6 Cylinder 12.8 L Diesel Engine, 2008 US EPA Label, Engine Brake, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 158 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 1,257,903 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED CANNOT VERIFY ODOMETER READING-VEHICLE IS EXEMPT FROM MILEAGE DISCLOSURE; EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	9786	2002 Volvo VNM 4x2 S/A Day Cab Truck
Truck Tractor (Inoperable) S/N: 3HSDJSNR3EN013865 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Hendrickson Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED		Tractor (Inoperable) S/N: 4V4M19RF32N324628 C/W: Detroit Series 60 6 Cylinder 12.7 L Ultra Low Sulfur Diesel 470 hp Engine, 2001 US EPA Label, Eaton Fuller T-14607A 7-Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 2.93:1 Axle Ratio, 32000 lb GVWR, 275 /80R22.5, Volvo Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks, EQUIPMENT- FROM-YELLOW-CORP Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
2014 International 4400 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HCMKAAN6EL034677 C/W: 6 Cylinder Engine, 2013 US EPA Label, 8836 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 322,649 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	-9787	2001 Volvo VNM200 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 4V4M19RF81N306642 C/W: Detroit Series 60 6 Cylinder 12.7 L Ultra Low Sulfur Diesel 350 hp Engine, 2000 US EPA Label, Eaton Fuller T-14607A 7-Speed Manual Transmission, 12000 lb Front Axle, 19000 lb Rears, 3.07:1 Axle Ratio, 32000 lb GVWR, 275 /80R22.5, Air Ride Suspension, 154 in Wheelbase, Dual Fuel Tanks Usage: 791,634 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 2.67:1 Axle Ratio, Air Ride Cab, 275/80R22.5 Front Tires, MIXED Rear Tires, Airliner Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 810,762 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; EQUIPMENT-FROM-YELLOW-CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 International ProStar 6x4 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR3EN013865 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Hendrickson Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2014 International 4400 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HCMKAAN6EL034677 C/W: 6 Cylinder Engine, 2013 US EPA Label, 8836 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 322,649 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	Label, Requires Diesel Exhaust Fluid, Eaton Fuller FR-14210B 10-Speed Manual Transmission, 12000 lb Front Axle, 23000 lb Rears, Meritor RS23 Drive Axles, 2.67:1 Axle Ratio, Air Ride Cab, 275/80R22.5 Front Tires, MIXED Rear Tires, Airliner Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 810,762 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2014 International ProStar 6x4 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HSDJSNR3EN013865 C/W: Navistar N13 6 Cylinder 12.4 L Diesel 450 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller 10-Speed Manual Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GWWR, Air Ride Cab, 11R22.5 Front Tires, 295/75R22.5 Rear Tires, Hendrickson Air Ride Suspension, 182 in Wheelbase, Air Sliding 5th Wheel, Dual Fuel Tanks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2014 International 4400 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 3HCMKAANGEL034677 C/W: 6 Cylinder Engine, 2013 US EPA Label, 8836 Engine hrs, Allison Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GWWR, Air Ride Cab, 295 /75R22.5, Air Ride Suspension, 156 in Wheelbase, Dual Fuel Tanks Usage: 322,649 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

			1 age 454 01 457
Lot #	Details	Lot #	Details
9788	2002 International 9200i 4x2 S/A Day Cab Truck Tractor (Inoperable) S/N: 2HSCDAHN32C043192 C/W: 6 Cylinder Diesel Engine, Meritor 10- Speed Manual Transmission, 12000 lb Front Axle, 20000 lb Rears, 32000 lb GVWR, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, Air Ride Suspension, 160 in Wheelbase, Dual Fuel Tanks, EQUIPMENT-FROM-YELLOW-CORP Usage: 938,610 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9793	2007 International 7500 6x4 T/A Dump Truck (Inoperable) S/N: 1HTWNAZR17J519696 C/W: International DH330 6 Cylinder 9.3 L 330 hp Engine, 2006 US EPA Label, Eaton Fuller 10 Speed Manual Transmission, 12000 lb Front Axle, 40000 lb Rears, 52000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 11R22.5, Hendrickson Haulmaax Suspension, 196 in Wheelbase, PTO, OX Bodies 15 ft Long x 4 ft 8 in High Steel Body, Round Bottom, Electric Roll Tarp, Pintle Hitch Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE
9790	2005 Ottawa TY30 4x2 Spotter Truck		RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM
9791	(Inoperable) S/N: 311154 C/W: Allison Automatic Transmission, 275 /80R22.5 Front Tires, 295/75R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 1994 Ottawa 4x2 Spotter Truck (Inoperable) S/N: 1T9AA12S94A070507 C/W: 6 Cylinder Engine, Automatic Transmission, 295/75R22.5 Front Tires, 275 /80R22.5 Rear Tires, 112 in Wheelbase, Hydraulic Lift 5th Wheel Usage: Not Available	9794	2010 International 7400 6x4 Crew Cab T/A Dump Truck (Inoperable) S/N: 1HTWGAAR4AJ289665 C/W: International MaxxForce DT 6 Cylinder 7.6 L Diesel Engine, Allison Automatic Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb GVWR, 11R22.5, Hendrickson Spring over Walking Beam Suspension, 238 in Wheelbase, PTO, Martin 10 ft Long x 0 ft 48 in High Body, 10 cyd, Capacity, Pintle Hitch Usage: 91,700 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
R	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE		Asset located in: Humble, TX
	RECONSIGNED Asset located in: Humble, TX	9795	25 2012 International 4300 4x2 Flatbed Dump Truck (Inoperable)
9792	2018 Mack GU713 8x4 Tri/A Dump Truck (Inoperable) S/N: 1M2AX07C1JM037841 C/W: Mack MP8 6 Cylinder 12.8 L Ultra Low Sulfur Diesel 455 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust Fluid, Engine Brake, Automated Transmission, 20000 lb Front Axle, 44000 lb Rears, 64000 lb GVWR, Aluminum Wheels, 385/65R22.5 Front Tires, 11R24.5 Rear Tires, Air Lift Pusher Axle, Spring Suspension, 200 in Wheelbase, PTO, 16 ft Long x 5 ft 1 in High Steel Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 3HAMMAAL1CL629628 C/W: International MaxxForce DT 7.6 L Diesel Engine, 8400 Engine hrs, Eaton Fuller Automated Transmission, 10000 lb Front Axle, 19000 lb Rears, 25999 lb GVWR, Air Ride Cab, 11R22.5, Air Ride Suspension, 238 in Wheelbase, 20 ft 6 in Long x 5 in High Steel Body, Flat Bed Usage: 256,752 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		I	

Lot #	Details	Lot #	Details
9796	2005 Peterbilt 330 4x2 Flatbed Truck (Inoperable) S/N: 2NPNHD7X45M848006 C/W: Cat C7 6 Cylinder 7.2 L Ultra Low Sulfur Diesel 350 hp Engine, 2004 US EPA Label, 1480 Engine hrs, Manual Transmission, 12000 lb Front Axle, 21000 lb Rears, 4.88:1 Axle Ratio, 33000 lb GVWR, Aluminum Outer Wheels, 295 /75R22.5, Low Air Leaf Air Ride Suspension, 178 in Wheelbase, 12 ft 2 in x 96 in Bed Usage: 333,409 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	9801	2020 Chevrolet Silverado 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1HTKJPVK7LH869504 C/W: V8 Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7500 lb Front Axle, 13500 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 199 in Wheelbase, 11 ft 4 in x 88 in Bed Usage: 193,499 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9802	2019 Ford F-550 XL 4x4 Crew Cab Flatbed
9797	1999 Freightliner FL70 4x2 Flatbed Truck (Inoperable) S/N: 1FV3HJAC6XHB77403 C/W: Cat 6 Cylinder Diesel Engine, Manual Transmission, 8000 lb Front Axle, 19000 lb Rears, 26000 lb GVWR, 48 in Flat Top Sleeper Cab, 11R22.5, Airliner Air Ride Suspension, 304 in Wheelbase, PTO, 25 ft x 102 in Bed, Winch Usage: 591,906 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Truck (Inoperable) S/N: 1FD0W5HT1KEC07475 C/W: V8 6.7 L Diesel 330 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 6500 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 203 in Wheelbase, 11 ft 2 in x 94 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9798	1992 Ford F-700 4x2 Flatbed Truck (Inoperable)	1	Asset located in: Humble, TX
27.50	S/N: 1FDNK74P5NVA36675 C/W: 10R22.5, Spring Suspension, 228 in Wheelbase, 20 ft x 92 in Bed, Pintle Hitch Usage: 35,992 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9803	2016 Ford F-550 XL 4x4 Extended Cab Flatbed Truck (Inoperable) S/N: 1FD0X5HT2GEB56704 C/W: Ford 6.7 L Diesel 300 hp Engine, 2016 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 14706 lb Rears, 19500 lb GVWR, 225/70R19.5, Spring Suspension, 186 in Wheelbase, 11 ft 4 in x 92 in Bed
9799A	2001 Ford F-650 XL 4x2 Flatbed Truck (Inoperable) S/N: 3FDWF65H51MA77466 C/W: Cat 6 Cylinder Diesel Engine, Manual Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295/75R22.5 Front		Usage: 277,617 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2017 Ford F-450 XL 4x4 Crew Cab Flatbed
	Tires, 10R22.5 Rear Tires, Spring Suspension, 176 in Wheelbase, 12 ft x 92 in Bed Usage: 86,528 Mi Asset located in: Humble, TX		Truck (Inoperable) S/N: 1FD0W4HT4HED28150 C/W: Ford V8 6.7 L Diesel Engine, Requires Diesel Exhaust Fluid, Automatic Transmission, 7000 lb Front Axle, 12880 lb Rears, 16500 lb
9800	2006 Ford F-650 4x2 Flatbed Truck (Inoperable) S/N: 3FRNF65FX6V331580 C/W: Cummins ISB 6 Cylinder 230 hp Engine, Automatic Transmission, 8500 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 10R22.5, Spring Suspension, 160 in Wheelbase, 11 ft x 96 in Bed, Pintle Hitch Usage: 127,777 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		GVWR, 225/70R19.5, Spring Suspension, 203 in Wheelbase Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9807	2017 Ford F-350 XL 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3G62HEB81111 C/W: Ford Power Stroke 6.2 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4700 lb Front Axle, 10040 lb Rears, 14000 lb GVWR, 245/75R17, Spring Suspension, 179 in Wheelbase, 9 ft 6 in x 96 in Bed, Receiver Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM	9812	2006 Chevrolet 3500 4x2 Crew Cab Flatbed Truck (Inoperable) S/N: 1GBJC33D56F219199 C/W: GM 6.6 L Diesel Engine, 2006 US EPA Label, Automatic Transmission, Dual Rear Wheel, 215/85R16, Spring Suspension, 166 in Wheelbase, 9 ft x 92 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX Liftmoore L-21 2000 lb on 2008 Ford F-350 4x4
9808	Asset located in: Humble, TX 2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H61GEB16957 C/W: Ford 6.2 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase, 9 ft 2 in x 94 in Bed, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 235,308 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9814	Crew Cab Flatbed Truck with Crane (Inoperable) S/N: 1FTWW33R58EA12311 C/W: Ford 6.4 L Engine, 2008 US EPA Label, Automatic Transmission, 6000 lb Front Axle, 9000 lb Rears, 13000 lb GVWR, 245/75R17, Spring Suspension, 172 in Wheelbase, 2000 lb Capacity, Rear Mounted, 3 ft 8 in - 3 Section Boom, 8 ft 10 in x 92 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 1999 Ford F-350 4x2 Flatbed Truck (Inoperable)
9809	2016 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H63GEB16961 C/W: Ford 6.2 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase, 9 ft x 94 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED	9815	S/N: 1FDWF36FXXEB36540 C/W: 5-Speed Manual Transmission, 4850 lb Front Axle, 8600 lb Rears, 12500 lb GVWR, 235 /85R16, Spring Suspension, 165 in Wheelbase, 11 ft x 92 in Bed Usage: 241,719 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2011 Peterbilt 348 6x4 Vacuum Tanker Truck (Inoperable) S/N: 2NP3LN9X2BM129454
9810	2015 Ford F-350 XL 4x4 Crew Cab Flatbed Truck (Inoperable) S/N: 1FD8W3H66FEC97097 C/W: V8 6.2 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 5600 lb Front Axle, 9750 lb Rears, 14000 lb GVWR, 245 /75R17, Spring Suspension, 176 in Wheelbase, 9 ft x 94 in Bed, EQUIPMENT-FROM-PUMPCO- ENERGY-INFRASTRUCTURE Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		C/W: Paccar PX-8 8.3 L Diesel 330 hp Engine, Requires Diesel Exhaust Fluid, Eaton Fuller 9LL Transmission, 14600 lb Front Axle, 40000 lb Rears, 4.33:1 Axle Ratio, 54600 lb GVWR, Aluminum Front Wheels, 12R22.5 Front Tires, 11R22.5 Rear Tires, Air Trac Air Ride Suspension, 256 in Wheelbase, PTO Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED **Vacuum Tank Missing**, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9817	2002 Rebel on 2002 Kenworth T-800 8x6 Vacuum Tanker Truck (Inoperable) S/N: 1NKDXBEX92R967220 C/W: Cat C15 6 Cylinder Diesel 490 hp Engine, 13328 Engine hrs, Engine Brake, Eaton Fuller 8- Speed Manual Transmission, Triple Differential Locks, Aluminum Wheels, 445/65 R 22.5 Front Tires, 11R24.5 Rear Tires, Dual Steering Boxes, AG400 Air Ride Suspension, 285 in Wheelbase, Steel Debris Tank, Front Hose Reel, Hydraulic Lift Tailgate, Wash Down System, Manual Tailgate Locks, 17 ft Boom, 9 in Suction Hose, Cat Hydraulic Driven Pump, Blower, Cordless Remote Control Usage: Not Available Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE	9820	2005 Peterbilt 357 6x4 Roll-Off Truck (Inoperable) S/N: 1NPALU0X55D861506 C/W: 6 Cylinder Diesel Engine, Engine Brake, Eaton Fuller 8LL Manual Transmission, Differential Lock, 18740 lb Front Axle, 44000 lb Rears, 62740.0 lb GVWR, 11R22.5, Dual Steering Boxes, Double Frame, Hendrickson Spring over Walking Beam Suspension, 270 in Wheelbase, PTO, 2005 Galbreath U5-0R-174 Roll-Off Body, 23 ft 4 in Hoist Usage: 147,489 Mi Notes: LOCATED-IN-LIVINGSTON_LA; SUBJECT TO LOUISIANA SALES TAX. THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Livingston, LA
	RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES	9821	2006 MCI J4500 6x2 56-Seat Coach
9818	(Inoperable) S/N: 1NKDL70X7EJ394269 C/W: Cummins ISX12 6 Cylinder 11.9 L Ultra Low Sulfur Diesel 350 hp Engine, 2013 US EPA Label, Requires Diesel Exhaust Fluid, Eaton Fuller RTO-14909ALL 9LL Manual Transmission, 20000 lb Front Axle, 46000 lb	-	(Inoperable) S/N: 2M93JMPAX6W063474 C/W: Air Conditioner, Automatic Transmission, Lavatory, Detroit Diesel Engine, Aluminum Front Wheels, 315/80R22.5 Front Tires, 315 /80R22.5 Rear Tires, Air Ride Suspension, 340 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Rears, Meritor RT-46-160 Drive Axles, 4.89:1 Axle Ratio, 66000 lb GVWR, Air Ride Cab,	9822	2005 MCI J4500 6x2 56-Seat Coach
	Axle Ratio, 66000 lb GVWR, Air Ride Cab, Aluminum Front Wheels, 425/65R22.5 Front Tires, 11R22.5 Rear Tires, Dual Steering Boxes, Double Frame, Chalmers Rubber Suspension, 224 in Wheelbase, PTO, 3 Removable Chutes, Remote Control w/Cord Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		(Inoperable) S/N: 2M93JMDAX5W063011 C/W: Air Conditioner, Automatic Transmission, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Front Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 315 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9819	2007 Mack CV713 6x4 Rear Loader Waste	9823	2005 MCI J4500 6x2 56-Seat Coach
	Collection Truck (Inoperable) S/N: 1M2AG12CX7M055888 C/W: Mack 6 Cylinder Diesel Engine, Automatic Transmission, 20000 lb Front Axle, 46000 lb Rears, 66000 lb GVWR, Air Ride Cab, 315 /80R22.5, Hendrickson Haulmaax Rubber over Walking Beam Suspension, 250 in Wheelbase, PTO, Mc Neilus Collection Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		(Inoperable) S/N: 2M93JMDA15W063012 C/W: Air Conditioner, Automatic Transmission, Lavatory, Cat 6 Cylinder Diesel Engine, Aluminum Wheels, 315/80R22.5 Front Tires, 315/80R22.5 Rear Tires, Air Ride Suspension, 315 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

			1 ugc 430 01 437
Lot #	Details	Lot #	Details
9824	2006 BlueBird 4x2 School Bus (Inoperable) S/N: 1BABNCKA96F237961 C/W: Allison Automatic Transmission, Cat C7 6 Cylinder Diesel Engine, 11R22.5, Air Ride Suspension, 232 in Wheelbase Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9826	2005 International 4300 4x2 Van Truck (Inoperable) S/N: 1HTMMAAN05H118468 C/W: International DT466 6 Cylinder Diesel Engine, 2004 US EPA Label, 16696 Engine hrs, Manual Transmission, 275/80R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 95 in High Body, Curbside Door, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: 414,813 Mi
9825A	2015 Hino 268 4x2 Van Truck (Inoperable) S/N: 5PVNE8JV4F4S53629 C/W: Hino 6 Cylinder 7.7 L 220 hp Engine, 2014 US EPA Label, Requires Diesel Exhaust Fluid,		Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Automatic Transmission, 10000 lb Front Axle, 19000 lb Rears, 25950 lb GVWR, 11R22.5, Spring Suspension, 272 in Wheelbase, Morgan 26 ft x 102 in Wide x 103 in High Body, Liftgate Usage: 329,222 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9827A	1997 Ford E-350 Cargo Van (Inoperable) S/N: 1FTJS34F9VHB85401 C/W: Diesel Engine, Automatic Transmission, Air Conditioner Usage: 344,173 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9825	2019 Peterbilt 337 4x2 Van Truck (Inoperable)		Asset located in: Humble, TX
	S/N: 2NP2HM7X3KM497054 C/W: Paccar PX-7 6 Cylinder 6.7 L Ultra Low Sulfur Diesel 220 hp Engine, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Allison 2500 Automatic Transmission, 12000 lb Front Axle, 20000 lb Rears, Dana Spicer Drive Axles, 6.17:1 Axle Ratio, 32000 lb GVWR, 275/80R22. 5, Reyco Spring Suspension, 276 in Wheelbase, Wabash 26 ft x 102 in Wide x 90 in High Body, Liftgate, EQUIPMENT-FROM-YELLOW-CORP Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9827	2015 Ford F-750 4x2 Van Truck (Inoperable) S/N: 3FRNF7FA9FV745491 C/W: Ford 6.7 L Diesel Engine, 2015 US EPA Label, Requires Diesel Exhaust Fluid, Automatic Transmission, 10000 lb Front Axle, 21000 lb Rears, 26000 lb GVWR, 295/75R22.5 Front Tires, 295/75R22.5 Rear Tires, Spring Suspension, 281 in Wheelbase, 26 ft x 102 in Wide x 104 in High Body, Liftgate Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9826A	Asset located in: Humble, TX 2018 International 4300 4x2 Van Truck	9828	2017 Chevrolet Express 2500 4x2 Cargo Van
3020A	(Inoperable) S/N: 3HAMMML1JL003751 C/W: Cummins ISB 6 Cylinder 6.7 L Diesel 220 hp Engine, 2017 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, 7883 Engine hrs, Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 25999 lb GVWR, 11R22.5, Air Ride Suspension, 273 in Wheelbase, Supreme 26 ft x 102 in Wide x 100 in High Body, Liftgate Usage: 291,005 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		(Inoperable) S/N: 1GCWGAFF1H1142306 C/W: 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 74 in Wide x 52 in High Body, Curbside Door Usage: 175,542 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9829	2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGAFF8H1140875 C/W: V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 136 in Wheelbase, 6 ft x x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9832	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB8G1126637 C/W: V8 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x x 52 in High Body Usage: 173,702 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9830	2017 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGAFF1H1140622 C/W: GM 4.8 L Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9833	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB0G1150527 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 158 in Wheelbase, 6 ft x 72 in Wide x 53 in High Body Usage: 138,188 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9831A	2017 Chevrolet Express 2500 4x2 Cargo Van		Asset located in: Humble, TX
	(Inoperable) S/N: 1GCWGAFF8H1140410 C/W: GM 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 135 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 159,102 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB0G1148132 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 157,159 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9831	2017 Chevrolet Express 2500 4x2 Cargo Van		Asset located in: Humble, TX
	(Inoperable) S/N: 1GCWGAFF8H1143484 C/W: GM V8 4.8 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245 /75R16, Spring Suspension, 134 in Wheelbase, 6 ft x 73 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9835	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFBXG1126686 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: 169,399 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9836	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB3G1129798 C/W: GM 6.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 154 in Wheelbase, 6 ft x 72 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9841	2016 Ram Promaster 4x2 Cargo Van (Inoperable) S/N: 3C6TRVAG1GE114870 C/W: 3.6 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, 4629 lb Front Axle, 5291 lb Rears, 8550 lb GVWR, 225/75R16, Spring Suspension, 134 in Wheelbase, 10 ft x 78 in Wide x 66 in High Body, Curbside Door Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE
9837	2016 Chevrolet Express 2500 4x2 Cargo Van S/N: 1GCWGBFBXG1148025 C/W: Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 6 ft x x 52 in High Body Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9842	ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING; TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX 2009 Chevrolet 4500 4x2 Ambulance (Inoperable) S/N: 1GBKG316191158061 C/W: Automatic Transmission, 4600 lb Front Axle, 9600 lb Rears, 14200 lb GVWR, GM 6.6 L Ultra Low Sulfur Diesel 250 hp Engine, 2009 US
9838	2016 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGBFB4G1148828 C/W: Gasoline Engine, Automatic Transmission, 245/75R16, Spring Suspension, 152 in Wheelbase, 11 ft x 72 in Wide x 52 in High Body Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		EPA Label, Dual Rear Wheel, 225/75R16, Spring Suspension, 160 in Wheelbase, 14 ft Body Usage: Not Available Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2000 Ford E-350 4x2 Ambulance (Inoperable) S/N: 1FDWE35F5YHA30596 C/W: Automatic Transmission, 4600 lb Front
9839	Asset located in: Humble, TX 2015 Chevrolet Express 2500 4x2 Cargo Van (Inoperable) S/N: 1GCWGGCB8F1109093 C/W: GM 6.0 L Gasoline Engine, 2015 US EPA Label, Automatic Transmission, 4100 lb Front Axle, 5360 lb Rears, 8600 lb GVWR, 245/75R16, Spring Suspension, 156 in Wheelbase, 11 ft x 73 in Wide x 51 in High Body Usage: Not Available		Axle, 7500 lb Rears, 10700 lb GVWR, V8 Diesel Engine, 225/75R16, Spring Suspension, 138 in Wheelbase, 12 ft Body Usage: 27,320 Mi Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX 2011 International 4300SBA 4x2 Attenuator
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Truck (Inoperable) S/N: 1HTMMAAN2BH322958 C/W: International GDT255 6 Cylinder 7.6 L Diesel 255 hp Engine, 2009 US EPA Label, 8911
9840	2015 Chevrolet Express 2500 Cargo Van (Inoperable) S/N: 1GCWGGCB3F1108756 C/W: Gasoline Engine, Automatic Transmission, Air Conditioner, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Engine hrs, Automatic Transmission, 12000 lb Front Axle, 21000 lb Rears, 33000 lb GVWR, 295 /75R22.5, Air Ride Suspension, 272 in Wheelbase, Flatbed, Arrow Board, In-Cab Arrow Board Controller Usage: 177,195 Mi Notes: BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9845	2016 Dodge Charger Automobile (Inoperable) S/N: 2C3CDXHG6GH302642 C/W: 3.6 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING Asset located in: Humble, TX 2016 Infiniti Q50 Automobile (Inoperable)	9849	(Inoperable) S/N: 2B3CL5CT5BH521044 C/W: V8 5.7 L Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BI RECONSIGNED; SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE
70.0	S/N: JN1EV7AP4GM304465		INSPECTION REPORT Asset located in: Humble, TX
	C/W: V6 3.0 L Gasoline Engine, 2016 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TITLE COMES WITH	9850	1991 Chevrolet Camaro Automobile (Inoperable) S/N: 1G1FP23TXML136933 C/W: Gasoline Engine, 1991 US EPA Label, Automatic Transmission, Air Conditioner Usage: 135,263 Mi
	REPOSSESSED AFFIDAVIT		Notes: THIS INOPERABLE ITEM NEEDS TO BE
	Asset located in: Humble, TX	_	REMOVED FROM THE YARD AND CAN NOT BE
9847	S/N: 1G11B5SL7EF225175 Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED 9851		RECONSIGNED THIS UNIT IS BEING SOLD WITH A REBUILT SALVAGE TITLE
		2054	Asset located in: Humble, TX
		9851	1974 MG Classic Car (Inoperable) S/N: GHD5UE345015 C/W: Gasoline Engine, Manual Transmission, Air Conditioner Usage: 78,057 Mi
	Asset located in: Humble, TX	9852	
9848	2013 Kia Soul 2WD SUV (Inoperable) S/N: KNDJT2A5XD7527218 C/W: 4 cyl 1.6 L Gasoline Engine, 2013 US EPA		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks		Asset located in: Humble, TX
	Usage: 144,571 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2014 Dodge Grand Caravan SE Minivan (Inoperable) S/N: 2C4RDGCG7ER331894 C/W: 3.6 L Gasoline Engine, 2014 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available
9849B	2006 Chrysler Crossfire Automobile	┪	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
70475	(Inoperable)		RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	S/N: 1C3AN69L86X064426 C/W: V6 Gasoline Engine, 2005 US EPA Label,		Asset located in: Humble, TX
	Automatic Transmission, Air Conditioner,	9853	2020 Chevrolet equinox 2WD SUV (Inoperable)
	Power Windows, Power Locks Usage: Not Available Notes : DEFICIENCIES NOTED - PLEASE SEE		S/N: 3GNAXLEX8LS705964 C/W: Automatic Transmission, Air Conditioner, Power Windows
	THE INSPECTION REPORT		Usage: Not Available
9849A	Asset located in: Humble, TX 2007 BMW 53i Automobile	-	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	S/N: WBANE73527CM51279 C/W: 6 cyl 3.0 L Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: 152,290 Mi Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Humble, TX
	THE INSPECTION REPORT		
	Asset located in: Humble, TX	I	

	Deteile	T1 00 #	Dataila
Lot #	Details OWD OUNT (1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	Lot #	Details OFFICE A 4 0 0 1
9854	2017 Chevrolet equinox 2WD SUV (Inoperable) S/N: 2GNALDEK2H6254199 C/W: 4 cyl 2.4 L Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9859	2017 GMC Sierra 3500HD 4x4 Crew Cab Pickup (Inoperable) S/N: 1GT42VCY2HF179435 C/W: 6.6 L V8 Diesel Engine, 2017 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Dual Rear Wheel, Spray-On Bed Liner, 13025 lb GVWR, 235 /80R17 Tires, 8 ft Bed Usage: 154,646 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
9855	2015 Infiniti QX60 AWD SUV (Inoperable) S/N: 5N1AL0MM2FC526562 C/W: V6 3.5 L Gasoline Engine, 2015 US EPA		RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: 173,376 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		2008 Ford F-350 XL 4x4 Crew Cab Pickup (Inoperable) S/N: 1FTSW31R08EE22354 C/W: 6.4 L V8 Diesel Engine, 2008 US EPA Label, Manual Transmission, Tool Box, 10000 lb GVWR, 275/70R18 Tires, 8 ft Bed Usage: Not Available
9856	2012 Jeep Patriot 2WD SUV (Inoperable) S/N: 1C4NJPBA6CD631222 C/W: 4 cyl 2.0 L Gasoline Engine, 2012 US EPA Label, Automatic Transmission, Air		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9857	Conditioner, Power Windows, Power Locks Usage: 196,401 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2011 Infiniti QX56 2WD SUV (Inoperable)		2024 Ford F-250 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT8W2BT2REC24293 C/W: Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 275/70R18 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
	S/N: JN8AZ2NF8B9501370 C/W: V8 5.6 L Gasoline Engine, 2013 US EPA Label, Automatic Transmission, Air		RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9858	Conditioner, Power Windows, Power Locks, Rear View Camera, 3rd Row Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED BUYER'S RESPONSIBILITY FOR REMOVAL OF THIS ITEM Asset located in: Humble, TX 2001 Chevy Tahoe LS 2WD SUV (Inoperable) S/N: 1GNEC13T61R214049 C/W: V8 5.3 L Gasoline Engine, 2001 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Power Locks, Towing Hitch		(Inoperable) S/N: 1FT7W2BT9JEB38172 C/W: 6.7 L V8 Diesel Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 10000 lb GVWR, 35x12.50R20 Tires, 6 ft 8 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TITLE BRAND NOT ACTUAL MILEAGE DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Acceptable in Figure 17

Lot #	Details	Lot #	Details	
9863	2018 Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6UR5HJ2JG348601 C/W: 6.4 L V8 Gasoline Engine, 2018 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Headache Rack, Fuel Tank /w Pump, Weather Guard Tool Box, Spray-On Bed Liner, 10000 lb GVWR, 275 /70R18 Tires, 7 ft 11 in Bed Usage: 138,800 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS	9869 9870A	2001 Dodge Ram 2500 4x2 Pickup (Inoperable) S/N: 3B7KC26621M275049 C/W: 5.9 L 6 Cylinder Diesel Engine, 2000 US EPA Label, 5 Speed Manual Transmission, Air Conditioner, Drop-In Bed Liner, 8800 lb GVWR, 245/75R16 Tires, 8 ft 2 in Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED EQUIPMENT-FROM-YELLOW- CORP DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2015 Ford F-150 XL 4x2 Pickup (Inoperable)	
9865	Asset located in: Humble, TX 2017 Ford F-250 XLT 4x4 Crew Cab Pickup (Inoperable) S/N: 1FT7W2B62HEC65768 C/W: 6.2 L V8 Gasoline Engine, Automatic Transmission, Air Conditioner, Power Driver's Seat, Power Windows, Spray-On Bed Liner, 10000.0 lb GVWR, 265/70R17 Tires, 6 ft 8 in Bed Usage: Not Available		S/N: 1FTMF1C80FFB83932 C/W: 3.5 L V6 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, UWS Tool Box, 6010 lb GVWR, 275/55R20 Tires, 6 ft 6 in Bed Usage: 153,343 Mi Notes: TEXAS BUYERS MUST STOP IN OFFICE TO SIGN REQUIRED DOCUMENTS Asset located in: Humble, TX	
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9870	2017 Ford F-150 XL 4x2 Extended Cab Pickup (Inoperable) S/N: 1FTEX1C84HKC50155 C/W: 3.5 L V6 Gasoline Engine, 2017 US EPA Label, Automatic Transmission, Air	
9866	2015 Ram 2500 4x4 Crew Cab Pickup (Inoperable) S/N: 3C6UR5HL0FG601150 C/W: 6.7 L 6 Cylinder Diesel Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 10000 lb GVWR, 275/70R18 Tires, 11 ft Bed		Co GV Us No RE RE	Conditioner, Better Built Tool Box, 6100 lb GVWR, 245/70R17 Tires, 6 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	Usage: 252,991 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		2015 Ram 1500 ST 4x2 Crew Cab Pickup (Inoperable) S/N: 1C6RR6KT9FS651199 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 6900 lb GVWR, 275/60R20 Tires, 5 ft 6 in	
9868	2010 Ford F-250 XL 4x2 Pickup (Inoperable) S/N: 1FTNF2A56AEA70133 C/W: 5.4 L Gasoline Engine, 2010 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, 8800 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available			Bed Usage: 237,206 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX	9872	2015 Ram 1500 SLT 4x2 Crew Cab Pickup (Inoperable) S/N: 1C6RR6KT3FS570733 C/W: 5.7 L V8 Gasoline Engine, 2015 US EPA Label, Automatic Transmission, Air Conditioner, Power Windows, Fiberglass Truck Cap, 6900 lb GVWR, 275/60R20 Tires, 5 ft 6 in Bed Usage: 285,201 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	

Asset located in: Humble, TX

Details	Lot #	Details
2011 Ford F-150 XL 4x2 Pickup (Inoperable) S/N: 1FTNF1CF7BKD32647 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Weatherguard Tool Box, Drop-In Bed Liner, 7050 lb GVWR, 235/75R17 Tires, 8 ft Bed Usage: 200,602 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9878	2003 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCEC14X33Z165549 C/W: 4.3 L V6 Gasoline Engine, 2003 US EPA Label, Automatic Transmission, Air Conditioner, Spray-On Bed Liner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
· · · · · · · · · · · · · · · · · · ·	9879	2016 Great Dane 53 ft x 102 in T/A
(Inoperable) S/N: 1FTPX14V99FB02963 C/W: 5.4 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 101,889 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2008 Chevrolet Silverado 1500 4x2 Pickup		Refrigerated Trailer (Inoperable) S/N: 1GRAA0624GW702913 C/W: Air Ride Suspension, Ducted Floor, Swing Door, Thermo King SB-200 Refrigeration Unit, Serial Number 01467R2023,, 295/75R22.5 Tires Usage: 34,720 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
S/N: 1GCEC14C58Z255435		Asset located in: Humble, TX
Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCEC14CX7Z520624 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available	9880	2015 Wabash RFALHSA 53 ft T/A Refrigerated Trailer (Inoperable) S/N: 1JJV532B4FL840000 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Aluminum Outer Wheels, 295/75R22.5 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED SELLING WITH A REPOSESSION AFFIDAVIT AND MAY NOT BE ACCEPTED IN YOUR STATE. VERIFY WITH YOUR LOCAL DMV PRIOR TO BIDDING DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
Notes: THIS INOPERABLETTEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE	9881	2014 Utility 53 ft x 102 in T/A Curtain Side
RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 GMC Sierra 1500 4x2 Pickup (Inoperable) S/N: 3GTEC14X67G154695 C/W: 4.3 L V6 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 273,926 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Refrigerated Trailer (Inoperable) S/N: 1UYVS2536EM080405 C/W: Air Ride Suspension, Sliding Suspension, Ducted Floor, Swing Door, Carrier Refrigeration Unit, Serial Number 3419UA0268, Aluminum Wheels, 295/75R22.5 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	2011 Ford F-150 XL 4x2 Pickup (Inoperable) S/N: 1FTNF1CF7BKD32647 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Weatherguard Tool Box, Drop-In Bed Liner, 7050 lb GVWR, 235/75R17 Tires, 8 ft Bed Usage: 200,602 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2009 Ford F-150 XL 4x4 Extended Cab Pickup (Inoperable) S/N: 1FTPX14V99FB02963 C/W: 5.4 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 101,889 Mi Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2008 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCEC14C58Z255435 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCEC14CX7Z520624 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 GMC Sierra 1500 4x2 Pickup (Inoperable) S/N: 3GTEC14X67G154695 C/W: 4.3 L V6 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: 71,926 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	2011 Ford F-150 XL 4x2 Pickup (Inoperable) S/N: 1FTNF1CF7BKD32647 C/W: 5.0 L V8 Gasoline Engine, 2011 US EPA Label, Automatic Transmission, Air Conditioner, Weatherguard Tool Box, Drop-In Bed Liner, 7050 lb GVWR, 235/75R17 Tires, 8 ft Bed Usage: 200,602 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2009 Ford F-150 XL 4x4 Extended Cab Pickup (Inoperable) S/N: 1FTPX14V99FB02963 C/W: 5.4 L V8 Gasoline Engine, 2009 US EPA Label, Automatic Transmission, Spray-On Bed Liner, 7200 lb GVWR, 265/70R17 Tires, 6 ft 6 in Bed Usage: 101,889 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX 2008 Chevrolet Silverado 1500 4x2 Pickup S/N: 1GCEC14C58Z255435 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 Chevrolet Silverado 1500 4x2 Pickup (Inoperable) S/N: 1GCEC14CX7Z520624 C/W: 4.8 L V8 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6400 lb GVWR, 245/70R17 Tires, 8 ft Bed Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2007 GMC Sierra 1500 4x2 Pickup (Inoperable) S/N: 3GTEC14X67G154695 C/W: 4.3 L V6 Gasoline Engine, 2007 US EPA Label, Automatic Transmission, Air Conditioner, 6100 lb GVWR, 245/70R17 Tires, 6 ft 6 in Bed Usage: 273,926 Mi Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9882	2019 Lark VT8520TA 20 ft T/A Enclosed Trailer (Inoperable) S/N: 571BE2024KM032616	9886A	John Deere F1445 Ride-On Lawn Mower (Inoperable)
	C/W: Ball Hitch, Spring Suspension, Electric Brakes, 95 in Deck Width, 102 in Overall Width, Side Door 225/75R15 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: TC1445D031630 C/W: Hydrostatic Drive, 2003 US EPA Label, 23x10.50x12 Front Tires, 18x8.50x10 Rear Tires, 72 in Mower Usage: Not Available
			Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9886	John Deere 2653A Ride-On Lawn Mower
9883	2019 LeeBoy L150 S/A 150 gal Asphalt Distributor Trailer (Inoperable) S/N: 1B9AA1117K1309158 C/W: Double Flue w/ LPG Burners, Hand Spray Wand, Pump w/ Honda Engine, Ball Hitch, Spring Suspension, 225/75R15 Tires Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -		(Inoperable) S/N: TC2653D081681 C/W: Hydrostatic Drive, 1995 US EPA Label, 20x10.00x10 Front Tires, 20x10.00x8 Rear Tires Usage: 2,079 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	PLEASE SEE THE INSPECTION REPORT	9887	Cub Cadet Ride-On Lawn Mower (Inoperable)
9884B	Asset located in: Humble, TX 2014 John Deere 8700 Precision Cut Ride-On Fairway Lawn Mower (Inoperable)		S/N: Not Available C/W: Hydrostatic Drive, 2005 US EPA Label, 23x9.50-12 Rear Tires Usage: Not Available
	S/N: 1TC8700XJEF070083 C/W: Canopy, Hydrostatic Drive, 2013 US EPA Label, 26x12.00x12 Front Tires, 20x10.00x8 Rear Tires, 100 in Mower		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Usage: 3,239 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE		Asset located in: Humble, TX
	THE INSPECTION REPORT	9888	Cub Cadet Ride-On Lawn Mower (Inoperable) S/N: Not Available
9884A	Asset located in: Humble, TX E-Z-Go Electric Golf Cart (Inoperable) S/N: 3036943 C/W: 4 Passenger Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Hydrostatic Drive, 2005 US EPA Label, 54 in Mower Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9884	Cushman Utility Cart (Inoperable)	9889	Grasshopper 227 Zero-Turn Lawn Mower
9885	S/N: 3154020 C/W: Open Operator Station, 2 Passenger Usage: 536 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX John Deere 2653A Ride-On Lawn Mower		(Inoperable) S/N: 6714891 C/W: Hydrostatic Drive, 13x6.5-4.5 Front Tires, 24x12.00-12 Rear Tires, 50 in Mower Usage: 1,210 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9000	(Inoperable)	0000	Asset located in: Humble, TX
	S/N: TC2653D090367 C/W: Hydrostatic Drive, 2000 US EPA Label, 20X10.00-10 Front Tires, 20X10.00-8 Rear Tires, 72 in Mower Usage: 2,818 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9890	Grasshopper 225 Zero-Turn Lawn Mower (Inoperable) S/N: 6812024 C/W: Hydrostatic Drive, Tier 2, 23.50x10-12 Rear Tires, 50 in Mower Usage: 1,443 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9891	Engine (Inoperable) S/N: 264574 C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9895	Pioneer Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Cat 6 Cylinder Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9892B	2007 Cat 3406A Engine (Inoperable) S/N: 3ER10114	9896	Asset located in: Humble, TX 350 kW Skid-Mounted Generator Set
	C/W: 2007 US EPA Label, 6 Cylinder 14.6 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	3090	(Inoperable) S/N: 465520810 C/W: 8 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9892A	Cat 3306 Engine (Inoperable) S/N: 7N3375		Asset located in: Humble, TX
9892	C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX Kubota D1105 Engine (Inoperable) S/N: 8N0747 C/W: 3 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9897	2012 Miscellaneous Generator 309 kVA Skid-Mounted Generator Set (Inoperable) S/N: 121002951 C/W: 2011 US EPA Label, John Deere 6090HF484a,B,C 6 Cylinder 315 kW 9.0 L Diesel Engine, 208 V / 480 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Asset located in: Humble, TX	9898	Cummins DQAE5769141 275 kW Skid-
9893	1999 International A250 Engine (Inoperable) S/N: Not Available C/W: Ford Transmission Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Mounted Generator Set (Inoperable) S/N: 1060970124 C/W: Tier 1, Cummins QSM11-G2 6 Cylinder 470 hp 10.8 L Diesel Engine, /275 kW Rated 3 Phase Output, 139 V / 220 V / 230 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE
9894	Cat 3508 900 kW Containerized Generator Set (Inoperable) S/N: 23Z04466 C/W: Cat 3500 8 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM; DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9899	2014 Kohler Generator 180 kW Skid-Mounted Stand-By Generator Set (Inoperable) S/N: SGM329W7X C/W: 2014 US EPA Label, John Deere 6068HFG82C,E,I 6 Cylinder 6.8 L Diesel Engine, /180 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9903	2011 HiPower HRJW-115 115 kVA Skid-Mounted Generator Set (Inoperable) S/N: 111003335 C/W: 2011 US EPA Label, John Deere 4 Cylinder Diesel Engine, 115 kVA/ Rated 3 Phase Output, 208 V / 480 V Rated Voltage, 79 kVA,/ Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 14,678 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9900	Aggreko XBSG200 168 kW Skid-Mounted Generator Set (Inoperable)		Asset located in: Humble, TX
	S/N: Not Available C/W: 2013 US EPA Label, Cummins 6 Cylinder 476 hp 6.7 L Diesel Engine, 210 kVA/168 kW Rated 3 Phase Output, 380 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9904	2012 HiPower HRJW-115.T6 95 kW Skid-Mounted Generator Set (Inoperable) S/N: 111006440 C/W: 2012 US EPA Label, John Deere 4045HF285 4 Cylinder 4.5 L Diesel Engine, 115 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 79 kVA,/ Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank Usage: 9,566 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR
9901	2014 HiPower HRNG 165 164 kVA Skid-		REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION
,,,,,	Mounted Generator Set (Inoperable) S/N: U4130086		REPORT Asset located in: Humble, TX
	C/W: 6 Cylinder 8.1 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Multiquip DCA125SSJE 72 kW Skid-Mounted Generator Set (Inoperable) S/N: 7500864 C/W: John Deere 6068TF 6 Cylinder 6.8 L Diesel Engine, 125 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, /72 kW, Rated Single Phase Output, 120 V / 240 V Rated
9902 2013 HiPower HRNG165T6 Mounted Generator Set (Ino S/N: U41400273 C/W: 6 Cylinder Diesel Engir Usage: Not Available Notes: THIS INOPERABLE IT	2013 HiPower HRNG165T6 164 kVA Skid- Mounted Generator Set (Inoperable) S/N: U41400273 C/W: 6 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE		Voltage, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 524 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	RECONSIGNED. DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		•
	Asset located in: Humble, TX	9906	2011 Magnum MMG150 Skid-Mounted Generator Set (Inoperable) S/N: 1105921 C/W: 2010 US EPA Label, John Deere 6068HF 6 Cylinder 6.8 L Diesel Engine, /145 kW Rated 3 Phase Output, 208 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank Usage: 19,490 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

	Details	Lot #	Details
Lot # 9907	Newage 100 kW Skid-Mounted Generator Set (Inoperable) S/N: Not Available C/W: Perkins 4 Cylinder 4.4 L Diesel Engine, 125 kVA/100 kW Rated 3 Phase Output, 480 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9910	2016 Multiquip DCA220SSJU4F 220 kVA Mobile Generator Set (Inoperable) S/N: 5SLBG1821GL018610 C/W: 2016 US EPA Label, John Deere 6068HFG09 6 Cylinder 6.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 220 kVA/ Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE
9908A	Onan DFCE-3380744 400 kW Stand-By Generator Set (Inoperable) S/N: J990007923 C/W: Cummins D210 6 Cylinder Diesel Engine, 500 kVA/400 kW Rated 3 Phase Output Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Cummins 100DGDB 100 kW Mobile Generator Set (Inoperable) S/N: F970640488 C/W: Cummins 6BT5.9 6 Cylinder 166 hp 5.9 L
9908	2006 Cummins DGDK 125 kW Stand-By Generator Set (Inoperable) S/N: E060925300 C/W: Cummins 6BTAA5.9-G-1 6 Cylinder 5.9 L Diesel Engine, 156 kVA/125 kW Rated 3 Phase Output, 240 V / 440 V / 480 V Rated Voltage, 125 kVA,/125 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Bottom Mounted Fuel Tank Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE		Diesel Engine, 125 kVA/100 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage, 67 kVA, /67 kW, Rated Single Phase Output, 120 V / 208 V Rated Voltage, T/A Trailer, Electric Brakes Usage: 962 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2018 TechnoGen G60 56 kW Mobile Generator
9909	RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2013 MQ Power 240 kW Mobile Generator Set (Inoperable) S/N: 5SLBG2022DL013736 C/W: 2013 US EPA Label, CARB Compliant, Cummins CPL1404 6 Cylinder 399 hp 8.9 L Diesel Engine, 240 V & 120 V Receptacles, Sound Attenuated, T/A Trailer, Ball Hitch, Electric Brakes Usage: 12,600 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE		Set (Inoperable) S/N: 16MBB1624HD076464 C/W: 2017 US EPA Label, FPT 4 Cylinder 67 kW Diesel Engine, 70 kVA/56 kW Rated 3 Phase Output, 480 V / 277 V / 208 V Rated Voltage, 52.5 kVA,/42 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, T/A Trailer, Surge Brakes Usage: 16,045 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9913	2006 Wacker Neuson G50C 38 kW Mobile Generator Set (Inoperable) S/N: 185945 C/W: 2006 US EPA Label, John Deere 4 Cylinder 50 kW 4.5 L Diesel Engine, 48 kVA/38 kW Rated 3 Phase Output, 208 V / 480 V Rated Voltage, 32 kVA,/32 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring, Surge Brakes Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT

Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9914	2017 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set (Inoperable) S/N: Not Available C/W: 2017 US EPA Label, Isuzu 4 Cylinder Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 2,375 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9916	Marathon 90 kW Skid-Mounted Generator Set (Inoperable) S/N: 729063 C/W: 8 Cylinder 8.8 L Engine, 113 kVA/90 kW Rated 3 Phase Output, 120 V / 240 V / 480 V Rated Voltage, 66 kVA,/66 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2010 Taylor TG30 27 kW Skid-Mounted
9915B	Asset located in: Humble, TX 2016 Atlas Copco QAS25 20 kW Mobile Generator Set (Inoperable) S/N: 4500G1118GR121153 C/W: 2016 US EPA Label, Isuzu BZ-4LE2T 4 Cylinder Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 270 V / 480 V Rated Voltage, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, S/A Trailer, Ball Hitch Usage: Not Available		Generator Set (Inoperable) S/N: 23289 C/W: 33 kVA/27 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 21,717 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9918	Taylor TG30 27 kW Skid-Mounted Generator Set (Inoperable) S/N: 23285
9915A	Shindaiwa 15KVA 12 kW Mobile Generator Set (Inoperable) S/N: D163019000086 C/W: Tier 4, 2018 US EPA Label, CARB Compliant, Kubota D902-EF01 18.2 kW 0.8 L Diesel Engine, 15 kVA/12 kW Rated 3 Phase Output, 208 V / 220 V / 240 V Rated Voltage, 9 kVA,/9 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, 240 V & 120 V Receptacles, Bottom Mounted Fuel Tank, S/A Trailer, Ball Hitch Usage: 3,474 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Engine, 33 kVA/27 k 277 V / 480 V Rated Usage: 15,875 Hr Notes: THIS INOPER REMOVED FROM TH RECONSIGNED DEF PLEASE SEE THE IN Asset located in: Hu S/A 9919 Taylor TG30 27 kW S/N: 23350 C/W: 2010 US EPA I Engine, 33 kVA/27 k 277 V / 480 V Rated Usage: 16,773 Hr
Generator Set (Ir S/N: 4GNBG0910 C/W: 2015 US EF	2016 Multiquip DCA25SSIU4F 20 kW Mobile Generator Set (Inoperable) S/N: 4GNBG0910PB066326 C/W: 2015 US EPA Label, Isuzu 4LE2T 4		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Cylinder 30 kW 2.1 L Diesel Engine, 25 kVA/20 kW Rated 3 Phase Output, 240 V / 480 V Rated Voltage, 14.4 kVA,/14.4 kW, Rated Single Phase Output, 240 V / 120 V Rated Voltage, 240 V & 120 V Receptacles, Sound Attenuated, Bottom Mounted Fuel Tank, S/A Trailer, Lunette Ring Usage: 9,437 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9920	2012 Taylor TG30 19 kW Skid-Mounted Generator Set (Inoperable) S/N: 24767 C/W: 4 Cylinder Engine, 23 kVA/19 kW Rated 3 Phase Output, 277 V / 480 V Rated Voltage Usage: 33,908 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9921	(Inoperable) S/N: 3011405698 C/W: Generac 2 Cylinder Natural Gas Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9926	2010 Ingersoll Rand XP375WIR-T3 Air Compressor (Inoperable) S/N: 413388UDUC48 C/W: 250 psi Working Pressure, 2010 US EPA Label, John Deere AJDXL06.8117 4 Cylinder 4.5 L Diesel Engine, EQUIPMENT-FROM-PUMPCO-ENERGY-INFRASTRUCTURE Usage: 8,982 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	S/N: 5335344	9927	2010 Ingersoll Rand P185WJD-T4I Air
	C/W: 2 Cylinder Natural Gas Engine, /10 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Compressor (Inoperable) S/N: 413641UEUD75 C/W: 200 psi Working Pressure, 2010 US EPA Label, John Deere AJDXL02.4074 4 Cylinder 2.4 L Diesel Engine, EQUIPMENT-FROM- PUMPCO-ENERGY-INFRASTRUCTURE Usage: 3,308 Hr
9923	Generac 5528 Skid-Mounted Stand-By Generator Set (Inoperable) S/N: 5765553 C/W: 2 Cylinder Natural Gas Engine, 120 V / 240 V Rated Voltage, Sound Attenuated		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	Usage: Not Available	9928A	2018 Atlas XAS185 185 cfm Mobile Air
9924	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Generac 5883 10 kW Skid-Mounted Stand-By	9926A	Compressor (Inoperable) S/N: HOP057162 C/W: 125 psi Working Pressure, 2018 US EPA Label, CARB Compliant, Kubota D1803-CR-TI- EF02 3 Cylinder 36.5 kW 1.9 L Diesel Engine, S /A Trailer, Ball Hitch
	Generator Set S/N: 5569490 C/W: 2 Cylinder Natural Gas Engine, /10 kW, Rated Single Phase Output, 120 V / 240 V Rated Voltage, Sound Attenuated Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: 2,287 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
		9928	Asset located in: Humble, TX 2004 Ingersoll Rand P185WJDU Skid-Mounted
			Air Compressor S/N: Not Available C/W: US EPA Label, John Deere 4045DF150 4 Cylinder 4.5 L Diesel Engine
9925	2011 Atlas Copco XAS1600CD6 1600 cfm Mobile Air Compressor (Inoperable)		Usage: Not Available Asset located in : Humble, TX
	S/N: APP188393 C/W: 100 psi Working Pressure, Cat C13 6 Cylinder 328 hp Diesel Engine, T/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9929	Quantity of (2) Skid-Mounted Air Compressor (Inoperable) S/N: 29367 C/W: 200 psi Working Pressure, Honda Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9930	Onan Generator Set (Inoperable) S/N: Not Available C/W: 2 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9931	Westinghouse 4500 Generator Set (Inoperable) S/N: 45A0622B3468 C/W: Gasoline Engine, 120 V Rated Voltage, 120 V Receptacles Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9936	Hydraulic Trailer Mounted Power Swivel (Inoperable) S/N: 1M9GU1421CD886022 C/W: Cat C4.4 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
9932	Hydraulic Skid-Mounted Power Swivel (Inoperable) S/N: Not Available C/W: Cat C7 6 Cylinder 250 hp Diesel Engine Usage: 2,616 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9937	2010 Pioneer PP66S12L Trailer-Mounted Water Pump (Inoperable) S/N: 12811 C/W: Centrifugal 2012 US EPA Label, Deutz D914L04 4 Cylinder 78 hp 4.3 L Diesel Engine, S /A Trailer, Lunette Ring Usage: 4,282 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	Asset located in: Humble, TX	9938	Godwin Pumps Trailer-Mounted Water Pump
9933	Hydraulic Skid-Mounted Power Swivel (Inoperable) S/N: Not Available C/W: Cat C7 6 Cylinder 225 hp Diesel Engine Usage: 1,482 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		(Inoperable) S/N: 16MPF06127D050360 C/W: 6 in Intake, 6 in Discharge, Centrifugal 2007 US EPA Label, John Deere 4045DF 4 Cylinder 60 kW 4.5 L Diesel Engine, S/A Trailer, Lunette Ring, Electric Brakes Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
	Asset located in: Humble, TX	9939	Godwin Pumps CD100 Trailer-Mounted Water
9934	Hydraulic Skid Mounted Power Swivel (Inoperable) S/N: Not Available C/W: 2007 US EPA Label, CARB Compliant, John Deere 6090HF 6 Cylinder 9.0 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES		Pump (Inoperable) S/N: 9410012 C/W: 4 in Intake, 4 in Discharge, Centrifugal 3 Cylinder Diesel Engine, S/A Trailer, Lunette Ring Usage: 4,274 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED; NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY Asset located in: Humble, TX
	NOTED - PLEASE SEE THE INSPECTION	9940A	2014 Jetstream UNx 4200 Skid Mounted
	REPORT Asset located in: Humble, TX		Water Pump (Inoperable) S/N: 4123009 C/W: Triplex 6 Cylinder Diesel Engine
9935	Logan Oil PS365512 Power Swivel (Inoperable) S/N: Not Available C/W: Cummins QSB 6.7 6 Cylinder 240 hp Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9940	Gorman-Rupp 10 in Skid-Mounted Water Pump (Inoperable) S/N: 03GBA383824 C/W: 10 in Intake, 10 in Discharge, Centrifugal Water Pump Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9945	2014 Lincoln Electric Vantage 500 500 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141204866 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 8,706 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9941	2010 Industrial Vacuum Industrial Vacuum System (Inoperable)		Asset located in: Humble, TX
	S/N: 1D9BV1526AW048060 C/W: Lunette Ring Hitch, Spring Suspension, Electric Brakes, Steel Debris Tank, Roots Blower, 235/85R16 Tires, 2010 US EPA Label, John Deere 6068HF 6 Cylinder 6.8 L Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9946	2008 Lincoln Vantage 500 500 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1080210779 C/W: 2008 US EPA Label, Deutz 4 Cylinder 49 hp 3.1 L Diesel Engine, Welding Leads Not Included Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9942	Skid Mounted Hydraulic Power Pack		Asset located in: Humble, TX
9943	(Inoperable) S/N: Not Available C/W: Kubota 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 2016 Lincoln Electric Vantage 500 500 A Skid-	9949A	Lincoln Electric Vantage 500 500 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 2014 US EPA Label, 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, 120 V Rated Voltage Usage: 7,523 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Mounted Multi-Process Engine Driven Welder		Asset located in: Humble, TX
9944	(Inoperable) S/N: U1160205219 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9950C	Lincoln Electric Vantage 500 500 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 2016 US EPA Label, 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, 120 V Rated Voltage Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
9944	2016 Lincoln Welding Equipment Engine Driven Welder (Inoperable) S/N: U1162025219 C/W: 4 Cylinder Diesel Engine Usage: 708 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9950B	Lincoln Electric 500 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,016 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9950A	Lincoln Electric Vantage 500 500 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available	9955	2009 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1090400570
	C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage		C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: Not Available
	Usage: 7,664 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9951	•	-	Asset located in: Humble, TX
9901	2014 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141205934 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage	9956	2008 Lincoln Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1080705131 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, / 240 V Rated Voltage, 120 V / 240 V Rated Voltage
	Usage: 6,367 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: 1,383 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
9952	2014 Lincoln Electric Vantage 400 400 A Skid-		Asset located in: Humble, TX
9932	Mounted Multi-Process Engine Driven Welder (Inoperable)	9957	2008 Lincoln Electric 400A 400 A Skid- Mounted Multi-Process (Inoperable)
	S/N: U1141205625 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 120 V / 240 V Rated Voltage, 120 V Rated Voltage Usage: Not Available		S/N: U1080705136 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 4,886 Hr
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX	<u> </u>	Asset located in: Humble, TX
9953	2014 Lincoln Electric Vantage 400 400 A Skid-Mounted Multi-Process (Inoperable) S/N: U1140807442 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 3,822 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	9958	2008 Lincoln Electric Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: 1080907986 C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
0054	Asset located in: Humble, TX	9959	2008 Lincoln Vantage 400 400 A Skid-Mounted
9954	2014 Lincoln Electric Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1141206025 C/W: 4 Cylinder Diesel Engine, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,409 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Multi-Process Engine Driven Welder (Inoperable) S/N: U1080210520 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 4,562 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9960	2008 Lincoln Vantage 400 Engine Driven Welder (Inoperable) S/N: U1080210524 C/W: 4 Cylinder Diesel Engine Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9966	Lincoln SAE300 300 A Skid-Mounted Stick Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9962	2007 Lincoln Vantage 400 400 A Skid-Mounted Multi-Process Engine Driven Welder		PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	(Inoperable) S/N: 1070806989 C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9967A	2018 Miller Big Blue 500 Pro 500 A Mobile Engine Driven Welder (Inoperable) S/N: MJ011174R C/W: 2017 US EPA Label, CARB Compliant, Kubota V2403 36.0 kW 2.4 L Diesel Engine, 3 Phase, Single Phase, 120 V / 240 V Input, 240 V Rated Voltage, 120 V / 240 V Rated Voltage, S /A Trailer, Ball Hitch Usage: 4,211 Hr
9963	2007 Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: U1070711281	RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX 9967 Lincoln RA-250-V1903 300 A Skid-Mount Engine Driven Welder (Inoperable) S/N: C1080500072 C/W: Tier 4, 2008 US EPA Label, CARB Compliant, Kubota V2003-M-BG-ET02e 4 Cylinder 24.3 kW 2.0 L Diesel Engine, We Leads Not Included, 40 V Rated Voltage Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TREMOVED FROM THE YARD AND CAN NRECONSIGNED Asset located in: Humble, TX 9968 2018 Lincoln Vantage 350 A Mobile Mult Process Engine Driven Welder (Inoperabl S/N: U1180103785 C/W: Tier 4, Kubota V1505 4 Cylinder 1.5 Diesel Engine, 3 Phase, Single Phase, 120 240 V Input, Welding Leads Not Included kW Rated 3 Phase Output, 240 V Rated Voltage, /11.5 kW Rated Single Phase Output, 240 V Rated Voltage, /11.5 kW Rated Single Phase Output, 240 V Rated Voltage, S/A Trailer, Hitch Usage: 5,256 Hr Notes: THIS INOPERABLE ITEM NEEDs TREMOVED FROM THE YARD AND CAN NRECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 5,395 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: C1080500072 C/W: Tier 4, 2008 US EPA Label, CARB Compliant, Kubota V2003-M-BG-ET02e 4 Cylinder 24.3 kW 2.0 L Diesel Engine, Welding Leads Not Included, 40 V Rated Voltage
9964A	Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable)		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage Usage: 7,124 Hr Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		C/W: Tier 4, Kubota V1505 4 Cylinder 1.5 L Diesel Engine, 3 Phase, Single Phase, 120 V, 240 V Input, Welding Leads Not Included, /1 kW Rated 3 Phase Output, 240 V Rated Voltage, /11.5 kW Rated Single Phase Outpu
9964	Lincoln Electric Vantage 400 400 A Skid- Mounted Multi-Process Engine Driven Welder (Inoperable) S/N: Not Available C/W: 4 Cylinder Diesel Engine, Welding Leads Not Included, 240 V Rated Voltage, 120 V / 240 V Rated Voltage		Hitch Usage: 5,256 Hr Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9969	Lincoln Mobile Electric Welder (Inoperable) S/N: Not Available C/W: Tier 4, 2018 US EPA Label, Kubota V1505 4 Cylinder 1.5 L Diesel Engine, Welding Leads Not Included, S/A Trailer, Ball Hitch Usage: 3,238 Hr Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

9971	2017 Wacker RTLX-SC3 Trench Compactor (Inoperable)	9976	2021 Wacker Neuson BS70-4 Jumping Jack
	0.01 40.400.4	9976	Tamper (Inoperable)
	S/N: 424284 C/W: 2017 US EPA Label, Kohler 3 Cylinder 1 L Diesel Engine, / 32 in Drums, Cordless Remote Control, Articulated Steering Usage: 354 Hr Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		S/N: 11344031 C/W: 1 Cylinder Gasoline Engine Usage: Not Available
			Notes : THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE
			RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9977	20500 Lb Truck Mounted Knuckle Boom
0070	Asset located in: Humble, TX		(Inoperable)
9972	2000 Rammax RW-1404MR Trench Compactor (Inoperable) S/N: 329001		S/N: 3221378 C/W: hydraulic outriggers, hydraulic tank Usage: Not Available
	C/W: Hatz 2G40 2 Cylinder Diesel Engine, 33 in Drums Usage: 296 Hr		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED, BUYER RESPONSIBLE FOR
	Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED		REMOVAL OF THIS ITEM DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
	Asset located in: Humble, TX		Asset located in: Humble, TX
9973	1998 Rammax RW-1404MR Trench Compactor (Inoperable)	9979	2012 Wanco WVT3 Solar Message Board (Inoperable)
	S/N: 323528 C/W: Hatz 2G40 2 Cylinder Diesel Engine, 33 in		S/N: 5F12S1211C1001024 C/W: Solar Powered, S/A Trailer, Ball Hitch,
	Drums Usage: Not Available		EQUIPMENT-FROM-A-PRIMORIŚ-SERVICEŚ- CORP-COMPANY
	Notes: THIS INOPERABLE ITEM NEEDS TO BE		Usage: Not Available
	REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -
9974	Rammax Trench Compactor (Inoperable)		PLEASE SEE THE INSPECTION REPORT
<i>331</i> 4	S/N: Not Available C/W: Hatz 2G40 2 Cylinder Diesel Engine, 33 in Drums Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -	0000	Asset located in: Humble, TX
		9980	2000 American Solar Message Board (Inoperable) S/N: 1A9BS3313Y2228068
			C/W: Solar Powered, Hydraulic Raise and Lower, S/A Trailer, Ball Hitch Usage: Not Available
	PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO B REMOVED FROM THE YARD AND CAN NOT I
9975	Portable Concrete Mixer (Inoperable)	-	RECONSIGNED NO TITLE AVAILABLE, SOLD WITH BILL OF SALE ONLY DEFICIENCIES
	S/N: Not Available		NOTED - PLEASE SEE THE INSPECTION
	C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available		REPORT Asset located in: Humble, TX
	Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED -	9982	Allison 3000RDSP Automatic Transmission (Inoperable)
	PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		S/N: 30-31570 Usage: Not Available
9976A	Husqvarna FS520 Walk-Behind Saw	-	Notes: THIS INOPERABLE ITEM NEEDS TO BE
JJ/ UA	(Inoperable)		REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	S/N: Not Available C/W: Water Hose Connection, 2016 US EPA		Asset located in: Humble, TX
	Label, Honda GX630 2 Cylinder Gasoline Engine Usage: Not Available	9983	Eaton Fuller Manual Transmission (Inoperable) S/N: Not Available
	Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Usage: Not Available
	Asset located in: Humble, TX		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT
			Asset located in: Humble, TX

Lot #	Details	Lot #	Details
9984B	Quantity of (2) Nobles Speed Scrub Walk-Behind Electric Floor Scrubber (Inoperable) S/N: Not Available C/W: 33 in Working Width Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9988	Champion 7 kW Mobile Generator Set (Inoperable) S/N: 255230 C/W: Champion 1 Cylinder 389 cc Gasoline Engine, 120 V Receptacles Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE
9984A	Quantity of Tennant T500E & T600E Electric Floor Scrubber (Inoperable)		RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in : Humble, TX
	S/N: T600E11028226/T500E10921735 C/W: T600E, T500E Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX Quantity of (2) Pressure Washer (Inoperable) S/N: Not Available C/W: Electric Operated	9989	Quantity of Generac Generator & Water Pump (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, XC6500 generator, XC3000P pump Usage: Not Available
9984			Notes : THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
	Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9990	Asset located in: Humble, TX Quantity of (2) Generac XC3000P Water Pump (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine
9985	Quantity of Generator & Pressure Washer (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, DXGNR6500 generator, Generac pressure washer Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX		Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9991	Quantity of Generac Generator & Pump (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine, XC6500 generator, XC3000P pump
9986	2011 Cat Pumps CT80020 Pressure Washer (Inoperable) S/N: AP3411213 C/W: Yamaha MZ300 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT		Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
		9992	2021 Multiquip QP4TH 4 In Trash Water Pump (Inoperable) S/N: 4 TH7610 C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available
9987	Asset located in: Humble, TX Quantity of (4) DeWalt DXGNR6500 Generator Set (Inoperable) S/N: Not Available		Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX
	C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	9993	2017 Multiquip QP4TH WPT004 - 4" Trash Water Pump (Inoperable) S/N: 4TH6019 C/W: Honda 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX

Lot#	Details	Lot #	Details
9994	2017 Multiquip QP4TH 4 In Trash Water Pump (Inoperable) S/N: 4TH6060 C/W: Honda GX340 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	10000	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8668811 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Carrier 69NT40 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9995	Quantity of (2) Generac T20-S Water Pump (Inoperable) S/N: Not Available C/W: 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	10001	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TRIU8125943 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Carrier 69NT40 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9996B	Power Breeze Swamp Cooler (Inoperable) S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	10002	40 ft Refrigerated Storage Container (Inoperable) S/N: Not Available Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED
9996A	Power Breeze Swamp Cooler (Inoperable) S/N: Not Available Usage: Not Available Notes: DEFICIENCIES NOTED - PLEASE SEE THE INSPECTION REPORT Asset located in: Humble, TX	10003	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TCLU1132252 C/W: 8 ft Wide, 9 ft 6 in High, 2010 Thermo King Magnum-575 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX
9996	2017 Multiquip QP4TH 4 In Trash Water Pump (Inoperable) S/N: 4TH6073 C/W: Trash Pump, Honda GX340 1 Cylinder Gasoline Engine Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDS TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		
9998	2024 Suihe 203012R 30 ft x 20 ft Storage Building (Unused) S/N: Not Available C/W: One Crate Usage: Not Available Asset located in: Humble, TX		
9999	40 ft High Cube Refrigerated Storage Container (Inoperable) S/N: TCLU1015955 C/W: 8 ft Wide, 9 ft 6 in High, 2008 Thermo King Magnum 575 Reefer Unit Usage: Not Available Notes: THIS INOPERABLE ITEM NEEDs TO BE REMOVED FROM THE YARD AND CAN NOT BE RECONSIGNED Asset located in: Humble, TX		