

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Cabrio Full Size/ Premium	Cabrio Luxury	
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury	Kleinbusse			
Fahrzeugdach	Antenne	gebrochen	471,07	448,62	391,35	735,51	368,40	230,02	700,10		
		verformt	471,07	448,62	391,35	735,51	368,40	230,02	700,10		
		fehlt	471,07	448,62	391,35	735,51	368,40	230,02	700,10		
	Schiebedach	gebrochen	4294,50	4408,01	5617,09	6823,89	6777,06	6880,16		3877,26	
		verformt	4294,50	4408,01	5617,09	6823,89	6777,06	6880,16		3877,26	
		fehlt	4294,50	4408,01	5617,09	6823,89	6777,06	6880,16		3877,26	
	Dach	gebrochen	5017,59	5044,10	6245,67	7468,69	7540,90	7948,20		3877,26	
		Delle >15 cm	1908,32	2063,28	2592,76	2308,85	2757,01	3123,40			
		Delle 5-15 cm	1554,69	1630,24	1943,87	1956,20	2211,72	2687,92			
		verformt	5017,59	5044,10	6245,67	7468,69	7540,90	7948,20		3877,26	
		gestrichen 2-5 cm	644,70	626,67	821,76	898,19	1073,44	1442,23			
		gestrichen 5-15 cm	836,26	911,81	1225,77	1237,77	1493,29	1969,49			
		Kratzer >15 cm	1030,24	1185,20	1715,09	1430,77	1878,93	2245,32			
		Kratzer 2-5 cm	644,70	626,67	821,76	898,19	1073,44	1442,23			
		Kratzer 5-15 cm	836,26	911,81	1225,77	1237,77	1493,29	1969,49			
		Glasdach (fest)	gebrochen	1141,40	692,96	911,21	2745,53	2955,41			
	verformt		1141,40	692,96	911,21	2745,53	2955,41				
	Fahrzeugfront	Motorhaube	gebrochen	1422,19	1559,96	1874,23	2325,82	2162,59	1833,92	2420,44	2711,01
			Delle >15 cm	1422,19	1559,96	1874,23	2220,31	2101,12	1792,63	2067,23	2141,37
			Delle 5-15 cm	1400,10	1526,06	1694,81	1867,31	1743,98	1559,01	1907,58	1981,72
verformt			1422,19	1559,96	1874,23	2325,82	2162,59	1833,92	2420,44	2711,01	
Kratzer >15 cm			811,85	1048,46	1293,69	1342,23	1223,04	914,55	1189,15	1263,29	
Kratzer 2-5 cm			556,02	583,81	671,56	869,11	771,70	652,19	969,87	1032,89	
Kratzer 5-15 cm			681,67	807,63	976,71	1148,88	1025,55	840,58	1189,15	1263,29	
Markenemblem vorn		gebrochen	80,07	92,37	112,13	137,50	82,15	96,75	74,99	87,29	
		fehlt	80,07	92,37	112,13	137,50	82,15	96,75	74,99	87,29	
Stossfaenger vorn		gebrochen	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Delle >15 cm	1182,79	1414,84	1505,63	1634,70	1632,57	931,41	1664,27	1630,03	
		Delle 5-15 cm	1182,79	1299,29	1346,05	1444,90	1423,53	931,41	1504,62	1470,38	
		verformt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		gestrichen 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		gestrichen 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
		fehlt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Kratzer >15 cm	639,04	585,89	627,95	756,62	754,49	836,52	786,19	751,95	
		Kratzer 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		Kratzer 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
Stossfaenger vorn mitte		gebrochen	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Delle >15 cm	1182,79	1414,84	1505,63	1634,70	1632,57	931,41	1664,27	1630,03	
		Delle 5-15 cm	1182,79	1299,29	1346,05	1444,90	1423,53	931,41	1504,62	1470,38	
		verformt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		gestrichen 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		gestrichen 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
		fehlt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Kratzer >15 cm	639,04	585,89	627,95	756,62	754,49	836,52	786,19	751,95	
		Kratzer 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		Kratzer 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
Stossfaengerecke vorn links		gebrochen	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Delle >15 cm	1182,79	1414,84	1505,63	1634,70	1632,57	931,41	1664,27	1630,03	
		Delle 5-15 cm	1182,79	1299,29	1346,05	1444,90	1423,53	931,41	1504,62	1470,38	
		verformt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		gestrichen 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		gestrichen 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
		fehlt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Kratzer >15 cm	639,04	585,89	627,95	756,62	754,49	836,52	786,19	751,95	
		Kratzer 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		Kratzer 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
Zierleiste Stossfaenger vorn		gebrochen	358,48	541,05	888,55	407,99	815,39	174,42	1009,23	679,71	
		verformt	358,48	541,05	888,55	407,99	815,39	174,42	1009,23	679,71	
		fehlt	358,48	541,05	888,55	407,99	815,39	174,42	1009,23	679,71	
Stossfaengerecke vorn		gebrochen	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
	rechts	Delle >15 cm	1182,79	1414,84	1505,63	1634,70	1632,57	931,41	1664,27	1630,03	
		Delle 5-15 cm	1182,79	1299,29	1346,05	1444,90	1423,53	931,41	1504,62	1470,38	
		verformt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		gestriffen 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
		gestriffen 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95	
		fehlt	1182,79	1414,84	1818,19	1885,04	1825,61	931,41	1784,30	1977,94	
		Kratzer >15 cm	639,04	585,89	627,95	756,62	754,49	836,52	786,19	751,95	
		Kratzer 2-5 cm	529,37	450,81	453,77	519,22	512,61	578,89	536,33	503,15	
	Kratzer 5-15 cm	616,99	580,86	627,95	726,47	705,10	774,30	786,19	751,95		
Fahrzeugfront	Spoilerlippe vorn (unterh.Stossf.)	gebrochen	389,54	442,95	376,97	401,82	497,93	257,01			
		Delle >15 cm	389,54	442,95	376,97	401,82	497,93	257,01			
		Delle 5-15 cm	389,54	442,95	376,97	401,82	497,93	257,01			
		verformt	389,54	442,95	376,97	401,82	497,93	257,01			
		gestriffen 2-5 cm	144,20	340,70	337,52	339,45	310,17				
		gestriffen 5-15 cm	360,50	423,95	371,04	439,34	412,67				
		fehlt	389,54	442,95	376,97	401,82	497,93	257,01			
		Kratzer >15 cm	360,50	423,95	371,04	440,20	412,67				
		Kratzer 2-5 cm	144,20	340,70	337,52	339,45	310,17				
	Kratzer 5-15 cm	360,50	423,95	371,04	439,34	412,67					
	Frontgrill	gebrochen	462,93	384,20	423,22	684,16	797,60	388,65	717,90	526,07	
		Delle >15 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83	
		Delle 5-15 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83	
		verformt	462,93	384,20	423,22	684,16	797,60	388,65	717,90	526,07	
		gestriffen 2-5 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83	
		gestriffen 5-15 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83	
		fehlt	462,93	384,20	423,22	684,16	797,60	388,65	717,90	526,07	
		Kratzer >15 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83	
		Kratzer 2-5 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83	
	Kratzer 5-15 cm	462,93	384,20	423,22	660,92	774,36	388,65	694,66	502,83		
	Nebelscheinwerfer links	gebrochen	204,54	218,42	281,07	179,95	248,75	239,78			
		verformt	204,54	218,42	281,07	179,95	248,75	239,78			
		fehlt	204,54	218,42	281,07	179,95	248,75	239,78			
	Wischerarm vorn links	gebrochen	103,93	103,30	134,22	138,31	163,69	121,13	163,88	280,22	
		verformt	103,93	103,30	134,22	138,31	163,69	121,13	163,88	280,22	
		fehlt	103,93	103,30	134,22	138,31	163,69	121,13	163,88	280,22	
	Wischerblatt vorn links	gebrochen	72,91	69,36	79,22	84,97	123,69	63,01			
		verformt	72,91	69,36	79,22	84,97	123,69	63,01			
		fehlt	72,91	69,36	79,22	84,97	123,69	63,01			
	Nebelscheinwerfer rechts	gebrochen	240,02	223,71	281,07	179,95	248,75	239,78			
		verformt	240,02	223,71	281,07	179,95	248,75	239,78			
		fehlt	240,02	223,71	281,07	179,95	248,75	239,78			
	Wischerarm vorn rechts	gebrochen	107,71	105,21	128,41	149,40	170,51	135,34	220,11	394,47	
		verformt	107,71	105,21	128,41	149,40	170,51	135,34	220,11	394,47	
		fehlt	107,71	105,21	128,41	149,40	170,51	135,34	220,11	394,47	
	Wischerblatt vorn rechts	gebrochen	70,25	68,75	79,24	84,97	123,69	63,01			
		verformt	70,25	68,75	79,24	84,97	123,69	63,01			
		fehlt	70,25	68,75	79,24	84,97	123,69	63,01			
	Abschleppöse Abdeckung vorn	gebrochen	177,97	181,11	168,04	226,40	166,64	27,69	42,81	162,77	
		verformt	177,97	181,11	168,04	226,40	166,64	27,69	42,81	162,77	
		fehlt	177,97	181,11	168,04	226,40	166,64	27,69	42,81	162,77	
	Scheinwerfer links	gebrochen	687,52	949,63	1364,14	1712,88	2224,26	646,40	2197,49	1757,58	
		verformt	687,52	949,63	1364,14	1712,88	2224,26	646,40	2197,49	1757,58	
		fehlt	687,52	949,63	1364,14	1712,88	2224,26	646,40	2197,49	1757,58	
	Kennzeichen Vorn	gebrochen	35,54	34,36	35,69	39,68	39,33	33,04	44,97	44,97	
		verformt	35,54	34,36	35,69	39,68	39,33	33,04	44,97	44,97	
		fehlt	35,54	34,36	35,69	39,68	39,33	33,04	44,97	44,97	
	Scheinwerfer rechts	gebrochen	687,52	949,63	1364,14	1712,88	2224,26	646,40	2197,49	1757,58	
		verformt	687,52	949,63	1364,14	1712,88	2224,26	646,40	2197,49	1757,58	
		fehlt	687,52	949,63	1364,14	1712,88	2224,26	646,40	2197,49	1757,58	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury	Kleinbusse		
	Unterbodenverkleidung	gebrochen	203,44	219,15	204,28	385,07	351,35	281,83	313,01	460,19
		verformt	203,44	219,15	204,28	385,07	351,35	281,83	313,01	460,19
		fehlt	203,44	219,15	204,28	385,07	351,35	281,83	313,01	460,19
	Windschutzscheibe	gebrochen	925,29	1082,36	1183,83	1257,14	1605,56	1342,16	1499,27	1948,55
Fahrzeugheck	Heckschloss / Heckoeffner	gebrochen	123,85	162,96	155,36	221,57	224,24	327,81	198,71	212,01
		verformt	123,85	162,96	155,36	221,57	224,24	327,81	198,71	212,01
		fehlt	123,85	162,96	155,36	221,57	224,24	327,81	198,71	212,01
	Heckklappe	gebrochen	2003,58	2335,35	2776,83	2839,94	3044,65	3481,20	2988,27	4364,19
		Delle >15 cm	1516,42	1641,60	1826,15	1729,11	1856,47	2186,48	1632,56	1689,90
		Delle 5-15 cm	1273,11	1351,50	1476,28	1480,50	1649,33	1893,94	1472,91	1530,25
		verformt	2003,58	2335,35	2776,83	2839,94	3044,65	3481,20	2988,27	4364,19
		gestrichen 2-5 cm	461,20	479,17	542,13	602,73	699,40	897,67	640,69	661,10
		gestrichen 5-15 cm	554,68	633,07	758,19	762,07	930,90	1175,51	754,48	811,82
		Kratzer >15 cm	638,34	763,52	948,48	851,03	978,39	1308,40	754,48	811,82
		Kratzer 2-5 cm	461,20	479,17	542,13	602,73	699,40	897,67	640,69	661,10
		Kratzer 5-15 cm	554,68	633,07	758,19	762,07	930,90	1175,51	754,48	811,82
	Tuergriff Hecktuer/Heckklappe	gebrochen	178,55	331,45	361,34	285,20	369,13	248,14		171,24
		verformt	178,55	331,45	361,34	285,20	369,13	248,14		171,24
		fehlt	178,55	331,45	361,34	285,20	369,13	248,14		171,24
Fahrzeugheck	Heckspoiler oben	gebrochen	559,63	869,64	640,59	1174,53	932,07			
		Delle >15 cm	1261,30	1372,79	1181,95	1408,67	1598,85			
		Delle 5-15 cm	1100,73	1213,14	1022,39	1248,60	1420,75			
		verformt	559,63	869,64	640,59	1174,53	932,07			
		gestrichen 2-5 cm	250,72	377,46	259,02	359,46	410,75			
		gestrichen 5-15 cm	382,30	494,71	304,34	530,17	702,32			
		Kratzer >15 cm	383,22	494,71	304,34	530,59	720,77			
		Kratzer 2-5 cm	250,72	377,46	259,02	359,46	410,75			
	Kratzer 5-15 cm	382,30	494,71	304,34	530,17	702,32				
	Markenemblem hinten	gebrochen	80,07	92,37	112,13	137,50	82,15	96,75	74,99	87,29
		verformt	80,07	92,37	112,13	137,50	82,15	96,75	74,99	87,29
		fehlt	80,07	92,37	112,13	137,50	82,15	96,75	74,99	87,29
	Stossfaenger hinten	gebrochen	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55
		Delle >15 cm	1086,26	1335,14	1547,05	1708,72	1662,73	1154,14	1710,47	1763,61
		Delle 5-15 cm	1086,26	1335,14	1387,48	1518,08	1555,24	1154,14	1550,82	1603,96
		verformt	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55
		gestrichen 2-5 cm	480,34	530,03	490,64	563,19	599,77	603,11	570,87	618,18
		gestrichen 5-15 cm	602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53
		fehlt	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55
		Kratzer >15 cm	611,64	686,05	669,38	830,64	873,48	810,25	832,39	885,53
		Kratzer 2-5 cm	480,34	530,03	490,64	563,19	599,77	603,11	570,87	618,18
	Kratzer 5-15 cm	602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
	Stossfaenger hinten mitte	gebrochen	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55
		Delle >15 cm	1086,26	1335,14	1547,05	1708,72	1662,73	1154,14	1710,47	1763,61
		Delle 5-15 cm	1086,26	1335,14	1387,48	1518,08	1555,24	1154,14	1550,82	1603,96
		verformt	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55
		gestrichen 2-5 cm	480,34	530,03	490,64	563,19	599,77	603,11	570,87	618,18
gestrichen 5-15 cm		602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
Kratzer >15 cm		1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
Kratzer 2-5 cm		602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
Kratzer 5-15 cm	611,64	686,05	669,38	830,64	873,48	810,25	832,39	885,53		
Zierleiste Stossfaenger hinten	gebrochen	500,79	369,75	516,75	428,99	514,70	153,82	711,74	1448,01	
	verformt	500,79	369,75	516,75	428,99	514,70	153,82	711,74	1448,01	
	fehlt	500,79	369,75	516,75	428,99	514,70	153,82	711,74	1448,01	
Stossfaengerecke hinten rechts	gebrochen	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
	Delle >15 cm	1086,26	1335,14	1547,05	1708,72	1662,73	1154,14	1710,47	1763,61	
	Delle 5-15 cm	1086,26	1335,14	1387,48	1518,08	1555,24	1154,14	1550,82	1603,96	
	verformt	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
	gestrichen 2-5 cm	480,34	530,03	490,64	563,19	599,77	603,11	570,87	618,18	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
		gestrichen 5-15 cm	602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
		Kratzer >15 cm	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
		Kratzer 2-5 cm	602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
		Kratzer 5-15 cm	611,64	686,05	669,38	830,64	873,48	810,25	832,39	885,53	
	Spoilerlippe hint. (unterh.Stossf.)	gebrochen	265,69	428,15	368,83	619,49	604,16				
		Delle >15 cm	265,69	428,15	368,83	619,49	604,16				
		Delle 5-15 cm	265,69	428,15	368,83	619,49	604,16				
		verformt	265,69	428,15	368,83	619,49	604,16				
		gestrichen 2-5 cm	324,21	400,98	381,45	410,47	367,15				
		gestrichen 5-15 cm	422,14	455,42	509,66	537,22	515,04				
		fehlt	265,69	428,15	368,83	619,49	604,16				
		Kratzer >15 cm	422,14	455,42	509,66	614,49	515,04				
		Kratzer 2-5 cm	324,21	400,98	381,45	410,47	367,15				
		Kratzer 5-15 cm	422,14	455,42	509,66	537,22	515,04				
		Stossfaenger Spoiler hinten	gebrochen	265,69	428,15	368,83	619,49	604,16			
	Delle >15 cm		265,69	428,15	368,83	619,49	604,16				
	Delle 5-15 cm		265,69	428,15	368,83	619,49	604,16				
	verformt		265,69	428,15	368,83	619,49	604,16				
	gestrichen 2-5 cm		265,69	400,98	368,83	410,47	367,15				
	gestrichen 5-15 cm		265,69	428,15	368,83	537,22	515,04				
	fehlt		265,69	428,15	368,83	619,49	604,16				
	Kratzer >15 cm		265,69	428,15	368,83	614,49	515,04				
	Kratzer 2-5 cm		265,69	400,98	368,83	410,47	367,15				
	Kratzer 5-15 cm	265,69	428,15	368,83	537,22	515,04					
	Hecktuerscheibe hinten links	gebrochen	240,25	255,21	283,82	302,70	523,67	1008,86			
		verformt	240,25	255,21	283,82	302,70	523,67	1008,86			
	Nebelschlussleuchte links	gebrochen	159,61	189,09	168,66	230,99	444,54	152,58			
		verformt	159,61	189,09	168,66	230,99	444,54	152,58			
		fehlt	159,61	189,09	168,66	230,99	444,54	152,58			
Fahrzeugheck	Rueckleuchte links	gebrochen	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
		verformt	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
		fehlt	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
	Kennzeichen Hinten	gebrochen	35,54	34,36	35,69	39,68	39,33	33,04	44,97	44,97	
		verformt	35,54	34,36	35,69	39,68	39,33	33,04	44,97	44,97	
		fehlt	35,54	34,36	35,69	39,68	39,33	33,04	44,97	44,97	
	Kennzeichenbeleuchtung hinten	gebrochen	91,35	102,31	95,06	107,83	120,23	103,51	61,06	61,06	
		verformt	91,35	102,31	95,06	107,83	120,23	103,51	61,06	61,06	
		fehlt	91,35	102,31	95,06	107,83	120,23	103,51	61,06	61,06	
	Hecktuerscheibe hinten rechts	gebrochen	226,57	248,77	283,80	302,65	522,38	823,79			
		verformt	226,57	248,77	283,80	302,65	522,38	823,79			
	Nebelschlussleuchte rechts	gebrochen	158,80	182,59	143,33	230,99	406,24	152,58			
		verformt	158,80	182,59	143,33	230,99	406,24	152,58			
		fehlt	158,80	182,59	143,33	230,99	406,24	152,58			
	Rueckleuchte rechts	gebrochen	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
		verformt	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
		fehlt	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
	Heckscheibe	gebrochen	819,06	813,92	1229,31	1065,46	1158,82	788,40			
		verformt	819,06	813,92	1229,31	1065,46	1158,82	788,40			
	Abschleppoese Abdeckung hinten	gebrochen	228,70	107,89	146,18	296,26	152,34		159,51	168,74	
		verformt	228,70	107,89	146,18	296,26	152,34		159,51	168,74	
	Wischerarm hinten	gebrochen	85,78	78,86	81,75	91,37	88,05	132,83			
		verformt	85,78	78,86	81,75	91,37	88,05	132,83			
		fehlt	85,78	78,86	81,75	91,37	88,05	132,83			
	Wischerblatt hinten	gebrochen	48,20	47,08	45,08	37,56	46,63	49,38			
		verformt	48,20	47,08	45,08	37,56	46,63	49,38			
		fehlt	48,20	47,08	45,08	37,56	46,63	49,38			
Hecktürverriegelung rechts	gebrochen	115,97				23,92	180,37				
	verformt	115,97				23,92	180,37				
	fehlt	115,97				23,92	180,37				

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
	3.Bremsleuchte	gebrochen	124,64	145,74	132,82	216,31	181,51	159,65	209,43	209,43	
		verformt	124,64	145,74	132,82	216,31	181,51	159,65	209,43	209,43	
		fehlt	124,64	145,74	132,82	216,31	181,51	159,65	209,43	209,43	
	Stossfaengerecke hinten links	gebrochen	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
		Delle >15 cm	1086,26	1335,14	1547,05	1708,72	1662,73	1154,14	1710,47	1763,61	
		Delle 5-15 cm	1086,26	1335,14	1387,48	1518,08	1555,24	1154,14	1550,82	1603,96	
		verformt	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
		gestriffen 2-5 cm	480,34	530,03	490,64	563,19	599,77	603,11	570,87	618,18	
		gestriffen 5-15 cm	602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
		Kratzer >15 cm	1086,26	1335,14	1746,47	1765,32	1662,73	1154,14	1894,93	2075,55	
		Kratzer 2-5 cm	602,06	682,80	669,38	799,65	836,81	790,56	832,39	885,53	
	Kratzer 5-15 cm	611,64	686,05	669,38	830,64	873,48	810,25	832,39	885,53		
Innenraum	Teppich Kofferraum	verschmutzt/Fleck	188,98	328,87	215,70	337,74	352,37	846,57	287,37	155,17	
		Dachhimmel innen	Brandloch	1147,69	954,44	1071,40	1468,04	2310,27	1739,64	2108,80	2095,50
		Schnitt / Riss		1147,69	954,44	1071,40	1468,04	2310,27	1739,64	2108,80	2095,50
	verschmutzt/Fleck	1147,69		931,20	1048,16	1421,56	2263,79	1716,40	2062,32	2049,02	
	Armaturentafel komplett	gebrochen	1631,14	1883,72	2041,22	2449,28	2320,10	1283,10	2490,09	2637,45	
		Teppich vorn	Brandloch	809,25	858,18	1177,95	1157,42	1671,59	1025,79	953,99	863,86
			Schnitt / Riss	809,25	858,18	1177,95	1157,42	1671,59	1025,79	953,99	863,86
	verschmutzt/Fleck		786,01	834,94	1154,71	1134,18	1648,35	1025,79	953,99	863,86	
	Teppich hinten	Brandloch		596,01	1018,65	991,26	1274,67	909,27	898,19	928,51	
		Schnitt / Riss		596,01	1018,65	991,26	1274,67	909,27	898,19	928,51	
		verschmutzt/Fleck		596,01	995,41	968,02	1251,43	909,27	874,95	905,27	
	Teppich vorn+hinten	Brandloch	809,25	914,57	1217,79	1544,08	2164,91	1931,41	1875,42	1815,61	
		Schnitt / Riss	809,25	914,57	1217,79	1544,08	2164,91	1931,41	1875,42	1815,61	
		verschmutzt/Fleck	786,01	891,33	1194,55	1520,84	2118,43	1908,17	1828,94	1769,13	
	Fensterheber vorn links	gebrochen	142,92	163,19	176,94	222,03	190,87	158,81	316,08	180,22	
		fehlt	142,92	163,19	176,94	222,03	190,87	158,81	316,08	180,22	
	Fahrersitz Rueckenlehne	Brandloch	406,64	563,13	619,36	662,10	917,09	717,69	604,97	547,95	
		Schnitt / Riss	406,64	563,13	619,36	662,10	917,09	717,69	604,97	547,95	
		fehlt	406,64	563,13	619,36	662,10	917,09	717,69	604,97	547,95	
		verschmutzt/Fleck	406,64	563,13	619,36	662,10	917,09	717,69	604,97	547,95	
	Fahrersitz Sitzflaeche	Brandloch	384,64	519,04	678,90	730,13	854,46	714,31	673,02	1045,42	
		Schnitt / Riss	384,64	519,04	678,90	730,13	854,46	714,31	673,02	1045,42	
		fehlt	384,64	519,04	678,90	730,13	854,46	714,31	673,02	1045,42	
		verschmutzt/Fleck	384,64	519,04	678,90	706,89	854,46	714,31	649,78	1022,18	
	Sicherheitsgurt vorn links (Fahrer)	gebrochen	369,49	354,30	452,92	584,99	575,57	356,38	620,07	909,68	
		fehlt	369,49	354,30	452,92	584,99	575,57	356,38	620,07	909,68	
	Innenraum	Beifahrersitz Rueckenlehne	Brandloch	422,35	584,79	620,79	658,01	837,61	687,53	604,97	547,95
			Schnitt / Riss	422,35	584,79	620,79	658,01	837,61	687,53	604,97	547,95
fehlt			422,35	584,79	620,79	658,01	837,61	687,53	604,97	547,95	
verschmutzt/Fleck			422,35	584,79	620,79	658,01	837,61	687,53	604,97	547,95	
Beifahrersitzflaeche		Brandloch	365,41	493,89	680,55	851,63	868,31	665,62	686,32	1912,25	
		Schnitt / Riss	365,41	493,89	680,55	851,63	868,31	665,62	686,32	1912,25	
		fehlt	365,41	493,89	680,55	851,63	868,31	665,62	686,32	1912,25	
		verschmutzt/Fleck	365,41	493,89	680,55	828,39	868,31	665,62	663,08	1889,01	
Fensterheber vorn rechts		gebrochen	79,61	93,27	125,95	123,50	99,13	48,98	166,45	84,78	
		fehlt	79,61	93,27	125,95	123,50	99,13	48,98	166,45	84,78	
Sicherheitsgurt vorn rechts (Beif.)		gebrochen	341,71	343,10	452,90	583,81	573,58	363,15	620,07	833,23	
		fehlt	341,71	343,10	452,90	583,81	573,58	363,15	620,07	833,23	
Schaltknaf		gebrochen	178,08	227,17	222,95	151,15	145,36	179,79			
		fehlt	178,08	227,17	222,95	151,15	145,36	179,79			
Handschuhfach Klappe		gebrochen	350,74	251,17	387,10	437,74	492,37	233,85	880,56	575,10	
		fehlt	350,74	251,17	387,10	437,74	492,37	233,85	880,56	575,10	
Himmel (Dachinnenverkleidung)		Brandloch	1147,69	954,44	1071,40	1468,04	2310,27	1739,64	2108,80	2095,50	
		Schnitt / Riss	1147,69	954,44	1071,40	1468,04	2310,27	1739,64	2108,80	2095,50	
		verschmutzt/Fleck	1147,69	931,20	1048,16	1421,56	2263,79	1716,40	2062,32	2049,02	
Innenbeleuchtung		gebrochen	214,40	162,30	142,32	414,65	437,98	329,93		534,83	
		fehlt	214,40	162,30	142,32	414,65	437,98	329,93		534,83	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
	Innenraumreinigung	verschmutzt/Fleck	200,00	200,00	200,00	200,00	200,00	200,00	200,00	200,00	200,00
	Airbag Abdeckung links	gebrochen	668,03	531,98	636,63	540,97	566,23	418,56	391,88	412,59	
		fehlt	668,03	531,98	636,63	540,97	566,23	418,56	391,88	412,59	
	Tuergriff vorn links innen	gebrochen	85,50	124,58	183,61	162,91	200,36	136,79	182,10	160,07	
		fehlt	85,50	124,58	183,61	162,91	200,36	136,79	182,10	160,07	
	Tuergriff hinten links innen	gebrochen	78,86	119,65	150,91	165,13	180,85	88,72			
		fehlt	78,86	119,65	150,91	165,13	180,85	88,72			
	Lichtschalter	gebrochen	149,35	121,71	119,37	277,95	185,53	167,75	116,41	408,19	
		fehlt	149,35	121,71	119,37	277,95	185,53	167,75	116,41	408,19	
	Fensterheber hinten links	gebrochen	65,79	82,27	85,48	114,89	157,10			57,07	
		fehlt	65,79	82,27	85,48	114,89	157,10			57,07	
	Ruecksitz links Rueckenlehne	Brandloch	393,08	489,73	534,47	631,69	756,70	285,01	660,00	595,79	
		Schnitt / Riss	393,08	489,73	534,47	631,69	756,70	285,01	660,00	595,79	
		fehlt	393,08	489,73	534,47	631,69	756,70	285,01	660,00	595,79	
		verschmutzt/Fleck	393,08	489,73	534,47	631,69	756,70	285,01	660,00	572,55	
	Ruecksitz links Sitzflaeche	Brandloch		229,72	571,63	772,27	658,29	1004,09	448,07	385,39	
		Schnitt / Riss		229,72	571,63	772,27	658,29	1004,09	448,07	385,39	
		fehlt		229,72	571,63	772,27	658,29	1004,09	448,07	385,39	
		verschmutzt/Fleck		229,72	571,63	772,27	658,29	980,85	448,07	385,39	
	Sicherheitsgurt hinten links	gebrochen	338,47	356,71	400,25	399,13	553,99	792,49	554,08	521,58	
		fehlt	338,47	356,71	400,25	399,13	553,99	792,49	554,08	521,58	
	Ruecksitz rechts Rueckenlehne	Brandloch	383,19	495,32	614,28	593,55	760,11	303,89	709,85	506,03	
		Schnitt / Riss	383,19	495,32	614,28	593,55	760,11	303,89	709,85	506,03	
		fehlt	383,19	495,32	614,28	593,55	760,11	303,89	709,85	506,03	
		verschmutzt/Fleck	383,19	495,32	614,28	593,55	760,11	303,89	686,61	506,03	
	Ruecksitz rechts Sitzflaeche	Brandloch		204,22	540,85	596,21	563,71	970,00	448,07	372,08	
		Schnitt / Riss		204,22	540,85	596,21	563,71	970,00	448,07	372,08	
		fehlt		204,22	540,85	596,21	563,71	970,00	448,07	372,08	
		verschmutzt/Fleck		204,22	540,85	596,21	563,71	946,76	448,07	372,08	
	Fensterheber hinten rechts	gebrochen	65,79	82,30	85,07	112,60	157,74			57,07	
		fehlt	65,79	82,30	85,07	112,60	157,74			57,07	
	Sicherheitsgurt hinten rechts	gebrochen	339,41	350,98	400,09	399,32	570,89	782,28	580,69	548,19	
		fehlt	339,41	350,98	400,09	399,32	570,89	782,28	580,69	548,19	
	Innen-Rueckblickspegel	gebrochen	152,79	284,28	234,17	387,85	351,99	198,00	471,10	765,47	
		fehlt	152,79	284,28	234,17	387,85	351,99	198,00	471,10	765,47	
	Airbag Abdeckung rechts	gebrochen	674,91	530,97	642,76	530,74	566,68	525,24	391,88	412,59	
		fehlt	674,91	530,97	642,76	530,74	566,68	525,24	391,88	412,59	
	Tuergriff vorn rechts innen	gebrochen	85,58	124,13	183,76	162,84	199,67	138,06	182,10	160,07	
		fehlt	85,58	124,13	183,76	162,84	199,67	138,06	182,10	160,07	
	Tuergriff hinten rechts innen	gebrochen	76,66	117,13	150,77	164,48	182,82	133,32			
		fehlt	76,66	117,13	150,77	164,48	182,82	133,32			
	Lenkrad	gebrochen	643,51	705,35	860,70	1103,89	924,01	950,87	1791,33	1729,99	
		fehlt	643,51	705,35	860,70	1103,89	924,01	950,87	1791,33	1729,99	
	Bordwerkzeug	gebrochen	85,57	52,94	27,19	16,48	29,17	71,46			
		fehlt	85,57	52,94	27,19	16,48	29,17	71,46			
	Display (Navi/Radio)	gebrochen									
Linke Seite	Radhausverkleidung vorne links	gebrochen	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		Delle >15 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		Delle 5-15 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		verformt	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		gestriffen 2-5 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		gestriffen 5-15 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		fehlt	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		Kratzer >15 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		Kratzer 2-5 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
		Kratzer 5-15 cm	136,75	203,87	169,46	197,04	231,26	165,27	246,99	248,65	
	Tuer Vorn links	gebrochen	2464,56	2623,52	3091,10	3188,79	3461,64	3446,90	3928,59	4388,80	
		Delle >15 cm	2262,06	2282,39	2336,85	2354,54	2565,31	2911,38	2538,61	2582,73	
		Delle 5-15 cm	1665,66	1667,04	1712,54	1795,47	1898,20	2139,62	1982,23	2002,03	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
		verformt	2464,56	2623,52	3091,10	3188,79	3461,64	3446,90	3928,59	4388,80	
		gestrichen 2-5 cm	510,34	495,96	510,76	601,05	620,18	697,17	709,98	717,83	
		gestrichen 5-15 cm	947,23	948,61	994,44	1077,04	1179,77	1421,19	1263,80	1283,60	
		Kratzer >15 cm	1383,98	1404,31	1459,17	1476,46	1687,23	2033,30	1660,53	1704,65	
		Kratzer 2-5 cm	510,34	495,96	510,76	601,05	620,18	697,17	709,98	717,83	
		Kratzer 5-15 cm	947,23	948,61	994,44	1077,04	1179,77	1421,19	1263,80	1283,60	
	Tuergriff vorn links	gebrochen	314,18	272,42	256,69	226,52	291,08	135,56	90,86	90,86	
		verformt	314,18	272,42	256,69	226,52	291,08	135,56	90,86	90,86	
		fehlt	314,18	272,42	256,69	226,52	291,08	135,56	90,86	90,86	
	Tuerschloss vorn links	gebrochen	285,17	323,91	342,56	417,91	427,91	369,09	477,14	490,44	
		verformt	285,17	323,91	342,56	417,91	427,91	369,09	477,14	490,44	
		fehlt	285,17	323,91	342,56	417,91	427,91	369,09	477,14	490,44	
	Zierleiste Tuer vorn links	gebrochen	382,72	293,62	319,97	224,54	216,29	262,94			
		verformt	382,72	293,62	319,97	224,54	216,29	262,94			
		fehlt	382,72	293,62	319,97	224,54	216,29	262,94			
	Blinker vorn links	gebrochen	109,50	86,74	88,57	243,95	147,85	39,81			
		verformt	109,50	86,74	88,57	243,95	147,85	39,81			
		fehlt	109,50	86,74	88,57	243,95	147,85	39,81			
	Innenkotfluegel Vorn links	gebrochen	61,87	67,21		66,79	71,35	103,11			
		verformt	61,87	67,21		66,79	71,35	103,11			
		fehlt	61,87	67,21		66,79	71,35	103,11			
	Tuerscheibe vorn links	gebrochen	253,62	231,21	249,72	302,71	361,64	243,50	302,20	397,72	
		verformt	253,62	231,21	249,72	302,71	361,64	243,50	302,20	397,72	
	Kotfluegel Vorn links	gebrochen	1725,64	1740,82	1854,35	2006,26	2222,94	2132,84	2130,02	2219,61	
		Delle >15 cm	2075,57	2019,35	2054,04	2140,54	2232,35	2506,78	2313,77	2368,71	
		Delle 5-15 cm	1529,47	1504,33	1535,02	1629,75	1661,01	1807,75	1757,39	1788,01	
		verformt	1725,64	1740,82	1854,35	2006,26	2222,94	2132,84	2130,02	2219,61	
		gestrichen 2-5 cm	413,98	389,56	399,31	490,76	463,07	464,15	545,38	550,09	
		gestrichen 5-15 cm	811,04	785,90	816,92	911,32	942,58	1089,32	1038,96	1069,58	
		fehlt	1725,64	1740,82	1854,35	2006,26	2222,94	2132,84	2130,02	2219,61	
		Kratzer >15 cm	1197,49	1141,27	1176,37	1262,46	1354,27	1628,70	1435,69	1490,63	
		Kratzer 2-5 cm	413,98	389,56	399,31	490,76	463,07	464,15	545,38	550,09	
		Kratzer 5-15 cm	811,04	785,90	816,92	911,32	942,58	1089,32	1038,96	1069,58	
	B-Saeule links	gebrochen	2616,98	3607,81	5746,76	4510,01	5656,85	5178,26	9931,50		
		Delle >15 cm	1307,16	1566,08	1712,85	1545,76	1563,66	1537,40			
		Delle 5-15 cm	1119,08	1334,76	1485,89	1340,62	1400,88	1360,31			
		verformt	2616,98	3607,81	5746,76	4510,01	5656,85	5178,26	9931,50		
		gestrichen 2-5 cm	319,19	453,82	576,88	510,04	562,61	524,86			
		gestrichen 5-15 cm	400,65	616,33	767,80	622,19	682,45	641,88			
		Kratzer >15 cm	429,08	688,00	835,18	667,68	685,58	659,32			
		Kratzer 2-5 cm	319,19	453,82	576,88	510,04	562,61	524,86			
		Kratzer 5-15 cm	400,65	616,33	767,80	622,19	682,45	641,88			
	A-Saeule links	gebrochen	3372,10	4549,95	4672,61	4843,40	4177,14	4946,83	7888,77	5627,39	
		Delle >15 cm	1327,97	1486,09	1639,61	1388,60	1527,36	1747,76	1437,43	1232,80	
		Delle 5-15 cm	1126,76	1274,52	1362,66	1199,63	1344,79	1555,84	1277,78	1073,15	
		verformt	3372,10	4549,95	4672,61	4843,40	4177,14	4946,83	7888,77	5627,39	
		gestrichen 2-5 cm	329,54	427,33	505,92	425,51	512,71	689,84	487,08	258,42	
		gestrichen 5-15 cm	408,33	556,09	644,23	481,20	626,36	837,41	559,35	354,72	
		Kratzer >15 cm	449,89	608,01	761,53	510,52	649,28	869,68	559,35	354,72	
		Kratzer 2-5 cm	329,54	427,33	505,92	425,51	512,71	689,84	487,08	258,42	
		Kratzer 5-15 cm	408,33	556,09	644,23	481,20	626,36	837,41	559,35	354,72	
Linke Seite	Seitenwand vorn links	gebrochen						8512,96			
		Delle >15 cm						3399,00			
		Delle 5-15 cm						2528,66			
		verformt						8512,96			
		gestrichen 2-5 cm						883,23			

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
		gestrichen 5-15 cm						1810,23			
		Kratzer >15 cm						2520,92			
		Kratzer 2-5 cm						883,23			
		Kratzer 5-15 cm						1810,23			
	Tankverschluss links	gebrochen	54,60	49,68	37,33	23,42	33,04	47,83	18,62	39,72	
		fehlt	54,60	49,68	37,33	23,42	33,04	47,83	18,62	39,72	
	Tankklappe links	gebrochen	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		verformt	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		gestrichen 2-5 cm	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		gestrichen 5-15 cm	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		fehlt	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
	Aussenspiegelverkleidung links	gebrochen	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		Delle >15 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		Delle 5-15 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		verformt	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		gestrichen 2-5 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		gestrichen 5-15 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		fehlt	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		Kratzer >15 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		Kratzer 2-5 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
		Kratzer 5-15 cm	184,97	238,55	298,29	283,84	223,53	167,77	132,86	132,86	
	Aussenspiegel links	gebrochen	432,51	410,65	433,73	632,62	640,34	632,00	798,75	609,57	
		verformt	432,51	410,65	433,73	632,62	640,34	632,00	798,75	609,57	
	Spiegelglas Aussenspiegel links	gebrochen	102,87	112,23	257,93	362,81	287,07	98,67	424,11	424,11	
		verformt	102,87	112,23	257,93	362,81	287,07	98,67	424,11	424,11	
		fehlt	102,87	112,23	257,93	362,81	287,07	98,67	424,11	424,11	
	A-Saeule Verkleidung links	Delle >15 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
		Delle 5-15 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
		gestrichen 2-5 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
		gestrichen 5-15 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
		Kratzer >15 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
		Kratzer 2-5 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
		Kratzer 5-15 cm	90,05	84,92	18,58	125,78	78,54		300,57	238,32	
	Spiegelblinker links	gebrochen	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
		verformt	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
		fehlt	321,60	313,88	334,10	408,63	428,07	171,84	368,25	425,13	
	C-Saeule links	gebrochen		919,09		1220,56	5857,06	8908,97			
		Delle >15 cm		919,09		1220,56	1388,77	1424,59			
		Delle 5-15 cm		759,44		1060,91	1229,12	1264,94			
		verformt		919,09		1220,56	5857,06	8908,97			
		gestrichen 2-5 cm		41,01		342,48	510,69	546,51			
		gestrichen 5-15 cm		41,01		342,48	510,69	546,51			
		Kratzer >15 cm		41,01		342,48	510,69	546,51			
		Kratzer 2-5 cm		41,01		342,48	510,69	546,51			
		Kratzer 5-15 cm		41,01		342,48	510,69	546,51			
	Seitenwand hinten links	gebrochen	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		Delle >15 cm	2173,13	2280,99	2454,31	2359,21	2631,51	3583,84	2579,15	2698,38	
		Delle 5-15 cm	1561,39	1687,65	1890,26	1815,80	1991,42	2763,62	2022,77	2117,68	
		verformt	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		gestrichen 2-5 cm	400,28	494,21	617,76	630,01	730,27	1140,46	777,91	830,82	
		gestrichen 5-15 cm	842,96	969,22	1172,16	1097,37	1272,99	2045,19	1304,34	1399,25	
		Kratzer >15 cm	1295,05	1402,91	1576,64	1481,13	1753,43	2705,76	1701,07	1820,30	
		Kratzer 2-5 cm	400,28	494,21	617,76	630,01	730,27	1140,46	777,91	830,82	
		Kratzer 5-15 cm	842,96	969,22	1172,16	1097,37	1272,99	2045,19	1304,34	1399,25	
	Tuerschweller links	gebrochen	4350,43	3495,27	4018,56	4807,82	4884,03	3899,39	10351,19		
		verformt	4350,43	3495,27	4018,56	4807,82	4884,03	3899,39	10351,19		
	Schiebetuer links	gebrochen					3927,58	4213,39			
		Delle >15 cm					2753,55	2558,03			
		Delle 5-15 cm					2006,62	1861,30			
		verformt					3927,58	4213,39			
		gestrichen 2-5 cm					680,45	552,44			

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
		gestrichen 5-15 cm						1288,19	1142,87		
		Kratzer >15 cm						1875,47	1679,95		
		Kratzer 2-5 cm						680,45	552,44		
		Kratzer 5-15 cm						1288,19	1142,87		
Linke Seite	Schiebetuerscheibe links	gebrochen	422,57	391,68	730,49	614,96	676,31	1182,17	390,59	440,56	
		verformt	422,57	391,68	730,49	614,96	676,31	1182,17	390,59	440,56	
	Kunststoff Heckverkleidung L	gebrochen					4128,31	6237,13			
		verformt					4128,31	6237,13			
		gestrichen 2-5 cm					450,62	387,60			
		gestrichen 5-15 cm					930,73	930,21			
		fehlt					4128,31	6237,13			
	Radhausverkleidung hinten links	gebrochen	131,56	277,54	169,52	611,17	622,14	1358,26	156,81	151,26	
		Delle >15 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
		Delle 5-15 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
		verformt	131,56	277,54	169,52	611,17	622,14	1358,26	156,81	151,26	
		gestrichen 2-5 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
		gestrichen 5-15 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
		fehlt	131,56	277,54	169,52	611,17	622,14	1358,26	156,81	151,26	
		Kratzer >15 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
		Kratzer 2-5 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
		Kratzer 5-15 cm	131,56	277,54	169,52	587,93	598,90	1288,54	156,81	151,26	
	Tuer Hinten links	gebrochen	2376,44	2549,62	3052,78	3098,15	3660,01				
		Delle >15 cm	2191,04	2218,24	2277,51	2286,00	2391,53				
		Delle 5-15 cm	1621,46	1624,84	1676,53	1739,87	1803,89				
		verformt	2376,44	2549,62	3052,78	3098,15	3660,01				
		gestrichen 2-5 cm	480,65	469,53	483,58	557,48	580,51				
		gestrichen 5-15 cm	903,03	906,41	958,43	1021,44	1085,46				
		Kratzer >15 cm	1312,96	1340,16	1399,84	1407,92	1513,45				
		Kratzer 2-5 cm	480,65	469,53	483,58	557,48	580,51				
	Kratzer 5-15 cm	903,03	906,41	958,43	1021,44	1085,46					
	Tuergummi (Dichtung) hinten links	gebrochen	121,26	123,16	193,78	305,84	249,68	160,38			
		verformt	121,26	123,16	193,78	305,84	249,68	160,38			
		fehlt	121,26	123,16	193,78	305,84	249,68	160,38			
	Tuergriff hinten links	gebrochen	313,51	229,74	237,71	207,33	309,37	180,59			
		verformt	313,51	229,74	237,71	207,33	309,37	180,59			
		fehlt	313,51	229,74	237,71	207,33	309,37	180,59			
	Tuerscheibe hinten links	gebrochen	240,25	255,21	283,82	302,70	523,67	1008,86			
		verformt	240,25	255,21	283,82	302,70	523,67	1008,86			
	Innenkotfluegel Hinten links	gebrochen	85,30	60,82	61,19	30,90	83,44	77,76			
		verformt	85,30	60,82	61,19	30,90	83,44	77,76			
		fehlt	85,30	60,82	61,19	30,90	83,44	77,76			
	Kotfluegel Hinten links	gebrochen	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		Delle >15 cm	2173,13	2280,99	2454,31	2359,21	2631,51	3583,84	2579,15	2698,38	
		Delle 5-15 cm	1561,39	1687,65	1890,26	1815,80	1991,42	2763,62	2022,77	2117,68	
		verformt	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		gestrichen 2-5 cm	400,28	494,21	617,76	630,01	730,27	1140,46	777,91	830,82	
gestrichen 5-15 cm		842,96	969,22	1172,16	1097,37	1272,99	2045,19	1304,34	1399,25		
fehlt		4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92		
Kratzer >15 cm		1295,05	1402,91	1576,64	1481,13	1753,43	2705,76	1701,07	1820,30		
Kratzer 2-5 cm		400,28	494,21	617,76	630,01	730,27	1140,46	777,91	830,82		
Kratzer 5-15 cm		842,96	969,22	1172,16	1097,37	1272,99	2045,19	1304,34	1399,25		
Seitenblinker/Seitenreflektor links	gebrochen	132,75	114,72	95,67	135,66	138,14	64,44	118,35	140,04		
	verformt	132,75	114,72	95,67	135,66	138,14	64,44	118,35	140,04		
	fehlt	132,75	114,72	95,67	135,66	138,14	64,44	118,35	140,04		
Räder/Bereifung	Notrad	gebrochen	224,31	155,88	158,82	270,98	155,00	153,75			
		Schnitt / Riss	224,31	155,88	158,82	270,98	155,00	153,75			
		fehlt	224,31	155,88	158,82	270,98	155,00	153,75			
		Loch	224,31	155,88	158,82	270,98	155,00	153,75			
	Alu Radnabe vorn links	gebrochen	36,72	22,19	23,15	36,40	21,96	41,64	68,65	15,43	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Cabrio Full Size/ Premium	Cabrio Luxury	
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury	Kleinbusse			
		verformt	36,72	22,19	23,15	36,40	21,96	41,64	68,65	15,43	
		gestrichen 2-5 cm	136,33	137,42							
		gestrichen 5-15 cm	136,33	137,42							
		fehlt	36,72	22,19	23,15	36,40	21,96	41,64	68,65	15,43	
	Alufelge Vorn links	gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
		gestrichen >15 cm									
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		Reifen Vorn links	gebrochen	224,51	189,76	157,66	203,33	166,99	153,82		300,00
			Schnitt / Riss	224,51	189,76	157,66	203,33	166,99	153,82		300,00
	Loch		224,51	189,76	157,66	203,33	166,99	153,82		300,00	
	Stahlfelge vorn links	gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
Räder/Bereifung		Alu Radnabe vorn rechts	gebrochen	36,72	21,60	22,95	36,31	21,26	41,64	68,65	15,43
			verformt	36,72	21,60	22,95	36,31	21,26	41,64	68,65	15,43
			gestrichen 2-5 cm	136,33	135,63						
	gestrichen 5-15 cm		136,33	135,63							
	Alufelge Vorn rechts	gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
	Stahlfelge vorn rechts	gestrichen >15 cm									
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
	Reifen Vorn rechts	gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		Schnitt / Riss	224,51	189,76	157,66	203,33	166,99	153,82		300,00	
	Reifen Hinten links	Loch	224,51	189,76	157,66	203,33	166,99	153,82		300,00	
		gebrochen	212,49	188,56	157,66	256,15	166,99	153,82		300,00	
		Schnitt / Riss	212,49	188,56	157,66	256,15	166,99	153,82		300,00	
		Loch	212,49	188,56	157,66	256,15	166,99	153,82		300,00	
	Alufelge Hinten links	gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
	Stahlfelge hinten links	gestrichen >15 cm									
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
		verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
	Alufelge hinten rechts	gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
		gestrichen >15 cm									
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
	Reifen Hinten rechts	gebrochen	212,49	188,56	157,66	256,15	166,99	153,82		300,00	
		Schnitt / Riss	212,49	188,56	157,66	256,15	166,99	153,82		300,00	
		Loch	212,49	188,56	157,66	256,15	166,99	153,82		300,00	
		gebrochen	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
	Stahlfelge hinten rechts	verformt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
		gestrichen 2-5 cm	147,87	160,66	175,67	185,31	186,74	181,21	189,13	189,13	
		gestrichen 5-15 cm	184,88	203,72	177,97	231,02	232,79	213,35	197,08	197,08	
		fehlt	379,26	455,57	582,05	681,63	793,66	246,96	931,97	1064,83	
Rechte Seite	Radhausverkleidung vorne rechts	gebrochen	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		Delle >15 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		Delle 5-15 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		verformt	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		gestrichen 2-5 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		gestrichen 5-15 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		fehlt	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		Kratzer >15 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		Kratzer 2-5 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
		Kratzer 5-15 cm	136,38	203,90	185,35	193,13	228,66	165,27	239,36	216,92	
	Tuer Vorn rechts	gebrochen	2464,56	2623,52	3091,10	3188,79	3461,64	3446,90	3928,59	4388,80	
		Delle >15 cm	2262,06	2282,39	2336,85	2354,54	2565,31	2911,38	2538,61	2582,73	
		Delle 5-15 cm	1665,66	1667,04	1712,54	1795,47	1898,20	2139,62	1982,23	2002,03	
		verformt	2464,56	2623,52	3091,10	3188,79	3461,64	3446,90	3928,59	4388,80	
		gestrichen 2-5 cm	510,34	495,96	510,76	601,05	620,18	697,17	709,98	717,83	
		gestrichen 5-15 cm	947,23	948,61	994,44	1077,04	1179,77	1421,19	1263,80	1283,60	
		Kratzer >15 cm	1383,98	1404,31	1459,17	1476,46	1687,23	2033,30	1660,53	1704,65	
		Kratzer 2-5 cm	510,34	495,96	510,76	601,05	620,18	697,17	709,98	717,83	
	Tuergriff vorn rechts	gebrochen	314,47	270,18	253,18	220,10	294,62	129,13	90,86	90,86	
		verformt	314,47	270,18	253,18	220,10	294,62	129,13	90,86	90,86	
		fehlt	314,47	270,18	253,18	220,10	294,62	129,13	90,86	90,86	
	Zierleiste Tuer vorn rechts	gebrochen	382,72	292,93	321,25	229,11	216,71	269,66			
		verformt	382,72	292,93	321,25	229,11	216,71	269,66			
		fehlt	382,72	292,93	321,25	229,11	216,71	269,66			
	Rechte Seite	Blinker vorn rechts	gebrochen	109,50	86,74	88,12	266,09	147,85	39,81		
			verformt	109,50	86,74	88,12	266,09	147,85	39,81		
			fehlt	109,50	86,74	88,12	266,09	147,85	39,81		
		Innenkotfluegel Vorn rechts	gebrochen	61,87	67,08		66,79	72,48	103,28		
			verformt	61,87	67,08		66,79	72,48	103,28		
			fehlt	61,87	67,08		66,79	72,48	103,28		
Tuerscheibe vorn rechts		gebrochen	264,96	228,30	249,72	303,39	351,27	238,53	302,20	397,72	
		verformt	264,96	228,30	249,72	303,39	351,27	238,53	302,20	397,72	
Kotfluegel Vorn rechts		gebrochen	1725,64	1740,82	1854,35	2006,26	2222,94	2132,84	2130,02	2219,61	
		Delle >15 cm	2075,57	2019,35	2054,04	2140,54	2232,35	2506,78	2313,77	2368,71	
		Delle 5-15 cm	1529,47	1504,33	1535,02	1629,75	1661,01	1807,75	1757,39	1788,01	
		verformt	1725,64	1740,82	1854,35	2006,26	2222,94	2132,84	2130,02	2219,61	
		gestrichen 2-5 cm	413,98	389,56	399,31	490,76	463,07	464,15	545,38	550,09	
		gestrichen 5-15 cm	811,04	785,90	816,92	911,32	942,58	1089,32	1038,96	1069,58	
		fehlt	1725,64	1740,82	1854,35	2006,26	2222,94	2132,84	2130,02	2219,61	
		Kratzer >15 cm	1197,49	1141,27	1176,37	1262,46	1354,27	1628,70	1435,69	1490,63	
		Kratzer 2-5 cm	413,98	389,56	399,31	490,76	463,07	464,15	545,38	550,09	
		Kratzer 5-15 cm	811,04	785,90	816,92	911,32	942,58	1089,32	1038,96	1069,58	
Kunststoff Heckverkleidung R		gebrochen					4143,67	5633,36			
		verformt					4143,67	5633,36			
		gestrichen 2-5 cm					457,36	387,60			
		gestrichen 5-15 cm					930,73	930,21			
		fehlt					4143,67	5633,36			
Radhausverkleidung hinten rechts		gebrochen	135,41	276,85	169,61	615,11	620,62	1358,26	156,81	151,26	
		Delle >15 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26	
		Delle 5-15 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26	
		verformt	135,41	276,85	169,61	615,11	620,62	1358,26	156,81	151,26	
		gestrichen 2-5 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26	
		gestrichen 5-15 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26	
		fehlt	135,41	276,85	169,61	615,11	620,62	1358,26	156,81	151,26	
	Kratzer >15 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26		
	Kratzer 2-5 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26		
	Kratzer 5-15 cm	135,41	276,85	169,61	591,87	597,38	1288,54	156,81	151,26		

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
	Tuer Hinten rechts	gebrochen	2376,44	2549,62	3052,78	3098,15	3660,01				
		Delle >15 cm	2191,04	2218,24	2277,51	2286,00	2391,53				
		Delle 5-15 cm	1621,46	1624,84	1676,53	1739,87	1803,89				
		verformt	2376,44	2549,62	3052,78	3098,15	3660,01				
		gestriffen 2-5 cm	480,65	469,53	483,58	557,48	580,51				
		gestriffen 5-15 cm	903,03	906,41	958,43	1021,44	1085,46				
		Kratzer >15 cm	1312,96	1340,16	1399,84	1407,92	1513,45				
		Kratzer 2-5 cm	480,65	469,53	483,58	557,48	580,51				
		Kratzer 5-15 cm	903,03	906,41	958,43	1021,44	1085,46				
	Tuergummi (Dichtung) hinten rechts	gebrochen	121,28	123,16	193,27	305,82	250,65	198,58			
		verformt	121,28	123,16	193,27	305,82	250,65	198,58			
		fehlt	121,28	123,16	193,27	305,82	250,65	198,58			
	Tuergriff hinten rechts	gebrochen	316,78	233,69	238,03	208,65	314,74	112,48			
		verformt	316,78	233,69	238,03	208,65	314,74	112,48			
		fehlt	316,78	233,69	238,03	208,65	314,74	112,48			
	Tuerscheibe hinten rechts	gebrochen	226,57	248,77	283,80	302,65	522,38	823,79			
		verformt	226,57	248,77	283,80	302,65	522,38	823,79			
	Innenkotfluegel Hinten rechts	gebrochen	85,30	60,82	61,19	30,90	83,44	77,76			
		verformt	85,30	60,82	61,19	30,90	83,44	77,76			
		fehlt	85,30	60,82	61,19	30,90	83,44	77,76			
	Kotfluegel Hinten rechts	gebrochen	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		Delle >15 cm	2173,13	2280,99	2454,31	2359,21	2631,51	3583,84	2579,15	2698,38	
		Delle 5-15 cm	1561,39	1687,65	1890,26	1815,80	1991,42	2763,62	2022,77	2117,68	
		verformt	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		gestriffen 2-5 cm	400,28	494,21	617,76	630,01	730,27	1140,46	777,91	830,82	
		gestriffen 5-15 cm	842,96	969,22	1172,16	1097,37	1272,99	2045,19	1304,34	1399,25	
		fehlt	4093,56	4833,19	7134,36	6570,99	7613,34	10755,73	7616,00	7775,92	
		Kratzer >15 cm	1295,05	1402,91	1576,64	1481,13	1753,43	2705,76	1701,07	1820,30	
		Kratzer 2-5 cm	400,28	494,21	617,76	630,01	730,27	1140,46	777,91	830,82	
	Kratzer 5-15 cm	842,96	969,22	1172,16	1097,37	1272,99	2045,19	1304,34	1399,25		
	Spiegelblinker rechts	gebrochen	328,75	309,74	333,08	405,51	427,87	173,81	368,25	425,13	
		verformt	328,75	309,74	333,08	405,51	427,87	173,81	368,25	425,13	
		fehlt	328,75	309,74	333,08	405,51	427,87	173,81	368,25	425,13	
	Rechte Seite	B-Saeule rechts	gebrochen	2616,98	3607,81	5746,76	4510,01	5656,85	5178,26	9931,50	
			Delle >15 cm	1307,16	1566,08	1712,85	1545,76	1563,66	1537,40		
			Delle 5-15 cm	1119,08	1334,76	1485,89	1340,62	1400,88	1360,31		
			verformt	2616,98	3607,81	5746,76	4510,01	5656,85	5178,26	9931,50	
			gestriffen 2-5 cm	319,19	453,82	576,88	510,04	562,61	524,86		
			gestriffen 5-15 cm	400,65	616,33	767,80	622,19	682,45	641,88		
			Kratzer >15 cm	429,08	688,00	835,18	667,68	685,58	659,32		
			Kratzer 2-5 cm	319,19	453,82	576,88	510,04	562,61	524,86		
			Kratzer 5-15 cm	400,65	616,33	767,80	622,19	682,45	641,88		
		A-Saeule rechts	gebrochen	3372,10	4549,95	4672,61	4843,40	4177,14	4946,83	7888,77	5627,39
			Delle >15 cm	1327,97	1486,09	1639,61	1388,60	1527,36	1747,76	1437,43	1232,80
			Delle 5-15 cm	1126,76	1274,52	1362,66	1199,63	1344,79	1555,84	1277,78	1073,15
verformt			3372,10	4549,95	4672,61	4843,40	4177,14	4946,83	7888,77	5627,39	
gestriffen 2-5 cm			329,54	427,33	505,92	425,51	512,71	689,84	487,08	258,42	
gestriffen 5-15 cm			408,33	556,09	644,23	481,20	626,36	837,41	559,35	354,72	
Kratzer >15 cm			449,89	608,01	761,53	510,52	649,28	869,68	559,35	354,72	
Kratzer 2-5 cm			329,54	427,33	505,92	425,51	512,71	689,84	487,08	258,42	
Kratzer 5-15 cm			408,33	556,09	644,23	481,20	626,36	837,41	559,35	354,72	
Seitenwand vorn rechts		gebrochen						8512,96			
		Delle >15 cm						3399,00			
		Delle 5-15 cm						2528,66			
		verformt						8512,96			
		gestriffen 2-5 cm						883,23			
		gestriffen 5-15 cm						1810,23			
		Kratzer >15 cm						2520,92			

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Kleinbusse	Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury				
		Kratzer 2-5 cm						883,23			
		Kratzer 5-15 cm						1810,23			
	Tankverschluss rechts	gebrochen	54,60	49,68	37,33	23,42	33,04	47,83	18,62	39,72	
		fehlt	54,60	49,68	37,33	23,42	33,04	47,83	18,62	39,72	
	Tankklappe rechts	gebrochen	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		verformt	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		gestrichen 2-5 cm	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		gestrichen 5-15 cm	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
		fehlt	315,79	297,36	271,64	330,38	440,90	360,44	337,36	378,38	
	Aussenspiegelverkleidung rechts	gebrochen	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		Delle >15 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		Delle 5-15 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		verformt	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		gestrichen 2-5 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		gestrichen 5-15 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		fehlt	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		Kratzer >15 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		Kratzer 2-5 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
		Kratzer 5-15 cm	184,97	233,35	284,98	285,74	224,62	167,77	132,86	146,16	
	Aussenspiegel rechts	gebrochen	432,51	410,65	433,73	632,62	640,34	632,00	798,75	609,57	
		verformt	432,51	410,65	433,73	632,62	640,34	632,00	798,75	609,57	
	Spiegelglas Aussenspiegel rechts	gebrochen	102,87	112,23	257,93	362,81	287,07	98,67	424,11	424,11	
		verformt	102,87	112,23	257,93	362,81	287,07	98,67	424,11	424,11	
		fehlt	102,87	112,23	257,93	362,81	287,07	98,67	424,11	424,11	
	A-Saeule Verkleidung rechts	Delle >15 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
		Delle 5-15 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
		gestrichen 2-5 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
		gestrichen 5-15 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
		Kratzer >15 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
		Kratzer 2-5 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
		Kratzer 5-15 cm	87,15	84,85	18,58	125,78	78,54		300,57	238,32	
	C-Saeule rechts	gebrochen		919,09		1220,56	5857,06	8908,97			
		Delle >15 cm		919,09		1220,56	1388,77	1424,59			
		Delle 5-15 cm		759,44		1060,91	1229,12	1264,94			
		verformt		919,09		1220,56	5857,06	8908,97			
		gestrichen 2-5 cm		41,01		342,48	510,69	546,51			
		gestrichen 5-15 cm		41,01		342,48	510,69	546,51			
		Kratzer >15 cm		41,01		342,48	510,69	546,51			
		Kratzer 2-5 cm		41,01		342,48	510,69	546,51			
		Kratzer 5-15 cm		41,01		342,48	510,69	546,51			
Rechte Seite	Seitenwand hinten rechts	gebrochen	4108,09	4852,82	7156,87	6635,92	7791,24	9825,84	7607,60	7900,57	
		Delle >15 cm	2173,66	2284,47	2454,31	2366,25	2633,99	3385,31	2594,18	2713,40	
		Delle 5-15 cm	1561,39	1690,39	1890,26	1822,85	1992,53	2598,92	2037,80	2132,70	
		verformt	4108,09	4852,82	7156,87	6635,92	7791,24	9825,84	7607,60	7900,57	
		gestrichen 2-5 cm	400,28	496,78	617,76	640,97	733,47	1111,95	777,91	845,84	
		gestrichen 5-15 cm	842,96	971,96	1172,16	1104,42	1274,10	1880,49	1319,37	1414,27	
		Kratzer >15 cm	1295,58	1406,39	1576,64	1488,17	1755,91	2507,23	1716,10	1835,32	
		Kratzer 2-5 cm	400,28	496,78	617,76	640,97	733,47	1111,95	777,91	845,84	
		Kratzer 5-15 cm	842,96	971,96	1172,16	1104,42	1274,10	1880,49	1319,37	1414,27	
	Tuerschweller rechts	gebrochen	4364,53	3536,04	4073,33	4546,80	4737,86	4403,48	10342,79		
		verformt	4364,53	3536,04	4073,33	4546,80	4737,86	4403,48	10342,79		
	Schiebetuer rechts	gebrochen					3924,36	4049,65			
		Delle >15 cm					2753,55	2968,99			
		Delle 5-15 cm					2006,62	2192,48			
		verformt					3924,36	4049,65			
		gestrichen 2-5 cm					680,45	734,14			
		gestrichen 5-15 cm					1288,19	1474,05			
		Kratzer >15 cm					1875,47	2090,91			
		Kratzer 2-5 cm					680,45	734,14			
	Kratzer 5-15 cm					1288,19	1474,05				
Schiebetuerscheibe rechts	gebrochen	423,85	394,90	727,69	658,50	676,38	1207,09	390,59	440,56		

Direkte Schadenregulierung - Europcar PKW Preisliste

Bereich	Element	Schadenart	Kategorie						Cabrio Full Size/ Premium	Cabrio Luxury
			Mini/ Economy	Compact	Intermediate/ Standard	Full Size/ Premium	Luxury	Kleinbusse		
		verformt	423,85	394,90	727,69	658,50	676,38	1207,09	390,59	440,56
	Seitenblinker/Seitenreflektor Re.	gebrochen	135,36	114,55	95,67	135,59	138,01	64,44	118,35	140,04
		verformt	135,36	114,55	95,67	135,59	138,01	64,44	118,35	140,04
		fehlt	135,36	114,55	95,67	135,59	138,01	64,44	118,35	140,04
Zubehör	Wagenheber	gebrochen	92,55	67,31	73,38	114,22	102,50	125,23	108,47	108,47
	Sonderreinigung	verschmutzt/Fleck	200,00	200,00	200,00	200,00	200,00	200,00	200,00	200,00