

VIN # X14 HKBE 8356

~~19,000~~ 19,000

BD

- 1) ALL SMOG EQUIP. PURCH/INSTALLED
  - 2) NEW WIRING LOOM (ENG. COMPARTMENT)
  - 3) NEW CARBURETOR
  - 4) NEW GENERATOR
  - 5) NEW MUFFLERS / TAILPIPES
  - 6) NEW(2) MAIN/AUX. FUEL TANKS, SENDING UNITS, SWITCHES & HOSES
  - 7) NEW HEATER COIL, BLOWER & CABLES
  - 8) NEW CLUSTER GAUGES & LIGHTS
  - 9) NEW IGNITION SWITCH & LIGHT SWITCH
  - 10) HORN FIXED
  - 11) EMERG. BRAKE FIXED
  - 12) NEW REAR BRAKES & CYLINDERS
  - 13) NEW MASTER CYLINDER
  - 14) NEW TONNEAU TOP
- (ALL RECIEPTS FOR ABOVE WORK)
- NEW FRONT SEATBELTS
- NEW FRONT/REAR ALL WEATHER FLOOR MATS
- 15) REPLACED ELECTRONIC IGNITION w/ STD. DIST. & COIL



# on's Muffler and Automotive

## REPAIR ORDER

No 451807

Bar No. ARD 00293338  
 Located at Blosser Lane and Highway 20  
 850 Blosser Lane • Willits, CA 95490  
 Phone (707) 459-3549 • Fax (707) 459-0942

NAME

OPERATION	
MAINTENANCE INSPECTION	<input type="checkbox"/>
LUBRICATION	<input type="checkbox"/>

# n's Muffler and Automotive

## REPAIR ORDER

No 451538

Bar No. ARD 00293338  
 Located at Blosser Lane and Highway 20  
 850 Blosser Lane • Willits, CA 95490  
 Phone (707) 459-3549 • Fax (707) 459-0942

NAME

OPERATION	
MAINTENANCE INSPECTION	<input type="checkbox"/>
LUBRICATION	<input type="checkbox"/>

\* CODE N=NEW U=USED R=REBUILT

ADDRESS

# uffler and Automotive

## REPAIR ORDER

No 451245

Bar No. ARD 00293338

OPERATION

# uffler and Automotive

## REPAIR ORDER

No 45430

Bar No. ARD 00293338  
 Blosser Lane and Highway 20  
 Blosser Lane • Willits, CA 95490  
 Phone (707) 459-3549 • Fax (707) 459-0942

# and Automotive

## REPAIR ORDER

No 45207

00293338

# and Automotive

## REPAIR ORDER

No 45397

00293338  
 Lane and Highway 20  
 • Willits, CA 95490  
 • Fax (707) 459-0942

U=USED R=REBUILT

OR DESCRIPTION

SALE AMOUNT

NAME

ADDRESS

CITY

DATE

WHEN PROMISED

PHONE

YEAR / MAKE / MODEL

LICENSE NO

MILEAGE

WRITTEN BY

OPERATION

MAINTENANCE INSPECTION

LUBRICATION

CHANGE OIL GRADE

CHANGE OIL FILTER CART

TRANS

DIFF

DESCRIPTION OF WORK

AMOUNT

under motor 6021

13 14

25 68

10 08

heat core, blower, cables, wiper brush  
 light switch ~~over~~ amp meter, Dome light  
 replace all dash lights

IN  
 4  
 Org

Phone  
 B-Name  
 B-Addr.

513-6379





# D.C. Customs, INC.

3301 N. State St.  
Ukiah, CA 95482

Phone #7074632227

Fax # (707) 463-2228

ARB#00242210

EPA#CAL000331085

Business Lic#112883

## Invoice

Date	Invoice #
9/12/2022	195776

**PAID**  
**10/13/2022**

NO RETURNS AFTER 30 DAYS FROM SHIP  
DATE

Bill To:

Date Scheduled: 10/12/22

If paying by Credit Card a 3% Convenience Fee will be added.

Sales Rep	Emailed/Faxed	P.O. #	License	VIN#	Odometer
CBM					
Part #	Qty.	Description	U/M	Rate	Amount
JRF1290	1	1978 Ford F-150		1,393.00	1,393.00T
	1	Pace Edwards Manual Retractable Tonneau Cover Black Aluminum		21.00	21.00
	1	Shipping		130.00	260.00
	2	Installation-Labor			

SHIPPING: Charges will be added to invoice after parts arrive.

RETURNS: If a change must be made to an order, please contact us immediately. Items may be returned if unused within 30 days from time they are received, with 25% re-stocking fee. Freight & Shipping is non-refundable. Prices may go up from time of estimate.

Warranties-30 Day Warranty General Labor rate is \$130 per hour w/1 hr min.

I hereby authorize the above repair work and necessary materials to complete the job and grant you and/or your employees permission to operate my vehicle for the purpose of the (inspection &/or testing, etc.). I hereby acknowledge the express mechanics lien on my vehicle if this job is not paid in full at time of completion. All vehicles left over 48hrs after time of completion will incur a \$25.00 per day storage fee.

I am aware that I am responsible for wrong or missing carry in parts.

I am aware that truck cover hardware can loosen up over time and should be checked regularly.

I am aware that truck covers are not guaranteed to be leak proof.

I understand that I am responsible for the retorquing of my lug nuts after 25 miles.

I understand that special order parts are not returnable and in some cases may take a while to get.

Subtotal	\$1,674.00
Sales Tax (7.875%)	\$109.70
Total	\$1,783.70
Payments/Credits	-\$1,783.70
Balance Due	\$0.00

All take off parts left after completion of job are considered to be forfeited by customer. Please pick them up or make arrangements at time of job completion.

Signature:

Date:

Athorized In Person:

Towed In:

Phone:

\$30.00 dollar fee on all returned checks. Finance Charge of 1.8% on all unpaid balances after 30 days.



FUEL TANK

**Subject** Order Confirmation  
**From** <customerservice@radiatorexpress.com>  
**To:**  
**Date** Today at 10:15 AM



Thank you for purchasing with RadiatorExpress.com.  
Feel free to log-in via our website to check the status of  
your order and receive great deals on additional items!!!

Order Summary Below:

**Order ID:** 198946  
**Order Date:** 2/17/2022 1:15:20 PM  
**Shipped To:**

FUEL TANK  
\$ 412.09

**Card:**

**Order Stage:** Order received, ready to be processed

Order Recap - Order #: 198946

Qty	Item	Unit Price	Total
1	FUEL TANK 20.2 GALLON, TWO GAUGE HOLES	\$339.90	\$339.90
		Subtotal:	\$339.90
		Shipping:	\$45.00
		Tax:	\$27.19
		<b>TOTAL:</b>	<b>\$412.09</b>



DEALER # 42737  
4001 Forest St  
Denver, Colorado 80216  
TEL: 877-422-1570

## SALES CONTRACT AND INVOICE

SALES PERSON: Ryan Corrick  
STOCK NO.: LCC1232

Buyer's Name:		Date: 1/8/2022	
Address:		Yr. and Make: 1978 Ford	
City/State/Zip:		Model: F-150 Supercab	Body: PK
Phone No.:		Color: Red	Mileage: Exempt
License No.:	Dealer #:	VIN/Serial: X14HKBE8356	
Date of Birth:	Business EIN:	Advertising Source:	
Trade In:		Selling Price	\$24,501.00
Yr. and Make:	Model:	Trade-in	\$0.00
VIN/Serial:	Mileage:	Sub Total	\$24,501.00
Due List:		RTD	\$0.00
Deposit Info:		State Tax	\$0.00
Shipping (Diff. than listed on title):		Processing Fee	\$399.00
		Shipping	\$0.00
		Total	\$24,900.00
		Deposit with Order	\$500.00
Finance Co:		Cash On Delivery	\$24,400.00

Seller maintains ownership of the title to Vehicle until Buyer pays the full purchase price. **DEPOSIT 500.00**  
By signing this agreement, the Buyer warrants that Buyer is eighteen years of age or older and has all legal right to purchase this Vehicle. **24,900**

Buyer hereby agrees to fully insure the Vehicle, effective the date of purchase from Seller, and will timely provide proof of sufficient insurance.

Buyer agrees to verbally confirm wire instructions with WWVA before sending payment.


Buyer understands this vehicle is being sold emissions exempt and has checked with Buyer's local state on emissions requirements.

☒ I have carefully reviewed, understand, and have had the opportunity to ask questions about the Vehicle Inspection and Warranty Agreement (Attachment A).

☒ I have carefully reviewed, understand, and have had the opportunity to ask questions about the Dispute Agreement (Attachment B).

☒ I have carefully reviewed, understand, and have had the opportunity to ask questions about the Vehicle Delivery Agreement (Attachment C).

I have carefully reviewed the terms of this Buyer's Order Invoice, including all the Attachments identified above and expressly incorporated into the sales contract. I understand and agree to be bound by these terms.

BUYER'S SIGNATURE 

WWVA MANAGER'S SIGNATURE

DocuSigned by:

Ryan Corrick

54E0BF2E4E604E8



DFM Auto Repair  
575 S State St.  
Ukiah, CA. 95482  
Phone: 707-462-3008

INVOICE

44882

Org. Est. # 047048  
BAR ARD#0081847  
EPA #CAL000099093

Printed Date: 09/08/2022

Work Completed: 09/08/2022

1978 Ford - Cab & Chassis F150 - 6.6L, V8 (400CI) VIN(S)

Lic # : ..

Odometer In : 6319

VIN # : X14HKBE8356

Hat # : 201

on / Number	Qty	Sale	Ext	Labor Description	Ext
				Flush Brake Fluid includes: Remove fluid from master cylinder, refill with fresh fluid, bleed brake system and top off Master Cylinder with fresh brake fluid. Test drive to verify brake operation	68.00
				QA Drive	n/c
				Quality Assurance Drive	

Revisions 1,174.25 Current Estimate 1,258.20

ount: 83.95 Additional Cost: 191.00 Revised Estimate: 274.95, Parts: \$0.00 Labor: \$191.00 Sublet: \$0.00 Taxes  
planis, ron, Date - 8/23/2022, Time - 9:57 AM, Initiated By - Shop, Written By - Kessen, Dillan, Reason - smog diag  
g  
ount: 274.95 Additional Cost: 491.59 Revised Estimate: 766.54, Parts: \$123.15 Labor: \$357.50 Sublet: \$0.00  
- karaglanis, ron, Date - 8/24/2022, Time - 11:25 AM, Initiated By - Shop, Written By - Kessen, Dillan, Reason -  
ber - Cell 707-513-6379  
ount: 758.29 Additional Cost: 118.69 Revised Estimate: 876.98, Parts: \$109.01 Labor: \$0.00 Sublet: \$0.00 Taxes  
anis, ron, Date - 8/24/2022, Time - 3:02 PM, Initiated By - Shop, Written By - Kessen, Dillan, Reason - intake  
ell 707-513-6379

nt: 897.45 Additional Cost: 299.02 Revised Estimate: 1196.47, Parts: \$92.78 Labor: \$198.00 Sublet: \$0.00  
araglanis, Ron, Date - 9/1/2022, Time - 4:02 PM, Initiated By - Shop, Written By - Kessen, Dillan, Reason -  
707-513-6379

Labor:	880.40
Parts:	285.71
SubTotal:	1,166.11
Tax:	24.64
Total:	1,190.75
Bal Due:	\$0.00

1978 FORD DOCUMENTS



Vehicle must return for warranty work. Parts and labor warranted 90 days, however some manufacturers provide additional parts warranties. Electrical parts cannot be warranted. Please pay from invoice. Accounts payable in 10 days. 112% Service Charge on all Past Due Accounts. VEHICLES NOT PICKED UP WITHIN THREE DAYS OF COMPLETION OF WORK WILL BE CHARGED \$25 PER DAY STORAGE.

**WARRANTIES:** Vehicle must return for warranty work. Parts and labor warranted 90 days, however some manufacturers provide additional parts warranties. Once installed, electrical parts cannot be warranted. Please pay from invoice. Accounts payable in 10 days. 1 1/2% Service Charge on all Past Due Accounts.

**VEHICLES NOT PICKED UP WITHIN THREE DAYS OF COMPLETION OF WORK WILL BE CHARGED \$25 PER DAY STORAGE.**

WHITE - OFFICE      CANARY - CUSTOMER

days, however some manufacturers provide additional parts warranties.  
 is payable in 10 days. 1 1/2% Service Charge on all Past Due Accounts.  
 OF WORK WILL BE CHARGED \$25 PER DAY STORAGE.

WHITE - OFFICE      CANARY - CUSTOMER

ily, replace both  
 clamps, install  
 mast, replace all  
 ⑦ one in heater  
 and state switch, wipers  
 light bulb  
 8.4K 1000.00

ON			
3 KR.	Total Labor	1000.00	
BY	Total Parts	109.11	
BY	Hazardous Waste Fee	6.00	
	Sublet Repairs		
	Sales Tax	99.6	
	Please Pay This Amount	1125.67	

urers provide additional parts warranties.  
 Service Charge on all Past Due Accounts.  
 RGED \$25 PER DAY STORAGE.

Y - CUSTOMER





# Smog Check Vehicle Inspection Report (VIR)



www.esp-global.com

www.autorepair.ca.gov

Test Date/Time: 09/01/2022@09:52:39

Model Year: 1978

License: NONE

Engine Size: 6.60 L

GVWR: 5999

Odometer: 6319

Fuel Type: Gasoline

Make: FORD

State: XX

Type: Truck

Test Weight: N/A

Certification: Federal

Exhaust: Single

Model: F150 PICKUP

VIN: X14HKBE8356

Transmission: Automatic

Cylinders: 8

VLT Record #: 12027

Inspection Reason: Initial Registration

## Vehicle Information

## Overall Test Results

Thank you for performing the needed emissions-related repairs to your vehicle. These repairs help California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air.

Smog Check Certificate Number: IP631230

DMV ID Number: 5149P731I786

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Pass	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Not applicable	Catalytic Converter	Pass	Air Injection	Not applicable	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Pass	EGR Functional	Pass	Ignition Timing: PB12	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Not applicable	Wiring to Sensors	Not applicable	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

## Idle Emission Test Results

Idle Emission Test Results										
		%CO2	%O2	HC (PPM)			CO (%)			
	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
	945	13.4	0.6	250	73	202	2.50	0.50	1.93	Pass
0 RPM	2539	11.8	4.2	200	67	69	3.00	0.90	0.57	Pass
= Maximum Allowable Emissions				AVE = Average Emissions For 5						

= Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Actions

Leaks (Engine Mechanical) Rep  
Manifold (Engine Mechanical) Rep

## Repair Costs

Total Repair Time: 4.3 hours  
Emission-Related Repairs (Parts): \$247  
Emission-Related Repairs (Labor): \$325  
Tamper Repairs (Parts and Labor): \$0  
Estimated Costs of Additional Repairs: \$0  
Hourly Labor Rate: \$0  
Emission-Related Repairs (Parts - LIRAP): \$0  
Emission-Related Repairs (Labor - LIRAP): \$0

## Smog Check Inspection Station Information

Technician Name/Number:

Repair Tech Name/Number:

Software Version/EIS Number:

CHADWICK, GEORGE/EO042487

CHADWICK, GEORGE/EO042487

2201 / EP727748

AGE INC  
St. Ukiah CA 95482

008  
Number: RC081847

Under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate. Repairs performed on this vehicle were not tamper related.

Technician's Signature



**DFM Auto Repair**  
575 S State St.  
Ukiah, CA. 95482  
Phone: 707-462-3008

INVOICE

44882

Org. Est. # 047  
BAR ARD#0081  
EPA #CAL000099

INVOICE

Printed Date: 09/08/2022

Work Completed: 09/08/2022

1978 Ford - Cab & Chassis F150 - 6.6L, V8 (400CI) VIN(S)  
Lic # : .. Odometer In : 6

VIN # : X14HKBE8356

Hat # :



Part Description / Number	Qty	Sale	Ext	Labor Description
Manifold Gasket Set - Intake NEW MS96020	1.00	103.15	103.15	Smog Inspection 1995 and older Perform appropriate smog inspection for vehicle.
Carburetor Gasket NEW 60716	1.00	18.98	18.98	Reason For Smog:
Antifreeze - Regular Green - Concentrate - 1 gal NEW 1GAL	1.00	25.99	25.99	Pass ____ Failed _X_ Diagnostic Phase 1
Oil Filter - ProSelect - Master Pack 21515MP	1.00	6.86	6.86	Diagnostics includes a test drive to verify customers complaint (if needed or possible) followed by a preliminary inspection. We then retrieve data from the engine control unit. (if applicable) The next step is any needed inspections of the electronic engine controls, fuel and ignition system. (if applicable) Plus complaint specific diagnostics using available data and equipment. Note: if components need to be removed to test additional charges may occur. You will be notified for approval prior to removal.
5w30 Motor Oil 1 Qt - New 5w30Blend	5.00	6.99	34.95	Diagnostics is the process of elimination. We verify the correct operation of systems involved. Once it is determined which system is not working correctly, we then have to test components within the affected system until a problem is found and a solution is arrived at. This must then be corrected before it is possible to know if this is the entire problem or just one facet of the problem. To arrive at the complete solution may be multifaceted. We will keep you informed. After repairs note: Some diagnostic codes prevent other codes from being set. (if applicable) After diagnosing and repairing codes present on arrival the engine management system may identify further codes that will need to be diagnosed. (if applicable) The system may reset either right away or at a later date, if this happens, additional diagnostic fees may occur.
Smog Certificate Pre 2K SCPre2K	1.00	8.25	8.25	
Brake Master Cylinder - New M2405	1.00	74.08	74.08	Checked for Vac leaks Found intake manifold leaking on passenger side Need to remove and replace intake manifold gasket then recheck for any other issues
Hazardous Waste WBF	1.00	2.95	2.95	
DOT 4 Brake Fluid - 6oz NEW BF	2.00	5.25	10.50	

\$ 1,190<sup>75</sup>

**INTAKE MANIFOLD GASKET - Remove & Replace -**  
V8,400CID Eng

removed and replaced intake manifold gasket

Checked Tp readings after OK

Test drive OK

Brake master cylinder is covered in fluid and vehicle is hard to

**Express Oil Change Plus**

We recommend changing oil every 3500 miles, your manufacturer may have a different recommended interval, if you would like a different interval than we use let us know and your reminder sticker will reflect as such.



17301 W 113th  
800-562-8782  
913-541-0684  
913-599-0323

www.LM

**O'Reilly** AUTO PARTS  
PROFESSIONAL PARTS PEOPLE

**MC  
RUCK**

ORD  
DAT

Shin To

ORDER #

W5429915

LOCATION

L02 01 00

L03 09 00

L03 11 02

L03 11 04

L03 12 04

M02 14 02

M03 07 05

M03 07 05

M04 07 01

M04 07 01

N01 04 06

N01 07 05

O02 07 02

O03 08 04

Store hours:

Mon-Sat: 07:30 AM-09:00 PM

Sun: 08:00 AM-08:00 PM

Counter #: 477321

STEVE

Date: 04/19/2022 10:01 AM

Drawer: 6

Invoice #: 5545-488883

TMC 2-889

299.99 T

CARBURETOR

90 DAY LIMITED WARRANTY

TMC 2-889 Core Charge

30.00 T

TMC 2-889 Core Exchange

-30.00 T

FEL 60716

6.99 T

CARB GSKT

1978 Ford F-150

MMM 8011

14.99 T

ADHESIVE

MMM 8008

14.99 T

ADHESIVE

4 Items

**CARBURETOR**

Sub-Total 336.96

Senior Discount: -6.74

Sales Tax 30.13

Total 360.35

Cash 361.00

Change Due .65

PAYMENT

MEN

SELECTOR ✓

VER MOTOR ✓

VE ✓

REGULATOR ✓

RATURE ✓

RATURE ✓

R ✓

R ✓

COOL WHITE ✓

5"H x 6"W ✓

R ✓

MITTENT ✓

\$1 261

W5429915

15

Regular - L02

Run# 63: 90 of 2

**LONG  
MOTOR  
CORPORATION.**

main hub in shopping at  
O'Reilly Auto Parts!

AVAILABLE.

CANCELLED, REORDER IN 3-4 WEEKS.

Y), PART HAS BEEN CANCELLED

Y AT A FUTURE DATE.

PLETED OR NO MANUFACTURER.

STD



## 1978 Ford F-150 Super

Engine: 400 CID V8  
 Transmission: Automatic  
 Color: RED  
 Interior: Red  
 Mileage: 5,965  
 Stock #: LCC1232.2

### DRIVETRAIN

Engine Size: 400 CID V8  
 Transmission Type: Automatic  
**CHASSIS**

### BODY

Body Color Original: No  
 Stripes: No

### DEALER INFO

tel: (877) 422-1570 (tel: (877) 422-1570)  
 Worldwide Vintage Autos  
 4001 Forest St  
 Denver CO, 80216

**SPEEDDIGITAL**



**SUPERCAB F150 RANGER EXPLORER NEW 400 V8  
 AUTOMATIC 4X4 PS PB VINYL BENCH SEATS**

Worldwide Vintage Autos is one of the largest classic automobile consignment dealerships in the world. With over 200 vehicles in stock spanning over 80,000 square feet, we have what you are looking for!

We provide top tier service for both online buyers and in-person transactions. Stemming from selling over 1,000 cars per year, we have become experts in domestic and international shipping and can help you find a shipping company.

To view current inventory, you do not see INVENTORY.

### ADDITIONAL

\*New Crate 4  
 \*Automatic  
 \*Power Steer  
 \*Power Brake

### DISCLOSURE

\*Cosmetic: Th  
 \*Mechanical:  
 \*Please note t  
 motor. Addition  
 systems.  
 \*This vehicle is  
 reading.  
 \*For more deta  
 (tel: 1-877-422-

The engine size  
 like to verify bl  
 The cost of part  
 and, therefore,  
 for the future. C

Worldwide Vintage Autos have historically appreciated at a rate greater than the stock market, gold and other arts and collectibles as documented by many articles and auction result tracking.

1) RUN'S MUFFLER \$5446.78  
 2) S&S AUTO 3324.15  
 3) DFM AUTO REPAIR 1190.75  
 4) " " 572.25  
 5) D.C. CUSTOMS } 1783.70  
 TONNEAU COVER }  
 6) SMOG EQUIP 1203.00  
 7) FUEL TANKS 815.00  
 8) SHOP MANUALS } 243.00  
 (FORD) }  
**\$ 14,578.63**

Worldwide Vintage Autos [ . c o m ]  
 IPCOMING

ve.  
 d to "open up" th  
 or suspension

current odometer  
 -877-422-1570

fied. If you wou  
 making any mor

and ensure your investm



FUEL TANK  
HARDWARE  
ASSY.

Oversized Parts Fees	\$0.00
Core Charges	\$0.00
Standard Delivery & Handling	\$43.25

**Order Total (USD): \$338.15**

Customer Information:

Shipping Information:

[View or Manage Order →](#)

Questions about your order? Contact Customer Care at **1-800-562-8782**

Monday - Friday: 7:00 a.m. to 8:00 p.m. CST

Saturday: 8:00 a.m. to 6:00 p.m. CST

**Sunday: Closed**

Or email us at: **CustomerCare@longmotor.net**

Please do not reply to this message. Replies to this message are routed to an unmonitored mailbox.

**LMC  
TRUCK**  
PARTS & ACCESSORIES

LMC Truck - (800) 562-8782  
PO Box 14991  
Lenexa, KS 66285 - 4991





Name	
Addr.	
Phone	
B- Name	
B-Addr.	
B-Phone	
OTHER INFO	
V.I.N. #	X14HKBE8356

Inv. Date	04/07/22	YEAR	1978
S.O. Date	02/09/22	MAKE	FORD
QC'd by	UA	MODEL	F150
Salesman	AJ	IDENT	
Division	SS	MILES	6174
		LIC #	

Service Description		hrs.	Cost
NOT SHIFTING UNTIL HIGH RPM FOUND VACUUM MODULATOR TUBE BROKEN, REPLACE TUBE, FOUND ELECTRIC FUEL PUMP LEAKING, CUT BAD PORTION OF HOSE AND RECONNECT. NO LONGER LEAKING. VEHICLE SHIFTING NORMALLY. IDLE HIGH ADJUST DOWN.		1.00	120.00
4WD LINKAGE STIFF; INSPECT CHECK OIL LEAK ON FRONT OF ENGINE FOUND OIL LEAK COMING FROM ENGINE OIL DIPSTICK HOLE. PLUG HOLE AND RETEST NO LONGER LEAKING OIL FROM HOLE.		0.50	60.00
TRANSMISSION SERVICE T#15 INSPECT FLUID LEVEL/CONDITION. REMOVE TRANSMISSION PAN, INSPECT FOR SIGNS OF ABNORMAL DEBRIS OR OBVIOUS DAMAGE. REPLACE THE FILTER CLEAN MAGNET. REFILL TRANSMISSION WITH F-TYPE/MAXLIFE MIX.		1.50	180.00
INSTALL CUSTOMER SUPPLIED FUEL TANK FOUND CUSTOMER SUPPLIED STRAPS HAD NO ISOLATING MATERIAL, AND HARDWARE INCORRECT, INSTALL STRAPS AND BUILD CUSTOMER HARDWARE FOR FUEL TANK. FUEL TANK FILLER TUBE NOT LONG ENOUGH, STENT FUEL FILLER NECK. VEHICLE GAUGE NOW WORKING AND FUEL TANK SELECTOR VALVE WORKING.		3.50	420.00

Qty	Part Number	Part Description	Price
0	FREIGHT CHARGE		33.99
2	10702	FUEL CAP	27.90
1	E7DZ*9B593*A	VALVE ASSEMBLY	49.95
1	AIR PUMP BRACKET		89.95
6	TYPE-F	TYPE-F ATF 1QT	77.70
1	FK121	PT AUTO TRANS FILTER KIT	24.95
1	7D128	SINGLE LEAD COIL WIRE	9.95
1	242103	2 GROOVE PULLEY FORD	44.95
1	30812	PAINLESS WIRING HARNESS	149.95
2	PTF12B	HEX PLUG	13.90
1	NUTBOLTS MANIFOLD	15	10.00
1	50/50 MIX	GREEN	19.95
1	2-7053	IGNITION MODULE	39.95
1	SM11568	STREET MAX MUFFLER	154.95
1	OIL PLUG		5.95
10	A2.5	2.5 " EXHAUST PIPE	49.50
3	12JRHANG	J HANGER&INSULAT	38.85

Additional Items		Sublet or Add'l Services	
		GAS	20.01
Total Items		Total Sublets	20.01

REPAIRS RECOMMENDED
Next service due on: ???

Totals	
Labor	2388.00
Parts	842.34
Supplies	0.00
Sublets	20.01
Addl. Items	0.00
Subtotal	3250.35
Tax	73.80
<b>Total</b>	<b>3324.15</b>

(Page 1 of 3)

I acknowledge receipt and oral approval of an increase in the original estimated price.

X

REPAIRS PERFORMED WITH CUSTOMER SUPPLIED PARTS CARRY  
NO WARRANTY ON PARTS OR LABOR. SERVICE INSTALLED PARTS  
CLAIMS MUST BE SUBMITTED TO THE PART SUPPLIER BY THE  
PERSON WHO PURCHASED THE PART.

WARRANTY: From date of delivery for a period of 4,000 miles or 90 days, whichever comes first, this firm  
will repair free of charge any defects in material and workmanship to the repairs stated on this invoice. All work  
to be done in our shop only.  
This does not include towing charges.

\$ per day storage fee will be charged 24 hours after notification of work completed.

**1637 SOUTH MAIN STREET, WILLITS, CA. 95490-4313 707-459-1853**

DFM GARAGE INC  
575 S. State St. Ukiah CA 95482  
707-462-3008

**Smog Check Inspection Station Information**  
Technician Name/Number:  
Repair Tech Name/Number:

Hourly Labor Rate \$0  
Emission-Related Repairs (Parts - LIRAP) \$0  
Emission-Related Repairs (Labor - LIRAP) \$0

CHADWICK, GEORGE



UCK.com

Ship To:

DATE	CATALOG	VEHICLE	PAYMENT	METHOD OF PYMENT OR CREDIT C/		
11/05/22	FC 93	FD F1504 78				
QTY	PART	DESCRIPTION	O/S	PRICE	AMO	
2	40-2557	KNOB-HEAT/AC/TANK SELECTOR ✓		7.95	1	
1	43-2450	BLOWER FAN ✓		37.95	3	
1	43-1042	MOUNT GASKET-BLOWER MOTOR ✓		3.95		
1	43-0665	HEATER CONTROL VALVE ✓		19.95	1	
1	40-3420	CLAMP-HEATER FAN ✓		0.45		
1	43-0754	VALVE-AC/HEAT TEMP REGULATOR ✓		59.95	5	
1	40-1422	CABLE-HEATER TEMPERATURE ✓		23.95	2	
1	40-1422	CABLE-HEATER TEMPERATURE ✓		23.95	2	
1	40-1420	HEATER CABLE ASSY-AIR ✓		9.95		
1	40-1420	HEATER CABLE ASSY-AIR ✓		9.95		
1	47-0205	LED BULB-DOME LAMP-COOL WHITE ✓		12.95	1	
1	43-2524	HEATER CORE-W/O AC 6"H x 6"W ✓		34.95	3	
1	47-4268	DOME LAMP LENS-CLEAR ✓		6.95		
1	47-0659	WIPER SWITCH-W/INTERMITTENT ✓		44.95	4	

\$1 261.80

- BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE.  
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, REORDER IN 3-4 WEEKS.  
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED  
NLA - FROM ORDER, CHECK AVAILABILITY AT A FUTURE DATE.  
- NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

PARTS

30

NOTES:

STD

SHIPPING