

DENT REPAIR, INC.

34 Tobinleigh Court
Acworth, GA 30101

PAINTLESS DENT REMOVAL
Specializing in
DENTS, DINGS & HAIL DAMAGE


PHONE: 770.424.5555

DATE: _____

NAME Charlie Shatzen (Mazcare)		PHONE: HOME OFFICE	
ADDRESS			APT#
CITY	STATE	ZIP	
AUTOMOBILE MAKE MAZ	MODEL RX8	VIN	COLOR BLK
INSURANCE CO.	ADJUSTER/PHONE		

REMARKS R+1-HEADLINER
HEADLIGHTS
RTAIL LIGHT
HOOD LINER

LOC	NO.	COST
HOOD	Alum ↑ 25% 51-75 (N)	87 ⁵⁰ 350
TRUNK		
ROOF	1-5 (N)	125-
LFF	1-5 (N)	75
LFD		
LRD		
1 1/4		
RFF	1-5 (N)	75-
RFD	1-5 (N)	75-
RRD		
R 1/4	1-5 (N)	75-
OTHER		
	R+1 TIMES	195-
TOTAL		1057 ⁵⁰



THIS ESTIMATE IS VALID FOR 30 DAYS

ESTIMATOR

CUSTOMER

Date: 6/15/2011 03:27 PM
 Estimate ID: 11-5605-73501
 Estimate Version: 0
 Committed
 Profile ID: Cobb County

STATE FARM INSURANCE COMPANIES

Damage Assessed By: CHRIS DAVENPORT

Type of Loss: Comprehensive
 Date of Loss: 4/15/2011
 Deductible: 0.00
 Claim Number: 11-5605-73501

Insured: CHARLES SHATZEN

Mitchell Service: 910100

Description: 2004 Mazda RX8
 Body Style: 4D Cpe
 VIN: JM1FE173440107253
 Mileage: 33,101
 OEM/ALT: A
 Color: BLACK
 Options:

Drive Train: 1.3L Inj 4 Cyl 6M RWD
 License: MAZCARE GA

Search Code: ATLANTA

POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING
 MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, LEATHER SEAT
 ANTI-LOCK BRAKE SYS., FOG LIGHTS, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL
 FRONT AIR DAM, REAR AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM, AM/FM STEREO CD
 FRONT BUCKET SEATS, FRONT HEATED SEATS, KEYLESS ENTRY SYSTEM
 LIMITED SLIP DIFFERENTIAL, POWER DISC BRAKES, POWER LIFTGATE/TRUNK, REAR SPOILER
 STEERING WHEEL AUDIO CONTROLS, SUNROOF/MOONROOF (POWER)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Lamps</u>							
1	001718	BDY	REMOVE/INSTALL	R Frt Combination Lamp			0.4 #
2	001719	BDY	REMOVE/INSTALL	L Frt Combination Lamp			0.4 #
<u>Hood</u>							
3	001731	BDY	REMOVE/INSTALL	Hood Assy	Sublet	437.50 *	0.0* #
4		BDY	PAINTLESS REPAIR	Hood Panel	Existing		0.3 r
5	000107	BDY	REMOVE/INSTALL	Hood Insulator			
<u>Front Fender</u>							
6		BDY	PAINTLESS REPAIR	R Fender Panel	Sublet	75.00 *	0.0* #
7		BDY	PAINTLESS REPAIR	L Fender Panel	Sublet	75.00 *	0.0* #
8	000249	BDY	REMOVE/INSTALL	R Fender Rear Liner	Existing		0.3 r
9	000250	BDY	REMOVE/INSTALL	L Fender Rear Liner	Existing		0.3 r
<u>Front Door</u>							
10		BDY	PAINTLESS REPAIR	R Frt Door Shell	Sublet	75.00 *	0.0* #
11	001782	BDY	REMOVE/INSTALL	R Frt Door Trim Panel			0.3
<u>Roof</u>							

15	001801	BDY	REMOVE/INSTALL	R Rear Combination Lamp					0.3
				<u>ADDITIONAL OPERATIONS</u>					
16	933005	BDY	ADD'L OPR	RESTORE CORROSION PROTECTION				30.00	*

* - Judgment Item
 # - Labor Note Applies
 r - CEG R&R Time Used For This Labor Operation
 Paintless Dent Repair amounts are based on a user defined matrix.

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	4.7	40.00	30.00	862.50	1,080.50	Total Replacement Parts Amount	0.00
	Non-Taxable Labor				1,080.50		
Labor Summary	4.7				1,080.50		
III. Additional Costs						IV. Adjustments	
Total Additional Costs				Amount	0.00	Insurance Deductible	Amount 0.00
						Customer Responsibility	0.00
						I. Total Labor:	1,080.50
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	0.00
						Gross Total:	1,080.50
						IV. Total Adjustments:	0.00
						Net Total:	1,080.50

Point(s) of Impact
 16 Non-Collision (P)

Insurance Co: State Farm Insurance

Inspection Site: Mazcare;1962 Airport Ind Par;CAT- Marietta;
 Address: 1962 Airport Ind Park Dr
 CAT- Marietta, GA 30060
 TE00

Inspection Date: 6/15/2011

This is an estimate. Repair facilities must inspect the vehicle to determine if any repairs not listed are required, and to contact State Farm before making such repairs. Repairer also is responsible for conducting any necessary inspection and safety checks prior to and after completing repairs.

Failure to use the insurance proceeds in accordance with a security

ESTIMATE RECALL NUMBER: 06/15/2011 15:27:32 11-5605-73501

Mitchell Data Version: OEM: APR_11_V0607 UltraMate is a Trademark of Mitchell International

MAPP:APR_11_V0605 Copyright (C) 1994 - 2011 Mitchell International

UltraMate Version: 7.0.330

All Rights Reserved

Body Kit
Front - \$ 800
Back - \$ 800
Sides - 1200
SKirts
Spoiler - 700

Retail

Tein
Coilovers - \$ 800 x 4 = \$ 3200

Comp SSR wheels - \$ 868 x 4 = \$ 3500

Michelin PS2^s - \$ 550 x 4 = \$ 2200

Front Sway - \$ 300

Mazda rear Sway - \$ 300

Front Strut Brace - \$ 300

Rear " Brace - \$ 200

ACT Prohibit ^{Clutch} Flywheel - \$ 700

Revi Intake \$ 400

Xm Radio

Racing Beat
~~Exhaust~~ Exhaust - \$ 500

Indigo Pulleys - \$ 500

WIRE RACK® WHOLESALE

7101 Vorden Parkway
South Bend, IN 46628-8422
Phone: (574) 287-2316
800: (800) 445-0179
Customer Service: Ext. 360
Fax: (574) 236-7700

INVOICE

INVOICE NUMBER	INVOICE DATE	PAGE
933479401	5/02/05	1
PURCHASE ORDER NUMBER		
CHARLES		

2

5/02/05
9:09:15

BILL TO:

0677270-000
MAZCARE (5)
1962-B AIRPORT IND PARK DR
MARIETTA GA 30062

SHIP TO:

0677270-000
MAZCARE (5)
1962-B AIRPORT IND PARK DR
MARIETTA GA 30062

SHIP METHOD: UPS GROUND
81ST ST

SHIP-TO PHONE: 770-859-9643
Plan 126929 Team AWHEEL Wave 006 Prcl 11

ORDER DATE	SALES REP. NAME / PHONE EXT.	TERMS	MAKE, MODEL AND YEAR	WHSE	OPER.	
4/29/05	SAM-EXT371	VISA	RX8 6-SP 4	SB	SAM	
PART NUMBER	QUANTITY ORDERED	QUANTITY SHIPPED	DESCRIPTION	UNIT PRICE	EXTENSION	LOC.
TC8848JSML	4	4	90 18X8 5-114 ET48 SSR COMP SILVER W/ MACH LIP (79.5 RING)	399.00	1596.00	A- 1
AL671	4	4	90 MM 79.5-67.1 CENTER RING	N/C		F-70 8
N1SSR	20	20	90 NC12X1.5 SSR LUGNUT 17H LUGNUT FROM GORILLA	N/C		G-78 193
BR172119	1	1	90 19/21 TO 17MM LUG ADAPTER	N/C		A- 1
COMPCAPLG	4	4	90 SSR COMPETITION CAP (LG) POLISHED ALU CAP WITH O'RING	N/C		D- 9 2
TOTAL THIS ORDER					1596.00	
FREIGHT CHG/ALLW					32.36	
VISA PAYMENT					1628.36-	
TOTAL AMOUNT DUE					\$.00	
Weight	83					

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.

Customer Detailed Copy

Jim Ellis Mazda of Marietta
 1715 Cobb Parkway
 Marietta, GA 30060 US
 (888) 354-1968

CUSTOMER NO.	1018447	SERVICE ADVISOR	DougAldridge	TAG NO.	4996	INVOICE DATE		INVOICE NO.	
		HOURLY RATE		LICENSE NO.		MILEAGE IN	211820	COLOR	BLACK
		YEAR/MAKE/MODEL	2004 Mazda RX8			DELIVERY DATE	09/09/2003	MILEAGE OUT	
		VEHICLE IDENTIFICATION NO.	JM1FE173440107253			DEALER NO.		EFFECTIVE DATE	
		CELL PHC		RO #	2920526Z	R.O. DATE	08/07/2020	FLEET NO.	
TEL HOME		TEL BUSINESS		COMMENTS	ENG:1.3_LITER				

LINE	OP CODE	DESCRIPTION		ESTIMATE
# A	MA40	Tires - Rotate Tires - Rotate	Labor	19.95
			Parts	0.00
			Misc	0.00
			Discount	(0.00)
			Line Total	19.95
# B	BGEVAP	AC EVAPORATOR CORE CLEANING SERVICE AC EVAPORATOR CORE CLEANING SERVICE Parts: FRIGI CLEAN, Qty 1.00, C	Labor	52.49
			Parts	45.00
			Misc	0.00
			Discount	(0.00)
			Line Total	97.49
# C	BGMAF	PERFORM MASS AIR FLOW SENSOR CLEANING SERVICE PERFORM MASS AIR FLOW SENSOR CLEANING SERVICE Parts: MASS AIRFLOW, Qty 1.00, CPC	Labor	50.00
			Parts	29.95
			Misc	0.00
			Discount	(0.00)
			Line Total	79.95
# D	BGISK	PERFORM INDUCTION SERVICE PERFORM INDUCTION SERVICE Parts: GDI INTAKE SERVICE KIT, Qty 1.00, CPC	Labor	102.45
			Parts	78.00
			Misc	0.00
			Discount	(0.00)
			Line Total	180.45
# E	BGTB	PERFORM THROTTLE BODY CLEANING SERVICE PERFORM THROTTLE BODY CLEANING SERVICE Parts: THROTTLE BODY , Qty 1.00, CPC	Labor	55.45
			Parts	22.50
			Misc	0.00
			Discount	(0.00)
			Line Total	77.95

Subtotal	455.79
Shop Charges	28.03
Sales Tax	12.21
Total	496.03

Printed On 08/07/2020 11:50:27 AM
 Estimate Expires on 09/06/2020

From:
Sent: Monday, August 10, 2020 3:32 PM
To:
Subject: Fwd: Receipt for your payment to Jim Ellis Mazda of Marietta Invoice # R62TJ8K3KP

----- Forwarded message -----

From: **Jim Ellis Mazda of Marietta** <jemm-jimellismazdaofmarietta@kaarmadealer.com>
Date: Mon, Aug 10, 2020, 3:31 PM
Subject: Receipt for your payment to Jim Ellis Mazda of Marietta Invoice # R62TJ8K3KP

Jim Ellis Mazda of Marietta
1715 Cobb Pkwy SE
Marietta, GA 30060
(770) 590-4450

RECEIPT


Invoice Details:
Invoice #: R62TJ8K3KP
Invoice Date: Monday, August 10, 2020 03:17 PM
Repair Order/Ref #: 2920526Z

Description of Product/Services	Amount
	\$ 498.98

Customer Signature

Jim Ellis Mazda of Marietta

Processed by myKaarma eBridge Payments



Jim Ellis Mazda of Marietta
 1715 Cobb Pkwy SE
 Marietta, Georgia, 30060, US
 Phone: 7705904450
<https://www.jimellismazdamarietta.com>

Repair Order #: 2920526Z
 Tag #: T4996
 Advisor: Doug Aldridge
 Advisor No. #: 300344
 Order Open Date: 2020-07-27

Customer Information	Vehicle Information
	2004 MAZD RX8
	VIN #: JM1FE173440107253
	Color #: <u>BLACK</u>
	Mileage In/Out #: 41061/41065

Job # A **Labor Total: No Charge**

Fuel Tank Leak At Fuel Pump Discharge Outlet Port

Cause: FF
Correction: XXN6GCRX R1017E: REPLACE PUMP RING SET AND FDD (INCLUD
 Tech Number: 300385 Labor Type: W
 XXN6GDRX R1017E: REPLACE PUMP RING SET AND FDD (INCLUD
 Tech Number: 300385 Labor Type: W

Part Number	Part Description	Qty	List	Parts Total:	No Charge
F1Y1-42-A1X	NUT,RETAINER & GASKET KIT	1			
N3Y1-13-ZE0C	FILTER,FUEL PUMP	1			

211824 PERFORM RECALL 1017E. DRAIN TANK AND INSTALL FUEL PUMP AND LOCK RINGS AND GASKETS. REFILL TANK AND ROAD TEST.

Job # A Total **\$ 0.00**

Job # B **Labor Total: No Charge**

Front Lower Arm Ball Joint

Cause: FF
Correction: XXN61ARX 1117E: FRONT LOWER ARM, R&R (INCL. WHEEL ALIG
 Tech Number: 300385 Labor Type: W

Part Number	Part Description	Qty	List	Parts Total:	No Charge
F1Y1-34-30XA	KIT,LWR ARMS	1			

211824 PERFORM RECALL 1117E. REPLACE LOWER CONTROL ARMS AND ROAD TEST.

Job # B Total **\$ 0.00**

CUSTOMER #: 1018447

2920526Z



INVOICE

MAZDA OF MARIETTA

1715 Cobb Parkway SE · Marietta, GA 30060
Main: (770) 590-4450
www.jimellis.com

PAGE 3

SERVICE ADVISOR: 300344 DOUGLAS ALDRIDGE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	MAZDA RX8	JM1FE173440107253		41061/41065	T4996	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
03SEP03 IS							
09SEP03 DD		03SEP2006	19:00 27JUL20		0.00	CASH	10AUG20
R.O. OPENED	READY	OPTIONS: DLR:23466 ENG:1.3 LITER					
08:04 27JUL20	14:58 10AUG20						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

I**	PERFORM INDUCTION SERVICE						
	BGISK PERFORM INDUCTION SERVICE						
	300385 CPC					102.45	102.45
	6592T GATX					4.68	4.68
	6592 GDI FUEL INDUCTION					78.00	78.00
PARTS:	0.00	LABOR:	102.45	OTHER:	82.68	TOTAL LINE I:	185.13
	41065 PERFORM INDUCTION SERVICE.						

J**	PERFORM THROTTLE BODY CLEANING SERVICE						
	BGTB PERFORM THROTTLE BODY CLEANING SERVICE						
	300385 CPC					55.45	55.45
	4068 THROTTLE BODY					22.50	22.50
	4068T GATX					1.35	1.35
PARTS:	0.00	LABOR:	55.45	OTHER:	23.85	TOTAL LINE J:	79.30
	41065 PERFORM THROTTLE BODY CLEANING SERVICE.						

EST: 465.23 07AUG20 16:00 SA: 300344

CONTACT: *****

CUSTOMER PAY SUPPLY FEE FOR REPAIR ORDER 28.03

COMPANY NAME FIDELITY WARRANTY
 COMPANY PHONE
 POLICY NUMBER 80160326
 POLICY TERM
 EFFECTIVE DATE
 DEDUCTIBLE 0.00
 MILEAGE LIMIT
 BEGIN MILES
 END MILES
 COMPONENTS



Please read carefully the statement below, and sign, 72 hours after completion of work on the vehicle, I will incur a storage fee of \$10.00 a day, I, the undersigned, agree to pay all court costs and a reasonable attorney's fee and, or collection agency fee.

TERMS STRICTLY CASH UNLESS ARRANGEMENTS MADE
ALL PARTS REMOVED WILL BE DISCARDED UNLESS SPECIFIED OTHERWISE.

"The Factory Warranty constitutes all of the warranties with respect to the seller of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose and the seller neither assumes nor authorizes an other person to assume for it any liability in connection with the sale of this item/items."

AUTHORIZATION FOR REPAIR AND DISCLAIMER FOR DELAY, LOSS OR DAMAGE

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	280.34
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	216.96
TOTAL CHARGES	497.30
LESS INSURANCE	0.00
SALES TAX	1.68
PLEASE PAY THIS AMOUNT	498.98

CUSTOMER SIGNATURE

CUSTOMER COPY

RX-8

Universal Motorsports

1902 A Elberta Rd
Warner Robins, GA 31093
478-328-8206

oil + brake fluid

Hi temp

Customer Copy

Invoice #3871

Estimated Time Due

Thursday, November 08, 2018
5:54:24 PM

Ordered on
Thursday, November 08, 2018

Workorder # 7656

for Reebing
Nov 2018

MAKE & MODEL	FLEET NO.	PHONE	REP	CSH	PO #	TERMS	
2004 Mazda RX-8 Base Coupe 4 Door		478-953-2176	Paco Price	PP		Cash	
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
CONEKLR	212121 / 212121	JM1FE173440107253		1.3 LITER R2 GAS VIN			
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	TOTAL	Code
LOFP	Oil Package Synthetic					\$25.00	
SL	Oil Change Labor	0.2					EC-PP
HWF	Hazardous Waste Fee	1					
BFF	Brake Fluid Flush						
SL	Power Flush Brake Fluid	0.8		120.00		\$96.00	EC-PP
	Remove Old Worn Brake Fluid						
	Insert Fresh New Brake Fluid						
	Clean Brake Fluid Reservoir						
	Check and Top Off Brake Fluid If Required						
	SUBTOTAL		.00	96.00		\$96.00	
SS	Shop Supplies					\$6.00	

Welcome, We appreciate your business.

PAID BY	Parts	\$0.00	Taxable	\$6.00
AMEX \$127.42, *****1349 A#889148	Labor	\$120.00	Non-Taxable	\$121.00
	Freight	\$0.00	Local Tax (Set in Sa	\$0.42
	Other	\$1.00		
	Supplies	\$6.00	TOTAL	\$127.42

I agree to pay the above total amount according to card issuer agreement.

Parts and Labor warranties 100% for 12 months or 12000 miles, whichever comes first. This warranty limited to the work on this form only. Vehicle must be returned to our shop at customer's expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereb. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Because of the extent of the leardown and inspection, the vehicle may not perform as well as before. No refunds on installed Tires and or Wheels, Special Orders or discontinued items. All returns are subject to 15% handling charge. Any deposits are subject to forfeit if cancelled.

Print Name _____ Signature _____ Date _____



Chandler Collision

1360 Radio Loop, Warner Robins, GA 31088
 Phone: (478) 328-0370
 FAX: (478) 328-3798

Workfile ID: 0ad292fa
 Federal ID: 26-052-1619

Final Bill

RO Number: 12752

Adjuster: Estimator: Eric Chandler
 Phone: Create Date: 6/19/2017
 Claim:
 Loss Date:
 Deductible:

2004 MAZD RX-8 Automatic 2D CPE Rotary-1.3L Gasoline MPI BLACK

VIN: JM1FE173440107253 Interior Color: Mileage In: Vehicle Out: 6/21/2017
 License: Exterior Color: BLACK Mileage Out:
 State: Production Date: Condition: Job #:


Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		PILLARS, ROCKER & FLOOR						
2	E01	Remove/Install	RT Rocker molding w/Sport susp.				2.5	Body	
3	E01	Remove/Replace	RT Rocker molding clip	5	19.90T	OEM			

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					19.90
Labor, Body			46.00	2.5	115.00
Subtotal					134.90
Sales Tax					1.39
Grand Total					136.29
Net Total					136.29

Estimate Version	Total \$
Original	136.29

Insurance Total \$:	136.29
Received from Insurance \$:	0.00
Balance due from Insurance \$:	136.29
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural





Done
Same day Vic Saw Pulmonary
DR
5 star Mazda

2007-2007



28902

IMPORTANT SAFETY RECALL

**Driver Air Bag Inflator Final Repair - Safety Recall 8215F
NHTSA Campaign No. 15V-382**

November 2015

This notice applies to your vehicle, **VIN JM1FE173440107253**

Dear Mazda Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in 2004-2008 RX-8, 2003-2008 Mazda6, and 2006-2007 Mazdaspeed6 vehicles.

If you are a recipient of this notice, your vehicle is included in this Safety Recall.

What is the problem?

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the driver's front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the driver's side frontal air bag. An inflator rupture could result in metal fragments striking the driver or other vehicle occupants, resulting in serious injury or death.

You may have had an interim air bag inflator installed under Safety Recall 7914J. However, you still need to have the final repair completed and the permanent remedy inflator installed.

What will Mazda do?

Your Mazda dealer will replace the driver air bag inflator with the permanent remedy air bag inflator, free of charge. The repair should take less than one hour to complete; however, it may take longer depending on the service workload at your Mazda dealership.

What should you do?

Even if you already had the interim replacement part previously installed under Safety Recall 7914J, please make an appointment with an authorized Mazda dealer to have the permanent



Raffield Tire Masters, Inc.
4001 Watson Blvd
Warner Robins, GA 31093
(478)971-7400

RX-8

Oil change

Year: 08
 Make: MAZDA
 Model: RX8
 Lic No: ~~CONEKLR~~
 VIN: JM1FE173440103253
 Color:
 Engine: 1.3
 Mileage In: 38884
 Mileage Out: 38884

Create Date: 09/15/16 13:26:59
 Date/Time: 09/15/16 14:56:47
 Workorder #: 2046073
 Invoice #: 1025731

Email Address:
 PO Number:
 Fleet/Wholesale: N

Salesperson: J. BARNHART
 Service comments:

FINAL INVOICE APPROVAL: _____

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
L/O/F SERVICES							
5	5903			5W-20 Synthetic Blend Sunoco	4.95	0.00	24.75
1	CAST5			5W-20 Synthetic-Blend Sunoco	0.00	0.00	0.00
1	LUBE			OIL CHANGE LABOR	0.00	11.40	11.40
1	SHOP			SHOP SUPPLIES	0.80	0.00	0.80
1	M4612			Oil Filter	7.00	0.00	7.00
				TOTAL L/O/F SERVICES:	43.95		
DISPOSAL FEES							
1	EF			ENVIRONMENTAL IMPACT FEE	1.00	0.00	1.00
				TOTAL DISPOSAL FEES:	1.00		

*** Customer Wishes To Discard Old Parts ***

CREDIT CARD #: XXXX-XXXX-XXXX-3006
 APPROVAL # : 523414
 TICKET # :

For your file

Thank you for your business.	PAY AMEX	AMOUNT 47.30	PARTS TOTAL	33.55
			SALES TAX	2.35
	TECH: 000095-0.00	JUSTIN	LABOR TOTAL	11.40
	000018-0.00	BOBBY	GRAND TOTAL	47.30

Customer Signature: _____
 X



*RX-8 2 new tires
put on front,
+
oil change*

Raffield Tire Masters, Inc.
4001 Watson Blvd
Warner Robins, GA 31093
(478)971-7400

Year: 04
 Make: MAZDA
 Model: RX-8
 Lic No: CONEKL
 VIN: CONEKL
 Color:
 Engine: R2-1308cc 1.3L
 Mileage In: 38084
 Mileage Out: 38084

Create Date: 03/23/15 09:58:01
 Date/Time: 03/23/15 13:19:03
 Workorder #: 2020722
 Invoice #: 1011510

Email Address:
 PO Number:
 Fleet/Wholesale: N

5W30

Salesperson: R. BROWN
 Service comments:

REPLACE REAR MOVE FRONT TO REAR

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
MICHELIN PASS TIRES							
2	*78156			245/40R18 MICH SP PILOT	315.50	0.00	631.00
				TOTAL MICHELIN PASS TIRES:			631.00
TIRE LABOR							
2	MT			MOUNT	0.00	7.50	15.00
				TOTAL TIRE LABOR:		15.00	
L/O/F SERVICES							
5	0080			Castrol 5W-30 GTX	3.49	0.00	17.45
1	CAST1			Castrol GTX LOF	0.00	0.00	0.00
1	SHOP			FREIGHT	21.00	0.00	21.00
1	SHOP			SHOP SUPPLIES	0.80	0.00	0.80
1	LUBE			OIL CHANGE LABOR	0.00	5.70	5.70
1	M4612			Oil Filter	5.00	0.00	5.00
				TOTAL L/O/F SERVICES:		49.95	
DISPOSAL FEES							
2	TDF			TIRE DISPOSAL FEE	0.00	2.75	5.50
1	EF			ENVIRONMENTAL IMPACT FEE	1.00	0.00	1.00
				TOTAL DISPOSAL FEES:		6.50	

*** Customer Wishes To Discard Old Parts ***

Thank you for your business.

PAY AMOUNT
 AMEX 749.79
 TECH: 000086-0.00 RANDY

PARTS TOTAL 676.25
 SALES TAX 47.34
 LABOR TOTAL 26.20
 GRAND TOTAL 749.79

Customer Signature:

X _____



FIVE STAR
DODGE
CHRYSLER MAZDA
JEEP

3068 Riverside Drive
 Macon, Georgia 31210
 (478) 474-3700

DRIVER'S SIDE
 AIR BAG

RECALL
 DONE
 8-31-16

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE. UNLESS OTHERWISE SHOWN, SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURERS REPRESENTATIVE.

(SIGNED)

DEALER, GENERAL MANAGER OR AUTHORIZED PERSON

(DATE)

Adv: 572 RICHARD P. COOK		Tag 3979	License 9	JM1FE1734 40107253	Page 1 (Last)	Invoice W57686	
Invoice to				Driver/Owner Information			
For Office Use				Vehicle Information			
Odometer in: 38791 Out: 38792		Dist: MAZ WAR W Prelim		04 MAZDA RX8 QUAD COUPE			
Begin: 08/31/16 Done: 08/31/16		Invoiced: 08/31/16 13:38 RC					
Customer Concern							
Concern 24	CUSTOMER STATES MAZDA FULL CIRCLE SERVICE INSPECTION			Operation	Tech	Amount	
Correction	PERFORM SERVICE INSPECTION			99P	359		
Comment	NO CHARGE TO MAZDA VALUED CUSTOMER						
Type: WAR	Line Flags: NOS						
Concern 51	CUSTOMER STATES 8215F DRIVER FRONT AIR BAG INFLATOR			Operation	Tech	Amount	
Cause	8215F DRIVER FRONT AIR BAG INFLATOR			XXL83ARX	359		
Correction	8215F INFLATOR REPLACEMENT OF DRIVER SIDE FRONT AIR BAG INFLATOR PROCESS NUMBER AF037A SC 99 DO 99 CAUSAL PART NUMBER (RX8 ** F1Y2-57-K80) (MAZDA 6 **GPYA-57-K80) QUANTITY 1 LABOR OPERATION NUMBER XXL83ARX LABOR HOURS 0.3 H						
Facts	Part Number	PO#	Note	Description	Qty	List	Sell
	MAZ	F1Y2-57-K80		INFLATOR, AIR BAG	1		
Summary of Charges for Invoice W57686				Payment Distribution for Invoice W57686			
If you have any questions - please see RICHARD P. COOK							

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

X



Raffield Tire Masters, Inc.
4001 Watson Blvd
Warner Robins, GA 31093
(478)971-7400

Year: 04
 Make: MAZDA
 Model: RX-8
 Lic No: CONEKLK
 VIN:
 Color: BLACK
 Engine: R2-1308cc 1.3L
 Mileage In: 38131
 Mileage Out: 38131

Create Date: 08/05/15 13:22:40
 Date/Time: 08/05/15 15:56:14
 Workorder #: 2027532
 Invoice #: 1015056
 Email Address:
 PO Number:
 Fleet/Wholesale: N

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
OTHER MECHANICAL PARTS							
1	NOTES			Comments	0.00	0.00	0.00
	DRIVER SIDE BROKEN VISOR,						
1	SUN VISOR FROM MAZDA - \$229.01			CHECK ENGINE LIGHT DIAGNOSTIC	0.00	99.80	99.80
	CEL						
	ECCENTRIC SHAFT POSITION SENSOR CLEANED						
	P0302 - MISFIRE-CYL 2						
				TOTAL OTHER MECHANICAL PARTS:		99.80	
COUPONS/DISCOUNTS							
1	VIP			VIP DISCOUNT	0.00	(20.00)	(20.00)
				TOTAL COUPONS/DISCOUNTS:		(20.00)	

*** Customer Wishes To Discard Old Parts ***

Thank you for your business.

PAY AMOUNT
 AMEX 79.80

TECH: 000095-0.00 JUSTIN
 000060-1.00 CURTIS

PARTS TOTAL 0.00
 SALES TAX 0.00
 LABOR TOTAL 79.80
 GRAND TOTAL 79.80

Customer Signature:

X _____



FIVE STAR
DODGE
CHRYSLER MAZDA
JEEP

3068 Riverside Drive
 Macon, Georgia 31210
 (478) 474-3700

Recall performed on passenger side.

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE. UNLESS OTHERWISE SHOWN, SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE

3-8-15

(SIGNED)

DEALER, GENERAL MANAGER OR AUTHORIZED PERSON

(DATE)

Adv: 572 RICHARD P. COOK	Tag: 1191	License: 9	JM1FE1734 40107253	Page: 1	Invoice: W27249	
Invoice to			Driver/Owner Information			
For Office Use			Vehicle Information			
Odometer in: 38046	Out: 38047	Dist: MAZ WAR W	Prelim	04 MAZDA RX8 QUAD COUPE		
Begin: 03/09/15	Done: 03/09/15	Invoiced: 03/09/15 14:57 RC				
Customer Concern						
Concern 24 Correction	CUSTOMER DECLINES TO PROVIDE E-MAIL ADDRESS CUSTOMER DECLINES TO PROVIDE E-MAIL ADDRESS CUSTOMER DOES NOT WANT E-MAIL UPDATES ON REPAIRS CUSTOMER DOES NOT WANT E-MAIL COUPON OFFERS / DISCOUNTS CUSTOMER DOES NOT WANT E-MAIL RECALL NOTIFICATIONS Line Auth: COOKRICH 03/09/15 14:56			Operation EMAIL	Tech 359	Amount
Concern #25 Correction Comment Type: WAR	MAZDA FULL CIRCLE SERVICE INSPECTION PERFORM SERVICE INSPECTION NO CHARGE TO MAZDA VALUED CUSTOMER Line Auth: COOKRICH 03/09/15 14:56 Line Flags: NOS			Operation 99P	Tech 359	Amount
Concern 51 Cause Correction Parts	CUSTOMER STATES 8114L PASS AIRBAG REGIONAL RECALL 8114L PASS AIRBAG REGIONAL RECALL REPLACEMENT OF PASSENGER SIDE FRONT AIR BAG INFLATOR APPLICABLE MODEL MAZDA6, RX-8, MPV B-SERIES WARRANTY TYPE R PROCESS NUMBER AF004A SC 99 DC 99 PNMC & QUANTITY 7777-SP-K02 & 0 RELATED PART NUMBER & QUANTITY GJYA-57-K80 & 1 (MAZDA6, MPV) LABOR OF XXL29XRK LABOR HOURS 0.4 HRS Part Number PC# Note Description MAZ FEY1-57-K8DA INFLATOR, AIR BAG Line Auth: COOKRICH 03/09/15 14:28			Operation XXL29XRK	Tech 359	Amount
				Qty 1	List	Sell

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

X



Rich Cook
Sve mfg. Macon 5 Star
474-3700

Replaced ~~Side~~
3-8-15 Passenger
Side
only 05/14291

IMPORTANT SAFETY RECALL

**Passenger Air Bag Inflator Replacement - Safety Recall 8114L
NHTSA Campaign No. 14V-773**

February, 2015

Black 2004

This notice applies to your vehicle: VIN JM1FE173440107253

Dear Mazda Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation decided that a defect which relates to motor vehicle safety exists in certain 2004-2005 RX-8, 2004-2005 MPV, 2003-2006 Mazda6, and 2004-2005 B-Series Trucks.

If you are a recipient of this notice, your vehicle is included in Safety Recall 8114L for passenger air bag inflator replacement.

What is the problem?

In the subject vehicles sold in or ever registered in Alabama, Florida, Georgia, Hawaii, Louisiana, Mississippi, Texas, Puerto Rico, Saipan and Guam continued exposure to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger side frontal air bag. An inflator rupture could result in metal fragments striking and potentially seriously injuring vehicle occupants.

What will Mazda do?

Your Mazda dealer will replace the passenger air bag inflator with a new one, free of charge. The repair should take less than one hour to complete; however, it may take longer depending on the service workload at your Mazda dealership.

What should you do?

Mazda is concerned about your safety, and we encourage you to make an appointment with any authorized Mazda dealer to have the airbag inflator replaced as soon as possible. Making an appointment provides the dealer the opportunity to reserve the necessary part for your repair and plan their service activity, thus minimizing your wait time and inconvenience this recall may cause you. You do not need to bring this notice to the dealer, but it may assist in the check-in process.



2 tires Black Rx 8

Raffield Tire Masters, Inc.
 4001 Watson Blvd
 Warner Robins, GA 31093
 (478)971-7400

in prep
 for Roebly Rd.
 PAGE 1

Year: 08
 Make: MAZDA
 Model: RX8
 Lic No: CONEKLK
 VIN: JM1FE173440103253
 Color:
 Engine: 1.3
 Mileage In: 36633
 Mileage Out: 36633

Create Date: 01/09/14 14:25:58
 Date/Time: 01/11/14 09:23:10
 Workorder #: 2000033
 Invoice #: 1000066
 Email Address:
 PO Number:
 Fleet/Wholesale: N

Salesperson: R. BROWN
 Service comments:

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
2	VS			VALVE STEM	0.00	0.00	0.00
2	MB			Installation package includes mounting, balancing, new valve stems (non-tmps or metal) flat repairs and tire rotation and rebalancing for the life of the tires. Road Hazard Warranty sold seperately.	0.00	16.50	33.00
2	TDF			TIRE DISPOSAL FEE	0.00	2.75	5.50
2	T			GA STATE TIRE FEE	0.00	1.00	2.00
				TOTAL :	40.50		
MICHELIN PASS TIRES							
2	*78156			MICH-PILOT SPORT	317.34	0.00	634.68
				TOTAL MICHELIN PASS TIRES:	634.68		
TIRE LABOR							
1	DEL			DELIVERY FEE	0.00	79.80	79.80
				TOTAL TIRE LABOR:	79.80		

*** Customer Wishes To Discard Old Parts ***

These Parts And/Or Services Were Declined by the Customer:
 2 TPP TIRE PROTECTION POLICY

Thank you for your business.	PAY AMEX	AMOUNT 799.41	TECH: 000026-0.00	CHRISTOPHER	PARTS TOTAL	634.68
					SALES TAX	44.43
					LABOR TOTAL	120.30
					GRAND TOTAL	799.41

Customer Signature:
 X _____



Universal Motorsports

105 C Industrial Way
Centerville, GA 31028
478-328-8206

Customer Copy

Invoice #1160

*Black RX8
28 DEC 13*

Saturday, December 28, 2013
12:14:23 PM

Ordered on
Friday, December 27, 2013

Workorder # 2321

MAKE & MODEL	FLEET NO.	PHONE	REP	CSH	PO #	TERMS	
2004 Mazda RX-8 Base Coupe 4 Door		478-953-2176	Harley Mathe	S		Cash	
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
CONEKLR	/36538	JM1FE173440107253		1.3 Liter R2 GAS Vin -			
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	TOTAL	Code
PKCD	Computer Diagnostics						
BCD	Basic Computer Diagnostics	1		90.00		\$90.00	LB
	Includes basic scope check and inspection of computer system.						
LOFP	Oil Package Synthetic						
OC	Oil Change	1		27.00		\$27.00	LB
	10W30 Valvoline Engine Oil	5	9.00			\$45.00	HM
	Oil Filter	1	4.99			\$4.99	
SL	Oil Change Discount	1		-17.00		(\$17.00)	S
	Hazardous Waste Fee	1	1.00			\$1.00	
COMMENT	P0037 HO2S: Heater Control Circuit Bank 1 Sensor 2 O2	1	143.98			\$143.98	
SL	Oxygen Sensor, Replace Oxygen Sensor	0.4		90.00		\$36.00	LB
RDS	Rear Differential Service						
	GL-5 SAE - 90 Rear Diff Fluid	2	17.79			\$35.58	HM
COMMENT	Inspect Axle and Pinion Seals						
LABOR	Rear Differential Service Labor	1		37.50		\$37.50	LB
PKTRANS	Transmission Service						
TRFLUSH	Transmission System Flush	1.5		60.00		\$90.00	LB
	GL-5 SAE - 75W90 Full Synthetic Fluid Part Number: 10436198W573	2	37.48			\$74.96	
SS	Shop Supplies					\$49.90	

Welcome, We appreciate your business.


PAID BY	Parts	Labor	Freight	Other	Supplies	Taxable	Non-Taxable	Local Tax (Set in Sa	TOTAL
Debit \$643.72, ****4436 A#141137	\$304.51	\$263.50	\$0.00	\$1.00	\$49.90	\$354.41	\$264.50	\$24.81	\$643.72

I agree to pay the above total amount according to card issuer agreement.

Parts and Labor warranties 100% for 12 months or 12000 miles, whichever comes first. This warranty limited to the work on this form only. Vehicle must be returned to our shop at customer's expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Because of the extent of the teardown and inspection, the vehicle may not perform as well as before. No refunds on installed Tires and or Wheels, Special Orders or discontinued items. All returns are subject to 15% handling charge. Any deposits are subject to forfeit if cancelled.

Print Name _____ Signature *Vickie* _____ Date _____

visit www.dynolab.net or call 678 560 0692





NOPI - Smyrna
 1848 Spring Road
 Smyrna, GA 30080

INVOICE
 3 - 127911
 11/15/2005 13:56

Ship To: MAZCARE
 1962 B AIRPORT IND. PARK DR.
 MARIETTA, GA 30062

Bill To: MAZCARE
 300134 1962 B AIRPORT IND. PARK DR.
 MARIETTA, GA 30062

Order #	PO #	SalesPerson	Ship Via	Terms	Date
3 127911		Christopher Arthur	Delivery	COD	11/15/2005

NOPI #	Part Number	Description	Ord	Shp	Retail	Price	Core	Core Adj	Extended
923+0333	923+0333	HKS Twin Pwr Dual Ign Amp RX8 03-05	1	1	\$647.67	\$473.90	\$0.00	\$0.00	\$473.90

Charlie

*pd.
 1 CK # 2288
 11/15/05*

	SubTotal	Shipping	Spec Chgs	Ins	Sales Tax	COD Adj	-Dep/GC	Total
W-100/Z-2/CN-0/TN-	\$473.90	\$10.22	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$484.12

Sales invoice must accompany ALL returns, warranties and cores. All merchandise MUST be returned in original packaging and in resalable condition. No refund on electrical items, special orders or items over 90 days old. Manufacturer's warranty ONLY. Returns over 30 days old are subject to a 20% restocking fee. Certain products are not intended for highway use, these products are sold for show, race or off-road use only.



JIM Ellis
Expect the best



MAZDA

1141 Cobb Parkway MARIETTA, GEORGIA 30060
(770) 590-4450

CUSTOMER NO. 97308	ADVISOR DOUG ALDRIDGE	300344	TAG NO. 878	INVOICE DATE 01/03/04	INVOICE NO. MICS536950
CHARLES JOSEPH SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068	LABOR RATE	LICENSE NO.	MILEAGE 4,161	COLOR BLACK/BLACK	STOCK NO. Z42587
	YEAR / MAKE / MODEL 04/MAZDA/RX8/RX8 6SPD MAN. 250HP			DELIVERY DATE 09/09/03	DELIVERY MILES 7
	VEHICLE I.D. NO. J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO. 23466	PRODUCTION DATE
	F. T. E. NO.		P. O. NO.		PO DATE 01/02/04
COMMENTS					MO: 4165

LABOR & PARTS		WARRANTY	
J# 1 04MAZ	ENGINE/BLOCK ASSY	UNITS: 0.30	TECH(S):37620
CUSTOMER STATES: CHECK ENGINE LIGHT ON....CHECK FOR REFLASH			
PCM REFLASH			
REFLASH PCM WITH UPDATES FOR CODE P1688 LACK OF POWER.4107			
PREFORM DRIVE CYCLE			
JOB # 1 TOTAL LABOR & PARTS		0.00	
TOTALS-----			
TOTAL LABOR....		0.00	
TOTAL PARTS....		0.00	
TOTAL SUBLET....		0.00	
TOTAL G.O.G....		0.00	
TOTAL MISC CHG.		0.00	
TOTAL MISC DISC		0.00	
TOTAL TAX.....		0.00	
TOTAL INVOICE \$		0.00	

CUSTOMER SIGNATURE _____



JIM Ellis
Expect the best



MAZDA
1141 Cobb Parkway MARIETTA, GEORGIA 30060
(770) 590-4450

CUSTOMER NO. 97308	ADVISOR DOUG ALDRIDGE	300344	TAG NO. 309	INVOICE DATE 03/22/04	INVOICE NO. MICS564713
CHARLES JOSEPH SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068	LABOR RATE	LICENSE NO.	MILEAGE 6,825	COLOR BLACK/BLACK	STOCK NO. 242587
	YEAR / MAKE / MODEL 04/MAZDA/RX8/RX8 6SPD MAN. 250HP			DELIVERY DATE 09/09/03	DELIVERY MILES 7
	VEHICLE I.D. NO. J M I F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO. 23466	PRODUCTION DATE
	F. T. E. NO.			P. O. NO.	DATE 03/22/04
COMMENTS					MO: 6829

LABOR & PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
J# 1 26MAZ1604B FRONT PASS AIR BAG UNITS: 0.20 TECH(S):37620 WARRANTY					
CUSTOMER REQUEST RECALL 1604B, FRONT PASSENGER-SIDE AIRBAG FOR THE 2004 MPV AND RX8 THE VEHICLE COULD HAVE BEEN PRODUCED WITH IMPROPERLY WIRED FRONT PASSENGER SIDE AIRBAGS INSPECT AND REPAIR BY INSTALLING A NEW WIRING HARNESS IN THE IN THE FRONT PASSENGER SIDE AIRBAG SYSTEM A4417H, FEY-67-SHO 1, XX643XRX .2 CSOXX, F, FREIGHT					
PARTS	1	FEY0-67-SHO	CORD, SHOR		WARRANTY
				JOB # 1 TOTAL PARTS	0.00
				JOB # 1 TOTAL LABOR & PARTS	0.00
J# 2 26MAZ1704B MANJAL TRANS DAMPER UNITS: 1.00 TECH(S):37620 WARRANTY					
CUSTOMER REQUEST RECALL 1704B, MANUAL TRANSMISSION DYNAMIC RECALL THE DYNAMIC DAMPER HEAT INSULATOR, MAY BY CRACKED, CAUSING ABNORMAL NOISE NECESSARY TO INSPECT AND REPLACE DAMPER BRACKET Y6Y0-22-100, A4418H, XX644XRX 1.0 CSOXX, F, FREIGHT AMOUNT					
PARTS	1	Y6Y0-22-100	BRACKET, I		WARRANTY
				JOB # 2 TOTAL PARTS	0.00
				JOB # 2 TOTAL LABOR & PARTS	0.00
J# 3 10MAZ BODY ASSEMBLY UNITS: 0.00 TECH(S):37620 WARRANTY					
BODY ASSEMBLY CUSTOMER STATES: CONSOLE LID IS BROKEN... SOP					
PARTS					WARRANTY
				JOB # 3 TOTAL PARTS	0.00
				JOB # 3 TOTAL LABOR & PARTS	0.00
J# 4 10MAZ001 BODY ASSEMBLY UNITS: 0.00 TECH(S):37620 WARRANTY					
CUSTOMER STATES: DOOR SILL EMBLEMS ARE COMING UP.... SOP					
PARTS					WARRANTY
				JOB # 4 TOTAL PARTS	0.00
				JOB # 4 TOTAL LABOR & PARTS	0.00
J# 5 00MAZ99P FULL CIRCLE SERVICE UNITS: 0.00 TECH(S):37620 0.00					
FULL CIRCLE SERVICE INSPECTION					



JIM Ellis
Expect the best



MAZDA

1141 Cobb Parkway MARIETTA, GEORGIA 30060
(770) 590-4450

CUSTOMER NO. 97308	ADVISOR DOUG ALDRIDGE	300344	TAG NO. 309	INVOICE DATE 03/22/04	INVOICE NO. M1CS564713
CHARLES JOSEPH SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068	LABOR RATE	LICENSE NO.	MILEAGE 6,825	COLOR BLACK/BLACK	STOCK NO. Z42587
	YEAR / MAKE / MODEL 04/MAZDA/RX8/RX8 6SPD MAN. 250HP			DELIVERY DATE 09/09/03	DELIVERY MILES 7
	VEHICLE I.D. NO. J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO. 23466	PRODUCTION DATE
	F. T. E. NO.			P. O. NO.	P. O. DATE 03/22/04
COMMENTS					MO: 6829

SEE ATTACHED FULL CIRCLE REPORT CARD.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
JOB # 5 TOTAL PARTS				0.00
JOB # 5 TOTAL LABOR & PARTS				0.00
J# 6+00MAZTIRG			TIRE INSPECTION UNITS: TECH(S):37620 UPON INSPECTION OF TIRES, 50 PERCENT OR MORE IS REMAINING	
JOB # 6 TOTAL PARTS				0.00
JOB # 6 TOTAL LABOR & PARTS				0.00
J# 7+00MAZBRKG			BRAKE STATIS UNITS: TECH(S):37620 UPON INSPECTION OF FRONT AND REAR BRAKE LININGS, FOUND 50 PER CENT OR MORE REMAINING NO REPAIRS	
JOB # 7 TOTAL PARTS				0.00
JOB # 7 TOTAL LABOR & PARTS				0.00
TOTALS				
TOTAL LABOR....				0.00
TOTAL PARTS....				0.00
TOTAL SUBLET....				0.00
TOTAL G.O.G....				0.00
TOTAL MISC CHG.				0.00
TOTAL MISC DISC				0.00
TOTAL TAX.....				0.00
TOTAL INVOICE \$				0.00

CUSTOMER SIGNATURE _____



JIM Ellis
Expect the best



MAZDA

1141 Cobb Parkway MARIETTA, GEORGIA 30060
(770) 590-4450

CUSTOMER NO. 97308	ADVISOR DOUG ALDRIDGE	300344	TAG NO. 8406	INVOICE DATE 08/25/04	INVOICE NO. MICS620438
CHARLES JOSEPH SHATZEN 5270 RIVER MILL CIR MARIETTA, GA 30068-4726	LABOR RATE	LICENSE NO.	MILEAGE 9,975	COLOR BLACK/BLACK	STOCK NO. Z42587
	YEAR / MAKE / MODEL 04/MAZDA/RX8/RX8 6SPD MAN. 250HP	DELIVERY DATE 09/09/03		DELIVERY MILES 7	
	VEHICLE I.D. NO. J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3	SELLING DEALER NO. 23466		PRODUCTION DATE	
	F. T. E. NO.	P. O. NO.	R. O. DATE 08/23/04		
COMMENTS					MO: 9982

LABOR & PARTS	UNITS	TECH(S)	WARRANTY
J# 1 11MAZ008 AIR CONDITIONING CUSTOMER STATES A/C STOPS BLOWING COLD SOP		37620	
JOB # 1 TOTAL LABOR & PARTS			0.00
J# 2 00MAZ99P FULL CIRCLE SERVICE FULL CIRCLE SERVICE INSPECTION SEE ATTACHED FULL CIRCLE REPORT CARD.		37620	
JOB # 2 TOTAL LABOR & PARTS			0.00
J# 3+08MAZ005 BRAKES/MECHANICAL CUSTOMER STATES: BRAKES VIBRATE WHEN APPLIED, ADVISE BOTH FT ROTORS WOPPED AND WAVIE MACHINE BOTH FT ROTORS WOPPED WAVIE	1.20	37620	WARRANTY
JOB # 3 TOTAL LABOR & PARTS			0.00
J# 4+04MAZ000 ENGINE/BLOCK ASSY CUSTOMER STATES: VEHICLE IS HARD TO START AT TIMES. ADVISE PCM REFLASH REFLASH PCM WITH UPDATES N3H6-18881-M PREFORM TEST DRIVE	0.30	37620	WARRANTY
JOB # 4 TOTAL LABOR & PARTS			0.00
J# 5+00MAZTIRG TIRE INSPECTION UPON INSPECTION OF TIRES, 50 PERCENT OR MORE IS REMAINING		37620	
JOB # 5 TOTAL LABOR & PARTS			0.00
J# 6+00MAZBRKG BRAKE STATIS UPON INSPECTION OF FRONT AND REAR BRAKE LININGS, FOUND 50 PER CENT OR MORE REMAINING NO REPAIRS		37620	
JOB # 6 TOTAL LABOR & PARTS			0.00



MAZDA

5855 Peachtree Industrial Blvd. ATLANTA, GEORGIA 30341
(770) 454-3300

CUSTOMER NO: 97308	ADVISOR STEVEN DOOLEY	27950	PAGE NO. M945	INVOICE DATE 11/07/05	INVOICE NO. MACS773075
CHARLES JOSEPH SHATZEN 5270 RIVER MILL CIR MARIETTA, GA 30068-4726	LABOR RATE 85.00	LICENSE NO.	MILEAGE 15,059	COLOR BLACK/BLACK	STOCK NO. Z42587
	YEAR / MAKE / MODEL 04/MAZDA/RX8/RX8 6SPD MAN. 250HP			DELIVERY DATE 09/09/03	DELIVERY MILES 7
	VEHICLE I.D. NO. J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO. 23466	PRODUCTION DATE
	E.T.E. NO.			P.O. NO.	R.O. DATE 11/04/05
COMMENTS					MO: 15064

JOB # 9 TOTAL LABOR & PARTS		0.00
G.O.G. & SUPPLIES		
JOB # 4	FREIGHT (PARTS)	
TOTAL - GOG		0.00
WARRANTY		0.00
ESTIMATE-----		
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$0.00 (+TAX)		
COMMENTS-----		
RECOMMENDED JUAN DELGADO.		
TOTALS-----		

*IN THE NEAR FUTURE, YOU WILL BE RECEIVING *		TOTAL LABOR.... 0.00
*A SURVEY FROM THE MANUFACTURER. IF FOR *		TOTAL PARTS.... 0.00
*ANY REASON YOU CANNOT ANSWER "EXCELLENT" *		TOTAL SUBLET... 0.00
**YES" OR "EXTREMELY SATISFIED" PLEASE *		TOTAL G.O.G.... 0.00
*CONTACT YOUR SERVICE ADVISOR OR SERVICE *		TOTAL MISC CHG. 0.00
* MANAGER *		TOTAL MISC DISC 0.00
*****		TOTAL TAX..... 0.00
TOTAL INVOICE \$		0.00
CUSTOMER CALLED BY:.....AT.....ON.....		
(advisor) (time) (date)		
INVOICE AMOUNT & REPAIRS REVIEWED WITH CUSTOMER.....(check)		
_____ CUSTOMER SIGNATURE		

Reynolds and Reynolds, BRAINTINE, GM69825 Q (10/02)



FULL CIRCLE SERVICE REPORT CARD

Customer Name: Shatzen Year/Model: _____

Date: _____ License: _____ VIN: _____

RO/Tag#: _____ Mileage: _____

INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	REQUIRES IMMEDIATE ATTENTION
------------------------	--------------------------------	------------------------------

Inspect Each Service	Info. / Estimate	Check Tires/Measure Tire Tread Depth
----------------------	------------------	--------------------------------------

<input checked="" type="checkbox"/>	C	<input type="checkbox"/>	Window washer fluid level	
<input checked="" type="checkbox"/>	H	<input type="checkbox"/>	Automatic transmission fluid level/condition	
<input checked="" type="checkbox"/>	E	<input type="checkbox"/>	Brake fluid level/condition	
<input checked="" type="checkbox"/>	C	<input type="checkbox"/>	Power steering fluid level/condition	
<input checked="" type="checkbox"/>	K	<input type="checkbox"/>	Coolant recovery reservoir fluid level/condition	
<input checked="" type="checkbox"/>	&	<input type="checkbox"/>	Transaxle, transfer case, clutch reservoir fluid/condition (as equipped)	
<input checked="" type="checkbox"/>	F	<input type="checkbox"/>	Windshield for cracks, chips and pitting	
<input checked="" type="checkbox"/>	I	<input type="checkbox"/>	Operation of horn, interior and exterior lights	
<input checked="" type="checkbox"/>	L	<input type="checkbox"/>	Windshield washer spray and wiper operation	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Cooling system for visible leaks and damage	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Oil and/or fluid leaks (Specify _____)	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Constant velocity (CV) drive axle boots (if equipped)	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Exhaust system (leaks, visible damage, loose parts)	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Drive belt(s)	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Steering, steering linkages/wheel end play/bearings	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Suspension (shocks/struts for bounce/leaks/damage)	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Brake lines, hoses, parking brake	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Battery terminals (clean, if necessary)	
<input checked="" type="checkbox"/>		<input type="checkbox"/>	Clutch operation (if equipped)	

Tire Pressure Set to Factory Recommendation


DOWN TO WEAR BAR



LF	<input checked="" type="checkbox"/>	RF	<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
LR	<input checked="" type="checkbox"/>	RR	<input checked="" type="checkbox"/>

50% or more remaining
20% - 50% remaining
Less than 20% remaining

Measure Front / Rear Brake Linings



LF	<input checked="" type="checkbox"/>	RF	<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>
LR	<input checked="" type="checkbox"/>	RR	<input checked="" type="checkbox"/>

Recommended Additional Services

<input type="checkbox"/>	<input type="checkbox"/>	Rotate Tires	
<input type="checkbox"/>	<input type="checkbox"/>	Air Filter	
<input type="checkbox"/>	<input type="checkbox"/>	Wiper Inserts	
<input type="checkbox"/>	<input type="checkbox"/>	Tire Repair	
<input type="checkbox"/>	<input type="checkbox"/>	Brakes (Specify)	
<input type="checkbox"/>	<input type="checkbox"/>	Other	

Brake Measurements Not Taken This Service Visit

50% or more remaining
20% - 50% remaining
Less than 20% remaining

Check Battery Performance

<input checked="" type="checkbox"/>	Good	 Actual Cold Cranking Amps and/or attach test results <input type="text"/>
<input type="checkbox"/>	Bad	

Customer Signature _____

White Copy - Customer • Yellow - Attach to RO File Copy



3546 BUFORD DRIVE
 (HWY. 20)
 BUFORD, GA 30519
 (678) 714-9000

CUSTOMER NO. 10166	ADVISOR SUSAN WHITE	6574	TAG NO. 1792	INVOICE DATE 10/16/06	INVOICE NO. MACS10430
CHARLIE SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068-4726	LABOR RATE	LICENSE NO.	MILEAGE 19,283	COLOR /	STOCK NO.
	YEAR / MAKE / MODEL 04/MAZDA/RX-8/2 DOOR COUPE			DELIVERY DATE	DELIVERY MILES
	VEHICLE I.D. NO. J M I F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 10/09/06		
BUSINESS PHONE	COMMENTS				

JOB# 1 CHARGES

LABOR
 J# 1 31MAZ01 MANUAL TRANS CONCERN TECH(S):5007
 CUSTOMER STATES TRANSMISSION IS GRINDING WHEN SHIFTING FROM FROM 1ST INTO 2ND GEAR
 FOUND 2ND GEAR GRINDS ON UP SHIFT & DOWNSHIFT; TORE DOWN TRANS & FOUND 2ND GEAR ENGAGEMENT TEETH ROUNDED; SYNCRO WORN & TEETH ROUNDED; SLIDING SLEEVE TEETH ROUNDED; SHIFT FORK FRO END GEAR IS ALSO WORN BELOW SPECS
 REPLACED ALL ABOVE PARTS & REASSEMBLED - TEST DROVE NORMAL OPERATION AT THIS TIME

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
	1	Y602-17-233	BEARING,NE	
	1	Y611-17-262	SLEEVE,CLU	
	1	Y611-17-26Y	RING,SYNCH	
	1	Y611-17-251	GEAR,2ND	
	1	8527-77-739	TUBE,SILIC	
	1	Y601-17-40X	SHIFT FORK	
	3	0000-77-80W9-QT	SAE 80W-90	
	1	Y612-17-640A	SWITCH,PAR	
				TOTAL - PARTS

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on vehicle to secure the amount of repairs thereto.

THANK YOU FOR THIS OPPORTUNITY TO SERVE YOU. IT IS OUR AIM TO PERFORM ALL THE REPAIRS REQUESTED ON THIS REPAIR ORDER TO YOUR COMPLETE SATISFACTION. IF OUR SERVICE WAS SATISFACTORY TELL YOUR FRIENDS. IF NOT, PLEASE TELL US IMMEDIATELY.

JOB# 1 TOTALS

JOB# 1 JOURNAL PREFIX MACS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES

LABOR
 J# 2 00MAZ99P FULL CIRCLE INSPECT TECH(S):5007
 PERFORM COMPLIMENTARY MAZDA FULL CIRCLE INSPECTION
 FULL CIRCLE INSPECTION COMPLETE
 COPY OF INSPECTION RESULTS ATTACHED

JOB# 2 TOTALS

JOB# 2 JOURNAL PREFIX MACS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR
 J# 3 10MAZR X RX8 RECALL - PART A TECH(S):5007
 RECALL 4206F - PART A IS OUTSTANDING
 COMPLETED RECALL PART A - PCM REPROGRAM
 PNMC: 7777-18-019/L0: XXB390R1/PROCESS: A0634A

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
	2	N3Z4-18-110	SPARK PLUG	
				TOTAL - PARTS

JOB# 3 TOTALS

JOB# 3 JOURNAL PREFIX MACS JOB# 3 TOTAL 0.00



JIM Ellis
Expect the best



MAZDA

1141 Cobb Parkway MARIETTA, GEORGIA 30060
(770) 590-4450

CUSTOMER NO. 97308	ADVISOR DOUG ALDRIDGE	300344	TAG NO. 8406	INVOICE DATE 08/25/04	INVOICE NO. M1CS620438
CHARLES JOSEPH SHATZEN 5270 RIVER MILL CIR MARIETTA, GA 30068-4726	LABOR RATE	LICENSE NO.	MILEAGE 9,975	COLOR BLACK/BLACK	STOCK NO. Z42587
	YEAR / MAKE / MODEL 04/MAZDA/RX8/RX8 6SPD MAN. 250HP			DELIVERY DATE 09/09/03	DELIVERY MILES 7
	VEHICLE I.D. NO. J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO. 23466	PRODUCTION DATE
	F. T. E. NO.		P. O. NO.		REC. DATE 08/23/04
COMMENTS					MO: 9982

TOTALS	
TOTAL LABOR....	0.00
TOTAL PARTS....	0.00
TOTAL SUBLET....	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	0.00
TOTAL MISC DISC	0.00
TOTAL TAX.....	0.00
TOTAL INVOICE \$	0.00

CUSTOMER SIGNATURE



3546 BUFORD DRIVE
 (HWY. 20)
 BUFORD, GA 30519
 (678) 714-9000

CUSTOMER NO.	10166	ADVISOR	SUSAN WHITE	6574	TAG NO.	1792	INVOICE DATE	10/16/06	INVOICE NO.	MACS10430	
CHARLIE SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068-4726	LABOR RATE	LICENSE NO.	MILEAGE	19,283	COLOR	7	STOCK NO.				
	YEAR / MAKE / MODEL	04/MAZDA/RX-8/2 DOOR COUPE					DELIVERY DATE	DELIVERY MILES			
	VEHICLE I.D. NO.	J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3					SELLING DEALER NO.	PRODUCTION DATE			
	F.T.E. NO.	P.O. NO.	P.O. DATE	10/09/06							
BUSINESS PHONE	COMMENTS										

JOB# 1 CHARGES

LABOR	WARRANTY									
J# 1 31MAZ01	MANUAL TRANS CONCERN	TECH(S):5007								
CUSTOMER STATES TRANSMISSION IS GRINDING WHEN SHIFTING FROM FROM 1ST INTO 2ND GEAR FOUND 2ND GEAR GRINDS ON UP SHIFT & DOWNSHIFT; TORE DOWN TRANS & FOUND 2ND GEAR ENGAGEMENT TEETH ROUNDED; SYNCRO WORN & TEETH ROUNDED; SLIDING SLEEVE TEETH ROUNDED; SHIFT FORK FRO END GEAR IS ALSO WORN BELOW SPECS REPLACED ALL ABOVE PARTS & REASSEMBLED - TEST DROVE NORMAL OPERATION AT THIS TIME										
PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY					
	1	Y602-17-233	BEARING, NE		WARRANTY					
	1	Y611-17-262	SLEEVE, CLU		WARRANTY					
	1	Y611-17-26Y	RING, SYNCH		WARRANTY					
	1	Y611-17-251	GEAR, 2ND		WARRANTY					
	1	8527-77-739	TUBE, SILIC		WARRANTY					
	1	Y601-17-40X	SHIFT FORK		WARRANTY					
	3	0000-77-80W9-QT	SAE 80W-90		WARRANTY					
	1	Y612-17-640A	SWITCH, PAR		WARRANTY					
				TOTAL - PARTS	0.00					

JOB# 1 TOTALS

JOB# 2 CHARGES	JOB# 1 JOURNAL PREFIX	MACS	JOB# 1 TOTAL	0.00
----------------	-----------------------	------	--------------	------

LABOR	WARRANTY									
J# 2 00MAZ99P	FULL CIRCLE INSPECT	TECH(S):5007								
PERFORM COMPLIMENTARY MAZDA FULL CIRCLE INSPECTION FULL CIRCLE INSPECTION COMPLETE COPY OF INSPECTION RESULTS ATTACHED										
JOB# 2 TOTALS	0.00									

JOB# 2 TOTALS

JOB# 3 CHARGES	JOB# 2 JOURNAL PREFIX	MACS	JOB# 2 TOTAL	0.00
----------------	-----------------------	------	--------------	------

LABOR	WARRANTY									
J# 3 10MAZRX	RX8 RECALL - PART A	TECH(S):5007								
RECALL 4206F - PART A IS OUTSTANDING COMPLETED RECALL PART A - PCM REPROGRAM PNMC: 7777-18-019/LO: XXB390R1/PROCESS: A0634A										

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY					
	2	N324-18-110	SPARK PLUG		WARRANTY					
				TOTAL - PARTS	0.00					

JOB# 3 TOTALS

JOB# 3 JOURNAL PREFIX	MACS	JOB# 3 TOTAL	0.00
-----------------------	------	--------------	------

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on vehicle to secure the amount of repairs thereto.

THANK YOU FOR THIS OPPORTUNITY TO SERVE YOU. IT IS OUR AIM TO PERFORM ALL THE REPAIRS REQUESTED ON THIS REPAIR ORDER TO YOUR COMPLETE SATISFACTION. IF OUR SERVICE WAS SATISFACTORY TELL YOUR FRIENDS, IF NOT, PLEASE TELL US IMMEDIATELY.

Reynolds and Reynolds EPANTINVE C2648756 Q (09/05)



3546 BUFORD DRIVE
(HWY. 20)
BUFORD, GA 30519
(678) 714-9000

CUSTOMER NO.	10166	ADVISOR	SUSAN WHITE	6574	TAG NO.	1792	INVOICE DATE	10/16/06	INVOICE NO.	MACS10430	
CHARLIE SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068-4726	LABOR RATE	LICENSE NO.	MILEAGE	19,283	COLOR	/	STOCK NO.				
	YEAR / MAKE / MODEL	04/MAZDA/RX-8/2 DOOR COUPE					DELIVERY DATE	DELIVERY MILES			
	VEHICLE I.D. NO.	J M 1 F E 1 7 3 4 4 0 1 0 7 2 5 3					SELLING DEALER NO.	PRODUCTION DATE			
	F.T.E. NO.	R.O. NO.	F.O. DATE	10/09/06							
F	BUSINESS PHONE	COMMENTS									
JOB# 4 CHARGES -----											
LABOR -----											
J# 4 10MAZRXB RX8 RECALL - PART B TECH(S):5007 WARRANTY COMPLETE RX8 RECALL 4206F PART B COMPLETED PART B OF RECALL 4206F: CAT CONV INSPECTION PNMC: N3Y1-20-SA0/LO: XXB392R1/PROCESS: A0635A											
JOB# 4 TOTALS -----											
JOB# 4 JOURNAL PREFIX MACS JOB# 4 TOTAL 0.00											
JOB# 5 CHARGES -----											
LABOR -----											
J# 5 10MAZR8WA RX8 COURTESY WASH TECH(S):5007 WARRANTY CUSTOMER REQUESTS PLS COMPLETE COURTESY WASH PER RECALL 4206 PNMC: 5555R8003A / LBR OP: MM017XR2 / SUB INV: WASH / TYPE X COMPLETED											
JOB# 5 TOTALS -----											
JOB# 5 JOURNAL PREFIX MACS JOB# 5 TOTAL 0.00											
JOB# 6 CHARGES -----											
LABOR -----											
J# 6 10MAZRXF RX8 RECALL REFUEL TECH(S):5007 WARRANTY CUSTOMER REQUESTS PLS REFUEL PER RECALL 4206F PNMC: 5555R8002A / LBR OP: MM017XR3 / INV: FUEL / TYPE X COMPLETED											
G.O.G. & SUPPLIES -----											
1.0 GAS SPEED 6/RX-8 @ /UNIT TOTAL - GOG WARRANTY 0.00											
JOB# 6 TOTALS -----											
JOB# 6 JOURNAL PREFIX MACS JOB# 6 TOTAL 0.00											
JOB# 7 CHARGES -----											
LABOR -----											
J# 7+70MAZRENTAL RENTAL VEHICLE TECH(S):5007 WARRANTY RENTAL VEHICLE WAS PROVIDED TO CUSTOMER M-CODE RENTAL - CX7											
JOB# 7 TOTALS -----											
JOB# 7 JOURNAL PREFIX MACS JOB# 7 TOTAL 0.00											
JOB# 8 CHARGES -----											
LABOR -----											
J# 8+00MAZTIRG FULL CIR TIRE INSP. TECH(S):5007 0.00 PERFORM FULL CIRCLE TIRE INSPECTION TREAD LIFE IS OVER 50% REMAINING - TIRES ARE GOOD AT THIS TIME											

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on vehicle to secure the amount of repairs thereto.

THANK YOU FOR THIS OPPORTUNITY TO SERVE YOU. IT IS OUR AIM TO PERFORM ALL THE REPAIRS REQUESTED ON THIS REPAIR ORDER TO YOUR COMPLETE SATISFACTION. IF OUR SERVICE WAS SATISFACTORY TELL YOUR FRIENDS, IF NOT, PLEASE TELL US IMMEDIATELY.

Reynolds and Reynolds ERAUT/INVE C0648759 Q (00/05)



3546 BUFORD DRIVE
 (HWY. 20)
 BUFORD, GA 30519
 (678) 714-9000

CUSTOMER NO. 10166	ADVISOR SUSAN WHITE	6574	TAG NO. 1792	INVOICE DATE 10/16/06	INVOICE NO. MACS10430
CHARLIE SHATZEN 5270 RIVER MILL CIRCLE MARIETTA, GA 30068-4726	LABOR RATE	LICENSE NO.	MILEAGE 19,283	COLOR /	STOCK NO.
	YEAR / MAKE / MODEL 04/MAZDA/RX-8/2 DOOR COUPE			DELIVERY DATE	DELIVERY MILES
	VEHICLE I.D. NO. J M I F E 1 7 3 4 4 0 1 0 7 2 5 3			SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 10/09/06		
BUSINESS PHONE	COMMENTS				

JOB# 8 TOTALS-----			JOB# 8 JOURNAL PREFIX MACS	JOB# 8 TOTAL	0.00
JOB# 9 CHARGES-----			JOB# 9 JOURNAL PREFIX MACS	JOB# 9 TOTAL	0.00
LABOR-----	J#9+00MAZBRKG FULL CIR BRAKE INSP.		TECH(S):5007		0.00
PERFORM FULL CIRCLE VISUAL BRAKE INSPECTION BRAKE PADS HAVE APPROX 50% OR MORE REMAINING BRAKES ARE GOOD AT THIS TIME					
JOB# 9 TOTALS-----			JOB# 9 JOURNAL PREFIX MACS	JOB# 9 TOTAL	0.00
JOB# 10 CHARGES-----			JOB# 10 JOURNAL PREFIX MACS	JOB# 10 TOTAL	0.00
LABOR-----	J#10+00MAZBATT FULL CIR BATT INSP.		TECH(S):5007		0.00
PERFORMED FULL CIRCLE BATTERY INSPECTION BATTERY TESTS GOOD AT THIS TIME					
JOB# 10 TOTALS-----			JOB# 10 JOURNAL PREFIX MACS	JOB# 10 TOTAL	0.00
TOTALS-----					
*****			TOTAL LABOR....		0.00
* [] CASH [] CHECK CK NO. []			TOTAL PARTS....		0.00
* [] VISA [] MASTERCARD [] DISCOVER			TOTAL SUBLET...		0.00
* [] AMER XPRESS [] OTHER [] CHARGE			TOTAL G.O.G....		0.00
* DATE PAID [/ /] CASHIER INITIALS []			TOTAL MISC CHG.		0.00
*****			TOTAL MISC DISC		0.00
			TOTAL TAX.....		0.00
			TOTAL INVOICE \$		0.00

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on vehicle to secure the amount of repairs thereto.

THANK YOU FOR THIS OPPORTUNITY TO SERVE YOU. IT IS OUR AIM TO PERFORM ALL THE REPAIRS REQUESTED ON THIS REPAIR ORDER TO YOUR COMPLETE SATISFACTION. IF OUR SERVICE WAS SATISFACTORY TELL YOUR FRIENDS, IF NOT, PLEASE TELL US IMMEDIATELY.

THANK YOU AND WE APPRECIATE YOUR BUSINESS!
 YOU MAY RECEIVE A SURVEY FROM MAZDA ABOUT YOUR VISIT TODAY
 IF FOR ANY REASON YOU ARE NOT COMPLETELY SATISFIED PLEASE
 CALL SUSAN WHITE DIRECTLY TO ANSWER ANY QUESTIONS OR RESOLVE
 ANY SERVICE ISSUES YOU MAY HAVE

 CUSTOMER SIGNATURE

CUSTOMER #: 1018447

2920526Z



INVOICE

MAZDA OF MARIETTA

1715 Cobb Parkway SE · Marietta, GA 30060
Main: (770) 590-4450
www.jimellis.com

PAGE 3

SERVICE ADVISOR: 300344 DOUGLAS ALDRIDGE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	MAZDA RX8	JM1FE173440107253		41061/41065	T4996	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
03SEP03 IS							
09SEP03 DD		03SEP2006	19:00 27JUL20		0.00	CASH	10AUG20

R.O. OPENED READY OPTIONS: DLR:23466 ENG:1.3 LITER

08:04 27JUL20 14:58 10AUG20

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

I** PERFORM INDUCTION SERVICE
 BGISK PERFORM INDUCTION SERVICE
 300385 CPC 102.45 102.45
 6592T GATX 4.68 4.68
 6592 GDI FUEL INDUCTION 78.00 78.00
 PARTS: 0.00 LABOR: 102.45 OTHER: 82.68 TOTAL LINE I: 185.13
 41065 PERFORM INDUCTION SERVICE.


J** PERFORM THROTTLE BODY CLEANING SERVICE
 BGTB PERFORM THROTTLE BODY CLEANING SERVICE
 300385 CPC 55.45 55.45
 4068 THROTTLE BODY 22.50 22.50
 4068T GATX 1.35 1.35
 PARTS: 0.00 LABOR: 55.45 OTHER: 23.85 TOTAL LINE J: 79.30
 41065 PERFORM THROTTLE BODY CLEANING SERVICE.

EST: 465.23 07AUG20 16:00 SA: 300344

CONTACT:

CUSTOMER PAY SUPPLY FEE FOR REPAIR ORDER 28.03

COMPANY NAME FIDELITY WARRANTY
 COMPANY PHONE
 POLICY NUMBER 80160326
 POLICY TERM
 EFFECTIVE DATE
 DEDUCTIBLE 0.00
 MILEAGE LIMIT
 BEGIN MILES
 END MILES
 COMPONENTS



Please read carefully the statement below, and sign. 72 hours after completion of work on the vehicle, I will incur a storage fee of \$10.00 a day, I, the undersigned, agree to pay all court costs and a reasonable attorney's fee and, or collection agency fee.

TERMS STRICTLY CASH UNLESS ARRANGEMENTS MADE
ALL PARTS REMOVED WILL BE DISCARDED UNLESS SPECIFIED OTHERWISE.

"The Factory Warranty constitutes all of the warranties with respect to the seller of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose and the seller neither assumes nor authorizes an other person to assume for it any liability in connection with the sale of this item/items."

AUTHORIZATION FOR REPAIR AND DISCLAIMER FOR DELAY, LOSS OR DAMAGE

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	280.34
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	216.96
TOTAL CHARGES	497.30
LESS INSURANCE	0.00
SALES TAX	1.68
PLEASE PAY THIS AMOUNT	498.98

CUSTOMER SIGNATURE

CUSTOMER COPY

CUSTOMER #: 1018447

2920526Z



INVOICE

MAZDA OF MARIETTA

1715 Cobb Parkway SE · Marietta, GA 30060
Main: (770) 590-4450
www.jimellis.com

PAGE 2

SERVICE ADVISOR: 300344 DOUGLAS ALDRIDGE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	MAZDA RX8	JM1FE173440107253		41061/41065	T4996	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
03SEP03 IS							
09SEP03 DD		03SEP2006	19:00 27JUL20		0.00	CASH	10AUG20
R.O. OPENED	READY	OPTIONS: DLR:23466 ENG:1.3 LITER					
08:04 27JUL20	14:58 10AUG20						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
DISCONNECTED AT TIMES FOR 1 MONTH. LAST TIME WHEN HOOKED BACK UP THE ELECTRICAL SYSTEM WENT CRAZY SO VEH WAS TOWED HERE BUT VEHICLE STARTED RIGHT UP OFF THE TRAILER NPF UNABLE TO REPRODUCE CUSTOMER COMPLAINT AT THIS TIME,							
PARTS:						0.00	0.00
	300385		C				
	0.00	LABOR:		0.00	OTHER:	0.00	TOTAL LINE D:

E COMPLIMENTARY MAZDA FULL CIRCLE INSPECTION, \$49.95 VALUE							
99P COMPLIMENTARY MAZDA FULL CIRCLE INSPECTION, \$49.95 VALUE							
	300385		C			0.00	0.00
		CF compliance fee				2.95	2.95
PARTS:						0.00	0.00
	0.00	LABOR:		0.00	OTHER:	2.95	TOTAL LINE E:

F** Tires - Rotate							
MA40 Tires - Rotate							
	300385		CQS			19.95	19.95
PARTS:						0.00	0.00
	0.00	LABOR:		19.95	OTHER:	0.00	TOTAL LINE F:

G** AC EVAPORATOR CORE CLEANING SERVICE							
BGEVAP AC EVAPORATOR CORE CLEANING SERVICE							
	300385		C			52.49	52.49
	709	FRIGI CLEAN				45.00	45.00
	709T	GATX				2.70	2.70
PARTS:						0.00	0.00
	0.00	LABOR:		52.49	OTHER:	47.70	TOTAL LINE G:

H** PERFORM MASS AIR FLOW SENSOR CLEANING SERVICE							
BGMAF PERFORM MASS AIR FLOW SENSOR CLEANING SERVICE							
	300385		CPC			50.00	50.00
	4073	MASS AIR FLOW				29.95	29.95
	4073T	GATX				1.80	1.80
PARTS:						0.00	0.00
	0.00	LABOR:		50.00	OTHER:	31.75	TOTAL LINE H:

Please read carefully the statement below, and sign, 72 hours after completion of work on the vehicle, I will incur a storage fee of \$10.00 a day, I, the undersigned, agree to pay all court costs and a reasonable attorney's fee and, or collection agency fee.

TERMS STRICTLY CASH UNLESS ARRANGEMENTS MADE
ALL PARTS REMOVED WILL BE DISCARDED UNLESS SPECIFIED OTHERWISE.

"The Factory Warranty constitutes all of the warranties with respect to the seller of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose and the seller neither assumes nor authorizes an other person to assume for it any liability in connection with the sale of this item/items."

AUTHORIZATION FOR REPAIR AND DISCLAIMER FOR DELAY, LOSS OR DAMAGE

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #: 1018447

2920526Z



INVOICE

MAZDA OF MARIETTA

1715 Cobb Parkway SE · Marietta, GA 30060
Main: (770) 590-4450
www.jimellis.com

PAGE 1

SERVICE ADVISOR: 300344 DOUGLAS ALDRIDGE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
BLACK	04	MAZDA RX8	JM1FE173440107253		41061/41065	T4996	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
03SEP03 IS							
09SEP03 DL		03SEP2006	19:00 27JUL20		0.00	CASH	10AUG20
R.O. OPENED	READY	OPTIONS: DLR:23466 ENG:1.3 LITER					
08:04 27JUL20	14:58 10AUG20						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A Fuel Tank Leak At Fuel Pump Discharge Outlet Port
CAUSE: FF

XXN6GCRX R1017E: REPLACE PUMP RING SET AND FDD
(INCLUD

300385 W

1 F1Y1-42-A1X NUT,RETAINER & GASKET KIT

(N/C)

(N/C)

XXN6GDRX R1017E: REPLACE PUMP RING SET AND FDD
(INCLUD

300385 W

1 N3Y1-13-ZE0C FILTER,FUEL PUMP

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

211824 PERFORM RECALL 1017E. DRAIN TANK AND INSTALL FUEL PUMP AND
LOCK RINGS AND GASKETS. REFILL TANK AND ROAD TEST.

B Front Lower Arm Ball Joint

CAUSE: FF

XXN61ARX 1117E: FRONT LOWER ARM, R&R (INCL. WHEEL
ALIG

300385 W

1 F1Y1-34-30XA KIT,LWR ARMS

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

211824 PERFORM RECALL 1117E. REPLACE LOWER CONTROL ARMS AND ROAD
TEST.

C Permanent Passenger Airbag Inflator

CAUSE: FF

XXP7AARX R2618F PASSENGER SIDE AIR BAG INFLATOR
(APPS)

300385 W

1 F1Z2-57-K80 INFLATOR, AIR BAG

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

41065 PERFORM RECALL 2618F. REPLACE PASS AIR BAG INFLATOR.

D CUSTOMER STATES VEHICLE IS NOT DRIVEN VERY MUCH AND THE BATTERY IS

Please read carefully the statement below, and sign, 72 hours after completion of work on the vehicle, I will incur a storage fee of \$10.00 a day, I, the undersigned, agree to pay all court costs and a reasonable attorney's fee and, or collection agency fee.

TERMS STRICTLY CASH UNLESS ARRANGEMENTS MADE
ALL PARTS REMOVED WILL BE DISCARDED UNLESS SPECIFIED OTHERWISE.

"The Factory Warranty constitutes all of the warranties with respect to the seller of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose and the seller neither assumes nor authorizes an other person to assume for it any liability in connection with the sale of this item/items."

AUTHORIZATION FOR REPAIR AND DISCLAIMER FOR DELAY, LOSS OR DAMAGE

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER SIGNATURE

CUSTOMER COPY