

Dealer: SAN DIEGO EUROPEAN MOTORCARS LTD
 Model: DBS Superleggera Coupe Engine Number: AE3153047
 Model Year: 2019 VIN: SCFRMHA5V8KGR00661
 Exterior Colour: Hyper Red
 Interior Colour: Metallic Black Leather/Spicy Red Leather

Owner Benefits: Port of Entry
 3 years unlimited mileage warranty Suggested Retail Price at P.O.E.

\$333,095.00

24 hour roadside assistance

STANDARD FEATURES

Engineering and Performance
 2-door coupe
 715hp 5.2L Twin Turbo V12 Engine
 8-speed automatic transmission, rear-mid mounted
 Limited-Slip Differential and Active Torque Vectoring via Braking
 3 Selectable Powertrain & Adaptive Driving System Drive Modes - GT, Sport, Sport+
 Full LED Headlights with integrated DRLs, side lights, and cornering lights
 Carbon Fiber Hood, Trunk, Spoiler, and Diffuser
 Carbon Ceramic Brakes
 21" Alloy Wheels
 Safety and Security
 Dynamic Stability Control (DSC), Traction Control (TC), and Positive Torque Control (PTC)
 Dual-Stage Driver & Passenger Front Airbags and Seat Mounted & Curtain Side Impact Airbags
 Tire Pressure Monitoring System (TPMS)
 Comfort and Convenience
 8" Navigation System
 Bluetooth Phone & Streaming Audio
 Satellite Radio with Trial Subscription - 1yr Radio, 3yr Traffic Data
 iPhone® Integration and USB Input
 360 Degree Camera with Front & Rear Parking Sensors
 Power Folding Heated Exterior Mirrors
 Keyless Entry/Keyless Go w/Crystal Start Button
 12-Way Heated Front Seats with 3-Position Memory
 Power-Adjustable Tilt/Telescoping Steering Column
 12" Color TFT LCD Cluster
 Dual-Zone Automatic Climate Control
 Rain-Sensing Wipers
 Electronic Park Brake (EPB)

OPTIONAL EQUIPMENT

Leather Colour - AME Special Part - Special AME Colour \$5,330.00
 Bang & Olufsen BeoSound Audio \$8,330.00
 Ventilated Front Seats \$1,595.00
 Stitching / Welt - Contrast Colour \$2,270.00
 Alcantara - Contemporary \$1,595.00
 Two Leather Colour Interior \$750.00
 Roof Strake - Carbon Gloss \$3,190.00
 Fender Louvre - Carbon Fibre Gloss \$3,785.00
 Heavy Plt Floor Mats / Leather Binding \$750.00
 Hood Louvre - Gloss Carbon \$3,190.00
 Roof Panel - Carbon Fibre \$4,545.00
 Traxial Quilting \$3,190.00
 Personalised Sill Plaques \$750.00
 Colour Keyed Steering Wheel \$750.00
 Smoked Rear Lamps \$750.00
 Umbrella \$295.00
 Forged Y Spoke - Satin Black/Gloss Black \$3,785.00

Gas Guzzler \$1,000.00
 Transportation and handling \$3,066.00
TOTAL SUGGESTED RETAIL* \$358,361.00

EPA DOT Fuel Economy and Environment Gasoline Vehicle

Fuel Economy
 17 MPG combined city/hwy
 14 MPG city
 22 MPG highway
 5.9 gallons per 100 miles

You spend \$6,250 more in fuel costs over 5 years compared to the average new vehicle.

Annual fuel cost \$2,650

Fuel Economy & Greenhouse Gas Rating 3 (Best)

Smog Rating 3 (Best)

Actual results will vary for many reasons, including driving conditions and how you drive and maintain your vehicle. The average new vehicle gets 27 MPG and costs \$7000 to fuel over 5 years. Cost estimates are based on 15,000 miles at \$3.00 per gallon. MPG is miles per gallon equivalent. Vehicle emissions are a significant cause of climate change and smog.

fueleconomy.gov
 Calculate personalized estimates and compare vehicles

Smartphone QR Code

PARTS CONTENT INFORMATION
 FOR VEHICLES IN THIS CARLINE:
 U.S./CANADIAN PARTS CONTENT: 3%

MAJOR SOURCES OF FOREIGN PARTS CONTENT:
 UK 66%
 Germany 22%

NOTE: PARTS CONTENT DOES NOT INCLUDE FINAL ASSEMBLY, DISTRIBUTION OR OTHER NON-PARTS COSTS.

FOR THIS VEHICLE:
FINAL ASSEMBLY POINT:
 Gaydon, Warwickshire, UK

COUNTRY OF ORIGIN:
ENGINE PARTS:
 GERMANY

TRANSMISSION PARTS:
 GERMANY

BUMPER QUALITY LABEL
 THIS VEHICLE IS EQUIPPED WITH A FRONT BUMPER THAT HAS BEEN TESTED AT AN IMPACT SPEED OF 2.5 MILES PER HOUR, AND A REAR BUMPER THAT HAS BEEN TESTED AT AN IMPACT SPEED OF 2.5 MILES PER HOUR AND HAS SUSTAINED NO DAMAGE TO THE VEHICLE'S BODY AND MINIMAL DAMAGE TO THE BUMPER AND ATTACHMENT HARDWARE. MINIMAL DAMAGE TO BUMPER MEANS DAMAGE THAT CAN BE REPAIRED WITH THE USE OF COMMON REPAIR MATERIALS WITHOUT REPLACING PARTS. THE STRONGER THE BUMPER THE LESS LIKELY THE CAR WILL REQUIRE REPAIR AFTER A LOW SPEED COLLISION. (FOR CORNERS, THE IMPACT IS 60% OF THAT STATED ABOVE).

IMPORTANT NOTICE
 THESE IMPACT SPEEDS ARE GOOD FAITH ESTIMATES OF THE SPEEDS AT WHICH THE DESCRIBED EXTENT OF BUMPER DAMAGE WILL NOT BE EXCEEDED BASED ON REASONABLE ENGINEERING JUDGMENT AND DATA FROM TESTING PURSUANT TO THE FEDERAL BUMPER STANDARD WHICH PROHIBITS DAMAGE TO THE VEHICLE BODY OR SAFETY SYSTEM IN 2.5 MPH IMPACTS, BUT SETS NO LIMIT ON DAMAGE TO BUMPERS AND THEIR ASSOCIATED COMPONENTS AND FASTENERS. THIS VEHICLE MEETS THE FEDERAL BUMPER STANDARD AT 2.5 MPH FRONT AND REAR, AND 1.5 MPH ON THE BUMPER CORNERS.

GOVERNMENT 5-STAR SAFETY RATINGS

This vehicle has not been rated by the government for overall vehicle score, frontal crash, side crash or rollover risk.

Source: National Highway Traffic Safety Administration (NHTSA)
 www.safercar.gov or 1-888-327-4236



SALES AGREEMENT

Buyer Name: [REDACTED]
 Address & Phone: [REDACTED]
 Dealer Name: [REDACTED]
 Date of Sale: 08/07/2023

TRADE INFO
 Make: [REDACTED] Model: [REDACTED] Year: [REDACTED]
 VIN: [REDACTED] Mileage: [REDACTED]

LIEN PAYOFF INFO
 Lender Name: [REDACTED]
 Lender Address: [REDACTED]
 Lender City: [REDACTED]
 Lender State: [REDACTED]
 Lender Zip: [REDACTED]

LIEN INFORMATION
 Lienholder Name: MEDALLION BANK
 Lienholder Address: 110 E 66th St, SUITE 210
 Lienholder City: BAY LAKES CITY
 Lienholder State: FL
 Lienholder Zip: 33422

WARRANTY
 I, the undersigned, being the dealer who has sold for resale the vehicle described in this agreement, do hereby warrant to the buyer that the vehicle is in the condition shown and described in this agreement and that it is free from all liens and encumbrances and that the title is clear and marketable. I warrant that the vehicle is free from all liens and encumbrances and that the title is clear and marketable. I warrant that the vehicle is free from all liens and encumbrances and that the title is clear and marketable.

Buyer Signature: [REDACTED]
 Dealer Signature: [REDACTED]
 Date: 08/07/2023

Mercedes-Benz of Midland

CUSTOMER #: 70299 628434 *INVOICE*

5801 Andrews Highway
 Midland, TX 79706
 (432) 699-7993

PAGE 1
 SERVICE ADVISOR: 400865 Michelle Rodriguez

DATE	PROD. DATE	WARRANTY	PO NO.	RATE	PAYMENT	INV. DATE
01JAN19	DI	READY	18.00 05SEP24	189.95	CASH	10SEP24

01JAN19 DI READY OPTIONS: DL#: 52736

LINE	CD	TECH	TYPE	HOURS	LABOR	OTHER	TOTAL
A	B	05SEP24	10SEP24	18.00	510.00	0.00	510.00

DESCRIPTION:
 FULL SYNTHETIC OIL CHANGE AND F-FILTER REPLACEMENT FLUID TOP OFF, CHANGE COMBINATION-FILTER, BRAKE FLUID EXCHANGE, CHECK AND REGULATE - TIRE PRESSURE, RESET SERVICE INDICATOR LIGHT.

PARTS:
 400191 CP LABOR: 510.00 OTHER: 0.00 TOTAL LINE A: 510.00

DESCRIPTION:
 COOLANT FLUSH - - - - -

PARTS:
 20MB204 COOLANT FLUSH - - - - - LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

DESCRIPTION:
 C/S WHEN PUTTING VEHICLE IN PARK THE SCREEN WILL GO BLACK AND THEN BACK ON - HAS A MERCEDES INFOTAINMENT SYSTEM- PLZ CHK AND ADVISE

PARTS:
 01 ENGINE PERFORMANCE DIAGNOSIS/REPAIR - - - - - LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

DESCRIPTION:
 MULTI-POINT INSPECTION CAUSE: MULTI-POINT INSPECTION

PARTS:
 400191 ISP LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

ODOMETER DISCLOSURE STATEMENT

Federal law (and State law, if applicable) requires that you state the mileage upon transfer of ownership. Failure to complete or providing a false statement may result in fines and/or imprisonment.

I/We, Gas Motorcars Inc. (no cents) miles and to the best of my/our knowledge that it reflects the actual mileage of the vehicle described below, unless one of the following statements is checked.

(1) I/We hereby certify that to the best of my/our knowledge the odometer reading reflects the AMOUNT OF MILEAGE IN EXCESS OF THE ODOMETER MECHANICAL LIMITS.

(2) I/We hereby certify that to the best of my/our knowledge, the odometer reading is NOT THE ACTUAL MILEAGE. WARNING - ODOMETER DISCREPANCY.

Stock Number: AC0681
 Model: DB8 Superleggera
 Year: 2019
 Make: Aston Martin

Transferor's Printed Name: Gas Motorcars Inc.
 Transferor's Street Address: 2012 Airport Industrial Park Drive
 City: Marietta
 State: GA
 Zip: 30060

Date: 08/07/2023

Signature of Person Signing: [REDACTED]

Printed Name of Person Signing: [REDACTED]

RECEIPT OF COPY ACKNOWLEDGED

Date: 08/07/2023

Signature of Transferee: [REDACTED]

Printed Name of Transferee: MICHAEL EUGENE DOWNING

Date: 08/07/2023

Signature of the Co-Transferee: [REDACTED]

Printed name of the Transferee: [REDACTED]

ORIGINAL MUST ACCOMPANY APPLICATION FOR CERTIFICATES OF TITLE

Page 1 of 1
 MichState: AL, AK, AR, CA, CO, CT, DE, DC, HI, GA, IL, IN, IA, KS, KY, LA, ME, MD, MA, MI, MN, MS, MO, MT, NV, NH, NJ, NY, ND, OH, OK, OR, PA, SC, SD, TN, TX, VT, WA, WI, WY

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP. THE DEALERSHIP EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHERS TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OF THE ORIGINAL PARTS OR ACCESSORIES. ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

Customer Signature: [REDACTED]
 Authorized Dealership Representative Signature: [REDACTED]

DATE: [REDACTED]

CUSTOMER COPY

ODOMETER DISCLOSURE STATEMENT

Federal law (and State law, if applicable) requires that you state the mileage upon transfer of ownership. Failure to complete or providing a false statement may result in fines and/or imprisonment.

I/We, Gas Motorcars Inc certify that the odometer of the (of the vehicle described below) now reads 18295 (no tenths) miles and to the best of my/our knowledge that it reflects the actual mileage of the vehicle described below, unless one of the following statements is checked.

- (1) I/We hereby certify that to the best of my/our knowledge the odometer reading reflects the AMOUNT OF MILEAGE IN EXCESS OF THE ODOMETER MECHANICAL LIMITS.
(2) I/We hereby certify that to the best of my/our knowledge, the odometer reading is NOT THE ACTUAL MILEAGE. WARNING - ODOMETER DISCREPANCY.

Stock Number AC0661 Year 2019 Make Aston-Martin Model DBS Superleggera Body Coupe COLOR Red Identification Number SCFRMIAV6KGR00661

Transferor's Printed Name Gas Motorcars Inc
Transferor's Street Address 2017 Airport Industrial Park Drive
City Marietta State GA Zip 30060
Date 08/07/2023
Signature of Person Signing
Printed Name of Person Signing Gas Motorcars Inc

Transferee's Printed Name

RECEIPT OF COPY ACKNOWLEDGED
Date 08/07/2023
Signature of Transferee
Printed Name of Transferee
Date 08/07/2023
Signature of the Co-Transferee
Printed name of the Transferee

ORIGINAL MUST ACCOMPANY APPLICATION FOR CERTIFICATES OF TITLE

**BENTLEY CHARLOTTE
MASERATI CHARLOTTE
ASTON MARTIN CHARLOTTE
ALFA ROMEO CHARLOTTE**

300 Foreign Cars Bldg of Charlotte
400 TYVOLA ROAD • CHARLOTTE, NC
704-535-7100



ASTON MARTIN



10011200701820

ALFA ROMEO	RYAN	8485	683	07/07/23	ASCS701820
CAR MAKE	TECH NO	PRICE	17,563	DATE	ASCS NO
YEAR MAKE MODEL	19/ASTON MARTIN/DBS/2DR SUPERLEG CPE			DEALER USE	CLIENT USE
FINANCE TO NO	S C F R M H A V 6 K G R 0 0 6 6 1			WARRANTY CENTER	PRODUCTION SITE
FINANCE	FINANCE	FINANCE	12/20/22		
FINANCE					

MO: 17563

JOB# 4 TOTALS	JOB# 4 JOURNAL PREFIX	ASCS	JOB# 4 TOTAL	0.00
JOB# 5 CHARGES				
LABOR				
J# 5 04AS22ZTIR11	WHEEL/TIRE CONCERN	HOURS:	TECH(S):07833	INTERNAL
CLIENT STATED CHIP ON DR W/OT R/TAN WHEEL SUBLET WHEEL REPAIR SUBLET REPAIR				
JOB# 5 TOTALS	JOB# 5 JOURNAL PREFIX	ASCS	JOB# 5 TOTAL	0.00
JOB# 6 CHARGES				
LABOR				
J# 6-09ASZ2	ELECTRICS	HOURS:	TECH(S):07833	0.00
Added Operation (075007M # 12/20/2022 14122) CLIENT STATED CARPLAY WILL CONNECT TO THE PHONE BUT NOT PLAY MUSIC AFTERMARKET INSTALLATION correct part is now on order				
JOB# 6 TOTALS	JOB# 6 JOURNAL PREFIX	ASCS	JOB# 6 TOTAL	0.00
MISC	CODE	DESCRIPTION	CONTROL NO	
JOB # A	SI	SHOP SUPPLIES	INTERNAL	INTERNAL
TOTAL - MISC				0.00
TOTALS				

DISCLAIMER OF WARRANTIES
The only warranties, if any, applying to this part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damage for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

WE WANT AND APPRECIATE YOUR BUSINESS!

We would like to thank you for your business! One of our many goals is your complete satisfaction. If you have any questions or concerns about your service visit, please contact our Service Director Carry Neil at 980-267-0774 or email at gnel@foreigncarscharlotte.com

TOTAL LABOR...	0.00
TOTAL PARTS...	0.00
TOTAL SUBLET...	0.00
TOTAL O.O.G...	0.00
TOTAL MISC CHG...	0.00
TOTAL MISC DISC...	0.00
TOTAL TAX...	0.00
TOTAL INVOICE \$	0.00

CASH CHECK CHECK NUMBER
 VISA/MC DISCOVER AMERICAN EXPRESS
 A/R

CUSTOMER SIGNATURE _____
DUPLICATE INVOICE



**MASERATI CHARLOTTE
ASTON MARTIN CHARLOTTE
ALFA ROMEO CHARLOTTE**

dba Foreign Cars Italia of Charlotte
400 TYVOLA ROAD • CHARLOTTE, NC
704-535-7100



ASTON MARTIN



0701ASC5701820

ALVINSON RYAN	INTL NO 8485	661	INVOICE DATE 02/07/23	VEHICLE NO ASC5701820
LABOR RATE	LICENSE NO	MILEAGE 17,563	COLOR /	STOCK NO
YEAR / MAKE / MODEL 19/ASTON MARTIN/DBS/2DR SUPERLEG CPE			DELIVERY DATE	DELIVERY MILES
VEHICLE ID NO S C F R M H A V 6 K G R 0 0 6 6 1			SELLING DEALER NO	PRODUCTION DATE
P.O. NO		R.O. DATE 12/28/22		
COMMENTS				

MO: 17563

JOB# 1 CHARGES-----		
LABOR-----		INTERNAL
J# 1 09ASZ9100 STEREO/TELE/COMPUTER HOURS: TECH(S):07833		
CLIENT STATED REAR SUB RATTLING 3RD REQUEST FOR REPAIR REMOVE INTERIOR TRIM TO INSTALL NEW BASE SPEAKER ONLY TO FIND THE INCORRECT PART WAS ORDERED . CORRECT PART IS NOW ON ORDER		
JOB# 1 TOTALS-----		
JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL		0.00
JOB# 2 CHARGES-----		
LABOR-----		INTERNAL
J# 2 90ASZZMPI MULTI-POINT INSPECT HOURS: TECH(S):07833		
MILEAGE IN: MILEAGE OUT: THE REPAIRS TO THIS VEHICLE HAVE BEEN PERFORMED USING A 3 STEP PROCESS AND I HAVE TEST DRIVEN "IF NECESSARY" TO CONFIRM THE REPAIR TO BE COMPLETE. PERFORMED MULTI-POINT INSPECTION CHECKLIST COMPLETED MULTI-POINT INSPECTION		
JOB# 2 TOTALS-----		
JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL		0.00
JOB# 3 CHARGES-----		
LABOR-----		INTERNAL
J# 3 50ASZ01 COURTESY CAR WASH HOURS: TECH(S):02758		
CLIENT REQUESTS COURTESY CAR WASH (\$ 29.99 VALUE) TECH # COMPLETED COURTESY CAR WASH		
MISC-----CODE-----DESCRIPTION-----CONTROL NO-----		INTERNAL
CLT1 MAS COURTESY WASH		INTERNAL
OF SHOP SUPP OFFSET		0.00
TOTAL - MISC		0.00
JOB# 3 TOTALS-----		
JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL		0.00
JOB# 4 CHARGES-----		
LABOR-----		WARRANTY
J# 4 09ASZZZTRIM3 INT TRIM DIAG HOURS: TECH(S):04470		
CLIENT STATED THE STEERING COLUMN WILL NOT ADJUST REMOVE STEERING WHEEL AND UNDERDASH PANEL FAULT TRACE AND FOUND STEERING COLUMN VERTICAL MOTOR IS DEFECTIVE. AWAIT AUTH TO REPLACE STEERING COLUMN		

DISCLAIMER OF WARRANTIES
The only warranties, if any, applying to this part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages damages to property, damages for loss of use, loss of time, loss of profits, or income or any other incidental damages.

WE WANT AND APPRECIATE YOUR BUSINESS!



The Reynolds and Reynolds Company EVANTHANE C0636416 Q (01/22)

**BENTLEY CHARLOTTE
MASERATI CHARLOTTE
ASTON MARTIN CHARLOTTE
ALFA ROMEO CHARLOTTE**

100 Foreign Cars Italia of Charlotte
4000 YOUNG BLVD • CHARLOTTE, NC
704-536-7100



ASTON MARTIN



0101 JAN 20 2025

REVENUE	SCOTT MACDONALD	03505	SALE NO	661	APPROVAL DATE	11/28/22	INVOICE NO.	ASCS700856
LABOR RATE	LICENSE NO.	MILEAGE	17,457	COLOR	STOCK NO.			
YEAR / MAKE / MODEL	19/ASTON MARTIN/DBS/2DR SUPERLEG CPE				DELIVERY DATE	DELIVERY MILES		
VEHICLE ID NO.	S C F R M H A V 6 K G R 0 0 6 6 1				SELLING DEALER NO.	PRODUCTION DATE		
F.T.E. NO.	P.O. NO.	R.O. DATE		10/06/22		REPRINT# 1		
COMMENTS								MO: 17461

ATTEND TO CUSTOMER'S CONCERN OF REAR BASE SPEAKER DISTORTING OR BLOWN
TEST AUDIO SYSTEM AND FOUND REAR DECK LID VIBRATING AT CERTAIN FREQUENCY TESTED WITH ASTON MARTIN SOUND BIT TESTER SECURE REAR DECK LID AND RETEST WITH SOUND BIT TESTER AND AGAIN WITH CONVENTIONAL RADIO AND MEDIA PLAYER AND NO NOISE NOTED.
REPORT:
PLEASE ADVISE CUSTOMER TO TEST AUDIO PRIOR TO LEAVING THE DEALERSHIP

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to this part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

WE WANT AND APPRECIATE YOUR BUSINESS!



JOB# 4 TOTALS

JOB# 4 JOURNAL PREFIX ASCS JOB# 4 TOTAL 0.00

MISC	CODE	DESCRIPTION	CONTROL NO	INTERNAL
JOB# A		SI SHIP SUPPLIES INTERNAL		0.00
TOTAL - MISC				0.00

TOTALS

We would like to thank you for your business!
One of our many goals is your complete satisfaction.
If you have any questions or concerns about your service visit, please contact our Service Director Garry Mel at 880-267-0774 or email at gmel@foreigncarscharlotte.com

TOTAL LABOR....	23100.50
TOTAL PARTS....	59265.85
TOTAL SUBLET....	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	0.00
TOTAL MISC DISC	-0.01
TOTAL TAX.....	5971.57

TOTAL INVOICE \$ 88337.91

- CASH CHECK CHECK NUMBER
 VISA/MC DISCOVER AMERICAN EXPRESS
 A/R

CUSTOMER SIGNATURE

DUPLICATE INVOICE

The Reynolds and Reynolds Company, LANSING, MI 48106-1500

**BENTLEY CHARLOTTE
 MASERATI CHARLOTTE
 ASTON MARTIN CHARLOTTE
 ALFA ROMEO CHARLOTTE**

dba Foreign Cars Italia of Charlotte
 100 TYVOLA ROAD • CHARLOTTE, NC
 704-535-7100



ASTON MARTIN



07011ASCS700856

ADVISOR SCOTT MACDONALD	03505	TAG NO 661	INVOICE DATE 11/28/22	INVOICE NO ASCS700856
LABOR RATE	LICENSE NO	MILEAGE 17,457	COLOR	STOCK NO
YEAR / MAKE / MODEL 19/ASTON MARTIN/DBS/2DR SUPERLEG CPE			DELIVERY DATE	DELIVERY MILES
VEHICLE I.D. NO. S C F R M H A V 6 K G R 0 0 6 6 1			SELLING DEALER NO	PRODUCTION DATE
F.T.E. NO	P.O. NO	R.O. DATE 10/06/22	REPRINT# 1	
COMMENTS				

MO: 17461

JOB# 1 TOTALS		TOTAL - MISC	-0.01
		LABOR	23100.50
		PARTS	59265.85
		MISC	-0.01
JOB# 2 CHARGES		JOB# 1 JOURNAL PREFIX ASCS	JOB# 1 TOTAL 82366.34
LABOR			
JOB# 2 90ASZMPI	MULTI-POINT INSPECT	HOURS: 0.00	TECH(S):05723
INTERNAL			
MILEAGE IN:			
MILEAGE OUT:			
THE REPAIRS TO THIS VEHICLE HAVE BEEN PERFORMED USING A			
3 STEP PROCESS AND I HAVE TEST DRIVEN "IF NECESSARY"			
TO CONFIRM THE REPAIR TO BE COMPLETE. PERFORMED MULTI-POINT			
INSPECTION CHECKLIST			
COMPLETED MULTI-POINT INSPECTION			
JOB# 2 TOTALS		JOB# 2 JOURNAL PREFIX ASCS	JOB# 2 TOTAL 0.00
LABOR			
JOB# 3 50ASZ01	COURTESY CAR WASH	HOURS:	TECH(S):05540,05723
INTERNAL			
CLIENT REQUESTS COURTESY CAR WASH			
(\$ 29.99 VALUE)			
TECH #			
COMPLETED COURTESY CAR WASH			
MISC		CODE	DESCRIPTION
		CLT2	ASTON COURTESY WASH
			OF SHOP SUPP OFFSET
			INTERNAL
		TOTAL - MISC	0.00
JOB# 3 TOTALS		JOB# 3 JOURNAL PREFIX ASCS	JOB# 3 TOTAL 0.00
LABOR			
JOB# 4 4+09ASZ	ELECTRICS	HOURS:	TECH(S):05723
WARRANTY			
Added Operation (07SCOTTM @ 11/09/2022 08:21)			
CLIENT STATED SUB WOOFER SOUNDS BLOWN RATTLING WHILE PLAYING			

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to this part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

**WE WANT
 AND APPRECIATE YOUR BUSINESS!**



The Reprocity and Remedy Company, Inc. (01/22)

**BENTLEY CHARLOTTE
MASERATI CHARLOTTE
ASTON MARTIN CHARLOTTE
ALFA ROMEO CHARLOTTE**

dba Foreign Cars Italia of Charlotte
400 TYVOLA ROAD - CHARLOTTE, NC
704-535-7100



ASTON MARTIN



0701IASC8700856

ADVISOR SCOTT MACDONALD	INV NO 03505	INV NO 661	INVOICE DATE 11/28/22	INVOICE NO ASCS700856
LABOR RATE	LICENSE NO	MILEAGE 17,457	COLOR	STOCK NO
YEAR / MAKE / MODEL 19/ASTON MARTIN/DBS/2DR SUPERLEG CPE			DELIVERY DATE	DELIVERY MILES
VEHICLE ID. NO. S C F R M H A V 6 K G R 0 0 6 6 1			SELLING DEALER NO	PRODUCTION DATE
F.T.E. NO.		P.O. NO	P.O. DATE 10/06/22	REPRINT# 1
COMMENTS				

MO: 17461

JOB# 1 CHARGES

LABOR
J# 1 06ASZ BODY/EQUIP/INT.&EXT. HOURS: 98.30 TECH(S):05723 23100.50
VEHICLE HIT A CURB AIRBAGS DEPLOYED
CARRY OUT FULL UNDER CARRIAGE AND BODY REPAIRS AS AUTHORIZED
AND QUOTED

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT	PRICE-	
1		HY53-10655-AA	BATTERY HB AGM		583.95	583.95
1		HY53-14300-AC	BATTERY PLUS TO PSS		1049.98	1049.98
1		HY53-5019-AC	FRONT LOWER FRAME		8695.67	8695.67
1		KY73-6A003-AA	ENGINE MOUNT LH		1255.00	1255.00
1		KY73-6A003-BA	ENGINE MOUNT RH		1255.00	1255.00
2		704441	BOLT-M10X40 HEX FLG		5.51	11.02
6		703194	BOLT M8X45 HEX FLNG		3.96	23.76
10		HY53-N103218-AB	BOLT-M12X45 W/PILOT		9.17	91.70
4		HY53-E802299-AA	M12 SHOULDER BOLT		24.38	97.52
1		KY73-5494-AA	FR ANTI ROLL BAR		881.65	881.65
2		HY53-5489-AB	FRT ANTI ROLL BAR L		96.94	193.88
2		KY73-5484-AA	FR ANTI ROLL BR BUS		127.68	255.36
2		HY53-5487-AA	ANTI ROLL BAR STRAP		113.05	226.10
1		KY73-1007-EA	WHEEL GL/SATIN FR L		4626.00	4626.00
1		HY53-18D603-AA	AUX HT EXC ASY LH		703.43	703.43
1		KY73-166563-AB	FRT W/ARC LINER LH		551.24	551.24
1		KY73-8C465-AB	AUX RAD DUCT LH		353.48	353.48
1		KY73-61J05-AB	LH RAD SEAL		161.07	161.07
1		KY73-8084-AB	MOUNTING BRACKET		118.81	118.81
1		KY73-8083-AB	MOUNTING BRACKET RH		118.81	118.81
1		KY73-11464-AE	FRT U/TRAY		1211.79	1211.79
1		HY53-110A66-AE	FRT MID U/TRAY		1658.00	1658.00
1		KY73-5E206-AA	FRT UTRAY AIRDAM		236.63	236.63
1		HY53-611B70-AEM	ASSY SEAT BELT DR L		1158.00	1158.00
1		HY53-610E54-AE	FRT ST BELT BUCKLE		159.28	159.28
1		HY53-5147-AI	INFL KNEE BOLSTR		675.17	675.17
1		HY53-042885-AB	DRIVERS AIRBAG		1867.37	1867.37
1		KY73-13W030-CB	H/LAMP LHS FED		5967.00	5967.00
1		KY73-8A100-BB	RAD GRILLE FED		1830.87	1830.87
1		HY53-14C246-AD	ORC ECU		1248.67	1248.67
4		701743	NUT-M12X1.5 FLG		9.78	39.12
4		707134	BOLT M8X25 HEX FLG		3.47	13.88
4		703566	WASHER M12-HARDENED		5.10	20.40
1		HY53-17C857-AD	SHLD REAR BHPR		695.38	695.38
1		KY53-SR003-AD	REAR SUBFRAME		10662.00	10662.00
1		KY73-17626-AB	FRONT SPLITTER		8144.90	8144.90
1		HY53-F01991-AC	PNL VEN AIR LH		652.63	652.63
1		HY53-13069-AE	PNL H/LAMP MNT LH		777.98	777.98
1		HY53-8052-AF	RAD SUPT LHR		660.77	660.77
1		KY73-8B413-AB	GOP SIDE LH		277.92	277.92
2		JY53-322666-AA	COOLANT G 40		27.33	54.66
					TOTAL - PARTS	59265.85

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to this part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

**WE WANT
AND APPRECIATE YOUR BUSINESS!**



MISC	CODE	DESCRIPTION	CONTROL NO
	01-01	SERVICE DISCOUNT	-0.01

The Reproducible and Removable Company, FRANKFORD, CO. 60416 Q (01/22)

TRUE360°



CERTIFICATE

OF INTEGRITY

ASSIGNED TODAY TO THIS:

2019 Aston Martin DBS Superleggera

SCFRMHAV6KGR00661

18,308 Miles

True360, acting upon the findings of the assigned inspector has awarded this vehicle a Certificate of Integrity. This certificate validates the report findings. Please review the Comprehensive Vehicle Condition Report to review the findings that designates:

Very Minor Cosmetic Repairs

CHIEF EXECUTIVE OFFICER

INSPECTED
ON
06/13/2023

COMPREHENSIVE VEHICLE CONDITION REPORT



Cosmetic Body Score	True360 Structural Standards
97	

Current Vehicle Condition

No Damage Found

Previous Vehicle History

Very Minor Cosmetic Repairs

Vehicle Details

VIN	SCFRMHAV6KGR00661
Year	2019
Make	Aston Martin
Model	DBS Superleggera
Mileage	18,308

Inspection Details


ID#	1686678045627
Date	6/13/2023
Technician	Amy W.

TRUE360° reports are engineered to identify prior repairs or existing cosmetic damage to exterior body parts and provide a topside structural inspection for vehicles that have, or have not reported accident history. In addition, when structural components have been identified as previously repaired, we will document these areas in an easy to read photo identified explanation of the findings. Any modifications or damage to this vehicle that occur after the inspection date will not be reflected in this report, as this is a snapshot of the vehicle's cosmetic and topside structural condition as of the inspection date listed on the report. This Report does not include an evaluation of the vehicle's underbody structural, mechanical or interior condition and in no way guarantees the safety of the vehicle, or that all prior repairs or existing damage will be identified.

Cosmetic Inspection

The highlighted points on this vehicle diagram indicate the general areas where our inspection found prior repairs. These issues are not structural in nature and are considered to be purely cosmetic.

Please be aware that this diagram may not be identical in appearance to the actual vehicle being inspected.




Exterior Body Inspection (Cosmetic)

Front Bumper Cover	Original
Hood	Original
Left Fender	Original
Left Front Door	Original
Left Rear Door	Not Applicable
Left Cosmetic Rocker	Original
Left Cab Corner	Not Applicable
Left Quarter Panel	Refinished
Left Bedside	Not Applicable
Roof	Original
Left Roof Rail	Original
Right Roof Rail	Original
Rear Bumper Cover	Refinished
Decklid/Liftgate/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Not Applicable
Right Cosmetic Rocker	Original
Right Cab Corner	Not Applicable
Right Quarter Panel	Original
Right Bedside	Not Applicable
Cladding/Mirror Housing	Original



Structural Inspection

True360 Structural inspection checks the following components for any evidence of structural damage. Structural damage is commonly found in welds that have been torn, separated, or re-welded, as well as body/fiberglass filler, physical damage, or areas of previous repair in relation to the inner/outer pillars. Please be aware, this report only determines if any damage has occurred and does not pass judgement on severity of damage or degree of repair.



Engine Bay Underhood (Structural)

	Meets True360 Structural Standards
Core Support	✓
Left Strut Tower/Apron	✓
Right Strut Tower/Apron	✓
Cowl Panel/Firewall	✓
Front Left Frame Rail	✓
Front Right Frame Rail	✓
Front Cross Member	✓



Inner Body Inspection (Structural)

	Meets True360 Structural Standards
A. Pillar Left	✓
B. Pillar Left	Not Applicable
C. Pillar Left	✓
D. Pillar Left	Not Applicable
A. Pillar Right	✓
B. Pillar Right	Not Applicable
C. Pillar Right	✓
D. Pillar Right	Not Applicable
Left Structural Rocker	✓
Right Structural Rocker	✓
Left Rear Strut Tower/Wheel Housing	✓
Right Rear Strut Tower/Wheel Housing	✓
Rear Body Panel	✓
Bracket/Bracing	✓
Left Quarter Panel	✓
Right Quarter Panel	✓
Roof	✓

General Report Notes