

[MENU](#)[\(888\) 231-7965](#)

REPORT #573397

2001 BMW M COUPE

[Click to View Large Gallery](#)[Download Full-size Pictures \(zip\)](#)

SUMMARY

There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos. There is one ding at passenger side lower ground effect. The exterior lights were working. The vehicle panel alignment looked good. The wheels looked good and the tires show to have good tread life.

There is light wear to the seats. The carpet shows normal wear consistent with age and mileage. The climate controls were working as designed. The heat was hot and the air was cold. The window and mirror switches were working as designed. The windows showed no issues when opening or closing during the inspection. The seats moved freely when adjusting. The radio was working and the sound was clear.

The engine area looked good. The accessible fluids were at the appropriate levels and the condition of the fluids looked good. The drive belt and hoses looked good. The front end and suspension are in good condition. The struts, springs, axle shafts, CV joints and suspension components look good.

The engine had plenty of power and there were no misfires or smoking. The transmission shifts smooth through all the gears and the clutch felt firm and no signs of slippage. The steering was responsive and the suspension was firm and the vehicle handled well. There were no abnormal vibrations or odd noises.

The brakes were firm with no pulsation felt. There were no visible leaks found to the underside of the vehicle. I hooked up my Scan Tool to the computer system and found no current or pending codes. All of the live data looked good with no issues reported.

See below and pictures for more info.

VEHICLE INFO	
YEAR	2001
MAKE	BMW
MODEL	M Coupe
MILEAGE	60872
TRANSMISSION	Manual
VIN NUMBER	WBSCN93441LK60184
INTERIOR	Leather
INTERIOR COLOR	Black
BODY COLOR	Blue
ENGINE	6 Cylinder
DRIVE TYPE	Rear Wheel Drive
FUEL TYPE	Gas

EXTERIOR	
WIPER BLADES	✔
WINDSHIELD WASHER	✔
BODY ALIGNMENT	✔
SCRATCHES	⚠
There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos.	
DINGS	⚠
There is one ding at passenger side lower ground effect.	
DENTS	✔
PAINT CONDITION	✔
RUST	✔
EXTERIOR LIGHTS	✔
SUNROOF	✔
DOOR MIRRORS	✔
BUMPERS	✔
SIDE MOLDINGS	✔
FRAME DAMAGE	✔
GLASS	✔
BODY SEALS	✔
HOOD	✔
DOORS	✔
FLOORS	✔
ROCKERS	✔
QUARTER PANELS	✔

INTERIOR	
STEERING WHEEL	
HORN	
CRUISE CONTROL	
SEAT CONDITION	
<i>There is light wear to the seats.</i>	
HEATED SEATS	
SEAT BELTS	
CLOCK	
RADIO/NAVIGATION	
INNER DOOR PANELS	
POWER LOCKS	
WINDOW SWITCHES	
WINDOW FUNCTION	
CENTER CONSOLE	
DASH	
SUN VISORS	
DASH LIGHTS	
DASH GAUGES	
AIR CONDITIONING	
HEATER	
REAR DEFROSTER	
CARPET	
<i>The carpet shows normal wear consistent with age and mileage.</i>	
FLOOR MATS	
CIGARETTE USE	
UNUSUAL ODORS	
CUP HOLDERS	
HEADLINER	
BLOWER MOTOR	
INTERIOR TRIM	
INNER TRUNK	

MECHANICAL	
BATTERY CONDITION	
CHARGING SYSTEM	
COOLING FAN CONDITION	
RADIATOR CAP SEALING PROPERLY	
HOSES	
RADIATOR	
ENGINE COOLANT	
COOLANT LEAKS	
BELTS	
POWER STEERING	
ENGINE OIL	
ENGINE FLUID LEAKS	
TRANSMISSION LEAKS	
BRAKE SYSTEM	
BRAKE FLUID LEAKS	
DIFFERENTIAL LEAKS	
MUFFLER SYSTEM	
CV JOINTS AND AXLES	
SHOCKS AND BUSHINGS	
BALL JOINTS AND TIE RODS	

ROAD TEST	
ROAD TEST	Yes
ENGINE PERFORMANCE	
TRANSMISSION PERFORMANCE	
CLUTCH PERFORMANCE	
DIFFERENTIAL PERFORMANCE	
WHEEL BEARING PERFORMANCE	
BRAKING PERFORMANCE	
SUSPENSION PERFORMANCE	
STEERING PERFORMANCE	
ENGINE STARTING	

MANUFACTURER

Driver Front	Goodyear	Goodyear	Passenger Front
Driver Rear	Goodyear	Goodyear	Passenger Rear

SIZE

Driver Front	235/35R17	235/35R17	Passenger Front
Driver Rear	275/30R19	275/30R19	Passenger Rear

AXLE COUNT

TIRE CONDITION

Driver Front	No Issues	No Issues	Passenger Front
Driver Rear	No Issues	No Issues	Passenger Rear

WHEEL CONDITION

Driver Front	No Issues	No Issues	Passenger Front
Driver Rear	No Issues	No Issues	Passenger Rear

TIRE TREAD

Driver Front	11/32	11/32	Passenger Front
Driver Rear	7/32	7/32	Passenger Rear

SPARE TIRE

SPARE TIRE	No
-------------------	----

TIRE TREAD EXPLANATION





10/32 OR MORE

Tires have plenty of tread!
(standard)

8/32 OR MORE

Tires have plenty of tread!
(low profile)

5/32 TO 7/32

Tires will need replacement soon!

4/32 OR LESS

Tires need replacement!



THE BEST WAY TO BUY TIRES

Say hello to discounts and enjoy the best rates on your new tires.

SHOP TIRES



DON'T SPEND YOUR HARD EARNED MONEY ON A LEMON. GET YOUR VEHICLE INSPECTED

ORDER NOW



Contact

Phone: (888) 231-7965

Orders may be placed online 24/7

SOCIAL FEEDS



BECOME AN INSPECTOR

2024 © ALL Rights Reserved. Privacy Policy | Terms of Service.