

# Sales Receipt

Deluxe Detail & Tint  
444 S. Gilbert Rd.  
Mesa, AZ 85204  
(480) 890-2566

| Date      | Sale No. |
|-----------|----------|
| 2/18/2015 | 19797    |

|  |
|--|
|  |
|  |

| Check No. | Payment Method | Project |
|-----------|----------------|---------|
|           |                |         |

| Description                                 | Qty | Rate             | Amount   |
|---|-----|------------------|----------|
| 1995 BLUE MERCEDES E320 COUPE VIN#208791    | 1   | 0.00             | 0.00     |
| TOP MOTOR CLEANING                          | 1   | 59.00            | 59.00    |
| INTERIOR DETAIL PACKAGE W/LEATHER TREATMENT | 1   | 219.00           | 219.00   |
| EXTERIOR DETAIL PACKAGE                     | 1   | 349.00           | 349.00   |
| HAND WASH & CLAY BAR TREATMENT              | 1   | 0.00             | 0.00     |
| 2 STEP BUFF, POLISH & WAXING                | 1   | 0.00             | 0.00     |
| Thank you for your business.                |     | Subtotal         | \$627.00 |
|   |     | Sales Tax (4.2%) | \$0.00   |
|   |     | Total            | \$627.00 |



Gilbert  
1618 N Higley Rd, Gilbert

## Here's your inspection

1995 Mercedes-Benz E320 - Mileage: 28,290

 Schedule Next Appointment

Guide

### ● Video Presentation



### ● Reasons for my visit

2 Reasons (Click to hide details) ^

1. Customer requests oil and filter change. Perform courtesy inspection. >
2. CBA Courtesy Inspection Accepted >


### ● Vehicle Health Report

34 Checked & OK (Click to hide details) ^



#### 1. Exterior Body Condition / Glass and Mirrors (VIDEO WALKAROUND)

Walk Up

 Notes: No Severe Body Damage - The vehicle body is free from severe scratches or dents. No action needed.



#### 2. Dash Warning Lights / Odometer

Walk Up

 Notes: No Warning Lights - No dashboard warning lights are currently displayed. No action needed.



#### 3. Diagnostic Codes Present or Recently Cleared with OBDII

Scan Tool Output / Test Drive

 Notes: No DTCs - No diagnostic trouble codes stored in the vehicle's onboard computer. No action needed.



#### 4. Vehicle Lighting

Safety / Lighting / Wipers



✓ **12. Cabin Air Filter**  
Fluids / Filters / Scheduled Maintenance

✍ Notes: Cabin Filter Not Accessible - Cabin Filter is not easily accessible for visual inspection. No action needed.

✓ **13. Tune Up Condition (Spark Plugs / Ignition Wire / Ignition Coil)**  
Fluids / Filters / Scheduled Maintenance

✍ Notes: Ignition System Good - No action needed.

✓ **14. Fuel Injection / Induction Service**  
Fluids / Filters / Scheduled Maintenance

✍ Notes: Fuel/Air Intake Good - No action needed.



✓ **15. Battery Test Results**  
Electrical & Ignition Systems

✍ Notes: Battery Good - No action needed.



✓ **16. Battery Terminals**  
Electrical & Ignition Systems

✍ Notes: Terminals Good - No action needed.



✓ **17. Radiator Hoses**  
Cooling System

✍ Notes: Hoses Good - No action needed.



✓ **18. Is the vehicle free from undercar modifications?**  
Undercar Inspection

✍ Notes: No Modifications - No action needed.

✓ 19. **Exhaust**  
Undercar Inspection

✍ Notes: Exhaust System OK - No action needed.

✓ 20. **Engine Mount(s)**  
Undercar Inspection


✍ Notes: Mounts Good - No action needed.

✓ 21. **Tire Pressure**  
Tires

✍ Notes: Pressure Good - No action needed.

✓ 22. **Tire Condition**  
Tires

✍ Notes: Tread Depth OK - No action needed.



✓ 23. **Front Brake Pads / Linings**  
Braking System

✍ Notes: 6mm - Front brake pads have 6mm of life left.



✓ 24. **Rear Brake Pads / Linings**  
Braking System

✍ Notes: 6mm - Rear brake pads have 6mm of life left.




✓ 25. **Wheel Bearings**  
Steering & Suspension

✍ Notes: Wheel Bearings Good - No action needed.

✓ 26. **Control Arm Bushings / Ball Joints**  
Steering & Suspension

✍ Notes: Control Arms Good - No action needed.



✓ 27. **Tie Rod Ends**  
Steering & Suspension

📝 Notes: Tie Rods Good - No action needed.


✓ 28. **Front Shocks / Struts**  
Steering & Suspension

📝 Notes: Front Shocks/Struts Good - No action needed.




✓ 29. **Rear Shocks / Struts**  
Steering & Suspension

📝 Notes: Rear Shocks/Struts Good - No action needed.



✓ 30. **CV Shafts / Axles Condition**  
Transmission & Drive Train

📝 Notes: CV Shafts Good - CV shafts and axles are in good condition.



✓ 31. **Transmission Mount(s)**  
Transmission & Drive Train

📝 Notes: Transmission Mounts Good - Transmission mounts are free from excess wear and in good working condition.

✓ 32. **Is the vehicle free from underhood modifications?**  
Underhood Inspection

📝 Notes: No Under Hood Modifications - No action needed.

✓ 33. **Windshield Washer Fluid**  
Underhood Inspection

📝 Notes: Reservoir Full - No action needed.

✓ 34. **Underhood Fluid Leaks**  
Underhood Inspection

📝 Notes: No Leaks - No action needed.

1 Recommend Attention (Click to hide details)

! 1. **Engine Air Filter**  
Fluids / Filters / Scheduled Maintenance

AIR FILTER REPLACED

📝 Notes: Filter Due - Due for replacement by time or mileage. Recommend replacing the air filter to ensure maximum engine performance.