

NCRS 1968-1972

Operations

Page 1 of 2

Revised 5/2013

Name

JC Morris #52293

VIN

1970 VIN# 194670S400939

Year

2013 Lone Star Regional, TX

FLIGHT, Thursday

Scoring: No repair or adjustment during judging. PRIOR to engine start; Check for cold engine, choke operation, fire extinguisher, decal & battery disconnect switch. Deduct 25 points per line item failure. Make partial deductions for faulty or incomplete function. If no deduction, mark with a slash. Mark factory delete with N/A.

A. Performed by Team Leader

VIN Plate authenticity & attachment

B. Performed by Operations Judging Team

Start judging with a cold engine for proper testing of choke operation. Start engine with hood open and with air cleaner in place. Ensure car is in neutral or park with parking brake set.

Score

Reason for deduction

Start engine

1. Neutral safety, ignition, gearshift & clutch interlock
2. Horn(s) & alarms: ignition key, anti-theft
3. Ease of start (*score choke and idle at item #18*)
4. Headlights hi & low beams
5. Headlamp door function
6. **12** Parking & side marker lights *FRONT SIDE MARKERS FLASHING*
7. License & tail lights
8. Brake & back up lights
9. Turn signal lights & hazard warning
10. Windshield & headlamp washers (where applicable)
11. Windshield wipers (2 speeds); door opening function
12. High beam, turn indicators & fiber optic monitors
13. Headlight, park brake, door ajar & seat belt warning
14. Gauges & tachometer function
15. Radio operation AM/FM/Stereo
16. Heater, defroster & air conditioning
17. Lower dash vent operation; rear defroster if applicable
18. Choke, fast & slow idle. TCS or CEC in 70-72
19. Engine fan, belts & noises
20. Exhaust leaks

For tabulation use only

Deduction subtotal, page 1 of 2

Tabulator initial

NCRS 1968-1972

Operations

Page 2 of 2

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

Stop engine

- 21. Leaks: water, fuel, oil, brake fluid _____
- 22. Clock & reset function _____
- 23. Cigarette lighter & well light _____
- 24. Interior lights: courtesy (2), rear compartment, glove box _____
- 25. Dash lights & brightness control: gauges, radio, console _____
- 26. Odometer reset; tilt-tele column if applicable _____
- 27. Seats: adjustment, back latching, seat & shoulder belts, retractors _____
- 28. Window operation _____
- 29. Lock & latching function: glove compartment, ignition, doors, spare tire _____
- 30. Driver and passenger door hold-open spring function _____

<i>For tabulation use only</i>	
<input type="checkbox"/> Deduction subtotal, page 2 of 2	Tabulator initial <input type="checkbox"/> <input type="checkbox"/>

Bonus Points		
Yes	No	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Fire Extinguisher
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Battery Disconnect
<input checked="" type="checkbox"/>	<input type="checkbox"/>	NCRS Decal

Review

Judge	<input type="text" value="FRED JENKINS"/>	Judge	<input type="text" value="Terry McManis"/>		
Owner review & initial	<input type="text" value="SM"/>	Team Leader	<input type="text" value="SF"/>	Judging Chairman initial	<input type="text" value="G"/>

For tabulation use only

Tabulator initial	<input type="checkbox"/> <input type="checkbox"/>
-------------------	---

Page 1 subtotal	=	<input type="text" value="12"/>	Total possible	750
Page 2 subtotal	=	<input type="text" value="0"/>	Less deductions	<input type="text" value="12"/>
Total deduction		<input type="text" value="12"/>	Total	<input type="text" value="738"/>
Bonus	Add 3 points for each "yes" (10 if all "yes")			<input type="text" value="10"/>
Transfer to Scoring Summary & Judging Summary			Total Operations	<input type="text" value="748"/>

NCRS 1968-1972

Chassis

Page 1 of 4

Revised 5/2013

JC Morris #52293
 Name: **1970 VIN# 194670S400939**
 VIN: 2013 Lone Star Regional, TX
 Year: FLIGHT, Ops.: Thursday

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a slash. If deduction is made, note reason for deduction to right of the judged item.

Score		Reason for deduction
Originality	Condition	
1. Cooling System		Originality: 40 Condition: 33 Total: 73

13	<input checked="" type="checkbox"/>	12	<input checked="" type="checkbox"/>	Radiator	CROSS BAR, SVC RING, TOP SEAL MISSING, H.D.W.R., BOLT MISSING
8	<input checked="" type="checkbox"/>	6	<input checked="" type="checkbox"/>	Fan shroud	N/T FASTENERS
8	<input checked="" type="checkbox"/>	6	<input checked="" type="checkbox"/>	Expansion tank	
3	<input checked="" type="checkbox"/>	3	<input checked="" type="checkbox"/>	Radiator cap	RC22 S/B RC15
8	<input checked="" type="checkbox"/>	6	<input checked="" type="checkbox"/>	AC Condenser & dryer	

2. Horns & Area Behind Grille		Originality: 16 Condition: 12 Total: 28
--	--	---

6	<input checked="" type="checkbox"/>	4	<input checked="" type="checkbox"/>	Horns, alarm horn (if applicable)	SVC RING
4	<input checked="" type="checkbox"/>	4	<input checked="" type="checkbox"/>	Headlamp actuators	NO DOT MISSING
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Radiator area finish & seals	MOUNT BOLT MISSING ON CORE SUPPORT, DAMAGE
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Striped vacuum hoses in this area	AGING

3. Front Bumper Brackets, Hardware, Valance & Extensions		Originality: 22 Condition: 18 Total: 40
---	--	---

16	<input checked="" type="checkbox"/>	14	<input checked="" type="checkbox"/>	Front bumper brackets & mounting hardware	PAINT, POR, POD
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Front valance	N/T FINISH
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Extension (spoiler)	DAMAGE, H.D.W.R. N/T FINISH

4. Starter & Heat Shield		Originality: 16 Condition: 14 Total: 30
-------------------------------------	--	---

12	<input checked="" type="checkbox"/>	10	<input checked="" type="checkbox"/>	Starter	1108338 9J11
2	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Solenoid	WIRE REPAIR?
3	<input checked="" type="checkbox"/>	2	<input checked="" type="checkbox"/>	Starter solenoid, heat shield & brace	

5. Oil Pan & Filter		Originality: 19 Condition: 16 Total: 35
--------------------------------	--	---

8	<input checked="" type="checkbox"/>	7	<input checked="" type="checkbox"/>	White AC oil filter	SVC RING
11	<input checked="" type="checkbox"/>	9	<input checked="" type="checkbox"/>	Oil pan, gasket & fasteners	OVER RESTORED

For tabulation use only

+ =

Deduction subtotal, page 1 of 3 Tabulator Initial

POR - PAINT OVER RUST
 POD - " " " DIRT

NCRS 1968-1972

Chassis

Page 2 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

6. Exhaust System, Heat Riser Valve & Tail Pipe Originality: 28 Condition: 22 Total: 50

8	<input type="checkbox"/>	5	7	<input type="checkbox"/>	1	Exhaust Pipes & heat riser	SS PIPES, CUT PIPE
6	<input type="checkbox"/>	3	4	<input checked="" type="checkbox"/>		Exhaust hangers & clamps	N/T, HDWR, HANGAR DAMAGE
8	<input type="checkbox"/>	5	7	<input checked="" type="checkbox"/>		Mufflers	NO BLACKOUT SUC PIPE
6	<input type="checkbox"/>	5	4	<input checked="" type="checkbox"/>		Exhaust tips	SS, CLAMP INSTALL +

7. Suspension Components Originality: 69 Condition: 65 Total: 134

10	<input type="checkbox"/>	2	8	<input checked="" type="checkbox"/>		Control arms upper & lower (exclude control arm shafts)	POP
4	<input type="checkbox"/>	1	4	<input checked="" type="checkbox"/>		Upper & lower ball joints	BOOTS U+L
2	<input checked="" type="checkbox"/>		2	<input checked="" type="checkbox"/>		Front springs	BLACK COATING
5	<input checked="" type="checkbox"/>	1	4	<input checked="" type="checkbox"/>		Front sway bar & linkage	POP, LINKAGE N/T.
5	<input type="checkbox"/>	2	4	<input checked="" type="checkbox"/>		Steering linkage	N/T TIE RODS + TUBES, PAINT, HD IDLER
5	<input type="checkbox"/>	1	5	<input checked="" type="checkbox"/>		Rear spring & linkage	PLATED CUPS/PAINT, COTTER KEYS
6	<input type="checkbox"/>	2	6	<input checked="" type="checkbox"/>		Rear strut rods & trailing arms	ZNO DESIGN/STAY RODS,
4	<input checked="" type="checkbox"/>		4	<input checked="" type="checkbox"/>		Rear sway bar & linkage	
4	<input type="checkbox"/>	1	4	<input checked="" type="checkbox"/>		Axle shafts & universal joints	DIRT, PAINT
8	<input type="checkbox"/>	3	8	<input checked="" type="checkbox"/>		Shock absorbers	N/T FINISH, WASHER BACKWARDS, WASHER INSTALL
8	<input checked="" type="checkbox"/>		8	<input checked="" type="checkbox"/>		Brake rotors & hoses	
4	<input type="checkbox"/>	1	4	<input checked="" type="checkbox"/>		Four calipers	FRONT BRACKET PLATE/BOOTS, CALIPER FINISH.
4	<input checked="" type="checkbox"/>		4	<input checked="" type="checkbox"/>		Brake backing plates	

8. Frame & Undercarriage Originality: 60 Condition: 50 Total: 110

10	<input type="checkbox"/>	1	8	<input checked="" type="checkbox"/>		Frame, cross members & stencil	NO STENCIL, SHIM MARKS
17	<input type="checkbox"/>	1	11	<input checked="" type="checkbox"/>		Transmission, shift linkage & bell housing	PAINT ON Bell HOUSING B. TRANS
3	<input checked="" type="checkbox"/>		3	<input checked="" type="checkbox"/>		Underbody heat shields & various mounting brackets	UNDERCOAT
4	<input checked="" type="checkbox"/>	1	4	<input checked="" type="checkbox"/>		A/T coolant hose lines & clamps or clutch linkage	ZIRIC, SPRING MISSING
4	<input checked="" type="checkbox"/>	1	4	<input checked="" type="checkbox"/>		Fuel & brake lines	UNDERCOATING
2	<input checked="" type="checkbox"/>		2	<input checked="" type="checkbox"/>		Fuel & brake line clamps	
5	<input checked="" type="checkbox"/>		4	<input checked="" type="checkbox"/>		Differential, differential mounting bracket & strut rod bracket	
2	<input checked="" type="checkbox"/>		2	<input checked="" type="checkbox"/>		Drive shaft & universal joints	COATING, STRAP CLAMPS, BLACK PAINT ON
3	<input checked="" type="checkbox"/>		2	<input checked="" type="checkbox"/>		Front & rear alignment shims & upper inner control arm shafts	PAINT, S/B VAL
2	<input checked="" type="checkbox"/>		2	<input checked="" type="checkbox"/>		Body to frame cushions & shims	AGING
8	<input checked="" type="checkbox"/>	2	8	<input checked="" type="checkbox"/>		Gas tank, sending unit & mounting straps	COATING OUTLINE

For tabulation use only

+ =

Deduction subtotal, page 2 of 3 Tabulator Initial

NCRS 1968-1972

Chassis

Page 3 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

9. Wheel Wells & Splash Pans	Originality: 16	Condition: 14	Total: 30
---	-----------------	---------------	-----------

16 4 14 Wheel wells & splash pans PAINT, OVER RESTORER

10. Spare Tire Carrier	Originality: 5	Condition: 4	Total: 9
-------------------------------	----------------	--------------	----------

5 4 Spare tire carrier, cover, strap & bolts PAINT ON RUSTS

11. Rear Bumper Brackets	Originality: 8	Condition: 7	Total: 15
---------------------------------	----------------	--------------	-----------

8 2 7 Rear Bumper Brackets & hardware PAINT ON LOWER PORT, PUP

12. Overall Cleanliness	Originality: None	Condition: 20	Total: 20
--------------------------------	-------------------	---------------	-----------

none 20 Cleanliness

<i>For tabulation use only</i>				
<input type="checkbox"/> 6	+	<input type="checkbox"/> 0	=	<input type="checkbox"/> 6
Deduction subtotal, page 3 of 4		Tabulator Initial	<input type="checkbox"/> RJC	<input type="checkbox"/> CMB

NCRS 1968-1972

Chassis

Page 4 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

Review

Judge PAUL OSLANSKY

Judge BILL KING

Owner review & initial [Signature]

Team Leader Initial [Signature]

Judging Chairman Initial [Signature]

For tabulation use only

Page 1 subtotal	=	<u>22</u>	Tabulator initial	<u>[Signature]</u>	<u>CMB</u>
Page 2 subtotal	=	<u>29</u>			
Page 3 subtotal	=	<u>6</u>			
				574	
			(Subtract from 574 possible) -	<u>67</u>	
Total Deduction		<u>67</u>	Total Chassis	<u>507</u>	

NCRS 1968-1972 SCORING SUMMARY

(Revised 5/2013)

Owner's Name: _____ #: _____ Date: _____
 Address: _____
 City: _____
 Area Code & Phone: _____
 Chapter Affiliation (if any): _____
 Location of Meet: _____
 Model Year: _____
 Exterior Color: _____

JC Morris #52293
 7613 Norwood Drive City: Amarillo St: TX C: USA
 2013 Lone Star Regional
1970 VIN#: 194670S400939 D: Driven
 350ci, 370hp Engine
 Ext: Monza Red, Int: Red (Vinyl), Body: Convertible
 Title: Accepted, Registration: Unknown, Insurance: Accepted
Flight #

_____ ntion
 _____ Horsepower: _____
 _____ Fabric: _____

Coupe Convertible
 Driven _____ Miles Trailered _____ Miles

SCORING SUMMARY SECTION

Team Leader Trim Tag Sub Section

Rejection Signature _____
 Printed name S. M. FALONSKI Authentication Signature * 

*** Without the appropriate Team Leader Signature in the Authentication area and on the Judging Summary Sheet (Green Sheet) the car will be "Branded Counterfeit" and judging will not be completed.**

Transfer to Judging Summary Sheet (Green Sheet).

Operations Section (760 possible w/bonus)	<u>748</u> ✓
Interior Section (750 possible)	<u>717</u> ✓
Exterior Section (1075 possible)	<u>978</u> ✓
Mechanical Section (1351 possible)	<u>1307</u> ✓
Chassis Section (574 possible)	<u>507</u> ✓
Total RAW Score (4510 possible)	<u>4257</u>
Net Score (Divide Raw score by 45 figure to 1/10 th do not round)	<u>94.6</u>
Driving Points (Refer to Reference Manual) 100% is the maximum score attainable	<u>112</u>
* Grand Total Score	<u>958</u>

Judging Chairman Signature  Tab Initial SK/paw

Flight Award Presented * Top 94 2nd 85 3rd 75 None

NCRS 1968-1972

Interior

Page 1 of 4

Revised 5/2013

Name	JC Morris #52293
VIN	1970 VIN# 194670S400939
Year	2013 Lone Star Regional, TX FLIGHT, Thursday

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a slash. If deduction is made, note reason for deduction to right of the judged item.

Score	Originality	Condition	Reason for deduction
	A15	407	974
	Jan	trim red vinyl	paint

1. Upholstery & Belts Originality: 37 Condition: 24 Total: 61

20	/	15	/	Seat upholstery & backs	D-small tear, touchup on backs D+P
5	/	3	/	Adjustment hardware, bolts & release	chrome missing - D
6	/	3	/	Seat belts	label coming off S2 B 69 buckles corrosion on
6	/	3	/	Shoulder belts	

2. Carpets Originality: 34 Condition: 28 Total: 62

5	/	5	/	Color	
12	/	12	/	Material, backing & jute padding	
11	2	5	/	Bindings & fit	passenger seat on top of flaps carpet plugs not thru
6	/	6	/	Heel & dimmer switch pads	No impco carpet on D

3. Door Panels, Kick Panels & Rear Quarter Trim Originality: 30 Condition: 21 Total: 51

12	4	9	/	Door panels, window felts, pulls	Red overspray top screws missing leaving large gap
6	/	4	/	Door Hardware	
6	/	4	/	Kick panels	wear on D kick panel
6	/	4	/	Rear quarter trim panels	2 small dings P

4. Dash Pads & Center Bezel Originality: 35 Condition: 29 Total: 64

21	/	19	/	Dash panels (3), defroster grille, map pocket & air outlet balls	P- corner cracked paint missing on screws - D screw loose
6	/	5	/	Center cluster	
6	/	4	/	Washer wiper control area	
2	/	1	/	Headlight knob & bezel	missing chrome center section

5. Steering Wheel & Column Originality: 23 Condition: 17 Total: 40

7	/	6	/	Steering wheel	
4	/	3	/	Horn button	
6	/	4	2	Steering column	chips by keyway + on top
6	/	4	/	Levers & flasher button	

For tabulation use only
 [6] + [3] = [9] Deduction subtotal, page 1 of 4 Tabulator Initial [CJC] [JW]

D - drivers S/B - should be
 P - passenger

NCRS 1968-1972

Interior

Page 2 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

6. Instruments & Radio Originality: 35 Condition: 31 Total: 66

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|--------------------------------|--------------------------------|
| 16 | <input checked="" type="checkbox"/> | 14 | <input checked="" type="checkbox"/> | Speedometer & tachometer | <u>lenses dirty</u> |
| 10 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Center console instruments (5) | |
| 9 | <input checked="" type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Radio or radio block off plate | <u>Corrosion on Radio knob</u> |

7. Console Originality: 29 Condition: 25 Total: 54

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|----------------------------------|------------------------------------|
| 10 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Console sides and top | |
| 7 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Emergency brake console & handle | <u>Cracks on top + side</u> |
| 6 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Shift boot or seal | <u>minor wear</u> |
| 6 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Ashtray, door & lighter | <u>white rim missing CASCO AAC</u> |

8. Transmission Shifter Originality: 8 Condition: 7 Total: 15

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|----------------|--|
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Shifter & knob | |
|---|-------------------------------------|---|-------------------------------------|----------------|--|

9. Door Jamb Area Originality: 30 Condition: 20 Total: 50

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|--|
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Door & Body Jambs, Power window wiring & striker bolt | <u>MISSING SX
rub wear on P side lower</u> |
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Door sills | <u>Some wear + paint chipping rear jam scratches</u> |
| 8 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | All weather stripping | <u>no split on either side</u> |
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Blue certification label and/or Canadian transport sticker | |
| 4 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Door hinges | |

10. Under Dash Area Originality: 20 Condition: 15 Total: 35

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|---------------------------------------|--|
| 7 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Under dash area & turn signal flasher | <u>S/B blue plastic turn signal
NO colored fuses red + white
10 Amp 25 Amp - wiring block hanging down</u> |
| 6 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hazard flasher, fuses & fuse block | |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hood release handle & cable | <u>chips along bottom</u> |
| 4 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Override knobs | |

11. Pedals Originality: 9 Condition: 7 Total: 16

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|---------------|--------------------------|
| 9 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Pedals & trim | <u>Scratches on trim</u> |
|---|-------------------------------------|---|-------------------------------------|---------------|--------------------------|

For tabulation use only

4	+	8	=	12	Deduction subtotal, page 2 of 4	Tabulator Initial	Aga	epk
---	---	---	---	----	---------------------------------	-------------------	-----	-----

NCRS 1968-1972

Interior

Page 3 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

12. Battery Cables, Bolts & Seal Originality: 10 Condition: 7 Total: 17

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|----------------------------|-------|
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Battery cables & terminals | _____ |
| 2 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Hold down clamp & bolt | _____ |
| 2 | <input checked="" type="checkbox"/> | 1 | <input checked="" type="checkbox"/> | Compartment seal | _____ |

13. Battery & Caps Originality: 25 Condition: 15 Total: 40

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|--------------|-------|
| 21 | <input checked="" type="checkbox"/> | 12 | <input checked="" type="checkbox"/> | Battery | _____ |
| 4 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Caps & hoses | _____ |

14. Rear Storage Area Originality: 46 Condition: 31 Total: 77

- | | | | | | |
|---|-------------------------------------|------|-------------------------------------|---|---|
| 9 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Storage compartment lids & frames | Screws S/B phosphate oxide not painted
Paint missing Battery hinge + P-hinge
corrosion |
| 4 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Seat shims & bag | wrench should be loose not in plastic bag |
| 4 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Fiberboard tray in passenger storage compartment | original |
| 2 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Center storage compartment & lamp | |
| 6 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Owner's packet & contents | Owners manual bag wheel card
Am/Fm radio (repa)
Warranty folder and P-O-P are not judged. missing consumer info |
| 4 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Keys | |
| 2 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Key knockouts | missing 2 |
| 2 | <input checked="" type="checkbox"/> | none | <input type="checkbox"/> | Storage compartment lock on proper compartment | |
| 5 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Top panel storage bags & hold down straps (coupe) | |
| 2 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Rear window storage tray (coupe) | |
| 4 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Jack | am Bumper not on right |
| 2 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Lamp on rear panel | |

15. Convertible Top or Hardtop or Coupe (Judge A, B or C only, Check Box) item C located on page 4
Originality: 24 Condition: 22 Total: 46

- A. Soft top**
- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|-------|
| 6 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Soft top interior & latches | _____ |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Convertible top bows | _____ |
| 8 | <input type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Underside of deck lid & release hardware | _____ |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Top side of deck lid | _____ |
- B. Hardtop**
- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|--|--|
| 11 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Hardtop interior & latches | Missing rubber plastic coating all 3
Missing one bumper |
| 8 | <input checked="" type="checkbox"/> | 8 | <input checked="" type="checkbox"/> | Underside of deck lid & release hardware | _____ |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Top side of deck lid | _____ |

For tabulation use only

<input type="text" value="6"/>	+	<input type="text" value="2"/>	=	<input type="text" value="8"/>	Deduction subtotal, page 3 of 4	Tabulator Initial	<input type="text" value="rjc"/>	<input type="text" value="ck"/>
--------------------------------	---	--------------------------------	---	--------------------------------	---------------------------------	-------------------	----------------------------------	---------------------------------

NCRS 1968-1972

Interior

Page 4 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

15. Convertible Top or Hardtop or Coupe (Continued) item A or B located on page 3
 Originality: 24 Condition: 22 Total: 46

- C. Coupe**
- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|-----------------------------------|-------|
| 15 | <input checked="" type="checkbox"/> | 14 | <input checked="" type="checkbox"/> | Removable top panels & latches | _____ |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Rear halo panel & release latches | _____ |
| 3 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Panel below the rear window | _____ |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Rear window aluminum surround | _____ |





16. Sun Visors, Windshield Garnish Molding & Rearview Mirror
 Originality: 20 Condition: 16 Total: 36

- | | | | | | | |
|----|-------------------------------------|---|---|-------------------------------------|---|---|
| 6 | <input checked="" type="checkbox"/> | 2 | 4 | <input checked="" type="checkbox"/> | Sun visors replacement too thin | _____ |
| 10 | <input checked="" type="checkbox"/> | 2 | 9 | <input checked="" type="checkbox"/> | Windshield garnish molding, L & R pillar post molding | screw should be chrome wrong configuration PS |
| 4 | <input checked="" type="checkbox"/> | 3 | 3 | <input checked="" type="checkbox"/> | Mirror (include all trim & mounting bracket) | _____ |

17. Overall Cleanliness Originality: None Condition: 20 Total: 20

none 20 Cleanliness _____

Review

Judge  Judge 
 Bob Demme James White
 Owner review & initial  Team Leader Initial SF Judging Chairman Initial 

For tabulation use only

4 + 0 = 4 Deduction subtotal, page 4 of 4 Tabulator Initial njc cjk

Page 1 subtotal	=	<input type="checkbox"/> 9	Tabulator initial	<input type="checkbox"/> njc	<input type="checkbox"/> cjk
Page 2 subtotal	=	<input type="checkbox"/> 7			
Page 3 subtotal	=	<input type="checkbox"/> 8			
Page 4 subtotal	=	<input type="checkbox"/> 4			
Total Deduction		<input type="checkbox"/> 33	(Subtract from 750 possible) -	<input type="checkbox"/> 33	
			Total Interior	<input type="checkbox"/> 717	

NCRS 1968-1972

Exterior

Page 1 of 4

Revised 5/2013

Name
VIN
Year

JC Morris #52293
1970 VIN# 194670S400939
2013 Lone Star Regional, TX
FLIGHT, Thursday

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a slash. If deduction is made, note reason for deduction to right of the judged item.

A-15
T-407 P-974
Score
Originality Condition Reason for deduction

1. Body Color Originality: 85 Condition: None Total: 85

85 none Body color shade slightly off (Dark) OK JB

2. Body Paint Originality: 45 Condition: 40 Total: 85

45 40 Body paint (hood panel not STD) chips / cracking / finish up / 50%
"Gloss clear on surface" (STD defect)
Right fender front - spots

3. Body Fit Originality: 65 Condition: 55 Total: 120

65 55 Body, fiberglass & component fit left side fender well fiberglass repair
Hood fit not STD
left side crease front area

4. Bumpers Originality: 40 Condition: 32 Total: 72

20 16 Front bumper extra chalking / chips scratches
20 16 Rear bumpers p-fochrome

5. Parking & Side Marker Lamps & lenses Originality: 10 Condition: 10 Total: 20

6 6 Parking lamps & lenses ASE
4 4 Side marker lamps 10x

6. Grilles, License Mount & Headlamp Shields Originality: 22 Condition: 18 Total: 40

11 10 Front grilles & hardware screws not black
3 2 Headlamp shields fit not STD
5 4 Front license recess ASE / chrome missing
3 2 License plate frame & 2 screws frame has rivet

7. Headlamps & Bezels Originality: 18 Condition: 9 Total: 27

6 5 Headlamp doors, bezels & nozzles R Rnt Door - Rear screen
12 4 Headlamps left low beam "cross hair"

For tabulation use only
 42 + 21 = 63 Deduction subtotal, page 1 of 4 Tabulator Initial SK

NCRS 1968-1972

Exterior

Page 2 of 4

Revised 5/2013

Name _____

VIN _____

Year _____ Date _____

8. Hood, Windshield Vent Grille & windshield Wiper Door

Originality: 17 Condition: 13 Total: 30

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|---|---------------|
| 7 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Hood (exterior only) | _____ |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Chrome trim moldings (LT1, 427, 454 only) | _____ |
| 7 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Windshield vent grille & wiper door | Rivet Painted |

9. Wipers & Windshield Trim

Originality: 16 Condition: 12 Total: 28

- | | | | | | |
|------|-------------------------------------|---|-------------------------------------|---|------------------------------------|
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Wiper arms, transmission & actuating arms | _____ |
| 3 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Wiper blade & holder | holder not STD / Blades no "lines" |
| SF 3 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Washer tubing & retainers | not metal |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Windshield stainless trim | Use - real sealant |

10. Windshield

Originality: 20 Condition: 10 Total: 30

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|------------|-----------------------------|
| 20 | <input checked="" type="checkbox"/> | 10 | <input checked="" type="checkbox"/> | Windshield | Real Deal (smiley face) Use |
|----|-------------------------------------|----|-------------------------------------|------------|-----------------------------|

11. Windows

Originality: 29 Condition: 26 Total: 55

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|------------------------------------|--------------------------------|
| 21 | <input checked="" type="checkbox"/> | 19 | <input checked="" type="checkbox"/> | Side windows | left chip RT VX lef CV Back AV |
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Back window (coupe or convertible) | _____ |

12. Fender Grilles or Louvers

Originality: 11 Condition: 9 Total: 20

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|------------------------------------|-------------------|
| 11 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Side grilles or louvers & hardware | chips/heavy paint |
|----|-------------------------------------|---|-------------------------------------|------------------------------------|-------------------|

13. Rocker Moldings or side Pipe Covers

Originality: 21 Condition: 19 Total: 40

- | | | | | | |
|----|-------------------------------------|----|-------------------------------------|-------------------------------------|---------------------------------|
| 21 | <input checked="" type="checkbox"/> | 19 | <input checked="" type="checkbox"/> | Rocker moldings or side pipe covers | scratches tab and bolts missing |
|----|-------------------------------------|----|-------------------------------------|-------------------------------------|---------------------------------|

14. Outside Mirror, Door Handles & Locks

Originality: 18 Condition: 14 Total: 32

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|------------------------|------------------------------|
| 9 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Outside mirror | 11 DM19 Use large Gasket |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Door handles & gaskets | left Paint left insula RT dx |
| 4 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Door lock bezels | _____ |

For tabulation use only

+ =

Deduction subtotal, page 2 of 4

Tabulator Initial

NCRS 1968-1972

Exterior

Page 3 of 4

Revised 5/2013

Name _____

VIN _____

Year _____ Date _____

15. Antenna

Originality: 6

Condition: 4

Total: 10

- 3 2 Mast & ball 20
- 3 2 Base, nut & gasket

16. Gas Door Area & Rear Deck Vent Grilles

Originality: 26

Condition: 21

Total: 47

- 8 7 Gas lid door, bezel & hardware Base Rust
- 10 8 Gas cap
- 2 2 Rubber boot & drain drain tube tie w/ white
- 6 4 Rear grilles & hardware

17. Rear License Recess, Tail Lamps & Alarm

Originality: 24

Condition: 18

Total: 42

- 7 5 License recess
- 3 2 License plate frame & 2 screws
- 8 7 Tail lamp & back-up lenses
- 3 2 Lens mounting screws (12)
- 3 2 Alarm switch

18. Exhaust Bezels & Rear Valance

Originality: 16

Condition: 14

Total: 30

- 8 7 Exhaust bezels
- 8 7 Rear valance & bolts color

19. Emblems

Originality: 22

Condition: 16

Total: 38

- 7 5 Crossed flags
- 7 5 Corvette letters
- 4 3 Stingray emblems Black to outer edge
- 4 3 LT1 decals, 427 or 454 emblems size large

For tabulation use only

H + 1 = 5

Deduction subtotal, page 3 of 4

Tabulator Initial

SK

SK

NCRS 1968-1972

Exterior

Page 4 of 4

Revised 5/2013

Name _____

VIN _____

Year _____ Date _____

20. Hardtop or Convertible Top or Coupe (Judge A, B or C only, Check Box)

Originality: 38 Condition: 32 Total: 70

A. Hardtop

23 19 Hardtop _____

4 3 Exterior metal moldings As e

11 10 All weatherstrip _____

B. Soft top

4 3 Fit of top _____

15 13 Material _____

4 3 Heat seal of rear window _____

11 10 All weatherstrip _____

4 3 Caution label _____

C. Coupe

19 16 Removable top panels _____

15 13 All weatherstrip _____

4 3 Exterior metal moldings _____

21. Wheels & Wheel Covers

Originality: 32 Condition: 24 Total: 56

16 12 Four wheels _____

16 12 Four wheel covers or hub caps & trim rings — use dents / scratches

22. Tires

Originality: 30 Condition: 30 Total: 60

30 30 Tires (5) as described _____

23. Spare Wheel, Tire Lock & Boot

Originality: 10 Condition: 8 Total: 18

5 4 Spare wheel & date spare weight NOT STD

5 4 Lock & boot (no operation) _____

24. Overall cleanliness

Originality: none Condition: 20 Total: 20

none 20 Overall cleanliness _____

Review

Judge [Signature] Judge [Signature]

Owner review & initial [Signature] Team Leader Initial [Signature] Judging Chairman Initial [Signature]

For tabulation use only

1 + 3 - 4

Deduction subtotal, page 4 of 4

Tabulator Initial

[Signature]

SK

Page 1 subtotal	=	63
Page 2 subtotal	=	25
Page 3 subtotal	=	5
Page 4 subtotal	=	4
Total Deduction	=	97

Tabulator initial

[Signature]

SK

1075

(Subtract from 1075 possible) -

97

Total Exterior

978

NCRS 1968-1972

Mechanical

Page 1 of 4

Revised 5/2013

Name	JC Morris #52293
VIN	1970 VIN# 194670S400939
Year	2013 Lone Star Regional, TX FLIGHT, Thursday

Scoring: Point assignments at left of score boxes. Mark originality deductions in first column and condition deductions in second column. If no deduction, mark score box with a slash. If deduction is made, note reason for deduction to right of the judged item.

Score	Originality	Condition	Reason for deduction
1. Cylinder Case Originality: 350 Condition: none Total: 350			
350	<input checked="" type="checkbox"/>	<input type="checkbox"/> none	A. Casting number & case configuration _____ <i>(If incorrect, deduct 350 & do not judge or score B, C, or D below)</i>
175	<input checked="" type="checkbox"/>	<input type="checkbox"/> none	B. Casting date <u>L 19 9</u> <i>(If incorrect, deduct 175 & do not judge or score C or D below)</i>
25	<input checked="" type="checkbox"/>	<input type="checkbox"/> none	C. Assembly stamping <u>VIZIACU</u>
25	<input checked="" type="checkbox"/>	<input type="checkbox"/> none	D. VIN derivative <u>70S400939</u>
38	<input checked="" type="checkbox"/>	<input type="checkbox"/> none	E. Stamp pad surface finish _____
2. Cylinder Heads Originality: 50 Condition: none Total: 50			
50	<input checked="" type="checkbox"/>	<input type="checkbox"/> none	Cylinder heads _____
3. Valve Covers Originality: 26 Condition: 23 Total: 49			
16	<input checked="" type="checkbox"/>	14 <input checked="" type="checkbox"/>	Valve covers _____
4	<input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Attachments, clips _____
4	<input checked="" type="checkbox"/>	4 <input checked="" type="checkbox"/>	Oil cap _____
2	<input checked="" type="checkbox"/>	1 <input checked="" type="checkbox"/>	Engine suffix code label _____
4. Air Cleaner Originality: 19 Condition: 16 Total: 35			
11	<input checked="" type="checkbox"/>	9 <input checked="" type="checkbox"/>	Air cleaner base & lid _____
3	<input checked="" type="checkbox"/>	2 <input checked="" type="checkbox"/>	Silk screen instructions and/or label _____
5	<input checked="" type="checkbox"/>	5 <input checked="" type="checkbox"/>	Air filter element _____
5. Carburetor(s) Originality: 38 Condition: 22 Total: 60			
38	<input checked="" type="checkbox"/>	22 <input checked="" type="checkbox"/>	Carburetor, heat insulator & fasteners <u>SEVERAL DATE / NO INK / GASK</u>
6. Thermostatic Choke Stove Originality: 4 Condition: 3 Total: 7			
4	<input checked="" type="checkbox"/>	3 <input checked="" type="checkbox"/>	Choke stove, cover, rod & clip _____
7. Intake Manifold Originality: 33 Condition: 24 Total: 57			
30	<input checked="" type="checkbox"/>	22 <input checked="" type="checkbox"/>	Intake manifold, gaskets & fasteners _____
3	<input checked="" type="checkbox"/>	2 <input checked="" type="checkbox"/>	Lifting eyes _____

For tabulation use only

18	+	<input checked="" type="checkbox"/>	=	12	Deduction subtotal, page 1 of 4	Tabulator Initial	<input type="checkbox"/>	<input type="checkbox"/> SK
----	---	-------------------------------------	---	----	---------------------------------	-------------------	--------------------------	-----------------------------

NCRS 1968-1972

Mechanical

Page 2 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

8. Distributor & Coil Originality: 30 Condition: 20 Total: 50

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|--|--------------------|
| 13 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Distributor | 9 18 29 |
| 6 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Distributor cap | |
| 4 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | RFI Shield (70-1/2 and newer) & timing tab | |
| 7 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Ignition coil & pulse amplifier | |

9. Exhaust Manifolds Originality: 22 Condition: 18 Total: 40

- | | | | | | |
|----|--------------------------|----|-------------------------------------|--------------------------------------|--------|
| 22 | <input type="checkbox"/> | 18 | <input checked="" type="checkbox"/> | Exhaust manifolds, fasteners & locks | FINISH |
|----|--------------------------|----|-------------------------------------|--------------------------------------|--------|

10. Ignition Shielding & Wires Originality: 21 Condition: 19 Total: 40

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|--------------------|-------------|
| 10 | <input type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Ignition shielding | REPLACEMENT |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Heat shields | |
| 8 | <input type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Ignition wires | REPLACEMENT |

11. Oil Dipstick Originality: 11 Condition: 9 Total: 20

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|--------------------------|--|
| 11 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Dipstick tube & dipstick | |
|----|-------------------------------------|---|-------------------------------------|--------------------------|--|

12. Alternator, Power Steering, Brackets & Pulleys Originality: 38 Condition: 24 Total: 62

- | | | | | | |
|-----------|-------------------------------------|----|-------------------------------------|---|------------------------------|
| 5 | <input checked="" type="checkbox"/> | 2 | <input checked="" type="checkbox"/> | Voltage Regulator (68 Only) | |
| FINISH 19 | <input type="checkbox"/> | 11 | <input checked="" type="checkbox"/> | Alternator | 884 GL4 STATOR FINISH 2/MTG? |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Power steering pump & belt guard on SB | |
| 4 | <input type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Alternator & power steering mounting hardware | HARDWARE |
| 5 | <input checked="" type="checkbox"/> | 4 | <input checked="" type="checkbox"/> | Alternator & power steering pulleys | |

13. Fuel pump Originality: 11 Condition: 9 Total: 20

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|-----------|----------------|
| 11 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Fuel pump | SAFETY CLAMPS? |
|----|-------------------------------------|---|-------------------------------------|-----------|----------------|

14. External Fuel Filter Originality: 8 Condition: 7 Total: 15

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|-------------|--|
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Fuel filter | |
|---|-------------------------------------|---|-------------------------------------|-------------|--|

15. Fuel & Vacuum Advance Lines Originality: 17 Condition: 13 Total: 30

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|----------------------------------|----|
| 7 | <input type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Engine fuel lines | SS |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Fuel line & vacuum line supports | |
| 7 | <input checked="" type="checkbox"/> | 5 | <input checked="" type="checkbox"/> | Vacuum advance lines | |

For tabulation use only

<input type="checkbox"/>	14	+	<input type="checkbox"/>	0	=	<input type="checkbox"/>	14	Deduction subtotal, page 2 of 4	Tabulator Initial	<input type="checkbox"/>	SK
--------------------------	----	---	--------------------------	---	---	--------------------------	----	---------------------------------	-------------------	--------------------------	----

NCRS 1968-1972

Mechanical

Page 3 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

16. Emissions Label Originality: 6 Condition: 4 Total: 10

6 4 Emissions label

17. Brake Master Cylinder & Power Booster Originality: 24 Condition: 20 Total: 44

12 10 Master cylinder MACHINED AREAS PAINTED
6 5 Master cylinder cover AGE
6 5 Power brake booster

18. Emission Controls Originality: 40 Condition: 34 Total: 74

9 8 AIR pump & diverter valve 340915 FIX IS IT NO SUFFIX CODE
6 5 AIR hoses & clamps REPLACEMENT
7 6 Check valves & manifold trees
7 6 ECS carbon canister, hoses & clamps
7 6 PCV valve & clamps
4 3 TCS solenoid and/or anti-diesel solenoid

19. Engine Color & Mounts Originality: 25 Condition: 25 Total: 50

20 20 Engine orange & aluminum paint TOO MUCH PAINT
5 5 Engine mounts & ground strap

20. Air Conditioning System & Blower motor Originality: 18 Condition: 15 Total: 33

7 6 Air conditioning compressor
5 4 A/C hoses, pipes & clamps
3 2 Expansion, POA & water shut-off valves
3 3 Blower motor

21. Water Pump, Fan Clutch, Radiator Hoses & Thermostat Housing Originality: 41 Condition: 37 Total: 78

9 8 Water pump
8 7 Pulleys
3 3 Harmonic damper
6 5 Belts
6 5 Fan & fan clutch
3 3 Thermostat housing & fasteners
3 3 Radiator hoses & clamps REPLACEMENT 15/16 TOWERS
3 3 Heater hoses & clamps

For tabulation use only

<input type="checkbox"/> 6	+	<input type="checkbox"/> 1	=	<input type="checkbox"/> 7	Deduction subtotal, page 3 of 4	Tabulator Initial	<input type="checkbox"/> <u>AGC</u>	<input type="checkbox"/> <u>SK</u>
----------------------------	---	----------------------------	---	----------------------------	---------------------------------	-------------------	-------------------------------------	------------------------------------

NCRS 1968-1972

Mechanical

Page 4 of 4

Revised 5/2013

Name	_____
VIN	_____
Year	_____ Date _____

22. Windshield Washer Components, Wiper Motor, Wiper Door Actuator & Vacuum Valve

Originality: 23 Condition: 21 Total: 44

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|---|-------|
| 7 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Windshield washer fluid reservoir & hoses | _____ |
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Wiper motor | _____ |
| 8 | <input checked="" type="checkbox"/> | 7 | <input type="checkbox"/> | Vacuum actuator & valve | AGT |

23. Engine Compartment Color, Firewall, Hood Fasteners & Inner Skirts

Originality: 35 Condition: 33 Total: 68

- | | | | | | |
|----|-------------------------------------|---|-------------------------------------|---|--------------------------------|
| 11 | <input checked="" type="checkbox"/> | 9 | <input checked="" type="checkbox"/> | Engine compartment blackout-hood, inner skirts & firewall | TOO CRISPY
MISSING SEATBELT |
| 6 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Firewall, sealant & grommets | ← |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Emblem studs & nuts (on underside of hood) & weatherstrip | _____ |
| 3 | <input checked="" type="checkbox"/> | 3 | <input checked="" type="checkbox"/> | Hood hinges & support | MISSING SCREW OUT |
| 6 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Hood latches & hardware | FIXES IT |
| 6 | <input checked="" type="checkbox"/> | 6 | <input checked="" type="checkbox"/> | Inner skirts, seals & dust shields | _____ |

24. Horn Relay & wiring

Originality: 16 Condition: 14 Total: 30

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|---------------------------|-------|
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Horn relay | _____ |
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Engine compartment wiring | _____ |

25. Color-coded Vacuum Hoses

Originality: 8 Condition: 7 Total: 15

- | | | | | | |
|---|-------------------------------------|---|-------------------------------------|--|-------|
| 8 | <input checked="" type="checkbox"/> | 7 | <input checked="" type="checkbox"/> | Vacuum color-coded hoses in engine compartment | _____ |
|---|-------------------------------------|---|-------------------------------------|--|-------|

26. Overall Cleanliness

Originality: none Condition: 20 Total: 20

none 20 Overall cleanliness _____

Review

Judge Judge

Owner review & initial Team Leader Initial Judging Chairman Initial

For tabulation use only

+ = Deduction subtotal, page 4 of 4 Tabulator Initial

Page 1 subtotal	=	<input type="text" value="18"/>	Tabulator initial	<input type="text" value="agc"/>	<input type="text"/>
Page 2 subtotal	=	<input type="text" value="14"/>			
Page 3 subtotal	=	<input type="text" value="7"/>			
Page 4 subtotal	=	<input type="text" value="5"/>			
Total Deduction		<input type="text" value="44"/>	(Subtract from 1351 possible) -	<input type="text" value="44"/>	
		<input type="text" value="1307"/>	Total Mechanical	<input type="text" value="1307"/>	