



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

District Director of Customs

Re: Phillip Birch, Jr.

OFFICE OF
AIR AND RADIATION

JUL 5 1985

Dear District Director:

Approval is hereby given for the release of the EPA obligation on the bond for the vehicle described below:

Make: *Porsche*
Model Year: *1979* Model: *911*
VIN: *4309700358*

Importer: *Phillip Birch*
Port: *Baltimore*
Entry Number: *85101233-1*
Date of Entry: *7-13-85*

The importer has been conditionally excepted from demonstrating that the vehicle has been brought into conformity with Federal emission requirements based on EPA's understanding that, (1) the vehicle was five or more model years old on the date of entry, (2) it was imported by this individual, (3) it is the first nonconforming vehicle imported by the individual, (4) it was imported for personal use and not for resale and (5) it was not purchased through or with the assistance of a business or agent. This release applies only to an importation by an individual in accordance with the above requirements. This release is void if the requirements are not met.

This nonconforming vehicle may not be resold in the U.S. for at least two years from the date of entry.

This letter does not release the importer from the obligation to comply with Federal safety requirements administered by the U.S. Department of Transportation or with any applicable state or local emission related requirements.

We have been informed by the California Air Resources Board that a used vehicle, as defined in Section 43156 of the California Health and Safety Code, may not be registered in California unless it is first brought into conformity with California or Federal emission requirements.

Very truly yours,

Charles R. Case, Acting Chief
Investigation/Imports Section
Manufacturers Operations Division
EN-340F

4G

Prepared by

T. M. Lami

Rev. 4/85

011
41
5666
80583

(610) 832-3004 FAX

* turbo brakes + : \$2,500.-
* turbo rear body arms + : \$1,800.-
* turbo torsion bars + : \$100.-
* turbo pendulums/flares + : \$2,500.-
* turbo wheels + \$1,200
sport seats + \$1,200
who tie rods + \$100
crank + \$500
trans + \$750

12,900

routing #
051404260
account #
5134312655
bb & T
Wayne Rodgers
\$8,100. ^{\$16,000}

cah3@shentel.net
wrodgers@shentel.net
\$2,550.-

ebay 290000796478

Coalition against Hunger
fed the people.org

Haymarket VA 20168-0455

703
615 6630

703 754 1355

Wayne Rodgers (703) 615-6630

mor
wile
Thursday
week

Tuesday

Woodstock VA off \$1
100m West of Waynes
Richard
Wayne
Wideth
20 - 50 - 1/4
66 - 81
16k
3 yrs
clonated
1992
lookin 84

wire 16k

TISCHER AUTOPARK INC.

3211 Automobile Blvd.
Silver Spring, MD 20904
(301) 890-3000

INVOICE NO. 88922
SOURCE 61

DATE 04/20/90
PAGE 1 OF 1




SOLD TO:

KEITZ

CUST. NO.

SOLD BY	SHIP VIA	CUST. ORDER NO.	TERMS
			CA
VIN / TAX EXEMPT NO.			MILEAGE

MAKE SEQ.	SOURCE	W/F	QTY/TIME	PART / LABOR DESCRIPTION	UNIT PRICE	TOTAL
X			1	911 531 957 00 DOOR CHECK	32.40	32.40



NOTE:

PARTS WITH NUMBER BEGINNING WITH "0" ARE NOT COVERED BY THE WARRANTIES OF PORSCHE AUDI, OR BMW!! SEE PARTS DEPT. FOR DETAILS.
NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED PARTS.
ALL RETURNS SUBJECT TO A 15% RESTOCKING FEE.
NO RETURNS AFTER 30 DAYS.
ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE.

PORSCHE PTS 0/C RETA 32.40
SUBTOTAL 32.40
TAX 1.62
CASH TOTAL 34.02

04/20/90
11:56 AM

PAID
APR 20 1990

[Signature]

X _____
CUSTOMER ACKNOWLEDGEMENT

US Department
of Transportation

400 Seventh St. S.W.
Washington, DC 20590

National Highway
Traffic Safety
Administration

01 July 1985
In Reply Refer To:
NEF-32-CUS
PCI NO. 8502-410-0

District Director of Customs
Attn: Motor Vehicle Imp Spec
103 S. Gay Street
Baltimore, MD 21202

Dear Sir:

The National Highway Traffic Safety Administration acknowledges receipt of a statement of compliance submitted by the importer for the below identified vehicle. Customs entry shown:


Importer's Name: PHILLIP W. BIRCH
Customs Entry No. & Date: 101233, 2/13/1985
Port Code: BAL-1303
Vehicle Make & Model: PORSCHE 911
Vehicle Identification No. (VIN): 930970 0358

The statement meets the requirements of 19 CFR 12.80(e). Release from all liability under the bond posted with respect to compliance with the requirements of NHTSA is, therefore, satisfactory. Release must be obtained from the Environmental Protection Agency (EPA) relative to compliance with the emission control requirements (19 CFR 12.73), if applicable.

It should be noted that this bond release letter does not constitute agreement by NHTSA that the vehicle, in fact, is in conformance with all applicable Federal Motor Vehicle Safety Standards (FMVSS). Since actual conformance is determinable only by compliance testing.

By copy of this letter the importer is advised that NHTSA reserves the right to make an actual compliance inspection of the vehicle at a future date to verify the accuracy of data contained in this statement of compliance.

Sincerely,



Francis Armstrong
Director
Office of Vehicle Safety Compliance
Enforcement

CC: PHILLIP W. BIRCH
1150 MCHENRY DRIVE
FERNDALE, MD 21061

FOREIGN INTRIGUE

SOLD TO: 13413 (C) 7/14/70 NS

SHIP TO: _____

B+B RESTORATIONS

4209 MISTY RIDGE RD

HAVANKE7 UA 22069

[illegible]

Thank you

55-70

50 -

15-

—

120.70

WT/ZO 5/12

DATE SHIPPED 18 APR 97

207/698-1000
FAX: 207/698-1001

SHIP TO: _____

DATE 31 Mar 73	HOW SHIPPED UPS	TERMS C.O.D.	M/C VISA #	EXP
MAKE Porsche	MODEL	YEAR	DAY PHONE # 703 754-9366	EXT
REF	REP. YES NO		EVENING PHONE #	

[illegible]

Titanium

NEW PARTS	157-
USED PARTS	—
FREIGHT, HANDLING C.O.D. & INSURANCE	10.50
TAX	—
TOTAL	167.50

WT/ZO 3/4	DATE SHIPPED 16 April 93
-----------	--------------------------



VERTEX

570 West 39 Place
Hialeah Florida 33012

(305) 556-4881

EUROPEAN AUTOMOTIVE PARTS PORSCHE, MERCEDES & BMW

Invoice #

06930025

Customer #

1300

Sold to:

B.B. RESTORATIN
4209 MISTY RIDGE DRIVE
HAYMARKET, VA 22069

Ship to:

B.B. RESTORATIN
4209 MISTY RIDGE DRIVE
HAYMARKET, VA 22069

ORDER
DATE

SHIPPING
DATE

INVOICE #

PAYMENT
TERMS

SHIPPING:

6/2/93

6/2/93

06930025

MM

C.O.D.

UPSr - COD

QTY. ORD.	QTY. SHIP.	PRODUCT CODE	DESCRIPTION	\$/EA	TOTAL
2	2	911424701101	911 HEATER CABLES	7.90	15.80
1	1	911TRNKCART	911 TRUNK CARPET	79.00	79.00
4	4	93010776400	911 OIL FILTER	8.90	35.60
1	1	911TRNKCART	911 TRUNK CARPET <i>Already sent</i>	50.00	50.00
				Items Total	180.40
				shipping & handling	15.00
				TOTAL	195.40
				Received	0.00
				C.O.D.-PAID ON DELIVERY	

SORRY JIM. DID NOT HAVE THE
RUBBER SEAL FOR THE SPARK PLUGS.
ALSO THE TRUNK CARPET SET HAS
3, PIECES.
CASH ONLY...

thank you

A 3.00% fee is added to all credit card orders.

TIF'S FOREIGN CAR

11 MORELAND PKWY
ANNAPOLIS, MD. 21401
268-8288

NAME

ADDRESS

CITY

DATE

CUST. ORDER NO.

WHEN PROMISED

PHONE

YEAR & MAKE OF CAR-TYPE OR MODEL

SERIAL NO.

LICENSE NO.

MILEAGE

WRITTEN BY

DESCRIPTION OF WORK

AMOUNT

AMT.	PART NO.	NAME OF PART	SALE AMT.
2	99970147340	SEAL	5 14
1	99919217650	ALT. BELT	5 81
1	91141330501	T/SIGNAL SWITCH	68 49
1	93035502700	SERVO UNIT	263 28
1	90160930900	PLUG RESISTOR	7 90
1	91461830311	RELAY	41 31
1	CAN	BRAKE FLUID	2 50
	6 FT.	FUEL HOSES	24 90
5	ASSORTED	HOSE CLAMPS	3 50
1		T-FITTING	60

CHECK & ADJUST ENGINE CAM TIMING
REMOVE, CHECK & CLEAN ALL INJECTORS
SCOPE TEST ENGINE & ADJUST FUEL
MIXTURE TO SPECIFICATION
REPLACE 1 SPARK PLUG RESISTOR
" SEAL BETWEEN TURBO UNIT
& INTERCOOLER, REPLACE ALT. BELT
CHECK CLUTCH OPERATION - SEEMS O.K.
" OIL LEVEL GAUGE - PROBABLY NEEDS
NEW SENDING UNIT

285 00

N/C

GAS, OIL & GREASE

CHECK BELOW LUBRICATE

LABOR ONLY

GALS. GAS

CHANGE ENGINE OIL

PARTS

QTS. OIL

TRANSMISSION

ACCESSORIES

LBS. GREASE

DIFFERENTIAL

GAS, OIL & GREASE

WASH

MISC. MERCHANDISE

POLISH

SUBLET REPAIRS

TOTAL GAS OIL & GREASE

TOTAL SERVICE

TAX

TOTAL ACCESSORIES

AUTHORIZED BY

TOTAL

SEE BACK FOR ADDITIONAL PARTS

TOTAL PARTS

ACCESSORIES - TIRES AND TUBES

ESTIMATES ARE FOR LABOR ONLY, MATERIAL ADDITIONAL

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE TO VEHICLES PLACED WITH THEM FOR STORAGE, SALE, REPAIR OR WHILE ROAD TESTING.

PAY THIS AMOUNT



934

1CF2

20 67

1,061 12

No. 94349

Performance DISCOUNT TIRE CO. INC.

- ☐ Forestville, MD, 7601 Penn Belt Drive,
5-6400
☐ Annapolis, MD, 8509 Grovemont
Circle, 948-1090
☐ Alexandria, VA, 5426 Eisenhower
Avenue, 823-2666
☐ Rockville, MD, 11910 Parklawn Drive,
770-4320
☐ College Park, MD, 5103 College Avenue,
277-1888

- ☐ Marlow Heights, MD, 4712A Saint
Barnabas Rd., 423-6161
☐ Merrifield, VA, 8217 Lee Highway,
560-6400
☐ Landover, MD, 8450 Ardwick-Ardmore
Rd., 772-1400
☐ Silver Spring, MD, 9155 Brookville Road,
495-9790
☐ Crofton, MD, 1047 MD 3 North
858-1515, 721-7766

- ☐ Chantilly, VA, 14220 M Sullyfield Circle
631-5252
☒ Annapolis, MD, 30 Hudson Street, Unit
101, 266-6066, 970-2111
☐
☐

NAME		HOME PHONE	
SOLD BY		☒ CASH	☐ ON ACCT.
		☐ RETURNS	DATE
		☐ CHARGE	☐ PAID OUT
		3-21 1990	
MAKE OF VEHICLE	MODEL	TAG NO.	YEAR
		MILEAGE	

QUAN.	DESCRIPTION	PRICE	AMOUNT
1	245/45 VR16 B.F.G. Comp TA	208.97	208.97
	VALVE STEMS		
1	SPIN BALANCE	9.00	9.00
	ROAD HAZARD POLICY		
	CASING DISPOSAL CHARGE		
P.O. No.	THANK YOU!	TAX	10.45
Tax No.		TOTAL	228.42

REC'D BY

1. All claims and returned goods MUST be accompanied by this bill.
2. All returns subject to a 15% handling charge.
3. 1 month limit on deposits.
4. It is imperative that you retorque your custom and/or aluminum wheel lug nuts 25 miles after installation.

See Conditions of Sale on Reverse Side

No. 48364

Performance DISCOUNT TIRE CO., INC.

- ☐ Forestville, MD, 7601 Penn Belt Drive,
735-6400
- ☐ Gaithersburg, MD, 8509 Grovemont
Circle, 948-1090
- ☐ Alexandria, VA, 5426 Eisenhower
Avenue, 823-2666
- ☐ Rockville, MD, 11910 Parklawn Drive,
770-4320
- ☐ College Park, MD, 5103 College Avenue,
277-1888

- ☐ Marlow Heights, MD, 4712A Saint
Barnabas Rd., 423-6161
- ☐ Merrifield, VA, 8217 Lee Highway,
560-6400
- ☐ Landover, MD, 8450 Ardwick-Ardmore
Rd., 772-1400
- ☐ Silver Spring, MD, 9155 Brookville Road,
495-9790
- ☐ Crofton, MD, 1047 MD 3 North
858-1515, 721-7766

- ☐ Chantilly, VA, 14220 M Sullyfield Circle
631-5252
- ☒ Annapolis, MD, 30 Hudson Street, Unit
101, 266-6066, 970-2111
- ☐
- ☐
- ☐

NAME		HOME PHONE	
SOLD BY	☐ CASH	☐ ON ACCT.	☐ RETURNS
T.E.	☐ CHARGE		☐ PAID OUT
DATE		15 Feb 1989	

MAKE OF VEHICLE	MODEL	TAG NO.	YEAR	MILEAGE
Porsche	930T	WFS 514	79	25,000 +

QUAN.	DESCRIPTION	PRICE	AMOUNT
2	245/45VR16 Comp TA	200.00	400.00
2	205/55VR16 Comp TA	191.48	382.96
	Paid ck #551		
	VALVE STEMS Has Perms.		-
4	SPIN BALANCE	9.00	36.00
	ROAD HAZARD POLICY		
4	CASING DISPOSAL CHARGE	.50	2.00
P.O. No.	THANK YOU!	TAX	39.15
Tax No.		TOTAL	860.11

REC'D BY

1. All claims and returned goods MUST be accompanied by this bill.
2. All returns subject to a 15% handling charge.
3. 1 month limit on deposits.
4. It is imperative that you retorque your custom and/or aluminum wheel lug nuts 25 miles after installation.

See Conditions of Sale on Reverse Side

IF'S FOREIGN CAR

11 MORELAND PKWY
ANNAPOLIS, MD. 21401
268-8288

1175

NAME

ADDRESS

CITY

DATE

CUST. ORDER NO.

WHEN PROMISED

PHONE

YEAR & MAKE OF CAR-TYPE OR MODEL

SERIAL NO.

LICENSE NO.

MILEAGE

WRITTEN BY

DESCRIPTION OF WORK

AMOUNT

3/21/86 850-4267 202-861-4948
79 PORSCHE 930
8,436
TROUBLESHOOT ENGINE FOR POOR
RUNNING AFTER COLD STARTING
REMOVE INTERCOOLER, DISASSEMBLE
+ CLEAN WARM-UP REGULATOR, SCOPE
TEST ENGINE + RESET FUEL MIXTURE
CHANGE ENGINE OIL + FILTER (USED
CUSTOMER'S OIL)

CHECK BRAKE WARNING LIGHT SYSTEM-
REFIT CONNECTIONS AT LOGIC RELAY

GAS, OIL & GREASE

CHECK BELOW
LUBRICATE

LABOR ONLY

GALS. GAS

CHANGE
ENGINE OIL

PARTS

QTS. OIL

TRANSMISSION

ACCESSORIES

LBS. GREASE

DIFFERENTIAL

GAS, OIL
& GREASE

WASH

MISC.
MERCHANDISE

POLISH

SUBLET
REPAIRS

TOTAL GAS,
OIL & GREASE

TOTAL
SERVICE

TAX

AUTHORIZED BY

TOTAL

TOTAL ACCESSORIES

243 64

SEE BACK FOR
ADDITIONAL PARTS

TOTAL PARTS

16.85

ACCESSORIES - TIRES AND TUBES

ESTIMATES ARE FOR LABOR
ONLY, MATERIAL ADDITIONAL

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THEREOF. IT IS UNDERSTOOD THAT THIS COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE TO VEHICLES PLACED WITH THEM FOR STORAGE, SALE, REPAIR OR WHILE ROAD TESTING.

PAY THIS
AMOUNT

No. _____

[illegible]

C & J MOTORS

**109 N. Stonestreet Avenue
Rockville, Maryland 20850**

Phone 279-0171

Name				Date 7/23/86	
Address				City	
Phone When Ready	Yes ☐ No ☐	Res. Phone	Bus. Phone 202 861 4948	Promised	
License No.		Year	Make 79	Model 430	Mile ge
Serial No.		Motor No.			Written by

Labor	V	Amount
Lubricate		
Change Oil		
Change Lub. Trans. ☐ Diff. ☐		
Replace Oil Filter		
Clean Air Filter		
Repack Front Wheels		
Adj. Brakes		
Rotate Tires		
Wash ☐ Polish ☐		
Tune Motor		

EVAC & CHARGE AC	45	00
LUBE RT WINDOW CHANNEL		
✓ CV RT SIDE REPL BOTH	60	00
RT SIDE		
A/C COMPRESSOR CLUTCH	90	00
REPL CLUTCH		
✓ TURBO LAG		
ADJ CO + THROTTLE LINKAGE	30	00
REPL FUSE PANEL	15	00
1		

Accessories

Sublet

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By

			Total Labor	240.00
	Gal. Gas @		Total Parts	438.23
	Qts. Oil @		Total Accessories	
	Lbs. Grease @		Total Sublet	
			Total Gas-Oil-Grease	
			Tax	24.16
		Total	Total	702.39

REPAIR ORDER

J. K. MOTORS

Foreign Car Service Center

879-0301

NAME

ADDRESS

CITY

DATE

CUST. ORDER NO.

WHEN PROMISED

PHONE

YEAR & MAKE OF CAR - TYPE OR MODEL

SERIAL NO.

MOTOR NO.

LICENSE NO.

MILEAGE

WRITTEN BY

DESCRIPTION OF WORK

AMOUNT

DOT COMPLIANCE WORK ON

930-

DOT PASSAGE GUARENTEED: NO OTHER
GUARENTEES EXPESD OR IMPLIED.

GAS, OIL, GREASE, WASH, POLISH

LABOR ONLY

GAS-GALS.

LUBRICATE

PARTS

OIL-QTS.

CHANGE
ENGINE OIL

ACCESSORIES

GREASE-LBS.

TRANSMISSION

GAS, OIL
& GREASE

DIFFERENTIAL

MISC.
MERCHANDISE

WASH/POLISH

SUBLET
REPAIRS

TOTAL GAS,
OIL & GREASE ▶

TOTAL
SERVICE ▶

TAX

TOTAL ACCESSORIES ▶

AUTHORIZED BY

TOTAL ▶ 1500

ESTIMATES ARE FOR LABOR
ONLY. MATERIAL ADDITIONAL

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF
TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, sale, repair or while road testing.

**THIS IS YOUR
INVOICE**

17656

TERIAL USED			
QVAN.	ITEM NO.	DESCRIPTION	PRICE
1	911.32241120	gear sleeve	103 67
1	911.613.571.01	O/PRESSURE SW	10 24
1		roll pin	4 00
1		A/C Belt	12 95
1	999.701.469.40	O-RING	4 41
1	93035193805	BRAKE PADS	89 95
8	93035155500	SEALRING	23 12
8	93035154700	"	85 44
2	477.2105611	seal	17 24
1	91134111906	PISTON	12 57
1		NUT	50
1	99918200336	LUG NUT	6 64
REPAIRS			
1	91442321000	PEDAL PAD	2 10
1		VENT KIT	49 95
1	PB 900	pedal bushing kit	19 95
SUBLET REPAIRS			30 00
TOTAL PARTS			442 73

NAME				RECEIVED		DATE	
ADDRESS				A. M.	P. M.	8/21/87	
CITY & STATE				PROMISED		TERMS	
				A. M.	P. M.		
PHONE WHEN READY YES ☐ NO ☐			HOME PHONE NO.	BUS. PHONE NO.		CUSTOMER ORDER No.	ORDER WRITTEN BY
YEAR 79	MAKE Porsche	TYPE OR MODEL 930	SERIAL/M.V.I. NO.		LICENSE No.		SPEEDOMETER

OPER. No.	INSTRUCTIONS	LABOR CHARGE	
	Replace clutch cable	63	00
	R+I pedal cluster - remove broken rod pin - replace bushing	252	00
	Charge A/C system	112	00
	Install Install porchair bulkhead vent	62	00
	Install front Bilstein's (R+I Rt. STRUT incl.)	126	00
	Replace 1 CV boot	42	00
	Replace 2 oil return tube's (Rt. side)	63	00
	R+I calipers, Rotors, rebuild calipers	294	00
	Turn rotors, repack bearings - reinstall make up brake line - Bleed & flush brake system		

I hereby authorize Autothority, Inc. to perform the repair work or diagnosis outlined above together with the necessary materials and to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing or inspecting the vehicle. I recognize that this vehicle, due to its value, is particularly vulnerable to theft and vandalism, that the indoor locked storage facilities of Autothority, Inc. are limited, and hence, in consideration of Autothority, Inc. agreement to undertake this repair, do agree to deliver the said vehicle to Autothority no more than one day before the date marked above and agree to pick up the said vehicle no more than two days after I am notified of the repair completion. I agree that Autothority, Inc. is not liable for theft, vandalism, or accidental damage during any period more than one day before the bring-in date or more than two days after notification of completion of repairs. I agree that an express mechanic's lien is created by virtue of the repairs performed, and further agree that in the event the repair charges are not timely paid, to pay attorney's fees of 1/3 of the bill balance if legal counsel is obtained by Autothority, Inc. to collect any unpaid balance.

GAS, OIL, GREASE				CUSTOMER PAYS			
GAL. GAS @				TOTAL LABOR	9.05	00	
				SUBLET REPAIRS	30	00	
QTS. OIL @				TOTAL PARTS	4.47	73	
				GAS, OIL & GREASE			
LBS. GREASE @							
TOTAL GAS, OIL, GREASE				TAX	19	92	
				TOTAL AMOUNT	103	65	

THANK YOU

QTY.	PART NO. AND DESCRIPTION	PRICE
	Rebuilt ALT	208 75
1	Van. T	3 95
1	Battery 24-50	12 95
1	H4 Lamp	9 71

MT. WASHINGTON AUTOHAUS
 5727 Falls Road
 BALTIMORE, MARYLAND 21209
 (301) 323-8163

① 361-0161

NAME		DATE 3/17/88	
ADDRESS		PROMISED	
CITY		A.M. P.M.	
YEAR, MAKE AND MODEL Porsche 1979 930T	SERIAL NUMBER	LICENSE NUMBER	TERMS
	MOTOR NUMBER	ODOMETER	

DESCRIPTION OF WORK	AMOUNT
LUBRICATION ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE UP ☐	
TRANSMISSION ☐ DIFFERENTIAL ☐ WASH ☐ POLISH ☐	
Charging Problem. Brakes Pull - Clutch Stiff Replace Alt test charging sys Replace battery (surfed) Ch. brake pres. bleed + switch pads side Repair wires to cold start system Disc. wire problem to gas gauge Disc. water gate problem causes boost gauge not to work. Bypass Problem. Replace Van T at Boost control	475 00
TOTAL PARTS	295 16

ACCESSORIES	LITERS/GALS. OF GAS @ Replace head light	TOTAL LABOR	475 00
CUSTOMERS' RIGHTS UNDER MARYLAND LAW: 1. The customer may request a written estimate for repairs which cost in excess of \$50. Written estimate available only with diagnostic service charge (7.50 minimum and up.) 2. The customer may not be charged any amount 10 percent in excess of the written estimate without his consent. 3. The customer is entitled to the return of any replaced parts, except when parts are required to be returned to the manufacturer under a warranty agreement. 4. Repairs not originally authorized by the customer may not be charged to the customer without the customer's consent. 5. The labor rate charged is computed by use of a rate book, which is available for customer inspection upon request.	LITERS/QTS. OF OIL @	TOTAL PARTS	295 16
	kg/LBS. OF GREASE @	ACCESSORIES	
		GAS, OIL AND GREASE	
		OUTSIDE REPAIRS	
		TAX	14 71
		Thank You TOTAL	784

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SIGNATURE

[Signature]

MATERIAL USED			
QUAN.	ITEM NO.	DESCRIPTION	PRICE
1	911.302.917.30	gear teeth	135 00
1	911.302.917.31	gear teeth	135 00
1	930.107.764.00	oil f. ltr	10 92
	hardware		2 00
1	930.110.185.01	a/f filter	19 34
1	930.110.189.00	f/f filter	32 45
2	930.185.194.00	valv cover gskt	6 00
2	930.105.195.01	valv cover gskt	8 00
6	B8EV	plugs	27 00
1	113.131.123	a/pump filter	5 85
2	900123.011.20	crush rings	1 00
1	930.116.081.10	t/o bearing	69 95
1	930.116.014.02	disc	189 95
1	930.116.021.03	pressure plate	230 36
2	930.302.301.00	syncros 1,2	114 56
2	930.302.303.00	syncros 3,4	105 62
1	915.301.191.00	trans gskt	99
1	915.301.351.00	trans gskt	99
1	900112.001.50	shift shaft seal	4 96
1	999113.283.40	input shaft seal	9 95
1	930.302.411.02	shift screw	103 25
1	930.351.938.03	parts	69 95
3	flange, lbs.		11 25
1	901.332.293.12	axle boot	8 20
2	CD911	oil return tubes	44 00
1	911.107.233.00	SUBLET REPAIRS oil line	18 21
2	DOT 3	brake fluid	4 00
2	R36 5001	bit stains	258 00
1	930.423.401.50	clutch cables	73 77
1	999.166.001.02	clavis pin	2 10
1	900.166.002.02	TOTAL PARTS	457



AutoTherity, Inc.

3763 Pickett Road
Fairfax, Virginia 22031
(703) 323-7830
Servicing Porsches Since 1975

17503

NAME		RECEIVED		DATE	
ADDRESS		A. M. 7/6/87		P. M. 8/21/87	
CITY & STATE		PROMISED		TERMS	
PHONE WHEN READY YES ☐ NO ☐		A. M.		P. M.	
HOME PHONE NO. 854 3463		BUS. PHONE NO. 854-3446		CUSTOMER ORDER No.	
YEAR 79		MAKE		TYPE OR MODEL 930	
SERIAL/M.V.I. NO. BLACK		LICENSE No.		SPEEDOMETER 17903	

OPER. No.	INSTRUCTIONS:	LABOR CHARGE
	Major Service: valve adjustment + leakdown Test (890% 6% 8% 8% 6%)	630 00
	replace filters + spark plugs	
	change engine & transaxle oil	
	set timing & fuel mixture	
	chassis inspection + road test	
	R+I engine & transaxle	610 00
	Replace clutch Assembly	40 00
	Disassemble transaxle - replace 4 syncros 2-3 gear dogs - 1-2 & 3-4	250 00
	SPAR sleeves - reassemble	
	WELD EXHAUST LEAKS	89 -

I hereby authorize Autothority, Inc. to perform the repair work or diagnosis outlined above together with the necessary materials and to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing or inspecting the vehicle. I recognize that this vehicle, due to its value, is particularly vulnerable to theft and vandalism, that the indoor locked storage facilities of Autothority, Inc. are limited, and hence, in consideration of Autothority, Inc. agreement to undertake this repair, do agree to deliver the said vehicle to Autothority no more than one day before the date marked above and agree to pick up the said vehicle no more than two days after I am notified of the repair completion. I agree that Autothority, Inc. is not liable for theft, vandalism, or accidental damage during any period more than one day before the bring-in date or more than two days after notification of completion of repairs. I agree that an express mechanic's lien is created by virtue of the repairs performed, and further agree that in the event the repair charges are not timely paid, to pay attorney's fees of 1/3 of the bill balance if legal counsel is obtained by Autothority, Inc. to collect any unpaid balance.

X AUTHORIZED SIGNATURE

CAR OWNER OR AGENT OF OWNER

GAS, OIL, GREASE

CUSTOMER PAYS

7 GAL. 8W GAS @ 90	9 10	TOTAL LABOR	1478 00
12 QTS. 70W OIL @ 50	21 60	SUBLET REPAIRS	
3 LBS. GREASE @ 6 00		TOTAL PARTS	170 34
		GAS, OIL & GREASE	36 70
		GRAND TOTAL	1685 04
		TAX	78 21
		TOTAL AMOUNT	1763 25

THANK YOU