

SHOW REPORT FOR TEXAS VEHICLE REGISTRATION

TEXAS VEHICLE INSPECTION REPORT

Safety & Emissions Inspection

FOR INFORMATION ABOUT VEHICLE INSPECTION, VISIT www.dps.texas.gov/rsd/vi/.

FOR INFORMATION ABOUT ONLINE VEHICLE REGISTRATION, VISIT www.twostepsonesticker.com.

Vehicle Identification

Test Date/Time: **02/16/2026, 11:19**
Test and Type: Initial - OBDII
Insp. Type: **EMONLY**
Version/Test Number: 2503/2230
License Number: **VF152258**
Vehicle ID Number: **WDBSK71F89F152258**
Vehicle Make: **MERZ**
Vehicle Model: **SL550**
Vehicle Year/Type: **2009/Passenger Car/Station Wagon**
Engine Size/Cyl/Ign: 5500/8/D
Authorization Number: **HNNERB5Z1BEW0**
Transmission/GVW: Automatic/4500
Odometer/Fuel Type: 31212/Gasoline

Station Identification

Station Name: VALVOLINE INSTANT OIL CHA
Station #/Analyzer: **2P052810/ES902473**
Station Address: 24311 SOUTHWEST FREEWAY
Station City: ROSENBERG
Station Zip Code: 77471
Inspector First Name: JERIME
Inspector Last Name: HARMON

Safety Inspection Fee: \$0.00
Safety Repair Cost: \$0.00
Emissions Test Fee: \$18.50
Emissions Repair Cost: \$0.00

Total Inspection Cost: \$18.50

Emissions Test Results

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your annual safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

Status of Bulb Check	Monitors	Status	Monitors	Status	Monitors	Status
MIL Cmd Status: OFF	Misfire:	Ready	Heated Cat:	Not Supported	O2 Sens:	Ready
MIL:	Fuel Sys:	Ready	Evap:	Ready	O2 Sens Htr:	Ready
Engine On: PASS	Comp Cmpnt:	Ready	2 nd Sys:	Ready	EGR/VVT:	Ready
Engine Off: PASS	Catalyst:	Ready	Air Cond:	Not Supported	DLC:	Pass

Fault Codes: No Codes Present

Gas Cap Integrity: Pass

Safety Items: Pass

Overall Result: PASS
See Back for Recall Information



I certify that I have properly performed the emissions test according to state regulations and procedure manuals, and as the undersigned duly appointed inspector, hereby certify that I have physically examined the manufacturer's vehicle identification number of the motor vehicle described above.

Plate Type: 2, Plate Number: VF152258, TxDot: , Auth: HNNERB5Z1BEW0



VIN: WDBSK71F89F152258



Certified Inspector Signature