



THE VINTAGE TRIUMPH REGISTER

Concours d' Elegance SUMMARY SCORE

Date: 8/8/03 Location: Armagh, PA
Participant's Name: AL TAYLOR
Entry No: 1704 Model: TR3
Year: 1957 Commision#: 18419

CATEGORY

Exterior

Interior & Soft Trim

Chassis & Undercarriage

Engine Compartment

DEDUCTION

.5

.5

0

0

400

1

399

PERFECT SCORE:

TOTAL DEDUCTIONS:

NET SCORE:

CERTIFICATE OF EXCELLENCE


GOLD:
SILVER:
BRONZE:

350 ☒
300 ☐
250 ☐

VTR Chief Judge:

Revised 7/03

Barrell J. J.





THE VINTAGE TRIUMPH REGISTER

Concours d' Elegance SUMMARY SCORE

Date: 7/29/05 Location: Rockford, IL
Participant's Name: AL TAYLOR
Entry No: 161 Model: TR3
Year: 1957 Commision#: TS18419

CATEGORY

DEDUCTION

Exterior

0.5

Interior & Soft Trim

2

Chassis & Undercarriage

0

Engine Compartment

3

PERFECT SCORE:

400

TOTAL DEDUCTIONS:

5.5

NET SCORE:

394.5

CERTIFICATE OF EXCELLENCE

GOLD: 350 ☒
SILVER: 300 ☐
BRONZE: 250 ☐

For additional information on the detail of your score, please feel free to contact me at:
1996 Four Seasons Drive, Akron, Ohio 44333
email: wedgeinfo@aol.com

VTR Chief Judge:



THE VINTAGE TRIUMPH REGISTER

Concours d' Elegance SUMMARY SCORE

Date: July 20, 2007 Location: Valley Forge, PA
Participant's Name: AL TAYLOR
Entry No: 85 Model: TR-3
Year: 1957 Commision#: T5184192

CATEGORY

DEDUCTION

Exterior

3.0

Interior & Soft Trim

5.8

Chassis & Undercarriage

0.0

Engine Compartment

4.0

PERFECT SCORE:

400

TOTAL DEDUCTIONS:

12.0

NET SCORE:

388

CERTIFICATE OF EXCELLENCE

GOLD: 350 ☒
SILVER: 300 ☐
BRONZE: 250 ☐

For additional information on the detail of your score, please feel free to contact me at:
1996 Four Seasons Drive, Akron, Ohio 44333
email: wedgeinfo@aol.com

VTR Chief Judge:

Revised 10/06



THE VINTAGE TRIUMPH REGISTER

Concours d' Elegance SUMMARY SCORE

Date: August 8, 2008 Location: Ypsilanti, MI
Participant's Name: Al Taylor
Entry No: 171 Model: TR3
Year: 1957 Commision#: 18149

CATEGORY

DEDUCTION

Exterior

1

Interior & Soft Trim

1

Chassis & Undercarriage

1

Engine Compartment

2

PERFECT SCORE: 400


TOTAL DEDUCTIONS: 5

NET SCORE: 395

CERTIFICATE OF EXCELLENCE

GOLD: 350 ☒
SILVER: 300 ☐
BRONZE: 250 ☐

For additional information on the detail of your score, please feel free to contact me at:
1996 Four Seasons Drive, Akron, Ohio 44333
email: wedgeinfo@aol.com

VTR Chief Judge: 

Wadsworth, OHIO July, 2002

TRA

Master Scoresheet

Entry # 33 Model TR3 Year 57

Commission # TS 18419 L0

Owner Al Taylor

Area	Points	Unadjusted Score	Weight	Adjusted Score
.....				
Exterior	(100)	<u>97</u>	x .40	= <u>38.8</u> ✓
Underhood	(100)	<u>83</u> 86	x .20	= <u>16.6</u>
Interior	(100)	<u>92</u>	x .25	= <u>23</u>
Chassis	(100)	<u>97</u>	x .15	= <u>14.55</u>

Grand Total (100) 92.95 CER
.16 CLK
93.55

Computing Score

1. Record scores from area worksheets in "Unadjusted Score" columns.
2. Multiply "Unadjusted Score" for each area by the "Weight" for that area.
3. Round result to nearest 100th point (eg., 12.345 is rounded up to 12.35) and record in "Adjusted Score".
4. Compute Grand Total as sum of "Adjusted Scores" from each of the judging areas. A perfect score would be 100.

Exterior Scoresheet

Entry # 33 Model TR3 Year 57
 Commission # TS 18419 LD
 Owner Taylor

Body Panels -- Quality of Restoration

Enter score from Exterior Scoring, Bodywork and Paint Worksheet
 Subtotal -- Quality of Restoration 47 ✓

Body Panels -- Originality Deductions

* Doors	- Incorrect handle(s). Deduct 2 per door	2:4	_____
	- Incorrect door(s). Deduct 2 point per door	2:4	_____
* Fenders	- Incorrect Fender. Deduct 5 per fender.	5:20	_____
	- Missing Stone guards	2:4	_____
	- Missing fender stay	2:4	_____
* Trunk	- Incorrect trunk	5	_____
	- Incorrect trunk latch/securing	2	_____
* Hood	- Incorrect hood	5	_____
	- Incorrect hood latch/securing	2	_____
* Aprons	- Incorrect front or rear apron	5:10	_____
	- Radiator deflector missing or color different from body	2	_____
* Fiberglass panels. Deduct 3 point per panel (3:12 fenders, 3:6 aprons)		2:18	_____
* Paint	- Poor paint match from panel to panel	3	_____
	- Nonoriginal decals or pin-stripes.	5	_____
	- Nonstandard Paint used (body color). Includes use of metallic paint. No deduction if color is documented.	8	_____
Subtotal -- Body Panel Originality Deductions			<u>-10-</u>

Miscellaneous Exterior

* Badge	- Badge, Front Letters, and Rear Letters	6	<u>6</u>
* Lights	- Headlight rims	2	<u>2</u>
	- Turn Signals - Front	2	<u>2</u>
	- License Illumination Lamp/cover	2	<u>2</u>
	- Rear Turn Signals/Tail Lights, Reflectors (TR2 only)	2	<u>2</u>
* Grille		6	<u>6</u>
* Bumpers	- Front and Rear	10	<u>10</u>
* Windshield	- Frame, Glass and Wipers	10	<u>10</u>
* Hinges		3	<u>3</u>
* Fender Welt/Beading		3	<u>3</u>
* Fasteners: Doors, windscreen, and rear scuttle		4	<u>4</u>
Subtotal -- Miscellaneous Exterior		(50)	<u>50</u>

Body Panel Subtotal (Quality of Restoration less Originality Deductions)..... (50) 47

(If Originality Deductions subtotal is greater than the Quality of Restoration subtotal, enter zero.)

Exterior Total Score (Body Panel Subtotal plus Miscellaneous Exterior Subtotal)..... (100) 97 ✓


Judge DL

CER
clh

Exterior Scoring Bodywork and Paint Worksheet

Entry # 33

Owner _____



Annotations:

X Bodywork flaw
VVV Paint flaw
// Alignment flaw

Major flaws circled.

Quality of Restoration Scoring

		Bodywork		Paint		Mountings	Total
Doors & Rockers	4	<u>4</u>	2	<u>2</u>	2	<u>2</u> 8	<u>8</u>
Fenders	8	<u>7</u>	6	<u>6</u>	2	<u>2</u> 16	<u>15</u>
Trunk	3	<u>3</u>	3	<u>3</u>	2	<u>2</u> 8	<u>8</u>
Hood	3	<u>3</u>	3	<u>3</u>	2	<u>2</u> 8	<u>8</u>
Aprons	5	<u>4</u>	3	<u>2</u>	2	<u>2</u> 10	<u>8</u>
Subtotal	23	<u>21</u>	17	<u>16</u>	10	<u>10</u> (50)	<u>47</u>

Judge RL

CER
alk

TRA

Underhood Scoresheet

Entry: 33

Model/year: TR3/57

Commission #: TS 18419 LO

Owner: Taylor

Category	Originality Deductions			Quality Points	Quality Earned	Originality Deductions
Identification Plates	5 pts	3 pts	1 pts	5	4	-
Commission	Missing or incorrect	Eng# less Comm#	Plate fasteners or location	2		
Chassis EB	Missing or incorrect		Chassis pl painted EB paint	2 1	-1	
Inner Panels	5 pts	3 pts	1 pts	10	7	-3
Firewall	Incorrect panel	Panel not body paint	Mount HW finish	3	-1	
Inner Fenders	Incorrect panel	Hood support	Mounting HW	3		
Hood underside		Hood latch	Box to body seams	3	-2	
Washer Bottle		Bottle not period		1		-3 OK JRC
Battery	5 pts	3 pts	1 pts	5	5	-3
Battery	Battery not std 12v	Battery cables	Finish	1		
Cables		Starter cable	Not lead caps	2		-3
Securing Assemb		Securing assembly	Securing nuts	2		
			Box to body seams			
			Boot on + lead			
Electrics	5 pts	3 pts	1 pts	20	20	-4
Wiring Harness	Incorrect component	Harness insulat. type	Finish	4		-1
Wipers		rubber insul.	Wire striping	2		
Starter		Starter cable	Routing/dressing	2		
Solenoid			Mounting HW	1		-1
Voltage regulator		Spade vs screw conn	Mounting position	2		
Fuse box		Fuses	Fuse spares	2		
Flasher unit				1		
Coil			Coil decal	2		-1
Generator			Generator, coil, horn, or wiper terminals	2		-1
Horns				2		
Hydraulics	5 pts	3 pts	1 pts	10	9	-1
Clutch/brake Master cylinder assembly	Incorrect assembly	Incorrect: Hyd lines	Incorrect: Resv. decal	5		-1
Hydr lines		C/B line adapter	Mount hardware	2		
		Restrictor valve				
Slave cylinder		Slave support rod		3		
		Slave spring				
		Slave mounting				
		Pedal stops				

Category	Originality Deductions			Quality Points	Quality Earned	Originality Deductions
Engine	10 pts	3 pts	1 pts	25	25	-1.0
Block	Incorrect component	Incorrect: Removal HW Drain cock	Incorrect: Finish Eng Serial # expose Ground strap Decals	5 7		
Head		Head bolts Rocker cover <u>Oil filler cap</u>	Mount hardware	5 3		-1.50
Oil filter		Oil dip stick, breather	<u>Distributor terminal</u>	3		-1.25
Distributor		Distributor clamp plate Distributor cap Spark wires Hoses	VA line routing <u>Clamps</u>	3 2		-1.25 Grommet
Vacuum advance						
Fuel System	5 pts	3 pts	1 pts	10	10	0
Carbs	Incorrect component	Incorrect:	Incorrect:	2		
Float bowls		Linkage	Finish	2		
Air filters		Fuel lines	Routing	2		
Manifolds		Hoses	Decals	2		
Fuel pump			Mount hardware Clamps	2		
Controls	5 pts	3 pts	1 pts	5	5	0
Steering Unit	Incorrect component	Incorrect:	Incorrect:	2		
Temperature Sending Unit		Steering brackets	Finish	2		
Cables		Tach or Speedo cable	Cable routing Rubber	1		
Cooling System	5 pts	3 pts	1 pts	10	10	0
Radiator	Incorrect component	Incorrect:	Incorrect paint	3		
Fan		Hoses	Wrong or missing clamps	2 2		
Water pump		Heater return				
Thermostat		Water pump pulley	Missing water pump grease fitting Routing	1 2		
Heater valve						
Total Quality pts earned and subtract originality deductions				Total possible	100	95
						12

Judges Annotation Key:

Circled item - originality deduction
Underlined item - quality deduction

UH Total

83

CER
clh

TRA

Interior Scoresheet

Entry #	33	Model	TR3	Year	57
Commission #	TS 18419 LO				
Owner	Taylor				

Category	Originality Deductions			Quality pts Earned	Origin. Deduct
Top and Sidecurtains (I)	8 pts	4 pts		24	24 1
Top	Fabric, color, or pattern (Hardtop) Headliner	Top or tonneau fasteners (Hardtop) fittings		12	
Hoodsticks	Hoodstick unit	Paint Webbing Fasteners		4	
Sidecurtains	Fabric, color, or pattern	Brackets <i>side glass</i>		8	-1
Trunk and Tools (VII)	4 pts	2 pts	1 pts	6	6 1
Floor	Covering	Paint Drainage tubes		2	
Spare tire	Tire	Stowage straps		0	
Millboard	Pattern	Paint		2	
Tools - all	<i>dirty</i>	Jack & handle/ratchet	Finish	1	#0
		Coach key	Finish	1	
		Instruction book	Binding	1	
Tools-Disc wheels		Wheelbrace	Finish	1	
		Nave plate removal tool	Finish	1	
Tools-Wire wheels		Knockoff hammer	Finish	1	
Tool Roll		(quality only)		0	
Door Panels (III)	8 pts	4 pts	2 pts	8	8 0
Panels	Upholstery fabric, color, or pattern	Piping (TR3A only)		4	
Pockets		Pockets or covering		3	
Pulls			Cables Fittings	1	
Trim (VII)	-3	4 pts	2 pts	6	3 1
Upholstery		Fabric, color, or pattern: <u>Wheelarch</u> <u>Quarter casing</u> <u>Rear bulkhead</u> <u>Elbow Capping</u> <u>Tonneau capping</u> <u>Center tonneau</u> <u>Door edge roll</u>	Piping	4	-1
Draught excluder			<u>Vinyl up furlon</u>	1	-1
Door Sill			Sill finishers	1	
Battery box drain			Tube (TS3288 on)	0	
Jacking hole cover			Cover	0	

Judges' Annotations Key: Circled item = Originality deduction Underlined item = Quality deduction

Category	Originality Deductions			Quality		Origin. Deduct
	pts	pts	pts	pts	Earned	
Seats (II)	8 pts	4 pts	1 pts	16	16	
Upholstery	Fabric, color, or pattern (Hardtop) Headliner	Fabric construction (if noticeable)		12		
Slides	Slide unit <i>revised</i>	Paint	Hardware (if noticeable)	4		
Occasional Seat	Fabric, color, or pattern		Mount hardware	4		
Carpet (IV)	8 pts	4 pts	1 pts	12	12	0
Carpet	Fabric, color, or pattern	Binding	Attachment hardware	10		
Mats		Front floor mats		2		
Steering Wheel (VI)		4 pts	2 pts	4	4	0
Wheel		Wheel	Wheel fittings (adjustable only)	2		
Control Head		Control head assembly		2		
Dash and Instruments (V)	8 pts	4 pts	1 pts	24	23	0
Dash Coverings	Center instrument panel Cubbybox door			2		
Gauges, Switches & Controls	Incorrect location or gauge: Speedometer Tachometer Fuel gauge Ammeter Oil pressure gauge Temperature gauge	Incorrect location or switch: Center panel controls Heater switch Headlamp dipper Vent control Overdrive switch Windscreen washer	Warning lights (2)	8		
Cubbybox assembly	Cubbybox	Cubbybox lock Cubbybox door backing Plate and hinge	Buffer plates Check rod Striker plate Attach hardware	2		
Pedals	Pedal assembly	Brake/clutch pedals	brake/clutch pads	1		
Gearshift	Gearshift lever	Gearshift knob Rubber boot		2		
Handbrake	Handbrake lever	Handbrake grip Boot		1		
Grab Bar		Chrome vs black		1		
Rear Mirror	Mirror/frame		Mountings	2		
Ashtray			Ashtray & mountings	1		
Dash support	Support		Finish Hardware	2		
Heater	Heater unit		Mountings	1		
Radio & Add-ons		Non-period		4		
Subtotal (Quality points earned subtotal and Originality deductions subtotal)					98	4
Interior Total Score (Quality Points earned less Originality Deductions)				100	94	6

Note: Items in *Italics* are optional on all or some models.CER
ckh

Chassis Scoresheet

Entry # 33 Model TR3 Year 57
 Commision# TS 18419 L0
 Owner Taylor

	Quality Points Earned	Originality Deductions
I. Chassis Chassis paint, cleanliness, hardware.	(15) <u>14</u>	<u>-</u>
II. Exhaust System Configuration, exhaust condition, exhaust hardware	(10) <u>10</u>	<u>-</u>
III. Fuel and Brake Line Routing	(5) <u>5</u>	<u>-1</u>
IV. Front Brakes, Suspension, and Lower steering. Configuration and finish of front brakes, suspension components, and lower steering. Condition of hardware.	(10) <u>10</u>	<u>-</u>
V. Rear Brakes, Suspension, and Rear Axle Assembly Configuration and appearance of rear end components. Hardware.	(10) <u>10</u>	<u>-</u>
VI. Propeller Shaft, Transmission and Road Wheels Propellor Shaft and Transmission: Finish and configuration of propellor shaft, transmission. (8 point allocation)	(8) <u>8</u>	<u>-</u>
Road Wheels: Type and finish of road wheels, tires, knaveplates, world medalions, knockoffs (if applicable), hardware. (8 point per allocation per wheel)	(32) <u>32</u>	<u>-</u>
VII. Wheelarches and Underbody Panels Finish and cleanliness of underbody and wheelarches, small underbody panels and hardware.	(10) <u>9</u>	<u>-</u>
Subtotals	<u>98</u>	<u>1</u>
	CER <u>CH</u>	<u>CH CER</u>

Chassis Total Score (Quality Points earned less Originality Deductions)

(100) 97
CH CER

}} ROAD DAMAGE FRONT FRAME
 SHUT OFF NOT CONNECTED
 PAINT OVER UNDERCOAT

Bullshit!