

# 1997 Mercedes-Benz E300 Diesel

4dr Sedan . 6-cyl. 2996cc/134hp MFI Diesel

#1 Concours condition

**\$19,900**

▾ -17.1%

#2 Excellent condition

**\$14,400**

▾ -16.8%

#3 Good condition


**\$10,900\***

▾ -16.8%

#4 Fair condition

**\$7,600**

▾ -17.4%



NOTE: The chart displays price changes for the last year.

## Model description

We apologize, but no model history was found for this vehicle.

### Body styles

4dr Sedan

### Engine types

6-cyl. 2996cc/134hp MFI Diesel

## 1996-2003 Mercedes-Benz W210 stats

Highest sale

**\$74,195**

Lowest sale

**\$1,210**

Most recent sale

**\$6,326**

Sales

**671**

\*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)<sup>®</sup> on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

## Equipment

### Standard Equipment

AM/FM CASS  
 Air Conditioning  
 All Wheel  
 Dual Air Bags Front and Sides/Active Belts  
 Pass Key  
 Power Brakes  
 Power Steering  
 Power Windows  
 Tilt Steering Wheel

### Optional Equipment

AM/FM CD  
 Power Sun/Moon Roof

### Additional Info

Drive Type: RWD  
 Front Tire Size Code: 38  
 Front Tire Size: 16R215  
 Manufacturer Code: C127  
 Manufacturer MSRP: 39900  
 Market Segmentation: Mid Size Luxury Car  
 Shipping Weight: 3405  
 Wheel Base Longest - Inches: 111.5  
 Wheel Base Shortest - Inches: 111.5

## Vehicle's condition classification

### #1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

### #2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

### #3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

### #4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.