

1997 Chevrolet K1500 1/2 Ton

2dr Fleetside Extended Cab Short Bed 4x4 · 8-cyl. 350cid/255hp SFI

#1 Concours condition

\$58,500

0%

#2 Excellent condition

\$34,600

0%

#3 Good condition


\$19,100*

0%

#4 Fair condition

\$7,200

0%



NOTE: The chart displays price changes for the last year.

Model description

We apologize, but no model history could be found.

Body styles

2dr Fleetside Extended Cab Long Bed 4x4

2dr Fleetside Extended Cab Short Bed 4x4

2dr Fleetside Long Bed Pickup 4x4

2dr Fleetside Short Bed Pickup 4x4

2dr Sportside Extended Cab Pickup 4x4

2dr Sportside Pickup 4x4

Engine types

6-cyl. 262cid/200hp SFI

8-cyl. 305cid/230hp SFI

8-cyl. 350cid/255hp SFI

8-cyl. 395cid/180hp Turbo Diesel

1988-2000 Chevrolet GMT400 Series Trucks stats

Highest sale

\$47,775

Lowest sale

\$6,050

Most recent sale

\$16,013

Sales

103

Equipment

Standard Equipment

5 Speed Manual
 Yes
 Yes
 AM/FM
 All Wheel
 Dual Front Air Bag/Active Belts

Optional Equipment

4 Speed Automatic
 Yes
 Yes

Additional Info

Wheel Base Shortest - Inches: 141.5
 Wheel Base Longest - Inches: 155.5
 Shipping Weight: 4544
 Drive Type: 4RD
 Manufacturer Name: General Motors
 Truck Tonnage Rating: 1/2
 Manufacturer MSRP: 20826
 Truck Front Axle: Standard Axle
 Truck Rear Axle: Single
 Market Segmentation: Full Size Half Ton Pickup
 Truck Gross Vehicle Weight Rating Code: 2
 Manufacturer Code: C137
 Truck Tonnage Rating Code: B

Vehicle's condition classification

#1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)[®] on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.