



Hagerty Marketplace *Cat-D-Matic* Cataloger

General Information			
Year, Make, Model		VIN/Chassis Number	
1990 BENZ 420SEL		WDBCA35E4LA552176	
Engine (Displacement/Number of Cylinders/Etc.)		Transmission	
		<input type="checkbox"/> Manual	<input type="checkbox"/> PDK
		<input type="checkbox"/> Automatic	<input type="checkbox"/> Other
		Speeds:	
Odometer		Wheels/Tires (Size/Brand/Etc.)	
<input type="checkbox"/> Mile <input type="checkbox"/> Km			
<input type="checkbox"/> Actual <input type="checkbox"/> TMU			
Options/Notes			
Checklist			
Location	Imperfections?	Photos?	
Passenger Front Quarter Panel	RT BUMPER SCRAPES RT MIRROR RT ROCKER: CHIPS	<input type="checkbox"/>	
Passenger Door	RT DOORS SCRATCHES & CHIPS RT SIDE CHROME	<input type="checkbox"/>	
Passenger Rear Quarter Panel	RT BUMPER: PAINT BUBBLES BUMPER: CHIPS + SCRATCHES	<input type="checkbox"/>	
Rear End and Rear Chrome	REAR CHROME: PITTED/SCRATCHED LFT TAIL LIGHT CRACK	<input type="checkbox"/>	
Rear Deck Lid	LFT REAR: CHIPS RT REAR DOOR: CHIPS DRIVER'S: S+C	<input type="checkbox"/>	
Rear Trunk Lid	LFT ROCKER: SCRATCHES LFT BUMPER: CHIPS/CRACKS	<input type="checkbox"/>	
Drivers Rear Quarter Panel	FRNT BUMPER: S+C, CHROME CHIP AND SCRATCHES	<input type="checkbox"/>	
Drivers Door	LFT SIDE CHROME BAD LFT REAR JAM SCRATCHES	<input type="checkbox"/>	
Roof/Top of Automobile	RT DOOR JAM SCRATCHES + TOP CORNER	<input type="checkbox"/>	
Dashboard	LFT REAR WINDOW TRIM POPPED ARM REST SEPERATED	<input type="checkbox"/>	
Front Seats	PASS SEAT LEATHER CONSOLE WOOD CRACKED/MATCH	<input type="checkbox"/>	
Rear Seats	SHIFT BOOT WORN DRIVER'S BOLSTER	<input type="checkbox"/>	
Front Carpet	LFT LOWER DASH LFT MIRROR DRIVER'S DOOR RUST	<input type="checkbox"/>	
Rear Carpet	RT FENDER RUST LFT HEADLIGHT CONDENSATION	<input type="checkbox"/>	
Gauges/Radio/Speedometer/Odometer	TRUNK CARPET DISCOLORED	<input type="checkbox"/>	
Undercarriage		<input type="checkbox"/>	