

2011 Mercedes-Benz SLS AMG

2dr Coupe . 8-cyl. 6208cc/563hp PFI

#1 Concours condition

\$255,000

▾ -5.2%

#2 Excellent condition

\$216,000

▾ -10.4%

#3 Good condition


\$180,000*

▾ -10%

#4 Fair condition

\$111,000

▾ -17.8%



NOTE: The chart displays price changes for the last year.

Model description

We apologize, but no model history was found for this vehicle.

Body styles

2dr Coupe

Engine types

8-cyl. 6208cc/563hp PFI

2010-2015 Mercedes-Benz SLS AMG stats

Highest sale

\$1,001,000

Lowest sale

\$86,735

Most recent sale

\$224,512

Sales

476

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)[®] on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

Equipment

Standard Equipment

7 Speed Automatic
 AM/FM CD/MP3
 Air Conditioning
 All Wheel
 Audible Backup Assist
 Daytime Running Lights
 Dual Front & Side Air Bags/Active Seat Belts w/Auto Passenger Sensor
 Electronic Stability
 Hands Free Calling
 Independent
 Mirror Turn Signal
 Navigation System
 Power Brakes
 Power Steering
 Power Windows
 Radio Antitheft
 Rain Sensing Wipers
 Sentry key / keyless entry / and alarm
 Tilt Steering Wheel
 VVTL
 Vehicle Theft Tracking
 Visual Backup Assist
 Voice Control Navigation

Optional Equipment

Engine Immobilizer

Additional Info

Drive Type: RWD
 Front Tire Size Code: 64
 Front Tire Size: 19R265
 Manufacturer Code: C280
 Manufacturer MSRP: 183000
 Market Segmentation: Prestige Sport
 Rear Tire Size Code: 76
 Rear Tire Size: 20R295
 Shipping Weight: 3748
 Vehicle Height: 49.3
 Wheel Base Longest - Inches: 105.5
 Wheel Base Shortest - Inches: 105.5

Vehicle's condition classification

#1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.