

1991 GMC Syclone 1/2 Ton

2dr Pickup . 6-cyl. 262cid/280hp Turbo

#1 Concours condition

\$75,700

↗ +12%

#2 Excellent condition

\$60,100

↗ +17.6%

#3 Good condition


\$31,800*

↗ +2.9%

#4 Fair condition

\$20,900

↔ 0%



NOTE: The chart displays price changes for the last year.

Model description

Momentarily inspired to build a hot-rod pickup, GMC released the Syclone in 1991. Based on a Sonoma regular cab truck, GMC had Production Automotive Services heavily modify the Sonoma's optional 4.3-liter V-6, most notably by adding a turbocharger and intercooler to boost power to 280 hp. Speculation runs rampant that true output was much higher. All-wheel drive helped put the power to the pavement, and a tuned suspension helped the truck better handle its newfound muscle.

The Syclone became the fastest pickup truck in the world upon its introduction, and the truck was actually quick by any standard. Enthusiast magazines recorded quarter-mile times in the 13s and blistering 0-60 times of 4.6 seconds, and pitted the Syclone against various sports cars of the day. The Syclone also lays claim to being the first production pickup truck to be outfitted with four-wheel anti-lock brakes.

Only 2,998 GMC Syclones were produced, 3 of which were 1992 models. All are menacingly blacked out, save for 2 of the 1992 models, and 10 Marlboro Syclones were modified as post-production contest giveaways, with these special editions wearing red paint and a Targa-style roof.

Today the GMC Syclone is popular among performance truck fans as it is one of the fastest production trucks to ever be produced. Marlboro Editions carry a big premium over standard Syclones due to their rarity, and documentation is mandatory for one of these unique models.

Body styles

2dr Pickup

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)[®] on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

Engine types

6-cyl. 262cid/280hp Turbo

1991-1992 GMC Syclone stats

Highest sale	Lowest sale	Most recent sale	Sales
\$136,500	\$6,588	\$46,200	139

Equipment

Standard Equipment

4 Speed Automatic

AM/FM CASS

Active (Manual) Belts

Air Conditioning

All Wheel

None

Power Brakes

Power Steering

Power Windows

Tilt Steering Wheel

Additional Info

Drive Type: AWD

Manufacturer Code: C137

Manufacturer MSRP: 25500

Market Segmentation: Mid Size Pickup

Shipping Weight: 4200

Truck Front Axle: Unknown

Truck Gross Vehicle Weight Rating Code: 1

Truck Rear Axle: Unknown

Truck Tonnage Rating Code: B

Truck Tonnage Rating: 1/2

Wheel Base Longest - Inches: 108.3

Wheel Base Shortest - Inches: 108.3

Vehicle's condition classification

#1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.