

Year 1937	Make STUDEBAKER	Model COUPE EXPRESS P.U.
VIN J5-C6 2592		Color YELLOW

Rt. Front Fender C
 Rt. Front Wheel _____
 Rt. A Pillar _____
 Rt. Front Door _____
 Rt. Rocker Panel _____
 Rt. B Pillar _____
 Rt. Rear Door _____
 Rt. C Pillar _____
 Rt. Rear/Fender _____
 Rt. Rear Wheel _____
 Rear Bumper _____
 Rear _____
 Tail Lights _____
 Trunk Lid _____
 Lft. Rear/Fender CR, _____
 Lft. Rear Wheel _____
 Lft. C Pillar _____
 Lft. Rear Door _____
 Lft. B Pillar _____
 Lft. Rocker _____
 Lft. Front Door _____
 Lft. A Pillar _____
 Lft. Front Wheel _____
 Lft. Front Fender LIGHT HAS VERY SLIGHT S
 Front Bumper _____
 Headlights _____
 Grill _____
 Lower Valance _____
 Hood _____
 Cowl _____
 Glass _____
 Emblems _____
 Engine Bay _____
 Trunk Interior _____

Video Checklist

- ☒ Cold Engine Start
☒ 360 Walk Around Engine Running
☒ In Car Video 1. Getting up to 45mph Gauges
☒ In Car Video 2. Looking out of windshield
☒ In Car Video 3. All Gears if manual
☒ Turnsignals, headlights and high beams
☒ Rear turnsignals, Taillights, brake lights, backups
☐ Radio working/speakers
☐ Winshield wipers operating

Rt. Front Door Jam/Sill S
 Rt. Front Door Card _____
 Rt. Front Carpet _____
 Rt. Front Seat _____
 Rt. Rear Door Jam/Sill _____
 Rt. Rear Door Card _____
 Rt. Rear Carpet _____
 Backseat _____
 Lft. Rear Door Jam/Sill _____
 Lft. Rear Door card _____
 Lft. Rear Carpet _____
 Lft. Front Door Jam/Sill CR
 Lft. Front Door Card ST
 Lft. Front Carpet _____
 Lft. Front Seat _____
 Center Console _____
 Steering Wheel _____
 Dashboard _____
 Glove Box _____
 Gauges _____
 Headliner _____
DRIVERS SIDE WIPER DOESNT WORK

Trucks

Tailgate _____
 Truckbed _____
 Truckbed Interior Panels S

Imperfections Key

"S" = Scratch	"T" = Tear/Rip
"C" = Chip	"F" = Faded
"SC" = Scuff	"H" = Hazy/Cloudy
"R" = Rust	"ST" = Stained
"PI" = Paint Imperfection	"OX" = Oxidized
"CHP" = Chrome Pitted	"CR" = Crack