



Hagerty Marketplace *Cat-D-Matic* Cataloger

General Information			
Year, Make, Model		VIN/Chassis Number	
2014 TIGÉ 23 BOAT		TIX0437A1314	
Engine (Displacement/Number of Cylinders/Etc.)		Transmission	
		<input type="checkbox"/> Manual <input type="checkbox"/> Automatic	<input type="checkbox"/> PDK <input type="checkbox"/> Other
Odometer		Wheels/Tires (Size/Brand/Etc.)	
<input type="checkbox"/> Mile <input type="checkbox"/> Km <input type="checkbox"/> Actual <input type="checkbox"/> TMU			
Options/Notes			
TIGÉ TRAILER: RT SIDE: CHIPS + SCUFFS LFT SIDE: SCRATCHES, RUST + CHIPS FRONT: PAINT ISSUES, SCRATCHES + RUST REAR: RUST AT BOTTOM			
Checklist			
Location	Imperfections?	Photos?	
Passenger Front Quarter Panel	BOAT RT. SIDE: DECAL CHIP SCUFFS IN CHROME	<input type="checkbox"/>	
Passenger Door	CHIPS SCUFFS ON RUBBER	<input type="checkbox"/>	
Passenger Rear Quarter Panel	BOAT REAR: PAINT CHIPS RUST UNDERNEATH	<input checked="" type="checkbox"/>	
Rear End and Rear Chrome	NEAR PROP	<input type="checkbox"/>	
Rear Deck Lid	BOAT LFT SIDE: CHIPS SCUFFS IN CHROME	<input type="checkbox"/>	
Rear Trunk Lid	AND RUBBER RUST ON CHROME LOGO	<input type="checkbox"/>	
Drivers Rear Quarter Panel		<input type="checkbox"/>	
Drivers Door	INTERIOR: GOUGE OUT OF BLACK METAL PIECE	<input type="checkbox"/>	
Roof/Top of Automobile	CRACKS AND CHIPS AND DISCOLORATION ON SEATS	<input type="checkbox"/>	
Dashboard	SCUFFS AND CHIPS ON FIBERGLASS AND IN BINS	<input type="checkbox"/>	
Front Seats	DISCOLORATION ON CARPET SCREEN DELAMINATED	<input type="checkbox"/>	
Rear Seats	DEEP SCRAPES UNDER REAR SEAT CUSHION	<input type="checkbox"/>	
Front Carpet	SCRAPES IN TOP RUBBER/FOAM SURROUND	<input type="checkbox"/>	
Rear Carpet		<input type="checkbox"/>	
Gauges/Radio/Speedometer/Odometer		<input type="checkbox"/>	
Undercarriage		<input type="checkbox"/>	