

2013 Ford Mustang Shelby GT500

2dr Coupe . 8-cyl. 351cid/650hp Supercharged

#1 Concours condition

\$76,800

▼ -5.9%

#2 Excellent condition

\$60,500

▼ -3%

#3 Good condition


\$38,500*

▼ -10.5%

#4 Fair condition

\$31,200

▼ -6.9%



NOTE: The chart displays price changes for the last year.

Value adjustments

-15%
for 6-cyl.

-10%
for auto trans.

-15%
for Super Snakes
with lower output.

Model description

We apologize, but no model history was found for this vehicle.

Body styles

2dr Convertible

2dr Coupe

Engine types

8-cyl. 351cid/650hp
Supercharged

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)® on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

2007-2014 Ford Mustang Shelby GT500 stats

Highest sale	Lowest sale	Most recent sale	Sales
\$1,100,000	\$19,250	\$56,175	1454

Equipment

Standard Equipment

6 Speed Manual

AM/FM CD/MP3

Air Conditioning

All Wheel

Audible Alarm

Dual Air Bags Front and Sides/Active Belts

Electronic Stability

Engine Immobilizer

Hands Free Calling

Injury Protection Seating

Keyless entry and alarm

Live

Mirror Turn Signal

Power Brakes

Power Steering

Power Windows

Retractable Roof Panel

Tilt Steering Wheel

Voice Control Navigation

Optional Equipment

Navigation System

Satellite

Wheel Lock

Additional Info

Drive Type: RWD

Front Tire Size Code: 63

Front Tire Size: 19R255

Manufacturer Code: C134

Manufacturer MSRP: 54200

Market Segmentation: Mid Size Sport

Rear Tire Size Code: 66

Rear Tire Size: 19R285

Shipping Weight: 3820

Vehicle Height: 55.1

Wheel Base Longest - Inches: 107.1

Wheel Base Shortest - Inches: 107.1

Vehicle's condition classification

#1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.