

1999 Mazda MX-5 Miata

2dr Convertible • 4-cyl. 1839cc/140hp MPFI

#1 Concours condition

\$26,000

↗ +97%

#2 Excellent condition

\$16,900

↗ +108.6%

#3 Good condition


\$9,900*

↗ +94.1%

#4 Fair condition

\$4,900

↗ +19.5%



Value adjustments

-20%
for auto trans.

+\$1000
for Hardtop.

Model description

We apologize, but no model history was found for this vehicle.

Body styles

2dr Convertible

Engine types

4-cyl. 1839cc/140hp MPFI

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)® on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

1999-2005 Mazda MX-5 Miata stats

Highest sale	Lowest sale	Most recent sale	Sales
\$57,750	\$4,510	\$8,611	466

Equipment

Standard Equipment	Optional Equipment	Additional Info
5 Speed Manual	4 Speed Automatic	Drive Type: RWD
AM/FM CD	AM/FM CASS	Front Tire Size Code: 15
Dual Front Air Bags/Active Seat Belts/Pass Deactivate/Cutoff	Air Conditioning	Front Tire Size: 14R185
None	All Wheel	Manufacturer Code: C134
Power Brakes	Power Steering	Manufacturer MSRP: 19770
	Power Windows	Market Segmentation: Compact Sport
		Shipping Weight: 2299
		Wheel Base Longest - Inches: 89.2
		Wheel Base Shortest - Inches: 89.2

Vehicle's condition classification

#1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.