



**Z Car Guy Cincinnati**  
1416 Ledlie St  
Cincinnati, 45225  
(513) 546-1086  
zcarguycin@gmail.com  
On facebook : Z Car Guy Cincinnati

## Estimate #140

Created: 2/18/2025 03:58 PM EST  
Payment Term: On Receipt  
Service Writer: Paul Krimmer

### Notes

**Paul Krimmer**

2/18/2025 4:15 PM EST

Hi Ron,

Below is a link to the first estimate (fuel drain and replenish) you requested from Z Car Guy Cincinnati. Please review and let us know if you have any questions.

File: Estimate\_140\_-\_Fuel\_cell\_drain\_and\_inspection\_-\_Ron\_Schierer\_-\_1981\_Nissan\_\_280\_ZX\_Non\_2\_2.pdf

**Paul Krimmer**

2/24/2025 4:37 PM EST

Hi Ron,

Below is a link to the completed estimate / repair file from Z Car Guy Cincinnati. Please review and let us know if you have any questions.

File: Estimate\_140\_-\_Fuel\_cell\_drain\_and\_inspection\_-\_Ron\_Schierer\_-\_1981\_Nissan\_\_280\_ZX\_Non\_2\_2.pdf

**Paul Krimmer**

4/25/2025 9:17 AM EDT

Hi Matt,

1981 280 ZX fuel service. Below is a link to the estimate you requested from Z Car Guy Cincinnati. Please review and let us know if you have any questions.

File: Estimate\_140\_-\_Fuel\_cell\_drain\_and\_inspection\_-\_Ron\_Schierer\_-\_1981\_Nissan\_\_280\_ZX\_Non\_2\_2.pdf





**Z Car Guy Cincinnati**  
1416 Ledlie St  
Cincinnati, 45225  
(513) 546-1086  
zcarguycin@gmail.com  
On facebook : Z Car Guy Cincinnati

## Estimate #140

Created: 2/18/2025 03:58 PM EST  
Payment Term: On Receipt  
Service Writer: Paul Krimmer

**ZCGC ZCGC**  
zcarguycin@gmail.com

**1981 Nissan 280 ZX Non 2+2 (White)**  
VIN: HS130254565  
Mileage: 44,609

Customer Comments	Recommendations
Car is in excellent original condition. All ways garaged. Started but not driven for a few years.	Shop recommends draining existing fuel and not starting engine until new fuel is in place to avoid injector contamination. Tow to shop.

### Fuel cell drain and inspection.

Fuel tank in excellent condition with out any contaminates or rust stains. Sending unit in the same condition.

Description	Price	QTY	HRS	Subtotal
1 Remove / reinstall rear carpet, fuel sending unit and floor cover plate. Suction remove existing fuel from tank. Inspect with scope for condition.			1	\$160.00
2 Re fuel with 10 gallons of 91 octane new. Estimated per gallon cost.	\$4.25	10		\$42.50
Shop Supplies (13.7%): \$21.92 Tax (7.8%): \$17.50				<b>Total: \$241.92</b>

Please note a current Insurance policy reflecting the value of the vehicle to its owner must be provided prior to repair initiation. Billing invoice in increments via e mail link must be paid with in a 7 day period via PayPal or another agreed method for repairs to continue. Any unpaid repair after the 7 day period will accrue a \$25.00 a day storage fee. Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost.

Parts .....	\$42.50
Labor .....	\$160.00
Subtotal .....	\$202.50
Shop Supplies .....	\$21.92
Tax .....	\$17.50
<b>Grand Total .....</b>	<b>\$241.92</b>
Paid To Date .....	(\$241.92)

**REMAINING BALANCE \$0.00**

All parts are new unless specified otherwise.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control. We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter. You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature \_\_\_\_\_

Payments			
2/25/2025	Check #2567	PK 2 bills ck fo r\$664.37	\$241.92





**Z Car Guy Cincinnati**  
1416 Ledlie St  
Cincinnati, 45225  
(513) 546-1086  
zcarguycin@gmail.com  
On facebook : Z Car Guy Cincinnati

## Estimate #142

Created: 2/18/2025 04:16 PM EST  
Payment Term: On Receipt  
Service Writer: Paul Krimmer

ZCGC ZCGC

1981 Nissan 280 ZX Non 2+2 (White)

VIN: HS130254565

Last Recorded Mileage: 44,609

Customer Comments	Recommendations
Excellent original condition car . Started but not driven recently. Inspection requested for the benefit to a potential buyer.	Shop recommends a physical and test drive inspection for sale preparation. This car is un molested and extremely original. With absolutely no signs of rust , original refinish . Show condition would only require paint cleaning.

### Lift Inspection.

Lift inspection consist of : Check condition and level of all fluids (coolant, fuel, brake and clutch , transmission and differential).  
Brake inspection (remove wheels and inspect brake parts condition, look for leaks, test E Brake operation) Steering and suspension (test / inspect steering joints. control arm bushings, strut seals) Tire condition / date stamp . Options / controls operation (exterior and interior lighting and signals , gages, windshield wipers, heat /AC, radio / antenna, )

Description	HRS	Subtotal
1 Lift inspection.	2.25	\$360.00
2 Test drive inspection. Test drive after lift inspection approximately 5 miles of city and HI way conditions.	0.25	\$31.88
3 Fluid levels / condition : Fuel tank drained / inspected / hand wiped out. Perfect condition. Engine oil clean. Trans and diff level correct. Brake and clutch fluid clean. Coolant good.		\$0.00
4 Brake inspection : Front brake pads @ 20% wear , Rotors are slightly scored. Rear brake pads @ 50 % wear , Rotors slightly scored. No leaks present. Fluid clean , Brakes including E brake operate as it should.		\$0.00
5 Steering / suspension inspection : Steering joints tight with grease boots intact, control arm bushings show minimal age , Compression rod bushings and sway bar all show more a bit moor. Struts are dry and test drove well.		\$0.00
6 Tire condition : Tires date stamped 2008 (17 years old). Minimal tread wear , flat spots felt above 55 MPH. Tires have aged out. Original rims are in excellent condition.		\$0.00
7 Controls testing : All interior and exterior lighting works as should with the exception of the hazard switch only operated one side , over head dome lamp not operating. Gages , heating / AC system , cruise control , power mirrors, radio (volume control crackles when adjusting) antenna , power mirrors , wipers , all working as should.		\$0.00
8 Test drive results : Ten mile test drive . Car handles , runs , shifts exceptionally well. Cruise control also working. Wheel shake above 55 . Tires would need replacement to be certain of any additional causes but un unlikely.		\$0.00
Tax (7.8%): \$30.57		<b>Total: \$422.45</b>





**Z Car Guy Cincinnati**  
1416 Ledlie St  
Cincinnati, 45225  
(513) 546-1086  
zcarguycin@gmail.com  
On facebook : Z Car Guy Cincinnati

## Estimate #142

Created: 2/18/2025 04:16 PM EST

Payment Term: On Receipt

Service Writer: Paul Krimmer

Please note a current Insurance policy reflecting the value of the vehicle to its owner must be provided prior to repair initiation. Billing invoice in increments via e mail link must be paid with in a 7 day period via PayPal or another agreed method for repairs to continue. Any unpaid repair after the 7 day period will accrue a \$25.00 a day storage fee. Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost.

Parts .....	\$0.00
Labor .....	\$391.88
Subtotal .....	\$391.88
Tax .....	\$30.57
<b>Grand Total .....</b>	<b>\$422.45</b>
Paid To Date .....	(\$422.45)

<b>REMAINING BALANCE</b>	<b>\$0.00</b>
--------------------------	---------------

All parts are new unless specified otherwise.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control. We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter. You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature \_\_\_\_\_

### Payments

2/25/2025	Check #2567	ck to Pk for \$664.37 includes other bill	\$422.45
-----------	-------------	----------------------------------------------	----------