


PLAZA TIRE SERVICE

<b>Vehicle</b> 1986 Alfa Romeo Spider Mileage In: 115275	<b>From</b> Paul Rager Service Advisor  Plaza Tire 9098 19700 Cantrell Rd.  5012149166	Caleb Mahfouz Technician
--	---	-----------------------------

**REASON FOR TODAY'S VISIT**

**MULTIPLE FLUID LEAKS PTS WINDSHIELD HAS CHIPS PTS, MILAGE IN 115275 TEST DROVE CAR AND THE ENDING MILAGE 115278 THE ODOMETER IS WORKING THE OLD TIRES HAD 10/32 AND STARTED AT 11/32**

**8 ITEMS HAVE SERVICE REQUIRED**

<b>Fluid Leaks</b>	<b>Observations:</b>
	<b>Finding:</b> Seeping <b>Recommendation:</b> Degrease and Dye
<b>Under Hood: Other findings</b>	<b>Observations:</b>
	<b>Finding:</b> Multiple leaks <b>Recommendation:</b> Other
	<b>Photos:</b>
	
<b>Left Front Tire Inspection</b>	<b>Observations:</b>
	<b>Finding:</b> Left Front Tire Aged <b>Recommendation:</b> Replace Left Front Tire
<b>Right Front Tire Inspection</b>	<b>Observations:</b>
	<b>Finding:</b> Right Front Tire Aged <b>Recommendation:</b> Replace Right Front Tire
<b>Left Rear Tire Inspection</b>	<b>Observations:</b>
	<b>Finding:</b> Left Rear Tire Aged <b>Recommendation:</b> Replace Left Rear Tire
<b>Right Rear Tire Inspection</b>	<b>Observations:</b>
	<b>Finding:</b> Right Rear Tire Aged <b>Recommendation:</b> Replace Right Rear Tire
<b>Oil Leaks</b>	<b>Observations:</b>
	<b>Finding:</b> Multiple Leaks Present <b>Recommendation:</b> Perform Cleaning Service With Dye
	<b>Photos:</b>



**Rear Differential**

**Finding:** Differential Cover Leaking  
**Recommendation:** Reseal Differential Cover

**Photos:**



**Observations:**

**Finding:** Due by Manufacturer Recommendation  
**Recommendation:** Rear Differential Fluid Exchange \*

**2 ITEMS HAVE SERVICE SUGGESTED**

**Windshield**

**Observations:**  
**Finding:** Cracked  
**Recommendation:** Replace Windshield

**Photos:**



\* DIFFERENTIAL & TRANSMISSION OIL changed by PLAZA TIRE SERVICE ON MAY 21, 2025.

**Transmission Fluid**

**Observations:**  
**Finding:** Due By Manufacturer Recommended Time/Mileage  
**Recommendation:** Recommend Transmission Fluid Exchange \*

**12 ITEMS ARE OK!**

✓ Exterior Body "4 Corner"



- ✓ Front Brake System Inspection
- ✓ Front Suspension Inspection
- ✓ Alignment

- ✓ Warning Lights
- ✓ Horn
- ✓ Wipers/Washers
- ✓ Front Lights
- ✓ Rear Lights
- ✓ Other Findings
- ✓ Front Shocks and Struts
- ✓ Steering Component Inspection