

Murphy Appraisal
Bristol CT 06010
Office/Cell/Text 860-...
Email

June 21, 2024

Subject - 1928 Chrysler
Body Style - 2 Door w/rumble seat
Color - Dark Gold / Brown

Model - 72 Sports Roadster
V.I.N. - 225847
Mileage - 61,284

The following is a summary of observations and opinions in reference to the condition and market value for the listed vehicle.

Grading is determined on a six tiered scale respectively being excellent, fine, very good, good, restorable, and parts only. These categories can also be listed as 1-6 with 1 being the best condition. These are often used as the standard, taken from guidebooks, classic car books, auctions and magazines.

This vehicle had undergone a full high quality restoration that was completed years ago. The automobile is showing some age from its restoration which included the interior, full body and paint and all of the mechanicals. The vehicle shows as a factory appearing automobile.

The front seats are upholstered in brown leather seats and are in fine condition. The seats are immediately adjacent to each other. The black floor mat shows as new and the two piece door trim panels are in excellent condition. Gauges are located in the center of the dash and are surrounded by an engine turned bezel that is trimmed with chrome moldings. The gauges read amperes, oil pressure, and coolant temperature. The original 4-spoke steering wheel has the proper hub controls.

The cloth top has been replaced and its framework has been fully restored. Wind wings are mounted to the windshield frame. The back compartment has a right side access door which was purposeful to allow golf clubs to be loaded. The owner has period correct golf clubs and a golf bag. The rumble seat is fully functional and in fine condition. The step pads to "climb aboard" to the rumble seat are present and properly mounted.

The front and rear bumpers are proper and the rear of the vehicle has a luggage rack. A proper luggage box is with the vehicle. The frame is painted brown to match the color of the fenders.

Murphy Appraisal
Bristol CT 06010
Office/Cell/Text 860-302-2295

Page 2 of 2

The side of the vehicle sports an orange stripe that runs from the doors to the front section of the quarter panels. The spoke wheels are painted to match this stripe and are wrapped with reproduction wide whitewall tires. Spare tires are mounted in the wells located at the rear of each fender. Each spare tire has a rear view mirror strapped into place. The headlamp housings and the grille surround have been re-chromed and are in excellent condition. The body and paint work was of high quality and survived the years extremely well. The car has been stored properly and well cared for.

The engine remains as the 248.9 cubic inch 6 cylinder which is mated to a manual transmission. All of the mechanicals were restored and under the hood was nicely and properly detailed for a factory issue appearance. The car runs and drives without issue.

All of the interior switches and components function properly. There are no exterior trim pieces missing. Overall the car is graded to be in fine condition.

If I can be of any further assistance, please do not hesitate to contact me.

Respectfully,

Jim Murphy
License #'s 919719 & 963029