

2012 Ford Mustang Shelby GT500

2dr Coupe · 8-cyl. 330cid/550hp SFI Supercharged

#1 Concours condition

\$63,200

▾ -2%

#2 Excellent condition

\$46,300

▾ -2.1%

#3 Good condition


\$38,500*

↗ +20.3%

#4 Fair condition

\$26,400

↗ +2.7%



NOTE: The chart displays price changes for the last year.

Model description

We apologize, but no model history was found for this vehicle.

Body styles

2dr Convertible 2dr Coupe

Engine types

8-cyl. 330cid/550hp SFI Supercharged

2007-2014 Ford Mustang Shelby GT500 stats

Highest sale	Lowest sale	Most recent sale	Sales
\$1,100,000	\$19,250	\$30,976	1617

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)[®] on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

Equipment

Standard Equipment

6 Speed Manual
 AM/FM CD/MP3
 Air Conditioning
 All Wheel
 Audible Alarm
 Dual Air Bags Front and Sides/Active Belts
 Electronic Stability
 Engine Immobilizer
 Hands Free Calling
 Injury Protection Seating
 Keyless entry and alarm
 Live
 Mirror Turn Signal
 Navigation System
 Power Brakes
 Power Steering
 Power Windows
 Retractable Roof Panel
 Tilt Steering Wheel
 Voice Control Navigation

Optional Equipment

Satellite
 Wheel Lock

Additional Info

Drive Type: RWD
 Front Tire Size Code: 63
 Front Tire Size: 19R255
 Manufacturer Code: C134
 Manufacturer MSRP: Indeterminate
 Market Segmentation: Mid Size Sport
 Rear Tire Size Code: 66
 Rear Tire Size: 19R285
 Shipping Weight: Indeterminate
 Vehicle Height: Indeterminate
 Wheel Base Longest - Inches: 107.1
 Wheel Base Shortest - Inches: 107.1

Vehicle's condition classification

#1. Concours

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.