

Barr's Performance Restoration
 3950 Mercantile Ave
 Naples, FL 34104 US
 (239) 261-2230
 Sharilynbarr@gmail.com
 http://barrsrestorations.com/



INVOICE

BILL TO



Bonita Springs, Florida 34135
 United States

SHIP TO



Bonita Springs, Florida
 34135
 United States

INVOICE # 2882

DATE 05/26/2023

TERMS Due on receipt

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Parts	Oil Filter	1	25.19	25.19T
Parts	VR1 20w50 Oil	6	13.97	83.82T
Parts	Radiator Cap	1	12.08	12.08T
Parts	Transmission Fluid	4	15.81	63.22T
Parts	Transmission Pan Gasket	1	20.99	20.99T
Parts	Speedometer Bullet	1	30.73	30.73T
Freight	Freight: Speedometer Bullet	1	20.42	20.42
Parts	Tires 2 Front 225/60/R15	2	259.00	518.00T
Parts	Tires 2 Rear 245/60/R15	2	287.00	574.00T
				Subtotal: 1,348.45
Hazardous Waste Removal:Solid Waste Tax	Tire Disposal	4	1.00	4.00
Subcontractor	Subcontractor Mount and Balance Tires	4	35.00	140.00T
59 Mechanical Labor	Checked Front End Diagnosed Driving Issues	1:30	175.00	262.50T

Notes

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	Inspected Transmission Leaks			
Alignment	Alignment 2 hrs \$400 Additional hour \$175 Total 3 Hours	1:00	575.00	575.00T
59 Mechanical Labor	Removed and Charged Battery Made New Battery Cables Detailed Battery Tray Repaired Battery Hold Down Clean Up Wires to MSD by Battery Auto Transmission Service Complete Oil Change Replace Radiator Cap Complete Inspection	7:30	175.00	1,312.50T
59 Mechanical Labor	Replaced 2 Fuel Hoses By Fuel Tank Installed A/C 134 Fittings Add 2oz Die Evacuate and Recharge A/C Replace Speedo Bullet Replace Dash Light Bulbs Replace Heater / A/C Control Head Bulb Road Test	4:15	175.00	743.75T
Shop Supplies	Disposal fees, environmental fees, various miscellaneous supplies	15.25	15.95	243.24T

Please sign below to accept your invoice.

X Sign here

SUBTOTAL	4,629.44
TAX	322.35
TOTAL	4,951.79
BALANCE DUE	\$4,951.79