

REPAIR ORDER



Date : 07/30/2014
 License # : 4XLM524
 Make : PORSCHE
 Model : 911
 Year : 99
 Odometer In: 52451

VIN : WP0CA2998XS651687

LABOR	AMOUNT
CALIFORNIA STATE SMOG INSPECTION.	41.75

Perform visual, functional and emissions test.

Check and set air pressure in tires

NOTICE: YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM THE NEEDED REPAIRS, INSTALLATIONS, ADJUSTMENTS, OR SUBSEQUENT TESTS.

PARTS All parts new unless otherwise noted.

SC SMOG CERTIFICATE

PRICE	QTY	AMOUNT
8.25	1	8.25
Parts Sub-Total		8.25
Job Sub-Total		50.00

Original Estimate : 50.00

Increases to Estimate					
Date	Time	OK'd By	Phone	Emp.	Increase

LABOR	41.75
PARTS	8.25
SUBLETS	.00
ENVIRONMENTAL RECYCLING	.00
FREIGHT	.00
SUB TOTAL	50.00
TAX	.00
TOTAL	<u>50.00</u>

LABOR GUARANTEED 1 YEAR OR 12,000 MILES. WHICHEVER OCCURS SECOND.

I hereby authorize the repair work to be done along with necessary material, and hereby grant you and/or your employees permissions to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. I also authorize any sublet work that you deem necessary.

Authorized by : _____ Date : _____

SMOG CHECK VEHICLE INSPECTION REPORT

(07/30/2014 @ 12:50:50 pm)

Vehicle Information

Year..... 1999	Make..... FORSCHE	Model..... 911 CARRERA
Plate No..... 4XLM524	State..... California	VIN..... WFOCA2998XS651687
Engine Size..... 3.4 Liters	Type..... Passenger	Transmission..... Manual
..... N/A	Test Weight..... 3375 lbs.	Cylinders..... 6
..... 52451	Certification..... California	VLT Record #..... 28999
Fuel Type..... Gasoline	Exhaust..... Single	Inspection Reason..... HEP
Engine Year..... N/A	Engine Make..... N/A	Bar Number..... N/A
..... N/A		

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection..(Pass) Functional Check..(Pass) Emissions Test..(Pass)

DMV ID Number..(8375I067P127)
Smog Check Certificate Number..(PI756090)

Your Smog Check certificate has been electronically transmitted to the DMV.
This certificate is valid for ninety (90) days from the date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist the identification of oxides of nitrogen, crankcase, and cold start emissions which are not measured during the idle tests)

ECS	Result	ECS	Result	ECS	Result
PCV.....	Pass	Fuel Evaporative Controls.....	Pass	Catalytic Converter.....	Pass
Spark Controls.....	Pass	Fuel Injection.....	Pass	Pump Air Injection.....	Pass
Oxygen Sensor.....	Pass	Wiring to Sensors.....	Pass	Vacuum lines sensors/switches..	Pass
Other related emis. components.	Pass	Liquid Fuel Leak.....	Pass	Fuel Cap Integrity Test.....	Pass
Fuel Cap Visual.....	Pass	OBD System Check.....	Pass	Ignition Timing.....	N/A

ASM Emission Test Results

Test	RPM			HC (PPM)			CO (%)			NO (PPM)			Result
	MEAS	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
M1: 15 MPH	1502	14.9	0.1	55	9	2	0.50	0.03	0.00	437	67	191	Pass
M2: 25 MPH	1794	14.9	0.1	39	6	0	0.48	0.03	0.00	724	62	45	Pass

MAX = Maximum Allowed Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Station Information

RANDALL BROTHERS AUTOMOTIVE
7505 REDWOOD BLVD.
NOVATO, CA 94945
1 415 892 8821

Technician Name/Number..... VASSEGHI, SAIED/E0149712
Repair Tech Name/Number..... N/A
Software Version/EIS Number... 1201/SX041072
Station Number..... RM074681

I certify under penalty of perjury under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and correct.

07-30-2014

Date

Paul R. Vasaghi

Technician's Signature



Baldwin's German Autowerks

400 Enfrente Road, Novato, CA, 94949 ☎ 415-883-1684

Baldwin's Courtesy Inspection

Repair Order #
013247

Certified Date/Time of Upload
08/14/2014 09:11:54

Technician Name Technician #2

Summary of Inspection Findings



Additional Information

<p>VIN: WPOCA2998XS651687</p> <p>Body Style: CONVERTIBLE 2-DR</p> <p>Anti-Lock Braking System: 4-Wheel ABS</p> <p>Transmission: 5-Speed Automatic 6-Speed Manual</p>	<p>Trim: Carrera Cabriolet</p> <p>Engine Type: 3.4L H6 DOHC 24V</p> <p>Driveline: RWD</p>	<p>Vehicle: Porsche 911 1999</p> <p>Manufactured in: GERMANY</p> <p>Mileage: 52488</p> <p>Steering Type: R&P</p>
--	--	--

Under the Car

OK: Checked and okay.	Service Soon: Recommend future action.	Urgent Service: Recommend immediate action.
<ul style="list-style-type: none"> <input checked="" type="checkbox"/> Rear Tires (Left-Right) <input checked="" type="checkbox"/> Brakes - Front <input checked="" type="checkbox"/> Brakes - Rear <input checked="" type="checkbox"/> CV Axles / Boots <input checked="" type="checkbox"/> Lower Control Arm <input checked="" type="checkbox"/> Upper Ball Joint <input checked="" type="checkbox"/> Lower Ball Joint <input checked="" type="checkbox"/> Tie Rod <input checked="" type="checkbox"/> Sway Bar <input checked="" type="checkbox"/> Front Shock Absorbers <input checked="" type="checkbox"/> Rear Shock Absorbers <input checked="" type="checkbox"/> Front Suspension <input checked="" type="checkbox"/> Rear Suspension 	<ul style="list-style-type: none"> <input type="checkbox"/> Front Tires (Right-Left) Comments: Inside Wear, Recommend Alignment Check <input type="checkbox"/> Clutch Comments: Slightly Stiff 	

Under the Car

OK: Checked and okay.	Service Soon: Recommend future action.	Urgent Service: Recommend immediate action.
<ul style="list-style-type: none"> <input checked="" type="checkbox"/> Engine / Transmission Mount <input checked="" type="checkbox"/> Manual Transmission <input checked="" type="checkbox"/> Oil Filter Housing <input checked="" type="checkbox"/> Crankshaft Seal <input checked="" type="checkbox"/> Oil Pan <input checked="" type="checkbox"/> Power Steering Fluid Leaks <input checked="" type="checkbox"/> Exhaust <input checked="" type="checkbox"/> Body Plastics 		

Under the Hood

OK: Checked and okay.	Service Soon: Recommend future action.	Urgent Service: Recommend immediate action.
<ul style="list-style-type: none"> <input checked="" type="checkbox"/> Belts (Engine) <input checked="" type="checkbox"/> Valve Cover <input checked="" type="checkbox"/> Engine Oil Level <input checked="" type="checkbox"/> Coolant 	<ul style="list-style-type: none"> <input checked="" type="checkbox"/> Water Pump Comments: Looks Original, Recommend Replacement Every 3 Years <input checked="" type="checkbox"/> Cooling System Comments: Looks Original <input checked="" type="checkbox"/> Power Steering Fluid Comments: When Was the Fluid Flushed Last? <input checked="" type="checkbox"/> Brake Fluid Comments: Every 2 Years, Recommend Flush 	

Body and Electrical

OK: Checked and okay.	Service Soon: Recommend future action.	Urgent Service: Recommend immediate action.
<ul style="list-style-type: none"> <input checked="" type="checkbox"/> Battery <input checked="" type="checkbox"/> Warning Lights <input checked="" type="checkbox"/> Exterior Lights <input checked="" type="checkbox"/> Windshield Washers 		

Body and Electrical

OK: Checked and okay.	Service Soon: Recommend future action.	Urgent Service: Recommend immediate action.
✓ Parking Brake ✓ Rear Hatch / Hood Struts		

Additional Items Noticed

OK: Checked and okay.	Service Soon: Recommend future action.	Urgent Service: Recommend immediate action.
	ⓘ Porsche IMS Comments: Bank 1 -3°, Below 3% OK, Camshaft Deviation Values, Recommend Full Flow Oil Filter Upgrade, Recommend IMS Bearing Upgrade	

Preview of Your Inspection Images

Able Tire & Brake

7090 Redwood Blvd.
 Novato, CA 94945
 (415) 897-4125
 BAR #AJ081903 EPA #CAL000070763

Customer Copy

Invoice #552067

Wednesday, September 09, 2015
 3:06:24 PM

Ordered on
 Tuesday, September 08, 2015

Workorder # 250135

MAKE & MODEL	FLEET NO.	REP	CSH	PO #	TERMS			
1999 PORSCHE 911 CARRERA/CARRERA 4 Carrera 2		Doug Cresta	BA	54518	Cash sale			
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE	
4XLM524	53974	WPOCA2998XS651687		3.4L H6 FI DOHC	6 SPEED MANUAL			
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	FET	TOTAL	Code


OPT20	225/40R18 HANKOOK S1 NOBLE2 92W	2	151.33				\$302.66	DC
B20	COMPUTER BALANCE W/ TIRE PURCH	2		15.00			\$30.00	DC
TAX1	DISPOSAL FEE	2	2.00				\$4.00	
STEM	SMALL RUBBER VALVE STEM	2	.25				\$0.50	DC
TAX5	CA RECYCLE FEE 1.75	2	1.75				\$3.50	

BAR BRAKES APPROX. REMAINING: FRONT 10MM
 BAR1 RECOMMEND REPLACEMENT @ 2MM (DISC) 1MM (DRUM)

Welcome, We appreciate your business.

PAID BY
 AMEX \$367.94

TIRES
 FILLED
 TO:



Parts	\$303.16	Taxable	\$303.16
Labor	\$30.00	Non-Taxable	\$37.50
Freight	\$0.00	Local 9%	\$27.28
Other	\$7.50		
FET	\$0.00		
Supplies	\$0.00		
TOTAL			\$367.94

I, the Registered Owner authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. You and your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it.

In the event any attorney is retained to bring suit for collection of any sums due, I agree to pay costs of collection & reasonable attorney fees. I also understand that the dealer is not a depositor for personal property left in the vehicle & assumes no risk for loss thereof. If the vehicle described herein is not called for within 3 days after such notice is given a storage charge of \$_____ or at least \$10 per day will be made for each day thereafter.

I have read & understood the above.

Receipt of a copy of his order, a copy of an estimate, our warranty & a copy of the Song-Beverly Act is hereby acknowledged.

Print Name _____ Signature _____ Date _____

8009

MAGNACIO MOTORSPORTS

BAR #44137009
384 Hamilton Drive
NORWALK, CA 94062
(415) 584-4666

DATE 10-8-17 AM	DATE PROMISED	A.M. P.M.
CUSTOMER'S ORDER NO.	ORDER WRITTEN BY K. [Signature]	

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
1	OIL FILTER	25.00
9	BRUSHES & OIL	90.00
1	COOLANT HOSE	60.00
1	WATER PUMP	75.00
1.5	SAE 15W-40 MOTOR OIL	45.00
2	HOSE CLAMPS	4.00
1	DIFFERENTIAL FLUID	30.00
		<u>304.00</u>

YEAR, MAKE AND MODEL
1999 Pontiac Vibe 2.5L I4

SERIAL NO./VIN
1G2PC927955651687

LICENSE NO. 44149524 57882

MILEAGE

CALL WHEN READY YES NO

MECHANIC/TECHNICIAN

TERMS

SERVICES REQUESTED/DESCRIPTION OF WORK	AMOUNT
INSPECTED THE CAR FOR A LEAK AND I HAVE FOUND A COOLANT LEAK AND I HAVE REPAIRED THE LEAK AND I HAVE ADJUSTED THE TIGHTENING OF THE HOSE AND I HAVE ADJUSTED THE TIGHTENING OF THE HOSE AND I HAVE CHECKED THE LIGHTS, TIRES, BRAKES AND TOPPED OFF ALL FLUIDS.	
2.5 HRS LABOR AT \$1400 PER HR.	350.00

TOTAL PARTS 304.00

ESTIMATED COSTS			TOTAL LABOR 350.00
PARTS	LABOR	TOTAL 686.84	TOTAL PARTS 304.00
AUTHORIZED BY	DATE	TIME	CALLLED BY
			PHONE
REVISED ESTIMATE / ADDITIONAL WORK			TOTAL SUBLET
PARTS	LABOR	TOTAL	GAS, OIL AND GREASE
AUTHORIZED BY	DATE	TIME	CALLLED BY
			PHONE
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.			EPA / WASTE DISPOSAL 7.00
SIGNATURE [Signature]	SAVE OLD PARTS <input type="checkbox"/> YES <input type="checkbox"/> NO	TAX 25.84	TOTAL 686.84

PRODUCT 6593A To Order by State: 6593B (OH) 6593C (CA)

**TEETERS AND SCHACHT
 AUTO GLASS & UPHOLSTERY
 62 HAMILTON DR.
 NOVATO, CA 94949
 PH:415-883-3400 FAX:415-883-7037**


Copy 1

Contractor License: BAR#AJ235657
 Federal Tax ID: 43-2044765

P/O#: Taken By: Installer: DT	Cust State Tax ID: Cust Fed Tax ID: Ship Via:	Cash Sale: C021094 Date: 10/19/2016 Time: 01:26 PM
SalesRep:	Adv. Code:	

Bill To: CASH

Sold To: CASH



ESTEP BILL

Vehicle Information

Make: Porsche Model Style: 911 Carrera 2 Door Convertible Year: 1999
 Odometer: 55167 VIN: WP0CA2998XS651687 License: 4XLM524

Qty	Part Number	Description	List	Disc%	Sell	Total
1	OEM-PART	99680318309 DRIVERS SEAT BUCKLE	\$115.51	0.00	\$115.51	\$115.51
1.5	LABOR	INSTALL SEAT BUCKLE	\$120.00	0.00	\$120.00	\$180.00

A Payment has been made on this order: AMEX (\$305.62).

TEETERS SCHACHT AUTO
 62B HAMILTON DR
 NOVATO, CA 949490000

10/19/2016 13:27:04

CREDIT CARD
 AMEX SALE

Card #: XXXXXXXXXXX1002
 Chip Card: AMERICAN EXPRESS
 AID: A00000025010801
 ATC: 004C
 TC: 4E83B16D962CFEAA
 SEQ #: 2
 Batch #: 290
 INVOICE: 2
 Approved: 854153
 Issued by: Chip Read
 Mode: Issuer

Sub Total: \$295.51
 Tax: \$10.11

SALE AMOUNT \$305.62

CUSTOMER COPY

AMEX: \$305.62


REPAIR ORDER

ANDALL BROS., INC
 7505 REDWOOD BLVD.
 NOVATO, CA 94945
 415-892-8821
 B.A.R. #AM074681
 E.P.A. #CAL 000233926



Date : 07/15/2016
 License # : 4XLM524
 Make : PORSCHE
 Model : 911
 Year : 99
 Odometer In: 54819

VIN : WP0CA2998XS651687



Work:
 Other:

LABOR	AMOUNT												
CALIFORNIA STATE SMOG INSPECTION.	46.75												
Perform visual, functional and emissions test.													
Check and set air pressure in tires													
NOTICE: YOU MAY CHOOSE ANOTHER SMOG CHECK STATION TO PERFORM THE NEEDED REPAIRS, INSTALLATIONS, ADJUSTMENTS, OR SUBSEQUENT TESTS.													
PARTS All parts new unless otherwise noted.													
SC SMOG CERTIFICATE													
	<table border="0" style="margin-left: auto; margin-right: 0;"> <thead> <tr> <th style="text-align: left;">PRICE</th> <th style="text-align: left;">QTY</th> <th style="text-align: left;">AMOUNT</th> </tr> </thead> <tbody> <tr> <td style="text-align: right;">8.25</td> <td style="text-align: right;">1</td> <td style="text-align: right;">8.25</td> </tr> <tr> <td colspan="2">Parts Sub-Total</td> <td style="text-align: right;">8.25</td> </tr> <tr> <td colspan="2">Job Sub-Total</td> <td style="text-align: right;">55.00</td> </tr> </tbody> </table>	PRICE	QTY	AMOUNT	8.25	1	8.25	Parts Sub-Total		8.25	Job Sub-Total		55.00
PRICE	QTY	AMOUNT											
8.25	1	8.25											
Parts Sub-Total		8.25											
Job Sub-Total		55.00											

Original Estimate : 55.00

Increases to Estimate					
Date	Time	OK'd By	Phone	Emp.	Increase

LABOR	46.75
PARTS	8.25
SUBLETS	.00
ENVIRONMENTAL RECYCLING	.00
FREIGHT	.00
SUB TOTAL	55.00
TAX	.00
TOTAL	<u>55.00</u>

LABOR GUARANTEED 1 YEAR OR 12,000 MILES, WHICHEVER OCCURS SECOND.
 I hereby authorize the repair work to be done along with necessary material, and hereby grant you and/or your employees permissions to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. I also authorize any sublet work that you deem necessary.

Authorized by : _____ Date : _____



Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 07/15/2016@09:37:22	Make: PORSCHE	Model: 911 CARRERA
Model Year: 1999	State: CA	VIN: WP0CA2998XS651687
License: 4XLM524	Type: Passenger Car	Transmission: Manual
Engine Size: 3.40 L	Test Weight: 3375	Cylinders: 6
GVWR: N/A	Certification: California	VLT Record #: 28999
Odometer: 54,819	Exhaust: Single	Inspection Reason: Change of Ownership
Fuel Type: Gasoline		

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: ZF832174

DMV ID Number: 8526F468Z667

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls				
Not applicable	Fuel Evaporative Controls Functional				

ASM Emission Test Results

Test	RPM	%CO2		%O2		HC (PPM)		CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS		
15 mph	1542	15.2	0.0	55	9	31	0.50	0.03	0.04	437	67	100	Pass	
25 mph	1781	15.1	0.1	39	6	13	0.48	0.03	0.00	724	62	46	Pass	

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

RANDALL BROS AUTOMOTIVE INC
7505 REDWOOD BLVD. NOVATO, CA 94945
(415)892-8821
Station Number: RC074681

Technician Name/Number: VASSEGHI, SAIED/EO149712
Repair Tech Name/Number:
Software Version/EIS Number: 1509 / EP525426

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

07-15-2016
Date

SAIED VASSEGHI
Technician's Signature

8176

IGNACIO MOTORSPORTS

BAR #AA197999
501 Hamilton Drive
NOVATO, CA 94949
(415) 883-8856

DATE 6-23-20	DATE PROMISED	AM. PM.
CUSTOMER'S ORDER NO.	ORDER WRITTEN BY	
LICENSE NO. 44V11524	MILEAGE 54776	
CALL WHEN READY <input type="checkbox"/> YES <input type="checkbox"/> NO	MECHANIC/TECHNICIAN	
TERMS		

PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
1 INTERSTATE BATTERY	2100
1 STARTER RELAY	5000
1 QT MOTOR OIL	1000
	<u>27000</u>

YEAR, MAKE AND MODEL
1999 PONTIAC FIREBIRD

SERIAL NO. AT (VIN)
W110 CA 2798X5651A97

SERVICES REQUESTED/DESCRIPTION OF WORK

INSPECTED THE CAR WOULD NOT CRANK OVER OR START. CHARGED AND TESTED THE BATTERY. REPLACED THE WEAK BATTERY. TESTED THE IGNITION SWITCH AND THE STARTER MOTOR. BOTH WERE WORKING PROPERLY. SCANNED THE CAR AND FOUND A FAULT FOR THE TAMPERED LOCK SYSTEM. TRACED THE FAULT TO THE STARTER LOCKOUT RELAY. REPLACED THE RELAY CHECKED THE LIGHTS, HORN, BRAKES BELT AND DROPPED ALL FLOODS.

DME FAULT CODE -
P1571 TAMPERED
OPEN CIRCUIT RESISTANCE

4.0 HRS LABOR AT 15000 PER HR. 60000

SUBLET THE CAR TO SMOG CENTER OF MARIN FOR A SMOG INSPECTION - 10000

TOTAL PARTS 27000

ESTIMATED COSTS		TOTAL	TOTAL LABOR
PARTS	LABOR	99795	60000
AUTHORIZED BY		<input checked="" type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE	TOTAL PARTS
DATE	TIME	DATE	27000
		DATE	TOTAL SUBLET
		DATE	10000
REVISED ESTIMATE / ADDITIONAL WORK			GAS, OIL AND GREASE
PARTS	LABOR	TOTAL	EPA / WASTE DISPOSAL
			TAX
			2295
AUTHORIZED BY		<input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE	TOTAL
DATE	TIME	DATE	99795
		DATE	

RADIO CODE - 0517

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.

SIGNATURE: *[Signature]* SAVE OLD PARTS YES NO

Able Tire & Brake

7090 Redwood Blvd.
 Novato, CA 94945
 (415) 897-4125
 BAR #AJ081903 EPA #CAL000070763

Customer Copy

Invoice #659303

Estimated
 Time Due

Thursday, August 4, 2022
 5:02:22 PM

Ordered on
 Wednesday, July 27, 2022


Workorder # 394241

MAKE & MODEL	FLEET N	REP	CSH	PO #	TERMS			
1999 PORSCHE 911 CARRERA		Justin Grimm	GG		Cash sale			
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE	
4XLM524	59718	WPOCA2998XS651687		3.4L H6 FI DOHC	6 SPEED MANUAL	BLACK	07/98	
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	FET	TOTAL	Code
HAN1014499	225/40ZR18XL 92W HANKOOK H452 VENTUS S1 NOBLE2	2	166.24				\$332.48	AG
FEE	TRANSFER FEE	2	5.00				\$10.00	AG
HAN1014521	265/35ZR18XL 97W HANKOOK H452 VENTUS S1 NOBLE2	2	218.44				\$436.88	AG
FEE	TRANSFER FEE	2	5.00				\$10.00	AG
B20	COMPUTER BALANCE W/ TIRE PURCH	4		20.00			\$80.00	JY-AG
TAX1	TIRE DISPOSAL FEE	4	4.75				\$19.00	
TAX5	CA RECYCLE FEE 1.75	4	1.75				\$7.00	
AL9	EUROPEAN/IMPORT 4-WAY ALIGNMENT 1.5HRS	1		270.00	-27.00		\$243.00	CR-AG
BAR	BRAKES APPROX. REMAINING: 9MM FRONT, 7MM REAR							
BAR1	RECOMMEND REPLACEMENT @ 3MM (DISC)							

Welcome, We appreciate your business.

PAID BY:
 Deposit \$100.00
 VISA \$1,101.83

TIRES
 FILLED
 TO:



Parts	\$769.36	Taxable	\$769.36
Labor	\$350.00	Non-Taxable	\$396.00
Freight	\$0.00	Local 8.25%	\$63.47
Other	\$46.00	Discount	(\$27.00)
FET	\$0.00		
Supplies	\$0.00		
		TOTAL	\$1,201.83

I, the Registered Owner authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. You and your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it.

In the event any attorney is retained to bring suit for collection of any sums due, I agree to pay costs of collection & reasonable attorney fees. I also understand that the dealer is not a depositor for personal property left in the vehicle & assumes no risk for loss thereof. If the vehicle described herein is not called for within 3 days after such notice is given a storage charge of \$ _____ or at least \$10 per day will be made for each day thereafter.

I have read & understood the above.

Receipt of a copy of his order, a copy of an estimate, our warranty & a copy of the Song-Beverly Act is hereby acknowledged.

Parts & Labor guaranteed to the original purchaser at 12 Months or 12,000 miles, whichever first occurs Vehicle must be returned for warranty work.

Print Name _____

Signature _____

Date _____

